Available from

GPO Sales Program

Division of Technical Information and Document Control

U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

and

National Technical Information Service Springfield, Virginia 22161

Title List of Documents Made Publicly Available

July 1-31, 1980

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	V
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket 50 Items by Facility Name	xvii
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	2
Domestic Licensing of Production and Utilization Facilities - Docket 50	12
Domestic Licensing of Special Nuclear Material - Docket 70	336
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions - Docket 71	351
Nondocketed Items	361
10CFR — Commission Meeting Records	361
ACRS — Advisory Committee on Reactor Safeguards	362
COMMISSION — NRC Commissioners	364
CONTRACT — NRC Contracts and Modifications	367
DISCLOSURE — Financial Disclosure Information	371
FOIA — Freedom of Information Act Requests and Releases	371
GEN TECH IS — Generic Technical Issues	377
I&E — Inspection and Enforcement	377
MISC — Public Document Room Miscellaneous	378
NUREG — NUREG Reports and Related Correspondence	380
ORG — Correspondence with Other Organizations	383
PR — Proposed Rule	384
PRM — Petition for Rulemaking	395
PROJ — Projects - Predocket Licensing	396
PT21 — Noncompliance Reports and Related Correspondence	397
QA999 — Quality Assurance Inspections	397
REGGD — Regulatory Guides	401
RES — Research and Technical Assistance Reports	402
REVIEW GRP — NRC Research Review Groups	404
SECY — Position Papers Before the Commission	405
STATE PROG — State Programs	407
TOPREP — Vendor Reports and Related Correspondence	409
WASTE MGT — Nuclear Waste Management	412
XPORTLIC — Export and Import Licenses	413
Personal Author Index	423
Corporate Source Index	459
Report Number Index	493
Cross Reference of Enclosures to Principal Documents	495
Appendix A - Definitions of Docket 50 Categories	513
Anneadiv B. Definitions of Nondocketed Categories	521

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- II. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- O Inspection reports, IE Bulletins and correspondence
- R Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

Appendix A sets forth those categories and described the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report

The principal elements of the entries in the list are:


(1)

P. Operating license stage documents & correspondence



7904[70015 Forwards info on TMLJM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration of incident.

REHM, T.A. Office of the Executive Director for Operations



- 1 NRC/PDR Document category (see Appendix A)
- 2, NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO"

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases

GEN TECH IS - Generic Technical Issues

I&E — Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG — NUREG Reports and Related Correspondence

ORG — Correspondence with other organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects-Predocket Licensing

PT9 — Public Records

PT21 — Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD — Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence

WASTE MGT — Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

1 NUREG - NUREG Reports and Related Correspondence



7901060007 NUREG/CR-0161

"Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.

FIN A-2093. 78/11/30. 26pp. Available at NTIS.

(7) (5) (8) (9) (10) (6)

- 1. Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document

10 If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" or "Available at NTIS." See NOTES on this page for information on ordering publications.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-010	Beatty, NV	1	40-8056	Bronson Methodist Hospital,	6
27-039	Sheffield, IL, Nuclear Engineering Co.	1	10.0100	Kalamazoo, MI	
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8102	Exxon Minerals Co. USA, Exxon Corp.	6
27-048	Richland, WA, Nuclear Engineering Co.	2	40-8200	Cleveland Cliffs Iron Co.	6
40-0215	S. F. Appliance, Ltd.	2	40-8304	Wyoming Mining Corp.	6
40-0299	Union Carbide Corp.	2	40-8329	Salem Hospital, Salem, MA	7
40-1162	Western Nuclear, Inc.	3	40-8380	Rocky Mountain Energy Co.	7
40-1341	Edgemont Uranium Mine, TVA, and	3	40-8438	Eastman Kodak Co.	7
	Mines Development, Inc.		40-8452	Bear Creek Uranium Co.	7
40-1852	Fisher Scientific Co.	4	40-8481	Beeing Co.	8
40-2061	West Chicago Facility, Kerr-McGee Corp.	4	40-8502	Irigaray Mine, Wyoming Mining Corp.	8
40-2259	Pathfinder Mines Corp.	4	40-8584	Union 76 Minerals Exploration Co.	9
40-2561	Zircoa Products, Corning Glass Works	4	40-8585	Wyoming Mining Corp.	9
40-2674	Univ. of Notre Dame	4	40-8602	United Nuclear Corp.	9
40-2940	NL Industries, Inc.	4	40-8647	Kerr-McGee Corp.	9
40-3392	Allied Chemical Corp.	· 4	40-8681	Energy Fuels Nuclear, Inc.	10
40-3453	Atlas Minerals	4	40-8693	Ogle Petroleum, Inc.	10
40-4337	Marquette Univ.	5	40-8697	Rocky Mountain Energy Co.	10
40-4492	Federal American Partners (Mining)	5	40-8698	Piateau Resources, Ltd.	10
40-4669	Case Western Reserve Univ.	5	40-8702	Dept. of the Army, Armament Materials	10
40-5021	Standard Oil Co.	5	40.0514	Readiness Command	10
40-6622	Pathfinder Mines Corp.	5	40-8714	Cleveland Cliffs Iron Co.	10
40-6659	Petrotomics Co., Getty Oll	5	40-8721	Rocky Mountain Energy Co.	11
40-6789	Howard Univ.	5	40-8727	Kerr-McGee Nuclear Corp.	11
40-7402	Allegheny Ludlum Industries,	6	40-8728	Teton Exploration Drilling Co., Inc.	11
	Chemtron Corp.		40-8745	Ogle Petroleum, Inc.	11
40-7982	Honeywell, Inc.	6	40-8768	Kerr-McGee Nuclear Corp.	12
40-8027	Kerr-McGee Corp.	6	40-8771	Nuclear Assurance Corp.	12
40-8045	Suisman & Blumenthal, Inc.	6	50-2	Univ. of Michigan Research Reactor	12

Docket	Name	Page	Docket	Name	Page
50-3	Indian Point Station, Unit 1	12	50-134	Worcester Polytechnic Institute Research	22
50-5	Pennsylvania State Univ Research Reactor	13	-0.444	Reactor	22
50 -10	Dresden Nuclear Power Station, Unit 1	13	50-135	Walter Reed Research Reactor	22
50 -13	Babcock & Wileox Co. Critical Facility	16	50-139	Univ. of Washington Research Reactor	22
50-20	Massaschusetts Institute of Technology	16	50-142	UCLA Training Reactor	22
	Research Reactor		50-150	Ohio State Univ Research Reactor	22
50-27	Washington State Univ. Research Reactor	17	50-151	Univ. of Illinois Research Reactor	22
50-29	Yankee-Rowe Nuclear Power Station	17	50-152	Florida West Coast Nuclear Group Inc.	22
50-47	Army Materials Research Reactor	18	50-155	Big Rock Point Nuclear Plant	22
50-54	Union Carbide Research Reactor	18	50-156	Univ. of Wisconsin Research Reactor	25
50-57	State Univ. of New York Research Reactor	18	50-157	Cornell Univ. Research Reactor	25
50-59	Texas A&M Univ. Research Reactor	19	50-160	Georgia Institute of Technology Research Reactor	25
50-62	Univ. of Virginia Research Reactor	19	50-163	General Atomic Co.	25
50-67	McMaster Univ. Research Reactor	19	50-166	Univ. of Maryland Research Reactor	25
50-70	General Electric Test Reactor	19	50-170	National Naval Medical Center	26
50-73	General Electric Nuclear Test Reactor	19	50-171	Peach Bottom Atomic Power Station,	26
50-77	Catholic Univ. of America Research Reactor	20	30-171	Unit 1	20
50-83	Univ. of Florida Training Reactor	20	50-182	Purdue Univ. Research Reactor	26
50-87	Westinghouse Critical Experiment	20	50-184	National Bureau of Standards Reactor	26
50-89	General Atomic Co.	20	50-186	Univ. of Missouri Research Reactor	26
50-97	Cornell Univ. Zero Power Reactor	20	50-187	Space Radiation Research Reactor	26
50-99	Babcock & Wilcox Test Reactor	20	50-193	Rhode Island & Providence Plantations AEC	26
50-106	Oregon State Univ.	20	50-199	Manhattan College Research Reactor	27
50-111	North Carolina State Univ. Research Reactor	20	50-201	West Valley Reprocessing Plant	27
50-112	Univ. of Oklahoma Research Reactor	20	50-206	San Onofre Nuclear Station, Unit 1	27
50-116	lowa State Univ. Research Reactor	20	50-208	Columbia Univ. Research Reactor	30
50-123	Univ. of Missouri Research Reactor	20	50-213	Haddam Neck Plant	30
50-124	Virginia Polytechnic Institute Training	21	50-219	Oyster Creek Nuclear Power Plant	32
20-124	Reactor	21	50-220	Nine Mile Point Nuclear Station, Unit 1	35
50-128	Texas A&M Univ. Research Reactor	21	50-223	Univ. of Lowell Research Reactor	36
50-129	West Virginia Univ. Research Reactor	21	50-224	Univ. of California Research Reactor	36
50-133	Humboldt Bay Power Plant, Unit 3	21	50-225	RPI Critical Experiment	36

Docket	Name	Page	Docket	Name	Page
50-228	Acrotest Radiography & Research Reactor	37	50-278	Peach Bottom Atomic Power Station, Unit 3	82
50-236	Lockheed Aircraft Corp.	37	50-280	Surry Power Station, Unit 1	85
50-237	Dresden Nuclear Power Station, Unit 2	37		•	88
50-243	Oregon State Univ. Research Reactor	39	50-281	Surry Power Station, Unit 2	
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	39	50-282	Prairie Island Nuclear Station, Unit 1	90
50-245	Millstone Nuclear Power Station, Unit 1	41	50-284	Idaho State Univ. Research Reactor	92
50-247	Indian Point Station, Unit 2	43	50-285	Fort Calhoun Station, Unit I	92
50-249	Dresden Nuclear Power Station, Unit 3	45	50-286	Indian Point Station, Unit 3	94
50-250	Turkey Point Plant, Unit 3	47	50-287	Oconce Nuclear Station, Unit 3	97
50-251	Turkey Point Plant, Unit 4	49	50-288	Reed College Research Reactor	99
50-254	Quad-Cities Station, Unit 1	50	50-289	Three Mile Island Nuclear Station, Unit I	99
50-255	Palisades Nuclear Plant	52	50-293	Pilgrim Nuclear Power Station, Unit I	107
50-259	Browns Ferry Nuclear Power Station,	55	50-294	Michigan State Univ. Research Reactor	109
00 427	Unit 1		50-295	Zion Nuclear Power Station, Unit 1	109
50-260	Browns Ferry Nuclear Power Station, Unit 2	58	50-296	Browns Ferry Nuclear Power Station, Unit 3	112
50-261	H. B. Robinson Plant, Unit 2	60	50-297	North Carolina State Univ PULSTAR Reactor	114
50-263	Monticello Nuclear Generating Plant	61	50-298	Cooper Nuclear Station	114
50-264	Dow Chemical Co.	63	50-301	Point Beach Nuclear Plant, Unit 2	115
50-265	Quad-Cities Station, Unit 2	63	50-302	Crystal River Nuclear Plant, Unit 3	117
50-266	Point Beach Nuclear Plant, Unit 1	65	50-304	Zion Nuclear Power Station, Unit 2	119
50-267	Fort St. Vrain Nuclear Generating Station	67	50-305	Kewaunce Nuclear Power Plant	121
50-268	Midwet Fuel Recovery Plant	68	50-305	Praire Island Nuclear Station, Unit 2	123
50-269	Oconce Nuclear Station, Unit 1	68		Maine Yankee Atomic Power Plant	125
50-270	Oconee Nuclear Station, Unit 2	70	50-309		
50-271	Vermont Yankee Nuclear Power Station	73	50-311	Salem Nuclear Generating Station, Unit 2	127
50-272	Salem Nuclear Generating Station, Unit 1	75	50-312	Rancho Seco Nuclear Generating Station	129
50-273	Beznau Nuclear Station, Switzerland	77	50-313	Arkansas Nuclear One, Unit !	131
50-274	U. S. Geological Survey Research Reactor	77	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	133
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	77	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	135
50-276	Georgia Tech Research Reactor	79	50-317	Calvert Cliffs Nuclear Power Plant,	136
50-277	Peach Bottom Atomic Power Station, Unit 2	80	ı	Unit I	

Docket	Name	Page	Docket	Name	Page
50-3		139	50-361	San Onofre Nuclear Station, Unit 2	215
	Unit 2 Three Mile Island Nuclear Station, Unit 2	141	50-362	San Onofre Nuclear Station, Unit 3	217
50-3			50-363	Forked River Nuclear Station, Unit 1	219
50-3		152 156	50-364	Joseph M. Farley Nuclear Plant, Unit 2	219
50-3			50-366	Edwin I. Hatch Nuclear Plant, Unit 2	221
50-3	Diablo Canyon Nuclear Power Plant, Unit 2	157	50-367	Bailly Generating Station	225
50-3	Brunswick Steam Electric Plant, Unit 2	159	50-368	Arkansas Nuclear One, Unit 2	226
50-3	Brunswick Steam Electric Plant, Unit 1	161	50-369	William B. McGuire Nuclear Station, Unit 1	228
50-	Univ. of California at Irvine Research Reactor	163	50-370	William B. McGuire Nuclear Station, Unit 2	230
50-3	327 Sequoyah Nuclear Plant, Unit 1	163	50-373	LaSalle County Station, Unit 1	232
50-3	328 Sequoyah Nuclear Plant, Unit 2	169	50-374	LaSalle County Station, Unit 2	233
50-3	Midland Plant, Unit 1	172	50-375	Nuclear Examination Reactor	235
50-3	330 Midland Plant, Unit 2	174	50-376	North Coast Nuclear Plant, Puerto Rico	235
50-3	331 Duane Arnold Energy Center	177	50-378	Caorso Nuclear Station, Italy	235
50-3	332 Barnwell Reprocessing Plant	179	50-382	Waterford Generating Station, Unit 3	235
50-:	James A. Fitzpatrick Nuclear Power Plant	179	50-387	Susquehanna Steam Electric Station, Unit 1	236
50-3	Beaver Valley Power Station, Unit 1	181	50-388	Susquehanna Steam Electric Station, Unit 2	239
50-3	335 St. Lucie Plant, Unit 1	183	50-389	St. Lucie Plant, Unit 2	241
50-3	Millstone Nuclear Power Station, Unit 2	186	50-390	Watts Bar Nuclear Plant, Unit 1	242
50-3	North Anna Power Station, Unit 1	188	50-390	Watts Bar Nuclear Plant, Unit 2	243
50-3	North Anna Power Station, Unit 2	191	50-395	Virgil C. Summer Nuclear Station, Unit 1	244
50-3	340 Scabrook Nuclear Station, Unit I	196	50-396	Univ. of Virginia Cavalier Reactor	246
50-3	B41 Enrico Fermi Atomic Power Plant, Unit 2	196	50-397	WPPSS Nuclear Project, Unit 2	246
50-3	344 Trojan Nuclear Plant	197	50-400	Shearon Harris Nuclear Power Plant,	248
50-3	Davis-Besse Nuclear Power Station, Unit 1	201	30-400	Unit 1	240
	arley Nuclear Plant, Unit 1	205	50-401	Shearon Harris Nuclear Power Plant, Unit 2	250
	v Hnit J	206	50-402	Shearon Harris Nuclear Power Plant,	252
	5	208	20 102	Unit 3	
		210	50-403	Shearon Harris Nuclear Power Plant, Unit 4	254
		211	50-4 04	North Anna Power Station, Unit 3	255
		213	50-405	North Anna Power Station, Unit 4	256
		213			

Docket	Name	Page	Docket	Name	Page
50-406	Tuskegee Institute Research Reactor	256	50-460	WPPSS Nuclear Project, Unit 1	289
50-409	La Crosse Boiling Water Reactor	256	50-461	Clinton Power Station, Unit 1	290
50-410	Nine Mile Point Nuclear Station, Unit 2	258	50-462	Clinton Power Station, Unit 2	291
50-412	Beaver Valley Power Station, Unit 2	259	50-463	Fulton Generating Station, Unit 1	291
50-413	Catawba Nuclear Station, Unit 1	260	50-464	Fulton Generating Station, Unit 2	292
50-414	Catawba Nuclear Station, Unit 2	261	50-466	Allens Creek Nuclear Station, Unit 1	292
50-416	Grand Gulf Nuclear Station, Unit 1	262	50-467	Allens Creek Nuclear Station, Unit 2	294
50-417	Grand Gulf Nuclear Station, Unit 2	264	50-471	Pilgrim Nuclear Power Station, Unit 2	294
50-423	Millstone Nuclear Power Station, Unit 3	267	STN-50-482	Wolf Creek Generating Station	294
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	267	STN-50-483	Calloway Plant, Unit 1	297
50-425	Alvın W. Vogtle Nuclear Plant, Unit 2	268	STN-50-484	Tyrone Energy Park, Unit 1	299
50-433	Univ. of California at Santa Barbara	269	STN-50-485	Sterling Power Project Nuclear, Unit 1	300
OTN 1 40 445	Research Reactor	260	STN-50-486	Calloway Plant, Unit 2	300
STN-50-437	Floating Nuclear Plant	269	STN-50-488	Perkins Nuclear Station, Unit 1	302
50-438	Bellefonte Nuclear Plant, Unit 1	270	STN-50-489	Perkins Nuclear Station, Unit 2	303
50-439	Bellefonte Nuclear Plant, Unit 2	271	STN-50-490	Perkins Nuclear Station, Unit 3	304
50-440	Perry Nuclear Power Plant, Unit 1	272	STN-50-491	Cherokee Nuclear Station, Unit I	304
50-441	Perry Nuclear Power Plant, Unit 2	273	STN-50-492	Cherokee Nuclear Station, Unit 2	305
50-443	Scabrook Nuclear Station, Unit 1	275	STN-50-493	Cherokee Nuclear Station, Unit 3	305
50-444	Seabrook Nuclear Station, Unit 2	276	50-496	Montague Nuclear Power Station, Unit I	306
50-445	Comanche Peak Steam Electric Station, Unit 1	277	50-497	Montague Nuclear Power Station, Unit 2	306
50-446	Comanche Peak Steam Electric Station,	280	STN-50-498	South Texas Project, Unit 1	306
	Unit 2		STN-50-499	South Texas Project, Unit 2	309
50-448	Douglas Point Nuclear Station, Unit 1	282	50-500	Davis-Besse Nuclear Power Station, Unit 2	312
50-449	Douglas Point Nuclear Station, Unit 2	282	50-501	Davis-Besse Nuclear Power Station, Unit 3	312
50-452	Greenwood Energy Center, Unit 2	283	STN-50-502	Haven Nuclear Plant, Unit 1	312
50-453	Greenwood Energy Center, Unit 3	283	STN-50-508	WPPSS Nuclear Project, Unit 3	312
50-454	Byron Station, Unit 1	283	STN-50-509	WPPSS Nuclear Project, Unit 5	313
50-455	Byron Station, Unit 2	284	50-513	WPPSS Nuclear Project, Unit 4	313
50-456	Braidwood Station, Unit 1	285	50-514	Pebble Springs Nuclear Plant, Unit 1	314
50-457	Braidwood Station, Unit 2	287	50-515	Pebble Springs Nuclear Plant, Unit 2	315
50-458	River Bend Station, Unit 1	288	STN-50-516	Jamesport Nuclear Station, Unit 1	315
50-459	River Bend Station, Unit 2	289			

Docket	Name	Page	Docket	Name	Page
STN-50-517	Jamesport Nuclear Station, Unit 2	316	50-599	Carroll Facility I	336
STN-50-518	Hartsville Nuclear Plant, Unit 1	316	50-600	Carroli Facility II	336
STN-50-519	Hartsville Nuclear Plant, Unit 2	317	50-754	General Electric Test Reactor	336
STN-50-520	Hartsville Nuclear Plant, Unit 3	318	70-0008	Battelle Columbus Laboratories	336
STN-50-521	Hartsville Nuclear Plant, Unit 4	319	70 0025	Rockwell International Corp.	336
STN-50-522	Skagit Nuclear Power Project, Unit 1	320	70 0027	Babcock & Wilcox Co	337
STN-50-523	Skagit Nuclear Power Project, Unit 2	321	70-0033	Texas Instruments, Inc.	337
STN-50-528	Palo Verde Nuclear Station, Unit 1	321	70-0036	Combustion Engineering, Inc.	338
STN-50-529	Palo Verde Nuclear Station, Unit 2	323	70-0135	Babcock & Wilcox Co.	338
STN-50-530	Palo Verde Nuclear Station, Unit 3	325	70-0143	Nuclear Fuel Services, Inc.	338
50-537	Clinch River Breeder Reactor	326	70-0157	Univ. of Texas	341
50-538	Memphis Station Univ. Research Reactor	327	70-0184	Westinghouse Electric Corp	341
STN-50-546	Marble Hill Nuclear Station, Unit 1	327	70-0203	Univ. of Notre Dame	341
STN-50-547	Marble Hill Nuclear Station, Unit 2	328	70-0364	Parks Township Site, Babcock & Wilcox Co.	341
50-549	Greene County Nuclear Power Plant	330	70-0371	United Nuclear Corp.	342
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	330	70-0398	Dept. of Commerce	342
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	331	70-0474	Upsala College	342
STN-50-556	Black Fox Station, Unit 1	332	70-0572	Monsanto Research Corp.	342
STN-50-557	Black Fox Station, Unit 2	333	70-0625	Howard Univ.	342
STN-50-561	B-SAR-205	333	70-0687	Union Carbide Corp.	342
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	333	70-0734	General Atomic Co.	343
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	314	70-0754	Vallecitos Nuclear Center,	343
STN-50-568	NEP Nuclear, Unit 1	335	15 111	General Electric Co.	
STN-50-569	NEP Nuclear, Unit 2	335	70-0820	United Nuclear Corp.	343
STN-50-580	Erie Nuclear Plant, Unit 1	335	70-0824	Babcock & Wilcox Co.	343
STN-50-581	Eric Nuclear Plant, Unit 2	335	70-0925	Cimmaron Facility, Kerr-McGee Corp.	344
50-582	Sundesert, Unit 1	335	70-0971	Oregon State Univ.	344
50-583	Sundesert, Unit 2	335	70-0 984	Pacific Northwest Laboratory	344
STN-50-592	Palo Verde Nuclear Station, Unit 4	335	70-0997	Westinghouse Electric Corp.	344
STN-50-593	Palo Verde Nuclear Station, Unit 5	335	70-1062	Todd Shipyards Corp.	344
50-594	Ko-Ri, Units 3 & 4, Korea	335	70-1100	Combustion Engineering, Inc.	344
STN-50-596	New Haven, Unit 1	336	70-1113	Cieneral Electric Co.	345
STN-50-597	New Haven, Unit 2	336	70-1143	Westinghouse Electric Corp.	345

Docket	Name	Page	Docket	Name	Page
70-1151	Westinghouse Electric Corp.	346	70-2909	Westinghouse Electric Corp.,	351
70-1177	Davis & Elkıns College	346	TO 2010	Power Systems	
70-1193	Cimarron Facility, Kerr-McGee Corp.	346	70-2910	Tennessee Valley Authority	351
70-1201	UF-6 Conversion Facility,	347	71-0002	Chem-Nuclear Systems, Inc	351
70 1220	Babock & Wilcox Co.		71-0005	Magnaflux Corp.	351
70-1220	General Electric Co.	347	71-0017	Rhode Island Atomic Energy Commission	351
70-1252	Edlow International Co.	347	71-0082	Kerr-McGee Nuclear Corp.	351
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	347	71-0109	Union Carbide Corp.	351
70-1278	Public Service of Colorado	348	71-0121	Neutron Products, Inc.	351
70-1308	Morris Operations, General Electric Co.	348	71-0139	Tulsa Gamma Ray, Inc.	352
70-1309	Morris Operations, Sources & Standards,	348	71-0143	Ranchers Exploration & Development Co.	352
	General Electric Co.		71-0170	General Electric Co.	352
70-1319	U.S. Nuclear, Inc.	348	71-0173	Battelle-Pacific Northwest Laboratory	352
70-1333	Metropolitan Edison Co.	348	71-01 7 9	Nuclear Containers, Inc.	352
70-1359	IRT Corp.	349	71-0189	Todd Shipyards Corp	352
70-1489	Goodyear Aerospace Corp.	349	71-0192	Nuclear Packaging, Inc.	352
70-1738	Pacific Gas & Electric Co.	349	71-0221	Allis Chalmers Corp.	352
70-1739	Tri-State Motor Transit Co.	349	71-0249	Nuclear Fuel Services, Inc.	352
70-1869	Radiation Management Corp.	349	71-0251	Westinghouse Electric Corp.	352
70-2000	Mt. Sinai Hospital, Hartford, CT	349	71-0252	Dayton X-Ray Co.	352
70-2153	United Nuclear Corp.	349	71-0271	Ridthalgh, Eggers & Associates	352
70-2175	United Nuclear Corp.	349	71-0346	Public Service Co. of Colorado	352
70-2375	Pacific Gas & Electric Co.	350	71-0368	Branch Radiographic Laboratories	352
70-2478	Transnuclear, Inc.	350	71-0370	Amersham Corp.	352
70-2574	Carlisle Hospital, Carlisle, PA	350	71-0371	Model: NNFD-10, Unified Nuclear Corp.	352
70-2609	Commonwealth Edison Co.	350	71-0381	E.L. Conwell & Co	352
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	350	71-0383	Model: NLI 1/2 LWT Cask,	353
70-2651	Manchester Memorial Hospital, Manchester, CT	350	71-0384	NL Industries, Inc. New England Nuclear Corp.	353
70-2838	Cincinnati Gas & Electric Co.	350	71-0387	Massachusetts Materials Research, Inc.	353
70-2860	South Carolina Electric & Gas Co.	351	71-0389	Univ. of Georgia	353
70-2885	Commonwealth Edison Co.	351	71-0391	Dept. of the Navy	353
70-2902	North Memorial Medical Center, Minneapolis, MN	351	71-0392	Baker Testing Services, Inc.	353

Docket	Name	Page	Docket	Name	Page
71-0393	Allis-Chalmers Corp.	353	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc	356
71-4824	Model: HA-10, Babcock & Wilcox Co.	353	71-671 <i>7</i>	Model. 6717 B	356
71-4888	Model: Sentinel-25A, B, C, C3, D, E, F, Teledyne Energy Systems	353	71-9009	Model: FL 10-1, General Electric Co.	356
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	353	71-9010	Model: NLI-1/2, NL Industries, Inc	356
71-5088	Model: D34710-1, U.S. Nuclear, Inc.	353	71-9015	Model. TN-8, Transnuclear, Inc.	356
71-5341	Model: NFP-55, Babcock & Wilcox Co	354	71-9016	Model TN-9, Transnuclear, Inc	356
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	354	71-9018 71-9019	Model: BU-6, General Electric Co Model: BU-7, General Electric Co.	357 357
71-5607	Model: GE T-2, General Electric Co.	354	71-9022	Model: CE-250-2, Combustion	357
71-5768	Model: BB-250-2, Combustion Engineering, Inc.	354	71-9027	Engineering, Inc Model: 741, Technical Operations, Inc	357
71-5862	Model; Sentinel-100F, Teledyne Energy Systems	354	71-9030	Model: Sentinal-8, 3, & MW-3000, Teledyne Energy Systems	357
71-5926	Model: 100, General Electric Co.	354	71-9032	Model: 650, Technical Operations, Inc	357
71-5942	Model: GE-700, General Electric Co.	354	71-9033	Model: 660 & 660E, Technical	357
71-5957	Model: BMI-1, Dept. of Energy	354	71.0025	Operations, Inc.	
71-5971	Model: GE-200, General Electric Co.	354	71-9035	Model: 680, Technical Operations, Inc.	357
71-5979	Model: 5979, Alpha-Omega Services, Inc.	354	71-9039	Model: 715, Technical Operations, Inc.	357
71-5980	Model: GE-600, General Electric Co.	355	71-9044	Model: GE-1600, General Electric Co.	357
71-5998	Model: GE-400, General Electric Co.	355	71-9049	Model: GE-500, General Electric Co.	357
71-6078	Model: 927 At & C1, Combustion Engineering, Inc.	355	71-9053 71-9070	Model: 683, Technical Operations, Inc. Model: N-55, Dept. of Energy	357 358
71-6144	Model: 6144, Nuclear Engineering Co.	355	71-9080	Model: HN-600, Hittman Nuclear	358
71-6294	Model: UNC-2901, Combustion Engineering, Inc.	355	71-9081	& Development Corp. Model: CNSI-1600, Chem-Nuclear Systems,	358
71-6375	Model: PB-1, Chem-Nuclear Systems, Inc.	355		Inc.	
71-6387	Model: 60, Battelle Memorial Institute	355	71-9094	Model: CNSI-14-195-II, Chem-Nuclear Systems, Inc.	358
71-6400	Model: Super Tiger, Westinghouse Flectric Corp.	356	71-9096	Model: CNSI-21-300, Chem-Nuclear Systems, Inc.	358
	Valley	356	71-9108	Model: AL-33-90, Atcor, Inc.	358
		356	71-9130	Model: NP-50-XXL, Nuclear Packaging, Inc.	358
			71-9132	Model: T-3, Nuclear Packaging, Inc.	358
		356	71-9136	General Electric Co.	358
	tric Co.	356	71-9139	Model: GE-589, General Electric Co.	358

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Acrotest Radiography & Research	50-228	37	Brunswick Steam Electric Plant, Unit 2	50-324	159
Reactor Allens Creek Nuclear Station, Unit 1	50-466	292	Byron Station, Unit 1	50-454	283
			Byron Station, Unit 2	50-455	284
Allens Creek Nuclear Station, Unit 2	50-467	294	Calloway Plant, Unit 1	STN-50-483	297
Arkansas Nuclear One, Unit 1	50-313	131	Calloway Plant, Unit 2	STN-50-486	300
Arkansas Nuclear One, Unit 2	50-368	226	Calvert Cliffs Nuclear Power Plant,	50-317	136
Army Materials Research Reactor	50-47	18	Unit 1		
Duane Arnold Energy Center	50-331	177	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	139
B-SAR-205	STN-50-561	333	Caorso Nuclear Station, Italy	50-378	235
Babcock & Wilcox Co. Critical Facility	50-13	16			336
Babcock & Wilcox Co. Test Reactor	50-99	20	Carroll Facility I	50-599	
Bailly Generating Station	50-367	225	Carroll Facility II	50-600	336
Barnwell Reprocessing Plant	50-332	179	Catawba Nuclear Station, Unit 1	50-413	260
Beaver Valley Power Station, Unit 1	50-334	181	Catawba Nuclear Station, Unit 2	50-414	261
Beaver Valley Power Station, Unit 2	50-412	259	Catholic Univ. of America Research Reactor	50-77	20
Bellefonte Nuclear Plant, Unit 1	50-438	270	Cherokee Nuclear Station, Unit 1	STN-50-491	304
Bellefonte Nuclear Plant, Unit 2	50-439	271	Cherokee Nuclear Station, Unit 2	STN-50-492	30 <i>5</i>
Beznau Nuclear Station, Switzerland	50-273	77	Cherokee Nuclear Station, Unit 3	STN-50-493	305
Big Rock Point Nuclear Power Plant	50-155	22	Clinch River Breeder Reactor	50-537	326
Black Fox Station, Unit I	STN-50-556	332	Clinton Power Station, Unit 1	50-461	290
Black Fox Station, Unit 2	STN-50-557	333	Clinton Power Station, Unit 2	50-462	291
Braidwood Station, Unit 1	50-456	285	Columbia Univ. Research Reactor	50-208	30
Braidwood Station, Unit 2	50-457	287	Comanche Peak Steam Electric Station, Unit 1	50-445	277
Browns Ferry Nuclear Power Station, Unit 1	50-259	55	Comanche Peak Steam Electric Station, Unit 2	50-446	280
Browns Ferry Nuclear Power Station, Unit 2	50-260	58	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	133
Browns Ferry Nuclear Power Station, Unit 3	50-296	112	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	135
Brunswick Steam Electric Plant, Unit 1	50-325	161	<i>.</i> .		

Name	Docket	Page	Name	Docket	Page
Cooper Nuclear Station	50-298	114	General Atomic Co.	50-163	25
Cornell Univ. Research Reactor	50-157	25	General Electric Test Reactor	50-70	19
Cornell Univ. Zero Power Reactor	50-97	20	General Electric Test Reactor	50-754	336
Crystal River Nuclear Plant, Unit 3	50-302	117	General Electric Nuclear Test Reactor	50-73	19
Davis-Besse Nuclear Power Station, Unit 1	50-346	201	Georgia Institute of Technology Research Reactor	50-160	25
Davis-Besse Nuclear Power Station, Unit 2	50-500	312	Georgia Tech Research Reactor	50-276	79
Davis-Besse Nuclear Power Station, Unit 3	50-501	312	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	39
Diablo Canyon Nuclear Power Plant,	50-275	77	Grand Gulf Nuclear Station, Unit 1	50-416	262
Unit 1			Grand Gulf Nuclear Station, Unit 2	50-417	264
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	157	Greene County Nuclear Power Plant	50-549	330
Douglas Point Nuclear Station, Unit 1	50-448	282	Greenwood Energy Center, Unit 2	50-452	283
Douglas Point Nuclear Station, Unit 2	50-449	282	Greenwood Energy Center, Unit 3	50-453	283
Dow Chemical Co.	50-264	63	Haddam Neck Plant	50-213	30
Dresden Nuclear Power Station, Unit 1	50-10	13	Shearon Harris Nuclear Power Plant, Unit 1	50-400	248
Dresden Nuclear Power Station, Unit 2	50-237	37	• • • • • • • • • • • • • • • • • • •	ED 401	250
Dresden Nuclear Power Station, Unit 3	50-249	45	Shearon Harris Nuclear Power Plant, Unit 2	50-401	250
Eric Nuclear Plant, Unit 1	STN-50-580		Shearon Harris Nuclear Power Plant,	50-402	252
Erie Nuclear Plant, Unit 2		335	Unit 3	£0.403	264
·	STN-50-581	335	Shearon Harris Nuclear Power Plant, Unit 4	50-403	254
Joseph M. Farley Nuclear Plant, Unit 1 Joseph M. Farley Nuclear Plant, Unit 2	50-348	205	Hartsville Nuclear Plant, Unit 1	STN-50-518	316
•	50-364	219	Hartsville Nuclear Plant, Unit 2	STN-50-519	317
Enrico Fermi Atomic Power Plant, Unit 2	50-341	196	Hartsville Nuclear Plant, Unit 3	STN-50-520	318
James A. Fitzpatrick Nuclear Power Plant	50-333	179	Hartsville Nuclear Plant, Unit 4	STN-50-521	319
Floating Nuclear Plant	STN-50-437	269	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	152
Florida West Coast Nuclear Group, Inc.	50-152	209	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	221
Forked River Nuclear Station, Unit 1	50-363		Haven Nuclear Plant, Unit 1	STN-50-502	312
Fort Calhoun Station, Unit 1		219	Hope Creek Nuclear Station, Unit 1	50-354	210
Fort St. Vrain Nuclear Generating	50-285	92	Hope Creek Nuclear Station, Unit 2	50-355	211
Station Station	50-267	67	Humboldt Bay Power Plant, Unit 3	50-133	21
Fulton Generating Station, Unit 1	50-463	291	Idaho State Univ. Research Reactor	50-284	92
Fulton Generating Station, Unit 2	50-464	292	Indian Point Station, Unit 1	50-3	12
General Atomic Co.	50-89	20	Indian Point Station, Unit 2	50-247	43

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	94	Montague Nuclear Power Station, Unit 2	59-497	306
Iowa State Univ Research Reactor	50-116	20	Monticello Nuclear Generating Plant	80 D63	61
Jamesport Nuclear Station, Unit 1	STN-50-516	315	National Bureau of Standards Reactor	50-263	26
Jamesport Nuclear Station, Unit 2	STN-50-517	316		50-184	
Kewaunee Nuclear Power Plant	50-305	121	National Naval Medical Center	50-170	26
Ko-Ri, Units 3 & 4, Korea	50-594	335	NEP Nuclear, Unit 1	S IN-50-568	335
La Crosse Boiling Water Reactor	50-409	256	NEP Nuclear, Unit 2	S TN-50-569	335
LaSalle County Station, Unit 1	50-373	232	New Haven, Unit 1	S I N-50-596	336
LaSalle County Station, Unit 2	50-374	233	New Haven, Unit 2	STN-50-597	336
Limerick Generating Station, Unit 1	50-352	206	Nine Mile Point Nuclear Station, Unit 1	50-220	35
Limerick Generating Station, Unit 2	50-353	208	Nine Mile Point Nuclear Station,	50 410	258
Lockheed Aircraft Corp.	50-236	37	Unit 2	eo 420	1.00
Maine Yankee Atomic Power Plant	50-309	125	North Anna Power Station, Unit I	50-338	188
Manhattan College Research Reactor	50-199	27	North Anna Power Station, Unit 2	50-339	191
Marble Hill Nuclear Station, Unit 1	STN-50-546	327	North Anna Power Station, Unit 3	50-404	255
Marble Hill Nuclear Station, Unit 2	STN-50-547	328	North Anna Power Station, Unit 4	50 405	256
Massachusetts Institute of Technology Research Reactor	50-20	16	North Carolina State Univ. PULSTAR Reactor	50-297	114
William B. McGuire Nuclear Station, Unit 1	50-369	228	North Carolina State Univ. Research Reactor	50-111	20
William B. McGuire Nuclear Station,	re Nuclear Station, 50-370 230	230	North Coast Nuclear Plant, Puerto Rico	50-376	235
Unit 2			Nuclear Examination Reactor	50-375	235
McMaster Univ. Research Reactor	50-67	19	Oconee Nuclear Station, Unit 1	50-269	68
Memphis State Univ. Research Reactor	50-538	327	Oconee Nuclear Station, Unit 2	50-270	70
Michigan State Univ. Research Reactor	50-294	109	Oconce Nuclear Station, Unit 3	50-287	97
Midland Plant, Unit 1	50-329	172	Ohio State Univ. Research Reactor	50-150	22
Midland Plant, Unit 2	50-330	174	Oregon State Univ	50-106	20
Midwest Fuel Recovery Plant	50-268	68	Oregon State Univ. Research Reactor	50-243	39
Millstone Nuclear Power Station,	50-245	41	Oyster Creek Nuclear Power Plant	50-219	32
Unit 1	60.226	186	Palisades Nuclear Plant	50-255	52
Millstone Nuclear Power Station, Unit 2	50-336	180	Palo Verde Nuclear Station, Unit 1	STN-50-528	321
Millstone Nuclear Power Station, Unit 3	50-423	267	Palo Verde Nuclear Station, Unit 2	S FN-50-529	323
	50 406	306	Palo Verde Nuclear Station, Unit 3	STN-50-530	325
Montague Nuclear Power Station, Unit 1	50-496		Palo Verde Nuclear Station, Unit 4	STN-50-592	335

Name	Docket	Page	Name	Docket	Page
Palo Verde Nuclear Station, Unit 5	STN-50-593	335	RPI Critical Experiment	50-225	36
Peach Bottom Atomic Power Station, Unit 1	50-171	26	Salem Nuclear Generating Station, Unit 1	50-272	75
Peach Bottom Atomic Power Station, Unit 2	50-277	80	Salem Nuclear Generating Station, Unit 2	50-311	127
Peach Bottom Atomic Power Station, Unit 3	50-278	82	San Onofre Nuclear Station, Unit 1	50-206	27
Pebble Springs Nuclear Plant, Unit 1	50-514	314	San Onofre Nuclear Station, Unit 2	50-361	215
Pebble Springs Nuclear Plant, Unit 2	50-515	315	San Onofre Nuclear Station, Unit 3	50-362	217
Pennsylvania State Univ. Research	50-5	13	Seabrook Nuclear Station, Unit 1	50-340	196
Reactor			Seabrook Nuclear Station, Unit 1	50-443	275
Perkins Nuclear Station, Unit 1	STN-50-488	302	Seabrook Nuclear Station, Unit 2	50-444	276
Perkins Nuclear Station, Unit 2	STN-50-489	303	Sequoyah Nuclear Plant, Unit 1	50-327	163
Perkins Nuclear Station, Unit 3	STN-50-490	304	Sequoyah Nuclear Plant, Unit 2	50-328	169
Perry Nuclear Power Plant, Unit 1	50-440	272	Shoreham Nuclear Power Station	50-322	156
Perry Nuclear Power Plant, Unit 2	50-441	273	Skagit Nuclear Power Project, Unit 1	STN-50-522	320
Phipps Bend Nuclear Plant, Unit 1	STN-50-553	330	Skagit Nuclear Power Project, Unit 2	STN-50-523	321
Phipps Bend Nuclear Plant, Unit 2	STN-50-554	331	South Texas Project, Unit 1	STN-50-498	306
Pilgrim Nuclear Power Station, Unit 1	50-293	107	South Texas Project, Unit 2	STN-50-499	309
Pilgrim Nuclear Power Station, Unit 2	50-471	294	Space Radiation Research Reactor	50-187	26
Point Beach Nuclear Plant, Unit 1	50-266	65	State Univ. of New York Research	50-57	18
Point Beach Nuclear Plant, Unit 2	50-301	115	Reactor		
Prairie Island Nuclear Station, Unit 1	50-282	90	Sterling Power Project, Nuclear, Unit 1	STN-50-485	300
Prairie Island Nuclear Station, Unit 2	50-306	123	St. Lucie Plant, Unit 1	50-335	183
Purdue Univ. Research Reactor	50-182	26	St. Lucie Plant, Unit 2	50-389	241
Quad-Cities Station, Unit 1	50-254	50	Virgil C. Summer Nuclear Station, Unit 1	50-395	244
Quad-Cities Station, Unit 2	50-265	63		£0 £05	226
Rancho Seco Nuclear Generating Station	50-312	129	Sundesert, Unit 1 Sundesert, Unit 2	50-582 50-583	335 335
Reed College Research Reactor	50-288	99	Surry Power Station, Unit 1	50-280	85
Rhode Island & Providence	50-193	26	Surry Power Station, Unit 2	50-281	88
Plantations AEC River Bend Station, Unit 1	50-458	288	Susquehanna Steam Electric Station, Unit 1	50-387	236
River Bend Station, Unit 2	50-459	289	Susquehanna Steam Electric Station,	50-388	239
H.B. Robinson Plant, Unit 2	50-261	60	Unit 2		/

Name	Docket	Page	Name	Docket	Page
Texas A&M Univ. Research Reactor	50-59	19	U.S Geological Survey Research Reactor	50-274	77
Texas A&M Univ Research Reactor	50-128	21	Vermont Yankee Nuclear Power Station	50-271	73
Three Mile Island Nuclear Station, Unit I	50-289	99	Virginia Polytechnic Institute Training	50-124	21
Three Mile Island Nuclear Station, Unit 2	50-320	141	Reactor	50 424	267
Trojan Nuclear Plant	50-344	197	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	
Turkey Point Plant, Unit 3	50-250	47	Alvin W Vogtle Nuclear Plant, Unit 2	50-425	268
Turkey Point Plant, Unit 4	50-251	49	Walter Reed Research Reactor	50-135	22
Tuskegee Institute Research Reactor	50-406	256	Washington State Univ. Research Reactor	50-27	17
Tyrone Energy Park, Unit 1	STN-50-484	282	Waterford Generating Station, Unit 3	50-382	235
UCLA Training Reactor	50-142	22	Watts Bar Nuclear Plant, Unit 1	50-390	242
Union Carbide Research Reactor	50-54	18	Watts Bar Nuclear Plant, Unit 2	50-391	243
Univ. of California at Irvine	50-326	163	Westinghouse Critical Experiment	50-87	20
Research Reactor			West Valley Reprocessing Plant	50-201	27
Univ of California at Santa Barbara Research Reactor	50-433	269	West Virginia Univ. Research Reactor	50-129	21
Univ. of California Research Reactor	50-224	36	Wolf Creek Generating Station	ST N-50-482	294
Univ. of Florida Training Reactor	50-83	20	Worcester Polytechnic Institute Research Reactor	50-134	22
Univ. of Illinois LOPRA Research Reactor	50-356	213	WPPSS Nuclear Project, Unit 1	50-460	289
Univ. of Illinois Research Reactor	50-151	22	WPPSS Nuclear Project, Unit 2	50-397	246
Univ. of Lowell Research Reactor	50-223	36	WPPSS Nuclear Project, Unit 3	STN-50-508	312
Univ. of Maryland Research Reactor	50-166	25	WPPSS Nuclear Project, Unit 4	50-513	313
Univ. of Michigan Research Reactor	50-2	12	WPPSS Nuclear Project, Unit 5	STN-50-509	313
Univ. of Missouri Research Reactor	50-123	20	Yankee-Rowe Nuclear Power Station	50-29	17
		26	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	333
Univ. of Missouri Research Reactor	50-186		·		334
Univ. of Oklahoma Research Reactor	50-112	20	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	
Univ. of Virginia Cavalier Reactor	50-396	246	William H. Zimmer Nuclear Station, Unit 1	50-358	213
Univ. of Virginia Research Reactor	50-62	19	Zion Nuclear Power Station, Unit I	50-295	109
Univ. of Washington Research Reactor	50-139	22	Zion Nuclear Power Station, Unit 2	50-304	119
Univ. of Wisconsin Research Reactor	50-156	25			

	•	
		,
		1

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-010 BEATTY, NV

- 8006(10736 Forwards Weste Packaging Insp Rept 80-20 on 800128-0201 of activities under License 19-17039-01 No noncompliance noted SMITH G H Region i. Philadelphia. Office of the Director 80/04/24 ip
- --B006110739 Waste Puckaging Insp Rept 80-20 on 800128-0201 No noncompliance noted Major areas inspected waste shipments & packages, vehicle placarding, packaging conditions & labels BDDK.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch BROWNE.W O Advanced Fuel & Spent Fuel Licensing Branch THOMAS.R D Region 5. San Francisco. Office of the Director 60/03/31 10pp
- 8007020202 Requests (posideration of having Atomic Energy Council of Taiwan visit facilities on 800728-30 (at Richland) & 800731-0801 (at Beatty) Council interested in observing waste mpt activities LAFLEUR.J D Assistant Director for International Cooperation 80/05/13 4pp
- 8007140453 Forwards Waste Packaging Insp Repts 15000027/80-31, 15000027/80-3B & 15000027/80-47 on 800319, 21 & 0409 SMITH. G H Region i. Philadelphia, Fuel Facility & Materials Safety Branch 80/05/21 2pp
- --8007140657 Waste Packaging Insp Rept 15000027/80-31 on 800321
 Noncompliance noted bottom of wooden box for solid scrap
 containing U-238 was pulled away, revealing contents
 BODK.H E Region 1, Philadelphia, Fuel Facility & Materials Safety
 Branch THOMAS.R D. RLIDLINGER, B.A. Region 1, Philadelphia,
 Office of the Director 80/04/13 3pp
- --8007140663 Waste Packaging Insp Rept 19000027/80-38 on 800321
 Noncompliance noted side of wooden box containing solid
 scrap contaminated w/V-238 was pulling away from rest of
 container exposing plastic bag inside box
 BODK.H E. Region 1. Philadelphia, Fuel facility & Materials Safety
 Oranch THOMAS.R D. REDILINGE, B A. Region 1. Philadelphia,
 Office of the Director 80/04/15 Spp
- --80071406/0 Waste Packaging Insp Rept 15000027/80-47 on 800409
 Noncompliance noted Drum 40.containing depleted U.found
 leaking & transport vehicle not properly placarded as
 radioactive shipment
 BODK, H C Region 1. Philadolphia, Fuel Facility & Materials Bafety
 Branch THOMAS.R D . ZURAKUMEKI, P R Region 1. Philadelphia.
 Office of the Director 80/04/30 12pp
- B007:70545 Forwards Waste Packaging Insp Rept 18000027/80-46 on 8000229 & notice of violation DAVIS.A II Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/06/10 2pp
- --8007170550 Notice of violation from inap on 800227 * Region 3, Chicago, Office of the Director 80/04/28 Ip
- --B007170556 Waste Packaging Insp Rept 15000027/80-46 on 800229
 Noncompliance noted no placerd on shipment boxes
 DECKER.T , FHOMAS.R D Region 5, San Francisco, Office of the
 Director BORK.H E Region 5, San Francisco, Fuel Facility &
 Materials Safaty Branch BO/04/20 App
- DOCKET 27-039 SHEFF TELD, IL., NUCLEAR ENGINEFRING CO
- 8007070030 Notifies licensee that independent contractor will visit site to obtain info relative to facility MARTIN, J B Division of Waste Management 80/06/18 lp

- 8007070012 Transcript of 800626 prehearing conference in Peoria IL fp i13-172 Morning session * Atomic Safety and Licensing Board Panel 80/06/26 60pp
- 8007130058 Submits issues to be litigated in waste disposal site proceeding per ASLB 800626 prehearing conference directive Guestions NRC 790320 order re absence of jurisdiction over entity no lunger in possession of radioactive matl CENNER. F B Conner. Moore & Corber 80/07/08 2pp
- 8007230527 Submissions of issues to be litigated in proceeding, in response to ASLB 800626 order Questions illegality of license termination prior to determination of necessity of site maint for health & safety Certificate of Byc encl SCOTT, N. J. SEKULER. S. N. Illinois, State of 80/07/16 Spp
- B007220149 Bubmits issues to be litigated in low level radwaste disposal site proceeding in response to ASLB B00626 directive Urges adoption of liability issue along w/technical issues H/site stabilization & closure conditions LESGY.R P Antitrust Division B0/07/17 App
- 8007290442 Brief urging dismissal of appeal due to Chicago Section of ANS untimely exceptions to ASLB 790503 order Appeal does not assert discernible injury No EIB required since order does not affect environ W/appearance & Certificates of Svc SCOTT, W J . SEKULER, S N . MURRAY, M J Illinois, State of 80/07/20 RODD
- 8007310133 Corrected Page 8 to State of IL 800721 brief Includes addl wording corrections SEKULER, S N Illinois, State of 80/07/25 2pp

DOCKET 27-047 BARNWELL, SC . CHEM-NUCLEAR SYSTEMS

- 8007010285 Forwards IE Waste Packaging Insp Rept 15000039/80-03 on 800227-29 No noncompliance noted 8MITH:0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/04/24 Spp
- --B007010291 IE Waste Packaging Insp Rept 15000039/80-03 on 800227-29 No noncompliance noted Major areas inspected skipping paper requirements.DDT placarding requirements.radiation levels, removable contemination & external package features PEERY.W W. POTTER, U.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 80/03/18, 7pp
- B007010277 Forwards IE Waste Packaging Insp Rept 15000039/80-03 on B00227-27 No noncompliance noted SMITH, G H Region t, Philadelphia, Fuel Facility & Materials Safety Branch. B0/04/24 ip
- --8007010306 IE Waste Packaging Insp Rept 15000039/80-03 on 800027-29 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements. radiation levels, removable contamination & external package features PEERY, W W , POTTER, J P Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/18 7pp
- 8007020189 Requests consideration of having Atomic Energy Council of Talwan visit facility on 800901-03 Council interested in observing waste mgt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR.J D Assistant Director for International Cooperation 80/05/13 3pp
- B007020760 Forwards B00827-28 trip rept Chem-Nuclear brisfed State of BC & NRC personnel re preliminary site stabilization & closure plan Current conditions & practices at site were observed BRACDNETTE, N.S. Low Level Waste Licensing Branch B0/06/20 4pp.

- 7290395 Forwards Waste Packaging Insp Rept 15000039/80-21 on 800428 0501
 'REILLY, J.P. Region 2. Atlanta. Office of the Director 60/06/20
- 007290401 Waste Packaging Insp Rept 15000039/80-21 on 800428 & 0501 Noncompliance noted radiation levels on surface of closed, exclusive use vehicle in excess of regulatory limits TROUP, OL . PEERLY, W M. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/20 App
- 7290406 Forwards Waste Packaging Insp Rept 15000039/80~08 on 00803-06 No noncompliance noted TOHR.J P Region 2. Atlanta. Fuel Facility & Materials Safety ranch 80/08/20 3pp
- 007290410 Waste Packaging Insp Rept 150000039/80-08 on 800603-06 No noncompliance noted Major areas inspected compliance w/DOT & NRC regulations IROUP, 0 L. MACARTHUR, T C Region 2, Atlanta, Fuel Facility & Materials Sefety Branch 80/06/20 6pp
- 7300976 Forwards IE Insp Repts 50-321/80-14 & 50-364/80-14 on 00319,0429 & 30 Enforcement action discussed in NRC 800619 to
- TREILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/23
- 007300580 iE Insp Repts 50-321/80-14 & 50-366/80-14 on 800319.0429 & 30 Noncompliance noted radiation levels an vehicle cab in excess of regulatory limits
 STOHR,J P , WOODRUFF,R L Region 2. Atlanta, Fuel Facility & Haberials Safety Branch LACEY,L R Region 2. Atlanta, Office of the Director 80/06/19 Spp
- 7010482 Affidavit re support of request that Chem-Nuclear Sys.Incocument 6D-DP=005, "Process Control Program for CNSI Mobile Dildification Units Using Dow Process," be withheld ref 10CFR2 790)
 EYNOLDS.L E Chem-Nuclear Systems, Inc. 80/06/25 3pp
- HET 27-04B RICHLAND, WA . NUCLEAR ENGINEERING CD
- 7100002 Forwards Waste Packaging Insp Rept 15000046/80-04 on 20107-18 No noncompliance noted 41TH, G H Region 1. Philadelphia. Fuel Facility & Materials Safety ranch. B0/03/24 2pp
- 007100003 Waste Packaging Insp Rept 15000046/B0-04 on B00107-18 No noncompliance noted Major areas inspected waste shipments for compliance w/D07 & NRC regulations including vehicle placarding, package marking & condition of packages THOMAS,R D. PECK.C C Region i. Philadelphia, Office of the Director B00K HE Region 1. Philadelphia, Fuel Facility & Materials Safety Branch B0/03/25 7pp
- 7020202 Requests consideration of having Atomic Energy Council of siwan visit facilities on 800728-30 (at Richland) & 800731-01 (at Beatty) Council interested in observing waste tactivities

 **RLEUR, J D Assistant Director for International Cooperation 2/05/13 400
- 7140604 Forwards IE Insp Repts 27-004B/80-01 & 1500046/79-36 on 10403 No noncompliance noted ITH.G H Region 1. Philadelphia, Fuel Facility & Materials Safety ranch 80/05/21 2pp
- 00714060B IE Insp Rept 27-0048/80-01 on 800403 No noncompliance noted Major areas inspected transportation program ROTH.J Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80704/25 5pp
- 007140609 IE Insp Rept 1500046/79-36 on 800403 No noncompliance noted Major areas inspected Trailer 68-1832 800K/H E Region 1. Philadelphia. Fuel Facility & Materials Gafety Branch 80/02/27 7pp
- /160700 Forwards Waste Packaging lnsp Rept 15000046/80-60 on 800515 notice of violation WIS.A B. Region 3. Chicago, Fuel Facility & Materials Safety ranch 80/06/27 2pp
- 107160710 Notice of violation from insp on B00515
 * Region 5. San Francisco. Office of the Director 80/06/10 in

- --B007160721 Waste Packaging Insp Rept 15000046/B0-06 on B00515 Noncompliance noted drum containing radwaste found to have gash.exposing cardboard of similar solid math BDDK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Dranch THOMAS.R D Region 5, San Francisco, Office of the Director B0/06/10 Spp
- 8007300574 Forwards Waste Parkeging Insp Rept 15000046/80-07 on 800131 Notice of violation forwarded under separate cover KEPPLER.J O Region 3. Chicago, Office of the Director 80/06/27
- --8007300565 Waste Packaging Insp Rept 15000046/80-07 on 800131 Nancompliance noted radiation levels on surface of trailer in excess of regulatory limits BOOK.H E Region 5. San Francisco, Fuel Facility & Materials Safety Branch CAIN.C L Region 4. Dallas, Office of the Director 80/02/27 /pp
- 80073i0335 Forwards Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/06/30 3pp
- --8007310339 Waste Fackaging Insp Rept 15000046/80-32 on 800222 & 26 Noncompliance w/DOT regulations noted max dose rate on surface of transport trailor was 220 millirem/h O'REILLY,L A Region 5, San Francisco, Office of the Director THOMAG.R D. BOOK,H E Region 5, San Francisco, Fuel Facility & Haterials Safety Branch BO/04/02 12pp
- B007280271 Forwards draft Waste Parkage Insp Repts 15000046/80-76 & 18000046/80-77 on 800623-27 & corresponding NRC-766 forms AVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/07/14 9pp
- 8007220508 Responds to 800626 ltr re possible noncompliance identified during low level radwaste disposal site insp Radwaste container punctured during transport Radioactive mail not released Inspectors briefed re tight container requirements BAER.F. 8 Nuclear Engineering Co., Inc., (subs of Teledyne, Inc.) 80/97/18 ip
- BOO7270350 PNO-V-BD-060 on BOO723. Region 5 ofc was notified that Con Ed low level radwaste shipment was not properly packaged Based upon noncompliance, state of MA has cancelled burial permit banned util from use of site THOMAS.R D Region 3. San Francisco. Office of the Director BO/07/23 ip

DOMESTIC LICENSING OF SOURCE MATERIAL

- DOCKET 40-0215 S F APPLIANCE, LTD
- 8007080096 Responds to IE Bulletin 79-19 re shipment of low level radwaste Encl lists 800208 shipments of 29 55-gallon & 44 55-gallon drums of low level mantle radwaste Further shipments of waste will be placed in sealed steel drums JONESON.B J S F Appliance, Ltd 80/06/16 5pp
- DOCKET 40-0299 UNION CARBIDE CORP
- 8007310494 "Subsurface Investigation Clay Liner Mati East Gas Hills. WY " RATHBUN.D J Inberg-Miller Engineering Co 80/03/10 85pp
- 8007290221 "Subsurface Investigation Clay Liner Exploration East Hills. WY." for Union Carbide Corp CORCORAN.T Inberg-Miller Engineering Co 80/04/17 42pp
- 8007170571 Forwards design memo & drawings for add1 spray evaporation sys.in compliance w/Consistion 9 of Amend 13 to License SUA-648 Brawings available in Central Files only WONG.T Union Carbide Corp 80/06/04 5pp
- 80073002/9 Forwards "Field Compaction Test Results," 800609-16 RATHBUN,D J Miller Technical Services 80/06/18 ip
- --8007300285 "Field Compaction Fest Results," 800609-16
 * Miller Technical Services 80/06/18 23pp
- 8007220307 Describes field wish of proposed evaporation pend at Fast Qas Hills site Areas inspected include entire crost of proposed dam toe of existing overburden specified on which pend is being built, const & RC program HANSON, W W Barr Engineering Co 80/06/25 2pp

- B007220257 FDIA request for three categories of info re NRC source matl license requirements for Union Carbide. Gas Hills. WY U mill facility SALZBERG. H Black Hills Alliance 80/06/30 ip
- B0073002BB Forwards "Field Compaction Test Results," 800617-26 RATHBUN,D J Miller Technical Services 80/06/30 ip
- --8007300287 "Field Compaction Test Results." 800617-26 * Miller Technical Services 80/06/30 19pp
- 8007080219 Bubmits analytical results from samples taken from two releases in restricted areas, to be included as addit data for 800528 ltr Union Carbide Corp 80/07/01 1p WANG, T
- 8007140371 Forwards A12-B0-23, "Soil Sample Location Map," as required by Condition 7 of Bource Matl License SUA-648, Amend 15 Map shows location of areas affected by seepage from Sump C Map available in Central Files only WDNG, T. Union Carbide Corp 80/07/07 ip
- --8007140380 "Soil Sample Location Map," for East Gas Hills area, Natrona County, NY JAMES, H E United Nuclear Corp 80/07/03 1p
- 8007220263 Partial response to FOIA request for three categories of NOVEWERS PARTIAL response to rula request for three categor: info re NRC source math license requirements for Union Carbide, Cas Hills, HY U mill facility Forwards documents listed in App A Search for other documents in progress FELTON, J M Division of Rules and Records BO/07/15 2pp.
- --B00722026B Confirms telcon that NRC position re regulation of in situ U extraction in MY remains as stated in JF Ahearne 800422 ltr NRC is prepared to accept MY in situ groundwater protection requirements in NEPA analyses of associated Accilities SHAPAR.H X Office of the Executive Legal Director 80/07/07
- ---BOOTR20273 Discusses Governor's 800403 visit to discuss regulation of U milling & mill tailings in WY NRC will not act on license renswal until WY Dept of Environ Quality environ impacts evaluation results are received & reviewed AHEARNE.J F. Commission 80/04/22 Rpp

DOCKET 40-1162 WESTERN NUCLEAR, INC

- 8007070099 Discusses 791003 onsite visit to Split Rock mill & mine Photographs encl PETERBON.R Western Nuclear, Inc (subs of Phelps Dodge Corp) 79/10/03 5pp
- 8006240081 Forwards tabulation of water level readings from piezometers in Sections A-A & B-B for 1979 to present Also forwards Brawing RM78-678-EE showing plots of piezometer water level slevations vs time from Jul 1977 to present BAGDEN. O Western Nuclear. Inc. 80/05/28 2pp
- B007010241 Forwards, for review & comment, figure showing proposed location of groundwater monitoring wells Figure is mod to Figure 4 3 of FCB Requests comments by 800411 BCARANG, R A Uranium Recovery Licensing Branch B0/08/30 3pp
- BOO7010559 Forwards, for review & comment, figure showing proposed location of groundwater monitoring wells Figure is mod to Figure 6 3 of FEB Requests comments by BO0411
 BCARANO, R A. Uranium Recovery Licensing Branch 80/05/30 3
- ---8007010562 Responds to request for review of FEB In order to minimize risk of addl contamination caused by preferential movement of seepage along unknown high-permeability pathway intensive monitoring network showed be installed WILLIAMS,R E Affiliation Unknown 80/04/03 5pp
- 8007010567 Discusses review of const rept submitted 600408 Requests add1 info re survey results, settlement, piscometer & pond elevation data by 800613 Plan view of site showing final disposal locations for debris required LINEHAN, J J Uranium Recovery Licensing Branch 80/06/02 ip
- 8007100447 Summary of 800508 meeting in Sethesda, MD re continuing mafety review of series of raises to tailings dam GARGIA.P Uranium Recovery Licensing Branch 80/06/02 2pp

- 8007020446 Advises of need to increase amount of Williams-Robinette contract due to extensive ongoing work Prompt attention will be appreciated because of immediate nature of matter SCARAND RA Uranium Recovery Licensing Branch B0/06/04
- 8007240021 "Magnetic Survey Western Nuclear Split Rock Tailings Impoundment, Joffrey City, WY. 800605 " * Williams-Robinotte & Associates, Inc. 80/06/12 17pp
- 8007100088 Summary of B00522 meeting w/Western Nuclear & D'Appolonia Consulting Engineers in Bilver Spring.MD re possible existence of debris layer underlying teilings embankment & removal of debris from dump area GARCIA:P J Uranium Recovery Licensing Branch BO/06/16 Jpp
- --B007100091 Summary of B00522 meeting w/Western Nuclear & D'Appolonia Consulting Engineers in Silver Spring.MD re possible existence of debris layer underlying tailings embankment & removal of debris from Sump area LINEHAN, J J Uranium Recovery Licensing Branch BOODEN, 0 Hestern Nuclear, Inc. (subs. of Pholps Dodge Corp.) 80/05/22
- 8007290262 Forwards rept describing magnetometer survey conducted by NRC consultants at Western Nuclear. Inc Split Rock tailings dam on 800605 Wo enci QARCIA, P. J. Uranium Recovery Licensing Branch 80/06/20 1m
- BOO7220520 Amend to potition to intervene Paragraphs 6 & 27 re utilization of Sweetwater River waters for educational & recreational purposes & inaccuracy of FEB BOOKE, B L. Booke, B L. BOOKE, B L. Booke, B L. BOOKE, B L.
- B007290600 Bubmits comments ro monitoring well locations & design per NRC 800604 request geologic description of Sweetwater River Valley by RE Williams dtd 800430 & NRC 800530 ltrs provide considerable impetus & consistency w/previous comments GIEDT.J R Environmental Protection Agency 80/06/25 2pp
- 8007220314 Forwards "Rept on Reinterpretation of Ground Magnetometer Survey Data Western Nuclear Split Rock Tailings Impoundment Jeffrey City, MY" BOODEN.9 Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.) 8000EN.G Wes
- ---8007220317 "Rept on Reinterpretation of Ground Magnetometer Survey Data Western Nuclear Split Ruck Tailings Impoundment Jaffroy City.HY " * Allan Spector & Associates.Ltd J231 80/06/30 10pp
- B007300358 Order directing appointment of ABLB to rule on WY Outdoor Council intervention & appointment of ABLAB to exercise Commission authority & functions CHILK:B J Office of the Secretary of the Commission B0/07/28 200
- DOCKET 40-1341 EDGEMONT URANIUM MINE, TVA & MINES DEVELOPMENT, INC
- B007070042 Forwards Revision 4 to decommissioning plan environ rept MILLB.L M Tennessee Valley Authority 80/06/13 5pp
- ---B007070045 Revision 4 to decommissioning plan environ rept * Tempessee Valley Authority B0/06/30 13ipp
- 8007240099 Amend 3 to Source Matl License SUA-816, changing Condition 16 allowing receipt & storage of U mill tailings & mine waste rock from offsite locations BCARANO, R A Uranium Recovery Licensing Brench 80/06/04 lp
- 8007280585 Forwards affidavit certifying that on 800616 correspondence re Edgemont U mill decommissioning plan environ rept was served on individuals identified in attached list MILLS:L M Tennessee Valley Authority 80/06/23 5pp
- 8007210150 Expresses concern re noncompliance w/dose stds for local residents noted in TVA 800613 ltr Objects to TVA request for variance from stds Midwest Environmental Protection Association 60/06/27
- 8007230094 Recommends radiological survey program for U mill tailing activities Grab working level measurements, gamma radiation measurements, radon propeny integrating sampling unit & engineering assessment should be implemented EADIE.0 0 Uranium Recovery Licensing Branch 80/07/07 Spp

KET 40-1852 FISHER SCIENTIFIC CO

17290402 IE Insp Findings & Lirensee Ack dtd 800529 of Licenses 19-10211-01 & SMB-0201 Insp Findings no noncompliance noted BYEARNS, C F Region 1, Philadelphia, Office of the Director 0/05/29 1p

KET 40-2061 WEST CHICAGO FACILITY, KERR-MUGEE CORP

)7110025 Forwards application for amend of License STA-583 HELLEY,W J. Kerr-McGee Corp. B0/05/28 lp

OO7110027 Application for amend of License STA-593 authorizing installation of incinerator to reduce vol of combustible waste at facility incinerator will be equipped w/NRC-approved effluent cleaning equipment
* Korr-McGeo Corp 80/05/28 lipp

7210100 Notifies of new modiling address for West Chicago facility at 90 Factory Street Nest Chicago II. 40105 ENNY, I L. Kerr-HcGee Chemical Corp. (subs of Kerr-HcGee Corp.) 0/04/11 . 1p.

7210480 Summary of 800605 meeting w/Kerr-McGee re decommissioning outractor performance
IXON-W A Uranium Fuel Licensing Branch 80/07/11 Opp

731027) Summary of 800610 meeting w/vendor in Chicago. IL re waste isposel & site decommissioning IXON.W A Uranium Fuel ticensing Branch B0/0//15 App

ET 40-2297 PATHFINDER MINES CORP

7010443 Notifies that mods to leach circuit planned Feed will be langed creating two circuits in parallel each containing a tanks in series Flow rate will remain unchanged No ignificant change to processing procedure represented JGENT, E.L. Pathfinder Mines Corp. 80/06/25 1p

230131 Discusses Amend B to License SUA-672 which would permit BNWL obtain small quantity of tailings solution from mine site support of study re deterioration of clays due to acid tack Recommends approval of amend LLEN.D M . LINEMAN.J J Uranium Recovery Licensing Branch

230171 Requests that IC conduct const insps of addition to Tailings bankment 4 Const authorized by Amends 5 & 7 to License A-672 Also requests notification of dates on which insp 11 be performed stability roview ARANO.R A Uranium Recovery Licensing Branch 80/06/24 4pp

2:0163 Ack receipt of Permit to Construct BO-13R for addition to ilings Reservoir 4 Owner has removed Chen & Associates om project
MME.K. E. Chen & Associates, Inc. BO/06/27 1p

CT 40-2561 ZIRCUA PRODUCTS, CORNING GLASS WORKS

200343 Responds to IE Bulletin 79-19, "Packaging of Low Level dwaste for Transport & Burkel " Facility is in process of ing out of theria business No matl sent for burial since ne 1971 . CHEBMO.C M Corning Glass Works, Zircoa Products Div B0/07/15

T 40-2674 NOTRE DAME, UNIV DE

010047 Ack receipt of 800028 ltr informing NRC of steps taken to rect noncompliance identified in 800013 ltr Discusses consecutions of noncompliance Item 10 Six-munth look test required Supporting documentation encl
PLER.J 6 Region 3. Chicago, Office of the Director 80/06/09

07010Q60 Requests that provision for possession of Pu-benyllium be removed from License SNM-198 Also requests designation of TU dirent as course instructor & only person responsible for landling leak testing AY.N R Notre Dame. Univ of 61/12/21 ip

- --8007010067 Requests changes in provisions of Liconse SUD-197 Authorized location of use should be Mechanical Engineering Dept lab on Old Juniper Road Radioactive math planned for use in graphite moderated subcritical assembly GAY,N R Notre Dame, Univ of 61/12/21 ip
- --8007010077 Forwards response to NRC 800513 ltr re noncompliance identified in 800513 ltr Corpertive actions personal authorization of tritium for investigator increased to 30 mCi on 770314 Internal correspondence encl MADON I J Notre Dame. Univ of 80/05/29 23pp
- --B007010085 Application for amend to Item 14 of License 13-01983-08, deleting statements, procedures & representations made in previously submitted documents Internal correspondence encl MADN.T J Notre Dame: Univ of 80/05/28 Spp
- --8007030091 Application for renewal of expired Source Matl License CBA-4087, authorizing possession of 1,900 kg natural U metal NEHMAN.M K Notre Dame, Univ of 41/04/10 3pp
- ---8007010097 Requests mod of License Condition 14 permitting film badge of course instructor to provide documented record of possible exposure LUCEY.J W Notre Dame, Univ of 80/03/20 Spp
- B007210550 Ack receipt of B00623 ltr informing NRC of steps taken to correct violations identified in NRC B00609 ltr
 KEPPLER.J C Region 3, Chicago, Office of the Director B0/07/10
- --8007210358 Responds to NRC 800607 ltr re violation noted in IE Insp of License SUD-197 Corrective actions responsible investigator in charge of source matl advised matl must be wipe-tested before use MASON.T J Notre Dame. Univ of 80/04/23 2pp
- ---B007210569 Requests amend to License SUD-197 to delete six-month leak testing requirement MASON.T J Notre Dame, Univ of 60/06/23 ip

DOCKET 40-2940 NL INDUSTRIES, INC.

- 8007140653 Forwards Waste Packaging Insp Repts 18000027/80-31, 15000027/80-38 & 15000027/80-47 on 800319.21 & 0409 SMITH,0 H Region I, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/21 2pp
- --8007140657 Waste Packaging Insp Rept 15000027/80-31 on 800321
 Noncompliance noted bottom of wooden box for solid scrap
 containing U-238 was pulled away, revealing contents
 BDOK, H E Region 1, Philadelphia, Fuel Facility & Materials Safety
 Branch THOMABR D , REIDLINGER, B A Region 1, Philadelphia,
 Office of the Director 80/04/15 3pp
- ~~8007149663 Waste Packaging Insp Rept 15000027/80~38 on 800321
 Noncompliance noted side of wooden box containing solid
 screp containated w/V-238 was pulling away from rest of
 container expasing plastic bag inside box
 BODK, H E Region 1. Philadelphia, Fuel Facility & Materials Safety
 Branch THOMAS:R D. REIDLINGER, B. A. Region 1. Philadelphia,
 Office of the Director 80/04/15 3pp
- ~~B007140670 Waste Packaging Insp Rept 15000027/B0-47 on B00409
 Noncompliance noted Drum 40.containing depleted U.found
 leaking & transport vehicle not properly placarded as
 radioactive shipment
 BOOK,H E Region 1. Philadelphia, Fuel Facility & Materials Safety
 Branch THOMAS,R D. ZURAKOMSKI.P R Region 1. Philadelphia,
 Office of the Director 80/04/30 12pp

DOCKET 40-9392 ALLIED CHEMICAL CORP

8007170613 Forwards IE Circular 80-14. "Radioactive Contamination of Flant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/06/24

DOCKET 40-9459 ATLAS MINERALS

8007150076 Summary of 800319 meeting w/Atlas Minerals in Bilver Spring. MD re final riprap design & installation prior to mill decommissioning GARCIA.P J Uranium Recovery Licensing Branch 80/04/25 3pp B007220291 Confirms recent telcons re various licensing conditions required prior to decommissioning facility Licensee proceeding w/add1 tailing disposal alternative studies Agreement needed on raising tailings structure BWANBY, G T Atlas Minerals 80/06/26 1p

DOCKET 40-4337 MARQUETTE UNIV

- 8007250006 Ack receipt of 800606 ltr informing NRC steps taken to correct violations noted in IE insp of Licenses 48-02931-06, 48-02931-10 & 800-0231 on 800422 & 0508
 KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/24
- --8007250012 Responds to NRC 800921 ltr re violations noted in IE insp of Licenses 48-02931-06, 48-02931-10 & SUD-0231 on 800423 & 0508 Corrective actions survey meters calibr biannually w/ std provided w/instrument PIACSEK, B E . MINER, L E Marquette Univ 80/06/06 27pp
- 8007240249 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE insp of Liconses 48-02931-06, 48-02931-10 & SUD-231 KEPPLER. J Q Region 3. Chicago, Office of the Director 80/07/16
- --8007240258 Responds to NRC 800624 ltr re violations noted in IE insp of Licenses 48-02931-06 & 48-02931-10 & SUD-231 Provides add1 info re administrative authority licensing, recordseping & purchases PIACSEK.B E , MINER, L E Marquette Univ 80/07/09 3pp

DOCKET 40-4492 FEDERAL AMERICAN PARTNERS (MINING)

- B007020013 Amends 791114 request for permission to construct & operate major mod & expansion of 950 dry ton per day U ore processing facility Reduces request from 2,950 to 2,000 short tons per day at average ore grade of 0 15% U oxide HRIGHT, K H Federal American Partners 80/04/25 1p
- 8007100084 Advises NRC that KH Wright has resigned from Federal-American Partners, effective 800701 All correspondence should be addressed to OH Pierson WRIGHT, K H Federal American Partners, 80/06/11 lp
- 8007100087 Responds to NRC request for add1 info re "Suppl to Environ Rept Bubsurface Tailings Disposal " Date for submittal of add1 info cannot be met Geotechnical work programs will require approx 26-27 wks, until approx Dec 1980 HRIGHT, K H Federal American Partners 80/06/i1 ip
- 8007140673 Submits contract costs incurred & manhours used in reviewing 781107 application Project status rept dtd 800610 encl OARCIA,P J , LINEHAN,J J Uranium Recovery Licensing Branch 80/06/13 2pp
- 8007020280 Advises that review of manpower expanditures required re review of 781109 application for Amend 5 to License SUA-667 determined actual fee Refund will be forthcoming Applopizes for delay MILLER, W O License Fee Management Branch 80/06/18 ip
- 8007210169 Forwards "Proposal Evaluation of Ground Water Impacts, Proposed Subsurface Disposal Project.West Cas Hills.WY " PIERBON, Q W Federal American Partners 80/07/01 7pp
- ---8007210170 "Proposal Evaluation of Ground Water Impacts, Proposed Bubsurface Disposal Project, West Gas Hills, WY " HURDOCK, L T Dames & Moore 80/03/03 lipp
- B007230050 Forwards request for add1 info based on review of environ rept & suppl re subsurface tailings disposal Info form for radiological assessment & draft reg guide encl W/o info form & draft reg guide BCARAND, R A Uranium Recovery Licensing Branch 80/07/03 5pp

DOCKET 40-4669 CABE WESTERN RESERVE UNIV

7910150157 Responds to IE Bullatin 79-19 re packaging & disposal of low level radwaste Ten shipments, containing 4 82 C1 radwaste. were made from Jan 1978-June 1979 BOXICH.T A Case Western 79/09/26 2pp 8007030099 Forwards 790926 response to IE Bulletin 79-19. "Packaging of Low Level Radwaste for Transport & Durial." in response to NRC request BOZICH.T A Case Western 80/06/12 1p

DOCKET 40-502: STANDARD DIL CO

8007090131 Provides annual rept on transfer of products containing exempt concentrations of hyproduct matl for License SHB-785 & License 12-13837-01 No transfers made Jul 1979-June 1980 BANAS.E M Standard Oil Co of Indiana (see also AMDCO) 80/07/01

DOCKET 40-6622 PATHFINDER MINES CORP

- 8007180131 Amend 1 to License SUA-442, revising License Condition 28 to reduce amount of required cover for Dam 5 chimney drain from 5 ft to 1 ft & to approve gradation range of 1 ft of cover matl All other license conditions will remain same SCARAND, R A Uranium Recovery Licensing Branch 80/06/04 2pp
- 8007230576 Tabulates contract costs incurred & manhours used in revisuing 761227 license application PERSON.L., LINEHAN.J.J. Uranium Recovery Licensing Branch 80/07/03 2pp
- 8007280277 Informs of partial refund of fee accompanying 781120 application for Amend 1 to License 8UA-0442 MILLER.W O License Fee Management Branch 80/07/16 1p

DOCKET 40-6659 PETROTOMICS CO . GETTY QIL

- 8007230020 Requests amend to Condition 16 of License SUA-551 to read "mill tailings shall not be transferred from site w/o specific prior approval from NRC " Amend required to carry out research program on tailings mgt & reclamation PFAFF, B J Potrotomics, Inc 80/06/11 1p
- B007140993 Requests review of oncl suppl info to licensee embankment final const rept Forwards 800401 IE insp rept of completed tailings dam raise, authorized by Amends 1-5 to License BUA-551 W/o encls LINCHAN J Uranium Recovery Licensing Branch 80/06/13 ip
- 8007230193 Discusses proposed amend of License SUA-591 to upgrade effluent & environ monitoring program & to incorporate two minor revisions into reduction safety program Revisions will improve program Recommends approval of license amend KOTSCH, J. L., LINCHAN, J. J. Uransum Recovery Licensing Branch 80/06/20 Gpp
- B007310543 Amend 6 to License BUA-551 modifying effluent & environ monitoring proyram & revising radiation safety program Revised environ monitoring program encl BCARAND R A Uranium Recovery Licensing Branch 80/06/20 Spp
- 8007230245 Advises that Amend & for License SUA-551 was issued on 800620 & should be exempt from fees Amend was NRC-initiated & requires mad of effluent & environ manitoring program (KOTECH, J. L., LINEHAN, J. J. Uranium Recovery Licensing Branch 80/07/10 1p
- B007300269 Amend 7 to License SUA-591 authorizing transfer of tailings samples & extending completion dates for new tailings impoundment monitor Wells RTH 1.2 & 3 from 800714 to 31 KDTSCH.J L., LINEHAN.J J. Uranium Recovery Licensing Branch 80/07/14 2pp

DOCKET 40-6769 HOWARD UNIV

- 8007010180 Ack receipt of 800485 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 30-11063/80-01, 30-01321/80-01, 40-6789/80-01 & 70-0625/80-01 SMITH, QH Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/28 ip
- --8007010185 Responds to NRC 800328 1tr rg violations noted in IF Insp Repts 30-11063/80-01.30-01321/80-01.40-6789/80-01 & 70-0625/80-01 Corrective actions effluent concentrations evaluated & Cf-252 source tested ALEXIS.C P Howard Univ 80/04/25 2pp

7010197 Discusses IE Insp Repts 30-1106J/80 01.30-01321/80-01. 0-6789/80-01 & 70-0625/80-01 on 800320-21 & Forwards notice f violation

afety Oranch

17010209 Notice of violation from insp on 800320-21 Noncompliance ated failure to conduct required surveys/CF-252 source total in unlocked room & food stored in refrigerator w/

adicisotopes
Region 1, Philadelphia, Office of the Director 80/03/20 2pp

'T 40-7402 ALLEGHENY LUDLOM INDUSTRIES, CHEMTRON CORP

40178 Requests confirmation of planned actions discussed in 800623 con se radioactive maths disposed at McOlean Disposal p in Newburgh Heights.OH | lence will be repaired by 1625 patrol established & source of math investigated PLER.J G Region 3, Chicago. Office of the Director 80/06/25

30100 Confirms 800703 telcon be McGean Disposal Dump in Newborg ghts, DN Requests extension to complete assessment of

ES.R 8 Chemtron Curp 80/07/07 ip

T 40-7902 HONEYHELL, INC

60700 Furwards Weste Packaging Insp Rept 15000044/80-60 on 600515 utice of violation

19:A B Region 3, Chicago, fuel facility & Materials Safety
nch 80/06/27 2pp

7160710 Notice of violation from insp on 800515 Region 5. San Francisco. Office of the Director 80/06/10 ip

7160721 Waste Packaging Insp Rept 19000/46/80-06 on 800515 encompliance noted from containing radwaste found to have ash exposing cardboard or similar sulid matl DOK. If C. Region 5. San Francisco, Fuel Facility & Materials afety Branch THOMAS, R.D. Region 5. San Francisco. Office of the irector BO/06/10 Spp

T 40-BO27 KERR-MCGLE CORP

10509 Forwards remainder of license fee in response to NRC 900502 informing that request for amend to License GUB-1010 to mit disposal of reffinets sludge in below grade pit has classified as major amend EY.H J Korr-McGee Nuclear Corp 80/06/10

7010661 Application for amond to Excense 808-1010 to permit isomal of raffinate sludge in below grade pit HELLEY.W J. Kerr-McGee Nuclear Cosp. 80/05/22 tp

7010615 Environ ropt for Bequoyah facility raffinate sludge isposal Three oversize drawings encl Kerr-McOse Nuclear Corp 90/05/22 80pp

00117 Amend 11 to Spurce Matt License SUB-1010 authorizing use of ium-treated neutralized solvent extraction reffinate for tilizer on licensee-owned property per 800129 application 00403 ltr.sub; to HRC requirements E.R G Uranium Fuel Licensing Branch 80/06/17 2pp

50634 Forwards proposal for continued monitoring in virinity of worth effluent outfall, in accordance $\omega/Condition\ 19$ of ease SUB-1010

LLLY, W J Kerr-McGee Nuclear Corp 80/05/17 7pp

10970 Lists contract costs incurred & manhours expended in twing license amend application UN-W A . Uranium Recovery Licensing Branch . BO/07/23 $\,$ 1p

40-8045 SUISMAN & BLUMENTHAL, INC

10872 Discusses IE Insp Rept 40-8049/80-01 conducted on 800616 No compliance moted Major areas inspected radiation safety. plance w/NRC rules, regulations & conditions of license corrective action on previous item NEMAN. J D Region i. Philadelphia, Fuel facility & Materials etg Branch 80/07/14 Ip

DOCKET 40-8056 BRONSON METHODIST HOSP KALAMAZOO, MI

8007080273 Forwards personnel monitoring mept for 1979 per 10CFR20 requirements SIMONS,C S Bronson Methodist Hosp Kalamaios,MI

--8007080278 Personnel monitoring rept for 1979
SIMONS, C 8 Uronson Methodist Hosp Kalamazoo, MI 80/06/27 1p

DOCKET 40-8102 EXXON MINERALS CO. USA, EXXON CORP.

8007030352 Forwards Exxon commercial scale in situ amend application & related mat1 in response to NRC request MATHISEN,R i. Wyoming, State of 80/06/04 10pp

BOO71/0A79 Discusses proposed monitor wells for Area MB re application for Mining Permit 218C for solution mining at facility Brilling will begin in June so that 21 wells can be completed & sampled during summer Location maps encl TRUSSCLL.H H Exxon Minerals Co . USA BO/06/13 4pp

8007070106 Forwards requests for add1 hydrologic info identified during review of FES re operation of U mill & U solution mining project LINENAN, J J Uronium Recovery Licensing Branch 80/06/18 4pp

8007290231 Forwards 1E Insp Rept 40-8102/80-01 on 800404-06 & notice of violation BROWN, C D F or Region 4, Dellas. Fuel Facility & Materials Safety 9D/06/20 2pp

---8007290237 Notice of violation from insp on 800604-06
* Region 4, Dallas, Office of the Director 80/06

--8007290244 IE Insp Rept 40-8102/80-01 on 800604-06 Nancompliance noted worker exposed to excess airborne U BRDHN.0 D . CAIN.C L Region 4. Dallas, Fuel Facility & Materials SaPety Branch 80/06/20 7pp

BOO7280047 Responds to NRC BOO618 request for addl info re hydrogeologic sys at site Preliminary analysis to Guestions 7-9 & response to Guestions 1-6 will be submitted by BOO831 Addl comprehensive studies should be completed by BIO930 DRILDIFF, G D Exxon Minerals Co. USA BO/07/03 Ip

DOCKET 40-8200 CLEVELAND-CLIFFB IRON CO

BOD7100DB2 Bummary of BOD509 meeting w/Cleveland Cliffs Iron Co in Bilver Spring.MD re status of Licenses SUA-1199 & SUA-1352 & EADIE, C. C. Uranium Recovery Licensing Branch 80/04/11 3pp

8007230279 Safety evaluation re review of 800529 site final restoration plan Estimated schedule for completing restoration of site appears reasonable Proposed three-phase program shoud be initiated as soon as possible.w/820331 completion date EADIE, G G, ROTHFLEISCH.J, MILLER.H J Uranium Recovery Licensing Branch 80/07/02 2pp

8007230294 Amend 1 to License SUA-1199 authorizing proposed three-phase site final restoration program Program will permit bermination of license BCARAND.R A Uranium Recovery Licensing Branch 80/07/07 1p

BOO7B70B49 Confirms plan to conduct Phase I water sampling at in situ solution mining test sits on BOO721 LOUDERBACK,T E Cléveland-Cliffs Iron Co BO/07/14 ip

DOCKET 40-8304 HYONING MINERAL CORP

8007010367 Advises that Dept of Environ Quality, Land Quality Div has not received showing of compliance w/In Situ Mining Act for Itcensee operations in District 4 Requests status rept remeasures to comply w/mining act MDRRIS.D Wyoming. State of 80/06/05 ip

BOO7220303 Application for renewal of License SUA-1204 authorizing aplution mining R&D activities in area Also forwards "Test Site 517 Test 4" TIEPEL-E W Wydming Mineral Corp. 80/07/07 ip

DOCKET 40-8327 SALEM HOSP BALCH, MA

B0072B0224 Notifies of expired License SUC-1215 & discusses actions to be taken by licensee MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director B0/01/14 2pp

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO

- 8007210243 Summary of 800313 meeting w/util in Silver Spring, MD te in situ solution mining operations RDTHFLEISCH, J E Uranium Recovery Licensing Branch 80/04/30 4pp
- B007020702 Corrects B00331 application to amend License SUA-1228 Licensee does not intend to use exident \(\sigma / \cap \) because to show reverse commissioning extreme going directly to evaporation reservoir NEUMANN, M R Rocky Mountain Energy Co 80/05/30 5pp
- B007030002 Application for amend to License SUA-1228, containing statements & commitments which supersede any potentially conflicting statements in 800331 amend application State of WY, Dept of Environ Guality Guadeline Number 8 encl NEUMANN, M R Rocky Mountain Energy Co 60/06/03 27pp
- 8007210146 Outlines items discussed & commitments made during 800530 meeting re reclamation & land & water quality review process Requests concurrence on specific Agreements NEUMANN.M R Rocky Mountain Energy Co 80/06/03 3pp
- 8007070i15 Responds to 800603 ltr Concurs w/meeting summary w/three exceptions re monitor Hell M-54.Reno Creek addendum & Pattern IV startup conditional approval WY Dept of Environ Guality 80060 internal memo encl
 MORROW, D Wyoming, State of 80/06/10 2pp
- 8007220035 Provides WY Dept of Environ Quality w/results of sample analyses for lime overflow circuit Reservoir A & B grab samples Requests approval of proposed monitoring program mods & revised discharge stds
 NEUMANN, M R Rocky Mountain Energy Co 80/06/12 lipp
- 8007030219 Responds to 800613 ltr re preliminary water quality data for Pattern IV Conditional authorization is granted to start Pattern IV pending completion of review of 800930 compliance submitted & receipt of addl data MORROH, D Wyoming, State of 80/05/13 1p
- 8007170583 Safety evaluation supporting Amend 5 to License SUA-1228 Approval is recommended subj to stated license conditions RDTHFLEISCH.J E, MILLER.H J Uranium Recovery Licensing Branch 80/06/13 400
- BOO7180086 Amends License BUA-1228, revising Condition B authorizing use of carbonate/bicarbonate lisiviant in Test Pattern 4
 BCARAND, R A Uranium Becovery Licensing Branch 80/06/13 2pp
- B007240100 Forwards preliminary water quality data Upper control limits for Well M-54 have been established for pH.bicarbonate.U & vanadium NEUMANN.H R Rocky Mountain Energy Co 80/06/13 3pp
- 8007220022 Forwards application to construct wastewater facility for proposed Reservoir C Corrects vanadium level reported in 800612 ltr. Table 2 Assay results for Reservoir B. Monitor Hell PH-3 encl NEUMANN. M R Rocky Mountain Energy Co 80/06/23 App
- B007160390 Forwards results of B00505 & 0607 samplings of Pattern III monitor wells No significant change in well status & no change in pattern operation NEUMANN.M R Racky Mountain Energy Co 80/06/26 5pp
- 8007210224 Clarifies 800416 review of operations prepared to accompany license renewal request Differences in soils data U values attributable to different sampling & analytical techniques Discussion of Nov 1979 Pattern III excursion encl NEUMANN, M R Rocky Mountain Energy Co 80/06/30 34pp
- 8007300042 Outlines contract costs incurred & personnel hours expended in reviewing 800303 license application ROTHFLEISCH.J., SCARANO.R.A. Uranium Recovery Licensing Branch 80/07/14 io

DOCKET 40-8438 EASTMAN KODAK CO

8007010266 Application by Kodak for Amend 3 to renew export License (formerly BTB-B274)
HARTER, E 8 Eastman Kodak Co 80/06/09 1p

DOCKET 40-8452 BEAR CREEK URANIUM CO

- 8007240007 Forwards addl info for amend to License SUA-1310 "Tailings Mgt Plan," Bear Creek Tailings Disposal into Mined-Out Open Pit," & "Leachate Movement from B-3 Pit Tailings Disposal Area," encl MEDLOCK, R L Bear Creek Uranium Co 80/07/01 76pp
- --B007240011 "Key Plan & Site Plan " * Davy McKee Corp 80/06/30 1
- --8007240013 "Pipe Line Haul Road Route Graded "
 * Davy McKee Corp 80/06/30 1p
- --B007240022 "Underdrain Sys Plan & Details "
 * Davy McKee Corp 80/06/30 1p
- --B007240029 "Geological Cross Section A-A',B-3 Nine Area "
 * Hydrology Associates,inc 80/07/02 ip
- ---B007240041 "Geological Cross Section B-B',B-3 Mine Area "
 * Hydrology Associates,Inc 80/07/02 1p
- --8007240048 "Geological Cross Sections"

 * Hydrology Associates, Inc. 80/07/02 ip
- 8007280073 Submits preliminary questions needing clarification from review of supplemental environ rept re proposed tailings mgt plan Questions may be answered during 790320 site visit More detailed evaluation will be presented SHEPHERD. T A Calorado State Univ 79/03/14 3pp
- B007210183 Discusses licensee revised tailings mgt plan presented during site visit Revised plan includes extension of existing disposal operation w/o in-pit disposal Addl points require clarification
 NELSON.J D , BHEPHERD.T A Colorado State Univ 79/03/29 3pp
- 8007210177 Discusses responses to Rocky Mountain Energy Co questions re project Complete analysis of long-term stability of proposed plan will be provided upon receipt of data noted in Questions 3 & 5 NELBON, J D Colorado Statu Univ 79/06/01 8pp
- 8007230135 Discusses review of responses to NRC 790927 questions, 790409 Question 2 re differential settlement in tailings impoundment & Chen & Associates analysis Estimated differential settlement is acceptable NELSON; J D Colorado State Univ 79/10/05 1p
- B007180303 Amend to License BUA-1310 authorizing raise of tailings dam to elevation 5,160 fl above mean see level SCARAND,R A Uranium Recovery Licensing Branch 80/07/10 3pp
- B007230715 Discusses proposed Amend 7 to License SUA-1310 to authorize raising existing tailings retention embankment from elevation 5150 4 to 5160 Recommends approval of amend subj to listed conditions Drawing encl OARCIA,P J, GILLEN D M, LINEHAN,J J Uranium Recovery Licensing Branch B0/07/10 Gpp
- --8007230721 Forwards hydrologic engineering summary for U mill Proposed design for operational period meets hydrologic design criteria suggested in Reg Guide 3 11 Beveral issues should be addressed before long-term stability can be assured BIVINS.W B Hydrologic & Geotechnical Engineering Branch BO/06/18 6pp
- --8007230725 Discusses questions re proposed tailings reclamation plan Expresses doubt that extensive cracking would extend through depth of cover if min thickness of 3m is adhered to All outstanding issues have been adequately addressed NEL6QN, J D Colorado State Univ 80/06/23 ip

DOCKET 40-8481 BOEIN'S CO

- 8007280218 Application by Boring Co for Amend & to export license, adding Angola Comercon & Libyan Arab Airlines as ultimate consignee

 MORGAN, W E Boeing Co 80/06/[1 lp
- DOCKET 40-8502 IRIGARAY MINE, WYOMING MINING CORP
- 8007140606 Expresses concern re immediate economic consequences Buffalo,NY will experience if work at U mine is halted NYGRON,J Affiliation Unknown 80/04/25 lp
- 8007010591 Forwards licensee 800-129 ltr to State of My re mine site, including weekly water quality analysis results plexometric contour naps & map of new shallow research well locations Drawing available in Central Files only MICHERS, D.L. Wydming Mineral Corp. 80/05/02 (5pp.
- 8007020079 Submits lept re 800413 results of weekly sample analysis from Shallow Munitor Well SN-12 exceeding upper control limit values for chloride & total alkalinity Diagnostic wells drilled to define extent of chloride magnation HICHERS.D L Hyoming Mineral Corp 80/05/20 ip
- 8007210285 Summary of 800430 meeting w/State of HY officials & HY Minerals Corp in Cheyenne. HY re NRC order to show cause FONNER.R L Office of the Elecutive Legal Director SCARAND.R A Uranium Recovery Licensing Branch 80/05/21 Spp
- 8007030358 Forwards 800530 biweekly status rept to recent monitoring offerts of shallow monitor case Two oversize drawings encl WICHERS.D L. Wyoming Mineral Corp. 80/06/02 10pp
- ---B007030363 "Piezometric Contours Rescarch Well Locations, Production Units 1.2,3,4,5 & 6 " Sheet | of 1 • Hyoming Maneral Corp 80/09/13 1p
- --8007030364 "Pierametric Contours Research Well Locations, Production Units 1.2,3,4,5 & 6 " Sheet 1 of 1

 * Wyoning Mineral Corp #0/05/19 ip
- 8007100445 Forwardt 800521 surmary of 800430 meeting w/licensed & State of Wy re 800421 show cause order BCARAND,R A - Uranium Recovery Licensing Dranch 80/06/03 1p
- --800/100444 Summary of S00430 meeting w/licensee & State of MY re NRC 800421 older to show Cause issued to licensee Conditions for lifting of immediate effectiveness of order encl SCARANDLR A Urenium Recovery Licensing Branch FGNNER, R L Regulations Division 80/05/2) 5pp
- B007020694 Approves expansion into Production Unit 6 of U mine u/sodium bicarbonate lixiviant, contingent upon NRC approval Groundwater restaration after completion of mining shall be to average baseline values using best possible technology ACKERMAN. & C Wyoming, State of B0/06/04 3pp
- 8007010567 Advises that Dept of Environ Quality, Land Quality Div has not received showing of compliance w/In Situ Mining Act for licenser operations in District 4 Requests status rept re measures to comply w/mining act MORRIS, D. Wyoming, State of 80/06/05 1p
- B007070120 Submits data of 800603 & 05 samples taken from latest extursion into G field of Unit 5 R5-47 pumping authorized MORROW.D Myoming, State of 80/06/06 1p
- 8007070147 Forwards Trigaray site 800602 itr to State of WY re assay data from Sh-14
 WICHERS, D.L. Wyoming Maneral Corp 80/06/06 4pp
- 8007100452 Summary of 800428 meeting w/licenses to State of MY in Bilver Spring.MD re licenses response to 800421 show cause order suspending solution mining operations k asking why suspension should not be permanent KAUFMANN.R S. Uranium Recovery Licensing Dranch. 80/06/12 Spp.
- B007140600 Responds to 800607 memo by advising that NRC corrective action to date re-project has been issuance of 800421 to 0523 orders First order had effect of directing immediate suspension of normal activities at site W/a encl orders BCARAND.R A Uranium Recovery Licensing Branch 80/06/13 ip

- --8007140607 Discusses hackground for modifying license & terminating 800421 show cause order to licensee NRC has concluded that immident & pollukants are being confined laterally to well field vicinity in designated hydrostratigraphic horizons KAUFMANN.R S Uranium Recovery Licensing Branch 80/06/13 2pp
- 8007150644 Forwards latest communications between site & State of WY, dated 800613 MICHERS, D.L. Wyoming Mineral Corp. 60/06/16 1p
- --R007150651 Bubmits biweekly status rept for Mine 478 Forwards piezometric contour maps of shallow zone based on static water level measurements from 800027 & 0602 samplings Two oversize drawings ent!
 WICHERS.B.L. Wyoming Mineral Corp. 80/04/13 10pp
- --- B007150657 "Research Well Locations Pierometric Contours " Sheet 1 of
 - * Wyoming Mineral Corp 80/04/09 1p
- --8007150667 "Research Well Locations, Piezometric Contours " Sheet 1 of
 - * Wyoming Mineral Corp 80/04/09 is
- BOD7210066 Requests that all available water quality data from newly drilled shallow monitor wells be forwarded & that future data be encl w/biweekly status repts Also requests info resplit samples taken BOD512-15
 MORROW.D Wypming, State of BO/06/19 ip
- 8007210542 Forwards correspondence w/8tate of WY re Irigarary site shallow 52nd monitor well data Oversize drawing encl WICHERS.D L. Wyoming Mineral Corp. 80/05/20 4pp
- --8007210548 Provides MV Dept of Environ Quality w/water quality data & map identifying locations of exploration hole in area of Production Unit & Quersize map encl MICHERB, D.L. Mycmang Mineral Corp 80/06/18 7pp
- 8007210953 "Location of Exploration Hole in Production Unit & " Sheet 1 of 1 * Wyoming Mineral Corp 80/05/05 ip
- B007210096 Discusses concorn to economic consequences that could be imposed on Buffelo & Johnson County.47 w/curtailment of U solution mining project Modifying license order issued B00925 permitting limited operation for 90 days SCARAND,R A Uranium Rocovery Licensing Branch B0/06/23 ip
- B007230071 Addresses concerns re economic consequences of project curtailment NRC B00523 modified license order permits resumption of limited operations Licensee must demonstrate anvironmentally acceptable operation SCARAND R A Uranium Recovery Licensing Branch B0/06/23 ip
- 0007R3007/ Addresses concerns re economic consequences of project curtailment NRC 000523 modified litense order permits resumption of limited operations Licensee must demonstrate environmentally acceptable operation BCARANGR, A Uranium Recovery Licensing Branch 00/06/23 2pp
- BOO72300BR Addresses concerns re economic consequences of project curtailment NHC BOO5R3 modified license order permits resumption of limited operations Licensee must demonstrate environmentally acceptable operation SCARANO.R A Uranium Recovery Licensing Branch BO/06/23. lp
- B007230274 Advisus that NRC is sensitive to economic consequences of project curtailment to Town of Buffalo & Johnson County, MY NRC issued modifying license order on B00523: allowing license to resume limited operations for 70-day period SCARAND-R A Uranium Recovery Licensing Branch B0/04/23 1p
- 8007230318 Advises that NRC is sensitive to economic consequences of project curtailment to Town of Buffala & Johnson County, MY NRC issued modifying license order on 800525; allowing license to resume limited operations for 90-day period SCARAND, R A Uranium Recovery Licensing Branch 80/04/23 ip
- 8007250642 Responds to concern about economic consequences of project curtailment NRC 800923 order will permit resumption of limited operations Public health & safety will not be endangered SCARAND, R.A. Uranium Recovery Licensing Branch 80/06/23 lp
- 8007210145 Requests info re contaminants in aquifiers near Buffalo.WY DREY.K. Affiliation Unknown 80/06/26 ip

- 8007210101 Notifies that on 800522 samples from shallow munitor well SM-14 indicated chloride & total alkalinity exceeded upper control limits Caused by producing recovery well Addl monitoring underway HICHERS, D. L. Wyoming Mineral Corp. 80/06/27 3pp
- 8007210191 Outlines status of action items agreed on at 800616 meeting re authorization of Production Unit 6 & 1.600 gpm flow expansion request Technical support info has been submitted Lists addl environ studies
 TIEPEL,E W Wyoming Mineral Corp 80/06/30 3pp
- B007280054 Notifies that 800617 restoration plan & license request are acceptable w/following condition Burface reclamation is not complete until good vegetative cover is present MDRROW.D Wyoming. State of B0/07/03 ip
- 8007210095 Forwards requested tabulated data on monitor well upper control limits & initial & current assays for research wells TIEPELLE W Wyoming Mineral Corp 80/07/07 5pp
- 8007210095 Forwards requested tabulated data on monitor well upper control limits & initial & current assays for research wells TIEPELLE W obsolete code 80/07/07 5pp
- BOO7280200 Notifies that JM Corcoran has been appointed mine manager of Irigarary in situ mine site, Johnson County, WY HOHNE, F. C. Wyoming Mineral Corp. 80/07/09 1p
- 8007280303 Bubmits analysis of ammonia in shallow sand monitor wells. Unit 6 MORROW.D. Wyoming, State of 80/07/15 ip
- B007230063 Addresses concerns re economic consequences of project curtailment NRC B00523 modified license order permits resumption of limited operations Licensee must demonstrate environmentally acceptable operation BCARAND.R A Uranium Recovery Licensing Branch B0/07/18 lp

DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

- 8007020028 Advises of intention to occupy existing in situ camp facilities in Section 21. Township 24 north. Range 93 west. Bweetwater County. WY for approx 2 yrs beginning in May or June 1980 to canduct U exploration activities ACOSTA. A P Union Minerals 80/02/21 2pp
- 8007010305 Notifies that fill placement has resumed on Call C of subsurface tailings impoundment at Sweetwater U project Bubmits tentative schedule for completing cell const Revised date for tailings cell liner installation is 800614 ACOBTA.A P Union 74 Minerals Exploration Co 80/05/08 Ip
- 8007180601 Discusses proposed Amend 3 to License BUA-1350 involving mods to tailings pend liner sys Recommends approval Const mods include removal of soil cover except in traffic areas, at dike top, at dise bench & at PVC/Hypalon seam GILLEN, D M Uranium Recovery Licensing Branch 80/06/03 4pp
- 8007240103 Amends Source Mat) License SUA-1350 to add Paragraphs J, k & 1 to Condition 39 & modifies Condition 41.42 & Paragraph d of Condition 40. 4 Uranium Recovery Licensing Branch 80/05/03 3pp
- B007210860 Submits add1 monitoring &/or clarifying data per RA Scarano 790216 request re "Preoperational Monitoring Rept " Oversize map encl ACOBTA:A P Union 76 Minerals Exploration Co 80/06/04 20pp
- --8007210366 "Preoperational Environ Monitoring Locations "
 * Union 76 Minerals Exploration Co 80/05/31 ip
- BOO7100450 Requests that two const insps be conducted of tailings impoundment. Insp of results of excavation by blasting should be performed during last wk in June 1980 Insp of synthetic liner installation should be performed in mid-Jul 1980 BCARANO, R A Uranium Recovery Licensing Branch 80/06/19 2pp
- 8007230680 Submits contract costs incurred & manhours used in reviewing 790713 license application OILLEN.D., LINEHAN.J J Uranium Recovery Licensing Branch 80/07708 2pp

- 8007250157 Advises licensee that no add) fee is required in connection W/Amend 3 to License SUA-1350, issued on B00603 Licensee paid max fee for minor safety & environ amond MILLER:W O License Fee Management Branch B0/07/15 lp
- 8007270619 Refers to 800514 ltr re 800514 mill start-up notification Mill start-up expected 800910 instead of 800815, due to const delays ARCOSTA A P Union Minerals 80/07/29 lp

DOCKET 40-8585 WYOMING MINERAL CORP

- B007010214 Application for amend to License SUA-1315 revising Figure 3 2-1 estimates for flows through resin ion exchange columns Requests issuance of amend by 800902 Fee encl SCHENDEL, K R Wyoming Mineral Corp 80/05/27 2pp
- 8007230084 Discusses 800827 application to amend Condition ii of License SUA-1318, altering flow rates from 6,666 to 10,000 gpm ion exchange feed & 6,710 to 10,070 gpm ion exchange tails Recommends approval of application HEYER, R S . LINEHAN, J J. Uranium Recovery Licensing Branch 80/07/10 2pp
- 8007240300 Amené i to License SUA-1315, revising Cométition 11 re release of process waste SCARAND R A Uranium Recovery Licensing Branch 80/07/10 ip

BOCKET 40-8602 UNITED NUCLEAR CORP

- 8007180288 Summarizes 800422 visit to main embankment foundation & impoundment area preparation Recommends continued const Profenginoer should supervise monitor, document & cortify all phases of const process

 ABT. S R United Nuclear Corp 80/04/27 3pp
- B0072B0066 Advises of recommendations made re increased documentation to certification of embankment const from 800422 insp. Forwards rept of initial work following NRC insp. Entire documentation will be examined during 10% insp. phase ABT.S R. Colorado State Univ. B0/05/12 4pp.
- B007170291 Forwards 1E Insp Rept 40-8602/80-01 on B00422 No nuncompliance noted BROWN, O D Region 4, Dallus. Fuel Facility & Materials Sufety Branch B0/06/10 2pp
- --9007170297 IE Insp Rept 40-8602/80-01 on 800422 No noncompliance noted Major areas inspected NRC regulations & applicable civil engineering soil stds HARRISON.H C Region 4. Dallas, Office of the Director ABT.S R Colorado State Univ BROWN.G D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/06/06 2pp
- --G007170302 Provides trip rept re 800422 site visit to main embankment foundation & impoundment area preparation Recommends United Nuclear Corp proceed w/main embankment const & prof engineer supervise all phases of const ABT.8 R Colorado State Univ 80/04/27 3pp
- --8007170308 Forwards consulting engineer rept of initial work, reincreased documentation & critification of embankment const. following NRC 800422 insp.
 ABT.8 R Colorado State Univ 80/05/12 App

DOCKET 40-8647 KERR-MCGCE CORP

- B007030031 Forwards environ rept.Suppl 1 & Addendum 1.responding to NRC 791219 questions re proposed new U mill Includes three design drawings of proposed retention pond
 BHELLEY,W J Kerr-McGes Nuclear Corp B0/05/09 ip
- --8007030035 Environ rept. Suppl 1 & Addendum 1. responding to NRC 791219 questions * Kerr-McGee Nuclear Corp 80/05/09 Spp
- --8007030039 "Tailings Disposal Study Hillside Deposition W/Drainage to Excavated Pond 'P' "
 * Stearns-Roger, Inc. 80/03/05 ip
- --8007030047 "Tarlings Disposal Study Hillside & Rond 'P' Sections " * Stearns-Roger, Inc. 80/03/05 ip

0

DOCKETED ITEMS

- 8007030055 "Tailings Disposal Study Hillside & Pond P' Reclamation Plan "
 * Stearns-Roger, Inc 80/02/04 ip
- 007010570 Forwards addendum to 'Environ Rept.South Powder River Basin Mill." in response to NRC B00201 request Dose calculations used in initial rept were modified to include milk pathway evaluation SHELLEY, W.J. Kerr-McGee Nuclear Corp. 80/06/06
- 8007010392 Addendum 2 to "Environ Rept, South Powder River Basin Mill " # Kerr-McGee Nuclear Corp 80/86/06 29pp

OCKET 40-8681 ENERGY FUELS NUCLEAR, INC

- 007180471 Summarizes 800415 safety insp of Dike 3 & placement of PVC liner in Cell 2 Recommends continued const Consulting engineer should remain ensite to observe, theck & document all activities re preparation, placement & insp of PVC liner AUT.B R Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/04/18 13pp
- 007280070 Forwards photos of iOX insp of Embankment 3 % lining of Cell 2 Requests that typographical error on Page 3,Paragraph h, Line 4 in 800418 rept be corrected to read "18 inches along embankment "Change critical for compliance W/o encl ABT,S R Colorado State Univ 80/04/30 lp
- 007:80277 Summarizes 800424 70% insp of Dike 3 Recommends continued const Density recurds we sand drain on Embaniment 2 should be checked for licensee compliance prior to final approval neration B R United Nuclear Corp BO/05/15 3pp
- D07280175 Bafety evaluation recommending approval of Amend 3 to License SUA-1358 w/noted conditions Amend would involve addition of second crusher unit to one buying station circuit at mill OLLEN,D M . LINEMAN, J J Uransum Recovery Licensing Branch 80/06/04 2pp
-)07170327 Forwards 1E Insp Rept 40-8681/80-01 on 800415 t 24 No noncompliance noted BROWN.0 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/05/11 2pp
- 0007170327 IE Insp Rept 40-8681/80-01 on 800415 & 24 No noncompliance noted Major areas inspected NRC regulations & applicable civil engineering soil stds
 HARRISON-H C Region 4. Dallas. Office of the Director ABT.S R
 Colorado State Univ BRDWN-6 D Region 4. Dallas, Fuel Facility & Materials Safety Branch 80/06/06 2pg
- -8007170331 Bubmits trip rept re insp of Dike 3 & placement of PVC liner in Cell 2 Recommends that work conducted up to insp time be approved for continuation & that consulting engineer remain onsite to observer.check & document all activities ART.8 R Colorado State Univ 80/04/18 | 13pp
- -8007170332 Bubmits typographical correction for 800418 trip rept re placement of PVC liner in Cell 2.indicating that Energy Fuels Nuclear has complied w/license conditions ABT.8 R Colorado State Univ 80/08/08 lp
- -8007170335 Trip rept re 800424 70% insp of Dike 3 Recommends that work up to insp time be approved & that Energy Fuels Nuclear be allowed to continue const of embankment Also recommends that final approval be rendered for mill operation ABT.8 R Colorado State Univ 80/05/09 3pp
- 007100019 Discusses actions taken by NRC in response to State of UT 800612 ltr re archaeological activities being performed at facility Interagency Archaeological Svcs will check work for conformance w/memorandum of agreement 8CARANO.R A Uranium Recovery Licensing Branch 80/06/17 ip
- 007210090 Discusses Items 1-3 addressed in first lit to NRC & discussed at 800618 mesting to sibe Piecemeal approach to memo of agreement will have detrimental effect on archaeological analysis 8NITH.M T Utah, State of 80/06/30 2pp
- 007230672 Submits contract costs incurred & manhours used in reviewing 800414 license application GILLEN.D., LINEHAN, J. Uranium Recovery Escensing Branch 80/07/08 Spp

- 8007230731 Forwards copy of NRC 800606 fee request for 800523 amend to License SUA-135B for relief from License Conditions 41 & 47 Requests payment within 15 days WEISB, D License Foe Management Branch 80/07/16 ip
- B007280564 Informs of forthcoming refund re review of 800414 application for Amend 3 to Litense SUA-1398 MILLER:W D License Fee Management Branch 80/07/14 ip

DOCKET 40-8693 OGLE PETROLEUM, INC

- 8007020293 Submits quarterly rept for 800201-0430 re pilot in situ U solution mining operation Neither U recovery plant nor restoration plant was in operation Thus no info re injection/recovery rates & vols & reverse osm
- DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO
- 8007020083 Responds to 800506 request for written confirmation of agreements reached at 800502 meeting Land & Water Quality Divs are currently reviewing 800530 submitted re compliance w/In Situ Act Wyoming. State of 80/04/12 ip
- 8007020064 Notifies that 800830 submittal does not demonstrate compliance w/In Situ Mining Act R&D activity at site will be permitted until groundwater restoration & other data are sufficient to support application MORROW.D Hypoming. State of 80/06/13 lp
- 8007180057 Summarizes proposed changes or additions to 800423 license amend request Mods correct omissions in original document or revise procedures based on recent field experience IWANICKI, R Rocky Mountain Energy Co 80706/19 3pp
- HOO7210063 Suggests that state suspend Reno Creek license to mine after 30-day notice for failure to make application for commercial facility Orace period will provide facility w/add1 time to complete forms for in situ R&D license MORROW.D Hyoming, State of 80/06/20 2pp
- 8007290870 Forwards Form 5, "Application for In Situ Research Testing License," in response to State of MY.Dept of Environ Guality 800613 request M/o encl IWANICKI.R E Rocky Mountain Energy Co 80/07/10 Ip

DOCKET 40-8698 PLATEAU RESOURCES, LTD

- 8007180074 Amend 14 to License 8UA-1371 revising Condition 41 to change advance notification required prior to certain const milestoned from 3 to 6 wks
 BCARAND, R A Uranium Recovery Licensing Branch 80/05/09 2pp
- B007180480 Summarizes B00429 site visit & insp of embankment foundation & impoundment area Recommends continued const Vendor should formulate & implement design for insuring tight seal is formed between Zone | matl & grooves & overhang joint ABT.6 R United Nuclear Corp B0/05/20 7pp
- DOCKET 40-8702 ARMY, DEPT OF, ARMAMENT MAT READINESS COMMAND
- 8007140627 Forwards IE Insp Rept 40-8/02/80-01 on 800422 No noncompliance notes CROCKER.H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/08/21 2pp
- --BO07140631 IE Insp Rept 40-8702/80-01 on BO0422 No noncompliance noted Major areas inspected review of decentamination plans & Pacility tour CROCKER.H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch COSTELLO,F Region 1, Philadelphia, Office of the Director 80/05/20 2pp

DOCKEY 40-8714 CLEVELAND CLIFFS IRON CO.

80071000B2 Bummary of B00509 meeting w/Cleveland Cliffs Iron Co in Silver Spring, MD re status of Licenses BUA-1199 & SUA-1352 & sites EADIE, Q C - Uranium Recovery Licensing Branch, 80/04/11 - 3pp

- 8007230161 Safety evaluation re minor changes in supporting info submitted w/application for Licenes 8UA-1352 Increasing project site to 42 5 acres should be authorized EIS, negative declaration or EIA need not be prepared EADIE: 6 9 , ROTHFLEISCH. J , NILLER, H J Uranium Recovery Licensing Hearch 80/06/20 20p
- 8007310546 Amend 1 to License 8UA-1352 increasing total permit area to 42 1/2 acres while actual woll field is unchanged 8CARANO.R A Uranium Recovery Licensing Branch 80/06/20 Ip
- 8007310457 Application to amend License SUA-1352, changing Condition 10 to authorize testing of oxygen &/or hydrogen peroxide w/ammonium carbonate lixiviant to oxidize & liberate U from mineralized sand Fee oncl
 LDUDERBACK.T E Cleveland-Cliffs Iron Co 80/07/14 3pp

DOCKET 40-8721 RDCKY MOUNTAIN ENERGY CO

- 8007210243 Summary of 800313 meeting w/util in Bilver Spring.ND re in situ solution mining operations ROTHFLEIBCH.J E Uranium Recovery Licensing Branch 80/04/30 4pp
- 8007020458 Responds to 800504 request for written concurrence reagreements reached at 800502 meeting Mining permit must be converted to in situ R&D license in order to conform w/code requirements
 MCRROH, D. Hyoming, State of 80/05/12 1p

DOCKET 40-8727 KERR-MCGEE NUCLEAR CORP

- B007300531 Provides Subcommittee on Energy & Power w/notice of issuance of License SUA-1378 W/o encl * Office of Nuclear Material Safety & Safeguards B0/04/16 1p
- 8007300555 Provides Bubcommittee on Nuclear Regulation w/notice of issuance of License 8UA-1378 W/o encl
 * Office of Nuclear Material Safety & Bafeguards 80/04/16 ip
- 8007300557 Provides Bubcommittee on Environ,Energy & Natural Resources w/notice of issuance & negative declaration for License 8UA-1378
 - * Office of Nuclear Material Bafety & Bafeguards 80/04/16 1p
- --8007360560 Notice of issuance of License SVA-1378 & negative declaration. SCARAND,R A. Uranium Recovery Licensing Branch 80/04/09 ip
- 8007300563 Provides Subcommittee on Energy & Environ w/notice of issuance of License SUA-1378 W/o encl # Office of Nuclear Material Safety & Bafeguards 80/04/16 ip
- 8007230620 Tabulates contract costs incurred & manhours used in reviewing 7906ii license application
 WU.O., MILLER.H J. Uranium Recovery Licensing Branch 80/07/03

DOCKET 40-8728 TETON EXPLORATION DRILLING CO . INC

- 8007010129 Forwards "Embankment Info for North & South Levenberger Reservoirs," required by Stipulation 32 of Spurce Matl License 8UA-1373 Fee encl HERLINY,D Teton Exploration Drilling Co., Inc. 80/02/01 2pg
- --8007010140 "Enbankment Info for North & South Levenberger Reservoirs" for Tetan-Nedco Levenberger in situ maning project HERLIHY, D Tetan Exploration Drilling Co , Inc 80/02/01 46pp
- BOO7020335 Advises that reporting identification symbol "XMU" has been assigned to License SUA-13/3, to be used in completing all NRC transfer repts
 BPARKB.E Technical Planning & Information Branch 80/03/27 lp
- 8007280694 Forwards water levels for wells PN5-L307 for first quarter of operation.per NRC 800207 request Omission of data in quarterly rept was oversight HERLIHY.D Teton Exploration Drilling Co , Inc 80/06/05 App
- 8007220063 Forwards 800606 ltr informing that to date outhor has not received info re continued operation of facility Operation has been put in holding pattern pending NRC decision re Levenberger Reservoirs Requests timely review HERLIHY.D. United Nuclear Corp. 80/06/17 ip

- --8007270070 Requests use of freeboard analysis for evaporation of presented in 800201 rept. "Embankment Info for North & South Levenbeiger Reservoirs " Timely review would be appreciated in order to demonstrate groundwater restoration HERLIHY, D. United Nuclear Corp. 80/06/06. 4pp
- 8007010432 Submits (valuation for license SUA-1373 to direct exhausabove process equipment & tanks Above tank vintilation systematical concentrations of ladon & radon daughters to which plant personnel were potentially explased RIEGER.S N Teton Exploration Drilling Co., Inc. 80/06/20
- E0072B0702 Submits evaluation of need for direct exhausting above process equipment & tanks to reduce potentially high concentrations of radon & radon daughters RIEGER, S. N. Taton Ciploration Drilling Co., Inc. 80/06/20
- 8007230667 Discusses 800617 application to amond License SUA-1973, authorize effluent waste levels in evaporation pends to rise to 5,214 & ft Recommends approval of amond provided License Condition 32 is revised to permit 2.4 ft of freeboard RAUPHANN, R.S., GILLEN, D.M., LINEHAN, J.J. Uranium Recovery Licen Branch 80/07/07 3pp
- 0007230711 Amend I to License SUA-1373 authorizing increase in eff level is evaporation ponds SCARAND, R A. Uranium Recovery Licensing Branch B0/07/07 ip

DOCKET 40-0745 DOLE PETROLEUM

- 8007030226 Advises that application for permission to drill wells complete for publication & notification Wells indicated in 800927 ltr should be drilled as soon as possible to get baselining further along FRANCIS.E. Wyoming, State of 80/05/29 3pp
- B007170433 Forwards NUREG-0687, DES on environ consequences to Sister Basin Project & FR notice SCARAND, R A Uranium Recovery Licensing Branch 80/06/13 ip
- --8007170436 Nutice of availability of DES for Bison Basin Project SCARANO,R A - Uranium Recovery Licensing Branch 80/06/09 - 2
- ---B007170440 DES for Bison Bason Project * Office of Nuclear Material Sofety & Safeguards NUREG-0607, 80/06/30 175pp
- 8007300046 Provides Subcommittee on Energy & Power w/June 1980 DEG encl * Office of Nuclear Material Safety & Safeguards - 50/06/13 - 1
- ---8007300048 Provides Subcommittee on Nuclear Regulation w/June 198 W/o encl * Office of Nuclear Naterial Safety & Safeguards 80/06/17
- --8007300051 Provides Subcommittee on Energy & Environ w/June 1910 H/o encl * Office of Nuclear Material Safety & Safeguards = 60/06/13
- --8007300058 Provides Subcommittee on Environ. Energy & Natural Resp W/June 1980 DES & related FR notice W/o DES * Office of Nuclear Material Safety & Safeguards 80/06/13
- --B007300062 Notice of issuance & availability of DTS
 SCARAND, R.A. Uranium Recuvery Licensing Branch 80/06/09 &p
- 80072803J3 Expresses appreciation for apportunity but has no commenter PIS
 DICKSON:F S Agriculture, Dept of 80/06/17 ip
- 8007170104 Ask receipt of DEB for U project & requests that M Amble & D Johnson be deleted from & O O'Oara added to list of interested citizens in Fremunt County-WY EAST, D Wymning Outdoor Council 80/06/19 lp
- B007220051 Submits review of DLS re project compatability w/local & regional comprehensive planning & impacts on urban areas Decument is adequate for agency responsibility MCKINNCY, R D Housing & Orban Development Dept of BU/06/25 |
- 8007210141 Responds to 800609 request for comments on DES for Ogle Petroleum, Inc. Bison Basin Project. Fremont County, WY Council reviewed DES Declines comment at this time MALL. S. Advisory Council on Historic Preservation. 80/06/26

DCKET 40-8768 KERR-MCKEE NUCLEAR CORP

007210067 Confirms major points of 800620 telcon re-setting groundwater quality bescline & evaluation of groundwater hydrology at R&D U site KAUFHANN.R S Uranium Recovery Licensing Branch 80/07/01 2pp

OCKET 40-8771 NUCLEAR ASSURANCE CORP

00722006B Forwards application for source matt license permitting use OUVEZOOOB Forwards application for source mati license p of unamyl peroxide & ammonium diurante in in situ pilot scale testing to recover U Nuclear Assurance Corp will operate project for AZ Public Evc Co WARD. B Nuclear Assurance Corp BO/06/20 2pp

-8007220073 Application for source matt license permitting use of uranyl perroxide & ammonium divrante in in situ pilot scale testing to recover U from underground mineralized ione Oversize drawings & supporting documentation encl BECKIM K Arizona Public Service Co WARD. D Nuclear Assurance Corp. 80/06/05 300pp

-8007220077 "Site Facility Layout Peterson In Situ U Extraction Project " * Ortloff Mineral Services Corp (subs of Ortloff Corp) 88700 80/02/12

-8007220082 "Solar Evaporation Reservoirs Peterson In Situ U Extraction Project " JELINEK, J A Affiliation Unknown 80/02/15 ip

OMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOKET 50-2 UNIO DE MICHIGAN RESEARCH REACTOR Inspection reports, IE Bulletins & correspondence

007170657 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/24

OCKET 50-3 INDIAN POINT STATION, UNIT 1

Adjudicatory correspondence

007020481 Forwards 800619 order revoking authority to operate facility & directing util to submit decommissioning plan within 120 days
DENTORAL R Office of Nuclear Reactor Regulation, Director 80/06/19 2pp

-8007020485 Order revoking authority to operate facility DENTON:H R Office of Nuclear Reactor Regulation, Director 80/06/19 29s

CO731024J Forwards Commission B00527 momorondem & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition snught action re fire protection for olectrical cables EISENHUT.D Q Division of Licensing 80/06/25 179pp

007090215 Order granting extension until 800725 for Commission to consider whether to review ALAB-936 & portions of ALAB-941

ing extension until 800801 for Commission to $^{\rm A1}\,\Delta \rm B-A^3 \Delta S$ relevant portions of

tary of the Commission 80/07/10

esident Carter re Indian otest public r planned for

ion. Director

8007170259 Responds to 800206 ltr re status & responsibilities for emergency preparedness in facility environs FEMA has lead responsibility in offsite emergency planning GRIMES.D & Emergency Preparedness Program Office 80/07/07 2pp

pagggoodg paguasts documentation that future correspondence re facilities be addressed to P Zarakas Requests that WA Monti-MF Shatkovsks & JM Makepeace be placed on distribution for ome correspondence Consolidated Edison Co of New York 80/07/24 1p

I Financial information

8007240127 Forwards Annual Financial Rept 1979 ZARAKAS:P Consolidated Edison Co of New York 80/07/15 1p

-8007240129 Annual Financial Rept 1979 # Consolidated Edison Co of New York 80/02/26 43pp

D Advisory Committee on Reactor Safeguards reports & correspondence

8007220308 Provides summary of 800507-08 meeting w/utils re core melt accident sequences Utils appear to expect NRC to resolve problems & do nothing to mitigate consequences of Class 9 CATTON, I California, Univ of, Los Angeles 80/05/10

P. Operating license stage documents & correspondence

B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Hudel Tech Specs which would provide acceptable resolution encl for guidance EIBENHUT, D G Division of Licensing 80/06/11 42pp

8007010110 Notification of 800625 meeting w/utils & Sandia Labs in Bethesda,MD for presentation of overview of facilities risk study Agenda encl ISRAFLES L Reliability & Risk Assessment Branch 80/06/16 3pp

B007090279 Forwards info updating B00505 ltr re control room habitability Drawing available in Central Files only ZARAKAS,P Consolidated Edison Co. of New York B0/07/01. Opp

8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Hadel Tech Speca & Model License conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENWIT.D & Division of Licensing 80/07/02 69pp

B007140392 Forwards "Program Plan for Performance Testing of PWR Bafety & Relief Valves." Revision 1, addressing NUREG-0578 Requirement 2 1 2 YOUNGDAIL.R C Consumers Fower Co B0/07/08 1p

--8007140393 "Program Plan for Performance Testing of PWR Safety & Relief Valves" Revision 1

* Electric Power Research Institute B0/07/01 90pp

O Insputtion reports, IE Bulletins & correspondence

8007020124 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required ORIFR.B H Rogion 1. Philadelphia. Office of the Director 80/05/28 1p

8007010322 Forwards IE Info Nutice 80-23, "Loss of Suction to Emergency Faedwater Pumps " No written response required ORICR.D II Region 1. Philadelphia. Office of the Director 80/05/29 ip

80070100B1 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "All Unit 2 tanks that could contain primary sys water have adequate protection Bulletin nat applicable to Unit 1 CAMILLUI J Cunsolidated Edison (o of New York 80/06/06 3pp

B007020077 Forwards response to IE Bulletin B0-12, "Decay Heat Removal Bys Operability " Bulletin not applicable to Unit 1 which is in defueled condition Existing Unit 2 procedures provide for adequate alternate means for removal of decay heat CAHLL.N J Consolidated Edison Co of New York B0/06/Q6 5pp.

B007210856 Forwards IL Info Nutice 80-26, "Evaluation of Contractor GA Programs " No written response required ORIER,D H. Region 1, Philadelphia, Office of the Director 80/06/10 ip

- 8007i60341 Forwards IE Info Notice 80~27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required ORIER.O H Region 1, Philadelphia, Office of the Director 80/06/11 ip
- 8007170287 Forwards partial response to IE Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls," for Unit 2 Unit 1 was shutdown 741031 & in defueled condition, therefore bulletin not applicable
 CAMILL, U. J. Consolidated Edison Co. of New York 80/06/13 5nn
- 8007020710 Forwards (E Bulletin 80-19. "Pussible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required ORIER. B H Region 1. Philodelphia, Office of the Director 80/06/18 ip
- 8007020497 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/04/20 1p
- 8007180560 Responds to IE Bulletin 80-09 No Hydramotor actuators used in any Unit 2 safety-related sys Unit 1 presently in defueled condition CAHILL.W J Commonwealth Edison Co 80/06/20 ip
- 8007180592 Responds to IE Builetin 80-10 Investigation revealed potential for nonradioactive sys to become contaminated through isolation valve seal water/city water interface Double check valves installed Monitoring program described CAHILL.H J Commonwealth Edison Co 80/06/20 2pp
- 9007iòòòBB Forwards IE Circuler 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80006/24 10
- 8007219172 Forwards IE Info Notice 80-24, "Low Level Radwaste Durial Criteria" No writton response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/86/25 ip
- 8007230106 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-11 also entl No written response required ORIER, D H Region i, Philadelphia, Office of the Director 80/06/27 2pp
- R Periodic operating reports & related correspondence
- 8007170363 Forwards "Annual Environ Monitoring Rept,Part B Radiological Rept " CAHILL.H J Consolidated Edison Co of New York 80/04/30 lp
- --8007170365 "Annual Environ Monitoring Rept, Part D Radiological Rept "
 * Consolidated Edison Co of New York 80/06/30 &&pp
- 8007130669 Submits daily fish counts from intake screens for June 1980 MONTI.W A Consolidated Edison Co of New York 80/07/10 17sp
- 8007210473 Forwards util 800613 ltr & "Guarterly Rept on Beismic Monitoring Network in Vicinity of Indian Point,NY, Con Ed Project Dec 1979-Feb 1980" of New York 80/07/14 App
- 8007220523 Forwards "Daily Count from Intake Screens for June 1980 " ZARAKAS,P Consolidated Edison Co of New York 80/07/15 ip
- --8007220524 "Daily Count from Intake Screens for June 1980" * Consolidated Edison Co of New York 80/07/15 4pp
- T Hearing transcripts on non-antitrest matters
- B007140084 Unofficial transcript of 800626 briefing on recommendations of Indian Point Task force in Washington BC Pp 1-62 Viewgraphs and Wiewgraphs and B0/06/26 64pp
- 8007240144 Transcript of 800711 public meeting in Washington.DC Pp 1~6 * Commission 80/0//11 App

- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

 F Security, medical, omergency & fire protection plans
- 8007310383 Forwards physical security plan Plan withheld (ref 10CFR2 700 CUNNINGHAM, R Pennsylvania State Univ 80/07/25 19
- G Inspection reports, IE Bulletins & correspondence
- 8007160806 Forwards 1E Circulat 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No writton response required ORIER, B.H. Region 1. Philadelphia, Office of the Director 80/06/24 1p
- 8007210134 Forwards IC Info Notice 80-24. "Low Lovel Radwaste Durial Criteria" No written response required GRIER.B H Region i. Philadelphia. Office of the Director 80/06/23 ip
- DOCKET 50-10 DRESDEN NUCLEAR FOWER STATION, UNIT 1

 D NRC Draft/final Covironmental Statements, supply & correspondence
- 8007100218 Responds to 800530 ltr requesting comments on DES NRC contentrates review of other agencies' EIS on areas of electric power natural gas & oil pipeline industries or where staff has special expertise in evaluating EIS HEIMEMANN, J M Federal Energy Regulatory Commission 80/06/12 Ip
- B007070263 Submits comments re DFG for preliminary cooling sys chemical decontamination at facility Recommends that NRC appoint commissions to examine decontamination process Findings should be discussed at public hearings PLANTIR L. Affiliation Unknown 80706/27 2pp
- 8007100215 Criticius NUREG-0686.DES re primary coeling sys chemical decentomination DES totally deficient & fails to address problems w/refurbishing non-nuclear power plants for elongated operating times

 LEWIS.M I Affiliation Unknown 80/06/28 ip
- 8007070264 Provides review of DES, May 1980 NUREG-OARS, re primary cooling sys chemica) decontemination Suggests environ monitoring section be added Personnel training adequately assures ALARA exposure levels
 WEAVER, C. L. HEW, Dept of, US Public Health Service 80/06/30 2pp
- 8007090269 Comments on NURES 0.686 re DES for decontamination of plant Where data is unavailable, programs should be undertaken to design & evaluate specific degradation procedures CRERAN, D.A. Princeton Univ. B0/07/01 2pp
- 8007160340 Ack receipt of DES in primary cooling sys chemical decontamination Disappointed that rept resterates stems originally raised about dangers accompanying operation & contains no new info re decontamination problem BANASZAK. L. J. Washington Univ. 80/07/01 4pp
- 6007180368 Submits concerns re decommissioning of facility Disappointed that DES does not address any new problems project will create NRC should consider isotopy migration to adequate experimentation of amount on radionuclides removed BANASZAK, L. J. Washington Univ. 80/07/01 4pp
- 8007230649 FOIA requist for five categories of documents re decontamination of facility GOLDSMITH.R Citizens for a Setter Environment 80/07/02 2pp
- 8007230932 Discusses DES reprimary coulding tys chemical decontamination at facility Polymer & ground are only containment for wastes Response to leaching problems is no reassuring Many double acist whollic safety at stake AYERS, P. J. Affiliation Unknown 60/07/08 2pp
- BOO7290185 Forwards NUREO-0616 to DES for primary cooling sys decontamination % related FR notice Comments must be received by 800721 EISENBUT, D G Division of Licensing 80/07/09 ip
- ---8007/280205 Protests against proposed decontamination scheduled for Mar Urges CIS be prepared & public hearings be held immediately RDSENTHALIA J Affiliation Unknown 80/05/13 ip

- 107220386 Comments on proposed NRC.DDE.DDW Chemical Co & util chemical decontamination demonstration project as described in draft Els.NUREG-GA86 Fipresses contern re possibility of accident, effort on workers & public DREY.K Affiliation Unknown 80/07/16 9pp
- 007220393 Comments on draft E15 on decontamination, NUREQ-0686 Document is rehath of old responses Bafety of proposed operation not ployen RUEKBLRO, B. Affiliation Unknown 80/07/16 4pp
- 007.220889 Submits comments on NUREG-0686.DEG for decontamination of facility Comparative data on leach rates solidification & rates between BNL & DOW should be shown in tabular form Info is currently unclear your lear YON ZELLEN, BW Northern Illinois Univ 80/07/16 Spp
- 307220538 Comments on NUREO-0686 draft environ statement re primary cooling sys chemical decontamination does not evaluate occupational or public radiation exposure resulting from serious vehicle accident during transport of nuclear waste OUTHLR W RPF foological Associates 80/07/17 lp
- 007230513 Forwards questions re May 1980 DES concerning primary cooling sys chemical decontamination Expresses doubt re NRC safety evaluation of area volcanic & seismic activity, citing previously documented readionuclide magration MCCAULEY. B K Affiliation Unknown 80/07/17 5pp
- 007230644 Partial response to FOIA request for five categories of documents re decentamination of facility Documents re Item 2 can be found in IC insp. repts in FDR Search is currently underbway for documents under Items 3 & 4 FELTON.J. M. Division of Rules and Records 60/07/17 2pp
- -8007230563 Distussus proposed plans for disposal of wastes from facility decontamination operation Provides detailed description of disposal method Disposal method found acceptable MARTIN J B Division of Weste Management 80/03/05 2pp
- --8007230478 Provides NRC agenda for solidification demonstration at facility
 JANCER, B B Commonwealth Edison Co 80/07/02 in
- 3007220540 Forwards comments on DES to chemical decontamination of facility DES inadequate to serve as model for similar decontaminations
 GOLDBUILDING Citizens for a Better Environment 60/07/18 2500
- 3007230524 Comments on DES to primary cooling sys chemical decontamination at Pacility DES falls short of being complete detailed & fully documented Public comment period should be extended Supportive into encl
 SHINEFLUG
- BOO728053/ Comments on DES re chemical decontamination DES is deficient & superfictal in analysis Euviron impact of futura decontaminations should be considered since decontamination of plant will serve as model GDLOSMITHER, GINSBURG, R Citizens for a Better Environment BO/07/18 24pp
- 8007300323 Comments on NUREG-0586, draft EIS Decument defective & does not adequately discuse passible alternatives to proposed action Rationals for need of proposed action not developed MONTAGUE.P National Campaign for Radioactive Waste Safety 80/07/20 16pp
- B007280595 Comments on NUREQ-0696. "DEB for Primary Bys Chemical Decentemination." Questions neccessity of preparation of environ statement for action which has minor impact on public & environ.considering cost involved JANECEK.R F. Commenwealth Edison Co. 80/07/21 Bpp
- 8007220491 Park LIS & requests info re positive & negative effects of using other decontaminating agents that might not contribute to increased indianoclide mobility LEVERING.R Affiliation Unknown 80/07/22 1p
- 8007250369 Forwards comments on NURCG-0686 to proposed removal of radioactive crud from interior of facility No justification for conclusion that no significant environ impact will result from decrudding COGOL.E Citiens Against Nuclear Power 80/07/23 11pp

- 8007270621 Discusses NUREG-0686, DES Anticipates no significant effect on forested land from decontamination projects Shutting down react; would result in const of alternate plant, w/ considerable effect on vegetation
 HERNOLBHEMIER Agriculture, Dept of, Forest Service 80/07/23 lp
- 8007270694 Forwards comments, correcting several inaccuracies in DEG for primary cooling sys chemical decontamination Recommends that NRC prepare generic EIS identifying available waste treatment & disposal options for other plants HEDEMAN.W N Environmental Protection Agency 80/07/25 3pp
- F Security, medical, emergency & fire protection plans
- B007010347 Forwards safeguards contingenty plan amend Plan withheld (ref 105FR 790)
 PEOPLES, D.L. Cummonwealth Edison Co. B0/06/27 1p
- B007240250 Discusoes review of fire protection mods Forwards evaluation status, evaluation of design details & review of Items 3 2 3, "Fire Water Sys Feeds" & 3 2 4. "Exposed Structural Steel "Addi Info requested within 30 days CRUTCHFIELD,D Operating Reactors Branch 5 80/07/09 9pp
- Q Adjudicatory correspondence
- 8007170323 Responds to 790920 petition re proposed chemical decontamination at facility & preparation of EIS Petition combined w/K Drey potition due to similarities EISENRUT.D g Division of Licensing 80/06/19 2pp
- --B007170330 Responds to 770319 petition requesting that E18 be prepared re-proposed chemical decontamination at facility Petition for action has been granted Public meeting will be held in vicinity of facility to discuss NRG findings
 DENTON, HR Office of Nuclear Reactor Regulation, Director 80706/26 2pp
- --8007170333 Director's decision under 2 206 determining that EI8 should be propared for facility decontamination DENTON,H R Office of Nuclear Reactor Regulation, Director BO/06/26 31pp
- --8007170336 Notice of issuance of director's decision under 10GFR2 206 raproparation of EIS for proposed decontamination of facility DENTON.H R Director 80/06/26 2pp
- 0007180072 Responds to 800313 patition re proposed chemical facility decontamination & preparation of EIS Petition was combined w/similar potition filed by K Drey on 790319
 EISENBUT D 0 Division of Licensing 60/06/19 2pp
- ---BOO7180187 Forwards petition requesting preparation of EIS.
 GOLDSMITH.R Citizens for a Better Environment. 80/03/13 2pp
- ---BOO7180212 Petition for preparation of E19 on proposed chemical decontamination is major federal action & significantly affects human environ GOLDSMITH: R Citizens for a Better Environment BO/03/13 4pp
- B0073i0243 Forwards Commission B00327 memorandum & order containing decisions on UCB 760502 petition for reconsideration of 760413 memorandum & order UCB 771104 petition sought action re fire protection for electrical tables EISENHUT.D 0 Division of Licensing 80/06/25 89pp
- 800/140337 Petition requesting bearings on ETB re chemical decontemination & on application for OL emend States interest of authors & K Drey, D Rorem & M Shineflug OOLDBMITH, R Citizens for a Detter Environment GOLDBMITH, R Prairie Alliance GOLDBMITH, R Illinois Bafe Energy Alliance 80/07/08 9pp
- H General correspondence
- E007020183 Responds to 800319 & 0414 ltrs re EIS preparation Recipient will receive director's decision under 10CFR2 206.EIS & NRC comments when available EIRENIUT, 0 G Division of Licensing 80/06/19 3pp
- ---8007020195 Bubmits questions re X Drey 790319 request & Citizens for Better Chylron 800313 petition for EIS on proposed decontamination GOLDSHITHER Citizens for a Better Environment 80/03/19 3pp

- --8007020203 Requests to be notified when decision is made re Cititens Per Better Environ & other groups' petitions for EIS on proposed decontamination GOLDSMITH,R Cititens for a Better Environment 80/04/14 2pp
- 8007140230 Responds to 800324 request for info re K Masterson 800318 ltr concerning burial of radwaste from plant in IL at disposal site in Deatty, NV Discusses disposal site conditions Draft EIS for decontamination encl W/o encl DIRCKS.W J DI Office of the Executive Director for Operations
- ---B007i4023i Forwards K Masterson B003i8 ltr re burial of radwaste from plant in IL at disposal site in Boatty.NV Requests findings & views LAXALT.P Senate B0/03/24 3pp
- 8007310022 Responds to E Gogek 800415 ltr to IL state wengtor Forwards copy of NRC response EIBENHUT, D Q Division of Licensing 80/07/10 ip
- -B007310025 Forwards DES & related FR notice, in response to ltr to IL State Senator RM Daley EISENHUT, D 0 Division of Licensing 80/07/10 ip
- P Operating license stage documents & correspondence
- 8007250558 Forwards NUREQ-0619, "TWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," for review & comment CRUTCHFIELD,D M Operating Reactors Branch 5 80/06/04
- 8007010146 Forwards final rule published in 800507 FR amending 10CFRSO 71 to require periodic updating of FSARs Compliance is not required until completion of SEP GRUTCHTIELD.D Operating Reactors Branch 5 80/06/10 5pp
- 8007020186 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/06/11 2pp
- 8007010042 Forwards NRC evaluation of GEP Topic V-5 re RCPB leakage detection Requests info concerning util as-built facility differing from licensing basis assumed in assessment CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/06/12 80/06/12 5pp
- 8007010R17 Forwards NRC evaluation of SEP Inpic VIII-4 re electrical penetrations of reactor containment Requests info concerning util as-built facility differing from licensing basis assumed in assessment CRUTCHFIELD, D M Operating Reactors Branch 5 80/06/12 10pp
- 8007010292 Forwards evaluation of SEP Topic V-12 A re water purity of NMR primary coolant Review rempleted & resulting evaluation will form input to integrated safety assessment unless changes are needed to reflect as-built Londitions GRUICHFIELD, D Operating Reactors Branch 5 80/06/12 3pp
- 8007100399 Responds to 800229 ltr which expressed opposition to ACRB recommendation to restructure SEP Role of licensees in program will expand ttr forwarded to Commissioners ENTON.H R Office of Nuclear Reactor Regulation, Director DENTON H R O 80/06/18 4pp
- --8007100420 Expresses apposition to ACRS recommendation to restructure SEP For SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFBTALL. A SEP Quarers Group 80702/29 2pp
- 8007020479 Confirms arrangements for WA Williams to review Dow Chemical proprietary info re formula for NS-1 polyent Info is being made available w/understanding that info will be withheld (ref 100FR2 790) CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/06/19 2pp
- 8007160459 Forwards "Loss of Offsite Power Survey Status Rept " Requests views re causes & possible remedies within 120 days
 CRUTCHFIELD, D M Operating Reactors Branch 5 80/06/19 2pp
- --BO07160463 "Loss of Offsite Power Survey Status Rept." Revision i BCHOLL, R F Systematic Evaluation Program Branch 80/06/17 9pp
- 8007070116 Submits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads JANECEK,R F Commonwealth Fdison Co 80/06/26 4pp

- 8007080063 Responds to NRC 800515 request for add; info concerning adequacy of station electric distribution sys voltages JANECEK, R F Commonwealth Edison Co 80/06/30 4pp
- 8007180436 Forwards evaluation of SEP Topic V-11 A to requirements for isolation of high & low pressure sys Requests notification of as-built facility differs from Jicensing basis assumed in assessment CRUTCHFIELD, D M Operating Reactors Branch 5 90/07/01 5pp
- 8007180438 Forwards evaluation of SEP Topic III-10 A re thermal overload protection for motor operated valves Requosts notification if as-built facility differs from licensing basis assumed in assessment CRUTCHFIELD.D M Operating Reactors Branch 5 #80/07/01
- 8007240275 Forwards avaluation of "SEP Topic VIII-7.DC Power Sys Bus Valtage Monitoring & Annunciation " Requests that NRC be informed if as-built facility differs from basis assumed in CRUTCHFIELD, D. Operating Reactors Branch 5 80/07/01
- B007250032 Forwards "Loss of Offsite Power Survey Status Rept " Replaces 800619 rept which amitted Table 4 CRUTCHFIELD D N Operating Reactors Branch 5 80/07/08 3pp
- --8007250035 "Loss of Offsite Power Survey Status Rept SCHOLL, R F Plant Systems Branch (Pre 791030) 80/0 80/07/08 10pp
- B007280076 Responds to 600318 ltr to J Ahearne objecting on behalf of IO/ZEMOV/A Mespanos to Buddid itr to o Americe objecting, on a dumers of plants under SEP review, to current plans for expedited roview of environ qualification of electrical equipment forwards applicable memorandum t order DENTON, H. R. Office of Nuclear Reactor Regulation. Director
- @ Imagection reports, IE Bulletins & correspondence
- 8007010605 Advises that IE Bullptin 79-01B, "Environ Qualification of Class IE Equipment," was sent to listed utils on 800116 CARROLL.D E Region 3. Chicago. Office of the Director 80/01/30
- 8007140845 Forwards IE Dullotin 80-13, "Cracking in Core Spray Spargors" Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/12
- 8007070072 Forwards IS Insp Repts 50-010/80-09,50-207/80-08 t 50-249/80-12 on 800407-0502 t notice of violation KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/23
- --8007070074 Notice of violation from insp on 800407-0502 * Region 3, Chicago, Office of the Director 80/05/2
- -B00707000B0_IE_Insp Repts 50-10/80-09.50-237/80-08 & 50-249/80-12 10/07/0080 it inap Repts 30-10/80-107-30-23/7/20-06 30-23/7/80 is on 800407-9502 Mancompliance noted failure to adhere to GA program requirements Contaminated clothing found lying inside controlled contaminated area SPESSARD.R L , IMARKER, J L , TONQUE, T M Region 3. Chicago, Office of the Director 80/05/23 7pp
- B007020065 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/05/28
- 8007010086 Forwards IC Info Notice 80-23, "Loss of Suction to Emargency Feedwater Pumps" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29
- 8007010150 Advises that IE lnfo Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps," was sent to listed utils on 800529 PAPPAS, H Region 3, Chicago, Office of the Director BO/05/30
- 8007020278 Advises that IE Info Notice 80-22, "Breakdowns in Contamination Control Programs," was sent to listed utils on 800528
 PAPPAS, H. Region 3, Chicago, Office of the Director 80/05/30
- 8007220156 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/06/10

- 8007020662 Forwards site-specific & generic questions re QE disc cracking indications per 800109 meeting & IE Info Notice 79-37 on Westinghouse low pressure turbines disc cracks Response requested within 30 days CRUTCHFIELD.D Operating Reactors Branch 5 80/06/11 Spp
- 8007140309 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability "Written response required
 KEPPLER, J G Region 3, Chicago, Defice of the Director B0/06/12
- 8007100004 Forwards response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies," No safety-iclated sys or component at Dresden 2 & 3 uses AH-90 or NH-90 scries hydramotor PEOPLES:D L Commonwealth Edison Co 80/06/16 3pp
- 8007030037 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLERJ G Region 3. Chicago. Office of the Director 80/06/1 Region 3. Chicago. Office of the Director 80/05/18
- 8007030052 Advises that IE Dulletin 80-15, "Possible Loss of Emergency Notification Sqs (ENS) W/Loss of Offsite Power," was sent to listed utils on 800618 PAPPAS.H. Region 3. Chicago. Office of the Director 80/06/19
- B007110200 Ack receipt of B00607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-010/80-08 DAVIS.A B Region 3, Chicago, Fuel Fatility & Materials Safety Branch B0/06/17 ip
- -8007i10206 Responds to NRC 8005i6 ltr re violations noted in IE Insp Rept 50-010/80-08 Corrective actions initiated daily sampling t analysis program for gross beta activity for svc water discharge from sphere PEOPLES.D L. Commonwealth Edison Co. 80/06/09 3pp
- B007230371 Forwards IE Insp Repts 50-010/80-10,50-237/80-09 & 50-249/80-13 on B00505-29 & notice of violation HEISHMAN.R F. Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/06/19 Zpp
- --B007230379 Notice of violation from imag on 800505-29
 Region 3, Chicago, Office of the Director 80/0
- --8007230388 IE Insp Repts 50-010/80-10,50-237/80-09 & 50-249/80-13 on 800505-29 Noncompliance noted failure to report events in accordance w/Tech Specs NARKER,J L. SPESSARD,R L. Region 3, Chicago, Office of the Director '800/06/19 9pp
- 9097020587 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/04/20
- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Persunnul " No written response required KEFPLER.J G Region 3, Chicago, Office of the Director 80/04/R4
- 8007140566 Advises that IE Builetin 80-16 % IE Circular 80-16 re Rosemount pressure transmitters & trip units were sent to listed utils on 800627 PAPPAS, H. Region 3, Chicago. Office of the Director 80/06/27
- B007230289 Forwards IE Bulletin 80-16. "Potential Misopplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Writter response required IE Circular 80-16 also enci No written response required KERRIED IN PROJECT OF ALSO WILLIAM BOYOGA RESPONSE PROJECT OF RESPONSE PROJECT BOYOGA 27

ning NRC of steps taken to . 50-010/80-09.

the Director BO/07/01

Repts 50-010/80-09, 50-237/80-08 & 50-247/80-12 Corrective actions improved mgt controls were implemented Radiation protection training classes were held for contractors REED, C Commonwealth Edison Co 80/06/13 App

- 8007180509 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Stram at BWR," will start at 12 Of AM on 800708 Test should be completed within 20 days Requests notification of malfunction (REPPLER.J G Region 3, Chicago, Office of the Director 80/07/0 80/07/07
- 8007250641 Responds to IE Bulletin 80-10. "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ " Any affected sys will be rostricted if Contamination found PEOPLES,D L. Commonwealth Edison Co. 80/07/07 2pp
- 8007250650 Forwards response to IE Bulletin GO-ii, "Masonry Wall Design " Requested investigation not performed at Dresdon. Unit i due to extended outage Requirements will be met prior to startup W/o encl Commonwealth Edison Co BO/07/07 2pp PEOPLES D L
- B007230638 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresden Unit 1 designs will be reviewed & Foaskbilly of performing radiographic examinations will be assessed before unit returned to svc PEOPLES, D.L. Commonwealth Edison Co. 80/07/09 7pp
- 8007310432 Forwards response to NRC 800611 request for info re turbine disc design & previous inspiresults Provides only info which was available within requested response time Remaining info will be provided prior to startup JANECEK, R F Commonwealth Edison Co 80/07/28 2pp
- R Periodic operating reports & related correspondence
- 8007180333 Forwards monthly operating repts for June 1980 STEPHENSON, B B Commonwealth Edison Co 80/07/09 1p
- --8007180336 Monthly operating repts for June 1980 CIESZIEWICZ-S Commonwealth Edison Co 80/07 80/07/02 2300
- U Congressional/Executive Correspondence
- 8007020082 Responds to 800512 inquiry re long-term storage of solidified wastes resulting from decontamination of primary cooling say Maste will be shipped to commercial low level waste burial site in either NV or WA DIRCKS.H J Diffice of the Executive Director for Operations DIRCKS, W J
- -8007020088 Requeste info about NRC action re long-term storage of soludified wastes resulting from decontamination of arimary cooling sys CORCORAN, T House of Rop 80/05/12 1p
- BOCKET 50-13 BADCOCK & WILCOX CD CRITICAL FACILITY G Inspection reports, IE Bulletins & correspondence
- 8007170137 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Bentheralized Water Sys & Resultant Internal Contamination of Personnel" No written response required, CAREILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/2
- DOCKET 50-20 MASSACHUSETTS INST. OF TECH. RES. REACTOR G Inspection reports: IE Bulletins & carrespondence
- 8007160825 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER B H Region 1, Philadelphia. Office of the Director 80/06/24 ip
- 8007210133 Forwards IE InPo Notico 80-24. "Low Level Radwaste Burial Criteria " No written response required GMIER.B H Region 1, Philadelphia. Office of the Birector. 80/06/25 | 19

- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 8007180254 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Cantamination of Persunnel" No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/24 ip
- 8007210474 Forwards IE Insp Rept 50-027/80-01 on 800609-10 No noncompliance noted Encl withheld (ref 10cFR2 790) NDRDERHAUG,L R Region 5: San Francisco, Safeguards Branch 80/07/10 2pp
- DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION
- F Security, medical, emergency & fire protection plans
- 8007080310 Requests clarification of NRC emergency plan concurrence schedule Facility revised draft emergency plan will be submitted by 800725

 KAY.J A Vankee Atomic Electric Go 80/04/30 ip
- 8007090233 Forwards Revision & to security plan Plan withheld (ref 10CFR2 /90) MDODY.D E Yankee Atomic Clottric Co E0/07/01 1p
- 8007280492 Forwards final revised emergency plan per NRC 800414 comments Requests prompt review KAY.J A Yankee Atomic Electric Co 80/07/25 ip
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCB 780902 petition for reconsideration of 780413 memorandum & order UCB 77104 petition sought action re fire protection for electrical cables EISENHUT, D 9 Division of Licensing 80/06/25 99pp Division of Licensing
- I Financial information
- B007010404 Forwards util 1780 internal cash flow projections in order to meet retrospective premium guarantee requirements under Price-Anderson Act Vankes Atomic Electric Co 80/06/25 4on SDUCY, A.R.
- P Operating license stage documents & correspondence
- 8007160421 Forwards Amend 60 to Litense BPR-3 & notice of issuance & CRUTCHFIELD, D M Operating Reactors Branch 5 80/06/02
- --8007i60425 Amond 60 to License DPR-3 adding surveillance requirements for auxiliary feedwater sys in Section 3/4 7 2 CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 Opp
- --8007160427 Notice of issuance & availability of Amend 60 to License CRUTCHFIELD, D. Operating Reactors Branch 5 80/04/02 2pp
- 8007010118 Forwards final rule published in 800309 FR amending IOCFR50 71 to require periodir updating of PSARs Compliance is not required until completion of SEP CRUTCHFIELD. D Operating Reactors Branch 5 80/06/10 5pp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance
 EISENHUT, D G Division of Licensing 80/06/11 62pp
- 8007180530 Confirms 800424 mgt meeting at site re assessment of regulatory performance of facility GRICR, II H Region 1. Philadelphia, Office of the Director 80/06/16 2pp
- B0072B000B Requests add1 info re NRC requirements for auxiliary feedwater sys Review status encl Requests response within 30 days of receipt of itr LAINAB.0 C Assistant Director for Safety Assessment B0/06/16

- 8007100399 Responds to 800229 ltr which expressed apposition to ACRS recommendation to restructure SEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp
- ~-8007100420 Expresses opposition to ACRS recommendation to restructure SEP for SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFSTALLR SEP Quiners Group 80/02/29 2pp
- 8007180466 Forwards evaluation of SLP Topic VIII-4 re electrical penetrations of reactor containment Requests notification if as-built facility differs from licensing basis assumed in assessment CRUTCHFIELD, D. M. Operating Reactors Branch 5 80/07/01
- 8007250001 Requests submittal of application for amend to license consisting of Yach Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items entl for guidance EISENHUT.D O Division of Licensing 80/07/02 67pp
- 8007080079 Provides specific life or auxiliary feedwater pump endurance test All parameters remained within normal operating ranges throughout test Drawings & charts encl KAY, J A Yankee Atomic Electric Co 80/07/03 Bpp
- B007140300 Submits results of review ro anchorage sys for safety-related electrical equipment listed in encl IE Info Notice B0-21 & observations heightened awareness of Jeaving free standing nonseismic auxiliary items around when not in use KAY, J A Yankee Atomic Electric Co 80/07/09 3pp
- 8007140338 Forwards YOBAP-1-A. Revision 8. per NRC 800702 request Also forwards document change instructions for removing & inserting correct pages HEIDERIL R Yankee Atomic Electric Co 80/07/07 2pp
- --8007140342 Advises that YBGAP-I-A. Revision B. is acceptable Programmatic changes should be submitted to NRC for review prior to implementation Requests that itr replace 800410 ltr & rept be renumbered w/revision & submitted to NRC HAASS. W.P. Quality Assurance Branch 80/07/02 ip
- 8007280076 Responds to 800318 ltr to J Ahearne objecting on behalf of owners of plants under SEP review to corrent plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON.H R Office of Nuclear Reactor Regulation. Director 80/07/16 App
- B007280621 Forwards revised description of proposed vent sys for both reactor vossel head % pressurator Vessel head vent will be piped directly to containment atmosphere Equipment will be installed B10101 Yankee Atomic Electric Co 80/07/22 5pp
- BOO7RB0439 Submits alternate method of mitigation effects of grid dogradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENDURGED Yanker Atomic Electric Co 80/07/24 7pp
- BOO72805B& Discusses commitment to install containment hydrogen monitor by 810101 Describes compliance w/NRC 791030 ltr Sys will be composed of Bendix analyser & Commitment Inc. Holm 1 K-111 thermal conductivity analyser KAY.J A Yankee Atamic Electric Co. 80/07/P4 Ppp
- B007280626 Requests that evaluation of proposed mode, re tessons Learned task force Category B items be completed by 800701 Further delays in evaluation may result in inability to meet 810101 Yankee Atomic Electric Co 80/07/24 App
- Q Inspection reports. IE Buildtins & correspondence
- 8007020101 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/05/28 ip
- 8007010288 Forwards IC Info Notice 80-2). "Lose of Suction to Emergency Feedwater Pumps" No written response required GRIER, B H. Region 1. Philadelphia. Office of the Director 80/08/29 ip

- 00/18009/ Submits reply to IE Bulletin 80-12 re decay heat removal operability Plant procedures were analyzed for adequacy of safeguards agoinst loss of redundancy & diversity of decay heat removal sys heat removal sys VANDENBURG.D E Yankee Atomic Electric Co 80/06/09 4pp
- 007010057 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Tanks used for low pressure process or holdup purposes are adequately protected against vacuum conditions MQODY, D & Yankee Atomic Electric Co. 80/06/10. 2pp
- 007210626 Forwards IE Info Notice 80-26, "Evaluation of Contractor 9A Programs " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/06/10 | Ip
- 007160370 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response crequired GRIER, D. H. Region 1. Philadelphia, Office of the Director
- 007170116 Forwards response to 1E Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls "Circuit mode will be made to proclude automatic reset of safety-related equipment from emergoncy mode as result of resetting ESF signal VANDENBURGH, D E Yankee Atomic Electric Co 80/06/12 3pp
- 007020706 Forwards IE Bullotin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER, B. II Region 1. Philadelphia, Office of the Birector 30/06/18 | Ip
- 007170582 Responds to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies" No ITT General Controls AH-90 or NH-90 Series hydramotor actuators used in safety-related sys MODDY. D. E. Yankee Abomic Electric Co. 80/06/18. 1p
- 007180144 Forwards reply to IE Bulletin 79-27 re loss of non-Class IE instrumentation & control power Performed review & evaluation of power supplies which could affect ability to achieve cold shutdown MOODY, D E Yankee Atomic Electric Co. 80/06/18 15pp
- 00/020530 Forwards IE Circular 80-15. "Loss of Reactor Coulant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER.9 II Region I, Philadelphia. Office of the Director
- 007160752 Forwards IE Circulat 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORICE, IH Region 1. Philadelphia. Diffice of the Director 80/06/24 1p
- 007210291 Forwards IC Info Notice 80-24, "Low Level Radwaste Burial Criteria "No written response required dRIER.D H Region i, Philadelphia. Office of the Director 80/06/23 tp
- 007210505 Informs of affirmative findings in response to IE Builetin 80-08 re existence of flued head designed penetration connections Addl stems concerning penetration assemblies leo discussed Yankee Atomic Electric Co 80/05/25 in MOODY, D E
- 007230189 Forwards IE Bulletin BO-16. "Potential Misapplication of Resembunt Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Gutput Codes." Written response required II Circular 80-16 also enc) No written response required GRIER.D H. Region 1. Philadelphia. Office of the Director ORIER, D.H. Re 80/06/27 Rpp
- 307210002 Advises that IE Bulletin 79-17 reporting requirements for LER 80-12 re linear indications are no longer applicable
 Internal liquid peretiant examinations of internal surfaces
 confirm no through-wall defects
 AUTIO-H A Yankee Atomic Electric Go 80/07/02 ip
- 007250273 Submits reply to IF Nulletin 80-10 re contamination of nonradioactive sys & potential for release Present sampling frequency will promptly identify any contamination MOODV. DF Yankoe Atomic Ejectric Co. 80/07/07 2pp
- 007250278 Submits reply to IE Bulletin 60-11 re makanny wall design No further justification for use of codes as basis of re-evaluation criteria is required HEIDER: LH Yankee Atomic Electric Co 80/07/08 App

- R Periodic operating reports & related correspondence
- 8007210399 Forwards "Effluent & Waste Disposal Semiannual Rept. Jan-June GROCE, R. H. Yanken Atomic Electric Co. 79/08/29 1p
- ~~8007210405 "Effluent & Wasto Disposal Semiannual Ropt.Jan~June 1979 "
 * Yankeo Atomic Electric Co 79/08/29 lipp
- 8 Reportable occurrences. LERs & related correspondence
- 80070/0284 RD 80-12 during liquid penetrant examinations of piping, two linear indications were found on weld used to join valve to schedule 10 coupling Valve will be removed to examined AUTIO.H A Vanker Atomic Electric Co 80/06/27 Ip
- DOCKET 50-47 ARMY MATERIALS RESEARCH REACTOR
- G. Inspection reports, IC Bulletins & correspondence
- 800/160832 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sqs & Resultant Internal Contamination of Personnel " No written response required RRIER, B Region i. Philadelphia. Office of the Director 80/06/24 ip
- 8007210151 Forwards IE Info Notice 80-24, "Low Level Radweste Burial Criteria " No written response required GRIER.B H Region I, Philadelphia, Office of the Director 80/06/25 Ip
- DOCKET 50-54 UNION CARDIDE RESCARCH REACTOR
- F Socurity, medical, emergency & fire protection plans
- 80072300Bi Requests resolution of outstanding fee issues for certain physical security-related documents & emergency plans Memodtd 770910 re 790220 guard training plan submitted by GA Co License Fee Management Branch 80/07/16 200
- O Inspection reports. IE Bulletins & correspondence
- 8007160849 Forwards IF Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 lp
- 800721014/ Forwards IE Info Notice 80-24, "Low Lovel Radwaste Burial Criteria" No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/66/25 1p
- 8007300038 Ack receipt of 800428 ltr in response to NRC 800407 notice of violation & notice of propused imposition of civil panalities Also forwards order imposing civil monetary penalty STELLO, V NRC Regional Offices 80/07/11 2pp
- --8007300040 Order imposing civil monotary penalty re-noncompliance noted in IE Insp of facility on 800102-29 App A, evaluation & conclusion encl STELLO, V NRC Regional Offices 80/07/11 Spp
- 8 Reportable occurrences, LERG & related correspondence
- 8007230148 EN-80~012A on 800711, order imposing civil penalty of \$1,000 was issued After consideration of licensee response, IE concluded that one item of noncompliance did occur BROCKETT-T W , THOMPSOND Office of Inspection & Enforcement, Office of the Director 80/07/11 ip
- DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR G. Inspection reports. IE Bullotins & correspondence
- B007160827 Forwards IE Circular B0-14, "Radioactive Contamination of Flant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required GRIER, B II Region 1. Philadelphia. Office of the Director B0/06/24 | 1p

- 8007210140 Forwards IE Info Notice 80-24, "Low Level Rudwaste Burial Criteria" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/25 ip
- R Periodic operating reports & related correspondence
- 8007280654 Annual rept of changes, tests & experiments for Jul 1979-ORLOSKY, P M New York, State Univ of, Buffalo 80/07/22 ip
- 8007290674 Provides rept for Jul 1979-June 1980 re changes experiments & tests conducted W/o prior NRC approval per License R-77 None conducted
 ORLOSKY,P M New York, State Univ of, Buffalo 80/07/22 In

- DOCKET 50-59 TEXAS AWN UNIV RESEARCH REACTOR A Periodic operating reports & related correspondence
- 8007210502 Furwards "Annual Operations Ropt of TY ASM Univ AGN~201M Training Reactor," for June 1979-May 1980 COCHRAN,R 9 Texas A & M Univ 80/07/11 1p
- --B007210812 "Annual Operations Rept of TX A&M Univ AGN-201M (raining Reactor," for June 1979-May 1980
 ZOLICZYNSKI, J B. CDCHRAN.R O Texas A & M Univ B0/07/11 9pp
- B007240038 Forwards "Annual Operations Rept of TX A&M Univ AGN-204M Training Reactor" June 1979-May 1980 COCHRAN R 0 Yexas A & M Univ 80/07/11 1p
- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR F Becurity, medical, emergency & fire protection plans
- 8007210429 forwards physical security plan & proposed changes to Tech Specs Plan withhold (ref 10CFR2 790) SHRIVER.B L. Virginia, Univ of 80/07/15 2pp
- --8007210433 Tech Specs 3 3.4 1.4 2.4 8.6 P & 6 3 re safety limits. limiting conditions for operation & surveillance requirements * Virginia, Univ of 80/07/15 9pp
- 4 Inspection reports. IE Bulletins & correspondence
- 8007170173 Forwards IE Circular 80-14, "Radioautive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'RELLCV.J P Region 2. Atlanta, Uffice of the Director 80/06/24
- DOCKET 50-67 MCMASTER UNIV RESEARCH REACTOR
- R. Periodic operating reports & related correspondence
- 8007020370 Responds to NRC 800502 request for plant personnel exposure & monitoring rept
 MAXWELL,L V Army, Dept of BO/05/14 ip
- --8007020375 Forwards 1979 personnel exposure & monitoring rept MAXWELL, L V Army, Dept of 80/03/19 ip
- --8007020382 Rept of recorded personnel whole body exposures for 1979

 * Army Dept of 80/03/19 lp
- DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR
- 9 Adjudicatory correspondence
- B00702046B Forwards May 1980 safety evaluation re CETR BWANSON, D T Hearing Branch 1 D0/06/27 1p
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8007180609 Comments on GETR data NRC & USGS have prepared studies which favor shutting down facility Most dangerous condition is assumed as being in existence, but no steps have been taken to correct condition PHILBRICK. 8 8 Philibrick. 8 8 80/06/07 1p

- P Operating license stage documents & correspondence
- 8007160360 Advises that landslide investigation program began on 800623 & final rept will be submitted to NR(between 800815-29 Monitoring program not intended to provide data for evolution before issuance of landslide stability SER suppl DARMITZEL.8 W General Electric Co. 80/07/67 2pp
- 8007240399 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles positions & aveignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08
- 8007220349 Forwards response to NRC 800610 request for info demonstrating ability of GETR to meet loadings associated w/ design bases specified in NRC 800523 safety evaluation Six consultant repts encl DARMITZEL.R W General Electric Co 80/07/17 3pp
- --8007220353 "Structural Swismic Investigations of GETR," summary rept
 # Engineering Decision Analysis Company, Inc EDAC-117-258 02
 80/07/08 43pp
- ---8007220356 "Add1 Investigations to Determine Effects of Vibratory Motions Due to Earthquake on Calaveras Fault," Revision 1 * Engineering Decision Analysis Company, Inc. EDAC-117-253 02 Ri 80/06/30 11pp
- -B007220362 "Expanded Description of Soil Pressure Analyses," Suppl 1 to "Addl Investigations to Determine Effects of Combined Vibratory Notions & Surface Rupture Offset Due to Earthquake on Postulated Verona Fault." Revision 1 & Engineering Decision Analysis Company, Inc. EDAC-117-253 OI R1 S 80/06/27 24pp
- --8007220366 "Evaluations for 0 6 Gravity Ground Acceleration Case."
 Suppl 2 to "Addl Investigations to Determine Effects of
 Combined Vibratory Motions to Surface Rupture Offset Due to
 Earthquake on Postulated Verona Fault." Revision 1
 f Engineering Decision Analysis Company. Inc EDAC-117-293 01 R1
 8 80/06/30 15pp
- --8007220369 "Review of Seismic Adequacy of Piping & Equipment, GETR "
 # Engineering Decision Analysis Company, Inc. EDAC-117-258 01
 80/06/30 10pp
- ---B007280372 "Combined Parameter Probability Analysis.OETR" * Jack R Benjamin & Associates.Inc 111-017-02 80/0 16pp 80/07/18
- 9007290007 Nutification of 800730 meeting w/GE in Bethesda, MD for licenses presentation of addl GETR structural evaluations NELSON, C C Licensing Branch 3 80/07/23 3pp
- E007280577 Forwards memo describing slope menitoring program initiated in Apr 1980 Monitoring sys designed to detect ground movements of several inches or more which might accompany reactivation of landslide complex Afridavit enci QILLILAND,DL General Electric Co 80/07/25 7pp
- 8007280637 Discusses landslade stability investigation Field exploration phase complete Gummary rept entl to verify that field work performed will provide satisfactory samples to determine adjacent hall stability under present conditions GILLILAND.D.L. General Electric Co. 80/07/25 4pp
- O Inspection reports. IE Bulletins & correspondence
- B007180305 Forwards IE Circula: 80-14, "RadioActive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Porsonnel " No written response required ENDELKEN,R H. Region 5, San Francisco, Office of the Director 80/06/24 1ρ
- DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR Q Inspection reports, IE Bulletins & correspondence
- 8007220330 Forwards IE Insp Rept 50-073/80-02 on 800421-22 No noncompliance nuted CREMS.J L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/06/04 2pp

- *800/220337 IC Into Rept 50-0/3/80-02 on 800421-22 No noncompliance noted Major artis inspected logs records review audit functions uperator requalification training facility procedures, surveillance it experiments ZWETZ10.G B Region 5. San Francisco. Office of the Director FAMLKENBERRY.B Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/06/03 6pp
- 1007180305 Forwards JE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELWEN,R H. Region 5, San Francisco, Office of the Director 80/06/24 1p
- OCKET 50-7/ CATHOLIC UNIV OF AMERICA RESEARCH REACTOR
- 007160792 Forwards IE fircular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80706724 1p
- 007810126 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required Offer. B H Region 1, Philadelphia. Office of the Director 80/06/25 |
- ICKET 50-83 UNIV OF FLORIDA TRAINING REACTOR
- Inspection reports. IE Bulletins & correspondence
- 707170166 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Domineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/24
- ICKET 50-87 HLS7INGHOUSE CRITICAL EXPERIMENT
- Inspection reports, IE Bulletins & correspondence
- 307280454 Forwards IE Insp Rept 50-087/80-04 on 800410-11 No noncompliance notes DAVIG.A B Region 3. Chicago: Fuel Facility & Materials Safety Branch 80/04/23 2pp
- U00/280457 IF Insp Rept 50-087/80-04 on B00610-11 No noncompliance noted Major areas inspected emergency planning including training, drills, alarms & evacuation procedures ORECE, R. J. FSSIG, T. H. Region 3, Chicago, Diffice of the Director 80/06/19 App
- 07170626 Forwards 1E Circular 80-14, "Radioactive Contamination of Plant Duminovallind Water Siys & Resultant Internal Contamination of Personnel " No written response required KEPPLER J G Region 3. Chicago. Office of the Director 60/06/24
- CKET 50-69 GENERAL ATOMIC CO
- Security, medical, emergency & fire protection plans
- OPENOBIL Requests Lemilution of outstanding for leaves for contain physical sociurity-related documents & weergency plans Memorated dtd 790910 re 790220 gward training plan obbaitted by GA Co never answered
 MILLER. N. D. License Fee Nanagement Branch 80/07/16 2pp
- Inspertion reports, IE Bullotins & correspondence
- 07180274 Forwards IE Circular 80-14, "Radioartive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel "No written response required ENGELWEN.R H Region 5, San Frantisco. Office of the Director BO/06/24 is

- DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR
- G. Inspection reports: 1E Bulletins & correspondence
- 8007160803 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " Nu written response required GRIER, B H Region i. Philadelphia. Office of the Director 80/06/24 ip
- 8007210155 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER. I M Region), Philadelphia, Dffice of the Director 80/06/25 ip
- DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR
- G Inspection reports, IE Bulletine & correspondence
- 8007170137 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " No written response required Circulary J P. Region 2. Atlanta, Office of the Director 80/06/24
- DOCKET 50-106 DREODN STATE UNIV
- Q Inspection reports. IE Bulleting & correspondence
- 8007240361 Forwards IE Insp Repts 90~106/80~02.50~243/80~03 & 70~0971/80~01 on 800630~0701 No noncompliance noted Encis withheld (ref 10CFR2 790) NORDERHAUG, L.R. Region 5, San Francisco, Safeguards Branch 80/07/14 2sp
- 8007150599 Forwards "Final Decommissioning Rept.OR State Univ AON-201 Reactor, License R-51 " Describes changes to physical security plan required in conjunction w/decommissioning WANO.C H Oregon State Univ 20/07/10 3pp
- --B007150562 "Final Decommissioning Rept.OR State Univ AGN-201 Reactor License R-51 "
 * Bregon State Univ B0/07/09 LOpp
- DDCKET 50-111 NORTH CAROLINA BIATE UNIV RESEARCH REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8007170164 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Domineralized Water Sys & Resultant Internal Cantamination of Personnel " No written response required O'REILLY.J.P. Region 2, Atlanta, Office of the Director, 80/06/24
- DOCKET 50-112 UNIV OF OKLAHOMA REBEARCH REACTOR
- G Inspection reports. IE Bulletins & correspondence
- 8007180282 Forwards II Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel" No written response required ENGELMENTRY Region 5, San Francisco. Office of the Director 80/06/24 tp
- DOCKET BO-116 IOWA STATE UNIV RESEARCH REACTOR
- O Inspection reports, IE Bulletins & correspondence
- 8007170629 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J. G. Region G. Chicago, Office of the Director 80/06/24 in
- DOCKET 50~123 UNIV OF MISSOURI RESEARCH REACTOR
- Q Inspection reports. IE Bulletine & correspondence
- 8007170646 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24

- 8007220122 Ack receipt of IE Gircular 80-14 & distribution to demineralized water sys staff PLANJE, T J Missouri Univ of Rolla 80/06/30 lp
- DOCKET 50-124 VIRGINIA POLYTECH INST TRAINING REACTOR
 P Operating license stage documents & correspondence
- 8007230498 Forwards proposed Tech Specs & operator requalification program for research reactor per License R-62 CURTNER, A P Virginia Tech 80/0//18 Spp
- --8007230803 Proposed Tech Specs.App A.re safety limits & limiting safety sys settings. Limiting conditions for operation.surveillance requirements.design features & administrative controls * Virginia Tech 80/07/18 33pp
- A Inspection reports, IE Bulletins & correspondence
- 8007170181 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/24
- DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR

 R Periodic operating reports & related correspondence
- 8007290468 Ferwards ORO-4207-13, "Sixteenth Progress Rept of TX A&M Univ Nuclear Science Ctr." 1979 RANDALL.J D Texas A & M Univ 80/07/25 1p
- --8007290475 "Sixteenth Progress Rept of TX A&M Univ.Nuclear Science Ctr." 1979 BATES, C. F., FELTI, D. E., TAFT, J. P. Toxas A & M Univ. CRO-4207-13 BO/06/30 BOpp
- DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR

 O Inspection reports, 16 Bullstins & correspondence
- 8007170185 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultent Internal Contamination of Personnel" No written response required 8/REILLY, J P. Region 2. Atlanta, Office of the Director 80/06/24
- DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D Q Division of Licensing 80/06/25 89pp
- 8007300340 Renews 800606 request for all repts prepared by TERA Corp Related correspondence BROWNLJ Janes, Brown & Clifford 80/07/02 2pp
- 8007180398 Forwards Hoodward-Clyde Consultants 800701 itr outlining status of geologic & seismic investigations re facility & status of work accomplished during May & June, 1980 per ASLB 790619 order Certificate of Svc enc1 FURBUSH.M.H., CRANE,P.A., LOCKE,R.F. Pacific Cas & Electric Co 80/07/15 & don
- 8007250386 Advises that info & repts requested in 800606 & 0702 ltrs were not included in agreement for informal discovery reached at 800603 hearing lngo will be incorporated w/Woodward-Clude filing to be made by 801001 LOCKE,R F Pacific Gas & Electric Co 80/07/18 2pp
- P Operating license stage documents & correspondence
- 8007100049 Notification of 800507 meeting w/util in Rethesda.MD to discuss proposed continuation & examing preliminary results of seismic & geologic investigation ROONEY.V L Operating Reactors Branch 3 80/04/28 lp

- 8007010469 Responds to 800507 ltr re addl TM1-2 requirements Schedule for meeting requirements will be proposed following resolution of seismic issues

 CRANE.F A Pacific Gas & Electric Co 80/06/26 lp
- Q Inspection reports, IE Bulletins & correspondence
- B00725066B Responds to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Schedule for submittal of info will be proposed when seismic issues currently under study have been resolved CRANE.P A Pacific Gas & Electric Co. 80/03/05 in
- B007230662 Responds to IE Bulletin 80-03 Util does not use charcoal tray adsorber cells CRANE.P A Pacific Gas & Electric Co 80/03/31 ia
- 8007230016 Forwards response to IE Bulletin B0~02 Feedwater spargers & thermal sloves mfg by Marvin Engineering Co are not used in facility CRANE,P A Pacific Gas & Electric Co 80/04/22 3pp
- BOO7140584 Forwards IE Bulletin BO-13., "Cracking in Core Spray Spargers" Written response required ENGELMENT E Region 5, San Francisco, Defice of the Director BO/03/12 ip
- 8007020242 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required ENGELKEN,R H Region 5, San Francisco, Dffice of the Director B0/05/2B ip
- BOO7220237 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required ENGELKEN, R H Region 5, Ban Francisco, Office of the Director BO/06/10 ip
- 8007140412 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " Written response required ENGELKEN,R H Region 5, Sap Francisco, Office of the Director 80/06/12 ip
- B007170084 Forwards IE Insp Rept 50-133/80-02 on 800520-22 No noncompliance noted CREMS.JL Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/06/12 2pp
- --800717008B IE Insp Rept 50-133/80-02 on 800520-22 No noncompliance noted Major areas inspected operations organization & administration, follower on IE bulletins & circulars & insependent insp CARLSON, J D , MORRILL, P J Region 5, San Francisco, Office of the Director STERNBERG, D Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/06/10 App
- 8007020474 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required EMSELKEN, R H Region 5, San Francisco, Défice of the Director 80/06/20 ip
- 8007180287 Forwards IE Circular 80-14, "Radioartive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required ENGELKELS H Region 5, San Francisco, Office of the Director 80/06/24 1p
- 8007230397 Forwards IE Bulletin 80-16. "Potential Misapplication of Resemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required E Circular 80-16 also encl No written response required ENGELMEN, R H. Region 5, San Francisco, Office of the Director 80/06/27 1p
- 8007310468 Responds to 1E Bulletin 80-11 re masonry wall design Resolution of problems will be performed following completion of geologic investigation CRANE,P A Pacific Gas & Electric Co 80/07/10 ip
- A Periodic operating reports & related correspondence
- 8007150568 Forwards monthly operating rept for June 1980 MEEKS.E D Pacifir Gas & Electric Co 80/07/07 ip
- --B007150573 Monthly operating rapt for June 1980 BAUN.P W Parific Gas & Electric Co 80/07/03 App

OKET 50-134 MORCESTER POLYTECH INST. RESCARCH REACTOR
Inspection reports: IE Bulletins & correspondence

07160820 Forwards IC Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No unitten issponse required GRICE, 8 H. Region I. Philadelphia, Office of the Director 80/06/24 lp

07210144 Forwards IE Info Notice 80-24, "Low Level Radwasto Burial Criteria" No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 80/06/25 lp

GRET 50-135 WALTER REED RESEARCH REACTOR

Operating liquise stage documents & correspondence

07100379 Responds to 800227 its which expressed opposition to ACRS recommendation to restructure SEF Role of licenaees in program will espand Ltr forwarded to Commissioners DENTON-H R Office of Nuclear Reactor Regulation. Director 80/04/18 4pp

8007100420 Expresses opposition to ACRS recommendation to restructure SEP For SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFSTALL, R SEP Owners Group 80/02/29 2pp

CRET 50-139 UNIV OF WASHINGTON RESCARCH REACTOR

Inspection reports. IE Bulletins & correspondence

07180267 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required ENGELKENR H Region 5. San Francisco, Office of the Director 80/06/24 lp

07310523 Forwards IR Insp Rept 50-139/80-03 on 800511 No noncompliance noted Encl withheld (ref 10CFRZ 790) NOBBERHAUGL R Region 5, San Francisco, Bafeguards Branch 80/07/22 2pp

ICKET 50-142 UCLA TRAINING REACTOR

Security, medical, emergency to fire protection plans

107160240 Forwards Amend 1 to physical security plan for protection of SNN of moderate strategic significance Plan withheld (ref 10CFR 790) CATTON-I . WEGST.W California, Univ. of, Los Angeles 80/07/03

Adjudicatory correspondence

NOTO 90197 Response to Committee to Bridge the Gap June 1980 potition to intervene Patitioner relied on case law not wholly applicable to instant action Allegations re appects are not specified w/clarity & detail W/Certificate of Evr HELWICKS C. REIDMARS D. L., HELWICKS C. California, Univ. of, Los Angeles 80/07/07 13pp

07250708 Order schuduling 800718 prehvaring conference in Log Angeles CA Committee to Bridge the Cap suppl to 800522 petition to intervene must be served by 8000818 2 Univ of CA response by 800702 Public invited w/o limited appearance BOMERS E S Atomic Safety and Licensing Board Panel 80/07/21

Inspection reports. IE Bulletins & correspondence

107180R61 Forwards IE Circular 80-(4. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELERNR H Region 5. Gan Francisco, Office of the Director 80/06/24 lp

DOCKET 50-130 ONLO STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

8007020169 Advises that 800110 revision of security plan has been approved Forwards Amend 9 to License R-75 identifying currently approved security plan MILLER.J R Standardization & Special Projects Branch 80/06/16 2pp

--800/020174 Amend 9 to License R-75 identifying currently approved physical security plan
MILLER, J R Standardization & Special Projects Branch 80/06/16
2pg

G Inspection reports, IE Bulletins & carrespondence

8007170636 Forwards IE Circuler 80-14, "Radioactive Contamination of Plant Demineralized Nater Bys & Resultant Internal Contamination of Personnel "No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/06/24

8 Reportable accurrences, LERs & related correspondence

B0070107B7 informs that reportable noncompliance item exists involving Tech Spec & 1 Air conditioner for multichannel analyzer room not tied to emergency switch in control room Action initiated to have air conditioner tied to control room REDMOND.R F Oblo State Univ 80/06/17 2pp

DOCKET 50-191 UNIV OF ILLINOIS RESEARCH REACTOR

Q Inspection reports, JE Bulletins & correspondence

6007170644 Forwards IE Circular 80-45, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J C Region 3, Chicago, Diffice of the Director 80/06/24 to

DOCKET 50-152 FLORIDA WEST COAST NUCLEAR GROUP INC

O Inspection reports. IE Bulletins & correspondence

8007170638 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER.) 9 Region 3. Chicago. Office of the Director 80/06/24 is

BOCKET 30-188 BIG ROCK POINT NUCLEAR PLANT F Hecurity, medical, emergency & fire protection plans

8007220566 Forwards revised site emergency plan for final NRC approval All requested changes & revisions, including App M, have been made Revised Palisades sate emergency plan will be forwarded within wk M/o oncl
JURY.M J Consumers Power Co 80/06/09 ip

8007230478 Forwards revised emergency plan. App M HARTMAN.C J Consumers Power Co 80/06/12 ip

--8007230479 Revised emergency plan: App M * Consumers Power Co H0/06/01 18pp

8007170042 Notifies that FCMA/NRC steering committee reconsidered size of emergency planning zone for water cooled reactors of less than 250 MW thormal & adopted encl position Proposed rule & NURGO/OS54/FEMA-HED-1 will be modified in conformance CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/13 3pp

8007010473 Distusses proposed change to 10CFR50 adding requirement for fire protection plan at facilities Forwards comments on rule supplementing consultant comments Questions appropriateness of rule isince rule reopens resolved issues HOFFMAN.D P Gonsumers Power Co 80/06/27 8pp

6007140391 Forwards Revision 2 to 790220 security plan Plan withheld (ref 100FR2 790) HOFFMAN D P Consumers Power Co 60/07/06 1p

- 8007250406 Forwards scenario of emergency exercise conducted on 800624 at Big Rock Point Util has agreed to critique exercise & provide action plan to identify deficiencies & indicate corrective actions AXELSON, W L Emergency Preparedness Licensing Branch 80/07/11
- 800722034! Forwards add! info re switability, training & qualification plans, in response to NRC 800515 & 0606 requests Info witabald (ref 10CFR2 790)
 HOFFMAN, D.P. Consumers Power Co. 80/07/17 1p
- B007280870 Responds to 791129 request for info me evacuation time estimates in site emergency plan Evacuation clear time for O- to 10-mile area around Palisades estimated at approx 2 hrs in summer & winter HDFFMAN.D P Consumers Power Co 80/07/23 1p
- 8007300439 Forwards revised safeguards contingency plans Plans withhold (ref 10CFR2 790) HOFFMAN,D P Consumers Power Co 80/07/24 1p

Q Adjudicatory correspondence

- 8007310243 Forwards Commission 80052/ memorandum & order containing decisions on USS 780502 petition 60052/ memoransum & preef consideration of 780413 memorandum & order USS 771104 petition sought action reference protection for alectrical cables EIBENHUT, D Q Division of Licensing 80/06/25, 89pp
- 8007100033 Forwards Christa Maria second set of interrogatories in spent fuel pool expansion proceeding MS Jordan 800626 ltr to J Gallo & affidovits encl Related correspondence JORDAN.W S Sheldon, Harmon & Weiss 80/06/26 5pp
- --8007100037 Becond set of interrogatories directed to util Requests identification of witnesses intended to be called recontentions of ASLB 800117 order & questions of ASLB 800327 memorandum & order Related correspondence JORDAN, W S Christa-Maria JORDAN, W S Bheldon, Harmon & Weiss 80/04/26 12pp
- --8007100042 Interrogatories directed to NRC Requests identification of witnesses intended to be called re contentions of ASLB 800117 order & questions of ASLB 800327 memorandum & order Certificate of Bvc encl Related correspondence JURDAN, W 8 Christa-Maria JORDAN, W 8 Sheldon, Harmon & Weiss 80/06/26 Spp
- 8007110556 Ack receipt of 800401 telegram submitted on behalf of Concerned Citizens for Charlevoir Arosa requesting immediate shubdown of plant Notice of petition will be published in FR PR DENTON: D R OI Office of Nuclear Reactor Regulation, Director
- ~-8007110563 Notice of request for action on 800401 patition filed on behalf of Concerned Citizens for Charlevoix Area requesting immediate shutdown of plant for alleged failure to meet containment integrity requirements DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/26 2pp
- B007150052 Second set of interrogatories directed to J O'Neill Requests identification of inadequacy alleged in Contention IIE-3 recriticality analysis PP Steptoe B00708 itr to J O'Neill enci BTEPTOE,P.P Consumers Power Co STEPTOF.P.P Isham, Lincoln & Beale 80/07/09 Spp
- BO07170304 Response to Christa-Maria et al BO0626 Interrogatories Identifies witnesses intended to be called to Christa-Maria Contentions 2 & 3 & J O'Noil] Contentions IB-5, IIA, IIB, IIE-4 & IIF&O Whoffidaytts, bibliographies & Certificate of Svc MOORE, J E Hearing Branch 2 BO/07/10 18pp
- -8007170355 Transcript of 800506 brinfing in Washington DC re SEP Pp 1-4B Key to topic status listing w/definitions encl * Commission 80/05/06 104pp
- B007290612 Forwards NRC rules of discovery, JR Weeks rept re Christa Maria Contention 3 & Board notification re spent fuel pool mod Emergency plan available at LPDR Other related document sent on 791115 W/o encl JONES, B W Huaring Branch 2 80/07/22 ip
- 8007300468 Discusses NRC evaluation of util compliance w/certain THI-2 Lessons Learned Task Force requirements Cvaluation in Section 2 1 6 b is irrelevant to O'Neill's Contention IIE-4 Clerifies statement to avoid controversy at hearing OALLO. J Isham, Lincoln & Beale 80/07/23 2pp

- 8007300464 Requests that NRC furnish Refs 12-14 noted on Page 7 of NRC Ovaluation of several SEP issues refacility Evaluation is directly applicable to D'Moill Contention IID re flight of military aircraft near plant GALLO. J Isham Lincoln & Beale 80/07/24 2pp
- 9007310400 Notifies that responses to Set II interrogatories will be sent next wk
 O'NEILL, J Affiliation Unknown 80/97/25 ip

H General correspondence

- 8004300355 Comments on operation of power plant which is within terminile radius of residence Decisions re plant should be based on safety & health of people, not profit of util NEUMAN, R. F. Affiliation Unknown 80/04/22 ip
- 8006270181 Responds to BO0429 request for info re M LeMiere inquiry about amount of nuclear waste disposed in State of MI Spent fuel from four operating MI reactors stored onsite NRC evaluated status of waste mgt in 1977 W/related FR excerpts DIRCKS.W J Office of the Executive Director for Operations BO/05/09 10pp
- 8007180180 Ack recoipt of RF Neuman 800422 ltr re operation of plant NRC considers safety of public as paramount in evaluation of licensees CRUTCHFIELD.D M Operating Reactors Branch 5 60/06/25
- BOO7140236 Responds to 800424 ltr re proposed expansion of spent fuel pool Describes NRC review process for mods proposed by licensee DOE efforts to select site for spent fuel storage underway CRUTCHFIELD.D Operating Reactors Branch S 80/06/26 3pp
- 8007080255 Criticises safety practices at util re containment bldg dome & increased storage of spent fuel rods CALDHELL.E Affiliation Unknown 80/07/02 lp
- 8007310532 Responds to ltr re concerns of C Cox.of Indamer Co.about accuracy of local news article Facility granted exemption from 1005780 46 failure criterion requirements on 760576 No other exemptions in effect Related order encl
 DIRCKS Office of the Executive Director for Operations 80/07/24
- ---B007310535 Hemorandum & order granting facility exemption from IOCERSO 46 failure criterion requirements Dissenting opinion of Commissioner Gilinsky enc)
 HOYLE J C Office of the Secretary of the Commission 76/05/26 19pp
- J Insurance & indemnity information
- BOO7150479 Forwards Endorsement 81 to ANI Policy NF-117 FOSTER,5 C Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Di√ BO/07/10 ≧pp
- 8007280597 Requests revision of Indemnity Agreement 8-22 Revision provides more detailed description of site location & is current description used by util in insurance policies w/Nuclear Mutual Ltd & American Nuclear Insurance HOFFMAN.D P Consumers Power Co 80/07/22 3pp
- 8007310422 Requests revision to Indomnsty Agreement N-22 to provide more detailed description of site location & current description used in insurance policies w/Nuclear Mutual Limited & American Nuclear Insurance HDFFMAN.D P Consumers Power Co 80/07/22 2pp
- --8007310425 "Big Roc) Point Site Property Survey," Sheet 3
 * Consumers Power Co 80/07/22 lp
- P Operating license stage documents & correspondence
- 8007030303 Advises that licensing activities will be coordinated by W Paulson as result of reorganization of for of Nuclear Reactor Regulation Description of reorganization cutl CRUTCHFIELD, Operating Reactors Branch 5 80/06/02 28pp
- 8007290541 Forwards NUREG-0419. "BHR Faedwater No.11e & Control Rod Drive Return Line No.11e Gracking." for review & comment CRUTCHFIELD.D Deprating Reactors Branch 5 80/06/04 2pp
- BOO7010111 Forwards finel rule published in BO0509 FR amending 10CFR50 71 to require periodic updating of FSARs tumpliance is not required until completion of BEP CRUICHFIELD:D Operating Reactors Branch 5 BO/06/10 App

107010700 Forwards info re util request to expand spent fuel storage capacity Info includes integrity of structural elements in event of boiling in pool & provision of makeup water to pool if containment cannot be entered t connot be entered Consumers Power (o - 80/06/20 - 248pp

4

- 107010447 Application for amend to License DPR-6 to change fech Specs to add operability & surveillance testing requirements for fire protection equipment

 MOFFMAN.D.P. Consumers Power (p. 80/06/27 2pp Consumers Power (c. 80/06/27 2pp
- 800/010451 Proposed changes to Erch Opers 3 7 11 P & Table 3 3-8 to add operability & surveillance testing requirements for fire protection equipment # Consumers Power to 60/06/27 5pp
- x07070710 forwards response to NRC 800.2/8 requests for info necessary to calculate containment temp & pressure after accident & date re-protected (RAA mass & energy release Ervion Rept XN-NF-78-93 contains most recept LOGA enalysis of facility HOFFHAND P Consumers Power Co 80706/30 lipp
- 0703026B Forwards response to NRC 800907 request 1e applicability of concerns addressed in GF 800221 ltr re generic post-accident operating conditions at LWRs HOFFMAN D P Consumers Power Cu = 00707/01 9pp
- 77290373 forwards evaluation of REP Topic VIII-0 re electrical senetrations of reactor containment Requests reply within 10 days if as-built facility differs from licensing basis issumed CRUTCHFTELD,D M Operating Reactors Branch 5 80/07/01 12pp
- 27290364 Forwards evaluations of 66P Topics 111-10 A.VII-11 A & FIII-3 D we electrical sys & components Requests reply within 60 days if as-built facility differs from licensing Assis assumed RUTCHFIFLD.)) M Operating Reactors Branch 5 80/07/09 11pp
- 7/110204 Forwards application to amend License DPR-6 Tech Specs & mended Tech Specs for encl GFFMAN.D P (onsumers Power to H0/0//07 1p
- 007110209 Application to amend License DPR 5 revising necessity of attaining rold shuddown while conducting containment spray sys terveillance test
 DEWITT.R B Consumers Power (n. 80/07/07 Epp.
- 007110210 Tech Spech 11 3 3 4 5 11 4 3 4 B & Table 11 4 3 4 For containment spray sys * Consumers Power Co = 80/07/07 = Rep
- 2280076 Responds to 900318 for to J Abserne objecting on behalf of where of plants under SP review, to correct plans for spedited review of environ qualification of electrical subpense forwards applicable memorandum & order NTEM. B (9f910 of Nuclear Regulation, Director NTDN, H R 3/07/16
- 7300 MB Forwards NUE-3567. "Structural Analysis of Spent Fool Pool nor & Concrete Due to Conlant Sys Forlors." DP Hoffman 10660 ltr to DM Crotthfield & related NUT of Million rs in support of 79,463 application for OL omend ALCO. Isham. Lincoln & Beale 100/07/24 lipp
- PBOSTS Discusses status of testing re-degraded gold voltage & equacy of station planticle distribution sys voltages. In 1900FG v. BOD219 commitments firsting complete Evaluation data in progress Responses to open items for theoming FFMAN.D.P. (passes) & Power Co. 10/07/275. ip
- nupertion reports (1) Bulletinu 4 correspondence
- 140917 forwards It Hutletin (80.4% "Cracking in Gore Spray argers" thatten response required "PELROJ O Region 3. Chirago, Orfice of the Director B0/09/12
- 140485 Forwards II. Insp Rept 50 155780-96 on 805505-08 No roughtants into 1 (18) Rept of 1 (1900) And in include of a compliants into 1 (18) Rept of 1 (1900) And Indiana Nuclear Support 94/37 Esp
 - DED Rept 50 199760-05 on (P0505-08 No noncompliance rang England follows of items in NURFO 0578
 rang England menting between NRC & licensee
 BARFR. R Region & Chirago, thefire of the Diroctor

- 8007020051 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28
- 8007010115 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written tesponse required KEPPLER.J O Region 3. Chicago. Office of the Director 80/05/29
- 8007220188 Forwards II Info Natice 80-26, "Evaluation of Contractor Oh Programs" No written response required REPPLER. J G Region 3, Chicago, Office of the Director 80/06/10
- B007020676 Forwards site-specific & generic questions re GE disc cracking indications per 800109 meeting & IE Info Notice 79-37 on Westinghouse low pressure turbines discs cracks Response requested within 30 days W/o encl CRUTCHFIELD.D Operating Reactors Branch 5 80/06/11 5pp
- 8007140317 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability "Written response required KEFPLER.J G Region 3. Chicago, Office of the Director 80/06/12
- 8007240004 Forwards IE Insp Rept 50-159/80-04 on 800303-14 & notice of violation re health physics appraisal Significant appraisal findings encl REPPLER. J & Region 3. Chicago, Office of the Director 80/06/13
- --8007240006 Natice of violation from insp on 800303-14 * Region 3, Chicago, Office of the Director 80/0 80/06/05 1p
- --8007240009 IE Insp Rept 50-i55/80-04 on 800303-14 Noncompliances noted inadequate affishift radiation protection coverage & inadequate high radiation area access controls GREGER.L R . CARBAUGH.E H Region 3. Chicago. Office of the Director FISHER.W L Region 3. Chicago. Fuel Facility & Materials Bafety Branch 80/06/05 39pp
- 8007030034 Forwards IE Bulletin 80~15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/1 Region 3. Chicago, Office of the Director 80/04/18
- B007020552 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/20
- B007170474 Furwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J G Region J. Chicago, Office of the Director B0/06/24
- 8007010313 Responds to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Actuation drawings for designated syshave been reviewed All equipment except for listed Items e & i meet acceptable criteria bos
- 8007140430 Atk receipt of 800609 ltr informing NRC of steps taken to correct violations noted in It Insp Rept 50-155/80-05 Region 3 comments re util response to Item i encl Util position not fully responsive HIND, J A Region 3, Chicago, Safeguards Blanch 80/06/26 ip
- 8007230312 Forwards IE Bulletin 80~16. "Potential Misapplication of Resemburt Inc Mudels 1151 % 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IC Circular 80~16 also encl No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/23 80/06/27
- B0071B0575 Notifies that time clock of Item 2 of IE Bulletin 80~17, "Failure of Control Rods to Insert During Scram at BHR." will start at 12 01 AM on 800708 Test should be completed within 20 days Requests notification of malfunction KEPPLFR.J G Region 2. Atlanta, Office of the Director 80/07/07
- 8007140424 Forwards Bechtel Power Corp "Sixty-Day Response to IE Bulletin 80-11 HOFFMAN, D F Consumers Power Co 80/07/09 ip

- --8007140428 "Bixty-Day Response to IE Bulletin 80-11 " * Bechtel Corp 80/06/30 32pp
- BD07140444 Responds to IE Builetins BO-CB. "Examination of Containment Liner Penetration Welds "Penetrations w/flued head design & designs w/containment boundary butt welds between penetration sleeve & process piping total 114
 HOFFMAN,D P Consumers Power Co 80/07/09 4pp
- 8007150664 Responds to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Stram at BWR " Design of scram discharge vol sys different from Browns Ferry Tests required by bulletin completed & acceptable WITHROW.6 C Consumers Power Co 80/07/10 2pp
- 800716045B Responds to IE Bulletin 80-10. "Contamination of Nonradicactive Gys & Resulting Potential for Unmonitored, Uncontrolled Release of Radicactivity to Environ" Review of sys complete Documentation available during onsite insp HOFFMAN.D.P Consumers Power Co 80/07/11 ip
- 8007180424 Forwards response to 1E Bulletin BO-17, "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR" Primary sys will not exceed design pressure in event of ATMS
 HOFFMAN, D.P. Consumers Power Co. 80/07/14 15pp
- B007220482 Forwards affirmation for B00710 response to IE Bulletin 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During Boram at 848 " Affirmation should be attached to response HOFFMAN, D P Consumers Power Co 80/07/16 2pp
- 8007220472 Responds to NRC 800626 request for add1 info re IE Insp Rept 50-185/80-03 Requests issue of plant security sys operability be maintained as an open item pending resolution HDFFMAN.D P Consumers Power Co 80/07/16 14
- 8007230465 Submits add1 response to IE Insp Rept 50-155/80-05 Requests that plant security sys operability issue be maintained as open itam pending resolution by NRC & licensee HOFFHAN.D P Consumers Power Co 80/07/16 ip
- 8007230516 Responds to NRC 800613 ltr re violations noted in IE Imap Rept 50-155/80-04 Corrective actions util will establish new supervisory training position to insure upgraded radiation protection training of plant staff HOFFHAN, D P Consumers Power Co 80/07/18 Bpp
- 8007240017 Forwards affirmation inadvertently emitted from 800709 response to IE Bulletin 80-11, HOFFMAN.D P Consumers Power Co 80/07/18 2pp
- 8007290373 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes " Four pressure transmitters of identified type exist. One has output code in question HOFFMAN, D P Consumers Power Co 80/07/21 2pp
- B007290606 Responds to IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Emergency operating procedures have been revised to assure appropriate operator actions in event of scram HOFFHAN.D P Consumers Power to 80/07/23 3pp
- 8007290691 Responds to IE Bulletin BO-17. "Failure of 76 of 189 Control Rods to Fully Insert During Scram at BWR " Mod implemented to provide alternate vent path to containment bldg atmosphere HOFFRAN.D P Consumers Power Co 80/07/25 2pp
- R Pariodic operating reports & related correspondence
- B007080346 Farwards monthly operating rept for June 1980 HARTMAN.C J Consumers Power Co B0/07/01 ip
- --8007080348 Monthly operating rept for June 1980 HIMEBAUCH,N Consumers Pawer Co 80/07/01 3pp

- DDCKET 50-156 UNIV OF WISCONSIN RESEARCH REACIOR

 O Inspection reports, IE Bulletins & correspondence
- 8007170862 Forwards IE Cartular 80-14 "Reducetive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J 9 Region J. Chicago, Office of the Director 80/06/24 to
- $oldsymbol{R}$ Periodic operating reports $oldsymbol{b}$ related correspondence
- B007310403 Forwards "Annual Operating Rept for License R-74" for Jul 1979-June 1980 CASHWELL R J Wisconsin Univ of Madison 80/07/11 1p
- --8007310405 "Annual Operating Rept for License R-74," for Jul 1979-June 1980 CABHMELL.R J. Wisconsin, Univ. of Hadison 60/07/11 150pp
- DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- B007160B03 Forwards IE Circular B0-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIER, B H Region 1. Philadelphia. Office of the Director B0/06/24 1p
- G007210155 Forwards IC Info Natice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/06/25 ip
- DOCKET 50-160 GEORGIA INST OF TECH RESEARCH REACTUR

 G Inspection reports, IE Bulletins ** correspondence
- 8007i70i58 Forwards IE Circular 80-14. "Radioantive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24
- DOCKET SO-163 GENERAL ATOMIC COMPANY
- F. Security, medical, emergency & fire protection plans
- B0072300B1 Requests resolution of nutstanding foo issues for certain physical security-related documents & emergency plans Memo dtd 770910 re 790220 quard training plan submitted by GA Co mever answered MILLER, W O License Fee Management Branch 80/07/16 2pp
- O Inspection reports, IE Bulletins & correspondence
- 800/1802/4 Forwards IE Gircular BO-14. "Redinactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN, R H Region 5, Sun Francisco. Office of the Director BO/06/24 ip
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR

 G Inspection reports, 18 Nulletins & correspondence
- 8007160813 Forwards IE (incolor 80-14. "Redicactive Contamination of Plant Desineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER B H Region 1. Philadelphia, Office of the Director 80/06/24 ip
- 8007210143 Forwards IF Info Notice 80-24. "I um Level Radmasta Durial Criteria" No miitton response required GRIER, B. H. Region), Philadolphia, Office of the Director 80/06/25 1p
- R Periodic operating reports & related correspondence
- 8007230495 Submits operations rept for June 1979 to June 1980 BELCHER, R. L. Maryland, Univ. of 80/07/01 Apr

Inspection reports. IE Bulletins & correspondence

007160833 Polwards IE Gircular 80-14, "Radioactive Contamination of Plant Senteralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required GRIER 8 H. Region 1, Philadelphia, Office of the Director 80/06/24 ip

007210296 Forwards IE Info Natice 80-24. "Low Level Radwasto Burial Criteria " No written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/06/25 ip

OCKET 50-171 PBACH BOTTON ATOMIC POWER STATION, UNIT : Security, medical, emergency & fire protection plans

307140361 Forwards input for fire protection review 10 fire detection, water suppression, combustible control, gas suppression, fire doors & interior hose stations
MALL.R E Brookhaven National Laboratory 80/06/20 Opp

General correspondence

NOTO20147 Requests consideration of site visit by Atomic onergy Council of Taiwan on 8009-25-26 Council interested in observing waste mgt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR, J D Assistant Director for International Cooperation 80/05/12 3pp

07280549 Responds to 800920 ltr re JL & WS Randell concerns about emergency planning Discusses various options for funding offsite support agencies Public announcement for facility emergency planning meeting issued on 800331 W/Randell ltrs BBCKS.W J Office of the Executive Director for Operations BO/07/02 7pp

CKET 50-182 PURDUE UNIV REGEARCH REACTOR

Inspection repurts, IE Bulletins & correspondence

9717064: Forwards JE Circular BO-14, "Radivective Contamination of lant Demineralized Water Sys & Resultant Internal Londamination of Personnel "No written response required (EPPLER, J & Region 3: Chicago Office of the Director 90/06/24

AET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR
Operating litense stage documents & correspondence

1719028 Forwards Amend 3 to License TR-5, safety evaluation & notice f issuance & availability [ILLER.J.R. Standardization & Special Projects Branch 80/06/30

007/50035 Amend 3 to License TR-5, incorporating Tech Specs contained in App A re reactor core
MILLER, J.R. Standardization & Special Projects Branch 80/06/30
App A re

007150037 Gafoty evaluation supporting Amend 3 to License TR-5 & Office of Nuclear Reactor Regulation, Director 80/06/30 2pj

07150041 Notice of issuance & availability of Amend 3 to License TR-5 TR-5 MILLER, J.R. Standardization & Special Projects Branch 80/06/30 2pp

Inspection reports. IE Bulletins & correspondence

7160829 Forwards IE Circular 80-14. "Radioartive Contamination of lant Demineralized Water Sys & Resultant Internal antamination of Personnel" No written response required RIERO B Region 1. Philodelphia. ()ffice of the Director 3/06/24 ip

7210149 Forwards IC Info Notice 80-24. "Low Level Rapwaste Burial riteria" No written response required SIER, B. H. Region I. Philadelphia, Affice of the Director, 3705/25

DOCKET 50-184 UNIV OF MISSOURI RESEARCH REACTOR

@ Inspection reports, IE Bulletins & correspondence

B007170653 Forwards IE Circular 80-14, "Radioective Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER. J G Regian 3, Chicago, Office of the Director 80/06/24

S Reportable occurrences, LERs & related correspondence

8007080266 RO on 800909, emergency generator failed to start when starting sequence initiated Caused by starter motor trip due to lack of fuel in emergency generator day tank Tank refilled & sight glass added to verify tank fuel level MCKINBEN, J C , BRUGGER, R M Missouri, Univ of Columbia 80/06/02 2pp

8007080260 RO on 800516 automatic regulating blade drive mechanism failed Caused by worn spot on drive gear Gear drive assembly replaced & blade cycled through full travel to assure proper apperation MCKIBBEN, J. C. BRUGGER, R. M. Missours, Univ. of, Columbia 80/06/04, 20p

B007140351 RO on 800616, while verifying sample loading of triple-tubed sample predicted facility located in ctr test hole one tube was found dissing 2-inch long spacer No unreviewed safety question existed during period of operation, MCKIBDEN. J C . ALGER, D M Missouri, Univ of, Columbia 80/07/07 Zoo

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

9 Inspection reports, IE Bulletins & correspondence

B007180270 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Hoter Bys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director B0/06/24 1p

DDCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC F Security, medical, emergency & fire protection plans

B007020490 Forwards Amend 7 to License R-95, reflecting state 790205 necurity plan MILLER, J R - Standard Zation & Special Projects Branch - 80/06/17 200

--B007020493 Amend 7 to License R-95, reflecting state 790205 security plan PILLER, J.R. Standardization & Special Projects Branch 80/06/17 2pp

P Operating license stage documents & correspondence

8007020490 Forwards Amend 7 to License R-95, reflecting state 790205 security plan MILLER.J R Standardization & Special Projects Branch 80/06/17 2pp

--8007020493 Amend 7 to License R-95, reflecting state 790205 security plan MILLER, J. R. Standardization & Special Projects Branch 80/05/17 2pp

B007070272 Advises NRC that rept re nonpower reactor physical protection upgrade requirements will be submitted to NRC by B00801 DIMEGLIO, A.F. Rhode Island, State of 80/07/01 ip

G Inspection reports. IE Bulletins & correspondence

8007160837 Forwards IE Circular 80-14, "Radigactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required CRIER, 8 H Region I. Philadelphia, Office of the Director BO/06/24 1p

8007210161 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER.B H Region & Philadelphia, Office of the Director 80/06/25 ip POCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR O Inspection reports, IE Bulletins & correspondence

8007160822 Forwards IE Circular 80-14, "Radjuactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region i, Philadelphia, Office of the Director BO/06/24 ip

8007210127 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/25 1p

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

I Financial information

8007010001 Forwards audited financial statements consisting of statements as of 791231 & 781231 w/auditor rept Affidavit only ent! CONTIP L Nuclear Fuel Services, Inc. (subs of Getty Oil Co.) 80/05/28 3pp

P Operating license stage documents & correspondence

8007020515 Ack receipt of Apr 1980 monthly rept & 800530 ltr re insp & evaluation of facility high level storage sys Copies will be dispatched to encl external distribution list HAUONEV.C J Advanced Fuel & Spent Fuel Licensing Branch 80/06/04 3pp

8007020078 Questions intentions, as colicensee, re NFS 760922 announcement of withdrawal from commercial reprocessing NRC considers plans for future of facility to be joint responsibility CUNNINOHAM, R. Division of fuel Facility & Materials Safety 80/06/05 3pp

B007140580 Requests info re future licensing & operation of facility Requests reply within 30 days CUNNINGHAM, R. E Division of Fuel Cycle & Material Bafoty B0/06/05

8007230117 Urges atrong support & cooperation in Rockwell Hanford Operations program to insp & evaluate condition of high lavel liquid waste storage sys NFB insistence on prior agreement impedes gathering of necessary info DIRCKS.W J. Office of Nuclear Material Bafety & Safeguards 80/06/26. App

8007090384 Natification of 800813 meeting w/vendor in Silver Spring.MD NULVYUCHE NOTIFICATION OF BOORIS meeting w/vendor in Silver Stodiscuss progress of NFB efforts to process technical infonesded to provide basis for future decontamination to decommissioning of facility
HAUCHREY, C. J. Advanced Fuel & Spent Fuel Licensing Branch
BO/06/27 Spp

B007140193 Bummary of 800618 meeting w/NFS & NY State Energy R&D Authority in Bilver Spring, MD re decontamination & decommissioning technical data processing & potential tornado generated missile consequences HAUGHNEY, C. J. Advanced Fuel & Spent Fuel Licensing Branch, B0/06/27. 28pp

8007280069 Notification of 800717 meeting w/NF8 & NY State Energy R&D Authority in Giver Agring. MD to discuss indemnification & Authority in Giver Agring. MD to discuss indemnification & liability issues associated w/implementation of work by Rockwell Hanford Operations
HAUGHNEY. C. J. Advanced Fuel & Spent Fuel Licansing Dranch SO/07/09 ip

Q. Inspection reports. IE Bulletins & correspondence

8007020714 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required QRIER, B.H. Region I, Philadelphia, Office of the Director. 80/06/18 ip.

8007160783 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminsralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H. Region 1, Philadelphia, Office of the Director 80/06/24, 1p

8007210159 Forwards 1E Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required CRIER.B H Region 1, Philadelphia, Office of the Director 80/06/25 1p

8007080246 Advises that emergency notification sys telephone does not require ansite auxiliary power supply in response to IE Bulletin 80-15 Test to verify independent power will be conducted within next 30 days, during scheduled power outage DUCKHORTH, JP Nuclear Fuel Services. Inc., West Valley Reprocessing Plant 80/06/26 ip

8007210028 Advises that onsite auxiliary power supply is not required in response to IE Bulletin 80-15 Insp revealed that emergency notification sys does not receive power from plant supply Test of emergency diesel generator will be conducted DUCKMORTH.J P Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/06/26 ip

B007230441 Forwards response to NRC 800617 ltr re deficiency moted in IE Insp. Rept 50-201/80-04 on 800519-21 Encl withheld (ref 100FR2 790)
DCCMURTH, J. P. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) Nuclear Fuel Services, Inc. (subs. of Getty Oi) Co.) 80/07/01 1 n

BOCKET 50-204 SAN ONOFRE NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans

B007080271 Advises that revisions to safeguards contingency plan will be submitted by 800718 BABKIN-K P Southern California Edison Cp 80/07/02 tp

Q Adjudicatory correspondence

8007020426 Requests that entl listing of add1 petitions, received from CA residents under 10CFR2 206 for facility seismic conditions, be added to 791213 ltr on file All have received NRC 791213 ltr w/FR notice of receipt of petition SMITH, H Operating Reactors Branch 5 80/06/21 5pp

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCA 780502 patition for reconsideration of 780413 memorandum & order UCA 771104 patition sought action re fire protection for electrical cables EISENHUT.D & Division of Licensing 80/06/25 89ep

H General correspondence

B007020181 Requests consideration of having Atomic Energy Council of Taiwan visit facility on 800804-05 Council interested in observing waste mpt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEURIA D Assistant Director for International Cooperation 80/05/13 3pp

8007170049 Forwards US map showing location of reactors licensed to operate under const or planned in response to 800526 ltr M McCann added to mailing list of petitioners requesting facility shutdown CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/02 1p

--B007170051 "Nuclear Power Reactors in US "
Energy Dept of 79/10/31 2pp

--8007170057 Requests map of UB showing location of nuclear reactors licensed to operate, under const or planned Expresses opposition to facility operation MCCANN, M Affiliation Unknown 80/05/26 in

P Operating license stage documents & correspondence

8007110401 Forwards response to 790808 request for info re adequacy of offsite power sys & ensite distribution sys
BABKIN,K P Southern California Edison Co 80/05/01 13pp

B007100097 Forwards Amend 49 to License DPR-13, safety evaluation & notice of issuance & availability
CRUTCHFIELD.D M Operating Reactors Branch 5 80/05/29 2pp

--8007100102 Amend 49 to License DPR-13, replacing ref to cycle-specific eyected rod worths & predicted fuel centerline temps CRUTCHFIELD.O M Operating Reactors Branch 5 80/05/29 5pp

--8007100105 Bafrity evaluation supporting Amend 49 to License DPH-13
* Office of Nuclear Reactor Regulation, Director 80/05/29 4

- 8007100107 Notice of issuance & availability of Amend 19 to License
 - CRUTCHFIELD.D N Operating Reactors Branch 5 80/05/29 2pp
- JO7010137 Forwards final rule published in 800507 FR amending 1007830 71 to require periodic updating of FBARs Compliance is not require until completion of SEP GRUTCHVIELD, D. Operating Reactors Branch > 80/06/10 5pp
- 10/020190 Requests cooperation in NRC study of people-related security problems in nuclea: industry GRUTCHTIFLD.O M Operating Reactors Branch 5 80/06/11 2pp
- 107230099 Requests submittal of proposed Tech Spec changes providing for redundancy in dociny heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution entl for guidance EISENHUT, D.O. Division of Licensing 80/06/11 62pp
- 07100399 Responds to 400229 ltr which expressed apposition to ACRS recommendation to restructure SEP Role of licenses in program will expand Ltr forwarded to Commissioners BERTONIA R Office of Nuclear Reactor Regulation. Director 40/06/18 4pp
- B007100420 Expresses upposition to ACH9 recommendation to restructure SEP for SEP numers to perform safety analysis as outlined, cost in dollars & manpower would intrease dramatically SCMAFFSTALL.R SEP Owners Group B0/02/29 2pp
- 17010465 Forwards addl info re SEP Topic VI-4 & drawings re ontoinment isolation sys.in response to NRC 800417 & 0612 trs Drawings available in (entral Files only 'AGKIN, K.P. Southern California Edison Co. 80706723 4pp
- >7220158 Forwards Amend 50 to License DPR-13 % notice of issuance &
- RUTCHFIELD, D Operating Resitors Branch 5 80/06/25
- 007220162 Amend 90 to License OPR-13, revising certain provisions to reflect changes in corporate organizational structure CRUTCHFIELD.D Decrating Reactors Branch 5 80/06/25 11pp
- 00/220165 Notice of issuance & availability of Amend 50 to License
- CRUTCHFIELD.D Operating Reactors Branch 5 80/06/25 2pp
- 7020362 Forwards Amend 91 consisting of Proposed Change 93 to Tech pers for Apps A & B of License DPR-13 Proposed Change 93 aguests mod of Trob Specs to revise definition of operable" to comply w/definition of STS IETCH, R Southern California Edison Co 80/06/30 ip
- 007020066 Application for Amend 91 to License DPR-13.consisting of Proposed Change 93 modifying Tech Specs to revise definition of "operable" to comply w/definition used in STS Certificate of SVC encl DIETCH,R Southern California Edison Co 80/06/30 7pp
- 10/0203/2 Proposed Tech Spec 3 O for Limiting Conditions for Operation (Omperal) & revision to Section 1 O reddefinitions
- Bouthern California Edison Co BO/Oh/30 5pp
- 090704 Urges extension of comment period for NUREO-0577 & 800519 lend until 800915 More stringent requirements broader plicability & EPRI study results warrant addl time LMAN,D W San Diego das & Electric Co 80/06/30 ip
- 170693 Advises of NAC acceptance of Amend 3 to Topical Rept, F-1-A, "GA Program " Topical rept must be referenced in apter 17 of SAR ASS.W P Quality Assurance Branch 80/07/01 in Quality Assurance Branch 80/07/01 ip
- P80001 Requests submittal of application for amend to license issting of Tach Spec changes & ticense conditions PHR well Teth Specs & Model license conditions for TMF-2 stone Learned Category & items ently for guidance SERHUT.D & Division of Licensing 80/07/02 69pp
- 180172 Forwards NRC evaluation of SEP Topics III-10 A.V-II A. -7 C | & VIII-3 & Evaluation will be imput to safety sessment unless changes needed to reflect as-built JTCHFIELD, D M Operating Reactors Branch 5 80/07/03

- 8007150579 Forwards "Post-Accident Sampling Sys, Capabilities & Description," & drawings, in response to open item identified in NRC 800502 ltr re implementation of TMI lessons learned requirements Drawings available in Central Files only BASKIN, K P Southern California Edison Co 80/07/09 2pp
- --8007150587 "Post-Accident Sampling Sys, Capabilities & Description "
 * Southern California Edison Co 80/07/09 5pp
- B007280098 Forwards NRC evaluation of control rod guide thimble wear issue Based on review.issue is resolved for 14x14 fuel assemblies designed by Wrstinghouse CRUTCHFIELD.D Operating Reactors Branch 5 80/07/10 4pp
- 8007210053 Notification of 800724 meeting w/util in Rosemead.CA to discuss results of Imperial Valley Dct 1979 earthquake enalysis, using Unit I analytical modeling technique ROGD.H Licensing Branch 3 80/07/11 2pp
- 8007280076 Responds to 800318 ltr to J Ahearne objecting on behalf of puzzouve respons to Buodis it to a Angaine dojecting on be numers of plants under SEP review to current plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON-HR Office of Nuclear Reactor Regulation, Director 80/07/16 4pp
- B007280486 Act receipt of NRC responses to Marine Review Committee 791009 rept re facility radiological monitoring program evaluation Detailed response will be submitted following matl review FIBCHER,N.L. California, State of 80/07/18 ip
- 8007290705 Submits responses to Items 1.2 & 3 of NRC 800620 ltr re failure of saltwater cooling sys Response to Item 4 will be submitted by 800804 MAYNES,J 9 Bouthern California Edison Co 80/07/24 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007290883 Responds to IE Bulletin BO-04, "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition " Scoping studies will be completed by 800513 Studies include effect of auxiliary feedwater runout & impact of other energy sources OTTDSON.H L Southern California Edison Co 80/05/12 2pp
- 8007250636 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Failure mode & effects analysis indicates loss of vital bus or util bus will not prevent achieving cold shutdown OffOSON.H L. Southern California Edison Co. 80/05/15 Spp
- 8007280072 Supple 800512 response to IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break W/Continued Feedwater Addition"
 Results of scoping studies & reportability determination will be forwarded when available
 OTTOSON, H L Southern California Edison Co 80/05/19 2pp
- 8007110174 Forwards IE Insp Rept 50-204/80-13 on 800423-25 & notice of violation BOOK. H E Region 5, San Francisco, fuel Facility & Materials Safety Branch 80/05/23 2pp
- --8007110179 Notice of violation from insp on 800423-25 * Region 5. San Francisco, Office of the Director 80/05/23 1p
- --B007110184 IE Insp Rept 50-204/80-13 on 800423-25 Noncompliance noted failure to follow radiation protection procedure required by Tech Specs BDOK. H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch JDUKOFF.P. NORTH, H S Region 5. San Francisco. Office of the Director 80/05/23 22pp
- 8007180014 Forwards 1E Insp Rept 50-206/80-11 on 800421-25 No noncompliance noted SPENCER, O.S. Region 5, Ban Francisco. Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8007180018 IE Insp Rept 50-206/80-11 on 800421-25 No noncompliance noted Major areas inspected inservice inspactivities maintain the repair activities on pressurizer safety valves licensee activities & personnel interviews **
 **HAIST, D.P. NARBUT, P.P. Region B. San Francisco, Office of the Director, DODDS, R.T. Region B. San Francisco, Reactor Construction & Engineering Support Branch. 80/05/23 7pp
- 8007020246 Forwards IE Info Notice BO-22. "Breakdowns In Contamination Control Programs " No written response required ENGELKEN.R H Region 5. App Francisco. Office of the Director 80/05/28 1p

- B007250355 Responds to IE Bulletin B0-12. "Decay Heat Removal Sys Operability " One event reported in LER 77-03.involved degradation of docay heat removal capability for several minutes Emergency & main procedures revised BASKIN.K P Southern California Edison Co 80/06/09 6pp
- 8007310162 Forwards review summary in response to IE Bulletin 80-05 re vacuum conditions resulting in domage to chemical vol control sys holdup tanks Bys reviewed are adequately designed to protect against vacuum conditions BASKIN.K P Bouthern California Edison Co 80/06/09 3pp
- 8007220249 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 80/06/10 ip
- 8007030010 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required ENGELKENR H Region 5, San Francisco, Office of the Director 80/06/18 1p
- B00702047B Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director B0/06/20 1p
- 8007240318 Forwards IE Insp Rept 50-206/80-15 on 800528-30 No noncompliance noted SPENCER, G S Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/06/20 2pp
- --B007240326 IE Insp Rept 50-206/80-15 on B00528-30 No noncompliance noted Major areas inspected insp activities per IE Bulletin 79-13 re cracking in feedwater sys piping HAIST, D P Region 5, Ban Francisco, Office of the Director DODDS, R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/06/20 5pp
- 8007180292 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 80/06/24 ip
- 8007230394 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Cirtular 80-11 also encl No written response required ENGELKENR H Region 5, San Francisco. Office of the Director 80/06/27 ip
- 8007240267 Forwards IE Insp Rept 50-206/80-18 on 800519-22 No noncompliance noted CREM9.J L Region 5, San Francisco, Reactor Operations Nuclear Bupport Branch 80/06/27 2pp
- --8007240273 IE Insp Rept 50-206/80-18 on 800519-22 Ng noncompliance noted Major areas inspected surveillance of pipe support & restraint sys & IE bulletin/circular followup HORN, A J Region 5, San Francisco, Office of the Director FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/06/27 3pp
- BOO7250358 Responds to IE Bulletin 79-03A: "Longitudinal Weld Defects in ASME SA-312, Type 304 Stainless Steel Pipe " Review of piping revealed no piping sys exceeding code allowable design stresses OTTOSON,H L Southern California Edison Co BO/06/30 2pp
- BOO7170961 Ack receipt of BOO616 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-206/80-12 CREWS.J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch BO/07/01 ip
- ---B007170565 Responds to NRC 800528 ltr re violations noted in IE Insp Rept 50-206/80-12 Corrective actions instrument & test technicians cautioned that use of procedures necessary Required signs poated PAPAY, L T Southern California Edison Co 80/06/16 4pp
- ---B007170369 Forwards IE Insp Rept 50-206/80-12 on 800405-0502 & notice of violation CREMB.J L. Region 5, San Francisco, Reactor Operations Nuclear Burgsort Branch 80/05/28 2pp
- --B007170573 Netice of violation from insp on 800405-0502 * Region 5, San Francisco, Office of the Director 80/05/28 2pp

- --800/170579 IE Insp Rept 90-206/80-12 on 800405-0592 Noncompliance noted failure to follow procedure re source range instrumentation detectors & to implement fully IOCFR20 posting requirements for indication area MILLER.L. Region 5, San Francisco. Office of the Director FAULKENDERRY.B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/05/28 8pp
- B007100217 Notification of B00710 meeting w/util in Bethesda, MD to discuss results of steam generator insps & corrective actions

 MOMICKI, B. J. Departing Reactors Branch 5 80/07/07 1p
- 8007300339 Forwards IE Imsp Rept 50-206/80-20 on 800616-19 No noncompliance noted CREMS, J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/07/09 2pp
- --B007300343 IE Insp Rept 50-206/80-20 on 800616-19 No noncompliance noted Major areas inspected major maint major surveillance. IE buildetin & circular followup & independent insp effort HORN.A J Region 5. San Francisco. Office of the Director FAULMENBERRY, B Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/07/09 3pp
- 8007230282 Ack receipt of 800701 ltr informing NRC of steps taken to correct violation noted in It Insp Rept 50-206/80-14 800K.H E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch 80/07/16 ip
- --8007230287 Responds to NRC 800611 ltr le violation noted in IE (nsp Rept 50-206/80-14 Corrective actions frequency of air samples inside steam generators has been increased to once per shift PAPAY.L T Southern California Edison Co 80/07/01 2pp
- --B007230271 Forwards IC Insp Rept 40~206/80-14 on B00415-18 & notice of violation B00K.H E Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch B0/06/11 2pp
- --8007230295 Notice of violation from imap on 800415-18
 * Region 5, San Francisco, Office of the Director 80/06/10 ip
- --B007230297 IE Insp Rept 50-206/80-14 on B00415-18 Noncompliance noted failure to perform airborns activity surveys D00K.HE Region 5. San Francisco, Fuel Farility & Materials SaFety Branch CURTISJ R. NDR(H.H. Region 5. San Francisco, Office of the Director B0/06/10 4pp
- R Periodic operating reports & related correspondence
- 8007010216 Forwards "1979 Annual Operating Rept. San Onofre Nuclear Generating Station," Vol 5. Biological & Oceanographic Data Analyses Includes ETS for Unit 1. (onst % preoperational monitoring programs for Units 2 & 3 BASKIN, K.P. Southern California Edison Co. 80/06/25 ip
- --BOD7010226 "1979 Annual Operating Rept.San Under Nuclear Operating Station," Vol 5, Biological & Oceanographic Data Analysis "Includes ETB for Unit 1, const & preoperational monitoring programs for Units 2 & 3 * Brown & Caldwell * Lockheed Environmental Sciences * Marine Biological Consultants, Inc., 80-80-100 80/06/25
- B007100262 Forwards "Biological 3 Oceanographic Data Analyses ETS for Unit 1.Const Monitoring Program for Units 2 & 3. Preoperational Honitoring Program for Units 2 & 3 & Special Study re Ichthugolankton: "Vol 5 for 1979 OTTOSON.K i. Southern California Edison Co. 80/06/30 2pp
- --8007100268 "Biological & Oreanographic Data Analyses ETS for Unit i. Const Monitoring Program for Units 2 & 3. Prooperational Monitoring Program for Units 2 % 3 & Special Study for Ichthyoplankton: "Vol 5 for 1979 AMBERG.P J Brown & Caldwell ANDERSON.D T Lockhood Environmental Sciences ABGRAB.K Harine Biological Consultants, Inc. 80-RD-100 80/06/30 800pp
- 8007150599 Forwards monthly operating rept for June 1980 CURRAN, J. M. Sputhern California Eduson Co. 80/0//68 1p
- --8007150605 Monthly operating rept for June 1980 JOY.J M Southern California Educin Co 80/07/08 Spp

- S Reportable occurrences, LERs & related correspondence
- 8004240300 PNO-V-80-18 on 800310, salt water cooling sys out-of-syc for approx 41 minutes due to broken pump shaft North pump started but discharge valve failed to open Auxiliary pump started but failed due to pump priming sys FAULKENBERRY. B Region 5, San Francisco, Office of the Director 80/03/11 2pp
- 8007030021 PNO-V-80-033 on 800619, film badge data of subcontractor employee indicated exposure exceeding quarterly limit Self-reading dosimeter reading indicated significantly lower exposure Valldity of data being examined CURTIS.J. RENSLAWSKI, F. Region 3, San Francisco, Office of the Director BO/06/20 1p
- 8007210591 Requests add3 info re failure of saltwater cooling sys on 800310 info about events where multiple equipment failures occur & contracting factors would be beneficial LAINAS.0 C Assistant Director for Safety, Assessment 80/06/20
- 8007010533 Forwards LER 80-027/03L-0 OTTOSON.H L Southern California Edison Co 80/06/23 2pp
- --8007010537 LER 80-027/03L-0 on 800528, radiographic examination of feedwater sys welds inside containment found seven unacceptable defects including lack of penetration porosity & slag inclusion Caused by original const defects CURRAN, J M Southern California Edison Co 80/06/23 ip
- 8007080403 Forwards LER 80-028/01T-0 OTTOSON,H L Southern California Edison Co 80/07/01 App
- --8007080410 LER 80-028/017-0 on 800512, during 1E Bulletin 79-14 insp, inadequate pipe guides discovered in safety injection sys injection lines Caused by improper installation Guides will be modified before return to svc CURRAN.J M Southern California Edison Co 80/06/30 1p
- 8007280371 Forwards LER 80-024/01T-T OTTOSON.H L Southern California Edison Co 80/07/16 3pp
- --8007280396 LER 80-024/01T-T on 800516, while performing radiographic examination of main steam lines, six welds found w/indications in excess of code Apparently caused by consternor Weld w/cracks in root repaired CURRAN, J M Southern California Edison Co 80/07/16 ip
- --8007280404 "Significance of Circumforential Weld Indications in 24-Inch Main Steam Piging at San Onofre Nuclear Generating Station Unit 1 - Fracture Analysis " CIPOLLA,R C. GROVER,J L., EGAN.G R Aptech Engineering Services 80/07/31 64pp
- 9007280375 Forwards LER 80-029/01L-0 OTTOSON.H L. Southern California Edison Co. 80/07/21 2pp
- --8007280382 LER 80-029/OiL-0 on 800705.RCS dilution inadvertently occurred while containment integrity was unestablished Caused by leaking inflatable plugs in generators Generator channel heads discontinued 8 Southern California Edison Co 80/07/21 1p
- POCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR

 Inspection reports, IE Bulletins & correspondence
- 007160796 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required, GRIER.8 H Region i. Philadelphia. Office of the Director BO/06/24 ip
- 007210193 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/06/25 ip

DOCKET 50-213 HADDAM NECK PLANT

- F Security, medical, emergency & fire protection plans
- B007180196 Forwards NRC 800425 ltr to all power reactor licensees, in response to 800529 ltr re emorgency response facilities at reactor sites Sites w/approval to use closed-circuit television link w/technical support ctr listed CRUTCHFIELD,D M Operating Reactors Branch 5 80/07/07 2pp
- --8007180208 Requests copy of NRC 800425 ltr to utils updating requirements for emergency response facilities & technical support ctr List of plants w/approval to use closed-circuit supervision link w/technical support ctr requested HICKEY.A E American Institute for Research in the Dehavioral Sciences 80/05/29 ip
- BD07010337 Comments on proposed rule 10CFR50 regulation for fire protection excessively specific & unjustifiably restrictive Suggested revisions to App R w/justifications encl COUNDIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNDIL, W G Connecticut Yankee Atomic Power Co COUNDIL, W G Northeast Utilities B0/06/16 31pp
- 8007030356 Comments on proposed rule 10CFR50 requirements for exceed those necessary to resolve generic assums & are excessively specific & restrictive Forwards alternative App R fire protection program COUNSIL.W 9 Connecticut Yankse Atomic Power Co 80/06/16 16pp
- 8007070231 Forwards responses to NUREO-0654 criteria & facilities emergency plans per NRC 800512 & 791010 ltrs Encls available in Central Files only Emergency plans withhold (ref 10CFR2 790)
 CDUNSIL.W C Connecticut Yankee Atomic Power Co COUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/06/30 2pp
- 8007170425 Confirms position discussed in BO0624 telcon re safeguards contingency plans NRC requested revisions are ill-advised & unnecessary Specifics of plan implementation can be detailed in procedures COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/01 2pp
- 8007210445 Dutlines actions to be undertaken & completed per GH Smith & J White 800703 telcons w/MO Counsiline emergency preparedness capabilities identified in 800623-0703 appraisal NRC must be notified in 24-h if not agreeable ORIER, B H Region 1. Philadelphia, Office of the Director 80/07/03 2pp
- O Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cob
- I Financial information
- B007140355 Forwards estimated 1980 cash flows for facility
 O'CONPER.L A Connecticut Yankee Atomic Power Co 80/06/27 4pp
- P Operating license stage documents & correspondence
- BOG7010122 Forwards final rule published in B00509 FR amending 100FRBO 71 to require periodic updating of FBARs Compliance is not required until completion of BEP GRUTCHFIELD, D Operating Reactors Branch 5 80/06/10 5pp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISCNHUT.D 0 Division of Licensing. 80/06/11 62pp
- 8007240054 Informs that NRC has completed review of info provided in util 780626.791017 & 800423 ltrs re positive displacement vibrations Operation will not cause fatigue failures in chemical vol control sys NRC considers matter closed LAINAS. G C Assistant Director for Safety Assessment 80/06/16 Zpp
- ---B007240061 Safety evaluation re charging pump vibrations Fatigue failures not anticipated by operation of metering pump * Assistant Director for Safety Assessment 80/07/16 ip

- 8007100397 Responds to 800229 ltr which expressed opposition to ACRS recommendation to restructure SEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON, H.R. Office of Nuclear Reactor Regulation. Director 80/06/18
- --B007100420 Expresses opposition to ACRS recommendation to restructure SEP for SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFSTALLR SEP Owners Oroup 80/02/29 2pp
- 8007020549 Clarifies 800506 response to NRC 791030 request for info concerning Lessons Learned Task Force Item 2 1 0 a improved post-accident sampling capability Info ensures accurate NRC understanding of design philosophy & intent COUNBIL.W G Connecticut Yankee Atomic Power Co COUNBIL. Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/23. 3pp COUNSIL N O
- 8007250694 Advises that NRC has approved conceptual design of post-accident sampling sys Lists several addl areas which should CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/01 3pp
- 8007280103 Forwards request for add1 info re adequacy of station electric distribution sys voltages Response requested within 45 days of 1tr receipt CRUTCHFIELD.D Operating Reactors Branch 5 80/07/01 5pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TM1-2 Lessons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 69pp
- 8007280150 Advises that NRC has completed review of plans to implement Item 2 1 4 of Category A lessons learned requirements Measures taken constitute acceptable resolution of concerns expressed in NRC 800507 itr GRUTCHFIELD, D Operating Reactors Branch 5 80/07/02 2pp
- 8007280180 Forwards request for add1 info re testing of reactor trip sys & engineered safety features Response requested by 801201 CRUTCHFIELD, D Operating Reactors Branch 5 80/07/07 3pp
- BOO7210239 Submits corrected Page 1 of Attachment 3 to util 800321 ltr rs low pressure disc integrity, summary of arguments from BOO328 meeting w/NRC re disc integrity & answers to sitespecific general questions COUNSIL, W G Connecticut Yankee Atomic Power Co BO/07/08 10pp
- 8007280206 Forwards NRC evaluation of SEP Topics III-10 A.V-11 A.VI-4. VI-7 C 1 & VIII-3 B Evaluations will be input to safety assessment, unless changes needed to reflect as-built Conditions CRUTCHFIELD,D Operating Reactors Branch 5 80/07/08 31pp
- BOO7250472 Forwards NRC evaluation of control rod guide thimble wear in PMR Issue resolved for 13X15 fuel assemblies designed by Westinghouse CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/10 App
- BOO7300324 Discusses BOO630-0701 site audit by NRC & Franklin Research Ctr re environ qualification of electrical equipment, SEP Topic III-12 Info provided & requested during audit encl Proprietary portion withheld (ref 10CFR2 790) COUNSIL, W G Connecticut Yankee Atomic Power Co 80/07/14 23pp
- ---8007300331 Forwards summary of results of evaluation of environ qualifications of safety-related electrical equipment Evaluation indicates that electrical equipment at facility would perform safety functions to allow safe shutdown SWITZER, D.C., FEE, W.F. Connecticut Yankee Atomic Power Co-78/03/04 22pp
- --8007300338 Forwards "Special T4 Teledyne Valve Operator Performante of Unit in Steam Environ Indicated in Westinghouse Equipment Spec 0676258 " Rept updates & supplements Table A-1 attached to NRC 780306 ltr COUNSIL, W G Connecticut Yankee Atomic Power Co 78/07/27. 2pp
- --8007300342 "Special T4 Teledyne Valve Operator Performance of Unit in Steam Environ Indicated in Westinghouse Equipment Spec Q676288 "
 - Connecticut Yankes Atomic Power Co 69/10/20 | 11pp
- BOO7240053 Application for amend to License DPR-61 re App A.safety Tech.

 Boess & App B.ETS, reflecting title changes within util organization
 COUNSIL,N G Connecticut Yankee Atomic Power Co 80/07/16 3pp

- ~-B00724005B Proposed amended App A safety Tech Specs Section 6, reflecting title changes within util organization # Connecticut Yankee Atomic Powor Co B0/07/31 9pp
- ~-8007240062 Proposed amended App B.ETS Section 5 ! 5, reflecting title changes within util organization # Connecticut Yankee Atomic Power Co 80/07/31 4pp
- B007240047 Application for amend to License DPR-61 re ETS Section 2 4 3 1(1), modifying gaseous release rate limit to one averaged over 1-b period COUNSIL-N 6 Connecticut Yankee Atomic Power Co 80/07/16 3pp
- --B007240070 Proposed amended ETS Section 2 4 3L(1) modifying gaseous release rate limit to one averaged over 1-h period
 * Conhecticut Yankee Atomic Power Co 80/07/31 2pp
- 8007280076 Responds to 800318 ltr to J Ahearne objecting on behalf of owners of plants under SEP review to current plans for espedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON. H R Defice of Nutlear Reactor Regulation, Director 80/07/16 4pp
- 8007280673 Requests extension of comment period re NUREG-0877.
 "Potential for Low Fracture Toughness & Lamellar Teating on PUR Steam Generator & Reactor Coolant Pump Supports." until COUNSIL.W G Northeast Utilities 80/07/21 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007020140 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No Written response required GRIER, B H Region i. Philadelphia, Office of the Director 80/03/28 ip
- B007010275 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 80/05/29 ip
- 8007170494 Responds to IE Bulletin 80-12. "Decay Heat Removal Sys Operability " Based on noted reviews of sys & procedures, no changes to existing procedures or hardware are considered necessary GOUNBIL.W C Connecticut Yankee Atomic Power Co 80/06/09 3pp
- 80072:0559 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required ORIER, Bil Region 1, Philadelphia. Office of the Director 80/06/10 ip
- 8007160344 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response GRIER.B H Region 1, Philadelphia, Dffice of the Director 80/06/11 1p
- 800723036) Forwards 1E Insp Rept 50-213/80-10 on 800519-23 No noncompliance noted MARTIN.W G Region 1. Philadelphia. Safeguards Branch 80/06/11
- -8007230366 IE Insp Rept 50-213/80-10 on 800519-23 No noncompliance noted Major areas inspected security plan, security organization & protected & vital areas physical barriers Details withheld (ref 10CFR2 770)
 LADUN, R H Region i, Philadelphia, Defice of the Director DEVLIN, J W Region 1, Philadelphia, Safeguards Branch & 80/06/02
- 8007170320 Responds to IE Bulletin 80-04, "Engineered Safety Feature (ESF) Reset Controls "Three facilities will have completed mods per IE Bulletin 80-04 by 810101 List of equipment & status of criteria encl CGUNBIL, W G Connecticut Yankee Atomic Power Co CGUNSIL, W G Northeast Utilities 80/06/13 43pp
- 8007020692 Forwards IE Bulletin 60-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power" Written response required ORIER, B H Region 1, Philadelphia. Office of the Director BO/06/18 1p
- 8007180137 Submits reply to IE Bulletin 60-69 re examination of containment liner penetration welds bue to absence of abnormal conditions no further action planned CQUNSIL.W 0 Northeast Utilities 80/06/19 lipp

- 8007020496 Forwards IE Circular 80-15, 'Less of Reactor Coolant Pump Cooling & Natural Circulation Conldown " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director
- B007180578 Responds to IE Bulletin B0-10 Plant design & operation reviewed to identify nonradioactive sys which could become radioactive through sys interface Routine sampling program exists for each sys to identify unmonitored releases COUNSIL, W G Connecticut Yankee Atomic Power Co B0/06/23 P BD/04/23 2nn
- 8007160690 Forwards JE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/24 tp
- 8007210174 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER,B H Region 1. Philadelphia. Office of the Director 60704/2") ip
- B007230107 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007160367 Responds to teleph request for info re results of turbine inspiperformed during 1980 refueling outage Util intends to conduct next inspiduring 1981 outage based on submitted info Confirms that rated power for operation is appropriate COUNSIL.N G Connecticut Yankee Atomic Power Co 80/07/09 2pp
- 8007230411 Forwards rept on Core 9 fuel insp as part of post-irradiation exam of fuel assemblies GRAVES, R H Connecticut Vanker Atomic Power Co 80/07/16 7pp
- " Periodic operating reports & related correspondence
- 8007180390 Forwards monthly operating rept for June 1980 GRAVES,R H Connecticut Yankee Atomic Power Co 80/0 80/07/11
- --8007180395 Monthly operating rept for June 1980 * Connecticut Yankee Atomic Power Co 80/07 B0/07/11 12pp
- Reportable occurrences. LERs & related correspondence
- i007020536 PND-I-80-092 on 800616, while performing test on low pressure safety injection pumps under runout conditions, partial vacuum was drawn on RWST Licenses investigating apparent cause Plant shut down for refueling until 800712 SMITH, R H , KEIMIG, R R , BRUNNER, E J Region i, Philadelphia, Office of the Director 80/06/16 ip
- 007080077 RD 80-06 on 800622 during draindown of refueling cavity to refueling water storage tank.grab sample indicated radioactivity in tank exceeding ETS Caused by crud displaced into RMR conlant sys by testing GRAVES R H Connecticut Yankee Atomic Power Co 80/07/01 2pp
- 007:40359 RO on 8006:22 during draindown of refueling water storage tank cavity, grab sample indicated that curies exceeded ETS limit of 10 Caused by crud displacement into residual heat removal sys Tank placed on recirculation mode 0RAVES,R H Connecticut Yankee Atomic Power Co 80/07/01 2pp
- 107090321 Forwards LER 80-010/011-0 GRAVES.R H Connecticut Yankee Atomic Power Co 80/07/04 1p
- 8007090326 LER 60-010/01T-0 on 600621, per IE Bulletin 79-14, five seismic-type supports determined missing from two separate HPSI lines & two addl supports found w/excess gap Caused by failure to install restraints required by piping drawing THOMAS.R H. Connecticut Yankee Atomic Power Co. 80/07/04
 - lanned release occurred from waste % out stack Total of 3 9% of Tech Spec
 - Region 1, Philadelphia, Office

- B007250535 RO on B00717, while investigating reactor coolant pump seal water flow problems seal water supply bypass Valve 2 failed, allowing full flow through valve Valve was clamped closed, cooldown commenced & valves replaced GRAVES.R H Connecticut Yankoe Atomic Power Co 80/07/21 2pp
- DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8007020Dio forwards summary of 790706 mgt meeting re status of schedule for upgrading facility radiation protection program Minutes de not contain proprietary info Meeting identified need far plant health physics audit program GRIER. B H Region 1. Philadelphia. Office of the Director 80/06/04 3pp
- 8007030399 Forwards summary of 770830 mgt meeting re planned & completed improvements in licensee radiation protection program Licensee is on schedule for upgrading program Summary contains no proprietary info ORIER, B H Region i. Philadelphia. Office of the Director 80/06/04 3pp
- B00711011B Summary of B00422 meeting w/util re emergency planning NOWICKL B J Operating Reactors Branch 5 80/06/06 4pp
- 8007010399 Confirms 800613 mgt meeting in King of Prussia, PA to discuss actions taken & planned by licensee to improve radiation protection program at facility GRIER, 8 H Region 1, Philadelphia, Office of the Director 80/06/11 1p
- 8007020193 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIELD,D M Decrating Reactors Branch 5 80/06/11 200
- 8007070262 Notifies of delay in implementation schedule for installation of alternate water supply per safety evaluation Table 3 I Caused by engineering & manpower problems Alternate water supply will be completed by 801101 FINFROCK, I R Jersey Central Power & Light Co 80/07/02
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for slectrical cables EISENHUT.D G Davision of Licensing 80/06/25 89pp
- H General correspondence
- 8007180060 Responds to 800311 request for info needed for fuel cost study Forwards excerpts of MASH-740, MASH-1224, MASH-12250, MASH-1400, NUREG-0020 (Vol 4. Number 1), NUREG-0480, NUREG-0512, NUREG-0517, NUREG-CT-1060 & FES
 DENTON, H R Office of Nuclear Reactor Regulation, Director 80/05/14 153pp
- ---B007180063 Requests documents containing info needed for fuel cost study HILGER,W Affiliation Unknown 80/03/11 2pp
- P Operating license stage documents & correspondence
- B007230028 Summary of 800207 mpeting w/Mark I owners group in Bethesda, MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES, C T Plant Systems Branch 80/02/21 3ipp
- 8007100394 Forwards Amend 48 to License DPR-16, eafety evaluation & notice of issuance & availability CRUTCHFIELD, D Operating Reactors Branch 5 80/04/02 2pp
- --8007100401 Amend 48 to License DPR-16 approving max average planar linear heat generation rate limits & multiplier for five & four recirculation loop operation & deleting specs for fuel no longer in core CRUTCHFIELD.D Operating Reactors Branch 5 80/06/02 14pp
- --8007100405 Safety evaluation supporting Amend 48 to License DPR-14 * Office of Nuclear Reactor Regulation, Director 80/06/02 4
- --B007100408 Notice of issuance & availability of Amend 48 to License DPR-16 CRUTCHFIELD.D Operating Reactors Branch 5 BO/06/02 2pp

1

- 8007230554 Forwards NUREO-0619, "BWR Fredwater Nozzle & Control Rod Drive Roturn Line Nozzle Cracking," for review & cumment CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/04 2pp
- 8007010113 Forwards final rule published in 800909 FR amending 10CFR90 71 to require periodic updating of FSARs Compliance is not required until completion of SEP CRUTCHFIELD, D Operating Reactors Branch 5 H0/06/10 Spp
- 8007030300 Urges response within 30 days to 800303 request for add1 info re util 790925 & 1101 ltrs concerning degraded grid voltage & adequacy of electric distribution sys voltages Seven points need clarification
 LAINAS, & C Assistant Director for Safety Assessment 80/06/16-300
- 8007100399 Responds to 800229 itr which expressed opposition to ACRS recommendation to restructure REP Role of licensess in program will expend Ltr forwarded to Commissioners DENTON, HR Defice of Nuclear Reactor Regulation, Director 80/04/18 4pp
- ----8007100420 Expresses opposition to ACRS recommendation to restructure SEP For SEP awners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically BCHAFFSTALL, R SEP Owners Group 80/02/29 2pp
- 8007010468 Notifies of intent to commit to implementation of addl TNI-2 related requirements when acceptance criteria is developed Forwards util initial assessment of applicability of 32 requirements
 FINFROCK.IR Jersey Central Power & Light Co 80/06/23 App
- 8007140824 Notification of 800630 meeting w/util in Bethesda.MD to discuss util proposed action concerning visual indications of cracks in core spray piping at facility PAULSDN,W A Operating Reactors Branch 5 80706726 2pp
- B007030216 Submits schedule for mods to improve testability of plant sys as committed to in 781122 request for partial exemption from code requirements instrument air/nitrogen sys & demineralized water sys mods completed FINFROCK, I R Jersey Central Power & Light Co 80/06/27 1p
- 8007070113 Forwards responses to questions raised at 800630 meeting re NRC evaluation of two possible cracks in core spray piping Also forwards suppl to util 800627 evaluation BARTNOFF, B Jersey Central Power & Light Co 80/07/02 App
- 8007180113 Notifies that 790921 & 1004 route approval request for spent fuel shipment is subj to licence fee Review of requests was completed on 800416 MILLER.W O License Fee Management Branch 80/07/03 lp
- 8007250716 Forwards NRC evaluation of SEP Topics III-10 A, V-11 A, VI-7 C 1, VIII-3 B & VIII-4 Evaluation will be input to safety assessment unless changes needed to reflect as-huilt conditions GRUTCHFIELD, D Operating Reactors Branch 5 80/07/03 23pp
- 8007160500 Forwards response to NRC 800507 ltr re add1 TM1-2 requirements per NUREG-0660 Generally agrees w/GE 800221 ganerac BMR responses Questions 3 % 7 cannot be answered due to insufficient supporting documentation FINFROCK, I R Jersey Central Power & Light Cp 80/07/08 Sp.
- 8007230691 Discusses crack in emergency core spray piping Agrees w/plan to complete quantitative evaluation on Inw-low-low water level by 800801 & provide for possible replacement of reducers Operation for one fuel cyclo permissible CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/09 3pp
- 8007310519 Summary of 800630 meeting w/util re visual indications of possible cracks in plant core spray sys
 PAULSON,W A Operating Reactors Branch 5 80/07/09 12pp
- B007250720 Forwards NRC current evaluation of SEP Topic III-5 B & request for addI info re pipe break outside containment CRUTCHFIELD.D Operating Reactors Branch 5 60/07/10 30pp
- 8007170279 Responds to NRC 800111 ltr & forwards addl info re failure of control rod to fully insert on scram signal FINFROCK, I Jursey Central Power & Light Co 80/07/14 2pp
- B007180407 Forwards Tech Bpec Change Request 87 for amend to License DPR-16. App A. re add1 fire proctection sys installed during 1980 refueling outage Class III amend fee encl FINFROCK. I R Jersey Central Power & Light Co

- ~~8007180415 Tech Spec Change Request 87 for amend to License DFR -16.
 App Aire addl fire protection sys installed during 1980
 refueling outage Certificate of Svc & lit to Lacey Township
 mayor end
 FINFROCK.1 R Jersey Central Power * Light Co 80/07/14 3pp
- --8007180423 Toch Spec Change Request 87 for amend to License BFR-16.

 App A.re add1 fire protection sys installed during 1980 refueling outage Consists of replacement Sections 3-12 & 4-12

 * Jersey Central Power & Light Co. 80/07/14 | JSpp
- 80072800/6 Responds to 800318 ltr to J Ahearne objecting on behalf of numers of plants under SEP review, to current plans for expedited review of environ qualification of electrical equipment forwards applicable memorandum % order DENTON. H R Office of Nuclear Reactor Regulation, Director 80/07/16 4pp
- 8007270184 Forwards summary of results of leakage roduction program conducted during Spring 1980 autage, in response to NUREG-0578 Spection 2 I 68 FINFROCK, I R Jersey Central Power & Light Co 80/07/21 App
- B007310019 "Analysis of Populations of Boring & Fouling Organisms in Vicinity of Oyster Creek Notlear Generating Station," quarterly rept Jane-Aug 1979 HOAGLAND, K E. CROCKET, L. Lehigh Univ FIN B-5/44 NUREG/CR-1209 80/07/31 61pp
- O Inspection reports, IE Bulletins & correspondence
- 8007010299 Forwards JE Waste Packaging Insp Rept 15000039/80-03 on 800227-29 No inprompliance noted SMIJH.Q H. Region I. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/24 ip
- --0007010306 JE Waste Packaging Inap Rept 15000039/80-03 on 800227-29 No noncompliance noted Major areas inspected shipping paper requirements. DOT placarding requirements, radiation levels, removable contemination & external package features PEERY, N W. POTTER, J P. Region I. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/18 7pp
- 8007220050 Forwards IC lasp Rept 50-219/80-10 pn 800317-20 & notice of violation BRUNNER, E J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/09/09 2pp
- --8007220052 Notice of violation from insp on 800317-20 * Region I, Philadelphia, Office of the Director 80/05/06 Ip
- ---8007R20060 IE Insp Rept 50-P19780-10 on 600317-20 Noncompliance noted failure to implement inservice testing program & procedures per Tech Spec & B REKITO, W.A. Region I. Philadelphia, Office of the Director CAPHTON, D.L. Region I. Philadelphia, Reactor Operations Nuclear Support Branch B0/05/06 9pp
- 8007140445 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers" Written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/05/12 1p
- 8007020169 Forwards IF Info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required GRIER.B H Region i, Philadelphia. Office of the Director 80/09/28 ip
- 900717068B Forwards IE Insp Rept 50-219/80-13 on 800407-tt No noncompliance noted BRUNNER,E J. Region 1, Philadelphia, Reactor Operations Noclear Support Branch 80/05/28 2pp
- --80071/0492 IE Insp Rept 50-219/80-13 on 800407-11 No poncompliance noted Major areas inspected GA/OC administration.dosign changes/mods & followup on previously identified items NAPUDA.O., CONMAY.J. Region 1, Philadelphia. Office of the Director ORECNMAN.C O Region 1, Philadelphia. Reactor Operations Nuclear Support Dranch 80/05/23 9pp
- B007010318 Forwards IE Info Notice 80-23. "toss of Suction to Emergency Feedwater Pumps" No written response required ORIER.0 H Region 1. Philadelphia, Office of the Director 80/05/27 ip

- 4 Addl response to FOIA request for records concerning Hittman & Development Corp.RAD Svcs.inc & Rediation High Inwards balance of documents (143 pages) listed in
- J M Division of Rules and Records 80/04/02 2pp
- 266 Discusses IE Insp Rept 50-219/75-01 on 751031-1105 & rds notice of violation N.P.R. Region I. Philadelphia. Fuel Facility & Materials y Branch 76/01/02 2pp
- 271 Notice of violation from insp on 751031-1105 Noncompliance failure to notify NRC of possession of byproduct matling NRC Form 241 within 3 days prior to engaging vivity plants. Fuel Facility & Materials Safety Branch 1702
- 276 Ack receipt of 760127 itr informing NRC of steps taken to rt violation noted in 1E insp on 751031-1105 Also ack pt of NRC Form 241. "Rept of Proposed Activities in resment States"

 4.P R Region 1. Philadeiphia, Fuel Facility & Materials
- Perment States **
 4-P R Region i. Philadeighia. Fuel Facility & Materials
 4 Branch 74,03/02 ip
- 286 Informs NRC of steps taken to correct violation noted in IG Rept 50-219775-01 on 751031-1105 Corrective actions late personnel have been advised to file NRC Form 241 outline sycs in nonagreement states & T Hittman Nuclear & Development Corp (subs Hittman) 76/01/27 Spp
- Ack receipt of 800519 ltr responding to NRC request for tion of several commitments Based on 800528 telcon, arstands that environ air samples discussed in ltr in calibr using approved procedures H. Region 1, Philadelphia. Office of the Director
- Forwards IE Info Notice 80-26. "Evaluation of Contractor ams " No written response required H Region 1. Philadelphia. Office of the Director 10
- Forwards site-specific & generic questions re GE disc indications per 800109 moeting & JE Info Notice Westinghouse low pressure turbines disc cracks requested within 30 days W/o encl ELD.D Derating Reactors Branch 5 80/06/11 5p
- Forwards IE Bullatin BO-14, "Degradation of BHR Scram e Vol Capability " Written response required i Region i, Philadelphia, Office of the Director
- Forwards IE Insp Rept 50-219/80-06 on 800204-08 No lance noted ... T Region (, Philadelphia, Reactor Construction & ing Support Branch 80/06/13 2pp
- 28 IE Insp Rept 50-219/80-06 on 800004-08 No noncompliance Major areas inspected activities associated rvice insp program AN.E.P. Region 1. Philadelphia. Office of the Director L.E. Region 1. Philadelphia. Reactor Construction & ering Support Branch 80/06/11 5pp
- Forwards 12 Bulletin 80-15, "Possible Loss of Emergency tion Sys (ENS) W/Loss of Opfisite Power " Written required
- Region 1. Philadelphia, Office of the Director
- Responds to 1E Dulletin 80-06, "Engineered Safety Feature set Controls" Main steam isolation, containment isolation condenser sys will be tested within 45 r startup from 1980 refuelling outage Jersey Central Power & Light Co 80/06/19 6pp
- Forwards IE Circular 80-15, "loss of Reactor Coolant Pump

 Natural Circulation Coolfown " No written response
- Region 1. Philadelphia, Office of the Director
- Ack receipt of 800603 ltr re JE Insp Rept 50-219/80-10 vibration analysis sys understood to be ated & appears to exceed regulatory requirements closely monitor progress

 J. Region to Philadelphia, Reactor Operations Nuclear Branch 80/06/23 1p

- --8007180451 Responds to NRC 800509 ltr re violations noted in IE Insp Rept 50-219780-10 Corrective actions implementation of inservice insp program delayed due to personnel & recruiting problems Fstimated completion 801126 ROSS, D.A. Jersey Central Power & Light Co. 80/06/03 2pp
- 8007140699 forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, D. H. Region I. Philadelphia. Office of the Director GRIER, B H R
- 8007210193 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria" No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/06/25 ip
- 8007020377 Forwards response to IE Dulletin 80-13, "Cracking in Core Spray Spargers" Rept encl FINFROCK,1 R Jersey Central Power & Light Co 80/06/27 17pp
- 8007230122 Forwards IE Bulletin 80-16, "Potential Misapplication of Resembert Inc Models 1151 & 1152 Pressure Transmitters WEither A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007210042 Responds to IE Bulletin BO-10 Required actions completed & results are on file at facility, available for review FINFROCK,I R Jersey Central Power & Light Co 80/07/01 ip
- 8007090259 Updates 800627 ltr re evaluation of possible cracks on segments of core spray piping within reactor vossel between inlet nozzle & vessel shroud Encl replacement pages discuss cyclic stresses induced by low level dynamic inputs
 FINTROCK, I R Jersey Central Power & Light Co 80/07/07 App
- 8007250170 Forwards reply to IE Bulletin 80-08 re containment liner penetration welds Response to Action Items 1 through 3 & 2b & 2c encl Addl weld info to be provided within 45 days RD98,D A Jersey Central Power & Light Co 80/07/07 7pp
- 800/250305 Forwards reply to IC Bulletin 80-11 re masonry wall design List of masonry walls & re-evaluation priority schedule encl No cases of safety-related piping attached to masonry walls have been found FINFROCK, IR Jersey Central Power & Light Co 80/07/07 7pp
- 8007210288 Discusses IE insp on 800318-19 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO.V Office of Inspection & Enforcement, Office of the Director 80/07/08 4pp
- --8007210294 Notice of violation from insp on 800318-19 Noncompliance noted failure to establish radioactive work permit on 790702-0318 & failure to use preceptionary procedures during control rod blade tool cleaning * Office of Inspection & Enforcement, Office of the Director 80/07/08 3pp
- --8007210299 Notice of proposed imposition of civil penalty in amount of \$21,000 for item of noncompliance noted in IE insp on 800318-19 * Office of Inspection & Enforcement. Office of the Director 80/07/08 ip
- --B00721034.) Order modifying DL immediately by adding Section 6 3 2 to Toch Spec 6 3 re facility staff qualifications Request for hearing may be submitted within 25 days STELLO, V Office of Inspection & Enforcement, Office of the Director 60/07/08 5pp
- BOO7240336 Confirms oral notification made on BOO707 that 20-day perind for completing tests required by IE Bulletin 80-17, Item 2. began at 12 OI AM on BOO708 Also requests immediate notification of any malfunction found during tests GRIER, B H Region i. Philadelphia, Office of the Director BO/07/09 2pp
- 6007220586 Ack receipt of 800317 ltr informing NRC of corrective actions to items of noncompliance in IE Insp Rept 50-219/79~18 Dased on responses to noncompliance & discussions at 800429 maeting, specified parts are withdrawn STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/17 2pp

- R Periodic operating reports & related correspondence
- B007150705 Forwards 800606 20th quarterly progress rept, "Woodborer Btudy Associated W/Oyster Creek Generating Station." for 800209-0510 FINFRDCK, I R Jersey Central Power & Light Co 80/07/08 ip
- --8007150712 Progress rept for 20th quarter, "Woodborer Study Associated W/Oyater Creek Generating Station." for period 800209-0510 MACIOLEK.N J , BELMORE,C I , HILLMAN.R E Dattello Memorial Institute, Columbus Laboratories 80/06/04 24pp
- 8007220363 Forwards monthly operating rept for June 1980 8088, D A Jersey Central Power & Light Co 80/07/15
- --8007220364 Monthly operating lept for June 1980 MCCLAIN.C M Jersey Central Power & Light Co 80/07/10 11pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004240221 PNO-1-80-37 on 800309. Licensee scheduled maint on fire JUNEAUGEL PNO-1-BU-3 on BUDSUY.licensoe scheduled maint on fi protection sys due to crarked & leaking valve body on sys supply header fire protection during outage will be supplied by fire truck connected to Number 2 fire hydrant BRIGOS.L. KEIMIG.R R. BRUNNER.E J Region 1, Philadelphia of the Director 80/03/07 ip Region 1, Philadelphia, Dffice of the Director
- 8007070259 Forwards LER 80-024/03L-0 FINFROCK, I R Jersey Central Power & Light Co 80/06/27
- --B007070265 LER 80-024/03L-0 on 800520 during investigation of LER 80-17/17, "one rod free travel interlock" surveillance requirements not performed as required Causer by failure to perform procedure & schedule surveillance ROSS,D A Jersey Central Power & Light Co 80/06/27 3pp
- ~-8007110373 LER 80-022/03L-0 on 800403, reactor high pressure isolation condenser initiation switch trip points found less condenser initiation switch trip points found less conservative than specified Caused by unusual svc condition Pressure switches roset & exercised to ensure operation ROSS,D A Jersey Central Power & Light Co. 80/07/01 Gpp
- 8007110975 Forwards LER 80-025/017-0 FINFROCK,I R Jorsey Central Power & Light Co 80/07/01 1p
- ~-80071103B3 LER 80~025/01T-0 on Q00618 during surveillance test.
 nonfunctioning operator discovered in valves V-9-12 & V-9-8
 found leaking Caused by component failure Defective valves
 replaced & will be inspected Revised rept will follow
 ROSS,D A Jersey Central Power & Light Co 80/07/01 3pp
- 8007140550 EN-80-030 notice of violation & proposed imposition of civil penalties will be issued to util by 800708 due to util failure to instruct workers, perform surveys of airborne radioactive math & failure to follow protection procedures SROCKETT, T. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/07/03 2pp
- 8007230570 Forwards RO 50-219/80-27-1P CARROLL,J T Jersey Central Power & Light Cn 80/07/17 ip
- --8007230574 RO 80-219/60-27-1P on 800716, reactor bldg to suppression chamber vacuum breaker sys inlet pipe was found blocked by plastic bag Caused by personnel error Plastic bag was removed from vacuum breaker inlet opening GROSBY.P J Jersey Central Pawer & Light Co 80/07/17 2pp
- 8007250197 FND-I-80-102 on 800717, pressure transient caused triple low water level signal followed by reactor low water level scram Cold shutdown underway for further analysis of incident KEIMIG, R R , BRUNNER, E J Region 1, Philadelphia, Office of the 80/07/18
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1 **Q** Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for ejectrical cables EISENHUT, D. Q Division of Licensing 80/06/25 89pp

- BQ070700B9 Petition to amend 800221 confirmatory order to all operation w/o recirculation pump trip until Spring 1981 refueling outage Equipment needs to be inspected & prepaired prior to installation Delay will be (conomical % practical DISE.D P Niagara Mohawk Power (orp. 80/06/30 App.
- 8007280093 Ack receipt of 800630 petition to amend confirmatory order Response will be forwarded shortly IPPOLITO T A Departing Reactors Branch 2 80/07/17 2pp
- H General correspondence
- 8007280540 Notifies of changes within util mgt All correspondence pertaining to security-related matters should be sent to JJ Sunser IE Lempges is vice president in charge of nuclear generation Niagara Mohawk Power Corp 80/07/17
- I Financial information
- B007280275 Forwards util Annual Financial Rept for 1979 LEMPGES, T E Niagara Mohawk Power Corp 80/07/22
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I owners group in Bethesda. MD re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program ORIMES.C T Plant Systems Branch 80/02/21 31pp
- BD07070261 Forwards addl info re util commitments to meet NUREG-05/B Recommendations 2 i 36/2 i 8a % RCS vonting Discusses inadequate core couling detection instrumentation & improved post-accident sampling capability DISE.D P Niagara Mohawk Power Corp 80/06/26 5pp
- 8007170393 Forwards application for amend to License DPR-43 consisting of changes to Tach Specs
 FHOMAB.E B LeBoeuf, Lamb. Leiby & MacRae 80/07/16 2pp
- ~-B007170394 Application for amend to Lirense DPR-64 consisting of changes to Tuch Specs re heat treatment of circulating DISE, D P Naggara Nuhawk Power Corp 90/07/10 3pp
- --8007170397 Proposed changes to Tech Specs 2 O for limiting conditions for operation & 2 1 5 for heat treatment of circulating water sus
- Niagara Mehawk Power Corp 80/0//10 Bpp
- ---8007170403 "Assessment of Biological Impacts of Increasing Temp Change Limitation at Nine Mile Point Unit 1 " * Lawler, Matusky & Skelly Engineers 80/03/31 27pp
- G. Inspection reports, IL Bulletins & correspondence
- 8007140474 Forwards IC Bulletin 80-13, "Gracking in Core Spray Spargers" Writton response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/12 Ip
- 8007020157 Forwards IE Info Notice 80-22, "Broakdowns In Contamination Control Programs" No written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/05/28 ip
- B007D10314 Forwards IC Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response required ORICR.D H Region i. Philodelphia. Office of the Director B0/05/29 1p
- 8007180073 Forwards reply to 1F Bulletin 80-08 re examination of containment liner penetration welds No deficiencies reported LEMPGES, T.C. Niagara Mohawk Power (orp. 80/06/09
- B007210100 Responds to Ik Rulletin 80 09, "Hydramator Actuator Deficiencies" None of subjequipment in use or planned for use at Pacility LEPPGES,T E. Niagara Mohawk Power (Drp. 80/06/09 lp.
- 8007210585 Forwards IC Info Notice 80-25. "Evaluation of Contractor QA Programs " No written response required GRIER. B H Region i, Philadelphia, Office of the Director BO/D6/10 1p

- 7170264 Addl response to fOIA request for records concerning Hittman uclear & Dovelopment Corp. RAD Sycs. Inc. & Radiation Mgt orp Forwards balance of documents (143 pages) listed in
- pp ELTON, J.M. Division of Rules and Records BO/06/02 2pp
- 007170266 Discusses IT Insp Rept 50-219/75-01 on 751031-1105 & forwards notice of violation NFLSDN.P R Region 1. Philodelphia. Fuel Facility & Materials Sofety Dranch 76/01/02 2pp
- 3071702/i Notice of violation from insp on 751031-1105 Noncompliance noted failure to notify NNC of pascossion of byproduct matl by filing NRC form 241 within 1 days prior to engaging in activity

 **Region 1. Philadelphia. Fuel facility & Noterials Safety Branch 76/01/02 ip
- PO7170276 Ack receipt of 760127 itr informing NRC of steps taken to correct violation noted in IF insp on 751031-1105 Also ack receipt of NRC Form 241. "Rept of Proposed Activities in Nonagreement States."

 Nonagreement States."

 NELSON.P R. Region I. Philodelphia, Fuel Facility & Materials Safety Branch. 76/03/02. 1p
- 07170286 Informs NRC of stops taken to correct violation noted in IE Insp Rept 90-219/78-01 on 791031-1105 Corrective actions appropriate personnel have been advised to file NRC Form 241 for routine Luck in managreement states
 TUITE.F T Hittman Nuclear & Development Corp (subs Hittman Corp.) 76/01/27 3pp
- 010955 Ack receipt of B00517 th responding to RRC request for office the second responding to RRC request for office and second responding to RRC request for understands that environ air samples discussed in 1tr vs been calify using approved procedures. IER. I H. Region 1. Philadelphia. Office of the Director 706705 ip
- Pt0564 Forwards IC Info Notice 80-26. "Evaluation of Contractor Programs" No written response required IER.B IJ Region I. Philadelphia. Office of the Director /06/10 Ip
- J20666 Forwards site-specific & generic quostions re GE disc icking indications per 800107 mooting & IE Info Notice -37 on Westinghouse low pressure turbines disc cracks sponse requested within 30 days W/o enc] JTCHTRELD.D Operating Reactors Branch 5 80/06/11 5p
- 40294 Forwards IE Bulletin NO-14. "Degradation of BHR Scram Icharge Vol (apability ' Written response required ER.O.H. Region I. Philadelphia, Office of the Director 06/12 ip
- 00326 Forwards IE 1msp Rept 50-219/86 06 on 800204-08 No LEON. R T Region 1. Philadelphia. Reactor Construction & incorping Support Branch 80/06/13 2pp
- 7300328 If. Insp. Rept. 50-019/80-06 on 900204-08 No noncompliance ofted Major areas inspected activities associated /inservice insp. program ERNIGAN.F.P. Region 1. Philadelphia. Office of the Director RIPP.L. F. Region 1. Philadelphia. Reactor Construction & ogineering Support Branch. 80/06/11. 5pp
- 2069? Forwards IE Bullstin 80-19, "Possible Loss of Emergency ification Sys (ENB) Wilmas of Offsite Power " Written points required
- Region 1. Philadelphia, Office of the Director R. B 11
- 30999 Responds to IE Dulletin 80-06. "Engineered Bafety Feature F Reset Controls " Main steam isolation, containment y R isolation condenser sys will be tested within 45 after startup from 1780 refueling outage , B A Jersey Central Power & Light Co 80/06/19 6pp
 - Jards IE Circular 80-18. "Loss of Reactor Coplant Pump Circulation Logidows "No written response
 - in 1. Philadelphyn. Office of the Director
 - the of 600A03 ltr rs IE Inap Rept 50-219/80-10 m analysis sys understood to be present to exceed regulatory requirements monitor progress ion 1. Philadelphia. Reactor Operations Nuclear

- --8007180451 Responds to NAC 800509 ltr re violations noted in IE Insp Rept 50-219/80-10 Corrective actions implementation of inservice insp program delayed due to personnel & recruiting problems Estimated completion 80128 Jersey Central Power & Light Co 80/05/03 2pp
- B007160699 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel " No written response required ORIER B H Region 1. Philadelphia. Office of the Director 80/06/24 ip
- 8007210193 Ferwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/06/25 1p
- 8007020377 Forwards response to 1E Dulletin 80-13, "Cracking in Core Spray Spargers" Rept encl FINFROCK, I R Jersey Central Power & Light Co 80/04/27 17pp
- BO07230122 forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Eitber A or D Output Codes " Written response required IE Circular BO-16 also encl No written response required ORIER, O H Region 1, Philadelphia, Office of the Director BO/06/27, 2pp
- 8007210042 Responds to IE Bulletin 80-10 Required actions completed & results are on file at facility, available for review FINTROCK, I R Jersey Central Power & Light Co 80/07/01 ip
- 8007090259 Updates 800627 Itr re evaluation of possible cracks on segments of core spray piping within reactor vessel between inlet nozzle & vessel shroud Encl replacement pages discuss cyclic stresses induced by low level dynamic inputs FINFROCK. IR Jersey Central Power & Light Co 80/07/07 App
- 8007250170 Forwards reply to IE Bulletin BO-08 re containment liner penetration welds Response to Action Items 1 through 3 & 2b & 2c encl Addl weld info to be provided within 45 days RDSS.D A Jersey Central Power & Light Co 80/07/07 7pp
- B007290305 Forwards reply to IC Bulletin B0-11 re masonry wall design List of masonry walls & re-evaluation priority schedule encl No cases of safety-related piping attached to masonry walls have been found FINFROCK, IR Jersey Central Power & Light Co 80/07/07 7pp
- 0007210288 Discusses IE insp on 800018-17 & forwards notice of violation & notice of proposed imposition of civil penalty STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/08 App
- --8007210294 Notice of violation from insp on 800318-19 Noncompliance noted failure to establish radioactive work permit on 790702-0318 & failure to use precautionary procedures during control rod blade tool cleaning a Office of Inspection & Enforcement, Office of the Director 80/07/08 | 3pp.
- -8007210299 Notice of proposed imposition of civil penalty in amount of \$21,000 for item of noncompliance noted in IE insp on B00310-19 Office of Inspection & Enforcement, Office of the Director 60/07/08
- --B007210343 Order modifying OL immediately, by adding Section 6 3 2 to Toch Spec 6 3 re facility staff qualifications Request for hearing may be submitted within 25 days STELLO.Y Office of Inspection & Enforcement, Office of the Director 80/07/08 Spp
- 8007240396 Confirms oral notification made on 800707 that 20-day UOY20036 Confirms dral notification made on 800707 that 20-period for completing tests required by IE Bulletin 80-17. Item 2.began at 12 Ol AM on 800708 Also requests immediate notification of any malfunction found during tests ORIER, B H Region 1. Philadelphia. Office of the Director 80/07/09 2pp
- 8007220886 Ack receipt of 800317 ltr informing NRC of corrective actions to items of noncompliance in IE Insp Rept 50-219779-18 Based on responses to noncompliance & discussions at 800429 meeting, specified parts are withdrawn STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/17 2pp

R Periodic operating reports & related correspondence

- B007150705 Forwards 800606 20th quarterly progress rept, "Woodborer Study Associated w/Oyster Creek Generating Station," for 800209-0510
- FINFROCK, 1 R Jersey Central Power & Light Co 80/07/08 1p
- ---8007150712 Progress cept for 20th quarter, "Hondborer Study Associated w/Dyster Creek Conerating Station," for period 800209-0510 MACIOLEK.N J. BELMORE, C I. HILLMAN.R E Battelle Memorial Institute, Columbus Laboratories 80/04/06 24pp
- 8007220369 Forwards monthly operating rept for June 1980 ROBS, D. A. Jersey Central Power & Light Co. 80/07/15 11
- --8007220344 Monthly operating rept for June 1980
 MCCLAIN, C M Jersey Central Power & Light Co 80/07/10 11pp
- 9 Reportable occurrences, LERs & related correspondence
- 8004240221 PND-I-80-37 on 800309, licensee schoduled maint on fire protection sys due to cracked & leaking valve body on sys supply header Fire protection during outage will be supplied by fire truck connected to Number 2 fire hydrant BRIOGE, L, KCIMIG.R R, BRUNNER, C J Region 1, Philadelphia, Office of the Director 80/03/07 ip
- 8007070259 Forwards LER 80-024/03L-0 FINFRDCK, I R Jersey Central Power & Light Co 80/06/27 ip
- --8007070265 LER 80-024/03L-0 on 800520, during investigation of LER 80-17/1T, "one rod free travel interlock" surveillance requirements not performed as required Caused by failure to perform procedure & schodule surveillance R055,D A Jersey Central Power & Light Co 80/06/27 3pp
- 8007110370 Forwards LER 80-022/03L-0 FINFROCK, I R Jersey Central Power & Light Co 80/07/01 1p
- --B007110373 LER 80-082/03L-0 on 800603, reactor high pressure isolation condenser initiation switch trip points found less conservative than specified Caused by Unusual svc condition Pressure switches reset & exercised to ensure operation ROSS, D.A. Jursey Central Power & Light Co. 80/07/01 3pp
- ---B007110383 LFR 80-025/01T-0 on 80061B, during surveillance test, nonfunctioning operator discovered in valves V-9-12 & V-9-8 found leaking Caused by component failure Defective valves replaced & will be inspected Revised rept will follow, ROSS,D A Jersey Central Power & Light Co 80/07/01 3pp
- 8007140550 EN-80-030 notice of violation & proposed imposition of civil penalties will be issued to util by 800708 due to util failure to instruct workers, perform surveys of airborne radioactive matl & failure to follow pretection procedures BROCKETT, T, THOMPSON, D Office of Inspection & Enforcement, Office of the Director 80/07/03 2pp
- B007230570 Forwards R0 50-219/B0-27-1F GARROLL.J T Jersey Central Power & Light Co B0/07/17 1p
- --8007230574 RO 50-219/60-27-1P on 800716, reactor bldg to suppression chamber vacuum breaker sys inlet pipe was found blocked by plastic bag Causad by personnel error Plastic bag was removed from vacuum breaker inlet opening CROBBY.P J Jersey Central Power & Light Co 80/07/17 2pp
- 8007250197 PNO-1-80-102 on 800717, pressure transient caused triple low water level signal followed by reactor low water level screm Cold shutdown underway for further analysis of incident KEIMIG.R R. BRUNNER.C. J. Region 1, Philadelphia, Office of the Director 80/07/18 2pp
- DDCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D. O Division of Licensing 80/06/25 89pp

- 8007070089 Petition to amend B00221 confirmatory order to allow operation w/o recirculation pump trip until Spring 1981 refueling outage Equipment needs to be inspected & prepared prior to installation Delay will be economical *practical DISE-D P Niagara Mohawk Power Corp 80/04/30 4pp
- 8007280093 Ack receipt of 800630 petition to amend confirmatory order Response will be forwarded thortly IPPOLITOIT A - Operating Reactors Branch 2 - 80'07/17 - 2pp
- H General correspondence
- 8007280540 Notifies of changes within util mgt All correspondence pertaining to security-related matters should be sont to JJ Sunser TE Lempus is vice president in charge of nuclear generation BARTLETT. J. Nisgara Mohawk Power Corp. 80/07/17. In
- I Financial information
- 8007280275 Forwards util Annual Financial Rept for 1979 LEMPGES, T.E. Niagara Mehawk Power Corp. 80/07/22 1p
- P Operating license stage documents % correspondence
- B007230028 Summary of B00207 meeting w/Mark I owners group in Osthesda. MD. re revisions to NRC acceptance criteria & outstanding issues relative to Mark I cuntainment long-turm program ORIMEB.CT Plant Systems Branch 80/02/21 Jipp
- B007070261 Forwards addition of putil commitments to meet NUREG-057B Recommendations 2 1 36.2 1 Ba & RCS venting Discusses inadequate core couling detection instrumentation & improved post-accident sampling capability
 DISE.DP Niagara Mohauk Power Corp 80/06/26 5pp
- 8007170393 Forwards application for amend to License DPR-63 consisting of changes to Tech Specs THOMAS.C.B. LeBoouf, Lamb, Leiby & MacRac 80/07/14 2pp
- ---8007170394 Application for amend to Lirense DPR-64 consisting of changes to Tech Spers re heat treatment of circulating water sys DISE D P Niagara Mohawk Power Corp 80/07/10 3pp
- --8007170397 Proposed changes to Tech Specs 2 O for limiting conditions for operation & 2 1 5 for heat treatment of circulating water sys
 - * Niagara Mohawk Power Corp 80/07/10 8pp
- --8007170403 "Assessment of Biological Impacts of Increasing Temp Change Limitation at Nine Mile Fount Unit 1" * Lawler, Matusky & Skelly Engineers 80/03/31 27pp
- Q Inspection reports. IC Bullotins & correspondence
- B007140474 Forwards IE Bulletin 80-13. "Cracking in Core Spray Spargers" Written response required GRIER, B M. Region 1. Philadelphia. Office of the Director B0/05/18 1p
- B007020157 Forwards IE Info Dutice 80-22, "Breakdowns In Contamination Control Programs " No written response required GRIER,B H Region 1, Philadelphia, Office of the Director GRIOS/2R in
- 8007010314 Forwards IE Info Notice 80-27, "lass of Suction to Emergency Foodwater Pumps" No written response required QRIER, B H Region i, Philadelphia. Office of the Director 80/05/29 ip
- 8007180073 Forwards reply to 1E Bulletin 80-08 re examination of containment liner penetration welds No deficiencies reported LEMPCES T C Niagara Mohauk Power (orp. 80/06/09 5pp.
- 8007210100 Responds to IE Rulletin 80~69, "Hydramotor Actuator Deficiencies " None of subjequipment in use or planned for use at facility LEMPRES, T.E. Niagara Mohawk Power Corp. 30/06/09. 1p
- 8007210989 Forwards IC Info Notice 80-26. "Fvaluation of Contractor GA Programs " No written response required GRIER, B H. Regjon 1, Philadelphia, Office of the Director 80/66/10 ip

07110272 Forwards IE Bulletin 80-14, "Degradation of BWR Stram Olischarge Vol Capability "Mritten response required GRIER.D H Region I, Philadelphia, Defice of the Director 80/06/12 lp

î

07020686 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) M/Loss of Offsite Power" Written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/06/18 ip

07020409 Forwards IE Carcular 80-15. *Loss of Reactor (bolant Pump Cooling & Natural Circulation Cooldown "No written response regulared SMIER D. H. Region 1. Philadelphia. Diffice of the Director

d H Region I. Philadelphia. Office of the Director G 1p 30/06/20

17160720 Forwards 1E Circujar BO-14. "Radioactive Contamination of Plant Dominoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required RIER. BH Region 1. Philadelphia. Office of the Director 10/06/24 ip

7210211 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial riteria" No written response required "RERD H Region 1, Philadelphia. Office of the Director 0/06/25 ip

7230149 Forwards IE Bulletin 80-16, "Potential Misapplication of osemount Inc Models 1151 & 1152 Pressure Transmitters /Either A or D Output Codes " Written response required E Circular 80-16 also encl No written response required RIER.B H Region 1, Philadelphia, Office of the Director RIER B H Re 0/05/2/ 2pp

7280471 Forwards response to 1E Bulletin 80-08. "Examination of intainment Ciner Ponetration Welds" No flued head enetrations utilized Penetrations used are end plates; silous type & cartridge type aVNE.J P Power Authority of the State of New York 80/06/27

/280465 Responds to IE Bulletin 80-10, "Contamination of impadioactive Sys & Resulting Potential for Unmonitored, acontrolled Release of Radioactivity to Environ" Istrument & house sic air sys added to analysis program MPOES. I E Niagara Mohawk Power Corp 80/07/02 ip

'250192 Submits reply to 1E Bulletin 80-17 re failure of control ids to insert Verified scram discharge vol sys was free of istructions
MPGES.TE Niagara Mohawk Power Corp 80/07/08 3pp

250241 Ack receipt of B00627 ltr informing NRC of steps taken to rest violations noted in IE Insp Rept 30-820/80-04 UNNER,E J. Region 1. Philadelphia. Reactor Operations Nuclear poort Branch 60/07/08 ip

07250258 Forwards IE Insp Rept 50-220/80-04 on 800505-09 & notice of Violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear
Support Branch 80/06/05 Epp

07250262 Notice of violation from insp on 800505-09
" Region 1, Philadelphia, Office of the Director 80/06/03 ip

0725026J IE Insp Rept 50-220/60-04 on 600505-09 Noncompliance noted failure to document site operations review committee

reviews (ISTER.H D Region 1. Philadelphia. Reactor Operations Nuclear upport Branch BAUNACK.W., HUDSON.S D Region 1. Philadelphia.)ffice of the Diroctor 80/06/03 7pp

10:19 Confirms that 20-day period for tests in Item 2 of IE letin 80-17. "Failure of 76 of 185 Control Rods to Fully ert Dusing Scram at 808." started at 12 01 AM on 800708 bests notification of malfunction & estimated manpower ER.B H Region 1, Philadelphia, Dffice of the Director 07/09 2pp

rindic operating reports & related correspondence

70360 Forwards monthly operating rept for June 1980 PGES.T E Niagora Mohawk Power Corp 80/07/11 2:

7170361 Monthly operating rept for June 1980 3MAN-7 W Niagara Mohauk Power Corp 80/07/11 3pp

S Reportable occurrences. LERs & related correspondence

8007270010 PNO-1-80-100 on 800711, normal reactor shutdown was conducted to investigate internal arring in main transformer Source of arring has not yet been found BAUNACK, W. KISTER, H. DRUNNER, E. Region 1. Philadelphia, Office of the Director BO/07/14 Ip

800727058A Forwards LER 80-011/04L-0 LEMPGES, T.E. Niapara Mohawk Power Core 80/07/22 in

--B007290600 LER B0-011/04L-0 on B00623, recorder review showed condenser inlet/circulating water discharge delta temp had exceeded Tech Spec limit on B00620-23 Btation load reduced, recorder scale expanded & Tech Spec change initiated HARRISON, P Niagara Mohawk Power Corp 80/07/22 2pp

DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

G Inspection reports. IE Bulletins & correspondence

8007160828 Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Bgs & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/06/24 1p

B007210142 Forwards IE Info Notice 60-24. "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director B0/06/25 ip

DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

H General correspondence

8007090277 Advises NRC that V Schrock is no longer reactor administrator 5 Kaplan has been reactor administrator since 791005 LIM.T H California, Univ of Berkeley 80/07/03 ip

O Inspection reports, IE Bulletins & correspondence

8007230350 Forwards 1E Insp Rept 50-224/80-02 on 800516 No noncompliance nated BOOKH E Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch 80/06/07 2pp

--8007230355 IE Insp Rept 50-224/80-02 on 800516 No noncompliance noted Major areas inspected upplanned accidental release of airborne radioactive matla, YUKAB.O P. Region 5. Ban Francisco. Fuel Facility & Materials Safety Branch WENSLAMSKI.F A , BOOK, H E Region 5, San Francisco. Office of the Director 80/06/09 4pp

8007210099 Forwards IE Insp Rept 50-224/80-01 on 800506-09 No noncompliance noted CREMS, J. Repton 5, Ban Francisco, Reactor Operations Nuclear Support Branch 80/06/11 2pp

--8007210107 IE Insp Rept 50-224/80-01 on 800506-09 No noncompliance noted Major areas inspected facility organization.logs & records & requalification training JOHNSON.A , CHAFFEE.A Region 5. San Francisco, Office of the Director FAVLKENBERRY.D Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/06/11 Spp

8007180959 Forwards 1E Circular 80-14, "Redicactive Contamination of Flant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENSELKENR H Region 5, San Francisco, Office of the Director 80/06/24 lp

DOCKET 50-225 RPI CRITICAL EXPERIMENT

O Inspection reports, IE Bulletins & correspondence

B007160809 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER. B H Region 1. Philadelphia, Office of the Director B0/06/24 ip

800721013B Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria " No written response required GRIER,B H Region 1, Philadelphia. Office of the Director 80/06/25 ip

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESCARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8007180272 Forwards IE Circular 80-14. "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required EMMELKENR H Region 5. San Francisco. Office of the Director 80/06/24 lp

DOCKET 50-236 LOCKHEED AIRCRAFT CORP

F Security, medical, emergency & fire protection plans

8007100123 Requests add1 time for completion of work re fire brigade medical evaluation program Completion date of 801031 established MAYER, L. O. Northern States Power Co. 80/06/27 1p

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 100FR2 790)
PEOPLES D L Commonwealth Edison Co 80/06/27 1p

B007290562 Submits results of mini-review of safe shutdown analysis No reasonable assurance that licensees fire protection will allow safe shutdown of Units 2 & 3 As minirecommends requirement for alternate shutdown sys or dedicated sys HALL: R E Brookhaven National Laboratory B0/07/09 7pp

@ Adjudicatory correspondence

BOO7310243 Forwards Commission BOO527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
EISENHUT, D Q Division of Licensing 80/06/25 B9pp

8007010331 Forwards safety evaluation & EIA re spent fuel pool mods W/o encls QDDDARD,R J Hearing Branch 2 80/06/27 ip

H General correspondence

B007300013 Responds to 770405 ltr re nuclear power State of IL has seven nuclear power plants Reasons for use of nuclear power plants in IL listed in encl excerpt from util annual rept President 771207 statement re Kemeny Commission Rept encl DENTON.H R Office of Nuclear Reactor Regulation. Director B0/06/26 2089

P Operating license stage documents & correspondence

B007230028 Summary of 800207 meeting w/Mark I owners group in Dethesda. MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES, C T Plant Systems Branch 80/02/21 Sipp

800725055B Forwards NUREG-0619. "BWR Feedwater Nozzle & Control Rod Drive Return Line Nozzle Cracking." for review & comment CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/04 2pp

B007010003 Forwards safety evaluation & EIA supporting proposed facility mods to increase spent fuel storage pool capacity Final approval cannot be granted until ASLB resolves legal issues CRUTCHFIELD, D.M. Operating Reactors Branch 2 80/06/05 2pg

--8007010008 Safety evaluation supporting proposed facility mods to increase spent fuel storage pool capacity # Office of Nuclear Reactor Regulation, Director 80/06/06 14no.

--B007010011 EIA supporting proposed facility mods to increase spent fuel storage pool capacity 4 Office of Nuclear Reactor Regulation, Director 80/06/04 10pp BOO7010146 Forwards final rule published in 800509 FR amending 10CFR50 71 to require periodic updating of FSARs Compliance is not required until completion of SFP CRUICHFIELD. D Operating Reactors Branch 5 80/06/10 5pp

8007020186 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIELD. D M Operating Reactors Branch 5 80/06/11 2pp

8007010042 Forwards NRC evaluation of SEP Topic V-5 re RCPB leakage detection Requests info concerning util as-built facility differing from litensing basis assumed in assessment CRUICHFIELD.D M Operating Reactors Branch 5 80706/12 Spp

BOO7010217 Forwards NRC evaluation of SEP Topic VIII-4 re electrical penetrations of reactor containment Requests info concerning util as-built facility differing from licensing basis assumed in assessment CRUTCHFIELD. D M Operating Reactors Branch 5 80/06/12 10pp

8007010292 Forwards evaluation of SEP Topic V-12 A re water purity of BHR primary coolant Review completed & resulting evaluation will form input to integrated safety assessment unless changes are needed to reflect as-built conditions CRUTCHFIELD.D Operating Reactors Branch 5 80/06/12 3pp

8007010030 Forwards request for add1 info on SEP Topic XV-16 re radiological consequences of small lines carrying primary coolant outside containment Response requested within 30 days of receipt of itr LAINAB.G C Assistant Director for Safety Assessment 80/06/16

8007100399 Responds to 800229 Iti which expressed apposition to ACRS recommendation to restricture SEP Role of licenses in program will expand Ltr forwarded to Commissioners DENTON IR Differ of Nuclear Reactor Regulation, Director 80/06/18 4pp

--B0071004R0 Expresses apposition to ACR9 recommendation to restructure SEP For SEP owners to perform safety analysis as autimed, cost in dullars & manpower would increase dramatically SCHAFFSTALL.R SEP Duners Group 80/02/27 2pp

B007160499 Forwards "Loss of Offsite Power · Survey Status Rept "
Requests views re causes & possible remedies within 120
days
CRUTCHFICLD.D M Operating Reactors' Branch 5 B0/04/19 2pp

--8007160463 "Loss of Offsite Power - Survey Status Rept," Revision 1 SCHOLL, R F Systematic Evaluation Program Branch 80/06/19 9pp

BD0701019D Responds to SBRT concerns re control rod drive sys lacking seismic analysis Guad Cities 1 & 2 seismic design of control rod drive sys calculations performed for facility while under const encl

JANECEK, R F Commonwealth Edison Co 80/06/24 App

--8007010193 "Quad Cities 1 & 2 Spismic Data on Control Rod Drive Sys "
* Reactor Controls, Inc 70/07/10 200pp

BOO7070116 Submits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads JANECEK.R F Commonwealth Edison Co BO/06/26 App

8007080063 Responds to NRC 800515 request for addl info concerning adequacy of station electric distribution sys voltages

JANECEK, R F Commonwealth Edison Co 80/06/30 App

BOO7070345 Forwards revised schedule & status info for Mark I program, feedwator sparger replacement & general work planned for Guad Cities I outage Proceeding on priority basis w/mods providing largest safety increase margins REED, C. Commonwealth Edison Co. 80/07/02 18pp

BOO7250032 Forwards "Loss of Offsite Power ~ Survey Status Rept " Replaces BOO619 rept which unitted Table 4 CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/OB Spp

--8007230035 "Loss of Offsite Power - Survey Status Rept " SCHOLL, R F Plant Systems Branch (Pre 791030) 80/07/08 10pp

8007210212 Responds to MRC request for add1 info le turbine disks Applicable turbine missile analysis was presented in Amend 2 to Quad Cities CP application Analysis applies to Dresden due to similarity of general arrangement JANECEM.R F Commonwealth Edison Co 80/07/15 ip

- 8007280074 Responds to 800318 ltr to J Ahearne objecting on behalf of owners of plants under SEP review to current plans for expedited review of environ qualification of electrical equipment forwards applicable memorandum & order DENTON, HR Office of Nuclear Reactor Regulation, Director 80/07/16 4ps
- @ Inspection reports, IE Bulletins & correspondence
- 8007140545 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers" Written response required MEPPLER, J G Region 3, Chicago, Office of the Director 80/05/12 10
- 8007070072 Forwards IE Insp Repts 50-010/80-09,50-237/80-08 & 50-249/80-12 on 800407-0502 & notice of violation KEPPLER, J G Region 3, Chilago, Office of the Director 80/05/23 200
- --8007070074 Notice of violation from insp on 800407-0502 * Region 3. Chicago. Office of the Director 80/05/23 2pp
- --8007070080 IE Insp Repts 50-10/80-09.50-237/80-08 & 50-249/80-12 on 800407-0502 Noncompliance noted failure to adhere to GA program requirements Contaminated clothing found lying inside controlled contaminated area SFESSARD.R L . DARKER.J L . TONGUE,T M Region 3. Chicago, Office of the Director 80/05/23 7pp
- 8007020065 Forwards IE info Notice 80-22, "Breakdowns in Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28 ip
- 1007010086 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Fumps " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/29 ip
- 3007220156 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required **XEPPLER, J G Region 3, Chicago, Office of the Director 80/06/10 is
- 1007020662 Forwards site-specific & generic questions re GE disc cracking indications per 800109 meeting & IE Info Notice 79-37 on Mestinghouse low pressure turbines disc cracks Response requested within '10 days CRUTCHFIELD D Operating Reactors Branch 5 80/06/11 5pp
- 1007140307 Forwards IE Bulletin 80-14, "Degradation of DWR Scram Discharge Vol Capability " Written response required MEPPLER, J G Region 3, Chicago, Office of the Director 80/06/12 16
- 007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or compenent at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor PEOPLES.B. L. Commonwealth Edison Co. 80706/16 3pp
- 007030037 Forwards IC Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPFLERJ O Region 3, Chicago, Office of the Director 80/06/18
- 007230371 Forwards IE Insp Repts 50~010/80-10,50-237/80-09 & 50-249/80-13 on 800305-29 & notice of violation HEIEHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/19 2pp
- -8007230379 Natice of violation from insp on 800305-29 * Region 3. Chicago. Difice of the Director 80/06/19 ip

010/80-10.50-237/80-09 & 50-249/80-13 on ted failure to report events in

reion 3. Chicago, Office of the

or Coalant Pump response

tor 80/06/20

- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24 ip
- 8007230289 Forwards JE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/27 ip
- 8007180003 Ack receipt of 800613 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-010/80-09, 57-237/80-08 & 50-249/80-12 KEPPLER, J & Region 3, Chicago, Office of the Director 80/07/01 to
- --8007180010 Responds to NRC 800523 ltr re viplations noted in IE Insp Repts 50-010/80-09,50-237/80-08 & 50-249/80-12 Corrective actions improved mgt controls were implemented Radiation protection training classes were held for contractors REED, C Commonwealth Edison Co 80/06/13 6pp
- 8007180509 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BMR," will start at 12 01 AM on BOO708 Test should be completed within 20 days Requests notification of malfunction KEPPLER, J Q Region 3. Chicago, Office of the Director 80/07/07 ip
- 8007250641 Responds to IE Bulletin 80-10. "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found PEOPLES,D.L. Commonwealth Edison Co. 80/07/07 2pp
- 8007250650 Forwards response to IE Bulletin 80-11, "Masonry Hall Design " Requested investigation not performed at Dresden, Unit 1 due to extended outage Requirements will be met prior to startup H/o encl PEOPLES.D L Commonwealth Edison Co 80/07/07 2pp
- 8007250638 Forward* response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresden Unit i designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES, D.L. Commonwealth Edison Co. 80/07/09 7pp
- B007160630 Responds to IE Bulletin 80-17 re results of tests required by Item 1 No significant amount of water in scram discharge vols Vent & drain lines also verified free of obstructions by performing dynamic air test

 JANECEK.R F Commonwealth Edison Co B0/07/10 2pp
- 8007300485 Responds to IE Bulletin 79-14, "Seasmic Analysis for As-Built Safety-Related Piping Sys," by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria" JANFCEK.R F Commonwealth Edison Co 80/07/16 1p
- ~-8007300498 "Engineering Criteria/Procedure for Review & Resolution of As-Built Deviations." Revision 2 SNYDER.T K EDS Nuclear: Inc 80/03/07 iipp
- --8007300508 "Engineering Criteria Procedure for Application of Blume Curves Criteria " SNYDER,T K EDS Nuclear, Inc 80/03/07 20pp
- --8007300508 "Engineering Criteria Procedure for Application of Blume Curves Criteria " SNYDER.T K. EDS Nuclear, Inc 80/03/07 20pp
- R Periodic operating reports & related correspondence
- 8007180333 Forwards monthly operating repts for June 1980 SYEPHENSON, B B Commonwealth Edison Co 80/07/09 1p
- --9007180334 Monthly operating repts for June 1980 ClebzieWicz, 8 Commonwealth Edison Co 80/07/02 23pp
- B Reportable occurrences. LERs & related correspondence
- B007010497 Forwards LER 80-022/01T-0 STEPHENSON, B II Commonwealth Edison Co 80/06/24 1p

1

- --8007010505 LER 80-022/01T-0 on 800611. found that control rod driveline scram discharge piping did not meet FBAR seismic requirements Caused by design deficiency New correct seismic supports are being designed

 * Commonwealth Edison Co 80/04/24 2pp
- 8007010544 Forwards LER 80-019/03L-0 8TEPHENSON, B B Commonwealth Edison Co 80/06/24 1p
- --8007010551 LER 80-019/03L-0 on 800528, at steady state power operation, C main steam line rad monitor tripped Caused by electronic component failura Assembly replaced BADRAN, 8 Commonwealth Edison Ca 80/06/24 ip
- 8007100179 Forwards LER 80-021/03L-0 8TEPHENSON, B, B Commonwealth Edison Co 80/07/02 ip
- ---8007100187 LER 80-021/03L-0 on 800607, during normal operation, while performing drywell-torus pumphack dp instrument surveillance drywell-to-torus dp dropped below 1 psi for 2-hr Cause not stated Personnel informed of requirement re dp MADROW, R Commonwealth Edison Co 80/07/02 lp
- 8007100187 Forwards LER B0-020/03L-0 BTEPHENSON, B B Commonwealth Edison Co 80/07/02 1p
- --8007100192 LER 80~020/03L~0 on 800608, during surveillance DDB 1600-9, torus-to-drywell vacuum broaker 2-1601-32D failed to give redundant open indication Caused by stuck switch Bracket was tightened & DDB 1600-9 was repeated successfully DUNBAR, J Commonwealth Edison Co 80/07/02 2pp
- 8007220557 Forwards LER 80-023/03L-0 8TEPHENSON, B B Commonwealth Edison Co 80/07/14 1p
- --B007220572 LER B0-023/03L-0 on 800228 during attempt to vent torus, valves A0-2-1601-60 & -61 failed to open Caused by loss of instrument air to air operated valves Air supply valved back in & valves demonstrated operable
 MAOROW, R Commonwealth Edison Co 80/07/14 2pp
- B007230339 LER 80-005 has been cancelled. COLLINS,M Commonwealth Edison Co. 80/07/22 1p
- DOCKET 50-249 GREGON STATE UNIV RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 8007150649 Advises of procedural inadequacy re radiography of unauthorized explosive matl on 800626 Caused by inadequacy in applying administrative or procedural controls Separate cover sheet indicating approved matls will be issued. HANO, C. H. Oregon State Univ. 80/07/11 4pp
- G Imagaction reports, IE Bullatins & correspondence
- 8007180247 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/24 1p
- 8007240361 Forwards IE Insp Repts 50-106/80-02, 50-243/80-03 & 70-0971/80-01 on 800630-0701 No noncompliance noted Encis withheld (ref 100FR2 790) NGRDERHAUG, R Region 5, Ban Francisco, Safeguards Branch. 80/07/14 2pp
- DOCKET 50-244 RDBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007110129 Notification of 800605 meeting w/util in Bathesda, MD to discuss fire protection plans
 NOWICKI.B J Operating Reactors Branch 5 80/06/02 2pp
- B007100214 Summary of 800605 meeting w/util in Bethesda.Md re proposed rule concerning fire protection program for nuclear power plants operating prior to 790101.
 NOWICKI.S J. Operating Reactors Dranch 2 80/06/26 4ipp
- 8007070342 Summarizes Gilbert & Associates, Inc study relactive & passive sys to control fires in areas of exposed structural stael in response to NRC 770214 fire protection safety avaluation, Item 3 2 8 HHITE; L D Rochester Gas & Electric Corp 80/06/30 App

- 8007300050 Ack receipt of 791210 ltr transmitting changes to security plan Second change is not consistent w/provisions of 10CFRSO 54(p) Addl info encl Encl & ref ltr withheld (ref 10CFR2 790)
 CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/17 2pp
- B007310350 Submits security plan info.per NRC 800717 ltr Info withheld (ref 100FR2 790)

 WHITE,L D Rochester Gas & Electric Corp 80/07/24 3pp
- 8007310378 Forwards security contingency plan Plan withheld (ref 10CFR2 790) WHITE,L D Rochester Gas & Electric Corp 89/07/24 ip
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D Q Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- 8007010124 Forwards final rule published in 800509 FR amending 10CFR50 71 to require periodic updating of FSARs Compliance is not required until completion of SEP CRUYCHF1ELD, D Operating Reactors Branch 5 80/06/10 5pp
- BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D 0 Division of Licensing 80/06/11 62pp
- 8007140623 Forwards Amend 33 to License DPR-18, safety evaluation & notice of issuance & availability
 CRUTCHFIELD, D Derating Reactors Branch 5 80/06/13 2pp
- --8007140628 Amend 33 to License DPR-18, approving secondary water chemistry monitoring program implementation Effective on B00630 CRUTCHFICLD. D Operating Reactors Branch 5 80/06/13 2pp
- --8007140632 Safety evaluation supporting Amend 33 to License DPR-18 * Operating Reactors Branch 5 B0/06/13 2pp
- --8007140636 Notice of issuance & availability of Amend 33 to License BPR-18 CRUTCHFIELD, D Operating Reactors Branch 5 80/06/13 3pp
- 8007100399 Responds to 800229 ltr which expressed apposition to ACRS recommendation to restructure SEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON.H R Office of Nuclear Reactor Regulation. Director EQ/06/18 4pp
- ---B007100420 Expresses apposition to ACRS recommendation to restructure BEP For SEP owners to perform safety analysis as outlined, cost in dullars & manpower would increase dramatically SCHAFFBTALL, R SEP Owners Group 80/02/29 2pp
- B007280107 Forwards "SEP Review of Pipe Break Outside Containment, Topic III-5 B. for Oinna Nuclear Power Plant " & five staff positions Requets addl info to complete review CRUYCHFIELD, D Operating Reactors Branch 5 80/06/24 3pp
- --8007280113 "SEP Review of Pipe Break Outside Containment, Topic III-5 | for Olma Nuclear Power Plant" # Operating Reactors Branch 5 #0/06/24 Ropp
- BOO7240067 Requests add1 info to continue review of SEP Topic VIII-i.A.
 "Isolation of Reactor Protection Bys From Nonsafety Bys.
 Including Qualification IO Isolation Bevices"
 GRUTCHFIELD, D M Operating Reactors Branch 5 80/06/25 3pp
- BOO7250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EIBENHUT, D Q Division of Licensing 80/07/02 49pp

- 7180109 Notifies that NOURDE request for route approval to cover highests of mixed oxide fuel rods to Ginna Station is subj., license fee Review of request had completed on 800213 ILLER.W () License Fee Management Branch 80/07/03 ip
- 7230057 Responds to util 800208 request for route approval covering imments of mixed axide fuel rods Review of licensee route approval requests subj to license fee schedule in 100FR170 ILLER, W D license Fee Management Branch 80/07/03 ip
- 7240144 Forwards evaluation of actions taken to satisfy Category A tems of NRC recommendations resulting from TMI-2 lessons earned recommendations Category A items have been atisfactorily met w/exception of Items B 2 I b & 2 I 3 b RUTCHFIFLD.D M Operating Reactors Branch S 80/07/07 11pp
- /180397 Responds to 800/03 inquiry re process whereby draft valuation performed by Franklin Inst & containing possibly coprietary info could be released to Rochestor Cas & ectric Hestinghouse has proprietary agreement within ESEMANN.R A Hestinghouse Electric Corp. 80/07/09 ip
- '200135 Forwards NRC review of control rod guide thimble wear in Rs Based on review issue is resolved for 14x14 fuel samblies designed by Westinghouse UYCHFIELD.D M Operating Reactors Branch 5 80/07/10 4pp
- 220403 Forwards response to NRC 791022 ltr requesting addl info re xiliary feedwater sys flow requirements Response to quest for info re evaluation of auxiliary feedwater sys quirements was provided 79128
 ITE, L. D. Rochester Gas & Electric Corp. 80/07/14 14pp
- 07220407 "Feedwater Sys Flow Diagram " * Rochester Gas & Electric Corp 80/05/30 ip
- 280076 Responds to 800318 itr to J Ahearne objecting on behalf of ners of plants under SCP review to current plans for pedited review of environ of electrical diagnost Forwards applicable memorandum & order JTQN-II R Diffice of Nuclear Reactur Regulation. Director /07/16 4pp
- '90740 Forwards comments on NAC assessment of SEP Topic VIII-4 ansmitted by DL Ziemann 800324 ltr Also: forwards responses add questions raised by review Oversize drawings silable in Central Files only ITE, L D Rochester Gas & Electric Corp 80/07/21 29pp
- 318401 Advises that design criteria for seismic upgrade program, maitted for 800/15 will be delayed until 800813 Delay 1 not impact submittal of analysis packages on schedule scribed in 800530 ltr
 ITE, L D Rochester Gas & Electric Corp 80/07/24 1p
- ispection reports. IE Bulletins & correspondence
- 120134 Forwards II Info Notice 80-22. "Orealdowns In Contamination strol Programs " No written response required ER,8 H Region I. Philadelphia. OPPice of the Director '05/28 ip
- 110296 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency dwater Pumps " No written response required 58.8 ft Region I. Philadelphia. Office of the Director 05/29 ip
- 10157 Forwards IC Inap Rept 30-244/80-03 on 600421-25 No compliance noted NNER.E J. Region 1. Philadelphia. Reactor Operations Nuclear port Branch 60/05/27 Epp
- 7210165 IC Insp Rept 50-244/80-03 on 800421-25 No noncompliance oted, Major areas inspected refueling & outage activities naturing preparations for refueling & previous inspinitings of the process of the Director IBTER:H D Region I, Philadelphia, Office of the Director Upper House Boyon, D Region I, Philadelphia, Reactor Operations Nuclear upport Branch 80/05/27 3pp
- 90176 Forwards IE Insp Rept 50-244/80-05 on 800421-24 No compliance noted IIN.H O Region I. Philodelphia. Bafeguards Branch 80/05/30

- --B007290197 IE Insp Hept 50-244/B0-05 on B00421-24 No noncompliance noted Major areas inspected security plan, decurity program audit, protected area physical barriers & access control to vital areas Details withhold (ref 100FR2 790) MADDEN, H. Region 1, Philadelphia, Office of the Director DEVLIN, J.W. Region 1, Philadelphia, Safeguards Branch, 80/05/27 to
- 8007020018 Responds to IE Bulletin 80-06. "Engineered Bafety Feature IESF) Reset Controls " No inconsistencies were found between schematics & actual installations No areas were identified that require mod or design change
 WHIYE.L D Rochester Gas & Electric Corp 80/06/03 3pp
- B0072i0619 Forwards IE Info Notice 80-26, "Evaluation of Contractor 8A Programs " No written response required GRIEP.B K Region 1, Philadelphia, Office of the Director 80/06/10 ip
- 8007160364 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required GRIEFAB H Region I, Philadelphia, Office of the Director GO/06/11 1p
- 8007020713 Forwards IE Bultetin BO-15. "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power " Written response required GRIER-B H Region 1, Philadolphia, Office of the Director. 80/06/18 1p
- 8007020487 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required CRIER B H Region 1, Philadelphia, Office of the Director. 80/06/20 1p
- B007160747 Forwards IE Circular B0-14. "Radioactive Contamination of Plant Demineralized Mater Bys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director B0/06/24 1p
- 8007180141 Submits reply to IE Bulletin 80-10 re contamination of nonradioactive sys & potential for release Based upon review of sys.no addit sampling or monitoring program need be established HHITE.L D Rochester Oas & Electric Corp 80/06/24 2pp
- 8007210286 Forwards lE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response requires. GRIER.8 H Region i. Philadelphia. Office of the Director 80/06/25 ip
- 8007230005 Ack receipt of B00523 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-244/78-24, BRUNNER.E J Region : Philadelphia Reactor Operations Nuclear Support Branch 80/06/26 ip
- --8007230008 Responds to NRC 790719 ltr re violations noted in IE Insp Rept 50-244/78-24 Corrective actions storage room will be built to comply w/NRC Reg Guide i 88 HHITE:L D Rochester Gas & Electric Corp 80/05/23 Zep.
- --8007230007 Ack receipt of 790907 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/78-24 BRP Paragraph 12 4 is acceptable atternative to Reg Guide 1 88 HAAS.W P Guality Assurance Branch 79/09/19, 1p.
- 8007230183 Forwards IE Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required. GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp.
- 8007230498 Forwards response to Items 1,2a & 3 of IE Bulletin 80-11, "Masonry Hall Design " All walls surveyed except svc bldg which is not safety-related All walls will be re-evaluated to determine adequacy to perform design function.

 WHITE,L.D Rochester Gas & Electric Corp 80/07/07 24pp.
- GOG7280142 Forwards NRC evaluation of Apr 1980 steam generator insp results Agrees that plant should return to power after insp & concurs w/proposed mid-cycle insp Insp program & comments should be submitted 40 days prior to scheduled shutdown CRUTCHFIELD.D Operating Reactors Branch 5, 80/07/08, 4pp

- R Portadic operating reports & related correspondence
- 8007130584 Forwards monthly operating rept for June 1980 SNOW.B A Rochester Gas & Electric Corp 80/07/09 ip
- --9007150590 Monthly operating rept for June 1980 MCNAMARA.A Rochester Gas & Electric Corp 80/07/07 5pp
- 8 Reportable occurrences, LERs & related correspondence
- BOO7160637 RO 80-06 on 300711, chemical analysis indicated boric acid storage tanks below Tech Specs for vol & percent weight boric acid Couse not stated Orderly power reduction & batching operations begun to restore tanks to specs SNDW, B A Rochester Gas & Electric Corp 80/07/11 ip
- 8007210443 RD 80-04 on 800714, chemical analysis indicated boric acid storage tanks out of spec for vol & % weight of boric acid Caused by inadvertent dilution of concentration determining chemical reagents Tanks restored to required specs SNOW, B A Rochester Gas & Electric Corp 80/07/14 2pp
- 8007280633 Forwards LER 80-006/017-0 WHITE.L D Rochester Gas & Electric Corp 80/07/24 lp
- --8007280639 LER 80-006/017-0 on 800711.during routine analysis of boric acid tank samples.concentration exceeded Tech Spec limit on three occasions Gaused by entry of ascerite into tank Reagent check now performed w/sampling FILKINS.D Rochester Gas & Electric Corp 80/07/24 2pp
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 ltr to all power reactor licensees, in response to 800529 ltr re emergency response facilities at reactor sites sites w/approval to vsv closed-circuit television link w/technical support ctr listed CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/07 2pp
- 8007010337 Gamments on proposed rule 10CFR50 regulation for fire protection excessively specific & unjustifiably restrictive Buggosted revisions to App R w/justifications oncl COUNSIL,W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W 0 Connecticut Yankow Atomic Power Co COUNBIL,W 0 Northeast Utilities 80/06/16 31pp
- 8007030956 Comments on proposed rule 10CFR50 requirements far exceed those necessary to resolve generic issues & are excessively specific & restrictive Forwards alternative App R fire protection program COUNSIL, W G Connecticut Yankes Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/16 | Lope
- 8007090231 Forwards responses to NUREG-0654 criteria & facilities emergency plans per NRC 800512 & 791010 ltrs Encls available in Central Files only Emergency plans withheld (ref 10CFRZ 790) COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (Bubs of Northeast Utilities) 80/06/30 2pp
- B007170425 Confirms position discussed in B00624 telcon is safeguards contingency plans NRC requested revisions are ill-advised & unnecessary Bpecifics of plan implementation can be detailed in pracedures
 CDUNSIL, W @ Connecticut Yankoe Atomic Power Co CDUNSIL, W @ Northeast Nuclear Energy Co (subs of Northeast Utilities)
 B0/07/01 2pp
- Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 polition for reconsideration of 780413 memorandum & order UCB 771104 polition sought action re fire protection for electrical Lables EIBENHUT, D. G. Division of Licensing 80/06/25 89pp
- I Financial information
- 8007150622 Forwards 1980 cash flow estimates for CT Light & Power Co. Hartford Electric Light Co & Mestern MA Electric Co Cash flows are adequate to meet potential premium requirements for 1975 amends to Price-Anderson Act
 O'CONNOR, L. A. Northeast Utilities 80/07/03 Spp

- P Operating likense stage documents & correspondence
- 800/2300/28 Summary of 800/207 meeting w/Mark I owners group in Bethesda, MD re revisions to NRC acceptance criteria & outstinding issues relative to Mark I containment long-torm program GRIMES, C.T. Plant Systems Branch 80/02/21 31pp
- 8007/250346 Forwards NUREG-0619, "BWR Fredwater Nozzle & Control Rod Drive Return Line Nozzle Cracking," for leview & comment CRUTCHFIELD.D Operating Reactor, Branch 5 80/06/04 2pp
- B007010130 Forwards final rule published in B00509 FR amending 10CFR30 71 to require perodic updating of FSARs Compliance is not required until completion of SEP CRUTCHFIELD, D Operating Reactors Branch 5 B0/Qb/10 5pp
- 8007010328 Advises that alternate insp: will be performed in lieu of ABME visual crams for 1980 refueling, pur WG Counsi; 800409 ltr to DL Ziemann Formal docketed waiver of requirement still requested COUNSIL.W G Hortheast Nuclear Energy Co (subs of Northeast Utilities) 80706/10 2pp
- B007100379 Responds to 800289 itr which expressed apposition to ACRS recommendation to restructure BEP Role of licensons in program will expand Ltr forwarded to Commissioners BENTON. If R. Office of Nuclear Reactor Regulation, Director 80/04/18 4pp
- --8007100420 Expresses apposition to ACRE recommendation to restricture SEP for SEP awners to perform safety analysis as autlined, cost in dollars & manquwer would increase dramatically SCHAFFSTALLR SEP Cuners group 80/02/29 2pp
- G007020969 Clarifies 600806 response to NRC 791030 request for info concerning Lessons Learned Task Force Item 2 1 B a, improved post-accident sampling capability Info ensures accurate NRC understanding of dissign philosophy & intent COUNSIL.W Q Connecticut Yankee Atomic Power Co COUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 60/06/23 30p
- 8007240073 Requests addl info to continue review of adequacy of station electric distribution sys voltages Response requested within 45 days of receipt of the CRUTCHITELD.D M Operating Reactors Branch 5 80/06/27 5pp
- 8007070251 Notifies of change to schedule described in 800314 ltr re environ qualification of safety-related equipment Unscheduled facility outage postponed scheduled start of 1780 refueling nutage for approx 2-4 wks COUNSII.4 Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/30 Zpp
- B007170319 Summary of B00612 meeting w/etils in Bethesda, MD re interim reliability evaluation program OLSHAN, L N - Operating Reactors Branch 1 - 80/06/30 - 3pp
- BOO7230iil Forwards NRC "SEP Technical Evaluation Topic VIII-4, Electrical Penutrations of Reactor Containment " Assessment compares facility w/criteria corrently used by regulatory psisonnel for licensing new facilities CRUTCHFIELD.D Operating Reactors Branch 5 80/07/01 2pp
- --800/230384 "SEP Technical Evaluation Topic VIII-4, Electrical Penetrations of Reactor Containment"

 * Operating Reactors Branch 5 86/07/01 9pp
- BOO7250694 Advises that NRC has approved conceptual design of postaccident sampling sys Lists soveral addl areas which should be addressed CRUTCHIIFLD, D M Operating Reactors Branch 5 BO/07/01 3pp
- 800/100200 Forwards response to NRC 900007 requests for add1 info re-proposed revisions to ETS State of CY Dept Environ Protertion 800611 ltr approving Thermal Plume Study Rept and1 COUNSIL-W G Hartheast Utilities 80/07/03 27pp
- 8007210387 Forwards info re environ qualification of electrical equipment info supersedes info provided by 800602 ltm & reflects additions & delections from original listing COUNSIL W G. FRE. W F. Northeast Nother Chergy Co. (subs. of Northeast Utilities) 60/07/07 214pp

- B007220457 Application for amend to Licenses DPR-21 % DPR-65 to incorporate changes to Tech Specs re organizational title Class I fee enci COUNSIL W G. FEE.N F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/07/14 Spp.
- --8007220467 Proposed revised Pach Specs, incorporating organizational title changes • Northeast Nuclear Energy Co (subs of Northeast Utilities)
- 8007250300 Application to amend lacenses DPR-21 % DPR-65, clarifying Tech Specs to reflect recent organizational tible changes License fee transmitted 800714 Affidavit encl COUNSIL,R C Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/15 2pp
- --8007250303 Proposed revisions to ETS.Pages 5 1-2 & 3 1-5, reflecting recent organizational title changes

 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/15 3pp
- 8007280075 Responds to 800318 ltr to J Ahearne objecting on behalf of owners of plants under SEP review, to current plans for expedited review of environ qualification of ejectrical equipment Forwards applicable memorandum & order DENTON:HR Office of Nuclear Reactor Regulation, Director 80/07/16 4pp
- 8007280574 Application for amend to License BPR-21, providing further assurance of adequacy of electrical distribution sysvoltages Class III fee encl COUNSILN G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/16 Spp
- --8007280582 Proposed Tech Spec changes providing further assurance of adequacy of electrical distribution sys voltages

 * Northeast Hurlear Energy Co (subs of Northeast Utilities) 80/07/31 900
- 8007280673 Requests extension of comment period re NUREG-0577.
 "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports," until 800915 COUNSIL, N G Northeast Utilities 80/07/21 2pp
- O Inspection reports, 16 Bulletins & correspondence
- B007140452 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers "Written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/05/12 1p
- 8007020146 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/05/28 ip
- 8007010312 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required GRIER.8 H Region i, Philadelphia, Office of the Director 80/05/29 ip
- 8007210580 Forwards 1E Info Nutice 80-26, "Evaluation of Contractor GA Programs "No written response required GRIER.B H Region 1. Philadelphia, Office of the Director BO/06/10 Ip
- 8007020569 Forwards site-specific & generic questions re GE disc cracking indications per 800109 meeting & IE Info Notice 79-37 on Mestinghouse low pressure turbines disc cracks Response requested within 30 days M/o soci CRUTCHFIELD, D Operating Reactors Branch 5 80/06/11 9pp
- 8007140260 Forwards IE Bulletin NO-14, "Degradation of DWR Scram Discharge Vol Capability " Written response required CRIER. B H Region 1. Philadelphia. Defice of the Director 80/06/12 ip
- 8007170320 Responds to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls." Three fucilities will have completed mods per IE Bulletin 80-06 by Bioldi List of equipment & status of criteria encl COUNSIL.W 9 Connecticut Yankee Atomic Power Co COUNSIL.W 9 Northeast Utilities. 80/06/13 43pp

- 8007020700 Forwards IE Bulletin 80-i5, "Possible Loss of Emergency Notification Sys (CNS) W/Loss of Offsite Power " Written response required GRIER, B H Region I, Philadelphia, Office of the Director 80/06/18 lp
- B007180137 Submits reply to IE Bulletin 80-08 re examination of containment liner penetration welds Due to absence of abnormal conditions no further action planned COUNBIL-W G Northeast Utilities B0/06/19 lipp
- 8007310361 Forwards IE Insp Repts 50-245/80-07 & 50-336/80-05 on 800501-31 No noncompliance noted BRUNNER E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/19 2pp
- --8007310365 IF Insp Repts 50-245/80-07 & 50-336/80-05 on 800501-31 No moncompliance noted Major areas inspected control rooms & accessible portions of Unit 1 reactor turbine, raduaste, gas turbine generator & intake bldgs
 SHEDLOSKY.J T , ZIMMERMAN,R P Region i, Philadelphie, Office of the Director KEIMBOR R, Region i, Philadelphia, Reactor Operations Nuclear Support Branch S0/96/18 9pp
- 8007020494 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response GRIER, D. H. Region 1, Philadelphia, Office of the Director 80/04/20
- B007140714 Forwards 1E Circular B0-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required CRIER, B H. Region 1, Philadelphia, Office of the Director B0/06/24 ip
- 8007210207 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/06/25 ip
- 8007230146 Forwards IE Bulletin 80-16, "Potential Misapplication of DO/20144 FORWARDS IE BUILETIN BOTIS. "Potential disapplica Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Csrcular 80-16 also encl No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 80/06/27 29p
- 8007210071 Confirms that 20-day period for tests in Item 2 of IE Bulletin BO-17, "Failure of 76 of 185 Control Rods to Fully Insert Buring Boram at BWR," started at 12 01 AM on 800708 Requests notification of malfunction & estimated manpower GRIER.D H Region 1. Philadelphia. Office of the Director BO/07/09 2pp
- B007290697 Submits add1 response to IE Bulletin B0-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR "
 Manual scram test revealed test connection wiring error
 Hiring corrected & Functional test performed
 MRGCZKA, E. J. Northeast Utilities B0/07/21 2pp
- R Periodic operating reports & related correspondence
- BOO7160676 Forwards monthly operating rept for June 1980 MRDCZKA:E J Northeast Utilities 80/07/09 ip
- --8007160680 Monthly operating rept for June 1980 HARRAN.O Northeast Utilities 80/07/07 9
- 8007180409 Forwards monthly operating rept for June 1980 MROCZKA:E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/09 ip
- ~~8007180413 Monthly operating rept for June 1980 HURRAN,G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/07. 19pp
- S Reportable occurrences, LERs & related correspondence
- BOO5230131 PNO-I-80-071 on 800505, significant number of security force personnel, contracted from Interstate Security Svcs, Inc. began taking leave at start of mid-shift Security supervisors working 12-h shifts will maintain full coverage ZIMMERMAN, R P. KEIMIG, R R. DEVLIN, J W. Region 1, Philadelphia, Office of the Director 80/05/05 ip
- B007100157 Forwards LER B0-009/03L-0 MRDCZKA E J Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/07/02 lp

--8007100164 LER 80-009/03L-0 on 800605, during routine surveillance, found grassure suitch 263-55C tripped outside allowable setpoint Caused by setpoint drift Prossure switch reset to required setpoint

* Northeast Nuclear Energy (o (subs of Northeast Utilities)

BO/07/02 3pp

8007100167 Forwards LER 80-008/03L-0 MRDCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/02 ip

--8007100172 LER 80-008/03L-0 on 800609, dwring routine surveillances, found pressures suitches 263-52C & 263-54A tripped outside allowable Tech Spec Coused by setpoint drift Pressure switches reset to required setpoints
BIGIARELLIM J Northeast Nuclear Energy (o (subs of Northeast Utilities) 80/07/02 3pp

8007110466 Forwards LER 80-009/03L-0 MOCCINATE J Northeast Utilities 80/07/02 ip

--BOO7110474 LER BO-009/O3L-O on BOO605, during reactor vessel high pressure scram functional & calibr test, pressure switch 263-550 tripped at 1105 psig Caused by setpoint drift Switch reset to required setpoint & matisfactorily tested * Northeast Utilities 80/07/O2 3pp

8007230212 PNO-1-80-098 on 800709, Chem-Nuclear truck carrying spiidifted redwaste developed crack in main I-boam of trailer Truck was repaired & released 800710 RDTH.J. CROCKER.H W. SMITH, G. H. Region 1. Philadelphia. Office of the Director 80/07/10 2pp

8007180278 Forwards LER 80-010/03L-0 HRGCZKA.E J Northpast Utilities 80/07/11 2pp

--8007180307 LER 80-010/03L-0 on 800613 during testing of penetration anchor X-45 base plate bolts one bolt broke & others found improperly installed Cause not stated Bolts removed & replaced.

* Northeast Utilities 80/07/11 ip

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emorgency & fire protection plans

B0071B0196 Forwards NRC B00425 ltr to all power reactor licensees in response to B00529 ltr re emergency response Pacilities at reactor sites Sites w/approval to use closed~circuit televistor link w/technical support ctr listed CRUTCHFIELD.D M Operating Reactors Branch 5 80/0//07 2pp

8007170245 Forwards request for add1 info for review of training & qualiffication plan Request withhold (ref 10CfR2 770)
VAROA.8 A Operating Reactors Branch I 80/06/20 2pp

B00721007B Advises licenses that design for reactor coolant pump oil collection sys (Item 3 i i3 of NRC 770131 fire protection safety evaluation) is acceptable VAROA.B A Operating Reactors Brench 1 00/06/30 2pp

e Adjudicatory correspondence

8007310243 Forwards Commission 80092/ memorandum & order containing decisions on UCB 780802 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EIBENHUT, D & Division of Licensing 80/06/25 89pp

8007090215 Order granting extension until 800725 for Commission to consider whether to review ALAB-436 & portions of ALAB-561 HOYLE, J. C. Office of the Secretary of the Commission 80/07/07 is

8007220160 Response in opposition to USC motion for disqualification of Chairman Hendric re UCS 790917 petition seesing shutdown of facility. Motion failed to show bias defined by Supreme Court in Withrow vs. Larkin proceeding PRATT, C.M. Power Authority of the State of New York BRANDENBURG, II. Consolidated Edison Co. of New York B0/07/08 4Pp

8007140363 Order granting extension until 800801 for Commission to elect whether to review ALAB-436 & rolevant portions of ALAB-561 HOYLE, J C Office of the Secretary of the Commission 80/07/10

8007150711 Response stating absence of pending proceeding in which NY State Energy Ofc petitions to participate as interested state No petitions to intervene were filled in spent fuel pool mod issue Certificate of Svc enci

8007290522 Motion for reconsideration of Commission 800530 order reportion instituting adjudicatory hearing before ASLB Interim Operations Task Force rept. 9ECY-283, eliminates basis for commoncement of investigation BRANDENBURG, B. Consolidated Edison Co. of New York PRATT, C. M. Power Authority of the State of New York 80/07/25 12pp

H General correspondence

8007210208 Responds to encl 800418 lir to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities surrently operating of planned for operation Village Voice news article and DENTON, HR Office of Nuclear Reactor Regulation. Director 80/05/21 10pp

8007170259 Responds to 800206 itr re status % responsibilities for emergency preparedness in facility environs FEMA has lead responsibility in offsite emergency planning GRIHES.B K Emergency Preparedness Program Office 80/07/07 2pp

8007290682 Requests documentation that Future correspondence refacilities be addressed to P Zarakas Requests that WA Monti.
HF Shatkouski & JM Makepeace be placed on distribution for some correspondence
ZARAMAR, P Consolidated Edison Co of New York 80/07/24 1p

I Financial information

8007240127 Forwards Annual Financial Rept \$979
ZARAKAS,P Consolidated Edison Co of New York 80/07/15 1p

---8007240129 Annual Financial Rept 1979
* Consolidated Edison Co of New York 80/02/26 43pp

D Advisory Committee on Reactor Safeguards reports & correspondence

BOO722030B Provides summary of BOO507-08 meeting w/utils re core melt accident sequences Utils appear to expect NRC to resolve problems & do nothing to mitigate consequences of Class 9 accidents
CATTON, I California, Univ nf. Los Angeles 80/05/10 6pp

P Operating license stage documents ∿ correspondence

B007020109 Forwards notice of proposed issuance of amend to DL Notice concerns 790907 application for increase in spent fuel storage capacity VAROA, S.A. Operating Reactors Branch 1 80/05/19 2pp

---8007020357 Notice of proposed issuance of amend to facility OL, increasing spent fuel storage rapacity VARGA, B.A. Operating Reactors Branch 1 80/05/17 Spp

8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENNUT, D Q Division of Licensing 80/06/11 62pp

8007100373 Summary of 800520 Technology Eschange Meeting 3 w/utils in Bethesda:M9 to discuss accident mitigation features for youer plants LONG.J K Division of Systems Integration 80/06/12 75pp

BOO7140182 Submits lept of task force on interim operation of facilities Rept includes accident risk considerations, social & economic impact considerations & summary of public comments HANRAHAN.F | Office of Policy Evaluations BICKMIT-L Office of the General Counsel SCCY-80-283 BO/06/12 ABpp

--BOO/140190 Gummarizes views of Economic Regulatory Administration. Div of Power Supply & Reliability re electric sys reliability impact of operation of facilities as described in NRC 800428 ltr WEINCR.R E Energy. Dept of 80/05/15 4pp

8007010192 Forwards interim safety evaluation of auxiliary feedwater sys reliability Requests addl info to complete NRC review of Lussons Learned Task Force Items 2 1 7 a & b VARGA.S A Operating Reactors Branch 1 80/06/13 2pp

- 007010199 Interim safety evaluation re implementation of recommendations for auxiliary feedwater sys * Operating Reactors Branch 1 80/06/13 17pp
- OlOilO Notification of 800625 meeting w/utils & Sandia Labs in thosdaiMD fur presentation of overview of facilities risk udy Agenda encl MAELIS L. Reliability & Risk Assessment Branch B0/06/16 Jpp
- 010075 Notification of 800624 moeting w/otil to discuss NRC -evaluation of operational GA program for facility NHAY,JT Quality Associance Branch 80/06/17 2pp
- 170447 Forwards request for addl info to complete review of ectric distribution sys voltages RGA:9 A Operating Reactors Branch 1 80/06/20 App
- 110557 Summary of 800530 meeting w/util in Bethesde, MD re status of tion plan SHANL N Operating Reactors Branch 1 80/06/23 3pp
- 010608 Notification of 800617 meeting w/utils in Bethesda.MD to stuss containment structural response failure pressures & illure modes for facilities as described in NRC 800410 ltr Gumm Ed
- VER. J. F. Reactor Systems Branch 80/06/26
- 090228 Forwards "Endurance Testing of Auxiliary Boiler Feedwater mps." per Bulletins & Orders Task Force Short-Term commendation 2 HILLIH J Consolidated Edison Co of New York 80/06/30 13pp
- 090291 Forwards detailed info for implementation of NUREG-0578, tagory B requirements.per 791231 response to commendation 2 1 6(b) One illegible ouxiliary bldg drawing
- HLL. W.J. Consolidated Edison Co. of New York 60/05/30 11pp
- 170319 Summary of 800612 meeting w/utils in Betheada.MD re interim Hability evaluation program HANJEN Operating Reactors Branch 1 80/06/30 3pp
- 210099 Requests that util submit revised schedule & justification, completion of ATHS mode within 30 days Util is requested improve upon Fall 1982 completion date because of risk presented by facility GA.S.A. Operating Reactors Branch 1 HO/O6/30 2pp
- 210490 "Evaluation of Impingament Losses of White Perch at Indian int Nuclear Station & Other Hodson River Power Plants "

 GHINKLE, W. J. BARRYTHOUSEL W. A. KIRK, D. L. Gak Ridge National oratory FIN R-0423 NUREG/CR-1100 90/06/30 152pp
- 170241 Forwards request for addk into re backfitting of sovers ident mitigation features Response requested within 30
- AK.T H Assistant Director for Operating Reactors 80/07/02
- '50001 Requests submittal of application for amend to license ssisting of Tech Spec changes & license conditions PWR lel Tech Specs & Model license conditions for TMI-2 ssous Learned Cotegory A items end for goodance SEMHUT.D Q Division of Licensing 80/07/02 A9pp
- 170598 Summary of BOO625 meeting w/Pickard.lowe & Garrick.Inc re k study including modeling for plume tragectory, itainment avent tree & modeling.use of plant data & isideration of external events RAELS L Reliability & Rick Accomment Dranch BO/07/0/ Opp
- 23046 Summary of 800507-00 terhnology exchange meetings w/utita Chirago IL re cure melt accident sequences t associated 'momenulogy for facilities MRC perceives real argency to answers to key technical questions 'EBAJF Reactor Systems Branch 80/07/09 12pp
- 120454 Forwards addl 111fo re effects of flooding due to failure of TClass I seiseat equipment, per NRC 800570 request Taisse drawings available in Central Files only MAB.P Consolidated Edison Co. of New York 80/07/14 24pp
- 20504 Forwards response to NRC 800523 request for addl info re GA gram & revised response to Question 10.originally mitted by util 800523 ftr IANAS.P Consolidated Edison (o of New York 80/07/15 23pp

- 8007230471 Forwards final response to request for additinfo re electrical override/bypass aspects of containment purge sys-per A Schwencer 800423 ltr ZARAMAS.P Consolidated Edison Co of New York 80/07/15 17pp
- G Inspection reports, IE Bulletins & correspondence
- 8007020124 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/28 1p
- 8007010322 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required (RIER, B # Region i, Philadelphia, Office of the Director 80/05/29 ip
- 8007010081 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sus (CVC8) Holdup Tanks "All Unit 2 tanks that could contain primary sys water have adequate protection Bulletin not applicable to Unit 1 CAHILL, W. J. Consolidated Edison Co. of New York 80/06/06 3pp
- 8007020077 Forwards response to IE Bulletin 80~12, "Decay Heat Removal Bys Operability " Bulletin not applicable to Unit 1 which is in defueled condition Existing Unit 2 procedures provide for adequate alternate means for removal of decay heat CANTILL.H J Consolidated Edison Co of New York 80/06/06 5pp
- 8007210555 Forwards IE Info Notice 80-25, "Evaluation of Contractor 9A Programs " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 49/06/10 1p
- B0071&034) Forwards IE Info Notice H0-27. "Degradation of Reactor Coolant Pump Studs" No specific action or response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/06/11 ip
- G007170287 Forwards partial response to IE Bullatin BO-OA, "Engineered Bafety Feature (ESF) Reset Controls," for Unit 2 Unit 1 was shutdown 741031 & in defueled condition, therefore bulletin not applicable CAMILL, W J Consolidated Edison Co of New York 80/06/13 5pp
- 8007020710 Forwards IE Bulletin BO-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/18 1p
- BOO7310499 Forwards IE Insp Rept 50-247/80-06 on BOO513-16 No noncompliance noted BRUNNER,E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/18 2pp
- --8007310504 IE Insp Rept 50-247/80-06 on 800513-16 No noncompliance noted Major areas inspected LOCA procedures & training of literased operators in use of LOCA procedures HIGGING, J C Region i. Philadelphia. Office of the Director KISTER.H B Region j. Philadelphia. Heactor Operations Nuclear Support Branch 80/06/16 Spp
- B007020497 Forwards IE Circular 80-15, "Loss of Reactor Coolent Pump Cooling & Natural Circulation Cooldown " No written response required CAIER B H Region 1, Philadelphia, Office of the Director B0/96/20 ip
- 8007180360 Responds to IE Bulletin 80-09 No Hydramotor actuators used in any Unit 2 safety-related sys Unit 1 presently in defuelod condition
 CAHILL, H. J. Commonwealth Edison Co. 80/06/20 ip
- 8007180592 Responds to IR Bulletin 80-10 Investigation revealed potential for nonradioactive sys to become contaminated through isolation valve seal water/city water interface Double check valves installed Monitoring program described CAHILL.W J Commonwealth Edison Co 80/06/20 2pp
- 9007160688 Forwards IE Circular 80-14, "Redioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel." No written response required GRIER, 8 H Region 1, Philadelphia, Office of the Director 80/96/24 ip

- 8007210172 Forwards IE Info Notice 80~24. "Low Level Radwaste Burial Criteria " No written response required ORIER,B H Region 1, Philadelphia, Office of the Director 80/06/25 1p
- 8007230106 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1191 & 1152 Pressure Transmitters W/Either A or D Dutput Codes "Written response required IE Circular 80-11 also enci No written response required ORIER.B H Region i, Philadelphia, Office of the Director
- R Periodic operating reports & related correspondence
- 8007170363 Forwards "Annual Environ Monitoring Rept.Part D Radiological Rept " CAHILL.W J Consolidated Edison Co of New York 80/04/30
- --B007170355 "Annual Environ Monitoring Rept, Part 0 Radiological Rept "
 * Consolidated Edison Co of New York 80/06/30 66pp
- 8007130669 Submits daily fish counts from intake screens for June 1980 MONTI.W A Consolidated Edison Co of New York 80/07/10 17pp
- 8007210473 Forwards util 800613 ltr & "Quarterly Rept on Seismic Honitoring Network in Vicinity of Indian Point,NY, Con Ed Project Dec 1979-Feb 1980" DAVIS.J P Consolidated Eduson Co of New York 80/07/14 2pp
- 8007220476 Forwards monthly operating rept for June 1980 ZARAKAS.P Consolidated Edison Co of New York 80/0 80/07/15 1 p
- ---8007220479 Monthly operating rept for June 1980 EICH.E Consolidated Edison Co of New York 80/07/08 7pp
- BO07220523 Forwards "Daily Count from Intake Screens for June 1780 "
 ZARAKAS,P Consolidated Edison Co of New York 80/07/15 ip
- --8007220524 "Daily Count from Intake Screens for June 1980" * Consolidated Edison Co of New York 80/07/15 4pp
- B Reportable occurrences, LERs & related correspondence
- 8007020145 PNO-I-80-093 on 800617, util workers Union Local 1-2 authorized strike on 800618 Senior operators are excluded Required IE prestrike insps have been completed OREENMAN,E G. BRUNNER,E J. Region i, Philadelphia, Office of the Director 80/06/17 1p
- B007110396 Forwards LER 80-005/03L-0 ZARAKAS,P Consolidated Edison Co of New York B0/07/07 ip
- ---8007110404 LER 80-005/03L-0 on 800&07, perturbation in secondary outlined the Mo-outleton sounds, perturbation in secondary bloodown piping associated w/steam generator 21 resulted in failure of pipe clamp associated w/snubber 46-8R-3 Caused by failure of water hammer Pipe clamp repaired MAKEPEACE, J M Consolidated Edison Co of New York 60/07/07
- O007240169 Forwards LER 80-007/03L-0
 ZARAKAS,P Consolidated Edison Co of New York 80/07/17 ip
- --B007240172 LER 80-007/03L-0 on 800621, found control for auxiliary feedwater pump 23 transferred to local Caused by unauthorized actuation of pump transfer switch Responsible dismissed J H Consolidated Edison Co of New York 80/07/17 personnel dismi MAKEPEACE, J M
- T Hearing transcripts on non-antitrust matters
- 8007140084 Unofficial transcript of 800626 briefing on recommendations of Indian Point Task Force in Washington, DC Pp 1-62 Viewgraphs enci # Commission 80/06/26 64pp
- 8007240164 Transcript of 800711 public meeting in Washington, DC Pp 1-6 * Commission 80/07/11 6pp
- B007250347 Unofficial transcript of B00717 discussion on Indian Point in Washington.DC Pp 1~72 Draft memorandum & order encl + Commission, 80/07/17 B0pp

- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8007010347 Forwards safeguerds contingincy plan amend Plan withheld (ref 10CFR2 790) PEOPLES D. L. Commonwealth Filison to 80/06/27 tp
- 8007290562 Submits results of mini-icvicw of safe shutdown analysis No reasonable assurance that licensees fire protection will allow safe shutdown of Units 2 & 3 Ar min recommends requirement for alternate shutdown bys or dedicated bys HALL R E Brookhaven National Laboratory 80/07/09
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 Memorandum & Oider containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical tables EISENHUT, D.G. Division of Licensing 80/06/25 89pp
- 800701033; Forwards safety evaluation & EIA re scent fuel pool mods W/o GDDDARD, R J Hearing Branch 2 80/06/27 tp
- P Operating license stage documents & correspondence
- B007230028 Summary of B00207 meeting w/Mark I dwners group in Bethesda, MD,re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program ORIMES,C T Plant Systems Branch 80/02/21 31pp
- 8007010003 Forwards safety evaluation & EIA supporting proposed facility mods to increase spent fuel storage pool capacity Final approval cannot be granted until ASLB resolves legal CRUTCHFIELD, D. M. Operating Reactors Branch 2 80/06/05 2pp
- --800701000B Rafety evaluation supporting proposed facility mods to increase spent fuel sturage pool capacity

 * Office of Nuclear Reactor Regulation, Director 80/06/06
- --8007010011 EIA supporting proposed facility made to increase spent fuel storage pool capacity
 # Office of Nuclear Reactor Regulation, Director 80/06/06 10pp
- B007020194 Requests cooperation in NRC study of people-related security problems in nuclear industry CRUTCHFIELD.D M Operating Reactors Granch 5 80/06/11 2pp
- 8007010070 Responds to FDIA request for 57 documents referenced in M Tokar memo to ACRG concerning pellet-cladding interaction Forwards documents Missing records are duplicative, superseded or available elsewhere FELTONJ M Division of Rules and Records 80/06/20 2pp
- --B00701008B Discusses similarities in fuel fod failules for BWRs resulting from control blade movements failure pattern w/Drosden & LACBHR fee) rods was associated w/location of fuel rods relative to control rods SIEGEL, B L Atomir Energy Commission, Directorate of Licensing 73/09/20 Rep
- --8007010103 Forwards summary of NRC 750219 meeting w/util GE.Comm Ed & BNEL to discuss fuel Pailure detection bys & AB which resulted in pellyt-cladding mechanical interaction fuel failure Discussion outline & list of attenders encl BIEGEL.R L. : MAGEN.H , FIEND.D Core Performance Branch 75/03/03 9pp
- B007070116 Bubmits revised responses to NRC 770603 ltrs resected level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads

 JANECEK.R F Commonwealth Edison Co B0/06/26 App
- B007080063 Responds to NRC B00515 request for add1 info concerning adequary of station electric distribution sys voltages JANECEK, R F Commonwealth Edison Co 80/96/30 App
- BOO7070345 Forwards revised schedule % status info for Mark I program. feedwater spargfr replacement % general work planned for Guad Cities i outage Proceeding on priority basis w/mods providing largest safety intreas margin-REED.C Commonwealth Edison Co 80/07/07 18pp

- B007210212 Responds to NRC request for addl info me turbine disks Applicable turbine missile analysis was presented in Amend 2 to Guad Cities (P application Analysis applies to Directed due to similarity of general arrangement JANECEK.R F Commonwealth Edison Co. 80/07/15 Ip
- G. Inspection reports. IE Bulletins & correspondence
- B007140545 Forwards 1E Hulletin 80-13, "(racking in Core Spray Spargers " Written response required KEPPLER.J 9 Region 3. Chicago, Office of the Director 80/05/12 to
- 8007070072 Forwards 1E Insp Repts 50-010/80-09,50-237/80-08 & 50-249/80-12 on 800407-0502 & notice of violation KEPPLER.J 6 Region 3. Chicago, Office of the Director 80/05/23
- --8007070074 Notice of violation from insp on 800407-0502 * Region 3. Chicago, Office of the Director 80/05/23 2pp
- --8007070080 IL Insp Repts 50-10/80-09, 50-237/80-08 & 50-249/80-12 on 800407-0502 Noncompliantic noted failure to adhere to QA program requirements Contaminated clothing found lying inside controlled contaminated area SPESSARD.R L. BARKER, J L. TONGUE, T M. Region 3, Chicago, Office of the Director 80/05/23 7pp
- B007020065 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required KEPPLER.J G Reginn 3. Chicago, Office of the Director 80/05/28 In
- 8007010086 Forwards IF Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPFLER.J G Region 3. Chicago. Office of the Director 80/05/29 lp
- 8007020756 Forwards revised response to IE Bulletin 79-018, "Environ qualification of Class IE Equipment" Identifies areas where affort is continuing in identification of equipment qualifications W/o encl
 JANECEK.R F. Commonwealth Edison Co. 80/06/02 1p
- 8007020074 Forwards revised response to JE Bulletin 79-018, "Environ Qualification of Class IE Equipment" W/o enc1 PEOPLES.D L. Commonwealth Edison Co. 80/06/10 ip
- 8007220156 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required KEPPLER.J 6 Region 3. Chicago. Office of the Director 80/06/10
- 8007140309 Forwards IE Dullatin 80-14, "Degradation of BWR Scram Discharge Vol Cupability "Written response required XEPPLER.J G Region 3, Chicago, Office of the Director 80/06/12
- B007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actustor Beficiencies," No safety-rolated sys or component at Bresden 2 & 3 uses AH-90 or NH-90 series hydramotor PEOPLES.D t. Commonwealth Edison Co. 80/06/16 3pp
- 8007030037 Forwards IE Bulletin 80-15, "Possible Lois of Emergency Notification Sys (FNS) W/Loss of Offsite Power" Written response required KEPPLER.J G Region 3, Chicago, Offsice of the Director 80/06/18 to
- 8007230371 Forwards 1E Insp Repts 50-010/80-10,50-23//80-09 & 50-249/80-13 on 800505-29 \ notice of violation HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/19 2pp
- --8007230377 Notice of violation from insp on 800505-27
 * Region J. Chicago: Office of the Director 80/06/19 ip
- --B0072303BB IE Insp Repts 50-010/80-10.50-237/80-09 & 50-249/80-13 on 800505-29 Noncompliance noted failure to report events in accordance w/Teck Specs BARKER, J. L. SPESSARD, R. t. Region 3, Chicago, Office of the Director 80/06/19 9pp
- 8007020589 Forwards IC Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldnum " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/20

- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Flant Demineralized Water Sys & Resultant Internal Contamination of Personnol " No written response required KEPPLER, J G Rogion 3, Chicago, Office of the Director 80/06/24
- 6007230289 Forwards IE Bulletin 60-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/27
- B007180003 Ack receipt of 800613 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/80-09, 59-237/80-08 & 50-249/80-12 KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/07/01
- ---8007180010 Responds to ARC 800523 ltr re violations noted in IE Insp Repts 50-010/80-09, 50-237/80-08 & 50-249/80-12 Corrective actions improved mgt controls were implemented Radiation protection training classes were held for contractors REED, C Commonwealth Edison Co 80/06/13 App
- 8007180509 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at INR," will start at 12 01 AM on 800708 Test should be completed within 20 days Requests notification of malfunction KEPPLER, J Q Region 3, Chicago, Office of the Director 80/07/07 in
- B007250641 Responds to IC Bulletin 80-10. "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found PEOPLES.D L Commonwealth Edison Co 80/07/07 2pp
- 8007250650 Forwards response to IE Sulletin 80-11, "Masonry Wall Design " Requested investigation not performed at Dresden, Unit 1 due to extended outage Requirements will be met prior to startup W/o encl PEDPLEG.D L Commonwealth Edison Co 80/07/07 2pp
- G007290698 Forwards response to 1E Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic araminations will be assessed before unit returned to svc PEOPLES.D L Commonwealth Eduson Co. 80/07/09 7pp
- 8007140630 Responds to IE Bulletin 80-17 re results of tests required by Item 1 No significant amount of water in scram discharge vols Vent & drain lines also verified free of obstructions by performing dynamic air test

 JANECEKAR F Commonwealth Edison Co 80/07/10 2pp
- 80073:0480 Forwards final inservice insp rept for 800103-0424 inservice insp of reactor pressure vessel & primary sys piping STEPHENSDN.B B Commonwealth Edison Co 80/07/10 1p
- --8007310486 Final inservice insp rept for 800103-0424 inservice insp of reactor pressure vessel & primary sys piping * Commonwealth Edison Co = 80/07/10 27pp
- 8007300485 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys." by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria " JANECEK,R F Commonwealth Edison Co 80/07/16 ip
- --8007300498 "Engineering Criteria/Procedure for Review & Resolution of As-Built Deviations," Revision 2 SNYDER,T K EDS Nuclear, Inc 80/03/07 iipp
- ---B00730050B "Engineering Criteria Procedure for Application of Blume Curves Criteria" SNYDER.T K. EDS Nuclear, Inc. 80/03/07 20pp
- E007240291 Ack receipt of BOO613 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-249/80-09 KEPPLER, J G Region 3, Chicago, Office of the Director BO/07/17
- --8007240298 Responds to NRC 800426 ltr re violations noted in IE Insp Rept 50-249/80-09 Corrective actions reactor water cleanup water hammer damage repaired & control red drive sys seismic design proved adequate PEOPLES, D.L. Commonwealth Edison Co. 1 80/06/13 46pp

- R Periodic operating reports & related correspondence
- BOO7180333 Forwards monthly operating repts for June 1980 STEPHENBON, B B Commonwealth Edison Co 80/07/09 1p
- --8007180336 Monthly operating repts for June 1980 CIE971EWICZ, 8 Commonwealth Edison Co 80/07/02 23pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007220455 Forwards LER 80-026/03L-0 STEPHENSON, B B Commonwealth Edison Co 80/07/09 tp
- --B007220459 LER 80-026/03L-0 on B00620.nbnormal amount of water was being added to sys Caused by thirteen leaking tubes Tubes were subsequently plugged * Commonwealth Edison Co 80/07/09 ip
- 8007220577 Forwards LER 80-027/01T-0 STEPHENSON B B Commonwealth Edison Co 80/07/15 is
- --8007220583 LER 80-027/017-0 on 800707, engineering evaluation of control rod drive scram discharge piping revealed failure to meet FBAR seismic requirements Caused by design deficiency Analysis performed. HOLLAND.P Commonwealth Edison Co 80/07/16 2pp
- BOO7230359 LER 79-024 has been cancelled COLLINS, M Commonwealth Edison Co 80/07/22 ip
- DOCKET 50-250 TURKEY POINT PLANT, UNIT 3
- C Utility Environmental Report (CR), amends & correspondence
- 8007290406 Forwards Waste Packaging Insp Rept 15000037/80-08 on 800603-06 No noncompliance noted STOHR, J. P. Region 2. Atlanta, Evel Facility & Materials Safety Branch 80/06/20 3pp
- --8007290410 Waste Packaging Insp Rept 150000039/80-08 on B00603-06 No noncompliance noted Major areas inspected compliance w/DOT & NRC regulations TROUP.0 L. MACARTHUR.T C Region 2. Atlanta, Fuel Facility & Materials Bafety Branch B0/06/20 6pp
- F Security, medical, emergoncy & fire protection plans
- 8007140518 Summary of B00619 meeting w/util in Bethesda.MD re proposed App R to 10CFR50 on fire protection GROTENHUIS.M Operating Reactors Branch 1 80/06/23 2pp
- BOO7E3044E Forwards facility evacuation time estimates in response to NRC 791129 request UMRIO.R E Fibrisa Power & Light Co BO/07/17 Epp
- 8007230454 Forwards facility evacuation time estimates in response to NRC 791129 request UHRIO, R E Florida Power & Light Co 80/07/17 7pp
- G Adjudicatory correspondence
- 8007070279 Requests permission to make comments at hearing to be held in Miami on steam generators repair PETERSON. A F Affiliation Unknown 80/06/24 1p
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp
- 8007070094 Advises of NRC estimates that DES re proposed amands to GLs parmitting steam generator repair,will be issued by 800901 & FES by 801201 GOLDDERG.S C Hearing Branch 2 80/07/02 ip
- H General correspondence
- 8007160808 Forwards responses to first 31 questions raised in 800402 correspondence re facility. Includes two pertinent repts & one page each from facility Tech Specs & STE Remainder of questions will be answered at later date VARGA.S A Operating Reactors Branch 1 80/06/24 Spp

- M Antitrust coricspandence
- 8007150/19 Response stating no objection to Orlando Utils Commission 800620 withdrawel of intervention FL Cities 800707 comments relegant treatment will be addressed in Unit 2 entitrest proceeding Critificate Sycience 1
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Nodel Tech Specs which would provide acceptable resolution encl for guidance CISENNUT. D G Division of licensing 80/06/11 63pp
- B00721031) Forwards Amends 58 % 51 to Licenses DPR-31 & DPR-41, respectively, sufety evaluation & notice of issuance & availability VARGA, 5 A Operating Reactors Branch 1 80/06/12 2pp
- --BOO7210314 Amends 58 & 51 to licenses DPR-31 t DPR-41, respectively, incorporating results of revised ECCS analysis for steam generator plugging level of 25% a permitting continued aperation of Unit 4 VARGA, S.A. Dffile of Nuclear Reactor Regulation, Director 60/04/12 15pp
- --8007210319 Safety evaluation supporting Amends 98 & 51 to Licenses DPR-31 & DPR-41, respectively # Office of Nuclear Reactor Regulation, Director 80/06/19
- --B007210323 Notice of issuance & availability of Amends 5B & 51 to Licenses DPR-31 & DPR-41.respectively VARGA.B A Operating Reactors Branch 1 80/06/12 2pp
- 8007110199 Advises NRC that NUKEG-05/8 requirement to measure chlorides & dissolved gases in RCS following accident is excessive & involves unnecessary personnel exposure to radiation Requests that NRC reconsider position UHRIG.R E. Florida Power & Light Co. 80/96/27 ip
- B0070B0140 Requests permission to delay schoduled shotdown for steam generator insp until 801006 Delay nooded to accommodate peak load demand for Jul-Aug 1780 Updated generating capacity, expected load demand info & Class 111 fee encl
 UHRIO.R E Florida Power & Light Co 80/06/30 12pp
- B007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Luarned Category Alitems entlifer guidance EISCNHUT.D Q Division of Licensing 50/07/02 69pp
- 8007110261 Notifies that commitment drite for completion of plant parameter display in interim technical support ctr is revised to 800831 URRIO.R E Florids Power's Light Co 80/07/03 lp
- 8007110256 Advises that Westinghouse submittal of WCAP-9748 & WCAP-9749 completes Phase C asymmetric LDCA loads analysis WCAP-9558 & WCAP-9570 provide add1 info requested at 800226 meeting UHRIO.R E Florida Power & Light Co 80/07/07 2pp
- B007190710 Responds to NRC B00619 request re endangered, threatened or proposed to be listed species in plant area Jacksonville ofc will provide list after review Advises of change in consultation procedures
 BTJE0LITZ, W O Interior, Dept of, Fish & Wildlife Service 80/07/08
- 8007210368 Responds to NRC 800619 ltr ie util Ol amend request Provides list of potentially threatened & undangered species in proximity to facility Compilete biological assessment should be provided Outlines info to be included in assessment HANKLA.D J. Interior, Dept of. Fish & Wildlife Service 80/07/14
- 8007220380 Advises that Henry Pratt (a torque & stress analyses re containment purge have been delayed Upon (ompletion & receipt of analyses, util will review & prepare leaponse demonstrating valve ability to close during DR-LDCA UHRIG.R E Florida Power & Light Co 80/0//th 1p
- 9007300567 Summary of 800630 menting w/all reviewers on steam generator repair program re overview of event chronology groups of Operating Reserve Beant 1 80/07/16 3pp

- 8007280531 Forwards responses to questions re proposed installation of condensate polishing demineralizers Responses suppl info previously submitted in 800318 & 0527 ltrs Oversize
 - Florida Power & Light Co 80/07/22 Sipp
- ---8007280551 "Sys Flow Diagram Condensate Polishing Demineralizer Sys "
 * Bechtel Corp 80/05/02 1g
- ---8007280556 "Site Plan " # Bechtel Corp 76/ 76/09/21
- 8007280562 Responds to 800830 ltr requesting info on auxiliary feedwater sys Attachment 2 provides addl info to suppl 791220 response UHRIO.R E Florida Power & Light Co 80/07/22 7pp
- B007310377 Informs that American crocodile & bald eagle inadvertently omitted from 800714 endangered species list

 OBERHEU, J C Interior, Dept of, Fish & Wildlife Service 80/07/25

Q Inspection reports, IE Bulletins & correspondence

- 800724020à Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode." No response required O'REILLY, J.P. Regio
- Region 2, Atlanta, Office of the Director 80/05/08
- B007020231 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007210458 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007010206 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Fasdwater Pumps" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007100128 Forwards response to Items 1,2 & 3 of IE Bulletin 79-018,
 "Environ Qualification of Class IE Equipment"
 UHRIG.R E Florida Power & Light Co 80/06/02 600pp
- 8007220062 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10,
- 9007160265 Forwards IE Info Notice 80-27. Degradation of Reactor Coolant Pump Stude " No specific action or response required
- O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/08/11
- 8007020752 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENB) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06.
- Region 2, Atlanta, Office of the Director 80/06/18 10
- 8007020454 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response
- required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20.
- 8007100025 Forwards response to IE Bulletin 80-05, "Engineered Safety Features (ESF) Reset Controls " Lists aquipment which does not remain in emergency mode upon reset of ESF signal. Followup response will be sent by 800801 UHR10.R.E. Florida Power & Light Co 80/06/20 App
- 8007170109 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director. 80/06/24

- 8007230243 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required. IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/2 80/06/27
- 8007210064 Forwards two vol Phase II response to IE Bulletin 79-01B re environ qualification of Class IE equipment Supersedes 800602 Phase I response, Wo encl UHRIO, R E Floride Power & Light Co 80/07/03 2pp
- 8007160375 Advises that addl info re inservice insp will be submitted by 800715 per NRC 800414 request U4RIG:RE Florida Power & Light Co 80/07/09 1p
- 8007280282 Responds to IE Bulletin 80-11. "Masonry Wall Derign " Rept not complete but safety-related walls have been identified & re-evaluation program developed Rept will be submitted by 800728 UHRIG.R E. Florida Power & Light Co BO/07/09 ip
- 8007300558 Advises that final response to IE Bulletin 80-10 will be O/300030 Advises for First First Feature to an advisor substitted by 800801
 UHRIG.R E. Florids Power & Light Co 80/07/09 1p
- 8007310084 Advises that full response to IE Bulletin 80-08 will be submitted by 801031 UHRIQ.R E Florida Power & Light Co 80/07/09 lp.
- 8007240261 Ack receipt of 800626 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-250/80-16 & 50-251/80-14 LENES, R C Region 2: Atlanta, Reactor Operations Nuclear Support Branch. 80/07/11
- ---8007240263 Responds to NRC 800529 itr re violations noted in IE Insp Repts 50-250/80-16 & 50-251/80-14 Corrective actions tracked open noncompliance items & hired add1 QC personnel UHRIG-R E Florida Power & Light Co 80/06/26. 3pp
- --8007240246 Forwards IE Insp Repts 50-280/80-16 & 50-251/80-14 on 800401-30 & notices of violation & deviation LEHIS.R.C Region 2: Atlanta, Reactor Operations Nuclear Support Branch 80/05/29 22:
- ---B007240272 Notice of violation from insp on 800401-30
 * Region 2, Atlanta, Office of the Director 80/0 80/05/29 10.
- --9007240276 Notice of deviation from insp on 800401-30 * Region 2, Atlanta, Office of the Director 80/0 80/05/29
- --800724028: IE Insp Repts 50-250/80-16 & 50-251/80-14 on B00401-30. Noncompliance noted: failure to track implementation of corrective action & to meet corrective action deadline. VOOT-LOHELLR J Region 2. Atlanta. Office of the Director MARTINER D Region 2. Atlanta. Reactor Operations Nuclear Support Branch. B0/05/29 6pp
- R Periodic operating reports & related correspondence
- 8007240075 Forwards semiannual radioactive effluent & environ monitoring rapts for Jan-June 1978 W/o environ monitoring rept UMRIG.R.E Florida Power & Light Co 78/08/30 ip
- --8007240086 "Semiannual Radioactive Effluent Repts for Jan-June 1978 * Florida Power & Light Co. 78/08/30. 15pp
- 8007220543 Forwards "Bemiannual Radioactive Effluent Rept," & "Bemiannual Monitoring Rept," for Jul-Dec 1978 per Tech Spec 6.9.4 UHRIGRE Florida Power & Light Co 79/03/01. 1p
- --Boo7220550 "Semiannual Rapt of Radioactive Effluent Releases." Jul-Dec Florida Power & Light Co 79/03/01 25pp.
- BOO7240174 Forwards monthly operating repts for June 1980 BCHMIDT.A D Florida Power & Light Co 80/07/05, ip
- --B007240177 Monthly operating repts for June 1980 CHILSON, V. T Florida Power & Light Co 80/07. 80/07/05

- 8 Reportable occurrences: LERs & related correspondence
- 8007220419 Forwards LER 80~014/01T-0 SCHMIDT,A D Florida Power & Light Co 80/07/10 ip
- --6007220421 LFR 80-014/01T-0 on 800626.AE advised that insp/evaluation in progress per IE Bulletin 79-14, revealed deficiency involving auxiliary feedwater sys pump suction piping Cause not stated PACE, P L Florida Power & Light Co 80/07/10 2pp

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- C Utility Environmental Report (ER), amends & correspondence
- B007290406 Forwards Waste Packaging Insp Rept 15000039/B0-0B on B00603-06 No nancompliance noted STOHR.J P Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/06/20 3pp
- --8007290410 Waste Packaging Insp Rept 150000039/80-08 on 800603-06 No noncompliance noted Major areas inspected compliance w/DDT & NRC regulations TROUP.G L. MACARTHUR.T C Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/20 6pp
- F Security, modical, emergency & fire protection plans
- BOO7140518 Summary of 800619 meeting w/util in Bethesda,MD ro proposed App R to 100FR50 on fire protection GROTENHUIS,M Operating Reactors Branch 1 80/06/23 2pp
- 8007230442 Forwards facility evacuation time estimates in response to WRC 791129 request
 UHRIG.R E Florida Pawer & Light Co 80/07/17 Bpp
- BOO7230454 Forwards facility evacuation time estimates in response to NRC 791129 request UHRIG.R E Florida Power & Light Co 80/07/17 7pp
- G Adjudicatory correspondence
- BOO7070279 Requests permission to make comments at hearing to be held in Miami on steam generators repair PETERSON, A F Affiliation Unknown 80/06/24 ip
- BOO7310243 Forwards Commission BO0527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action refire protection for electrical cables
 EISENHUT, D O Division of Licensing 80/04/25 89pp
- 8007070094 Advises of NRC estimates that DES re proposed amends to OLs permitting steam generator repair, will be issued by 800901 & FEG by 801201 QOLDBERO, S C Hearing Branch 2 80/07/02 ip
- H. General correspondence
- B007160B0B Forwards responses to first 31 questions raised in 800402 correspondence re facility Includes two pertinent repts & one page each from facility Tech Specs & STS Remainder of questions will be answered at later date VARGA.S A Operating Reactors Branch 1 80/06/24 8pp
- M Antitrust correspondence
- 8007150719 Response stating no objection to Orlando Utils Commission 800620 withdrawal of intervention FL Cities 800707 comments proceeding Certificate Byc encl
 DEWEY.L B Antitrust Division 80/07/11 4pp
- P. Operating license stage documents & correspondence
- BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance

 EISENHUT, D G Division of Licensing 80/06/11 62pp
- BOO7210311 Forwards Amends 58 & 51 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuence & availability UAROA.S A Operating Reactors Branch 1 80/06/12 2pp

- --B007210314 Amends 5B & 51 to Licenses DPR-31 % DPR-41, respectively, incorporating results of revised ECCS analysis for steam generator plugging level of 25/ & permitting continued operation of Unit 4 VARGA.S A Office of Nuclear Reactor Regulation, Director 80/06/12 15pp
- -B007210319 Safety evaluation supporting Amends 58 % 51 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation Director 80/06/12
- --8007210323 Notice of issuance & availability of Amends 58 & 51 to Licenses DPR-31 & DPR-41, respectively VARGA, S.A. Operating Reactors Branch 1 80/06/12 2pp
- B007110199 Advises NRC that NUREG-0578 requirement to measure chlorides & dissolved gases in RCS following accident is accessive & involves unnecessary personnel exposure to radiation Requests that TRC reconsider position UHRIG.R E Florida Power & Light Co. 80/06/27 ip
- B007250001 Requests submittal of application for amend to license consisting of Tech Spec changes % license conditions PWR Model Tech Specs & Model license conditions for TM1-2 Lessons Learned Category A items entl for guidance EISENHUT, D G Division of Licensing 80/07/02 69pp
- B007i10261 Notifies that commitment date for completion of plant parameter display in interim technical support Ltr is revised to B00831

 WHRIGHE Florida Power & Light Co B0/07/03 Ip
- 8007110256 Advises that Westinghouse submittal of MCAP-9748 & WCAP-9749 completes Phase C asymmetric LOCA loads analysis WCAP-9558 & WCAP-9570 provide addl info requested at 800≥26 UHRIG.R E Florada Power & Light Co 80/07/07 2pp
- B007150710 Responds to NRC B00619 request to endangered, threatened or proposed to be listed species in plant areo Jacksonville ofc will provide list after review Advises of change in STIEGLITZ.W D Interior.Dept of, Fish & Wildlife Service 80/07/08
- 8007210769 Responds to NRC 800617 ltr re util DL amend request Piovides list of potentially threatened & endangered species in proximity to facility Complete biological assessment should be provided Outlines info to be included in assessment HANKLA.D J Interior.Dept of. Fish & Wildlife Service 80/07/14
- 8007220380 Advises that Henry Pratt Co turque & stress analyses re containment purge have been dulayed Upon completion & receipt of analyses util will review & prepare response demonstrating valve ability to close during DBA-LOCA UHRIG.R E Florida Power & Light Co 80/07/15 ip
- 8007300567 Summary of 800630 meeting w/all leviewers on steam generator repair program re overview of event chronology GROTENHUIS.M Operating Reactors Branch 1 80/07/14 3pp
- 8007280531 Forwards responses to questions re proposed installation of condensate polishing demineralizers Responses suppl info previously submitted in 800318 % OSE7 ltms Oversize drawings enci UHRIO,R E Florida Power & Light Co 80/07/22 21pp
- --9007280991 "Sys Finw Diagram Condensate Polishing Demineralizer Sys " * Bechtel Corp = 80/05/02 1p
- --8007280556 "Site Plan" * Bechtol Corp 76/ 76/09/21 1p
- 8007280962 Responds to 800330 ltr requesting info on auxiliary feedwater sys Attachment 2 provides oddl info to suppl 791220 response UHR10.R E Florida Power & Light Co 80/07/22 7pp
- 8007310377 Informs that American crucodile & build eagle inadvertently omitted from 800714 endangered species list
 OBERHEU, J. C. Interior Dept. of, Fish & Wildlife Service 80/07/25

- Inspection reports. If Bulletin: % correspondence
- 00/240206 Forwards II Info Notice 80-20, "toss of Decay Heat Removal (apphility at Basis Besse Unit 1 While in Refueling Mode "No response required 0.48CH/Y J P Region 2, Atlanta, Office of the Director 80/05/08
- 00/070,711 forwards II into Notice 80-22. "Breakdowns in Contamination Control Programs" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28
- 300/210458 Forwards It Circular 80-13, "Orid Strop Damage in Westinghouse fund Assemblies," No written response required DYRFILLY, FP Region 2, Atlanta, Office of the Director
- 8007010206 Forwards 1F Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No whitten response required D'ABILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 1007100055 Foraids II Insp Rept h0-251/80-16 on 800515-16 No noncompliance insted MURPHY/C E Region 2/ Atlanta, Roactor Construction & Engineering Sepont Dinnet 80705729 App
- --8007100060 IE losp Rept 50-251/80-16 on 800515-16 No noncompliance nortaneous in them repet 90-391/180-16 on 800515-16 No contempliance noted Major ateas inspected steam generator feedwater line radiography per N. Bulletin 79-13 HERDI,A R. Region J. Atlanta, Reactor Construction & Engineering Ungper Branch CROMETY,B R. Region 2. Atlanta Office of the Director 60/05/29 Spp
- 800/10012B forwards response to Items 1.2 & 3 of IE Bulletin 79-01B; "Environ Qualification of Class IE Equipment" UMRIG.R f Florida Power & Fight Co 80/06/02 600pp
- R007220062 Inswirds IE Info Notice NG-26. "Evaluation of Contractor OA Programs" No written response required O'REILLY.JP Region 2. Atlanta. Office of the Director 80/06/10
- 800/160/A5 Forwards IF Info Natice 80-27, "Degradation of Reactor Coolant Pump Studs Na specific action or response
- D'RELLY, J.P. Region P. Atlanta, Office of the Director 80/06/11
- 8007020752 Forwards IF Bullotin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Office Power " Written response required O'RFILLY, J.P. Region 2, Atlanta, Office of the Director 80/06.
 - Region 2, Atlanta, Office of the Director 80/06/19
- 800/020454 Europelds IF (arcular 80-15, "loss of Reactor Copiant Pump Cooling & Natural (arculation (noldnon " No written response required O'REILLY J.P. Region 2, Allanta, Office of the Director 80/06/20
- 8007100029 Forwards response to IC Gulletin NO Ch. "Engineered Bafety Features (FST) Reset Controls "Lists equipment which does not ramain in mergency mode upon reset of EST eignal Followup response will be sont by 800804 UNRIGER! Florida Power & Light to 80706/20 4pp
- 800/1/0107 Forwards IE Circular H0-14. "Hadioective Contamination of Plant Semineralized Water Aya & Regultant Internal Contamination of Personnel" How mitter response required O'RF11tY.J P. Region 2. Atlanta. Office of the Director #00/06/24
- 8007230263 forwards IF Bulletin 80-ta. "Potential Hisapplication of Resembunt Int Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80 to also encl No written response required B/REIIIV.J P Region 2, Atlanta. Office of the Director 80/05/27
- 8007210064 forwards two voi Papse \$1 response to If Bulletin 79-018 re onviion qualification of Class 18 repriment Supersedes 800602 Phase 1 response W/v encl UHRIGR F Florida Fower % Light to 80/07/03 2pp

- 8007250202 Responds to IE Bulletin 80-11. "Masonry Wall Design " Rept not complete but safety-related walls have been identified & re-evaluation program developed Rept will be submitted by UHRIG.R E Florida Power & Light Co 80/07/09 ip
- 8007300558 Advises that final response to IE Bulletin 80-10 will be
- submitted by BOOBO1 UHR19, R.E. Florida Power & Light Co. BO/07/09 ip
- B007310084 Advises that full response to IE Bulletin 80-08 will be submitted by 801031

 UHRIG.R E Florida Power % Light Co 80/07/09 1p
- 8007240261 Ack receipt of 800626 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/80~16 &
 - 50-251/80-14
 LEWIS, R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/07/11 1p
- --8007240263 Responds to NRC 800529 ltr re violations noted in IE Insp Repts 50-250780-16 & 80-251780-14 Corrective actions tracked open noncompliance items & hired addl GC personnel UMIIG.R E Florida Power & Light Co 8070426 3pp
- --8007240266 Forwards IE Insp Repts 50-250/80-16 & 50-251/80-14 on 800401-30 & notices of violation & deviation LEHIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 80/05/27 2p
- --8007240272 Notice of violation from insp on 800401-30 * Region 2. Atlanta, Office of the Director 80/09 80/05/29
- --9007240274 Notice of deviation from insp on 800401-30 * Region 2. Atlanta, Diffice of the Director 80/08 80/05/29
- -8007240281 IE Insp Repts 50-250/80-16 % 50-251/80-14 on 800401-30 purenumn in insp kepts 30-230/80-16 & 50-251/80-14 on 800401-30 Noncompliance noted failure to track implementation of corrective action & to meet corrective action deadline VQQT-LOWELL.R J. Region 2. Atlanta. Office of the Director MARTIN.R D. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/29 App
- R Periodic operating reports & related correspondence
- 8007240075 Forwards semiannual radioactivo effluent & environ monitoring repts for Jan-June 1978 W/o environ menitoring UHRIGAR E Finrida Power & Light Co 78/08/30
- --8007240086 "Semiannual Radioactive Effluent Repts for Jan-June 1978 * Florida Power & Light Co 78/08/30 15pp

Florida Power & Light Co 79/03/01 ip

- 8007220543 Forwards "Semiannual Radioactive Effluent Rept." & "Semiannuwal Monitoring Rept." for Jul-Dec 1978 per Tech Spec 6 9 4
- --R007220550 "Semiannual Rept of Radioactive Effluent Releases." Jul-Dec Florida Power & Light Co 79/03/01 25pp
- 8007240174 Forwards monthly operating repts for June 1980 BCHNIDT, A D Florida Power & Light Co 80/07/05 1p
- --8007240177 Nonthly operating repts for June 1980 CHILEDN,V T Florida Power & Light Co 80/07/05 10pp
- DOCKET 50-254 QUAD-CITIES STATION, UNIT 1
- F Becurity, medical, emergenry & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 100FR2 790)
 PEOPLES,D L Commonwealth Edison Co 80/06/27 1p
- O Adjudicatory correspondence

UHRIO R E

8007310247 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 mumorandum & order UCS 771104 patition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/04/25 89pp

- J. Insurance & indemnity information
- B007150616 Forwards Endorsement 63 to NELIA Polity NF-187 OSTER.J Commonwealth Edison Co 80/07/09 app
- B007290709 Forwards Endorsements 62 & 64 to NELIA Policy NF-187 OBTER: J Commonwealth Edison Co 60/07/23 3pp
- P Operating license stage documents & correspondence
- B00723002B Summary of B00207 meeting w/Mark I owners group in Dethesda.

 MD.re revisions to NRC acceptance criteria & outstanding
 issues relative to Mark I containment long-term program

 GRIMCS.C T Plant Systems Branch B0/02/21 Jipp
- 8007290217 "Measurement of Xe~133,C-14 & Tritium in Air & [-13] in Vegetation & Milk Around Guad Cities Nuclear Power Btations,"
 - Betations,"
 KELLER, J H , AKERS, D W . DUCE, S W Idaho National Engineering
 Laboratory FIN A~6078 NUREG/CR-1195 80/03/31 400pp
- BOG7010190 Responds to SSRT concerns re control rod drive sys lacking seismic analysis Quad Cities i & 2 seismic design of control rod drive sys calculations performed for facility while under const encl

 JANECEK.R F Commonwealth Edison Co 80/06/24 4pp
- --B007010193 "Guad Cities 1 & 2 Seismic Data on Control Rod Drive Bys "
 * Reactor Controls: Inc 70/07/10 200pp
- B007070114 Submits revised responses to NRC 770603 ltrs resected level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads

 JANECEK-R F Commonwealth Edison Co B0/06/26 4pp
- B007140500 Forwards Amend 56 to License DPR-27, safety evaluation & notice of issuance & availability IPPOLITO.T A Operating Reactors Branch 2 B0/06/26 2pp
- --8007140505 Amend 56 to License DPR-27 authorizing operation of reactor beyond previously approved end-of-cycle coastdown conditions IPPCLITO.T A Operating Reactors Branch 2 80/06/26 2pp
- --B007140509 Safety evaluation supporting Amend 56 to License DPR-29
 * Operating Reactors Branch 2 80/06/26 3pp
- --8007140814 Notice of issuance & availability of Amend 56 to License DPR-27 IFPOLITO, T A Operating Reactors Branch 2 80/06/26 2pp
- 8007080063 Responds to NRC 800515 request for addl info concerning adequacy of station electric distribution sys voltages JANECCK, R F Commonwealth Eduson Co 80/06/30 4pp
- 8007070345 Forwards revised schedule & status info for Mark 1 program, feedwater sparger roplacement & general work planned for Guad Cities i outoge Proceeding on priority basis w/mods providing languest safeky increase margins. REED, C Commonwealth Edison Co 80/07/02 18pp
- B007100142 Application for amend to App A. Tech Specs of Licenses DPR-29 & DPR-30, implementing fire protection mode JANECEK, R F Commonwealth Edison Co 80/07/03 2pp
- --8007100147 Proposed changes to Tech Specs 3 12/4 12-1 through 3 12/4 12-9, implementing fire protection mods
 * Commonwealth Edison Co 80/07/03 18pp
- BOO7210212 Responds to NRC request for addl info re turbine disks Applicable turbine missile analysis was prosented in Amend 2 to Quad Cities CP application Analysis applies to Dresden due to similarity of general arrangement JANECEK.R F Commonwealth Edison Co 80/07/15 ip
- @ Inspection reports, IE Bulletins & correspondence
- 8007140545 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/12 io
- 8007020065 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/05/28 ip

- B007010086 Forwards IE Info Notice 80-23 "Loss of Suction to Emergency Feedwater Pumps No written response required KEPPLER J G Rogion 3. (hicago, Office of the Director 80/05/F9 1p
- B007020756 forwards revised (esponse to TE Bulletin /9-018, "Environ Qualification of Class IE Equipment " Identifies areas where effort is continuing in identification of equipment qualifications W/o ent!

 JANECEK.R F Commonwealth Edison Co. 80/06/02 1p
- 8007220156 Forwards IE Info Natice 80-76. 'Evaluation of Contractor GA Programs' No written response required KEPPLFR.J G. Region J. Chicago. Office of the Director 80/06/10 ip
- B007140309 Forwards IE Bulletin 80-14. 'Degindation of BWR Scram Discharge Vol Capability " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director B0/06/12 Ip
- 8007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators

 PEDPLES D L Commonwealth Edison (0 80/06/14 3pp
- 8007030037 Forwards IF Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER., G Region 3, Chicago, Office of the Director 80/06/18
- 8007020389 Forwards IE (ircular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Cisculation Conidown" No written response required KEPPLFH, J G Region 3, Chicago, Office of the Director 80/06/20
- B007110131 Forwards notice of violation 4 notice of proposed impossition of civil penalties arising from IE 800171 insp STELLO-V Office of Inspection & Enforcement, Office of the Director 80/06/20 Spp
- --8007110136 Notice of violation from insp on 800131 Noncompliance noted surface rediction of transporting vehicle exceeded max allowable millinem per hour b Diffice of Inspertion & Unforcement. Office of the Director 80/01/31 ipp
- ---B007110145 Notice of imposition of civil ponalties based on item of noncompliance re-excessive ourface radiation on transport vehicle

 # Office of Inspection & Enforcement, Office of the Director B0/06/20 in
- B007140147 Notice of proposed imposition of civil penalties in amount of \$4,000 for item of noncompliance to radiation levels on waste shipments exceeding regulatory limits

 * Office of Inspection & Enforcement, Office of the Director B0/06/20 ip
- 8007170430 Forwards IE Circular 80-14. "Radioartive Contamination of Plant Demineralized Mater Sys / Recultant Internal Contamination of Personnel " No written legionse required KEPPLER, J G Region 3, Chicagu, Office of the Director 80/06/24
- 8007230289 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 % 1152 Pressure Transmitters, W/Either A or D Quiput Codes " Whitten response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 1. Chicago, Office of the Director 80/06/27 in
- B007300574 Forwards Weste Packaging Insp Rept 15000046/80-07 on B00131 Notice of violation forwarded under separate cover KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/27
- --B007300585 Haste Packaging line Rept 15000046/80-07 on 800131 Noncompliance noted radiation levels on torface of trailer in excess of regulatory limits B00K.H E Region 5. Sen Francisco, Fuel Facility 4 Materials Safety Branch CAIN.C L Region 4. Dallas, Office of the Director 80/02/27 7pp

```
Z
```

00/180509 Notafies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Stram at BHR."

will start at 12 Of AM on 800708 Test should be completed within 20 days Requests notification of malfunction Region 3, Chicago, Office of the Director 80/07/07 in

107290441 Responds to IE Bulletin 80-10, "Contamination of Nonradinactive Sys & Resulting Potential for Unmonitored, Uncontrolled Rolease of Radioactivity to Environ" Any affected sys will be restricted if contamination found PLOPLES, D.L. Commonwealth Edison Co. 80/07/07 2pp

007290A%O Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Requested investigation not performed at Dresden. Unit I due to extended outage Requirements will be met prior to startup W/o entl PFOPLES,D L Commonwealth Edison Co 80/07/07 2pp

00/230638 Forwards response to 1E Bulletin 80-08, "Examination of funtainment Liner Penetration Welds " Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PLUPLES: D.L. Commonwealth Edison Co. 80/07/09 7pp

00/160630 Responds to IE Bulletin 80-17 re results of tests required by Item I No significant amount of water in scram discharge vols Vent & drain lines also verified free of obstructions by performing dynamic air test JANICCEK.R F Commonwealth Edison Co 80/07/10 2pp

007280074 Forwards add1 response to IE Bulletin 80-17. Items 2,3.4.5.ba & 6b New procedure has been written to cover actions necessary when control reds fail to fully insert during

PEOPLES D L Commonwealth Edison Co 80/07/11

00/310397 Responds to NRC 800620 notire of proposed imposition of civil penalties by forwarding payment PEOPLES.D L. Commonwealth Edison Co. 80/07/14 ip

00/310393 Forwards response to violation noted in IE insp on 80013) Corrective actions procedure now requires under-trailer check of radwaste shipments & pre survey of articles at shipment origin to assure packages are within dose limits JANECEK.R F Communwealth Edison Co. 80/07/15. 3pp

007300485 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Bofety-Related Piping Sys," by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria " JANECEK,R F Commanwealth Edison Co 60/07/16 ip

8007300498 "Engineering Criteria/Procedure for Review & Resolution of As-Built Deviations." Revision 2 5NYDER, T K EDS Nuclear, Inc. 80/03/07 11pp

8007300508 "Engineering Criteria Procedure for Application of Blume Curves Critoria " SNYDER.T K EDS Nuclear, Inc. 80/03/07 20pp

007290869 Forwards IE Insp Rept 50-254/80-16 on 800709-11 & notice of violation HIND, J.A. Region 3, Chicago, Safeguards Branch 80/07/21 2pp

-800/290871 Notice of violation from insp on 800709-11 * Ragion 3. (birago, Office of the Director 80/0 80/0//21 in

-800/290H75 IE Insp Rept 50-254/80-16 on 800709-11 Noncompliance noted failure to update fuel assembly locations on fuel location & exposure records tass of fission due to insufficient SNM procedures Details withheld (ref 100FR2 790)
FIN.EY.A.G., PATTERSON.J.P. Region 3. Chicago. Office of the Director HIND.J.A. Region 3. Chicago. Safeguards Branch

Periodic operating reports & related correspondence

190619 Forwards monthly operating repts for June 1980 IVIANAKIS:N Commonwealth Edison Co 80/07/01 1p

37150625 Monthly operating repts for June 1980 MATERA, T. Commonwealth Edison Co. 80/07/01

sportable occurrences, AERs & related correspondence

'40105 Forwards LER 80-014/03|-0
IVIANAKIS, N Commonwealth Edison Co B0/07/16 1p --8007240109 LER 80-016/03L-0 on 800621, during startup & shutdown, valve 1-203-2C failed to close while testing Caused by improper adjustment of exhaust restrictor on pilot valve Pilot valve dismantled & adjusted + Commonwealth Edison Co 80/07/21 2pp

♥ Operator Examinations

8007020319 Responds to 800512 ltr requesting extension until Fall 1980 for completinn of annual requalification exam due to addl work load Exam date may be delayed until 800930 CDLLINS.P F Operator Licensing Branch 80/06/18 1p

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8007010473 Discusses proposed thange to 10CFR50 adding requirement for fire protection plan at facilities Forwards comments on rule, supplementing consultant comments Questions appropriateness of rule, since rule reopens resolved issues HOFFMAN, D.P. Consumers Power Co. 80/06/27 8pp

8007140391 Forwards Revision 2 to 790220 security plan Plan withheld (ref 10CFR2 790) HDFFMAN.D P Consumers Power Co 80/07/08 1p

B007220341 Forwards add1 info re suitability, training & qualification plans, in response to NRC 800515 & 0606 requests Info withheld (ref 10CFR2 790)
HOFFMAN D P Consumers Power Co 80/07/17 ip

BOO7240402 Provides info re access of NRC & NRC contractor personnel to facilities for conducting appraisal of health physics program List of personnel requiring picture badges which specify "no escort required" encl

MEPPLER, J G Region 3, Chicago. Office of the Director 80/07/18

8007280570 Responds to 7911P9 request for info re evacuation time estimates in site emergency plan Evacuation clear time for O- to 10-mile area around Falisades estimated at approx 2 hrs in summer & winter HOFFMAN.D P Consumers Power Co 80/07/23 1p

8007300439 Forwards revised safeguards contingency plans Plans withheld (ref 10CFR2 790) HOFFMAN,D P Consumers Power Co 80/07/24 1p

G Adjudicatory correspondence

8007090316 Forwards Document E, "Equipment Outage Request, Maint Order 78-VAS-064:" as followup to util 800623 response to NRC interrogatories & document requests Related correspondence MURPHY.P M Isham, Lincoln & Beals 60/06/25 2pp

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/04/25 89pp

8007070126 Rept on discovery status re civil penalty proceeding NRC will respond to util supplemental motion to compel discovery on 800703 Need for further discovery requests under Consideration BURNS, S G Rulemaking & Enforcement Division 80/07/01 ig

8007210446 Forwards util 800702 ltr & Revision 1 to "Environ. Assessment - Palisados Plant - Steam Generator Replacement " GIBBS:M E Isham, Lincoln & Geale 80/07/14 ip

8007230810 Response in apposition to NRC 800703 motion for protective order to CPC 800221 interrogatories & requests for production of documents Relief not warranted per ALAB-594 H/Certificate of Byc MILLER.H I . MURPHY.P M . BIELAHSKI.A P Consumers Power Co 80/07/19 19pp

8007250678 Memorandum & order ruling on licensee 800514 & 0613 motions to compel NRC answers to 800221 requests Deliberative data leading to hearing privileged & exempt from production per traditional privilege tests Discusses & rules on other data SMITH. I W Atomic Safety and Licensing Board Panel 80/07/22

- 8007310319 Motion for proposed torrections to administrative law judge 800722 memorandum & order re licensee motion to compel discovery Interrogatory 13 was answered by NRC on 800331 & should be omitted from order Certificate of Svc encl BURNS.S G Rulemaking & Enforcement Division 80/07/29 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007110299 Forwards Revision 8 to FSAR FDGG.W Consumers Power Co 80/07/07 2pp
- --8007110301 Revision 8 to FSAR, ronsisting of replacement Page 9~2 re critical sys supplied by svc water sys * Consumers Power Co 80/07/07 ip
- P Operating license stage documents & correspondence
- BOO70102B9 Forwards evaluation of opened bypass lines in containment based on licensee accident assumptions Licensees DDA represents realistic accident consequences BLAND, J B Environmental Engineering Branch 79/11/07 App
- 8007100296 Forwards Amend 57 to License DPR-20, safety evaluation & notice of issuance & availability CRUTCHFIELD.D Operating Reactors Branch 5 80/06/06 2pp
- --8007100299 Amond 57 to License DPR-20, changing Tech Specs to include add1 radial peaking factor limit GRUTCHFIELD, D Operating Reactors Branch 9 80/06/06 13pp
- --8007100307 Safety evaluation supporting Amend 57 to License DPR-20 * Office of Nuclear Reactor Regulation, Director 80/06/06 3pp
- --B007100310 Notice of issuance & availability of Amend 57 to License
 DPR-20
 LATNAS.C C Assistant Director for Safety Assessment 80/06/06
- B007110247 Forwards Amend 58 to License DPR~20, safety evaluation & notice of issuance & availabilty
 CRUTCHFIELD.D M Operating Reactors Branch 5 80/04/04 2pp
- --8007110254 Amend 58 to License DPR-20, modifying total radial peaking for Tupe H fuel during Cycle 4 GRUTCHFIELDD M Operating Reactors Branch 5 80/06/06 5pp
- ---8007110264 Notice of issuance & availability of Amend 58 to License DPR-20 LAINAS OC Assistant Director for Safety Assessment 80/06/05
- 8006260145 Safety evaluation supporting Amend 58 to License DPR-20 Changes involve H-design reload in Cycle 4 only # Office of Nuclear Reactor Regulation, Director 80/06/06 5pp
- 8007010111 Forwards final rule published in 800507 FR amending 10CFR50 71 to require periodic updating of FSARs Compliance is not required until completion of SEP GRUTCHFIELD. D Operating Reactors Branch 5 80/06/10 6pp
- 8007110126 Notification of 800610 meeting w/util in Bethesda.MD to discuss shift technical advisor WAMBACK.T V Operating Reactors Branch 5 80/06/10 2pp
- BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance

 EISENHUT, D G Division of Licensing 80/06/11 42pp
- 8007100399 Responds to 800229 ltr which expressed opposition to ACRS recommendation to restructure SEP Role of licensess in program will expand Ltr forwarded to Commissioners DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/18 4pp
- ~-8007100420 Expresses apposition to ACRS recommendation to restructure SEP For SEP owners to perform safety analysis as outlined, cost in dollars & manpower would increase dramatically SCHAFFSTALLR SEP Owners Group 80/02/29 2pp
- BOO7180289 Requests comments on causes for & possible remedies for events re site identified in encl rept. "Loss of Offsite Power Survey Status Rept." within 120 days of receipt of ltr CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/19 2pp

- B007250666 Requests addl info re adequacy of station electric distribution sys voltages Requests response within 45 days of ltr receipt CRUTCHFIELD, D.M. Operating Reartors Branch 5 80/06/19 4pp
- B0072B0114 Forwards NRC "Draft Interim Technical Evaluation Rept on Equipment Environ Qualification " Ript will be used as input for safety assessment for Topic III-12 Request comments by B00430 W/p entl MAMBACH, T V Operating Reactors Branch 5 80/06/19 2pp
- 8007010722 Summary of B00606 meeting w/util * Eixon Noclear Co in Bethesda, MD re-outstanding issues from while request to change facility Tech Specs to increase total radial peaking factor for Cycle A reload w/Hedesign fuel LOIS.L. Core Performance Branch 80/06/20 3pp
- 8007020557 Forwards "RCS Asymmetric Luads Evaluation Program," final rept in response to NRC 780125 ltr to PWR licensees is asymmetric LOCA loads C-E affidavit for withholding encl Proprietary version of App A withhold (ref 10CRR 790) LUNDVALL, A E C-E Operating Plants Owners Group 80/06/30 2pp
- --8007020574 "RCS Asymmetric Loads Evaluation Program," final rept. Vol 1 * C-E Power Systems B0/06/30 20pp
- --8007020581 "RCS Asymmetric Loads Evaluation Program," final rept. Vol 2
- * C-E Power Systems B0/06/30 300pp
- --B007020588 "RCS Asymmetric Loads Evaluation Program." Final rept. Vol
 - * C-E Power Systems 80/06/30 300pp
- --8007020593 "RC9 Asymmetric Loads Evaluation Program," final rept.App A, numerical results, eyaluation of C-E fuel Nonpipprietary version App A.Palisades fuel analysis.encl # C-E Power Bystems 80/06/30 26pp
- _____
- --8007020599 "RCS Asymmetric Loads Evaluation Program," App C, pipe whip restraints & App D.plan for fracture analysis of util cold leg piping Final rept « C-E Power Systems 80/06/30 16pp
- --8007020600 "RCS Asymmetric Loads Evaluation Program," App E.ECCS
- analysis approach w/reduced area coolant channels in peripheral assumblies Final rept
 # C-E Power Bystoms 80/06/70 9pp
- 8007030250 Forwards "Rept on Endurance Testing of Auviliary Feedwater Pumps" HDFFMAN.D P Consumers Power Co 80/07/01 ip
- --8007030251 "Rept on Endurance Testing of Auxiliary Feedwater Pumps " * Consumers Power Co BD/G7/01 1/44p
- BOO70BO33B Nptifies that fuel evaluation % cavity wall analysis requested by NRC 79112O ltr.still in progress Progress of fuel evaluation provided in 300701 App B. Final ropt Ropt will be completed by BOO829 HOFFMAN. D.P. Consumers Power Co. 80/07/01 1p
- 8007250693 Forwards request for add) info re SFP design basis events Requests response within 45 days of ltr receipt CRUTCHFIELD.D Operating Reactors Branch 5 80/07/01 4pp
- 8007090008 Forwards Revision 1 to "Environ Assessment Steam Generator Replacement " HUBTON:R W Consumers Puwer Cu 80/07/02 3pp
- ---B007090010 Replacement Pages 5-8.6-1.6-19.8-1 \$ 8-8. submitted as Revision 1 to "Environ Assessment Steam Generator Replacement"

 * Consumbs Power Co 80/05/31 7pp
- B007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Spec & Model license conditions for MM-2 Lessons Learned Category A stems entl for guidance EISFNHUT,D G Division of Licensing 80/07/02 64pp
- 8007100197 Forwards application for amend to License DPR-20 consisting of changes to fock Specs FROST-S R Consumers Power (o. 80/07/03 2pp

- --8007100201 Application for amend of tirense OPR-20 consisting of changes to Tech Specs DEWITTOR B Consumer reth opecs - Consumers Power Co - 80/07/03 - 255
- --8007100204 Changes to Tech Spics 3 9 for effluent release & 4 11 for environ monitoring program * Consumers Power Co. 80/07/03 145pp
- 8007110358 Responds to NRC 800419 request for communis on "Draft Interim Yechnical Evoluation Rept on Equipment Environ Qualification for Palissdes Station Equipment capable of required function Resolution of issue can proceed HOFFMAN.D P—Consumers Power Fo—B0407707—2pp
- 800/28016) Forwards "Loss of Offsite Power Survey Status Rept," to replace rept forwarded o.o Table 4 CRUICHFIELD.D M. Operating Reactors Branch 5 80/07/08 2pp
- 8007160705 Responds to NRC ROO211 request for add1 info re SEP Topic VI-4.containment (volated sys Specific info & list of drowings encl W/o drawings HOFFMAN.D P Consumers Powor (o 80/07/14 lipp
- 8007280076 Responds to 800318 ltr to) Alwarme objecting on behalf of owners of plants under 55P review, to current plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON, H R Defrice of Nuclear Reactor Regulation, Director 80/07/16 4pp
- 800723047.3 Submits verification test results in response to NRC 790808 ltr re adequacy of ensite distribution of power from offsite circuits Results of analytical model simulating worst rase conditions carrelated well u/previous results FROST-S R Consumers Power Co 80/07/18 App
- O Inspection reports, IE Bulletins & correspondence
- 8007010178 Forwards 1E Insp Rept 50-255/80-06 on 800401-0502 No noncompliance noted
 HEISHHAN R F Region 3, Chirago, Reactor Operations Nuclear Support
 Branch 80/05/22 2pp
- ~~8007010393 IE Insp Rept 50-255/80-05 on 900401-0502 No noncompliance noted Major areas inspected activities during long-term shutdown, cleanliness, preparations for startup & action on provious insp findings BOYD.D C , DAKER,K R , JURGENSEN,B L Region 3, Chicago, Défice of the Director 60/05/21 Gpp
- 8007020051 Forwards 2E Info Notice 80-22, "Breakdowns In Contamination Control Programs" No westfor response required KEPPLER.J G. Region 3. Chicago, Office of the Director 80/09/28
- 8007210358 Forwards IE Circular 80-13, "Grid Strap Damage in Wastinghouse Fuel Assemblier" No written response required KEPPLER. J G Region 3. (hicago, Office of the Director 80 60/05/28
- 8007010115 Forwards IE Info Notice 80-23. Luss of Suction to Emergency Feedwater Pumps "No written response required KEPPLER.J G Region & Chicago, Uffice of the Director 80/05/29
- 8007220188 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs ' No written response required REPPLER.J G Region 3, (hicago, Office of the Director 80/06/10
- 8007140173 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Study" No specific action or response recuired KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/11
- 8007030004 Forwards IC Bulletin HO-15, "Possible Loss of Emergency Notification Sys (CMS) W/Loss of Officite Power " Written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 60/06/18
- 8007020552 Forwards IE Circular GO-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown 'No written response reported
- REPPLER, J 6 Region 3. Chicago, Office of the Director 90/06/20

- 8007170474 Forwards IE Circular 80-14. "Rudioactive Contamination of Plant Demineralized Water Sys & Resultant Intolnal Contamination of Personnel 'No written response required KEPPLFR.J G Region 3. Chicago. Office of the Director 80/06/24
- 8007230312 Forwards IE Bulletin 80-16, "Potential Misapplication of 10/23/112 Portugins I Bulletin Burla, "roteintal hisappin Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Clutput Codes "Written response required IE Circular 80-16 also encl No written lesponse required KEPPLER, J & Region 3, Chicago, Dffice of the Director
- B007310177 Responds to 1E Bulletin B0-12 re decay heat removal sys Consultant levieu unacceptable Review & response will be submitted by B00730 HDFFMAN,D P Consumers Power Co 80/07/01 ip
- 8007140350 Responds to IE Bulletin 80-10, "Contamination of Nonradioactive Sys & Resulting Patential for Unmonitored, Uncontrolled Release of Radioactivity to Environ" Domineralized water sys isolated from storage Lank at al HOFFMAN.U.P. Consumors Power Co. 40/07/08 3pp
- 8007140310 Responds to IE Builetin 80-08, "Examination of Containment Liner Penetration Wolds" Penetrations w/flued head design & designs w/containment boundary butt welds between penetration alseve & process piping total 95 HOFFMAN, D.P. Consumers Power Co. 80/07/09 4pp
- B007150803 Forwards "Sisty-Day Response to NRC IE Bulletin 80-11" HDFFMAN.D P Consumers Power Co 80/07/09 1p
- --8007130806 "Sixty-Day Response to NRC IE Bulletin 80-11 "
 * Dechtol Corp B0/06/30 92pp
- B00/220513 Informs of compliance w/order modifying license Insp completed June 1980 Results of insp showed that plant was in compliance w/limiting condition of operation requirements of Tech Specs HOFFMAN, D.P. Consumers Power (a 80/07/16
- B007230460 Notifies NRC of compliance w/791109 order requiring licenses to inspacconsible valves & other controls for engineered safety sys on monthly basis Inspacmplebed in June 1980 Plant is in compliance w/limiting conditions for operation HDFFMAN.D P Consumers Power Co 80/07/16 ip
- 8007230395 Forwards required affirmation inadvertently omitted from 800709 response to If Bulletin 80-11. "Masonry Wall Design " HOFFMAN.D P Consumers Power Co 80/07/18 2pp
- 8007290630 Responds to items of noncompliance noted in IE Insp Rept 50-255/BO OB Corrective actions administrative control procedures have been implomented to assure min instrument operability requirements are maintained HOFFMAN.D P Consumers Power to 80/07/23 3pp
- N Periodic operating reports & related correspondence
- 8007210427 Forwards "Palisades Nuclear Power Plant Radioactive Effluent Release Gemiannual Rept.Jan-June 1978 " HDFFMAN.D P Consumers Power Co 79/08/29 Ip
- ---8007210440 "Palisades Nuclear Power Plant Radioactive Effluent Release Semiannual Rept.Jan-June 1978 " * Consumers Power Co 79/08/29 9pp
- 8007110409 Forwards monthly operating rept for June 1980 MEINCKE, J A Consumers Power Co 80/07/03 1p
- --8007110414 Nonthly operating rept for June 1980 BODTKE,P J Consumers Power Co 80/07/02
- 87007210794 Submits status rept for June-Jul 1980 Bechtel is preparing final design for long-term cooling mods scheduled for 1981 refueling outage HOFFMAN D P Consumers Power Co 80/07/15 ip
- B Reportable occurrences. LERs & related correspondence
- 8007080189 Forwards LER 80-019/017-0 HOFFMAN, D. P. Consumers Power Co 80/07/01 1p

- --8007080199 LER 80-019/017-0 on 800609, during fech Spec review. Tech Spec 3 3 determined to provide too little borated water for safety injection Caused by imprecise wording of Tech Spec Low level alarm setpoint changed. Tech Spec under evaluation • Consumers Power Co 80/07/01 lp
- 8007090314 Forwards updated LFR 80-017/03X-1 HUBTON, R W Consumers Power Co 80/07/03 1
- --B007090319 Updated LER B0-017/03X-1 on B00b10.PS tosting procedures review revealed setpoint of PS-1801 through 1804 to be lower than permitted by Tech Specs Caused by faulty procedure Procedures revised to conform w/Tech Specs * Consumers Power Co 80/07/03 lp
- B00722047B Forwards NPDES noncompliance notification re exceeding of daily max limit for oil & grease on 800630 HOFFMAN,D P Consumers Power Co 80/07/16 1p
- --B0072204B4 NPDES noncompliance notification on 800630, daily max limit for oil & grease of lets than 20 mg/l was exceeded Weekly grab sample indicated 26 2 mg/l oil Caused by failure of F20/M13 filter elements Filters replaced F0BES, R L. Consumers Power Co B0/07/14 lp
- 8007270614 Forwards NPDES noncompliance notification HOFFMAN.D P Consumers Power Co 80/07/23 ip
- ---B007290616 NPDES noncompliance notification on B00703-07.oil & grease accumulation exceeded daily max & monthly average limitations Caused by burst welded seam on generator seal oil strainer Seam rewelded FDBES.R L Consumers Power Co B0/07/16 3pp
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007210024 Forwards list of vital areas & equipment resulting from vital area analysis conducted at facility & computer printbut containing supporting data for vital area analysis Encls withheld (ref 100FR2 770) IPPOLITO,T A Operating Reactors Branch 2 80/06/30 2pp
- BOO722002B Confirms that LASL will conduct vital area analysis of Units 2 & 3 on 800714 E Claibourne & J Rand will conduct visit IPPOLITO.T A Operating Reactors Branch 2 80/07/03 2pp
- 8007300061 Requests confirmation of agreement to participate in program to examine north wall of reactor bldg & review records retests on fire protection supper Commission Order CLI-80-21 Also requests that listed info be available for NRC visit EISENHUT, D O Division of Licensing 80/07/16 3pp
- O Adjudicatory correspondence
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007170380 Expresses concern re plans to construct low level waste storage & incineration facility Proposed facility would present significant health risks to highly populated area Requests public hearing & CIS HOLLINGSWORTH Affiliation Unknown 80/07/09 1p
- J Insurance & indomnity information
- 8007010516 Forwards Endorsement 51 to ANI Policy NF-198 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/06/23 2pp
- B007310434 Forwards Endorsement 43 to MARLU Policy MF-64 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div B0/07/21 2pp
- P. Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I owners group in Bethesda. MD. re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 31pp

- B00707026B Responds to 800123 ltr re use of DDYN code in determining operating limit min critical power ratio Util requests further clarification of expected penalties that may be imposed on top of DDYN calculations
 MILLS.L M Tennessee Valley Authority 80/05/2B 2pp
- 8007020711 Responds to 800422 its sellow level waste mgt at plant Ultimate util objective is to provide for ansite radwaste storage No target date has been established by TVA for submitting application for incineration approval NDVAK.T M Assistant Director for Operating Reactors 80/06/25 3pp
- 8007080286 Responds to fIRC 800521 request for facility participation in phase two Interim Reliability Evaluation Program Urges definitive conclusion of phase one before continuing Outline of critical areas to be resolved encl
 MILLS.L M Tennessee Valley Authority 80/06/30 3pp
- B007170319 Summary of 800612 meeting woutils in Bethesda.MD for interim reliability evaluation program
 DLSH4N,L N Operating Reactors Branch 1 80/06/30 3pp
- B0070B03B0 Responds to NRC 791002 ltr to all BWR licensees & 791031 ltr to util Util funds allocated for Mark I owners group full-scale test facility program Schedule for completion of plant-unique analysis forthcoming MILLS,L M Tennessee Valley Authority 80/07/01 1p
- 8007210026 Forwards request for addl info to complete review of containment purging & venting at facilities NDVAK.T M Assistant Director for Operating Reactors 80/07/08 5pg
- 8007220376 Forwards proposed changes to ETS Section 2 1 re thermal discharge limits HILLS.L M Tennessee Valley Authority #0/07/11 ip
- --B007220377 Proposed change to ETS, Section 2 1 re thermal discharge limits * Tennessee Valley Authority 80/07/14 1p
- 8007240225 Forwards Amends 61,56 & 93 to Licenses DPR-99, DPR-52 & DPR-6B. respectively 4 notice of issuance & availability IFPOLITO. I A Operating Reactors Branch 2 80/07/15 9pp
- --B007240231 Amends 61.56 % 33 to Licenses DPR-33.DPR-52 & DPR-48, respectively, changing Tech Specs re thermal discharge limits
 IPPOLITO, T A Operating Reactors Branch 2 80/07/15 13pp
- --B007240234 Notice of issuance & availability of Amends 61,56 & 33 to Licenses DPR-33,DPR-52 & DPR-68,respectively IPPOLITO,T A Operating Reactors Branch 2 80/07/15 2pp
- 8007220561 Advises of error in responses for Site Specific Question I. Parts B & C. submitted in 800616 ltr.in response to questions re low turbine disc tracking Correct responses encl PARKER. N D Duke Power Cn 80/07/1/ 2pp
- B007300284 Responds to entl B00602 memb re low level waste mgt at facility Util plans to construit two separate low level waste facilities onsite Const on first four cubicles began recently NRC approval of plans necessary DENTON.HR Office of Nuclear Reactor Regulation. Director 80/07/23 Spp
- --BQ07300291 Requests summary of util plans to build low level waste storage facility Alsa requests whether NRC approval is required & whether public hearings have been requested BRADFURD.P A. Commission. 80/04/02 1p
- G Inspection reports. IE Bulletine & correspondence
- BOO72400B9 Forwards II Info Notice BO-20. "Loss of Decay Heat Removal Capability at Davis-Basse Unit 1 While in Refueling Mode" No response required O'RELLLY, J.P. Region 2, Atlanta, Office of the Director BO/05/OB 3pp
- 8007140476 Forwards JE Bulletin GD-13. "Cracking in Care Spray Spargers " Written response required O'REILLY.J P Region 2, Atlanta. Office of the Director 80/05/12 tp
- 8007020192 forwards IE Into Notice 80 22, "Breakdowns to Contraction Control Programs "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Dills 19

- 0225 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency water Pumps" No written response required ILLY, J P. Region 2. Atlanta, Office of the Director 80/05/29
- .0029 Forwards IE Info Notice 80-26, "Evaluation of Contractor rograms " No written response required ILLY,J P. Region 2, Atlanta, Office of the Director 80/06/10
- 0306 Forwards IE Bulletin BO-14. "Degradation of BHR Scram harge Vul Capability " Written response required JLLY.J P. Region 2. Atlanta, Office of the Director 80/06/12
- 0499 Forwards response to IE Bulletin 80-09 transmitted by 'Resilly 800417 lir Final rept for Hartsville & Phipps plants will be sent on or before 901017 S.L.M. Tennessee Valley Authority 80/06/16 2pp
- 0267 Forwards notices of violation & proposed imposition of civil lty re IE insp on 800428 & 050i of transport volicle for carrying radwaste LO.V J Uffice of Inspection & Enforcement. Office of the rtor 80/06/18 2pp

- 020275 Notice of proposed imposition of civil penalty in amount of 0000 re insp on 800428 & 0501 Office of Inspection & Enforcement, Office of the Director /06/18 ip
- 77dl Forwards IE Bulletin BO-15, "Possible Loss of Emergency fication Bys (ENS) W/Loss of Offsite Power " Hritten nose required ILLY,J P Region 2, Atlanto, Office of the Director GD/06/18
- 0153 Discusses 800425 & 28 radiation survey which revealed ation lovels on vehicle surface exceeding regulatory ts forwards notice of yieldstion & notice of proposed sition of civil penalty
 -0.V Office of Inspection & Enforcement. Office of the ctor 80/06/18 2pp
- 140155 Notice of violation from insp on 800428 & 0901 Noncompliance of radiation levels on packages of licensed moti seded regulatory limit Office of the Director
- 40161 Notice of proposed imposition of civil penalties in amount \$5,000 for items of noncompliance re radiation levels on rface of packages exceeding regulatory limits of firector & Enforcement, Office of the Director 404/18 19
- 0391 Forwards IF Circular 80-19. "Loss of Reactor Coolant Pump ng & Natural Circulation Cooldown " No written response ired
- LLY, J.P. Region 2. Atlanta, Diffire of the Director 80/06/20
- 1395 Forwards Waste Parkaging Insp Rept 15000039/80-21 on 800428 LLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 290401 Wastu Packaging Insp Rept 14000039/80-21 on 800428 & 0501 scompliance noted radiation levels on surface of closed. clusive use vehicle in excess of regulatory limits MP.G L. PEERY. M Region 2 Atlanta. Fuel Facility & erials Eafety Branch 80/06/20 App
- 344 Forwards 15 Insp Repts 50-259/80-29.50 260/80-19. 6/80-20 & 50-327/80-22 LLY, J.P. Region 2, Atlanta, Office of the Director 80/06/23
- 10351 IE Insp Repts 50-259/80-25,50-260/00-19,50-296/80-20 & -327/80-22 on 800521 Insp consisted of enforcement meeting Atlanta, GA to discuss exceeding DOT radiation limits ing shipment of radwate from Drowns Forry (CE.H C. Regise 2, Atlanta, Reactor Operations Nuclear Support nch 80/06/20 Rep

- 8007170070 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24
- 8007180523 Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation," & to 800404 confirmatory orders Feedwater pump turbine & main turbine trip circuitry will be upgraded MILLS, L. M. Tennesser Valley Authority 80/06/26 Spp
- 8007230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/6 80/04/27
- B007210091 Forwards response to IE Bulletin B0-10 Potable water, mineralized water & auxiliary boiler sys have possible interfaces between nonradioactive & radioactive sys Routine sampling & analysis program established MILLS.L M Tennessee Valley Authority 80/07/07 3pp
- 8007230726 Forwards monthly status rept re IE Bulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys." presenting status of work as of B00701 MILLS,L H Tennessee Valley Authority 80/07/07 29pp
- 8007280615 Responds to IE Bulletin 80-08, "Examination of Containment Penetration Welds " Results of investigation encl MILLS.L M Tennessee Valley Authority 80/07/07 5pp
- 8007210103 Forwards response to IE Bulletin 80-11 Identifies masonry walls that support or are mear safety-related sys Submits schedule for re-evaluation program CROSS,J L Tennessee Valley Authority 80/07/08 3pp
- 8007280460 Ack receipt of B00616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-299/80-20, 50-260/80-15 k 50-296/80-16 LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/07/09 259
- --8007280468 Responds to NRC 800520 ltr re violations noted in Insp Repts 50-259/80-20, 50-260/80-15 & 50-296/80-16 Corrective actions calibr valve prientation corrected Justifies decision re nonreporting of deisel genrator failure MILLS.L M Tennessee Valley Authority 80/06/16 4pp
- --B007280475 Forwards IE Insp Repts 50-259/80-20,50-260/80-15 & 50-296/80-16 on 800405-0502 & notice of violation LENIS.R C Region 2, Atlants, Reactor Operations Nuclear Support Branch B0/05/20 2pp
- --8007200478 Notice of violation from insp on 800405-0502 * Region 2. Atlanta, Office of the Director 80/05/20
- --B007280484 IE Insp Repts 50-299/80-20,50-260/80-15 & 50-296/80-16 on B00405-0502 Noncompliance noted failure to adhere to surveillance instructions & to make prompt rept to NRC SULLIVAN.R F. CHASC, J W. Region 2. Atlanta. Office of the Director DANCF,H C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/05/20 7pp
- 8D07250896 Forwards response to Item i of IF Bulletin 80-17 re water in scram discharge vol No significant amount of water was found in discharge vol & associated piping Scram discharge vent valves are operable CROSS, J. L. Yennessee Valley Authority 80/07/11 2pp
- 8007310067 Forwards second interim rept in response to IE Bulletin BO-06 Since B00612 interim rept.util completed review of primary containment systreactor protection systRHR syst core spray systvaluation of other sysunderway CROSS, J.L. Tennessee Valley Authority 80/07/11 2pp
- 8007310335 Forwards response to NRC 800616 notice of violation & notice of proposed imposition of civil penalties to 1E 800428 & 0501 insp Corrective actions radwaste shipping procedure revision Civil penalty fee forward
- 8007220522 Requests extension until 800811 for performing manual & automatic scram required by IE Bulletin 80-17 Extension medded because of current heat wave MILLS.L M Tennessee Valley Authority 80/07/16 2pp

- 8007310200 Forwards response to Items 2 (Unit 3),4,5,6(c) & 7 of IE Bulletin 80-17 Present Standby liquid control sys design is unable to support two-pump flow but sys is equipped w/interlocking contacts Item 2 for Units 1 & 2 will be sent MILLO,L M Tennessee Valley Authority 80/07/14 10pp
- 8007290337 Grants extension of time to 800811 for performing scram tests per 1E Bulletin 80-17 EISENHUT, D.Q. Division of Licensing 80/07/18 2pp
- 8007300572 Forwards response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment " Summaries of equipment qualification evaluations based on Encl 4 criteria, encl Full response will be forwarded when evaluations complete MILLS.L M Tennesses Valley Authority 80/07/18 54pp
- R Periodic operating reports & related correspondence
- BOO7220443 Forwards "Effluent & Waste Disposal Semiannual Rept," supplemental info for second half 1978 DEWEASE, J G Tennessee Valley Authority 79/02/15 1p
- --8007220462 "Effluent & Waste Disposal Semiannual Rept," supplemental info for second half 1978 * Tennessee Valley Authority 79/02/15 15pp
- BOO7220342 Forwards "Effluent & Waste Disposal Semiannual Rept," supplemental info, first half 1979 ABERCROMBIE,H Tennessee Valley Authority 79/08/17 ip
- ---8007220346 "Effluent & Waste Disposal Semionnual Rept," supplemental info.first half 1979
 * Tennessee Valley Authority 79/08/17 16pp
- 8007220481 Forwards "Effluent & Haste Disposal Semiannual Rept, Supplemental Info Second Half 1979 " ABERCROMBIE.H Tennessee Valley Authority 80/01/31 tp
- --8007220491 "Effluent & Waste Disposal Semiannual Rept.Supplemental Info.Second Half 1979 " * Tennessee Valley Authority 80/01/31 16pp
- BOO7160552 Forwards monthly operating repts for June 1980 ABERCROMBIE, H. L. Tennessee Valley Authority 80/07/10
- ~~8007160536 Monthly operating repts for June 1980 THOM: T , GREEN.D Tennessee Valley Authority 80/07/02 32pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007080293 Forwards LER 80-045/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/27 1p
- --BOO70BO297 LER BO-045/03L-0 on BOO602.at BOX power, HPCI failed to meet Flow requirements because turbine stop valve tripped Caused by worn mechanical overspeed trip piston New parts installed & tested Tennessee Valley Authority 80/06/27 2pp
- BOO7080301 Forwards LER 90-044/03L-0
 CALHOUN, J. R Tennesses Valley Authority 80/06/27 ip
- --8007080308 LER 80-045/03L-0 on 800505, during power operation, while performing surveillance test, core spray pump discharge pressure switch: PB-75-44, exceeded sufpoint Caused by instrument drift Switch was inspected; callbr & tested # Tennessee Valley Authority 80/05/27, Ppp
- BOO7240455 Part 81 rept re defective Terry Turbine Co HPCI turbine Caused by machining error in fabrication of mechanical overspeed trip valve body assembly which resulted in HPCI remaining in tripped candition Valve body replaced PARRIS, H & Tennesses Valley Authority 80/06/30 Spp
- 8007080313 Forwards LER 80-047/03L-0 CALHOWN, J R, Tennesses Valley Authority 80/07/01 1p
- --8007080333 LER 80-047/03L-0 on 800604, during power operation, while heating drywell air sampling sys: Yecuum pump associated w/
 RM-1-90-236 failed Caused by normal wear Pump was replaced
 to Tennessee Valley Authority 80/07/01 2pp
- 8007690003 Forwards LER BO-048/00L-0 CALMOUN, J R Tennessee Valley Authority B0/07/01 1p

- --B007090006 LER 80-048/03L-0 pn 800602, at steady state power, leak , between root valve & main fire header on sensing line PS-26-44 during running of 51 4 il A Caused by crack in half inch schedule 40 carbon steel hipple threads due to corrosion * Tonnessee Valley Authority 80/07/01 2pp
- B007290864 AD on 80070B during toutine surveillance instruction, PCV 73-43, which controls cooling water to gland seal condensor & lube oil cooler, was found stuck in closed position Cause unknown Equipment expected to be returned to set by 800708 ABERCROMDIE.M Tennessee Valley Authority 80/07/08 ip
- B007150570 Forwards updated LER 79-025/01X-1 CALHOUN, J R Tennessee Valley Authority 80/07/10 1p
- ---8007150574 Updated LER 79-025/01X-1 on 790926, main steam lines not isolated after high temp logic actuation Caused by misinterpretation of Tech Specs Tech Spec revision proposed * Tennøssee Valley Authority 80/07/10 2pp
- 8007230445 Forwards RO 50-259,8054 MILLS,L M Tennessee Valley Authority 80/07/15 Lp
- --8007230452 RD 50-259/8054 on 800706, river temp exceeded max limita for over 1-h at downstream monitor Caused by computer error Predictive computer program underestimated max downstream temp by 2 F Cooling towers used, station load reduced * Tennessee Valley Authority 80/07/15 2pp
- B007230470 Forwards LER 80-047/03L-0 CALHOUN, J R Tennessee Valley Authority 80/07/15 Ip
- --8007230474 LER 80-049/03L-0 on 800620, during surveillance check, TI pressure increase detected on shell side of 1-C filfR heat exchanger Caused by loosened nuts due to thermal cycling & vibration Heat exchanger reassembled % tested # Tennessee Valley Authority 80/07/15 2pp
- HO07230490 Forwards LER 80-051/0JL-0 GALHOUN, J R Tennessee Valley Authority 80/07/18 ip
- --8007230491 LER 80-051/03L-0 on 800626, scram discharge vol high wate level switch LS-84-45A foiled Caused by fleat lodged in BL-305-E3-X level switches float chamber flushed * Tennossee Vallay Authority BO/07/18 2pp
- 8007230523 Forwards LER 80 050/03L-0 Tennessee Valley Authority 80/07/18 ip
- ~~8007230531 LER 80-090/03L-0 on 800624, during performance check, four pressure switch P5-47-144 miswired Caused by personnel failure to follow proper procedures for working on CSSC equipment Pressure switch rewired correctly * Tennessee Valley Authority 80/07/18 3pp
- 8007290657 Forwards LER 80-054/04T-0 CALHOUN, J R Tennessee Valley Authority 80/07/18 ip
- --8007290664 LER 80-094/04T-0 on 800706, during normal operation,U-2 & U-1 were placed on cooling towers Temp continued to rise River temp punked at 90 2 l & then declined Caused by inaccurate rivel temp predictions due to solar heating * Tennessee Valley Authority 80/07/18 2pp
- 8007290737 Forwards LER 80-059/0.HL-0 CALHOUN, J.R. Tennessee Valley Authority 80/0//F5 tp
- --8007290744 LER 80-052/03L-0 on 800628, during normal operation, 4kV Si E tripped on degraded voltage initiating auto start of diesel generator B Diesel generator tripped again on degraded voltage Caused by impraper switch alignment * Tennessee Valley Authority 80/0//25 2pp
- T Hearing transcripts on non-antitrust matters
- B007240091 Transcript of 800715 briefing on status of facilities in , Washington, BC Pp 1-21 * Commission 80/07/15 21pp

- Security, medical, emergency to fire protection plans
- 107210024 Forwards list of vital areas & equipment resulting from vital area analysis conducted at facility & computer printest containing supporting data for vital area analysis Encls withheld (ref 100782 790)

 1PPOLITO, T.A. Uperating Realters Brunch 2 80/06/30 2pp
- 00/2200/8 Confirms that LASE will conduct vital area analysis of Units 2 & 3 on 800/14 & Charbourne & J Rand will conduct visit IPPOLITO Y A Operating Reactors Branch 2 80/07/03 2pp
- 00/300061 Requests confirmation of agreement to participate in program to examine north wall of reactor bldg & review records retests on firm protection sysper Commission Order CLT 80-21 Also requests that insted info be available for MSC visit LIGENHUT, D.O. Division of Licensing 80/07/16 3pp
- Adjudiratory correspondence
- 007310243 Forwards Commission 800827 memorandum & order containing decisions on UCS 780302 petition for reconsideration of 780418 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENIBULD O Division of Licensing, 80706725 G9pp

Oeneral correspondence

- 007176980 Expresses concern to plans to construct low level waste storage & incineration facility Proposed facility would present significant health rioks to highly populated area Requests public hearing & C13
 HOLLINGSHORTH Affiliation Unknown G0/07/09 ip
- Insurance & indemnity information
- 007010916 Forwards Endorsement 51 to ANI Policy NF-198 FIELDER,J March & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/06/23 App
- 07310436 Forwards Endorgement 43 to MAELU Policy MF-66 FIELDER.J March & McLauman.Inc . M & M Nuclear Consultants.Inc Div 80/07/21 2pp
- Operating license stage documents & correspondence
- 07230029 Summary of 600,707 meeting w/Mark I owners group in Duthesda, HD, re revisions to NRC acceptance criteria & owtstanding issues relative to Mark I containment long-torm program GRIMES, C.T. Plant Systems Branch 80/02/21 31pp
- 97070268 Responds to 800123 ltm me use of OBYN code in determining operating limit min critical power ratio Util requests further clarification of experted penalties that may be imposed on top of 600N calculations
 MILLS:
- 070207ti Responds to 800402 ltm re low level waste mgt at plant Ultimate util objective is to provide for unsite radwante storage No target data has been established by TVA for submitting application for incineration approval NOVAK, T.H. Assistant Director for Operating Reactors 80/05/25 Jap
- 07080286 Responds to NRC 800523 request for facility participation in phase two Interim Reliability Evaluation fragram Urges definitive ronclusion of phase one before continuing Outline of critical areas to be resolved which MIIIS-L M Tennessee Valley Authority HO/06/30 3pp
- 07080300 Responds to NRC 791002 ltr to All BHR licensoes & 791031 ltr to util Util funds allocated for Mark I owners group full-scale test Pocility program Schedule for completion of plant-unique analysis forthioming flant-unique analysis forthioming flutSit M - fennessee Valley Authority - BO/O//Ot - 1p
- 07210026 Forwards request for addl info to complete review of containment purging & venting at facilities NOVAK.TM Assistant Director for Operating Reactors 80/07/08

- 8007170360 Application to amend Licenses DPR-52 changing Tech Specs to accommodate Reload 3,Cycle 4 operation Requests that approval of proposed change be given by 801010 to avoid impacting scheduled startup MILLS.L M Tennessee Valley Authority 80/07/14 2pp
- --8007170966 Proposed Tech Spec changes for License DPR-52 to accommodate Reload 3,Cycle 4 operation 4 Virginia Electric & Power Co 80/07/14 18pp
- --B007170574 Supplemental Reload Litersing Submittal for Browns Ferry Nuclear Power Station,Unit 2.Reload 3 " HILF.C L , ENGEL.R E General Electric Co , Y1003J01A12 B0/706/30 20pp
- 8007220374 Ferwards proposed changes to ETS Section 2 i re thermal discharge limits
 HILLS.L M Tennessee Valley Authority 80/07/14 1p
- --8007220377 Proposed change to ETS.Section 2 1 re thermal discharge limits * Tennessee Vailey Authority 80/07/14 1p
- 8007240225 Forwards Amends 61.56 & 33 to Licenses DPR-33.DPR-92 & DPR-6B.respectively & notice of issuance & availability 1PPDLITO.T A Operating Reactors Branch 2 80/07/15 3pp
- ~~8007240231 Amends 61.56 & 33 to Licenses DPR-33.DPR-52 & DPR-68, respectively, changing Tech Specs to thermal discharge limits
 IPPOLITO, T A Operating Reactors Branch 2 80/07/13 13pp
- --8007240234 Notice of issuance & availability of Amends 61,96 & 33 to Licenses DPR-33,DPR-52 & DPR-68,respectively IPPOLITO,T A Departing Reactors Branch 2 80/07/15 2pp
- 6007300284 Responds to oncl 800602 memo re low level waste mgt at facility Util plans to construct two separate low level waste facilities ensite Const on first four cubicles began recently NRC approval of plans necessary UENTON.H R Office of Nuclear Reactor Regulation. Director 80/07/23 Bpp
- --8007300291 Requests summary of util plans to build low level waste storage facility Also requests whether NRC approval is required & whether public hearings have been requested URADFORD.P A Commission 80/06/02 lp
- Q Inspection reports: IE Bulletins & correspondence
- 8007240089 Forwards IC Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"

 No response required
 O'REILLY.JP Region 2. Atlanta. Office of the Director 80/05/08
- 6007140476 Forwards IE Bulletin 80-13, "Cracking in Core Bpray Spargers " Written response required B'REJELY, J P Region 2, Atlanta, Diffice of the Director 80/05/12
- 8007020192 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/28 to
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY-J P Region 2. Atlanta. Office of the Director 80/05/29 ip
- B007220027 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs" No written response required O'HEILLY. J P Region 2. Atlanta, Office of the Director 80/06/10 3pp
- B007140306 Forwards IE Bulletin B0-14. "Degradation of BNR Scram Bischarge Vol Capability " Written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/06/12 Ip
- 8007020497 Forwards response to IE Bulletin BO-09 transmitted by JP D'Reilly 800417 Itr Finel ropt for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLS,L M Tennessee Valley Authority 80/06/16 2pp

- 800702076: Forwards IE Bulletin 80-19. "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power" Written response required O'REILLY, J.P. Region 2. Atlanta, Offsice of the Director 80/06/18 to
- B007020391 Forwards 1E Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLYJP Region 2. Atlanta. Office of the Director B0/06/2
- 8007310344 Forwards IE Insp Repts 50-259/80-25,50-260/80-19, 50-296/80-20 & 50-327/80-22 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20 30p
- --B007310351 IE Insp Repts 50-259/80-25,50-260/80-19,50-296/80-20 & 50-327/80-22 on 800521 Insp consisted of enforcement meeting in Atlanta GA to discuss exceeding DDT radiation limits during shipment of radwaste from Browns Ferry DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/20 2pp
- 8007170070 Forwards IE Circular 80-14. "Radicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/06/24
- 8007180523 Forwards response to IE Bullotin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." & to 800404 confirmatory orders Feedwater pump turbine a main turbine trip circuitry will be upgraded MILLS,L M Tennessee Valley Authority 80/06/26 8pp
- 8007230293 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes "Hritton response required IE Circular 80-16 also snc1 No written response required Q'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/27
- B007210091 Forwards response to IE Bulletin 80-10 Potable water, mineralized water & auxiliary boiler sys have possible interfaces between nonradicactive & radicactive sys Routine sampling & analysis program established MILLS.L M Tennessee Valley Authority B0/07/07 3pp
- 8007230726 Forwards monthly status rept re lE Bulletin 79-14, "Spismic Analysis for As-Built Bafety-Related Piping Bys." presenting status of work as of 800701 MILLB.L M Tennessee Valley Authority 80/07/07 29pp
- 8007280104 Forwards response to IE Bulletin 80-i1 Response includes general arrangement drawing indicating masonry walls of concern & equipment in approximate area of wall M/o encl FURR. B. J. Carolina Power & Light Co 80/07/07 ip
- 8007280615 Responds to IE Rulletin 80-08, "Examination of Containment Penetration Welds " Results of investigation encl MILLB,L M Tennessee Valley Authority 80/07/07 5pp
- 8007210103 Forwards response to 1E Bulletin 80-11 Identifies masonry walls that support or are near safety-related sys Submits schedule for re-evaluation program CROSS, J L Tennessee Valloy Authority 90/07/08 3pp
- 8007280460 Ack receipt of 800616 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/80-20, 50-260/80-15 & 50-294/80-16 LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/09 2pp
- --8007280468 Responds to NRC 800520 ltr re violations noted in Insp Repts 50-259780-20,50-260/80-15 & 50-296/80-16 Corrective actions calibr valve orientation corrected Justifies decision re nonreporting of deisel geneator failure MILLB.L M Tennessee Valley Authority 80/06/16 App
- --B007280475 Forwards IE Insp Repts 50-289/80-20,50-260/80-15 & 50-296/80-16 on 800405-0502 & notice of violation LEWIS,R C. Region R. Atlanta, Reactor Operations Nuclear Bupport Branch 80/05/20 2pp
- --B007280478 Notice of violation from imag on B00405-0502 * Region 2, Atlanta, Office of the Director 80/05/20 ip

- --8007280484 IE Insp Repts 50-299/HO-20,50-260/HO-15 & 50-296/HO-16 an BOO405-0502 Noncompliance noted failure to adhere to surveillance instructions & to make prompt rept to NRC SULLIVAN R F , CHASE, J W Region 2, Atlanta, Office of the Director DAMCE, H C Region P, Atlanta, Reactor Operations Nuclear Support Branch 80/05/20 /pp
- B007250596 Forwards response to item t of IE Bulletin B0-17 re water in scram discharge vol No significant amount of water was found in discharge vol % associated piping Scram discharge vent valves are operable
 CROSS.U L Tennessee Valley Authority 80/07/11 2pp
- 8007310067 Forwards second interim rept in response to IE Bulletin 80-06 Since 800612 interim rept, util completed review of primary containment systreactor protection systRHR sys & core spray sys Evaluation of other sys underway CROSS.J L. Tennessee Valley Authority 80/07/11 2pp
- 8007220522 Requests extension until 800811 for performing manual & automatic scram required by IE Bulletin 80-17 Extension needed because of current heat wave MILLS.L M Tennessee Valley Authority 80/07/16 2pp
- 8007310208 Forwards response to Items 2 (Unit 3), 4, 5, 6(c) & 7 of IE Bulletin 80-17 Present standby liquid control sys design is unable to support two-pump flow but sys is equipped w/interlocking contacts Item 2 for Units 1 & 2 will be sent MILLS, L M Tennessee Valley Authority 80/07/16 10pp
- B007270357 Grants extension of time to 800811 for performing scram tests per IE Bulletin B0-17 EISENHUT, D G Division of Licensing 60/07/18 2pp
- 8007300572 Forwards response to 1E Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Summaries of equipment qualification evaluations based on Encl 4 critoria, encl Full response will be forwarded when evaluations complete MILLS.L M Tennessee Valley Authority 80/07/18 54pp
- A Periodic operating reports & related correspondence
- BOO7220443 Forwards "Effluent & Maste Disposal Semiannual Rept."
 supplemental info for second half 1978
 DEWEASE, J. G. Tennessee Valley Authority 79/02/15 1p
- ---8007220463 "Effluent & Waste Disposal Semiannual Rept." supplemental info for second half 1978
 * Tennessee Valley Authority 79/02/15 15pp
- 8007R20342 Forwards "Effluent & Haste Disposal Semiannual Rept," supplemental info.first half 1979 ABERCROMBIE.H Tennossee Valley Authority 79/08/17 lp
- --B007R20346 "Effluent & Waste Disposal Sommannual Rept," supplemental inforfirst half 1979 * Tennessee Valley Authority 79/08/1/ 16pp
- 80072204Bi Forwards "Effluent & Waste Disposal Semiannual Rept. Supplemental Info. Second Haif 1979 " ABERCROMBIE.H Tennessee Valley Authority 80/01/31 lp
- --8007220491 "Effluent & Waste Disposal Semiannual Rept.Supplemental
- Info.Becond Half 1979 "
 * Tennessee Valley Authority 80/01/3; 16pp
- B007160552 Forwards monthly operating repts for June 1980 ABERCROM01E.H.L. Tennessee Valley Authority 80/07/10 lp
- --8007160556 Monthly operating repts for June 1980 THOM.T., GREEN.D. Tennessce Valley Authority 80/07/02 32pp
- 5 Reportable occurrences. LERs & related correspondence
- 8007110291 RU-BFRU-50-260/8025 on 800617. Dresser Industries safety valves identified as possibly having guides w/cracks Condition identified in smaller valves loaned to another util from Browns Forry Cause unknown ADERCRUMBIE:H Tennessee Valley Authority 80/86/17 ip
- 8007080394 Forwards LER 80-023/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/27 ip

- --8007080399 LFR 80-023/03L-0 on B(0607, during normal operation, 2A reactor recirculation motor generator set tripped due to generator stato, temp high relay actuation Probable cause was longe wire caused by vibration

 * Tennessee Valley Authority 80/06/27 ip
- 3007080405 Forwards LER 80-022/03L-0 CALHOUN.J R Tennessee Valley Authority 80/06/27 ip
- -8007080411 LER 80-027/031-0 on 800402 while performing S I 4 I A-14, turbine first stage prassure permissive pressure switches PS-1-91 A & B & setpoints exceeded Tech Spac limits Caused by switch drifting

 * Tennessee Valley Authority 80/06/27 2pp
- 007080370 Forwards LER 80-025/01T-0 CALHDUN, J.R. Tennessee Valley Authority 80/06/30 Ip
- -8007080373 LER 80-025/017-0 on 800617, during narmal operation discovered that spare Dresser Industries safety valve had guide Wicracks Cauged during initial pouring of casting & subsequent couling Addi valves will be inspected for tracks * Tennessee Valley Authority 80/06/30 2pp
- 007290720 Forwards LER 80-024/03L-0 CALHOUN, J.R. Tennessee Valley Authority B0/07/22 1p
- 8007290726 LER 80-024/03L-0 on 800624, during red sequence exchange w/ unit at 40% power, control red 30-27 failed to latch after insertion & drifted out when insert rod released Caused by failure of directional valve 85-40C Valve replaced # Tennessee Valley Authority 80/07/22 2pp
- Hearing transcripts on non-antitrust matters
- 07240091 Franscript of 600715 briefing on status of facilities in Vashington-DC Pp 1-21 Commission 80/07/15-21pp
- RET 50-241 H B ROBINSON PLANT, UNIT 2
- Security, modical, emergency & fire protection plans
- 7020330 Forwards request for addl info & revisions for safeguards ontingency plan submitted on 790323 Info should be provided ithin 30 days of receipt of ltr Request withheld ref IOCFR2 790)
 ARGA, S.A. Operating Reactors Branch 1 80/05/21 2pp
- 7010307 Responds to NRC 800521 request for add1 info re 790323 afaguards contingency plan Info will be submitted by 10801
- OBO) TLEY, E E | Farolina Power & Light Co | 80/06/27 | ip
- 7010514 Responds to B00604 request for addl info re administrative introls for fire protection Util will develop program thering to requirements (LEY, E E Carolina Power & Light Co B0/06/27 2pp
- djudicatory correspondence
- 310243 Forwards Commission B00727 memorandum % order containing scisions on UCS 780502 potition for reconsideration of O413 memorandum & order UCS 771104 petition sought action fire protection for electrical cables SENHUT.D 0 Division of Licensing 80/06/25 89pp
- inancial information
- 1200f1 Responds to 800508 request for comment on util 8-7 gistration statement Review identified no inaccurate atements to RRC regulatory requirements or financial infolled w/NRC 18TENBURY, E. Huarings Division. 80/05/27 lp
- perating license stage documents & correspondence
- 90126 Responds to B00318 ltr re NRC position on util approach of lying AIF position paper for procurement of off-the-shalf ms NRC does not concur wintil approach Procurement of ire or replacement parts vbj to QA controls

- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D G Division of Licensing 80/06/11 62pp
- 8007100150 Forwards Amend 47 to License DPR-23, safety evaluation & notice of issuance & availability
 VARGA.S A Operating Reactors Branch 1 80/06/12 2pp
- --8007100156 Amend 47 to License DPR-23, allowing blockage of channels when RCS pressure less than 2,000 psig VARGA: S A Operating Reactors Branch 1 80/06/12 App
- --8007100162 Safety evaluation supporting Amend 47 to License DPR-23 EGRO technical rept encl # Office of Nuclear Reactor Regulation, Director 80/06/12 9pp
- --BOO7100165 Notice of issuance & availability of Amend 47 to License DPR-23 VARGA/S A. Operating Reactors Branch 1 80/06/12 2pp
- 8007010384 Forwards responses to DG Eisenhut 800507 info request ra final recommendations of Bulletine & Orders Task Force UTLEY.E E Carolina Power & Light Co 80/04/27 2pp
- B007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items entl for guidance EISENHUT.D O Division of Licensing 80/07/02 69pp
- 8007190626 Responds to NRC 800602 request to modify administrative procedures to limit auxiliary feedwater flow Util will revise procedures to limit pump operation following postulated steam line break & prior to isolating component UTLEY.E E Carolina Power & Light Co 80/07/09 2pp
- 8007290420 Corrects inaccuracies in NRC 800418 evaluation of Category A.TMI-2 Lessons Learned Task Force items implementation No equipment is required to implement interimemergency sampling procedures

 UYLCY.E C. Carolina Power & Light Co. 80/07/22 2pp
- 8007280679 Submits schedule for refueling facility for Cycle 8 operation ECCS analysis being performed to allow for up to 10% steam generator tube plugging in event steam generator insp program indicates add1 tubes need to be plugged UTLEY.E C Carolina Power & Light Co 80/07/22 2pp
- 8007290670 Notifies that revised radiological effluent Tech Specs will be submitted by 801022 per NRC 800602 comments & 800701 meeting discussions UTLEY.E E Carolina Power & Light Co 80/07/22 1p
- 8007290686 Forwards addl info re adequacy of station electric distribution sys voltages in response to 800602 ltr Describes undervoltage relay trip setting for Class IE 480 yolt buses, spare startup transformer & offsite sources UTLEY.E E Carolina Power & Light Co 80/07/23 7pp
- 8907310517 Summary of 800701 meeting w/util in Bethesda.MD re proposed radiological ETS NEIGHBORS.D Operating Reactors Branch I 80/07/23 3pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007240i13 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/08
- 8007020187 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Centrol Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/20 10
- 8007210422 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28
- BOD7010179 Forwards IE Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/05/29 16

- B0070200B7 Responds to IE Bulletin B0-06 Review of control wiring diagrams of safety-related functions confirmed that emergency equipment would remain in emergency mode upon reset FURR.D J Carolina Power & Light Co 80/06/10 3pp
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor
- QA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 200
- 8007160223 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required D'RETLLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- B007020745 Forwards IC Bulletin B0-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsita Power " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/18
- 8007100031 Submits revised schedule for response to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment" Rept will now be completed as soon as all available info is obtained FURR. B J Carolina Power & Light Co 80/06/19 lp
- B007020440 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director B0/06/20
- 8007100093 Forwards IE Insp. Rept 50-261/80-12 on 800610-12 No noncompliance noted Details withheld (ref 10CFR2 790) KENNA,W B Region 2, Atlanta, Bafeguards Branch 80/06/20 [p
- --B007100095 IE Insp Rept 50-261/80-12 on 600610-12 No noncompliance noted Major areas inspected security organization Details withheld (ref 10CFR2 750) GILLEBPIE.F P. MORRE, D E., VORSE, J Y. Region 2, Atlanta, Office of the Director 60/06/20 1p
- B007190097 Ack receipt of 800409 1tr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-261/80-09
 KENNA, H B Region 2. Atlanta. Safeguards Granch 80/06/24 1p
- --B007150097 Responds to NRC 800514 ltr re violations noted in 1E Insp Rept 50-261/80-09 Attachment A describing corrective action withheld (ref 10CFR2 790) FURR.B J Carolina Power & Light Co 80/06/09 ip
- ~~8007150101 Forwards IE Insp Rept 50-261/80-09 on 800421-25 & notice of violation Notice of violation withheld (ref 10CFR2 790) KENNA.H B Region 2. Atlanta. Safeguards Branch 80/05/14 2pp
- --B007150107 IE Insp Rept 50-261/80-07 on 800421-25 Noncompliance noted insecure grates & hatches provided unauthorized access into vital area Details withheld (ref 1007R2,790)
 GILLEBPIE, F P Region 2, Atlanta, Safeguards Branch TILLMAN.A, HOWELL, J C Region 2, Atlanta, Office of the Director 80/05/14 to
- 8007160800 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24
- B007230220 Forwards IE Bulletin G0-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/27
- 8007220254 Responds to IE Bulletin BD-10 Review of facility design & operation complete Sampling, analysis & monitoring program established New or revised procedures implemented FURR, B J Carolina Power & Light Co 80/07/01 1p
- 8007220227 Responds to IE Bulletin 80-08 Facility has no flued head penetrations in containment Welds are fillet & were examined by magnetic particle method during const

- 6007210022 Forwards second response to IC Bulletin 79-01B Includes environ qualification data hased upon investigation to date Efforts to obtain available data from NSSS supplies are underway M/o encl
 EURY/L W Carolina Power & Light Co 80/07/0/ ip
- R Periodic operating reports & related correspondence
- B007150629 Forwards monthly operating rept for 1980
 STARKEY.R B Carolina Power & Light Co B0/07/10 ip
- ~~8007150633 Monthly operating ropt for June 1980 WATFORD,M Carolina Power & Light Co 80/07/02 5pp
- S Reportable occurrences, LERs & related correspondence
- 8007010401 LER 79-027 has been cancelled * Carolina Power & Light Co 80/06/30 lp
- 800701040B LER 79-023 has been cancelled * Carolina Power & Light Co 80/06/30 I
- B007010410 LER 79-022 has been cancelled * Carolina Power & Light Co B0/06/30 is
- 8007010461 LER 79-013 has been cancelled * Carolina Power & Light Co 80/06/30
- 9007010466 LER 79-021 has been cancelled * Carolina Power & Light Co 90/06/30 ij
- 8007220440 Forwards LER 80-014/01T-0 STARKEY, R B Carolina Pawer & Light Co 80/07/16 1p
- ---BOD7.220445 LER BO-014/017-0 on 800702, determined no certification of qualification available for PVC electric cable pigtails per IE Bulletin 79-010 Cause not stated Test to be conducted assuring pigtails ability to perform required function STARKEY, R D Carolina Power & Light CD BO/07/16 5pp
- V Operator Examinations
- B007220426 Forwards revised training programs for instructor requalification program & operator requalification program STARKEY, R B Carolina Power & Light Co 80/07/11 2pp
- --8007220427 Training Instruction 201.Revision 4, "HB Robinson Plant Operator Replacement Training Program"

 * Carolina Power & Light Co 80/05/17 9pp
- ---8007220433 Training Instruction 201A Revision 4. "Training of Replacement Reactor Operators for NRC Examination W/o Reactor Startup Demonstration " * Carolina Power % Light Co 90/06/27 14pp
- --8007820435 Training Instruction 203 Revision O. "Senior Reactor Operator Replacement Training Program " * Carolina Power & Light Co 80/05/25 10pp
- --8007220438 Training Instruction 902.Revision O. "Instructors Requalification Program" * Carolina Power & Light Co 80/05/29 10pp
- DOCKET 50-263 MONIFICELLO NUCLCAR GENERATING PLANT F Security, medical, emorgency & fire protection plans
- 8007010372 Forwards BNL fire protection review re diesel generator room automatic water suppression sys & cable spreading room gas suppression sys for facility HALL,R E Brookhaven National Laboratory 80/06/24 3pp
- 80070103B1 Submits description of motor generator set room vent duct fire proofing required by fire protection safety evaluation Main vent duct & duct branching into main duct will be covered with 2-sinch layer of Pyrorrete 241 MAYER, L. O. Northern States Fower Co. 80/06/25 1p
- 8007010325 Submits description of fire stops between Fire Zones 13C & 19C, required by fire protection safety evaluation Comments on proposed design should be conveyed by 800815 to comply w/work schedule MAYER, L.O. Northern States Power Co. 80/06/26 2pp

- 8007010311 Describes thanges planned for fire protection safety evaluation sections re commitment to provide capability to cool RHR pump seal coolers via emergency syr water sys forwards drawing of interconnection schematic MAYER.L.O. Northern States Power Co. 80/06/27 3pp
- B007280444 Forwards add1 info or fire protection safety evaluation Control room fire detectors, hose stations add1 hose & fire pumps are addressed MAYER, LO Northern States Power Co B0/07/18 App
- B0072B03B1 Submits design change to fire protection safety evaluation. Item 3 i 12(2). "Fire Suppression Sys Interconnection "Turbine bldg end of interconnection line will remain pressurited as supply for sprinkler curtain MAYER.L Q Northern States Power Co. 80/07/21 lp
- 8007280488 Discusses licensee review of alternate 250 volt do power source in HPCI & reactor core isolation cooling sys Independent source for HPCI is required to assure HPCI operability in event of fire in existing battery sys MAYER.L D Northern States Power Co 80/07/22 lp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENBUT, D & Division of Licensing 80/06/25 87pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I comers group in Bethesda, MD, re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment lung-term program GRIMES.C T Plant Systems Branch 80/02/21 31pp
- 8007030222 Notifies NRC of intention to ship radioactive matl from facilities using Model HN-600
 MAYER.L O Northorn States Power Co 80/06/13 1p
- B007010335 Submits description of battery room ventilation air flow monitoring installation Diagram ent!
 NAVERL O Northern States Power Co 80/06/24 2pp
- B007080291 Responds to GE B00221 Itr re list of concerns from ACRS consultant HPCI & reactor core isolation copiling described Completes commitment re NUREG-0560. Item II H 3 46 MAYER.L O Northern States Power Co 80706/20
- 8007100067 Advises that time-motion study & dose rate calculation using relevant dose rates completed per NUREC-0578, Item 2 1 8 a New post-accident Sampling station will be installed MAYER.L O Northern States Power Co 80/06/30 ip
- 8007220038 "Electrical, Instrumentation & Control Sys Support," technical evaluation rept for June 1980 CLEVELAND.C J EG&G Idaho.Inc FIN A-6256 8007220038 80/06/30 14pp
- 8007080265 Forwards summary of test data re completion of EDC 7 fuel insp & DDC 8 startup physics test MAYER, L O Northern States Power Co 80/07/02 4pp
- 8007210186 Forwards "Yest Rept EOC 7 Fuel Insp & BOC 8 Startup Physics" MAYER.L O Northern Statos Power Co 80/07/02 ip
- --8007210194 "Fest Rept EdC 7 Furl Insp & 200 B Startup Physics "
 * Northern States Power Co 80707702 Opp
- 8007280056 Advises of intention to ship radioactive matts from listed ackage Model CNSI AL-33-90 C 80/07/03 lp

nalysis tode for 1981 e code Addl I BWR

V07/07 200

for comments on Drive Return

Эрр

- 8007180700 Forwards Revision & of "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements " MAYER, L D Northern States Power Co 80/07/16 2ap
- ---8007180306 Revision & of "AGME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements " Northern States Fower Co 80/07/16 24pp
- 8007280410 Forwards comments on NUREC-0577. "Fracture Toughness & Susceptibility to Stress Corrosion Cracking of Equipment Bupports." in response to NRC 800519 request Addl analysis for stress corrosion cracking is unnecessary MAYER.L O Northern States Power Co 80/07/21 5pp
- 8007280489 Forwards NUTECH evaluation of low pressure turbine roll Results confirm earlier belief that present sys limitations associated w/intermediate range monitors cause 600 psi turbine roll Meds under review CLARITY, M H. Northern States Power Co. 80/07/21 16pp
- G Inspection reports. IE Bullotins & correspondence
- 8007140532 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/12 ib
- 8007020054 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J.G. Region 3. Chicago, Office of the Director 80/05/28 to
- 80070i0127 Forwards IE Info Notice 80~23. "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/29 to
- 8007140487 Forwards IE Insp Rept 50-263/80-09 on 800428-0502 No noncompliance noted HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/30 2pp
- --B007140494 IE Insp Rept 50-263/80-09 on B004RB--0502 No noncompliance noted Najor areas inspected plant operations, torus-dyrwell vacuum breaker mod & recirculation pump seel failures WARNICK, R F, SROWN, C, MADISON, A Region 3, Chicago, Défice of the Director B0/05/20 Opp
- 8007110044 Forwards IE Insp Rept 50-263/80-06 on 800324,27-30,0424-25 t 0505-07 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --B007110049 If Insp Rept 50-263/80-06 on B00324,27-30,0424-25 & 0506-07 No noncompliance noted Major areas inspected containment integrated loak rate test & local leak rate testing HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Bupport Branch CHOM.E T . HOPKINS.J B Region 3. Chicago. Office of the Director 80/06/03 7pp
- 8007220212 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER.J G Region 3. Chitago. Office of the Director 80/06/10 to
- 8007140331 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/12 ip
- E007020162 Responds to IE Bullstin 80-06, "Engineered Safety Feature Roset Controls" All safety-related equipment remains in emorgency mode upon roset of actuation signal w/listed exceptions
 GLUERTS, D E Northern States Power Co B0/06/16 3pp
- B007030043 Forwards IE Bulletin B0-15. "Possible Loss of Emergency Natification Bys (FNS) W/Lose of Offsite Power " Written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/06/18
- 8007020573 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J.O. Region 3. Chicago, Office of the Director 80/06/20, ip

- B007300307 Forwards IE Insp Rept 50-263/80-10 on B00520-22 No noncompliance noted HEISHMAN.R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch B0/06/23 2pp
- --8007300309 IE Insp Rept 50~263/80~10 on H00520-22 No noncompliance noted Major areas inspected fire protection prevention, IE bulletin followup, calibr & review of plant operations BROWN, C H, WARNICK, R Region 3, Chicago, Office of the Director 80/06/20 4pp
- 8007170506 Forwards IE Circular 80-14, "Radinactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPFLER, J. G. Region 3, Chicago, Office of the Director 80/06/24 to
- 8007210501 Ack receipt of 800528 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-263/80-08
 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/06/24 ip
- --8007210507 Responds to NRC 800508 ltr re violations noted in 1E Insp Rept 50-263/80-08 Currective actions labels reinforced w/ tage.redundant labels applied & extra set of labels provided w/instructions OILBERTS,D E Northern States Power Co 80/05/28 ip
- B007230336 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also ancl No written response required MEPPLER.J G Region 3. Chicago, Office of the Director 80/06/27
- B007210192 Responds to IE Builetin 80-10, "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Actions re Items 1 & 2 completed as of 800625 OILBERTS, D. C. Northern States Power Co. 80/06/30 ip
- 8007240104 Forwards IE Insp Rept 50-263/80-13 on 800609-13 & notice of violation Notice of violation withheld (ref 10CFR2 790) HIND, J A Region 3, Chicago, Safeguerds Branch 80/07/02 2pp
- --8007240107 IE Insp Rept 50-263/80-13 on 800609-13 No noncompliance noted Details withheld (ref 10CFR2 790) HIND.J A Region 3, Chicago. Safeguards Branch CHRISTOFFER. 0 M. MADEDA.T J Region 3. Chicago. Office of the Director 80/07/01 200
- B007210132 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Lists flued head penetrations & provides info re design & nondestructive examination of penetrations GILBERTS, D E Northern States Power Co 80/07/03 9pp
- B007180566 Notifies that time clock of Item 2 of IF Bulletin B0-17.
 "Failure of Control Rods to Insert During Scram at BWR."
 will start at 12 01 AM on 800708 Test should be completed
 within 20 doys Requests notification of malfunction
 KEPPLER, J G Region 2. Atlanta. Office of the Director 80/07/07
 18.
- B007250965 Responds to IE Bulletin B0-11 Bechtel Power Corp contracted to identify & re-evaluate masonry walls Surveys of inaccessible areas will be performed at earliest opportunity w/results provided in followup rept OILBERTS.D E Northern States Power Co 80/07/07 114pp
- 8007280057 Responds to IE Bulletin 80-17 Surveillance tests performed on 800704 Found no detectable water in sys Daily ultrasonic tests are being performed to manitor for residus water Item 7 not applicable OLDERTE.D E Northern States Power Co 80/07/09 2pp
- 8007290841 Submits Add1 response to IE Bulletin 80-17 Appropriate revisions of operating procedures issued on 800711 No water detected re Item 5 Reporting requirement re Item 6a accomplished Yurbal requirement per 6b made on 800703 OILBERTS.D E Northern States Power Co 80/07/17 Opp
- R Periodic operating reports & related correspondence
- 8007150611 Forwards monthly operating rept for June 1980 MAYER, L D Northern States Power Co 80/07/09 2pp
- --8007150614 Monthly operating rept for June 1980
 MYRABD.A L. Northern States Power Co. 80/07/03 3pp

- S. Reportable occurrences, LERs & related correspondence
- B007010531 Forwards LER B0-022/03L-0 MAYER, L. O. Northorn States Power Co. B0/04/24 1p
- --8007010542 LER 80-022/031 0 on 800529, primary containment oxygen concentration exceeded 5/ by weight Teck Spec limit Caused by open svc air isolation valve to drywell Procedures have been nevised to assure proper valve positioning SHURTS 5 J Nurthern States Power to 80/06/26 lp
- 8007100190 Forwards LCR 80-023/03L-0 MAYER, L D Northern States Power Co 80/07/01 1p
- --8007100195 LER 80-023/03L-0 on 80%501.311 sjector offgas radiation monitors dropped to about 20% normal for about 40 minutes Caused by mechanical vacuum pump offgas sample valve being incorrectly opened Valve now wired shut

 JACOBSON,R D Northern States Power Cu 80/07/01 1p

DOCKET 50-264 DOW CHEMICAL CO

- F Security, medical, emergency & fire protection plans
- B007280699 Discusses uproming review of physical security plan Encl 790628 Itr w/Amend 4 to License R-108 incorporated 781020 security plan Pending review of current plan submittal of changes is not nocessary MILLER, J R Standardization & Special Projects Branch 80/07/09 200
- Q Inspection reports. IE Bulletins & correspondence
- BQ07170617 Forwards IE Circular 80 14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required KEPPLER, J. G. Region 3, Chicago, Diffice of the Director 80/06/24 to

DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- B007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES.D L Commonwealth Edison Co 80/06/27 tp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D.G. Division of Licensing 80/06/25 87pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 morting w/Mark I owners group in Bethesda. MD re revisions to NRC acceptance criteria & outstanding issues relative to Mark I cuntainment long term program GRIMES,C T Plant Systems Granch 80/02/21 Sipp
- 8007270217 "Measurement of Xe-13),C-14 & Tritium in Air & I-131 in Vegetation & Milk Around Guad Cities Nuclear Power Stations." KELLER,J H. AKERS,D W., DUCC,S W. Idaho National Engineering Laboratory FIN A-6078 NUREG/CR-1195 80/03/31 400pp
- 8007010070 Responds to FOIA request for 97 documents referenced in M Tokar memo to ACRS concerning pellet-cladding interaction Forwards documents Missing fecords are duplicative, sugarsaded or available elsewhere FELTON.J H Division of Rules and Records 60/06/20 2pp
- --8007010119 Forwards description of causes of 750522 off-gas release at facility Release appears to be caused by flux peaking SIEGEL.B Core Performance Branch 75/06/05 5pp
- 8007010190 Responds to SSRT university control rod drive sys lacking teismic analysis Quad Cities 1 & 2 seismic design of control rod drive sys telculations performed for facility while under const encl

 JANSCEKUR F Commonwealth Edison Cu 90/06/24 App

- B007010193 "Guad Cities 1 % & Seismic Data on Control Red Drive Sys "
 # Reactor Controls. Inc 70/07/10 200pg
- 307070)16 Submits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads JANECEK,R F Cammonwealth Edison Co 80/06/26 App
- 007080069 Responds to NRC 800519 request for addl info concerning adequacy of station electric distribution bys voltages JANECFK.R F Commonwealth Edison Co 80/06/30 4pp
- 007280470 Forwards "Reactor Containment Bidg Integrated Leak Rate Test," & related app describing Type A test Next Type A test will be performed during shutdown scheduled for 1983 KALIVIANAKIS.N Communwealth Edison Co 80/07/01 ip
- -8007280474 "Reactor Containment Bidg Entegrated Leak Rate Test " « Commonwealth Edison Co BO/0J/12 39pp
- 007070349 Forwards revised schedule % status info for Mark I program, feedwate, sparyor replacement & general work planned for Quad Cities i suitago Proceeding on priority basin w/mods providing largost tafety increase margins RCED.C Commonwealth Edison Co 80/07/02 18pp
- 007100142 Application for amend to App A. Tech Specs of Licenses DPR-29 & DPR-30, implementing fire protection mods JANECEK.R F Commonwealth Edison Co 80/07/03 2pp
- 8007100147 Proposed changes to Trub Specs 3 12/4 12-1 through 3 12/4 12-9 implementing Fire protection mods * Commonwealth Edison Co. 80/07/03 18pp
- 007210212 Responds to NRC request for additinfo re turbine disks Applicable turbino missile analysis was presented in Amend 2 to Quad Cities (P application Analysis applies to Dresden dup to similarity of general arrangement JANECEK.R F Commonwealth Edison Co 80/07/15 1p
- Inspection reports. IE Bulletins & correspondence
- 07140945 Forwards IC Bulletin 80-13. "Cracking in Core Spray Spargers " Written response required KEPPLER.J G. Region 3. Chicago: Office of the Director 80/05/12
- 07020065 Forwards IC Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J 9 Region 3. Chicago, Office of the Director 80/05/28
- 07010086 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/05/29
- 07020756 Forwards revised response to IE Bulletin 79-016, "Environ Qualification of Class IT Equipment " Identifies areas where effort is continuing in identification of equipment qualifications W/o encl JANECEK,R F Commonwealth Edison Co 80/06/02 ip
- 07220154 Forwards 1E Info Notice 80-24. "Evaluation of Contractor OA Programs " No written responso required KEPPLER,J O Region 3, Chicago, Office of the Director 80/06/10
- 07140309 Forwards II Bulletin 80-14. "Degradation of BWR Scram Dimcharge Vol Capability " Written response required MEPPLER.J G Region 3. Chicago. Office of the Director 80/06/12
- 97100004 Forwards response to 1E Bulletin 60-09. "Hydramotor Actuator Deficiencies." No safety-related sys or component at Dresden 2 & 3 uses AH-70 or NH-90 series hydramotor Ictuators PEOPLES.D L. Commonwealth Edison Co. 80/06/16. 3pp
-)/030037 Forwards IE Bulletin 80-15, "Possible Loss of Emergency datification Bys (ENS) W/Loss of Offsite Power " Hritten response required (EPPLER.J Q Region 3, Chicago, Office of the Director 80/05/18

- 8007020589 Forwards IE Carcular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/20
- 8007110131 Forwards notice of violation & notice of proposed imposition of rivil penalties arising from IE 800131 ;nsp STELLO,V Office of Inspection & Enforcement, Office of the Director B0/06/20 2pp
- 80701731 1 n n
- --B007110145 Natice of imposition of civil penalties based on item of noncompliance re excessive surface radiation on transport vehicle Office of Inspection & Enforcement, Office of the Director 80/06/20
- 8007140147 Notice of proposed imposition of civil penalties in amount of \$4,000 for item of noncompliance re radiation levels on waste shipments exceeding regulatory limits

 * Office of Inspection & Enforcement, Office of the Director 80/06/20 ip
- 8007170430 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminaralized Water Sys. & Resultant Internal Contamination of Personnel" No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/04/24
- 6007230289 Forwards IE Bulletin 60-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 60-16 also encl No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/06/27
- 8007300574 Forwards Waste Packaging Insp Rept 15000046/80-07 on 800131 Notice of violation forwarded under separate cover KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/27
- -B007300585 Waste Packaging Insp Rept 15000046/B0-07 on B00131
 Noncompliance noted radiation levels on surface of trailer
 in excess of regulatory limits
 B00K.H E Region B. Ban Francisco, Fuel Facility & Materials
 Bafety Branch CAIN.C t. Region 4, Dallas, Office of the
 Director B0/02/27 7pp
- 8007180507 Notifies that time clock of Item 2 of IE Bulletin 80-17, "Failure of Control Rods to Insert During Scram at BHR," will start at 12 OI AM on BOO708 Test should be completed within 20 days Requests notification of malfunction REPPLER.J G Region 3. Chicago, Office of the Director. 80/07/07
- BOO7250641 Responds to IE Bulletin BO-10, "Cantamination of Nonradicattive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found, PEOPLES.D L. Commonwealth Edison Co BO/07/07 2pp
- B007250650 Forwards response to IE Bulletin B0-ii, "Masonry Wall Design " Requested investigation not performed at Dresden, Unit I due to extended outage Requirements will be met prior to startup W/o encl PCOPLES.D I Commonwealth Edison Co 80/07/07 2pp
- 8007230638 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D L Commonwealth Edison Co 80/07/09 7pp
- 8007140630 Responds to IE Bulletim 90-17 re results of tests required by 1tem 1 No significant amount of water in scram discharge vols Vent & drain lines also verified free of obstructions by purforming dynamic air test

 JANECEK, R F Commonwealth Edison Co 80/07/10 2pp
- B007280074 Forwards addl response to IE Bulletin 80-17. Items 2.3.4.5.6a & 6b New procedure has been written to cover actions necessary when central rods fail to fully insert during PEOPLES, D.L. Commonwealth Edison Co BO/07/11 5pp

- 8007310357 Responds to NRC 800620 notice of proposed imposition of civil penalties by forwarding payment
 PEOPLES, D. Commonwealth Edison Co. 80/07/14 1p
- 8007310353 Forwards response to violation hated in IE imsp on 800131 Corrective actions procedure now requires under-trailer check of radwaste shipments & prc survey of articles at shipment origin to assure packages are within dose limits JANECEK, R.F. Commonwealth Edison Co. 80/07/15 3pp
- B007300485 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys," by forwarding "Procedure for Review & Resolution of As-Built Deviations" & "Procedure for Application of Blume Curves Criteria"

 JANECEKAR F. Commonwealth Edison to 80/07/14 lp
- --8007300498 "Engineering Criteria/Procedure for Review & Rusalution of As-Built Devistons," Revision 2 SNYDER,T K EDS Nuclear, Inc. 80/03/07 lipp
- --8007300508 "Engineering Criteria Procedure for Application of Dlume Curves Criteria " SNYDER,T K EDS Nuclear, Inc. 80/03/07 20pp
- R Periodic operating reports & related correspondence
- 8007150619 Forwards monthly operating repts for June 1980 KALIVIANAKIS,N (ommonwealth Edison Co 80/07/01 1p
- --8007150625 Monthly operating repts for June 1980 HAFERA,T Commonwealth Edison Co 80/07/01
- 8 Reportable occurrences, LERs & related correspondence
- 8007080162 Forwards LER 80-015/03L-0 KALIVIANAKIS, N Commonwealth Edison Co 80/06/26 1p
- --B0070B0172 LER B0-015/O3L-0 on B00604, leak found in HPCI steam supply line Caused by thermal cycling during normal operation, weakening small section of fillet weld HPCI sys taken out of syc.weld ground out & welded 8ys returned to syc. XOPAC2, J Commonwealth Edison Co 80/06/26 lp
- 8007240112 Forwards LER 80-014/09L-0 KALIVIANAKIS,N Commonwealth Edison Cu 80/0//15 lp
- ---8007240114 LER 80-014/03L-0 on 800623 during surveillance check on HPC1 emergency oil pump, found oil leak on discharge line Caused by cracked threads on pipe mapple Pipe mapple cut & rethreaded * Commonwealth Edison Co 80/07/22 2pp
- 8007230397 LER 79-021 has been cancelled COLLING.M Commonwealth Edison Co. 80/07/22 1p
- V Operator Examinations
- B007020319 Responds to 800512 ltr requesting extension unt41 Foll 1980 for completion of annual requalification exam due to addition work load Exam date may be delayed until B00930 COLLINS.P F Operator Licensing Branch 60/06/18 lp
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8007300440 Forwards emergency plan, revised draft, Jul 1980 FAY, C. W. Wisconsin Electric Power Co. 80/07/25 ip
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIGENHUT.D G Division of Licensing 80/06/25 89pp
- 8007100241 Notices of appearance in license modeproceeding Cartificate of Bvc encl
 CYR, K D. HOEFLING, R K. Rulemaking & Enforcement Division 80/07/09 Spp

- 800773060/ Preliminary contentions alleging poscibility of steam generator tobe impture during sowere LOCA Contends that continued operation wisignificant tube degradation pases threat to public Certificate of Sic Encl.

 FALKIER Wiscomin 5 Environmental Decade 80/0//15 Spp.
- B007290070 Response in opposition to WI Environ Decade supplemental patition to intervine & contention. Intervet not affected Injury in fact test not met Volid contentions not submitted Hearing as of right must be defined (critiscate of Svi encl CYR.K D. Rulemaking & Enforcement Division. 80/07/25—15pp
- 8007300786 Response to WI Environ Decade Inc 800715 supplemental Filing Hearing is not warranted between intervener failed to state interest & failed to case one contention addressing issues of NRC 791130 order CHARNOTE, G. Wisconsin Electric Power (c. CH Pittman, Potts & Trowbridge 180/07/28 15pp CHARNOFF, G Show,
- --8007300390 Motion to deny WJ Physican Docado Inc 79121/ request for hearing re NRC 791330 order Intervenur not entitled to hearing as matter of right Discretionary hearing unwarranted Certificate of Svc & notice of appearance encl MURRAY, J P. CYR, K. LIEBERMAN, J. Rulemaking & Enforcement Division 80/02/11 18pp
- H General correspondence
- 8007290678 Viges NRC to conduct full probe of facility operation during 800730 prohearing conference Safety assurances should be given to community Local newspapers deficient in detailing SPRING, C.A., SPRING, W. Affiliation Unknown 80/07/14
- B007290631 Requests that facility not be allowed to continue operating w/faulty & defective steam generator tubes Defective & deteriorated tubes should be replaced now Bituation presents potential for another Thi 2 included KRACHT.W El Affiliation Unknown 90/07/Pri ip
- 80073103/3 Opposes util request for amend to mod order on grounds that seriousness of tube degradation problem demands complete review of 90 effective full power day inspiresults by NRC before opposition permitted to resume FALKIK N Wisconsin's Environmental Decade 80.07/26 1p
- P. Operating license stage documents $^{\mathfrak{p}_{\mathfrak{p}}}$ correspondence
- 8007230097 Requests submittal of proposed lech Spec changes providing for redundancy in decay heat commodal capability in all modes of operation Model Fech Specs which would provide acceptable resolution and for guidance EISENHUT, D. G. Division of Licensing 80/06/11 67pp
- \$8007170598 Porwards evaluation of control ros guide thimble wear in facilities designed by Westinghoust Based on review insue is resolved Operating Reactors Branch 's E0/07/0% App
- 8007250001 Requests submittal of application for amend to license consisting of Tach Spec changes & license conditions PMR Model Tech Specs & Model license conditions for INI-P Lessons Learned Category A items entil for guidance EISENHUT, D.O. Division of Licensing 80707702 69pp
- 8007150648 Requests extension of comment period on NUREO-05/7 until 800915, due to other work efforts Requests notification only if extension found unacceptable FAY: C W Wisconsin Electric Power Co 60/07/03 lp
- 800/190602 Gubmits comments on NUREG-0654 Two objectionable items 15-minute time frame proposed to complete public antification & propriety of min shift staffing requirements proposed in Table B-1 Table B-1
 FAY, C W Wisconsin Electric Power Co 80/07/03 App
- 8007210034 Confirms achedule for 800708 meeting at site to discuss recent increase of personnel errors at facilities
 KEPPLER.J G Region 3. Chicago, Office of the Director 80/0//03
- 8007150453 Advises that plant will be taken off-line on 800725 for scheduled outage to renduct hydrosteric tosts to inservice inspiper 70-day offective full power requirement FAY, C.W. Hisconsin Electric Power Co. 60/407/1/

- B007210408 Forwards revised forh Sper 15 3 4 for steam *c power conversion *up & Four 72-h test repts for auxiliary feed pump in response to NRC 800516 request for add1 info re auxiliary Feedwater *up FAYIC W Wisconsin Flectbix Power Co 80/07/08 4pp
- --8007250438 Revised Tech Spec 15 3 4 for steam & power conversion sys * Wisconsin Electric Power Co 80/07/08 3pp
- --B007210492 "Seventy-Two Hour Test of Turbine-Driven Auxiliary Feed Pump " + Hisconsin Flectric Power (n | WMTP 11 21 RO | 79/12/28 | 10pp
- --8007210460 "Seventy-lup Hoor Fest of Turbine-Driven Auxiliary Feed
- Pump "
 # Wisconsin Electric Power Co. UMTP 11 21 RO. 79/12/07 10pp
- --8007210465 'Seventy-Two Hour Test of Electrically-Oriven Auxiliary Feed Pomp '
- Pomp ' • Wisconsin Electric Power to WMTP ii 22 RO 79/12/26 10pp
- ---8007210469 "Seventy-Two Hour Test of Electrically-Driven Auxiliary
 - * Wisconsin Electric Power Co UMTP 11 22 RO 79/12/23 10pp
- 8007240330 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles positions & assignments of personnel Also submits info for GETA NOVAK, T.M. Assistant Director for Operating Reactors 80/07/08
- B0072504B0 Discusses potential welding deficienties in tanks fabricated by Graver Tank & Mfg Co Requests determination whether weldments in safety-related Graver tanks meet design specs & fabrication requirements MOSELEY,N C Division of Reactor Operations Inspections 80/07/08
- G. Inspection reports. IE Dulletins % correspondence
- B007020037 Forwards IE Info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required KEPPLER. J C Region 3. Chilago. Office of the Director 80/05/28 In
- 8007210409 Forwards IE Circular 80-13. "Orld Strop Domage in Westinghouse Fuel Assemblies " No written response required KEPFLER. J G Region 3. Chirago. Office of the Director 80/05/28
- 8007010080 Forwards IE Info Notice 80-23, "Lost of Syction to Emergency Feedwater Pumps" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/05/29 to
- 8007010030 Responds to 1E Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Control of solenoid valve will be modified such that total recirculation of control room air will continue efter reset of contamnent isolation FAY,C W Wisconsin Electric Power Co 80/06/06 2pp
- 8007010062 Responds to 1E Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVC9) Holdup Tanks "
 Mod will be implemented to prevent aperation of holdup tank recirculation pump w/u positive pressure in tank FAY.C W Wiscumsin Electric Power (a 80/06/06 9pp
- 8007160757 Responds to IE Bulletin flo-Op Review conducted of schematic drawings to determine actions resulting from engineered safety feature actuation signal & whether equipment returned to nonemprogency mode upon removal of actuation signal FAY.C N Misconsin Electric Power Co. 80/06/06. 2pp
- 8007010043 Updater #00307 response to [E Bulletin 79-14, "Beismic Analysis for As-Built Safety-Related Piping Bys " Piping analysis completed for 84 of 85 previously tabulated drawlings, as of 800523 Status of review entl FAY.C W Wisconsin Flectric Power Co 80/06/09 5pp
- B007220226 Forwards JE Info Mutice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/10 ip
- 8007160195 Forwards IE Info Notice 80-27. "Degradation of Reactor Conlant Pump Study" No specific action or response required KEPPLER.J O Region J. Chicago, Office of the Director 80/06/11

- 8007030030 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power "Written response required KEPPLER, J.G. Region 3, Chicago, Offsice of the Director 80/06/18 to
- B007020949 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required MEPPLER, J. G. Region G. Chicago, Office of the Director 80/06/20
- 8007170524 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER.J & Region 3, Chicago, Office of the Director 86/06/24
- B007200346 Forwards IE Bulletin B0-16. "Potential Misapplication of Rosemount inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutgut Codes " Written response required IE Circular B0-16 also encl No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/27
- 8007310304 Forwards IE Insp Repts 50-265/80-11 & 50-301/80-11 on 800616-17 No noncompliance noted FIDRELLI, C Region 3, Chicago, Reactor Construction & Engineering Support Deanch 80/06/30 2pp
- --8007310316 IE Insp Repts 50-266/80-11 & 50-301/80-11 on 800616-17 No noncompliance noted Major areas inspected licensee actions re IE Bulletin 79-14
 YIN.I T. BRICKLEY.R H. Region 3, Chicago, Office of the Director DANIELSON.D H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/30 Spp
- B007170526 Responds to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds " All containment welds either have leak chase channel or penetration has closure cap or expansion beliens welded outside containment FAY. G H Wisconsin Electric Pawer Co B0/07/03 Opp
- 8007220071 Submits reply to IE Bulletin 80-10 re contamination of nonradioactive sys & potential for releases Completion of bulletin review not anticipated until 800831 FAY.C W Wisconsin Electric Power Co 80/07/07 2pp
- B007240342 Responds to IE Bulletin B0-15 re power supply to emergency notification sys telephones Charger supplied by telephone company is connected to safeguards Bos 2842 Phones verified operational wiless of ac to charger FAY.6 W Wisconsin Electric Power Co 60/07/08 2pp
- 8007300456 Forwards drawings for revised pump & valve inservice insp & testing program replacing 770520 program Program & drawings available in Central Files only FAV.C W Misconsin Electric Power Co 80/07/25 ip
- A Periodic operating reports & related correspondence
- 8007150610 Forwards monthly operating repts for June 1980 FAY: C W Wisconsin Electric Power Co 80/07/10 ip
- --8007150618 Nonthly operating repts for June 1980 FAY-C W Wisconsin Electric Power Co 80/07/08 App
- S Reportable occurrences. LFRs & related correspondence
- #007010409 Forwards LER 80~007/017-0
 FAY.C W Wisconsin Electric Power Co 80/06/25 1
- ---8007010420 LER 80-007/01T-0 on 800611, blue instrument bus 1Y02 was de-energised, resulting in de-energisation of 3 containment pressure channels Caused by personnel error Power restored & instrumentation returned to normal FAY, C W Hisconsin Electric Power Co 80/06/25 2pp
- 8007110333 Forwards LER 80-008/03L-0 FAY.C W Wisconsin Electric Power Co 80/07/03 ip
- ~-8007110340 LER 80-008/08L-D on 800606.during normal operation, testing revealed that relay 1-247/AN2X in train B would not drop out to initiate undervoltage trip function Cause not determined Relay replaced & tested satisfactorily FAY.C W Misconsin Electric Power Co 80/07/03 2pp

V Operator Examinations

- 8007240085 Responds to 800604 request for info re requirement that operator & senior operator litense applicants spend 3 months on-shift in training Variance to requirement cannot be permitted NOVAK.T M Assistant Director for Operating Reactors BO/07/08
- DOCKET 50-247 FORT SI VRAIN NUCLEAR GENERATING STATION
 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 ltr to all power reactor licensees.in response to 800529 ltr re emergency response facilities at reactor sites Sites w/approval to use closed-circuit television link w/technical support ctr listed CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/07 2pp
- 8007180150 Requests util participation in study re people-related problems in nuclear safeguards Portion of study involves collection of data on licensee security forces & practices NRC to contact security mpt to schedule visit EISENHUT.D © Division of Licensing 80/07/09 lp

9 Adjudicatory correspondence

- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT.D G Division of Licensing 80/06/25 89pp
- J Insurance & indemnity information
- 8007290629 Forwards Endorsement 32 to ANI Policy NF-192 & Endorsement 45 to MAELU Policy NF-69
 QASCHLER, J.A. Public Service Co. of Colorado. 80/07/22 3pp
- P Operating license stage documents & correspondence
- B007020251 Requests invoice for fee for shipping route approval PSC of CO 770882 application
 MILLER.W D License Fee Management Branch 80/06/06 1p
- B007090333 Submits info re thorium purification facility Proposes that processing take place in separate bldg adjacent to facility site & outlines purification process Requests response to 1tr by B00801
 BWART,F E Public Service Co of Colorado 80/07/02 4pp
- B007280493 Forwards GA Co B00620 memo re inside/out oxidation of graphite in relation to reactor Phonomenon will not occur at facility Oxidation was not observed in profiles generated in lab under representative reactor conditions
 BHART.F E Public Service Co of Colorado B0/07/18 3pp
- O Inspection reports, IE Bulletins & correspondence
- 8007020309 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME SA-312. Type 304 Stainless Steel Pipe " Piping specs do not allow use of spamed stainless steel piping in any sys BWART, F.E. Public Service Co. of Colorado 80/04/23 lp
- 8007020272 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/28
- 8007010044 Forwards IE Info Notice 80-23, "Loss of Section to Emergency Feedwater fumps" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director BO/05/29
- B007190083 Forwards JE Insp Rept 50-267/B0-10 on 800501-31 & notice of violation MADBEN.G L Region 4, Dallas. Reactor Construction & Engineering Bupport Branch B0/06/06 2pp
- --B0071800BB Natice of violation from insp on B00501-31 * Region 4. Dallas. Office of the Director B0/06/06 1

- --B007150091 IE lnsp Rept 50-267.80 io on 800501-3 Nencumpliance noted failure to meet fire watch A extinguisher requirements? failure to obtain procedur, change approval WESTERNAN IF A DICKERSON, IW COULTINS, R E. Region 4, Ballas, Office of the Director 80,06706 (2pp
- 8007220126 Forwards IV Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required SEYFRITER V Region 4, Dalla Office of the Director 80/06/10 in
- B007100223 Forwards IF Insp Rept 50-247/80-11 on 800527-28 No noncompliance noted MELLY, J.A.F. Region 1, Dalin Office of the Director 80/06/17 2on
- --B007100225 IF Insp Rept 50-767.80-11 on 800527-78 No noncompliance noted Major areas inspected physical protection of irradiated food in transit Botails withhold (ref 10CFR2 790) CALDMCLL.R A. KELLY.J A.F. Region 4, Dallow. Office of the Director B0706/16 ip
- 8007010231 Ack receipt of 80060? Its informing NRC of steps taken to correct violation, noted in If Insp Rept 50-267/80-08
 MADBEN.G L. Region 4, Dallas, Office of the Director 80/06/20
 to
- --8007010274 Responds to NRC 800506 ltm re violations noted in [E lisp Rept 50-267/RC OB Corrective actions maint of proper diesel generator day tunk level was re-emphasized to all operators [EE.O R Public Service to of Colorado 80/06/02 2pp
- 8007240054 Forwards IE Circular 89-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation (onldown " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/20
- 8007280645 Forwards reactor auxiliarly cooling water tys inservice inso & testing requirements analysis Includes draft Revision 3 to Tech Spec surveyllance requirements for reactor auxiliary cooling water systattachment to rept CF-46-0004 FULLER, F.K. Public Service (o. of Culorado 80/07/16 22pp
- ---B00728()652 "Inservice lnsp & fusting Program Surveillance Requirements Review for Rusctor Auxiliary Cooling Water Sys " * Public Service Co of Columbus EE-46-0004 80/06/24 45pp
- R Periodic operating reports trielated convesiondence
- BOO7010344 Forwards monthly operating lept for May 1980
 WAREMODURG, D. Public Service (c. of Colorado 80/06/23 2pp
- --8007010346 Monthly Operating Rept 77 for May 1980 OAHM J W Public Service to of Colorado 180706792 9pa
- QQQ708D406 Forwards monthly operating rept for June 1980
 WAREMDOURG.D Public Service Co. of Colorado 80/07/Q1 ip
- --8007080409 Monthly operating tept for June 1980 GARM, J W Public Service Co. of Colorado 80/07/01 5pp
- S Reportable occurrences: LLRs & related correspondence
- BO042402B1 PND-1V-BO-12 on BO0311 apparent failure occurred on circulating water cooling tower distribution header Reactor & turbine manually tripped while at 367 power Repair time unknown MESTERMAN, T. F., MADSEN, C. L. Region 4, Dallas, Office of the Director 80/03/11 by
- BOO7080254 Forwards LER BO-028/OUL-O WAREMBOURG, D. Public Service to of Colorado BO/06/17 5pp
- ---B0070B0262 LER 80-028/03L 0 on B005/0 during circulating water sys chierination, total chierine residual exceeded limit Caused by chierinate demand decrease Pollowing steady increase Chierination & blowdown reduced GAMM, JW Public Service Co. of culorado 80/06/19 ip
- 8007080268 Forwards LFR 80-025/03L-0
 WAREHBOURG,D Public Service (p. of Culorado 80/06/19 Sap

- 80070802"5 LER 80-025/03L-U on 800523.during 800523-30, total primary toolant oxidants, were greater than 10 ppm w/average core outlet temp above 1.200 F on 511 occasions Caused by moisture increase & carbon monoxide % dioxide combination GAHM.J W Public Service Co of Colorado 80/06/19 1p
- 07060422 forwards LER 80-026/03L-0 WAREMBOURG,D Public Service Co of Colorado 80/06/19 App

ţ

- 8007080425 IFR 80-026/OUL-O on 800524, during testing, helium circulator seal malfunction pressure differential switch units tripped outside fech Spor limits Caused by dirt accumulation in electrical switches Trip points readjusted OAHM, J W Public Service Co of Colorado 80/06/19 lp
- 97010496 Forwards LER 80-020/03X-1 #AREMBOURG.D Public Service Co of Colorado 80/06/23 5pp
- 007010505 LER 80-020/03X-1 on 80041B during testing two of 12 helium circulator seal malfunction pressure differential switch units tripped outside Fech Sper Limits Caused by dirt accumulation in electrical switch Switch
-)7080210 Forwards LER 60~027/03L=0 MRECIBOURG.D Public Service Co of Colorado 80/07/01 5pp
- 0070B0215 LER 80-027/03L-0 on 808403 to 11, three separate instances of reactor operation took place w/inoperable Class 1 shock suppressors Caused by retated reservoir.low oil level due to cracked fitting & pieton rod seal leak GAHN.J W Public Service Co of Calorado 60/07/01 lp
- 7080289 Forwards LER BO-029/03L-O AREMDOURG.D Public Service Co of Colorado 80/07/01
- 007080304 LER 60-029/03L-0 on 800602.at approx 604 power.reactor bldg pressure could not be maintained subatmospheric Gaused by frozen air line to reactor bldg louver pneumatic actuator due to liquid mitrogen proximity GAHM. J W Public Bervice Co of Colorado 80/07/01 ip due to liquid OAHM, J W Pu
- 7100173 Forwards LER 80-030/03L-0 ARENBOURG,D Public Service Co of Colorado 80/07/02 App
- 107100176 LER DO-030/03L-O on 800604, while performing leakage test, discovered that loop 2 steam generator penetration leakage exceeded allowable limit Cause unknown Temporary relief from allowable limit received from NRC DAHM.J W Public Service Co of Colorado 80/07/02 lp
- '150890 LER 79-063 has been cancelled JLLINS.M Public Service Co of Colorado 80/07/14
- 230543 Forwards LER 80-032/03L-0
 REMBOURG D Public Service Co of Colorado 80/07/15 5pp
- JO/230555 LER 80-023/03L-0 on 800617. W/plant operating at approx 68% thermal power & 193MW.PV-21243 was not controlling at appropriate setpoint Caused by defective Masoneilan PV Bevcot applied to seal ring dasket stopped valve leakage OAHM.J W Public Service Co of Colorado 80/07/15 1p
- 230548 Forwards LER 80-034/07L-0 REMBOURG,D Public Service Co. of Culorado 80/07/15 Spp
- O7230954 FER 80-034/03L-0 on 800519, two helium circulator seal malfunction pressure differential switches tripped outside limits Coused by dirt accumulation in electrical switches Switches Fedjusted Settings to be checked monthly GARM, J W Public Service Co of Colorado 80/07/15 Ip
- 230534 Forwards LER 80-033/03L-0 tCMBDURG,D Public Service Co of Colorado 80/07/18
- O7830539 LER 80-039/03L O on 800620. w/reactor operating at power-reactor despoint exceeded limits Caused by moisture ingress accurring during IA circulator buffer-mid-buffer upset & circulator trip
 OAHM.J W Public Service Co of Colorado 80/07/18 ip

- DOCKET 50-268 MIDWEST FUEL RECOVERY PLANT
- P Operating license stage documents & correspondence
- 8007020417 Forwards LC Rouse 740115 1tr to GE re OL schedule.per 800422 telcon CLARK.TA Advanced Fuel & Spant Fuel Licensing Branch 80/04/23
- --8007020423 Discusses schedule for preoperational testing & licensing OL could be issued 740315 One month is needed to review preoperational test info ROUSE, L.C. Atomic Energy Commission, Directorate of Licensing 74/01/15 ip
- DOCKET 50-249 GCONES NUCLEAR STATION, UNIT 1
- Security, medical, emergency & fire protection plans
- 8007010205 Forwards security plan re in-transit requirements for SNM of low strategic significance Plan withheld (ref lOCFR2 790) PARKER, N D Duke Power Co 80/06/24 lp
- B007230070 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mgt personnel at facilities EISENRUT, D. Q. Division of Licensing B0/07/11 2pp
- G Adjudicatory correspondence
- 8007140461 Statement of Board of Commissioners' position in apposition NOTATION SEASONNESS OF NORMAL OF COMMISSIONERS POSSESS IN to radiaste transportation through Gaston County,NC Urges transportation via Interstates 77 & 85 Encourages expending energy & money for recycling W/correspondence # Gaston County,NC 80/04/28 61pp
- 1074-0473 Forwards adds comments to vactor county board or Commissioners's position opposing spent nuclear fuel shipment through county & two proposed elternate routes Author does not uppose shipment if adequate safeguards are provided GABTON. H B Gaston County. NC 80/04/25 2pp
- --B007J40498 Forwards position of Gaston County Board of Commissioners. NC.opposing spent nuclear fuel shipment through county & two proposed alternate routes W/o encl RHYNE.C A Gaston County.NC B0/04/15 1p
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D O Division of Licensing 80/06/25 89pp Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- BOD6240237 Responds to technical assistance request for proposed Tech Spec Changes for B&W operating plants Forwards requirements for addl info ISRAEL,9 L TMI-2 Bulletins & Orders 79/08/29 13pp
- 8007240208 Forwards B&W litensees' responses to 790907 request for review of schedulo for installing safety-grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115 CAPRAIR A TMI-2 Bulletins & Orders 79/10/24 ip
- 8007140397 Refers to 800701 ltr requesting info re insp of fuel assembly hold-down springs Reviewed concern & documented results in 800606 ltr forwarding RO 50-269/80-15 & safety evaluation No further info required PARKER.W O Duke Power Co 80/06/08 lp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution enc1 for guidance EISENHUT.D 0 Division of Licensing 80/06/11 62pp
- 8007160429 Forwards Amends 83,83 & 80 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availabilisty REID.R W Operating Reactors Branch 4 80/06/12 2pp

- --8007160434 Amends 83.83 & 80 to Licenses DPR-38.DPR-47 % DPR-55, respectively, revising Tech Specs to support operation of Unit 2 at full rated power during Cyrie 5 REID.R W Operating Reactors Branch 4 80/06/12 23pp
- ---B007160445 Safety evaluation supporting Amends B3.83 & 80 to Licenses DPR-3B.DPR-47 & DPR-55.respectively

 * Office of Nuclear Reactor Regulation. Director B0/06/12

1

- --8007160453 Notice of issuance & availability of Amends 83.83 & 80 to Licenses DPR-38,DPR-47 & DPR-55,respectively REID.R W Operating Reactors Granch 4 80/06/12 2pp
- 8007020314 Notifies of NRC conclusion that util did not provide sufficient info to justify 780608 proposed increase in Tech Spec steam generator tube look rate limit Evaluation NOVAK.T Assistant Director for Operating Reactors 80/05/16 3pp
- BOO7010360 Advises that installation of add spent fuel coding train will be completed in Apr 1981 No more than 342 assemblies will be stored in pool until completion of installation or M/o NRC approval
 PARKER, W O Duke Power Co 60/06/24 ip
- BOD7070035 Forwards safety evaluation re postulated fuel handling accident inside containment
 REID.R W Operating Reactors Branch 4 80/06/24 2pp
- --8007070039 Safety evaluation re postulated fuel handling accident inside containment * Operating Reactors Branch 4 80/06/24 1p
- 8007020575 Summarizes actions undertaken by util re inadequate core cooling NRC review of previously submitted operator guidelines should be completed prior to util committing to install new instrumentation PARKER, W D Duke Power Co 80/06/27 2pp
- 8007080223 Advises that response to NUREG-0667 is in final review & will be submitted by 800723 PARRER.W D Duke Power Co 80/07/01 ip
- 8007090271 Forwards safety evaluation & environ appraisal for proposed Tech Boot revision re remacking of spent fuel puot, which will be submitted later Class I & IV amend fees encl PARKER, M D Duke Power Co 60/07/01 3pp
- --8007090274 "Units 1 & 2 Spent Fuel Pool Poison Relack Licensing Submittal " Duke Power Co 60/07/31 51pp
- BOO7210004 Forwards questions re fuel assembly holddown spring insps & safety significance of operating w/broken springs in core Requests response within 60 days

 NDVAK.T M Assistant Director for Operating Reactors BO/07/01
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A Items encl for guidance EISENHUT, D & Division of Licensing 80/07/02 69pp
- 8007180104 Notifies that 800317 request for route approval to cover spent fuel shipments to B&W Lynchburg Research Ctr is subj to license fee Review of request was completed on 800414 MILLER.W O License Fee Management Branch 80/07/03 ip
- BOO7230052 Responds to util BOO317 request for route approval covering shipments of spent fuel to B&W Lynchburg Research Ctr Review of licensee route approval requests subj to license fee schedule in 10CFR170 MILLER,W O License Fee Management Branch 80/07/03 tp
- 8007110294 Forwards application to amend Tech Specs to incorporate test frequency requirements of 10CFR30.App J PARKER, W O Duke Power Co 80/07/07 2pp
- --8007110331 Application to amend Tuch Spec 4 4 1 2 5 incorporating test frequency requirements of 1007850.App J Existing Tech Spec unacceptable for extended cycle lengths for which current & future cycles are/will be licensed # Duke Power Co 80/07/07 2pp

- B007230708 Provides infolio new off titles positions it assignments of personnel resulting from 8004/8 reorganization of life of Nuclear Reactor Regulation NUVAR-T M Assistant Director for Operating Reactors 80/07/10 2pp
- 8007150975 Forwards "Generic Startup Physics Test Program, Jul 1980 " Rept superseded in cutirety (upt- submitted 800604 v 11 PARKER, W.D. Duke Power Co. 80/07/11 lp
- ---B0071505B3 "Generic Startup Physics lest Program, Jul 1980" Rept supersedes in entirety previously submitted repts forwarded by 800604-11 ltms * Duke Power Co B0797741 14pp
- 8007220477 Forwards "Unit 1. Lycle & Startup Testing Summary " PARKER, W (I) Doke Power Co 80/0//11 1p
- --8007220483 "Unit 1.Cycle & Startup lesting Summary "
 * Duke Power Co 80/07 31 13pp
- 8007280437 Forwards proposed leassing to Jech Specs & amend to OL Proposal clarifies insp requirements after primary to secondary leak specified in Erch Spec 4 17 4 Requests that NRC review & approve proposal in timely manner PARKER, N.O. Duke Power Co. HO/07/15 3pp
- --8007280438 Proposed Tech Spec revision Page 4 17-3, clarifying insprequirements after primary to secondary leak

 * Duke Power Co #8/07/15, 2pp
- 8007310551 Forwards NUREC-1368 & NUREC 1769 detailing development of checklist for evaluating maint test & calibr procedures used in nuclear plants Ack objection on study Wo EMIS.R C Region 2. Atlanta, Reactor Op+rations Nuclear Support Dranch BO/07/15 ip
- 8007280944 Forwards response to recommendations in NUREG-0667. "Transtent Response of BMW Designed Reactors" Based on review no action is necessary for majority of recommendations
 PARKER, W G Duke Power Co 80/07/23 70pp
- B007310379 Application to amend licenses DPR-3B & DPR-47, changing Tech Specs to reflect assumptions used in util B00701 itr re spent fuel pool expension PARKER, W O Duke Power Co B0/07/25 3pp
- ---B007310381 Proposed Tech Specs 3 B 13 a,3 8 15 & 5 4 2 l to permit expansion of spent fuel pool storage capacity by roracking spent fuel pool w/poison racks * Duke Power Cn BD/07/25 App
- --8007310382 Revised pages to "Units 1 % 2 Spent Fuel Pool Poison Rerack Licensing Submittal" * Duke Power Co 80/0//25 Spp
- O Inspection reports, 1E Bulletins & correspondence
- 8007240122 Forwards IE Info Notice 80-20. "Loss of Dreay Heat Removal Capability at Davis-Bosse Unit I White in Refueling Mode" No response required O'REILLY, J.P. Region 2. Atlanta, Defice of the Director 80/05/08 2pn
- B007100144 Forwards IE lusp Repts 50-269/80-14.50-2/0/80-09 & 50-287/80-09 on 400428-0501 Na noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/27 2pp
- --8007100151 IE Insp Repts 50-269/80-14,10-770/80-09 % 50-287/80-09 on 800428-0501 Nu noncompliance noted Major areas inspected fire protection/prevention CONLOW T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch MillER.W H Region 2. Atlanta. Office of the Director BO/08/23 10pp
- 8007020204 Forwards IE Info Notice 80-22 "Broaddowns In Contamination Control Programs" No written response required O'REILLY, J.P. Region 2. Atlanta, Uffice of the Director 80/05/28
- B007210449 Forwards IE Circular 80 13. "Arid Strap Damage in Westinghouse Fuel Assemblies" Ne written response required O'REILLY, J.P. Region 2. Atlanta, Defice of the Director B0/05/28

- B007010213 forwards IE Info Notice 80-23. Loss of Suction to Emergency Feedwater Pumps: 'No written response required D'REILLY J.F. Region 2. Atlanta, Office of the Director B0/09/29
- 8007220048 Forwards IE Info Notice 80-26, 'Evaluation of Contractor OA Programs ' No written response required G'REILLY. J. P. Region 2, Atlanta, Office of the Director 80/06/10
- B007010065 Forwards update of info to 791026.1106.1207 & 800124 ltrs in response to 1E Bulletin 79-14.1tems 2 % 3 PARKER.H D Duke Power Cd 80/06/11 Spp
- 3007160255 Forwards IF Info Notice 80-27, "Degradation of Reactor Coolant Pump Study " No specific action of response
- O'REILLY, J.P. Region 2. Atlanta Office of the Director 80/06/11
- 1007020763 Forwards II Bulletin BD-15. 'Possible Loss of Emergency Notification Sys (ENS) W/Lous of Offsite Power " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/06/18
- 1007020459 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural virculation Cooldown " No written response
- O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/20
- 007150015 AER receipt of EE Insp Repts 50-269/80-18.50-270/80-13 & 50-287/80-12 on 800513-15 No proprietary info PARKER.W O Duke Power Co 86/06/23 ip
- -8007150019 Forwards IE Insp Repts 50-249/80-18.50-270/80-13 & 50-287/80-12 on 600913-19 No noncompliance noted MURPHY, C.E. Region 2, Atlanta, Reactor Constitution & Engineering Support Granch 60/05/29 2pp
- 8007150021 IE insp Repts 30-269/80-18,50-270/80-13 & 50-287/80-12 on 800513-13 No noncompliance noted Major areas inspected structural concrete for etandby shutdown facility HARRIS, J.R. Region 2, Atlanta, Office of the Director CONLON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/20 3pp
- 207170104 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sus & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J. P. Region 2, Arlanta, Office of the Director 80/06/24
- 107180533 Responds to JE Dulletin 79-03A, "Longitudinal Weld Defects in ASME 8A-312, Type 304 Stainless Steel Pipe " No Type 300 piping in use for pressure piping Future use of piping will PARKER, H C Duke Power Co 80/06/24 1p
- 07220192 Advises that hanger inspirequired by IE Bulletin 79-13 was not addressed in response to bulletin Hangers visually inspected as part of response to IC Bulletins 79-02 &
- PARKER, W.O. Duke Power Co. 80/06/27 1p
- 07230.33 forwards IE Bulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Written response required IE Circular 80-16 also norl No written response required 1*REILLY, J P Region 2, Atlanta, Office of the Director 80/06/2 BO/06/27
- 07280068 Confirms receipt of NRC 800617 itr transmitting IE Insp Rept 50-269/H0-22 Concors w/NRC decision that info contained in *ept is sucurrity**elated & whould not be placed in PDR PARKER, W.O. Duke Power Co. 80/Q6/30
- 07220245 Forwards response to 1ff Bulletin 60-08 Approx 53 senetrations concerned Weld defects classified as inclusion the repaired for tracking Design meets all requirements of ARKER, H D Dute Power Co 80/07/01 4pp
- 17140463 Forwards 800/04 Revision 2 to response to IE Bulletin '9-01B. "Environ Qualification of Class IE Equipment " eplaces previous submittal & 800519 revision entirely notices corrections of minor ortars HIES, A C Duke Power Co 80/07/07 36pp

- 8007250166 Forwards response to Items 1. 2 t 3 of IE Bulletin 80-11, "Masonry Wall Design " Lists all masonry walls which are in proximity to or have attachments from safety-related piping or equipment PARKER. W G Duke Power Co 80/07/07 21pp
- S. Reportable occurrences, LERs & related correspondence
- 8007070319 Forwards LER 80-018/03L-0 PARKER, W O Duke Power Co 80/06/30 3pp
- --8007070323 LER BO-018/03L-0 on 800601.high pressure svc water pump B declared inoperable due to motor cooler tube leaks Caused by erosion & corrosion essiting from constant flow of lake water Leaking tubes soldered & cooler pressurized PHILPOTT,FT Duke Power Co. B0/06/30 1p
- 8007110360 Forwards LER 80-020/01T-0 PARKER.W 0 Duke Power Cn 80/07/03 3pp
- --8007:10362 LER 80-020/017-0 on 800619.at 74% power.backup 125-volt de power to instrumentation & control power sys removed from syc to investigate ground alarm isolating transfer diades not reconnected within Tech Spec 24-h limit PHILPOIT, FT Duke Power Co 80/07/03 ip
- 8007210417 Forwards LER 80~021/03L-0 PARKER, W D Duke Power Co 80/07/11 4pp
- --B007210A21 LER B0-021/03L-0 on B00612.8 high pressure injection makeup liner found excessively hot Apparently caused by iHP-152 check valve not seating properly, allowing water to flow into tB1 cold leg
 PHILPOTT, F T Duke Power Cp 80/07/11 1p
- 8007210459 Forwards LER 80-017/03L-0 PARKER, W D Duke Power Co 80/07. 80/07/11 3pp
- --8007210470 LER 80-017/03L-0 on 800529.at 73% full power.CBAST pump was 10/21/04/0 Let BG-01/03(-0 an Sous), at 73% for 1 power upon removed from svc for preventive maint constituting operation in degraded mode Procedure was in violation of Tech Specs Tech Specs or procedure changes under evaluation PHILPDIT, FT Owke Power Co 80/07/11 ip
- 8007230239 Part 21 rept re cracked steam generator manway studs Batisfactory operating experience forms constitute reasonable basis for continued operation while investigations proceed
 TAYLOR, J H Babcock & Wilcox Co 80/07/11 5pp
- 8007220563 RO on G00709, high pH excursion in oil collection basin discharge was discovered Caused by water discharged from upper sump of safe shutdown facility const Const personnel advised of discharge limits PARKER, W O Duke Power Co 80/07/16 2pp
- 8007220424 Forwards LER 80-019/03L-0 PARKER, W 0 Duke Power Co 80/07 80/07/17 1p
- ---B007220427 LER 80--019/03L-0 on 800618, concentrated boric acid storage tank pump found inoperable according to Tech Spec requirement Caused by failed vacuum compensator within valve pump Valve diaphragm & motor replaced PHILPOTT,F (**Duke Power Co**) 80/07/17 2pp
- DUCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8007010205 Forwards security plan re in-transit requirements for SNM of low strategic significance Plan withheld (ref 10CFR2 790) PARKER.W O Duke Power Co 80/06/24 ip
- 8007230090 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security may personnel at facilities EISENHUT.D G Division of Licensing 80/07/11 2pp
- Adjudicatory correspondence
- 8007140461 Statement of Board of Commissioners' position in opposition to radwaste transportation through Gaston County.NC Urges transportation via Interstates 77 & 65 Encourages expending energy & money for recycling Mycorrespondence # Gaston County.NC 80/04/28 6ipp

- --8007140473 Forwards addit comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GASTON, H B Gaston County NC 80/04/25 2pp
- ---8007140488 Furwards position of Gaston County Board of Commissioners. NC opposing spont nuclea: fuel shipment through county % two proposed alternate routes W/o encl RHYNE, C A Gaston County, NC 80/04/15 ip
- 8007310243 Forwards Commission 800597 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re-fire protection for electrical cables
 EISENHUT, D C Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- 8007240208 Forwards B&W licensees' responses to 790907 request for review of schedule for installing safety-grade enticipatory reactor trip for loss of feedwater 7 turbine trip Review should be completed by 791315
 CAPRA.R A TMI-2 Bulletins & Orders 79/10/24 ip
- BOO7140397 Refers to BOO701 ltr requesting info re insp of fuel assembly hold-down springs Reviewed concern & documented results in BOO606 ltr forwarding RO 50-269/BO-15 & safety evaluation No further info required PARKER.W O Duke Power Co BO/06/08 ip
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D G Division of licensing 80/06/11 62pp
- 8007160429 Forwards Amends B3.83 & B0 to Licenses DPR-3B,DPR-47 & DPR-55,respectively, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 80/06/12 2pp
- --8007160434 Amends B3.83 & 80 to Licenses DPR-38.DPR-47 & DPR-95. respectively revising Tech Specs to support operation of Unit 2 at full rated power during Cycle 5 REID.R W Operating Reactors Dranch 4 80/06/12 23pp
- --8007160449 Bafety evaluation supporting Amends 83.83 & 80 to Licenses DPR-38, DPR-47 & DPR-55, respectively

 * Office of Nuclear Reactor Regulation, Director 89/06/12
- B007010340 Advises that installation of addl spent fuel coding train will be completed in Apr 1981 No more than 342 assemblies will be stored in pool until completion of installation or w/o NRC approval PARKER, W G Duke Power Co 80/06/24 1p
- B007070035 Forwards safety evaluation re postulated fuel handling accident inside containment REID.R W Operating Reactors Branch 4 80/06/24 2pp
- --8007070039 Bafety evaluation re postulated fuel handling accident inside containment * Operating Reactors Branch 4 80/06/24 1p
- 8007020575 Summarizes actions undertaken by util re inadequate core cooling NRC review of previously submitted operator guidelines should be completed prior to util committing to install new instrumentation
 PARKER,W O Duke Power Co 80706/27 2pp
- 8007080223 Advises that response to NUREG-0667 is in final review & will be submitted by 800723 PARKER.W () Duke Power Co 80/07/01 ip
- 8007070271 Forwards safety evaluation & environ appraisal for proposed Tech Spec revision re renacking of spent fuel pool, which will be submitted later Class I & IV amend fees encl PARKER.W O Duke Power Go BO/07/01 3pp
- ---B007090276 "Units 1 & 2 Spent Fuel Poel Poison Rerack Licensing Submittal " * Duke Power Co B0/07/31 Sipp

- 8007210004 Forwards questions refuct assembly holddown spring insps to safety significance of operating w/broken springs in core Requests response within 60 days.
 NOVAK, T.M. Assistant Director for Operating Reactors. 80/07/01.4pp
- 8007250001 Requests -ubmittal of application for amend to license consisting of Tech Spec changes "License conditions PWR Model Tech Specs t Model License conditions for TM1-P Lessons Learned Category A litense end for guidance EISENHUT, D.G. Division of Licensing 80/07/02 69pp
- B007170647 Forwards Reactor bys Branch evaluation of facility Fuel load for Cycle 5 operation & associated fuch Spics Review considered effects of normal operation, anticipated transients & postulated accidents 4/2 encl
 SPEIS.T.P. Reactor Systems Branch 20/07/03 ip
- ~-800/170656 Forward: Reactor Sufety Branch evaluation of facility fuel load for Cycle 5 operation & associated fech Specs Util has not submitted acceptable startup text program as of BOOGOO U/o encl
 CHECK-P 5 Assistant Director for Plant Systems 80/06/30 1p
- 8007110294 Forwards application to amend Tech Specs to incorporate test frequency requirements of 100FR90 App J PARKER, W Cl. Duke Power Co. #10/07/67 2pp
- --8007110331 Application to amend Tech Spec 4 4 1 2 5 incorporating test frequency requirements of 1004820. App J Existing Tech Spec unacceptable for extended cycle lengths for which current & future cycles accumulate licensed * Duke Power Co. 80/07/07 Ppp
- 8007230708 Provides into re new ofr titles, positions & assignments of personnel tesulting from GOUAPA Forganization of Ofc of Nuclear Reactor Regulation
 NDVAK.T M Assistant Director for Operating Reactors 60/07/10
- B007150575 Forwards "Generic Startup Physics Test Pingram, Jul 1980 " Rept supersedes in entirety repts submitted 800604 % 11 PARKER, W.O. Duke Power Co. 80707/11 1p
- --800/150583 "Generic Startup Physics lest Program, Jul 1980 " Rept supersodes in entircty previously submitted ropts forwarded by 800604-ti ltrs & Duke Power Co 80/07/3t 14pp
- B007280437 Forwards proposed revision to Tech Specs & amend to CL Proposal clarifies inspirequirements after primary to secondary leak specified in Teth Spec 4 17 4 Requests that NRC review & approve proposal in timely manner PARKER.W O Duke Power Co (80/07/15 Spp
- --B007280438 Proposed Tech Spot revision Page 4 1/-3 clarifying inspraguirements after primary to secondary look

 * Duke Power Cn B0/07/15 2pp
- 8007310851 Forwards NUREG-1368 & NUREG-1769 detailing development of checklist for evaluating maint test & calibr procedures used in nuclear plants Ack will couperation in study W/o encis
 LEMIS,R C Region P. Atlanta Reactor Operations Nuclear Support Branch 80/07/15 to
- 8007210425 Application for amend to DI revising (ech Spec 3 3 i c allowing continued operation of Unit 2 at full lated power, while maint continues on tOI pump until 800718 PARKER.W O Duko Power Co 80/07/16 App
- ~~9007210426 Proposed revision to Tech Spec 3.3.1 callowing continued operation of Mint 2 of Full rated power while maint continues on HPl pump until 80078.

 * Duke Power to 80/07/16 ip
- B007220561 Advases of orner in lisponsis for Site Specific Question I Parts B & C. submitted in B00al6 itruin response to questions re low turbine dist cracking (orsect responses encl PARMER N O Duke Power Co 90/07/17 2pp
- B007280119 Confirms 800716 toleum to temporarily amend Tech Spec 3 3 1 (62)(b) by adding HPT Pump Riper 800716 request Amend package including safety evaluation to notice will be forwarded shortly ROVAKIT M. Assistant Director for Operating Reactors 80/07/17

- 800728042/ Forwards proposed lech Spec 3 1 2 revision, changing pressure temp limits Class 1 * III license amend fee encl PARKER, W O Duke Power Co 80,07/P2 3pp
- 8007280544 Forwards response to recommendations in NUREC-0667, "Transient Response of B&W Designed Reacturs" Based on reviewing action is necessary for majority of eviewino attion ecommendations ARKER,N B. Duke Power (o. 80/07/23 70pp
- 8007310379 Application to amend Licenses DPR-38 to DPR-47, changing Tech Specs to reflect assumptions used in util 800701 ltm re spont fuel pool expansion PARKER.W O Duke Power Co 80/07/25 3pp
- --800731038: Proposed Tech Specs 3 8 13 a 3 8 15 to 5 4 2 1 to permit expansion of spent fuel pool storage capacity by reracking spent fuel pool u/poison racks
 - Duke Power Co 80/07/25 App
- --B007310392 Revised pages to "Units I & 2 Spont Fuel Pool Poison Rerack Licensing Submittal" * Duke Power (a B0/07/25 Spp
- Q Inspection reports, IE Bulletins & correspondence
- 8007240122 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit I While in Refueling Mode" No response required D'REILLY.J.F. Region 2. Atlanta. Office of the Director 80/05/08
- B007100144 Forwards IE Insp Repts 50-249/80-14 '2-270/80-09 & 50-287/80-09 on B00428-0501 No noncompliance noted MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/05/27 2pp
- --8007100151 IE Insp Repts 50-269/80-14.50-270/80-09 & 50-287/80-09 on 800428-0501 No noncompliance noted Major as: as inspected fire protection/prevention CONLOWING E Region 2, Atlanta, Reactor Construction & Engineering Support Branch MILLER, H H Region 2, Atlanta, Office of the Director 80/05/23 10pp
- B007020204 Forwards IE Info Notice 80-22. "Brenkdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/28
- 8007210449 Forwards IE Circular BO-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director E . 80/05/28
- 8007010213 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps." No writton response require: O'REILLY.J P. Region 2. Atlanta. Office of the Director. 80/05/29
- 8007220048 Forwards 1E Info Natice 80-26. "Evaluation of Contractor QA Programs " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/10
- 8007010065 Forwards update of info to 771026, 1106, 1207 & 800124 ltrs in response to IE Bullotin 79-14, Itoms 2 % 3
 PARKER W O Duke Power to 80/06/11 App
- 8007160255 Forwards IC Info Notice 80-27, "Degradation of Reactor Coplant Pump Stude" No specific action or response O'REILLY, J.P. Region P. Atlanta, Office of the Director BO/06/11
- 8007020763 Forwards IE Bulletin 80-15, "Mossible Loss of Emergency Notification bys (ENS) W/Loss of Offsite Power "Written response required O'REJLLY, J. P. Region 2, Atlanta, Office of the Director GD/06 Region 2, Atlanta, Office of the Director 60/05/18
- 3007100139 Responds to IE Butletin 79 13. "Crarking in Feedwater Sys Piping "Radiographic examinations required by Item 2 completed & undiceptable indications found not associated w/concern of bulletin Indications under review PARMER.W O Duke Pawer Co 80/06/19 Spp

- 6007180349 Responds to Item 2 in IE Dulletin 79-13 All weld joints considered acceptable for continued svc Util intends to restart Unit 2 Considers that NRC concurs w/position & that no further insps are expected PARKER. U. G. Duke Power Co. " | B0/06/19 | 3pg
- 8007020459 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007150015 Ack receipt of 1E Insp Repts 50-269/80-18,50-270/80-13 & 50-289/80-12 on 800513-15 No proprietary info PARKER, W D Duke Power Co 80/06/23 ip
- ~-B007150019 Forwards IE Insp Repts 50-269/80-18.50-270/80~13 & 50-287/80-12 on 800513-15 No noncompliance noted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch B0/05/29 2pp
- --8007150021 IE Insp Repts 50-269/80-18,50-270/80-13 & 50-287/80-12 on 800513-15 No noncompliance noted Major areas inspected structural concrete for standby shutdown facility HARRIS, J.R. Region 2, Atlanta, Office of the Director CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/28 3pp
- B007170104 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineratized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Dffice of the Director 80/06/24
- 8007180533 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 8A-312. Type 304 Stainless Steel Pipe" No Type 300 piping in use for pressure piping Future use of piping will be reviewed PARKER, W.O. Duke Power Co. 80/06/24 ip
- 8007220192 Advises that hanger inspirequired by IE Bulletin 79-13 was not addressed in response to bulletin Hangers visually inspected as part of response to IE Bulletins 79-02 & 79-14 PARKER, W D Duke Power Co 80/06/27
- 8007230235 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes "Written response required IE Circular 80-16 also enci No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/ 80704727
- 8007220245 Forwards response to IE Bulletin 80-08 Approx 53 penetrations concerned Weld defects classified as inclusion One repaired for cracking Design meets all requirements of ASME PARKER, W O Duke Power Co 80/07/01 4pp
- B007140463 Forwards 800704 Revision 2 to response to IE Bulletin 79-018, "Environ Qualification of Class IE Equipment" Replaces previous submittal & B00519 revision entirely Includes corrections of minor errors THIES.A C Duke Power Co 80/07/07 34pp
- 8007250166 Forwards response to Items 1.2a & 3 of IE Gulletin 80-11. "Masonry Wall Design " Lists all masonry walls which are in proximity to or have attachments from safety-related piping or equipment
 PARKER, W G Duke Power Co B0/07/07 21pp
- 8007280416 Ack receipt of IE lnsp Rept 50-270/80-16 Rept does not contain proprietary info PARKER. H O Duke Power Co 80/07/09 ip
- --8007280418 Forwards IE Insp Rept 50-270/80-16 on 800428-30 & notice of violation LEWIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/30 App
- ~-8007280421 Notice of violation from insp on 800428-30 * Region 2. Atlanta, Office of the Director 80/0 80/06/27 In
- --B0072B0425 IE Insp Rept 50-270/80-16 on B0042B-30 Noncompliance noted failure to uniap vent & diain lines & to provide adequate records re sys draining procedures HHITENER, H L., MOON, B T Region 2, Atlanta, Office of the Director UPRICHT, C M Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/06/27 Spp

- B007290267 Forwards further response to IE Builetin 79-13. "Cracking in Feedwater Sys Piping " H Thielsch B00531 final rept. "Exam of Radiographic Films & Wold Integrity of Pipe Butt Welds in 3-Inch OD by 0 300-Inch Ausiliary Feedwater Piping." encl PARKER.W O Duke Power Co 80/07/10 50pp
- 8007310491 Ack receipt of IE Insp Rept 50-270/80-19 on 800617-18 No proprietary info PARKEN, NO Duke Power Cn 80/07/16 ip
- ~~8007310495 Forwards IE Insp Rept 50-270/80-19 on 800617-18 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/02 2pp
- --8007310501 IE Insp Rept 50-270/80-19 on 800617-18 No noncompliance noted Major areas inspected feedwater sys piping as outlined in IE Bulletin 79-13 CROWLEY,B R Region 2, Atlanta, Dffice of the Director HERDT,A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/01 4pp
- S Reportable occurrences, LEAs & related correspondence
- 8007070319 Forwards LER 80-018/03L-0 PARKER, W O Duke Power Cn 80/06/30 3pp
- --8007070323 LER BO-018/03L-O on 800601.high pressure svc water pump D declared inoperable due to motor confer tobe leaks Caused by erosion & corrosion resulting from constant flow of lake water Leaking tubes soldered & cooler pressurized PHILPOTT.F T Duke Pawer Co 80/06/30 ip
- 8007080201 Forwards LER 80-005/01T-0 PARKER, W D Duke Power Co 80/07/02 2pp
- --8007080207 LER 80-009/017-0 on 800617 during RCS heatup, inconsistent boron concentration measurements obtained Caused by poor mixing in core flood tank Unit cooled down & boric acid added Methods under evaluation re maintaining concentration PHILPOTT,F T Duke Power Co 80/07/02 1p
- --8007180326 LER 80-007/01T-0 on 800626. w/unit at 48% newer, humidity in penetration room found to be above 70% Caused by steam leak on feedwator valve Humidity reduced to 50% & sys declared operable within 3 5-h PHILPOTT, FT Duke Power Co 80/07/10 1p
- 8007220563 RO on 800709, high pH excursion in oil collection basin discharge was discovered Caused by water discharged from upper sump of safe shutdown facility const Const personnel advised of discharge limits PARKER, W O Duke Power Co 80/07/16 2pp
- 8007270824 Forwards LER 80-006/03L-0 PARKER, W O Duke Power Co 80/07/25 2pp
- --B007290B30 LER B0-006/03L-0 on BD0625, at 407 full power, valve 2LP21 failed to open electrically on command Caused by loose setscrew on motor driven pinion Ecrow repaired JONES, J. L. Duke Power Co. B0/06/26 pp.
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

 F Security, medical, emergency & fire protection plans
- 8007070247 Advises that revised draft emorgency plan in response to NUREO-0.654 Will be submitted by 800725 Requests clarification of NRC schedule for emergency plan concurrence
 BMITH.R L Vermont Yankee Nuclear Power Corp 80/07/01 ip
- 8007210049 Requests mod of provision for adequate shutdown capability to meet encl fire protection sofety evaluation criteria Status summary of open issues & evaluation of safe shutdown capability following fire in three plant areas encl IPPOLITO.T A Operating Reactors Branch 2 80/07/03 15pp
- 8007280661 Forwards final revised emergency plan which addresses comments described in encl to DL Ziemann 800414 ltr to JA Kay & RL Smith Emergency plan available in Central Files only BMITH.R L Vermont Yankee Nuclear Power Corp 80/07/25 1p

- 9 Adjudicatory correspondence
- 8007020432 Forwards Director r decision under 105FRC 206 denying 800429 request for revocation of BL * institution of hearings on plant decommissioning DENTON.H R Office of Nuclear Reactor Regulation, Director 80706711 1p
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refere protection for electrical cubbes
- 8007020627 Order granting extension until 800719 for Commission to elect whether to review Director's 800611 denial under 100782 206 CHILK.B J Office of the Secretary of the Commission 80/06/27 in
- H General correspondence
- 8007020117 Responds to 800428 ltr encouraging NRC to meet w/VT Yankee Decommissioning Alliance (VVDA) NRC met w/VVDA on 800429 & received petitions requesting immediate plant shotdown DIRCKER W J Office of the Executive Director for Operations 80/06/18 | Ip
- 8007020451 Advises that NRC knows of no plans or proposals by util to change type or quantities of releasor from facility into CT River Releasor remain within limits Mods required on lang-term basis to increase safely in LOCA NOVANITM Assistant Director for Operating Reactors 80/06/18 200
- --8007020455 Requests that NRC demand util hold public hearing re possibility of util dumping more wastes into CT River COX.S Affiliation Unknown 80/04/10 Spp
- 8007;10082 Responds to 800419 ltm referred to NRC by Senator E Kennedy re environ & water safety in CT River Valley Forwards supporting info Radiological releases are within acceptable limits Any abnormal releases should be reported W/o encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/25 App
- --BOO7110093 Forwards 1) Kont BOO419 Itr to requesting info on unviron a water safety re util usage of CT River for radiological releases Requests response KENNEDY.E M. Benato. BO/04/24 2pp
- B007210448 Requests address change for NRC correspondence of License DPR-28 from JM Abbey in Rutland, VT to MF Conway in Vernon, VT SMITH, R L Vernont Yankee Nuclear Power Corp 80/07/16 lp
- B007300394 Advises that time period for consideration of Director's decision to deny request for liconse revocation & public hearings for famility has elapsed w/o Commission taking any review action Therefore decision is final NRC action CHILK.S J. Office of the Secretary of the Commission. 80/07/24
- 1 Financial infermation
- 8007010397 Forwards cash flow info by calendar quarters for company & cash info for sponsor companies for CYBO CAREY.W W. Vermont Yankee Nuclear Power Corp. 80/06/24 4pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark | owners group in Dethesda. MD.re revisions to NRC acceptance criteria & outstanding issues relative to Nark | containment long-term program GRIMES, C.T. Plant Systems Branch 80/02/21 Sipp
- 8007160777 Confirms 800687 agt meeting to be hold at facility re regulatory performance of facility Agonda encl GRIER, B. H. Region I. Philadelphia, Office of the Director 80706/11 App

- 80070/0346 Responds to NRC 800507 ltr.ltpm ll K 3 46.re TMI-2 related requirements & adequacy of GE 800221 ltr GE ltr is adequate & applicable to facility SMIFILR L Vermont Yankee Nuclear Power Corp 80/06/30 ip
- 8007140525 Summary of B006P4 meeting w/util in Bethesda.MD we possible proposal of radwaste incinerator Process info bulletin encl ROUNEY.V L Operating Reactors Branch 2 80/07/02 9pp
- 8007140338 Forwards YOBAP-I-A, Revision 8, per NRC 800702 request Also forwards document change instructions for removing & inserting correct pages HEIDER/L M Yankee Atomic Fluitiic Co 80/07/09 2pp
- --8007140342 Advises that Y80AP-I-A, Revision 8.1s acceptable Programmatic changes should be submitted to NRC for review prior to implementation Requests that itr replace 800430 ltr & rept be renumbered w/revision & submitted to NRC HAASS.W P Quality Assurance Branch 80/07/02 1p
- BOO7250488 Comments on NURES-0619, "DWR headwater Morrie & Control Rod Drive Return I into Norrie Cracking " Disagrees w/position re interference fit sparpers No cracking of norrie regions experienced Date of Doc 1985 recommended for sparger mod SMITH.R.L. Vermont Yankes Nuclear Power Corp. 80/07/18 is
- 8007280439 Submits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURGH & Yankee Atomic Electric Co 80/07/24 7pp
- 8007310365 Outlines proposed schedule for torus mods.per 800625 telcon Last two items listed will be implemented only if further analysis & testing shows need Mods would not be completed until fall 1981 refueling outage BMITH:R L Vermont Vankee Nuclear Power Corp 80/07/25 2pp
- Q Inspection reports. IE Builetins & correspondence
- 8007090370 Forwards IC Insp Rept 50-271/80-03 on H00P21 One item of noncompliance noted ORIER, B H Region i, Philadelphia, Office of the Birector B0/03/09 2pp
- ---8007070373 IE Insp Rept 50-271/80-03 on 600221 Noncompliance noted failure to package low specific activity waste package so that radiation levels from surface of package were within given limits
 KINNY, W W , RAYMOND, W J Region 1, Philadelphia, Office of the Director (ROCNER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/24 29pp
- 8007140433 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers" Written response required CRIER.B # Region 1, Philadelphia, Office of the Director 80/05/12 tp
- 8007230695 Responds to notice of violation & notice of proposed imposition of civil penalties, transmitted by NHC 800507 ltr
 Util administrative procedure for radwaste shipments revised to require instrument surveys Penalty payment encl
 CONWAY, W F Vermont Yankes Nuclear Power Corp 80/05/27 2pp
- 8007020125 Forwards IE info Notice 80-22. "Breakdowns in Contemination Control Programs " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/05/28 ip
- 8006260362 Ack recript of 800429 ltr informing NRC of steps taken to correct violation noted in IF insp Rept S0-271/79-14 SMITH, G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/29 ip
- 8007010286 Forwards IC Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/05/29 1p
- R007210623 Forwards IE Info Notice 80 26, "Evaluation of Contractor OA Programs " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/10 1p
- 8007140275 Forwards IE Bulletin 80-14. "Degradation of BWR Stram Discharge Vol Capability " Mritton response required GRIER, B Region 1. Philadelphia. Office of the Director 80/06/12 1p

- 8007170325 Forwards response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " All sefety-related equipment remains in emergency mode upon reset of ESF actuation signal w/listed exceptions
 TRIBBLE.J E Vermont Yankee Nuclear Power Corp 80/06/13 2pp
- 8007020704 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required Office, 0 H Region i, Philadelphia, Office of the Director B0/06/18 1p
- 8007020528 Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/06/20 1p
- 8007180549 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies " Facility does not use actuators CDNHAY.W F Vermont Yankee Nuclear Power Corp 80/06/20 1p
- B0071B0594 Responds to IE Bulletin B0-10 Measures described to prevent uncontrolled releases or contamination of nonradioactive sys Administrative controls, hardware mods & process radiation monitors added Sampling program expanded CONWAY, W F Vermont Yankee Nuclear Power Corp. 80/06/20 lp
- 8007160750 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Portannel " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 86/06/24 ip
- 8007210290 Forwards IE Info Notice 80-24. "Low Level Radwasts Burlai Criteria " No writton response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/25 ig
- 8007230186 Forwards IE Bulletin 80-16. "Potential Misapplication of Resemburt Inc Models 1191 & 1192 Pressure Transmitters W/Either A or D Quiput Codes "Written response required IE Circular 80-16 also encl No written response required GRIER.B H Region i. Philadelphia. Office of the Director 80/06/27 2pp
- B007080292 Forwards Revision 4 to inservice insp program
 BMITH-R L Vermont Yankee Nuclear Power Corp 89/07/01 ip
- 8007110460 Responds to NRC 800610 ltr re violations noted in IE Insp Rept 50-271/80-06 Appropriate personnel reinstructed on importance of completing all items on forms Correct data for Scram Test 94 recorded on necessary data sheet HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 80/07/03 2pp
- 8007210577 Responds to IE Bulletin 80-08 Util uses flued head design for penetration connections & other designs w/containment boundary butt welds ASME Code. Section III. 1968 edition, applied to fabrication & installation HEIDER. L. H. Vermont Yankee Nuclear Power Corp. 80/07/07 Opp
- 8007250173 Forwards reply to IE Bulletin BO-11 re masonry wall design Prioritized list for further evaluation encl No further justification is required for codes used at basis of re-evaluation HEIDER, L. H. Vermont Yankee Nuclear Power Corp. BO/07/07 Spp.
- BOD7250189 Submits reply to IE Builetin 80-17 re failure of control rods to insert Required tests were performed & scram discharge vol & associated piping are free of obstructions MEIDER, L. H. Vermont Yankee Nuclear Fower Corp. 60/07/08 2pp
- B007240422 Confirms and notification that 20-day period for completing tests required by Item 2 of IE Bulletin 80-17 started on 800708 NRC licensing project manager should be notified if test would cause severe impact on power reliability.

 GRIER, B H Region 1. Philadelphia. Office of the Director 80/07/09 2pp
- B007300044 Ack receipt of 800587 ltr forwarding payment of civil penalty & discussing corrective actions, in response to NRC 800507 ltr BTELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/13 2pp

- R Periodic operating reports & related correspondence
- 8007210456 Forwards "Effluent & Waste Disposal Semiannual Rept. Radiological Impact on Man for First & Second Quarters 1979."
 - GROCE, R. H. Vermont Yankee Nuclear Power Corp. 79/08/31 1p
- ---8007210467 "Effluent & Waste Disposal Semsannual Rept.Radiological Impact on Man for First & Second Quarters 1979 " * Vermont Yankee Nuclear Power Corp 79/08/31 47pp
- 8007180398 Forwards monthly operating rept for June 1980 CONMAY,W F Vermont Yankee Nuclear Power Corp 80/07/08 1p
- --8007180400 Monthly operating sept for June 1986 BURGER:F J - BERB:F C - Vermont Yankes Nurlear Power Corp BO/07/08 - App
- B Reportable occurrences, LERs & related correspondence
- 8007020540 PND-1-80-091 on 800611, planned drywell entry was conducted to investigate suspected reactor coolant leaks investigation revealed leakage originated from gasketed mechanical joint Tech Spec criteria lowered Plant shut down RAYMOND. H J. MARTIN, T T, BRUNNER, E J Region 1. Philadelphia. Office of the Director 80/04/13 Epp
- 8007010317 RG 79-205/17. Suppl 1 encl GE loose parts analysis addresses possibility that water red lower end plug could wear to extent that shank would break Licensee concurs w/conclusion that generation of loose part is unexpected W/o encl MURPHY. W P Vermont Yankee Nuclear Power Corp 80/06/25 ip
- B007010391 Forwards LER 80-018/017-0 MURPHY,W P Vermont Yankee Nuclear Power Corp 80/06/25 ip
- --8007010405 LER 80 018/017-0 on 800611.feedwater lines found leaking directly into torus & bypassing detection sys Caused by drywell leakage detection sys design inadequacy Tech spec leakage limits reduced Limits & detection sys under review MURPHY:W P Vermont Yonkee Nuclear Power Corp 80/06/25 2pp
- 8007070260 Suppl 1 to RD 79-25/1T concurs w/conclusions of encl GE proprietary info on loose parts analysis that water rod lower end plug would wear & cause shank to break GE info withheld (ref 10CFR2 790)
 MURPHY.W P Vermont Yankoe Nuclear Power Corp 80/Q6/25 ip
- B007230488 Forwards LER 80-020/03L-0
 MURPHY.W Vermont Yankes Nuclear Power Corp 80/07/17 1p
- --Boo7230489 LER 80-020/03L-0 on BOO617.PC15 valve FS0-109-76A failed to close after stram Cousad by dirt on plunger assembly Valve cleaned & returned to sec MURPHY.W Vermont Yankse Nuclear Power Corp BO/07/17 ip
- DDCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007080068 Forwards Submittal 4 to 800627 security contingency plan Bubmittal withheld (ref 1005762 790) LIBRIZZI,FP Public Service Riectric & Gas Co. of New Jersey 80/06/20 ip
- B007140429 Requests approval to proceed w/interim use of training facility in Quinton, NJ as near-title emergency operations facility
 SchnElder, FW Public Service Electric & Gas Co. of New Jersey 80/07/03 Aga
- © Adjudicatory correspondence
- 8007280555 Requests placement on svc last as friend of court an order to receive copy of all papers served MEBB.M Affiliation Unknown 20/05/16 2pp
- 8007300332 Requests inclusion in Salem syc list to receive all postm 800222 documents & presenting testimony responding to NRC witnesses' claim against RE Webb tectimony WEBB.R & Affiliation Unknown 80705716 Ppp

- 800711011. Correction to inter their dOVal's proposed findings of fact to conclusions of law variet Finibit Pic civil Action 79-1129, encl
 VALORE, C. J. Lower Alloway- *first NJ VALORE(* Valore, *
 80/06/25 53pp
- 8007310243 Firmwards Commission (00527 memorishduri & order containing decisions on UFS 780902 printion for incommideration of 780413 memorandum & order UCC 771104 printion sought action refere protection for electrical cable EISCNBUT D.G. (027); on 06 firmsing 80706725 (89pp.)
- B007100175 Responds to B00509 order v 10 FR; 750 v 2 710 by forwarding intervenor colemon proposed findings of fact 7 conclusions of law on Contentions 2 % 8, aways (rom-reactor alternatives & Board Guestion 5

 AYRES S T New Jersey, state of 80 06728 3pp
- --8007180178 Intervinor Calemann proposed findings of fact & conclusions of law on Contentions & * 6.0cmd upertion 5 & away-fromreactor alternatives in accordance w/Board 800509 order & 100702 754 & 7.710 VAN NESS C - New Jersey, 'state of 80706/26 20pp
- 8007150509 Reply findings of ract & cenclisions of law in form of partial initial difficult substituting for licensee 800513 findings, in response to ASLR 800509 order & ASLR 800528 Question 5 on away-from-tractor issues W/Certificate of Svc WETTERMANN.M J. FRYLING R. Public hervice Cictric & Gas Co. of New Jersey WETTERMANN.M J. Couner, Moore & Corber. 80/07/11 76pp
- J Insurance & indemnity information
- 8007010523 Forwards Endorsement 39 to ANI Folicy NF-230 CORREA,M A Marsh & McLebhan Inc., M G M Noclear (onsultants) inc Div 80705725 Bpg
- 8007310342 Forwards Endorsement 32 to NAELU Policy NE-90 CORREA,M A Marsh & McLennan,Inc & M & M Norlear Consultants Inc Biv 80707/21 2pg
- 8007310376 Forwards Endotsement 40 to ANSI Policy NF-230 CORREA,M A Marsh & Melemman, Inc. : M & M Noricar Consultants, Inc Div 80/07/2) 2pp
- P Operating liconse stage documents & correspondence
- B007230899 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat communal capability in all modes of operation Model Tech Specs which would provide acceptable resolution entl for guidance EISENIUT.D O Division of Licensing 80/06/11 62pp
- 6007:10456 Informs that second interim ruptiper facility 316(b) plan of study, will be distributed to technical advisory group by 800625 Delay coused by computer problem Submittal date should allow enough time for review before 600709 meeting 8HISSAIS. J A Public Service Flection & Gas Co of New Jersey 80/06/13 2pp
- 8007030249 Forwards response to 800004 confirmatory orders relass of non-Class IE instrumentation & control power bus Info written for Unit 1, but also applicable for Unit 2, ricept as noted includes response to 16 Circular 79-02 Affidavit encl SCHNEIDER, F.W. Public Service Cleater & Oos Co. of New Jersey 80/06/27 35pp
- 8007070280 Forwards responses to full power license requirements identified at NRC 800619 meeting HITL:R L. Public Service Electric & Gas Co. of New Jersey 80/06/27 14pp
- --8007070289 Tech Spec Pages 3/4 7-5 through 7 7 for autiliary Fredwater sys & autiliary feedwater sys & autiliary feedwater set & autiliary feedwater set & Public Servery Electric & Gas Cu. of New Jersey 80/06/27 Spo
- 8007030161 Forwards addl info in response to NRC 800618 request to auxiliary feedwater bys Auxiliary feedwater sys (or both units are identical in design, including equipment % automatic initiation logic MITTLER I Public Service Clertice * Gas Co of New Jersey 80/07/01 13pp
- B007250001 Requests submittal of application for amend to license consisting of Tech Sper changes to license conditions PMR Model Tech Spers & Model Icenso conditions for TMI-2 Lessons Learned Category & stems end for mudance LIBENHUT.D O Division of Licensing 09/27/02 69pp

- 00/08034) Notification of 10062J meeting w/util in San Luis Opispo.CA to discorr task action plan items BUCKLEY B C Licensing Branch \gtrsim 80/06/20 4pp
- 007020394 Forwards nonproprietary versions of previously submitted goneric Westinghouse proprietary little to support position on goide tube whom characteristics Requests acknowledgement of recoupt
- CRANCIP A Pacific Gas & Electric Co. 80/06/23 1p
- 007230001 forwards statement of policy reliequisements to be met for current 0L applications, as derived from NUREO-0660 & found in NUREO-0694
- FISENBUT, D.G. Division of Licensing 80/06/26 2pp
- 10072306J5 Forwards std order for DDE work MATTSON R J Division of Safety feebnology FIN A-1121-0 807067-10 lpp
- --8007230692 itd order for DOE work "Review of Auxiliary Feedwater Sys Relability Evaluation Studies for Diable Langen i, ReGuire 1.5wamer 1 & San Onefre 2 & ECCS Reliability Analysis of Hanual vs Automatic "Issued to Sandia Labs GRENIEN.B 1 Division of Safety Technology FIN A-1121-0 00/06/27 9pp
- 300/070197 Forwards Revision I to "Description of Sys Interaction Program for Sussmirally-Induced Events," originally submitted 800927 CRANELP A Pacifix Gas & Steetrix Co 80/07/01 Ip
- --8007070206 Revision (to "Obstription of Sys Interaction Program for Sersatically-Induced Eventa" * Pacific Ons * Electric Co = 80705/10 = 79pp
- 3007160392 Forwards Std Order for DOL Work, "Sys Interaction Support for Diable Conyon," issued to LLL ROSS, B J. Division of Systems Integration FIN A-0248-0 80/07/07
- --800/180395 fild Order for DOE work "Sys Interaction Support for Diable Canyon: (assed to LLL GRENIER,B Diffire of Standards Development, Director FIN A-O248-O 80/07/01 App
- 3007930029 Notification of 800718 meeting wrutil in Bethesda,MD to review nuxiliary foodwater bys reliability study BUCHLEY,B C Licensing Branch 3 80707708 4pp
- 1007280089 Summary of 800617-19 site visit w/NRC, util & two intervenors re audit of sys interaction program for selsmically-induced events Program is sound & can be satisfactorily completed Independent welkdown description encl THOMAS, C.D. Systems Interaction Branch 80/07/09 Opp
- 300/160920 Forwards draft Detating Procedure (PP-38, "Anticipated Transient W/o Trip," per AC Thadani request Procedure should not be considered part of docket file supporting OL application CRANE,P A Pacific Gas & Flectric Co GO/07/10
- --B007160521 "Anticipated Transient W/o Trip." emergency operating
 - procedure
 * Pacific One & Clusters Co. 90/06/07 5pp
- 8007230208 Disrusses augmented low power startup test program for near-term OL applicants Each applicant must perform tests similar to TVA proposed program President Carter 791207 statement on Kemmin Commission reft Prof EISCNIUT-D 9 Division of Licensing 80/07/11 App
- 8007180340 Forwards Revision 2 of "Description of Sys Interaction Program for Seismically-Induced Events " CRANE.P A Pocific Gas & Flectric Co 80/07/15 Ip
- ~-8007180344 Revasion P to "Description of Sys Interaction Program for Seismirelly Induced Events " # Pacific Gar & Ejectrac to 80/07/09 77pp
- 800/250090 Notification of 600725 meeting whotil in Bethesda.MD to discuss auxiliary feedwater sq. Meeting originally scheduled for 800/18 for 800/10 BUCKLEY-8 C | Licensing Dienich 3 | 80/0//17 | 5pp
- 8007310397 Advises that R McMollen response to Ouestion 9 of ASLAB-598 accurately reflects USGS position Ambiguities in location of cartaquake require conservative artumption that all faults have earthquake putential Interior.Dept of Geological Survey 80/07/29 1p MORRISOR H

- E NRC Safety Evaluation Report (SER), supply & correspondence
- B007110033 Forwards Suppl 9 to facility SER SCHWENCER, A Licensing Brench 2 80/06/13 5pp
- --8007110036 Suppl 9 to facility SER * Office of Nuclear Reactor Regulation, Director NUREG-0675 S9 80/06/30 86pp
- F Security, medical, emergency & fire protection plans
- 8007150377 Forwards Revision I to security training & qualification plan Revision I withheld (ref 100FR2 790)
 CRANE,P A Pacific Gas & Flectric Co B0/07/II ip
- 9 Adjudicatory correspondence
- 8007030048 Request for participation in security plan hearing per ASLB 791116 order admitting State of CA in DL proceeding Participation will assist in adequacy & workshility assessments Notice of appearance & Certificate of Evc encl BROWN, H.H. KLINE, J.A. California, State of BROWN, H.H. Hill Christopher & Phillips 80/06/11 9pp
- 8007140026 Ack receipt of Commission 800611 memorandum & order, CLI-80-24, on behalf of Snn Luis Obispo Mothers for Peace Adheres to prior position re Commissioner Hendrie participation in all aspects of OL proceeding re seismic & safety issues JONES, y I James, Grey & Bayley 80/06/18 2pp
- 8007100198 Expresses appreciation for NRC permission allowing joint intervenor representatives to participate in 800617-19 sys interaction audit at util NRC has demonstrated willingness to assure public participation Related correspondence FLEISCHAKER, D S Fleischaker, D S 80/06/25 1p
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fare protection for electrical cables
 EISENHUT, D O Division of Licensing 80/06/25 89pp
- 8007300419 Notice of appearance in proceeding Certificate of 8vc encl 9E0RQ10U, B S California, State of 80/08/30 4pp
- 8007070123 Advises of stipulation in OL proceeding, eliminating legal argument re wording of affidavit of nondisclosure & public dissemination of info Governor Brown of State of CA did not take part in stipulation
 TOWRTELLOTTE, J Hearing Branch 4 JONES, Y, NORTON, B Pacific Gas
 & Electric Co 80/07/02 2pp
- 8007119002 Order granting extension until 800722 for Commission to elect to review decision on enforcement action request. DD-80-22 HDYLF, J C Office of the Secretary of the Commission 80/07/08
- 8007180405 Motion for DLs permitting fuel loading, initial criticality process & low power testing Proposed operation may be conducted during appeal from ALSB 770727 partial initial decision W/documentation. Affidavit & Certificate of Svc CRANE, P A Pacific Qas & Electric Co GEHR, A C Snell & Wilmer NORTON, B Bruce Norton 80/07/14 13pp
- 8007220072 Memorandum & order amending & reissuing ASLAB 800403 protective order re security plan Governor of CA request for participation as interested state granted w/cortain conditions Sets timetable for future proceedings 818HDP, C J Atomic Safety and Licensing Appeal Panel 80/07/15 22op
- --8007220103 Amended protective order permitting limited access to Ban Luis Obispo Mothers for Peace & Governor of CA re security plen info Amended affildavit of nondisclosure encl BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/07/15
- 8007230508 Request for reconsideration of ASLAB B00624 decision, ALAB-598, or certification of M Trifanac & E Luco testimony on 791015 Imperial Valley earthquare Urges appropriation of Funds to facilitate testimony Certificate of Svc encl FLEISCHAKER, D 9, JOHNSTON, F F, PHILLIPS, J San Luis Chispo Mothers For Peace 80/07/17 App

- 8007310466 Notice of PC Valenting % YI Jones withdrawal % WA Baldwin designation as lead counsel in proceeding Certificate of Svc enci VALENTINE,P C , JONES,Y I San Luis Obispo Mothers for Peace 80/07/18
- 8007230536 Motion to change lead counsel designation from UR Tourtellotte to WD Dimstead Notices or WD Olmstead N LC Bwart: appearances, UR Tourtellotte withdrawal & (ertificate OLMSTEAD, W J., TOURTCLLOTTE, J. Hearing Branch 4 80/07/21
- BOOT300110 Notice of appearance in proceeding LANPHER.L C California State of LANPHER.L C Hill Christopher & Phillips 80/07/21 19
- BOO7290429 Statement in support of joint intervenors' BOO717 request for reconsideration of ALAB-598, or for certification of question ro Minhailo.Trufunac & Enrique independent views, to Commission Urges Funding for Trifunac & Luco BROWN, H H , KLINE, J A , GEORGIOU, B G California, State of BO/07724 2pp
- B00730009A Request by joint intervenors for extension until 800804 to respond to applicant motion for low power testing license Counsel out of town Certificate of Svc enci FLEISCHAKER, D S San Luis Obispo Mothors for Peace FLEISCHAKER, D S Fleischaker, D S JDHNSTON, M P Center for Law in the Public Interest 80/07/25 4pp
- B007310451 Discusses handling & delivery of sensitive security mat) between parties

 QLMSTEAD.W J. Hearing Branch 4 80/07/28 Upp
- H General correspondence
- 8007140016 Ack receipt of uncl & informa recipient about progress & expectation of required tultural & historical mitigation program Ltr forwarded to NRC for consideration NIELSEN. A D Interior. Dept of 80/06/18 3pp
- 8007010063 Expresses regret that failure to add Society for Environ Awareness to mailing list for weekly public announcements on facility, resulted in necessity to duplicate request Addition made to distribution list
 INGRAM.F L Office of Public Affairs 80/06/20 ip
- 8007010457 Opposes granting license for low level testing for util due to health & safety concerns re emergency planning radiation monitoring & safety issues based on TMI No testing should be allowed until conversion possibilities explored CLUCAB, J A League of Mamen Voters of Sanius Obispo.CA 80/06/24
- BOO7070218 Requests that NRC deny OL to facility Too much emphasis placed on possible purthquakes along Houges Fault & not enough concern on entire area of instability Conditions create distinct possibility for formation of more volcanous BNAPP.C Affiliation Unknown 60/0//01 1p
- 8007R50277 Responds to 800605 ltr re RH Leddy concerns about proximity of Hosgri Fault to site & obility of facility to withstand severe earthquake Fault is 3 5 miles from site Matter of seismic situation currently ponding before ASLAS DIRCKS, W. J. Office of the Executive Director for Operations app 80/07/02
- ---8007250284 Requests ruspouse to encl RH Leddy concerns about proximity of site to Hosgr: Fault LAGDMARGING.R J House of Bup , Foreign Affairs 80/06/05 3pp
- B007290647 Urges that NRC deny OLs for facility due to proximity to Hosgri fault & to protect health safety & welfare of people of CA ALLEN. B D Affiliation Unknown 80/07/21
- O Inspection reports, IE Bulletins & correspondence
- 9007280697 Forwards response to IC Bulletin 79-27. "Loss of Non-Class Departmentation & Control Power Sys Des During Operation "toss of power to Class If buses is audibly & visually indicated by control room annunciator CRANE.P A Pacific Oes & Electric Co 00/04/15 12pp
- 8007240187 Responds to IE Bulletin 80-04. "Analysis of PWR Main Steam Ling Break W/Continued Foodwater Addition " Review results indicate no potential for containment overpressure or worsening of return to power response CRANE.P A Pacific Cas & Electric Co 80/04/30 2pp

- BOO70202Ad Forwards IE Info Notice 80-7d. "Breakdowns in Contamination Control Program." No written response required ENGELKEN, R.H. Argion 5, San Francisco Office of the Director 80/05/28 1p
- 8007220237 Forwards IE Info Notice 80~26. "Evaluation of Contractor OA Programs 'No writton response required ENGELKEN,R H. Hegion 5. Son Franci co. Office of the Director B0/06/10
- 8007290086 Forwards 1E Info Nutice 83-20 Prompt Reporting of Info in Actordance W/IOCFR50 55(e) 'No written itsponee required ENGELKEN R H Region 5 San Franci /o, Office of the Director 80/06/13 ip
- 8007290658 Responds to (E Bulletin 19-25, "Failures of Westinghouse BFD Relays in Gafety Related Sus 1 Suby relays not used or planned for use in safety-related sus at plant GRANE, P.A. Pairfix Gas 5 Liectric Co. 80/06/16 1p
- 8007030017 Forwards 1E Mulletin 80-15, 'Possible Loss of Emergency Notification Sys (FNS) W/Loss of Offsite Power " Written response required ENGELKEN R H Region 5. Son Francisco. Office of the Director
- 8007240385 Forwards (E Insp Rept 90-275/80 13 on 800501-30 No noncompliante noted CREWS, J.L. Region 5. San Flancisco, Reartor Operations Nuclear Support Branch 80/06/18 2pp
- --8007240395 1E Insp Rept 50-275/80-13 on 600501 30 No noncompliance DOVEMBER OF THE REPT DUTITION BY MOUSE IN THE REPORT OF THE PROPERTY OF THE PR
- 8007020474 Forwards IE (incular 80-15, "Loss of keactor Coolant Pump Cooling & Natural (inculation (poldown ' No written response FNOELKEN, R II Region 5. San Francisco. Office of the Director 80/06/20
- B007180287 Forwards 1E Circului 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnol ' No written response required ENGELKEN R H Region 5. San Francisco. Office of the Director B0/06/24 ip
- 8007230385 Forwards IE Bulletin 80 16, "Potential Hisupplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl Nu written response required ENSELMEN.R H Region 5, San Francisco. Office of the Director 80/06/27 1p
- B007300200 Responds to 1E Bulletin 80-05 re vacuum damage to chemical yol control tank tys All five tanks protected against failure under vacuum conditions RC5 drain tank designed to withstand external pressure of 15 psig CRANE, P A Pacific Gas & Flortric Co 90/07/07 2pp
- 8007310321 Forwards IE Insp Repts 50-275/80 14 to 50-323/80-07 on 800601-20 No noncompliance noted CREMS J. L. Region S. San Francismo, Reactor Operations Nuclear Support Branch 80/07/10 2pp
- --B007310327 IE (nsp Repts 90 2/5/80-14 % 50-323/80 07 on 800601-20 No noncompliance nuted Major areas inspected preoperational testing, plant tour, feel is tour age operator training & witnessing of testing in progress young, T. BAGAGIJU.M. Region 5, San Francisco, Office of the Director STERNERGR, DM Region 5, San Francisco, Charles Gperations Nuclear Support Dranih 80/07/03 3pp

DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

- Q Insportion reports. IE Bulletins & correspondence
- B00717015B Forwards IE Circular B0-14. Radioartive Contamination of Plant Demineralized Mater '99s & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/06/2 80/06/24

- OCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 Security, medical, emergency 5 fire protection plans
- 007140361 Forwards input for fire protection review re fire detection, water suppression, combustible control, gas suppression, fire doors & interior base stations.

 HALL, R E Brookbasen National Laboratory 80/06/20 8pp
- 1007230018 Forwards summary of 600403 meeting woutil in King of Prussia.PA is proposals to meet Tuch Spec requirement in health physics staffing area SMIM.6 H Region 1. Philadelphia, fuel facility & Materials Safety Branch 60/05/27 3pp
- --8007230021 Summary of 800603 meeting w/util in King of Prussia.PA re proposals to meet Toch Spec requirements in health physics staffing area SERABIAN.J A Region 1. Philadelphia. Diffice of the Director 80/06/03 1p
- 1007230126 Requests participation in sludy of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & plantices NRC wishes to interview security myt personnel at facilities EISENHUT.D G Division of Licensing 80/07/11 Ppp
- Adjudicatory correspondence
- 3007080086 Proposed fundings of fact & conclusions of law responding to ASLAB questions on Battelle rept Findings are adopted by THI-2/Peachbottom Intervenors & Ecology Action Urges suspension of Dis Certificate of Svc encl KEPFORD.C Environmental Coalition on Nuclear Power 80/06/18
- 8007080046 Response to ASLAD request re Deficiency 1 Urges reversal of decision rejecting deficiency re correlation between U mino radon releases 's amount of U fuel Portion of Perkins decision re correlation must be variated CAPLAN.R Ecology Action of Oswego 80/06/20 2pp
- 8007080048 Proposed findings of fact endorsing Citizens for Bafe Environ filing re-radiation source terms from U mining & milling Rejects Pertins rationals & urges development of further evidence re-failure mochanisms & human factors CAPLAN,R Ecology Action of Dowego 80/06/20 App
- B007310243 Forwards Commission B00827 memorandum & order containing decisions on UE 780502 potation for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
- BO07080001 Proposed findings of fact & conclusions of law in form of memorandum & order affirming ASLB 780714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BORDENICK.B # Hearing Branch 4 80/07/03 58pp
- --8007080003 Proposed corrections to 800226 transcript BORDENICK, B M Hearing Branch 4 80/07/03 2pp
- --8007080005 Mation to include de minimus theory of health effects in NRC 800703 findings of fact & conclusions of law presented in form of memorandum & order inclusion is consistent w/ALAB-509; ALAB-540 & ALAB-542 Certificato of Svc encl BURDENIC, # Heaving Bratch 4 80/07/03 7pp
- 8007100258 Order granting Ecology Action of Dawego motion to file 800620 submission to generic radon issue BISHOPIC J. Atomic Safety and Licensing Appeal Panel 80/07/07 2pp
- BOO7310128 Response in support of KRC BOO703 pleading asserting validity of Perkins record on redon releases from U mining & milling Objects to KRC soution of the inside and the effects issues from roms ideration Supporting news articles encl CAPLANIR Erology Action of Osweço 80/07/16 13pp

ر در این ماجلور دا مهل

E007290353 Forwards revised Pages 7 % 16 to licensees reply to proposed findings of fait submitted by other parties filed B00718 Revised pages required to correct typographical errors Svc list enci

- H General correspondence
- 800702019/ Requests consideration of site visit by Atomic energy Council of Taiwan on 800825-26 Council interested in observing waste mpt activities Cooperation will be major contribution to NRC exchange arrangement LATLEUR, D Assistant Director for International Cooperation 80/05/LJ D Assistant Director
- 8007140115 Ack receipt of 800423 ltr re public announcement for recent meeting at facility FEMA will be holding public meeting later in the year at which time public will have opportunity to express view re emergency plans
 GRIMES, B K Energency Proparedness Program Office 80/06/09 ip
- --8007140118 Ack receipt of 800424 ltr expressing concern re arrangements for recent meeting at facility FEMA has responsibility for assessing emergency planning & will conduct meeting when plans are finalized DIRCKB.W J Office of the Executive Director for Operations 80/04/02 2pp
- B007110917 Ack receipt of GL Becker B00430 itr re concerns about emergency planning Forwards NUREO-0694 & NUREO-0396 H/o enci enci GRIMES, B Fmergency Preparedness Program Office 80/06/12 ip
- 9007280549 Responds to B00520 itr re JL & MS Randell concerns about emergency planning Discusses various options for funding offsite support agencies Public announcement for Pacility emergency planning meeting issued on 800331 W/Randell Itrs DIRCMS.W J Diffice of the Executive Director for Operations 80/07/02 7pp
- I Financial information
- 9007010138 Responds to B00405 ltr to Q Cunningham transmitting util 9-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY, E Hearings Division 80/04/17 tp
- P Operating licenso stage documents & correspondence
- B00723002B Summary of B00207 meeting w/Mark I dwners group in Dethesda. MD.re ravisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMEB.C T Plant Systems Branch 80/02/21 31pp
- 8007140641 Advises that dates of responses to 790927 generic ltr were 791025 for Peach Bottom 2 & 3 & 791115 for Match 1 & 2 Rept on valve operability program required only for plants desiring to justify inflimited purging VERRELLI,D M Operating Reactors Bronch 4 80/06/05 1p
- B0071705B1 Confirms B00619 mgt meeting to be held at facility revegulatory performance GRIER, B H Region i, Philadelphia, Office of the Director B0704/16 ip
- 8007020810 Advises that Clase III fee is required for review of 800603 application for amend of Liconses DPR-44 & DPR-56 Request involves redistribution of health physics functions & is considered to be of safety significance DIGGS.R M License Fee Management Branch 80/06/18 ip
- 8007100155 Requests technical assistance for review of 800523 & 0603 proposed Toch Spoc changes re executive mgt & onsite health physics functions Current Tech Specs & util ltrs encl NOVAN:T Assistant Director for Operating Reactors 80/06/19 ip
- --8007100158 Current Tech Specs Pages 243 through 246 re administrative controls # Philadelphia Electric Co 79/09/20 4pp
- 6007020435 Confirms licensee voluntary cooperation w/team of NRC research contractors during visit to facility in Sept 1980 Visit is related to NRC sponsored study re status monitoring of angineered safety features
 REID:R W Operating Reactors Branch 4 60/06/24 2pp
- G007180119 Requests that util propose amends to Facility Tech Specs to incorporate corrently installed science instrumentation & associated surveillance requirements Sample Tech Specs reflecting current MRC requirements encl NOVAK.7 M Assistant Director for Operating Reactors 80/07/01

- --B007180123 Sample Tech Specs Pages 3/4 3-46 through 3/4 3-48 for seismic monitoring instrumentation # General Electric Co 78/04/01 3pp
- 8007280342 Advises of personnel changes resulting from reorganization of Ofc of Nuclear Reactor Regulation NOVAK.T M Assistant Director for Licensing 80/07/10 2pp
- 8007240238 Forwards Amends 71 & 69 to Licenses DPR-44 & DPR-56, respectively, safety & evaluation & notice of issuance & availability
- REID, A W Operating Reactors Branch 4 80/07/15 2pp
- --8007240242 Amends 71 & 69 to Licenses DPR-44 & DPR-56, respectively, clarifying definition of operable & adding general limiting conditions for operation & action statements for Tach Boecs Onorating Reactors Branch 4 80/07/15 30pp
- --8007240249 Safety evaluation supporting Amends 71 & 59 to Licenses
 DPR-44 & DPR-56, respectively
 * Office of Nuclear Reactor Regulation, Director 80/07/15 3pp
- --8007240251 Notice of issuance & availability of Amends 71 & 69 to Licenses DPR-44 & DPR-56 respectively REID.R W Operating Reactors Branch 4 80/07/15 2pp
- B0071B0443 Forwards application for amend of facility QLs Application requests changes to Tech Specs re control rod drive return line mode, containment isolation valve mode & correction of typographical error Chock encl to cover fee for application BRADLEY, E J Philadelphia Electric Co 80/07/14 ip
- --8007180446 Application for amend of facility (L. requesting that Tech Brecs in App A of Oi. be amended by revising control rod drive return mode.containment isolation valves to typographical error in Tech Brecs Contificate of Svc encl KEMPER.J B Philadelphia Electric Co 80/07/16 18pp
- 8007220551 Forwards addl fee for application for amend to Licenses DRR-44 & DRR-56, in response to 800618 ltr BRADLEY, C J Philadelphia Electric Co 80/07/17 2pp
- a Inspection reports. IE Bulleting & correspondence
- 8007140462 Forwards IE Bulletin 80~13, "Cracking in Core Spray Spargers " Written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/05/12 ip
- 8007020039 Ack receipt of 800913 ltr informing NRC of steps taken to correct yiplations noted in IC Insp Repts 90-277/80-06 &
- --B007020041 Responds to NRC 800421 itr re violations noted in IE 1msp Repts 50-277/80-06 & 30-278/80-06 Corrective actions, personnel reminded of work documentation importance & Tech Specs data recorded GALAOHER,J W Philadelphia Electric Co 80/05/13 3pa
- ---8007020049 Forwards IE Insp Repts 50-277/80-06 & 50-278/80-06 on 800317-21 & notice of violation BRUNNER, C. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 80/04/21 2pp
- --8007020040 Natice of violation from insp on 800317-21 * Region 1, Philadelphia, Office of the Director 80/04/19 2pp
- --B007020070 IC Insp Repts 50-277/80-04 & 50-270/80-06 on B00917-21 Nancompliance noted util failed to document two surveillance tests & corrective maint & failed to record Tech Specs data BLUMMBERG, N Region 1. Philadelphia, Office of the Director GREENMAN, E 9 Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch 80/04/18 12pp
- 8007020148 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs." No written response required ORIER,B H Region 1, Philadelphia, Office of the Director 80/85/28 1p
- 8007010310 Forwards IE Info Notice 80-23, "Loss of Section to Emergency Fredwater Pumps" No written response required ORIER, 8 H Region 1. Philadelphia, Office of the Director 80/05/27 ip

- B007010378 Responds to IE Bulletin 79-14, "Srismic Analysis for As-Built Safety-Related Piping Sys " Bechtel Power Corp is purforming engineering review & analyses for safety-related piping Unit 3 rept will be rubmitted by 800615 DALTROFF.S L. Philadelphia Electric Co 80/06/03 lp
- B007210600 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs " No written response required GRIER.B H Region I. Philadelphia, Office of the Director B0/06/10 1p
- BOO7020072 Responds to IE Bulletin 80-04. "Engineered Safety Features (ESF) Reset Controls " Encl App A identifies any corrective action planned for safety-related equipment which does not remain in emergency mode upon reset of signal DALTROFF, & L Philadelphia Electric Co 80/06/11 App
- BOO7140267 Forwards IE Bulletin BO-14, "Degradation of BWR Scram Discharge Vol Capability "Written response lequired GRIER.B K Region 1, Philadelphia, Office of the Director BO/06/12 ip
- 8007180106 Bubmits reply to IE Bulletin 80-13 re cracking in core spray sgragers No cracks were found in insp of Unit 2 Insp of Unit 3 will be performed during next refueling outage DALTROFF, B L Philadelphia Electric Cu 80/06/13 2pp
- 8007180117 Bubmits reply to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys All Unit 3 safety-related plping is operable in present condition DALTROFF,S L. Philadelphia Electric Co. 80/06/13 3pg
- 8007170507 Updates 800415 environ qualification rept for Class IE electrical equipment in response to IE Bulletin 79-01B Forwards revised pages & info is high energy/one break profiles & LOCA profiles for reactor bldgs W/o encls DALTROFF.S L Philadelphin Electric Co 80/06/17 2pp
- 6007020700 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER, B_H Region 1, Philadelphia, Office of the Director GRIER, BH R
- 000702049% Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ORIER, D H R BO/06/20 10 Region i, Philadelphia, Office of the Director
- B007160836 Forwards IE Circular B0-14, "Redioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIEGE. D & Region 1. Philadelphia, Office of the Director B0/06/24 ip
- BOO721022B Forwards IE Info Notice 80-24, "Low Level Radwasto Burial Criteria "No written response required QRIER, D H Region 1, Philadelphia, Office of the Director 80/06/25 ip
- 8007310061 Forwards IE Insp Rept 50 277/80-17 on 800604-05 No CARLEDNAR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/26 2pp
- --8007310063 IE Insp Rept 50-27/80-17 on 800604-05 No noncompliance noted Major areas inspected MSIV provmatic control manifolds & mainsteam & feedwater sys FINMEL, A. BASSANI, A. Region I. Philadelphia, Office of the Director EDNETER, S.D. Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/18 5pp
- 8007230163 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Hodgis 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 25p
- 8007250631 Responds to IE Bulletin 80-08. "Examination of Containment Liner Penetration Wolds " Each unit has 26 flued head penetrations w/total of 40 containment boundary butt welds between penetration sleeve & process piping DALTROFF: SL Philadelphia Electric Co 80/06/30 13pp
- 8007230716 Ack receipt of 800512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-30 & 80-278/79-33 Region 1, Philadelphia, Office of the Director 90-278//7----ORIER, D.H. RI

- /230/22 Responds to NRC 80042) ltr re violations noted in IE Imap wpts 50-27//79-30 & 50-278/79-33 Corrective actions actures conducted u/persunnel & procedure for data sheet
- ALLACHER. J. W. Philadelphia Electric Co. 80/05/12 5pp
- 7.30/30 Forwards IE Insp Repts 50-2/7/79-30 & 50-2/8/79-33 on 91201-11 & notice of violation. Apps A & B RUBBER F J Region I. Philodelphia. Reactor Operations Nuclear upport Branch -80/04/21-3ep
- 7270732 Notice of violation.App A.from insp on 791201-31 Region 1. Philadelphia, Office of the Director 80/04 80/04/16 Ip
- 7230/34 Mutice of violation.App D.from insp on /91201-31 Portions ithheld (ref 100FR2 790)
 Region i, Philadelphia, Office of the Director 80/04/16 1p
- 7230/36 IE Insp Repts 50-2/7/79-30 & 50-2/8/79-33 on 791201-31 loncompliance noted failure to follow radiation protection equiroments & to record reactor water chloride data incompliance withhold (ref 10CR2 790) IREEMNANT G . BLOUGHA R Region i, Philadelphia, Office of the irector MCCAME.E C Region 1, Philadelphia, Reactor Operations luclear Support Branch 80/04/16 10pp
- 10197 Ack receipt of 800509 ltr informing NRC of steps taken to rect violations noted in IE Insp Repts 50-277/79-09 & 278/79-10
 CR. III Region 1. Philadelphia. Office of the Director
- 7210215 Responds to NRC 800414 ltr re violations & deviation ofed in IE Insp Repts 50-277/79-09 & 50-278/79-10 orrective actions mertings hold the each shift to inform perators of plant status & any unusual plant conditions ALTROFI.8 L. Philadelphia Electric Co. 80/05/09 8pp
- 7410226 Forwards If Imap Repts 50-277//9-09 % 50-2/8/79-10 on 9019 30 & notires of violation & deviation RICR.II H Heginn I, Philadelphia, Office of the Director O/04/16 2pp
- 7210872 Notice of violation from insp on 790319-30 Region to Philadelphia, Office of the Director 60/08/14
- 172102.15 Notice of deviation from insp on 790°117-30 Region 1. Philadelphia, Office of the Oxfector 80/02/14 1p
- /210307 (F. Insp. Repts 50: 277/79-09 & 50-270/79-10 on 790319-30 encompliance noted failure to provide adequate retraining regram for numlicensed permane) & Failure to perform GA
- units
 RNIFR,D R . MARFIN.T T . GAOI IARDD.T E Region 1. Philadelphia.
 Ifflic uf the Director 80/02/14 71pp
- 10947 Responds to IC Sulletin 80 ii Masonry walls in proximity to having attachments from safety-related piping & equipment observed in App A Justification for re-evaluation criteria I be numerited within 160 days Affidavit encl TROFF, U. Philadelphia Clectric Co. 80/07/01 18pp
- 250811 Responds to IE Bulletin 80-10 re contamination of tradioactive sys & resulting potential for unmonitored, entrolled release of radioactivity to environ Modigram initiated for listed identified sys
 TROFF-5 L Philadelphia Electric Co 80/07/02 5pp
- 40430 Confirms oral notification that 20-day period for completing ts required by Item 2 of IF Bulletin BO-17 started 1708 NRC irrotsing project manager should be notified if t woold cause severe impact on power reliability ER.B !! Region i. Philadelphia. Office of the Director 20/09
- (1995) Requests extension until 200809 for outage to perform acram ts on Unit 3. required by 12 Delletin BO-17. "Failure of of 185 Control Rods to Fully Insert During Stram at BMR " LAMMER, J W Philadelphia Electric Co 20/07/23 2pp
- rrindic operating reports & related correspondence
- 310414 Forwards "Environs Radiation Monitoring Program, 1979 & isological Regional Environ Monitoring Program Rept 15, 19 "
- LSEY, W B Philodelphia Clertric Co BO/07/08 ip

17310417 "Environs Radiation Monitoring Program, 1979 " Interex Corp 80/05/31 102pp

- --8007310420 "Radiological Regional Environ Monitoring Program Rept 15, * Radiation Management Corp 80/05/31 110pp
- 8007180419 Forwards monthly operating repts for June 1980 COONEY.N J Philadelphia Electric Co 80/07/10 ip
- ---BOO71BO433 Monthly operating repts for June 1980 ALDEN.W M Philadelphia Electric Co BO/07/10 9pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007080216 RO on 800329.RHR motor failed Caused by failure of lawer guide bearing Instructions issued to operate RHR sys at full flow conditions Fans an motor shaft ends being replaced Failed motor replaced w/new motor GO
- 8007210403 RO-2-80-i1/1P on 800714 diesel generator cardox sys vapor pilot valve was found closed Caused by failure to properly clear safety permit on 800730 Vapor pilot valve locked open ULLRICH.W T Philadelphia Electric Co 80/07/15 2pp
- 8007280649 RD 2-80-12/1P on 800721, while testing Unit 2 during refueling outago, scram backup valves in air supply to control rod drive scram valves failed Caused by design error Manual venting provided ULLRICH, W T Philadelphia Electric Co 80/07/22 2pp
- 8007300275 Discusses deficiency reported 800721 re installed solenoids of backup scram valves No immediate licensing or enforcement action required Deficiency should be corrected as soon as possible EISENHUT.D 9 Division of Licensing BO/07/22 2pp
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3 F Security, medical, emergency & fire protection plans
- 8007140261 Forwards input for fire protection review re fire detection, water suppression, combustable control, gas suppression, fire doors & interior hose stations

 MALL,R E Brookhaven National Laboratory 80/06/20 Spp
- 8007230018 Forwards summary of 800803 meeting w/util in King of Prussia.PA re proposals to moet Tech Spec requirement in health physics staffing area SMITH.9 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/08/27 3pp
- ---B007230021 Summary of B00603 meeting w/util in King of Prussia, PA re proposals to meet Tech Spec requirements in health physics staffing area SERADIAN, J A Region 1, Philadelphia, Office of the Director B0/06/03 1p
- 6007930126 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mpt personnel at facilities EIBENHUT.D G Division of Licensing 80/07/11 2pp
- O Adjudicatory correspondence
- BOO7080086 Proposed findings of fact & conclusions of law responding to ABLAB questions on Battelle rept Findings are adopted by TMI-2/Peachbottom Intervenors & Ecology Action Urges auspension of OLs Certificate of Svr encl MEPFORD.C Environmental Coalition on Nuclear Power 80/06/18
- BOO70800A6 Response to ASLAB request re Deficiency i Urges reversal of facision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated.

 CAPLAN.R Ecology Action of Oswego 80/06/20 2pp
- BOO708004B Proposed findings of fact endorsing Citizens for Safe Environ filing re radiation source terms from U mining & milling Rejects Perkins rationals & urges development of further evidence re failure mechanisms & human factors CAPLAN,R Ecology Action of Obwego BO/04/20 App
- BD07310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 7B0502 petation for reconsideration of 7B0413 memorandum & order UCS 771104 petation sought action re fire protection for electrical cables EIRENHUT. D © Division of Licensing B0/06/25 B9pp

- B0070B0001 Proposed findings of fact & conclusions of law in form of memorandum & order affirming ASLO 780714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BORDENICK, B M Hearing Branch 4 80/07/03 58pp
- ~-B0070B0003 Proposed corrections to B00226 transcript BORDENICK, B M Hearing Branch 4 B0/07/03 2pp
- ~-B0070B0006 Motion to include de minimus theory of health effects in NRC 800703 findings of fact & conclusions of law presented in form of memorandum & order Inclusion is consistent w/ALAB-509, ALAB-540 & ALAB-562 Certificate of Svc encl BORDENIC, K Hearing Branch 4 80/07/03 7pp
- 8007100258 Order granting Ecology Action of Oswego motion to file 800620 submission re generic radon issue 816HOP,C J Atomic Safety and Licensing Appeal Panel 60/07/07
- 8007310128 Response in support of NRC 800703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from consideration Supporting News articles encl GAPLAN.R Ecology Action of Oswego 80/07/14 13pp
- 8007250353 Forwards revised Pages 7 & 16 to licensees reply to proposed findings of fact submitted by other parties filed 80071B Revised pages required to correct typographical errors Svc list encl TRAVIESO-DIAZ Shaw, Pittman, Potts & Trombridge 80/07/21 10pp

H General correspondence

- 8007020197 Requests consideration of site visit by Atomic energy Council of Taiwan on 800825-26 Council interested in observing waste mgt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR.J D Assistant Director for International Cooperation 80/05/13 3pp
- 8007140115 Ack receipt of 800423 ltr re public announcement for recent meeting at facility FEMA will be holding public meeting later in the year at which time public will have opportunity to express views re emergency plans GRIMES, 8 K Emergency Preparedness Program Office 80/06/09 lp
- -8007140118 Ack receipt of 800424 ltr expressing concern re arrangements for recent meeting at facility FEMA has responsibility for assessing emergency planning & will conduct meeting when plans are finalized DIRCKB.W J Office of the Executive Director for Operations 80/04/02 2pp
- B007i10517 Ack recoipt of GL Berker B00430 ltr re concerns about amergency planning Forwards NUREQ-0654 & NUREQ-0396 W/o and!
 - ORIMES, B Emergency Preparedness Program Office 80/06/12 1p
- 8007280549 Responds to 800520 ltr re JL & WB Randell concerns about emergency planning Discusses various options for funding offsite support agencies Public announcement for facility emergency planning meeting issued on 800331 W/Randell ltrs DIRCKB, W J Office of the Executive Director for Operations 80/07/02 7pp

I Financial information

- 8007010138 Responds to 800605 ltr to 0 Cunningham transmitting util S-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY, E Hearings Division 80/06/19 lp
- P Operating license stage documents & correspondence
- 8007230028 Bummary of 800207 meeting w/Mark I owners group in Bethesda, MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program QRIMES,C T Plant Systems Branch 80/02/21 31pp
- 8007140641 Advises that dates of responses to 790927 generic ltr were 791025 for Peach Bottom 2 & 3 & 791115 for Hatch 1 & 2 Rept on valve operability program required only for plants desiring to justify unlimited purging VERRCLLI.D M Operating Reactors Branch 4 80/06/05 1p

- 8007170581 Confirms 800619 mgt meeting to be held at Carility to regulatory gerformance GRIER, B H Region 1. Philodelphia, Diffic of the Director 80/06/16 1p
- B0070205i0 Advises that Class III fec is required for review of f000tt application for amond of licenses DPR-44 t DPR-56 Request involves requistribution of health physics functions to is considered to be of safety displicance DIGGS.R M. License Fee Management Branch. 80/06/18 1p
- B007100155 Requests technical assistance for review of 800523 & 0607 proposed Tech Spec changes re elecutive mgt & obsite health physics functions (when Toch Specs & eth) ltrs entl NOVAK.T Assistant Director for Operating Reactors
- ---B00710015B Current Forh Spris Pages 243 through 245 re administrati Philadelphia Cleatric Co. 79/09/20 App.
- 8007170054 Dutlines NRC understanding of status of use of hafnium to control rod blades Amend 70 to License DPR-44 authorized use Util withdrew 790921 request following amend issuance REID, R W Operating Reacture Branch 4 80/00/25 2pp
- 8007180119 Requests that util propose amends to facility Tech Specs incorporate currently installed solsmic instrumoutation & associated surveillance requirements Sample Tech Specs reflecting current NRC requirements encl Assistant Director for Operating Rosstors
- --8007180123 Sample Tech Speca Pages 3/4 3-46 through 3/4 3-48 for seismic monitoring instrumentation * General Electric Cn 70/04/01 3pp
- 8007280342 Advises of personnel changes resulting from reorganization of Ofc of Nuclear Reactor Regulation NOVAK.T M Assistant Director for Excensing 80/07/10 2pp
- 8007240238 Forwards Amends 71 & 67 to Licenses DPR-44 & DPR-56, respectively, sufety & evaluation & notice of issuance & availability REID, R W Operating Reactors Branch 4 80/07/15 2pp
- --8007240242 Amends /1 % 69 to timenses DPR-44 % DPR-56, respectively, clarifying definition of operable & adding general limiting conditions for operation % action statements for Teck Specs REID.R W Operating Reactors Branch 4 80/07/15 30pp
- --8007249249 Safety evaluation supporting Amends 71 & 69 to Licenses DPR-44 & DPR-56 respectively * Office of Nuclear Reactor Regulation, Director 60/07/15 3
- --8007240251 Notice of issuance & availability of Amonds /1 & 69 to Licenses BPR-44 & DAR-56 respectively REID.R W Operating Reactors Branch 4 80/0//15 2pp
- B007180443 Forwards application for amend of facility OLs Application requests changes to Tech Specs recontrol and drive return line modes containment isolation value mode & correction of typographical error Check encl to cover fee for application DRADLEY. C. J. Philadelphia Electric Co. 80/07/16 ip
- ---8007180446 Application for amono or farility (M. requesting that T; Specs in App A of OL be amended by revising control rod drive return mode, contament isolation valves & typographical error in Tech Specs (ertificate of Svc encl KEMPER, J S Philadelphia Clottric Co 80/0//16 18pp
- 8007280384 Forwards application to amend OL & proposed temporary cha to fach Specs BRADLEY,E J. Philadelphia Clectric Co. 90/07/22 1p
- --8007280388 Application to amend License DPR-56, authorizing temporal change to Tech Specs which would allow relief from requirement to remove unit from svc if inoperable snubber cannot be repaired within 74-h (pritricate of Svc enci KEMPER, J S Philadelphia Electric Cu 80/07/18 6pp
- --8007280390 Proposed temporary change to fech Specs for snubbers a safety-related type allowing relief from requirement to remove unit from svc if inoperable snubber cannot be repaired within 72-h & Philadelphia Electric Co 80/0//22 2pp

- 8007300553 Confirms NRC 800719 oral authorization to temporarily amend Tech Spec 3 11 D2 (hange allows inoperability of snubber 10-03-5-44 for 10 days to parmit repair Formal amend safety evaluation & notice will be forwarded NOVAK.T M Assistant Director for Operating Reactors 80/01/22
- O Inspection reports, IE Bulletins & correspondence
- B007140462 Forwards IE Dulletin 80-13 "Cracking in Core Spray Spargers" Written response required ORIER, B H Region 1, Philodolphia, Office of the Director B0/05/12 lp
- 8007020035 Ack receipt of 800513 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-277/80-06 k 50-278/80-06 BRUNNER,E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/28 ip

- --8007020041 Responds to NRC 800421 ltr re violations noted in IE Insp Repts 50-277/80-06 & 50-278/80-06 Corrective actions personnel reminded of work documentation importance & Tech Specs data recorded OALLAGHER, J. W. Philadelphia Electric Co. 80/05/13 ... 3pp
- --8007020049 Forwards IE Insp Repts 50-277/80-06 % 50-278/80-06 on 800317-21 % notice of violation 3RUNNER.E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/21 2pp
- --8007020060 Notice of violation from insp on 800317-21 * Region 1, Philadelphia, Office of the Director . 80/04/18 2pp
- --B007020070 IE Insp Repts 50-277/B0-06 & 90-278/B0-06 on B00317-21
 Noncompliance noted util failed to document two surveillance
 tests & corrective maint & failed to record Tech Spacs data
 BLUMMBERG.N Region i. Philadelphia. Office of the Director
 GRECMAN.E G Region I. Philadelphia. Reactor Operations Nuclear
 Support Branch B0/04/18 12pp
- 8007020143 Forwards 1R Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required GRIER.D H Region I. Philadelphia. Office of the Director 80/03/28 ip
- 8007010310 Forwards 18 Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/05/29 ip
- 8007010378 Responds to 1E Bulletin 79-14. "Grismic Analysis for As-Built Safety-Rolated Piping Sys " Bechtel Power Corp is perforang engineering review & analyses for safety-related piping Unit 3 rept will be submitted by 800615 DALTROFF, S.L. Philadelphia Electric Co. 80/06/03 1p
- 8007210600 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required ORIER, 8 H Region I, Philadelphia, Office of the Director 80/06/10 Ip
- 8007020072 Responds to IE Bulletin RO-O6. "Engineered Safety Features (ESF) Reset Controls "Encl App A identifies any corrective action planned for safety-related equipment which does not remain in emergency mode upon reset of signal OALTROFF, S.L. Philadelphia Electric Co. 80/06/11 Spp
- 8007140267 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Written response required GRIER,B H Region 1. Philodelphia, Office of the Director 80/06/12 ip
- 8007180106 Submits reply to IE Bulletin 80-13 re tracking in core spray spragers No crarks were found in insp of Unit 2 Insp of Unit 3 will be performed during next refueling outage DALTROFF, S.L. Philadelphia Electric Co. 80/06/13 2pp
- B007180117 Submits reply to IE Bulletin 79-14 re seismic analysis for as-built safety-related piping sys All Unit 3 safety-related piping is operable in present conduction DALTROFF S.L. Philadelphia Electric Co. 80/06/13 3pp
- 8007170507 Updates 800415 environ qualification rept for Class IE electrical equipment in response to IE Dulletin 79-018 Forwards revised pages & info re high energy/one break profiles & LOCA profiles for reactor bldgs W/o encis DALTROFF,S L Philadelphia Electric Co 80/06/17 2pp

- 8007020703 Forwards It Bulletin 80-15, "Possible Loss of Emergency Notification Sys (CNS) W/Loss of Offsite Power" Written response required ORIER, B H Region I, Philadelphia, Office of the Director 80/06/18 lp
- 8007020492 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER, J. H. Region 1, Philadelphia, Office of the Director 80/06/20 ip
- B007160B36 Forwards IE Circular B0-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required CRIER, B H Region 1, Philadelphia, Office of the Director B0/06/24 1p
- 8007210228 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/04/25 ip
- B007230163 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosempunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes "Written response required IE Circular 80-16 also encl No written response required ORIER, I H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007250631 Responds to IE Bulletim BO-OB. "Examination of Containment Liner Penetration Welds " Cach unit has 26 flued head penetrations w/total of 40 containment boundary butt welds between penetration sleeve & process piping DALTROFF, B L Philadelphia Electric Co BO/O6/30 13pp
- B007230716 Ack receipt of B00512 ltr informing NRC of steps taken to correct violations noted in IE linap Repts 50-277/79-30 & 50-278/79-33 ORIER, B H Region 1, Philadelphia. Office of the Director 50-278/// GRIER, 1 H R
- -8007230722 Responds to NRC 800421 ltr re violations noted in IE Insp Repts 50-277/77-30 & 50-278/79-33 Corrective actions lectures conducted w/personnel & procedure for data sheet GALLAGHER, J. W. Philadelphia Electric Co. 80/05/12 Spp
- --8007230730 forwards IE Insp Repts 50-277/79-30 & 50-278/79-33 on 791201-31 & notice of violation. Apps A & B BRUNNER, E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/04/21 3pp
- --8007230732 Notice of violation. App A. From insp on 791201-31
 * Region 1, Philadelphia, Office of the Director 80/04
- --B007230734 Notice of violation. App B, from insp on 791201-31 Portiona withheld (ref 10CFR2 790)

 * Region 1, Philadelphia, Office of the Director 80/04/16 ip
- --8007230736 IE Insp Repts 50-277/79-30 & 50-278/79-33 on 791201-31 Noncompliance noted failure to follow radiation protection requirements & to record reactor whater chloride data accurately Portions withheld (ref 100FR2 790)
 GREENMAN.E G , DLDUGH.A R Region 1, Philadelphia, Defice of the Director MCCABE,E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/04/16 10pp
- 8007210197 Ack receipt of 800509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/79-09 & 50-278/79-10 QRIER, B H R B0/07/02 1p Region i, Philadelphia, Office of the Director
- --8007210215 Responds to NRC 800416 ltr re violations & deviation noted in IE Insp Repts 30-277/79-09 & 30-278/79-10 Corrective actions meetings held on each shift to inform operators of plant status & any unusual plant conditions DALTROFF,S L Philadelphia Electric Co 80/05/09 App
- -8007210226 Forwards IE Insp Repts 50-277/79-09 & 50-278/79-10 on 790319-30 & notices of violation & deviation GRIER.B H Region 1. Philadelphia. Office of the Director 80/04/16 2pp
- --8007210232 Notice of violation from insp on 790319-30
 * Region 1. Philadelphia, Office of the Director 80/02/14
- --8007210235 Notice of deviation from insp on 790319-30 * Region 1, Philadelphia, Office of the Director 80/02/14

- --8007210307 IE Insp Repts 50-277/79-09 & 50-278/79-10 on 790319-30 Noncompliance noted failure to provide adequate retraining program for nonlicensed personnel & failure to perform GA audits
 HUNTER, D. R., MARTIN, T. T., CAGLIARDO, T. E., Region 1, Philadelphia, Office of the Director B0/02/14 71pp
- B007210547 Responds to IE Bulletin B0-ii Masonry walls in proximity to or having attachments from safety-related piping & equipment identified in App A Justification for re-evaluation criteria will be submitted within 180 days Affidavit encl DALTROFF, & L Philadelphia Electric Co B0/07/02 18pp
- B007250511 Responds to IE Bulletin B0-10 re contamination of nonradioactive sys & resulting potential for unmonitored, uncontrolled release of radioactivity to environ Mod program initiated for listed identified sys DALTROFF. S L Philadelphia Electric Co B0/07/02 Spp
- 8007240430 Confirms oral notification that 20-day period for completing tests required by Item 2 of IE Bulletin 80-17 started 800708 NRC licensing project manager should be notified if test would cause severs impact on power reliability ORIER, BH Region 1, Philadelphia, Office of the Director 80/07/09 2pp
- H007280560 Requests extension until 800809 for outage to perform scram tests on Unit 3, required by IE Bulletin 80-17. "Failure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " GALLAGHER, J W Philadelphia Electric Co 80/07/23 2pp
- R Periodic operating reports & related correspondence
- 8007310414 Forwards "Environs Radiation Monitoring Program,1979 & Radiological Regional Environ Monitoring Program Rept 15, 1979 "
 WILLEY, W B Philodelphia Electric Co 80/07/08 ip
- ---8007310417 "Environs Radiation Monitoring Program, 1979 "
 # Interex Corp 80/05/31 102pp
- --8007310420 "Radiological Regional Environ Monitoring Program Rept 15, 1979"
 - # Radiation Management Corp 80/05/31 110pp
- B007180419 Forwards monthly operating ropts for June 1980 COONEY.M J Philadelphia Electric Co 80/07/10 1p
- --8007180433 Monthly operating repta for June 1980 ALDEN W M Philadelphia Electric Co 80/07/10 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007070382 LER 80-031/03L-0 on 800605, during surveillance test, pressure switch PS 3 5 12C found 0 3 psig above Tech Spec limit.
 Caused by setpoint drift Switch recalibritested & returned to svc
 CODNEY_M J Philadelphia Electric Co 80/06/30 lp
- 8007080216 RD on 800329.RHR motor failed Caused by failure of lower guide bearing Instructions issued to operate RHR sys at Pull flow conditions Fans on motor shaft ends being replaced Failed motor replaced w/new motor COONEY.M J Philadelphia Electric Co 80/06/30 2pp
- 8007210378 LER 80-014/03L-0 on 800608, while performing 9T 6 9, valve MD 3-10-268 failed to close after stroked open Caused by mechanical problem in valve, MD 3-10-268 to be disastembled & repaired CDONEY, M J Philadelphia Electric Co 80/07/14 1p
- B007280649 RD 2-80-12/IP on 800721, while testing Unit 2 during refueling outage, scram backup valves in air supply to control rod drive scram valves failed Caused by design error Manual venting provided ULLRICH, H. T. Philadelphia Electric Co. 80/07/22 2pp
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 ltr to all power reactor licensees in response to 800529 ltr re empresency response facilities at reactor sites Sites w/approval to use closed-circuit televiston link w/technical support ctr listed CRUTCHFIELD, D M Operating Reactors Branch 5 80/07/07. 2pp

- BOO7030184 Forwards revised emorgency plan Plan is based on elisting metorological capabilities & reflects critoria of NUREG-0654 York County, VA emergency plan encil Plans withhold per Privacy Act & Available in Central Files only BAUM, E.A. Virginia Electric & Power Co. H0/06/30 2pp
- 8007170412 Forwards revised nuclear security personnel training & qualification program in response to 800515 lt: Program withheld (ref 100FR2 790)
 SYLVIA.3 R Virginia Electric & Power Cb 80/0//14 1p
- G Adjudicatory correspondence
- BO07310243 Forwards Commission B00827 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action referre protection for electrical cables
 EISENHUT, D 0 Division of Licensing B0/06/25 89pp
- 8007310339 Order granting extension until 800723 for Commission to elect whether to review decision taken under 100FR2 206 on request for enforcement action, DD-80-23 MOYLE, J.C. Office of the Secretary of the Commission 80/07/09 to
- 8007300412 Advises that effective 800801.address for coalition will be 1105-C Dlive St.Greensboro, NC 27401 Related correspondence ALLEN, J. North Anna Environmental Coalition 80/07/15 is
- H General correspondence
- B007150047 Responds to B00307 ltr to President Carter re granting VEPCD authority to build another nuclear plant Discussors util plants.operating & under const & relative costs of coal vs nuclear energy YOUNGBLODD, B J Operating Reactors Branch i 80/05/13 Spp
- --8007070064 Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ coalition for action DENTON: HR Office of Nuclear Reactor Regulation, Director 80/06/20 25pp
- --8007070069 FR notice of issuance of 800620 Director's Decision DD-80-2 denying 800218, 22, 28, 0425 & 0525 requests by North Anna Environ Coalition for action DENTON. If R Office of Nuclear Reactor Regulation, Director 80/06/20 2pp
- --8007070075 Requests amend to 800218 ltr following discovery of addl problems in steam generator Facility should be kept shut down pending resolution of nuise, secondary chemistry, turbine cracks & domineralizer problems ALLEN, J North Anna Chvironmental Coulition 80/02/22 ip
- --8007070079 Requests action concerning defective demineralizer design, related corrosion & cracking in steam generators & turbing discs Commends NGC decision to require ETG re experimental replacement of steam generators
 ALLEN.J North Anna Environmental Coalition 80/02/18 4pp
- J Insurance & indemnity information
- 8007150490 Forwards Endorsements 28 & 27 to NFLIA Policy NF-240 PIERCE, D A Marsh & McLennon, Inc., M & M Nuclear Consultants, inc Div 80/07/10 3pp
- P Operating license stage documents & correspondence
- BOO7230099 Requests submittal of proposed Teth Spec changes providing , for redundancy in decay heat removal capability in all modes of operation Model Tach Specs which would provide acceptable resolution and! for guidance EISENHUT, D O Division of Licensing 80/06/11 62pp
- B007010430 Confirms agreement w/NRC re review criteria to be used to evaluate results of rod swap tests & administration of physics test program should deviations occur THOMAB.W N Virginia Electric & Power Co B0/06/Pb App

- 17030131 Application for amend to Licenses DPR-32 & DPR-37 consisting if proposed charges to Toch Specs ERGUSON, J.H. Virginia Electric & Power Co. 80/06/30. 3pp
- 007030:15 Evaluation & proposed changes to Tech Specs Sections 3 3, 3 43 6.4 8.4 1.4 5 & 4 Li re containment spray sys * Virginia Electric & Power Co 80/06/30 62pp
- 17830001 Requests submittal of application for amend to license ensisting of fech Spot changes & license conditions PMR lodel Tech Spocs & Model License conditions for TMI-2 essens tearned totagory A items entl for guidance ISEMBUT D 0 Division of Licensing 80/07/02 69pp
- 7080419 Forwards addl info re new fuel storage area for proposed hango 85 to Tech Specs.por recent telcon YLVIA.B.R. Virginia Electric & Power Co. 90/07/03 Spp
- 7100273 Submits addl info re implementation of short-term Lessons earned requirements Status of remaining Category A items, id-ur statum of design & installation of Category B mads & chedule for implementation one! Forwards drawings YEVIA.D R Virginia Electric & Power Co 80/07/07 180pp
- 0071002/7 "Sump Pump Discharge Piping Auxiliary Bldg to Containment " * Stone & Webster Engineering Corp 79/05/15 Ip
- 007100200 "Sump Pump Discharge Piping Auriliary Bldg to Containment " * Stons & Webster Engineering Corp 77/10/24 lp

80/04/07 10

- 007100204 "Flow Diagram Doron Recovery Sys " Sheet 1 * Stone & Webster Engineering Corp 80/07/07 1p
- 007)00288 "Fine Diagram Containment Atmosphere Cleanup Sys " * Stone & Webster Engineering Corp 77/10/22 11p
- 007100293 "Flow Diagram Waste Disposal Sys " Sheet 2 * Stone & Webster Engineering Corp 80/07/07 1p
- 107100298 "Flow Diagram Waste Disposal Sys " Shet # Stone & Wobster Engineering Corp 80/07/07 Sheet 1
-)07100 KD3 "Ventilation Thermal Recombiner "
 # Btone & Webster Engineering Core 80/6
- 107100309 "Pf.ID Liquid Sampling " Sheet 1 of 5 # NUS Curp | NO/09/05 | 1p
- 10/100315 "P&ID liquid Sampling Coolers" Sheet 3 of 5 F NUS Curp 80/05/05 1p
-)0/1001R1 "PM1D Liquid Sampling Panel " Sheet 4 of 5 s NUS Corp (00/05/05 ip
- 10/100323 "PhiD-Liquid Sampling " 5 of 5 * NUS Corp 80/05/05 1p NUS Corp
- NOTIONARY "PEID Containment & Air Sampling Sys " Sheet 1 of 1 * NUS Corp 80/05/05 1p
- 107100335 "Process Flow Diagram Liquid Sampling " Sheet 1 of 2 * NUS Corp 80/05/29 ip
- #07100338 "Process Flow Diagram Liquid Sampling " Sheet 2 of 2 * NUS Corp 40/09/22 1p
- 07100347 "Procuss Flow Diagram Containment Air Sampling " * NUS Corp B0/04/14 Ip
- 0/1003Bl "Qeneral Arrangement Auxiliary Bldg.Drumming Room Plan. Elevation 274 Ft " Bheet 1 * NUS Corp 80/05/29. 1p
- 07100059 "General Arrangement Auxiliary Bidg. Drumming Room, Section & Details " Sheet 2" * NVB Corp 80/05/29 Ip

- ---8007100365 "General Arrangement High Radiation Sampling Sys Waste Tank & Pumps.Plan Elevation 244 ft,6 Inches & Section " Sheet 1 * NUS Corp 60/05/29 Ip
- --8007100371 "P&ID Liquid Sampling " Sheet | of 5 * NUS Corp 80/05/05 ip
- --8007100375 "P&ID Liquid Sampling " Sheet 2 of 5 * NUS Corp BO/05/05 ip
- --8007100380 "P&ID Liquid Sampling Program " Sheet 3 of 5 * NUS Corp 80/05/05 ip
- ---B0071003B2 "P&ID Liquid Sampling Panel " Sheet 4 of 5 * NUS Corp B0/05/05 ip
- --8007100387 "P&ID Liquid Sampling Panel " Sheet 5 of 5 ** NUS Corp 80/05/05 ip
- --8007100391 "P&ID Containment Air Sampling Sys " Sheet 1 of 1 # NUS Corp 80/05/05 ip
- --8007100403 "Process Flow Diagram Liquid Sampling " Sheet 2 of 2 # NVS Corp 80/05/22 ip
- --B007100407 "Process Flow Diagram Containment Air Sampling " Sheet 1 of
 - * NVS Corp 80/04/14 1p
- --BOO7100409 "General Arrangement Auxiliary Bldg. Drumming Room Plan, Elevation 27 Ft. 6 Inches " Sheet 1 * NUS Corp 80/05/29 1p
- --8007i00414 "General Arrangement Auxiliary Bldg. Drumming Room. Section & Details " Shert 2 * NUS Corp 80/05/29 1p
- --8007100415 "General Arrangement High Radiation Sampling Sys Waste Tenk & Pumps Plan.Eloyation 27 Ft.6 Inches & Section " Sheet 1 * NUS Corp 80/05/29 1p
- 8007210435 Submits update to status of evaluation of asymmetric LOCA loads on reactor pressure vessels & references Phase-C results, WCAP-7748, submitted by Westinghouse on 800430 SYLVIA: B R Virginia Electric & Power Co 80/07/14 2pp
- 8007310421 Comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports "Requests extension of review period to 800915 to review stress corrosion cracking BROWN B C Virginia Electric & Power Co 80/07/21 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007240230 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J F Region 2, Atlanta, Office of the Director 80/05/08
- 8007020200 Forwards IE Info Natice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28
- 8007140169 Discusses 800422-23 radiation survey which revealed radiation levels on trunk surface exceeding regulatory limits Forwards notice of violation & notice of proposed imposition of civil penalties STELLO.V. Office of Inspection & Enforcement. Office of the Director 80/05/28 3pp
- --8007140174 Notice of proposed imposition of civil penalties in amount of \$8.000 for item of noncompliance re radiation levels on truck surface exceeding regulatory limits * Office of Inspection & Enforcement, Office of the Director 80/05/28 lp
- 8007210477 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28,

- 8007010239 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 20m
- 8007160307 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action of response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007090057 Forwards revision to Page 2 of 800611 response to IE Bulletin 80-12, "Decay Heat Removal Sys Operability " BYLVIA, B R Virginia Electric & Power Co 80/06/16 2pp
- 8007090423 Responds to IE Bulletin 79-018, "Environ Classification of IE Equipment " Class IE electrical equipment reviewed to ensure functioning during postulated accident Review of Action Items 1,2 & 3 provided in Encl repts W/a encl repts SYLVIA, B R Virginia Electric & Power Co 80/06/14 3pp
- 8007020757 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENB) W/Loss of Offsite Power " Written response required U'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/18 io
- 8007020434 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required 0'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007150462 Ack receipt of IE Insp Repts 50~280/80-16 & 50~281/80-17 No proprietary info Corrective actions to Enforcement Action 80~28 strengthened radwaste monitoring program implemented Radwaste section restaffed 8YLVIA, B R Virginia Electric & Power Co 80/06/20 5pp
- --8007150468 Forwards IE Insp Repts 50-280/80-14 & 50-280/80-17 on 800425 No noncompliance noted

 O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28 2pp
- ---B007150471 IE Insp Repts 50-280/B0-16 & 50-281/80-17 on 800423-25. No noncompliance noted Major areas inspected shipment of radwaste for burial including shipping paper requirements. labeling.placarding & raduation levels BROWN,R A. POTTER,J P. STOHR,J P. Region 2. Atlanta, Fuel Facility & Materials Safety Branch B0/05/08 9pp
- 8007140543 Forwards payment of civil penalty per NRC 800528 notice of proposed imposition of civil penalties re IE Insp Repta 50-280/80-16 & 50-281/80-17 Violations based on radwaste shipment arriving at site, w/excessive radiation SYLVIA, B R Virginia Electric & Power Co 80/06/20 tp
- 8007170119 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required, O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24 ip
- 8007230270 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007210030 Responds to unresolved items in IE Imap Repts 50-280/80-14 & 50-281/80-15 Relieves weld repair of Limitorque enclosure on MOV-FW-1510 was performed per specified procedures Nondestructive test exam will be performed SYLVIA, B R Virginia Electric & Power Co 80/07/01 Spp
- BO071101B9 Forwards reactor coolant pump support drawings & description of pump support disassambly & insp procedures in response to NRC 800707 ltr BYLVIA:B R Virginia Electric & Power Co 80/07/07 2pp
- ---8007110193 "Reactor Coolant Pump Supports General Arrangement "
 * Stone & Webster Engineering Corp 78/07/20 1p

- --8007110194 "Realtor Cuplent Pump Supports Detoils " Sheet 2 * Stone & Webster Engineering Corp. 79/07/30 to
- --8007110196 "Reactor Coolant Pump Support Details " Sheet I * Stone & Webster Engineering Corp 70/07/30 Ip
- BOO/170334 Forwards "IE Bulletin AO-Day Review" in response to ac required by Item 4 of IE Bulletin BO-LL: "Hasonry Wall Design " Rept available in Contral Files only BNLVIA.B R Virginia Electric & Power Co BO/07/07 Ip
- 8007250945 Forwards response to TE Bulletin 80-08, "Exam of Contai Liner Penetration Welds" Penetration assemblies of flued head forging design were used for penetrations listed in Tables 1 & 2 for North Anna SYLVIA, B R Virginia Electric & Power (o 80/0//0/ 7pp
- B007270840 Responds to IE Bullotin 80-10 re contamination of nonradioactive sys Lists sys considered nonradioactive but potentially radioactive through interfaces w/radioactive sys All discharge paths are sampled or monit
- 8007i10336 Responds to Items ? & 3a of IF Builntin /9-27. "Loss of Class IE Instrumentation & Control Power Sys Bus During Operation " Unit 1 inverter trip was not related to futiore mades described in bulletin SYLVIA.B R Virginia Electric & Power Co 80/0//09 2pp
- 8007170529 Forwards response to NRC 800618 ltr re violation noted 1 1E Insp Repts 50-280780-17 & 50-281780-23 Response withheld (ref 100FR2 790) 8YLVIA,R R Virginia Electric & Power Co 80707714 ip
- 8007270220 Forwards response to NRC 800607 ltr re violations noted IE Insp Repts 50-280779-70 & 50-281779-80 Corrective action all release procedures reviewed & changed as necessary Attachment 2 withheld (ref 100FR2 790)

 SYLVIA, B R Virginia Electric & Power Co 80/07/21 4pp
- R. Periodic operating reports & related correspondence
- 8007170389 Forwards monthly operating repts for June 1980 SYLVIA: B R Virginia Electric & Power Co 80/07/14 ip
- --8007170391 Monthly operating repts for June 1980
 DUNNIS D. Virginia Electric & Power Co. 80/07/07. 4tpp
- S Reportable occurrences, LERs & related correspondence
- B007230362 PNO-II-ED-09B on B00603.unit tripped when fire disabled one of four instrument buses Plant in hot shutdown while licensee replaces transformer & dilutes boron concentration for restart Licensee issued press release HEBBTER,E H , KELLOGG,P J Region 2. Atlanta, Office of the Director B0706703 ip
- 8007010429 Forwards LER 80-032/03L-0 WILBON, J L Virginia Electric & Power Co 80/06/26 ip
- --B007010442 | ER 80-032/03L-0 on B00329, during testing of air ejector divert valve TV-SV-202, max operating air differential pressure exceeded rating of AB(0 solenoid valve Couned by use of improper design criteria dering valve installation H1LSON, J i Virginia Electric & Power Co B0/06/P6 2pp
- 8097070389 Forwards LER 80-038/031-0 WILBON, J. L. Virginia Electric & Power Co. 80/07/03 1p
- --8007070397 LER BO-038/03L-0 on BOG610, during 100% power operation, isolation valve for IBR-TK-28 lepked during release of I-BR-TK-28 cousing unsampled release from tank B Caused by deterioration of volve disphragm Valve repaired.

 WILSON, J. L. Virginia Electric & Power Co. 80/07/01 Epp.
- 8007070224 Forwards LER 80-069/0,45-0 WILSON,J L. Virginia Electric & Power Co. 80/07/0s 1p
- --B007070229 LER 60-029/03L-0 on 80060% during normal operation vital 4 Sple failed, initiating automatic turbine ruples Caused by failure of filtering capacitor in Gold transforme re-energized fransformer roplaced WILBON.J L. Virginia Electric & Power Co. E()

- B007210092 Part 21 rept re existence of nonconservative assumption in cold shutdown design basis boron dilution accident analysis in FSAR Caused by use of incorrect sys vol Review will be performed to identify & analyze addl accidents
 SYLVIA.B R Virginia Ejectric & Power Co 80/07/02 4pp
- 8007140249 Forwards LER 80-039/01T-0 WILSON, J L Varginia Electric to Power Co 80/07/09 ip
- --8007140259 LER 80-039/01T-D on 800626, potential discovered for boron contentration nonconservatism during dilution accident w/RCS at reduced vol Analysis of boron dilution at cold & hot shutdown being evaluated by reactor vendor WILSON, J L. Virginia Electric & Power Co. 80/07/09. 2pp
- B007280607 Forwards LERs B0-043/03L-0 & 80-041/03L-0 W1L50N.J L. Virginia Electric & Power Co 80/07/24 1p
- --8007280618 LER 80-043/03L-0 on 800703, during normal operation condenser inlet valve MOV-CW-106C would not close when operated from control room Caused by broken study allowing motor stator to back out
 MILSON, J. L. Virginia Electric & Power Co. 80/07/24 2pp
- 8007280629 LER 80-041/03L-0 on 800625,pipe stress re-analysis indicated baseplate anchor bolts on hanger H-2 on line 12 inch -CC-27-121 & hanger H-9 on line 12 inch-CC-33-121 overstressed Mods to anchor bolts complete WILSON.J L Virginia Electric & Power Co 80/07/24 2pp

V Operator Examinations

- B007170348 Forwards revised, "Licensed Operator Requalification Program," in response to NRC 800328 request All training instructors are required to participate in program to maintain proficiency BYLVIA, B R Virginia Electric & Power Co 80/07/15 ip
- --8007170350 Revised. "Liconsed Operator Requalification Program " * Virginia Electric & Power Co 80/07/31 11pp
- DOCKET 50-281 SURRY POMER STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 ltr to all power reactor licensees, in response to 800529 ltr re emergency response facilities at reactor sites 91tes w/approval to use closed-circuit television link w/technical support ctr listed GRUTCHFIELB, D.M. Operating Reactors Branch 5 80/07/07 2pp
- 8007030184 Forwards revised emergency plan Plan is based on existing metorological capabilities & roflects criteria of NUREG-0654 York County-VA emergency plan encl Plans withheld per Privacy Act & available in Central Files only BAUM.E A Virginia Electric & Power Co 80/06/30 2pp
- BOO7170412 Forwards revised nuclear security personnel training & qualification program in response to BOO515 ltr Program withheld (ref IOCFR2 790)

 BYLVIA, B R Virginia Electric & Power Co BO/07/14 1p

Q Adjudicatory correspondence

- B007310243 Forwards Commission B00527 memorandum % order containing decisions on UCG 780502 petation for reconsideration of 780413 memorandum % order UCS 77104 petition sought action re fare protection for electrical cables EISENHUT.D 0 Division of Licensing 80/06/25 89pp
- BD07110339 Order granting extension until 800723 for Commission to elect whether to review decision taken under 100FR2 206 on request for enforcement action, DD-80-23 HOYLEJ C Dffice of the Secretary of the Commission 80/07/09 in
- 8007300412 Advises that effective 800801, address for coalition will be 1105-C Olive St. Greensboro, NC 27401 Related currespondence ALLEN, J North Anna Environmental Coalition 80/07/15 ip

H General correspondence

B007130047 Responds to B00327 ltr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants, operating & under const & relative costs of coal vs nuclear energy YOUNGDLOOD, B J Bearating Reactors Branch 1 80/05/13 Spp

- 8007070059 Forwards 800420 Director's Decision DD-80-23 denying 800218.22,0425 & 0525 requests for action FR notice encl DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/20 2pp
- --8007070064 Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ coalition for action DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/20 25pp
- --8007070069 FR notice of issuance of 800620 Director's Decision DD-80-23 denying 800216,22,28,0425 & 0525 requests by North Anna Environ Coalition for action BENTON: H R Office of Nuclear Reactor Regulation. Director 80/06/20 2pp
- --8007070079 Requests action concerning defective demineralizer design, related corrosson & cracking in steam generators & turbine discs Commends NRC decision to require EI8 re experimental replacement of steam generators
 ALLEN, J North Anna Environmental Coalition 80/02/18 4pp
- 8007020688 Responds to HB McDonald 1tr directed to DDE North Anna full power license issuance will be discussed w/Commission in Jul-Aug 1980 Surry is in shutdown condition due to seismic piping supports mods & will return to power in Aug 1980 YDUNGBLDQD, B J Licensing Branch 1 80/04/25 1p
- ---8007020693 Forwards HB McDonald 1tr expressing concerns ro continued operation of facilities
 DETANCOURT.B Energy.Dept of 80/06/06 2pp

J Insurance & indemnity information

- B007150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE, D A Marsh & McLennam, Inc., M & M Nuclear Consultants, Inc Div B0/07/10 3pp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittel of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D & Division of Licensing 80/06/11 62pp
- B007210037 Advises that 790820 safety evaluation re Unit i mods correcting underpower capacity conditions on 480 volt emergency buses applies equally to Unit 2 Mods are acceptable VARQA.S A Operating Reactors Branch 1 80/06/20 2pp
- 8007010422 Responds to NRC 800509 ltr re loss of offsite power Review of history reveals two partial losses of offsite power occurred SYLVIA, B R Virginia Electric & Power Co 80/06/26 3pp
- 8007010430 Confirms agreement w/NRC re review criteria to be used to evaluate results of rod swap tests & administration of physics test program should deviations occur THOMAS, W N Virginia Electric & Power Co 80/06/26 App
- 8007030131 Application for amend to Licenses DPR-32 & DPR-37 consisting of proposed changes to Tech Specs
 FERGUSON, J.H. Virginia Electric & Power Co. 80/06/30 ...3pp
- --8007030135 Evaluation & proposed changes to Tech Brecs Sections 3 3, 3 4,3 6,3 8,4 1,4 5 & 4 11 re containment spray sys performance * Virginia Electric & Power Co 80/06/30 6209
- BGO7250001 Requests submittal of application for amend to license consisting of Tech Spot changes & license conditions PHR Model Tech Spot & Model Tech Spot & Model Tech Spot & For TMI-2 Lessons Learned Category A Items encl for guidance EISENHUT, D & Division of Licensing 80/07/02 69pp
- 8007080419 Forwards add1 info re new fuel storage area for proposed Change 85 to Tech Specs.per recent telcon BYLVIA.B R Virginia Electric & Power Co 80/07/03 3pp
- 8007100273 Submits add1 info re implementation of short-term Leasons Learned requirements Status of remaining Category A items, mid-yr status of design & installation of Category B mods & schedule for implementation encl Forwards drawings SYLVIA:B R Virginia Electric & Power Co 80/07/07 180pp

07230270 Forwards IC Bulletin 80-16, Potential Misapplication of Overder of the Bolletin Ro-10. Potentia Hisappin Rosemount inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes. Whitten response required D'REILLY, J.P. Region 2. Atlanta Office of the Director 80/06/27

07210030 Responds to unresolved items in 1E Insp Repts 50-280/80-14 & 50-281/80-15 Believes weld repair of Limitorque enclosure on MOV-FM-151D was performed per specified procedures
Nondestructive test exam will be performed
SYLVIA.B R Virginia Electric & Power Co 80/07/01 App

07110189 Furwards reactor raciant pump support drawings & description of pump support drassembly & insp procedures. In response to NRC 800707 ltr SYLVIA, B R Virginia Electric & Power Co 80/07/07 2pp

-8007110193 "Reactor Coolant Pump Supports General Arrangement "
* Stone & Webster Engineering Corp 78/07/20 ip

-8007110194 "Reactor Coolant Pump Supports Details" Sheet 2 * Stone & Webster Engineering Corp 79/07/30 tp

-8007ii0194 "Reactor Coolant Pump Support Details " Sheet 1 * Stone & Webster Engineering Corp 70/07/30 Ip

307170334 Forwards "IE Bulletin 60-Day Review," in response to action required by Item 4 of IE Gulletin 80-13; "Masonry Wall Design " Rept available in Central Files only BYLVIALB R Virginia Electric & Power Co 80/07/07 in

007250545 Forwards response to 1E Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Penetration assemblies of flued head forging design were used for penetrations listed in Tables 1 & 2 for North Anna SYLVIA,B R Virginia Electric & Power Co BO/07/07 7pp

O07270840 Responds to IE Bulletin BC-10 re contamination of nonradioactive sys Lists sys considered nonradioactive but potentially radioactive through interfaces w/radioactive sys All discharge paths are sampled or monitored BYLVIA.B R Virginia Electric & Power Co BO/07/07 2pp

3007160664 Identifies proposed actions to be taken in response to IE Bulletin 79-14, "Scismic Analysis for As-Built Bafety-Related Piping Sys" Screening process will be used for Tech Spec sys to identify significantly overstressed supports SPENCER: W.C. Virginia Electric & Power Co. 80/07/08 3pp

3007110336 Responds to Items 2 & 3a of IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation "Unit 1 inverter trip was not related to failure modes described in bulletin Virginia Electric & Fower Co 90/07/09 2pp

BOO7180371 Submits clarification & addl info to 800708 ltr responding to LE Bulletin 79-14 Approx 294 supports needed Screening process will accompany determination of overstressed supports for mode exceeding 30 days
BROWN,S C Viryinia Electric *, Power Co 80/07/11 2pp

8007290365 Responds to 800708 discussions w/NRC re 800708 response to IE Bulletin 79-14. "Seismir Analysis for As-Built Bafety-Related Piping Sys " Approx 294 supports identified to require installation BROWN,8 C Virginia Electric & Power Co 80/07/11 2pp

Virginia Electric & Power Co BO/07/11 2pp

B007170529 Forwards response to NRC 800618 itr re viblation noted in IE Insp Repts 50-280/80-1/ & 50-281/80-23 Response withheld (ref 100782 790)
SYLVIA R R Virginia Flectii & Power Co 80/07/14 ip Virginia Electric & Power Co 80/07/14 1p

800729020 Forwards response to NRC 8006/7 itr re violations noted in IE Insp Repts 60-280/79-70 % 50-281/79-80 Corrective action all release procedures reviewed & changed, as necessary Attachment 2 withhold (see 100CFR2 790)

BYLVIA B R Virginia Electric & Power Co 80/07/21 4pp

8007110390 Submits info re actions proposed upon startup per IE Bulletin 79-14 Proposal predicated on provious procedents & commitments set für facility i is consistent w/mutuul concern for safe operation Requests prompt confirmation SPENCER.W.C. Virginia Electric & Power Co. 80/08/08 3pp

8 Periodic operating reports & related correspondence

8007170389 Forwards monthly operating repts for June 1980 SYLVIALE R Virginia Electric & Power Co 80/07/14 1

~-B007170391 Monthly operating tepts for June 1980 DUNN.S D Virginia Electric & Power Co B0/07/07 41pp

S Reportable occurrences, LERs & related correspondence

8007010340 Forwards LER 80-007/03L-0 WILBON, J.L. Virginia Electric & Power Co. 80/06/26 ip

--8007010394 LEA 80-007/03L-0 on 800605, w/unit in cold shutdown, smake detectors found inoperable Caused by breaker trip at motor control ctr which feeds detectors Cause of breaker trip

WILSON, J.L. Virginia Electric & Power Co. 80/06/26 2pp

B007210092 Part 2) rept re existence of nunconservative assumption in cold shutdown design basis boron dilution accident analysis in FBAR Caused by use of incorrect sys vol Review will be performed to identify & analyze addl accidents SYLVIA.B R Virginia Electric & Power Co 80/07/02 4pp

B0071B0319 Forwards LER 80-008/031-0
WILBON, J. Virgania Electric & Power Co 80/07/11 ip

--8007180327 LER 80-008/03L-0 on 800623, while performing periodic test 26 1. found air ejector monitor alarm setpoint above Tech Spec requirement Caused by instrument drift Alarm setpoint recaliby WILSON, J.L. Virginia Electric & Power Co. 80/07/11 2pp

V Operator Examinations

8007170348 Forwards revised, "Licensed Operator Requalification Program," in response to NRC 800328 request All training instructurs are required to participate in program to maintain proficiency SYLVIA.B R Virginia Electric & Power Co 80/07/15 ip

--8007170350 Revised. "Litensed Operator Requalification Program "
* Virginia Electric & Power Co 80/07/31 11pp

DOCKET 50-282 FRAIRIE ISLAND NUCLEAR STATION, UNIT 1 F Security, medical, emergency & fire protection plans

B007020235 Forwards request for limited revisions & addl info re 790323 plant safeguards contangency plan Encl withheld (ref 10CFR2 790) CLARK.R A Operating Reactors Branch 3 B0/06/10 2pp

8007110115 Forwards response to NRC 800618 questions re safe shutdown in event of fire MAYER.L D Northern States Power Co 80/07/08 3pp

9 Adjudicatory correspondence

B007100208 Ack receipt of NRC 800619 ltr to G Charnoff re nonreceipt of State of MN 800424 contentions Certificate of Svc encl DLSON, J. F. Minnesota, State of 80/06/23 3pp

8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp

8007250422 Amended Contentions 1 & 2 & withdrawal of Contention 3 Amend DO/200422 Amended Containtions 1 & 2 & withdrawal of Contents, request does not contain safety analysis re spent fuel storage & does not contain analysis of spent fuel pool expansion consequences Certificate of Bvc encl OLGON.JF, SENECHAL,M E. SPANNAUS,W Minnesota, State of BO/07/21 7pp

8007310493 Confirms ASLB request for hearing space at federal bidg in Baint Paul MN on 800806 to conduct 1-day prehearing conference re facility STEPHENS:C R Docketing & Services Branch 80/07/22 1p

8007230688 Comments stating no objection to admission of State of MN BOO721 Contentions 1 & 2 re cask drop accident & loss of water accident in spent feel pools Reserves rights re substance & validaty of contentions Centificate of Svc encl DARTH.C A Hearing Dranch 3 80/07/25 2pp

- 8007300463 Responds to State of MN 800424 suppl to petition to intervene & 800721 amended contentions Supporting documentation, notices of appearance of JE Siberg & DL Bernstein on behalf of util & Cortificate of Svc encl SILBERG. J E Northern States Power to SILBERG. J E Shaw, Pittman, Potts & Trombridge 80/07/25 24pp
- H General correspondence
- 8007310526 Responds to 800226 itr re-constituent concern about evacuation routes around facilities NRC & FEMA engage in program to upgrade emergency preparedness including evacuation planning DIRCKB, W J Office of the Executive Director for Operations 80/07/24 2pp
- --8007310528 Requests info re encl constituent ltr about evacuation routes around facilities
 BOSCHWITZ.R Senete 80/02/26 App
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D & Division of Licensing 80/06/11 42pp
- 8007030222 Notifies NRC of intention to ship radioactive math from facilities using Model HN-600 MAYER, L D Northern States Power Co 80/06/13 ip
- 8007010581 Responds to 800513 ltr re containment purge info by forwarding related correspondence MARTIN.R A Operating Reactors Branch 3 80/06/18 2pp
- --B0070105B3 Responds to E0NG 800513 questions LOCA dose calculations not completed Monitors are redundant, gas & particulate monitors provided, each giving isolation signal MUBDLF, D. Northern States Power Co. 80/06/03 ip
- ---8007010385 Requests preliminary evaluation of licensee response to NRC 791029 "Interim Position for Containment Purge & Vant Valve Operation Pending Resolution of Isolation Valve Operability." Generic Item B-24 Evaluation form encl REEVER, E A Operating Reactors Branch i (Pre 800428) 79/12/27 Opp
- 8007170076 Summary of 800520 meeting w/util re TOPROD fuel design MARTIN, R Operating Reactors Branch 3 80/07/01 7pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec thanges & license conditions PMR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D O Division of Licensing 80/07/02 69pp
- 8007280096 Advises of intention to ship radioactive matls from listed facilities using Package Model CNSI AL-93-90 MAYER.L O Northern States Power Co 80/07/03 1p
- 8007240388 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for GETR NOVAK, T.M. Assistant Director for Operating Reactors 80/07/08 200
- 8007280410 Forwards comments on NUREG-0577, "Fracture Toughness & Busceptibility to Stress Corrosion Cracking of Equipment Bupports," in response to NRC 800519 request Add1 analysis for stress Corrosion cracking is unnecessary MAYER.L O Northern States Power Co 80/07/21 5pp
- G Inspection reports. IE Bulletins & correspondence
- 8007070051 Forwards IE Insp Repts 50-282/80-04 & 50-304/80-07 on 800401-30 & notice of deviation HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/05/21 2pp
- --8007070056 Notice of deviation from insp on 800401-30
 * Region 3, Chicago: Office of the Director 80/05/16 1
- --B007070061 IE Insp Repts 50-282/80-06 & 50-306/80-07 on 800401-30
 No noncompliance noted failure to complete insp required by
 IE Bulletin 78-05
 BOYD, D. F. FEIERABEND, C. D. Region 3, Chicago, Office of the
 Director 80/05/14 7pp

- 8007020054 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/05/28 ip
- 8007210362 Forwards IE Circular 80-1J. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/05/28 is
- 8007010127 Forwards JE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps' No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 to
- B007240185 Forwards IE lmsp Repts 50-282/80-09 & 50-306/80-10 on 800501-31 No noncomplaence noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/06 2pp
- --B007240210 IE insp Repts 50-282/80-09 & 50-306/80-10 on 800501-31 No noncompliance noted Major areas inspected maint, surveillance security, radiation protection followup of licensee reported events & followup to IE circulars FEIERABEND.C D, BURGESS.R L, BOYD.D C Region 3. Chicago, Office of the Director 80/06/05 App
- B007010260 Responds to 1E Bulletin 79-17.Revision 1. "Pige Cracks in Stagnant Boratod Water Sys at FWR Plants " Visual insp required by Item 2(a) was completed on Unit 1 w/no corrective actions necessary QILBERTS,D E Northern States Power Co 80/06/09 ip
- B007010267 Responds to 1L Bulletin B0-06, "Engineered Safety Foature Reset Controls " Safety sys schematics reviewed Test demonstrating safety equipment remains in emergency mode after reset will be completed at next refueling outage GILBERTS,D E Northern States Power Co B0/Q6/09 2pp
- BOO7010549 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol (ontrol Sys (CVCB) Holdup Tanks "Chemical & vol control sys & components & gaseous & liquid waste disposal sys & components were reviewed GILBERTS,D E Northern States Power Co 80/06/09 2pp
- 8007160707 Responds to IE Bulletin 80-05 Review of chemical & vol control sys indicates holdup tank vulnerability to collapse Low suction pressure trip to be installed on holdup tank transfer & recirculation pumps by 810101 QILBERTS,D E Northern States Power Co 80/06/09 2pp
- 8007220212 Forwards IR Info Notice 80-24. "Evaluation of Contractor OA Programs " No written response required REPPLER, J 9 Region 3, Chicago, Office of the Director 80/06/10
- B007160182 Forwards IE Info Notice B0-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required KEPPLEM, J. G. Region 3, Chicago, Office of the Director B0/06/14
- 8007030043 Forwards IE Bulletin 80-19. "Possible Loss of Emergency Notification Sys (FNS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/18
- 8007020973 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Gooling & Natural Circulation Conldown " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/20
- B007140094 Ack receipt of encl 500517 ltr informing NRC of steps taken to correct violations noted in NRC 800972 ltr Encl withheld traf 100FR2 790)
 HIND, J. A. Region 3. Chicago, Rafequards Branch 80/05/24 1p
- B007170806 Forwards 1E Corcular 80-14, "Radioartive Contamination of Plant Demineralized Mater 3ys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Défice of the Director B0/06/24 to
- 8007140186 Ack receipt of 800A12 ltr informing NRC of steps taken to correct deviation noted in IF Insp Repts 50-282/80-06 & 50-308/80-07 forwarded by 800521 ltr Spnior resident inspector will follow remaining testing HEISHMAN R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/06/25 1p

- --8007140192 Responds to deviation noted in IE Insp Repts 50-282/80-04 & 50-306/80-07 forwarded by 800521 ltl Special insps of two out of four power operated relief isolation valve mater starters have been completed Two others will be performed GILBERTS.D E Northern States Power Co 80/06/12 lp
- 8007230336 | orwards | E Dulietin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Fither A or D Dutput Codes ' Written response required IE Circular 80-16 also onc! No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/2: 80/06/27
- 8007310105 Respunds to JE Bulletin 80-10 re contamination of nonradicactive sys Requested actions complete Specifics available at site OllBERTS, D E Northern States Power Co 80/07/03 Ip
- 8007150481 Advises that demonstration of ultrasonic insp method for detecting underclad cracking in reactor vessel noizle region for Unit 1 is scheduled for 800723 Unit 2 insp will take place during 1981 refueling outage

 MAYER.L Q Northern States Power Co 80/07/07 1p
- 8007250077 Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Concrete block walls are not in same design philosophy as design of Trojan plant masonry walls Walls were generally designed as partition walls or shield walls 011BERTS, D E Northern States Power Co 80/07/08 51pp
- 8007220090 Submits reply to IE Bulletin 80-08 re examination of containment liner penetration welds Review of Unit 1 revealed two deficient welds Further response will be sent bs 800810 GILBERTS, D E Northern States Power Co 80/07/10
- 8007220542 Submits reply to IF Bulletin 79-01B re environ qualification of Class IE equipment Qualified limit switches have been ordered 5 are scheduled for replacement during future ovidages Worksheets entil OllBERTS, D E Northern States Power Co 80/07/10 Spp
- 8007230211 Submits reply to IF Bulletin 79-17 re pipe cracks in borated water sys Visual insp required by bulletin was satisfactorily completed for Unit 1 No corrective actions GILDERTS, D E Northern States Power Co 80/07/10
- R Periodic operating reports & related correspondence
- 8007030178 Forwards "1979 Fiviron Monitoring & Ecological Studies Program Rept: Vols 1 & 2 WARD, E C Northern States Power Co 80/06/30 ip Program Rept WARD: E.C. N
- - Northern States Power Co 80/06/30 325pp
- --B007030193 "1979 Environ Monitoring & Ecological Studies Program Rept."
 - * Northern States Power Co 80/06/30 325pg
- 8007160538 Forwards monthly operating repts for June 1980 MAYER, L. O. Northern States Power Co. 80/07/11 1p
- --8007160562 Monthly operating tepts for June 1980 HUNSTAD.A A. Northern States Power Co. 80/07/01 9pp
- B Reportable occurrences, LERs & related correspondence
- 8007140660 RO 80-18 on 800629, steam generator 12 experienced minor primary-to-secondary leakage of about 0 006 gallons per minute Leakage was carefully monstored & showed increase facility is shutdown Couldown is planned TIERNEY,F P Northern States Power Co 80/07/01 lp
- 8007210437 Forwards LER 80-018/01T-0 MAYER: L B Northern States Power Co 80/07/1% ip
- --8007210444 LER 80-018/01T-0 on 800/01.unit was shut down due to leaking tube in hot leg of vertical steam generator 12.Westinghouse Series 5: Cause not stated Defective tube will be plugged HUNSTAD.A A Horthern States Power Co 80/07/15 2pp

- B007250340 RO B0-20 on B00715, w/Umit 2 at 1007 power & Unit 1 at cold shutdown, main generator separated from grid & one offsite source was lost, tripping reactor & coolant pumps Caused by severe electrical storm Transformer restored TIERNEY, F P Northern States Power Co B0/07/16 1p
- 8007290669 Forwards LER 80-019/03L-0 MAYER, L D Northern States Power Co 80/07/24 1p
- ~-B007290477 LER B0~019/03L-0 on B00430.two power range high power trip setpoints were over Tech Spec limit Caused by personnel error Rept reviewed & technicians cautioned HDNSTAD.A A Northern States Fower Co 80/07/24 ip
- DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR
- @ Inspection reports, IE Bulletins & correspondence
- B007070157 Forwards 1E Insp Rept 50-284/80-01 on B00529-30 No MELLY, F Region 4: Dellas, Office of the Director 80/06/20
- --8007070161 IE Insp Rept 50-284/80-01 on 800529-30 No noncompliance noted Major areas inspected security plan, alarm sys, keys, locks, hardware, communications, & surveillance Details withheld (ref 100FR2 790) CALDHELL, R A , KELLY, A F Region 4, Dallas, Office of the Director B0/04/18 ip
- DOCKET SO-285 FORT CALHDUN STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8007230530 Forwards addl info supporting security contingency plans & revised gage to Chapter 3 of site security plan Info & revision withheld (ref 10CFR2 790)

 JUNES, W C Omaha Public Power District 80/07/09 ip
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 putition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EIGENHUT: D Q Division of Licensing 80/06/25 89pp
- D Advisory Committee on Reactor Bafeguards reports & correspondence
- 7906220186 Summarizes ressonses to IE Bulletin 79-068 Coerating manuals Vone 100 Summarizes responses to 16 SULETIN V-OS Operat are being scrutinized Operational personnel are being trained Radioactive gases & liquids transfer lines are interlocked w/containment isolation &/or rediation signals TAM.P Division of Site Safety & Environmental Analysis 79/05/00
- P Operating license stage documents & correspondence
- B005190062 Notification of 800807 meeting w/util in Betheeds.HD to discuss analyses required & methods used in evaluating asymmetric loads WAGMER.P C Operating Reactors Branch 3 80/05/03 ip
- 8007030194 Forwards "Technical Evaluation of Electrical, Instrumentation & Control Design Aspects of Override of Containment Purge Valve Isolation & Other Engineered Safety Feature Signals for Fort Calhoun Nuclear Power Plant " CLARK.R A Operating Reactors Branch 3 80/06/04 3pp
- --8007030208 "Technical Evaluation of Electrical, Instrumentation & 1070/30/00 "Technical Evaluation of Electrical Instrumentate Centrol Design Aspects of Override of Containment Purge Valve Isolation & Other Engineered Safety Feature Signals for Fort Calhoun Nuclear Power Plant "HACKETI, D B. RADDEEVIC.J R., BRODERICK,N E EG&G, Inc URCL-15172 80/01/31 15pp
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENRUT.D G Division of Licensing 80/06/11 62pp.
- 8007020067 Summary of 800610 meeting w/util re work performed after 800507 meeting on asymmetric loads analyses WAGNER, P.C. Operating Reactors Branch 2 80/06/18, 5pp

- 8007010471 Forwards results of leak tate tests performed in response to Item 2 1 6 a of NUREG-0578

 JONES.W C Omaha Public Power District 80/06/25 1p
- ---8007010477 "Integrity of Sys Outside Containment Likely to Contain Radioactive Matl " * Omaha Public Power District 80/04/25 2pp
- 8007300078 Comments on proposed rule 10CFR50 re fire protection installation of stand pipe & hose station inside containment presents potential safety concern re boron dilution in event of pipe rupture of pipe rupture JONES, W.C. Dma Omaha Public Power District 80/06/25 3pp
- B007020857 Forwards "RCS Asymmetric Loads Evaluation Program," final rept in response to NRC 780125 ltr to PWR licensess re asymmetric LOCA loads C-E affidavit for withholding encl Proprietary version of App A withhold (ref 10CFR2 790) LUNDVALL.A E C-E Operating Plants Owners Group B0/06/30 2pp
- --8007020574 "RCS Asymmetric Loads Evaluation Program," final rept.
 - C-E Power Systems 80/06/30 20pp
- --8007020581 "RCB Asymmetric Loads Evaluation Program," final rept. C-F Power Sustems 80/06/30 300pp
- --9007020588 "RCS Asummetric Loads Evaluation Program," final rept, Vol
 - * C-E Power Bystems 80/06/30 300pp
- --8007020593 "RCS Asymmetric Loads Evaluation Program." final rept.App A, numerical results, evaluation of C-E fuel Nonproprietary version App B.Palisades fuel analysis.encl
 * C-E Power Systems 80/06/30 2App
- ---8007020399 "RCS Asymmetric Loads Evaluation Program." App C,pipe whip restraints & App D,plan for fracture analysis of util cold leg piping Final rept # C-E Power Systems 80/06/30 16pp
- --8007020600 "RCS Asymmetric Loads Evaluation Program." App E.ECCS analysis approach w/reduced area cholant channels in peripheral assemblies Final rept * C~E Power Sustems 80/06/30 9pp C-E Power Systems 80/06/30
- 8007080364 Provides update re evaluation of asymmetric loads per Jan 1978 request Several approaches considered to substantiate util position that safety problem does not exist Detailed discussion of plan due no later than 800901 JONES.H C Omaha Public Power District 80/06/30 2pp
- 8007170658 Confirms telcon re NRC contract personnel 800708-11 site visit to perform engineering analysis to identify vital areas at plant Contractors will require access to plant info & areas Proprietary info will be protected HAGNER, P C Operating Reactors Branch 3 80/06/30 2pp
- B007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EIBENHUT, D G Division of Licensing 80/07/02 67pp
- 8007240335 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08 personnel NOVAK, T M
- 80072B0530 Responds to NRC request for evaluation of plant RCS susceptibility to overpressurization events Mass input & savergy input analyses sections were re-evaluated using new valve discharge coefficients

 JONES.W C Omaha Public Power District 80/07/15 App
- Q Inspection reports, IE Bulletins & correspondence
- 8007020299 Responds to IE Bulletin 80~04, "Analysis of PWR Main Steam Line Break w/Continued Feedwater Addition" Reanalysis of reactivity increase will be submitted by 800516 Containment pressure response analysis is being performed by vendor JONES.W C Omaha Public Power District 80/05/08 2pp
- 8007020075 Forwards response to open Item 5.Encl 13 of IE Bulletin 79-018 H/o response JONES.W C Omeha Public Power Distract BO/05/13 1p

- 9007210187 Advises that response to IF Bullitin 80-12. 'Decay Heat Removal Sys Operability," will be delayed approx 3 whs.until 800630 JONES.W C Omaha Public Power District 80/05/21
- 8007020430 Responds to 1E Bulletin 80-09. High amotor Actuator Deficiencies "No ITT General actuators are installed at JONES, W.C. Omaha Public Power District 80/05/22 ip
- 8007020263 Forwards IE Info Notice 80-22 "Breakdowns in Contamination Control Programs" No written response required SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 80/05/28
- 8007210350 Forwards IE (incular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies 'No written response required BEYFRIT,K V Region 4, Dallas, Office of the Director 80 80/05/28
- 8007010033 Forwards IE Info Notice 80-23, "loss of Suction to Emergency Feedwater Pumps " No written response required SEYFRIT, N. V. Region 4, Dallas, Office of the Director 80/05/29
- 8007190165 Fowards IE Insp Rept 50-285/80-09 on 800505-08,12-15 & 22-23 No noncompliance noted

 MADSEN, G L Region 4, Dallas, Reactor Construction & Engineering
 Bupport Branch 80/06/04 2pp
- --8007150171 IE Insp Rept 50-205/80-09 on 800509-08,12-15 & 22-23 No JUVISOUP IE Insp Rept SU-200.000 on BUUSUN-00.12-15 & 22-2.

 moncompliance moted Major areas interested progless on IE

 Bulletin 79-14 startup preparation, reactor coolant pump

 cover stud detelloration & followop insp

 WESTERMAN.T F , RELLEY, D | Region 4, Dollas, Office of the

 Director 80/06/04 4pp
- 8007020419 Forwards response to IE Bullefin 80-05. "Engineered Safety Feature (ESF) Reset Controls " Summery of equipment deviations during resetting of engineered safety features actuation says enci JONES.W C Omaha Public Power District 60/06/06 Spp
- 8007220124 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required SEYFRIT, K. V. Region 4. Dallas, Office of the Director 89/04/10
- 8007160331 Forwards lE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required SEYFRITAK V Region 4, Dallas, Office of the Director 80/06/11
- B007110086 Ack receipt of 800%08 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 50-285/80-03 MADBEN G L Region 4, Dallas, Heactor Operations Nuclear Support Branch 80/06/20 ip
- -8007110096 Responds to NRC 800415 ltr re violations noted in 1E Insp Rept 50-285/80-03 Corrective actions Maint Procedure MP-RV-1 will be revised to indicate specific valves procedure applies to JDNCS.U C Omaha Public Power District 80/05/08 3pp
- B007240047 Forwards IE Circulat 80-15, "loss of Reactor Contant Pump Cooling & Natural Circulation Couldown" No whitten response required BEYFRIT, K V Region 4, Dallas, Office of the Director B0/06/20
- 8007180112 Ack recipt of 800613 ltr informing NRC of steps taken to correct violation noted in IE linsp Rept 50-280/80-10 BROWN,0 D Region 4, Dallus, Fuel Facility & Materials Safety Branch 80/07/01 lp
- --8007180122 Responds to NRC 800523 ltr re violation noted in IE Insp Rept 50-285/80-10 Corrective actions technicians reinstructed on requirement to conduct full survey Fire door alarm repaired JONES, W.C. Omaka Public Power District 80/06/13 Ppp
- 8007230558 Advises NRC of inspirosults of containment recirculation piping check valve.51-159 Valve was found in "like new" condition w/no valve degradation observed & returned to operation w/n need for maint JONES, W.C. Omeha Public Power District 80/07/09 ip

07310324 Updates into re admittance of NRC inspectors to facility Discusses entrance procedules & types of identification required Requests site orientation SELYFRIT.K V Region 4. Dallas. Offsie of the Director 80/07/14 2pp

07280601 Forwards summary of irradiated fuel anse following Cycle 5 operation performed during 1980 refueling outage No major abnormalties observed in six irradiated fuel assemblies inspected No failed fuel pins were observed JONES, W.C. Omaha Public Power District 80/07/15 3pp

Periodic operating reports & related correspondence

07170374 Forwards monthly operating rept for June 1980 JONES, W.C. - Omaha Public Power District - 80/07/09 ip

8007170379 Northly operating rept for June 1980 MICKLE, B. J. Dmaha Public Power District 80/07/09 9pp

Reportable occurrences. LERs % related correspondence

)7070375 Forwards LER 80-011/03L-0 STEVENS, S.C. Omaha Public Power District 80/05/25 1p

3007070385 LER BO-011/031-0 on B00528.during 1980 refueling outage type B & C containment leak rate tests.total leakage exceeded 0 6La limit Gussed by leaking fuel transfer tube, electrical, mechanical sleeve & piping penetrations CORE.M. CONNOLLEY, J | Omaha Public Power District | 80/06/16 7pp

07240130 Forwards LER BO-016/03L-0 STEVENS.S C Dmaha Public Power District 80/07/21 ip

007240134 LER BG-014/03L-0 on 600621.weld on suction side of pump CH-18 in demineralized water flush line crarked Caused by vibration of piping in svc Crack was ground out & rewelded using certified procedure & line tested JEMELL.W A Omaha Public Power District 40/06/25 App

KET 50-286 INDIAN POINT STATION, UNIT 7 Security, medakah, amergancy & fire protection plans

7030294 Forwards security Contingenty plan lan withheld (ref 100FR2 790) AYNE, J P Powe: Authority of the State of New York 80/06/20 ip

7290735 Notifies NRC that 791109 t 800221 revised emergency plans ill become effortive on 800801 t procedures to implement lan will become effective within 90 days of plan ffective date
AYNE.JP Pawer Authority of the State of New York 80/07/24 ip

The state of the s

Adjudicatory correspondence

7310243 Forwards Commission B00527 memorandum & order containing ecisions on UCS 780502 petation for reconsideration of 80413 memorandum & order UCS 771104 petition sought action of fire protection for electrical cables ISENHUT, D.G. Davision of Licensing 80/06/25 89pp

7090215 Order granting extension until 800725 for Commission to possible whether to review AtAB-436 & portions of ALAB-541 OYLE, J.C. Office of the Secretary of the Commission 80/07/07

7220160 Response in apposition to NBC motion for disqualification of lairman Hendrin re UCS 740917 pritition seeking shutdown of cility Motion failed to show blus defined by Supreme Court i Withrow vs Larkin proceeding
ATT.C M Power Authority of the State of New York
RANDENBURG, B I Consolidated Edison Co of New York 80/07/08

7140363 Order granting extension until 800801 for Commission to lect whether to review ALAB-4.16 % relevant portions of AB-561
PV.E.J. C. Office of the Secretary of the Commission 80/07/10

BOO7290522 Motion for reconsideration of Commission BOO530 order reportion instituting adjudicatory hearing before ABLB Interim Operations Task Force rept. SECV-283, eliminates basis for commencement of investigation
BRANDENBURG, B L Consolidated Edison Cu of New York
Power Authority of the State of New York BO/07/25 12pp

H General correspondence

E00721020B Responds to encl 800418 ltr to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities currently operating or planned for operation Village Voice news article encl
DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/21 10pp

B007170259 Responds to B00206 ltr re status & responsibilities for emergency preparedness in facility environs FEMA has lead responsibility in offsite emergency planning GRIMES, B K Emergency Preparedness Program Office 80/07/07 2pp

I Financial information

BO072B0461 Forwards Annual Financial Rept 1979
BAYNE.J P Power Authority of the State of New York 80/07/24 1p

--8007280463 Annual Financial Rept 1979

* Power Authority of the State of New York 80/07/24 41pp

O Advisory Committee on Reactor Safeguards reports & correspondence

BOO722030B Provides summary of BOO507-0B meeting w/utils re core melt accident sequences Utils appear to expect NRC to resolve problems & do nothing to mitigate consequences of Class 9 accidents CATTON: 1 California, Univ of, Los Angeles BO/05/10 App

P Operating license stage documents & correspondence

BOOM2404BO Forwards add1 info re review of unresolved safety issues, trip rept of Lessons Learned implementation team. A task action plan in view of high population density surrounding plants

DENTON, H R Office of Nuclear Reactor Regulation, Director BO/04/09 33pp

8007220094 Responds to 800609 telcon re NRC concerns over operability of control room ventilation sys in emergency mode Initiating air flow measurements in emergency mode to determine control room habitability is not in accordance w/ectual plans GRIER/B H Region i, Philadelphia, Office of the Director 80/06/11 ip

8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removel capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance
EISENHUT, D 6 Division of Licensing 80/06/11 62pp

8007100393 Summary of B00520 Technology Exchange Meeting 3 w/utils in Bethesda.MD to discuss accident mitigation features for power plants LCNG, J K Division of Systems Integration 80/06/12 75pp

8007140182 Submits lept of task force on interim operation of facilities Rept includes accident risk considerations, social & economic impart considerations & summary of public comments

HANRAHAN, E. J. Diffice of Policy Evaluations BICKWIT, L. Office of the General Counsel BECY-80-283 80/06/12 68pp

--BO07140170 Summarizes views of Economic Regulatory Administration, Div of Power Supply & Reliability re electric sys reliability impact of operation of facilities as described in NRC BO0428 ltr HEINFR.R E Energy. Dept of 80/05/15 4pp

8007100103 Forwards Amend 30 to License DPR-64, safety evaluation & notice of issuance & availability
VARGA/S A Operating Reactors Branch 1 80/06/13 3pp

--8007100104 Amend 30 to License DPR-64, adding surveillance requirements for containment vent & purge sys VARGA, S.A. Operating Reactors Branch 1 80/06/13 9pp

---B007100110 Safety evaluation supporting Amend 30 to License DPR-64
* Office of Nuclear Reactor Regulation, Director 80/06/13 6pp.

- VARGA.S A Operating Reactors Branch 1 80/05/13 2pp
- B007010110 Notification of B00625 meeting w/utils & Sandia Labs in Bethesda.MD for presentation of overview of facilities risk study Agenda encl ISRAEL.5 L. Reliability & Risk Assessment Branch B0/06/16 Jpp
- 8007110557 Summary of 800530 meeting w/util in Bethesda.MD re status of action plan OLSHAN.L N Operating Reactors Branch 1 80/06/23 3pp
- 8007010608 Notification of 800617 meeting w/utils in Dethosda.MD to discuss containment structural response, failure pressures & failure modes for facilities as described in NRC 800410 ltr to Comm Ed Reactor Systems Branch 80/06/26 2pp
- 8007180044 Forwards Amend 31 to License DPR-64.safety evaluation & notice of issuance & availability
 VAROA.S A Operating Reactors Branch 1 80/06/27 3pp
- --B007180046 Amend 31 to License DPR-64, revising Tech Specs to add mid-cycle insp of one steam generator & end-of-cycle insp of all four steam generators VARGA:S A Dperating Reactors Branch 1 B0/06/27 13pp
- --8007180051 Safety evaluation supporting Amend 31 to License DPR-64 * Operating Reactors Branch 1 80/06/27 9pp
- --8007180053 Notice of issuance & availability of Amend 31 to Liconse VAROA.9 A Operating Reactors Branch 1 80/06/27 2pp
- 8007210055 Requests that util submit revised schedule & justification for completion of ATWS mods within 30 days Util is requested to improve upon Fall 1982 completion date because of risk represented by facility VAR9A:S A Operating Reacturs Branch 1 80/06/30 2pp
- 8007210498 "Evaluation of Impingement Losses of White Perch at Indian Point Nuclear Station & Other Hudson River Power Plants " VAN MINKLE, W. RARNTHOUSE, L. W. KIRK, B. L. Oak Ridge National Laboratory FIN B-0423 NUMEQ/CR-1100 80/06/30 175pp
- B0070B0367 Provides method by which derivative action was removed from proportional integral derivative controller par B00616 ltr.

 Item II K 3 9 responding to TMI-related requirements Feature eliminated by placing rate control to min BAYNE.J P Power Authority of the State of New York B0/07/02 ip
- 8007170241 Forwards request for add1 info re backfitting of severe accident mitigation features Response requested within 30 NOVAK.T M Assistant Director for Operating Reactors 80/07/02
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 69pp
- 8007170598 Summary of 800625 meeting w/Pickard, Lowe & Garrick, Inc re risk study including modeling for plume tragectory, containment event tree & modeling, use of plant data & consideration of external events IBRAEL. B L Reliability & Risk Assessment Branch 80/07/07 App
- 8007230646 Summary of 800907-08 technology exchange meetings w/utils in Chicago. IL re core melt accident sequences & associated phenomenology for facilities NRC perceives real urgency to for answers to key technical questions MEYER. J F Reactor Systems Branch 80/07/09 12pp
- B007070101 Notification of change in location B00625 meeting w/util in Bethesda,MD to discuss re-evaluation of operational GA BELKE,W L Quality Assurance Branch 80/07/17
- 8007300092 Notification of 800724 meeting w/util in Bethesda:MD to discuss sys interactions study OLSHAN,L N Operating Reactors Branch 1. 80/07/17 2pp
- 8007290728 Forwards Revision 2 to steam generator operating history questionnaire & attached supplementary info BAYNE, J.P. Power Authority of the State of New York 80/07/23 50рр

- 8007310514 Summary of 800625 meeting wrutil re GA program
 OLSHANIM, U. N. Operating Reactors Branch 1 80707773 App
- 8007290580 formards comments on NUMI 6 02/7 re bondia tabs andlyses on OUT 290380 Towards comments on Nord 6 027' or sandia cas sharper potential susceptibility or strain generator teacher contant pump supports to low fraction laughboss & fultitle failure Analyses but technically justified BAYNE, J.P. Phour Authority of the State of New York. 60/07/4
- G. Inspection reports: 16 Bulleting * correspondence
- 8007170606 Forwards IE Insp Rept 50 286280 04 on 800 112 14 No noncompliance moted CARLSON.R T Region 1, Philadelphia (1991) of the Director ՝ Ձրր
- --B00/170614 IF Insp Rept 50 286/80 04 on 800312-14 No nontempliance DD7/0611 II (REP REST SO 13/6/14/ 04 on 1606/16-14 An non-implia-noted Major areas inspected fire provintion/protection program pertaining to fire protection mode in Amound 24 to License DPR-64 KDLTAY-P S Region i, Philadelphia, Office of the Director EBNETER S D Region i, Philadelphia, Reactor Construction & Engineering Support Dianch 80/05/16 App
- B007020154 Forwards IE Info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required GRIER,B H Region 1 Philadolphia. Office of the Director B0705/28 ip
- B007010303 Forwards IE Info Notice (10 P.), "tost of Sultion to Emergency Feedwater Pumps" No written response required GRIEFAITH Region 1. Philadulphia (Office of the Director 80/05/29)
- 8007180111 Forwards reply to (E Butletin 80-05 te various condition resulting in damage to holding tanks Results of review did not identify any corrective artison required EARLYP J. Power Authority of the State of New York. 180/06/07 4pp
- 8007210599 Forwards IC Info Notice UG 25, "Evaluation of Contractor GA Programs" No written response toquired GRIEROB II Region 1, Philadelphia. Office of the Director 50706/10 Ip
- 8007160358 Forwards II Info Notice 80-27. "Degradation of Reactor Comlant Pump Study " No specific action of response required GRICR. B 14 Region to Philadelphia Office of the Disector 00/06/11
- 8007170316 Forwards response to IF Dulletto 80-06, "Ingineered balety Feature (ESF) Resol Controls " All safety related equipment remains in emergency mode upon result of the struction signal except as listed BAYNE; J.P. Power Authority of the State of New York. B0706/17 60 p
- 8007020687 Forwards IE Bulletin 60 15 "Possible Lune of Emorgeory Notification Sys (ENS) W/Lors of Definite Power" Written response required REFER B Region 1. Philadelphia, Defice of the Director 80706/18 | 1p
- 8007020491 Forwards If Carculat 80 lb. "Loss of Rearter Lociant Rump Copling & Natural Circulation Couldown " No written response required ORIER, B.) Region to Philadelphia. Office of the Director 80/06/20 ip
- B007180597 Responds to IF Bulletin 80 09, "Hydramator Actuator Deficiencies" Examination of project valve drawings showed no hydramotor actuators furnished BAYNE, J.P. Power Authority of the State of New York | 80706790
- 8007160726 Forwards IC Circular 80 14 "Redicartive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORICR 8 H Region 1, Philosophylas (Office of the Director 80/06/24) Contamine, ORIER B H R
- 8007210222 Forwards It Info Hotice SG 24, "Low Level Radwaste Burial Criteria" No written response required ORIFR B H Region 1. Philadelphia: Office of the Director 80704/25 ip

- 8007140347 Forwards response to NRC request for addl info re inservice insp program

 BAYNE, J.P. Power Authority of the State of New York - 80/06/27
- 8007230156 Forwards IE Bulletin 80-16, "Putential Misapplication of Rosemount Inc Models 1151 % 1452 Pressure Transmitters W/Either A or D Output Codes," Written response required IE Circular 60-16 also enti No written response required GRIER.B H. Region 1, Philadelphia, Office of the Oirector TE Circuis.
 GRIER, B.H. Re
 27 2pp
- B007210456 Responds to IE Bulletin B0-10 re potential nonradioattive sys contamination % uncontrolled radioattive releases. Actions required by Items 1 & 2 immpleted. 20LLA-S S Power Authority of the State of New York. 80/07/03 Ip.
- 8007250313 Ack receipt of 800613 ltr informing NRC of steps taken to correct violations noted in IS Insp Rept 50-286/79-29
 ORIER.D H. Region I. Philadelphia. Office of the Director 80/07/03 | Ip
- -8007250317 Responds to NRC B00514 ltr re violations noted in IE Insp Rept 50-286/79-79 Corrective actions personnel instructed to evaluate surveillance results more carefully Program instituted to resulve discrepancies ZULLA/S S Power Authority of the State of New York B0/06/13
- --8007250325 Forwards IE Insp Rept 50-286/79-29 on 791125-800119 & notice of violation GRIER.B II Region L. Philadelphia, Office of the Director 80/05/14 2pp
- --8007250329 Notice of violation from insp on 791125-800119 * Region & Philadelphia, Office of the Director 80/ 80/05/05 2pm
- --8007250302 le insp Arpt 50-286/79-29 on 7911/9-800119 Noncompliance noted failure to evaluate surveillance results properly & to resulve discrepances noted during containment insp KISTER, H. Rogion i, Philadelphia, Roactor Operations Nuclear Support Branch REBELOWSKI T., JOHNSON J. Region i, Philadelphia, Office of the Director 80/05/05 20pp
- R Periodic operating reports & related correspondence
- 8007170363 Forwards "Annual Environ Monitoring Rept.Part U Radiological CANILL, W. J. Consolidated Editon Co. of New York 80/05/30 1p
- ---8007170765 "Annual Environ Monitoring Rept, Part B Radiological Rept " * Consolidated Edison Co. of New York 80/06/30 Abps
- 8007150669 Submits deally fish counts from intake screens for June 1980 MONTL-W A Consolidated Edison Co of New York B0/07/10 17pp
- 9007210374 Forwards monthly operating rept for June 1980 ZULLArS S Power Authority of the State of New York B0/07/14 to
- --8007210377 Monthly operating rept for June 1980 CBNNELL.C Power Authority of the State of New York 80/07/02
- 8007210473 Forwards util 800A13 ltr & "Guarterly Rept on Seismic Monitoring Nutwurk in Vicinity of Indian Point,NY. Con Ed Project Dec 1979-Feb 1980 " DAVIS: J. P. Connelidated Edison Co. of New York 80/07/14 2pp
- 8007220923 Forwards "Daily Count from Intake Screens for June 1980 " ZARAKAS.P Consolidated Edison Co of New York 80/07/15 ip
- --B007220324 "Daily Count from Intake Screens for June 1980 " * Consultdated Edison Co. of New York 80/07/15 4pp
- 5 Reportable occurrences. Lifts & related correspondence
- B004240212 PNO~1-80~35A oil sumples from hydraulic control mys storage tanks & both main feed pumps found out of specs for particulates increase in main feed pump oil micros particle size possibly due to filter overload & breakdown MCCABE.E. BRUNNER.E. Region 1. Philadelphia, Office of the Director 80/03/07 2pp

- 8007020145 PND-1-80-093 on 800617, util workers Union Local 1-2 authorized strike on 800618 Senior operators are excluded Required IE prestrike insps have been completed GREENHANE G . RRUNNER. E J Region 1. Philadelphia. Office of the Director 80/06/17 ip
- 8007150081 PND-1-80-074 on 800624, while performing maint on incore detector drives, three individuals sustained possible whole body radiation exposure & internal & external radioactive contamination Awaiting dosimetry results NIMITZ.R , KNAPP.P . HANTIN.T Region 1. Philadelphia. Defice of the Director 80/06/24 2pp
- 8007010452 Submits info re 800624 radiation exposure in excess of permissible limits During routine containment entry to effect repairs to E drive, repair team withdrew severed drive cable wincore detector Contamination within limits IULLA.S B Power Authority of the State of New York 80/06/25
- 8007010448 Forwards LER 80~004/017-0
 ZULLA, S 5 Power Authority of the State of New York 80/06/27 ip
- --- B007010455 LER 80-006/01T-0 on 800614. while operating at full power. Follows Len Bu-Good 11-0 on Books 14, while operating at fill power test of control room air filtration sys indicated total filter flow above Yeck Spocs Coused by drifting of Allen-Bradley BO2T-A damper Bys balanced GUMBLE.F W Power Authority of the State of New York 80/06/27
- 8007210019 Confirms 800627 telcon re util actions following 800624 personnel exposure incident Approved protedure for maint & repair of incore flux monitoring drive components will be implemented by 800711 & addl guidance by 800702 GRIER. B H Region 1, Philadelphia, Office of the Director 800702 GRIER, B H Re BO/06/27 200
- 8007080350 Forwards LER 80~008/03L-0 ZULLA.8 5 Power Authority of the State of New York 80/07/02 ip
- --8007080354 LER 80-00B/03L-0 on 800403, while operating at 60% power. 307080394 LER 80-908704L-0 on substituting as easy producting power to 138 kV feeder was lost Dissal generators 32 & 33 were activated Caused by transmission tower ground lead which fell across feeder after being struck by lightning CUMBLE.F H Power Authority of the State of New York 80/0 80/07/02
- B007080355 Forwards LE' 80-009/03L-0

 ZULLA, S B Power Authority of the State of New York 80/07/02
- -8007080362 LSR 80-009/03L-0 on 800604, while operating at 100% power, boric acid heat tracing test 3PT-08 indicated no continuity on circuit 39 Caused by failed Chromolox 120 volt.500 watt strip heator Heater replaced * Power Authority of the State of New York 80/07/02 ip
- 8007140333 Responds to concerns recontrol room ventilation systoperability in emergency mode noted in LER 80-006/QI-O Dampers readjusted charcoal filters replaced & thyroid dose rate calculations reanalyzed ZULLA, B Power Authority of the State of New York 80/07/03 2pp
- 8007290052 RO on 800624, poisonnel overexposed to radiation Occurrence re-enacted Rept expected soon from dosimetry contractor Intake evaluation completed Results indicate no exposure in excess of 10CFR2O 103 limits W/o encl ZULLA, 8 8 Power Authority of the State of New York 80/07/11
- B00721041B Provides supplemental info to B00625 & 0711 ltrs ra B00624 overexposure, in rusponse to NRC request Encl table provides radiation exposure history In all cases, radiation exposure is within legal limits for annual exposure TULLA.S S Power Authority of the State of New York B0/07/16
- 8007290098 PNO-1-80-101 on 800715, plant tripped from 100% power due to water leakage on coolant pump penetrations Possible damage to coolant pumps & penetrations is being damage to contant pumps a penetrations is vering investigated REBELDMEKI.T , MARTIN.T , BRUNNER.E Region i, Philadelphia, Office of the Director 80/07/16 ip
- 8007310424 Forwards LER 80-010/03L-0
 ZULLA, S S Power Authority of the State of New York, 80/07/25 ip

- --8007310430 LER 60-010/03L-0 on 800629, while operating at 100% power, upon completion of trip test operator was unable to reset trip lever on 32 diesel generator Caused by unsecured trip latch spring having lost attaching screw PABSMAN, N A Power Authority of the State of New York 80/07/28
- T Hearing transcripts on non-antitrust matters
- 8007140084 Unofficial transcript of 800626 briefing on recommendations of Indian Point Task Force in Washington,DC Pp 1-62 Viewgraphs enci * Commission 80/06/26 64pp
- 8007240164 Transcript of 800711 public meeting in Washington, DC Pp 1-6 Commission 80/07/11 6pp
- 8007250347 Unofficial transcript of 800717 discussion on Indian Point in Washington DC Pp i-72 Draft memorandum & order encl * Commission 80/07/17 80pp

V Operator Examinations

B007080303 Notifies NRC of commitment to enroll employees who do not sucessfully complete any portion of reactor operator exam in accelerated requalification program Declines to commit employees to Item B i f of NPC B00328 request
BAYNE, J. P Power Authority of the State of New York 80/07/01

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

- F. Becurity, medical, emergency & fire protection plans
- 8007010205 Forwards security plan re in-transit requirements for BNM of low strategic significance Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/05/24 ip
- 8007230090 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security may be resonnel at factities EISENHUT, D & Division of Licensing 80/07/11 2pp

O Adjudicatory correspondence

- 8007140461 Statement of Board of Commissioners' position in opposition to radwaste transportation through Gaston County, NC Urgas transportation via Interstates 77 & 85 Encourages expending energy & money for recycling W/correspondence # Gaston County, NC 89/04/28 6ipp
- --B007140473 Forwards addl comments to Gaston County Board of Commissioners' position opposing spont nuclear fuel shipmont through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GABTON.H B. Gaston County.NC B0/04/25 2pp
- 8007310243 Forwards Commission 800327 memorandum & order containing DO/310243 FORWARDS COMMISSION BUODS? MANGAINMEN & Gruen to the decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action to fire protection for electrical cables.

 EISENHUT, D Q Division of Licensing 80/06/23 87pp

P Operating license stage documents & correspondence

- 8007240208 Forwards B&W licensees' responses to 790707 request for TOTAL TOTAL TOTAL BOWN INCENSESS TO PROPRIES TO PROVE TO PROVISE OF SCHOOLS FOR THE PROPRIES TO PROVIDE TOTAL THE PROPRIES OF FORMWATER & TURBINE TRIP REVIEW SHOULD BE COMPLETED BUILDING & Orders 79/10/24 1p.
- 8007140397 Refers to 800701 Itr requesting info re insp of fuel assembly hold-down springs. Reviewed concern & documented results in 800606 ltr forwarding RD 50-269/80-15 & safety avaluation No further info required PARKER, W D Duke Power Co 80/06/08 lp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance.

 EIBENHUT.D G. Division of Licensing 80/06/li A2pp

- 9007160429 Forwards Amends 83,83 & 80 to Licenses DPR-38,DPR-47 & DPR-35, respectively, safaty evaluation & notice of issuance & availability availability REID:R W Operating Reactors Branch 4 80/06/12 2pp
- ~-8007140434 Amends 83,83 & 80 to titrenses DPR-38,DPR-47 & DPR-55, respectively, revising Tech Specs to support operation of Unit 2 at full rated power during Cycle 5 REID,R H Operating Reactors Granch 4 80/06/12 23pp
- ~-B007160445 Safety evaluation supporting Amenda 83.83 & 80 to Licenses DPR-38.DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 80/06/12
- --8007160453 Notice of issuance & availability of Amends 83,83 & 80 to Lirenses DPR-38,DPR-47 & DPR-55.respectively REID,R W Operating Reactors Branch 4 80/06/12 2pp
- 8007070p35 Forwards safety evaluation re postulated fuel handling accident inside containment REID.R W Operating Reactors Branch 4 80/06/24 2pp
- --8007070039 Safety evaluation re postulated fuel handling accident inside containment Dperating Reactors Branch 4 B0/05/24 1p
- 8007020575 Summarizes actions undertaken by util re inadequate core cooling NRC review of previously submitted operator guidelines should be completed prior to util committing to install new instrumentation
 PARKER, W D Duke Power Co 80/06/27 2pp
- B007080223 Advises that response to NUREG-0667 is in final review & will be submitted by 800723
 PARKER.W O Duke Power Co 80/07/01 ip
- 8007210004 Forwards questions re fuel assembly holddown spring insps & safety significance of operating w/broken springs in core Requests response within 60 days NDVAK, T.M. Assistant Director for Operating Reactors 80/07/01
- B007110294 Forwards application to amend Tech Specs to incorporate test frequency requirements of 10CFR30.App J
 PARKER.W Q Duke Power Co 80/07/07 259
- --8007110331 Application to amend Tech Spec 4 4 1 2 5 incorporating test frequency requirements of 10CFR50, App J Existing Tech Spec unacceptable for oxtended cycle lengths for which current & future cycles are/will be licensed * Duke Pawer Co 80/07/07 2pp
- 8007230708 Provides info re new ofc titles, positions & assignments of parsonnel resulting from 800428 reorganization of Ofc of Nuclear Reactor Regulation Assistant Director for Operating Reactors 80/07/10
- 8007150575 Forwards "Generic Startup Physics Test Program, Jul 1980 " Rept supersedet in entirety repts submitted 800804 & 11 PARKER, W O Duke Power Co 80/07/11 ip
- --8007150583 "Generic Startup Physics Test Program, Jul 1980 " Rept supersedes in entirety previously submitted repts forwarded by 800604-11 ltrs 4 Duke Power to 80/07/31 14pp
- 8007280437 Forwards proposed revision to Tech Specs & amend to OL Proposal clarifies, inspired equipments after financy to secondary leak specified in Toth Spec 4 17 4 Requests that NRC review & approve proposal in timely manner PARKER, W G Duke Power Co 80/07/15 3pp
- --8007280438 Proposed Tech Spoc revision Page 4 17-3 clarifying insprequirements after primary to secondary leak
 * Duke Power Co 80/07/15 & 2pp
- 8007310551 Forwards NUREG-1368 & NUREG 1367 detailing development of checklist for evaluating maint tost & ralibr procedures used in nuclear plants Ack otil cooperation in study W/o encls

 encls

 EMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support

 Branch 80/07/15 ip
- 8007280427 Forwards proposed fech Spec 3 1 2 revision.changing pressure temp limits Class I & III license amend fee encl PARKER.H O Duke Power Co 80/07/22 3pp

- --8007280430 Proposed Tech Spec 3 1 2 revising pressure temp limits * Dute Power Co 80/07/22 7pp
- 8007280544 Forwards response to recommendations in NUREG-0667, "Transient Response of DEW Designed Reactors ' Based on reviews no action is necessary for majority of recommendations FARKER, W.O. Duke Power Co. 80/97/23 70pp
- G. Inspection reports. It Bulletins ? correspondence
- 8007240122 Forwards IE Info Notice 80-20 "Lose of Docay Heat Removal Capability at Davis-Bosse Unit 1 While in Refueling Node" No response required G'RE[LLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- B007100144 Forwards | E | Insp | Repts | 50-269/80-14, 50-2/0/80-09 & 50-287/80-09 on | 800/828-0501 | No | Honcompliance | noted | MURPHY.C | Region | 2. Atlanta, | Roactor | Construction | & Engineering | Bupport | Branch | | 80/05/27 | | Ppp |
- --B007100151 IE Insp Repts 50-269/80-14,50-270/80-09 & 50-287/80-09 on B0042D-0501 No nancompliance noted Major areas inspected fire protection/prevention CONLOBLT E Region 2. Atlanta. Reactor Construction & Engineering Support Branch MillER,W H Region 2. Atlanta, Office of the Director 80/05/23 10pp
- 8007020204 Forwards 1E Info Notice 80-22. "Breakdowns in Contamination Control Programs" No written response required O'REILLY, J.P. Rigion 2, Atlanta, Office of the Director 80/05/28
- 8007210449 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/03/28 to
- 8007010213 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/05/29
- B007F2004B Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs" No written response required O'REILLY. J.P. Region 2. Atlanta. Office of the Director B0/06/10-200
- 8007010069 Forwards update of info to 791026,1106,1207 & 800124 ltrs in response to 1E Bulletin 79 14,1tems 2 & 3
 PARKER, W Q Buke Power Co 80/06/11 App
- 8007160255 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Fump Stude " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11 ip
- 8007020763 Forwards IE Dulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/18 ip
- 8007020459 Forwards IL Circulat 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007150015 Ark receipt of IC lines Repts 90-269/80-18,50-270/80-13 & 50-287/80-12 on 800513-15 No proprietary info PARKER, N O Duke Power Co 80/06/23 ip
- --B007150019 Forunids 1E Insp Repts 50-269/80-18, 50-270/80-13 & 50-297/80-12 on 800513-13 No nuncompliance noted NURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/29 2pp
- --8007150021 IE insp Repts 50-269/00-18,50-270/80-13 & 50-287/80-12 on 800913-15 No noncompliance noted Najor areas inspected structural tuncrete for standby shutdown faculity HARRIS.J R Region 2. Atlanta, Diffice of the Director Construction & Engineering Support Branch 80/05/air 3pp

- G007170104 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required D'REILLY. J P Region 2, Atlanta, Office of the Director 80/06/24 1p
- 8007180533 Responds to 1E Bullotin 79-03A. "Longitudinal Weld Defects in ASMF SA-312, Type 304 Stainless Stoel Pipe " No Type 300 piping in use for pressure piping Future use of piping will be reviewed PARKER. W 0 Duke Power Co 80/06/24 1p
- 8007220192 Advises that hanger insp required by IE Bulletin 79-13 was not addressed in response to bulletin Hangers visually inspected as part of response to IE Bulletins 79-02 & 79-14 PARKER, W O Duke Power Co 80/06/27 1p
- B007230235 Forwards IE Bulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1192 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-14 also encl No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/27
- 8007220245 Forwards response to IE Bulletin 80-08 Approx 53 ponetrations concerned Weld defects classified as inclusion One repaired for cracking Design meets all requirements of ASME PARKER.W O Duke Power Co 80/07/01 4pp
- 8007140463 Forwards 800704 Revision 2 to response to IE Bulletin 79-01B, "Environ Qualification of Class IC Equipment" Replaces previous submittal & 800519 revision entirely Includes corrections of minor errors THIES.A C Duke Power Co 80/07/07 34pp
- 8007250166 Forwards response to Items 1.2a & 3 of IE Gulletin 80-11.
 "Masonry Wall Design " Lists all masonry walls which are in proximity to or have attachments from safety-related piping or equipment
 PARKER. H O Duke Power Co 80/07/07 21pp
- BCC731053B Provides shipping instructions for deficient steam generator mainway bolts set aside for independent metallurgical analysis per NRC BCC627 request Requests notification when bolts have been shipped LEHIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/0//18 ip
- B Reportable occurrences, LERs & related correspondence
- 8007070319 Forwards LER 80-018/03L-0 PARKER. H D Dake Power Co 80/06/30 3pp
- ---8007070323 LER 80-018/03L-0 on 800601.high pressure svc water pump B declared inoperable due to motor cooler tube leaks Caused by erosion & corrosion resulting from constant flow of lake water Leaking tubes soldered & cooler pressurized PHILPOTT.F T Duke Power Co 80/06/30 1p
- 8007180417 Advises that 800610 incident involving loss of power to reactor protection sys Channel B does not constitute RO, as reported on 800611 Review indicates Tech Spec 3 5 1 requirements were met Input fuse blew due to loose wires PARKER, W O Duke Power Co 80/07/10 2pp
- 800/210607 Forwards LER 80-010/01T-0 PARKER, W O Duke Power Co 80/07/11 3pp
- --B007210617 LER 80-010/017-0 on B00614, at 100% full power, increase in condensor air ejector off-gas count rate indicated that once-through steam generator A had developed tube loak Probably caused by racent main steam atop valve testing PHILPOTT,F T Duke Power Co B0/07/11 ip
- 8007/220963 RD on 800709, high pH excursion in oil collection basin discharge was discovered Caused by water discharged Prom Upper sump of safe shutdown facility const Const personnel advised of discharge limits
 PARKER, W O Duke Power Co 80/07/16 2pp
- B007290640 LER 80-007/01T-0 on 800710, during normal operations, breaker which supplies control power A phase of emergency power switching logic tripped, due to burned but relay coil Caused by coil clearing contract failing to clear PHILPOIT, FT Duke Power Co 80/07/24 ip
- 8007290635 Forwards LER 80-009/01T-0 PARKER, W O Duke Power Co 80/07/24 3pp

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

Inspection reports, IE Bulletins & correspondence

8007180251 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/24 lp

- 8007310163 Forwards IE Insp Rept 80-288/80-02 on 800130-31 No noncompliance noted BOOK, H E Region 5, Ban Francisco. Fuel Facility & Materials Safety Branch B0/06/26 2pp
- ~-BOO7310168 IE Insp Rept 50-288/80-02 on 800130-31 No noncompliance noted Major areas inspected tour of facility, examination of logs & records of surveys, monitoring & personnel exposure HENBLAWSKI,F A , CURTIS,J R Region 5, San Francisco, Office of the Director BOOK,H & Region 5, San Francisco, Fuel Facility & Materials Safety Branch BO/06/26 App

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1
F. Security, medical, emergency & fire protection plans

800701038B Forwards Revision 6D of TMI modified amended physical security plan Plan withheld (ref 10CFR2 790)
HERBEIN, J @ Metropolitan Edison Co 80/06/27 ip

8007080244 Forwards 790619 ltr of agreement between Radiation Mgt Corp & Met Ed for insertion into 800601 TM1 emergency plan. App C HERBEIN.J Q Metropolitan Edison Co 80/06/30 3pp

8007140647 Forwards State of PA authorization for open burning to train firefighters HGRBEIN, J Q Metropolitan Edison Co 80/07/11 2pp

BOO7/2R0553 Forwards revised fire protection program plan, replacing previous plan submitted Apr 1977
HERBEIN.J G Metropolitan Edison Co 80/07/11 1p

---B007220555 Revised fire protection program plan
* Metropolitan Edison Co 80/07/11 Spp

BOO7220471 Forwards "Independent Assessment of Evacuation Time for TMI Nuclear Power Plant" in response to NRC 800510 ltr HERBEIN, J @ Metropolitan Edison Co 80/07/17 ip

BO07310340 Forwards Suppl 3 to fire protection safety evaluation supporting deletion of requirement to install thermal insulation on decay heat removal valves REID.R W. Operating Reactors Branch 4 80/07/21 5pp

--B007310341 Suppl 3 to fire protection safety evaluation supporting deletion of requirement to install insulation on decay heat removal valves * Operating Reactors Branch 4 80/07/21 4pp

O Adjudicatory correspondence

BOO71404BB Forwards position of Gaston County Board of Commissioners, NC: apposing spont nuclear fuel shipment through county & two proposed alternate routes W/o entl RHYNE, C. A Gaston County, NC 80/04/15 ip

8007230142 Forwards UBGB photographs of exhibit panel featuring TMI computer-plotted land use map. JR Wray 800429 memo re restart hearing map exhibit needs full size copies W/o photos.

WRAY, J. R. Interior, Dept of: Geological Survey 80/06/04 11pp.

--BD07230164 Forwards data outlining space for protetype hazard mitigation maps. Compilations will be completed by 800630 WRAY, J. R. Interior, Dept. of, Caplogical Survey. 80/05/27 2pp

8007020651 Reconsideration of contentions withdrawing prior Contentions 2,7,10 & 12 modifying Contentions 1.5,6,8,9,11,14,16,&17 & retaining Contentions 3,4,13 & 15 Draft of revised contentions & Certificate of Svc encl SHOLLY,8 C Affiliation Unknown 80/06/05 15pp

8007020648 Motion speking extension of discovery period re Commission 800516 memorandum & order,CLI-BO-16, ASLB response concerning hydrogen control contentions Certificate of Syc encl
SHDLLY,S C Affiliation Unknown 80/06/09 9pp

B007010269 Forwards time & attendance records for Ofc of Nuclear Reactor Regulation personnel, updated through B00419, in response to UCB Interrogatory 210 Copies available in PDR & LPDRs SWARTZ, L Hearing Branch 1 B0/05/10 1p

B007930057 Motion to withdraw Contention 16 due to negotiations w/ licensee which solved intervenor concerns to security Supporting documentation to Certificate of Svc encl SHOLLY.S C Affiliation Unknown B0/06/10 9pp

8007280265 Forwards York County Industrial Development Corp 800610 resolution Urges NRC to expedite restart of TMI~1 BELL.J J Affiliation Unknown 80/06/12 App

B00714000B Response in opposition to licensee reply to TMI Alert B00527 motion to compel followed discovery Motion was filed within period prescribed in regulations for mailing Certificate of Svc ontl ADLER, T A Three Mile Island Alert ADLER, T A Widoff, Reager, Selkowitz & Adler 80/06/18 3pp

---B007140007 Second ret of followup interragatories directed to licensee Requests work-related acrident dotumentation involving personal or property injuries Responses to THI Albert Interragatories 5-6 must be updated Certificate of Svc encl ADLER.T A Three Mile Island Alert ADLER.T A Widoff, Reager, Selkowitz & Adler B0/06/18 App

8007310243 Forwards Commission B00527 memorandum & order centaining decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 77104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp

8007080043 Forwards UCS affidavit of RD Pollard Requests svc on parties in restart proceeding
WEIBS:E R Sheldon, Harmon & Weiss 80/06/26 ip

--8007GB0090 Affidavit submitting add1 answers to Tourtellette questions at RD Pollard 800411 deposition States that NRC approach in 800331 response to UCS Interrogatories 150-153 is inadequate & Unacceptable Certificate of Svc encl
POLLARD.R D Union of Concerned Scientista 80/04/24 App

8007020616 Supplemental rept on search for suitable TMI-1 hearing facilities re restart proceeding Identifies three possible places in Harrisburg.PA Svc list encl * Metropolitan Edison Co 80/06/27 4pp

8007020633 Response in opposition to TMI Alert second set of followup interrogatories due to untimely filing & irrolevance Argument re application of hew info per ASLO 800505 order is w/o merit Certificate of Svc encl ZAHLER.R E Metropolitam Edison Co ZAHLER.R E Shaw, Pittman, Potts & Troubridge 80706/27 App

8007010332 Response stating no opposition to SC Sholly 800610 motion to withdraw Contention 16 re security issues Cartificate of Syc encl

BWANSON, D. T. Hearing Branch & 80/06/30 3pp

8007070278 Forwards PA Emergency Mgt Agency 800104 directives & circulars, suppl to hazard analysis matls & "RAC Comments on Annex E to Disaster Operations Plan," w/800519 cover ltr W/o attachments Cortificate of Svc encl CARTER, K W Pennsylvania, State of 80/06/30 4pp

8007080004 Forwards People Against Nuclear Energy request for ASLB guidance on scheduling of psychological distress issue Svc to parties in restart proceeding requested JORDAN, W. S. Sheldon, Harmon & Weiss 60/06/30 ip

--B0070B0005 Request for ASLR guidance re preparation of case in absence of Commission decision per present schedule of psychological distress issue Issues may be added to end of bearing or may be subj of separate schedule W/Certificate of Svc JORDAN, W 9 People Against Nuclear Energy JORDAN, W 9 Bheldon, Harmon & Waise B0/06/30 Spp

- B007140005 Interrogatories directed to licensee & NRC Requests technical info re bypass capability around filter unit. vantilation sys mod in NUREG-0680 & restart evaluation Certificate of Svc encl LEWIS, M Affiliation Unknown B0/06/30 3pp
- 8007030290 Second set of interrogatories directed to UCS Requests identification of all pertinent info intended to be used in intervenor direct case & cross-examination on Contentions 1-14
 - SHARTZ, L. L. Antitrust Division 80/07/01 Spp
- --8007030293 Second set of interrogatories directed to MI Lewis Requests identification of all pertinent info intended to be used in intervenor direct case & cross-eramination on contention Demands statements re gaseous raduaste sys capability SWARTZ.L.L. Antitrust Division 80/07/01 4pp
- --9007030296 Second set of interrogatories directed to TMI Alert, Inc Requests spec of alleged violations in safety evaluation & identification of all pertinent info intended to be used in intervenor direct case & cross-eramination on contentions SMART2.L L Antitrust Division 80/07/01. 7pp
- ---8007030297 Second set of interrogatories directed to Chesapeake Energy Alliance Requests statements on NRC review of separation of TMI-i & 2 operations & identification of all pertinent info intended to be used in intervolor direct case SHART2.L L Antitrust Division 80/07/01 7pp
- --8007030297 Second set of interrogatories directed to MM Aamodt Requests statments on technician test performance & identification of all pertinent info intended to be used in intervenor direct case & cross-examination on Contentions 2,4,5 & 8
 SWARTZ,L L Antitrust Division 80/07/01, 6pp
- --8007030301 Second set of interrogatories directed to SC Sholly Requests statements on safety evaluation of emergency plan offsite monitoring & identification of all pertinent info intended to be used in intervenor direct case & cross-examination SMARYZ.1. L. Antitrust Division 80/07/01 10pp
- ---8007030302 Second set of interrogatories directed to Antinuclear Group Representing York Requests statements on State of PA emergency plan & identification of pertinent info intended to be used in intervenor direct case EHARTZ.L.L. Antitrust Division 80/07/01 6pp
- ---B007030303 Second set of interrogatories directed to Newberry Township Requests statements on emergency plan as reviewed by NRC & identification of all pertinent info intended to be used in intervenor direct case & cross-examination SWARTZ.L L Antitrust Division B0/07/01 4pp
- --8007030304 Second set of interrogatories directed to Environ Coalition on Nuclear Power Requests all pertinent info intended to be used in intervenor direct case & cross-examination on Contentions I(a)(c)(d)(e), 2 & 4 Certificate of Svc enci SCHRTZ.L L Antitrust Division 80/07/01 7pp
- 8007140003 Followup safety evaluation interrogatories directed to NRC, re mpt & technical capability, operational GA program & Tech Specs per IE Bullatin 79-03A ref Certificate of Svc & supporting documentation encl WIDDFF, M P Three Mile Island Alert WIDDFF, M P Widoff, Reager, Bellowitz & Adler 80/07/01 iipp
- 8007090220 Memorandum & order granting extension until 800707 for UCS to hand deliver safety evaluation discovery in restart proceeding SMITM, I W Atomic Safety and Licensing Board Panel 80/07/03 2pp
- 8007090212 Clarifies confusion in NRC 800701 second set of interrogatories directed to parties Intended to inquire how safety evaluation will be used in direct case & cross-examination
 SWARTZ.L. Antitrust Division 80/07/07 3pp

' set of interrogatories re NRC restart
/07/07 15

TC re new info test to ster entl R. Sheldon,

- BO07250680 Followup interrugatories directed to licensee Requests complete narration of events leading to 800627 accident involving leak of 10,000 gellons of contaminated water Certificate of Svc encl ADLER, T A Three Mile Island Alert ADLER, T A Widoff, Reager, Selkowitz & Adler 80/07/07 5pp
- 8007250689 Motion to compel licenses responses to second set followup interrogatories Intervenor complied w/ASL8 800505 order re schedule for discovery based on new info Interrogatory 2 will elicit new evidence. Certificate of Svc ancl ADLER.T A Three Mile Island Alert ADLER.T A Widoff, Reager. Bolkowitz & Adler 80/07/07 App
- 8007310138 Response in opposition to NRC second set of interrogatories NRC established no justification for untimely filing Certificate of Byc encl Related correspondence SHCLLV, S C Affiliation Unknown 60/07/07 7pp
- 8007160594 Forwards memorandum & supporting documents re ASLB request for assistance in obtaining USGS special maps for TMI-1 restart hearing Maps will be distributed in Jul 1980 when completed W o encl TOURTELLOTTE.J Hearing Branch 4 80/07/08 1p
- BOO7220203 Motion to compel production of licensee emergency plan implementing document Means by which licensee intends to effectuate plan must be reviewed BRADFORD.9 P. Anti-Nuclear Group Representing York 80/07/08 2pp
- ---R007220209 Responses to NRC second set of interrogatories Includes infore state plan review.role of local agencies in emergency response test exercise & absence of offsite monitoring devices in safety evaluation

 BRADFORD.0 P Anti-Nuclear Group Representing York. BO/07/08
 2pp
- --B007220217 Response in opposition to majority of NRC 800701 second set of interrogatories due to generality of questions.

 Gertificate of Byc ancl

 BRABFDRD, G P Anti-Nuclear Group Representing York 80/07/08.

 Zon
- B007280130 Ack receipt of ltr to President Center requesting intervenor funding for activities re restart hearings Consumer Advocate of PA request for intervenor funding denied Petition filed on 800530 REID,R W Operating Reactors Branch 4 80/07/08 ip
- --8007280140 Forwards D Hossier ltr to President re intervanor funding for reply ROTHKOPF,C L Energy,Dept of 80/01/22 2pp
- 8007i10324 Hemorandum on People Against Nuclear Energy request for ASLB guidance re psychological stress issue hearing preparation Present situation reveals no problem for filing testimony by and of Oct Future schedule will solve uncertainties SMITM.I W Atomic Safety and Licensing Board Panel 80/07/09. 3pp
- 8007140224 Response in opposition to Antinuclear Group Representing York 800630 motion for reconsideration of ASLB 800125 order rejecting Contention II(C) Commission apparently does not intend to revise emergency zone Certificate of Svc encl ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trombridge 80/07/09 Spp.
- B007170210 Response to NRC B00701 interrogatories re restart proceeding Alleges inadequate training of potential radiation monitoring team members & poor calibr preparedness Certificate of Bvc encl.
 BHOLLY, B C Affiliation Unknown B0/07/09, lipp.
- BOO7170370 Response to Chesapeake Energy Alliance Interrogatory 6-9 on Contention 6 re identification of TMI-2 event sequences that could result in substantial reactor coolant loss, W/unsigned & unsubscribed affidavits & Certificate of Svc SMARTZ, L Antitrust Division BO/07/09 7pp
- 8007220001 Motion for reconsideration of ASLB 800625 memorandum & order danying TMI Alart motion to compel licensee answers to interrogatories Info is necessary to determine if pipe cracking resulted from deferred maint W/Cartificate of Syc. ADLERIT A Three Mile Island Alert. ADLERIT A Widoff, Reager, Selkowitz & Adler 80/07/10 5pp.
- 8007300035 Forwards complete set of correspondence re hearing ASLAB request for easistance in obtaining special maps for TMI-i restart hearing from GB Maps being developed will serve as models for establishing base map requirements within NRC.

 BALLARD, R L Environmental Engineering Branch 80/07/10 2pp

- 8007220002 Response in opposition to NRC second set of Interrogatories 1.2 & S due to untimeliness & irrelevancy Certificate of Svc
 - ADLER, T A Three Mile Island Alert ADLER, f A Widoff, Reager, Belkowitz & Adler 80/07/11 2pp
- 8007170150 Response in support of licensee 800623 motion for order requiring Environ Coalition on Nuclear Power to specify Contentions 2-2 & 2-4 Opposes request for imposition of sanctions. M/notice of appearance & Cortificate of Svc ORAY.J R Hearing Branch 1 80/07/14 9pp
- 8007180391 Response in opposition to TMI Alert 800707 motion to compel licensee responses to second set of followon interrogatories intervenor position re availability of info is contradictory to prior statements W/Certificate of Svc ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge 80/07/14 8pp
- BOO7180421 Requests lifting of suspension of prehearing activities Repts on BOO711 emergency planning meeting Revisions made after briefing & discovery on scope of emergency plan issues may generate addl contentions Certificate of Bvc encl AFTER BRIEFING Hetropolitan Edison Co ZAHLER.R E Shaw, Pittman, Potts & Troubridge BO/07/14 9pp
- 8007210487 Forwards UCS objection to second set of NRC interrogatories Byc on parties requested WEIGS.E R Bholdon, Harmon & Weiss 80/07/14 ip
- ---B007210495 Objection to second set of NRC interrogatoriet Questions are not based upon new info in SER Certificate of Svc encl HEISS, E. R. Union of Concerned Scientists HEISS, E. R. Sheldon, Harmon & Weiss B0/07/14 2pp
- --8007210503 Second set of interrogatories directed to UCS Requests identification of info relevant to Contentions 1-14 w/names of witnesses intended to be called SHARTZ. L. Diffice of the Executive Lagal Director 80/07/01
- 8007180376 Advises that licensee identified two add1 possibilities for hearing space wince 800627 filing of supplemental rept on wearch for suitable hearing facilities. Further delay may preclude scheduled commencement of hearing in Oct # Metropolitan Edison Co 80/07/15 3pp
- 8007220085 Memorandum & order requesting resumption of prehearing activities re emergency planning Specific discovery requests must be made within 10 days Objections must be received in five days from suc of requests & responses in 15 days SMITH.I W Atomic Safety and Licensing Board Panel BO/07/15 Spp
- B007310137 Rept on search for suitable hearing facilities Two addlessibilities identified in Harrisburg.PA Further development will be reported Cartificate of Bvc encl Related correspondence * Metropolitan Edison Co B0/07/15 Spp
- 8007180394 Motion for dismissal of TMI Alert Contention 5 from restart proceeding due to deliberate refusal to answer licensee 800613 interprogatories. Intervenor refused to give facts in support of contention Certificate of Svc encl BLAKE, E. L. Metropolitan Edison Co. BLAKE, E. L. Shaw, Pittman, Potts & Trowbridge 80/07/16 32pp
- B007220529 Forwards request on behalf of People Against Nuclear Energy requestion of whether psychological distress contentions are admissable in TMI restart proceeding JORDAN, W. S People Against Nuclear Energy JORDAN, W. S Sheldon, Harmon & Weiss B0/07/16, jp
- ---8007220930 Requests Commission decision on psychological distress issues. Buggests that matter be first item of business for new chairman JORDAN, W 8 People Against Nuclear Energy JORDAN, W 8 Bheldon, Hermon & Helss 80/07/16 7pp
- ---8007220533 Memorandum re People Against Nuclear Energy request for ABLB guidance Unable to rule whether filing of direct testimony by end of Dot will be timely BMITH.I W Atomic Bafety and Licensing Board Panel 80/07/09
- BOO7220585 Requests that ABLB issue subpoena to WDR-TV for tape or transcript of "What's Happening, America " Program broadcast on BOO324 & revealed facts re util maint practices Cartificate of Syc encl. Related correspondence ADLER.T A. Widoff, Reager, Selkowitz & Adler 80/07/16 Spp

- 8007310143 Response to second set of interrogatories Questions preheater role on filter sys as described in safety evaluation & restart repts Certificate of 8vc encl LEWIS M l Affiliation Unknown 80/07/16 2pp
- BO07220562 Advises that despite late receipt of UCS third set of interrogatories NRC responses will be hand delivered to UCS t ASLB on 800728

 SWARTZ L L Antitrust Division 80/07/17

 2pp
- BO07220564 Forwards signed affidavits identifying authors of NRC response to Chesapeake Energy Alliance Interrugatory 6-9
 BMARTZ,L L Antitrust Division BO/07/17 3pp
- 8007230521 Response in opposition to TMI Alert 800707 followup interrogatories re 800627 leak of contaminated water Relation to remaining contentions not shown Certificate of Syc encl Related correspondence BLAKE, E.L. Metropolitan Edison Co. BLAKE, E.L. Shaw, Pittman, Potts & Trowbridge 80/07/17 Spp
- 8007230500 Response to MI Lewis 800630 interrogatories of SER Includes explanations on absence of investigation re lack of auxiliary bldg ventilation sys bypass Affidavits, profiquallifications & Certificate of Svc encl
 SWARTZ,L L Antitrust Division 80/07/18 15pp
- 8007230506 Forwards licensee response to interrogatories re TMI-1 restart Related correspondence
 ZAMLER.R E Shaw. Pittman. Potts & Trowbridge 80/07/18 lp
- --B007230514 Response to Intervenor MI Lewis interrogatories on NiREG-OSBO, "TMI-1 Restart Evaluation " Related correspondence ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 80/07/18 4pp
- 8007230610 Response in opposition to Antinuclear Group Representing York 8007079 motion to compet see of emergency plan implementing document Mation inconsistent u/production groundrules Certificate of Sec encl ZAHLER, R E Metropolition Edison Co ZAHLER, R E Shaw, Pittman, Patts & Trombridge 80/07/18 App
- 8007230604 Response in support of People Against Nuclear Energy 800716 request for Commission decision on psychological distress issue Urges striking Section III of motion re opportunity for raply briefs Certificate of Svc encl TROMBRIDGE, 0 F Metropolitan Edison Co TROMBRIDGE, 0 F Shaw, Pittman, Potts & Troubridge 80/07/21 5pp
- BOO7230A09 Forwards WL Jensen BO0721 affidavit re NRC responses to BC Bholiy safety evaluation interrogatories 9-10 BWARTZ.L L Antitrust Division BO/07/21 2pp
- --8007230614 Response to SC Sholly 800630 interrogatories on restart safety evaluation re steam generator level instrumentation designed to meet safety grade requirements & other issues Affidevits, prof qualifications & Certificate of Svc encl SWARTZ, L L Antitrust Division 80/07/21 33pp
- --8007R30617 Response to TMI Alert 800701 followup interrogatories re safety evaluation Explains suggested changes re improved agt capability & technical expertice Certificate of Svc oncl BWANBON,D T Hearing Branch 1 80/07/21 20pp
- 8007250446 Forwards ASLS 800721 Subpoons directed to R Fennimors of WOR-TV Ark requested SMITH.I W Abomic Safety and Licensing Board Panel 80/07/21 1p
- --B007250492 Subposens commanding R Fenningre of MOR-TV to appear on behalf of TMI Alert on B00804 in Dethesús MD.re Fennimore B00324 television interview SMITH.I W Atomic Safety and Licensing Doard Ponel 80/07/21
- 8007290779 Response to NRC interrogatories based on safety evaluation Submits items supporting allegation that licensee is not technically qualified Intervenor will rely on corrent financial statements re Contention 6 W/Certificate of Svc HIDDFF,M P Three Mile Island Alert WIDDFF,M P Widoff, Reager, Selkowitz & Adler 80/07/21 9pp
- B007230426 Memorandum & order ruling on TMI Alert 800707 motion to compel licensee responses to interrogatories Interrogatories 1.3 & 4 must be answered within 15 days Interrogatory 2 need not be answered BMITH-I W Atomic Safety and Licensing Board Panel 80/07/22 3pp

- 9739 Memorandum advising that ASLB 800715 memorandum & order has purpose of setting scope of Commission discovery reity & establishing schedule for litigation of sency planning issues LIN Atomic Safety and licensing Board Panet 80/07/23 2pp
- 066: Forwards documents sent to SC Shally in response to 800630 regalaries Copies avoilable in Local PDR H/o encls FZ,L L. Antitrust Division 80/07/24 ip
- 1437 Response in opposition to TMI Aleit 800710 motion for sideration of ASLO 800A25 order denying intervenor in to compel Affirms licenses 800515 % 0604 responses to there discovery & motion to compel W/Certificate of Syc I.E. L. Hetropolitan Edison Co. DLAKE, E.L. Shaw, Pittman, Potts subridge 80/0//24 iOpp
- 0219 Forwards H Silver.AR Keimig.JW Gilray & FR Allanspach davits & prof qualifications re NRC 800721 response to Alart foliousp interrogatories 3DN.D T Hearing Branch I 80/07/25 lipp
- 2319 Nesponds to UCS third set of interrogatories re new info in ty evaluation Functional test not expected prior to ing Adequate means for prevention of steam generator full demonstrated W/affidavits & Certificate of Svc TZ.L. L. Antitrust Division 80/07/20 42pp
- ral correspondence
- 0282 Responds to 600320 ltr re 80 Ames concerns about delays in lity restart Commission 770809 order identifies itams must be resolved prior to restart Time required to lye items will delay restart until late 1980 CRER.C Office of Congressional Affairs 80/04/02 2pp
- CRA Responds to B00414 lin ne CM Leveau concerns about util notal condition PA Public Utile Commission should be acted Dactsion on facility restant could not be expected ne end of 1980 due to proceeding scope & other factors REA.C Office of Congressional Affairs B0/04/18 Rps
- 0345 Responds to 800414 ltr re E Clark concerns about util icial condition PA Public Utils Commission should be acted Decision on facility restant could not be expected re end of 1980 dus to proceeding scope & other factors IRFR.C Office of Congressional Affairs 80/04/18 2pp
- 1420 Responds to ltr ro Sf Argubright concerns about delays in lity restart Decision on restart will not be made until 1780 due to time required to complete tasks ro ission 770007 order ERCR.C Office of Congressional Affairs 80/05/05 2pp
- DIOS Responds to 800321 questions re possible financial failure vil Financial Pailure provides grounds for immediate cation of license Contingency plans under development vill ensure protection of public boolth RNE.J F Commission 80/05/07 Rpp
- 0655 Urges ARC approval of venting at TMI .A.A. Affiliation Unknown = 80/06/04 | 1
- 0027 Urges expeditions restart of facility due to continuous ease of power cost resulting from indecisions & delays STER.C F Affiliation Unknown BO/04/24 ip
- 0013 Urges afforts to restart unit at early date due to rate pass approved by PA Public Util Commission for Met Ed
- omers INGER.C W Affiliation Unknown 80/04/26 2pp
- 0385 Responds to 660503 invoice & forwards insp fees for period or 1979 to Mar 1986 per 1807R170 W/o encl EIN.J G Metropolitan Edison Co 80/07/02 2pp
- OODI Responds to 800612 ltr forwarding recent recolution adopted out County Industrial Development Corp advocating return activity to svc. Hearing ordered to determine whather lity should be operating a under what conditions ON, IR. Office of Nuclear Reactor Regulation, Director 7/08 19
- 220033 Forwards resolution unanimously adopted by York County dustrial Dovelopment Corp on 800610. Hesplution urges NRC expedite return of facility to svc LL.J J York, PA 80/06/12 2pp

- 8007180154 Responds to 800317 ltr re delay in placing TMI-1 back into svc Public hearing scheduled to begin Fall 1980 to determine whether facility should be operated & under what conditions Questions re nuclear R&D activities should be sent to DOE. REID.R W Operating Reactors Branch 4 80/07/09 1p
- --80D7180160 Expresses support for nuclear power to replace imported oil & urges expediting return of TMI-1 to svc RIPLEY, WI A Affiliation Unknown 80/03/19 2pp
- B007180457 Responds to B00622 ltr re restart at TMI-1 Public meeting scheduled for Fall 1980 to determine whether facility should be operated & under what conditions NRC primary responsibility is assurance of public health & safety RCID.R W Operating Reactors Branch 4 80/07/09 Ip
- --8007180461 Guestions when TMI-1 will be allowed to restart & what is required of util by NRC SAWYER, E & Affiliation Unknown 80/06/22 2pp
- B007210084 Forwards NUREO-0591 & NUREO-0454 in response to request Advises that App A to NUREO-75/087 does not exist Several individual SARs identified in SRP have App A H/o sncls. B0UDER. J t. Division of Rules and Records B0/07/07 lp
- G007210121 Responds to 790709 ltr to NRC re concerns about facility & actions being taken by Concerned Citizens of Londonderry NRC has ordered public hearing to determine whether Unit i should be operated Unit 2 feasibility studies are underway SNYDER. D J THI Program Office 80/07/07 2pp
- --8007210101 Expresses appreciation for 790629 visit to Middletown, PA Concerned Citizens of Londonderry, who have collected 750 signatures, are dedicated to closing facility NRC status regts would be of great benefit to area residents STREET, PA Affiliation Unknown. 79/07/09 2pp
- 8D07220320 Responds to 800401 ltr to President Carter expressing concerns over financial impact as stockholder w/licensee NRC is concerned w/economic impact Responsibility is limited to public health & safety RFID.R W Operating Reactors Branch 4 80/07/09 2pp
- 8007230344 Responds to entl 800302 ltr to President Carter re delay in returning TMI-1 to svc NRC has ordered public hearing to be conducted to determine whether facility should be operated to if to under what conditions

 REID.R W Operating Reactors Branch 4 80/07/09 2pp
- 8007R40394 Responds to 8003R8 ltr to President Carter requesting that facility be returned to svc Public hearing re issues to assure public health & safety scheduled for Fall 1980. NRC review of technical issues underway Ltr encl REID.R W Operating Reactors Branch 4 80/07/09 Spp
- 8007240371 Responds to 800328 ltr re delay in returning facility to svc Public hearing scheduled for Fall 1980 re issues appropriate to assure public health & safety NRC review of technical issues underway Restart not expected before 1981 REID.R W Operating Reactors Branch 4 80/07/09 1p
- --8007240378 Requests that facility be returned to svc BARTMAN.V Affiliation Unknown, 80/03/28 ip
- 8007240392 Responds to 800329 ltr to President Carter re delay in returning facility to svc. Public hearing re issues to assure public health & sefety scheduled for Fall 1980 NRC review of tochnical issues underway Ltr encl. REID: R H Operating Reactors Branch 4. 80/07/09. 2pp
- 8007240398 Responds to 800321 itr to President Carter re delay in returning facility to svc Public hearing re issues to assure sublic health & safety scheduled for Fall 1980 NRC review of tochnical issues underway. Ltr encl REID, R W Operating Reactors Branch 4 80/07/09. 3pp
- 8007240404 Responds to 800420 ltr re delay in returning facility to svc Public hearing scheduled for Fall 1980 re issues appropriate to assure public health & safety NRC review of technical issues underway Restart not expected before 1981 REID.R W Operating Reactors Branch 4 80/07/09. 1p
- 8007240412 Responds to 800420 itr to President Carter re delay in returning facility to svc. Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues undarway Ltr encl REID.R W Operating Reactors Branch 4. 80/07/09. 2pp

- 8007240416 Responds to 800306 ltr to President Carter is delay in returning facility to svc Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr enci
- 8007240419 Responds to 800323 ltr to President Carter re delay in returning facility to svc Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr encl REID, R W Operating Reactors Branch 4 80/07/09 2pp
- 8007240423 Responds to 800226 ltr to President Carter re delay in returning facility to svc Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr encl REID;R W Operating Reactors Branch 4 80/07/09 3pp
- 8007240428 Responds to 800318 ltr to President Carter re delay in returning facility to svc.Public hearing re issues to assure public health & safety scheduled for Fall 1980 NRC review of technical issues underway Ltr encl REIB.R.W Operating Reactors Branch 4 80/07/09 2pp
- E007300006 Responds to 1tr re accident at TMI-2 Public hearings will be conducted to determine whether Unit 1 should be operated & under what conditions Licensee has not submitted proposal for overall plant recovery for Unit 2

 SNYDER.B J TMI Program Office B0/07/09 2pp
- B007250624 Responds to B00619 itr to J Ahearne re resolution adopted & comments re THI-1 restart NRC has ordered that public hearing be conducted to determine if facility should be operated & under what conditions
 DENTON; H, R Office of Nuclear Reactor Regulation, Director 80/07/10 p
- 8007290031 Responds to 800618 ltr to Commissioner Hendrie urging expedited proceedings to return TMI-1 to avc Development of record re restart is not expected before early 1981 Primary Commission responsibility is for public health DENTON. H R Office of Nuclear Reactor Regulation. Director 80/07/14 ip
- --R007290035 Urges NRC to expedite proceedings on TMI-i on behalf of constituents serviced by JCP&L Requests are prompted by rate bikes
 GALLO, D. A. New Jersey, State of 80/06/18 5pp
- 8007310373 Urges restart of facility ADAM.L. D. Affiliation Unknown 80/07/17 ip 1
- 8007310398 Requests action in restoring svc to facility Economic burden to electricity users has been substantial LAMPE.W F Ecolairs Condenser, Inc. 80/07/21 ip
- 8007310375 Forwards MB Hayden 800717 ltr urging facility restart Requests reply ODDDLING. B House of Rep 80/07/22 3pp

I. Financial information

- 8007150730 Confirms 800626 telcon & forwards graph illustrating market price of General Public Utils Corp common stock for period Jan 1979 to mid~June 1980 HOWBON T G General Public Utilities GPU Service Corp 80/06/26 20ep.
- J Insurance & indemnity information
- 8007110011 FDIA request for all indomnity agreements, insurance policies & associated info between util, NRC &/or AEC refacility KEARNEY, R. W. Affiliation Unknown 80/05/29 App
- 8007i10009 Responds to FDIA request for all indemnity agreements, insurance policies & associated info between util NRC &/or AEC re facility Forwards documents listed in App A FELTON, J M Division of Rules and Records 80/06/23 7pp
- --800/110017 Confirms that NELIA has bound Insurance Policy NF-220 at limit of one million dollars issued to Met Ed. JCP&L k
 PEPCO covering facility Includes policy site description.
 GUATTROCCHI, J Nuclear Energy Liability Insurance Association
 73/12/06 ip
- --B00711Q028 Executed Amend 3 to Indemnity Agreement B-44 changing amount of financial protection BALTZMAN, J Antitrust & Indemnity Group 75/04/04 2pp

- ---B007110030 Executed Amond 5 to Indomnity Agreement B-64.changing amount of financial protection SALTZMAN.J Antitrust & Indomnity Group ARRIDLD.R C Metropolitan Edison Co 77/05/20 2pp
- --8007110032 Executed Amend & to Indomnity Agreement B-64, changing license numbers SALTZMAN. J Antitrust & Indomnity Group HERBEIN, J O Metropolitan Edison Co 80/02/24 ip
- ~-B007i10037 Amend 8 to Indemnity Agreement B-64, changing amount of financial protection BALTZHAN.J Antitrust & Indemnity Group 79/05/01 2pp
- ---B007110040 Executed Amond 9 to Indomnity Agreement B-64, modifying profatory language of Paragraph 5, Article 1, re course of transportation NELIA Policy (facility form) enci SALTZMAN. J. Antitrust t Indomnity Group HERBEIN, J. G. Metropolitan Edison Co. 80/01/03 Spp
- --8007110046 Endorsement 2 to NELIA Policy NF-220 designating enpual premium Declaration encl * Nuclear Energy Liability Insurance Association 79/01/12 2pp
- --B00711005; Amend to Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 2 MARRONE.J Nuclear Energy Liability Insurance Association 73/12/14 ip
- ~-8007110052 Amend to NELIA Policy NF-220 Cunatitutes Endorsement 4 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- ~-8007110057 Amend to industry credit rating plan premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 5 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- ~-B00711Q060 Endotsement 6, wasver of defenses endorsement (END), to NELI, Policy NF-220 MARRONE, J. Nuclear Energy Liability Insurance Association 73/12/14 2pp
- ~-8007i1Q062 Endorsement 7 to supplementary endorsement waiver of defenses for reactor const to NELIA Policy NF-220 MARRONE.J Nuclear Energy isability Insurance Association 73/12/14 lp
- --800711006B Amend to Insuring Agreement IV of NELIA Policy NF-220, "Application of Policy" Constitutes Endorsement & MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 lp
- --8007110072 Amend to advance premium & std premium endorsement of NELI Policy NF-220 Constitutes Endorsement 9 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 1p
- --8007110077 Endursement 10 to advance premium & std premium endorsemen w/changes in subscribing companies & proportionate liability endorsement to NELIA Policy NF-220 MARRANE, J Nuclear Energy Liability Insurance Association 73/11/01 ip
- --B007i10084 Endorsement li,assignment of interest in return premium & in reserve premium refundato NELIA Policy NF-220 MARRONE, J Nuclear Energy Liability Insurance Association 74/07/15 2pp
- ---80071100B9 Amend to Condition 4 endorsement in NELIA Policy NF-220 Constitutes Endorsement 12 MARRONE.J Nuclear Energy Liability Insurance Association 74/01/15 1p
- --B007110091 Amend to Endorsement 10, advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 13
 MARRONE, J. Nuclear Energy Liability Insurance Association 74/02/15 ip
- --8007110075 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 14 MARRONE, J Nuclear Energy Liability Insurance Association 74/03/15 1p
- ~-800711009B Endorsement 15 to NELIA Policy NF-220 increasing liability limits MARRONE, J Nuclear Energy Liability Insurance Association 74/04/25 is

- ---8007110103 Amend to Endorsement 13 to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 16 HARRONE, J Nuclear Energy Liability Insurance Association 74/04/26 1p
- --8007110107 Amend of std premium endorsement w/changes in subscribing companies & proportionate liability endorsement Constitutes Endorsement IB BANDES.C R Nuclear Energy Liability Insurance Association 74/12/12 19
- --B007110125 Amend of Condition 4 ondersement to NELIA Policy NF-220 Constitutes Endorsement 19 BARDES C R Nuclear Energy Liability Insurance Association 75/01/01 1p
- --8007110128 Endorsement 20 to NELIA Policy NF-220, increasing limit of liability endorsement BARDES.C R Nuclear Energy Liability Insurance Association 75/03/21 ip
- -8007:10132 Amend to Endorsement 18 of advance premium & std promium endorsement to NELIA Policy NF-220 Constitutes Endorsement 21 DARDES,C R Nuclear Energy Liability Insurance Association 75/03/21 10
- --8007110135 Amend to Endorsement 17 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 22 BARDES C R Nuclear Energy Liability Insurance Association 75/04/22 ip
- --8007110140 Endorsement 23 to advance premium & std premium endorsement to NELIA Policy NF-220 w/changes in subscribing companies & proportionate liability endorsement BARDESIC R Nuclear Energy Liability Insurance Association 75/12/01 ip
- --8007110143 Amend to Endorspment 23 to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement PARDESIC R I Nuclear Energy Liability Insurance Association
- --8007110147 Amend to Condition 2.insp & suspension, to NELIA Policy NF-220 Constitutes Endorsament 26 BARDES CR Nuclear Energy Liability Insurance Association 76/12/15 ip
- --8007110181 Endorsement 27 to waiver of defenses endorsement (ENO) to NELIA Policy NF-220 Constitutes Endorsement 27 BARDES,C R Nuclear Energy Liabality Insurance Association NELIA PO... BARDES CR N
- ---B007110184 Amend to definition of nuclear energy hazard to NELIA Policy NF-220 Constitutes Endonsement 28 BARDES, C. R. Nuclear Energy Liability Insurance Association 76/12/15 1p
- --B007110160 Endorsement 29 to advance premium & std premium endorsement to NELIA Policy NF-220 BARDES, C. R. Nuclear Energy Liability Insurance Association 76/12/31 2pp
- --8007110167 Amend to Condition 4 % amend in 1977 subscribing companies & proportionate liability endorsement to NELIA Policy NF-220 Constitutes Endorsement 30 BARDES.C R. Nucleur Energy Liability Insurance Association 77/01/31 2pp
- ---8007110173 Endorsement 31 to NELIA Policy NF-220, increasing limit of liability endorsement
 4 Nuclear Energy Liability Insurance Association 77/05/06 ip
- ~8007110176 Amend to Endursement 29 to advance premium & std promium endorsement to NFLIA Policy NF-220 Constitutes Endorsement 32 BARDES.C R Nuclear Energy Liability Insurance Association 77/05/06
- --8007i10i78 Amend to Endorsement 32 to advance premium & std premium endorsement to NCLIA Policy NF-720 Constitutes Endorsement 33 BARDES, C.R. Nuclear Energy Liability Insurance Association 77/08/17 1p

- --B007110201 Amend to Endorsement 34 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 35 BARDES.C R Nuclear Energy Liability Insurance Association. 78/03/06
- --B00711020B Amend to advance premium & std premium endorsement & amend of Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 36 BARDES, C. R. Nuclear Energy Liability Insurance Association 79/01/03 ip
- ---8007110212 Amend to Endorsement 35 of advance premium & std premium endorsement to NECIA Policy NF-220 Constitutes Endorsement 37 BARDES, C.R. Nuclear Energy Liability Insurance Association 79/01/14 ip
- --8007110217 Endorsement 38 to NELIA Policy NF-220.w/changes in subscribing companies & proportionate liability endorsement BARDES,C R Nuclear Energy Liability Insurance Association 79/01/20 1p
- --BD07110222 Amend to Insuring Agreement 3 to NELIA Policy NF-220 Constitutes Endorsement 1 MARRONE.J Nuclear Energy Liability Insurance Association 73/12/14 1p
- --8007110224 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 3 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 1p
- 8007110043 Endorsement 1 to NELIA Policy EB-45

 * Nuclear Energy Liability Insurance Association 78/09/18 1p
- 8007180404 Responds to 800613 request for addl info re compliance w/financial protection provisions of Atomic Energy Act Forwards proposed Endorsements 43 & 44 to NELIA Policy HERBEIN, J G Metropolitan Edison Co 80/07/14 App
- 8007220584 Responds to NRC 800613 ltr re compliance w/financial protection requirements Proposed endorsement provides max protection available from private sources Restoration of limit of liability endorsement encl HERDEIN.J.O Metropolitan Edison Co BO/07/14 7pp
- P Operating license stage documents & correspondence
- B007240208 Perwards B&W licensees' responses to 790907 request for review of schedule for installing safety-grade enticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115 CAPRA-R A TMI-2 Bulletins & Orders 79/10/24 1p
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resulution encl for guidance EIEENHUT, D G Division of Licensing 80/06/11 62pp.
- 8007020017 Discusses licensee consideration of increased onsite MACONIV DISCUSSES licensee consideration of increase radwaste storage Requests reviews for onsite storage additions in monthly operating repts Draft licensing position re onsite storage safety considerations enc.

 REID.R W Operating Reactors Dranch 4 80/06/12
- 8007140413 Submits info detailing leak testing operation plans, per 800527 telcon Test to be performed 800705-15 & 0725-0804, pending PaDER approval KLIN9AMAN,R M Hetropolitan Edison Co 80/06/16 2pp
- 8007140123 Forwards revised Tech Specs Table 4 1-2 from which footnote was inadvertently unitted per 800603 Amend 55 to License DPR-50 Footnote is not related to Amend 55 but to 761217 REID:R W Operating Reactors Branch 4 80/06/20 3pp
- --8007140125 Revised Tech Spec Table 4 1-2, from which footnote was inadvertently omitted * Dperating Reactors Branch 4 80/06/20 1p
- 8007010460 Requests NRC concurrence in use of Mine Safety Appliances, Go OMR-I & Scott TEDA-R respiratory protection cannisters against airborne radioactive matis Lists add) precautions for use of cannister Related correspondence and HDVEY. 8 K matropolitan Edison Co 80/06/26 Bpp

- BOO7170309 Requests implementation of recommendations contained in MUREQ-0612 "Control of Heavy Loads at Nuclear Power Plants-Resolution of Task Action Plan A-36" Guidelines for control of heavy loads encl
 EISENHUT, D Q Division of Licensing BO/06/26 47pp
- BOO7240141 Requests licensee action to begin implementation of recommendations to assure safe handling of heavy loads Also requests review of control for handling heavy loads to datermine extent to which encl guidelines are satisfied EIBENHUT, D O Division of Licensing 80/06/26 47pp
- B007010326 Forwards simplified logic of degraded grid voltage.in response to questions raised during 800605 conference call Revised Tech Specs Change Request 60 will be submitted by 800827 HERBEIN.J Q Metropolitan Edison Co 80/06/27 3pp
- 8007070281 Responds to NRC 800202 request for revised submitted date re inadvertent reactor scram/safety injection Review of safety sys surveillance procedures & mgt policies & procedures scheduled for completion by Jan 1781 HERBEIN, J. 9 Metropolitan Edison Co 80/06/30 1p
- 8007070294 Responds to NRC 800307 ltr re TMI-2 related requirements Items I A 1 3.I A 3 i.I C 5.II K 3 & III D 3 4 currently under review for TMI-1 Items for TMI-2 will be reported under separate cover HERBEIN.J Q Metropolitan Edison Co 80/06/30 2pp
- B007070343 Informs that due to relationship of tests to Crystal River 3 event & IE Bullstin 79-27 response tests verifying effects of combination of power loss on instruments & control functions will be provided by 800730

 HERBEIN, J @ Metropolitan Edison Co 80/06/30 lp
- B0070B0074 Forwards resolutions to long-term generic issues re May 1979 Commission orders & add1 info requested concerning small break LDCA. HERBEIN-J G Metropolitan Edison Co B0/06/30 100pp
- 8007170651 Forwards questions re fuel assembly holddown spring failures first observed at Davis-Besse 1 & under investigation by 8&W Results of holddown spring insps at facility as well as safety significance required within 60 days NOVAK, T. M Assistant Director for Operating Reactors 60/07/01.
- 8007210004 Forwards questions re fuel assembly holddown spring insps & safety significance of operating w/broken springs in core. Requests response within 60 days NOVAK.T M Assistant Director for Operating Reactors 80/07/01
- B007080358 Forwards 800616 info ltr to PADER, requesting approval to leak test two new tanks at TMI per ETB 5 6 HERBEIN.J Q Metropolitan Edison Co 80/07/02 3pp
- B007140419 Forwards info ltr submitted to PaDER, requesting new tank leak test approval per ETB 5 & 2 4 2 W/o encl HERBEIN, J Q Metropolitan Edison Co B0/07/02 2pp
- BOO7250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D Q Division of Licensing 80/07/02 69pp
- B007100216 Responds to B00626 1tr requesting correspondence from NRC in response to B00321 1tr from Chairman Shanaman to J Ahearne, Forwards Ahearne B00507 1tr to Shanaman W/o encl BWANBUN,D T Hearing Branch 1 B0/07/07 ip
- BOO7160670 Notifies that drawings have been forwarded in response to NRC request for info re containment bldg reinforcing steel to prestressed tendons
 SLEAR.D G General Public Utilities GPU Service Corp BO/07/08 in
- B007140346 Requests exemption from requirements of iOCFR50.App H, concerning reactor vessel matt surveillance program Encl justification provides bests for request MERBEIN.J Q Metropolitan Edison Co 80/07/09 2pp
- 8007140365 Comments on NUREO-0577 re inclusion of facility as Class i susceptibility Unit will be reclassified based on encl info Oversized drawings available in Central Files only HERBEIN J G Metrapolitan Edison Co 80/07/09 24pp

- B0071B0414 Provides info omitted from response to NUREG-0577 due to lack of info Info re lateral support of steam generator, reactor coolant & identification of min operating temps should result in lower susceptibility classification HERBEIN, J G Metropolitan Edison Co B0/07/09 5pp
- B007280345 Advises of personnel changes resulting from reorganization of Ofc Nuclear Reactor Regulation
 NDVAK.T M Assistant Director for Licensing 80/07/10 App
- 8007150589 Forwards response to 800519 ltm re discovery of cracks in keyway & bore sections in Westinghouse low pressure turbines
 HERBEIN, J G Metropolitan Edison Co 80/07/11 25pp
- 8007210372 Forwards description of control room design & guidelines for control room review Guidelines will be expanded Agrees to discuss progress at 800721 opening session of NRC control
 - room design review HERBEIN.J G Metropolitan Edison Co 80/07/14 29pp
- B007220561 Advises of error in responses for Site Specific Question I, Parts B & C. submitted in B00616 ltr. in response to questions re low turbine disc cracking Correct responses encl PARKER. W D Duke Power Co B0/07/17 2pp
- 8007280023 Forwards list of YMI program ofc staff members to be used for ref in future correspondence COLLINS.R C TMI Program Office 80/07/17 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007100009 Forwards combined IE Insp Repts 50-320/79-29 & 30-289/79-21 on 791023-1127 & notice of violation GRIER. B H. Region i, Philadelphia. Office of the Director 80/01/09 3pp
- --8007100012 Notice of violation from insp on 791023-1127
 * Region 1, Philadelphia, Office of the Director 79/12/20 ip
- --8007100014 Combined IE Insp Repts 50-320/79-29 & 50-289/79-21 on 791023-1127 Noncompliance noted failure to store & control licensed matis in unrestricted areas WHITCLUR, YUNHAS OP, MCGAUDHY,R W Region 1, Philadelphia, Office of the Director 79/12/20 16pp
- 8007020161 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/05/28 ip
- 8007010315 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/05/27 ip
- 8007230301 Forwards IE Insp Rept 50-289/BO-12 on 800423-25 No noncompliance noted MARTIN.W O Region 1, Philadelphia, Safeguards Branch 80/05/30 2nn
- --B007230308 IE Insp Rept 50-289/80-i/ on 800423-25 No moncompliance noted Major areas inspected physical barriers, access control, assessment aids, communications & records Details withheld (ref 10CFR2 790) LADUN, R H Region 1, Philadelphia, Office of the Director DEVLIN, J W Region i, Philadelphia, Safeguards Branch 80/05/22 in
- 8007010135 Responds to IE Bulletin 79 27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation" Requests extension until 800730 to submit remaining required info
- 8007210572 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required GRIER.I H Region 1. Philadelphia. Office of the Director 80/06/10 In
- 8007160347 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Study No specific action or response required ORIER, B H Region 1. Philadelphia. Office of the Director 80/06/11 1p

- 8007230130 Forwards IE Insp Rept 50-289/80-11 on 800428-0502 No noncompliance hoted BRUNNER,E J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/12 2pp
- --8007230137 IE Insp Rept 50-289/80-11 on 800428-0502 No noncompliance noted Hajor areas inspected QA program implementation in areas of design changes, mods, audits, QA/QC surveillance & restart program

 NAPUDA.G Region i, Philadelphia, Office of the Director GREENMAN, E. Q. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/11 ppp
- B007020715 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power" Hritten response required ORIER, BH Region I. Philadelphia. Office of the Director 80/05/18 tp
- B007020526 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required GRIER.B H Region 1. Philadelphia. Office of the Director B0/06/20 [p
- 8007210120 Confirms 800701 mgt meeting w/util in King of Prossia,PA to discuss planned near-term licensee mgt reviews/appraisals which will augment routine NRC insp program ORIER,B H Region i, Philadelphia, Office of the Director 80/06/20 ip
- 8007160708 Forwards 1E Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internat Contamination of Personnel " No written response required ORIER 8 H Region 1, Philadelphia, Défice of the Director 80/05/24 1p
- 8007020535 Notifies that response to IE Bulletin 80-12. "Decay Heat Removal Sys Operability," will be provided by 800630 HERBEIN, J G Metropolitan Edison Co 80/06/25 2pp
- 8007210202 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER.B H Region I. Philadelphia. Office of the Director 80/06/25 1p
- B007070266 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Review of bulletin is still underway Response will be provided by B00725
 HERBEIN.J G Metropolitan Edison Co 80/06/27 200
- 8007230129 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Butput Codes " Written response required IE Circular 80-16 also enci No written response required GRIER. B H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- 8007110446 Forwards response to IE Gulletin 80-06 Elementary diagrams for all engineered safety features revealed some sampling valves not remaining in emergency mode Resetting containment isolation signal will close valves
 HERBEIN.J G Metropolitan Edison Co 80/07/02 App
- 80070B0375 Responds to IE Bulletin 80-12 re decay heat removal sys operability Dayly logs & weekly & monthly surveillances monitor performance capabilities of decay heat removal sys Discrepancies corrected by corrective maint program HERBEIN.J & Motropolitan Edison Co 80/07/03 3pp
- 8007150/21 Responds to 1E Bulletin 80-12 re decay heat removal loss Provides procedural changes from review re adequacy of safeguarding against redundancy loss & diversity of decay heat removal capability & adequacy of loss event response HERBEIN.J G Metropolitan Edison Co 80/07/03 App
- BO0714038: Requests formal resolution to settle disagreement between util & Region 1 re use of vitrasonic calibr blocts, as discussed in IE lasg Rept 50-289/80-09, Item 2 Util disagrees w/interpretations of ASME Boiler & Pressure Vessel Code HERBEIN.J Q Metropolitan Edison Co 80/07/09 11pp
- 8007280336 Forwards response to IE Builetin 80-ii. "Masonry Wall Design " Walls located in reactor auxiliary fuel handling & turbine bldgs have been identified as being in proximity or having attachments from safety-related equipment HERBEIN.J G Metropolitan Edison Ce 80/07/11 34pp

- 8007210398 Forwards response to deviation noted in IE Insp Rept 50-289/80-05 Corrective action issued GAI/GPUNC TMI project mpt menual & GPUNC E8-009 to ensure that all GAI work is done per RRR KERBEIN, J G Metropolitan Edison Co 80/07/16 2pp
- B007250504 Responds to deviation noted in IE Insp Rept 50-289/80-05 Corrective actions GAI/GPUNC TMI project mpt manual Revision O dtd B00430 & GPUNC EB-009.Revision O dtd B00708 issued to ensure all GAI work is completed par util document HERBEIN.J G Metropolitan Edison Co B0/07/16 2pp
- 8007220592 Advises that review of IE Bulletin 80-10 re contamination of nonradioactive sys & resulting potential for unmonitored uncontrolled environ releases has not been completed Response will be submitted by 800815 HERBEIN. J G Metropolitan Edison Co 80/07/17 ip
- 8007220492 Responds to JE Bulletin 80~08, "Exam of Containment Liner Penetration Welds" Containment penetrations were shop fabricated, examined & pressure tosted prior to shipment to site for installation HERBEIN, J G Metropolitan Edison Co 80/07/18 1p
- 8007250401 Forwards final master list of Class IE electrical equipment required to function under postulated accident conditions in response to IE Bulletin 79-018, Item I Final response to incomplete items will be provided by 800901
 HERBEIN, J G Metropolitan Edison Co 80/07/18 32pp
- 8007290617 Responds to noncompliances noted in 791025 notice of violation Corrective action procedures extensively reviewed & revised radiation protection plan revised & review organization under study

 MERBEIN.J 0 Metropolitan Edison Co 80/07/21 13pp
- A Periodic operating reports & related correspondence
- 8007020182 Forwards TMI Program Ofc weekly status rept for wk of 800614-20. COLLING.J T TMI Program Office 80/06/23 App
- 8007180539 Forwards TM1 Program Ofc weekly status rept for wk ending 800709. COLLINS J T TMI Program Office 80/07/07 20pp
- BO07250719 Forwards status rept for wk of 800706-12 COLLINS.J T TM1 Program Office 80/07/14 Spp
- 8007310136 Forwards weekly status rept for 800713-19 Liquid effluents from Unit 1. released to Spsquehanna River.were within Tech Spec limits No liquid effluents discharged from Unit 2 COLLINS.J T TMI Program Office 80/07/21 Spp
- B007290799 Forwards monthly operating rept for June 1980 HERBEIN J G Metropolitan Edison Co 80/07/24 1p
- --8007270E05 Manthly operating rept for June 1980 MITCHELL,D 0 Metropolitan Edison Co 80/07/15 App
- S Reportable occurrences, LERs & related correspondence
- B007250223 PNO-TMI-80-025 on 800627, inadvertent emergency safeguards sys signal was actuated while in cold shutdown w/RCS partially drained Opened valve caused 10,000 gallons of water to be spilled in reactor bldg HAVERKAMP.D. FASAND, & Region 1. Philadelphia, Dffice of the Director COLLINS, J.T. TMI Program Office 80/06/27 ip.
- 8007250615 RO BO-12/IP during review of equipment required by IE Bulletin 79-01B, found that post-accident pressure & temp would be higher than postulated in NSC 730705 rept 8hort & long-term action to be discussed in followup rept TODLE, R J Metropolitan Edison Co BO/06/27 ip
- 8007070248 Forwards LER 80-010/01T-0 HERBEIN J & Metropolitan Edison Co 80/06/30 2pp
- --8007070256 LER 80-010/01T-O on 800606, licensee received itr stating FBAR does not assume that radioactive release paths exist via main safety valves or emergency feed pump turbing exist exacted by implementation of small break guidelines MITCHELL, D G Motropolitan Edison Co 80/06/30 ip
- 8007070302 Ferwards LER 80-008/99X-0 HERBEIN.J G Metropolitan Edison Co 80/06/30 ip

- --8007070313 LER 80-008/97X-0 on 800430 during annual insp of A emergency diesel generator, bearing insulation determined deteriorated Caused by normal agang or heating bearing lube oil Insulation replaced & lower viscosity oil used MITCHELL, D G Motropolitan Edison Co 80/06/30 3pp
- 8007080211 Forwards revised LER 80-004/01T-1 HERBEIN, J. G. Metropolitan Edison Co. 80/07/03 Lp.
- --8007080214 Revised LER 80-004/017-2 on 80030a errors found in seismic analysis of common decay heat suction piping associated w/ valves DH-V1 & DH-V2 Seismic analysis corrected & mods made to DH-V2 Mods to DH-V1 to be completed by 801015 MITCHELL, D Q Metropolitan Edison Co 80/07/03 2pp
- B007230158 PNS-1-80-018 on B00709, licensee received telephone bomb threat Licensee conducted full scale search y/negative results BAILEY,R , MARTIN,W Region 1, Philadelphia, Office of the Director B0/07/09 ip
- 8007160524 Forwards LER 80-012/01T-0 MERBEIN.J Q Metropolitan Edison Co 80/07/11 1p
- --B007160526 LER B0-012/01T-0 on B00627 during review of environ qualification of equipment required to operate during main steam line break per IE Bulletin 79-01B, found that postactident analysis exceeded previous figures
 MITCHELL,D Q Metropolitan Edison Co B0/07/11 2pp
- 8007160618 Forwards LER 80-011/03L-0 HERBEIN, J 0 Metropolitan Edison Co 80/07/11 1p
- --B007160623 LER 80-011/03L-0 on 800610 reactor bldg spray sys compressed air test exceeded late date Caused by incorrect date being entered into surveillance data tracking sys Info corrected Review of infrequent surveillances will be performed MITCHELL.D 0 Metropolitan Edison Co 80/07/11 2pp
- 8007230239 Part 21 rept re cracked steam generator manway studs Satisfactory operating experience forms constitute reasonable basis for continued operation while investigations proceed TAYLOR, J H Babcock & Wilcox Co 80/07/11 5pp
- 8007240133 PNO-80-002 on 800716 during NRC operations ctr drill large number of difficulties were experienced w/telephone sys, primarily due to cutting of telephone cable MEISB, B H . THOMPSON, D Office of Inspection & Enforcement, Office of the Director B0/07/18 Ip
- B0072804B3 RD 80-15/4P confirming B00722 telcon,on B00721.river water discharge temp was more than 3 F below inlet river water temp for approx 6-h incident will be reviewed to determine corrective action Review to be included in followup rept TOOLE.R J Metropolitan Edison Ca 80/07/22 1p
- U Congressional/Executive Correspondence
- 8007110363 Expresses interest of Environ, Energy & Natural Resources
 Bubcommittee in TMI accident implications Commissioners are
 invited to B00702 public hearings to present NRC policy
 statement & discuss intervenors' limitations
 MOFFETT, T Congress (Joint & Rotating Committees, etc.) B0/06/24
- DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 800701020B Forwards updated table of incomplete fire protection issues as of 800612 Proliminary fire protection review rept identifies supplemental info/mods for items requiring addlinfo IPFOLITO.T A Operating Reactors Branch 2 80/06/19 2pp
- 8007030142 Forwards draft revision to radiological emergency plan Plan withheld per Privacy Act & available in Central Files only ANDOGNINI, G C Boston Edison Co 80/07/01 1p
- **G** Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp

- P Operating license Stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Hart I owners group in Bethesda.
 MD.re revisions to NRC acceptance criteria & outstanding
 issues relative to Mark I contaminent long-term program
 ORIMES, C T Plant Systems Branch 80/02/21 31pp
- 8007010070 Responds to FOIA request for 57 documents referenced in M Tokar memo to ACR5 concerning pellet-cladding interaction Forwards documents Missing records are duplicative, superseded or available elsewhere FELTON, J M Division of Rules and Records 80/06/20 2pp
- --B007010134 Forwards DM Steinberg 750/23 memo re plant problems due to poor fuel performance Factors identified in memo are sufficient cause for NRC to re-ecomine requirements applicable to fuel 0.781LLY. J.P. Region 2, Atlanta, Office of the Director 75/07/25 2p
- --8007010141 Discusses facility problems dur to poor fuel performance Includes info re releases to environ, usposure to site personnel operational limitations plans for future & impact on Region i
 STERNBERO D M Region i, Philadelphia, Office of the Director 75/07/23 3pp
- B007210057 Advises that Class [II fee is required for review of 800403 ltr requesting Tech Spec changes to permit operation in Cycle 5 w/core spray spanger cracks MILLER.W O License Fee Management Branch 80/07/02 ip
- BOO7180557 Discusses review of facility Tech Spec definition of term, "operable," applying to single failure criterion for safety sys Current definition of operable will be modified to be consistent w/model Tech Spec version
 ANDOGNINI, C. G. Boston Edison (a. 80/07/03. 2pp
- BOO7180393 Forwards secondary containment leak rate test data Test was performed 800423 to verify that secondary containment was not violated by work performed during refueling MCGUIRE,P J. Boston Edison Co. 80/07/07 ip
- --B007180402 Secondary containment leak rate test data Includes test conditions, base reading & standby Ges Treatment Sys A & B performance

 * Boston Edison Co 80/04/23 1p
- B007290576 Requests extension until 800915 for comment period for NUREG-0577, "Potential for Low Flacture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Coelant Pump Supports " NUREG-0577 experienced distribution difficulties ANDGONINI, G C Boston Edison Co 80/07/21 1p
- O Inspection reports. IE Bulleting & correspondence
- 8007140440 Forwards IE Bulletin 80-13. "Cracking in Core Spray Spargers " Written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/05/12 1p
- 80071B0077 Forwards IE Insp Rept 50-293/80-11 nn 800310-14 No nancampliance noted BRUNNERE J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/23 2pp
- --B0071B010) IE Insp Rept 50-293/80-11 on B00310-14 No noncompliance noted Major areas inspected GA annual review GA/GC administration program design changes, mod program & plant mods SAPUDA, 0, RODERTB, K. Region 1, Philadelphia, Office of the Director GREENNAN E. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch B0/05/20 ilps
- 8007020116 Forwards IE Info Notice 80~22, "Breakdowns In Contamination Control Programs" No written response required GRIFR, D H Region 1, Philadelphia, Office of the Director 80/05/28 ip
- BOO7010277 Forwards IE Info Natice 80-23, "Loss of Sultion to Emergency Feedwater Pumps" No written response required ORIER.D M. Region I. Philadelphia, Office of the Director BO/05/29 1p
- B00710006B Ack receipt of 800520 ltm informing NRC of stops taken to correct violations noted in IF Imap Rept 50-293/80-08 | tr withheld (ref 10CFR2 790)
 MARTIN.W G Region 5. Philadelphia, Safeguerds Branch 80/06/04

- --B007100071 Forwards IE Insp Rept 50-293/80-08 on B00227-29 & notice of violation Notice of violation withheld (ref 100FR2 790) MARTIN W G Region 1, Philadelphia, Safeguards Branch B0/04/24 200
- ---B007i00074 IE Insp Rept 50-293/80-08 on 800227-29 Noncompliance noted failure of security organization to follow response procedures in security contingency plans Details withheld (ref 100FR2 790) LADUNR W Region I, Philadelphia. Office of the Director DEVLIN, J W Region I, Philadelphia. Sateguerds Branch 80/04/17
- 8007210551 Forwards IE Info Notice 80~26. 'Evaluation of Contractor GA Programs " No written response required ORIER,B H Region 1. Philadelphia. Office of the Director 80/06/10 ip
- 8007140257 Forwards IE Bulletin 80-14. "Degradation of DWR Scram Discharge Vol Capability " Written response required GRIER, B M Region 1. Philadelphia. Office of the Director 80/06/12 1p
- 8007250267 Forwards 1E Insp Rept 50-293/80-24 on 800409-10 Na noncompliance noted CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/16 2pp
- --B007230270 IE Insp Rept 50-293/B0-24 on B00409-10 No noncompliance noted Major areas inspected routing insp of installed main steam automatic depressurization sys relief valve & solenoid valves
 EBNETER, S D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch FINMEL.A E Region 1. Philadelphia, Office of the Director B0/06/13 3pp
- B007280401 Forwards IE Investigation Rept 50-293/80-19 on B00428-0502 No noncompliance noted GRIER, B M Region 1. Philadelphia. Office of the Director B0/06/17 2pp
- --8007280408 IE Investigation Rept 50-293/80-19 on 800428-0502 No noncompliance noted Major areas inspected allegations contained in 800320,0403 & 08 newspaper articles re security guard misconduct ALLANJ M . SMITH-R H Region I, Philadelphia, Office of the Director 80/06/13 17pp
- 800702069: Forwards IE Bulietin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power "Written response required GRIER, D H Region 1. Philadelphia, Office of the Director BO/06/18 1p
- 8007020486 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/20 kp
- 8007160683 Forwards 1E Circular 80-14, "Radioactive Contomination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel " No written response required ORIER II H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- B007210164 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria" No written response required ORIER.B H Region 1. Philadelphia. Office of the Director 80/06/25 ip
- BOO7140415 Responds to 1E Bulletin 79-14 re as-built safety-related piping sys seismic analysis Safety-related piping sys physical inspicompleted & inspicoviations resolved Seismic analyses input documents reviewed & most mode completed ANDOGNINI.9 C Boston Edison Co 80/06/27 Ppp
- 8007210006 Submits summary of insp % analysis results w/status of mods per util overall commitment, in response to IF Bulletin 79-14 Final rept re grocedures & uniteria will be submitted by 801233 Support mode axpected to be completed by 800901 ANDUGNINI, C C Boston Edison Co 80/06/27 2pp
- B007210301 Responds to 1E Bulletin 80-06 me engineered safety feature reset controls Components assigned to two categories items requiring single operator action & items requiring two operator actions to reset initiating beginning of signal ANDCONINI.O C Boston Edgen Co 80/06/2/ 4pp

- 800723009) Forwards 1E Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-11 also encl No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007230182 Ack receipt of 800604 ltr informing NRC of steps taken to correct violation moted in IE Insp Rept 50-293/80-14 BRUNNER,E J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/27 1p
- --B007230196 Responds to NRC 800315 ltr re violation noted in IE Insp Rept 50-293/80-14 Corrective actions records of all licensed operators being reviewed to bring Forms 0-3 up to date ANDGONINI.9 C Boston Edison Co 80/06/04 2pp
- --8007230202 Forwards IE Insp Rept 50-293/80-14 on 800408-11 & notice of violation BRUNNER.E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/15 2pp
- --8007230209 Notice of violation from insp on 800408-11 * Region 1, Philadelphia, Office of the Director 80/05/09 ip
- --B007230221 IE Insp Rept 50-293/B0-14 on B0040B-11 Nencompliance noted failure to keep requalification program records as required by licensee manual BETTENHAUSEN.L. KEHOE, D V Region i, Philadelphia, Office of the Director CAPHTON.D L Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/09 8pp
- 8007220174 Forwards notice of violation notice of proposed imposition of civil penalties & ltr of reprimand re 800308 incident of irradiated fuel being moved w/o secondary containment integrity
 BTELLD,V Office of Inspection & Enforcement, Office of the Director 80/07/08 3pp
- --8007220175 Notice of violation from insp on 800303-21 * Office of Inspection & Enforcement, Office of the Director 80/07/08 2pp
- --8007220181 Notice of proposed imposition of civil penalties in amount of \$13,000 re 800308 moving of irradiated fuel w/o secondary containment integrity

 * Office of Inspection & Enforcement, Office of the Director 80/07/08
- --8007220187 Expresses concern re conduct during 800308 incident at facility future violations may result in stringent NRC enforcement actions including license mod, revocation or suspension &/or civil penalty BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/07/08 lp
- ~~8007220191 Forwards notice of violation reactions during 900309 moving of irradiated fuel w/o secondary containment integrity at facility
 BTELLO, V Defice of Inspection & Enforcement, Defice of the Director 80/07/09 200
- --8007220199 Notice of violation for License SOP-1585-4, based on insp on 800303-21 re J Alukonis activities during 800308 moving of irradiated fuel w/o secondary containment integrity # Défice of Inspection & Enforcement, Office of the Director 80/07/08 19
- 8007240972 Confirms oral notification made on 800707 that 20-day period for completing tests required by IE Bulletin 80-17, Item 2, began at 12 01 AM on 800708 Also requests immediate notification of any malfunction found during tests GRIER, B.M. Region 1. Philadelphia, Office of the Director 80/07/09 2pp
- BOO7210373 Responds to Item 1 & provides comments re Item 2 of IE Bulletin 80-17, "Fai)ure of 76 of 185 Control Rods to Fully Insert During Scram at BWR " Examinations showed insignificant amount of water in 6-inch discharge header HOMARD, J C Boston Edison Co BO/07/10 3pp
- 8007250309 Submits reply to IE Sulletin 60-10 re contamination of nonradioactive sys & potential for release to environ Sampling analysis & monitoring programs determined to be adequate ANDGONINI.G C Boston Edison Co 80/07/11 1p
- BOO7RBO24B Ack receipt of BOO619 ltr informing NRC of steps taken to correct violation noted in IE lnsp Rept 50-293/80-18 BRUNNER,E J. Region L. Philadelphia, Reactor Operations Nuclear Bupport Branch BO/07/11 ip

- --8007280282 Responds to NRC 800527 ltr re violation noted in IE Insp Rapt 50-293/80-18 Corrective actions covers installed on feedwater check valves when work not being performed ANDOGNINI.6 C Boston Edison Co 80/06/19 2pp
- --8007280256 Forwards IE Insp Rept 50-293/80-18 on 800422-30 & notice of violation BRUNNER, E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/27 2pp
- --8007280258 Notice of violation from insp on 800422-30 * Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/22 ip
- --8007280262 IE Insp Rept 50-293/80-18 on 800422-30 Noncompliance noted failure to control foreign matl in accordance w/maint procedure requirements JOHNSON, J. ROBERTS, K. Region 1. Philadelphia. Office of the Director MARTIN.T.T. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/22 Bpp
- B007210280 Ack receipt of B00310 ltr informing NRC of steps taken to correct violation noted in B00215 notice of violation BTELLO,V Office of Inspection & Enforcement, Dffice of the Director B0/07/14 2pp
- A Periodic operating reports & related correspondence
- BOO7150699 Forwards monthly operating rept for June 1980 MCQUIRE, P J Boston Edison Ca 80/07/08 ip
- ---B007150704 Monthly operating rept for June 1980 WHITNEY, G G Boston Edison Co 80/07/07 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 8004240228 PNO-I-80-38 on 800308, two irradiated fuel assemblies lifted & rotated in spent fuel pool w/o meeting Tech Specs for secondary containment & diesol generator operability Fuel movement halted until Tech Specs met
 LAZARUS, W. J. BRUNNER, E. Region i, Philadelphia, Office of the Director 80/03/10 ip
- B007010540 Forwards LER 80-022/03L-0 MCQUIRE, J.P. Boston Edison Co. 80/04/25 1p
- --8007010545 LER 80-022/03L-0 on 800527, during performance of surveillance test re RCIC steam line high temp.temp switch 1360-17A was found out of calibr Caused by setpoint drift MCLOUGHLINM T Boston Edison Co 80/06/25 IP
- 8007070378 Forwards LER 80-021/04T-0 MCQUIRE,P J Boston Edison Co 80/06/25 ip
- --8007070382 LER 80-021/04T-0 on 800508; algae sample from discharge outfall area contained reportable concentration of Co-60, according to Yankee Environ Lab 800616 analysis rept Cause not stated MCLOUGHLIN.M Y Boston Edison Co 80/06/25 2pp
- 8007030287 Forwards LER 80-024/03L-0 MCQUIRE, P.J. Boston Edison Co. 80/07/01 1p
- ---8007030289 LER 80-024/03L-0 on 800930 reactor core isolation cooling sys was declared inoperable Caused by faulty auto flow control Unit repaired & returned to svc MCLOUGHLIN, M T Boston Edison Co 80/07/01 ip
- 8007070357 Forwards LER 80-023/03L-0 MCGUIRE, P. J. Boston Edison Co. 80/07/01 ip
- --8007070388 LER 80-023/03L-0 on 800526, during surveillance testing, Channel B of rod block monitor sys determined to be out of calibr Caused by misinterpertation of Tech Specs Requalification program will include sys review MCLOUGHLIN, M T Baston Edison Co 80/06/26 2pp
- 8007080182 Forwards LER 80-025/03L-0 MCQUIRE, P J Boston Edison Co 80/07/02 1p
- --B0070B0192 LER B0-025/03L-0 on BC0602, fire detection alarm from HPC1 quadrant sounded in control room on panel C-94 Roving fire patrol initiated & immediate investigation conducted Caused by leak at flange on HPC1 drain line valve AD2301-29 WHITNEY, G O Boston Edison Co 80/07/01 1p

- 8007080196 Forwards LER 80-026/03L-0 MCOUIRE,P J Boston Edison Co 80/07/02 ip
- --8007080200 LER HO-026/O3L-O on B00603) reactor scram initiated by reactor low water level switcher of reactor protection sys NRC not notified within required time Caused by operations personnel error Requirements in e-emphasized MCLQUGHLIN, M T Boston Edison Co B0/0//02 ip
- B0070B0202 Forwards LER B0-027/03L-0
 MCGUIRE, P. J. Boston Eduson Co. B0/07/03 10
- --B0070B0205 LER B0-027/O3L-0 on B0060%, stack gas grab sample pump PI4 tripped Caused by hinding in pump due to accumulation of dirt Pump refurbished & returned to svc MCLOUGHLIN.M T Buston Edison Co B0/07/02 ip
- B007160641 Forwards updated LER 77-009/03L-1 MCGUIRE,P J Boston Edgen Co B0/07/03 lp
- ---B007160648 Updated LER 77-009/03L-1 on 7/0323 during standby operation HPCI was inoperable for 5-h Caused by burnt out undervoltage coil in broaker for motor operated valve MD 2301-3 steam supply valve to HPCI Caused by overheating MCLGUOHLIN, M T Doston Edison Co 60/07/03 2pp
- BOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACIOR

 O Inspection reports, IE Builetins & correspondence
- B007170633 Forwards 1E Circular B0-14. "Radioactive Centamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J 0 Region 3. Chicago. Office of the Director 40/06/24
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withhold (ref 10CFR2 790)
 PEOPLES,D l Communwealth Edison Co 80/06/27 tp
- O Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum to order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum to order UCS 771104 petition sought action refire protection for electrical cables CISENHUTIO 8 Division of Licensing 80/06/25 89pp
- 8007020646 Memorandum specifying issues to be discussed at 800701 oral argument, re State of IL contention that applicant commitments should be integrated in license Tech Specs, in storage pool mod proceeding TOMPKINS.B A Atomic Safety and Licensing Appeal Panel 80/06/26
- B007100022 Farwards "Tech Specs for Nuclear Power Reactors." 10CFR50 advance notice of rulemaking for which counsels attention is invited by ASLB Comments may be rubmitted to Commission re B00701 oral argument BISHDP.C J. Atomic Safety and Licensing Appeal Panel 80/07/03
- --8007100026 "Tech Specs for Nuclear Power Reactors." (GCFR50 advance notice of rulemaking Establishes std for deciding which items from SAR must be incorporated into Tech Specs & modifies definitions of spec categories.

 CHILK.S J Dfface of the Secretary of the Commission 80/06/30
- 9pp

 8007300000 Updates certain projected load & capacity estimates which appear in record of proceeding per applicant obligation to keep ASLAO appraised of development. Related concespondence STEPTOE, P.P. Isham, Lincoln & Seale 80/07/08 2pp
- H General correspondence
- 8007110533 Responds to 8002/8 request to reject util livense to increase storage capacity or facility spent fuel pool Actions initiated 791010 to assure that emergency plans are implemented at all licensed operating reactor sites DENTON, HR Office of Nuclear Reactor Regulation. Director 80/09/06 200

- 8007210208 Responds to encl 800418 ltm to President Camber re Indian Point Facility Describes NRC efforts to protect public health at Facilities currently operating or planned for operation Village Voice news article encl BENTON. H R Office of Nuclear Reactor Regulation, Director 10pp
- B00731033B Responds to enal B00401 telegram to President Carter urging closing of facility & all nuclear plants near populated areas NRC 800829 confirmatory order required immediate short-term actions to assure public safety EISENHUT.D G DIVISION of Licensing 80/07/17 App
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 800722030B Provides summary of 800507-08 meeting w/utils re core melt accident sequences Utils appear to expect NRC to resolve problems & do nothing to mitigate consequences of Class 9 accidents CATTON, I California, Univ. of. Los Angeles 80/05/10 App
- P Operating license stage documents & correspondence
- 8004240480 Forwards addl info re review of unresolved safety issues. trip rept of Lessens Learned implementation team & task action plan in view of high population density surrounding plants
 DENTON, H.R. Office of Nuclear Reactor Regulation. Director
 80/04/09 33pp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution entl for guidance EISENHUT.D G Division of Licensing 60/06/11 &2pp
- 8007100393 Summary of 600520 Technology Exchange Meeting 3 w/utils in Bethesda.AD to discuss accident mitigation features for power plants LONG, J K Division of Systems Integration 80/08/12 75pp
- 8007010110 Notification of 800625 meeting w/utils & Sandia Labs in Bethesda.MD for presentation of overview of facilities risk study Agenda encl 18RAEL.5 L. Reliability & Risk Assessment Branch 80706/16 3pp
- 8007110557 Summary of 800530 meeting w/util in Dethesda, MD re status of action plan OLSHAN, L N Operating Reactors Dranch L 80/06/23 3pp
- B00701042B Forwards Drawing RZE-1-4B50 re reactor, turbine & generator trip protection, in response to B00619 discussion concerning automatic initiation of auxiliary feedwater sys Brawing available in Central Files only NAUGHTON, W.F. Commonwealth Edison Co. B0/06/24 1p
- 8007010211 Forwards response to 800229 confirmatory order requiring review of key plant sys volnerability areas, possible operator dependent areas & control room emergency Procedures NAUGHTON:W F Communwealth Edison Co 80/06/26 49pp
- 800701060B Notification of 800617 meeting w/utils in Bethesda.MD to discuss containment structural response failure pressures & failure modes for facilities as described in NRC 800410 ltr to Comm Ed MEYER.J F Reactor Systems Granch 80/06/26 2pp
- B007070116 Submits revised responses to MRC 770603 ltrs re second level of undervoltage protectson for 4 kV emergency power buses supplying safety-related loads
 JANECEK.R / Commonwealth Edison Co 80/06/26 4pp.
- 8007170319 Summary of 800612 meeting w/utils in Bethesda.MD re interim reliability evaluation program DLSHAN.L N Operating Reactors Branch 1 80/06/30 3pp
- 8007170241 Forwards request for add) into re backfitting of severe accident mitigation features Response requested within 30 days MOVAK, T M Assistant Director For Operating Reactors 80/07/02
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PMR Model Tech Specs & Model License conditions for TMX-2 Lessons Learned Category & Items encl for guidant G EISENHUF.D & Division of Licensing 80/07/02 69pp

- 8007150476 Submits addl info re 10CFR50.App J.exemption Mod to install flowmeter w/high flow alarm on penetration pressurization piping to personnel air lock door seels completed Includes marked set of drawings W/o drawings
 NAUGHTON.W F Commonwealth Edison Co 80/07/07 4pp
- B00717059B Summary of B006R5 meeting w/Pickard.Lowe & Garrick.Inc re risk study including modeling for plume tragectory, containment event tree & modeling.use of plant data & consideration of external events ISRAEL.S L Reliability & Risk Assessment Branch B0/07/07 Bpp
- 9007230646 Summary of 800307-08 technology exchange meetings w/utils in Chicago IL re core melt accident sequences & associated phonomenology for facilities NRC perceives real urgency to for answers to key technical questions
 MEYERJ F Reactor Systems Branch 80/07/09 12pp
- B007280605 Notifies that PG Stoddart, primary NRC reviewer for Zion, has requested add1 info to complete review, as result of discussions re NUREG-0578 Item 2 1 8a on improved post-accident sampling capability Lists drawings sent NAUGHTON.W F Commonwealth Edison Co 80/07/21 2pp
- @ Inspection reports, IE Bulletins & correspondence
- 8007020065 Forwards IE Info Notice 80-22, "Breekdowns In Contamination Control Programs " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/05/28
- BOO7210356 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 8 80/05/28
- 8007010086 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J C Region 3. Chicago. Office of the Director. 80/05/29
- 8007020050 Forwards response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVGS) Moldup Tanks "Three Zion heldup tanks can be valved to contain primary sys water Positive pressure is maintained PEGPLES, D. L. Commonwealth Edison Co. 80/06/04 3pp
- B007220156 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/10
- E007020199 Forwards IE Insp Repts 50-295/80-09 & 50-304/80-09 on B00512-15 & 19-20 & notice of violation Notice of violation withheld (ref 10CFR2 790) HIND. J A Region 3. Chicago. Safeguards Branch 80/05/11 2pp
- ---B00702021) IF Insp Repts 50-299/80-09 & 50-304/80-09 on 800512-15 & 19-20 Noncompliance noted failure to conduct proper personnel screening to secure & attend doors of vital areas & to test alarm sys Details withheld (ref 10CFR2 790) MADEDA; T J. CHRISTOFFER: O Region 3, Chicago, Office of the Director HIND, J A Region 3, Chicago, Safeguards Branch B0/06/10 2pp
- 8007160169 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Stude " No specific action or response KEPPLER, J 0 Region 3, Chicago, Office of the Director 80/06/11
- 8007020076 Forwards response to IE Bulletin 80~12, "Docay Heat Removal Sys Operability " Review of RHR degradation events found nume similar to Davis-Besse incident DELGEDROG, L O Commonwealth Edison Co 80/06/16 Spp
- B007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators
 PEOPLES,D L Commonwealth Edison Co 80/06/16 3pp
- 8007030037 Forwards IE Bulletin BO-15. "Possible Loss of Emergancy Notification Bys (ENS) W/Loss of Offsite Power " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/: Region 3. Chicago, Office of the Director 80/06/18

- 8007020589 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown " No written response
- REPPLEASING Region 3. Chicago, Office of the Director 80/06/20
- BOO7230754 Forwards IE lnsp Repts 90-295/80-08 & 90-304/80-08 on BOO421.0815-20.30 & 31. No noncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch BO/06/23 2pp
- ---B007230758 IE Insp Repts 50-295/80-08 & 50-304/80-08 on 800421,0515-20. 30 & 31 No noncompliance noted Major areas inspected Bergen-Paterson large bore hydraulic snubbers on Unit 2 steam Patersun large Colon 3. Chicago, Reactor Constitution & DANIELSON, D.H. Region 3. Chicago, Office of Engineering Support Branch YIN.1 T. Region 3. Chicago, Office of the Director 80/06/18 3pp
- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required MEPPLERJ G Region 3, Chicago, Office of the Director 80/06/24
- 8007230268 Forwards IE Imap Repts 50-275/80-11 & 50-204/80-11 on 800527-29 & notice of violation DAVIS, A B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/06/24 2pp
- --8007230272 Notice of violation from insp on B00527-29 * Region 3. Chicago, Office of the Director 80/0 80706720 In
- --B007230276 IE Insp Repts 50-299/80-11 & 50-304/80-11 on 800527-29 Noncompliance noted excess pH of waste water roleased & failure to standardize sodium hydroxide solution during boric acid titration E6910.TH, DESTMANN,M J. ROYTEM,C Region 3, Chicago, Office of the Director 80/06/20 9pp
- BOO7230289 Forwards IR Bulletin BO-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular BO-16 also encl No written response required MEPPLER.J O Region 3, Chicago, Office of the Director BO/06/2 B0/04/27
- B007310507 Forwards IR Health Physics Appraisal Repts 50-275/80-05 & 50-304/80-04 on B00310-21, notice of violation & significant appraisal findings KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27
- ---8007310810 Notice of violation from health physics appraisal on Ragion 3, Chicago, Office of the Director 80/06/27 2pp
- ---8007310515 IE Health Physics Appraisal Repts 50-295/80-05 & 50-304/80-04 on 800310-21 Noncompliance noted significant weaknesses found in areas reflecting on mgt & mgt support Weaknesses in emergency response & access control BCHUMACHER, M. G. MILLER, D. E. Region 3. Chicago, Office of the Director FISHER; W. Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/06/23 58pp
- 8007310335 Forwards Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 DAVIS A B Region 3, Chicago, Fuel Facility & Materiels Safety Branch 80/06/30 3pp
- -8007310339 Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 Noncompliance w/DDT regulations noted max dose rate on surface of transport trailer was 220 millitrem/h O'REILLY,L A Region 5, Ban Francisco, Office of the Director THOMAS,R D , 8008.H E Region 5, Ban Francisco, Fuel Facility & Materials Bafoty Bronch 80/04/02 12pp
- 8007310339 Waste Packaging Insp Rept 15000046/80-32 on 800222 & 26 Noncompliance w/DOT regulations noted max dose rate on surface of transport trailer was 220 milliram/h O'RELLYL A Region 5, San Francisco, Office of the Director 80/04/02 12pp
- 8007250641 Responds to IE Bulletin 80-10, "Contamination of Nonradioactive 8ys & Resulting Potential for Unmonitored. Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found PEOPLES, D. L. Commonwealth Edison Co 80/07/07 2pp.

- 8007250650 Forwards response to IE Bulletin 80~11. "Masonry Wall Design " Requested investigation not performed at Dresden. Unit 1 due to extended outage Requirements will be met prior to startup W/o encl
 PEDPLES.D L Commonwealth Edison to 80/07/07 2pp
- 8007250638 Forwards response to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds " Dresden Unit I designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D L. Commonwealth Edison Co. 80/07/09. 7pp
- A Periodic operating reports & related correspondence
- 8007140327 Forwards monthly operating repts for June 1980 GRAESSER. W. L. Commonwealth Edison Co. 80/07/07 ip
- ---6007(4033) Monthly operating repts for June 1980 CODK, J M Commonwealth Edison Co 80/07/07
- 8 Reportable occurrences, LERs & related correspondence
- 8007170230 Part 21 rept re defective Westinghouse Type W-2 switch Caused by intermittent contact closure w/switch in automatic start position Utils notified of potential problem NSD technical bullotin encl ANDERBON, T. M. Westinghouse Electric Corp 80/05/18
- 8007010484 Forwards LER 80-028/03L-0 WANDRE, N E Commonwealth Edison Co 80/06/23
- -8007010488 LER 80-028/03L-0 on 800524.while performing diesel generator loading test on ID diesel generator engine tripped after running 5 minutes at full load Caused by air leak on supply line fitting to fuel shutoff pistons Fitting replaced RRAHCZAK,A T Commonwealth Edison Co 80/06/27 ip
- 8007010493 Forwards LER 80-029/03L-0 WANDRE,N E Communication Edison (Commonwealth Edison (c 80/06/26 12
- --8007010500 LER 80-029/03L-0 on 800531.while removing insulation to repair leak on discharge line to boric acid filter 1.heat trace on circuits DME 190/205 were damaged Caused by numerous nicks 11 heat trace by personnel offecting HAZELRIGG, S Commonwealth Edison Co 80/06/26 ip , repair
- 8007140655 Forwards LER 80-030/03L-0 GRAESSER, X L. Commonwoalth Edison Co. 80/07/0/
- -8007160662 LFR 80-030/03L-0 on 800612.during normal operation.condenser air ejector offgas rad monitor.IRT-P126, failed low Caused by worn contacts inside photohelic.apparently worn down through normal use Photohelic replaced OST.F Commonwealth Edison Co. 80/07/07 ip
- 8007220449 Forwards LER 80-032/03L-0 GRAESSER, K.L. Commonwealth Edison Co. 80/07/15 1p
- --8007220453 LER 60-032/03L-0 on 800616, fuel oil storage tank level Notational Commonwealth Edison Co. 80/07/16 ip

80/07/21

80/07/21

- 8007220379 LER 80-007 has been cancelled COLLING M Commonwealth Edison Co 80/07/21 1p
- 8007220400 LER 80-006 has been cancelled COLLING.M Commonwealth Edison Co. 80/07/21
- 8007220401 LER 80-004 has been cancelled COLLINS, M Commonwealth Edison Co. 6 80/07/21
- 8007220402 LER 79-075 has been cancelled COLLING, M. Commonwealth Edison Co. 8

8007220404 LER 79-067 has been cancelled COLLINS, M Commonwealth Edison Co 8

- 8007220405 LER 79-064 has been cancelled COLLING.M Commonwealth Edison Co 80/07/21
- 8007230345 LER 80~003 has been cancelled COLLINS, M Commonwealth Edison Co 8 80/07/22

- 8007230347 LER 79-089 has been cancelled COLLINS, M. Commonwealth Edison Co. 80/07/22 to
- 8007230351 LER 79-988 has been tancelled COLLINS.M Commonwealth Edison Co. 80/07/22 ip
- 8007230332 LER 79-086 has been cancelled COLLINS,M Commonwealth Edison Co 80/07/22 ip
- 8007230357 LER 79-080 has been cancelled COLLING.M Commonwealth Edison Co 90/07/22 1p
- T Hearing transcripts on non-antitrust matters
- 8007150024 Transcript of B00701 morning hearing in Bethesda,MD Pp
- * Atomic Safety and Licensing Board Panel 80/07/01 123pp
- DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8007210024 Forwards list of vital areas & equipment resulting from vital area analysis conducted at facility & computer printout containing supporting data for vital area analysis Encls withheld (ref 10CFR2 790)

 IPPOLITO.T A Operating Reactors Branch 2 80/06/30 2pp
- 8007220028 Confirms that LASL will conduct vital area analysis of Units 2 & 3 on 800714 E Claibourne & J Rand will conduct visit IPPOLITO T A Operating Reactors Branch 2 80/07/03 2pp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refire protection for electrical cables EISEMANUT, D G Division of Licensing 80/06/25 87pp
- H General correspondence
- 8007170380 Expresses concern re plans to construct low level waste storage & incineration facility Proposed facility would present significant health risks to highly populated area Requests public hearing & FIS
 HOLLINGSWORTH Affiliation Unknown 80/07/09 1p
- J. Insurance & indemnity information
- B007010516 Forwards Endorsement 51 to ANI Policy NF-198 FIELDER, J. Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc. Div 80/06/23 2pp
- B007310436 Forwards Endorsement 43 to MAELU Policy MF-66 FIELDER.J Marsh & McLennan.lnc . B & M Nuclear Consultants.inc Div B0/07/21 2pp
- P Operating license stage documents & correspondence
- B00723002B Summary of B00207 meeting w/Mark I owners group in Bethesda. MD.re revisions to NRC acceptance criteria & gustending issues relative to Mark I containment long-term program GRIMEB.C T Plant Egstems Branch 80/02/21 31pp
- 8007070269 Responds to 800123 ltr re use of DDYN code in determining operating limit min critical power ratio Util requests further clarification of expected penalties that may be imposed on top of DDYN calculations
 MILLS.L M Tennessee Valley Authority 80/05/28 2pp
- B007020711 Responds to 800422 ltr re low level wasto mgt at plant Ultimate util objective is to provide for ansite radwaste storage No target date has been established by TVA for submitting application for incineration approval NOVAK, T M Assistant Director for Operating Reactors 80/06/25 3pp
- 8007080286 Responds to NRC 800523 request for facility participation in phase two Interim Reliability Evaluation Program Urges definitive conclusion of phase one before continuing Outline of critical areas to be resolved encl
 MILLS,L M Tennessee Valley Authority 80/06/30 3pp

- B007080390 Responds to NRC 791002 ltr to all BWR licensess & 791031 ltr to util Util Funds allocated for Mark I owners group full-scale test facility program Schedule for completion of plant-unique analysis forthcoming MILLS.L M Tennessee Valley Authority 80/07/01 1p
- 8007210026 Forwards request for add1 info to complete review of containment purging & venting at facilities
 NDVAK.T M Assistant Director for Operating Reactors 80/07/08
 500
- 8007220376 Forwards proposed changes to ETS Section 2 1 re thermal discharge limits
 MILLS.L M Tennessee Valley Authority 80/07/14 ip
- ---B0072203/7 Proposed change to ETS, Section 2 % re thermal discharge limits
- * Tennessee Valley Authority 80/07/14 1p
- 8007310531 Confirms 800712 concurrence w/util schedule for returning to power operation Concurrence based on util completion of corrective actions re failure of control rod sys following manual trip
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/07/14
- 8007240225 Forwards Amends 61.56 & 33 to Licenses DPR-33.DPR-52 & DPR-68.respectively & notice of issuance & availability IPPDLITO.T A Operating Reactors Branch 2 80/07/15 Spp
- --8007240231 Amends 61.56 & 33 to Licenses DPR-33, DPR-52 & DPR-68, respectively, changing Tech Specs re thermal discharge limits
 IPPOLITO, Y.A. Operating Reactors Branch 2 80/07/15 13pp
- --B007240234 Notice of issuance & availability of Amends 61.56 & 33 to Licenses DPR-32, DPR-52 & DPR-48, respectively IPPOLITO, T A Uperating Reactors Branch 2 80/07/15 2pp
- BOO/300284 Responds to encl BO0602 memo re low level waste mgt at facility Util plans to construct two separate low level waste facilities onsite Const on first four cubicles began recently NRC approval of plans necessary DENTON.HR Office of Nuclear Reactor Regulation, Director BO/07/23 Bpp
- ---800730029: Roquests summary of util plans to build low level waste storage facility Also requests whether NRC approval is required & whether public hearings have been requested BRADFORD.F A Commission 80/06/02 ip
- G Inspection reports. IE Bulletins & correspondence
- 8007240089 Forwards JE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/05/08
- 8007140476 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/12 In
- 8007020192 Forwards IE Info Notice 80-22. "Dreakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/28 io
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29 is
- G007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director G0/06/10 30a
- BOO7140306 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/12 ip
- 8007020497 Forwards response to IC Bulletin 80-09 transmitted by JP D'Reilly 800417 ltr Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLS,L M Tennessee Valley Authority 80/06/16 2pp

- 8007020761 Forwards IE Bulletin 80~15, "Postable Loss of Emergency Notification 8ys (ENB) M/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Offsice of the Director 80/06/18
- 8007020391 Forwards IF Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/20
- B007310344 forwards IE Insp Repts 50-239/80-25,30-260/80-19, 50-296/80-20 & 50-327/80-22 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/23
- --8007310351 IE Insp Repts 50-259/80-25,50-260/80-19,50-294/80-20 & 50-327/80-22 on 800521 Insp consisted of enforcement meeting in Atlanta. GA to discuss exceeding DOT radiation limits during shipment of radwaste from Browns Ferry DANCE. H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/20 2pp
- BOO7170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/24 is
- BOO7180523 Forwards response to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation." & to 800404 confirmatory orders Feedwater pump turbing & main turbing trip circuitry will be upgraded MILLS.L M Tennessee Valley Authority 80/06/26 Spp
- 8007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Rogion 2, Atlanta, Office of the Director 80/06/27
- BOO7210091 Forwards response to IE Bulletin BD-10 Potable water, mineralized water & auxiliary boiler sys have possible interfaces between nonradioactive & radioactive sys Routine sampling & analysis program established MILLB.L.M Tennessee Valley Authority BO/07/07 Spp
- B007230726 Forwards monthly status rept re IE Bulletin 79-14. "Seismic Analysis for An-Built Bafety-Related Piping Bys." presenting status of work as of 800701 MILLS.L H Tennessee Valley Authority 80/07/07 29pp
- B007280615 Responds to IE Bulletin 80-08. "Examination of Containment Penatration Welds " Results of investigation encl MILLS,L M | Fannessee Valley Authority | 80/07/07 | 5pp
- 8007210103 Forwards response to IE Bulletin 80-11 Identifies masonry walls that support or are near safety-related sys Submits schedule for re-evaluation program CROSS, J L Tennesser Voiley Authority 80/07/08 3pp
- 8007280460 Ack receipt of 800616 ltr informing NRC of steps laken to correct violations noted in IE Insp Repts 50-259/80-20. 50-260/80-15 & 50-296/80-16 LEWIB,R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/07/09 2pp
- --800728046B Responds to NRC 800520 ltr re violations noted in lnsp Repts 50-259/80-20,50-260/80-15 & 50-296/80-16 Corrective actions calibr valve orientation corrected Justifies decision re nonreporting of deisel genrator failure MILLS.L M Tennessee Valley Authority 80/06/16 4pp
- --8007280475 Forwards IE Insp Repts 50-259/80-20.30-260/80-15 & \$0-296/80-16 on 800405-0502 & notice of violation LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/20 2pp
- --8007280478 Notice of violation from insp on 800405-0502

 * Region 2, Atlanta, Office of the Director 80/05/20 ip

- 8007250596 Forwards response to Item 1 of IC Bulletin 80-17 to water in scram discharge vol No significant amount of water was found in discharge vol % associated piping Scram discharge vent valves are operable CROSS.U.L. Tennessee Valley Authority 80/07/11 2pp
- B007310067 Forwards second interim rept in response to IE Bulletin B0-06 Since B00612 interim rept.util completed review of primary containment sys.reactor protection sys.RMP sys *core spray sys Fvaluation of other sys underway CROSS.J L Tennessee Valley Authority B0/07/11 2pp
- B007220522 Requests extension until B00811 for performing manual & automatic scram required by IE Bulletin 80-17 Extension needed because of current heat wave MILLS.L M Tennessee Valley Authority 80/07/16 2pp
- 8007310208 Forwards response to Items 2 (Unit 3).4.5.6(c) & 7 of IE Bulletin BO-17 Present standby liquid control sys design is unable to support two-pump flow but sys is equipped w/ interlocking contacts Item 2 for Units I & 2 will be sent MILLS.L M Tennessee Valley Authority 80/07/16 10pp
- BOO7270357 Grants extension of time to BOOB!! For performing scramests per IE Bulletin BO-17
 EISENHUT.D G Division of Licensing BO/07/18 2pp
- 8007300972 Forwards response to IF Bulletin 79-018, "Environ Qualification of Class IE Equipment " Summaries of equipment qualification evaluations, based on Encl 4 criteria, encl Full response will be forwarded when evaluations complete MILLS.L M Tennessee Valley Authority 80/07/18 54pp
- R Periodic operating reports & related correspondence
- 8007220443 Forwards "Efficient % Waste Disposal Semiannual Regt," supplemental info for second half 1978
 DEWEASE, J G Tennessee Valley Authority 79/02/15 1p
- ~-8007200462 "Effluent & Waste Disposal Semiannual Rept." supplemental info for second half 1978 * Tennessee Valley Authority /9/02/15 15pp
- 8007220342 Forwards "Effluent & Waste Disposal Semiannual Rept." supplemental info, first half 1979 ABERCROMBIE.H Tennesse Valley Authority 79/08/17 1p
- --B007220346 "Effluent & Waste Disposal Semiannual Rept." supplemental info.First half 1979 * Tennessee Valley Authority 79/08/17 14pp
- BOO7220481 Forwards "Efficent & Waste Disposal Semiannual Rept. Supplemental Info.Second Half 1979 " ABERCROMBIE.H Tennessee Valley Authority 80/01/31 ip
- --B007220491 "Effluent & Waste Disposal Semiannual Rept. Supplemental Info. Becond Half 1979 " * Tennessee Valley Authority 80/01/31 16pp
- BOO7160552 Forwards monthly operating repts for June 1980 ABERCROMBIE:H L. Tennessee Valley Authority 80/07/10 1p
- --B007160556 Monthly operating repts for June 1980 THOM.T. GREEN.D. Tennessee Valley Authority 80/07/02 32pp
- B Reportable occurrences. LERs & related correspondence
- 8007010370 Forwards LER 80-017/03L-0 CALBOUN, J R Tennessee Valley Authority 80/06/25 1p
- --8007010377 LER 80-019/03L-0 on 800527.during normal operation, discovered drywell sump flow transmitter FY-77-16 had output signal shift Cause unknown Transmitter replaced % instrument loop calibr # Tennassee Valley Authority 80/06/25 2pp
- 8007080415 Forwards LER 80-023/017-0 CALHQUN, J R Tennessee Valley Authority 80/05/30 [p
- --8007080416 LER 80-023/01T-0 on 800617.duting normal operation, spare Dresser Industries safety valve was discovered w/cracks in guide Caused by initial pouring of costing & cooling Spare valves will be inspected for cracks

 * Tennessee Valley Authority 80/06/30 2pp

- 8087110425 RD-BFRO-10-294/8024 on B00628, during routine maint shutdown, approx 68 of 185 control rods failed to fully insert when reactor was manually tripped Unit is shut down until cause determined & corrective action taken ABERCROMBIE, H i Tennessee Valley Authority 80/06/30 ip
- 8007240256 PND-11-80-119 on 800628.76 control rods failed to fully insert during routine shutdown Manual strams failed to effect repair Auto scram caused full insertion Cause being investigated Confirmation of action ltr issued ULLIAN.C., LEMIS.R.C. Region 2, Atlanta, Office of the Director 80/06/30 2pp
- B00711037B Forwards LER B0-020/03L-0
 CALHOUN.J R Tennessee Valley Authority 80/07/03 19
- ---8007110380 LER 67-020/03L-0 on 800409, during normal operations, 38 diesel generator auxiliary oil pump motor tripped twice Caused by failure of Hoover Model 5203; sealed bearings Motor replaced Bearings replaced every two yrs rennessee Valley Authority 80/07/03 2pp
- 8007110388 Forwards LER 80-021/03L-0 CALMOUN, J R Tennessee Valley Authority 80/07/03 1p
- --B007110394 LER B0-021/03L-O on B00609.during normal operation, reactor core isolation cooling turbine tripped on overspeed due to loss of speed control Caused by failure of voltage suppressor CF-1; type B-240; in F6M box # Tennossee Valley Authority 80/07/03 2pp
- 8007240260 PND-II-80-i17A updates PND-II-80-i17 Cause of 7A control rods not fully inserting after 80058 routine shutdown still not determined No blockage found in scram discharge piping Addl flow tests will compare drain capabilities JULIAN.C. LEMIS.R.C. Region 2. Atlanta, Office of the Director 80/07/03 ip
- 8007180301 Forwards LER 80-022/03L-0 CALHOUN, J R Tennessee Valley Authority 90/07/14 ip
- --8007180314 LER 80-022/07L-0 on 800616, while performing 81 4 1 A-14, turbine first-stage pressure permissive & pressure switches PS-1-9) A & B exceeded limits Caused by setpoint drift Switches recalibre Tennesses Valley Authority 80/07/14 2pp
- 8007290820 Forwards LFR 80-024/01T-0 CALHOUN, J R Tennessee Valley Authority 80/07/18 Ip
- --8007270829 LER 80-024/017-D on 800628,when reactor was manually scrammed.72 of 195 control rods failed in folly insert Probable cause due to water in scram discharge vol Investigation in progress to determine corrective action

 * Tennessee Valley Authority 80/07/18 2pp
- 8007290695 Forwards LER 80-025/03L 0 CALHOURL J R Tennesser Valley Authority 80/07/24 ip
- --B007290702 LER B0-025/03L-0 on 800625 during normal operation, continuous heat detector damaged & caused false alarm Caused by accidental damage to host detector by personnel performing modes in area Craftamen cautioned

 * Tennessee Valley Authority B0/07/24 29p
- T Hearing transcripts on non-antitrust matters

- 8007240271 Transcript of 800703 briefing by NRC on facility Pp 1-54 Commission 90/07/03 Blpp
- 800724909) Transtript of 800715 bracking on status of facilities in Mashington, DC Pp 1-21 * Commission 807077/15 elpp
- DOCKET 50-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR

 G Inspection reports, IE Bulletins & correspondence
- 8007170164 Forwards IE Circulas 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internel Contamination of Personnel" No written response required O'RESLLY, J.P. Region 2. Atlanta, Office of the Director 80/06/24
- B007140542 Forwards IE Insp Rept 50-297/B0-01 on 800605 No noncompliance noted KENNA-W B Region 2. Atlanta, Safeguards Branch B0/06/25 lp

- ---8007140555 IE Insp Rept 50-297/80-01 on 800405 No noncompliance noted Najor areas inspected licenses security plans security urganization, access control, surveillance & protection against sabutage Details withheld (ref 10CFR 2790) HOWELL, J C . OILLESPIE, F P Region 2. Atlanta, Office of the Director 80/06/25 ip
- DOCKET 50-298 COOPER NUCLEAR STATION
- F Security, medical, emergency & fire protection plans
- B007230713 Ack receipt of util 800326 ltr transmitting Revision 9 to physical security plan Encl to util ltr withheld (ref 10CFR2 790) IPPOLITO. I A Operating Reactors Bianch 2 80/07/07 2pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 0 Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- B00723002B Summary of 800207 meeting w/Mark I owners group in Bethesda, Mb,re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES,C T Flant Systems Branch 80/02/21 31pp
- 8007140480 Forwards Amend 63 to Liconse DPR-46 & notice of issuance & availability
 1PPDLITD.T A Operating Reactors Branch 2 80/06/24 3pp
- ---8007140486 Amend 63 to License DPR-46 modifying App B of Tech Specs to delete Section 2 1 1/3 1 1 Section is superfluous to requirements in Section 2 1 2 re max thermal discharge temp IPPOLITO.T A Operating Reactors Branch 2 80/06/24 Spp
- --8007140492 Notice of issuance & availability of Amend 63 to License DPR-46 IPPOLITOR TA Decrating Reactors Branch 2 80/06/24 2pp
- B007160440 Bubmits status & schedule for completion of Mark 1 program mods at facility per NRC telcon request PILANY, J M Nebraska Public Power District 80/07/10 2pp
- 8007240255 Forwards Pages 193 & 194 to be inserted in facility Tech Specs Pages 193a & 194a 1ssued w/Amends 43 & 45 are redundant & should be removed IPPOLITO.T A Operating Reactors Branch 2 80/07/14 2pp
- --8007240257 Tech Specs Pages 193 & 194 re limiting conditions for operation & surveillance requirements for auxiliary electrical sys * Nobraska Public Power District 78/05/02 2pp.
- " (tent bakt) t and to t amet. Danni ten Johonn de Abb.
- 8007280452 Application for amend to License DPR-46 deleting Tech Spec 2 i 2/3 i 2 re max discharge temp. In response to Region 4 request Amend fee was submitted w/previous Tech Spec change request PILANT.J M Nebraska Public Power District 80/07/14 3pp
- --8007280467 Ravised Tech Specs deleting Section 2 1 2/3 1 2 re max discharge temp State pollutant discharge permit encl * Nebraska Public Pewer District 80/07/16 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007140563 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " Written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/12 19
- 8007030179 Responds to IE Bulletin 80-09 re hydramotor actuator deficiencies 81x Model AH-90 &/or NH-90 Beries hydramotor actuators are used at factliby. None vses springs made &/or installed between Rept 1975 & Jan 1978
 PILANT, J M Nebraska Public Power District 80/05/20 1p
- BO07100016 Updates response to 1E Bulletin BO-07. "BWR Jet Pump Assembly Failure " Licensee will perform surveillance required by Tech Specs & surveillance recommended by GE instead of program outlined in IE Bulletin 80-07 PILANT, J M Nebraska Public Power District 80/05/21 2pp

- 8007020268 Forwards IE Info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required BEYFRIT.K V Region 4, Dallos, Office of the Director 60/05/28
- 8007010048 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/05/29 in
- 8007210152 Responds to IE Bulletin 80-13. "Cracking in Core Spray Spargers" No cracking found during insp of spargers & segment of piping between inlet nozzle & vossel shroud PILANT. J H Nebrasia Public Power District 80/05/31 ip
- 8007020333 Responds to IE Bulletin, 79-02, "Pipe Hupport Dase Plate Designs Using Concrete Expansion Anchor Bolts " Lists hangers to be repaired LEBSOR.L C Nebraska Public Fower District 80/06/03 3pp
- 8007130125 Forwards IE Insp Rept 30-298/80-08 on 800506-09 & 19-23 No noncompliance noted HADBEN,G.L. Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/06/06 2pp
- --B007150136 IE Insp Rept 50-298/80-08 on B00504-09 & 19-23 No moncompliance noted Major areas inspected previously identified items, refueling activities, surveillance, pipe support & restraint sys, maint & leak rate tost HEGTERMAN.T f , SPANGLER.R Q , TAPIA.J Region 4, Dallas, Office of the Director 80/06/06 Spp
- 8007220120 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/10 in
- BOO7140410 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Written response required SEYFRIT,K V Region 4. Dallas, Office of the Director BO/06/12
- 800724005i Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required. SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/20
- R Periodic operating reports & related correspondence
- 8007080391 Forwards monthly operating rept for June 1980 LESSOR, L C Nebraska Public Power District 80/07/01 1
- --B007080375 Monthly operating rept for June 1980
 BALLINGER,P L Nebraska Public Power District 80/07/01 9pp
- B007250421 Forwards corrected monthly operating rept for June 1980 LEBEOR.L C Nebraska Public Power District 80/07/18 1p
- --BOO7250425 Corrected monthly operating rept for June 1980
 BALLINGER, P L Nebraska Public Power District 80/07/01 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007080295 Forwards LER 80-012/03L-0 LESBOR, L C Nabraska Public Power District 80/06/12 4pp
- ---8007080302 LER 80-012/03L-0 on 800521, during local leak rate test, nine penetrations found leaking excessively Caused by normal wear Seal ring replaced, seats polished, packing tightened & ring seal cleaned PHILLIPB, D. Nebraska Public Power District 80/06/12 ip
- 8007090005 Forwards LER 80-013/03L-0 LESSOR, L C Nebraska Public Power District 80/06/13 2pg.
- --8007090007 LER 80-013/03L-0 on 8005i6.during surveillance procedure on primary containment isolation valve timing.RHR discharge to radwaste inboard isolation failed to close in time Caused by failure to check stroke time after mailut

 DOAN.P F Nebraska Public Power District 80/06/13 ip
- 8007080365 Forwards LER 80-014/03L-0 LESSOR, L C Nebraska Public Puwer District 80/06/16 2pp

- --B0070B036B LFR B0-014/03L-0 on B00519, while performing SP & 3 i3 l, relay 14A-K2B was found dr-chergized, preventing start of core appay pump on normal power Superflows contacts were inadvertently left connected in core spray pump circuits BEDNAR.L F Nebraska Public Power District 80/06/14 1p
- B007280584 Forwards LER 80-015/03L-0 LESSOR.L C Nobreska Public Power District 80/07/02 2pp
- --8007280592 LER 80-015/03L-0 on 800505 during control rod scramtime testing. Full-in control rods incorrectly scrammed & fully uithdrawn Cauled by personnol error Rad returned to correct position Procedure modified BORER. P. J. Nebraska Public Power District 80/07/02 29p
- 8007150702 LER 79-031 has been concelled COLLINS.M Nebraska Public Power District 80/07/14 ip
- 8007250501 Confirms 800710 telcon re temp exceeding limit of 10JF in facility discharge canal on 800709 Periodic noncompliances expected as long as hot weather creates increased demand for full power operation Tabulations for 800709-16 oncl COOPER.L J Nebraska Public Power District 80/07/18 3pp
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency % fire protection plans
- 8007300440 Forwards emergency plan, revised draft, Jul 1980 FAY, C W Wisconsin Electric Power Cu 80/07/25 1p
- 9 Adjudicatory correspondence
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D.G. Davision of Licensing B0/06/25 69pp
- B007210A43 Corrected notification that 800312 petition is denied Forwards B00610 FR notice, Director's decision under 100FR2 206 & related SERs DENTON H R Office of Nuclear Reactor Regulation, Director 80/07/10 1p
- --B007210445 Notice of issuance of Director's decision under 10CFR2 204 denying WI Environ Decade Inc 800312 petition DENTON If R Office of Nuclear Reactor Regulation. Director 80/06/10 1p
- ---BD07210447 Director's decision under 100FR2 206 denying WI Environ Becade, Inc 800312 petition for show cause order & order enjoining operation of facility due to steam generator tube degradation DENTUN, H R Diffice of Nuclear Reactor Regulation. Director B0706/10 Spp
- --8007210649 Safety evaluation to steam generator tube degradation supporting continued operation of facility

 + Office of Nuclear Reactor Regulation, Director 60/07/10
 10pp
- 8007280477 Ack receipt of directors' 800710 decision re facility Attachments to decision jumbled Requests complete set of attachments FAKK, M Misconsin's Environmental Decade 80/07/14 ip
- P Operating license stage documents & correspondence
- 8007230079 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Bopes which would provide acceptable resolution encl for guidance EISENHUT, D Q Division of Licensing 80/06/11 62pp
- 8007090230 Notifies that four Westinghnuse demonstration optimized fuel assemblies will be loaded in Cycle 8 core during Mar 1981 refueling shutdows Reload safety evaluation to be performed per McAP-9272, including assessment of core impact FAY,C W Wisconsin Electric Power Co 80/07/01 2pp
- B007170588 Forwards evaluation of control rod guide thimble wear in facilities designed by Westinghouse Based on review, issue is resolved CLARK, R.A. Operating Reactors Branch 3 80/07/01 4pp

- 8007280001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions FWR Model Fech Specs & Model license conditions for TNI-2 Lessons Learned Category A items encl for guidance EISENHUT.D O Division of Licensing 80/07/02 69pp
- B007190648 Requests extension of comment period on NURES-0577 until B00915.due to other work efforts Requests notification only if extension found unacceptable FAY.C N Wistonsin Electric Power Co 90/07/03 lp
- 8007150482 Submits comments on NUREG-G654 Two objectionable items 19-Annute time frame proposed to complete public notification to propriety of min shift staffing requirements proposed in Table B-1 FAY, C W Hisconsin Electric Power Co 80/07/03
- 8007210034 Confirms schadule for 800/08 meeting at site to discuss recent increase of personnel errors at facilities KEPPLER.J G Region 3. Chicago, Office of the Director 80/07/03
- B007210408 Forwards revised Tech Apec 15 3 4 for steam & power conversion sys & feur 72-h test repts for auxiliary feed pump in response to NRC 800516 request for addl info re Lary feedwater sys W Wisconsin Electric Power Co 80/07/08 App
- --BOD721043B Revised Tech Spec 15 3 4 for steam & power conversion sys

 * Wisconsin Electric Power Co BO/07/08 3pp
- --8007210452 "Seventy-Two Hour Test of Turbine-Driven Auxiliary Feed Pump " * Wisconsin Flectric Power Co WMTP 11 21 RO 79/12/28 10pp
- --8007210460 "Seventy-Two Hour Test of Turbine-Driven Auxiliary Feed
 - Wisconsin Electric Power Co WMTP 11 21 RO 79/12/07 10pp
- -~8007210465 "Seventy-Two Hour Test of Electrically-Driven Auxiliary Feed Pump " * Wisconsin Electric Pawer Co WMTP 11 22 80 79/12/26 10pg
- --8007210469 "Seventy-Two Hour Test of Electrically-Driven Auxiliary Wisconsin Electric Power Co WMTP 11 22 RO 79/12/23 10pp
- 007240330 Advises of NRC reorganization on 800428 which resulted in number of changes in ofe titles, positions & assignments of personnel Also submits info for OETR NOVAK, T.M. Assistant Director for Operating Reactors 80/07/09
- 3007250480 Discusses potential wolding deficiencies in tanks fabricated by Graver Tank & Mfg Co Requests determination whether weldments in safety-related Graver tanks meet design specs & Pabrication requirements MOSELEY, N C Division of Reactor Operations Inspections 60/07/08
- Inspection reports, IE Bulletins & correspondence
- 007020037 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 60/05/28
- 1007210409 Forwards IR Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director B 80709728
- 1007010080 Forwards IE Info Nutice 80-23. "Loss of Auction to Emergency Feedwater Pumps" No written rasponse required KEPPLER, J. Q. Region 3. Chicago, Office of the Director 80/05/29
- 007010030 Responds to IE Bulletin 80-05. "Engineered Safety Feature (ESF) Reset Controls " Control of solenoid valve will be modified such that total regionalition of control room air will continue after reset of containment isolation.

 FAY, C H Hisconsin Electric Power Co 80/06/06 2pp
- 007010062 Responds to IE Bulletin 80-05. "Vacuum Condition Resulting DU/OLOGE Response to IE Bulletin BO-O5. "Vacuum Condition R in Damage to Chemical Vol Control Sys (CVCb) Holdup Tanks "Mod will be implemented to prevent approtion of holdup tank rectriculation pump w/o positive pressure in tank FAY.C W Wisconsin Electric Power Co BO/O6/06 9pp

- 3007160757 Responds to IE Bulletin 80-06 Review conducted of schematic drawings to determine actions rosulting from engineered safety feature actuation signal & whether equipment returned to nonemergency mode upon removal of actuation signal FAY.C W Wisconsin Electric Power Co 80/06/06 Zpp
- 8007240012 Forwards IE Insp Rept 50-301/80-09 on 800527-29 No noncompliance noted
 noncompliance noted
 NEIBHMANR F Region G. Chicago, Reactor Operations Nuclear Support
 Branch 80/05/06 2pp
- -800724001B IE Insp Rept 50-301/80-09 on 800527-29 No noncompliance overwors it inspread to be sold the control of the sold of the control of the con Region 3, Chicago, Office
- 8007010049 Updatos 800307 response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Piping analysis completed for 84 of 85 previously tabulated drawings as of 800523 Status of review encl FAY.C W Hisconsin Electric Power Co 80/06/09 5pp
- 8007220226 Forwards IE Info Nutice 80-26, "Evaluation of Contractor GA Programs" No written response required REPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/16 80/06/10
- 8007160195 Forwards IE Info Notice 80-27, "Degradation of Reactor Coglant Pump Studs " No specific action or response KEPPLER. J G Region 3: Chirago, Office of the Director 80/06/11
- B007030030 Forwards IE Bulletin B0-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLERJ G Ragion 3, Chicago, Office of the Director 80/06/1 Region 3. Chicago, Office of the Director 80/06/18
- BO07020549 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required KEPPLERJ 0 Region 3, Chicago, Office of the Director. 80/06/20
- 8007170524 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Domineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLERIJ 0 Region 3, Chicago. Office of the Director 80/06/24
- 8007230344 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemont Inc Hodels 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27
- 8007310304 Forwards IE Insp Repts 50-266/80-11 & 50-301/80-11 on 800616-17 No noncompliance noted FEORELLI, C Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/30 2pp
- --8007310316 IE Insp Repts 50-266/80-11 & 50-301/80-11 on 800616-17. No noncompliance noted Major areas inspected licensee actions re IE Mulletin 79-14 THE INTERIOR OF THE PRICE OF THE DIRECTOR OF THE DIRECTOR DAMIELBON, D. R. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/30 5pp
- 8007170526 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " All containment welds either have leak chase channel or penetration has closure cap or expansion bellows welded outside containment 80/07/03 Wisconsin Electric Power Co
- 800722007: Submits reply to IE Bulletin 80-10 re contamination of nonradicactive sys & potential for releases. Completion of bulletin review not anticipated until 80083: FAY.C W Wasconsin Electric Power Co 80/07/07. 2pp
- 8007240342 Responds to IE Bulletin 80-15 re power supply to emergency notification sys telephones Charger supplied by telephone company is connected to safeguards Bus 2842 Phones Verified operational whose of ac to charger FAY.C W Wisconsin Electric Power Co 80/07/08. 2pp

- 8007300430 Forwards drawings & revised pump & valve inservice insp & testing program.replacing 790219 program Program & drawings available in Central Files only FAY.C W Wisconsin Electric Power Co 80/07/25 ip
- R Periodic operating reports % related correspondence
- B007150610 Forwards monthly operating repts for June 1980 FAY.C U Wisconsin Electric Power Co 80/07/10 ip
- --8007150618 Monthly operating repts for June 1980
 FAY.C W Wisconsin Electric Power Co 80/07/08 App
- B Reportable occurrences, LERs & related correspondence
- B007080381 Forwards LER 80-005/03L-0 FAY,C W Wisconsin Electric Power Co 80/06/27 ip
- ---B0070B03B4 LER 80-005/03L-0 on B00607, during training walkdown of safeguards electrical supply cabinets, noted that tie breaker between A05 & A06 safeguards buses was shut Probably caused by improper electrical lineup after loss of ac test FAY.C W Wisconsin Electric Power Co B0/06/27 3pp
- 8007110342 Forwards LER 80-006/01T-0 FAY.C W Wisconsin Electric Power Co 80/06/30 in
- ---8007110349 LER 80-006/01T-0 on B00617.during safeguards logic test w/
 one emergency diesel generator out of svc.auto containment
 spray pump actuation threatoned during loss of ac & highhigh containment pressure Caues d by personnel error
 FAY.C W Wisconsin Electric Power Co 80/06/30 3pp
- BOO7110353 Forwards LER BO-007/01T-0 FAY, C W Wisconsin Electric Power Co BO/07/03 ip
- --8007110357 LER 80-007/01T-0 on 800619, at full power, test IT-04 was performed w/emergency diesel generator 3D out of svc Emergency safeguards train equipment would have been inoperable on loss of ac power Caused by personnel error FAY.C W Wisconsin Electric Power Co 80/07/03 2pp

♥ Operator Examinations

8007240085 Responds to 800404 request for info re requirement that operator & senior operator lirense applicants spend 3 months on-shift in training Variance to requirement connot be permitted NOVAK,T M Assistant Director for Operating Reactors 80/07/08

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- 8007020467 Forwards site emergency plan review & list of deficiencies per NUREO-0654 NRC site emergency plan review indicates that addl info & commitments are required to meet evaluation criteria stated in NUREO-0654
 NOVAK.T M Assistant Director for Operating Reactors 80/06/24
- BOO7080259 Forwards add1 info re safeguards contingency plan in response to NRC 800522 ltr Plan withheld (ref 100FR2 790) BRIGHT.R M Florida Pawer Corp 80/07/01 2pp
- BOG7230184 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview accurity mpt personnel at facility
 EISENHUT.D G Division of Licensing 80/07/11 2pp
- 8007280373 Updates status of fire protection mode identified in 790727 safety evaluation Requests expeditious review of previously submitted items in Table 3 BAYNARD.P Y Florida Power Corp 80/07/23 App

9 Adjudicatory correspondence

BOO7310243 Forwards Commission BOO327 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
EISENHUT, D G Division of Licensing 80/06/25 87pp

- H General correspondence
- B007110144 FOIA request for documents in facility & info concerning clothing & cleaning procedures for truse of clothing & washing procedures for clothing used at facility MAGNER, D. Wagner, Cunningham, Vaughan, Genders & McLaughlin B0/06/13 2pp
- 8007230237 FOIA request for three categories of documents re facility GIVEL.M. Affiliation Unknown 80/06/23 ip
- 8007110139 Responds to FDIA request for documents re facility & infoconcerning clothing & cleaning procedures for reuse of clothing & washing procedures for clothing used at facility Forwards documents listed in App A W/o encls FELTON, J M Division of Rules and Records 80/07/08 2pp
- 8007180098 Partial response to FOLA request for three categories of documents re facility Response to Item 11 may be found in util semiannual repts in local PDR Forwards NUREO-0594 & draft personnel exposure chart Chart only end FELTON, J M Division of Rules and Records 80/07/15 2pp
- 8007230232 Addi response to FOIA request for three categories of documents re facility Info sought in Item 12 of request can be found in LER identified in NRC 800611 response to Items 13-22 FELTON, J M Division of Rules and Records 80/07/16 1p
- J Insurance & indemnity information
- 8007310435 Forwards executed Endorsement 31 to MAELU Policy MF-91 FIELDER, J. Marsh & McLennan. Inc., M & M Nuclear Consultants, Inc. Div 80/07/14 2pp
- P Operating license stage documents & correspondence
- 8006240237 Responds to technical assistance request for proposed Tech Spec changes for D&W operating plants Forwards requirements for addl info IBRAEL, S L 7M1-2 Bullotins % Orders 79/08/29 13pp
- 8007R40208 Forwards B&W licensees' responses to 790907 request for review of schedulo for installing safety grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 799115 CAPRA, R A TMI-2 Bulletins & Orders 79/10/24 1p
- 8005270617 Forwards NUREO-0645.Vols 1-2, "Ropt of Builetins & Orders Task Force" & NUREO-0626. "Generic Evaluation of Foeduater Transismts & Small Break LDCAs in GE-Designed Operating Plants & Near Term OL Applications "W/o encl REID,R W Operating Reactors Branch 4 80/05/13 2pp
- 8007100207 Advises of concurrence w/Ofc of Policy Evaluation conclusions re impact of NRC post TMI-2 requirements for B&W reactors & facility transient Forwards recommendations & comments

 DENTON. H R Office of Nuclear Reactor Regulation, Director 80/05/20 4pp
- --B007100211 Requests cumments on DFc of Policy Evaluation paper on impact of NRC post TMI-2 requirements on D&W reactors & facility transient Requests submittal by B00515, w/inclusion of Program OFc views AHEARNE.JF Commission 80/04/27 lp
- BOO7230099 Requests submittal of proposed feth Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance
 EISENHUT, D @ Division of Licensiny 80/06/ii 62pp
- 8007100}11 Forwards Amend 31 to License DPR-72, safety evaluation \$ notice of issuance & availability REID,R W Operating Reactors Branch 4 80/06/18 2pp
- --B007100115 Amend 31 to License DPR-72, deleting requirements for maintaining containment test pressure when inspecting tondon end anchorages RFID, R W Operating Reactors Branch 4 90/06/18 5pp
- --8007100118 Safety evaluation supporting Amend 31 to License DPR-72
 * Office of Nuclear Reactor Regulation, Director 80/06/18 2p
- --8007100121 Notice of issuance & availability of Amend 31 to License DPR-72 REID.R W Operating Reactors Branch 4 80/06/18 dpp

- 8007030242 Responds to NRC 800902 request for info me pressurizer safety valves includes data taken during 800226 incident to assist in determining flow mates & conditioners in RCV-B relief train Test results will be sent when available BRIGHT.R M Florida Power Corp 80/06/25 175pp
- 8007010399 Application for amend to License DPR-72 granting waiver from certain ASME Section X1 tosting & inspirequirements
 Cartificate of Svc encl
 BRIGHTR M Florida Power Corp 80/06/26 4pp
- 8007020397 Application for amend to License DPR-72, revising operator retraining requirements includes 1-uk simulator training course each yr 5 5 days shift work per 4-month interval for backup licensees nut at Unit 3 Certificate of Svc encil BAYNARD.P Y Florida Power Corp 80/06/27 4pp
- 6007070343 Informs that due to relationship of tests to Crystal River 3 event & IE Bulletin 79-27 response, tests verifying effects of combination of power loss on instruments & control functions will be provided by 800300
- B007210004 Forwards questions refuel assembly holddown spring insps & safety significance of operating w/broken springs in core Requests response within 60 days
 NDVAK.T M Assistant Director for Operating Reactors 80/07/01
- 8007210110 Requests response to and questions re fuel assembly holdown springs Several holdown spring failures have recently occurred at Davis-Besse, Unit 1 NRC wishes to obtain results of holdown spring insps at other facilities NOVAK.T M Assistant Director for Operating Reactors 80/07/01 3ao
- 8007210581 Forwards questions refuel assembly holddown spring failure NRC is interested in knowing results of spring inspet a safety significance of operating w/broken springs in core Response requested within 60 days of itr receipt NOVAK.I M Assistant Director for Operating Reactors 60/07/01
- 6007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Hodel Tech Specs & Hodel license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUF, B O Division of Licensing 60/07/02 69pp
- B0070B0075 Notifies that evaluation of BAH-1621.re overall asymmetric LOCA loads,will be submitted by B00B05 MODRE: 0 C Florida Power Corp 80/07/03 3pp
- 8007190494 Requests extension of comment period re NRC 800519 ltr forwarding NUREG-0577 for review Facility in extended outage implementing TMI commitments Extension until 800915 will permit adequate analysis of issue MOORE, O C Florida Power Corp 80/07/03 ip
- 8087:00193 Clarifies util 8002;5 ltm re compliance w/Category A requirements of NURCG-0578 Bilver reclite cantridges will be used to rollect samples under accident conditions Single channel analyzer will be utilized BRIGHF.R M Florida Power Corp 80/07/07 2pp
- BOO7110122 Notifies that listed guidelines & changes, submitted for NRC info & review on BOO923 were used to revise Emergency Procedures 101-104-106-108 & 113
 BAYNARD P Y Florida Power Corp 80/07/08 3pp
- 8007240037 Notification of 800711 meeting w/util in Bethesda.MD to discuss status of 51 corrective actions following 800226 incident FARATILE.M B Operating Reactors Branch 4 80/07/07 2pp
- 800725027B Provides info re new ofc titles positions & assignments of personnel resulting from 80042B reorganization of Ofc of Nuclear Reactor Regulation NUVAR.T H Assistant Director for Operating Reactors 80/07/10
- 8007190385 Forwards addl info re containment purge & vent sys, per NRC 800227 request Response prepared by B&W answers Questions ic & le Response to Questions la.ih.ld & If were submitted on 800620 Affidavit enct MOORE.Q C Florida Power Corp 80/07/li 9pp
- 8007210203 Notifies NRC that containment isolation valve.CAV-1 is functional effective 800712 Past provisions of Tech Spec 3 O 4 are applicable BAYNARD.P Y Florida Power Corp 80/07/15 2pp

- BOO7180294 Advises that restart w/o completion of Item 51 is justified as original FBAR is still valid for present design All items will be completed prior to Mode 2 operation Affidavit encl BAYARD P v Florida Power Corp
- 8007180313 Submits addl info re implementation of short-term lessons learned requirements, to supplement 800411 ltr Contract consultants will assess operating exportence from 800101 until technical advisors hired Certificate of Sv. encl BAYNARD, P Y Florida Power Corp 80/07/16 3pp
- 8007180384 Responds to Recommendation 22 of NUREQ-0667, requesting analysis of LERs attributed to licensed personnel error Tabular & graphic response prepared by Inst of Nuclear Power Operations encl BAYMARD. P Y Florido Power Corp 80/07/16 26pp
- G0072203B3 Responds to NRC 800502 request for info re pressurizer safety valves Forwards Gilbert Associates. Inc 800630 "Analysis of 8002B6 Pressurizer Translant Relief Valve Discharge " Supporting itrs enc! BAYNARD.P Y Florida Power Corp 80/07/17 9pp
- --8007220385 "Analysis of 800226 Pressurizer Transient Relief Valve Discharge " ARAUZ.G A. BUNKER.P L. Gilbert/Commonwealth Cos 80/06/30 12pp
- 8007270878 Safety evaluation of corrective action following 800224 incident Actions taken are sufficient to permit restart Operating Reactors Branch 4 80/07/18 8pp
- 8007240074 Forwards schedule for commitments to TMI-2 related requirements, per NRC 800507 request Affidavit encl BAYNARD, P Y Florida Power Corp 80/07/21 4pp
- 8007250326 Revision to Toch Spec Change Request 61 correcting simplifying assumption made by DRW in reanalysis of Cycle 3 that allowed utilization of flur/flow ratio of rounded-off i 04 Certificate of Svc 2 affidavit encl
- --8007250330 Proposed revisions to Tech Specs,Pages 2-3,-5,-7,8 2-5 & 8 2-6,changing flux/flow ratio
 * Florida Power Corp 80/07/22 5pp
- 8007280187 Application to amend License DPR-72, deleting power level cutoff requirement of Tech Spec 3/4 1 3 8, "Reactivity "
 Affidavit.Cortificate of Svc & Tech Spec Change Request 66 encl
 BAYMAD.P Y Florida Power Corp 80/07/23 App
- --8007280133 Tech Spec Change Request 66 for amend to License DPR-72, deleting power lovel cutoff requirement embodied in Tech Spec 3/4 1 3 8, "Reactivity" * Florida Power Corp 80/07/23 App
- G Inspection reports. IE Bulletins & correspondence
- B007240202 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8007020179 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs." No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/28 ip
- 8007210462 Forwards IE Circular 80-13, "Grid Strap Damage in Mestinghouse Fuel Assemblies" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007010251 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007220076 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 20a

- 8007140262 Forwards IC Info Notice 80-27. "Degradation of Reactor Coolant Pump Stude " No specific action or response coolant found action and specific action of response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/11
- 8007020743 Forwards IC Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENB) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2. Atlanta, Offsice of the Director 80/06/18

- 8007020409 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Looldown" No written response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/20
- 8007160794 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24
- 8007190495 Ack receipt of 800611 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/80-19 LEWIB,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/04/25 ip
- --BOO7150503 Responds to NRC 800515 ltr re violations noted in IE Insp Rept 50~302/80-19 Corrective actions meetings recorded on microfilm new drawings ordered & vendor manuals maintained & controlled HANCDCK: J A Florida Power Corp 80/06/11 3pp
- --8007150506 Forwards IE Insp Rept 50-302/80~19 on 800421-25 & notice of violation Branch
- -8007150510 Notice of violation from insp on 800421-25 * Region 2. Atlanta, Office of the Director 80/0 80/05/14 200
- --8007180811 IE Insp Rept 50-302/80-19 on 800421-29 Noncompliance noted failure to provide adequate document control program for vendor manuals PRICE, D. 8 Region 2. Atlanta, Office of the Director UPRIOHT, C. M. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/05/14 9pp
- 8007180340 Forwards response to IE Bulletin 80-10 Program to prevent unmonitored, uncontrolled liquid & gaseous releases to environ described Operation of sys as radioactive sys is acceptable Provisions made to monitor & control releases BRIGHT.R M Florida Power Corp 80/06/25 App
- 8007230210 Forwards IE Bulletin 80-14, "Potential Misapplication of Rossmount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 60/06/27
- BOO7240382 Forwards meeting minutes in response to IE Insp Rept 50-302/80-19 Records now incorporated into plant quality files FOOLE.D C Florida Power Corp 80/06/27 ip
- B007070329 Forwards rept responding to IE Bulletin 79-01B, "Environ Qualification of Class IE Equipment " Outstanding items in Sections 2 & 3 will be further evaluated as info becomes available W/o encl.
 BRIGHT.R M Florida Power Corp 80/06/30 ip
- 8007150598 Forwards response to IE Bulletin 80-11. "Masonry Wall Design " Licensee will develop re-evaluation acceptance criteria for walls based on consorvative design assumptions consistent wischedule in Itom 22 BRIGHT, R M Florida Power Corp 80/07/07 6pp
- 8007230562 Forwards response to open items of IE Bulletins 79-02 re pipe support base plate designs & 79-14 re seismic analysis of safety-rolated piping sys identified in IE Insp. Rept 50-302/80-02 BAYNARD, P Y Florida Power Corp. 80/07/16 7pp
- --8007230573 "Earthquake Intensity for Piping Analysis & Pips Support Design " FBAR except and FERRARELLO.8 Florida Power Corp 79/10/11 9pp

- R Periodic operating reports & related correspondence
- BOO715070B Forwards monthly operating rept for June 1980 BAYNARD.P Y Florida Power Corp 80/07/09 ip
- -8007150713 Monthly operating rept for June 19 CULVER.M W Florida Power Corp 80/07/01
- S Reportable occurrences. LERs & related correspondence
- B007010463 Advises that B00530 Part 21 rept re mainstream safety valve cracking in valve disc guides has been dispositioned Forwards analyses dotermining parts acceptable for use HANCOCK. J A Figurida Power Corp B0/06/24 17pp
- B007110402 Forwards LER 80-025/03L-0 HANCOCK, J A Florida Power Corp 80/07/07 ip
- --8007110410 LER 80-025/03L-0 on 800609, while performing SP-112 calibr of reactor protection sys, count rate amplifier for channel A source range neutron flux monitor found out-of-tolerance Caused by defective pulse & output amplifier cards LANCASTER.K F Florido Power Corp 80/07/03 2pp
- 8007270874 Forwards safety evaluation re 800226 incident Corrective actions taken are sufficient to permit restert & to ensure safe operation Operating Reactors Branch 4 80/07/18 2pp
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES, D. L. Commonwealth Fdison Co. 80/06/27 ip
- G Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS /71104 petition sought action re fire protection for electrical cables EISENHUT, N G Division of Licensing B0/06/25 89pp
- B007020646 Memorandum specifying issues to be discussed at 800701 oral argument, re State of Il contention that applicant commitments should be integrated in license Tech Specs, in storage pool mad proceeding TOMPKING, B A Atomic Safety and Licensing Appeal Panel 80/06/26
- B007100022 Forwards "Tech Specs for Nuclear Power Reactors." 10CFR50 advance notice of rulemaking for which counsels' attention is invited by ASLB Comments may be submitted to Commission re 800701 oral argument BIBHOP.C J Atomic Safety and Licensing Appeal Panel B0/07/03
- --8007100026 "Tech Specs for Nuclear Power Reactors," 100FR80 advance notice of rulemaking Establishes std for deciding which items from BAR must be incorporated into Tech Specs & modifies definitions of spec categories
 CHILK.S J. Office of the Serretary of the Commission 80/04/30
- B007300362 Updates certain projected load & capacity estimates which appear in record of proceeding per applicant obligation to keep ABLAB approximed of developments Related correspondence STEPTOC.P P Isham, Lincoln & Beale B0/07/08 Zpp
- H General correspondence
- 8007110533 Responds to 800228 request to reject util license to increase storage capacity of facility spent fuel pool Actions initiated 701010 to assure that energency plans are implemented at all licensed operating reactor sites DENTON H R Office of Nuclear Reactor Regulation, Director 80/05/06 2pp
- 8007210200 Responds to pncl 800418 ltr to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities currently operating or planned for operation Village Voice news article and DENION, HR Office of Nuclear Reactor Regulation, Director 80/05/21 10pp

- 6007310358 Responds to enci 800401 telegram to President Carter urging closing of facility & all nuclear plants near populated areas NRC 800227 confirmatory order required immediate short-term actions to assure public safety EISENHUT.D G Division of Licensing 80/07/17 3pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8007220309 Provides summary of 800507-08 meeting woutlis re core melt accident sequences Utils appear to expect MRC to resolve problems & do nothing to mitigate consequences of Class 9 accidents

 CATTON, I California, Univ of, Los Angeles 80705/10 6pp
- P. Operating license stage documents $\boldsymbol{\delta}$ correspondence
- 8004240480 Forwards add) info re review of unresolved safety issues, trip rept of Lessons Learned implementation team & task action plan in view of high population density surrounding plants

 DENTON.H R Office of Nuclear Reactor Regulation, Director, 80/04/09 33pp
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat remayal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D 0 Division of Licensing 80/06/11 62pp
- 8007100393 Summary of 800520 Technology Exchange Meeting 3 w/utils in Bethesda.ND to discuss accident mitigation features for power plants LONG.J K. Division of Systems Integration 80/06/12 75pp
- B007010110 Notification of S00625 meeting b/utils & Sandia Labs in Bethesda.ND for presentation of overview of facilities risk study Agenda encl ISRACL-S L Reliability & Risk Assessment Branch 80/06/14 3pp
- 8007110557 Summary of 800530 meeting w/util in Bethesda.MD ra status of action plan OLSMAN.L N Operating Reactors Branch 1 80/06/23 Jpp
- 8007010428 Forwards Drawing 22E-1~4950 re reactor, turbing & generator trip protection in response to 800619 discussion concerning automatic initiation of auxiliary feedwater sys Drawing available in Central Files only .

 NAUGHTON-W F Commonwealth Edison Co 80/06/24 Ip
- 80070103ii Forwards response to 800227 confirmatory order requiring review of key plant sys vulnerability areas.possible operator dependent areas & control room emergency procedures

 NAUGHTON.W F Commonwealth Edison Co 80/06/26 49pp
- 8007010608 Notification of 800617 meeting w/utils in Gethesda.MD to discuss containment structural response, failure pressures & failure modes for facilities as described in NRC 800410 ltr to Comm Ed MEYER.J F Reactor Systems Branch 80/06/24 2pp
- 8007070116 Submits revised responses to NRC 770603 ltrs re second level of undervoltage protection for 4 kV emergency power buses supplying safety-related loads JANECEK.R F Commonwealth Edison Co 80/06/26 4pp
- 8007170241 Forwards request for add1 info re backfitting of severa accident mitigation features Response requested within 30 days

 NOVAK.T M Assistant Director for Operating Reactors 80/07/02
 7pp
- 8007250001 Requests submitted of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENRUT, D G Division of Licensing 80/07/02 69pp.
- BOO7190476 Submits add1 info re lOCFR50. App J. exemption Mod to install flowmeter w/high flow alarm on penetration pressurization piping to personnel air lock door seals completed includes marked set of drawings M/o drawings NAUGHTON.W F Communwealth Edison Co 80/07/07 4pp
- BOO717059B Summary of BOO625 meeting w/Pickardiloue & Garrick, Inc re risk study including modeling for plump trajectory containment event tree & modeling.use of plant data & consideration of external events ISBAEL, S.L. Reliability & Risk Assessment Branch BO/07/D7 Bpp

- 8007230646 Summary of 800907-08 technology exchange meetings w/utils in Chicago. IL re core melt accident sequences & associated phenomenology for facilities NRC perceives real urgency to for answers to key technical questions
 MEYER.JF Reactor Systems Branch 80/07/09 12pp
- 8007280605 Notifies that PG Stoddart, primary NRC reviewer for Zion, has requested add1 info to complete review, as result of discussions re NUREO-0578 Item 2 1 8s on improved post-accident sampling capability Lists drawings sent NAUGHTON, W F Commonwealth Edison Co 80/07/21 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007020065 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28
- 8007210356 Forwards IE Circular 80~13, "Orid Strap Damage in Westinghouse Fuel Assemblies" No written response required XEPPLER.J O Region 3, Chicago, Office of the Director 80/05/20
- B007010086 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/29
- 8007020050 Forwards response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Zion holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES, D. Commonwealth Edison Co. 80/06/04 3pp
- 8007220156 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required KEPPLER.J O Region 3, Chicago, Office of the Director 80/06/10
- 8007020199 Forwards IE Insp Repts 50-295/80-09 & 50-304/80-09 on 800512-15 & 19-20 & notice of violation Notice of violation withheld (ref 10CFR2 790) HIND.J A Region 3. Chicago, Safeguards Branch 80/04/11 2pp
- --B00702021i IE Insp Repts 50-295/80-09 & 50-304/80-09 on B00512-15 & 19-20 Noncompliance noted failure to conduct proper personnel screening to secure & attend doors of vital areas & to test alarm sys Details withheld (ref 10CFR2 790) MADEDA:T J . CHRISTOFFER:0 Region 3. Chicago. Office of the Director HIND.J A Region 3. Chicago. Bafeguards Branch 80/06/10 2pp
- 8007160165 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11
- G007020075 Forwards response to IE Bulletin 80-12, "Decay Heat Removal Bys Operability " Review of RHH degradation events found none similar to Davis-Besse incident DELGEORGE, L O Commonwealth Edison Co 80/05/16 Spp
- B007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators
 PEOPLES D L Commonwealth Edison Co 80/06/16 3pp
- B007030037 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J 9 Region 3. Chicago, Office of the Director 80/06/18
- 8007230369 Forwards IE Insp Rept 50-304/80-07 on 800429-30,0519-21 & 0603-04 No noncompliance nated fidReLLico Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --8007230375 IE Insp Rept 50-304/80-07 on 800429-30, 0519-21 & 0603-04 No noncompliance noted Major areas inspected review of inservice insp program & observation of examination activities & results

 KEY, H J Region 3, Chicago, Office of the Director DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/18 7pp

- BOO7020389 Forwards IE Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director BO/06/20
 - KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/06/20
- 8007230754 Forwards IE Insp Repts 50-275/80-08 & 50-304/80-08 on 800421,0515-20,30 & 31 No noncompliance noted FIDRELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/23 2pp
- --B007230758 IE Insp Repts 50-275/80-08 & 50-304/80-08 on B00421,0515-20.
 30 & 31 No noncompliance noted Major areas inspected BergenPaterson large bore hydraulic snubbors on Unit 2 steam
 generators
 DANIELSON,D H Region 3. Chicago. Reactor Construction &
 Engineering Support Branch YIN,I T Region 3. Chicago. Office of
 the Director 80/06/18 3pp
- BOO7170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J. G. Region 3, Chicago. Office of the Director BO/06/24 In
- 800723026B Forwards IE Insp Repts 50-295/80-i1 & 50-304/80-ii on 800527-29 & notice of violation DAVIB,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/04/24 2pp
- --B007230272 Natice of violation from insp on 800527-29
 * Region 3, Chicago, Office of the Director 80/06/20 1p
- --8007230276 IE insp Repts 50-299/80-11 t 50-304/80-11 on 800527-29
 Noncompliance noted excess pH of waste water released to failure to standardize sodium hydroxide solution during boric acid titration
 ESSIO.T H. OESTMANN.H J . ROYTEK.C Region 3. Chicago. Office of the Director 80/06/20 9pp
- 8007230289 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE dircular 80-16 also encl No written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/06/27
- 8007310507 Forwards IE Health Physics Appraisal Repts 50-295/80-05 & 50-304/80-04 on B00310-21, notice of violation & significant appraisal findings MEPPLER, J C Region 3, Chicago, Office of the Director B0/06/27
- ---8007310510 Notice of violation from health physics appraisal on 800310-21
 - * Region 3, Chicago, Dffice of the Director 80/06/27 2pp
- --B007310515 JE Health Physics Appraisal Repts 50-295/80-05 & 50-304/80-04 on 800310-21 Noncompliance noted significant weaknesses found in areas reflecting on mgt & mgt support Heaknesses in emergency response & access control SCHUMACHER, M C. MILLER, D E Region 3, Chicago, Office of the Director FISHER, M L Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/06/23 58pp
- 8007310335 Forwards Waste Packaging insp Rept 15000046/80~32 on 800222 & 26
 DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety
 Branch 80/06/30 3pe
- --B007310339 Waste Packaging Insp Rept 15000046/80-32 on B00222 & 26 Noncompliance w/DOT regulations noted may dose rate on surface of transport trailer was 220 millirem/h O'REILLY,L A Region 5, San Francisco, Office of the Director THOMAS.R D. BOOK,H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch B0/04/02 12pp
- BOO7R50641 Responds to IE Bulletin BO-10. "Contamination of Monradioactive Bys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Any affected sys will be restricted if contamination found PEOPLES,D L. Commonwealth Edison Co. 80/07/07 2pp
- B007250650 Forwards response to IE Bulletin 80-11, "Masonry Wall Design" Requested investigation not performed at Dresden, Unit 1 due to extended outage Requirements will be met prior to startup W/o encl PEOPLES.D L Commonwealth Edison Co 80/07/07 2pp

- 8007250639 Forwards response to IE Bulletin 86-08. 'Examination of Containment Liner Penetration Welds.' Drusden Unit I designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit riturned to svc. PEOPLES.D. L. Commonwealth Edison Co. 80/07/09. 7pp
- R Persodic operating seports & related correspondence
- 8007140327 Forwards monthly operating repts for June 1980 GRAEBSER.K L. Commonwealth Edison Co. 80/07/07 tp
- ---B007140331 Monthly operating repts for June 1980 CDDK,J M Commonwealth Edison Co 80/0//07 11pp
- 8 Reportable occurrences, LERs & related correspondence
- BOO7220307 Forwards LER 80-009/03L-0 WANDKE,N E Commonwealth Edison Co 50/03/03 ip
- --B007220391 LEN 80-009/03L-0 on 800202 steam generator level transmitter 2LT-538 had shifted high by 2 257 Caused by transmitter drift due to natural component aging Transmitter recalibr & channel returned to svc JENKINS,R V Commonwealth Edison Co 80/03/03 lp
- 8007160668 Forwards LER 80-022/017-0
 WANDKE,N & Commonwealth Edison Co 80/06/27 is
- --BOO7160672 LER BO-022/01T-O on BOO618 during integrated leak rate test on Unit 2, accombilators for power operated relief valves vented & instrument air isolated Coused by air isolation Procedure change to block valves open during test made GAJIC. Z Commonwealth Edison Co 80/06/27 2pp
- B007220587 Forwards LER 80-023/03L-0 QRAESSER,K L Commonwealth Edison Co B0/07/16 1p
- --B007220593 LER 80-027/OSL-0 on 800627. Approx 4,000 gallons of OH lake discharge tank released w/o verification of dilution flow to discharge canal w/one svc water pump in svc Caused by personnel oversight Tech Spec requirements roviewed GURUNATHAN.S Commonwealth Edison Co 80/07/16 2pp
- BOO7220406 LER 80-007 has been cannolled COLLINS.N. Commonwealth Edison Co. BO/07/21 19
- 800722040B LER 80-005 has been cancelled CQLLINS:M Commonwealth Edison Co 80/07/21 1
- 8007220409 LER 80~003 has been cancelled COLLINS.M Commonwealth Edison Co 80/07/21 is
- BOO7220411 LER 79-048 has been cancelled CDLLINS.M Commonwealth Edison Co 80/0//21 1
- 8007220412 LER 79-047 has been cancelled CDLLINS.M Commonwealth Edison Co 80/07/21 1
- 8007220413 LER 79-046 has been cancelled COLLINS:81 Commonwealth Edison Co 80/07/21 1
- 8007220414 LFR 79-045 has been cancelled CQLLINS.M Commonwealth Edison Co. 80/07/21 4
- T Hearing transcripts on non-antitrost matters
- 8007150024 Transcript of 800701 morning hearing in Bethesda.MD Pp 1-120 * Atomic Safety and Licensing Board Panel 80/77/01 123pp
- DOCKET 50-305 KEWAUNEE NUCLEAR PUNER PLANT

 F Security, medical, emergency & fire protection plans
- 8007280414 Forwards Draft 4 of facility radiological emergency response plan Plan available in Central Files only MATHEMS.E R Wisconsin Public Service Corp 80/07/23 lp

G Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UTS 780802 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT. B © Division of Licensing 80/04/25 89pp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D C Division of Licensing 80/06/11 62pp
- 8007010224 Notifies of BOO616 meeting w/Westinghouse.Fluor Power Syc Carp & util in Dethesda.RD to discuss steam generator support bolt anomalies MERMANN.R A Division of Reactor Operations Inspections BO/06/13
- 8007220229 Lists actions taken by util after 800928-31 insp of steam generator bolts determined that leg 1 of steam generator B had four long bolts & two short bolts Attempt to replace bolts will be made during next refueling outage MATHEM9.E R Wisconsin Public Service Corp 80/06/20 Jpp
- --8007220234 "Safety Evaluation of Steam Generator Support Pad Connections Having Vascomax Bolts in Helicoil Inserts " PARIMI,S R , INCUGE,S , SETLYUR,A V Fluor Power Service, Inc 80706/18 20pp
- 8007080206 Forwards "Nuclear Purge Valve Stress Analysis," in support of reactor bldg vent valve mod MATHEMS.E R Wesconstin Public Bervice Corp 80/07/02 ip
- --8007080208 "Nuclear Purge Valve Stress Analysis " * Pioneer Service & Engineering Co 60/06/25 16pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENMUT.D O Division of Licensing 80/07/02 69pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007020029 Forwards IE Info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required KEPPLER.J G Region 3, Chicago. Office of the Director 80/05/28 ip
- 8007210412 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/28 ip
- 8007010078 Forwards IK lnfo Notice 80-23, "Loss of Suction to Emergency Fredwater Pumps" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/05/29 1p
- 8007010036 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 Review of sys demonstrated that adequate protection is included in design Table of sys reviewed enc!
 MATHEMS.E R Wisconsin Electric Power Co 80/06/09 2pp
- 800722028 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/10 to
- 8007020716 Advanes NRC that ultrasonic inep of Vascomax 250 CVM steam generator bolts was performed on 800928-31 to resolve steam generator reactor coulant pump support lamellar tearing issue Existing Log 1 support bolting is adequate MATHEMS.E R Wiscomen Public Service Corp 80/06/11 2pp
- 8007160203 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response Tequired KEPPLER, J. G. Region 3. Chiraço, Office of the Director 80/06/11.

- BOO7020032 Responds to IE Bulletin 80-12, "Decay Heat Removal Sys Operability " Licensee review indicates that current design is adequate Further response will be submitted within 1 wk MATHEMS.E R Wisconsin Public Service Corp 80/06/12 ip
- B007020256 Responds to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Review of schematic & logic diagrams indicates that all applicable equipment operates in intended manner after reset MATHEMS.E R Wisconsin Public Service Corp B0/06/17 2pp
- 8007030026 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3, Chicago: Office of the Director 80/06/18
- B007230314 Forwards IE Insp Rept 50-305/80-10 on 800507 & 19-23 & notice of violation HEISHMAN, R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch B0/06/18 2pp
- --B007230317 Notice of violation from insp on B00507 & 19-23 * Region 3, Chicago, Office of the Director 80/06/17 2pp
- --8007230328 IE Insp Rept 50-305/80-10 on 800507 & 19-23 Noncompliance noted failure to follow procedures & failure to rept loss of offsite power event within 1-h HARNICK,R F. CHULLESN C . NELSON,R L Region 3, Chicago, Office of the Director 80/06/17 7pp
- 8007020338 Forwards IE Circular 80-13. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/20
- 8007170528 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24
- B007230356 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Hritten response required IE Circular 80-16 also encl No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/27
- 8007240321 Responds to IE Bulletin 80-10 re contamination of nonradioactive sys & resulting potential for unmonitored, uncontrolled release of radioactivity to environ Several sampling & monitoring points have been added to program MATHEWS, E R Wisconsin Public Service Corp 80/07/07 ip
- B007240334 Responds to IE Bullotin B0-08. "Examination of Containment Liner Penetration Welds " Welds repaired as necessary, when unacceptable results were indicated by nondestructive insputelds acceptable by final rediographic insp
 MATHEWS, ER Wisconsin Public Service Corp 80/07/07 3pp
- 8007240415 Responds to IE Bulletin 80-11, "Mesonry Wall Design " Four masonry walls have been identified w/potential for interaction w/safety-related equipment Walls were designed Seismar Class I & Purther investigation is not warranted MATHEWS,E R Wisconsin Public Service Corp 80/07/09 2pp
- 8007310261 Forwards IE Insp Rept 50-305/80-13 on 800623-27 % notice of violation Notice of violation withheld (ref 10CFR2 770) HIND, J A Region 3. Chicago, Safeguards Branch 80/07/11 Rpp
- --8007310267 IE Insp Rept 50-305/80-13 on 800623-27 Noncompliance noted guards not qualified, inadequate screening & improper barrier control Details withheld (ref 10CFR2 790)
 BELANGER, J. L., CREED, J. R. Region 3, Chicago, Office of the Director HIND, J. A. Region 3, Chicago, Safeguards Branch BD/07/11 2pp
- B007240396 Advises that util 800613 response to NRC 800520 ltr is unsatisfactory Results of review will be communicated as soon as possible HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/07/18 ip
- R Periodic operating reports & related correspondence
- 8007160544 Forwards monthly operating rept for June 1980 MATHEWS, E. R. Wisconsin Public Bervice Corp. 80/07/09

- --8007160548 Monthly operating rept for June 1980
 RUITER & H. Wisconsin Public Service Corp. 80/07/09 Spr
- 8 Reportable occurrences, LERs & related correspondence
- 8007080386 Forwards LER 80-024/03L-0
 MATHENS, E.R. Wisconsin Public Service Corp. 80/07/02 lp
- --8007080390 LER 80-024/03L-0 on 800619, at hot shutdown while steam generator was in operation blowdown radiation monitor R-19 was not sampling blowdown for approx 6-h Caused by isolation of monitor during performance of prestartup checklist RALEPKA, D 8 Wisconsin Public Service Corp 80/07/03 ip
- 8007110317 Forwards LER 80-024/03L-0 MATHEWS,E R Wisconsin Electric Power Co 80/07/02 1p
- --B007110326 LER B0-024/03L-0 on B00619, at hut shutdown w/steam generator blowdown in operation, radiation monitor R-19 not sampling blowdown for approx 6-h Cause not stated Sampling sys being reviewed for initial conditions
 NALEPKA, D S Wisconsin Electric Power Co 80/07/03 1p
- BOO7160464 Forwards LER 80-026/01T-0 MATHEWS, E R Wisconsin Public Service Corp 80/07/07 1p
- --B007i60474 LER 80-026/01T-0 on B00624 refueling water storage tank level fell below Tech Spec limit Cause unidentified Makeup was initiated immediately & Tech Spec level was restored Investigation in progress & updated rept will be submitted NALEPKA, D S , SMOKER, C S Wisconsin Public Service Corp B0/0708 in
- 8007160485 Forwards LER 80-025/03L-0 & updated LER 80-019/03L-1 MATHEWS, & R Wisconsin Public Service Corp 80/07/11 ip
- --B007160502 LER B0-025/03L-0 on B00617 five containment isolation valves found w/unacceptable leakage Causes unspecified Two valves replaced two seats cleaned. & one stroke adjusted Subsequent leakrates below Tech Bpec limits
 NALEPKA.D B Wisconsin Public Bervice Corp 80/07/11 1p
- ---B007160510 Updated LER B0--019/03L--1 on B00611, shield bldg ventilation sys check damper BBV--10A failed to fully open Caused by controller setpoint drift Setpoint adjusted & design change study initiated NALEPKA, D 8 Wisconsin Public Service Corp 80/07/11 1p
- 8007280669 Forwards LER 80-027/03L-0 MATHEWS E R Wisconsin Public Service Corp 80/07/21 ip
- --8007280674 LER 80-027/03L-0 on 800621.during cooldown.diesel generator 18 failed to start on occurrance of inadvertent safety injection signal Caused by air start motor solenoid valve containing moisture & containments Tanks blown dry NALEPKA D S Wisconsin Public Service Corp 80/07/21 ip
- 8007280679 Forwards LER 80-028/031-0
 MATHEMS:E R Wisconsin Public Service Corp 80/07/22 ip
- --8007280685 LER 80-028/03L-0 on 800623, during hot shutdown, condensate storage tank was twice drawn below 75,000 gallons through normal water usage for plant startup Caused by normal high water usage during startup following refueling NALEPKA, D S Wisconsin Public Bervice Corp 80/07/23 lp
- DOCKET 50-304 PRAIRIE 18LAND NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- B007020235 Forwards request for limited revisions & add1 info re 790323 plant safeguards contingency plan Encl withheld (ref 100FR2 790) CLARK.R A Operating Reactors Branch 3 80/06/10 2pp
- B007110118 Forwards response to NRC B00218 questions re safe shutdown in event of fire MAYER.L.O Northern States Power Co 80/07/08 3pp
- C. Adjudicatory correspondence
- B00710020B Ack receipt of NRC B00619 ltr to 0 Charnoff re nonreceipt of Btate of MN 800424 contentions Certificate of Bvc encl OLBONIJ F Minnesota, State of 80/06/23 3pp

- 8007310247 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHULD Q Division of ilensing 80/06/25 B9pp
- 8007250422 Amended Contentions 1 & 2 & withdrawal of Contention 3 Amend request does not inntain safety analysis or spent fuel storage & does not contain analysis of spent fuel pool expansion consequences Certificate of Svc encl OLBON, J F, SEMECHAL, M E . SPANNAUS, W Minnesota, State of B0/07/21 7pp
- B007310473 Confirms ASLB request for hearing space at federal bldg in Saint Paul. NN on 800806 to conduct 1-day prehearing conference re facility STEPHENS.C R Docketing & Services Branch 80/07/22 ip
- B007250688 Comments stating no objection to admission of State of MN 800721 Contentions 1 % 2 re cask drup accident & loss of water accident in spent fuel pools Reserves rights re substance & validity of contentions (ortificate of 9vc encl BARTH, C A Hearing Granch 3 80/07/25 2pp
- B007300463 Responds to State of MN 800424 supplite petition to intervene & 800721 amended contentions Supporting documentation, notices of appearance of JE Siberg & DL Bernstein on behalf of util & Certificate of Svc end. SILBERG.J E Northern States Power Co SILBERG.J E Shaw Pittman, Potts & Trombridge 80/07/23 24pp

H General correspondence

- 8007310526 Responds to 800226 ltr re constituent concern about evacuation routes enound facilities NRC & FEMA engage in program to upgrade emergency preparedness including evacuation planning
 BIRCKS.W J Office of the Executive Director for Operations 80/07/24 Spp
- --B007310528 Requests info re chrl constituent ltr about evacuation routes around facilities
 B05CHWITZ,R Senate 80/02/26 App
- P Operating license stage documents & correspondence
- 8007230079 Requests submittal of proposed Tork Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Speck which would provide acceptable resolution encl for guidance EISENHUT, D G Division of Lichsing 80/06/11 62pp
- 8007030222 Notifies NRC of intention to ship radinactive math from facilities using Model HN-600 MAYER.L O Northern States Power Co 80/04/13 1p
- 8007010581 Responds to 800513 itr re containment purge info by forwarding related correspondence MARTINIR A Operating Reactors Branch 3 80/06/18 2pp
- ---B0070109B3 Responds to EGLO 800513 questions LOCA dose calculations not completed Monitors are redundantiges \ particulate monitors provided.each giving isolation signal MUSQLF.D Northern States Power Co G0/06/03 ip
- --800/010385 Requests preliminary evaluation of licensee response to NRC 791029 "Interim Position for Containment Purge & Vent Valve Operation Pending Resolution of Indiation Valve Operability," General Item B-24 Evaluation form entl REEVES E A Operating Reactors Branch 1 (Pre 800428) 79/12/27 App
- 8007010376 Forwards Westinghouse cept 80-509-PRAIR-RI, "Examination at Prairie Island 2 Income! Alloy 600 Steam Generator Tube," resulting from 800212 weeting re Jan 1980 Insh Rept withheld (ref 1001R2 790) Util 800627 itr end!
 MAYER.L D Northern States Power Co 80/06/27 ip
- --8007010381 Submits application to withhold Westinghouse research rept 80-507-PRARI-R1. "Examination at Prairie Island 2 Inconel Alloy 600 Steam Generator Tube." (ref 100FR2 790) Affidavit tupporting request encl MAYERL O Northern States Power Co 80/06/27 3pp
- B007170076 Summary of B00820 meeting w/util re TOPROD fuel design MARTIN.R Operating Reactors Branch 3 80/07/01 7pp

- B007290001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PMR Model Tech Specs & Model license conditions for TMI-2 Lagsons Learned Category A items poct for guidance EISENHUT, D G Division of Licensing 80/07/02 89pp
- B007280056 Advises of intention to ship radioactive matls from listed facilities using Package Model CNSI $\Lambda L=32$ -90 MAYER.L 0 Northern States Power Co B0/07/09 ip
- 8007240388 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for GETR NDVAN.T M Assistant Director for Operating Reactors 80/07/08
- B007280410 Forwards comments on NUREG-0577, "Fracture Toughness & Susceptibility to Stress Corrosion Cracking of Equipment Bupports," in response to NRC 800519 request Addi analysis for stress currosion cracking is unnecessary MAYER.L O Northern States Power Co 80/07/21 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007070051 Forwards IE Insp Repts 90-202/80-06 & 50-306/80-07 on 800401-30 & notice of deviation HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/05/21 2pp
- --8007070056 Notice of deviation from insp on 800401-30 * Region 3. Chicago. Office of the Director 80705/16 1
- 8007020054 Forwards IC Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J. G. Region J. Chicago, Office of the Director 80/05/28
- B007210362 Forwards IE ('srcular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director B0/05/28 to
- B007010127 Forwards IE Info Notice B0-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 90/05/29 19
- 8007240185 Forwards IE Insp Repts 50-292/60-09 & 50-306/80-10 on 800301-31 No noncompliance noted HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --8007240210 IE Insp Repts 50-282/80-07 % 50-306/80-10 an 800501-31 No managempliance moted Major areas inspected maint, surveillance, security, radiation protection, followup of licenses reported events & followup to IE circulars FELERABEND. C D. BURGESS. B L , BOYD. D C Region 3, Chicago, Office of the Director 80/06/05 App
- 8007010260 Responds to IE Builetin /9-17, Revision 1. "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants " Visual insprequired by Item 2(a) was rompleted on Unit 1 w/no corrective actions necessary OllDERTB, D E Northern States Power Co 80/06/09 ip
- 8007010267 Responds to IF Bulletin 80-06. "Engineered Safety Feature Reset Controls " Safety sys schematics reviewed Test demonstrating safety equipment remains in emergency mode after reset will be completed at next refueling outage GILBERTS.D E Northern States Power Co 60/06/09 2pp
- 8007010549 Responds to IE Belletin HO-Ob, "Varuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Chemical & vol control sys & components & gaseous & liquid waste disposal sys & components were reviewed GILBERTS, D.E. Northern States Power Co. 80/06/09 2pp
- 8007140707 Responds to IE Bulletin 80-05 Review of chemical & vol control sys indicates holdup tank vulnerability to collapse Low systion pressure trep to be installed on holdup tank transfer % recirculation pumps by 810101 OILDERTS,D E. Noithern Statis Puwer Co. 80/04/09 2pp
- 8007220212 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/10 in

- 8007160182 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11 to
- 8007030043 Forwards IE Bulletin 80~15. "Possible Loss of Emergency Notification Sys (ENS) W/Less of Offsite Power "Written response required KEPPLER.J 9 Region 3. Chicago. Office of the Director 80/06/19
- B007020973 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KLPPLER.J G Region 3. Chicago, Office of the Director 80/06/20
- 8007140094 Ack receipt of encl 800617 ltr informing NRC of steps taken to correct violations noted in NRC 800522 ltr Encl withheld (ref 10CFR2 790)
 HINDLY A Region 3, Chicago, Safeguards Branch 80/06/24 lp
- 8007170506 Forwards IE Circular 80-14, "Radinactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLEN, J G Region 3. Chicago, Office of the Director 80/06/24 to
- B007:40186 Ack receipt of B00612 ltr informing NRC of steps taken to correct deviation noted in IE lnsp Repts 50-282/B0-06 & 50-306/B0-07 forwarded by B00821 ltr Senior resident inspector will follow remaining testing HEISHHAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/25 lp
- --B007140192 Responds to deviation noted in IE Insp Repts 50-282/80-06 & 50-306/80-07 forwarded by 800521 ltr Special insps of two out of four power operated relief isolation valve motor starters have been completed Two others will be performed GILBERTS, D E Northern States Power Co 80/06/12 1p
- 8007230336 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1131 & 1132 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27, 19
- B007170186 Ack receipt of 800523 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 30-306/78-24 F10RELLIO Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/06/30 ip
- --8007170194 Responds to NRC 790123 ltr re violation noted in IE Insp Rept 50-306/78-24 Corrective actions replacement of snubbers planned for refueling shutdowns, unless carlier cold shutdown occurs. GILBERTS, D E Northern States Power Ca 80/05/23 1p
- 8007150481 Advises that demonstration of ultrasonic insp method for detecting underclad cracking in reactor vessel nozzle region for Unit 1 is scheduled for 800723 Unit 2 insp will take place during 1981 refueling outage MAYER, L D Northern States Power Co 80/07/07 ip
- B007250077 Forwards response to IE Bulletin 80-11, "Masonry Wall Design " Concrete block walls are not in same design philosophy as design of Trojan plant masonry walls Walls were generally designed as partition walls or shield walls OILBERTS.D E Northern States Power Co 80/07/08 5ipp
- 8007220090 Submits reply to IE Bulletin 80-08 re examination of containment liner penetration welds Review of Unit 1 revealed two deficient welds Further response will be sent by 800810 OILDERTS.D.E. Northern States Power Co. 80/07/10 ip
- BOO7220542 Submits reply to IE Bulletin 79-01B re environ qualification of Class IE equipment Qualified limit switches have been ordered & are scheduled for replacement during future outages Worksheets encl OILDERTS.D E Northern States Power Co 80/07/10 8pp
- B007230211 Submits reply to IE Rulletin 79-17 re pipe cracks in borated water sys Visual insp required by bulletin was satisfactorily completed for Unit 1 No corrective actions necessary GILBERTS: D & Northern States Power Co 80/07/10 1p.

- R Periodic operating reports & related correspondence
- 8007030178 Forwards "1979 Environ Monitoring & Ecological Studies Program Rept. "Vols 1 & 2 WARD, E C Northern States Power Co 80/06/30 ip
- --8007030180 "1979 Environ Monituring & Ecological Studies Program Rept."
 - Vol 1 * Northern States Power Co 80/06/30 325eo
- --8007030183 "1979 Environ Monitoring & Ecological Studies Program Rept." Vol 2 * Northern States Pawer Co 80/06/30 325pp
- 8007160598 Forwards monthly operating repts for June 1980 MAYER.L O Northern States Power Co 80/07/11 ip
- ~-8007160562 Monthly operating repts for June 1980 HUNSTAD, A. A. Northern States Power Co. 80/07/01 9pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007010524 Forwards LER 80-016/03L-0 MAYER,L D Northern States Power Co 80/06/27 lp
- ---BOQ7010829 LER BO-016/03L-O on BO0529 during instrument calibrinstrument was dropped on trip throttle valve linkage, tripping valve & making pump inoperable for 3 minutes Caused by personnel error
 MUNSTAD, A A Northern States Fower Co 80/06/27 ip
- 8007210379 Forwards LER 80-017/03L-0 MAYER, L 0 Northern States Power Co 80/07/14 lp
- ~~8007210380 LER 80-017/03L-0 on 800615 during normal operation, found one charging pump out of svr Charge pump 23 started & shut down Caused by air leaks on speed control unit due to broken packing ring Packing ring replaced
 HUNSTAD, A A Northern States Power Co 80/07/14 1p
- 8007250340 RD 80-20 on 800715, w/Unit 2 at 1007 power & Unit 1 at cold shutdown, main generator separated from grid & one offsite source was lost tripping reactor & coolant pumps Caused by severe electrical storm Transformer restored TIERNEY,F P Northern Btates Power Co 80/07/16 1p
- DOCKET BO-309 MAINE YANKEE ATOMIC POWER PLANT
- F Security, medical, emergency & fire protection plans
- B007100455 Forwards request for add1 info for review of util 790323 security contingency plan Encl withheld (ref 100FR2 790) NOVAX,T N Assistant Director for Operating Reactors 80/05/19
- B007170444 Forwards NRC comments on emergency plan Responses to comments must be submitted by 800630 NOVAK.T M Assistant Director for Operating Reactors 80/06/26
- Adjudicatory correspondence
- 8007310243 Forwards Commission 800827 memorandum & order containing AUGIDEAS requares commission august memoranism a view and decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENHUT, D G Division of Licensing 80/06/25 89ap
- BOO7020607 Response in apposition to applicant motion to postpone special prehearing conference respent fuel pool mod proceeding Urgos scheduling at earliest convenience due to significant benefit to all parties, including applicant MILLER, D.S. Sensible Maine Power MILLER, D.S. Miller, D.S. BO/06/26 2pp
- --8007020610 Memorandum of points & authorities in support of intervenor apposition to applicant motion to postpone special grahearing conference Public interest is better served by rapid decision.per case law Certificate of Svc enci MILLER, D S Sensible Maine Power MILLER, D S Miller, D B 80/06/26 App

- 8007030240 Response in opposition to licensee motion to postpone prehearing conference until after 801001 Suggests moderate delay until mid-Aug 1980 for licensee to consider amend resite spent fuel storage Curtificate of Svc encl REIS,E J. Hearing Branch 3 (00/07/02 Spp
- B007300122 Appeals ASLB 800714 memorandum & order on schoduling prehearing conference Urges reversal of order & convening of special probleming conference Certificate of Ske encl MILLER, D S. Sensible Maine Power MILLER, D S. Miller, D S. 80/07/26 Opp
- --8007300127 Brief in form of pleading in support of intervenor 800726 appeal from ASLB 800714 memorandum & order on scheduling prehearing conference Alleges denial of procedural due process per case law Urges helding of special prehearing MILLER.D S Sensible Mainc Power MILLER.D S Miller.D S 80070726 10pp
- 8007310463 Memorandum & order.ALAB-602 dismissing Sensible ME Power appeal from ASLB 800714 order which postponed prehearing conference in spent fivel pool compaction proceeding BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/29
- H General correspondence
- BOO6230378 Ack receipt of NRC BOO609 ltr & encl evacuation time estimates for facility Estimates do not adequately define risk in terms of total population Multiplier of 3 4 for Boothbay region is much too low GARRETT, E. G. Affiliation Unknown 80/06/14 3pp
- BOO71104B1 Requests that name of RR Radcliffo he replaced w/TH Macdonald on ME Dic of Energy Resources mailing list for correspondence re utils MACDUNALD, T. H. Haine, State of BO/07/01 1p
- 1 Financial information
- 8007080217 Forwards company statument of capita) requirements & sources for CY80 sources for CYBO CRABTREE,R A Maine Yankee Atomic Power Co 80/07/01 2pp
- P Operating license stage documents & correspondence
- 8007110329 Notification of 600505 meeting w/util in Bethesda.MD to discuss effect of automatic initiation of auxiliary feedwater sys upon consequences of steam line bleak NELSON, C.C. Operating Reartors Branch 3 80/05/01 2pp
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D.G. Division of Livensing 80/06/11 62pp
- 6007110123 Notification of 800623 meeting w/otil in Bethesda MD to discuss NRC version of ETS REGUA.0 Operating Reactor: Branch 3 80/0A/19 2pp
- B007010070 Responds to FDIA request for 57 documents referenced in M Tokar memo to ALRS concerning pellet-cladding interaction Forwards documents Missing records are duplicative, superseded or available elsewhere FELTON.J M Division of Rules and Records 80/06/70 2pp
- --BOO7010099 Forwards Summary of 741112 meeting w/util in Bethesda.MD to distuse examination of Core 1 fur) assemblies & Core IA reassembly procedures List of attenders encl HOUSTON.M D Atomic Energy Commission, Directorate of Licensing lOpp 74/12/15
- B007140465 Notification of 800/15 meeting w/licenses to discuss shortness storgeon taken from little structure on 800602 & 13 & to discuss details of incidents transmitted by NRC 800662 ltr Operating Reactors Branch 3 60/06/24
- B007170060 Forwards request for addling or details of 800602 & 13 discoveries of aborthose studyen, endangered species, in facility intake structure Traft responses will be discussed at 800715 site visit Formal response due 20 days from visit NOVAK.T M. Assistant Director for Operating Reactors 80/06/26

- 8007030225 Submits responses to NRC 80050A request for addl info re adequacy of station electrical distribution sys voltages ORBCE.R H Maine Yankee Atomic Power Co. 80/06/30 15pp
- B007090295 Advises NRC of completion of evaluation of effects of asymmetric LOCA loadings Design basis & safety evaluations described in FSAR are not adversely affected by asymmetric loadings resulting from postulated LOCA GRACE.R H. Haine Vankee Atomic Power Co. 80/07/01 2pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PAR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A Items encl for guidance EISENHUT.D & Division of Licensing 80/07/02 69pp
- 8007090388 Notification of 800715-16 meeting w/util in Wiscasset, ME to discuss answers to NRC 800701 quostions re inservice test program REGUA, G Operating Reactors Branch 3 80/07/03 ip
- 8007240346 Advises of NRC reorganization on 800428 which resulted in number of changes in off titles, positions & assignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08 200
- 8007140338 Forwards YOOAP-I-A.Revision 8.per NRC 800702 request Also forwards document change instructions for removing & inserting correct pages HEIDER: L H Yankee Atomic Electric Co 80/07/09 2pp
- --B007140342 Advises that YUGAP-I-A, Revision B, is acceptable Programmatic changes should be submitted to NRC for review prior to implementation Requests that Itr replace B00410 ltr & rept be renumbered w/revision & submitted to NRC HAASS, U.P. Quality Assurance Branch B0/07/02 ip
- 9007210020 Forwards request for addl info,re inservice testing program, to complete review Draft responses will be discussed during 800715-16 meeting Responses should be forwarded by 800816 NOVAK,f M Assistant Director for Operating Reactors 80/07/09 22pp
- B007250404 Application for amend to App A of License DPR-36, consisting of proposed Change 77 to modify Tech Spec 3 to 11 re reactor protection sys setpoints
 JOHNSON & P Haine Yonkee Atomic Power Co 90/07/16 3pp
- --8007250405 Revised Figure 3 10-3 of Tech Spec 3 10 11 re reactor protection sys subpoints, submitted as proposed Change 77

 * Maine Yankee Atomic Power Co 80/07/16 ip
- BO07280439 Submits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURGH.D Yankee Atomic Electric Co 80/07/24 7pp
- O Inspection reports. IR Bulletins & correspondence
- B007020163 Forwards 1E Info Notice B0-22, "Breakdowns in Contamination Control Programs" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director B0/03/2B 1p
- B007010314 Forwards JE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/05/29 ip
- 8007180090 Submits reply to 16 Bulletin 80-05 re vacuum condition resulting in 64mage to holdup tanks Neasures described are adequate to protect against excessive vacuum conditions No corrective actums are planned MODDY.D F Maine Yankee Atomic Power Co. 80/06/06. 2pp
- 8007230389 Forwards IE Insp Rept 50-309/H0-06 on 800407-11 & 21-24 No noncompliance nuttd BRUNNERF J Region i. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/09 2pp
- --8007230398 IE insp Rept 50-309/80-06 pn 600407-ii & 21-24 No noncompliance noted Major areas inspected accessible areas, logs & records & lisensce action on selected previous insp findings
 LAZARUS. H. MARTIN. T. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch: BMS(LAND.P. Region), Philadelphia.

 Diffice of the Director 80/06/07 8pp

- BO07210575 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/06/10 ip
- 8007160352 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pumps Studs " No specific action or response required GRIER.B H Region 1. Philadelphia, Office of the Director 60/06/11 1p
- B007230377 Forwards IE Insp Rept 50-309/80-07 on B00505-09 No noncompliance noted BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 60/06/12 2pp
- --8007230383 IE insp Rept 50-309/80-07 on 800505-07 No noncempliance noted Major areas inspected followup on selected LERs & licensee action to limit online containment purging & ventilation
 LAZARUS. R Region i, Philadelphia, Office of the Director MARTIN.T T Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/11 5pp
- 8007170321 Forwards response to IR Bulletin 60-06, "Engineered Safety Feature (ESF) Reset Controls " Changes were made to preclude automatic loss of containment isolation as result of resetting containment isolation signals VANDENBURG.D Maine Yankee Atomic Power Co 80/06/13 9pp
- B007020707 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required ORIER, 8 H Region 1, Philadelphia, Office of the Director B0/06/18 Ip
- 8007020501 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/04/20 ip
- 8007160711 Forwards JE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water 89s & Resultant Internal Contamination of Personnel "No written response required GRIER.8 H Region i. Philadelphia. Office of the Director 80/06/24 ip
- 8007910204 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 60/06/25 1p
- 8007280458 Responds to IE Dulletin 79-14. "Seismic Analysis for As-Built Safety-Related Piping Sys " Twenty-two piping sys reanalyzed due to pape &/or support function or location differences identified an field effort MODDY.D E Maine Yankee Atomic Power Co 80/06/25 App
- 8007230132 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Gutput Codes "Written response required. IE Circular 80-16 also encl No written response required GRIER. B H Region 1. Philadelphia, Office of the Director 80/06/27 2pp
- B007210A01 Forwards response to 16 Bulletin 80-11 Masonry walls in proximity to safety-related sys described in encl table JOHNSON.W P Maine Yankee Atomic Power Co 80/06/30 Spp
- 8007140403 Responds to TE Bulletin 80-08, "Examination of Containment Liner Penetration Welds." Flued head designs w/containment boundary butt welds not used & containment panetration weld repairs not required during facility const MDODY,D E Maine Yankee Atomic Power Co 80/07/01 2pp
- A Periodic operating reports & related correspondence
- 8007210367 Forwards, "Effluent & Waste Dispusal Bemiannual Rept. Jan-June 1979 GROCE.R H Maine Yankee Atomic Power Co 79/08/29 ip
- ---8007210369 "Effluent & Waste Disposal Semiannual Rept, Jan-June 1979 "
 * Maine Yankee Atomic Power Co 79/08/29 9pp
- B007110386 Forwards discharge monitoring rept for May 1980

 OARRITY, J H Maine Yankee Atomic Power Co 80/07/07 200

- ~~8007110389 Discharge monitoring rept for May 1980 FLANDERS.W Mains Yankoe Atomic Power Co 80/05/22 5pp
- 8007280604 Forwards discharge monitoring rept for June 1980, submitted to ME Dept of Environ Protection Transmittal ltr encl OARRITY.J H Maine Yankee Atomic Power Co 80/07/24 2pp
- B Reportable occurrences, LERs & related correspondence
- BOO7010339 RO 80-15/01T-0 during Engineering review discovered that Cycle 5 analysis did not consider four-step.long-term insertion of control element assemblies allowed by Tech Spacs, which would permit less conservative operation HOOD, E.C. Maine Yankes Atomic Power Co. BO/06/25 1p
- B0070B0413 Forwards LER B0-014/03L-0 W000.E C Maine Yankee Atomic Power Co B0/07/02 ip
- --B007080417 LER 80-016/03L-0 on 800602, during startup at 15% power, steam generator 1 outlet steam pressure found higher than other two pressures Caused by matl failure in heat affected ione of guide to disc weld flees welded BRINNLER. JE Maine Yankoe Atomic Power Co 80/07/02 is
- ---BOD7210431 LER BO-015/01T-O on 800625, analysis performed for Cycle 5 did not consider four-step, long-term insertion allowed by Tech Spec Reanalysis completed Tech Spec change will be submitted BRINKLER, J E Maine Yankee Atomic Pawer Co BO/07/09 1p
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8007070109 Informs that, as stated in Suppl 4 to SER, manual ECC8 whitchover approved in Suppl 1 to SER has been ra-evaluated NRC requires that manual switchover actions be replaced by automatic design complying whenci criteria SCHMENCER. A Licensing Branch 3 80/06/18 3pp
- F. Becurity, medical, emergency & fire protection plans
- B007080048 Forwards Submittal 4 to 800427 security contingency plan Bubmittal withheld (ref 10CFR2 790) LIBRIZZI,FP Public Service Flactric & Gas Co of New Jersey 80/04/30 lp
- 8007210277 Notification of 800701 meeting w/util in Bethesda.MD to discuss emergency preoperedness KERRIGAN, J Operating Reactors Branch 3 80/07/01 3pp
- BOO7140429 Requests approval to proceed winterim use of training facility in Quinton, NJ as nearsite emergency operations facility

 BCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey
- 9 Adjudicatory correspondence
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cablos EISENHUT.O G Division of Licensing 80/04/25 87pp
- J Insurance & indemnity information
- 8007010323 Forwards Endorsement 39 to ANI Policy NF-230 CORREA.M A Marsh & McLennan.Inc , N & M Nuclear Consultants.Inc Div 80/06/25 2pp
- 8007310342 Forwards Endorsement 32 to MAELU Policy MF-90 CORREA,M A Marsh & McLennan.Inc , M & M Nuclear Consultants.Inc Div 80/07/21 2pp
- BOO7310376 Forwards Endorsement 40 to ANSI Policy NF-230 CORREA,M A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/07/21 2pp

- P Operating license stage documents % correspondence
- 8007010563 Forwards NRC reorganization chart for life of Norlear Reactor Regulation, effective 800428 Considerations to activities should be made through assigned mot representatives Areas of disagreement may be discussed through informal appeal TEDESCO, R.L. Assistant Diroctor for Licensing 80/06/13 2pp
- 8007:10456 Informs that second interim rept.per facility 316(b) plan of study, will be distributed to technical advisory group by 800625 belay caused by computer problem Submittal date should allow enough time for review before 800709 meeting 8HISSAIS.J A Public Service Flectric & Gas Co of New Jersey 80/06/13 2pp
- B007160416 Notification of 8000h20 meeting w/util in Bethesda.MD to discuss NRC position on steam generator tube plugging & installation of insp ports KERRIGAN.J Licensing Branch J 80/06/13 2pp
- 8007020086 Forwards request (or add1 info needed to complete timely review of TMI-2 Lessons Learned Task Force short-torm items Response requested within 20 days

 8CHMENCER.A Licensing Branch 3 80/06/20 5pp
- 8007:10554 Summary of 800610 meeting w/util in Bethesda, MD re control rod position indicator sys license amend request tists three possible solutions to problem w/indicator Attendee list encl
 KERRIGAN, J Licensing Branch 3 80/06/24 3pp
- B007110561 Bummary of 800695 meeting w/util & Wostinghouse in Bethesda, MD re proposed conceptual design of automatic ECCS switchover sys List of attendors & meeting handout encl KERRIGAN, J Licensing Branch 3 80/Q6/24 16pp
- BOQ723000) Forwards statement of policy is requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EISENHUT, D.C. Division of Licensing BO/06/26 2pp
- 6007030249 Forwards response to 800404 tenfirmatory orders re loss of non-Class IE instrumentation & control power bus lines written for Unit 1 but also applicable for Unit 2 except as noted includes response to IE Circular 79-02 Affidavit and 80HNEIDER, F. M. Public Service Electric & Gas Co. of New Jersey 80/06/27 35pp
- 8007070110 Submits plan to replace long-term contractor personnel w/committed staff of licensee employees.in accordance w/Item 7 4(4) of Took Spets & commitment to NRC Licensee expects to start plan on 800801 Schedule & graph and LIBRIZILF P Public Service Electric & Oas Co. of New Jersey 80/06/27 4pp
- B007070285 Forwards responses to full power license requirements identified at NRC 800619 meeting MITTLR L Public Service Electric % Gas Co of New Jersey 80/06/27 14pp
- ---B007070289 Tech Spec Pages 3/4 7-5 through 7-7 for auxiliary feedwater sys & auxiliary feed storage tank Related documentation and Public Service Flortric & Gas Cu of New Jersey B0/04/27
- 8007030161 Forwards addl info in response to NRC 800618 request re auxiliary feedwater sys Auxiliary feedwater sys for both units are identical in design including equipment & automatic initiation logic MITTLER! Public Service kloctric & Gas Co. of New Jersey 80/07/01 13pp
- B007030227 Forwards add1 info re full power license requirements identified at 800619 meeting Info supplements 800627 ltr MITTL, R. L. Public Service Electric & Gas Co. of New Jersey 80/07/01 65pp
- B007030244 Forwards response to B00620 request for Addl info re TM1 Lessons Learned requirements MITTLER L Public Service Electric & Gas Co of New Jersey B0/07/02 App
- 8007140628 Forwards test procedure SUP 80 l.App G. "Feedwater Hammer Test." for review & approva) Procedure provided per requirement in Tech Spec 9 3 MITTLER L. Public Service Electric & Gas Co. of New Jersey 80/97/07 ip

- --8007160633 Test procedure SUP 80 1 'Foodwater Hammer Test "

 * Public Service Electric & Gay Co of New Jersey 80/07/07
- B007210365 Forwards revised page: to B00102 lessons loanned implementation submittal Addl info inflects discussion at 800408 meeting w/NRC LIBRIZZIFF Public Service Flectric & Gas Co. of New Jersey 80/07/08 54pp
- 8007230816 histosses required performance of augmonted low power startup test program Near-term QL applicants should perform tests similar to tests proposed by TVA prior to exceeding 5% of rated thermal power EISENHUT.b C Division of Licencing 80/07/11 2pp
- 800724008) Requests that encl list of inforce possibility that longterm water source for auxiliary feedwater by may contain salt, be provided to complete full-power requirements SCHMENCER.A Licensing Branch 3 80/07/11 Spp
- 8007280006 Notification of 800723 meeting w/otils in Bethesda, MD to discuss matters or TMI~2 dated requirements DROMFRICK, A U Licensing Branch 1 KERRIGAN, J D , STABLE, C R Licensing Branch 2 80/07/16 App
- 8007280442 Requests that 8003)7 request to amend License DPR-70 apply to License DPR-75 Requests authorization to lower individual cell min voltages on 125 & 28 volt batteries to 2 13 volts Battery manufacturer 800627 ltr % fee encl LIBRIZZI.F P Public Service Clectric & Gas Co of New Jorsey 80/07/16 4pp
- --8007280443 Proposed change to Tech Spec Pages 3/4 8-11 & 14 resurveillance requirements for electrical power sys at Unit 2

 * Public Service Electric & Gas Co of New Jersey 80/07/16
 3pg
- 8007210219 Forwards proposed conceptual design for automatic switchover of ECCS from injection phase to recirculation phase of operation Final design package will be submitted for NRC review & approval by 800901
 MITTL.R L. Public Service Electric & Gas Co. of New Jersey 80/07/17 23pp
- 8007210389 Submits addl info re containment sump model test program Objective is to confirm existing sump design or if improvements are indicated to develop suitable mode Check testing of final design will be performed MITTL.R L. Public Service Electric & Gas Co. of New Jorsey 80/97/17 3pp
- 8007310460 Forwards request for add1 info re effects of debris on containment emergency sump performance under post-LOCA conditions Concerns related to containment sump hydraulic performance have been acceptably resolved BCHMENCER.A Licensing Branch 3 80/07/21 7pp
- 0 Inspection reports: IE Bulletins & correspondence
- 8007020133 Forwards IE info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/05/28 ip
- 8007010300 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 80/00/29 1p
- 8007210610 Forwards IE Info Notice 60-26. "Evaluation of Contractor Oh Programs " No written response required (PIER.D H Region 1. Philadelphia. Office of the Director 80/66/10 ip
- 8007160362 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required GRIER, B K Region to Philadelphia, Affice of the Director 80/86/11 ip
- B007170570 Responds to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls "Describes instances discovered in fire protection, Feedwater & steam line isolations Design changes scheduled BCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 80/06/13 6pp

- 8007170642 Responds to IE Bulletin 80-10, "Contamination of Nonracloactive Sys & Resulting Potential for Unmonitored, Uncontrolled Rulease of Radioactivity to Environ " Requirements 1 & 2 were completed on 800612 SCHNEIDER: F W Public Service Electric & Gas Co of New Jersey 80/06/13 10
- 8007020693 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power " Written response required ORIER, D. H. Region 1, Philadelphia, Office of the Director 80/06/19 ip
- B007020519 Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER B H Region 1, Philadelphia, Office of the Director B0/06/20 1p
- 8007160736 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Porsonnel " No written response required ORIERS H Region 1, Philadelphia, Office of the Director 80/06/24 19
- 8007210274 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER.D H Region 1, Philadelphia, Office of the Director 80/06/25 ip
- B007310052 Forwards IE Insp Repts 50-272/80-ii & 50-311/80-07 on 800501-31 No noncompliance noted BRUNNER, E J Region i, Philadelphia, Reactor Operations Nuclear Support Branch B0/06/26 2pp
- --B0073i0055 IE lasp Repts 50-272/80-ii & 50-3ii/80-07 on 80030i-3i No noncompliance noted Major areas inspected tours of facility, lag & record reviews, reviews of licensee events & operational safety verification NORRHHOLM.L J. Hill.N M Region i, Philadelphia, Office of the Director KERIMIG.R R Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/23 17pp
- 8007230173 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8087210608 Forwards response to IE Bulletin 80-08 Both units have containment boundary butt welds All welds fabricated to Section VIII of ASME boiler & pressure vessel code 8CHMEIDER, FW Public Service Electric & Gas Co of New Jersey 80/06/30 4pp
- 8007210268 Forwards final response to confirmatory orders issued on 800404 in reply to 16 Bulletin 79-27 re lass of Nonclass 16 instrumentation & control power sys bus during operation Response submitted per util 800326 ltr W/offidavit & memo. 8CHNEIDERF W Public Service Electric & Gas Co of New Jersey 80/07/01 37pp
- B007210528 Returns documents re Item 10 of IE Insp Rept 50-311/78-51 on possible sensitization of safety injection pump piping W/o encl GARLBON.R.T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/07/01 1p
- 9 Reportable occurrences, LERs & related correspondence
- 8007170437 Forwards LER 80-004/03L-0 LIBR1221.F P Public Service Electric & Gas Co of New Jarsey 80/07/10 3pp
- --8007170448 LER 80-004/03L-0 on 800610 during routine surveillance, both safety injection pumps were made operable at less than 312 ff in RCB Caused by lack of procedure to limit max number of operable safety pumps
 MURPHY.M J Public Service Electric & Qas Co of New Jersey,
 80/07/10 ip

- ~-8007280632 LER 80-005/03L-0 on 800622 during preparation for heatup.
 position indication & mechanical operation of pressurizer
 averpressure protection valves gave false indication &
 failed to resuet Possibly caused by foreign math in valve
 MURPHY.M J Public Service Clectric & Gas Co of New Jersey
 80/07/21 10
- 8007270694 Forwards LER 80-006/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 80/07/23 1p
- ~-8007290711 LER 80-006/03L-0 on 800625, residual heat removal pump was discovered to have been previously improperly assembled Caused by either personnel error or procedural inadequacy Pump inspected, repaired & reassembled MURPHY, M J Public Service Electric & Gas Co of New Jersey 80/07/23 2pp

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

BOO7230093 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mgt personnel at facility EISENHUT, D O Division of Licensing BO/07/11 2pp

Q. Adjudicatory correspondence

- B007020243 Forwards 800619 ltr to Friends of the Earth forwarding Director's decision DD-80-22 in response to 791024 petition DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/19 3pp
- 9007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 potition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENHUT, D 0 Division of Licensing 80/06/25 89pp
- E007110002 Order granting extension until 900722 for Commission to elect to review decision on enforcement action request. DD-90-22 MCYLE.J C Office of the Secretary of the Commission 80/07/08
- 8007150827 Forwards licensee 800711 proposed findings of fact & conclusions of law in form of initial derision Assumes ASLB approval to parties' 800530 proposed transcript corrections per 800609 stipulation Certificate of Svc encl BAXTER.T A Shaw, Pittman, Potts & Trowbridge 80/07/11 4p
- --9007150555 Proposed findings of fact & conclusions of law in form of initial decision Long-term mods w/undertaken add1 changes provide reasonable assurance that plant will respond safely to feedwater transients Exceptions must be filed in 10 days BAXTER.T A TRAVIESO-DIAZ Sacramento Municipal Utility District MAXTER.T A Shaw, Pittman, Potts & Troubridge 80/07/11 252pp
- BOO7310389 Requests filing date be revised from BOO801 to 04 to allow opportunity to make changes in findings LANPHER, C California, State of LANPHER, C Hill Christopher & Phillips BO/07/25 2pp

H General correspondence

- 8007290236 Responds to 790405 ltr re nuclear power Nuclear plants generated 13% of electrical energy in 1979 Rancho Saco can resume operation when mods are completed Excerpts re GA. radiobiological hazards of PD & environ effects encl DENTON,H R Office of Nuclear Reactor Regulation. Director 80/06/27 26pp
- --B007290253 Requests info re percentage of electricity produced by nuclear plants, whether Runcho Soco will be closed down & cases where fuel rods or valves were found faulty UPTON: R T Affiliation Unknown 79/04/05 3pp
- 8007300370 Advises of change of address from 520 Capital Mall, Buite 700 to 455 Capital Mall, Buite 265 Related correspondence HURSH.G Sacramento Municipal Utility District 80/07/02 ip

- P Operating license stage documents % correspondence
- 8007240208 Forwards B&W licensers' responses to 790907 request for review of Schedule for installing tafety-grade anticipatory reactor trip for loss of Spedwater & turbine trip Review should be completed by 791115 CAPRARA THE BUILDING & Orders 74/10/24 Ip
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT. D C Division of Licensing 80/06/11 62pp
- B007010575 Discusses licensee consideration of increased onsite radwaste storage Requests reviews for onsite storage additions in monthly operating repts Draft licensing position to onsite storage safety considerations end REID,R W Operating Reactors Branch 4 80/06/52 imp
- B007100203 Application to amend License DPR-54 by incorporating proposed Amend &B for Tech Specs based on fire protection BTB Forwards proposed Amend &B to Tech Specs Bections 3 14 & 4 18 MATTIMSE, J. J. Sacramento Municipal Utility District 80/06/19 256
- --8007100206 Propused Amend AH to Tech Specs, Sections 3 14 & 4 18, based on fire protection sts * Sacramento Hunicipal Utility District 80/06/19 11pp
- BOO7170667 Forwards questions to fuel assembly holddown spring failures first observed at Davis-Besse 1 & under investigation by B&W Results of holddown spring insps at facility as well as safety significance required authin 60 days NOVAK.T M Assistant Director for Operating Reactors 80/07/01
- 8007210004 forwards questions to fuel assembly holddown spring inspt & safety significance of operating w/broken springs in core Requests response within 60 days
 NOVAK, T.M. Assistant Director for Operating Reactors 80/0//01
 Ann
- BOO7240244 Requests response to encl questions re fuel assembly holddown spring failures NRC is interested in results of holddown spring insps at facility 8 safety significance of operating w/broken springs in core NOVAN, T.M. Assistant Director for Operating Reactors 80/07/01 Spec
- BOO7250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMT-2 Lessons Learned Category A items encl for guidance EISENHUT.D @ Division of Lirensing 80/0//02 69pp
- 8007080183 Responds to NRC 780125 ltm requesting all PWR licensees to evaluate LOCA loads BAM-1597 & BAM-1621 submitted 800214 & 0701/respectively, demonstrate ability of facility to maintain core coolebility in event of asymmetric LOCA MATTIMOE, J J Sacramento Numicipal Utility District 80/07/03 1
- B007230432 Application for Amend 67 to License DPR-54 clarifying Tech Specs re-plant organization chart & surveillance requirements when reactor is critical MATTIMOE J. J. Sarramento Municipal Utality District 80/07/09 200
- ==8007230443 Revised Tuch Specs Page 4-1 & Figure 6 b-2 clarifying plant organization chart & surveillance requirements when reactor is critical
 - * Sacramento Municipal Utility District 80/07/09 2pp
- B007230651 Provides info re new off titles positions to assignments of personnel resulting from 800428 reorganization of Dfc of Nuclear Reactor Regulation
 NOVAK.T M Assistant Director for Operating Reactors 80/07/10
 3pp
- 8007240123 Bubmitt addi info to complete response to 791119 request for addi info re containment purge & vent sys MALBRIDGE.W C Batramento Municipal Utility District BO/07/11
- BOO7290622 Requests rorrespondence between NRC & util re seismic investigation Requests meeting w/util in CA to review progress of studies & present expertise in reviewing seismic data

 DAVIS.J F California. State of BO/07/11)p

- 8007250345 Forwards licensee 800721 ltm re safety grade anticipatory reactor trip Svc list end!

 BAXIER, T A Shaw, Flitman, Potts & Frowbridge 80/07/22 2pp
- ---8007250,348 Notifies that equipment being added to leactor protection sys cabinets is of sufficient mass as to require new seismit analysis of rabinets Analysis requires approx 20 wks linfo will be provided in time to allow for final design approval MALBRIDGE, W.C. Sacramento Hunicipal Utility District 80/07/21 ip
- G. Inspection reports, IE Bulletins & correspondence
- 8007240198 Responds to IE Builetin 80-03, "Loss of Charcoal from Type II.Tuo-inch. Thay Adsorber Cells" Const of trays does not ubilize rivets for securing perforated screen to casing Screen is spot welded at approx one-inch intervals MATTIMUE. J Sacramento Emiscipal Utility District 80/03/06 2pp
- B007250370 Forwards response to IE Bulletin /9-27, "Loss of Non-Class IE Instrumentation: A Control Power Sys Bus During Operation." Describes power upsit events on NMI/ICS Buffer cord installations will be checked MALBRIDGE.N (Sacriments Numbered Utility District 80/03/12 18pp
- 8007180541 Responds to IE Bulletin 79-17. Revision 1. "Pipe Cracks in Stagnant Borated Water Sys at PWR Plants "Three recordable Indications noted in two welds determined to be geometric reflections caused by weld not configuration MATTIMOE. J. J. Sacramento Municipal Utility District 80/03/28 i
- 8007240192 Forwards response to IE Bulletin 80-04. "Analysis of FWR Main Steam Line Break M/Continued Feedwater Addition " Plant sys & structures designed to respond to double ended guillotine steam line break inside containment MATTINORF, J. J. Sacramento Municipal Utility District 80/05/06 200
- 8007020240 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required ENGELHEN.E H Region 5. San Francisco. Difice of the Director BO/09/28 ip
- BOO7250676 Responds to JE Bulletin BO-12, "Decay Heat Removal Bys Operability " Operational assessment indicates similar occurrence not likely at facility because of differences in decay heat removal syst & ECCS
 HATTIMOE. J J Saciemento Municipal Utility District 80/06/04
- 9007290847 Responds to 1E Dulletin 80-05 Sys that could be valved directly to primary sys water reviewed RCS drain tankilash tank & makeup tank may be subjected to vacuum conditions. Other tanks can withstand conditions who inward buckling MATTIMDE J J Sacramento Municipal Utility District 80/06/09 Rpp
- 8007220250 Forwards IE Info Notice 80-25, "Evaluation of Contractor GA Programs" No written response required ENGELKEN,R H Region 9. San Francisco. Office of the Director 80/06/10 1p
- 8007310477 Responds to IE Bulletin 80~05 Review of electrical drawings made to insure safety-related equipment remains in emergency mode upon reset Testing completed for all equipment that can be tested while plant is in operation WALBRIDGE.H C Shoramento Nunscipal Utility District 80/06/10 2pp
- 8007030014 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Motification Sys (ENS) W/Loss of Offsite Power " Written response required ENGLIKEN.R H Region 5. San Francisco. Office of the Director 80/06/18 1p
- B007240407 Forwards IE Insp Rept 50-312/80-17 on 800501-30 No noncompliance noted GREMS, J.L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/05/18 2pp
- --B007240420 IF insp Rept 50-312/B0-17 on 800901-30 No noncompliance noted Major areas inspected followup on items of noncompliance k headquarters requests CANTER.H L. Region 5. San Francisco. Office of the Director FAULKENBERRY.O. Region 5. San Francisco. Reactor Operations Nuclear Bupport Branch. 80/06/17. Spp.

- B007020480 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ENGELMEN.R H Region 5, San Francisco, Office of the Director B0706/20 16
- 8007180295 Forwards I€ Circuler 80~14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/24 ip
- 8007230399 Forwards IE Bulletin 80-14, "Potential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Gueput Codes" Written response required IE Circular 80-16 also and No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/27 1p
- 8007310294 Forwards IE Insp Rept 50-312/80-13 on 800505-09 No noncompliance noted CREWS,J L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/02 2pp
- --8007310301 IE Insp Rept 80-312/80-13 on 800309-09 No noncompliance noted Major areas inspected document control program, onsite review committee operations reactor operator requalification program & 16 Bulletin 79-27 followup ZMETZIO, G B Region D, San Francisco, Office of the Director FAULKENBERRY, B Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/02 7pp
- R Periodic operating reports & related correspondence
- 6007150588 Forwards monthly operating rept for June 1980 RDPRIGUEZ.R J Sacramento Municipal Utility District 80/07/07 1p
- --B007150592 Monthly operating rept for June 1980 COLOMBORR W Sacramento Municipal Utility District 80/07/07
- S Reportable occurrences, LERs & related correspondence
- 8004240286 PND-V-80-17 senior resident inspector informed that spacer grads on five Cycle 3 fuel assemblies damaged during fuel movements Cause of damage due to contact between spacer grids w/bowed fuel & adjacent assemblies during refueling FAULKENEERY, B Region 5, San Francisco, Office of the Director 80/03/11 2pp
- 8007080270 Forwards LER 80-030/03L-0
 MATTIMOE. J J Sacramento Municipal Utility District 80/06/26
- --B007080277 LER 80-030/03L-0 on B00623, while performing I-108C, reactor protection sys channel C test, overpower bistable voltage setting was found drifted out of spec Caused by malfonctioning of semiconductor voltage regulator COLUMBO, R W Sacramento Municipal Utility District 80/06/26
- B007230165 PNO-V-80-057 on 800709, licensee reported that two direct radiation monitors on perimeter fance of restricted area showed results above reporting level of Teth Speec High values may be result of waste storage FISH: Region 5, San Francisco. Office of the Director B0/07/10 ip
- 8007230154 PNS-V-80-006 on 800603, employee denied access to vital areas because of personnel-related matter On 800604 employee again denied access to site because of behavior SCHUSTER.M D . NORDERHAUS, L R Region 5, San Francisco, Office of the Darector 80/07/11 2pp
- B0073104t0 Forwards LER 80-031/03L-0 MATTIMOE, J J Sacramento Municipal Utility District 80/07/17 2pp
- --BOO7310416 LER 60-031/03L-0 on 800703, during review of IE Bulletin 79~14 work, found atress analysis for nonconforming pipe support was overlooked Caused by design documentation & const drawings not conforming to seismic analysis COLOMBO, R W Sacramento Municipal Utility District 80/07/16

- DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT I
- F Security, medical, emergency & fire protection plans
- 8007010369 Forwards "Rept on Wall Penetration Fire Stops" & "Fire Test Criteria for Penetration Boals in Concrete Floors & Walls " TRIMBLE.D C Arkansas Power & Light Co 80/06/19 ip
- ---8007010373 "Rept on Wall Penetration Fire Stops"
 * Underwriters Laboratory 80/04/30 145pp
- --8007010380 "Fire Test Criteria for Penetration Seals in Concrete Floors & Walls " Four illegible drawings encl
 -- Arkansas Power & Light Co 80/06/04 Spp
- 8007070148 Documents NRC telcon & approval of temporary exemption to existing emergency plan. Section 4 3 i i-C requiring decontamination shower facilities in omergency control ctr TRIMBLE.D C Arkansas Power & Light Co 80/06/27 2pp
- 8007170281 Forwards Amend 60 to emergency plan TRIHBLE.D.C Arkansas Power & Light Co 80/07/11 1p
- --8907170285 Amend 60 to emergency plan consisting of Figure 3.instial notification in event of accident

 # Arkenses Power & Light Co 80/07/31 lp
- 8007230073 Notification of 800722 meeting w/AR Power & Light Co in Hethesda: MD to review proposed early warning sys VIBSING.0 8 Operating Reactors Branch 4 80/07/16 2pp
- Q Adjudicatory correspondence
- BOO7310243 Forwards Commission BOO327 memorandum & order containing decisions on UCS 780302 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENHUT.D 0 Division of Licensing BO/06/25 89pp
- H General correspondence
- BO07110449 Requests response to encl R Lacewell ltr re plans to increase facility spent fuel storage pand site BETHANE.E House of Rep 80/04/30 2pp
- 8007010024 Submits updated info re admittance of NRC personnel to facility Requests that permanent nonemployee picture badges & site orientation be provided W/o encl
 SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/16
- BOO7070020 Requests that util provide IE headquarters w/microfiche copy of listed P&IDs
 MADSEN. C L Region 4, Dallas, Office of the Director 60/06/16
- BO07250070 Responds to encl B00504 ltr to President Carter re nuclear energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl
 DENTON: H R Office of Nuclear Reactor Regulation. Director 80/06/27 22pp
- BOO7100148 Requests removal of TB Conner from list of correspondence recipients & addition of N Reynolds Licensee has changed legal representation TRIMBLE.D C. Arkansas Power & Light Co 80/07/03 ip
- BD07310331 Responds to 800625 ltr re B00510 event at Unit 1 Forwards LER 80-015/01-0 & IE Insp Repts 30-313/80-07 & 50-368/80-07 Discusses treatment of spilled water & radioactive content of water W/o encl BEYFRIT.K V Region 4, Dallas, Office of the Director 80/07/15
- P Operating license stage documents & correspondence
- BOO6240237 Responds to technical assistance request for proposed Tech Spec changes for B&W operating plants Forwards requirements for add1 info IBRAEL.B.L. TMI-2 Bulletins & Orders 79/08/29 13pp

- 900724020B Forwards B&W licensers' responses to 79090/ request for review of schedule for installing safety-grade anticipatory reactor trip for loss of fredwater & turbine trip Review should be completed by 791115

 CAPRAIR A TMI-2 Bulletine & Orders 79/10/24 1p
- B007020210 Responds to NRC B00401 request for info re potential failure of once through steam generator auxiliary feedwater sizeve/collar welds Probable cause & failure mode of weld cracking not yet determined

 TRIMBLE.D C Arkonsas Power & Light Co B0/06/05 3pp
- 8007230099 Requests submitted of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT. B G Division of Licensing 60/06/il 62pp
- 8007010356 Forwards abnormal transports operating guidelines program outputs Draft guidelines scheduled for submittal in Aug 1980 Copy numbers assigned to event tree drawings Requests controlled copies be withheld (ref 100FR2 790)
 TRIMBLE.D C Ariansas Power & Light Co 80/06/16 ip
- 8007030371 Forwards request for add1 info no waste gas sys NDVAK.T M Assistant Director for Operating Reactors 80/06/23 3ao
- 8007150489 Application to amend Licenses DPR-5t & NPF-6, deleting requirement for testing reactor bldg smoke detectors while reactors remain critical Suggested changes to Tech Spec pages & Class III fee encl CAVANAUGH.W Arkansas Power & Light Co 80/05/26 2pp
- ---8007150494 Buggested changes to Tech Spec Pages 3/4 3-43 & 110p re fire detection instrumentation * Arkansas Power & Light Co 80/06/26 2pp
- 8007170319 Summary of 800612 meeting w/otils in Bethesda, MD re interim reliability evaluation program DLBHANL N Operating Reactors Branch 1 80/06/30 3pp
- 8007290186 "Electrical Instrumentation & Control Aspects of Low Temp Overpressure Mitigation Sys. AR Nuclear Dna. Unit 1 " WEBER, D A E000 Idaho, Inc FIN A-6256 8007250186 80/06/30 16pp
- 8007070253 Responds to NRC 800410 ltr requesting that all licensees amend Tech Bpecs so that definition of term "operable" would be consistent w/NRC STS Revision will require at least 90 days
 TRIMBLE.D C Arkansas Power & Light Co 80/07/01 2pp
- 8007090287 Forwards small break w/failed power operated relief valve analysis in response to ltem 2D of NRC 790821 ltr Analysis demonstrates that present operator guidelines are adequate to mitigate consequences of valve failure

 TRIMBLE D C Arkansas Power & Light Co 80/07/01 14pp
- 8007180429 Informs that util is interested in participating in NRC research grogram for interim reliability evaluation program, discussed in B00612 meeting TRIMBLE.D C Arkansas Power & Light Co 80/07/01 3pp
- 800721000A Forwards questions to fuel assembly holddown spring ansps & safety significance of operating w/btoken springs in core Requests response within 60 days
 NOVAK.T M Assistant Director for Operating Reactors 80/07/01
- B007210587 Forwards questions re fuel assembly holddown spring failures NRC is interested in knowing results of imags to safety significance of operating w/broken springs in core Requests response within 60 days of itr receipt NOVAKIT M. Assistant Director for Operating Reactors. B0/07/01 300
- 800725000) Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PAR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encli for guidance EISENHUT.D G Division of Licensing 80/07/02 69pp
- 8007210023 Requests info re 800624 loss of offsite power transient at Unit 1 Info uncludes description of switchyard operation, process computer printouts of alarms during transient & strip charts for primary & secondary sys
 NOVAK.T M Assistant Director for Operating Reactors 80/07/08
 2pp

- 8007150394 Advises of continued compliance U/current regulations re hydrogen production from clad-water reaction after installation of RCS vents per NUREG-0578 Procedural guidelines will be submitted 810101 TRIMBLE,D C Arkansas Power & Light Co 80/07/10 2pp
- 8007280350 Advises of personnel changes resulting from reorganization of Ofc of Nuclear Reactor Regulation NOVAK,T N Assistant Director for Licensing 80/07/10 2pp
- 8007290603 Resterates util position re need for addl instrumentation for detection of inadequate core cooling No addl instrumentation is needed Util 800131 ftr summarized position No responses received to date TRIMBLE.D C Arkansas Power & Light Co 80/07/11 2pp
- 8007240120 Discusses NRC 800616 ltr se reactor vessel surveillance program Questions necessity for immediate change of Tech Spec 4 2 8 Cuerent procedure is adequate to maintain reactor vessel mati surveillance program TRIMBLE.D C Arkansas Power & Light Co 80/07/14 ip
- 8007290040 Responds to memo re fuel adjustment clause provision that would permit passing 90% of cost of replacement power on to ratepayers NRC would present any info at formal hearing No investigation planned VDEGELI, R J Office of the Executive Legal Director 80/07/18
- Q Inspection reports, IE Bulletins & correspondence
- 8007020194 Responds to IE Builetin 80-04, "Analysis of PWR Main Steam Line Break w/Continuod Feedwater Addition" Sufficient time would exist for operator to isolate affected oncethrough steam generator in event of overpressurization TRIMSLE.D C Arkansas Power & Light Co 80/05/27 Spp
- B007020269 Forwards IE info Notice 80-22. "Breakdowns in Contamination Control Programs " No written response required BEYFRIT.K V Region 4. Dallos. Office of the Director 80/05/28
- 8007210342 Forwards IE Circular 80-13, "Grid Strap Damuge in Hestinghouse Fuel Assemblies "No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/28 1p
- 8007010040 Forwards IE Info Notice 80-23, "Loss of Suction to Emergoncy Feedwater Pumps " No written response rodusted SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/29 ip
- B007220177 Forwards IE Insp Repts 50-313/80-07 & 50-368/80-07 on B00422-0521 & notice of violation MADSEN.6 L. Region 4. Dallas, Reactor Construction & Engineering Support Branch B0/06/05 2pp
- --8007220185 Notice of violation from insp on 800422-0521
 * Region 4. Dallas, Office of the Director 60/06/04 1;
- --8007220197 IE Insp Repts 50-313/80-0/ & 50-368/80-07 on 800422-0321
 Noncompliance noted incomplete written procedures,
 insufficient adherence to procedures & poor housekeeping
 measures
 WESTERMANIT F., JOHNSON W.D., CALLAHAN L.J. Region 4, Dallas,
 Dffice of the Director 80/06/04 IBpp
- 8007020201 Responds to IE Dulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCB) Holdup Tanks "Only Unit 1 reactor coolant make-up tank & Unit 2 vol control tank could contain appreciable amounts of hydrogen TRIMBLE.D C Arkansas Power & Light Co 80/06/10 5pp
- 8007220094 Forwards IE Info Notice 80-26. "Evaluation of Contractor QA Programs " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/06/10
- 884 BOY 16 V Region 4. Dallas, Office of the Director 80/06/11
- 8007300349 Forwards IC Insp Repts 50-313/80-09 & 50-368/80-09 on 800827-30 & notice of violation MADERN, 6 L Region 4. Dallas, Reactor Operations Nuclear Support Branck 80/06/12 2pp

- ---B007300353 Notice of violation from insp on 800527-30 + Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/04/11 1p
- --B007300354 IE Insp Repts 50-313/B0-09 & 50-368/B0-09 on B00527-30 Noncompliance noted failure to adhere to procedures for handling temporary mods to jumpers & bypasses YANDELLIL A , WEBTERMAN, T F Region 4. Dallas, Office of the Director 80/06/11 Spp
- 8007070172 Ack receipt of 800529 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-313/80-06 & 50-368/80-06 MAGEEN-O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 80/06/17 2p
- 8007230744 Forwards IE Investigation Repts 50-313/80-08 & 50-368/80-08 on 800510-12 No noncompliance noted BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 80/06/20 2pp
- --B007230257 IE Investigation Repts 90-313/80-08 & 50-348/80-08 on 800510-12 No noncompliance noted Major areas inspected radiological conditions & environ impact associated w/main coolant pump seal failure BROWN, 0 D Region 4, Dallas, Fuel Facility & Materials Safety Branth WILDORN, L Region 4, Dallas, Office of the Director 80/06/18 5pp
- 8007240031 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response regulated SEYFRIT,K V Region 4, Dallas, Office of the Director 80/06/20
- BOO7220495 Notifies that memo.re procedure for retention & performance of safety evaluation & notice of violation for deficiency in IE Insp Rept 50-313/80-05, has been forwarded to Licensing Bection personnel involved in design change package reviews TRIMBLE, D C Arkansas Power & Light Co 80/07/11 1p
- BC07300320 Ack receipt of B00627 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-313/80~07 & 50-368/80-07 MADSEN.9 L Region 4, Dallas, Reactor Operations Nuclear Support Dranch 80/07/22 lp
- -~8007300325 Responds to NRC 800605 ltr re violation noted in IE Inap Repts 50-313/80-07 & 80-366/80-07 Corrective actions Junction box cover replaced & door on end closed TRIMULE.D C Arkansas Power & Light Co 80/06/27 2pp
- B007300329 Ack receipt of B00702 ltr informing NRC of steps taken to correct violation noted in 1E Insp Repts 50-313/80-09 & 50-368/80-09 MADSENG L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/07/22 ip
- --H007300335 Responds to NRC 800612 ltr re violation noted in IE Insp Repts 50-313/80~09 & 50-368/80-09 Corrective actions entries in Jumper & bypass log were cleared Completed pages of log were forwarded to files TRIMBLE.D C Arkansas Power & Light Co 80/07/02 2pp.
- R. Periodic operating reports & related correspondence
- 8007210450 Rept on radinactive effluent release.Jan-June 1978, s Arkensas Power & Light Co 78/03/31 10pp
- 8007010470 Forwards corrected page for monthly operating rept for May 1980
 TRIMSLE, D.C. Arkensas Power & Light Co. 80/06/25 ip.
- --8007010480 Corrected page to monthly operating rept for May 1980 BRAMLETT.L 8 Arkansas Power & Light Co 80/06/13 ip
- B007100143 Forwards results of impingement monitoring at intake during May 1980, submitted in accordance w/ETS 4 1.2 a(2) Set of computer cards encl
 TRIMILE, D.C. Arkansas Power & Light Co. 80/06/30 14pp
- 8007210420 Forwards monthly operating rept for June 1980 TRIMBLE, D C Arkansas Power & Light Co 80/07/15 Ip
- --8007210432 Monthly operating rept for June 1980 BRANLETT, L 8 Arkansas Power & Light Co 80/07/15. 5pp.

- S Reportable occurrences. LERs & related correspondence
- 8007140621 PND-IV-80-023 on 800624, all offsite power to both units was lost when two lines were tripped by dispatcher Third line was out of syc for maint HUNNICUTT, D. Region 4, Dallas, Office of the Director 80/06/25 200
- 8007280346 ROs 50-313/80-22 & 50-368/80-042 on 800624, events occurred on 500 kv power lines which resulted in loss of all 500 kv power lines & reactor trips of both units Cause not stated Both units stable Followup rept will be transmitted O'HANLON, J P Arkansas Power & Light Co 80/06/26 2pp
- 8007150641 Forwards LER 80-022/01T-0
 TRIMBLE, D.C. Arkansas Power & Light Co. 80/07/07 1p
- --B007150650 LER 80-022/017-0 on 800624. w/Mayflower 500 kV transmission line out of svc & unit operating at full power, 500 kV Mabelvale line tripped Caused by ground fault & overload Lock-out relays were reset & 500 kV bus re-energized SHIVELY, C N Arkansas Power & Light Co 80/07/07 5pp
- **B007150593** Forwards LER 80-016/03L-0
 TRIMBLE.D C Arkansas Power & Light Co B0/07/10 lp
- --9007150603 LER 80-016/03L-0 on 800611 during hydrogen purge sys surveillance testing proper sys flow could not be obtained Caused by rust scale lodged in check valves Check valves cleaned & reassembled BRANLETT.L S Arkansas Power & Light Co 80/07/10 1p
- 8007150530 Forwards updated LER 80-011/03L-3 TRIMBLE,D C Arkansas Power & Light Co 80/07/11 1p
- 8007310334 Discusses 800706 routine surveillance test on emergency steam driven feedwater pump during which steam leak developed Requests that one of five failed studs be delivered to Parameters Inc for analyses HADEEN, & L. Region 4, Dallas, Roactor Operations Nuclear Support Branch 80/07/15 2pp
- 8007210406 Forwards LER 80-020/03L-0 TRIMBLE.D C Arkansas Power & Light Co 80/07/16 1p
- --BOD7210413 LER 80-020/03L-0 on 800621, during makeup pump test, rod index limits exceeded Caused by operator inadvertently opening inlet to standby demineralizer All operators reviewed accurrence BRAMLETT, L S Arkansas Power & Light Co 80/07/16 ip
- BOO7240176 Responds to NRC 800609 request for into re reactor coolant pump seal Failure analysis in progress diversize drawing awailable in Central Filos only TRIMBLE.D C Arkansas Power & Light Co 80/07/16 37pp
- B007180312 Forwards LER 80-021/03L-0
 TRIMBLE, D C Arkansas Power & Light Co 80/07/17 ip
- --8007180318 LER 80-021/03L-0 on 800624, during reactor trip, steam driven emergency feedwater pump automatically started per design but tripped on overspeed Cause undetermined Pump proved operable before returning to power BRAMLETT.L S Arkansas Power & Light Co 80/07/17 1p
- BOO724014B Forwards updated LER 80-015/01X-1
 TRIMBLE, D C Arkansas Power & Light Co 80/07/17 ip
- --B007240150 Updated LER 80-015/01X-1 on B00310, during steady state power operation, step increase in RCB leakage observed Caused by seal failure All four RCB seal cartridges replaced or rebuilt
 SHIVRLY, C N Arkansas Power & Light Co 80/07/17 App
- BOO7290331 PNO-TV-80-024 on 800716, plant was shut down due to primary to secondary leak Max radioactivity detected was below Tech Epec limit
 JOHNSON, N D . HUNNICUTT, D M . MADSEN, G Region 4, Dallas, Office of the Director. BO/07/17 1p
- 8007280504 Forwards LER 80-019/03L-0 TRIMBLE, D C Arkansas Power & Light Co 80/07/18 ip

- --8007280511 LER 80-019/03L-0 on 800619 duting fire sys testifire pump PAA could not be stopped from control room Caused by low fire sys pressure resulting from leaking fire sys relief valve Valve adjusted BRAMLETT.L S Arkansas Powrt % Light Co 80/07/18 ip
- DOCKET 50-315 DONALD C FOOK NUCLEAR POWER PLANT, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8007210080 Forwards request for additinfolis safeguards contingency plan Format should be revised to conform w/format for Reg Ouide 5 54 W/o encl NOVAK.T M Assistant Director for Operating Reactors 80/06/30
- Adjudicatory correspondence
- 8007310243 Forwards Commission 800327 memorandum % order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum % order UCS 77104 petition sought action re-fire protection for electrical cables EISENHUF, D.C. Division of Licensing 80706/25 89pp
- H General correspondence
- 8007020177 Requests consideration of having Atomic Energy Council of Taiwan visit facility on 800807-08 Council interested in observing waste mgt activities Cooperation will be major contribution to NRC exchange arrangement LAFLEUR, J D. Assistant Diructor for International Cooperation 80/05/13 3pp
- P Operating license stage documents h correspondence
- 8007110580 Advises that Class I & III licensing fees, requested in 800409 ltr re review of request to employ divers to cut studs in spent pool fuel, have not been reveived Requests that fees be submitted within 15 days of receipt of ltr MILLER.W O License Fee Management Branch 80/06/02 1p
- 8007010546 Notification of 800779-3; onsite meeting w/util to discuss inservice testing program for pumps & valves MINERS Operating Reactors Branch 1 80706/09 26pp
- B007230099 Requests submittal of proposed tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution entil for guidance EISENHUT.D G Division of Licensing 80/06/11 62pp
- 8007020591 Forwards response to request concerning add1 info on responses to NRC short-term requirements for avrillary feedwater sys BOLAN, J.E. Indiana & Michigan Flectric Co. 80/06/26 App
- 8007110555 Requests determination whother weldments in safety-related tanks fabricated by Graver Tank meet design specs Reply requested within 20 days
 MOSELEY,N C Division of Reactor Operations Inspections 80/06/27
- 8007250801 Requests submittal of application for amend to license consisting of Tech Spec changes % license conditions PWR Model Tech Specs & Model Incense conditions for TM1-2 Lessons Learned Category A items encl for guidance EISENHUT.D 0 Division of Licensing 80/07/02 69pp
- 8007280064 Informs that requested exemption from Class 1 for requirement for 800324 submittal for approval to employ divers in spent fuel pool is granted Refund will be forwarded when processed MILLER.W D License Fee Management Branch 80/07/11 ip
- B007250493 Responds to NRC B006F7 for reputantial welding deficiencies in tanks fabricated by Gravir Tank & Mfg Co Facilities have four Graver tanks Insp confirmed that full penetration weld prists & weldingree Myrequirements of design drawings HUNTER, R S Indiana & Michigan Electric Co 80/07/18 3pp
- O Inspection reports: lE Bulletins & correspondence
- 8007220075 Forwards IE lasp Repts 50-315/60-01 & 50-316/80-01 on 800114-18,21-25,27-31.0211-12.0303 (5 & 0415 & notice of vibilation HEISHMAN.R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/03/05 2pp

- ~~8007220100 Notice of violation from insp on 800114-18.21-25.29-31. 0211-12.0303-05 & 0415 # Region 3. Chicago, Office of the Director 90/05/02 2pp
- --8007220112 IE Insp Repts 50-315/80-01 & 50-316/80-01 on 800114-18, 21-25,29-31,0211-12,0303-05 & 0415 Noncompliance noted deficiencies to equipment classification, housekeeping, surveillance & infractions is audit findings & program STREETER, J.F., JACKIN, I.N. Region 3. Chicago, Office of the Director HEISHMAN, R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/02 21pp
- B007020043 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/28
- 8007210353 Forwards IE Circular 80-13, "Grad Strap Damage in Westinghouse Fiel Assemblies " No written response required KEPPLER, J G Region 3, Chicago, Uffice of the Director Bi 80/05/28
- 8007010068 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedbater Pumps" No written response required MEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29
- 8007170945 Forwards Waste Parkaging Insp Rept 15000027/80-46 on 800229 2027/0045 Formands waste Markaging inspired 1900002/200446 on 80 & notice of violation DAVIS.A D. Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/06/10 2pp
- 80/04/2B 1a
- --8007170556 Waste Packaging Insp Rept 18000027/80-46 on 800229 Roncompliance noted no placard on shipment boxes BECKER, T. JHDMASR D. Region 5. Sao Francisco, Office of the Director RODK.H E. Region 5. Sao Francisco, Fuel Facility & Materials Safety Dranch 80/04/88 App
- 8007220148 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 80/06/10
- 6007140158 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11
- 8007110465 Forwards response to IE Bulletin 60-05. "Vacuum Condition Resulting in Demage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Design review made of all sys containing low pressure tanks or holdup tanks Protective measures adequate DGLANJE Indiana & Michigan Electric Co 80/06/13 App
- 6007030206 Responds to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies " ITT General Controls Series AH-90 & NH-90 hydramotor actuators are not used in safety-related sys or components Indiana & Michigan Electric Co 80/06/16 1p
- 8007020245 Responds to tE Buttetin 80-12. "Decay Heat Removal Sys Operabolity " Incident described in IE Info Notice 80-20 is not likely to occur at plant, based on reasons listed RHR sys redundancy & diversity were reviewed DOLAN.JF Indiana & Michigan Electric Co 80/06/17 Spp
- 8007030042 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Lors of Offsite Power " Written response required KEPPLER.J G Region J. Chicago. Office of the Director, 80/06/18
- 8007020568 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3. Chirago, Office of the Director 80/06/20
- 8007180324 Responds to 800318 for forwarding IE Sulletin 80-06 Energization of reactor trip breakers closing coils is strictly manual operation Equipment does not change emergency mode because of trip signal reset HUNTER.R S. Indiana & Michigan Electric Co. 80/06/20 Spp

- #007170426 Forwards It Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 89s & Resultant Internal Contamination of Personnel" No wiltten response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/24
- 8007230305 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmittors W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER.J G Region J. Chicago, Office of the Director 80/06/2
- 80071603B4 Remits fee to cover NRC insps for period Mar 1979-Mar 1980 per NRC 800603 invoice HALONEY, G.P. Indiana & Michigan Electric Co. 80/07/09 Ip
- 8007150696 Submits reply to IE Bulletin 60-10 re contamination of nonradioactive sys & potential for releases Adequate monitoring is performed routinely on sys to preclude release problems No further action required MALQNEY, & P Indiana & Michigan Electric Co 80/07/10 2pp
- 8007220080 Bubmits reply to IE Bulletin 80-10 re contamination of nonradioactive sys & potential for releases Adequate menitoring is performed redtinely on sys to preclude release problems No further action required MALONEY, & P Indiana & Michigan Electric Co 80/07/10 2pp
- G007230267 Forwards reply to IE Bulletin GO-ii re masonry wall design Structural integraty evaluation of masonry walls is underway Full evaluation will be completed MALONEY.G P Indiana & Michigan Electric Co G0/07/10 Sipp
- B007300252 Corrects typographical error made in transcribing data to Table I of response to IE Bulletin 80-05 re damage to chemical vol control sys tanks Amended Table I enci HUNTER, R 8 Indiana & Michigan Electric Co 80/07/15 2pp
- 8007310278 Ack receipt of 800530 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-315/80-04 & 50-316/80-03 HEISHMANR F Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/07/25 ip
- --8007310284 Forwards response to NRC 800502 itr re violations noted in IE Insp Repts 50-315/80-04 & 50-316/80-03 Corrective actions procedure changed to probibit use of hoses for making up water to spent fuel pit & valves locked closed DDLAN.JE Indiana & Michigan Electric Co 80/05/30 3pp
- R Periodic operating reports & related correspondence
- 8007150542 Forwards monthly operating rept for June 1980 SHALLER, D. V. Indiana & Michigan Power Co. 80/07/09
- --8007[50547 Monthly operating rept for June 1980 OILLETT, W. T. Indiana & Michigan Power Co. B.
- S Reportable occurrences. LERs & related correspondence
- B007280510 RD during Apr 1980, estimated weight of fish impinged was substantially above level normally experienced Preliminary estimated weights for May indicate above normal fish impingeneent level final onviron impact rept pending SHALLER, D V Indiana & Michigan Electric Co 80/07/03 [p
- B007150586 Forwards LERs B0-012/03L-0 & 80-013/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/07/08
- -8007150597 LER 80~012/03L~O on 800609, two check valves, R-154 & R-157, discovered utilized as containment isolation valves Valvered utilized as containment isolation valves Valvere not included in type C leak test prior to Nov 1978
 Type C leak test performed & check volves added RischLing, J L. Indiana & Michigan Electric Co. 80/07/C
- --8007150623 LER 80-013/03L-0 on 800616, transmitter for steam generator level loop 4 (BLP 142) found to be out of spec low Cause attributed to instrument drift Transmitter, Barton Model 764 recellor & returned to syc DELONG, S.D. Indiana & Michigan Electric Co. 80/07/08
- 8007150696 Forwards LER 80~014/03L-0 8HALLER, D.V. Indiana & Michigan Electric Co. 80/07/10 lp.

--8007150703 LER 80-014/03L-0 on 800612 during divider barrier seal inspiseveral areas of seal found cracked & split Cause of seal failure unknown Design change request submitted to investigate alternate maths
BROWN.M S Indiana & Michigan Electric Co 80/07/10 ip

V Operator Examinations

8007310399 Forwards revised licensed operator requalification program, per NRC 800328 request Only major change is in central manipulation section now requiring annual simulator training as well as increased manipulation requirements

GHALLER, D V Indiana & Michigan Electric Co 80/07/25 12pp

BOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8007210088 Forwards request for addl info re safeguards contingency plan Format should be revised to conform w/format for Reg Quide 9 54 H/o encl NOVAK.T M Assistant Director for Operating Reactors 80/06/30

Q Adjudicatory correspondence

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
EISENHUT.D C Division of Licensing 80/06/25 89pp

H General correspondence

8007020177 Requests consideration of having Atomic Energy Council of Taiwan visit facility on 800807-08 Council interested in observing woste mgt activities Cooperation will be major contribution to NRC oxchange arrangement LAFLEUR. J D Assistant Director for International Cooperation 80/05/13 3no

8005270181 Responds to 800429 request for info re M LeMiere inquiry about amount of nuclear waste disposed in State of MI Spent fuel from four operating MI reactors stored onsite NRC evaluated status of waste mgt in 1977 W/related FR excerpts DIRCKB.H J Office of the Executive Director for Operations 80/06/09 10pp

P Operating license stage documents & correspondence

8007110580 Advises that Class I & III licensing fees, requested in 800409 ltr re review of request to employ divers to cut studs in spent pool feel, have not been revelved Requests that fees be submitted within 15 days of receipt of ltr MILLER, W O License Fee Management Branch 80/06/02 ip

8007010346 Notification of 800729-31 unnits meeting w/util to discuss inservice testing program for pumps & valves MINER 8 Operating Reactors Branch 1 80/06/09 26pp

BOO7230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance
EISENHUT,D Q Division of Licensing 80/06/11 62pp

8007170423 Forwards Amend 21 to License DPR-74, safety evaluation & notice of issuance & availability
VARGA-8 A Operating Reactors Branch 1 80/06/18 2pp

--B007170427 Amend R1 to License DPR-74,adding motor driven auxiliary feedwater pump to each unit to separate shared operation of motor driven auxiliary feedwater pumpn VARGA,8 A Operating Reactors Branch 1 80/06/18 5pp

--B007170431 Safety evaluation supporting Amend 21 to License DPR-74 * Operating Reactors Branch 1 B0/06/18 App

--8007170434 Notice of issuance & availability of Amend 21 to License DR-74 VAROA: B A Operating Reactors Brunch 1 80/06/18 2pp

BOO7020591 Forwards response to request concerning add1 info on responses to NRC short-term requirements for auxiliary feedwater sys

DOLAN, J E Indians & Michigan Electric Co 80/06/26 4pp

8007110555 Requires determination whether weldments in safety-related tanks fabricated by Graver fank meet design sport Reply requested within 20 days MISELEV.N.C. Division of Reactor Operations Inspections 80/06/27 30m

8007250001 Requests submittal of application for amend to license consisting of Tach Spec changes & license conditions PWR Madel Tach Specs & Midel License conditions for TMI-2 Lessons Learned (ategory A itoms ent for guidance EISENHUT, D.G. Division of Licensing 80007/02 69pp

8007280054 Informs that requested exemption from Class 1 fee requirement for 800324 submittal for approval to employ divers in spent fuel pool is granted Refund will be forwarded when processed MILLER.W O License Fee Management Granch 80/07/11 ip

8007250493 Responds to NRC 8006-7 ltm is potential uelding deficiencies in tanks fabricated by Graver lank & Mfg Co Facilities have four Graver tanks inspicunfirmed that full penetration weld exists & welds agree w/requirments of design drawings HUNTER.R B Indiana & Michigan Electric Co 80/07/18 3pp

G Inspection reports, (E Bulletin: & correspondence

B007220095 Forwards IE Insp Repts 50-315/80-01 & 50-316/80-01 on B00114-18,21-25,29-31,02(1)2 0303-05 % 0415 & nutice of violation
HEISHMAN.R F Region 3. Chicago, Reactur Construction & Engineering Support Branch B0/05/05 2pp

--890/220100 Notice of violation from insp on 800114-18,21-25,29-31. 0211-12,0303-05 & 0415 * Region 3. (hicago, Office of the Director 80/05/02 2pp

---B007220112 IE Insp Repts 50--T15/B0-01 & 50-316/B0-01 on B00114-18, 21-25,29-31,0211-12,0303-05 & 0415 Noncompliance noted deficiencies re equipment classification; housekeeping, surveillance & infractions re and it findings & program STREETER, J. F., JACKIW, I. N. Region 3. Chicago, Uffice of the Director MEISHMAN, F. Region 3. Chicago, Reactor Construction & Engineering Support Branch B0705/02 21pp

8007020043 Forwards IE Info Notice 80 22, "Breakdowns In Contamination Control Programs" No written response required MRPPLER.J G Region % Chicago, Office of the Director 80/05/28 16

B007210353 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required MEPPLER.J G Region J. Chicago. Office of the Director B0/05/28 in

8007010060 Forwards IE Info Notice 80-23. "Loss of Soction to Emergency Feedwater Pumps." No written response required KEPPLCR. J G. Region 3. Chicago, Office of the Director 80/05/29

BD07170545 Forwards Waste Packaging Insp Rept 15000027/80-46 on 800229 & natice of violation
DAVIS:A Region 3, Chicago, Fuel Pacility & Materials Safety
Branch B0/06/10 2pp

--B007170556 Waste Portaging Insp Rept 19000027/80 44 on B00229
Nontompliance noted no placerd on shipment boxes
DECKER, J. IHWAS, R.D. Region 5 San Francisco, Diffice of the
Director BUOK, H.C. Region 5. San Francisco, Fuel Facility &
Materials Safety Branch 80/04/28 App

800722014B Forwards IF Info Notice 80-74, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J G Rugson 3, Chicago, Office of the Director 80/06/10

8007160158 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Study " No specific action of response requested MEPPLER,) G Region 3, Chicago, Office of the Director 80/06/11 in

8007)10465 Forwards response to IE Bulletin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Lunkrol 54s (CV/S)
Holdup Tanks "Design review made of all sys containing low pressure tanks or Boldup tanks Protoctive measures adequate DDLAN, J.E. Indiana & Michigan Riectric Co. 80/06/13 App

- 8007030206 Responds to IE Builetin 80-09, "Hydramotor Actuator Deficiencies" ITT General Controls Series AH-90 & NH-90 hydramotor actuators are not used in safety-related sys or components.

 Onland J. F. Indiana & Michigan Electric Co. 80/06/16. 1p
- 8007020245 Responds to IE Builetin 80 id "Decay Heat Removal Sys Operability " Incident described in IE Info Notice 80-20 is not likely to occur at plant bosed on reasons listed 8HR sys redundancy "c diversity were reviewed DDLAN, J E Indiana", Michigan Electric Co 80/06/17 8pp
- 8007030042 Forwards JE Bulletin 80-15. "Possible toss of Emergency Notification Sys (EMS) W/Loss of Offsite Power " Written response required KEPPLER.J G Region 3. Chicago: Offsice of the Director 80/04/18
- B00702056B Forwards IF Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J. G. Region D. Chicago, Office of the Director 80/05/20
- 8007180324 Responds to 800318 itr forwarding IE Bulletin 80-06 Energization of reactor trip breakers closing coils is strictly manual operation Equipment does not change emergency mode because of trip signal reset HUNTER.R'S Indiana & Michigan Electric Co 80/06/20 8pp
- B007170426 Forwards IE Carcular 80-14, "Radicactive Contamination of Plant Demineralized Mater Syc 2, Resultant Internal Contamination of Personnel "No written response required MEPPLER. J G Region 3. Chicago, Office of the Director B0/06/24
- 8007230305 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required MEPPLER.J G Region 3. Chicago, Office of the Birector 80/06/27
- B007160364 Remits fee to cover NRC insps for period Mar 1979-Mar 1980 per NRC 800603 invoice MALGNEY,G P Indiana & Michigan Flectric Co 80/07/09 1p
- 8007250016 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Facilities contain flued head design for containment ponetration connection as illustrated in figure NE-IISO-1 of ASMC 8 & P V code MALONEY, G P Indiana & Michigan Electric Co HO/07/09 2pp
- 8007220080 Submits reply to 1E Bulletin 80-10 re contamination of nonradinactive sys & potential for releases Adequate monitoring is performed routinely on sys to preclude release problems No further action required MALONEY.0 P. Indiana & Michigan Electric Co. 00/07/10 2pp
- B007230269 Forwards reply to 1E Dulletin 80-11 re masonry wall design Structuret integrity evaluation of masonry walls is underway Full evaluation will be completed MALONEY.G F Indiana & Michigan Electric Co. 80/07/10 3ipp
- 8007300252 Corrects typographical error made in transcribing data to Table 1 of response to 15 Bulletin 80-05 re damage to chemical vol control sys tanks Amended Table I encl HUNTER.8 9 Indiana & Michigan Flector Co 80/07/15 2pp
- 8007310278 Ack receipt of 800930 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/80-04 t 50-315/80-03 HEISHMAN R F Region 3, Chicago, Roactor Operations Nuclear Support Branch 60/07/25 ip
- --8007310284 Forwards response to NRC 800502 its se violations noted in IE Insp Repts 90-319/80-04 & 50-516/80-03 (prective actions procedure changed to prohibit use of hoses for making up water to spont fuel pit & valves locked closed DOLANGUE Indiana & Michigan Electric Co. 80/05/30. 3pp
- R Periodic operating reports & seleted correspondence
- 8007150555 Forwards monthly operating rept for June 1980 SHALLER: D V - Indiana & Michigan Power Co - 80707709 - Ip
- --8007190561 Monthly operating rept for June 1980 GILLETT:W T - Indiana & Michigan Power Co - 80/07/03 - App

- S Reportable occurrences. LERs & related correspondence
- 8007090289 Forwards LER 80-025/03L-0 SHALLER D V Indiana & Michigan Electric Co 80/07/02 ip
- --B007070292 LER B0-025/03L-O on B00603 during normal operations, engineered safety feature vent fan HV-AES-1 circuit braaker tripped rendering ventilation sys inoperable Caused by failure of wiring insulation in connection boxes GROWN M S Indiana & Michigan Electric Co 80/07/02 ip
- 8007280510 RQ during Apr 1980, estimated weight of fish impinged was substantially above level normally experienced Proliminary estimated weights for May indicate above normal fish impingement level Final environ impact rept pending SHALLER,D V Indiana & Michigan Electric Ca 80/07/03 ip
- 8007150684 Forwards LER 80-026/03L-0 SHALLER, D V Indiana & Michigan Electric Co 80/07/08 ip
- --8007150495 LER 80-024/03L-O on B00409, check valves R-194 & R-157, utilized as containment isolation valves, found omitted from Type C leak test Valve R-196 installed backwards Caused by omission in procedure Valve R-156 reinstalled & tested RISCHLING, J L Indiana & Michigan Electric Co 80/07/08 2pp
- B007210537 Forwards LER B0-027/03L-0 SHALLER D V Indiana & Michigan Electric Co 80/07/14 ip
- --8007210841 LER 80-027/03L-0 on 800613, during piping modehand shutoff valve in suction line to motor driven auxiliary feed pump 1 was closed to stop leakage interfering w/welding Pump was inoperable until completion of welding LEASE.R S Indiana & Michigan Electric Co 80/07/14 ip
- V Operator Examinations
- 8007310379 Forwards revised licensed operator requalification program.

 per NRC 800328 request Only major change is in control
 manipulation section now requiring annual simulator training
 as well as increased manipulation requirements

 BHALLER.D V Indiana & Michigan Electric Co 80/07/25 12pp
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8007210416 Submits Dept of Public Safety comments on NRC review & safety evaluation of fire protection & life safety Licensee should be required to provide fire doors & automatic suppression sys 4s necessary RIDDLE.M W Calvert County, MD 80/07/14 2pp
- F Security, medical, emergency & fire protection plans
- B007160245 Forwards response to NRC comments re security training & qualification plan Response & revised plan withheld (ref 100FR2 790)

 EVANS,V R Baltimore Oas & Electric Co B0/07/14 ip
- B007220590 Informs that scheduled date for conducting additable tray penetration fire tests will be B00730 at Southwest Lab. Ban Antonio.TX Tests are designed to verify addit design of cable tray fire stops NRC has apportunity to witness fire tests LUNDVALL.A E Baltimore Gas & Electric Co 80/07/16 ip
- 8007280481 Submits correction to util 800402 submittal of facility modified amended security plan. Revision & Encls 1 & 3 incorrectly reflected Revision 5 Encls should be changed to Revision & EVANS, V R Baltimore Oas & Electric Co 80/07/22 ip
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 position for reconsideration of 780413 memorandum & order UCB 771104 position sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp

H Ceneral correspondence

- 8007250251 Responds to 800515 ltr re JA May questions about facility 800327 radioactive gas leakage Leak caused by poor gasket seal on Unit 2 degassifier relief valve W/safety evaluation of util post-TMI changes DIRCKS, W J Office of the Executive Director for Operations 80/07/07 2pp
- -~B007250264 Requests response to encl JA May ltr requesting info τe recent incident at facility
 SPELLMAN, 0 N House of Rep B0/05/15 ip
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7906220186 Summarizes responses to IC Bulletin 79-06B Operating manuals are being scrutinized Operational personnel are being trained Radioactive gases & liquids transfer lines are interlocked w/containment isolation %/or radiation signals TAM.P Division of Site Safety & Environmental Analysis 79/05/08
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Hodel Tech Specs which would provide acceptable resolution encl for guidance
 EISENHUT, D Q Division of Licensing 80/06/11 6Rpp
- E007010568 Notification of 800715 meeting w/util in Bethesda,MD to discuss Chalk Point 500 kV transmission line LB.C.Y Operating Reactors Branch 3 (Pre 800428) 80/06/16 1p
- 8007170066 Notification of cancellation of 800715 meeting w/util in Bethesda MD, to discuss agenda re 500 kV transmission line LI.C Y Operating Reactors Branch 3 80/06/16 1p
- --8007170071 Confirms telcon re tancellation of 800715 meeting w/util in Bethesda,MD re 500 kV transmission line FAUST.R: Plant Systems Branch (Pre 791030) 80/07/02 ip
- 9007020469 Summary of 800605 meeting w/util in Bothesda, MD re offsite Operating Reactors Branch 3 80/06/19 4pp
- B007020349 Discusses 790729 application to amend Tech Specs.including proposed revisions to organization chart & safety committee membership Forwards supplemental changes to current organization & safety committee membership OLSON.R C Baltimore Gas & Electric Co 80/06/24 ip
- --B007020354 Supplementary organizational changes to fech Specs for administrative controls # Baltimore Gas & Electric Co 80/06/24 Spp
- 8007010329 Discusses concerns w/interim reliability evaluation program as outlined at 800612 meeting w/NRC Includes problems w/scheduling, methodology, timing, licensee participation & regulatory ratcheting Suggests licensee methodology input LUNDVALL. A E Baltimora Oas & Electric Co 80/06/25 4pp
- B007090324 Forwards proprietary & nonproprietary revisions of C-E margin improvement repts justifying recovery of margin ishkerently available in design Affidavits encl Proprietary rept withheld (ref 10CFR2 790)
 LUNDVALL, A E Baltimore Gas & Electric Co B0/06/26 2pp
- ~-8007090332 "Bass Use of Incore Detector Sys to Monitor DNB-LCO on Calvert Cliffs Units 1 & 2," nonproprietary version * C-E Power Systems CEN-119(B)-NP 79/11/30 21pp
- ~-8007090341 "CEAW Method of Analyzing Sequential Control Element Assembly Group Withdrawal Event for Analog Protected Sys." monproprietary version. * C-E Power Bystems CEN-121(B)-NP 79/11/30 125pp
- ~~B007090345 "FIESTA One Dimensional. Two Group Space Time Kinetics Code for Calculating PNR Scram Reactivities " * C-E Power Systems CEN-133(B) 79/11/30 75pp
- -- 8007090352 "Statistical Combination of Uncertainties. Part 1," monproprietary version # C-E Power Systems CEN-124(B)-NP PT1 79/12/31 65pp

- --8007090361 "Statistical Combination of Uncertainties, Part 2." nonproprietary version

 * Combustion Engineering, Inc. UEN-124(B)-NP PT2 - 80/01/31 . 79pp
- --8007090368 "Statistical Combination of Uncertainties, Part 3." # C-E Power Systems CEN-124(B)-NP P13 80/03/31 85pp
- B007020434 Forwards proposed fech Spet, Changes 1 & 2 to amend OLs Change i clarifies definition of "operable" allows substitution of installed 69 to offsite power source in event of transformer failure Fice encl
 LUNDVALL, A E Baltimore Oat 7. Electric Co. 80/06/27 2pp
- --- 8007020442 Proposed Tech Sper Change 1 Clarifies definition of "operable" * Baltimore Oas & Electric Co - 80/06/27 - App
- --B007020448 Proposed Tech Spec Change 2 Allows substitution of installed 67 kV offsite power source, instead of 500 kV offsite power sources, in event of transformer failure * Baltimore Gas & Electric Co B0/06/27 Jpp
- B007020557 Forwards "RCS Asymmetric Loads Evaluation Program," final rept in response to NRC 7B0125 lti to PWR licensees to asymmetric LOCA loads C-E affidavit for withholding encl Proprietary version of App A withhold (ref 10CFR2 790) LUNDVALL.A E C-E Operating Plants Owners Group B0/06/20 2pp
- --8007020574 "RCS Asymmetric Loads Evaluation Program," final rept, Vo) I # C-E Power Systoms 80/06/30 20pp
- --8007020581 "RCS Asymmetric Loads Evaluation Program," final rept.
 - C-E Power Systems B0/06/30 300pp
- --8007020588 "ACS Asymmetric Loads Evaluation Program." final rept. Vol
 - * C-E Pawer Systems 80/06/30 300pp
- --8007020593 "RCS Asymmetric Loads Evaluation Program," final rest.Ass A. numerical results, evaluation of C-E fuel Nonproprietary version App 0.Palisades fuel analysis.enrl * C-E Power Systems 80/06/30 PApp
- --B007020600 "RCS Asymmetric Loads Evaluation Program," App E.ECCS peripheral assemblies Final rept

 # C-E Power Systems B0/06/30 9pp
- 8007170319 Summary of B00612 meeting w/utils in Bethesda.MD re interim reliability evaluation program DLSHAN.L N Operating Reactors Branch 1 80/06/30 3pp
- 8007250001 Requests *ubmittal of application for amond to license consisting of Tech Spec Lhanges & license conditions FMR Model Tech Specs & Model License conditions for TMI-2 Lessons Learned Category & stems entl for guidance EISENHUT,D & Division of Licensing 80/07/02 69pp
- B007180076 Notifies that C-E //1803 request for route approval to cover spont fuel shipmonts to BMI is subj to license fee Review of request was completed on B00226 MILLERIW O License Fee Management Branch 80/07/03 ip
- B007090291 Submits add) info requested by NRC /90721 ltr re 770703 request for amend to Licenses DPR-53 & DPR-69 concerning spent fuel poul mod Structural & liner plate analysis encl LUNDVALLA & Baltimore Gas & Electric Co 80/07/07 21pp
- 8007230176 Summary of 800618 meeting w/otil.No.lear Energy Svc & Bechtel Power Corp re spent fuel pool and structure design LLC Y Deerating Reactors Branch J 80/07/08 Spp
- 80072403B/) Advises of NRC reorganization on 80042B which resulted in number of changes in ofe titles positions & issignments of personnel Also submits info for NETR NDVAK, T.M. Assistant Director for Operating Reartors 80/07/08
- 8007210069 Notafication of 800/17 meeting w/util in Bethesda,MD to discuss 18-manth ruel cyrles for facility Util & C-E will present previou of documentation to be used in facility Cycle 5 reload analysis Operating Reactors Dranch 3 80/07/09 2pp

- 8007170354 Application for amend to Licenses DPR-59 & DPR-A9, revising Paragraph 4 5 1 b h adding Paragraph 4 5 1 f to Tech Specs re ECCS surveillance requirements
 LUNDVALL A F Baltimore Gas h Ejectric Co 80/07/14 3pp
- --BOO7170353 Proposed Tech Specs re ECCS surveillance requirements, revising Paragraph 4 5 1 b & adding Paragraph 4 5 1 f adding Paragraph 4 5 1 f BOLD BOO71714 ip
- O Inspection reports, JE Bulletins & correspondence
- B007090356 Forwards update to util B00417 response to IE Bulletin 79-018. 'Environ Gualification of Class IE Equipment " Evaluation of available qualification data for components expected to be completed by 800430 LUNDVALL.A E Baltimore Gas & Electric Co 80/05/27 200pp
- --B007090359 Forwards corrected response to IE Bulletin 79-01B. "Environ Qualification of Class IE Equipment." replacing incomplete version forwarded by AE Lundvall 800303 ltr ASH.R F Baltinorg Gas & Electric Co 80/03/05 200pp
- 8007020120 Forwards IE Info Notice 80-22, "Greatdowns In Contamination Control Programs" No written response required ORIER, 8 H Region 1. Philadelphia. Office of the Director 80/05/28 1p
- 8007010279 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required GRIER, U.H. Hegson 1, Phyladetphia. Office of the Director 8D/05/29 1p
- BOO7170111 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Dawage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Continued operation. even during interim period of nitrogen sys setpoint mod. Justified for listed reasons LUNDVALLA E Daltimore Gas & Electric Co 80/06/04 2pp
- BOO7210241 Forwards IE Insp Repts 50-317/80-05 & 50-318/80-05 on BOO407-30 No noncompliance noted BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 60/06/04 2pp
- --BOO7210247 IE Insp Repts 50-317/BO-05 & 50-318/BO-05 on BO0407-30 No noncompliance noted Major areas inspected control room & accessible portions of auxiliary turbine svc & intake bldgs, radiation protection & physical security ARCHITIEL.R Region i. Philadelphia. Office of the Director MCCABE.E C Region !, Philadelphia. Reactor Operations Nuclear Support Branch 80/05/30 20pp
- B007220278 Forwards 1E Insp Rept 50-317/80-07 on 800429-0501 No noncompliance noted CARLSON,R I Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/04 2pp
- --8007220285 [E Insp Rept 50-317/80-07 on 800429-0523 No noncompliance noted Major areas inspected pipe support activities performed to comply w/fc Buljetin 79-02 & radiation safety procedures DURR. J P. SERABIAN. J A. Region 1. Philadelphia. Office of the Director TRIPP.L E. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/23 13pp
- 8007210554 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required CRIER,8 H Region 1, Philadelphia, Office of the Director 80/06/10 ip
- 8007160337 Forwards 1E Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/86/11 1n
- 9007170576 Responds to IE Bulletin RO-06, "Engangered Safety Feature (ESF) Reset Controls " Test to verify that actual installed controls are consistent w/schematics reviewed will be completed during Fall 1980 & early 1981 refueling outages LURDVALL A E. Saltimore Gas & Electric Co. 80/06/17 4pp
- 8007020614 Forwards IE Bulletin 80-15. "Prossible Loss of Emergency Notification Sys (ENS) M/Loss of Offsite Power " Written response required GRIER.B H Region 1. Philadelphia. Offsice of the Director 80/06/18 Ip

- BOD718060D Responds to IE Bulletin 80-10 Review of nonradioactive systemic tuded valve lineups, leaking valves & points of contact between radioactive & nonradioactive phases Addisurveillance of nonradioactive systemillance of nonradioactive systemic be implemented LUNDVALL-A E Baltimore Gas & Electric Co 80/06/19 1p
- 8007020483 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80408-200 18
- BOD7160ABS Forwards IE Circular 80~14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ORIER, B H Region 1. Philadelphia, Office of the Director BO/06/24 19
- 8007210171 Forwards IE Info Notice 80-24. "Low Level Radwasto Burial Criteria" No written response required GRIER, BH Region 1, Philadelphia, Office of the Director 80/06/25 tp
- B007280096 Forwards IE Bulletin 80-16, "Potential Misapplication of Roseagunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B M. Region J. Philadelphia. Office of the Director 80/06/27 20p
- 8007250662 Corrects 800604 response to IE Bulletin 80-05 Operating experience has shown that even if reactor coolant drain tank is pumped to max flow rate tank pressure remains greater than atmospheric pressure
 LUNDVALL.A E Baltimore 8as & Electric Co 80/06/27 2pp
- E007100228 Submits info re fluid head design penetration connections or other designs w/containment boundary butt welds between sleeve & process piping.per IE Bulletin 80-08
 LUNDVALL.A E Baltimore Gas & Electric Co 80/07/03 Spp
- B007210044 Submits status of extensive survey program initiated in response to IE Bulletin B0-ii Accounts for half of masorry walls requiring insp Remaining items will be covered in final rept to be submitted after completion of surveys LUNDVALL, A E Baltimore Gas & Electric Co B0/07/03 32pp.
- B007210574 Responds to IE Bulibtin 80-08 Each unit contains five penetrations w/flued head design Penetrations N-stamped per requirements of Paragraph N-153 of ASME Code, Section III, Bummer 1979
 LUNDVALL, A E Pacific Gas & Electric Co 80/07/03 4pp
- B007250014 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Facilities contain flured head design for containment penetration connection as illustrated in figure NE-1120-1 of ASME 8 & P V code MALONEY, Q P Indiana & Michigan Electric Co 80/07/09 Qpp
- R Periodic operating reports & related correspondence
- HERSON, 8 D Baltimore Gas & Electric Co HO/06/13 19
- --8007010390 Monthly operating rept for May 1980 HERSON,S D Baltimore Oas & Electric Co 80/06/12 Spp.
- --8007010392 Monthly operating rept for May 1980
 MERSON, S D Baltimore Gas & Electric Co 80/06/12 9pp
- 8007220351 Forwards monthly operating repts for June 1980 MERSON S D Baltimore Gas & Electric Co 80/07/18 1p.
- ---9007220355 Menthly operating repts for June 1780
 HERSON.S D Baltzmore Qas & Electric Co 80/07/15 18pp
- S Reportable occurrences. LERs & related correspondence
- 8007280451 Forwards LER 80-031/03L-0 RUSSELL, L B Baltimore Gas & Electric Co 80/07/18 ip
- --8007280453 LER 80-031/03L-0 on 800625, high oil temp alarm received on 4 kV unit svc transformer Caused by failure of cooling fans due to blown fuse in control circuit fan did not transfer to backup power supply Cause unknown fuse replaced DAVIS.8 M , DAVFR, E R Baltimore Gas & Electric Co 80/07/10 ip

- 8007280664 Forwards LER 80-029/03L-0 RUSSELL.L B Baltimore Cas & Electric Co 80/07/18 1p
- 8007280676 LER 80-029/03L-0 on 800616, control room air conditioning Unit il placed out of svc to repair broken damper linkages Apparent cause was excessive wear due to inadequate linkage lubrication Periodic lubrication instituted DAVIS.S N . HUSESY.D E Baltimore Gas & Electric Co 80/07/18
- DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2 E NAC Bafety Evaluation Report (SER), supple & correspondence
- BOO7R10416 Submits Dept of Public Safety comments on NRC review & safety evaluation of fire protection & life safety Licensee should be required to provide fire doors & automatic suppression sys as necessary RIDDLE, M.W. Celvert County, MD BO/07/14 2pp
- F Security, medical, emergency & fire protection plans
- 8007:60245 Forwards response to NRC comments re security training & qualification plan Response & revised plan withheld (ref iOCFR2 790) Baltimore Gas & Electric Co 80/07/14 lp
- BOO7220590 Informs that scheduled date for conducting addl cable tray penstration fire tests will be 800730 at Southwest Lab, San Antonio. TX Tests are designed to verify addl design of cable tray fire stops NRC has opportunity to witness fire tests LUNDVALL. A E Baltimore Oss & Electric Co 80/07/16 ip.
- BOO7280481 Submits correction to util 800402 submittal of facility modified amended security plan. Revision 6 Encls 1 & 3 incorrectly reflected Revision 5 Encls should be changed to Revision 6 EVANS.V R Baltimore Gas & Electric Co 80/07/22 ip
- Q Adjudicatory correspondence
- BO07310249 Forwards Commission B00827 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D.O Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007230251 Responds to 800515 ltr re JA May questions about facility 800327 radioactive gas leakage Leak caused by poor gasket seal on Unit 2 degassifier relief valve W/safety evaluation of util post-TMI changes DIRCKS,W J Office of the Executive Director for Operations 80/07/07 2pp
- ---B007250264 Requests response to encl JA May ltr requesting info re recent incident at facility SPELLHAN.G N House of Rep 80/05/15 ip
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution ently for guidance EISENHUT, D O Davision of Licensing 80/06/11 62pp
- 8007010568 Notification of 800715 meeting w/util in Bethesda.MD to discuss Chalk Point 500 kV transmission line LI.C Y Operating Reactors Branch 3 (Pre 800428) 80/06/16 1p.
- 8007170066 Notification of cancellation of 800715 meeting w/util in Batheada MD. to discuss agenda re 500 kV transmission line LI.C.Y. Operating Reactors Branch 3 80/06/16 ip
- --8007170071 Confirms telcon re cancellation of B00715 meeting w/util in Bethesda.MD re 500 kV transmission line FAUST.R. Plant Systems Branch (Pre 791030), 80/07/02 ip

1

8007020449 Summary of 800605 meeting w/util in Bethesda. MD re offsite power Sources. LI,C Y Operating Reactors Branch 3 80/06/18 App

- 8007020349 Discusses 790729 application to amend Tech Specs, including proposed revisions to organization chart & safety tommittee membership Forwards supplemental changes to current organization & safety committee membership QLSON.R C Baltimore Gas & Electric Co BO/06/24 Ip
- --8007020354 Supplementary organizational changes to Tech Specs for administrative controls * Baltimore Gas & Electric Co 80/06/24 Bpp
- 8007090324 Forwards proprietary & nonproprietary revisions of C-E margin improvement repts justifying recovery of margin inherently available in design Affidavits end Proprietary rept withheld (ref 10CFRZ 790)

 LUNDVALL.A E Baltimore Gas & Electric Co BO/06/26 2pp
- ~-8007094332 "Bass Use of Incore Detector Sys to Monitor DNB-LCO on Calvert Cliffs Units & 2," nonproprietary version * C-E Power Systems CEN-119(B)-NP 79/11/30 21pp
- --8007070341 "CEAW Hethod of Analyzing Sequential Control Element Assembly Group WithGrawal Event for Analog Protected Sys," nanproprietary version * C-E Power Systems CEN-121(B)-NP 79/11/30 125pp
- --8007090346 "FIFBTA One Dimensional, Two Group Space Time Kinetics Code for Calculating PNR Scram Reactivities " * C~E Power Systems CEN-133(B) 79/11/30 75pp
- --8007090382 "Statistical Combination of Uncertainties, Part 1," monproprietary version

 * C~E Power Systems CEN-124(1)-NP PT1 79/12/31 65pp
- --8007090361 "Statistical Combination of Uncertainties, Part 2," monproprietary version * Combustion Engineering, Time CEN-124(B)-NP PT2 80/01/31 75ap
- --800709036B "Statistical Combination of Uncertainties.Part 3," nonproprietary version * C-E Power Systems CEM-124(B)-NP PT3 80/03/31 85pp
- B007020434 Forwards proposed Toch Spec.Changes 1 & 2 to amend OLs Change 1 clarifies definition of "operable" allows substitution of installed 49 kV offsite power source in event of transformer failure Fee and LUNDVALL.A E Beltimore Gas & Electric Co B0/06/27 2pp
- --8007020442 Proposed Tech Spec Change ; Clarifies definition of "operable" * Baltimore Cas & Electric Co 80/06/27 App
- --8007020448 Proposed Tech Spec Change 2 Allows substitution of installed A9 kV offsite power sources, in see ad 66 500 kV offsite power sources, in event of transformer failure

 * Baltimore Oas & Electric Co 80706/27 3pp
- 8007020557 Forwards "RCS Asymmetric Loads Evaluation Program," final rept in response to NRC 7801P5 itr to PMR licenses re asymmetric LUCA loads C-F affidavit for withholding encl Proprietary version of App A withheld tref 10CFR 790) LUNDVALL.A E C-E Operating Plants Owners Group 80/06/30 2pp
- --B007020574 "RCS Asymmetric Loads Evaluation Program," Pinal rept, Vol : * C-E Power Systems 80/06/30 90pp
- --B0070205B1 "RCS Asymmetric Loads Evaluation Program," final rept. C-E Power Systems 80/06/30 300pp
- --B007020588 "RCS Asymmetric loads Evaluation Program," final rept. Vol * C-E Power Systems 80/05/30 300pp
- ---8007020593 "RCS Asymmetric Loads Evaluation Program," final rept.App A. numerical results, evaluation of C-E fuel linn proprietory
 Version App B.Palisades fuel annalysis-enrl
 # C-E Power Systems 80/06/30 28pp
- ---8007020600 "RCS Asymmetric Loads Evaluation Program." App E.ECCS analysis approach w/reduced area toolant channels in peripheral ascemblies Final rept # C-E Power Bystems 80/06/30 9pp

- 8007.250001 Requests submittal of application for amend to license consisting of lech Spec changes & license conditions PHR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT.D G Division of Licensing 80/07/02 69pp
- 8007180076 Notifies that C-E 791203 request for route approval to cover spent fuel "hispments to BMI is subj to license fee Review of request was completed on 800226 MILLER, W D License Fee Management Branch 80/07/03 ip
- B007090291 Submits add1 info requested by NRC 790921 ltr re 790703 request for amend to Licenses DRR-53 & DRR-49 concerning spent foul pool mod Structural & liner plate analysis encl LUNDVALL.A E Baltimore Gas & Electric Cu B0/07/07 Zipp
- 8007230176 Summary of 800618 moeting wouth! Nuclear Energy Svc & Bechtel Power (arp re spent for) pool and structure design LI,C Y Operating Reactors Branch 1 80/07/08 5pp
- 8007240380 Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles positions & assignments of personnel Also submits info for GETR NOVAK-T M Assistant Director for Operating Reactors 80/07/08 200
- B007170352 Application for amend to Licenses DPR-53 & DPR-69, revising Paragraph 4 5 1 b & adding Paragraph 4 5 1 f to Tech Specs re ECCS surveillance requirements
 LUNDVALL.A E Baltimore Gas & Electric Co 80/07/14 3pp
- --B007170353 Proposed Tech Specs re ECCS surveillance requirements, revising Paragraph 4 5 1 b & adding Paragraph 4 5 1 f # Baltimore Gos & Electric Co = 80/07/14 1p
- O Inspection reports, IE Bulletins & correspondence
- 8007090356 Forwards update to util 800417 response to IE Bulletin 79-018. "Environ Qualification of Class IE Equipment " Evaluation of available qualification data for components expected to be completed by 800630 LUNDVALL.A E Baltimore Gas & Electric Co 80/05/27 200ap
- --8007090359 Forwards corrected response to IE Bulletin 79-018, "Environ Gualification of Class IE Equipment," replacing incomplete version forwarded by AE Lundvall 800303 ltr ABH.R F Baltimore Gas & Electric Co 80/03/05 200pp
- 8007020120 Forwards IE Info Notice BO-22. "Breakdowns In Contamination Control Programs ' No written response required ORIER, B H Region 1. Philadelphia. Office of the Director BO/05/28 1p
- 8007010279 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No writtn response required GRIER,O H Region 1, Philadelphia. Office of the Director 80/05/29 ip
- 8007170111 Responds to [E Du]letin 80~05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Moldup Tanks "
 Continued operation, even during interim period of nitrogen sys scipnint mod, justified for listed reasons tUNDVALL.A E Baltimore Gas & Electric Co GO/05/04 2pp
- B007210241 Forwards JE Insp Repts 50-317/R0-05 & 50-318/80-05 an 800407-30 No concemptioner noted DRUNNER.E J Region I. Philadetphia, Reactor Operations Nuclear Support Branch 80/06/04 2pp
- --8007210247 IE Insp Repts 50-317/80 05 & 50-318/80-05 on 800407-30 No noncompliance noted Mager areas inspected control room & accessible portions of auxiliary turbine set & intake bldgs, radiation protection & physical security ARCHITZELR Region 1, Philadelphia, Office of the Director NCCAGE.E & Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/30 20pp
- 80D7210574 Forwards IE Info Nutice 80-26, "Evaluation of Contractor GA Programs ' Na written response required GRIER,B H Region 1, Philadelphia. Office of the Director 80/06/10 lp
- 8007160937 Forwards IE Info Notice 80~27, "Degradation of Reactor Coolant Pump Study " No specific action or response fequired GRIER.D R Region 1. Philadelphia, Office of the Director 80/06/11 | ip

- BOO7170376 Responds to IE Bulletin BO-O6. "Engineered Safety Feature (ESF) Reset Controls " Test to verify that actual installed controls are consistent w/schematics reviewed will be completed during Fall 1980 & early 1981 refueling outages LUNBVALL.A E Baltimore Oas & Electric Co BO/O6/17 App
- 8007020614 Forwards IE Bulletin 80-15. "Possible Lose of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER, B H Region 1. Philadelphia Offsice of the Director. 80/05/18 1p
- 8007180600 Responds to IE Bulletin 80-10 Review of nonradipactive sys included valve lineups, leaking valves & points of contact between radioactive & nonradioactive phases Addl survestlance of nonradioactive sys will be implemented LUNDVALL. A E Baltimore Gas & Electric Co 80/06/19 ip
- B007020483 forwards IE Circular B0~15, "Loss of Reactor Coplant Pump Cooling & Natural Circulation Cooldown " No written response required. GRIER, B H Region 1, Philadelphia, Office of the Director B0/06/20 ip
- B007160686 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- B00721017; Forwards IE Info Notice B0-24, "Low Level Radwaste Burial Criteria" No written response required ORIER.B H Region 1, Philadelphia, Dffice of the Director B0/06/25 ip
- 8007230096 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER.D H Region i, Philadelphia, Office of the Director 80/06/27 200
- 8007250662 Corrects 800604 response to IE Bulletin 80-05 Operating experience has shown that even if reactor coalant drain tank is pumped to max flow rate, tank pressure remains greater than atmospheric pressure
 LUNDVALL.A E Baltimore Gas & Electric Co 80/06/27 2pp
- 8007100228 Bubmits info re fluid head design penetration connections or other designs w/containment boundary butt welds between sleeve & process piping.per IE Bulletin 80-08
 LUNDVALL,A E Baltimore Oas & Electric Co 80/07/03 5pp
- BOO7210044 Submits status of extensive survey program initiated in response to IE Bulletin BO-11 Accounts for half of masonry walls requiring insp Remaining items will be covered in final rept to be submitted after completion of surveys LUNDVALL.A E Baltimore Gas & Electric Co 80/07/03 32pp
- 8007210574 Responds to IE Bulletin 80-08 Each unit contains five panetrations w/flund head design Penetrations N-stamped per requirements of Paragraph N-153 of ASME Code, Section III, Buamer 1979
 LUNDVALL, A E Pacific Cas & Electric Co 80/07/03 App
- R Periodic operating reports & related correspondence
- B007010389 Forwards monthly operating rept for May 1980 MERSDN. S D Baltimore Gas & Electric Co 80/06/13 1p
- --B007010392 Monthly operating rept for May 1980 MERSON.S D Baltimore Gas & Electric Co B0/06/12 9pp.
- B007220351 Forwards monthly operating repts for June 1980 MERSON, S.D. Baltimore Gas & Electric Co. B0/07/19 1;
- --8007220355 Monthly operating repts for June 1980
 MERSON, S. D. Baltimore Gas & Electric Co. 80/07/15 18pp
- S Reportable occurrences. LERs & related correspondence
- 8004240213 PNO-I-80-36 on 800307, licensee reported via hot line that small fire occurred in diesel generator Room 21 Fire extinguished in one minute Caused by fuel oil accumulation in exhaust manifold BRIGOS.L., MCCABE, E., BRUNNER, E. Region 1, Philadelphia, Office of the Director 80/03/07 ip

240153 LER 80-030/03L~O on 800618, primary sample valve 1 CV-5967 dicated intermediate position & fully shut position could tbe verified Cause cannot be determined by remote means rrective action to be performed during shutdown VIS.S M., RIZZO,P G Baltimore Gas & Electric Co 80/07/18

0351 RD 80-32 on 800783, charging pumps 22,23 & 24 were placed of svc for mechanical reasons, leaving charging pump 21 mmergency power Caused by operator failure to verify tyrrelated sys out of 5 vc Corrective action forthcoming ELL.L B Baltimore Gas & Electric Co 80/07/24 1p

50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2 urity, medical, emergency & fire protection plans

0053 Forwards revised Pages 1-14 & new Page 148 for proposed 10CFR50 "Fire Protection Program for Nuclear Power ts Operating Prior to 790101," transmitted by NRC 800519 Page 148 not sucl NHUT. D G Division of Licensing 80/05/22 73pp

0388 Forwards Revision AD of TM1 modified amended physical rity plan Plan withheld (ref 10CFR2 790) EIN.J G Metropolitan Edition Co 80/06/27 ip

0667 Forwards State of PA authorization for open burning to train fighters FIN.J Q Metropolitan Edison Co 80/07/11 2pp

0593 Forwards revised fire protection program plan, replacing tops plan submitted Apr 1977
EIN. J G Metropolitan Edison Co 80/07/11 ip

220555 Revised fire protection program plan Hatropolitan Edison Co 80/07/11 Spp

O7i3 Informs that during site/general emergency, NRC personnel manitoring plant evaluations are to rept to ensite NRC ler complex or observation of the Accountability will be applished there & results provided INS. J T TMI Program Office 80/07/15 ip

udicatory correspondence

'0094 Urges R Hayhurst to respond to 800429 ltr re alleged 24 Flight 170 over plant Answer needed to avoid issuance ubscene to compel IDLER.L J Hearing Branch 1 BO/06/06 ip

0060 Forwards Director's 800613 decision under 10CFR2 206 & ited FR notice denying 790809 petition that Commission are EIS prior to authorizing venting of radioactive is from reactor bldg ON. H R Office of Nuclear Reactor Regulation, Director

INVICE OF issuance of Director's decision under 10 inving Antinuclear Group Representing Yark 790807 petition ist Commission prepare EIS prior to venting of radioactive isses from reactor bldg MSG.E O Defice of Nuclear Reactor Regulation, Director 1/06/13 '140066 Notice of issuance of Director's decision under 10CFR2 206

/140071 Director's decision under 10CCR2 206 denying Antinuclear top Representing York 790809 petition that Commission sue EIS prior to authorizing venting of radioactive gases tom held to the supplementary of the suppl

20550 Forwards Federal Republic of Germany energy & environ sarch rept. "Radiation Exposure Due To Venting TMI-2, .tor Bidg Atmosphere" due to concern re 800612 order for sorary mod of license to vent radiacative meti ER.R Affiliation Unknown 80/06/16 1p

7020554 "Radiation Exposure Due To Venting TMI-2 Reactor Bldg thoughbard "
RANKE, B. TEUFEL, D. Garmany, Federal Republic of 89/06/12,

B0070B00B6 Proposed findings of fact % conclusions of law responding to ASLAD quostions on Battelie rept Findings are adopted by THI-2/Peachbottom Intervenors & Ecology Action Orges suspension of Ols Certificate of Svt encl
WEPFORD, C Environmental Coalition on Nuclear Power 80/06/18

B007110075 Final contentions supplementing petition to intervone in OL amend proceeding Alleges inadequacy of RCS pressure Provisions to neutron monitoring instrumentation are insufficient to protect public Certificate of Svc encl SNGLLY, S C Affiliation Unknown B0/06/19 7pp

8007080046 Response to ASLAB request re Onficiency 1 Urges leveral of decision rejecting deficiency is correlation between U mine radon releases & amount of U fuel Portion of Porkins decision re-correlation must be vacated CAPLAN, R Ecology Action of Oswego 80/06/20 2pp

8007080048 Proposed findings of fact endorsing Citizens for Safe Environ filing re-radiation source torms from U mining & milling Rejects Perkins rationale & urges development of further evidence re-failure mechanisms & human factors CAPLAN,R Ecology Action of Oswego 80/04/20 4pp

8007070275 Suppl to 600315 request for hearing re-proposed change to Tech Specs.in reply to NRC 800404 response Specifies interest & standing & clarifies aspects of proceeding in which intervention is sought Certificate of Syc encl JOHNSRUD.J D Environmental Coalition on Nuclear Power 80/06/23

8007070276 Petition to intervene re Commission 800612 memorandum & order Alleges that util is inept at handling nuclear reactor & controlling cuntainment venting
LEHIS.M I Affiliation Unknown 80/06/24 2pp

8007080007 Motion before DC Court of Appeals requesting argument & hearing on panding 800623 & 24 motions for review of 800662 orders to satisfy notice requirement Evidence available Certificate of Svc encl Related correspondence 8HOLLY, 6 Affiliation Unknown SHEEHAN, D.P. Sheenan, D.P. 80/06/24 3pp

B007100240 Requests that NRC cure defects in B00612 memorandom & order by allowing enough time for litigants to seek administrative remedies before eventing NRC should look linto various objections before proceeding whom

8007310243 forwards Commission 800927 memorandum h order containing decisions on UCS 780902 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/06/20 89pp

8007020482 Matter to move 800707 prehearing conformice to wk of 800728 Licenses arranged 800707 meeting w/petitioners Shally & Lochsted during which simplification or alimination of issues re OL amend may take place (ertificate of 8vc encl TROMORIDOE, O f Metropolitan Edison Co TROMORIDOE, O f Shaw, Pittman, Potts & Trombridge 800/06/76 4pp

BOO7020621 Response in upposition to MII Douglas 800624 ltr requesting hearing re Commission 900612 older for temporary mod of Older reflects careful consideration of record including public comments W/Douglas ltre % Certificate of Syc TROMBRIDGE, O F Metropolitan Edison Co ROMBRIDGE, O F Shaw. Pittman, Potts & Trowbridge 80/06/26 App

8007070211 Forwards NRC 800628 urder denying intervenors SC Sholly. People Against Nuclear Energy & Newberry Township TM1 Sterring Committee 800623 joint motion for reconsideration of CLI-80-25 SNYDER, D J TMI Program Office 00/06/26

8007020654 Requests for adjudicatory hearing re Commission 800612 order amending OL Urges that he redinactive atmosphere venting be allowed until completion of hearing States interest & suggests B Franke, J Geyen & J Leas av. witnesses SHOLLY.S , HOSSIER.D E Affiliation Unknown 80706/P7 10pp

8007070337 Motion before US Court of Appeals for DC. Case 80-1694, requesting on heat reheating on putitioners' 800623 24 motions re 30-day prior notice for license amend 8HOLLY, 8, HOSSLER, D E Affiliation Unknown SHEFHAN, D P Sheenan, D P 80/06/27 2pp

- ---8007070353 Britef in lieu of pleading in support of patitioners' motion for an banc rebearing on 800623-24 motions to 800612 orders Requests that NRC comply w/statutory requirement for 30-day prior notice to license amend affectiveness SHOLLY, 8, HOSSLER, DE Affiliation Unknown BHEEHAN, DP Sheenan, DP 80/06/27 12pp
- --B007070365 Motion to file oversize brief in support of mation for an banc rehearing Court roled on patitioners' filings w/o hearing argument re right to 30-day pilor notice for license emend

 BMDLLY, B., H095LER, D.E. Affiliation Unknown BMEEHAN, D.P. Bheenan, D.P. B0706/27 2pp
- --8007070371 Motion requesting expeditions consideration of patition for rehearing Certificate of Svc encl SHOULY'S , HOSSLER, D E Affiliation Unknown SHEEHAN, D P Sheenan, D P 80706/27 2pp
- B007020623 Order denying licenses motion to reschedule OL amend 800707 prehearing conference Parties may confor & submit proposals to simplify or eliminate issues WOLF. JF Atomic Safety and Licensing Board Panel 80/06/30 2pp
- 8007080002 Memorandum & order advising that ASLB has received further delegation, per Commission 800612 order, for temporary license moduto rule upon hearing requests & to conduct evidentiary proceedings on venting issue

 MOLF, J.F. Atomic Safety and Licensing Board Panel 80/06/30 2pp
- B007070104 Notices of appearances in OL amend proceeding Certificate of Evc encl GOLDBERO, B C . SINGER, L N Hearing Branch 2 CHANDLER, L J Hearing Branch 1 80/07/01 5pp
- 8007280579 Forwards Director's decision under 10CFR2 206 (DD-80-21) denying Antinuclear Group Representing York request for EIS & related FR notice SNYDER.B J TM1 Program Office 80/07/02 2pp
- --8007280593 Director's decision under tOCFR2 20d denying Antinuclear Group Representing York 790809 request for E19 prior to venting of radioactive games from containment bldg Action does not constitute significant environ impact DENTON, HR Office of Nuclear Reactor Regulation, Director, 80/06/13 4pp
- 8007080001 Proposed fundings of fart & conclusions of law in form of mamorandum & order affirming ASLB 780714 partial initial decision & advising that radon releases associated w/U fuel tycle are insignificant in striking cost/benofit balance BORDENICK.B H Hearing Branch 4 80/07/03 58pp
- --8007080003 Proposed corrections to 800226 transcript BORDENICK, B M Hearing Branch 4 80/07/03 2pp
- --8007080006 Motion to include de manamus theory of health effects in NRC 600703 Findings of fact & conclusions of law presented in farm of memorandum & order inclusion is consistent w/ALAB-509. ALAB-500 & ALAB-562 Centificate of Syc entl BORDENIC. K Hearing Branch 4 80/07/03 7pp
- 8007080061 Response in apposition to KL Miller,MM Douglas & portions of SC Sholly & RE Hossler requests for hearing re Commission 800612 orders for temporary mod of AL W/Certificato of Byc & 800626 opposition to motion for injunction in Case 80-1691 CHANDLER,L J. Hearing Branch 1 SINGER,L Hearing Branch 2 80/07/03 34pp
- 8007100258 Order granting Ecology Action of Dawego motion to file 809620 submission re generic radom issue 818HOP.C J. Atomic Safety and Lirensing Appeal Panel 80/07/07 2pp
- 8007170337 Response in upposition to SC Sholly 800703 motion for temporary suspension or deferral of containment venting pending hearing AGLB has no jurisdiction to consider issue Urges prompt referral to ASLAB if ASLB declines denial CHANDLER.L J. Hearing Branch 1 GOLDBERG, B.C. Hearing Branch 2 80/07/07 10pp
- --BOD7:70359 Affidavit re alleged lack of consideration by NRC of doses due to particulate radionuclides cesium & strontium No new info presented that would lend to change in FES conclusions. Whibitographies & Certificate of Syr CONSEL.F J. Assistant Director for Radiation Protection WELLER.R A. Assistant Director for Fourtonmental Technology BO/07/07 9pp

- 8007280613 Petition & other pleadings before US Court of Appeals for Third Circuit, seeking declaratory judgement against NRC & stay of 800612 orders authorizing atmospheric venting Certificate of Svc encl Related correspondence SHEEHANLD P , HAGER R People Against Nuclear Energy 80/07/08 5259
- BOO7160591 Advises of considerable progress made during BOO711 meeting w/licenses & petitioners to intervene re advanced contentions Addl BOOB18 meetings will be held & ABLB will be informed of concrete results GOLDBERG.8 C. Hearing Branch 2 BO/07/15 1p
- 8007180411 Forwards NUREG-0597 "Evaluation of Long-Term Post-Accident Core Cooling of TMI-2," per 800711 negotiation session Dacoment sent to intervenor Sholly under separate cover W/o enci SINGER, L. N. Hearing Branch 2 80/07/15 1p
- 8007220000 Memorandum & order setting matters discussed & decisions made during Harrisburg,PA 800707 prehearing conference State of PA participation as interested party granted Decision restanding & acceptability of contentions held in absyance PARIS,D H , SHON,F J , WOLF,J F Atomic Safety and Licensing Board Panel, 80/07/15. App
- 8007310128 Response in support of NRC 800703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from consideration Supporting news articles encl CAPLAN, R Ecology Action of Oswego 80/07/16 13pp
- B007250353 Forwards revised Pages 7 & i6 to licensees reply to proposed findings of fact submitted by other parties filed B00718
 Revised pages required to correct typographical errors
 Svc list encl
 TRAVIESO-DIAZ Bhaw. Pittman. Potts & Troubridge 80/07/21 10pp
- 8007310467 Forwards R8 Hayhurst 800601 ltr re Johnsrud testimony on behalf of intervenors concerning 800124 US Air Flight 170 Substance consistent w/record Formal evidentiary consideration need not be given CHANDLER, L J Hearing Branch 1 80/07/28 1p
- --8007310469 Responds to talcon & 800429 ltr re 800124 US Air Flight 170 Contrary to Lines 11 & 12 of hearing transcript, author did not operate flight in question directly over facility on 800424 HAYAURST,R S Affiliation Unknown 80/06/01. 1p
- H General correspondence
- 8005140109 Responds to 800226 ltr re K Manges concerns about vanting radioactive gates from containment bldg Public comments are being solicited on NRC environ assessment & recommendations Krypton gas venting not permitted until final decision KAMMERER, C Office of Congressional Affairs 80/04/01 2pp
- 8007240406 Ark receipt of 800401 ltr concerning possible means of disposing of radioactive matl from facility NRC officials will review comments Ltr encl HAMMERSCHMIDT, J House of Rep 80/04/09 3pp
- 8005160225 Responds to 800408 ltr rp D Miller concerns about venting krypton gas from containment bldg Controlled venting recommended by NRC environ assessment No venting permitted pending review of public comments & consequent decision KAMMERER.C Office of Congressional Affairs 80/04/16 ip
- B005200319 Responds to B00331 ltr re J Piccolo conterns about venting krypton gas from containment bldg Controlled venting recommended by NRC environ assessment No venting permitted pending review of public comments & consequent decision KAMMERER, C Office of Congressional Affairs. B0/04/16 2pp
- 8005160124 Responds to 800418 ltr re M McGarrity interest in venting krypton from containment bldg No decision has been made to permit venting If decision favors venting, residents will be given ample notice.

 KAMMERER, C Office of Congressional Affairs 80/04/28, ip
- 8005200357 Responds to 800415 ltr re constituent concern about Kemeny Commission "secret findings" Commission recommendations on facility accident made available to public in 791030 rept to President Carter List of supplementary documents encl KAMMERER, C Office of Congressional Affairs 80/04/28 2pp

- SOC5200454 Responds to 800414 ltr re D Hossler comments on environ assessment of venting radioactive gas from containment bldg Comment will be considered prior to any Commission decision Conventing

 KAMMERER, C Office of Congressional Affairs 80/04/29 ip
- 8007030372 Confirms telcon re US Air Flight 170 on 800124 Forwards transcript excerpt re J Johnsrud testimony about experience on filght into Harrisburg Intl Airport CHANDLER, L J Hearing Branch 1 80/04/29 4pp
- BO05070512 Requests repts by PA Medical Society & Natl Cancer Inst.re impact of venting on public health & safety, discussed during BO0424 meeting in Lebanon.PA MECKLING, M Affiliation Unknown 80/04/30 ip
- BOG6120212 Responds to 800498 ltr re constituent inquiry about fatility NRC & EPA are monitoring plant releases Results of EPA monitoring made public twice weekly via local media NRC Middletown off selected to facilitate public needs KANMERER, C. Office of Congressional Affairs 80/05/05 2pg 80/05/05 2np
- BOO-6120437 Responds to BOO428 ltr re constituents concerns about venting radioactive gases from containment bldg NRC 800312 soviron assessment recommended that venting be permitted Venting not permitted pending final decision XAMMERER, C Office of Congressional Affairs 80/05/05 2pp
- BOO6120484 Responds to 800416 ltr re AB Howard ltr urging that cleanup activities & Kr-B5 venting be conducted as rapidly as possible Decision on proposed venting will be made in near future MANERER, C Office of Congressional Affairs 80/05/05 1p
- BO0723010B Responds to 800321 questions re possible financial failure of util. Financial failure provides grounds for immediate revocation of license Contingency plans under development NRC will ensure protection of public health AHEARNE. J F. Commission BO/05/07 2pp
- 8007180463 Responds to 1tr postmarked 800324 re nuclear power plants NRC has found that actions to improve safety, plant design & siting & health effects are necessary & fassible Plants found to be unsafe will not be allowed to operate DENTON.H R Office of Nuclear Reactor Regulation, Director 1p
- 9007180469 Responds to ltr postmarked 800327 re waste products of muclear power plants Presidential 800212 message to Congress re redwaste mgt program encl DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/08 6pp.
- BO07180067 Responds to encl B00306 ltr to President Carter re nuclear power plants Presidential 791207 statement on Kemeny Commission rept on TMI-2 & excerpts from NUREO-0662 & NUREO-0662 encl DENTON, H R Office of Nuclear Reactor Regulation, Director B0/05/12 16pp
- 8007180474 Responds to 790816 ltr to J Hendrie re nuclear power plants & disposal of radwaste Commissioners have approved licenses for three nuclear plants to load fuel & begin low power levels for testing Presidential 600212 message entl OFMTON, H R Office of Nuclear Reactor Regulation. Director 80/05/12 App
- --B007180478 Urgss govt financing of research projects to resolve nuclear waste disposal, generate synthetic fuels & nuclear fusion WHATLEY, H E Chamtron Corp 79/08/16 2pp
- 8007180492 Responds to encl 800323 ltr to President Carter re precautions to prevent another nuclear accident such as TMI-2 Efforts made to ensure public health & safety at all nuclear plants. Unsafe plants will not be allowed to operate DENTON.H R. Office of Nuclear Reactor Regulation, Director 80/05/12 Spp
- 8006/2050/ Discusses status of venting krypton from containment bldg in response to 8004/6 ltr re A Donley concerns Public comments are being solicited on environ assessment Krypton gas venting not permitted pending final decision KAMMERER, C. Office of Congressional Affairs 80/05/14 lp.
- BOO7180182 Responds to 800327 ltr to President Carter re nuclear power plants & nuclear wastes Carter 800212 message to Congress & 771207 statement on Kemeny Commission rept enci DENTON H R Office of Nuclear Reactor Regulation, Director, 80/05/14. 1ipp

- B007160731 Responds to B00317 ltr to President Carter re B00309 editorial in San Diego Union newspaper Forwards excerpt on nuclear power from "Second Natl Energy Plan: " & 791207 statement by President on Kemany Commission Rept on TMI DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/15 12pp
- 8007210046 Responds to 790316 itr re nuclear accidents before TMI NUREO-0572 & excerpts from 'Past Accidents in Nuclear Reactor Facilities & Nuclear Power Plant Airborne Radioactivity Releases. "& "Precursor Events TMI." encl DENTON.H R Office of Nuclear Reactor Regulation, Director BANDS-15
- --8007210047 Requests info re nuclear accidents before TMI incident MORRISON, J R Affiliation Unknown 79/05/16 ip
- 8007250063 Responds to BOOR13 itr re effects of radiation on children Allowable radiation doses have been evaluated for all age groups Acceptable radiation dose stds allow for special tensitivity of young children MULLER, D.R. Assistant Director for Environmental Technology 80/03/13 2pp
- 8007180546 Responds to 800129 itr to President Carter re licensing nuclear power plants TMI accident created need for changes in approach to safety Due to need for power-NRC has granted licenses for three units to begin inw level power testing DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/19 3pp
- 8007180553 Responds to 790402 ltr to President Carter re nuclear power plants Addl containment structure as suggested not considered necessary or feasible State of PA Emergency Mgt Agency pampalet on radiation incidents enci DENTONIM R Office of Nuclear Reactor Regulation, Director BOADS-LE
- 8007210208 Responds to encl 800418 ltr to President Carter re Indian Point facility Describes NRC efforts to protect public health at facilities currently operating or planned for operation Village Voice news article encl DENTON, H R Office of Nuclear Reactor Regulation, Director 80/05/21 10pp
- 8007020055 Responds to 790410 ltr to President Carter re safety of nuclear plants Plants designed to provent accidents through presence of protective sys.engineered safety features & safety evaluations of site suitabality D Lawe ltr encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/27 3pp
- 8007020655 Urges NRC approval of venting at TMI WILD:A A Affiliation Unknown 80/06/04 is
- 8007010246 Ack receipt of Westmoreland County Board of Supervisors' 800514 resolution No new nuclear plants will be licensed until improved safety criteria developed Certain plants allowed to operate for testing Winnel EENTON H R Office of Nuclear Reactor Regulation, Director 80/06/06 10pp
- 8007020657 Suggests venting of krypton gas into helium balloon SONNEBORN, M R Affiliation Unknown 80/04/06 1p
- 8007020677 Ack receipt of Lancaster County Board of Supervisors 800429 resolution Forwards President Carter 800212 message to Congress re establishment of comprehensive radioactive waste mpt program

 BENTON-H R Office of Nuclear Reactor Regulation, Director . Bթր 80/06/06
- 80071104B3 Discusses NRC post-TMT actions re mafety at nuclear power plants in response to enci Richmond County, VA Board of Bupervisors 800508 resolution supporting use of nuclear power President Carter 800212 message encl DENTON, HR Office of Nuclear Reactor Regulation. Director 80/06/06 9pp
- 8007170548 Responds to encl 800417 ltr to President Carter re nuclear power plants Every effort is being made to ensure public health & safety at all nuclear facilities White House press release & excerpt from NUREQ/CR-0130-Vol 1 encl DENTON H R Office of Nuclear Reactor Regulation, Director 22pp 80/06/05.
- 8007210530 Forwards President Carter's statement on Kemeny Commission rept on TMI-2 & Chapter 5 from Second natl energy plan per 800421 request for info on nuclear power DENTON H R Office of Nuclear Reactor Regulation, Director 80/96/06 19pp

- B007020229 Responds to B00409 ltr re MM Hocker contern about health & financial custs associated w/facility accident & cleanup Util.nut federal govt.is responsible for cleanup costs Fortion of costs covered by util insurance policy DIRCKS.W J Office of the Ejecutive Director for Operations 80/06/09 2pp
- --8007020237 Requests response to encl HM Hocker 800402 re financial costs associated w/facility accident & cleanup GUODLING.H House of Rep 80/04/09 4pp
- 8007110346 Ack receipt of 800329 ltr expressing concern about proposed facility purging Decision on how to best remove Kr-85 contained in reactor bidg not reached Review of mechanism for selecting panelists for advisory panel underway AMEARNE.J F Commission 80706/09 5pp
- B007170551 Responds to encl 900418 ltr to President Carter re nuclear power plants Every effort is being made to ensure public health & safety at all nuclear power plants White House press release & except from NURCO/CR-0640 encl DENTON, H R Office of Nuclear Reactor Regulation, Director press releas.
 DENTON, H R DI
- 8007100456 Responds to 800521 ltr suggesting means of improving nuclear power plant safety Accident at TMI was result of operators overriding automatic actions rather than allowing too much time for operator action MATTSON, R J Division of Safety Technology 80/06/11 3pp
- 800714023B FOIA request for info ie release of krypton gas into atmosphere from facility TROMBETTA.R Affiliation Unknown 80/06/12 2pp
- B007010508 Requests that NRC re-evaluate decision to release Kr-B5 gases from Facility when alternative for storage & isolation from environ is available MASSERBACK.A C New Yark Federation for Safe Energy B0/06/13
- 8007080226 Expresses concern re venting of krypton gas into environ Discusses health hazards of noble gases & magnitude of release DREY.K Affiliation Unknown 80/06/15 4pp
- 8007290047 Forwards Commissioner biographies in response to 790426 request for info on background of Commission No info developed to indicate that sabotage contributed to initiation of accident or in subsequent response DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 80/06/17 https://doi.org/10.1006/10.1
- --8007290051 Forwards analysis of possible substage involved in TMI-2 accident Also requests info on professional background of NRC staff SDXMAN.K A Affillation Unknown 79/04/26 7pp
- 8007100145 Responds to 800313 ltr re radiation effects on mutation rate & problem of radiatiste storage less than one mutation expected to result from effect; of TMI radiation to public compared w/60-970 from natural radiation sources DENTON.HR Defice of Nuclear Reactor Regulation, Director 80/06/18 1p
- 8007290064 Responds to 800527 Iti re THI-2 accident & precautions to prevent such accidents NRC action plan developed to provide comprehensive basis for actions necessary to correct or improve regulation Chapter 7 from NRC 1979 Annual Rept encl DENTON. HR Office of Nuclear Reactor Regulation, Director 80/06/18 23pp
- --B007290067 Requests info on TMI-2 accident & NRC precautions taken to grevent such accidents Every individual has right to know who is looking out for American interests & how well HENRY,L. Affiliation Unknown B0/05/22 lp
- 8007070154 Responds to 800512 request for info on availability of repts Kemeny Commission Rept may be purchased from OPO 470 and repts in security & sabotage SNYDER, B J TMI Program Office 80/06/19 ip
- --80070/0162 Requests price & availability of repts on TMI sabotage event analyses, pre & post-accident security status at TMI & Kemony Commission Rept ROBERTS, W J Affiliation Unknown B0/05/12 ip
- B007230686 Forwards General Assembly of State of PA 800429 House Resolution 185 Urges rapid formulation by NRC of criteria which will be used as guidelines for decontamination of facility Certificate of Eye encl MEDUS-C F Penn-glyania. State of 80/06/19 App

- 8006300220 Add1 response to FDIA request for written communications between NRC & Congress since 800322 concerning facility Forwards documents in App A FELTON. J M Division of Rules and Records 80/06/20 3pp
- ---8007100438 Ack receipt of 800422 1tr forwarding D Griffith correspondence No decision made re venting of containment bldg KAMMERER, C Office of Congressional Affeirs 80/05/05 lp
- B007010304 Forwards 790720 order for license mod, NUREG-0600, NUREG-0578 & NUREG-0385, in response to 800619 telcon re QL amend proceeding W/o encls
 CHANDLER, L J Hearing Branch 1 80/06/23 1p
- 8007020091 Responds to 800416 ltr re H Donley request for info about 800320 release of radioactive gases Air-exhaust duct effluent monitors did not detect radioactive matls above normal plant release rates
 DIRCKS.H J Office of the Executive Director for Operations 80/06/23 lp
- B007020653 Opposes krypton gas venting Newspaper article enc1 KIENLE:D, KIENLE:K M , MCCARTNEY:R M Affiliation Unknown B0/06/23 ip
- 80072B0129 Responds to 800615 ltr Decision to purge 97,000 Ci krypton gas from containment bldg was traumatic for all Forwards final EIA & Commission memorandum & order for better understanding of how & why decision was made W/o encl INGRAM.F L Office of Public Affairs 80/06/23 lp
- ---8007280136 Requests decision to purge krypton gas be reconsidered Policy reflects lack of responsibility MOODY,C J Affiliation Unknown 80/06/15 3pp
- B007140619 Addl FOIA request for all written communications between NRC & Congress since 800322 concerning facility FIDELL.E R LeBoeuf, Lamb, Leiby & MacRae 80/06/24 2pp
- 8007250056 Discusses human factors engineering issues associated w/ accident Offers svcs to NRC w/assurance that firm will provide key insight into conduct & application of post-TMI human factors research MAURO,C L Affiliation Unknown 80/06/25 2pp
- 8007i60i45 Expresses appreciation to Boise Interagency Fire Ctr for assistance during TMI-2 accident NRC benefitted from excellent communication capabilities of agency Certificate of appreciation encl W/a encl WEISS.B H Office of Inspection & Enforcement, Office of the Director 80/06/26 is
- 8007;60155 Expresses appreciation to Boise Interagency Fire Ctr for assistance during IMI-2 accident NRC benefitted from excellent communication capabilities of agency Cortificate of appreciation encl W/o encl WEISB.8 H Defice of Inspection & Enforcement, Office of the Director 80/06/26 ip
- B007160160 Expresses appreciation to Boise Interagency Fire Ctr for assistance during TMI-2 accident NRC benefited from excellent communication capabilities of agency Certificate of appreciation encl W/o encl WEIBS, B H Office of Inspection & Enforcement, Office of the Director 60/06/26 ip
- BOO7160167 Expresses appreciation to Boise Interagency Fire Ctr for assistance during TMI-2 accident NRC benefitted from excellent communication capabilities of agency Certificate of appreciation encl W/o encl WEISB.B H Office of Inspection & Enforcement, Office of the Director 80/06/24 ip
- 8007140170 Expresses appreciation to Boise Interagency Fire Ctr for assistance during TM1-2 accident NRC benefitted from excellent communication capabilities of agency, Certificate of appreciation encl W/o encl WEISB, B H Office of Inspection & Enforcement, Office of the Director 80/04/24 ip
- B007160183 Expresses appreciation for assistance during TMI-2 accident NRC benefitted from execllent communication capabilities of apency Cortificate of appreciation encl W/o encl. WEISS B H Dffice of Inspection & Enforcement, Office of the Director 80/06/26 ip

- 8007180237 Forwards Section 8 0 & draft Addendum 2 to NUREG-0662 re decontamination of TM1-2 reactor bidg atmosphere NRC will use real-time environ & meteorological data during purging H/o encl SNYDER.B J TM Program Office BO/06/26 ip
- --8007180250 Requests copy of Addendum 2 to NUREO-0662 re decontamination of TMI-2 reactor bldg atmoshpere Inquires whether actual site monitoring was done downwind of Kr-85 releases MASSERBACH.A E Affiliation Unknown 80/05/22 ip
- 8007230225 Responds to B00508 ltr to President Carter re reliability of NOVAMENTAL Responds to BOUSDE It to President Carter Re Tella const of nuclear power plants Purpose of NRC insp program is to essure adequate QA Forwards excerpts from NRC 1979 annual rept & Becond Natl Energy Plan DENTON, HR Diffice of Nuclear Reactor Regulation, Director BO/06/26 2pp
- 8007230626 Responds to 790405 request for info re nuclear energy Due to TMI incident NRC decided not to license new plants until improved safety criteria had been developed Excerpt re production of nuclear energy encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/26 10pp
- --8007230630 Requests info re nuclear energy & process by which energy is produced COLT:S Affiliation Unknown 79/04/05 Ip
- B007280122 Forwards President Carter statement on Remeny rept.in response to encl 800512 ltr to President Carter re safety of nuclear power plants DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/26 Spp
- 8007270054 Responds to 800512 ltr to President re status of nuclear power plants President 791207 statement on Remany Commission rapt on TMI encl Action plan developed to provide comprehensive & integrated basis for future actions DENTON.HR Office of Nuclear Reactor Regulation, Director 80/06/26 4pp
- B007300013 Responds to 790405 ltr re nuclear power State of IL has seven nuclear power plants Reasons for use of nuclear power plants in IL listed in encl excerpt from util annual rept President 791207 statement re Kemeny Commission Rept encl DENTON.H R Dffice of Nuclear Reactor Regulation. Director DENTON, H R OP-80/04/26 28pp
- 8007250070 Responds to encl 800504 its to President Carter re nuclear NO/ASOU/O Responds to entl 800504 itr to President Carter Pe i energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/27 22pp
- BOO7250081 Responds to 790429 request for info re nuclear energy Radiation doses from power plants is small fraction of dose from natural environ sources FEB excerpt & White House BOO212 message to Congress encl DENTON. H R Office of Nuclear Reactor Regulation, Director BO/06/27 18pp
- 8007140816 Appeals denial of FOIA request for info concerning venting of krypton gas from facility
 TROMBETTA:R Affiliation Unknown 80/06/30 Ip
- 8007140389 Responds to 800403 invoice & forwards insp fees for persod of Mar 1979 to Mar 1980 per 10CFR170 W/o encl HERBEIN, J Q Metropolitan Edison Co 80/07/02 2pp
- 8007140616 Responds to FOIA request for written communications between NRC & Congress since 800022 concerning facility Forwards items listed in Documents is \$2 of App A in NRC 800616 ltr & updated App A w/oxplanatory notes
 FELTON, J M Division of Rules and Records 80/07/02 9pp
- ----8007140525 Determines that EJ Sternglass 600125 paper, "Infant Mortality Changes Following TMI Accident," in w/o scientific merit Cites examples of data manipulation Questions re facility encl GOLDBMITH:R Radiological Health Standards Branch 60/04/29.
- -8007140629, "Analysis of Infant Mortality Following TMI Accident "
 PA Dept of Health 600402 press release encl
 QOLDBHITH: Radiological Health Standards Branch 80/04/29

- 8007180107 Forwards microfiche copy of "Logbook of Radiological Data." in response to request W/d encl SNYDER.B J FMI Program Dffice 80/07/02 1p
- --8007180110 Ack receipt of "Logbook on Radiological Data " Reproduction on many pages is poor Requests microfiche copy BARLEY'S R Affiliation Unknown BO/03/02 1p
- B007140233 Responds to FOIA request for info or release of krypton gas into atmosphere from facility Forwards documents listed in App A W/o encls FELTONIUM Division of Rules and Records B0/07/03 2pp
- 8007280182 Responds to 800509 ltr expressing concern because no notice to airmen was issued in conjunction w/release of Kr-85 on 800423 Assuming poor meteorological conditions, totalbody exposure would have been 0 008 millirem DENTON. H R Office of Nuclear Reactor Regulation, Director 80/07/07 lp
- --8007280188 Forwards FR Romano 800509)tr re venting Kr-85 from reactor containment bidg SNVDER, G L. Region I. Philadelphia. Office of the Director BO/05/14 ip
- ~~8007280195 Expresses concern because no notice was issued to pilots or passengers prior to entering Harrisburg airport area notifying of danger of concentrated krypton gas ROMANG.F R Affiliation Unknown 80/05/09 2pp
- 9007R10121 Responds to 790709 ltr to NRC re concerns about facility & actions being taken by Concerned Citizens of Londonderry NRC has ordered public braving to determine whether Unit 1 should be operated Unit 2 feasibility studies are underway BNYDER.D J TMI Program Office 80/0//09 2pp
- --B007210131 Expresses appreciation for 790629 visit to Middletown.PA Concerned Citizons of Londonderry,who have collected 750 signatures, are dedicated to closing facility NRC status repts would be of great benefit to area residents STREET.P A Affiliation Unknown 79/07/09 2pp
- 8007220320 Responds to 800401 ltr to President Carter expressing concerns over financial impact as stockholder w/licensee NRC is concerned w/economic impact Responsibility is limited to health & safety

 W Operating Reactors Branch 4 80/07/09
- 8007230286 Responds to encl 800508 ltr to President Carter expressing concern about TMI-2 cleanup process & purge of Kr-85 in reactor bldg Onsite NRC team is monitoring cleanup effort NUREG-0673 & NUREG-0662, Vol 1, encl W/o encls DENTON. H R Office of Nuclear Reactor Regulation, Director 80/07/09 5pp
- 8007230293 Responds to encl 1ths to US Public Health Svc & DDE re research project on nuclear power plants. In May 1977 NRC adopted resident inap program No water leak was implicated in initiating accident at TMI-2 reactor SNYDER, B J TMI Program Office 80/07/09 App
- 8007230278 Responds to 790514 itr to FRDA to info about TMI-2 accident Plant was never in danger of blowing up because no oxygen could have accumulated in hydrogen bubble under existing conditions Accident caused by human & mechanical errors BNYDER.B J TMX Program tyffice 80/07/09 app
- 8007230311 Responds to encl 790428 Itr to President Corter re TMI-2 accident Util customers will not have to pay for any damages or for restoration of facility Customers will, however, gay costs associated w/purchasing replacement power BNYDER.B J TMI Program Office 80/07/09 App BO/07/09 4
- 8007270032 Responds to 800430 ltr to HR Denton requesting two mpdical records NUREO-0662. "Final Environ Assessment for Decontamination of TMI-2 Reactor Bidg Atmosphere." "Low Level Radiation" & PA Medical Society rept encl W/o encl SNYDER.D J TMI Program Office 80/07/09 2pp
- 8007300006 Responds to ltr ie accident at lMI-2 Public hearings will be conducted to determine whether Unit 1 should be operated & under what confittions Licensee has not submitted proposal for overall plant recovery for Unit 2 SNYDER.D J THI Program Office 80/07/09 2pp
- 8007140511 Responds to appeal re-denial of FOIA request for info re-venting of krypton gas from facility NRC completed action on initial request by providing documents subj to request on 800703 No further action will be taken FELTON J M Division of Reles and Records 80/07/10 tp

- B007170362 Comments on 800609 review of "Method for Calculating Doses to Population from Xe-137 Releases During TMI Accident " Derivation values & accuracy of calculations discussed FAIROBENT. J E Affiliation Unknown 80/07/10 3pp
- 8007230969 Responds to 790403 ltr to President Carter re nuclear power Commission rept on TMI & excerpt from ARC 1979 annual rept re developmental of radiological emergency plans Ltr enci DENTON H R Office of Nuclear Reactor Regulation, Director 10pp
- BO07250167 Responds to B00509 ltr re JB Hurst comments & questions about reactor bldg decontamination Hurst comments were considered in preparation or final environ assessment Hurst B00411 ltr to NRC encl DIRCKS.W J Office of the Executive Director for Operations B0/07/10 lg
- --B007250174 Comments on environ assessment of reactor bldg decontamination health impacts should be determined by objective, independent data collected & analyzed over substantial period of time Related news article encl HURST, J B Affiliation Unknown 60/04/11 App
- BOO7250190 Responds to BO0514 ltr re D Mattson concerns about encl article in Paxton Herald on problems affecting farm animals near facility Issue under investigation field studies completed & data being evaluated Rept to be issued soon KAMMERER, C Office of Congressional Affairs 80/07/10 7pp
- BOO721048) Questions why BOO41; telegram does not appear in NUREQ-0662, Vol 2, environ assessment to venting of krypton gas at facility CHONO,L R Affiliation Unknown BO/07/14 1p
- 8007250062 Provides info on facility incident.in response to 800623 ltr re E Dobson inquiry Includes containment design strength & typical containment design pressure Director for Operations 90/07/15 2pp
- -8007250067 Requests response to E Dobson inquiry about facility incident BAUCUS.M Senate 80/06/23 1p
- 8007230727 Ack receipt of 800A23 ltr offering to help resolve some of human factors engineering issues raised by accident NRC has organized new Div of Human Factors Safety to address Precisely there issues

 BUBNITY, R J Office of Nuclear Regulatory Rosearch, Director

 80/07/16 ip
- 8007300010 Responds to 800521 ltr re 800324 newspaper article on release of Kr-85 gas from reactor bldg Purging of atmosphere considered to be safest & most expeditious way of effecting decontamination BNYDER. B J TMI Program Office 80/07/16 200
- --8007300012 Requests info re encl 800324 newspaper article on release of Kr-83 gas from reactor bldg MARSHALL:E N York: PA 80/05/21 2pp
- 8007280105 Ack receipt of 800604 ltr re purging TMI~2 containment atmosphere Forwards NUREG-0673 W/o encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/07/18 ip
- --8007280116 Requests broklet re qualities of krypton gas & six copies of NUREG-0673 HUBER, J.E. Langaster County, PA BO/06/04 10
- 8007300369 Advises that Director's decision re request that E18 be prepared prior to authorizing venting of radioactive gases from reactor bidg is final NRC action in praceeding Commission has taken no action for review or to extend time CHILK.S J Office of the Secretary of the Commission B0/07/24

I Financial information

BOO7130730 Confirms 800626 telcon & forwards graph illustrating market price of General Public Utils Corp common stock for period Jan 1979 to mid-June 1980 HOWBON:T & General Public Utilities - GPU Service Corp 80/06/26

- J Insurance & indemnity information
- BOO7110011 FDIA request for all indomnity agreements insurance policies & associated info between util NRC &/or AEC refacility
 MEARNEY.R W Affiliation Unknown 80/05/29 2pp
- B007110007 Responds to FOIA request for all indemnity agreements, insurance policies & associated info between util NRC &/or AEC re facility Forwards documents listed in App A FELTON, J M Division of Rules and Records B0/06/23 7pp
- ---B007110017 Confirms that NELIA has bound Insurance Policy NF-220 at limit of one million dollars issued to Mat Ed.JCP&L & PEPCO covering facility Includes policy site description QUATTRUCCHI, J Nuclear Energy Liability Insurance Association
- --8007110032 Executed Amend & to Indomnity Agreement B-44, changing licamse numbers SALTZMAN.J Antitrust & Indomnity Group HERBEIN.J & Matropolitan Edison Co 80/02/24 lp
- ---B007110037 Amend B to Indemnity Agreement B-64, changing amount of financial protection SALTZMAN, J Antitrust & Indemnity Group 79/05/01 2pp
- --8007110040 Executed Amend 9 to Indemnity Agreement 8-64, modifying prefatory language of Paragraph 5. Article 1.re course of transportation NELIA Policy (facility form) encl SALTMAN, J. Antitrust & Indemnity Group HERBEIN, J. G. Metropolitan Edison Co. 80/01/03 5pp
- --B007110046 Endorsement 2 to NELIA Policy NF-220 designating annual premium Declaration encl
 * Nuclear Energy Liability Insurance Association 79/01/12 2pp
- --B007i10051 Amend to Condition 4 endorsement to NELIA Policy NF-220, Constitutes Endorsement 2 HARRORE, J Nuclear Energy Liability Insurance Association 73/12/14 ip
- ---B007110052 Amend to NELIA Policy NF-220 Constitutes Endorsement 4 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- --8007110057 Amend to industry credit rating plan premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 5 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 2pp
- --8007119060 Endorsement 6.waiver of defenses endorsement (ENO), to NELIA Policy NF-220
 MARRONE, J Nuclear Energy Liability Insurance Association
 73/12/14 2pp
- --8007i10062 Endorsement 7 to supplementary endorsement waiver of defenses for reactor const to NELIA Policy NF-220 MARRONE. J Nuclear Energy Liability Insurance Association 73/12/14 ip
- ---B007i10068 Amend to Insuring Agreement IV of NELIA Policy NF-220, "Application of Policy " Constitutes Endorsement 8 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 | Ip
- --8007i10072 Amend to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 9 MARRONE, J Nuclear Energy Liability Insurance Association 73/12/14 1p
- ---B007110077 Endorsement 10 to advance premium & std premium endorsement,

 w/changes in subscribing companies & proportionate liability
 endorsement to MELIA Policy NF-220

 MARRONE, J Nuclear Energy Liability Insurance Association
 73/11/01 1p
- --8007ii00B4 Endorsement ii.assignment of interest in return premium & in reserve premium refund to NELIA Policy NF-220 MARROME, J Nuclear Energy Liability Insurance Association 74/07/15 2pp
- --8007i10089 Amend to Condition 4 endorsement to NELIA Pulicy NF-220 Constitutes Endorsement 12 MARRONE, J Nuclear Energy Liability Insurance Association 74/01/13 ip

- ---8007110091 Amend to Endorsement 10,advance premium & std premium andorsement of MELIA Policy NF-220 Constitutes Endorsement 13 MARRONE, J Nuclear Energy Liability Insurance Association 74/02/15 ip
- --B007110095 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 14 MARRONE. J Nuclear Energy Liability Insurance Association MARRONE, J N 74/03/15 ip
- --- B00711009B Endorsement 15 to NELIA Policy NF-220, increasing liability limits

 MARRONE.J Nuclear Energy Liability Insurance Association
 74/04/26 1p
- --8007110103 Amend to Endorsement 13 to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement 14 nd MARRONE, J Nuclear Energy Liability Insurance Association 74/04/26 ip
- ---8007110107 Amend of std premium endorsement w/changes in subscribing companies & proportionate liability endorsement Constitutes Endorsement 18 BARDES, C.R. Nuclear Energy Liability Insurance Association 74/12/12 in
- ---BO07110125 Amend of Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 19 BARDEG.C R Nuclear Energy Liability Insurance Association 75/01/01 1p
- -8007110128 Endorsement 20 to NELIA Policy NF-220, increasing limit of liability endorsement
 BARDEB: G R Nuclear Energy Liability Insurance Association
 75/03/21 ip
- ---B007110132 Amend to Endorsement 18 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 21 BARDEB/C.R Nuclear Energy Liability Insurance Association 75/03/21 1p 75/03/21
- ---B007110135 Amend to Endorsement 17 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 22 22 BARDES, C.R. Nuclear Energy Liability Insurance Association 75/04/22 ip
- ---8007i10i40 Endorsement 23 to advance premium & std premium endorsement to NELIA Policy NF-220 w/changes in subscribing companies & proportionate liability endorsement BARDEB.C R Nuclear Energy Liability Insurance Association 78/12/01 ip
- --8007110143 Amend to Endorsement 23 to advance premium & std premium endorsement of NELIA Policy NF-220 Constitutes Endorsement ∠a.
 BARDES, C. R. Nuclear Energy Liability Insurance Association
 76/07/09 ip 76/07/09
- ---8007110147 Amend to Condition 2, insp & suspension, to NELIA Policy NF--220. Constitutes Endorsement 26 BARDES, C. R. Nuclear Energy Liability Insurance Association 76/12/15 ip.
- ---8007110151 Endorsement 27 to waiver of defenses endorsement (ENO) to NELIA Policy NF-220 Constitutes Endorsement 27 BARDES, C. R. Nuclear Energy Liability Insurance Association 74/12/15 2pp.
- ---BO07110154 Amend to definition of nuclear energy hazard to NELIA Policy NF-220 Constitutes Endorsement 28 BARDES, C. R. Nuclear Energy Liability Insurance Association 76/12/15 1p
- --8007110160 Endorsement 29 to advance premium & std premium endorsement TARDEB, C R Nuclear Energy Liability Insurance Association 76/12/31. 2pp

- --B007110173 Endorsement 31 to NELIA Policy NF-220, increasing limit of liability endopsement

 * Nuclear Energy Liability Insurance Association 77/05/06 ip
- --800711017A Ampnd to Endorsement 29 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 32 ⊭ ARDES,C R Nuclear Energy Liability Insurance Association 7/05/06 in 77/05/06
- ---8007110178 Amend to Endorsement 32 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 33 BARDES,C R Nuclear Energy Liability Insurance Association 77/08/17 in
- --B007i10201 Amend to Endorsement 34 to advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement 35
 BARDES, C R Nuclear Energy Liability Insurance Association 78/03/06
- --8007110208 Amend to advance premium & std premium endorsement & amend of Condition 4 endorsement to NELIA Policy NF-220 Constitutes Endorsement 36 Nuclear Energy Liability Insurance Association BARDEB, C R l p 79/01/03
- --8007110212 Amend to Endorsement 35 of advance premium & std premium endorsement to NELIA Policy NF-220 Constitutes Endorsement BARDES, C.R. Nuclear Energy Liability Insurance Association 79/01/16 ip 79/01/16
- --8007110217 Endorsument 3B to NELIA Policy NF-2PO, w/changes in subscribing companies & proportionate liability endorsement BARDES, C R Nuclear Energy Liability Insurance Association 79/01/20 ip
- --B007110222 Amend to Insuring Agreement 3 to NELIA Policy NF-220 Constitutes Endorsement 1 MARRONE,J Nuclear Energy Liability Insurance Association 73/12/14 1p
- --8007i10224 Amend to address of NELIA endorsement to Policy NF-220 Constitutes Endorsement 3 MARRONE, J. Nuclear Energy Liability Insurance Association 73/12/14 p
- 8007110043 Endorsement 1 to NELIA Policy EB-65
 * Nuclear Energy Liability Insurance Association 78/07/18, 1p
- 8007180404 Responds to 800613 request for addi info re compliance w/financial protection provisions of Atomic Energy Act Forwards proposed Endorsements 43 & 44 to NELIA Policy HERBEIN. J G Metropolitan Edison Co 80/07/14 App
- 8007220584 Responds to NRC 800613 ltr re compliance w/financial protection requirements Proposed endursement provides max protection available from private sources Restoration of limit of liability enforsement encl HERBEIN, J 9 Metropolitan Edison Co 80/07/14 7pp
- P Operating license stage documents & correspondence
- 8007170083 Reports measured tritium concentrations above background levels in groundwater monitoring wells around TMI-2 reactor containment bldg DENTON.H R Office of Nuclear Reactor Regulation, Director SECY-80-181 80/04/08 3pp
- 8007170309 Requests timely review & response to British Nuclear Installations Inspectorate Dec 1979 request for info re TMI-II reactor pressurizer water lovel instrumentation LAFLEUR.J D Office of International Programs, Director. 80/04/28
- BOOA090165 Forwards addi TMI-2 related requirements to operating reactors Licensees requirements for TMI Action Plan include shift manning licensing exams & licensee dissemination of operating experiences Response requested within 30 days EIBENHUT.D 0 Division of Licensing 80/05/07 150pp
- 8005190626 Responds to 80042; request for comments on "Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere," Kryptun gas should be vented into atmosphere on controlled basis w/sufficient advance notice to public APPLEYARD, M H Harrisburg Hosp Harrisburg, PA 80/05/13 lp

- B006:30122 Requests comments on NUREG-0577. Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports "Proposed review procedure & implementation schedule entl
 EISENHUT.D C Division of Licensing 80/05/19 /2pp
- 1007110506 FDIA request for 790401-800530 documents re boron water maintaining subtriticality of facility core & processing & storage of boron water referred to in otil 800130-0228 documents PARSONS,R Friends of the Earth 80/05/30 ip
- 3007180004 Discusses approval of release of Kr-85 from teactor bldg atmosphere by controlled purging Recommends authorization for controlled gurging Draft negative declaration re purging & pross release encl
 DENTON.H R Office of Nuclear Reactor Regulation. Director
 SECY-80-132E 80/05/30 lipp
- --8007180007 "Fine) Environ Assessment for Decontamination of TMI-2 Reactor Bldg Atmosphere." final NRC rept Errata sheet encl TMI Program Office NURFG-0662 VI 80/05/31 104pp Available at NTIS
- --8007180012 Correction notice to SECY-80-132C, adding Table 1 re components presently being used & Office of the Gerretary of the Commission SECY-80-132C BO/05/15 3pp
- 8007010547 Responds to 800429 ltr expressing concern re progueed Kr-85 venting at TMI Method of Kr-85 removal not decided Forwards NUREO-0662. Final Environ Associament for Decontamination of TMI Unit 2 Reactor Bldg Atmos
- --- 8007010555 Requests plans to vent krypton be suspended until UCS study completed
 REED, S.R. Pennsylvania, State of 80/03/29 2pp
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in docay heat removal capability in all modes of operation Hodel Tech Specs which would provide acceptable resolution encl for guidance EISFNHUT.D G Division of Licensing B0/06/11 62pp
- 8007190042 "Radiation Exposure Due to Venting TMI-2 Reactor Bldg Atmosphere "
 FRANKE,B . TEUFEL.D Institute for Energy & Environmental Research
 Heidelberg.W Germany 80/06/12 23pp
- B007140413 Submits info detailing leak testing operation plans, per 800529 toleon Test to be performed 800705-15 & 0725-0804, pending PaDEK approval KLINGAMAN,R M Metropolitan Edison Co 80/06/16 2pp
- B007010290 Forwards comments on rept by Inst for Energy & Environ Research, Heidelberg, Federal Republic of Germany Major conclusions are based on highly inflated estimates of radionuclide releases Supports NURGG-0662 data SNYDER, B J TMI Program Office KREGER, U.E. Assistant Director for Radiation Protection B0/06/23 Spp
- 8907020399 Forwards response to United Kingdom Nuclear Installations Inspectorate request for technical info on reactor pressurtion water level instrumentation DENTON, H.R. Office of Nuclear Reactor Regulation, Director DENTON, H R O 80/06/24 8pp
- B007110272 Forwards Amend 11 to License DPR-73, safety evaluation & notice of issuance & availability SNYDER, B J THI Program (1+fico 80/06/24 4pp
- ---BOD71102BO Amend 11 to License DPR-73, permitting bypass of interlocks from reactor bldg exhaust monitors to dampers while purging to reactor bldg atmosphere SNYDER: B J TMI Program Office BO/06/24 3pp
- --8007110286 Safety evaluation supporting Amend 11 to License DPR-73 # Office of Nuclear Reactor Regulation, Director 80/06/24 4
- -- 8007110292 Notice of issuance & availability of Amend II to License DPR-73 SNYDER.B J TMI Program Office 80/06/24 2pp
- 8007170089 Comments on 800612 rept. "Radiation Exposure Due to Venting TMI-2 Reactor Bidg Atmosphere," by 8 Frank & D Teufel BEYEA, J National Auduborn Society, Central Midwest Reg Office 80/86/24 Spp

The same of the sa

- 8007020534 Requests that site discharge water composite sampling frequencies be changed to once every 24-h for continuous composite sample & once per month for long-term composite sample bate of PA concurs w/change HOVEY, 8 K Hetropolitan Edison Co 80/06/25 2pp
- 8007010460 Requests NRC concurrence in use of Mine Safety Appliances, Co OMR-I & Scott TEDA-R respiratory protection connisters against airborne radioactive matls Lists addl precautions for use of connister Related correspondence encl HDVEY, O K Metropolitan Edison Co 80/06/26 Spp
- 8007100183 Forwards T Gerusky 800624 ltr re water disposal in sampling wells at facility Based on ltr.water may be placed in storm water drainage sys after sampling for analysis Related water broinings was according to the correspondence COLLINS, J T TMI Program Office 80/06/26 App
- --8007100186 Advises NRC that water in sampling wells may be placed in storm water drainage sys after sampling for analysis Water discharges into onsite drainage pond Related Correspondence
 GERUSKY, T M Pennsylvania, State of 80/06/24 lp
- 8007110.293 Forwards PA Dept of Environ Resources 800624 ltr Water from sampling may be placed in storm sewer drainage sys COLLING.J T TMI Program Office 80/06/26 App
- 8007110478 Responds to FDIA request for 790401-800530 documents re boron water maintaining subcriticality of facility core & processing & storage of boron water referred to in util 800130-0228 documents Forwards documents in App A FELTON, J M Division of Rules and Records 80/06/26 3pp
- --8007110489 Summarizes discussions re recommendations concerning boron concentration in facility RCS Doron concentration should be minimized due to possible problems w/valve seating, J0 Herboin draft ltr ecil
 NEWBERRY, S NRC Three Mile Island Task Force 79/08/31 7pp
- --8007110493 "Criticality Analyses of Disrupted Core Models of TMI-2 "
 Excerpts from "Technical Staff Analysis Rept on Alternative
 Event Sequences to President's Commission on Accident at
 TMI." & GE Kulynych 790501 ltr to util encl
 MESIFALL:R H , WEST.J T , WHITEBIDES:O E Oak Ridge National
 Laboratory 79/10/31 118pp
- ---B007110501 Discusses nonconservative ref Keff of (MI-2 core as given in special task force rept. "Evaluation of Cleanup Activities at TMI" Questions re TMI encl PAROTTALC R Transportation Branch B0/04/01 App
- 800/100193 Approves 800ARS Operating Procedure 2104-4 dR re Unit 2 reactor bldg atmosphere cleanup & mode to hydrogen control & containment bldg purge sys per 800612 order for temporary mnd of license BNYDER, B J TMI Program Office 80/06/27
- 8007240158 Advises of approval of proposed procedure & mod to sys for purging reactor bldg SNYDER.B J TMI Program Defice 80/06/27 4PP
- 8007070287 Responds to NRC 800528 ltr re contaminated water in facility containment bldg Clarifies util position on issues re submerged demineralizer sys, solid waste disposal & contingency plan for transfer of untreated water ARNDLD, R C Metropolitan Edison Co 80/06/30 App
- 8007070294 Responds to NRC B00507 ltr re TMI-2 related requirements Items I A i 3,I A 3 i.I C 5,II K 3 & III D 3 4 currently under review for TMI-1 items for TMI-2 will be reported under separate cover HERBEIN.J G Metropolitan Edison Co B0/06/30 2pp
- 8007310299 FDIA request for info re mods to alarm sys in facility reactor bldg venting sys
 TROMBETTA.R Affiliation Unknown 80/06/30 2pp
- BD07220129 Requests participation in recovery activities at site recontaminated water Options presently involve discharge of tritium anto atmosphere No practical means of decontaminating tritium DENTON.HR Office of Nuclear Reactor Regulation, Director 80/07/01 2pp
- 8007070320 Forwards "EPICOR-II Radwaste Sys Linear Integrity & Resin Stability, Preliminary Evaluation," & info summarizing EPICOR-II operation as of 800604, in response to NRC 800515 HDVEY, G K Metropolitan Edison Co 80/07/02 13pp

- --8007070322 "EPICOR-II Radwaste Sys Linear Integrity & Resin Stability, Preliminary Evaluation "

 * Metropolitan Edison Co 80/07/01 35pp
- 8007080358 Forwards 800616 info ltr to PADER, requesting approval to leak test two new tanks at TMI per ETS 5 6
 HERBEIN.J G Metropolitan Edison Co 80/07/02 3pp
- 8007110422 Submits evaluation of EPICOR II waste in response to NRC 800515 ltr Forwards summary rept layout of protective barriers, data for liners, evaluation of liners & resins & drawlings W/o encl HOVEY O K Metropolitan Edison Co 80/07/02 3pp
- 8007140352 Forwards info re EPICOR-II radwaste sys.in response to NRC 800515 ltr Info includes summary rept of sys.layout of protective barriers re liner retention & discussion of liners & resins in use HOVEY.O K Metropolitan Edison Co 80/07/02 49pp
- 8007140419 Forwards info ltr submitted to PaDER, requesting new tank leak test approval per ETB 5 6 2 4 2 W/o sncl HERBEIN, J G Metropolitan Edison Co 80/07/02 2pp
- 8007230001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EIBENHUT, D Q Division of Licensing 80/07/02 67pp
- 8007170373 Forwards water processing & processed water disposition plan for 1980, Revision 2 & 1981, Revision 1, supplementary to rept submitted 800130 M/o plan Dversize drawing, "TMI-1981, Mater Processing Schedule," in Central Files only HOVEY, 0 K Metropolitan Edison Co 80/07/03 ip
- 8007180376 Submits suppl to 800130 water processing & processed water disposition plan for 1980 (Revision 2) & 1981 (Revision 1) One oversize drawing available in Central Files only HOVEY.O K Metropolitan Edison Co 80/07/03 ip
- 8007170456 Discusses preparation of draft programmatic EIB for cleanup & recovery activities at TMI Requests meeting between NRC.
 ANL & util to exchange technical info for input to EIB
 ARNOLD,R C Metropolitan Edison Co 80/07/07 2pp
- 8007230643 Responds to 800624 ltr re change in site discharges water composite sampling frequencies Concurs w/recommendations to raduce sampling frequency of RML-7 continuous composite sampling to 24-h period COLLINS.J T TMI Program Office 80/07/07 App
- 8007190479 Forwards recovery operations plan Change Request 2 re auxiliary bldg & fuel handling bldg ventilation sys surveillance requirements HOVEY.G K Metropolitan Edison Co 80/07/08 lp
- ---BOO7180502 Tech Bpec Change Request 2 for auxiliary bldg & Puel handling bldg ventilation sys flow rate surveillance testing requirements, subsequent to supplementary ventilation sys removal from syc # Metropolitan Edison Co BO/07/08 4pp
- B00717033B Forwards recovery operations plan Change Request 2 re surveillance requirements of auxiliary bldg & fuel handling bldg ventilation sys MCVEY.g K Metropolitan Edison Co 80/07/08 2pp
- --B007170340 Proposed Tech Specs Pages 4 9-1 & 2 re surveillance requirements of auxiliary bldg & fuel handling bldg yentilation sys
 * Metropolitan Edison Co 80/07/08 2pp
- BOO7150507 Responds to NRC/TMI-BO-B9 ltr dtd B00516 requesting addl info re submerged demineralizer sys technical evaluation rept Bpacific responses encl HOVEY.Q K Metropolitan Edison Co B0/07/09 BBpp
- 8007170442 Forwards addl info re submerged demineralization eys, per NRC 800516 ltr Piping & instrumentation & general arrangement oversize drawings encl HOVEY, O K Metropolitan Edison Co 80/07/09 BSpp
- --8007170446 "Piping & Instrumentation Drawing Supply Manifold Submerged Ion Exchangers "
 * Cham-Nuclear Bystems: Inc. 80/01/16 ip

- --8007170452 "Piping & Instrumentation Drawing Contaminated Feedwater
 - Sys " * Chem-Nuclear Systems, lnc 80/01/16 lp
- --8007170455 'Piping & Instrumentation Drawing Monstoring Tank Sys "
 6 Chem-Nuclear Systems, Inc. 80/01/16 ib
- --8007170458 "Piping & Instrumentation Drawing Offgas & Liquid Separation Chem-Nuclear Systems Inc 80/01/16 ip
- --8007170464 "Ion Exchange Flow Sheet "
 * Chem-Nuclear Systems, Inc. 80/0
- 80/01/IA 1n
- -8007170466 "Piping & Instrumentation Drawing 52/-A-03/Intermediate Sampling Sys "
 * Chem-Nuclear Systems, Inc. 80/01/14 ip
- ---8007170473 "General Layout Plum Ion Exchange Equipment "
 * Chem-Nuclear Systems: Inc 80/03/05 ip
- ---8007170478 "Util Flow Diagram "
 * Chem-Nuclear Systems: Inc 79/10/17 lp
- --8007170482 "Piping & Instrumentation Drawing 527-A+02/Beta Monitoring
 - Chem-Nuclear Systems, Inc 80/01/07 ip
- --8007170488 "Ion Exchanger Support Assembly Drawing "
 * Chem-Nuclear Systems. Inc 80/01/23 Ip
- --8007170490 "Piping & Instrumentation Drawing Dewatering Station " * Chem-Nuclear Systems. Inc 80/03/11 ip
- --8007170499 "Pump Removal Instructions For Elfgas Pump & Fepd Pump " * Chem-Nuclear Systems, Inc. 80/03/12 | 1p
- - * Chem-Nuclear Systems, Inc BO/05/05 ip
- --8007170505 "Prefilter 125 Micron" * Chem-Nuclear Systems, Inc. 80/03/18 ip
- --B007170511 "Final Filter 10 Micron " * Cham-Nuclear Systems, Inc. 80/03/18
- --8007170521 "Prefilter/Final Filter Details * Chem-Nuclear Systems, Inc. 80/01/21 1
- ~-8007170533 "Inn Exchanger W/Agitator " * Chem-Nuclear Systems. Inc 80/01/22 ip
- --8007170535 "General Arrangement Solidification Facility TMI
- Recovery " * Chem-Nuclear Systems, Inc. 80/0,3/10 | 1p
- 8007170395 Responds to NRC 800527 ltr re RCS water chemistry & corrosion control Control of dissolved oxygen is maintained by hydrogen overpressurization to ensure that free hydrogen exists in solution to control excepsive amounts of oxygen HOVEY,0 K Metropolitan Edison Co 80/07/11 lp
- 8007210383 Forwards Relovery Operations Plan Change Request 4 Request permits operation of standby pressure control sys w/lower nitrogen bank pressure, to avoid overpressurization of exposed decay heat sys piping
 HOVEY, O K Metropolitan Edison Co 80/07/15 4pp
- BOO7220323 Responds to FOIA request for "Submerged Demineralizer Bys Technical Evaluation Rept " Document available in DC FDR FELTON, J M Division of Rules and Records BO/07/15 ip
- 8007220442 Advises NRC of intention to enter reactor bldg during wk of 800721 to verify inner door operability & gather data on radiation levels & contamination near door NRC will be natified of subsequent entries HOVEY. 9 K Metropolitan Edison Co 80/0//15 2pp
- 8007310406 Forwards Attachment 13.EP1COR II resun irradiation data, as promised in util 800702 ltr lnfo withheld (ref 10CFR2 790)
 HOVEY, G K Metropolitan Edison Co 80/07/16, 2pp

- B007280023 Forwards list of TMI program ofc staff members to be used for ref in future correspondence CDLLINS.R C FMI Program Office B0/07/17 2pp
- 4007310337 Comments on util 800702 ltr discussing preliminary evaluations of résins & liners under postulated conditions Roquests specifics of postulated worst case conditions & datalled projections of duration of safe retention COLLING J T TMJ Program Office 80/07/18 5pp
- 8007300271 Comments on draft, preliminary EIS on cleanup list of all preparers & qualifications should be included Costs should be presented in quantified terms to extent possible, including economic & environ costs

 CHANDLER.L J. Hearing Branch 1 80/07/22 3pp
- 8007310354 Responds to util B00/15 ltr describing changes proposed to reactor bldg entry program following reactor bldg purge Entry preparations are satisfactory NRC approves entry as planned COLLINGS J 7 TNI Program Office B0/07/22 App
- B007310458 Concurs w/use of orbisphere as method to obtain more reliable dissolved oxygen values for RCS Concurrence withheld re-control of dissolved oxygen by hydrogen overpressurization COLLINS.J T TMI Program Office B0/07/22 App
- 8007300447 Advises of intent to purge reactor bldg atmosphere on routing basis Purge will be conducted w/Procedure 2104-4 91, using modified purge sys Total weekly releases will not access 72 Ci Kr-85
 HDVEY, 0 K Metropolitan Edison Co 80/07/24 lp
- BOO7310285 Responds to FOIA request for info re mods to alarm sys in facility reactor bidg venting sys Forwards document detailing info subj to request FELTON.J M Division of Rules and Records BO/07/25 ip
- --80073103iO Describes preparation for & procedures used to purge Kr-85 from facility reactor align atmosphere Purging continued at various sys flow rates based on meteorological conditions

 * Commission 80/07/25 2pp
- 8007310439 Forwards "TM1-2 Radiation Protection Plan.Revision 2." for final NRC approval Revised plan sets forth radiation protection policies & philosophies of Met Ed & General Public Utils Curp radiatological controls program W/O encl ARNOLD.R C Metropolitan Edison Co 80/07/25 2pp
- 8007280087 "NRC Plan for Cleanup Operations at TMI Unit 2 " * TMI Program Office NUREG-0498 80/07/31 25pp
- O Inspection reports. IE Bulletins & correspondence
- 8007100009 Forwards combined IE insp Repts 50-320/79-29 & 50-289/79-21 on 791023-1127 & notice of violation GRIER, B H Region 1, Philadelphia, Office of the Director 80/01/09 3pp
- --B007100012 Notice of violation from insp on 791023-1127

 * Region 1, Philadelphia, Office of the Director 79/12/20 lp
- --B007100014 Combined IE Insp Repts 50-320/79-29 & 50-289/79-21 on 791023-1127 Nonrompliance noted failure to store & control licensed matls in unrestricted areas WHITEL JR , VUMAS, GP , MCGAUGHY, R W Region i, Philadelphia, Office of the Director 79/12/20 15pp
- 8007100002 Forwards Waste Packaging Insp Rept 15000046/80-04 on BOD107-88 No noncompliance noted BHITH, Q H Region 1. Philadelphia, Fupl Facility & Materials Safety Branch B0/03/24 2pp
- --B007100003 Waste Packaging Insp Rept 15000046/80-04 on 800107-18 No noncompliance noted Major areas inspected waste shipments for compliance w/DOT & NRC regulations including vehicle placarding, package marking & condition of packages THOMAS.R D. PECK. C & Region I, Philadelphia, Office of the Director BOOK H E Region I. Philadelphia, Fuel Facility & Materials Safety Branch 80/03/25 7pp
- 8007020161 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required ORIER, B H Region 1, Philadelphia. Office of the Director 80/05/28 lp

- 8007010315 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required GRIER.I H Region 1. Philadelphia. Office of the Director 80/05/29 1p
- 8007210572 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/10 1p
- 8007160349 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs No specific action or response required GRIER.B H Region i, Philadelphia, Office of the Director 80/06/11 ip
- 8007020715 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/18 ip
- 8007020526 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER BH Region 1. Philadelphia, Office of the Director BO/06/20 1p
- B007160708 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER B H Region 1. Philadelphia. Office of the Director B0/06/24 ip
- 8007210202 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.B H. Region i. Philadelphia, Office of the Director 80/04/25 ip
- B007230129 Forwards IE Bullstin B0-16, "Potential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Writton response required IE Circular 80-16 also encl No written response required ORIER, B H Region i, Philadelphia, Office of the Director B0/06/27 2pp
- B00716043i Forwards evaluation & submittal schedule for all IE bulletin responses per util B00529 ltr & in response to NRC B00417 request Responses to IE Bulletins 79-10 & 80-09 encl. HDVEY, 0 K Metropolitan Edison Co B0/07/09 7pp
- 8007220485 Forwards list of recovery mode surveillance procedures reviewed & results per util 800519 commitment Sufficient administrative controls to assure compliance present in all but BP4303-M3 ARNOLD-R C Metropolitan Edison Co 80/07/10 lOpp
- R Periodic operating reports & related correspondence
- 8007020182 Forwards THI Program Off weekly status rept for wk of 800614-20 COLLINS, J T TMI Program Office 80/06/23 App
- 8007150053 Forwards status rept for wk of 800621-28 GOLLINS, J T TMI Program Office 80/06/30 7pp
- B007180102 Forwards status rept for wk of 800621-28 COLLINS.J T TMI Program Office 80/06/30. Spp
- 800717044R Forwards status rept for wk of 800629-0705 CDLLING.J T TM1 Program Office 80/07/07 7pp
- 80071B0539 Forwards TMI Program Off weekly status rept for wk ending 80070B CDLLINS.J T TMI Program Office 80/07/07 20pp
- 8007250719 Forwards status rept for wk of 800706-12 CDLLING.J T TMI Program Office 80/07/14 App
- 8007210359 Forwards "TMI-E Recovery Quarterly Progress Rept," for period ending 800630 Rept available in Central Files only HOVEY, C K Metropolitan Edison Co 80/07/15 ip
- 8007310136 Forwards weekly status rept for 800713-19. Liquid effluents from Unit 1, released to Busquehanna River: were within Tech Spec limits No liquid effluents discharged from Unit 2. COLLING, J T 781 Program Office 80/07/21. Spp

- 8 Reportable occurrences. LERs & related correspondence
- 8007010454 Forwards LER 80-020/01L-0 Metropolitan Edison Co 80/06/26 1p
- --800701045B LER 80-020/01L-0 on 800522, during containment entry, violation of containment integrity occurred via bulkhead makeup valve E Caused by procedural deficiencies Procedures CHAPLIN.8 D Metropolitan Edison Co 80/06/26 4pp
- BOO7250207 PNO-TMI-BO-036 on BO062B, purging of reactor bidg is scheduled to start at 8 00 AH CONTE,R J. FARAND, A. Region i, Philadelphia, Office of the Director COLLINS, J. TMI Program Office 80/06/27 lp
- 8007250201 PNO-TMI-80-037 at 8 00 AM on 800628, purging of reactor bldg atmosphere was started Purge was stopped after 4 minutes due to high particulate alarms CONTEX J. FASANO. A Region 1, Philadelphia, Office of the Director COLLINS, J. T. TMI Program Office 80/06/29 ip
- 8007140522 Forwards LER 80-024/03L-0 HOVEY, O K Metropolitan Edison Co 80/04/30 1p
- --8007160525 LER 80-024/03L+0 on 800529.while in recovery made of operations, pressure transducer used to monitor RCB pressure was isolated from RCS w/o control room knowledge Caused by deficient SUP Valve reopened within Tech Spec action period CHAPLIN.8 D Metropolitan Edison Co 80/06/30 2pp
- BOO7250214 PND-TMI-80-038 on BOO629, purging of reactor bldg atmosphere was resumed To increase sensitivity of stack monitor for particulates, addl instrumentation was installed CONTER.J. FASANO.A Region 1. Philadelphia, Office of the Director COLLINS.J T TMI Program Office 80/06/30 ip
- 8007250231 PNO-TMI-80-038A on 800701, purging of reactor bldg atmosphere continued at various flow rates based on meteorological conditions Momentary shutdowns also occurred due to stack monitor filter changeouts
 GONTE.R.J. FABAND.A Region 1, Philadelphia, Office of the Director COLLINS.J.T. TMI Program Office 80/07/01 1p
- 8007250237 PNO-TMI-80-0388 on 800702 purging of reactor hldg atmosphere continued at various flow rates based on meteorological conditions Scheduled shutdown lasting 5-h occurred for computer maint CONTE, R J , FASANO, A Region i, Philadelphia, Office of the Director. COLLINS, J T TMI Program Office 80/07/02 ip
- 8007170547 PND-TMI-80-038C on 800703, purging of reactor bldg atmosphere continued Shutdown occurred due to loss of sample pump for effluent monitor, Replacement pump was installed & purging CONTE,R J , SHANBAXY,M M Region i, Philadelphia, Office of the Director COLLING,J T TMI Program Office 80/07/03 ip
- BOO7170540 PNO-TMI-BO-D3BE on BOO707, purging of reactor bldg atmosphere continued Momentary shutdowns occurred due to stack monitor filter changeouts CONTE, R J, SHANBAKY, M M. Region 1, Philadelphia, Office of the Director COLLINB, J T TMI Program Office 80/07/07 ip
- BOO7160596 RD BO-27/1P deluge valve closed to preclude actuation of modified hydrogen purge filters & reactor pldg purge exhaust filter fire protection deluge Caused by omission of footnote from Tech Bpacs allowing closing.

 HOVEY, G K Matropolitan Edison Co 80/07/08 1p
- 8007170553 PNO-TMI-80-038F on 800708, purging of reactor bldg atmosphere continued At approx & 20 AM, sys was shut down due to high alarm on purge sys monitor noble gas channel Reason for alarm is under review CONTE, R J , SHANBAKY, M M. Region 1, Philadelphia, Office of the Director COLLINS, J T TM1 Program Office. 80/07/08, ip
- B007150513 Forwards LER 80-025/03L-0 Metropolitan Edison Co 80/07/09. Ip
- ---B007150514 LER B0-028/CGL-O on B00407, reactor coolant inlet temp meter on remote shutdown monitoring instrument panel found inoperable Caused by instrument failure, Replacement ordered & voltmetor temporarily installed CHAPLIN.B.D Metropolitan Edison Co B0/07/07 2pp
- 8007190515 Forwards LER 80-023/03L-0 HQVEY, O. K.: Metropolitan Edison Co 80/07/09 1p.

- ~-8007150519 LFR 80-023/03L-0 on 800403, boron concentration in boric acid ou/190519 Let MU-023/03L-V on MUMBULIBORON concentration I mix tank found exceeding Tech Spects Caused by evaporation from use of temporary air spange, mixing apparatus Boron solution diluted & regular tank mixer returned to svc CHAPLIN.S D Metropolitan Edison Co BO/07/03 2pp
- 8007170564 PNO-THI-80-0380 on 800709, purging of reactor bldg atmosphere continued at various flow rates Momentary shutdowns occurred due to stack monitor filter changeouts CONTER J. SHANBAKY.M M Region i. Philadelphia. D
- 8007230158 PNS-1-80-018 on 800709, licensie received telephone bomb threat Licensee conducted full scale search w/negative results ATLEY,R , MARTIN,W Region 1, Philadelphia, Office of the Director 80/07/09 1p
- B007170557 PND-TMI-80-03BH on B00710, purging of reactor bldg was shut down at 1 45 AH so that reactor bldg air samples could ,R.J. SHANBAKY,M M. Region i, Philadelphia, Dffice of the tor COLLINS,J.T. TMI Program Office 80/07/10 ip Director
- BOO7230237 Part 21 rept re cracked atomm generator manuou studs Satisfactory operating experience forms.constitute reasonable basis for continued operation while investigations proceed TAYLOR.J H Babcock & Wilcox Co 80/0//11 5pp
- BOO7240203 PND-TMI-BO-381 on BOD711.purging of reactor bidg atmosphere continued until approx 10 00 AM when purge sys was shutdown because licenses declared purge complete CONTE, R J . SHANBAKY, M M . COLLINB, J T TMI Program Office BO/07/11 ip
- BOO7240118 PMD-TMI-BO-040 on BOO716, inner door for reactor bldg personnel airlack 2 was successfully opened Upon closure of door, seal rangs for door failed loakage test CONTE,R J , COLLINS, J T TMI Program Office 80/07/16 is
- BOO7230218 PND-TMI-80-040A on 800716, reactor bldg personnel airlock inner door failed seal leakage tast While inner door was open Radiation surveys were taken inside reactor bldg near CONTE.R J. FASANO, A N. COLLINS, J.T. TMI Program Office 80/07/17
- 8007230434 RO 80-30/1P on 800717, surveillance testing of inner personnel arriock containment door indicated that leakage past inner door seals exceeded Tech Spec limit Subsequent surveillance testing of outer door was satisfactory HOVEY,O K Metropolitan Edison Co BO/07/17 lp
- 8007230439 RO 80-29/IP on 800714, while performing surveillance procedure 4303-Mi6, Gray balance of plant diesel generator failed to start Caused by problem w/100 speed switch Replacement parts have been ordered HOVEY, 9 Metropolitan Edison Co 80/07/17 2pp
- 8007290811 Forwards LER 80-026/03L-0 HOVEY.O K Metropolitan Edison Co 80/07/18 1p
- -8007270817 LER 60-026/03L-0 on 800618, during recovery mode, Unit 2 fire pump removed from svc Unit 1 pump discovered unaligned to fire suppression header Caused by personnel error Procedures revised to reflect permanent valve 1]neop change CHAPLIN,S D Metropolitan Edison Co 80/07/18 2pp
- T Hearing transcripts on non-antitrust matters
- 8007030345 Transcript of 790803 interview of D Sternberg in Bethesda. MD Pp 1-86 STERNBERG, D Region 5. San Francisco, Office of the Director 9696
- 8007030334 Deposition of RW Heward of General Public Utils, by NRC/TMI Special Inquiry Group on 790925 in Parsippany, NJ Pp 1-55 HEWARD R W General Public Utilities GPU Service Corp 79/09/25
- 8007030342 Transcript of 800610 continuation of discussion of facility yanting in Mashington, DC Pp 1-25 Marning session Related draft memorandum & orders encl * Commission 80/06/10 43pp

- 7140005 Transcript of B00630 conference call between parties Aldowo Instrict the book to conference can between parties issussing public hearing requests re 800612 order for emporary mod of license to allow reactor bldg purging DLF.J.F. Atomic Safety and Licensing Board Panel TROWBRIDGE, G.F. atropolitan Edison Co. CHANDLER, L.J. Hearing Branch 1 80706/30
- 7140222 Franscript of 800707 prahearing conference in Harrisburg, PA Atomic Safety and Licensing Board Panel 80/0//07 87pp
- 7180041 Transcript of 800707 public meeting in Washington.DC to iscuss TM1 action plan. Chapter V Pp. 1-37 Supporting matl Commission 80/07/07 58pp
- 7140219 Transcript of 800/OB prehearing conference in Harrisburg. Atomic Safety and Licensing Board Panel 80/07/08 36pp
- 7240254 Corrected transcript of 800708 prehearing conference in arrisburg,PA Pp 86-119
 Atomic Safety and Licensing Board Penel 80/07/08 36pp
- Congressional/Executive Correspondence
- 9240395 Responds to 790423 ltr to President re TMI-2 accident everal groups are investigating TMI-2 accident & huclear ower Assures that NRC will take necessary actions to nsure public agety
 ENDRIE J M Commission 79/08/02 9pp
- 5200252 Responds to 800404 request for info re EJ Sternglass paper. Infant Mortality Changes Following TM Accident "Analysis fradrobiological, epideminlogical & physiological aspects indicate no scientific validity to Sternaglass allegations IRCHS.N J Gffice of the Figurity Director for Operations 0/04/29 ip
- 7020303 Discusses status of actions my cleanup activities in esponse to 800327 ltm concerning proposed Kr-85 release HEARNE, J.F. Commission 80/06/04 2pp
- 0070P0313 Comment: on proposal to vent Kr-85 from containment bldg should identify all future problems & possible solutions that may arise in other phases of cleanup operation Offers support in Seeking technical or scientific advice THORNBURGH, D. Pennsylvania, State of 80/05/16 3pp
- 007020323 Expresses concern that NRC may permit venting of krypton gas from reactor in manner that may endanger public physical & mental health NRC should extablish independent panel of scientists to evaluate derisions re facility cleanup MENNEDY.E M Senate 80/03/27 2pp
- 7110363 Expresses interest of Environ, Energy & Natural Resources ubcommittee in TMI accident implications Commissioners are noted to 800702 public hearings to present NRC policy takement & discuss intervenors' limitations
- 17140050 Provides Subtommittee on Energy & Water Development w/info e reprogramming actions for approval Includes priorities & tatus items.reprogramming analysis.neur-term OL tosks & YBO base table M/o encl HEARNE.J F Commission BO/OA/25 2pp
- 007140062 Provides Subcommittue on Energy & Mater Development w/infore reprogramming actions for approval Includes priorities & status items.reprogramming analysis.near-term OL tasks & FY80 base table W/o encl
 AMEARNE.J F Commission 80/06/25 52pp
- 17230557 Supply previous responses to FGIA request for written ommunications between NRC & Congress since 800322 reactlity Forwards A Myers 800303 ltr to V Stello Info wartially withheld list of questions (ref FGIA Exemption 7) ELTON, J N Division of Rules and Records 80/07/17 ip
- 3007230565 Forwards questions concerning failure of util employees to provide govt officials w/certain significant info during early stages of facility incident Questions withheld (ref FDIA Fremption 7) MYERS, H House of Rep . Interior & Insular Affairs 80/05/05

- DOCKET 50-301 EDWIN I HATCH NUCLEAR PLANT, UNIT 1 F Security, medical, emergency & fire protection plans
- 8007020488 Forwards request for addl info re 800528 revised guard training & qualification plan Encl withheld (ref 10CFR2 790) REID.A W Operating Reactors Branch 4 80/06/19 200
- BOO7230104 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices NRC wishes to interview security mgt personnel at facilities EISENHUT, D O Division of Licensing 80/07/tl 2pp
- 8007280514 Advises that 800718 emergency plan upgrading per NUREO-0654 uill be delayed until 801001 Requests rept from 800422-23 Emergency Preparedness Team review WIDNER:W A Georgia Power Co 80/07/21 1p
- 9 Adjudicatory correspondence
- B007310243 Forwards Commission B00327 memorandum & order containing decisions on UCS 780302 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENHUT, D O Division of Licensing 80/06/25 69pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I owners group in Bethesda, MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 31pp
- 8007140841 Advises that dates of responses to 790927 generic 1tr were 791025 for Peach Bottom 2 to 3 to 791115 for Hatch 1 to 2 Rept on valve operability program required only for plants desiring to justify unlimited purging VERRELLI,D M Operating Reactors Branch 4 80/06/05 1p
- 8007010474 Advises that util will comply w/800307 ltr issuing five addl TMI-2 related requirements for operating reactors When implementation criteria is developed, NRC will be notified of any variation from schedule Ruserves three options WIDNER, W.A. Georgia Power Co. 80/06/20 ip
- B007020628 Advises that review has been completed on 800513 rept of calibr results on seismic instrumentation Triaxial Time-History Accelerograph. 2L51-NDQI was returned to vendor for repair as recommended MANRY. M Georgia Power Co 80/06/25 1p
- 8007090389 Notification of 800703 meeting w/utzl in Bethesda.MD to discuss util basis for delayed schedule for installing Trquenchers VERRELLI, D Operating Reactors Branch 4 80/06/26 2pp.
- 8007080287 Discusses applicability of GE response to questions raised by C Michelson, in response to NRC 800807 request Automatic isolation may occur for breaks outside or inside containment depending on break size & location WIDNER, W A Georgia Power Co 80/06/30 2pp
- BOO70B0322 Application for amend to App A of License DPR-57, submitted as proposed changes to Tech Specs re diagnostic test program for HPC1 sys

 WIDNER, W A Georgia Power Co BO/07/02 3pp
- ---8007080327 Propused amend to Tech Specs 3 5 8 2 & 4 5 D 1.allowing one time diagnostic test program of HPCI sys

 * Georgia Power Co 80/07/02 1p
- BOO7180506 Confirms D Verrelli BO0702 telcon w/CT Moore authorizing temporary amend to Tock Specs revising limiting conditions for operation of HPCI sys to perform operation BO0702-09 w/inoperable HPCI for diagnostic & rellability testing NOVAK.T M Division of Licensing BO/07/03 2pp
- BOD7180494 Confirms util commitments at 800703 meeting Te schedule for completing mods for resolution of Mark I containment long—term program Meeting summary encl
 REID:R W Operating Reactors Branch 4 B0/07/07 2pp
- --80071804B7 Summary of 800703 meeting w/util re licensee schedule for completing muss for resolution of Mark I containment long-term program VERRELLI.D M Operating Reactors Branch 9 80/07/07 6pp

1

- 8007230656 Provides info re new ofc titles, positions & assignments of personnel resulting from 800428 reorganization of Ofc of Nuclear Reactor Regulation Assistant Director for Operating Reactors 80/07/10
- 8007280634 Application to amend Licenses DPR-57 & NPF-5, changing Tech Specs re torus water temp If water temp cannot be restored within 24-h.reacter shall shutdown using normal shutdown procedures WIDNER,W A Georgia Power Co 80/07/17
- --B007280642 Proposed Tech Specs Sections 1 0 & 3 7 re torus water temp If water temp cannot be restored within 24-hiteactor shall shutdown using normal shutdown procedures * Georgia Power Co 80/07/17 9pp
- B007310336 Requests written confirmation of 800718 telcon recritical situation concerning electrical power generation in region served by util NOVAK.T M Assistant Director for Operating Reactors 80/07/22
- 9 Inspection reports. IE Bullatins & correspondence
- 8007240213 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8007140490 Forwards IE Bulletin 80-13. "Cracking in Core Spray Spargers " Written response required O'REILLY, J.F. Region 2. Atlanta, Office of the Director 80/05/12
- B007020178 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28
- 8007010220 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- B007100064 Forwards IE Insp Repts 50-321/B0-22 & 50-366/B0-22 on B00412-0512 No noncompliance noted LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/05/29 2pp
- -8007100066 IE Insp Repts 50-321/80-22 & 50-366/80-22 on 800412-0512 No PO/100060 It Insp Repts 50-32/180-22 & 50-366/80-22 on 800412-0512 noncompliance noted Major areas inspected Tech Spec compliance. ROS, housekeeping, plant operations, GA practices & IEB Bulletin 79-26 DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch ROGERS, R F Region 2, Atlanta, Office of the Director ROGERS. Branch ROGERS, R F 80/05/30 5pp
- 8007220072 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10
- 8007140294 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/12
- 8007020736 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06. Region 2. Atlanta, Office of the Director 80/06/18
- B007020298 Forwards notices of violation & proposed imposition of civil penalty re IE insp on 800319
 BTELLO, V Office of Inspection & Enforcement, Office of the Director B0/06/19 2pp
- --800702030] Notice of violation from insp on 800319 Noncompliance noted packages of licensed maths shipped on 800318 w/radiation levels in truck cab exceeding regulatory limit # Office of Inspection & Enforcement, Office of the Director 80/06/19 19
- --8007020305 Notice of proposed imposition of civil penalty in amount of #4,000 re violation noted during 800319 insp # Diffice of Inspection & Enforcement, Office of the Director

- 8007090074 Requests retension to 2002/H to complete response to Items 1 & 2 of IE Bolletin 80 10 "confiamination of Non-indicattive Sys & Resulting Potential for Observational Uncontrolled Rolesse of Radioartisty to Excited HOVE/19 to HOVE/19 to Proceed a Power Co. HOVE/19 to
- 8007140180 Discusses 800319 inclident which revealed radiation levels exceeding limits on truck cab arriving at Barowell bits Forwards notice of violation ! notice of proposed imposition of civil penalty STELLO.V Office of inspection & foreicement, effice of the Director BO706/19 dpp
- 8007020450 Forwards 1E Circular 80 15 Toks of Rearter (notable Pump Gooling & Natural Circulation (nothern No written coupins) O'REBLY, J.P. Region & Atlanto Delice of the Director 80706720
- B007110250 Ack receipt of 1000:00 ltr informing NRC of stops takes to correct violation noted in 15 Inop Repts 50 54780 19 5 50-36780-19 BTOHR, J.P. Rogics 2, Atlanta, Foel Facility & Naturials Nafoty 80705721 10
- --B007110259 Responds to NRC H00MP Its re-violation noted in IC lump Repts 50-321/80-19 & 50-365/80 19 Corrective actions full audit of emergency plan % implementing procedure: completed WIDNER W A Georgia Power to UP/06/04 1p
- --8007110262 Forwards If Imap Repts 50 \$21780 19 % 50 486/80 19 ms 800421-29 & matrix of violation STORG J.P. Region 2. Atlanta: for Unitarity & Notesials Hadety Branch 80/09/12 dpp
- ---BOD7110260 Notice of violation from in p on BO04-1

 * Region 2, Atlanta, Office of the Daretto | December | 00/05/44 ta
- -8007110276 IF Insp Ropes 50 SHIZHO IV 5 50-06740 IV on HOOAPI in Noncompliance noted failure to add to energency implementing procedures every 2 yra under conductors of agency invited PERROTTION OF TRUSHABUSKIA Region P. Atlanta, Office of the Director Staking OR Royson P. Atlanta, fool Carilly b Materials Safety Branch BOZOPZIP Sup
- 8007300576 Forwards IE Tosp Repts 50 3/1780 14 5 50 366710 14 on 800319,0427 & 30 Enforcement action discussed in NRC 000619 O'RETILY, J.P. Rugson P. Attanto, tiffice of the Director
- ~-8007300980 If. Imap Repts to J21780 to 5.50 Mod/80 to an H80119, bay to 30 Noncompliance noted radiation tevels on vehicle cab in excess of regulatory limits. STOMES P. MODEMUTIR C. Region ? Atlanta, Lord Carillety & Materials Safety Branch. LACLY: H. Region ? Atlanta, Office of the Director. 80706/19. Bpp.
- BOD/170115 Forwards IF (litula) 80-14 "Radioactive Contamination of Plant Demineralized Water Sys & Resoldant Internal Contamination of Personnel " No writte response required G'REILLY, J.P. Region 2, Atlanto (1811) of the Director (180/06/21
- 8007230247 Forwards II Welletin HO 16. "Perontral Broapplication of Resemble Inc Medels 1191 5 1192 Private Transmitters WEITHER A OF D Detpil Codes." Written response required IC Circular 80-16 also one No oritten response reported O'REILLYJE Region & Atlanta Office of the Breetin HO/NAS 100 Above C
- 8007220:81 Submits final response to H Bulletin 70 Hr Nuise evaluations performed for indexemble accord following traballation of evaluation wigners visual marriang lights will be installed during Fall 1980 (excepting outage WIDNER, W.A. Georgia Power on (60706730) ip
- 800709034) forwards into in response to Items to the P. s required by H. Bullotin BO-11. "Masonry Whit Derign " flem Pho to be addressed in final rept. Hebridge (he) Constant Found to the MIDNER, W.A. Groupia Power see the 2020/2021 Tipe.
- B007140384 Responds to 18 Belietin 80 Office containment liner penetration weld exam Requerts 30 day extension for including submittal due to targe number of Flued food containment liner penetrations & heavy high princity work load WIDNER, W.A. Georgia Power (a. 80/07/07 1)

```
07280126 Ack receipt of 800623 itr informing NRC of steps taken to
correct deviations noted in IF Insp Repts 50-321/80-02 &
50-366/80-02
MURPHY, C.E. Region & Atlanta, Reactor Construction & Engineering
Support Branch 80/07/09 ip
8007280128 Responds to NRC 800208 % 0411 ltrs rc deviations noted in
IE Insp Repts 50-321/80-02 & 50-346/80-02 Corrective
actions submitted encl draft engineering roviow of QA fire
protection program at NRC 800602 meeting
WIDNER.WA Georgia Power Co 80/06/23 42pp
07240252 Ack receipt of 800Ai2 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-17 & 50-36/80-17 D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/07/11
8007240264 Responds to NRC 800519 ltr re violations noted in IE Insp
Repts 50-321/60-17 & 50-366/80-17 Corrective actions new
airlock scheme installed Actions re event & deviation
reportability justified
WIDNER, W.A. Georgia Power Co. 80/06/12 App
8007240277 Forwards IE Insp Repts 50-321/80-17 & 50-366/80-17 on
800208-0411 & notice of violation
LEHIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support
Branch 80/03/19 2pg
8007240285 Natice of yielation from insp on R00308-0411
Region 2. Atlanta, Office of the Director 80/05/
                                                                                                                                                                       80/05/19 2pp
B007240272 IE Insp Repts 50-321/80-17 % 50-366/80-17 on 800308-0411
Nuncompliance noted failure to maintain secondary
containment door integrity & to meet NRC reporting
    concainment door integrity a to meet NRC reporting requirements
ROGERS.R F Region 2, Atlanta, Office of the Director DANCE Region 2, Atlanta, Reactor Operations Nuclear Support Granch 80/05/19 Spp
07230292 Responds to IE Bulletin 80-17, "Failure of Control Rods to
ully Insert " Scram discharge vol (SDV) vent & drain
operability verification test performed All drain & vent
valves verified operable No residual water found in SDV
WIDNER,W A Georgia Power Co 80/07/11 lp
07310275 Responds to NAC B00619 notice of violation re excessive radiation exposure rate inside cab of raduaste transport vehicle Radiation survey indicated radiation levels within code requirements Requests mitigation of violation severity WIDNER.W A Georgia Power Co 80/07/14 2pp
8007310287 Responds to NRC 800619 notice of proposed imposition of civil penalty Radiation survey of vehicle indicated levels within code requirements Requests mitigation of severity of violation & reduction of civil penalty WIDNER.W A Georgia Power Co 80/07/14 2pp
07310597 Submits summary of events in response to IE Bulletin 80-17
LPCI inverter R44-5003 declared imagerable twice Normal
supply breaker to 4 kV bus IF tripped, placing bus on
alternate feed
4ANRY, M Georgia Power Co 80/07/14 2pp
07220422 Responds to IE Bulletin 79-14. "Spismic Analysis for As-
Juilt Safety-Related Piping Syr " Requests ditension until
Bol001 to complete verification of prismic analysis, based on
Spogress made & number of ROs
4IDNER,W A Georgia Power Cn 80/07/15 2pp
07280538 Advises of proposed componentury measures re 2-wk
extension for scram testing required for IF Bulletin 80-17
left will perform tests as soon as possible should critical
load situation ease
AIDNER, W.A. Georgia Power Co. 80/07/19 1p
07280541 Advises of completion of Items 1 & 2 of IE Bulletin 80-10. 
"Contamination of Normadioartive 8ys " Complete 
Jocumentation of affected sys & associated munitoring 
Impocedures available for leview during future onsite imags 
AIDNER.W A Georgia Power Co 80/0//18 ip
```

07290618 Requests delay in performing scram tests required by IE Bulletin 80-17 dup to high temps in region Romaving large units from svc would plact scypie strain on electric generating capacity of region WIDNER.W A Georgia Power Co 80/07/18 2pp

```
R Periodic operating reports & related correspondence
 8007280678 Forwards monthly operating repts for June 1980 MANRY.M Georgia Pawer Co 80/07/10 lp
  ~-8007280680 Monthly operating rept for June 1980
BLACKWELL,R M Georgia Power Co BO/07/10
  --B007280686 Forwards monthly operating repts for June 1980 MANRY:M Georgia Power Co 80/07/10 1p
  --$007280692 Monthly operating repts for June 1980
BLACKWELL.R M Georgia Power Co 80/07/10 7pp
  S Reportable occurrences. LERs & related correspondence
 8007110285 RO-50-321/1980-61 on B00622, while preparing to run RHR sys, "B" RHR loop min flow manual valves were discovered closed Caused by failure to return to open position after loop was taken out of shutdown cooling mode Valves locked open MANRY, M Georgia Power Co 80/06/23 Ip
 8007030276 Forwards LER 80-065/03L-0
MANRY, M Georgia Power Co 80/06/24
  --B007030278 LER 80-065/03L-0 on 800614, while inerting primary
containment nitrogen storage tank was found to contain less
than 2,000 gallons nitrogen Caused by increased use of
           nitrogen
BAXLEY.8 X Georgia Power Co 80/06/24 2pp
 8007030261 RD on 800522, licensee reviewed Kinemetrics, Inc 800513 calibr
rept re seismic instrumentation Triaxial Time-History
Accelerograph 2L51-NO21 calibr indicates excessive change
in longitudinal channel characteristics
MANRY,N Georgia Power Co 80/06/25 1p
  8007030284 Forwards LER 80-062/01T-0
MANRY M Georgia Power Co 80/06/25 1p
  --8007030286 LER 80-062/01T-0 on B00612, w/Unit 1 in cold shutdown,
           investigation was begun to determine cause of pavemen deflection which occurred beneath crane outrigger pad Caused by improper compaction of localized area COGOIN.C L Georgia Power Co 80/04/25 2pp
 8007020638 Forwards LER 80-056/03L-0
MANRY.M Georgia Power Co 80/06/27 1p
 --B007020642 LER 80-056/03L-0 on 800205 standby gas treatment sys
ventilation & valve operability procedure changed on 800122,
had not been PRB reviewed or approved within 14 days as
required by Tech Spec Caused by person
 8007:110307 RO 50-321/1980-069 on 800626. Following auto initiation signal. HPCI failed to inject to reactor pressure vessel due to isolating on steam line high DP isolation signal Cause under investigation Reset isolation & opened inboard valve MANRY. M Georgia Power Co 80/06/27 1p
8007110400 Forwards revised LER 80-055/01X-1
MANRY, M Georgia Power Co 80/06/30 1p
    -8007il0403 Revised LER 80-055/01X-1 on 800531, while performing insp of
snubbrrs.45 out of 61 were found locked up Caused by
internal corrosion Snubbers replaced
* Georgia Power Co 80/06/30 2pp
 8007110304 Forwards LER 80-080/03L-0
MANRY.M Georgia Power Co 80/07/01
   --B007110313 LER B0-060/03L-0 on B00603.w/reactor in cold shutdown, insprevented two hanger mods to HVAC room sprinkler required for saismic qualification were incomplote Caused by failure to implement hanger mod sketches contrary to procedure HNP-B09 COGGIN.C L Georgia Power Co 80/07/01 2pp
8007110432 Forwards LER 80~051/01T~0
MANRY,M Georgia Power Co 80/07.
                                                                            80/07/01 1p
---B007110442 LER B0-061/01T-0 on B00422, while preparing to run RHR sys
per HNP-1-6006, operator discovered loop B min flow manual
valves Ei1-F018 B & D closed Caused by operator closing
valves to prevent reactor water from going to torus
BAXLEY.9 X Georgia Power Co G0/07/01 3pp
```

1 1

```
B007110368 RD 50-321/80-076 while reviewing as-builts submitted per
IE Bulletin 79-14.util discovered hangers IE11-RHRH-196 &
IE11-RHRH-313 would not adequately support loads during DBE
Caused by faulty design in incorrect valve weights
MANRY, M Georgia Power Co B0/07/02 2pp
                                                                                                                                                                                                                                                                               B007170414 Forwards LER 80-069/01T-0
MANRY,M Georgia Power Co 80/07
                                                                                                                                                                                                                                                                                     -8007170419 LER 80-049/01T-0 on 800626, after reactor scram, HPCI failed
                                                                                                                                                                                                                                                                                            to inject to reactor pressure vessel per auto initiation signal due to isolating on oteam line high DP Caused by turbine controls being out of dynamic calibr COGGIN.C L Georgia Power Co 80/07/10 2pp
8007110455 Forwards LER 80-072/03L-0
MANRY, M Georgia Power Co 80/07/02 1p
--8007110463 LER 80-072/O3L-0 on 800624, reactor bldg went radiation monitor sample pump failed in run mode at 2426 MWt Caused by swelled carbon wanes Pumps will be switched out more often to minimize moisture buildup & improve reliability ROGERB,W H. Georgia Power Co. 80/07/02 2pp
                                                                                                                                                                                                                                                                               8007210370 Forwards LER 80-076/017-0
MANRY-M Georgia Power Cu 80/07/14 Ip
                                                                                                                                                                                                                                                                               --B00721037; i.ER 80-076/017-0 on B00701, while reactor was at hot standby for HPCI/reactor core isolation cooling testing, site notified by AE that listed RHR supports would not adequately support all design based loads C0031N.C.C. Georgia Power (o 80/07/14 2pp
8007110415 Forwards LER 80-063/03L-0
MANRY, M Georgia Power Co 80/07/03 1p
--8007110424 LER BO-063/03L-O on 800512, while performing surveillance procedure HNP-1-3102, reactor high prossure shutdown cooling mode switch 1831-NO188 found to actuate higher than limit Caused by setpoint drift Switch recalibr NIX.R T Georgia Power Co 80/07/03 2pp
                                                                                                                                                                                                                                                                               B007210384 RO on B00711. Unit 1 LPCI invertes tripped & Unit 2 4-kV bus PF supply breaker & HPCI tripped Supply breaker trip caused by jumper missing from neutral leg Nator valve on HPCI repleced making it operable Events submitted per IEB 80-17 MANRY, M Georgia Power Co H0/07/14 2pp
8007150539 Forwards LER 80-059/03L-0
HANRY, M Georgia Power Co 80/07/03 ip
                                                                                                                                                                                                                                                                              H007210484 Forwards LER 80-078/03L-0
MANRY.M Georgia Power Co 80/07.
                                                                                                                                                                                                                                                                                                                                                                                    60/07/14 1p
--8007190544 LER 80-059/03L-0 on 800617, approx 2-h after performing suppression chamber to drywell vacuum breaker sys operability test closed indicating light for valve IT48-F323F found extinguished Cause unknown Testing continues NIX,R T Gaorgia Power Co 80/07/03 2pp
                                                                                                                                                                                                                                                                               --B007210492 LER 80-078/03L-U on 800630 & O/Ol.during hot standby aperation.primary containment oxygen concentration exceeded limit Coused by reactor bldg to torus vacuum breaker valve opening & oxygen analyzers not calibr Monitoring increased BAXLEY.S X Georgia Power (o. 80/07/15 2pp
8007150496 Forwards LER 80-064/03L-0
MANRY, M Georgia Power Co 80/07/08 ip
                                                                                                                                                                                                                                                                               8007220514 Forwards LER 80-080/03T-0
MANRY-M Georgia Power Co 80/07.
                                                                                                                                                                                                                                                                                                                                                                                 80/07/17 1p
                                                                                                                                                                                                                                                                                    -8007220519 LER 80-080/03T-0 on 800706.w/reector in hot standby &
 --8007150508 LER 80-044/03L-0 on 800613.during startup, reactor core
             isolation cooling sys initiated to maintain reactor water
level.but failed to respond to speed control Caused by EGR
not responding & limit switch being out of adjustment
NIX,R T Georgia Power Co 80/07/08 2pp
                                                                                                                                                                                                                                                                                            reactor water cleanup in normal operation,water found
coming from cleanup line insulation, due to crack in heat
affected ione of spool pince Cause unknown Piece replaced
COGGIN.C L Georgia Power Co 80/07/17 2pp
8007150666 Forwards LER 80-066/03L-0
MANRY, M Georgia Power Co 80/07.
                                                                                                                                                                                                                                                                               8007280448 Forwards LER 80-067/03L-0
                                                                                                                                                                                                                                                                                                                                                                                    80/07/17 1p
                                                                                                         80/07/08 1p
                                                                                                                                                                                                                                                                                                                     Georgia Power Co
                                                                                                                                                                                                                                                                               --8007280449 LER 80-067/03L-O on 8006.99, during diesel generator manual start procedure. B generator tripped Cause undertermined Probable cause is spurious alarm or crankcase gressure Generator proved operable & returned to svc NIX.R T Georgia Power Co 80/07/17 2pp
--B007130474 LER B0-046/03L-0 on 800615, diesel generator 10 declared inoperable when low air pressure alarm received w/reactor in run mode Caused by valves failing in unloaded mode. Unloader valves replaced & air receivers returned to proper pressure NIX.R T Georgia Power Co B0/07/08 2pp
8007170382 Forwards LER 80-058/03L-0
MANRY, M Georgia Power Co 80/07.
                                                                                                                                                                                                                                                                               B007280445 Forwards LER 80-075/03L-0
MANRY-M Georgia Power Co 80/07
                                                                                                        00/07/08 1p
---8007170387 LER 80-058/03L-0 on 8006i6 three addl control rod driveline accumulators declared inoperable Caused by hydraulic control units not maintaining nitrogen pressure due to cartridge valve ici1-Fiil leaking at stee packing NIX.R T Georgia Power Cn 80/07/08 2pp
                                                                                                                                                                                                                                                                               --B0072B0446 LER B0-075/03L-0 on B00626, w/mode switch in run, primary containment temp recorder, [T47-R611, found to be intermittently failing to print Coused by commutation motor gearbox failure Balancing arm imagnetic switch repaired NIX:R T Deorgia Power Co. 80/07/22 2pp
                                                                                                                                                                                                                                                                               B007280572 Forwards LER 80 081/03L-0
MANRY: M Georgia Power Co 89/07/22 1p
H007170392 Forwards LER 80-068/03L-0
MANRY, M Georgia Power Co 80/07/08 1p
                                                                                                                                                                                                                                                                               --8007280568 LER 80-081/031-0 on 800705 w/made switch in run.drywell pressure recorder IT48-R608 found inoperative Redundant recorder IT48-R609 was operable Caused by component failure Transmitter repaired, recalibr & returned to svi.

NIX.R T Grorgia Power (o 80/07/22 ip
 --8007170408 LER 80-068/03L-0 on 800619,1P33-R601 drywell dihudrogen/
              MILE TO SERVED THE STATE OF THE SERVED THE S
8007170491 Forwards LER 80-073/03L-0
MANRY, M. Georgia Power Co. 80/07/08 1p
                                                                                                                                                                                                                                                                               8007280629 Forwards LER 60-077/09L-0
MANRY,M Georgia Power Co. 80/07/22 1p
     -8007170463 LER 80-073/03L-0 on 800624.w/reactor at 100% power, drywell to torus temp recorder noted not stamping or changing position Caused by faulty stepping advance & chart drive motors Repaired & replaced motors

NIX.R T Georgia Power Co 80/07/08 Ppp
                                                                                                                                                                                                                                                                               --B007280640 LTR 80-077/03. O on Ano/OB during high reactor pressure instrumentation Punctional test % calibr found that pressure switch 1821-NB276 attuated in excess of Tech 9pecs Caused by setpoint duriff Suitch recallur & successfully tested NIX/R I Georgia Power Co 80/07/22 Zpp
                                                                                                                                                                                                                                                                               8007280682 Forwards 1ER 80-07070 8-0
MANRY-M Georgia Power Co 80707722 1p
--B007280690 IER 80-070/03 U on B006P6.during hanger insp on class one piping snubber 1841-MPSE H13 discovered to have oil leak Caused attributed to seal leakings on snubber failed snubber
```

NIX-R T Georgia Power to BO/07/22 2pp

- 107300392 Ferwards LER 80-074/03L-0 MANRY M Georgia Power Cu B0/07
- 8007300513 | ER 80-074763L-0 on 800626, following reactor scram reactor core isolation cooling failed in inject to reactor pressure vessel when manually started Laused by intermittent operation of NAMCO DI2000 limit switch or GE HFA relay CDGOIN, C L Georgia Power Co 80/07/24 2pp COGGLEG C. L.
- DOKET 50-322 SHOREHAM NUCLEAR POWER STATION
- Application/construction stage documents & correspondence
- 007030239 Notification of 800702 meeting w'BWR licensing review group in Bethesda,MD to discuss consenses position on reactor eve bldg open issue WILSON, J. N. Licensing Branch 1 80/06/18 9pp
- OO7010397 Summary of 800613 meeting w/utils,KMC, Inc. OE. Bechtel, S&W & Sargent & Lundy in Bethesda,MD re conscisus positions on reactor svc bldg & isolation cooling sys bldg open issues from La Salle docket Status repts encl
 WILSON,J N Assistant Director for Licensing 80/06/19 46pp
- 007210176 Forwards NRC evaluation of GE tupt.NFDE-24010-P & Suppls 1-3. "Technical Basis for Use of Square-Root-of-Sum-of-Bquares (SRSS) Nethod for Combining Dynamic Loads for Mark II Plants "Rept acceptable sub; to certain ronstraints MATTSON.R J Division of Safety Technology 80/06/25 3pp
- -8007210189 Inpical rept evaluation of NEDE-24010-P t Supple 1-3, "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable w/exception of Criteris * Mechanical Engineering Branch 80/09/31 8pg
- 007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0666 and the found of the following the following the following the following the following the following following the following followin
- 007170475 Summary of B00613 merting w/Mark II lead plant applicants re definition of T-quencher load spec following safety/ relief value autuation Viewgraphs enci SULT M Containment Systems Branch B0/06/27 App
- 007230252 Summary of 800613 meeting w/Mark II lead plant applicants re methodology proposed by applicants to define T-quencher load spec following safety relief valve actuation New methodology will be applicable to all Mark II lead glants SU.T M. Generic Issues Branch. 80/06/27. 3pp
- 007170339 Notification of rescheduling of B00702 meeting w/BWR licensing review group in Dethesda, MD to discuss consensus positions on Reactor Sys Branch open issues Meeting rescheduled for B00709 WILSOR, J N Assistant Director for Licensing 80/07/03 ip
- -8007170347 Notification of 800782 meeting w/RHR licensing review group in Bothesda.MD to discuss TNJ issues required for OL 1 ssuance
 - WILSON, J N Assistant Director for Licensing 80/07/03 1p
- ~8007170351 Notification of 800724 meeting w/BWR licensing review group in Bethesda.ND to introduce BWR licensing review group & present consensus gositions for Power Sys Branch.Containment Sys Dranch & Equipment Qualification Branch WILSON.J N Assistant Director for Licensing 80/07/03 9pp
- 10072:0189 Forwards requests for additinfo in connection w/util application for OL Info needed in areas of mechanical engineering.power sys & instrumentation & control TEDESCO.R L. Assistant Director for Licensing 80/07/03 2 . 80/07/03 24pp
- 007230521 Bupmary of 600513 meeting m/Mark II owners group in Bethesda. ND re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation be chapging pool boundary loads Viewgraphs encl ANDERSON.C J. Generic Issues Branch 80/07/03 57pp
- 1007180655 Submits comments on NUREC-0619, "DWR Feedwater Northe & Control Rad Drive Raturn Line North Cracking " Mod should be made in Table ... "Routine Inst Intervals" re two piston ring seals & Clad removal on Page 18
 NDVARPO, J.P. Long Island Lighting Co. 80/07/08 3pp
- 2007.240466 Notification of 8007.22 mreting w/util in Bethesda.MD to discuse status of non-TMI open (sauge WILSON, J. M. Licenting Branch 1 80/07/09 3pp

- BOO7230133 Notification of 800725 meeting W/BMR Licensing Review Group in Bethesda/ND to discuss concensus positions of BMR Licensing Review Group on ICSB open issues WILSDN/J N Licensing Branch 1 80/07/14 10pp
- 8007250569 "Final Rept on Reactor Vessel Repair" * Long Island Lighting Co 80/07/17 120pp
- 8007230450 Forwards "Design Criteria & Description Technical Support NOVARROJ P Long Island Lighting Co 80/07/21 1p
- --8007230462 "Design Criteria & Description Technical Support Ctr " + Long Island Lighting Co 11600 02 80/07/22 19pp
- B007250175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago. II. to discuss lead Mark II plants chugging & C/Q load specs ANDERSON.C Generic Issues Branch 80/07/23 2pp
- F Security, medical, emergency & Fire protection plans
- 8007140519 Notification of 800801 meeting w/util in Silver Spring, MD re evaluation of recent revisions to facility security plan WILSON, J N Licensing Branch i 80/06/26 3pp
- O Adjuditatory correspondence
- 8007030083 Notice of appearance in proceeding Certificate of Svc encl FARLEY-A F Long Island Lighting Co FARLEY,A F Hunton & Williams 80704/12 3pp
- 8007090304 Response to NRC & Shoreham Opponents Coalition 800404 DOTOYOUGHA Response to NMC & Shoreham Upponents Coalition BOOOOG
 stipulation Contentions 2 & 8 are adequately particularized
 Contentions 1 & 12 must be modified Contentions 7(a)(ii),10
 & 11 inadequate Certificate of 9vc encl
 REVELEY,W T, EARLEY,A F Long Island Lighting Co REVELY,W T
 Hunton & Williams 80/06/17 9pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protoction for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- 8007020584 Order rejecting NRC & Shoreham Opponents Coalition 800606 stipulation as submitted on 800612 States status of OL proceeding Contentions 1.2.7(a)(11).8,10 & 12 Joint request for extension until 800606 granted BDMERS, £ 8 Atomic Safety and Licensing Board Panel 80/06/26
- B007020606 Order accepting util.NRC & Buffolk County third stipulation recertain of Buffolk County contentions Agrees w/NRC B00611 interpretation of Footnote 2 BOMERS.E B Atomic Safety and Licensing Board Panel B0/06/26 ip
- 8007080204 Order admitting Shoreham Opponents' Coalition Contention 12, Subpart 3 in OL proceeding, as within guidelines of Commission 800316 memorandum & order issued in TMI-1 restart proceeding, CLI-80-16
 BOMERS, C.S. Atomic Safety and Licensing Board Panel 80/07/02
- 8007080059 Forwards documents on loan basis in response to request made during Shoreham 800617 meeting TREE-NURE0-1200.DNL-NUREQ-23364.NURE0/CR-0462 & NURE0/CR-0274 presently unavailable but will be provided when located W/a encl BORDENICK.B M Hearing Branch 4 80/07/03 4pp
- B007i60601 Forwards LER printout re passive mechanical valve failures, in response to Dec 1979 request concerning County Contention 4a(xi) Forwards ACRB latest repts on generic issues re County Contention 3(a)(i) & (ii) W/o encl BORDENICK, B M Hearing Branch 4 80/07/11 2pp
- 80071703B4 Mption to defer briefs re Commission 800620 policy statement, in response to ASLB 800626 order, until 801031.
 Process re particularization of contentions, should continue prior to writing briefs Certificate of Svc encl REVELEY, W T Long Island Lighting Co REVELEY, W T Hunton & Williams, 80/07/11 7pp
- B007160593 States no objection to applicant 800711 motion to defer briefs on Commission B00620 statement: BORDENICK.B M Hearing Branch 4 80/07/14 1p

ł

H General correspondence

- 8007180042 Responds to 800123 ltr re NRC approach to emergency planning around nuclear plants Commission endorsed NUREG-0394 for development of state & local radiological plans Exact configuration of iones will be decided during plant review DENTON, HR Office of Nuclear Reactor Regulation, Director 80/06/03 2pp
- --8007180047 Requests that NRC amend proposed regulation re formulation of evacuation plan to include all territory east of facility Proposed 10-mile radius is unworkable for people of Long Island Responsible plan should be developed BEHAN, J.L. New York, State of 69/01/23 ip
- 8007210032 Responds to 800520 ltr re NRC reneging on agreement to send representatives to Suffolk County Legislature 800528 meeting Fiscal limitations & other priorities may occasionally prevent requested attendance EISENHUT, D & Division of Licensing 80/06/13 ip
- 8007240008 Forwards NUREO/CR-1215.NUREO/CR-1243 & NUREG/CR-0131.in response to 800617 verbal request Kemeny rept not available for distribution Cleanup FIS not yet issued NUREG-0662.Vols 1 & 2 & NUREG-0588 sent separately M/o encls BORDENICK.B M Hearing Branch 4 80/07/22 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007070243 Forwards Amend 36 to OL application, submitted as Revision 18 to FSAR Affidavit encl NDVARRO, J P Long Island Lighting Co 80/06/27 2pp
- --8007090245 Revision iB to FBAR, incorporating responses to NRC requests submitted in ltrs SNRC-465,-469,-473 & -480 & clarifying portions of FBAR * Long Island Lighting Co 80/06/27 275pp
- B00723089B Certifies syc of Amend 36 to OL application in form of Revision 1B to FBAR, on 800707 MORIN.J P Long Island Lighting Co B0/07/14 ip
- Q. Inspection reports. IE Bulletins & correspondence
- 8007140458 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers" No written response required CRIER, B H Region 1, Philadelphia, Office of the Darector 80/05/12 ip
- 8007010280 Forwards IE Info Notice 80~23, "Loss of Suction to Emergency Feedwater Pumps " No writton response required GRIER B H Region 1. Philadelphia, Office of the Director 80/09/29 ip
- B007170283 Forwards IE Insp Rept 50-322/80-07 on B00422-24 No noncompliance noted. CARLSON.R.T Region in Philadelphia, Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --8007170288 IE Insp Rept 50-322/80-07 on 800422-24 No noncompliance noted Major areas inspected 8C program for work progress, outstanding items & bulletins & circulars status and NARRON, L. Region 1, Philadelphia. Office of the Director MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/28 4pp
- 8007210571 Forwards IE Info Notice BO-R6, "Evaluation of Contractor GA Programs " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director. BO/G6/10 1p
- 8007140278 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required ORIER, B. H Region 1, Philadelphia, Office of the Director BO/06/12 ip
- 8007280394 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 85(e)," No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/13, ip
- 8007020307 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required. GRIER, B H Region i. Philadelphia. Office of the Director 80/06/20, ip

- 8007160704 Forwards II. Chirular 80-14, "Radioartive (ontamination of Plant Demineralized Mater Sys 's Resultant Internal Contamination of Personnel " No written response required ORIER, DH. Region i Philadeiphia, Office of the Director 80/06/24 ip
- 8007140863 Ack receipt of 800862 ltr informing NRC of steps taken to correct violations noted in IE Investigation Rept 50-322/79-24
 CARLSON 7 T Region 1 Philadelphia, Reactor Construction & Engineering Support Dranch (20/06/25) ip
- --BD07160967 Responds to NRC 00042B Itr re-violations moted in IE Investigation Rept 50-3.27/9-24 Corrective actions defective welds were identified & removed MOFFORD.A W Lung Island Lighting Co. 80/06/02 .2pp
- B007210199 Forwards JE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER, B H. Region 1, Philadelphia. Office of the Director B0704725 ip
- 8007230128 Forwards 1E Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Eithur A or D Output Coder." Written response required IE Circular 80-16 also encl No written response required GRIER. B H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- BOD7210033 Ack receipt of BO0416 ltr informing NRC of staps taken to correct violations noted in IE Insp Rept 90-322/79-07 Analysis of raceway/cable stapsation requested due to continued noncompliance CARLSON, R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch 30/07/01 2pp
- --8007210040 Responds to NRC 791226 ltm re violation noted in IE Insp Rept 50-322/79-07 Corrective action independent analysis performed to ensure prevention of feature shutdown or decay heat removal Takes pixception to insp finding NOVARROLJ P Long Island Lighting Co. 80/04/16. 3pp
- 8007310527 Submits summary of events in response to 16 Bulletin 80-17 LPCI inverter R44 5003 declared inoperable twice Normal supply breaker to 4 kV bus 2f tripped placing bus on alternate feed MANRY.M Georgia Power Co 80/07/14 2pp
- # Reportable occurrences, LERs to related correspondence
- 8007020066 Ack roreipt of 780822 final significant deficiency rept re GE 4160 volt rircuit breakers CARLSON,R T Region 1, Philadolphia, Reactor Construction & Engineering Support Branch 78/09/14 2pp
- --8007020073 final significant deficiency rept re failure to electrically close circuit breaker Caused by wearing of driving pawl elecve bearing All breaker muchanism Tuf-loc sleeve bearings will be replaced w/aluminum-bronze bearings BURKE.T J long Island Lighting Co 78/08/22 3pp
- 8007290448 Part 21 rept re potential interference in full function of Bergen-Paterson strut assembly w/Parific Scientific Comechanical shock acrestor (ustumers will be notified of affected items & recommended solution
 BECKSTED,W F Bergen-Patterson Pipe Support Corp 80/06/20 5pp
- 8007140390 Followup deficiency rept to loose limit switches on GC circuit breakers (aused by mounting screws backing out Screws will be secured w/std strength lock-tite & insp will be revised NOVARRO, J P ! ong Island Lighting (o 80/07/01 3pp
- DOCKET 90-029 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction *tige documents & correspondence
- 8007080343 Notification of 800623 meeting w/util in San Luis Opispo.CA to discuss task action plan items
 BUCKLESS C. Licensing Branch 2 80/06/20 App
- 8007020394 Forwards nonproposation versions of previously submitted general Westinghouse proprietary less to support position on guide tube when characteristics Requests as knowledgement of receipt CRANE, P.A. Parific Gas & Fleitril Co. 00/06/23 lp.

- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 - EISENHUT, D G Division of Licensing 80/06/26 2pp
- 8007070153 Forwards Revision 1 to "Description of Sys Interaction Program for Seismitally-Induced Events," originally submitted 800527 CRANE,P A Pacific Gas & Electric Co 80/07/01 1p
- --8007070206 Revision 1 to "Description of Sys Interaction Program for Seismically-Induced Events" * Pacific Gas & Electric Co. 80/06/10 79pp
- 8007160392 Forwards Std Order for DOE Work, "Sys Interaction Support for Diable Canyon." issued to LLL ROSS.D F Division of Systems Integration FIN A-0248-0 80/07/07
- --8007160395 9td Order for DDE work "Sys Interaction Support for Diable Canyon." issued to LtL GRENIER.D (Iffice of Standards Development, Director FIN A-0248-0 80/07701 App
- 8007230027 Notification of B00718 meeting w/util in Bethesda.MD to review auxiliary feedwater sys reliability study BUCKLEY.B C Licensing Branch 3 80/07/08 4pp
- 8007280089 Summary of B00617-19 site visit w/NRC.util & two intervenors re audit of sys interaction program for seismically-induced events Program is sound & can be satisfactorily completed Independent walkdown description encl
 THOMAS.C O Systems Interaction Branch 80/07/09 Bpp
- B007160520 Forwards draft Operating Procedure OP-38, "Anticipated Transient W/o Trip," per AC Thadani request Procedure should not be considered part of dorket file supporting QL application

 CRANE.P A Pacific Gas & Electric Co BO/07/10 ip
- --8007160521 "Anticipated Transient W/o Trip," emergency operating Pacific Gas & Electric Co BO/06/07 5pp
- 800723020B Discusses augmented low power startup test program for near-term OL applicants Each applicant must perform tests similar to TVA proposed program President Carter 791207 statement on Komeny Commission rept entl EISENHUT, D.G. Division of Licensing 8 90/07/11 600
- 8007180340 Forwards Revision 2 of "Description of Sys Interaction Program for Seismically-Induced Events " CRANE, P A Pacific Gas & Electric Co 80/07/15 ip
- -8007180344 Revision 2 to "Description of Sys Interaction Program for Seismically-Induced Events" * Pacifit Gas & Electric Co 80/07/09 77pp
- 8007250550 Notification of 800725 meeting w/util in Bethesda.MD to discuss auxiliary feedwater sys Meeting originally scheduled for 800718
 BUCKLEY.B C Licensing Branch 3 80/07/27 5pp
- B007310397 Advises that R McMullen response to Question 9 of ASLAB-598 accurately reflects USOS position Ambiguities in location of carthquake require conservative assumption that all faults have earthquake potential MORRIS.R H Interior.Dept of, Geological Survey B0/07/29 ip

eport (SCR), supple & correspondence

์เจ 5pp

irector NUREG-0675 89

on plans

ning & qualification

/11 1o

- G Adjudicatory correspondence
- B007030040 Request for participation in security plan hearing per ABLB 791116 order admitting State of CA in OL proceeding Participation will assist in adequacy & workshillty assessments Notice of appearance & Certificate of Svc encl BROHN, H H . KLINE, J A California, State of BROHN, H H Hill Christopher & Phillips B0/06/11 9pp
- 8007140026 Ack receipt of Commission BOO611 memorandum & order, CLI-80-24, on behalf of San Luis Obispo Mothers for Peace Adheres to prior position re Commissioner Hendrie participation in all aspects of UL proceeding re seismic & safety issues

 JONES, Y I Jones, Grey & Bayley 80/06/18 2pp
- 800710019B Expresses appreciation for NRC permission allowing joint intervenor representatives to participate in 800617-19 sys interaction audit at util NRC has demonstrated willingness to assure public participation Related correspondence FLEISCHARER, D S Fleischaker, D S 80/06/25 1p
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp
- 8007300419 Notice of appearance in proceeding Certificate of Svc encl GEDRGIOU. N S Collfornia, State of 80/06/30 4pp
- 8007070123 Advises of stipulation in DL proceeding, eliminating legal argument re wording of affidavit of mondisclosure & public dissemination of info Governor Brown of State of CA did not take part in stipulation TOURTELLOTTE. J Hearing Branch 4 JONES, Y , NORTON, B Pacific Gas & Electric Co 80/07/02 2pp
- 8007110002 Order granting extension until 800722 for Commission to alect to review decision on enforcement action request, Dp-80-22 HOYLE, J C Office of the Secretary of the Commission 80/07/08
- BOQ7180405 Motion for OLs permitting fuel loading initial criticality process & low power testing Proposed operation may be conducted during appeal from ALBG 790787 partial initial decision W/documentation.affidavit & Certificate of Svc CRANE, P A Pacific Ons & Electric Co OCHR.A C Snell & Wilmer NORTON. B Bruce Norton 80/07/14 13pp
- B007220092 Memorandum & order amending & reissuing ASLAB B00403 protective order re security plan Governor of CA request for participation as interested state granted w/certain conditions Sets timetable for future proceedings BIBHDP.C J Atomic Safety and Licensing Appeal Panel 80/07/15
- --8007220103 Amended protective order permitting limited access to Ban Luis Obispo Mothers for Peace & Governor of CA re security plan info Amended affidavit of nondiscissure encl BISHOP, C J Atomic Safety and Licensing Appeal Panel 80/07/15.
- B00723050B Request for reconsideration of ASLAB B00624 decision.ALAB-59B, or certification of M Trifanac & E Luco testimony on 791015 ingerial Valley earthquake Urgas appropiation of funds to facilitate testimony Certificate of Svc encl FLEISCHAKER,D B, JOINSTON,M P, PHILLIPS,J San Luis Obispo Mothers for Peace 80/07/17 App
- 8007310466 Notice of PC Valentine & YI Jones withdrawal & WA Baldwin designation as lead counsel in proceeding Certificate of Svt enci VALENTINE,P C , JONES,Y I San Luis Obispo Mothers for Peace 80/07/18
- 8007230536 Motion to change lead counsel designation from JR Tourtellotte to MJ Dimstead Notices of MJ Olmstead & LL Swartz appearances. JR Tourtellotte withdrawal & Certificate of Svc encl DLMSTEAD, W.J. TOURTELLOTTE. J. Hearing Branch 4 80/07/21 6pp
- 8007300110 Notice of appearance in proceeding LANPHER.L C California, State of LANPHER,L C Hill Christopher & Phillips 80/07/25 ip

, 1

- 8007250429 Statement in support of joint intervenors' 800717 request for reconsideration of ALAB-598,or for certification of question re Mihailo.Trufunos & Enrique independent views, to Commission Urges funding for Trifunac & Luco BROWN,H H , KLINE.J A , GEOROIOU,B S California. State of 80/07/24 2pp
- BO07300096 Request by joint intervenors for extension until 800804 to respond to applicant motion for low power testing license Counsel out of town Certificate of Svc encl FLEISCHAKER. D S San Luis Obispo Mothers for Peace FLEISCHAKER. D S Fleischaker, D S JOHNSTON. M P Center for Law in the Public Interest 80/07/25 4pp
- B007310461 Discusses handling & delivery of sensitive security math between parties ULMSTEAD.W J Hearing Branch 4 80/07/28 2pp

H General correspondence

- 8007140024 FOIA request for NRC insp rept for Atomics Intl, info concerning TMI incident & status of licensing proceedings for facility Newspaper articles encl MILLER, T Affiliation Unknown 80/05/08 App
- 8007140016 Ack receipt of encl & informs recipient about progress & expectation of required cultural & historical mitigation program Ltr forwarded to NRC for consideration NIELBEN, A D Interior, Dept of 80/06/18 3pp
- 8007010063 Expresses regret that failure to add Society for Environ Awareness to mailing list for weekly public announcements on facility, resulted in necessity to duplicate request Addition made to distribution list INDRAM.F L. Office of Public Affairs 80/06/20 1p
- 8007140021 Responds to FDIA request for NRC insp rept re Atomics Intl. info concerning TMT incident & status of licensing processings for facility Forwards of Stein 800228 memo. Sept 1977 EIA & 770980 SER W/EIA & SER cover sheets only DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/82 Rpp
- 8007010457 Opposes granting license for low level testing for util, due to health & safety concerns re emergency planning, radiation monitoring & safety issues based on TMI No testing should be allowed until conversion possibilities explored CLUCAB, J A League of Momen Voters of San Luis Obispo, CA BO/Q6/24 ip
- 8007090218 Requests that NRC deny CL to facility Too much emphasis placed on possible earthquakes along Hosgri Fault & not enough concern on entire area of instability Conditions create distinct possibility for furmation of more volcances BNAPP.C Affiliation Unknown 80/07/01 ip
- B007250277 Responds to 800605 ltr re RH Leddy concerns about proximity of Hosgri Fault to site & ability of facility to withstand severe earthquake Fault is 3 5 miles from site Matter of smissic situation currently pending before ASLAB DIRCKS.W.J Office of the Executive Director for Operations 80/07/02 App
- --8007250284 Requests response to eacl RH Leddy concerns about preximity of site to Hosgri Fault LAGOMARBINO,R J House of Rep , Foreign Affairs 80/06/05 3pp
- 8007290647 Urges that NRC dany DLs for facility due to proximity to Hosgri fault & to protect health, safety & welfare of people of CA ALLEN.B D Affiliation Unknown 80/07/21 2pp
- G. Inspection reports: IE Bulletins & correspondence
- 8007280697 Forwards response to IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Loss of power to Class IE buses is audibly & visually indicated by control room annunciator CRANE,P A. Pacific Gas & Electric Co 80/04/15 12pp
- B007R40187 Responds to IE Bulletin 80-04. "Analysis of PWR Main Stram Line Break W/Continued Feedwater Addition " Review results indicate no potential for containment overpressure or worsening of return to power response CRANE,P A. Pacific Gas & Electric Co 80/04/20 2pp
- 8007020242 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required ENGELKEN,R. H. Region 5. San Francisco. Office of the Director 80/05/28 ip

- B007220237 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required FNGELKEN,R H Region 5, San Francisco, Office of the Director 80/66/10 1p
- 8007290086 Forwards 1E Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CPR\$0 55(e) " No written response required ENDELKEN.R H Region 5. San Francisco. Office of the Director 80/06/13 ip
- 8007250658 Responds to IE Nuiletin 79-25, "Fallures of Westinghouse BPD Relays in Safety-Related Sys "Subj relays not used or planned for use in safety-related sys at plant CRANE,P A Parific Gas & Electric Co 80/06/16 ip
- 8007030017 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (FNS) W/Loss of Offsite Power" Written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/18 ip
- 8007020474 Forwards | E Cirrolar 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Cirrolation Cooldown" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/04/20 | ip
- 8007180287 Forwards 1E Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENVELKEN,R H Region S. San Francisco. Défire of the Director BO/06/24 ip
- 8007230385 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes "Written response required IE Ctrcular 80-16 also encl No written response required ENGELKEN.R H Region 5, San Francisco: Office of the Director 80/06/27 lp
- BOO73002BO Responds to IE Bulletin BO-03 re vacuum damage to chemical vol control tank sys All five tanks protected against failure under vacuum conditions RCS drain tank designed to withstand external pressure of 15 paig
 CRANE.P A Pacific Gas & Electric Co 80/07/07 2pp
- 8007310321 Forwards IE Insp Repts 50-275/80-14 & 50-323/80-07 on 800601-20 No noncompliance noted CREMS.J L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 80/07/10 Epp
- --B007310327 IE Insp Ropts 50-P7b/B0-14 & 50-323/80-07 on B00601-20 No noncompliance noted Mayor areas inspected preoperational testing; plant tour, feel storage, operator training & witnessing of testing in progress
 YDUNO, T , BAOAOLID M Rogion 5, San Francisco, Office of the Director STERNBERG, DM Region 5, San Francisco, Reactor Operations Nuclear Support Branch 80/07/03 3pp
- DOCKET 50-324 BRUNSWICK STEAM ELFCIRIC PLANT, UNIT 2 F Security, medical, emergency 'Fire protection plans
- 8007010324 Informs NRC that util will submit revised emergency plan in Aug 1980 Implementing procedures for emergency plan will be developed by 801201 & complete plan implemented by 810101 per NURG-0654 requirements

 UTLEY.E C Carolina Power & Light Co 80/06/27 ip
- 8007010342 Advises that add) info or safeguards contingency plan which was requested in NRC 800527 ltr will be submitted by 800801.
 UTLEY-E C Carolina Power & Light Co 80/06/27 lp
- 8007170555 Notifies that intuke structure basement areas at facilities have been selected as possible test subj to conduct tests on fire protection sys in response to NRC 800523 order Requests agreement to participate in program EISENHUT. D O Division of licensing 80/07/08 Opp
- G Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D 0 Division of tirensing 80/06/25 89pp.

- H General correspondence
- 8007020198 Responds to 800516 ltr re Kudiu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors. Shearon Harris const to assure conformance w/requirements. Levels of confamination from Directic to public DIRCKS W J. Office of the Executive Director for Operations. 80/04/18 2pp
- --800702021/ Requests response to encl Kudzu Alliance 800512 itr commenting on ability of util to safely utilize nuclear ANDREWS I House of Rea #0/05/15 2am
- P Operating license stage decuments & correspondence
- 8007230028 Summary of 800707 meeting w/Mark I owners group in Betheada. MD, we revisions to NRC acreptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 Jipp
- 8007010423 Forwards responses to NRC 800507 request for evaluation of applicability to facilities of 0E 800221 responses to concerns provided by ACRS consultantic Hischelson, re-addl THI-2 related requirements UTLEY,E F Carolina Power & Light Co 80/06/27 App
- G007210415 Discusses 790531 commitment to installation of mods required by Mark I containment program during 1980 & 81 Complete incomporation of NRC input into GE load definition rept scheduled for mid-Jul 1980 UTLEY.E C Carolina Power & Eight Co 80/07/14 2pp
- 8007270723 Submits additinfoire adequacy of station electrical distribution sys voltage in response to NRC 800516 ltr Infofor incomplete Items 2 & 3 wilt be submitted by 801024 & 2020. 0926, respectively
 UTLEY.E E Carolina Power & Light Co 80/07/24 7pp
- 8007290163 'Electrical, Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Bignals.Brunswick Steam Cleetric Plant.Unit 2 " UDV, A.C. EG&O Idaha.Inc. FIN A-6286 8007290163 80/07/31 13pp
- 9 Inspection reports. IE Bulletins & correspondence
- 8007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Bease Unit | While in Refueling Mode " No response required D'METLLY, J P Region 2 Atlanta, Office of the Director 80/05/08
- 8007140489 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spengers " Written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/05/12
- 8007020187 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs 'No written response required B'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010179 Forwards IF Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps ' No written response required 0'REILLY.J P Region 2. Atlanta, Office of the Director 80/05/29
- 8007170420 Forwards 1E Insp Repts 50-324/80-16 & 50-325/80-19 on 800512-16 No noncompliance noted LEWIS.R C Region 2, Atlanta Reactor Operations Nuclear Support Branch 80/08/06 2pp
- --8007170429 1E Insp Repts 50-324/80-16 & 50-325/80-19 on 800512-16 No own/104er to insp Repts 30-344/80-16 & 30-327/80-19 on 800512-16 No noncompliance noted Major areas inspected maint surveillance & calibr of Tech Spec-related equipment & support equipment MESSITT, U R Region 2, Atlanta, Office of the Director UPRIGHT, C K Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/06/05 6pp
- 8007220040 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required O'REILLY, J.P. Region 2: Atlanta, Office of the Director 80/06/10
- 8007140289 Forwards IE Duiletin 80-14, "Degradation of BWR Scram Discharge Vol Capability" Written response required O'REILLY J.P. Region 2. Atlanta. Office of the Director 80/06/12 2pp

- 8007020745 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (CNS) W/Loss of Offsite Power" Written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/18
- B007020440 Forwards IE Circular 80-15, "Loss of Roactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/04/20
- 8007100354 Ack receipt of 800610 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-324/80-10 &
 - Correct Visiations (Mark Construction & Engineering MARPHY, C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 80/06/24 1p
- ---8007100367 Atk receipt of 800512 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-324/80-10 & 50-325/80-11 Per 800522 telcon, supplemental response should be provided by 800613 MNRHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/23 ip
- --B007100377 Responds to NRC B00418 ltr re violations noted in IE
 Insp Repts 50-324/80-10 % 50-325/80-11 Corrective actions
 diesel engine insp was purformed by manufacturer Periodic
 test implemented & scheduled for fire doors
 TOLLISON, A.C. Carolina Power & Light Co. 80/05/12 4pp
- --B007100384 Forwards IE insp Repts 50-324/80-10 & 50-325/80-11 on B00331 & 0401-03 & notice of violation MURPHY.C E Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/04/18 2pp
- --B007100395 Notice of violation from insp on B00331 & 0401-03
 * Region D. Atlanta, Office of the Director B0/04/19
- --8007100378 Notice of deviation from insp on 800331 & 040j-03 * Region 2, Atlanta, Office of the Director 80/04/18
- --8007100413 IE Insp Repts 50-324/80-10 % 50-325/80-11 on 800331 & 00/100413 IE Imps Repts 50-324/RO-10 to 00-325/RO-11 on 800331 & 0401-03 Noncompliance noted inadequate surveillance proceedings for fire protection sys & inadequate review of fire protection Tech Spec violations COM.ON.T E Region 2. Atlanta. Reactor Construction & Engineering Support Branch MILLER, W H Region 2. Atlanta. Office of the Director 80/04/18 9pp
- 8007160800 Forwards IE Circular 80-14, "Radioartive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/24
- B007010425 Forwards refrected Pages II-35 & II-36 for revised inservice insp program for pump & valvo testing.submitted on 800527 UTLEY,E E Carolina Power & Light Co 80/06/25 ip.
- --8007010431 Corrected Pages 11-35 & II-36 for "Inservice Insp Program, Program & Value Testing " * Carolina Power & Light Co 80/06/25 2pp
- 8007230220 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosenount Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Output Codes" Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/1 80/06/27
- 8007220260 Responds to IR Bulletin 80-10 Routing sampling, analysis & monitoring program established to promptly identify contaminating events that could lead to uncontrolled releases to environ FURR. B J Carolina Power & Light Co 80/07/01 ip
- 8007170516 Responds to IS Bulletin BO-OB. "Examination of Containment Liner Penetration Welds " All Final welds radiographed & results of const nondestructive examination acceptable as FURR.B J Carolina Power & Light Co 80/07/03 2pp
- 8007240189 Responds to 800611 notice of violation & notice of proposed imposition of civil penalties Boiler removed from svc for decontamination repair & mods Radiological operating limits established Civil penalties fee encl FURR.8 J Carolina Power & Light Co 80/07/03 7pp

- ---8007240196 Responds to NRC request for info re 780426 occurrence which resulted in onsite contamination of area around radwaste bldg Calculations indicate approx 200 gallons of waste was drawn into steam line
 TOLLISON, A C Carolina Power & Light Co 78/04/28 2pp
- 8007310449 Forwards response to NRC 800611 notice of violation & notice of proposed imposition of civil penalties re onsite contamination of area around radwaste bldg Corrective actions boiler decontaminated & repaired Penalty fee encl FURR.8 J Carolina Power & Light Co 80/07/03 5PP
- 8007280111 Forwards response to IE Bulletin 80-11 Response includes general arrangement drawings indicating masonry walls Also forwards data sheets re each wall M/o encis
 FURR.B J Carolina Power & Light Co 80/07/07 ip
- 8007250296 Responds to IE Builetin 80-17, "Failure of Control Rode to Fully Insert " No water observed in screm discharge vol Timing of vent & drain valves completed FURRY, 8 J Carolina Power & Light Co 80/07/10 2pp
- 8007190492 Responds to NRC ltr re violations noted in IE Insp Repts 50-324/80-20 & 50-325/80-23 Corrective actions ISI program reorganized & future submittals will be accurate & complete GA Procedure 23 written & approved to correct Items 2 & 4 TOLLISON, A C Carolina Power & Light Co 80/07/11 3pp
- 8007300561 Responds to IE Bulletin 80-13 No crecking indications noted in Unit 1 care spray sparger or in-vessel piping Unit 2 inspectly will be performed at next refueling outage FURR.B J Carolina Power & Light Co 80/07/15 ip
- 800/310206 Submits supplemental response to IE Bulletin 80-07 re DWR jet pumps No indications discovered either by visual or ultrasonic insp FURR, B J Carolina Power & Light Co 80/07/15 ip
- 8007310306 Responds to IE Bulletin 79-03A. "Lungitudinal Weld Defects in ABME 8A-312. Type 304 Stainless Steel Pipe " Piping specs do not permit use of A-312. Type 300 series fusion welded pipe in safety-related sys FURR. 8 J Cerolina Power & Light Co 80/07/15 ip
- R Periodic operating reports & related correspondence
- 8007110405 Forwards monthly operating repts for June 1980 TOLL180N, A.C. Carolina Power & Light Co 80/07/03 Rp
- --B007110404 Monthly operating repts for June 1980 WILLIB, E Carolina Power & Light Co 80/07/03 5pp
- 8 Reportable occurrences, LERs & related correspondence
- B007020334 Forwards LER 80-046/01T-0 TOLLISON.A C. Carolina Power & Light Co 80/06/24 ip
- --800702036i LER 80-046/01T-0 on 8006ii.while performing insps per IE Bullstin 79-01B, aplices connecting nuclear grade cables to solenoid pigtail leads for valves found not environmentally qualified Nuclear grade splices being installed TOLLIBON, A C Carolina Power & Light Co 80/06/24 2pp.
- 8007160632 RO 2-80-47 while replacing nonqualified splices connecting safety relief valve solenoid pigtails to nuclear grade cable, discovered that pigtails on solenoids were brittle & that insulation cracked when handled Solenoids unqualified TOLLISON, A C Carolina Power & Light Co 80/06/24 1p
- 8007020560 LER 79-107 has been cancelled * Caroline Fower & Light Co 80/07/01, 1p
- 8007020563 LER 79-108 has been cancelled * Carolina Power & Light Co. 80/07/01 1
- 8007140395 Forwards LER 80-047/01T-0
 TOLLIBON.A C. Carolina Power & Light Co 80/07/08 ip
- ---8007140399 LER 80-047/01T-0 on 800624. while replacing nonqualified splices connecting safety relief valve solenoid pigtails to nuclear grade cable, brittle pigtails discovered Caused by adverse reaction to tape adhesive Solenoids replaced TOLLISON.A C Carolina Power & Light Co. 80/07/08. 2pp
- 8007220464 Forwards LER 80-048/03L-0
 TOLLISON, A C Carolina Power & Light Co 80/07/16 ip

- --8007220470 LER 80-048/03L O on 800623. Inw level switch 2-821-L18-N031Ai would not reset when holmal reactor water level was simulated Caused by stock contacts Defective switch leplaced & calibr TOLLISON.A C Carolina Power & Light Co 80/07/16 1p
- BOO/220921 RO 1-BO-59 confilms 800716 telcom he notification by GE of incorrect use of total peaking factor for adjusting gain of average power range monitors Caused by incorrect ref value. Tech Spec values to be changed.
 TOLLIBON.A C Carolina Power & Light Co 80/07/1/ 3pp
- 8007250334 Forwards LER 80-047/03L-0
 TULLISON, A C Carolina Power & Light Co 80/07/17 ip
- --8007250341 LER 80-049/03L-0 on 800701. Suring performance of high drywell pressure channel pressure & functional test, technicians found pressure suitch 2-72-98-80028 actuating out of tolerance Caused by instrument drift TOLLISON. A C Carulina Power & Light Co 80/0//1/ 1p
- DOCKET 50-325 BRUNSWICK STEAM CLECTRIC PLANT, UNIT 1

 F Security, medical, emergency % fire protection plans
- B007010324 Informs NRC that util will submit revised emergency plan in Aug 1980 Implementing procedures for emergency plan will be developed by B01201 & complete plan implemented by B10101 per NUREC-0654 requirements

 UTLEY, E & Carolina Power & Light Co 80/06/27 ip
- 8007010342 Advises that add1 info re safeguards contingency plan which was requested in NRC 800527 ltr will be submitted by 800801

 VILEY,E E Carolina Power & Light Co 80/06/27 lp
- 8007170959 Notifies that intake structure basement areas at facilities have been selected as possible test subj to conduct tests on fire protection sys in response to NRC 800923 order Requests agreement to participate in program EISENHUT, D & Division of Licensing 80/07/08 3pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables

 EISENHUT, D G Division of Liconsing 80/06/25 89pp
- H General correspondence
- 8007020198 Responds to 800516 ltr ie Kudzu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearon Harris const to assure conformance Wrequirements Levels of contamination from Brunswick no threat to public DIRCKS.W J Office of the Executive Director for Operations 800/06/18 200
- --8007020217 Requests response to encl Kudio Alliance 800512 ltr commenting on ability of util to safely utilize nuclear power ANDREWS.1 House of Rep 80/05/16 2pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting m/Mark I owners group in Bethesda. MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 60/02/21 3ipp
- 6007010416 Confirms 600619 confirence (all w/BNL NRC, GE & util re fuel Cycle 3 Util will perform startup physics testing on Unit I during startup from current outage GE has confirmed that both units are equipped w/thermal power monitors

 UTLEY, C E Carolina Power & Light Co 80/06/25 2pp
- 8007010423 Forwards responses to NRC 800507 request for evaluation of applicability to facilities of GE 800221 responses re concerns provided by ACRB consultant. C Michalson, re add1 TMI-2 rolated requirements UTLEY.E E Carolina Power & Light Co 80/06/27 App
- 8007140605 Forwards Amend 29 to License DPR-71 safety evaluation & notice of issuance & availability
 IPPDLITD.T A Operating Resitors Branch 2 80/07/01 4pp

- -8007140614 Amend 29 to License DPR-71, changing Tech Specs to establish revised safety % operating limits for Cycle 3 operation & safety relief valve pressure settings to provide min nominal lift setting differential of 20 ps;
 IPPOLITO,T A Operating Reactors Branch 2 80/07/01 23pp
- -8007140418 Safety evaluation supporting Amend 29 to License DPR-71 * Operating Reactors Branch 2 80/07/01 10pp
- -B007140624 Notice of issuance & availability of Amend 29 to License IPPOLITO,T A Operating Reactors Branch 2 80/07/01 2pp
- 007210415 Discusses 790931 commitment to installation of mods required by Mark I containment program during 1980 & 81 Complete incorporation of NRC input into 8E load definition rept scheduled for mid-Jul 1980 UTLEY.C E Carolina Power & Light Co 80/07/14 2pp
- 207240427 Forwards corrected Page 3/4 2-7 of Tech Specs attached to 800701 Amend 29 to License DPR-71 Amend should ref Fuel Type PBDRB265H Also forwards corrected safety evaluation to Amend
- IPPOLITO, T A Operating Reactors Branch 2 80/07/15 3pp
- -8007240433 Revised page to Amend 29 to License DPR-71, correcting ref to Fuel Tupe P80RB265H IPPDLITD.T A Operating Reactors Branch 2 80/07/15 ip
- -B007240441 Corrected safety evaluation supporting Amend 29 to License DPR-71 Corrects incorrectly numbered pages * Operating Reactors Branch 2 80/07/01 lipp
- 007290723 Submits addl info re adequacy of station electrical distribution sys voltage in response to NRC 800516 ltr Info for incomplete Items 2 & 3 will be submitted by 801024 & 0926, respectively UTLEY.E E Carolina Power & Light Co 80/07/24 7pp
- 007250306 "Electrical Instrumentation & Control Aspects of Override of Containment Purge Valve Isolation & Other Safety Feature Signals Drumswick Steam Electric Plant, Unit 1 " UDY, A C E0&0 Idaho.Inc FIN A-6256 8007250306 80/07/31 13pp
- Inspection reports, IE Bulletins & correspondence
- 007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08.
- 007140489 Forwards IE Bulletin BO-13. "Cracking an Core Spray Spargers "Written response required
 D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/12
- 007020187 Forwards |E Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- 007010179 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY: J P Region 2. Atlanta, Office of the Director 80/05/29
- 007170420 Forwards 1E Insp Repts 50-324/80-14 & 50-325/80-19 on 800512-16 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/06 2pp
- -8007170427 IE Insp Repts 50-324/80-14 & 50-328/80-19 on 800512-14 No noncompliance noted Major areas inspected maints surveillance & calibr of Tech Spec-related equipment & support equipment MESSITT B R Region 2. Atlanta, Office of the Director UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/05 App
- 07220043 Forwards IE Info Notice 80-P6. "Evaluation of Contractor GA Programs" No written response required 0'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/10
- 007140289 Forwards JE Bulletin BO-14, "Degradation of BWR Scram Discharge Vol Capability " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/12

- 8007020745 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required D'REILLY.J F Region 2. Atlanta. Office of the Director 80/06/18
- 8007020440 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required required C'REILLY.J P Region 2, Atlanta. Office of the Director 80/06/20
- G007100396 Ack receipt of B00610 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts B0-324/80-10 & 50-325/80-11 HAPPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch
- -8007100367 Ack receipt of 800512 ltr informing NRC of ataps taken to correct violations noted in IE Insp Repts 50-324/80-10 & 50-325/80-11 Per 800822 telcon, supplemental response should be provided by 800613 MURPHY.C & Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/23 1p
- --B007100377 Responds to NRC B0041B ltr re violations noted in IE
 Insp Repts 50-324/B0-10 & 50-325/B0-11 Corrective actions
 diesel engine insp was performed by manufacturer Periodic
 test implemented & scheduled for fire doors
 TOLLISON.A C Carolina Power & Light Co B0/05/12 4pp
- --B007100384 Forwards IE Insp Repts 50-324/80-10 & 50-325/80-11 on B00331 & 0401-03 & notice of violation MURPHY.C E. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/04/18 2pp
- ---8007100395 Notice of violation from insp on 800331 & 0401-03 * Region 2. Atlanta, Office of the Director 80/04/18
- ---B007100398 Notice of deviation from insp on B00331 t 0401-03
 * Region 2, Atlanta, Office of the Director B0/04/18
- --800710D413 IE Insp Repts 50-324/80-10 & 50-325/80-11 on 800331 & 0401-03 Noncompliance noted inadequate surveillance procedures for fire protection sys & inadequate review of fire protection sys & inadequate review of fire protection Tuch Bysc violations CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Branch MILLER.H H Region 2. Atlanta, Office of the Director 80/04/18 9pp
- B00716080D Forwards IR Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel ** No written response required O'REILLY, J.P. Region R. Atlanta, Office of the Director 80/06/24
- B007010425 Forwards corrected Pages II-35 & II-36 for revised inservice insp program for pump & valve testing, submitted on 800527, UTLEY.E E Carolina Power & Light Co 80/06/28 ip
- -8007010431 Corrected Pages II-39 & II-36 for "Inservice Insp Program, Program & Value Testing " * Carolina Power & Light Co, 80/06/25 2pp,
- 8007230220 Forwards IE Bulletin 80-14, "Potential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-14 also encl. No written response required. O/REILLY, J P Region 2, Atlanta, Offics of the Director, 80/06/27
- B007220240 Responds to JE Bulletin B0-10 Routine sampling analysis & monitoring program established to promptly identify contaminating events that could lead to uncontrolled releases to environ
 FURR B J Caroline Power & Light Co 80/07/01 1p
- 8007170516 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " All final welds radiographed & results of const mondestructive examination acceptable as FURR, B J Carolina Power & Light Co 80/07/03 2pp
- BOO7240189 Responds to BOO611 notice of violation & notice of proposed imposition of civil penalties Boiler removed from svc for decontemination, repair & mode Radiological operating limits established Civil penalties fee encl FURR.B J Carolina Power & Light Co BO/07/03 7pp

- --B007240196 Responds to NRC request for info re 780426 occurrence which resulted in onsite contamination of area around radwaste bidg. Calculations indicate approx 200 gallons of waste was drawn into steam line TOLLIBON.A C Carolina Power & Light Co 78/04/28 2pp
- 8007310449 Forwards response to NRC 8006il notice of violation & notice of proposed imposition of civil penalties re onsite contamination of area around radwaste bidg. Corrective actions boiler decontaminated & repaired Penalty fee encl FURR, B J Carolina Power & Light Co 80/07/03 5PP
- 8007280111 Forwards response to IE Bulletin 80-11 Response includes general arrangement drawings indicating masonry walls Also forwards data sheets re each wall W/o encis. FURR.B J Carolina Fower & Light Co 80/07/07 ip
- 8007250274 Responds to IE Bullstin 80-17, "Failure of Control Rods to Fully Insert" No water observed in scram discharge vol Yiming of vent & drain valves completed. FURRY, B. J. Carolina Power & Light Co. 80/07/10 2pp
- BOO7150492 Responds to NRC ltr re violations noted in IE Insp Repts 50-324/80-20 & 50-325/80-23 Corrective actions IBI program reorganized & future submittals will be accurate & complete. GA Procedure 23 written & approved to correct Items 2 & 4 TOLLISON, A C Carolina Power & Light Co 80/07/11 3pp
- 8007300561 Responds to IE Bulletin 80-13 No cracking indications noted in Unit 1 core spray sparger or in-vessel piping. Unit 2 inspetil be performed at next refueling outage FURR.8 J Carolina Power & Light Co 80/07/15 ip
- 8007310206 Submits supplemental response to IE Bulletin 80-07 re BWR jet pumps No indications discovered either by visual or ultrasonic insp.
 FURR.B J Carolina Power & Light Co 80/07/15 ip
- 8007310306 Responds to IE Bulletin 79-03A. "Longitudinal Held Defects in ASME 8A-312.Type 304 Stainless Steel Pipe " Piping specs do not permit use of A-312.Type 300 series fusion welded pipe in safety-related sys.

 FURR.B J Carolina Power & Light Co 80/07/15. ip
- R Periodic operating reports & related correspondence
- 8007110405 Forwards monthly operating rapts for June 1980. TDLLIBON, A C Carolina Power & Light Co 80/07/03 2pp
- --B007i10406 Honthly operating repts for June 1980. WILLIB,E Carolina Fower & Light Co B0/07/03 5pp
- S Reportable occurrences, LERs & related correspondence
- 8007010556 Forwards updated LER 80-041/01T-1 TOLLISON, A C Carolina Power & Light Co. 80/06/20 ip
- ---B007010364 Updated LER B0-041/01T-1 on B00525, during review of environ qualification of electrical equipment, hylon insulating sleeve portions of compression-type terminator lugs did not pass qualification test Caused by sleeve deterioration TOLLIBON, A.C. Caroline Power & Light Co B0/06/20 2pp.
- 8007010501 Forwards LER 80-032/03L-0 TOLLISON, A.C. Carolina Fower & Light Co. 80/06/23. is
- --B007010509 LER B0-032/03L-0 on B00525, when rod was selected, rod block monitor B inoperable light on rod block monitor panel illuminated, Cause unknown Problem could not be reproduced or identified when troubleshooting sys.

 TOLLISON, A C Carolina Power & Light Co B0/06/R3 ip
- 8007010513 Forwards LER 80-035/03L-0 TOLLISON: A C. Carolina Power & Light Co. 80/06/24. 1p
- --B007010521 LER 80-033/03L-0 on 800826, while performing penetrant test
 1 10, count rate for source range monitors B & C did not
 decrease when detectors were removed from core. Caused by
 blown fuses & height discriminator maled justment.
 TOLLISON, A. C. Carolina Power & Light Cp. 80/06/24, 2pp.
- 8007070234 Forwards LER 80-050/03L-0 TOLLIBON:A C. Caroline Power & Light Co. 80/06/27. ip.

- --B007070237 IER B0-050/03L-0 on B00605.while performing reactor bl ventilation radiation monitoring sys test.monitor D12-RN-N010B failed to trip ventilation sys & start standby gas trains Coused by stuti relay 3DA TOLLISDN.A C Carolina Power & Light Co 80/06/27 ip
- 8007080180 Forwards LER 00-037/03L-0 TOLLISON, A.C. Carolina Fower & Light Co. 80/06/27 1p
- --B007080185 LER B0-037/03L-0 on B00528 during containment integrit check-required negative pressure not reached Caused by leaks in pipe & cable penetrations & steam line books Penetrations repacked & books replaced Test procedures revised TOLLISON, A C Caroline Power & Light Co B0/06/27 2pp
- 8007150654 Forwards LER 80-053/03L-0 TDLLISON:A C Carolina Power & Light Co 80/07/11 lp
- --8007180665 LER 80-083/03L-0 on 800607, during normal reactor bldg during refueling, inner & outer doors of 50-ft air lock found open Caused by burned coil in inner door interlock solenois Coil replaced & air lock access restored TOLLIBON, A C Carolina Fower & Light Co 80/07/11 lp.
- B007220521 RD 1-80-59 confirms 800714 telcon re-notification by GL incorrect use of total peaking factor for adjusting gain of average power range monitors Caused by incorrect ref value. Tech Spac values to be changed TOLLISON. A C Carolina Power & Light Co 80/07/17. 3pp
- 8007290824 Forwards LER 80-056/03L-0 TOLLISON, A C Carolina Power & Light Co GD/07/23 is
- --R007290833 LER 80-086/03L-0 on B00701, average nower range monitor (APRM) B & F determined inoperative due to lack of eleven low power range monitor (LPRM) inputs per monitor Caused by LPRM connectors that feel into APRM being pulled loose TOLLISON, A C Carolina Power & Light Co 80/07/23 2pp
- 8007290823 Forwards LER 80-039/017-0 TOLLISON, A C Carolina Power & Light Co 80/07/25 2pp
- --B007290B31 LER B0-0B9/01T-0 on B00710 util informed by QE that pr computer was not using correct fuel lengths when calculating max total peaking factor Cause not stated Procedures revised to correct TPF ref value TOLLIBON.A C Caroline Power & Light Co B0/07/25 ip
- DOGKET 50-326 UNIV OF CALIFORNIA AT INVINE RES REACTOR

 G Inspection reports. 1E Dulletine & correspondence
- B007180866 Forwards IE Circular 80-14, "Radinactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELMENTH Region 5. Ban Francisco, Office of the Director 80/04/24 lp.
- R Periodic operating reports & related correspondence
- 8007130615 Forwards "Annual Rapt for Period 790701-000630 "
 MILLER, Q. E. California, Univ. of, Irvine 80/07708 is
- DOCKET 50-327 BEQUOYAH NUCLEAR PLANT. UNIT 1

 A Application/construction stage documents & correspondence
- 8007220460 Nntifies that contract for additiontractor support to provide operational experience during low power test; gerfuel loading k low power testing requirement, will not be renswed. Existing contract terminates w/NRC concurrence, MILLB, L. M Tennessee Valley Authority 80/07/17 ip
- 8007230511 Notifies that initial performance of Special Yest 7 an BOO716 demonstrated that power operated relief valve can be manually operated to provide cooldown capability during abnormal conditions
 MILLS.L M Tennessee Valley Authority 80/07/18 ip.

- NRC Safety Evaluation Report (SER), suppls & correspondence
- 007300052 Forwards status rept on facility SER imputs Inputs on 24 items are still outstanding SER will not be ready in im for commission 800728 briefing unless approx input dates are improved
 HENYON T Assistant Director for Licensing 80/07/18 lp
- Security, medical, emergency & fire protection plans
- 07160643 Forwards revised commitment for fire protection program re-evaluation. Section A 3(b), re locking of fire protection water sys values Revision was made in response to IE Insp. Repts 50-227/80-10 t 50-328/80-06 MILLS.L M Transesse Valley Authority 80/07/03 3pp
- 07230499 Forwards fire protection mod schedule, per NRC 800702 request Requests approval Seven mods have completion dates after 801101
- Tennessee Valley Authority 80/07/17 15pp TILLS, L M
- 07230575 Forwards revised radiological emergency plan w/cross-ref between plan & NDREO-0654 & App F. IN radiological emergency response plan Encis available in Central Files only fillS.L M Tennessee Valley Authority 80/07/21 3pp
- 17280548 Advises that Westinghouse reviewed power-accension test rocedures per Task Action Plan Item 1 C 7 Review of mergency procedures documented by 800428 ltr to LS ubenstein ILLS.L M Tennessee Valley Authority 80/07/23 lp
- Tennessee Valley Authority 80/07/20 lp
- 7300434 Agrees, as intorim step decided at NRC 800725 meeting, to spand near site press facility to provide for command introl function for pmergency response Contral emergency esponse ctr.per util 800721 itr.requires add1 discussion RLS.L.M. Tennessee Valley Authority 80/07/28 ip
- Adjudicatory correspondence
- 07290287 Notice of request for action under 10CFR2 206 by NRC per B00528 petition to revoke low power DL DENTON.HR Office of Nuclear Reactor Regulation. Director 30706/24 1p
- 17270296 Requests NRC revoke limited OL of util to perform low your testing of facility because public health & safety is
- The Nuclear Regulatory Commission 80/05/28 3pp
- 10243 Forwards Commission 600527 memorandum & order containing isions on UCS 780502 petition for reconsideration of 413 memorandum & order UCS 771104 petition sought action fire protection for electrical cables ENHUT. D G Division of Licensing 80/06/25 89pp
- ility Final Safety Analysis Report (FSAR) & amends
- 00374 Amend to UL application, consisting of Amend & to FSAR, tsing Chapters 2,3,5,6 & 15 FBAR documentation of items is mitted by LM Mills 800613 ity & responses to NRC
- #tions øncl Tennessee Valley Authority 80/07/25 is
- 300376 Amend 66 to FBAR revising Chapters 2.3.5.6 & 19 Tennessee Valley Authority 80/07/28 92pp
 - ommittee on Reactor Bafeguards reports & correspondence
 - ce of ACRS Subcommittee on Sequeyah Nuclear Plant 800709 shington DC to review OL request ffice of the Secretary of the Commission 80/06/18
 - usses review conducted at 243rd ACRS mouting on 8007;0-plication to operate at full power Facilities ed at levels up to full power w/o undue risk ined are considered ACRS Advisory Committee on Reactor Safeguards

- 8007210531 Responds to 800710 request re particular aspects of facility Applicant committed to expedite installation of distributed agnition sys No practical need to hold up issuance of DL pending completion of proposed sys PLESSET.N S ACRS Advisory Committee on Reactor Bafeguards 80/07/15 1p
- B007290022 Forwards Ahearns 800718 ltr re AGRB review of application for authorization to operate SCHNENGER, A Licensing Branch 2 80/07/17 3pp
- P Operating license stage documents & correspondence
- B007020228 Forwards NRC Off of Nuclear Reactor Regulation B00428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities TEDESCO.R L Assistant Director for Licensing B0/06/13 2pp
- B007020747 Forwards requests for add1 info re shielding review & containment sump Responses should be submitted by B00701 Includes summary of shielding design review required by NRC 791109 itr implementing Item R 1 6 b of NREG-0578 SCHWENCER, A Licensing Branch 2 80/06/19 10pp
- 6007020042 Confirms 800520 oral authorization to proceed w/heatup b/ inoperable hanger on pressurizer line Deficiency will be corrected before initial criticality Formal amand to license will be processed in near future SCHMENCEN.A Licensing Branch 2' 80/06/29 2pp
- BOO7020722 Forwards commitments re steam generator insp ports & Row 1 steam generator tubes NRC requires commitment within 5 days re performance of required actions described in encl Insp ports must be installed just above upper support plate SCHMENCER, A Licensing Branch 2 80/06/23 3pp
- 8007030195 Forwards request for addl info re Table 17 2-1, "Critical Structures, Bys & Components," for FSAR, which identifies items subj to operational GA program Info requested by SCHNENCER, A Licensing Branch 2 80/06/24 5pp
- E007010327 Forwards add1 info re safety evaluation of facility special test program. Provides add1 assessment of potential upset conditions associated w/postulated rod withdrawal events Fuel clad failure is not expected MILLS.L M Tennessee Valley Authority 80/06/25 11pp
- B007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NURE9-0660 & found in NURE8-0674 Division of Licensing 80/06/26 2pp
- 8007070347 Requests that 800624 FR notice be reissued to correct implication that farm (TMRC) owns facility & allegation that plant is unable to withstand hydrogen burn pressure BATES,A X. Affiliation Unknown 80/07/01 3pp
- 8007170496 Forwards Amend 3 to License DPR-77, safety evaluation & notice of issuance & availability SCHWENCER, A Licensing Branch & 80/07/01. 2pp
- --BO07170303 Amend 3 to License DPR-77 changing pages to App A Tech Specs re surveillance requirements for taking radioactive liquid & gaseous samples SCHMENCER A licensing Branch 2 80/07/01 22pp
- --8007170508 Bafety evaluation supporting Amend 3 to Licenso DPR-77
 * Office of Nuclear Reactor Regulation, Director 80/07/01
- --- 8007170517 Notice of issuance & availability of Amend S to License DPR-77 SCHWENCER.A. Licensing Branch 2 80/07/01, 2pp
- 800718006: Forwards safety evaluation supporting Amend 2 to License DPR-77 SCHWENCER, A Licensing Branch 2 B0/07/01 2pp
- ---8007180070 Safety evaluation suppporting Amend 2 to License DPR-77
 * Licensing Branch 2 80/07/01 2pp
- BOO7180595 Forwards Amend 2 to License DPR-77, safety evaluation & notice of issuance & availability
 BCHWENCER, A Licensing Branch 2 80/07/01, 2pp,

- --8007180596 Amend ? to License DPR-77, changing Page 8-1 to App A Tech Specs to permit entry into Modes 3 & 4 Wunresolved piping support or restraint deficiencies SCHWENCER.A Licensing Branch 2 80/07/01 4pp
- -- 8007180599 Notice of issuance & availability of Amend 2 to License SCHWENCER, A Licensing Branch 2 80/07/01 2pp
- 8007150472 Forwards response to NUREG-0578. TMI-2 Leasons Learned Task Force status rept & short-term recommendations Consolidates previous ltrs Includes revisions to containment isolation & shielding items MILLS.L M Ten Tennessee Valley Authority 80/07/03 ip
- C007280001 "TVA Response to MUREG-0578, Short-Term Lossons Learned Requirements "
 * Tennessee Valley Authority 80/07/03 500pp
- G007150640 Advises that response to FSAR. Question 2 78, will not be organized & prepared for submittal until 800801 MILLS.L M Tennessee Valley Authority 80/07/OB ip
- 8007130692 Bubmits recommundations re facility steam generators, in response to NRC 800623 ltr Camera device will be designed & tested for remote insp of tube supports in lieu of addl parts Max active tube surface margin will be maintained MILLS.L H Tennosuse Valley Authority 80/07/08 2pp
- 8007150821 Forwards info ro Category 1 masonry walls in response to NRC 800421 ltr Results of investigation of inplace attachments to masonry walls will be submitted by 801017 Oversize encis available in Central Files (31 pp)
 MILLB.L M Tennessee Valley Authority 80/07/09 App
- ---8007150322 "Design Criteria for Reinforced Concrete Block Walls " STDNC, F A , CANNON, R W , LACY, Γ P Tennessee Valley Authority 72/04/07 27ρρ
- 8007210618 Notification of 800714 meeting w/util in Bethesda MD to discuss emergency operating instructions
 8TAHLE, C.R. Licensing Branch & 80/07/10 2pp
- 8007240297 Forwards Amend 4 to License DPR~77, safety evaluation & notice of issuance & availability

 DENTON, HR Office of Nuclear Reactor Regulation, Director 80/07/10 3pp
- --B007240302 Amend 4 to License DPR-77, modifying Tech Specs for law power testing DENION.H R O 80/07/10 4pp Office of Nuclear Reactor Regulation, Director
- -8007240306 Safety evaluation supporting Amend 4 to License DPR-77
- --8007240312 Natice of issuance & availability of Amend A to License DPR-77 SCHWENCER, A Licensing Branch 2 80/07/10 20p.
- 8007150571 Forwards Revision 2 to util response to Item 2 1 &s.NUREG-0578 Revision incorporates leak testing procedures for waste gas sys (App E) & results of leak reduction program for liquid & gas sys (App E) MILLB.L M. Tennessep Valley Authority 80/07/11 &pp
- ~~8007150878 Surveillance Instruction SI-656.Revision i. "Waste Gas Sys Gross Leakage Test" KUEHN-L B Tennessee Valley Authority 80/06/12 14pp
- --8007150982 Liquid sys leak test data CHURCH.JW Tennessee Valley Authority 80/07/01 9pp
- 8007160471 Responds to J Spraul informal questions re FSAR Table 17 2-1 & forwards operational GA manual.App A.re critical sys & Part 3. Section 2.re matl & spare parts MILLS.L M Tennessee Valley Authority 80/07/11 5pp.
- -8007160478 Operational GA manual.App Aire critical structures, sys & components list GREEN, H. J. Tennessee Valley Authority 78/08/15 50pp.

- ~-8007i60484 Operational GA manual Part 3.Section2.re mati & spare parts * Tennessee Valley Authority 78/08/29 33pp
- 8007280006 Notification of 800/23 meeting w/utils in Dethesde.ND to discuss matters re TM1-2 dated (equirements BROMERICK.A W. Licensing Branch 1 KERRIGAN.J D., STABLE.C R Licensing Branch 2 80/97/16 App
- 8007220532 Advises that util proposes installation & implementation of interim sys of distributed ignitors which would limit offects of large amounts of hydrogen Sofety analysis, drawings & FSAR revisions will be submitted by 800815 MILLS, L M Tennessee Valley Authority 89/07/17 Spp
- 8007230467 Forwards response to NRC 800507 request for commitment to most requirements & associated schedules in fave specific TMI items Includes shift mannang, licensing examinations & licensed dissemination of operating experience MILLS,L IS Tennessee Vailey Authority 60/07/18 4pp
- 8007230477 Forwards response to NRC 800619 request for addl info re shielding design review, high range containment radiation monitor & access control of areas adjacent to spent feel transfer tubes MILERIEN Tennessee Valley Authority 80/07/18 Spp
- 8007230480 Forwards "ECOPAC Solidification Sys Process Control Program," Revision 4. in response to NRC 800324 request MILLS.L M Tennessee Valley Authority 80/07/18 ip
- --8007230481 "ECOPAC Solidification Sys Process Control Program," Revision 4
 - Tonnessee Valley Authority 80/07/18 20pp
- ---8007230483 "Technical Rept on Urea Formaldehyde " Marked-up Amefco rept on procedure for onsite solidification of low level raduasts at facility enc! * Amefco.inc 80/07/18 45pp
- 8007230533 Forwards response to M Mendonca 800627 guestions re reactor vessel head venting sig Westinghouse is developing procedures for inadequate core cooling for recommended use of vent sign by utils IIILLB,L M Tennessee Valley Authority B0/07/18 11pp
- 8007J00092 Forwards status rept on facility SER inputs Inputs on 24 items are still outstanding SER will not be ready in time for Commission 800728 briefing unless approx input dates ard improved KENYON, T Assistant Director for Licensing 60/07/18 in
- 600/230408 Forwards add1 info per NRC 800619 request re control of containment sump debris MILLB.L M Tennesseo Valloy Authority 80/07/21 14pp
- 8007290724 Forwards description of program, "Training for Mitigating Core Damage "Program was developed to ansure that all incensed operating employees are properly trained to use available info should accident occur involving core damage MILLS.L M Tennessee Valley Authority 80/07/22 Spp
- 8007280623 Advises NRC of evaluation of patential basards in vicinity of plant & of main control room habitability sys for protection from radioactive & toxic gas releases Flant operators are adequately protected from possible hazards MILLS.L M Tennessee Valley Authority 80/07/24 ip
- 9007290651 Forwards evaluation of design & equipment delivery schedules MARKED HER STATE OF USE OF USE
- 8007290679 Forwards preliminary assessment of potential for barge tow heading upstream impacting new essential raw cooling water pumping station Blation not required for safe operation of Unit I MILLS, L M Tennessee Valley Authority 80/07/28 2pp
- 8007290757 Forwards data & drawings re settlement monitoring Revised Questions SNF 92 84 & SNF 92 73 will be incorporated into FBAR in next amend No significant settlement observed Brawings available in Central Files only MILLS.L M Tennossee Valley Authority 80/07/28 12pp
- B007310396 Advises that short-term items & two long-term items listed in NUREG-0011 re main control room design review have been corrected Util committed to investigate feasibility of correcting remaining items of first refueling outage MILLS,L M. Tennessee Valley Authority 80/07/28 4pp

- 310412 Forwards revised summary page for 800616 response to /REG-0568 LLS.L. M
- Tennessee Valley Authority 80/07/28 2pp
- 310323 Forwards "Unit 1 Special Startup Test Rept LLS.L M Temmessee Valley Authority 80/07/29
- 07310325 "Unit 1 Special Startup Test Rept " MACH, S R Tenne-see Valley Authority 80/07/28 3pp
- 3104() Submits test results of plant auxiliary bldg gas treatment per requirements of SER. Suppl 1 Negative pressure equal or more negative than minus 1/4-inch water gauge lative to outside atmosphere was achieved in pump rooms LLS:1 M Tennessee Valley Authority 80/07/29 1p
- 310416 Forwards addl info on temp control for main steam valve oms.per O Parr request LLS.L M Tennessee Valley Authority 80/07/29 2pp

napaction reports. IE Bulletins & correspondence

- 240087 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal pability at Davis-Besse Unit 1 While in Refueling Mode " response required REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- D20192 Forwards IE Info Notice 80-22. "Breakdowns In Contamination atrol Programs " No written response required REILLY, J.P. Region 2. Atlanta, Diffice of the Director 80/05/28
- 00127 Forwards 1E Insp Rept 50-327/80-18 on 800512-13 No
- J7100131 IE Insp Rept 50-327/80-18 on 800512-13 No noncompliance inted Major areas inspected seismic analysis for as-built safety-related piping sys per IE Bulletin 79-14 HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering upport Branch MODENOS.L Region 2. Atlanta, Office of the irector 80/05/27 3pp
- '10488 Forwards IE Circular 80-10, "Grid Strep Damage in tinghouse Fuel Assemblies " No written response required. 'EILLY,J P Region 2, Atlanta, Office of the Director 80/05/28
- 10225 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency dwater Pumps" No written response required EILLY.J P Region 2. Atlanta. Office of the Director 80/05/29
- 70219 Forwards IE Insp Rept 50-327/80-16 on 800409-30 & notice of Istion
 IS.R C Region 2, Atlanta, Reactor Operations Nuclear Support
 nch 80/06/02 2pp
- 7170221 Notice of violation from insp on 800408-30 Region 2. Atlanta, Office of the Director 80/0 B0/04/02 1p
- 7170224 1E Insp Rept 50~327/B0~1A on 800408-30 Noncompliance noted ailure to maintain vital area barrier integrity

 DTILE.W T Region 2. Atlanta. Office of the Director DANCE.H C
 Region 2. Atlanta. Reactor Operations Nuclear Support Branch

 9/06/02 12pp
- 30005 Forwards IE Insp Repts 50-327/80-19 & 50-328/80-12 on #13-16 No noncompliance noted IS,R C Region 2. Atlants. Reactor Operations Nuclear Support 10A 80/06/05 2pp
- 7180011 IE Insp Repts 50~327/80-19 & 50~328/80-12 on 800613-16 No /MBUOIT 16 Insp Nepts 50-32/780-19 & 50-328760-12 on BOU613-16
 Discomplishers noted Major areas inspected preoperational
 esting, program review & implementation & followup of
 reviously identified items
 MENDEN.M C. BUTLER, B D. Region 2. Atlanta, Office of the
 irector UPRIGHT, C M. Region 2. Atlanta, Reactor Operations
 sclear Support Branch BO/06/04 App
- 20029 Forwards IE Info Notice 80-26. "Evaluation of Contractor Programs " No written response required ILLY,J F Region 2. Atlanta, Office of the Director. 80/06/10

- 8007160287 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response equired 'REILLY.J.P. Region 2, Atlanta, Office of the Director <u>80/04/1</u>1
- 8007020740 Forwards response to IE Bulletin 80-06. "Engineered Safety Feature (ESF) Reset Controls " List of safety-related equipment which will not remain in emergency mode after reset of actuation signals encl CROSS.J L Tennessee Valley Authority 80/06/12 3pp
- 8007020347 Forwards response to IE Bulletin 80-04, "Analysis of PMR Main Steam Line Break w/Continued Feedwater Addition " Lists relevant assumptions used in all core transient analyses Assumptions further explained in FSAR HILLS.L N Tennesses Valley Authority 80/06/16 3pp
- 8007020761 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/ Region 2, Atlanta, Office of the Director 80/06/18
- 8007020391 Forwards IE Circular 80-15. "Lose of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required required O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 80/06/20.
- 8007310344 Forwards IE Insp Rept's 50-259/80-25,50-260/80-19, 50-296/80-20 & 50-327/80-22 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/23
- --8007310351 IE Insp Repts 50-259/80-25,50-260/80-19,50-296/80-20 & 50-327/80-22 on 900521 Insp consisted of enforcement meeting in Atlanta, GA to discuss exceeding BDT radiation limits during shipment of radwaste from Browns Ferry DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 90/06/20 2pp
- B007i10034 Ack receipt of 800523 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-327/80-14 & 50-327/80-08
 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/06/24 ip
- ---B007110039 Submits add1 response to NRC 800501 ltr re violation noted in IE Insp Repts 50-327/80-14 & 50-328/80-08. Corrective actions all Section 3 surveillance instructions comply w/ Section in of ABME boller code MILLB, L. M. Tennessee Valley Authority 80/06/09 ip
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Dymineralized Mater 8ys & Resultant Internal Contamination of Personnal." No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 80/06/24
- B007020627 Advises NRC that followup rept to B00612 response to IE Insp Rept 50-327/80-15 containing one infraction will be submitted by B00630 MILLS,L M Tennessee Valley Authority 80/06/26 ip
- 8007080220 Forwards rept on insp program re sys performance which was initiated in response to IE Insp Rept 50-327/60-15 Insp program should ensure sys performance will not be degraded. MILLS, L. H. Tennessee Valley Authority 80/06/27 12pp
- 8007230253 Forwards IE Bulletin 80-i6, "Potential Misapplication of Roseanunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Cutput Codes " Written response required. IE Circular 80-i6 also encl No written response required C/REILLY, J P. Region 2, Atlanta, Office of the Director. 80/06/27,
- 8007080331 Forwards response to Deviation Item 80-327/80-17-01/noted in IE Insp Repts 80-327/80-17 & 50-328/80-10 re inadequate fire barriers. Required insulation installed on seven conduits. & cover plates reinstalled on three conduit fittings HILLS.L.M. Tannessee Valley Authority 80/06/30. 3pp.
- 8007210036 Forwards response to IE Bulletin 80-08 re-examination of containment liner penetration welds Penetrations at Bequovah, Watts Dar & Bellefonte contain flued head design Design for Yellow Creek not yet completed.
 MILLS.L M Tennessee Valley Authority. 80/07/08 5pp.

1 0

- 9007210594 Responds to IE Bulletin 80~10 re contamination of nonradioactive sys Routine sampling & analysis program established Hill comply w/requirements should identified sys become contaminated MILLS.L M Tennessee Valley Authority 80/07/08 1p
- 8007310056 Forwards response to IE Bulletin 79-27 re loss of nonclass IE instrumentation & control power sys bus during operation No deficiencies discovered MILLS.L M Tennessee Valley Authority 80/07/15 Jop
- 8007290479 Forwards response to NRC 800626 1tr re violations noted in IE Insp Rept 50-327/80-20 Response withheld (ref 10FR2 790)
 MILLS.L. H Tennessee Valley Authority 80/07/21 1p
- 8007280498 Forwards addl response to IE Bulletin 80-06, "Engineered Bafety Feature (ESP) Reset Controls " Present control schemes adequate Equipment evaluation encl MILLS,L M Tennessee Valley Authority 80/07/24 5pp
- R. Pariodic operating reports & related correspondence
- 8007220358 Forwards monthly operating rept for June 1980. BALLENTINE, J M Tennessee Valley Authority 80/07/14 p
- S. Reportable occurrences, LERs & related correspondence
- 8007010087 PNB-II-80~007 on 800304, util amployee gained unauthorized entry to protected area & further access to reactor bldg Employee observed photographing fueling operation Search of areas entered revealed no contraband Employee apprehended TOBIN, M J., DANCE, H. C. Region 2, Atlanta, Office of the Director 80/03/03, 2pp
- B004240250 PNO-II-80-39, two issues currently under review by TVA which may result in delay in startup of unit. First issue covers replacing of split positioning pins used in mounting control rod guide tubes in upper core support assembly HARTIN.R., DAUCE, H. Region 2. Atlanta: Office of the Director, 80/03/12. 19
- 8007010382 Forwards LER 80-073/03L-0 GALHOUN: J. R Tennesse Valley Authority 80/06/23 ip
- ---B007010385 LER B0-0/3/03L-0 on 800520, during support & hanger insp, discrepancies discovered between as-built & as-analyzed configurations that could cause failure in piping during seiset event Deviations will be modified as required.

 SHEARINGEN, J. D Tannessee Valley Authority 80/06/23 Opp
- B007010435 Forwards LER 80-065/03L-0 GALHOUN, J R Tennessee Valley Authority. B0/06/23 1p.
- B00701052B Forwards LER 80-082/03L-0.
 CALHOUN, J. R Tennessee Valley Authority. 80/06/23. 1p
- --B007010539 LER B0-0B2/03L-0 on B00B26.w/unit in Mode 4.pressurizer heatup rate exceeded max allowable rate Caused by safety injunctor creating insurge into pressurizer. Level restored during recovery phase & temp restored to limits ROBINSON,F Tennessee Valley Authority 80/06/23 2pp
- 8007010417 Forwards LER 80-076/03L-0 CALHOUN, J. R Tennessee Valley Authority, 80/06/25, ip
- ---8007010419 LER 80-076/03L-0 on 800526 during normal operation, output circuit breaker on vital inverter 2-1 tripped causing 120 volt ac vital instrument power board 2-1 to become inogerable. Caused by thermostat being out of calibr.

 ROMINE, D. R. Tennessee Valley Authority 80/06/25 ip.
- 8007010479 Forwards LER 80-053/03L-0. GALHOUN, J. R. Tennessee Valley Authority. 80/06/25. 1p.

- --8007010502 LER 80-053/O3L-O an 800526, syc blog vent monitor O-RM-90-1320 declared inoperable due to loss of flow Caused by inoperative radiation monitor sample vacuum pump Other monitor sample pump valved in & monitor returned to syc HEREFORD. J M Tennessee Vailey Authority 80/06/25 1p
- 8007010525 Forwards LER 80-078/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/25 ip
- --8007010532 LER 80-078/03L-0 on 800526, during Mode 4 operation, boron concentration in RWST measured 2124 ppm Caused by boron concentration makeup being top high Boron diluted to proper concentration
 RECORD.D J Tennessee Valley Authority 80/06/24 2pp
- 8007010534 Forwards LER 80-081/03L-0 CALHOUN, J R Tennessee Valley Authority 80/04/25 Lp
- --8007010541 LER 80-081/03L-0 on 800527, during timing of 1-FCV-72-20, containment sump to train 8 of containment spray, for surveillance test 166 i.valve would not open Caused by switch controlling FCV-72-20 being out of adjustment ROMINE, D Tennessee Valley Authority 80/06/25 ip
- B007010490 Forwards LER 80-083/03L-0 CALHOUN, J # Tennessee Valley Authority 80/06/26 ip
- --8007010515 LER 80-083/03L-0 on 800529 pump motor on 0-RM-90~134 bur out causing common circuit breaker on 0-RM-90-134/141 & 1-RM-90-112 to trip Cause unknown Motor replaced ROMINE,P F Tennessee Valley Authority 80/06/26 2pp
- 8007010912 Forwards LER 80-080/03L-0 CALHOUN, J R Tennessee Valley Authority 80/06/26 1p
- --8007010522 LER SO-080/03L-0, an 800527, during test on 8 train of auxiliary bldg gas treatment systemetral fuse failed & tripped fan motor supply breaker Cause unknown Fuse replaced & sys declared operable RDMINE.D Tennessee Valley Authority 80/06/26 ip
- 8007080283 Forwards LER 80-040/01T-0 CALHOUN, J. R Tennessee Valley Authority 80/06/27 ip
- --8007080288 LER 80-040/01T-0 on 800531, upon preoperational testing o safety injection pumps, found that 6,900-volt breakers would lockout, preventing pump start Cause unknown Problem is being evaluated ROMINF, D Tennessee Valley Authority 80/06/27 ip
- 8007080334 Forwards LER 60-086/01T-0 GALHOUN, J R Tennesser Valley Authority 80/06/27 1p
- --B0070B0341 LER BQ-0B6/01T-0 on 890613. W/unit in Node i, centrifugal charging numps could fail due to insufficient flow delivery during postulated secondary side high energy line rupture w/coincident failure of power operated relief valve LOREK, M J Tannessee Valley Authority 80/06/27 2pp
- 8007110372 Forwards LER 80-087/031-0 GALHOUN, J R Tennessee Valley Authority 80/06/27 ip
- BO07080281 Forwards LER 80-085/01T-0 CALHQUN.J R Tennesses Valley Authority 80/06/30 1p-
- --B0070B0291 LER B0-0B5/01T-0 on B00530 during review of E0TS & AB078 equipment qualifications, sys solunoid valves found rated for 77 F normal ave temp Ambient temp may reach 104 F Cause not stated, New valves being Eur
- 8007080400 Forwards Special Rept 80-01 CALHOUN, J R Tennessee Valley Authority 80/07/01 Ip
- --8007080402 Special Rept 80-01 on 800405, firestop penetration MKI21 support clearence reported excessive during piping configuration insp Seven-day time requirement exceeded prior to penetration remassurement & closing on 800404 # Tennessee Velley Authority 80/07/01 ip

i

1

```
-8007250499 Special Rept BO-OR on 800706, moderator temp coefficient measured less positive than limit established in Tech Specs during low power physics testing Control rod withdrawel limit determined as shown in encl graph # Tennessee Valley Authority 80/07/15 2pp
7090249 Forwards revised final deficiency rept re spent fuel pool
ates
NLLS:L M  Tennessee Valley Authority   B0/07/02   1p
007090258 Nevised final deficiently rept ro spent fuel pool gates
Gates are not designed to Seismic Category I requirements
per Reg Guide I 13 GA aspects of gate integrity will be
verified for all three plants

* Tennessee Valley Authority 80/07/02 2pp
                                                                                                                                                                                                               8007290633 RO 80-2 on 800706 during low power physics testing at all-
control rods out configuration moderator temp coefficient
found out of spec Control rod withdrawal limits determined
% Tennessee Valley Authority 80/07/15 3pp
7150455 Forwards LER 80-093/017-0
ALHOUN.J R Tennessee Valley Authority 80/07/07 1p
                                                                                                                                                                                                               8007220568 Forwards LER 80-098/03L-0
CALHOUN,J R Tennesses Valley Authority 80/07/18 ip
007150466 EER 80-093/01T-0 on 800625, vent duct in temporary air lock discovered breaching aux bldg integrity Caused by unautherized installation of duct by const workers Duct removed, hole patched & sealed WILBOURN, G R Tennessee Valley Authority 80/07/07 2pp
                                                                                                                                                                                                               ~~8007220574 LER 80-098/03L-0 on 800624, during heat-up, tee fitting on pressurizer pressure sensing line for instrument i-PI-68-323 failed allowing primary coolent to leak into containment Caused by improper installation of ferrule ring on tee EMRATH.R M Tennessee Valley Authority 80/07/18 ip
7150504 Forwards LER 80-084/01T-0
ALHOUN,JR Tennessee Valley Authority 80/07/07 ip
                                                                                                                                                                                                              8007250418 Forwards LER 80-081/03L-0
CALHOUN, J R Tennessee Valley Authority 80/07/18
007150512 LER 80-084/01T-0 on 800623, control room integrity was
breached by removal of door C-49 for maint & removal of taps
from C-37 & C-50 for access Doors repaired or replaced
Personnel reinstructed
                                                                                                                                                                                                              8007290545 Forwards LER 80-087/03L-0
CALHOUN, J R Tennesses Valley Authority 80/07/18 ip
                                        Tennessee Valley Authority 80/07/07 2pp
 BULLIVAN, J H
                                                                                                                                                                                                               --BO07290459 LER 80-087/03L-0 on BO0A02, while in Mode 5 after inadvertent BI, diesel generators would not shut down normally after starting While attempting restart.lock out relays damaged Gause not stated Relays replaced CURTIS, J W Tennessee Valley Authority 80/06/27 2pp
7130470 Forwards LER 80-092/017-0
ALHOUN, J.R. Tennossee Valley Authority 80/07/08 ip.
007180488 LER 80-092/01T-0 on 800626.SR 4 8 1 1 1 a & 8R 4 8 1 1 2 a 4 were performed w/o subsequent 8-hour surveillance requirement being met Caused by personnel error due to shift change 8 hift & relief turnover procedure being changed RECORD, D J Tennessee Valley Authority 60/07/08 1p
                                                                                                                                                                                                              8007270790 Forwards LER 80-102/03L-0
GALHOUN, J R Tennessee Valley Authority 80/07/18 ip
                                                                                                                                                                                                              --8007290800 LER 80-102/03L-0 on 800622, while in Mode 3, operator observed 1-LI-3-110, steam generator 4 narrow range level. reading high Cause not stated Transmitter sense lines refilled & transmitter calibr checked REYNGLDB, R H Tennessee Valley Authority 80/07/18. ip.
7150580 Forwards updated LER 80-041/03L-1
ALHOUN.J R Tennessee Valley Authority 80/07/09. 1p.
007150595 Updated LER 80-041/03L-1 on 800430,1-FCV-32-i10 isolated on nonessential air pressure causing six valves providing flow to containment upper & lower compartment radiation monitors to close Gause unknown

MCGRIFF.J M Tennessee Valley Authority 80/07/09 2pp
                                                                                                                                                                                                              8007290822 Forwards LER 80-101/03L-0
CALHOUN.J R Tennessee Valley Authority 80/07/21 1p
                                                                                                                                                                                                                -8007290827 LER 80-101/03L-0 on 800422, steam generator level indicator
1-Li-3-51 was reading 10% higher than other two indicators
Caused by defective transmitter Defective transmitter was
7150491 Forwards LER 80-090/031-0
ALHOUN.J R Tennessee Valley Authority 80/07/10 ip
                                                                                                                                                                                                                        REYNOLDS, R H Tennessee Valley Authority 80/07/21 2pp
OC71505D1 LER 80-090/03L-0 on 800&13.discrepancy discovered between as-built & as-analyzed support & hanger configurations Full rept will be provided to NRC before initial criticality Daviations which could cause pipe failure will be modified EMEARINGEN.J D Tennessee Valley Authority 80/07/10 3pp
                                                                                                                                                                                                             8007250414 Forwards LER 60-091/03L-0
CALHOUN, J R Tennessee Valley Authority 80/07/22 ip
                                                                                                                                                                                                                --BOO7250416 LER BO-091/O3L-O on BOO625, while in Mode 3, containment sump
level.1-LI-63-179, indicated approx 10% w/other three
indicators reading zero Caused by defective loop
transmitter. Transmitter replaced & callbr
REYNOLDS, R H Tennessee Valley Authority, 80/07/22 2pp
/160519 Forwards LER 80-097/03L-0
ALHOUN,J R Tennessee Valley Authority 80/07/11 ip
007160923 LER 80-097/031-0 on 800616, cooling tower blowdown line effluent monitor (O-FR-27-175) declared inoperable Flow monitor recorder indicated incorrect flow Flow element retailer & design change in progress
BMITHSON, J D Tennessee Valley Authority 80/07/11 ip
                                                                                                                                                                                                             8007270636 Forwards LER BO-079/03L-0
CALHOUN, J R Tannessee Valley Authority 80/07/22 1p
                                                                                                                                                                                                             --8007290639 LER 80-099/03L-0 on 800623, valve 1-FCV-72-39 failed surveillance testing, rendering one train of containment spray sys inoperable Caused by limit switches being out of adjustment, not allowing proper closure Switches adjusted BIRCHELL, R. C Tennessee Valley Authority 80/07/22 ip.
7210461 Forwards LER 80-095/03L-0
ALHOUN,J R Tannessee Valley Authority B0/07/11. Ip
007210475 LER 80-095/03L-0 on 800614, auxiliary vent radiation monitor declared inoperable due to spurious high rad spikes. Caused by defective microswitch w/monitor inadvertently left in continuous advance mode
HEREFORD. J M Tennessee Valley Authority 80/07/11 1p
                                                                                                                                                                                                             8007290669 Forwards LER 80-107/03L-0
CALHOUN.J R Tennessee Valley Authority 80/07/22. ip
                                                                                                                                                                                                             --BO07290672 LER BO-107/03L-O on BO0623, while in Mode 3, steam generator 3 level indication, loop 1-1-3-97, indicated approx 10% higher than two narrow range channels Caused by defective transmitter on panel 1-1-185 in accumulator room 4 REYNOLDB.R.H Tannessee Valley Authority BO/07/22 2pp
'220469 Forwards LER 80~089/03L-0
NLHDUN, J.R. Tennessee Valley Authority 80/07/14 1p
007220474 LER 80-089/03L-0 on 800609, contract review revealed local centrol station selector switches (C-H type 102507) used in Class IE (incuits lack environ qualification for operation following high energy line break ROMINE, B Tennessee Valley Authority 80/07/14 2pp
                                                                                                                                                                                                            8007290810 Farwards LER 80-100/03L-0 CALHOUN, J R Tennessee Valley Authority 80/07/22, 1p.,
                                                                                                                                                                                                            --B007290B18 LER B0-100/O3L-0: on B00A23, containment isolation & purga exhaust valves FCV-30-37 & FCV-30-40 found to have excessive leakage. Caused by debris under seating surface Debris was blown out & valves restested BIRCHELL.R. C Tennessee Valley Authority 80/07/22, 1p.
'230436 Forwards Beetial Rept BO-02 re positive moderate temp
sefficient measured during low power physics testing at
1 control rods out of configuration
MLHDUNJR Tennessee Valley Authority 80/07/15 ip
```

- 8007290762 Forwards LER B0-108/03L-0 CALHOUN, J R Tennessee Valley Authority 80/07/23 1p
- BO07290865 Forwards LER 80~110/03L-0 GALHOUN.J R Tennessee Valley Authority 80/07/24 1p
- BO07290578 Forwards add1 copies of LER 80-041/03L-1 CALHOUN, J R Tennessee Valley Authority B0/07/25 1p
- BO07270649 Forwards LER 80-106/03L-0 GALHDUN, J. R Tennessee Valley Authority 80/07/25 1p
- ---B007290656 LER B0-106/O3L-0 on 800626, train B ERCW to turbine driven auxiliary feedwater pump isolation velve, 1-FCV-3-179B, found leaking excessively from tell-tale drain Caused by valve leaking through, Pump removed from svc & valve repaired BOLES, 0, B Tennessee Valley Authority 80/07/25 ip
- SOO7270662 Forwards revised LER 80-068/01T-1 GALHOUN, J R Tennessee Valley Authority 80/07/25 In
- 8007270675 Forwards LER 80-107/03L-0 CALHOUN,U R. Tennessee Valley Authority 80/07/25 ip
- ---8007290681 LER 80-109/03L-0 on 800626.during 81-166.containment spray pump discharge check valve.i A-A.found to leak excessively Caused by valve leaking through Pump removed from svc & valve repaired 80LE8.0 S Tennessee Valley Authority 80/07/25 ip
- B00729070B Forwards LER 80-111/03L-0 CALHOUN, J. R Tennessee Valley Authority B0/07/25 ip
- ---B007290715 LER 80-111/03L-0 on B00626, during normal operation, 1-FCV-62i36 (8 train to suction of charging pump from RWST) would not open from main control room Caused by valve operator torque spring being out of adjustment Spring readjusted ROMINE, D Tennessee Valley Authority 80/07/25 1p.
- T. Hearing transcripts on non-antitrust matters
- BOO7220061 Transcript of ACRS Subcommittee on Sequoyah Nuclear Plant BOO709 meeting in Washington DC Pp 1-266 * ACRS - Advisory Committee on Reactor Safeguards 80/07/09 325pp
- DOCKET 50-928 SEQUOYAH NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007020228 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCO,R L Assistant Director for Licensing 80/06/13 2pp
- 8007020747 Forwards requests for addl info re shielding review & containment sump. Responses should be submitted by 800701. Includes summary of shielding design review required by NRC 791109 itr implementing Item 2 1 6 b of NREG-0578 BCHWENCER, A Licensing Branch 2 80/06/19 10pp
- 8007020782 Forwards commitments to steam generator insp ports & Row 1 steam generator tubes. NRC requires commitment within 5 days re performance of required actions described in encl. Insp ports must be installed just above upper support plate BCHMENCER.A. Licensing Branch 2 80706/23 3pp

- BOO7030195 Forwards request for addl info re Table 17 2-1. "Critical Structures.Sys & Components." for FBAR, which identifies items subj to operational GA program Info requested by BOO300
 BCHWENCER, A Licensing Branch 2 BO/06/24 5pp
 - The state of the s
- 8007010384 Advises that util has received no response to 790928 request for extensions until Mar & Dec 1981 for Watts Bor 1 & 2 Addl safety requirements may result in completion by Jan 1981 for Sequoyah 2, May 1981 for Watts 1 & Feb 1982 for Watts 2 MILLS.L M Tennessee Volley Authority 80/06/26 1p
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EIGENHUT, D Q Division of Licensing 80/06/26 2pp
- 9007190472 Forwards response to NUREO-057B, TMI-2 Lessons Loarned Task Force status rept & short-term recommendations Consolidates previous ltrs Includes revisions to containment isolation & shielding items MILLS.L. M. Tennessee Valley Authority 80/07/03 1p
- 8007280001 "TVA Response to NUREG-0578, Short-Term Lessons Learned Requirements " * Tennessee Valley Authority 80/07/03 500pp
- 8007190640 Advises that response to FBAR.Guestion 2 76.will not be organized & prepared for submittal until 800801 MILLS.L M Tennessee Valley Authority 80/07/08 ip
- 8007190672 Submits recommendations re facility steam generators, in response to NRC 800623 ltr Camera device will be designed & tested for remote insp of tube supports in lieu of addl parts Max active tube surface margin will be mainLained MILLB.L M Tennessee Valley Authority 80/07/08 2pp
- 8007150521 Forwards info re Category 3 masonry walls, in response to NRC 800421 ltr Results of investigation of implace attachments to masonry walls will be submitted by 801017 Dversize encis available in Central Files (31 pp)
 MILLE, L M Tennessee Valley Authority 80/07/09 4pp
- --8007150922 "Design Criteria for Reinforced Concrete Block Walls " STONE,F A , CANNON,R W , LACY.F P Tennesses Valley Authority 72/04/07 29pp
- 8007150571 Forwards Revision 2 to util response to Item 2 1 da, NUREO-0578 Revision interporates leak testing procedures for waste gas sys (App E) & results of leak reduction program for liquid & gas sys (App E) MILLB.L M Tennessee Valley Authority 80/07/11 App
- --8007180978 Surveillance Instruction BI-405.Revision 1. "Weste Gas Sys Gross Leakage Test " KUEHN-L B Tennessee Valley Authority 80/06/12 14pp
- ---8007150882 Liquid sys leak test data CHURCH.J W Tennessee Valley Authority 80/07/01 9ap
- B007i60471 Responds to J Spraul informal questions re FSAR Table 17 2-i & forwards operational GA manual.App A.re critical sys & Part 3. Section 2.re matl & spare parts MILLS.L M Tennessee Valley Authority 80/07/ii 5pp
- --B007160478 Operational GA manual.App A.re critical structures, sys & components list
 OREEN.H J Tennessee Valley Authority 78/08/15 50pp
- --8007i60484 Operational QA manual,Part 3,Section2,re matl & spare parts * Tennessee Valley Authority 78/08/29 33pp
- 8007280006 Notification of 800723 meeting w/utils in Bethesda, MD to discuss matters re TMI-2 dated requirements DROMERICK.A W. Licensing Branch 1 KERRIOAN, J D , STABLE.C R Licensing Branch 2, 80/07/16 6pp
- 8007230467 Forwards response to NRC 800807 request for commitment to meet requirements & associated schedules in five specific TMI items includes shift manning.licensing examinations & licensed dissemination of operating experience MILLS.L M Tennessee Velley Authority 80/07/18 4pp
- 8007230477 Forwards response to NRC 800619 request for addl info re shielding design review. Sigh range containment radiation monitor & access control of areas adjacent to spent fuel transfer tubes MILLS.L.M. Tennesses Valley Authority 80/07/18 8ps

- 007230480 Forwards "ECOPAC Bolidification Sys Process Control Program." Revision 4.in response to NRC 800324 request MILLS.L M Tennessee Valley Authority 80/07/18 ip
- -8007230481 "ECOPAC Solidification Sys Process Control Program," Revision 4
 - Tennessee Valley Authority 80/07/18 20pp
- -8007230483 "Technical Rept on Urea Formaldehyde " Marked-up Amefco rept on procedure for unsite solidification of low level radwaste at facility encl # Ansfco.lnc 80/07/18 45pp
- 007230533 Forwards response to N Mendonce B00627 questions re reactor vessel head venting sys Westinghouse is developing procedures for inadequate core cooling for recommended use of vent sys by utils MILLS,L N Tennessee Valley Authority B0/07/18 iipp
- 00723040B Forwards add1 info per NRC B00619 request re control of containment sump debris MILLS.L M Tennessee Valley Authority B0/07/21 14pp
- 007290724 Forwards description of program, "Training for Mitigating Core Damage " Program was developed to ensure that all licensed operating employees are properly trained to use available info should accident occur involving core damage MILLS.L M Tennessee Valley Authority 80/07/22 5pp.
- 007280A23 Advises NRC of evaluation of potential hazards in vicinity of plant & of main control room habitability sys for protection from radioactive & toxic gas releases Plant operators are adequately protected from possible hazards MILLS, L. H. Tennessee Valley Authority 80/07/24 ip
- 007290757 Forwards data & drawings re settlement monitoring Revised Questions SNP 02 84 & SNP 02 73 will be incorporated into FBAR in next smend No significant settlement observed. Drawings available in Contral Files only MILLB.L. M Tennessee Valley Authority B0/07/28 12pp
- 007310394 Advises that short-term items & two long-term items listed in NUREO-0011 re main control room design review have been corrected Util committed to investigate feasibility of correcting remaining items of first refueling outage MILLS,L M Tennessee Valley Authority 80/07/28 4pp
- 007310411 Submits test results of plant auxiliary bldg gas treatment sys per requirements of SER, Suppl i Negative pressure equal to or more negative than minus 1/4-inch water gauge relative to outside atmosphere was achieved in pump rooms MILLS, L. M. Tennessee Valley Authority 80/07/29, ip
- 0073:0416 Forwards addl info on temp control for main steam valve rooms.per O Parr request MILLS.L M Tennessee Valley Authority 80/07/27 2pp
- Security, medical, emergency & fire protection plans
- 007160643 Forwards revised commitment for fire protection program re-evaluation, Section A 3(b), re locking of fire protection water sys valves Revision was made in response to IE Insp. Repts 50-327/80-10 & 50-328/80-06
 MILLB,L M Tennessee Valley Authority 80/07/03 3pp
- 007230575 Forwards revised radiological emergency plan w/cross-ref between glan & NOREG-0454 & App F.TN radiological emergency responso plan Encis available in Central Files only MILLS.L M Tennessee Valley Authority 80/07/21 3pp
- 00728054B Advises that Westinghouse reviewed power-ascension test procedures per Tosk Action Plan Item 1 C 7.Review of emergency procedures documented by 800428 ltr to LB Rubenstein.
- Tennessee Valley Authority 80/07/23 ip
- 007300434 Agrees, as interim step decided at NRC B00735 meeting, to expand near site press facility to provide for command control function for emergency response Central emergency response ctr.per util 800721 ltr.requires addi discussion MILLS, L.M. Tennessee Valley Authority, 80/07/28, ip
- Adjudicatory correspondence

11.

007310243 Forwards Chinissin CCCPT managed the arrest containing decisions on the first and the formation of 780443 memoral, in a core to the first send taction refire protect in order to a limit of the first send to a

- K Utility Final Bafety Analysis Report (FSAR) & amends
- BOO7300374 Amend to OL application, consisting of Amend 66 to FEAR, revising Chapters 2,3,5,6 & 15 FBAR documentation of items transmitted by LM Mills BOO613 ltr & responses to NRC questions encl CROSS, J. L Tennessee Valley Authority 80/07/25 ip.
- D Advisory Committee on Reactor Safeguards reports & correspondence
- BOO7230013 Notice of ACRS Bubcommittee on Sequoyah Nuclear Plant BOO709 meeting in Washington, DC to review DL request HOYLE, J C Office of the Secretary of the Commission 60/04/18.
- BOO7R1024B Discusses review conducted at 243rd ACRS meeting on 800710-12 of util application to operate at full power Facilities can be operated at levels up to full power w/o undue risk if items outlined are considered PLESET.M S ACRS Advisory Committee on Reactor Bafeguards. . Jpp
- 8007210531 Responds to 800710 request re particular aspects of facility Applicant committed to expedite installation of distributed ignition sys. No practical need to hold up issuance of OL pending completion of proposed sys. PLESEET.M S ACRS Advisory Committee on Reactor Safeguards 90/07/15 ip
- BOO7290022 Forwards Ahearne BOO715 ltr re ACRB review of application for authorization to operate BCHWENCER, A Licensing Branch 2. BO/07/17 3pp
- P. Operating license stage documents & correspondence
- 8007290679 Forwards preliminary assessment of potential for harge tow heading upstream impacting new essential raw cooling water pumping station Station not required for safe operation of MILLE, L M Tennessee Valley Authority 80/07/28 2pp
- G Inspection reports, IE Bulletine & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode."
 No response required.
 D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/05/08.
- 8007020192 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs "No written response required. O'REILLY,J P Region 2. Atlants, Office of the Director. 80/05/20
- 8007210488 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/05/28.
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feadwater Pumps " No written response required.

 O'REILLY J P Region 2, Atlanta, Office of the Director. 80/05/29,
- BO07180005 Forwards IE Insp Repts 50-327/80-19 & 50-328/80-12 on B00513-16. No noncompliance noted. LEHIS:R C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch B0/06/05 2pp
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs," No written response required.
 D'REILLY, J. P. Region 2, Atlanta, Diffice of the Director. 80/06/10.

- 8007160287 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " no specific action or response required O'REILLY, J.P. Region 2, Atlanta, Diffice of the Director 80/06/11
- B007250384 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/04/13
- 8007290846 Forwards IE Insp Rept 50-328/80-13 on 800922 & 23 No noncompliance noted BTCHR,J P Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 80/06/19 2pp
- --B007290B53 IE Insp Rept 50-328/B0-13 on B00522 & 23 No noncompliance noted Major areas inspected preparational & sperational environ monitoring programs

 JENKINS. OR Region 2. Atlanta, Fuel Facility & Materials Safety Branch CUNNINGHAM. A L. Region 2. Atlanta, Office of the Director B0/06/17 App
- 8007020391 Forwards IE Circulat 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/20
- BOO7110034 Ack receipt of 800523 ltr informing NRC of staps taken to correct violation noted in IE Insp Repts 50-327/80-14 & 50-328/80-08 MRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/24 lp
- --8007110039 Submits add1 response to NRC 800501 ltr re violation noted in IE Insp Repts 50-327/80-14 & 50-328/80-08 Corrective actions all Section 3 surveillance instructions comply w/ Section 11 of ASNE boiler code MILLS,L.M Tennessee Valley Authority 80/06/09 1p
- 8007170070 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Bys & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24
- 8007230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes" Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/27
- 8007080331 Forwards response to Deviation Item 50-327/80-17-01, noted in IE Imp Repts 50-327/80-17 & 50-328/80-10 re inadequate fire barriers Required insulation installed on seven conduits, & cover plates reinstalled on three conduit fittings
 MILLS, M. Tennessee Valley Authority 80/06/20 3pp
- 8007210036 Forwards response to IE Bulletin 80-08 re-examination of containment liner penetration welds Penetrations at Sequoyah. Watts Bar & Bellefonte contain flued head design Design for Yellow Creek not yet completed MILLS,L M Tennessee Valley Authority 80/07/08 5pp
- 8007230494 Responds to NRC 800625 ltr re deviation in IE Insp Rept 50-328/80-11 Corrective actions nondestructive examiners were cautioned & reminded that any & all failures to obtain complete scans must be documented MILLS,L M Tennessee Valley Authority 80/07/17 2pp
- 8007280498 Forwards add1 response to 1E Bulletin UO-06, "Engineered Safety Feature (ESF) Reset Controls " Present control schemes adequate Equipment evaluation encl MILLS:I. M Tennessee Vallay Authority 60/07/24 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007160571 Forwards final deficiency rept re chemical & vol control system centrifugal charging pumps
 MILLS,L M Tennessee Valley Authority 60/06/10 ip
- ---8007160578 Final deficiency rept re potential for degradation of one or more chemical & vol control sys centrifugal charging pumps
 Design & plant emergency operating procedures will be modified, as recommended by Hestinghouse
 * Tennessee Valley Authority 80/06/18 2pp

- BOD7170664 Part 21 Final Lept to Westinghouse Chemical & vol control sys contribugal charging pumps following secondary wide high energy line rupture & associated Leactor trip, mis flow may not be met Emergency operating pracedures modified MILLS.L M. Tonnessee Valley Authority 80/06/18 App
- 8007020543 Forwards final deficiency lept re-safety-reinted Cable inside containment
 MILLSL B Tomossee Valley Authority 80/06/26 lp
- --8007020545 Final deficiency trpt re-safety related cable inside containment Util will currect exposed cable & terminal boses by running cables in conduct, which will provide sufficient shiplding for qualification to remain valid # Tennessee Valley Authority 80706726 2pp
- 8007020944 Forwards final deficiency rept re wide stoom generator lavel transmittors
 MILLS,I M Tennessee Valley Authority 80/06/26 ip
- --H007020551 Final deficiency rept to wide range steam generator level transmitters Transmitters will be replaced by qualified transmitters Installation will be completed before preoperational testing of sys 4 Tennessee Valley Authority 80/05/26 1p
- 8007090949 Forwards revised final deficiency rept to spent fuel pool gates
 MILLS.L M [ennossee Valley Authority 80/07/0, Ip
- ~~8007090256 Revised final deficiency mept re spent fool pool gates Oates are not designed to Seismic Category I inquirements per Reg Guide i 13 GA aspects of gate integrity will be verified for all three plants * Tennessee Valley Authority 80/0//02 2pp
- 8007140443 Forwards first interim deficiency rept re solution switches environ qualification Will submit next rept by 800812 MILLBL M Tennessee Valley Authority 80/07/67 tp
- B007140666 Gecond interim deficiency rept re environ qualification of Class IE instruments in valve room All instruments are being evaluated Next rept will be submitted by 800912 MILLS.L M Tennessoe Valley Authority 80707707 ip
- 8007230431 First interim deficiency rept re environ qualification of Class IE equipment Util cherking files & petitioning manufacturors of components for required environ decumentation

 MILLS, L. M. Tennessee Valley Authority 80/0//16 App
- 8007230486 First interim deficioncy rept re safety injection pump breaker lockout initially repurted 800619 No visual or audial indication when lockout condition exists Problem under investigation Net rept to be submitted by 8000129 MILLS.L M Tennessee Valley Authority 80/07/10 Ppp
- 8007290632 Third interim deficiency rept so UHI hydraulic isolation valve accumulator weighing syr Util & Westinghouse are pursuing solution to problem Next rept will be rubmitted by 801001
 MILLS.L.M. Tennessee Valley Authority 80/0//2} ip
- B007270610 Second interim deficiency replies defective suartar vensel upper internals guids tube support pins Westinghouse has not completed evaluation of pint taken from operating plant. Next rapt will be forwarded by 880911 O'REILLY, J.P. Tonnessee Valley Authoristy 80/07/24 1p
- T. Hearing transcripts on non-amfittudt matters
- 800722006) Transcript of ACRS Gobiommitter on Sequeyah Nuclear Plant 800709 meeting in Washington NC Pp 1-266 # ACRS - Advisory Committee on Reactor Sufagoards 8000709

- OCKET 50-329 MIDLAND PLANT, UNIT 1
- Application/construction stage documents & correspondence
- 007020159 Discusses D Hood 791031 memo re potential for post-LOCA flow bloctage for PHR plants caused by containment sump screen deficiency Assessment needed to determine whether Board notification pecessary VARGA, S A Assistant Director for Light Water Reactors 79/11/24
- -8007020167 Discusses 791031 telcon w/util re 790917 trip rept of containment sump screen deficiency & B&W concern re potential for post-LOCA flow blockage Review requested to determine whether Board notification necessary HOOD, D Light Water Reactors Branch 4 79710/31 1p
- 007020151 Requests info from CP & OL applicants re BA Varga 791126 memo on post-LOCA flow blockage for PWR plants, based on insulation type & sump screen mesh size Evaluation necessary to determine whether Board notification necessary MATTSON.R J Division of Systems Safety 79/12/13 2pp
- 007310386 Forwards TR-3887-2, "Acceptability for Svc of Midland Reactor Pressure Vessel Anchor Studs." Revision 1 Related correspondence
 DOBSON, W.G., COOPER, W.E., Teledyne Engineering Services 80/05/15
- -8007310387 "Acceptability for Svc of Midland Reactor Pressure Vessel Anchor Studs:" Revision 1 Related correspondence # Teledyne Engineering Services TR-3887-2 Ri NO1 BO/05/20
- 007010597 Forwards NRC reoganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO,R L. Assistant Director for Licensing 80/06/13 2pp
- 007070119 Forwards "Model Testing of Containment Bump ECCS Recirculation Intakes," prepared by Western Canada Hydraulic Labs.Ltd.for Bechtel Power Co Comments on NRC 790917 trip rept encl
 COOK, J W Consumers Power Co 80/06/26 10pp
- -8007070130 "Model Testing of Containment Sump ECCS Recirculation Intakes," prepared for Becktel Power Co & util * Western Canada Hydraulic Laboratories, Ltd 80/04/30 92pp
- 007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0674 EISENNUT, D G Division of Licensing 80/04/26 2pp
- 0071B0081 Forwards request for add1 info re plant fill to support required geotechnical engineering studies for review of responses to NRC 791119 request SCHMENGER.A Licensing Branch 3 80/06/30 9pp
- 007280060 Responds to NRC 800522 ltr requiring two actions prior to resumption of safety-related work by Zack Co Limited work that is performed will be evaluated & if acceptance level of confidence is attained, then full production can resume CDGK.JW Consumers Power Co 80/06/30 8pp
- 007230116 Advises that util is not exempt from fee requirements for 791219 application for CP amends Any CP amends to be issued by NRC are not seen as resulting from 791206 order MILLER, W O License Fee Management Branch 80/07/03 ip
- 007280041 Submits revised facility project schedule Integrated 2-unit startup program retained Sept 1930 NRC Yellowbook update transmittal will reflect milestone dates based on listed completion dates.

 MILLER, D B Consumers Power Co 80/07/03 1p
- 007140496 Summary of 800929 meeting w/util.Bechtel.B&W & Teledyne in Bethesda.HD re three reactor vessel hold-down studs preservice failure HODD.B S Licensing Branch 3 80/07/07 10pp
- 007180019 Forwards guidelines for seismic & structural design analysis audit planned as part of review of OL application Info should be filled in on guideline forms prior to audit Audit will take faye working days SCHWENCER.A Licensing Branch & 80/07/07 187pp

- 8007230507 Lists drawings & sketches submitted by util found to be partially illegible Independent confirmatory piping analysis requested by NRC cannot be performed until better copies are obtained BATES, JO Rockwell International Corp. Energy Systems Div BO/07/07 2pp
- BOO7150497 Comments on proposed addl guidance on potential for low fracture toughness & lamellar twaring of LWR component support structures NRC generic guidance invalidates many support designs developed per past applicable codes & atds CODK.JW Consumers Power Co 80/07/08 4pp
- BOO7240040 Motification of B00B05 meeting w/util in Bethesda, HD to discuss schedules for const & licensing review HOOD, D & Licensing Branch 3 80/07/09 App
- 8007210483 Forwards updated FBAR Pages 3 8-24 through 3 9-26s,Pages 17 1-11 through 17 1-14 & Question & Response Pages 17 1-1 through 17 1-4 in response to NRC 800522 ltr W/o encl QOOK,JW Cansumers Pawer Cb 80/07/14 2pp
- 8007300104 Notification of 800731 meeting w/vtil & Bechtel in Bethesda, MD to discuss addl info on plant fill HOOD,D B Licensing Branch 3 , 80/07/21 4pp
- BD07300261 Notification of B00728 & 27 meetings & plant tour w/util & Bechtel to assess const completion schedules Meeting agenda & FR exempt encl
 H000.0 B Licensing Branch 3 80/07/21. 7pp
- 8007270036 Notification of 800821 open mesting w/util in Bethesda.MD, originally scheduled 800805, to discuss const & licensing raview schedules
 HOOD.D B Licensing Branch 3 80/07/22 Spp
- SD07290701 Objects to exclusion of proposed amends from 10CFR170 22, Fontnote 2.which excepts such amends from license fee requirements Requests reconsideration BRUNNER.J E Consumers Power Co 80/07/22 3pp
- --8007290707 Responds to 800403 Itr objecting to fees for 791219 application for amend to CPs Commission 791206 order does require application therefore exemption to 10CFR170 22 is not applicable MILLER. H O License Fee Management Branch 80/07/03 ip
- F Security, medical, emergency & fire protection plans
- BD07010473 Discusses proposed change to 10CFR30 adding requirement for fire protection plan at facilities Forwards comments on rule, supplementing consultant comments Guestions appropriateness of rule, since rule reopens resolved issues HOFFMAN, D P Consumers Power Co 80/06/27 8pp
- BDO7090393 Summary of B00611 meeting w/util & Bechtel in Bethesda. MD re security plans to protect against radiological sabotage HDOD, D Licensing Branch 3 80/06/30 App
- O Adjudicatory correspondence
- BOO7080051 Patition to intervene re-order for CP mod-alleging that mod-will result in unsafe & inefficient exercise of atomic energy use & will create adverse environ affects Centificate of Svc encl WILSON,G C Affiliation Unknown 80/06/24 3pp
- 8007070282 Petition to intervene in CP mod proceeding alleging that unresolved soil suttlement problems will create adverse safety problems Certificate of Bvc encl MILLER.T R Affiliation Unknown 80/06/25 3pp
- 8007080039 Petition to intervene in CP mod proceeding, alleging that unresolved soil settlement problems will adversely affect safety & will create inefficient exercise of atomic energy use Questions integrity of const. Certificate of Syc encl RACE, M.A. Affiliation Unknown 80/06/25 3pp
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D Q Division of Licensing 80/06/25 87pp
- 8007080054 Petition to intervene re order for CP mod.alleging that unresolved soil settlement issue will create adverse safety problems & will result in inefficient exercise of atomic energy use Certificate of Svc encl
 REIST.S D Affiliation Unknown 80/06/26 3pp

- BOO7020582 Memorandum & order granting NRC BOO616 request to postpone response to CPC BOO527 motion seeking consolidation of soil canditions & plant fill matls issues to DL & order for license mod proceedings
 SMITH, I W Atomic Bafety and Licensing Board Panel BO/06/2/ ip
- 6007010333 Ack recript of 800617 ltr re recent containment bldg publicity Util ltr re inconsistent cross-referencing between 86M & Bechtel encl Further rept on issue will be provided when available Representation status requested PATON, N D Hearing Branch 4 80/06/30 2pp
- BO07140017 Petition in opposition to util motion for consolidation re 791206 order modifying CPs Urges postponement of response & requests that activities be stopped due to deficiencies in const & safety-related structures HARBHALL, W H Mapleton Intervenors 80/06/30 2pp
- BOO7090045 Response stating no present opposition to WA Thibodeau.TR Miller.PA Race.B Stamiris & C Oilbert patitions to intervene Reserves right to oppose participation in future development & urges consolidation Certificate of Svc encl MILLER.M I . FARNELL.A S. Consumers Power Co MILLER.M I Isham. Lincoln & Beale 80/07/01 Spp
- 8007090055 Response in support of C Gilbert 800616 petition to intervene in CPs mod proceeding. Standing requirement satisfied Ruling on contention requirement premature Certificate of Svc encl PATON, W. D Hearing Branch 4. 80/07/07 6pp
- BO07140020 Response stating no present opposition to SK Harren. SD Reist, QC Hilson & MA Race patitions to intervene re license mod Reserves right for future objection & urges representation by single spokesman Certificate of Svc encl HILLER. H I , FARNELL. A B. Gonsumers Power Co Miller. M I Isham, Lincoln & Beale. B0/07/08 6pp
- 6007170226 Response in support of WA Thibodeau, TR Miller, GC Wilson, SD Raist, PA Race, B Harren, MA Race & B Stamiris petitions to intervene re 791206 order modifying CPs Ruling on adequacy premature Certificate of Svc encl PATON, W D Hearing Branch 4 80/07/14 App
- 8007170232 Response in support of WH Marshall 800623 petition to intervene re 791206 order modifying CPs Ruling on adequacy premature. Certificate of Bvc encl PATON, W D. Hearing Branch 4 80/07/14 App
- BOO7220194 Response to Mapleton Intervenors 800630 petition Argument rs consolidation untimely Request to postpone NRC response to CPC mution most Soil-related issues are within scope of CL proceeding & NRC 791206 order Certificate of Svc encl.
 MILLER, M I Consumers Power Co MILLER, M I Isham, Lincoln & Beale 80/07/15 8pp
- 8007170385 Advises that HH Harshall of Mapleton Intervenors 800430 patition to ALLS should not be given consideration at present stage since intervenor not yet admitted in proceeding PATON. H D Hearing Branch 4 80/07/16 ip
- BOO7;80242 Responds to 800410 ltr urging NRC action to stop const Issue will be submitted to ASLB who has proper jurisdiction over master in controversy Reminds of MRC position that WH Marshall has standing to intervens PATON, W D Hearing Branch 4 80/07/17 2pp
- 9007300421 Advises that util & Bechtel Power Corp have reached agreement on revised schedule re commercial operation of Units 1 & 2. Unit 2 scheduled for commercial operation in Dec 1963 & Unit 1 in Jul 1984 OIBBS.N E Isham. Lincoln & Beale 80/07/22 ip
- BOO7290730 Order & notice of BO0710 special prehearing conference in Midland, MI re identification of issues ruling upon intervention patitions & other related issues Public invited to attend w/o active participation SMITH, I.W. Atomic Safety and Licensing Board Panel BO/07/24 3pp
- 9007270752 Order denying Mapleton Intervenors' 800630 petition urging ASLB not to consider CPC motion for consolidation Intervenor may respond directly to motion.

 BMITH I H. Atomic Safety and Licensing Board Panel. 80/07/24 2pp
- BOO7270766 Hemorandum & order ruling that petitioners PA Race.B STemaris, SD Reist, SK Warren, TR Miller, MA Race. QC Wilson, WA Thibedeau & C Gilbert have satisfied interest & aspect requirements Conference rs DL will be set for BOO710 BMITH, I. W Atomic Safety and Licensing Board Panel 80/07/24 5pg

- H General correspondence
- 8007180168 Opposes const of facilities Great Lakes region would be destroyed if TMI-type accident occurred * Affiliation,Unknown 80/05/16 lp
- 8007110488 Responds to 800600 ltr re NRC insps of reactor vessel anchor bolts Bolts are susceptible to cracks in thread area due to original bolt specs, selection of matls & method of heat treating NRC reviewing revised design to determine adequacy STRASMA. J. Region 3. Chicago. Office of the Director 80/06/23 ip
- 8007280323 Responds to 800321 Itr requesting info re PA D'Archangel request that NRC expedite facility licensing Addl NRC effort resulting from TMI-2 accident caused delays in licensing Development of schedule for review of application underway DIRCKB.W J Office of the Executive Director for Operations 80/07/02 Spp
- --8007280536 Requests response to encl PA D'Archangel lt; requesting that NRC expedite facility licensing BANYER.M S House of Rep 80/05/Pi 2pp
- 8007140634 Requests response to each WH Marshall itr re Oct 1979 request for info about facility Request unanswered ALBOSTAD House of Rep. 80/07/09 2pp
- --BOO7160649 Provides list of conditions for which info is requested re safeguards for public health & safety Also requests resolutions re cracking dewatering bldg settlements & caisons problems per NRC 790223 & 0305 meetings in IL MARBHALL.H H Maploton Intervenors 79/09/04 2pp
- BOO7230190 Responds to BOO603 ltr re frequency of correlation strength test sampling on new safety-related concrete NRC position reflects increased testing during periods of low vol placement BCHMENCER, A Licensing Branch 3 80/07/09 Spp
- 8007190697 Forwards current rules of practice W/g enci PATON,W D Hearing Branch 4 60/07/11 lp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007240146 Updated FBAN Pages 3 B-P4 through 3 B-P6a,FBAR Pages 17 1-11 through 17 1-14b & Question & Response Pages 17 1-1 through 17 1-4 to be included in FBAR.Revision 2, in response to NRC 800522 itr # Consumers Power Cg 80/07/14 14ap
- Q Inspection reports. IE Bullatins & correspondence
- 8006300114 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on B00301-31 No nancompliance noted FIDRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/09/14 2pp
- --8006300138 IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No nencompliance noted Major areas insperted exam of site conditions & detensioning reactor vessel holddown bults CDDK,R J , KNOP,R C Region 3, Chicago, Office of the Director 80/05/13 Spp
- 8007210360 Forwards IE Circular 80-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies" No written response required KEPPLER, J. G. Region 3: Chicago. Office of the Director B0/05/28 1e
- 8007010144 Forwards IE Info Notice 80 23, "Loss of Suttion to Emergency Feedwater Pumps" No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/05/29 ip
- B007020649 Forwards status of actions to provide corrected response to IE Dulletin 79-02 Fanal response or status rept will be submitted by 801031 CDGK.J W. Consumers Power Co. 80/06/09 4pp
- 8007220183 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required KEPPLER, J. G. Region 3. Chicago. Office of the Director 80/06/10

- 40178 Forwards IE Info Notice 80-27, "Degradation of Reactor lant Pump Study " No specific action or response
- PLER.J G Region 3, Chicago, Office of the Director 80/06/11
- 80707 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in ordance W/10CFR50-55(e) " No written response required PLER.J G Region 3. Chicago. Office of the Director 80/06/13
- 20306 Responds to IE Bulletin BD-09, "Hydramotor Actuator iclencies "Vendors evaluating which actuators will uire mod or replacement to which will neet specuirements respring & sixing nomograph problem W.J. P. Consumers Power Co. BD/06/17 2pp
- 30402 Forwards IE Insp Repts 50-329/80-16 & 50-330/80-17 on MQ1-30 No nonrumpliance noted

 RELLI, G Region 3, Chicago, Reactor Construction & Engineering
 port Branch 80/06/17 2pp
- 07230412 IE Insp Repts 50-329/80-16 & 50-330/80-17 on 800401-30 No oncompliance noted Major areas inspected site conditions, reactor vessel holddown bolts & Unit I reactor coolant IODK, R T Region J. Chicago. Office of the Birector HAYES, D W legion J. Chicago. Reactor Construction & Engineering Support Branch 80/06/05 4pp
-)20562 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pumpsling & Natural Circulation Cooldown" No written response quired
 PPLER, J G Region 3, Chicago, Office of the Director 80/06/20
- 170467 Forwards IE Circular 80-14. "Radioactive Contamination of nt Deminerallized Water Sys & Resultant Internal stamination of Personnel " No written response required SPLER. J G Region 3. Chicago, Office of the Director 80/06/24
- 300300 Forwards IE Insp Repts 50-329/80-10 & 50-330/80-19 on 5501-31 No noncompliance noted MRELLI, G Region 3, Chicago, Reactor Construction & Engineering sport Branch 80/06/26 2pp
- 17300304 IE Insp Repts 50-329/80-18 & 50-330/80-19 on 800501-31 No noncompliance noted Major areas inspected suspect pips whip restraint bolting const activities of Zack Co. detensioning if reactor vessel holdown bolts & audit of Peabody Testing CODK. 8 J. KNOP. R G. Region G. Chicago, Office of the Director 80/06/24
- 230358 Forwards IE Bulletin 80-16. "Potential Misapplication of semount Inc Models 1151 to 1152 Pressure Transmitters ither A or D Output Codes " Written response required Circular 80-16 also and No written response required PPLER.J G Region 3. Chicago. Office of the Director 80/06/2 80/04/27
- 170625 Forwards TE Insp Repts 50-329/80-15 & 50-330/80-16 on 0602-05 No noncompliance noted ORELLIG Region 3. Chicago, Reactor Construction & Engineering pport Branch 80/06/30 2pp
- 07170635 IE Inap Repts 50-329/80-19 & 50-330/80-14 on 800602-05 No noncompliance noted Major areas inspected records & test results of steam generator anchor bolts & pape restraint
- VANDEL.Y E , ERB.C M , MAIDU.K R Region 3: Chicago, Office of the 80/06/26 12pp
- '160612 Providet interim response to IE Bulletin 90-08 re amination of liner penetration wolds Includes list of netration info un joint type flued head moth sleeve math & ameter type of examination performed & repair info IDK, J W Consumers Power Co 90/07/11 lipp
- '310521 Ack receipt of B00630 ltr informing NRC of steps taken to irrect const problems noted in IE Imap Repts 50-329/80-14 & -330/80-15
- Region 3. Chicago, Office of the Director 80/07/25
- 007310529 Forwards response to NRC 800522 ltr re const problems noted in IE losp Repts 50-329/80-14 & 50-330/80-15 Corrective actions Jack Co GA manual & GC control procedures were reviewed for edequacy & clarity CDOK.J W Consumers Power Co 80/06/30 App

- R Periodic operating reports & related correspondence
- 8007280124 Forwards Bechtel nonconformance repts. GA audit finding rept, mgt corrective action rept. B&W repts of nonconformity & util nonconformance repts, audit finding repts & corrective action repts for June 1980 COOK, J W Consumers Power Co 80/07/21 360pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007310386 Forwards TR-3887-2, "Acceptability for 8vc of Midland Reactor Pressure Vessel Anchor Stude," Revision 1 Related DOBSON, W G . COOPER, W E Teledyne Engineering Services
- -8007310387 "Acceptability for Svc of Midland Reactor Pressure Vessel Anchor Studs." Revision 1 Related correspondence * Teledyne Engineering Services TR-3887-2 Ri NO1 80/05/20.
- 8007i60807 Part 21 rept re defective fastener matls A490 & A540 supplied by Southern Bolt & Fastener Gorp for site assembly & installation of pipe whip restraints Possibly caused by improper heat treatment or wrong matls supplied HARBISON, D NPS Industries, Inc. 80/06/16 lipp
- 8007070197 Ack receipt of 800613 interim deficiency rept re component qualification test documentation re-review FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/23 ip
- 8007150032 Ack receipt of 800612 interim deficiency rept re broken reactor vessel anchor bolts Will review final rept upon receipt FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/24 ip
- 8007170520 Ack receipt of 800619 interim deficiency rept re letdown cooler supports FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/01 ip
- 8007240353 Interim Part 21 rept to defective ITT actuators in dampers. Customer notification encl Jobs classified nonnuclear safety-related are not reportable, actuators supplied for other jobs are considered purchaser responsibility SLOAN, D.E. American Warming & Ventilating, Inc. 80/07/08 50pp.
- 8007270206 Final deficiency rept re emergency core cooling actuation sys digital Subsystem 2 logic circuitry drawings 8kW will correct drawings by 800930 Facilities will be in conformance bu 800930 COOK. J. H Consumers Power Co 80/07/17 5pp

DOCKET SO-330 MIDLAND PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- B007020139 Discusses D Hond 791031 memo re potential for post-LDCA flow blockage for PWR plants caused by containment sump screen deficiency Assessment needed to determine whether Board notification necessary VAR9A:8 A Assistant Director for Light Water Reactors 79/11/26.
- ---BOO7020167 Discusses 791031 telcon w/util re 790917 trip rept of containment sump screen deficiency & B&W concern re potential for post-LOGA flow blockage Review requested to determine whether Board notification necessary.

 HOOD, D Light Water Reactors Branch 4 79/10/31 ip
- B007020151 Requests info from CP & OL applicants re SA Varge 791126 memo on post-LOCA flow blockage for PWR plants, based on insulation type & sump screen mesh size Evaluation incressary to determine whather Soard hotification necessary MATTSON.R J Division of Systems Safety 79/12/13 2pp
- 8007310386 Forwards TR-3087-2, "Acceptability for 8vc of Midland Reactor Pressure Vessel Anchor Studs," Revision 1.Related COTFOSPONÓBISCO DOBBON, W 9 . COOPER. W E. Seledyne Engineering Bervices 80/05/15
- --8007310387 "Acceptability for Rvc of Midland Reactor Pressure Vessel
 Anchor Stude: "Revision 1. Related correspondence
 # Teledyne Engineering Services TR-3887-2 Ri NO1. 80/05/20.

- 8007010557 Forwards NRC reoganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.A L Assistant Director for Licensing 80/06/13 2pp
- B007070119 Forwards "Model Testing of Containment Sump ECCS
 Recirculation Intakes," prepared by Western Canada Hydraulic
 Labs.Ltd, for Bechtel Power Co Comments on NRC 790917 trip
 rept encl
 GOOK,J W Consumers Power Co 80/06/26 10pp
- --8007070130 "Model Testing of Containment Sump ECCS Recirculation Intakes," prepared for Bechtel Power Co & util * Hestern Canada Hydraulic Laboratories, Ltd 80/04/30 92pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0674
 EISENHUT, D G Division of Licensing 80/06/26 2pp
- BOO7180081 Forwards request for add1 info re plant fill to support required gestechnical engineering studies for review of responses to NRC 791119 request SCHMENCER.A Licensing Branch 3 60/06/30 9pp
- 8007280060 Responds to NRC 800522 ltr requiring two actions prior to resumption of safety-related work by Zack Co Limited work that is performed will be evaluated & if acceptance level of confidence is attained, then full production can resume CDOK, J. W Consumers Fower Co 80/06/30 App.
- 8007230116 Advises that Util is not exempt from fee requirements for 791219 application for CP amends Any CP amends to be issued by NRC are not seen as resulting from 791206 order MILLER, N. d License Fee Management Branch 80/07/03 ip
- 8007280041 Submits revised facility project schedule Integrated 2-unit startup program retained Sept 1980 NRC Yellowbook update transmittal will reflect milestone dates hased on listed completion dates
 MILLER.D. B. Consumers Power Co 80/07/03 ip
- BO07140496 Bummary of B00529 meeting w/util.Bechtel.B&W & Teledyne in Bathesda.MD re three reactor vessel hold-down studs preservice failure M00D B Licensing Branch 3 B0/07/07 10pp
- BOO7180019 Forwards guidelines for seismir & structural design analysis guide planned as part of review of GL application Info should be filled in on guideline forms prior to audit Audit will take five working days

 BCHMENCER, A Licensing Branch 3 80/07/07 187pp
- 8007230507 Lists drawings & sketches submitted by util found to be partially illegible Independent confirmatory piping analysis requested by NRC cannot be performed until better copies are obtained

 BATES, J. O Rockwell International Corp. Energy Systems Div 80/07/07 2pp
- 8007150497 Comments on proposed addl guidance on potential for low fracture toughness & lamellar tearing of LWR component support structures NRC generic guidance invalidates many support designs developed per past applicable codes & stds COCKJW Consumers Power Co 80/07/08 4pp
- B007240040 Notification of 800805 meeting w/util in Bethesda. MD to discuss schedules for const & licensing review H000, D S Licensing Branch 3 B0/07/09 4pp
- BOD7210483 Forwards updated FBAR Pages 3 8-24 through 3 8-26#, Pages 17 1-11 through 17 1-145 & Question & Response Pages 17 1-1 through 17 1-4 in response to NRC BOD522 ltr M/o encl COOK, J M Consumers Power Co 80/07/14 2pp
- 8007300104 Notification of 800731 meeting w/util & Dechtel in Bethesda. MD to discuss addl info on plant Pill HOGD, D. S. Licensing Branch 3 80/07/21 4pp
- 8007300261 Natification of 800728 & 27 meetings & plant tour w/util & Bschtel to assess const completion schedules Meeting agenda & FR exerpt encl HDOD, D. B. Lizensing Branch 3 80/07/21 7pp
- 8007270036 Notification of 800821 open moeting w/util in Bethesda, MD, originally scheduled 800805, to discuss const & licensing raview achedules HOOD, D S Licensing Branch 3 80/07/22 8pp

- 8007290701 Objects to exclusion of proposed amends from 10CFR170 22, Footnate 2.which excepts such amends from license fee requirements Requests reconsideration BRUNNER. J E Consumers Power Co 80/07/22 3pp
- --8007290707 Responds to 800403 ltr objecting to fees for 791219 application for amend to CPs Commission 791206 order does require application, therefore exemption to 100FR170 22 is not applicable NILLER.W U License Fee Management Branch 80/07/03 1p
- F Security, medical, emergency & fire protection plans
- 8007010473 Discusses proposed change to 10CFR50 adding requirement for fire protection plan at facilities Forwards comments on rule, supplementing consultant comments Questions appropriateness of rule, since rule reopens resolved issues HOFFMAN, D P Consumers Power Co 80/06/27 Bpp
- 800/090393 Summary of 800411 meeting w/util % Bechtel in Bethesda, MD re security plans to protoct against radiological sabotage HDGD, D Licensing Branch 3 80/04/30 4pp
- Q Adjudicatory correspondence
- 8007080051 Petitian to intervene me order for CP mod, alleging that mod will result in unsafe & inefficient exercise of atomic energy use & will create advorse environ effects
 Centificate of Bvc encl
 WILSON, & C Affiliation Unknown 80/06/24 3pp
- B007070282 Petition to intervene in CP mod proceeding, alleging that unresolved soil settlement problems will create adverse safety problems Certificate of Svc encl HILLER, TR Affiliation Unknown 80/06/25 3pp
- B007080039 Potition to intervene in CP mod proceeding, alleging that unresulved soil settlement problems will adversely affect safety & will create inefficient exercise of atomic energy use Guestians integrity of const Certificate of Sv. encl RACE, M.A. Affiliation Unknown 80/06/25 3pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables CISENHUT.D O Division of Licensing 80/06/25 89pp
- HOO7GH0054 Petition to intervene re order for CP mod.alleging that unresolved soil settlement issue will create adverse safety problems & will result in inefficient exercise of atomic energy use Certificate of Svc encl
 HEIBT, B D Affiliation Unknown 80/06/26 3pp
- 8007020592 Memorendum & order granting NRC 800616 request to postpone response to CPC 800527 motion seeking ronsolidation of soil conditions & plant fill matls issues re CL & order for license mod proceedings
 SMITH, I W Atomic Safety and Licensing Board Panel 80/06/27 ip
- B007010333 Ack receipt of 800617 ltm re recent containment bldg publicity Util ltm re inconsistent cross-referencing between BkW & Dechtel enci Further rept on issue will be provided when available Representation status requetted PATON.W D Hearing Branch 4 80/06/30 2pp
- 8007)40017 Petition in opposition to util motion for consolidation re 791806 order modifying CPs Urgrs postponement of response & requests that activities be stopped due to deficiencies in const & safety-related structures MARSHALL. H H Mapleton Intervenors 80/06/30 2pp
- BOO709045 Response stating no present opposition to WA Thibodeau,TR Miller,PA Race,B Stamiris & C Gilbert petitions to Intervene Reserves right to oppose participation in future development & urges consolidation Certificate of Svc encl MILLER,M I FARNELL,A S Consumers Power Co MILLER,M I Isham, Lincoln & Beale 80/07/01 Spp
- 8007090055 Response in support of C Gilbert 800616 petition to intervene in CPs mod proceeding Standing requirement satisfied Ruling on contention requirement premature Certificate of Svc encl PATON.W D Hearing Branch 4 80/07/07 App

- 3007140020 Response stating no present opposition to SK Warren, SD Reist, OC Wilson & MA Race petitions to intervane relicense mod Reserves right for future objection & urges representation by single spokesman Certificate of Svc encl MILLER, M I . FARNELL, A S Consumers Power Co MILLER, M I Isham, Lincoln & Beale 80/07/08 App
- B007170226 Response in support of WA Thibodeau.TR Miller, GC Wilson, SD Reist-PA Race, S Warren, MA Race & B Stamiris petitions to intervene re 791206 order modifying CPs Rullng on adequacy premature Certificate of Svc encl PATCN, W D Wearing Branch 4 80/07/14 App
- 8007170232 Response in support of WH Marshall 800623 petition to intervene re 791206 order modifying CPs Ruling on adequacy promature Certificate of Svc encl PATON.W D Hearing Dranch 4 80/07/14 6pp
- 8007220194 Response to Mapleton Intervenors 800630 petition Argument re consolidation untimely Request to postpone NRC response to CPC motion most Soil-related issues are within scape of OL proceeding & NRC 791206 order Certificate of Svc encl MILLER, M I Consumers Power Co MILLER, M I Isham, Lincoln & Beale 80/07/15 8pp
- 8007170385 Advises that WH Marshall.of Mapleton Intervenors 800630 petition to ASLB should not be given consideration at present stage since intervenor not yet admitted in proceeding PATON,W D Hearing Dranch 4 80/07/16 in
- B007180242 Responds to 800410 ltr urging NRC action to stop const Issue will be submitted to ASLB who has proper jurisdiction over matter in controversy Reminds of NRC position that WH Harshall has standing to intervene PATON, W D Hearing Branch 4 80/07/17 2pp
- BD07300421 Advises that util & Nechtel Power Corp have reached agreement on revised schedule re commercial operation of Units 1 & 2 Unit 2 scheduled for commercial operation in Dec 1983 & Unit 1 in Jul 1984
 OIBUS,M E Isham, Lincoln & Deals 80/07/22 ip
- B007290730 Order & notice of B00910 special prehenring conference in Midland.MI re identification of issues, ruling upon intervention petitions & other related issues Public invited to attend w/o active participation SNITH, I W Atomic Safety and Licensing Board Panel B0/07/24 3pp.
- BOO7290752 Order denying Mapleton Intervenors' 800630 petition urging ASLB not to tonsider CPC motion for consolidation Intervenor may respond directly to motion
 SMITH I W Atomir Safety and Licensing Board Panel 80/07/24 2pp
- 8007290766 Memorandum & order ruling that petitioners PA Race, B 8Tamaris, 9D Reist, 8K Warren, TR Miller, MA Race, GC Wilson, WA Thibadeau & C Gilbert have satisfied interest & aspect requirements Conference re QL will be set for 800910 8MITH, I W Atomic Sofety and Licensing Board Panel 80/07/24 5pp
- H General correspondence
- 800/718016B Opposes const of facilities Great Lakes region would be destroyed if TMI-type accident occurred
 * Affiliation Unknown 80/05/16 1p
- BOO73B0523 Responds to BOO521 ltr requesting info re PA D'Archangel request that NRC expedite facility licensing Addl NRC effort resulting from TMT-2 accident caused delays in licensing Development of schedule for review of application underway DIRCKS.W J Diffice of the Executive Director for Operations BO/07/07 bpp
- ~~8007880836 Requests response to encl PA D'Archangel ltr requesting that NRC expedite facility licensing EAWYER. If B House of Rep 80/05/21 Rpp
- 8007160634 Requests response to enti WH Marshall 1tr re Oct 1979 request for info about facility Request unanswered ALBOSTA.D House of Rep 80/07/09 2pp
- ----8007160649 Provides list of conditions for which into is requested re safeguards for public health & safety Also requests resolutions re-cracking, dewatering, bldg settlements & caisons problems, per NRC 790223 & 0305 meetings in IL MARBHALL, W H Mapleton Intervenors 79/09/04 2pp

- 8007230190 Responds to 800405 ltr re frequency of correlation strength test sampling on new safety-related concrete NRC position reflects increased testing during periods of low vol placement SCHMENCER, A Licensing Branch 3 80/07/09 5pp
- 8007150697 Forwards current rules of practice W/o encl PATON W D Hearing Branch 4 80/07/11 1p
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8007240146 Updated FSAR Pages 3 8-24 through 3 8-26s FBAR Pages 17 1-11 through 17 1-14b & Question & Response Pages 17 1-1 through 17 1-4 to be included in FSAR Revision 2, in response to NRC 800522 ltr 8 Consumers Power Co 80/07/14 14p.
- G Inspection reports, IE Bulletins & correspondence
- 8006300114 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted FIDRELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8006300138 IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted Major areas inspected exam of site conditions & detensioning reactor vessel holddown bults CODK, R J , KMOP, R C Region 3, Chicago, Office of the Director. 80/05/13 3pp
- 8007210360 Forwards IE Circular 80-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies " No written response required. KEPPLER, J Q Region 3, Chicage, Office of the Director 80/05/28
- 8007010144 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER.J O Rogion 3, Chicago, Office of the Director. 80/05/29 in
- 8007220183 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director. 90/05/10
- 8007160178 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER. J G Region 3. Chicago. Office of the Director 90/06/11 ip
- 8007280707 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(s)" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/13
- 8007020306 Responds to IE Bulletin 80-09. "Mydramotor Actuator Deficiencies " Vendors evaluating which actuators will require mod or replacement & which will meet spec requirements respring nonograph problem GOOKLJ W Consumers Power Cn 80/06/17 2pp.
- 8007230402 Forwards IE Insp Repts 50-329/80-16 & 50-330/80-17 on 800401-30 No noncompliance noted FIORELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/17 2pp
- --8007230412 IE Insp Repts 50-329/80-16 & 50-330/80-17 on 800401-30. No noncompliance noted, Major areas inspected; site conditions, reactor years! holddown bolts & Unit I reactor coolant CODM, R T. Region 3, Chicago, Office of the Director HAYES, D. W Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/05 4pp
- 8007020562 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/06/20,
- 8007170467 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/06/24 in

- 8007300300 Forwards IE Inep Repts 50-329/80-18 & 50-330/80-19 on 800801-31 No moncompliance noted FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/26 2pp
- ---B007300304 IE Insp Repts 50-329/80-18 & 50-330/80-19 on 800501-31 No noncompliance noted Major areas inspected suspect pips whip restraint bolting, const activities of Zeck Co. detensioning of reactor vessel holdown bolts & audit of Peabody Testing CODM.R J , KNOP.R C Region 3. Chicago, Office of the Director ED. 60/6/24 7pp
- 8007230358 Forwards IE Bulletin 80-i6, "Potential Misapplication of Rosemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/27 to
- 6007170625 Forwards IE Insp Repts 50-329/80-15 & 50-330/80-16 on 800602-05 No percompliance noted FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/30 2pp
- --B007170635 IE Insp Repts 50-329/80-15 & 50-330/80-16 on 800602-05 No noncompliance noted Major areas inspected records & test results of steam generator anchor bolts & pipe restraint bolts VANDEL, T E , ERB. C M , NAIDU, K R Region 3, Chicago, Office of the Director B0/06/26 12pp
- 8007160612 Provides interim response to IE Bulletin 80-08 re examination of liner penetration welds Includes list of penetration info on joint type flued head math, sleeve math & diameter, type of examination performed & repair info COOK, J W Consumers Power Co 80/07/11 11pp
- 8007310321 Ack receipt of 800630 ltr informing NRC of steps taken to correct const problems noted in IE Inap Repts 50-327/80-14 & 50-330/80-15 KEPPLER, J C Region 3, Chicago. Office of the Director 60/07/25
- --8007310529 Forwards response to NRC 800522 ltr re const problems noted in IE Insp Repts 50-329/80-14 & 50-330/80-15 Corrective actions Zack Co GA manual & GC control procedures were reviewed for adequacy & clarity COOK.J W Consumers Power Co 80/06/30 8pp
- R Periodic operating reports & related correspondence
- 8007280124 Forwards Bechtel nonconformance repts GA audit finding rept, sgt corrective action rept.B&W repts of nonconformity & util nonconformance repts, audit finding repts & corrective action repts for June 1980 GODK, J W Consumers Power Co. 80/07/21 360pp
- 8 Reportable occurrences, LERs & related correspondence
- B007160807 Part 21 rapt re defective fostener matts A490 & A540 supplied by Southern Bolt & Fastener Corp for site assembly & installation of pipe whip restraints Possibly caused by improper heat treatment or wrong matts supplied HARBISON.D NPB Industries, Inc 80/06/16 lipp
- 8007070197 Ack receipt of 800613 interim deficiency rept re component qualification test documentation re-review FIGRELLIG Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/04/23 ip
- 8007150032 Ack receipt of 800612 interim deficiency rept re broken reactor yeasel packor bolts Will review final rept upon raceipt response of the second second for the second s
- 8007170520 Ack receipt of 800619 interim deficiency rept re letdown cooler supports FIORELLIP Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/01 ip
- 8007290205 Final deficiency rapt to amergency core cooling actuation sys digital Subsystem 2 logic circuitry drawings B&W will correct drawings by 800930 Facilities will be in conformance by 800930 CDCK, J W Consumers Power Co 80/07/17 5pp

- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 8004,25 ltr to all power reactor licenseds, in response to 800529 ltr re emergency response facilities of reactor sites Sites w/approval to use closed-circuit television link w/tochnical support ctr listed GRUTCHFIELD.D M Operating Reactors Branch 5 80/07/07 2pp
- 8007070207 Advises that review of safeguards contingency plan indicates need for add1 mods Enc1 NRC Lomments withhold (ref 10CFR2 790)
 1PPOLITO: T A Operating Reactors Branch 2 80/06/10 1p
- 0 Adjudicatory correspondence
- 80073i0243 Forwards Commission 800927 membrandum & order containing decisions on UCS 780902 petition for reconsideration of 780413 memorandum & order UCS 77i104 petition sought action re fire protection for electrical cables EISENHUT, D Q Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark I owners group in Dotheeda. MD,re revisions to NRC acceptance criteria & autotanding issues relative to Mark I containment long-term program GRIMCB,C T Plant Systems Dranch 80/02/21 'lipp
- 8007010453 Responds to NRC 800507 ltr re add1 TMI-2 requirements Intel assessment of collective impact not yet conducted Possible alternatives to requirements include equal or better wardty mode & exception to Uninconsisty renommendations ROUT/L D Town Electric Light & Power Co 80/06/23 (p
- B007230233 Describes Cycle 5 restart testing program & results of all tests were satisfactory Add1 testing proved that newly installed recirculation pump trip moves applicable criteria

 MINECK, D. L. Iowa Clectric Light & Power Co. 80706/2.1 App
- 8007070142 Application to reinstate Amend 60 to App A of License DPR-47 Amend will allow reactor startup & operation for greater than 24-h w/one recurrulation loop out of svt Category II amend fee encl
 ROOTLD Iowa Electric Light & Power Co. RO/06/20 ip
- 8007180341 Confirms 900628 telcon authorization to amend Tuch Specs as requested in 900628 application License DPR-49 is amended effective 900628 by reinstating Amend 60 until 800702 NOVAKIT M Assistant Director for Operating Reactors (80/04/30) 200
- BOO7070252 Forwards "Verification Test of Station Electric Distribution Sys Voltage for Duane Arnold Energy Gtr." in final response to NRC 799808 ftr restation electric distribution by ROOT, L D Tows Electric Light & Power Co 80/07/01 p
- --8007070254 "Verification Test of Station Electric Distribution Sys Voltages for Duane Arnold Energy Ctr " Oversize drawing encl # Bechtel Associates Professional Corp 80/06/30 16pp
- ---8007070255 "Single Line Diagram Station Connections "
 * lowe Electric light & Power Co 7884 75/94/19 Ip
- 8007140624 Forwards proposed mods to NRC /80807 request for info re design of voltage regulator sys of motor generator sets which supply power to reactor protection sys amplementation will depend upon further communication to agreement w/NRC RODT, LD Jown Electric Light & Power Co BO/07/01 App
- B007140434 Forwards "Alternate Shubdown Capability Analysis" & 73 oversize drawings in response to NRC 791022 ltr Analysis conclusions identical to those transmitted in 800405 ltr is need for procedural & design muds R007.L D Jowa Electric Light & Power Co 80707703 ip
- ---8007140442 "Alternate Shutdown Capability Analysis "
 * lows Electric Light & Power Co 80/06/30 55pp
- --8007140450 Package of 73 electrical drawings to be recalled at later date of microfilming * General Electric Co 77/06/22 ip

- '140366 Application to reinstate Amend 60 to App A (Tech Specs) to icense DPR-49 re reactor startup & operation for greater ian 24-h w/one recirculation loop out of svc IDT.LD Iowa Electric Light & Power Co 80/07/07 ip
- 170556 Confirms 800707 teleon authorization of util 800707 plication for change in Tech Specs License DPR-49 is lended by reinstating Amend 60 until 800714 Documentation ll be forwarded NAK.T M Assistant Director for Operating Reacturs 80/0
- Assistant Director for Operating Reactors 80/07/08
- 210156 Requests payment of add1 fee in connection w/800628 iplication for reactor startup & operation greater than —h w/one recirculation loop out of svc GGS.R M License Fee Management Branch 80/07/09 ip
- '220394 Forwards "Reactor Containment Local Leakage Rate Testing, '80 Outage " NECK.D L Iowa Electric Light & Power Co 80/07/15 ip
- 07220396 "Reactor Containment Local Leakage Rate Testing, 1980 FLOYD, S.O. Bechtel Corp. 80/04/22 21pp
- 230482 Forwards rept. "Reactor Containment Local Leakage Rate
- NECK, D. L. lowa Electric Light & Power Co. 80/07/15
- 07230484 "Reactor Containment Local Leakage Rate Testing, 1980 Outage " FLDYD, B O Bechtel Corp MINECK, D L Consumers Power Co 80/07/11 Ripp
- 310215 Forwards Amend 61 to License DPR-49.safety evaluation & tice of issuance & availability POL17D.T A Operating Reactors Branch 3 80/07/17 2ap
- 07310222 Amend 6) to License DPR-49, revising Tach Specs to allow interim operation w/one recirculation loop out of svc from 800628-0702 | IPPOLITE TA Operating Reactors Grench 3 80/07/17 7pp
- 07310226 Safety evaluation supporting Amend 61 to License DPR-49 Office of Nuclear Reactor Regulation, Director 80/07/17 5
- 07310229 Notice of issuance & availability of Amend 61 to License)PR-49 IPPOLITO,T A Operating Reactors Branch 3 80/07/17 2pp
- 200480 Forwards theck for difference between litemse amend class terminations made by util vs determination made by NRC, Diggs 800709 ltr
- lowa Electric Light & Power Co BO/07/22 1p
- B0377 Forwards response to NRC 800405 ltr re effect of dc power sply failure on ECCS performance Plant design assumptions GE analysis are conservative re facility TLD Iowa Clertric Light & Power Co 80/07/23 18pp
- espection reports. IE Bulletins & correspondence
- 140535 Forwards 15 Bulletin 80-13, "Cracking in Core Boray Written response required Region 3. Chicago. Office of the Director 80/05/12
- 100283 Forwards 15 Insp Rept 50-331/80-07 on 800324-26.0410-12 & -25 No noncompliance moted ISHN AN, R F Region 3. Chicago. Reactor Deerations Nuclear Bupport nch 80/05/20 2pp
- 7100291 IE Insp Rept 50-331/80-07 on 800324-24,0410-12 & 22-25 No viology) le inspired to discover a control of the c
 - Notice 80-22, "Breakdowns In Contamination en response required
 o. Office of the Director \$90/05/28
 - , 80-23, "Loss of Suction to Emergency ponse required
 Office of the Director 80/05/29

- 8007220201 Forwards IE Info Notice 80~26. "Evaluation of Contractor GA Programs " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/10
- 8007140317 Forwards IE Bulletin 80-14, "Degradation of 8WR Scram Discharge Vol Capability " Written response required KEPPLER,J G Region 3, Chicago, Office of the Director 80/06/12
- 8007020719 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" No hydramotor actuators as described by bulletin are installed at facility RDOTL D Towa Electric Light & Power Co 80/06/13 ip
- 8007030027 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required WEPPLER.J G Region 3, Chicago, Office of the Director 80/06/18
- 8007230296 Forwards IE insp Rept 50-331/80-08 on 800520-22 No noncompliance noted HEISHMAN, R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 80/06/18 2pp
- --8007230303 IE Insp Rept 50-331/80-08 on 800520-22 No noncompliance noted Major areas inspected Tech Spec compliance.containment vent & purge line isolation valves & followup on outstanding insp items
 LITILE, M S , WRIGHT.G C Region 3, Chicago, Office of the
 Director 80/06/13 3pp
- 8007020576 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response MEPPLER, J G Region 3. Chicago. Office of the Director 80/06/20
- 8007170489 Forwards IE Circular 80-14, "Radioactive Contamination of Flant Demineralized Mater 80s & Resultant Internal Contamination of Personnel" No written response required MEPPLERJ Q Region 3, Chicago. Office of the Director. 80/06/24
- 8007070272 Responds to IE Bulletin 80-10, "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ " Routine sampling/enalgis program has been implemented ROUT,L D Iowa Electric Light & Power Co 80/06/25 2pp
- 8007300132 Forwards IE Insp Rept 50-331/80-07 on 800616-17 No noncompliance noted
 FIORELLI, @ Region 3, Chicago, Reactor Construction & Engineering
 Support Branch 80/06/25 2pp
- --BOO7300136 IE Insp Rept 30-331/B0-09 on BOO616-17 No noncompliance noted Major areas inspected outstanding items & followup to IE Builotin 79-02.LERs on pipe supports & concrete cracks in floor under torus GALLAGHER.E J Region 3, Chicago, Office of the Director HAYEB, D W. Region 3, Chicago, Reactor Construction & Engineering Support Branch SO/06/24 4pp
- 8007230329 Forwards IE Bulletin 80-14. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-14 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director. 60/06/27
- 8007160259 Responds to IE Bullstin BO-15, "Possible Loss of Emergency Notification Sys w/Loss of Offsite Power " All telephone equipment fed power from single 240-volt ac line ROOT, L D lows Electric Light & Power Co 80/07/01 2pp
- 8007180497 Nptifies that time clock on Item 2 of IE Bullstin 80-17, "Failure of Control Rods to Insert During Scram at BHR," will start at 12 01 AM on 80070B Test should be completed within 20 days Requests notification of malfunction KEPPLER.J.O Region 3, Chicago. Office of the Director 80/07/07
- 8007250675 Forwards response to Items 1,2s & 3 of IE Bulletin 80-11 Safety-related sys in proximity to maxonry block walls will be surveyed & identified only if analyses indicate potential wall failure List of subj walls encl ROOT, L, D I swa Electric Light & Power Co 80/07/07 43pp.

- 8007250677 Forwards response to IE Bulletin 80-08 re examination of containment liner penetration welds All welds, except for double & triple flued heads: examined by radiography or by combination of radiography & liquid penetrant examinations RD07.L D lows Electric Light & Power Co 80/07/08 5pp
- 8007170363 Responds to IE Bulletin 80-17 No significant amount of water in scram discharge vol & associated piping. Vent valves operable & sys free of obstruction Results of addl required raview will be reported in subsequent correspondence ROOT.L D Town Electric Light & Power Co BO/07/09 2pp
- 8007220494 Notifies that results of inservice insp performed during 1980 refueling outage & summary of pump & valve operability testing will be submitted by 800725 rather than 800715 as previously scheduled RDOT.L D lows Electric Light & Power Co 80/07/15 ip
- 8007220544 Responds to IE Bulletin 80-17. "Failure of Control Rods to Fully Insert During Scram at BWR" Proliminary training of operators completed Full training will be completed by 800803 Items 2,3 % & a will be discussed in subsequent 1tr ROGT, LD I I lows Electric Light & Power Co 80/07/17 4pp
- R Periodic operating reports & related correspondence
- 8007220367 Forwards monthly operating rept for June 1980 MINECK,D L Iowa Electric Light & Power Co 80/07/15 1p
- ---BOO7220371 Monthly operating rept for June 1980
 VANSICKEL, J. Iowa Electric Light & Power Co. 80/07/15 6pp.
- 8 Reportable occurrences, LEAs & related correspondence
- 8007030212 Forwards LER 80-024/03L-0
 MINECK, D. L. Iowa Electric Light & Power Co. 80/06/26 ip
- --- 6007030217 LER 80-024/031-0 on 800603, during surveillance tasting, body-to-bonnet & packing leak discovered on pressure point isolation valve on reactor care isolation cooling turbine steam supply line, Caused by normal wear Gasket replaced RAGER, M I lowa Electric Light & Power Co 80/06/24 ip
- 8007030224 Forwards LER 80-023/03L-0 MINEC() D L Iows Electric Light & Power Co 80/06/26 ip
- --8007030235 LER 80-023/03L-0 on 800529; during surveillance testing, pressure differential switches controlling reactor bldg to suppression chamber vacuum breakers tripped at out-of-spec values. Caused by instrument drift Buitches recallbr RAOER; M Towa Electric Light & Power Co 80/06/26 1p
- 9007030238 Forwards LER 90-022/03L-0
 MINECK, D. L. lows Electric Light & Power Co 80/06/26 1p
- ~~8007030241 LER 80~022/03L~0 on 800528, during normal sparation, control room alarm indicated high/low oil level in B recirculation pump motor Gaused by low oil level in lower motor bearing No leakage found Oil restarted to normal level RAOER, M Iowa Electric Light & Power Co 80/06/26 1p
- BO07110411 Forwards LER 80-026/03L-0.
 MINECK, D. L. Iowa Electric Light & Power Co 80/07/03 1p
- ---8007i10419 LER 80-026/03L-0 on 800617.ons undervoltage relay found to have time delay during surveillance test Caused by instrument drift Relay recalibr & functionally tested RAGER.M Iowa Electric Light & Power Co 80/07/03 ip
- 8007110471 Forwards LER 80-025/03L-0 HINECK, D L lows Electric Light & Fower Co 80/07/03, ip.
- --8007110482 LER 80-025/03L-0 on 800404, during surveillance testing of main steam line leak detection sys, found temp switch T18-4478 setpoint was 208 degrees. Caused by instrument drift Instrument recallbr RAOER, M. Your Electric Light & Power Co 80/07/03 ip
- 8007220599 Submits special rept re repairs on Fire Pump IP-49 which resulted in pump being out of svc longer than Tech Spec limit. Repair work more extensive than anticipated when shaft & spiders found to be worn Pump repaired MINECK, D L lowa Electric Light & Power Co 80/07/10 2pp.

- 8007220497 RO on 800612, during use of reactor core indiation cooling sys to control reactor pressure following shutdown, suppression chamber water level was inadvertently reduced to below Tech Specs Caused by failure of alarm MINECK,D L lowa Clectric Light & Puwer Co 80/07/14 ip
- 8007R30464 RO during reactor scram functions teating required by IE Bulletin BO-17, determined that scram discharge vol drain valve CV-1867 would not seal against roted reactor pressure Causad by improper valve installation MINECK.D t lowa Electric Light & Power Co DO/07/16 ip
- BOCKET 50-332 DARNWELL REPROCESSING PLANT
- G Inspection reports, JE Bulletins & correspondence
- 8007220020 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/10 in
- B007020739 Forwards IE Bulletin B0-15, "Possible Loss of Emergency Notification Sys (ENS) H/Loss of Offsite Power " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/05/10
- B007170126 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/24 to.
- 8007310139 Responds to IF Bulletin 80-15 re emergency notification mysfailure w/loss of offsite power Licensing proceedings terminated facility is presently utilized in DOI R&D activities Bulletin does not apply HOLDEN.R B Allied General Nuclear Services 80/0///25 ip
- DOCKET 90-33'S JAMES A FITZPATRICK NUCLEAR PUMER PLANT
 F Bacurity, medical, emergency & fire protection plans
- B007070212 Forwards security contingency plan & addl into requested in NRC 800528 ltr Plan & addl into withheld (ref 100782 790)
 BAYNE, J.P. Power Authority of the State of Naw York 80/06/20 1p
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780902 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re-fire protection for electrical cables EISENHUT, D.O. Division of Licensing 80706720 13pp
- I. Financial information
- 8007280461 Forwards Annual Financial Rept 1979
 BAYNC, J P Power Authority of the State of New York | 40/07/24 | 1
- --8007280463 Annual Financial Ropt 1979 * Pawer Authority of the State of New York HO/07/24 4lpp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Hark I owners group in Sethesda, MD,re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 60/02/21 Dipp
- 8007080332 Forwards responses to NRC BOOBDS request for addl into re adequacy of electric distribution sys voltage BAYNE, J.P. Power Authority of the State of New York 00/07/01 11pp
- BOO7280229 Forwards Amend 49 to Livense DPR-59, safety evaluation & notice of issuance & availability
 IPPOLITO, T.A. Operating Reactors Branch & 00/07/LL 3pp
- ~~BOO72BOR47 Amend 49 to License DPR-D9, consisting of changes to Tack Brecs resentor operator responsibilities during refusions & replacement of fuel assemblies for refueling during Cycle 4 IPPOLITO:T A Operating Reactors Dranch 2 BO/07/11 29pp

- 300/200299 Notice of issuance & availability of Amend 49 to License POLK.P 3 Operating Reactors Branch 2 80/07/11 2pp

- 07290692 Submits 18f0 re effect of do nower supply failure on ECC9 performance, in response to NRC 800425 ltr NAYNE, J.P. Power Authority of the State of New York 80/07/25 Jpp
- Inspection reports: IE Bulletins & correspondence
- 1714043B Forwards IE Bulletin BO-13, "Cracking in Core Spray Spargers " Wrsten response required RIFR,U M Region 1, Philadelphia, Office of the Director O/05/12 1p
- 702014/ Forwards If Info Notice BO-22, "Breakdowns In Contamination outrol Programs" No written response required RIER.B H Region 1, Philadelphia, Office of the Director 0/05/20 ip
- 7010302 Forwards IF Info Notice 80-23, "Loss of Suction to Emergency Pumps " Na written response required REGION 1. Philadelphia. Office of the Director 0/05/29 1p
- 7210251 Forwards IT Insp Rept 50-333/B0-0B on 800517-23 No ancompliance noted RUNNER.L J. Region 1. Philadelphia, Roactor Operations Nuclear upport Branch 80/05/09 2pp
- 007210295 IE Insp Rept 70-333/80-08 on 800519-23 No nuncompliance noted Major areas inspected foul receipt handling & insp & fueling activities in control room & on fuel floor BAUNACK, by TRODAUSKI, W. Regiom t. Philadelphia, Defice of the Director KISTER, B & Region J. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/64 Opp
- /310595 Forwards lE Info Notice 80-26. "Evaluation of Contractor A Programs " No written response required RIER.D H Region i, Philadelphia. Defice of the Director 0/06/10 ip
- /010164 Porwards "Response to IF Bulletin 79-018 for JA Fitzpatrick utlear Power Plant" ASTERNAK.A J. Power Authority of the State of New York 80/06/11
- 30/010172 "Response to IF Bullatin 79-018 for JA Fitzpetrick Nuclear Stone & Webster Engineering Corp 80/05/30 500pp
- 7180128 Forwards reply to IL Bulletin 79-018 re environ ualification of Class IC equipment W/o and1 ASTERNAK.R J. Power Authority of the Btate of New York 80/06/11
- 7140267 Forwards IE Bulletin 80-14, "Degradation of BWR Beram ischarge Yul Capability " Written reaponse required HIR.O H Region 1, Philadelphia, Office of the Director 0/04/12 lp
- 72800/1 Forwards IE insp Rept 50-3.3/80-10 on 800514 No Incompliance noted MH.SON, R T Region 1. Philodelphia. Reactor Construction & Infinitering Support Branch 80/06/17 2pp
- 007280000 IL Insp Rept 50-333/80-10 on 600514 No noncompliance noted Major areas inspected RHR ays components addressed in factlity response to IE Dulletin 79-018.
 FINKELN E Region 1. Philadelphia, Office of the Director, EBNEICR. S D Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/16 3pp
- 020717 Forwards If Bulletin 80-15, "Possible Loss of Emergency etification Bys (FNS) W/Loss of Offsite Power " Written esponse required 1ER.B H Region 1, Philadelphia, Office of the Director 9/06/10 to
- 1020521 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump oling & Natural Circulation Cooldown " No written response quirad IIER.B H. Region 1. Philodelphia. Office of the Director 1706/20 ip
- /04/20

- 8007160723 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Domineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER. B H Region 1. Philadelphia. Office of the Director BO/06/24 1p
- 8007210218 Forwards IE Info Notice 80-24, "Low Level Radwaste Buriel Criteria " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/25 1p
- 8007250669 Responds to IE Bulletin 80-06. "Engineered Safety Feature Reset Controls "Training sessions w/licensed operators held to assure awareness of potential problem re unwented closing of automatic depressurization sys valves
 PASTERNAK.R J Power Authority of the State of New York 80/07/01
- 6007210526 Responds to IE Bulletin 60-08 re examination of containment liner penetration welds Liquid penetrant & wald joints magnetic particle examinations met applicable ASME code requirements

 PASTERNAKIR J Power Authority of the State of New York 80/07/03
- 8007250290 Submits reply to IE Bulletin 80-10 re contamination of nonradioactive sys Sampling & analyzing procedures implemented for sanitary waste sys PASTERNAK, R J Power Authority of the State of New York 80/07/07
- 8007240323 Confirms oral notification made on 800707 that 20-day period for completing tests required by IE Bulletin 80-17, Item 2, began at 12 Di AM on 800708 Also requests immediate notification of any malfunction found during tests GRIER.8 H Region I, Philadelphia, Office of the Director 80/07/09 2pp
- B007310474 Forwards responses to IE Bulletin 80-ii Items 1,2a % 3 remasonry wall design Scheduled completion dates are tentative W/a encl
 PASTERNAK,R J Power Authority of the State of New York 90/07/10
- A Periodic operating reports & related correspondence
- B007090192 Forwards monthly operating rept for June 1980 PASTERNAK.R J Power Authority of the State of New York 80/07/03
- --8007090195 Monthly operating rept for June 1980 * Power Authority of the State of New York 80/07/03 1400
- S Reportable occurrences, LERs & related correspondence
- 8007010486 Forwards LER 80-052/03L-0
 PASTERNAK, R J Power Authority of the State of New York 80/06/25
- --B007010495 LER 80-052/03L-0 on B00528, during refueling operations, refuel bridge movement to over core area did not generate control rod withdrawal block per Tech Bpocs Caused by drift at bridge position sensing limit switch Ewitch adjusted CHILDS, W V Power Authority of the State of New York B0/06/25 90/06/25.
- BD07010511 Forwards LCR B0-053/03L-0
 PASTERNAK, R J Power Authority of the State of New York B0/06/25
- --B007010319 LER B0-053/03L-0 on 800529, during normal refueling, review revealed that temporary changes to instrument maint procedure made on B00417 had not been reviewed by PORC Caused by administrative error PORC reviewed changes.

 CHILDS, W V Power Authority of the State of New York 80/06/25
- 8007010481 Forwards LER 80-054/04L-0 PASTERNAK, R J Power Authority of the State of New York 80/04/27
- -8007010485 LER 60-054/04L-0 on 800530.during normal shutdown.both recorders for gaseous release rate from reactor bldg ventilation sys & plant process computer were out of order during same 16-h period Caused by personnel error # Power Authority of the State of New York 80/06/27 2pp

- 8007148368 Forwards LER 80-095/03L-0
 PARTERNABLE J Power Authority of the State of New York 80/07/07
- --8007140374 LER 80-098/03L-0 on 800607, surveillance revealed intermediate range monitor, A indicating 120 when reading of 125 was required Gaused by instrument drift Adjustment & calibr restured instrument to aperable status
 CHILDB, W. V. Power Authority of the State of New York 80/07/07
- B007140383 Forwards updated LER 80-046/03X-1 PASTERNAK, R. J. Power Authority of the State of New York 80/07/07
- ~-800/140374 Updated LER 80~046/03X-1 on 800430, surveillance testing revealed shutdown loading permissive switches set in excess of 73 paig limit Caused by procedural error Instruments recalibr & returned to sv. CHILDEN # V Power Authority of the State of New York 80/07/07 Jan
- 9007150/07 Forwards LER 80-056/03L=0 PARTERNAK, R J Power Authority of the State of New York 80/07/10
- ~-800/150715 LER 80 086/03L~0 on 800610.during normal shubdown & surveillance testing.emergency diesel generator C tripped on high circulating current Caused by dirty or defective contact on voltage regulator dropp switch CHILDS.W V Power Authority of the State of New York 80/07/10
- 8007280515 Forwards LER 80-059/03L-0
 PABTCHNAK, R J Power Authority of the State of New York
- ---BOOTREOS24 LER 60-059/03L-0 on 800703, during normal shutdown surveillance, level switches & pressure inducator showed 128 instruments but of calibr or not properly operating Caused by instrument drift Instruments recalibr Two replaced CHILDS, W.V. Power Authority of the State of New York 80/07 80/07/22
- 6007200610 Forwards LER 80-058/03L-0 PABTERNAK, R J Power Authority of the State of New York 80/07/22
- ---80072E0617 LFR 80-058/03L-0 on BODA28. during normal chutdown operations, functional tests of average power range monitor instruments found not conducted gen Tech Bears Caused by mappuls scheduling of computer outage
 CHILDS, H V Power Authority of the State of New York 80/07/22
- 800/280662 Forwards LER 00-057/03L-0
 PASTERNAKIR J Power Authority of the State of New York 80/07/22.
- -800/2810/69 LER 80-057/03L-0 on 8006PB, during normal shutdown, one call in each RA voit bettory for diesel fire pump failed to meet min specific gravity requirements of surveillance test Caused by charger being out of suc during surveillance GHILDB, H V Power Authority of the State of New York 80/07/RR
- V Operator Examinations
- 8007080303 Notifies NRC of commitment to enrall employees who do not successfully complete any portion of reactor operator examin accelerated requalification program Dactions to commit amployees to Item 9 1 P of NRC 800328 request 80/07/01 BAYNE, J P fower Authority of the State of New York 80/07/01
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1 C Utility Environmental Report (ER), amends & correspondence
- 7904100186 Summary of aits visit on 790323 w/util re pips stress analysis & Manger reevaluation efforts for Beaver Valley Power Station Unit 1.

 #### History On Comparing Reacture Branch 1 (Pre 790625) 79/03/28

- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & 01 dot 6 patienting decisions on UCS 780502 patient for reconsideration of 780413 memorandum & order UCS 771104 patients sought at two refere grotection for electrical cables EISENHUT, D G Division of Licensing 80/05/25 (1707)
- P Operating license stage documents & correspondence
- 7904030186 Notification of 790323 meeting wouth in Shipp insport PA to discuss facility gips stress analysis status a plant Poi remanalysis, four facility & survey sys offected HIGGINTON.D. Operating Reactors Branch i (Pre 7904)235 2970122
- 7904160256 Notification of 790325 mgt meeting w/いたi in 月をもいらはa Hb, STELLO-V Division of Operating Reactors 7970ほんご だかり
- 8007230172 "Electrical Instrumentation & Control Funtures of Quanting Spray Sys Mods ~ Beaver Valley Nuclear Station Unit 1 " MAYS, S E E000 Idaho, Inc FIN A-6256 G007230172 (107/407/8) }
- 8007230099 Requests submittal of proposed Tech Spot through a providing for redundancy in decay heat removal capability in all models of operation Model Tech Spots which would provide an ever table resolution encl for guidance EISENHUT, D. G. Division of Licensing 80/06/61 (52294)
- 8007180191 Recommends that analysis be made of impact of estimated average dynamic settlement on equipment & pipe consuctions within turbine bldg Info needed for review of util 790;1002 "Boil Analysis of Turbine Bldg & Northern Yard Area "VARQA, S. A. Operating Reactors Branch 1 80706/20 Opp
- 8007010336 Forwards requested Teledyne TLD data for 3rd & Ath quarter of 1977 & 1st, 2nd & 3rd quarters of 1978 Califor repto for meteorological tower wind speed sensors for quarterly is althuaf 791018 & Mar 1980 also encl

 CONRAD.R E Duquesne Light Co 80/06/25 70pp
- BO07010395 Farwards response to NUREG-0578 Procedures downlipsed for issued that utilize temp & pressure indication in coastroil room along wisteam tables to calculate subcooling in the property of the prop
- 8007250001 Requests submittal of application for amend to consisting of Tech Spec changes & located conditions filled Model Tech Spec & Model license conditions for TMI AR Lessons tearned Category A items ently for guidance EISENHUT, D.O. Division of Licensing 80/07/02 & Ppp
- 8007080080 Forwards revision to proposed Tech Spuc Stortings (1874 to 2) 3 & 2 1 & 4 6 2 1, for NPSH mods to low head safety in your tion trecirculation appray pumps

 DUNN, C N Puquesne Light Co 80/07/03 Epp
- ---BOO70BOOSA Revision to proposed Teth Spec Sections 3/4 & 2.3 h 2 t 4 & 2 1, for NPSH mods to low head safety injection & recirculation spray pumps # Duquesns Light Co BO/07/03 3pp
- 8007080186 Forwards logic diagrams, elementary drawings & witten descriptions for bypass & reset of engineered anfoty features, in response to NRC 800404 ftr Drawings awaile) les in Central Files only Item 2d info available by EQOH(18 DUNN.C N Duquesne Light Co 80/07/03 34pp
- 8007160480 Forwards util 800707 ltr re NUREG-0577, "Futerittest Fracture Toughness & Lamellar Tearing on PWR Steam Gerserator & Reactor Collant Pump Supports" as replacement for residated ltr forwarded to NRC on 800707 M/o encl DUNN.C N Duquesne Light Co 80/07/09. 1p "Potential for low
- BOO7160555 Informs that date was inadvertently omitted from \$4400/6/1\$ ne extension of comment period for NUREG-0977 Requests team \$4400/6/1\$ date be added or original be replaced whencl DUNNIC N Duquesne Light Co 80/07/09 ip
- --8007160564 Requests extension until 800715 for comments the NURLO OF repotential for low fracture toughness & lamollat tour leng on PMR steam generator & reactor coolant pump supports 100NN, C N Duquesne Light Co 80/07/07 19
- 8007150480 Requests extension of comment period for NUREO-OBY Position NRC 800519 its is much stronger than original document textension to 800916 should be cufficient to address tout to to the DUNNIC N Dugussa Light Co 8007/15 ip

```
90A43 Documents verbal responses to NRC questions re station svc
undervoltage relays
N.C N Duquesne Light Co 80/07/24 3pp
```

spection reports, IE Bulletins & correspondence

10285 Forwards IE Waste Packaging Insp Rept 15000039/80-03 on 227-29 No noncompliance noted TH.O H. Region I. Philadelphia. Fuel Facility & Materials Safety nch 80/04/24 2pp

7010291 IE Waste Packaging Insp Rept 15000039/80-03 on 800227-29 No encompliance noted Major areas inspected shipping paper equiroments, DDT placarding requirements, radiation levels, emovable contamination & external package features ECRY, W W, POTTER, J P Region 2, Atlanta, Fuel Facility & aterials Safety Branch 80/03/18 7pp

20216 Forwards IE Insp Rept 50-934/80-10 on 800408-09 No compliance noted LABN.R T Region i. Philadelphia. Reactor Construction & insering Support Branck 80/05/08 2pp

7020225 IE Insp Ropt 50-334/80-10 on 800408-09 No noncompliance oted Major areas inspected two allegations re electrical ubcontractor weld rod control & work practices URR.J P. REYNOLDS, S D. Region I. Philadelphia. Office of the irector TRIPP-L E. Region I. Philadelphia. Reactor Construction Engineering Support Branch 80/05/02 9pp.

20110 Forwards IE Info Notice 80-22, "Breakdowns In Contamination trol Programs " No writton response required ER.B H Region 1, Fhiladelphia, Office of the Director 05/20 tp

10321 Forwards IC Info Notice 80-23, "Loss of Suction to Emergency dwater Fumps " No written response required ER.B H Region 1. Philadelphia. Office of the Director 05/29 1p

1056) Forwards IE Info Notice 80-26, "Evaluation of Contractor Programs " No written response required ER.B.H Region 1, Philadelphia, Office of the Director 06/10 ip

60398 Forwards IE Info Notice 80-27. Degradation of Reactor with Pump Bluds " No specific action or response ulwed ER. II H Region 1. Philadelphia. Office of the Director 06/11 tp

i tp

30660 Responds to IE Bulletin BO-05, "Vacuum Condition Resulting Damage to Chemical Vol Control Bys (CVCB) Holdup Tanks," sauriter relief tank,vol control tank & one primary in transfer tank designed for full vacuum conditions &C.N Duquesne Light Co BO/06/16 2pp

20696 Forwards IE Bulletin 80-18, "Possible Loss of Emergency ification Sys (ENS) W/Loss of Offsite Power " Written ponse required ER.B H. Region 1, Philadelphia, Office of the Director 36/18 Ip

20498 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump ling & Natural Circulation Cooldown " No written response wired ER.D H Region 1, Philadelphia, Office of the Director 06/20 ip

60696 Forwards II Circular 80-14, "Radioactive Contamination of nt Demineralized Water Sys & Resultant Internal tamination of Personnel " No written response required ER.D.H. Region I, Philadelphia. Office of the Director 36/24 Ip

1018: Forwards IE Info Notice 80-24, "Low Level Redwaste Burial teria." No written response required "A.B.H. Augion 1, Philadelphia. Office of the Director 06/29 ip

50543 Refers to 600625 telron re review & evaluation of constictionales in refueling water storage tank & domineralized er storage tank Corrective actions chould be taken to ure adequacy of const of containment liner & additanks.
ER.B.H. Region 1. Philadelphia. Office of the Director 06/26 20p

- 8007230113 Forwards IE Bulletin 80~16, "Potential Misapplication of Rosemburt Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Output Codes" " Written response required IE Circular 80~16 also and No written response required GRIER, D H Region 1, Philadelphia, Office of the Director 80/86/27 2pp
- B007210011 Advises of review completion in response to IE Bulletin 80-10 re radioactive sys contamination & resulting uncontrolled release potential Documentation re Items 1 & 2 responsive actions available at station
 DUNNIC N Duquesne Light Co 80/07/01 ip
- 8007230140 Ack receipt of 800618 ltr informing NRC of steps taken to correct violation noted in IE lnsp Rept 50-334/80-06
 BRUNNER.E J Region I, Philadelphia, Reactor Operations Nuclear Support Branch 80/07/01 lp
- ---B007230150 Responds to NRC 800521 ltr re violation noted in IE Insp Rept 80-334/80-06 Corrective actions maint work request initiated to repair identified fire doors Closure linkage adjusted & replaced w/beavy-duty mechanisms DUNN,C N Duquesne Light Co 80/06/18 3pp
- --8007230157 Forwards IE Insp Rept 50-334/80-11 on 800211-0307 & notice of violation BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/05/21 2pp
- --8007230162 Notice of violation from imap on 800211-0307. * Region 1, Philadelphia. Office of the Director 80/05/16 ip
- --8007230174 IE Insp Rept 50-334/80-06 on 800211-0307 Noncompliance noted failure to meintain fire protection barrier integrity.

 DECKMAN, D A . HEGNER, J. D Region 1, Philadelphia, Office of the Director MCGABE, E C Region 1, Philadelphia, Reactor Operationa Nuclear Support Branch 80/05/16 23pp
- 8007080276 Responds to NRC 800402 ltr re violations noted in IE Insp Rept 50-934/80-03 Corrective actions option of station superintendent to waive formal housekeeping tours will be deleted from housekeeping procedure DUNN.C N Duquesne Light Co 80/07/02 2pp
- 8007080424 Submits oddl info re insp & maint of iA & iD inside recirculation spray pumps in response to NRC request Includes info re modal analysis of pump column, mating faces of pump coupling & pump alignment S&W diagrams encl DUNN.C N Duquesne Light Co 80/07/03 18pp
- 8007150443 Advises that documentation in response to IE Bulletin B0-10 re-contamination of nonradioactive sys, will be available at facility
 DUNN.C N Duquesne Light Co 80/07/07 ip
- 8007160575 Notifies that date was umitted on ltr sent 800707 re completion of review of IE Bulletin 80-10 DUNN.C N Duquesne Light Co 80/07/09 lp
- 8007140647 Requests that date 800707 be added to response to IE Bulletin 80-11, previously submitted w/o date Encl response includes date & may replace original DUNN.C N Duquesne Light Co 80/07/07 2pp
- --BOO7160654 Responds to IE Bulletin 60-11 re masonry wall design Replaces original response w/o encl DUNN.C N Duquesna Light Co 80/07/07 1p
- 8007100483 Forwards "Final Rept IE Bulletin 79-02 Beaver Valley Power Station - Unit 1 " Rept available in Central Files only DUNN,C N Duquesne Light Co 80/07/10 ip
- 8007180867 Forwards final rept in response to IE Bulletin 79-02, "Pipe Bupport Base Plate Designs Using Concrete Expansion Anchor Bolts" Rept summerizes analytical inap & testing programs & incorporates applicable info previously submitted DUNN.C N Duquesne Light Co 80/07/10 120pp
- 800722098B Responds to IE Bulletin BO-08 Flued head design for penetration connections w/butt weld between penetration sleeve & process pipe were used Lists pipe penetrations utilizing flued butt head weld const DUNN:C N Duquesne Light Co 80/07/15 3pp
- 8007170546 Forwards "Rept for 60-Day Response to IE Bullatin 80-11.
 Masonry Walk Design." in response to bulletin Items 1.2a
 3 Response available in Central Files only
 DUNN.C N Duquesne Light Co 80/07/17 Ip

- 8007250294 Forwards reply to IE Bulletin 80-11 re masonry wall design W/o encl DUNN,C N Duquesne Light Co BO/07/24 1p
- 8007290680 Updates 790918 ltr that responded to IEB-79-18, "Temp Effects on Level Measurement" Revision of emergency procedures completed, steam generator low-low trip setpoint set at 12% & insulation applied to ref leg water columns DANN.C N Duquesne Light Co 80/07/24 2pp
- R Periodic operating reports & related correspondence
- 8007020546 Forwards NPDES monthly rept for May 1980 MODRE, G W Duquesne Light Co 80/06/25 2pp
- --8007020547 NPDE9 monthly rept for May 1980 No flow from Discharge 102 during May 1980
 MODRE, O W Duquesne Light Co 80/04/25 12pp
- 8007180418 Forwards monthly operating rept for June 1980 BUNN,C N Duquesne Light Co 80/07/11 1p
- --8007180422 Monthly operating rept for June 1980 TIMKO D R Dequesne Light Co 80/07/11 App
- 9 Reportable occurrences, LERs & related correspondence
- 8007010396 Forwards LERs 60-039/03L-0 & 80-042/03L-0 Duquesne Light Co B0/06/24
- --B007010400 LER 80-042/03L-0 on B00619, contractor notified util that river water lines grouted w/four inch space between adjacent bldg walls Lines could be severed during seismic event Orouting will be replaced w/suitable fire seal HERLING, J A Duquesne Light Co 80/06/24 ip
- --B007010456 LER B0-039/03L-0 on B00524, w/plant in Mode 5, power lost to vitel bus inverter 3, due to blown main power supply fuse fuse replaced & inverter returned to svc HERLING, J A Duquesne Light Co B0/06/24 Ip
- BOO7140615 PNO-1-80-016 on BO0625, watchman observed individual inside protected area Search was completed w/no suspect identified DEVELIN.J N , MARTIN.W O , BRUNNER Region 1, Philadelphia, Office of the Director BO/06/25 ip
- BOO7010526 Forwards LER 80-041/03L-0 WERLING, J. A. Duquesne Light Co. 80/06/26 2pp
- --B007010536 LER 80-041/03L-0.on B00502 during test supplementary leak collection & exhaust fan tripped Apparently caused by loose lead Motor lead reconditioned WERLING.J A Duquesne Light Co 80/06/26 ip
- 8007070276 RO 80-044/0iT design for steam generator shubber embedment found not to reflect as-constructed condition, resulting in nonconservative loads for anchors Caused by assumption that load was applied to normal surface HERLING. J A Duquesne Light Co 80/06/30 2pp
- 8007090334 Forwards LER 80-043/03L-0
 Noneane Light Co 80/07/02 2pp
- --8007090338 LER 80~043/03L-0 on 800605, one source range channel was last Caused by high voltage power supply failure New power supply installed & tested successfully LACEY.W S Duquesne Light Co 80/07/02 ip
- 8007090340 Forwards LER 80-037/017-0
- --B007070348 LER 80-037/01T-0 on 800620, one of original radiographs made DOVIVIOUS LER EU-03/01/-V an eucosy, her or origin-by vandur of reactor containment seal welds found code rejectable Cause unknown Four radiographs w/ questionable indications under evaluation LACEY.W B Duquesne Light Co 80/07/02 ip
- 8007180317 Forwards LER 80-044/01T-0 WERLING, J.A. Duquesne Light Co 80/07/11 2pp
- ---8007180322 LER 80-044/01T-0 on 800630 review showed existing steam generator snubber embedment design does not reflect ascenstructed embedment condition Cause not yet determined LACEY, W J Duquesne Light Co 80/07/11 2pp

- 8007220506 Forwards "Investigation of Graver Records of Field Erected Tanks (BVC-198) & Reautor Containment Liner (BVC-65), " as follower to LERs 80-025 & 80-037 Rept available in Central Files only DUNN:C N Duquesne Light Co 80/07/14 2pp
- 8007220430 Forwards L.R 80-033/03L~0
- --8007220434 LER 80-033/03L-0 on 800417, diesel generator i povernor control motor failed Caused by Lycling of governor while attempting to shot down diesel w/fast start signal still applied Motor replaced Duquesne Light Co 80/07/15 1p LACEY, M. S.
- 8007250315 Forwards LERs 80-049/01T-0 & 80-050/01T-0 WERLING.J A Duquesne Light Co 80/07/21 2pp
- --8007250324 LER 80-049/01T-0 on 800718 during investigation per IE Bulletin 79-14 determined that support on component cooling water supply line to IA residual heat removal heat exchanger has high probability of failure during seismic event LACEY.W S Duquesne Light Co 80/07/21 ip
- --B007250331 LER 80-050/017-0 on 800718 during investigation per IE Bulletin 79-14, found undersized snubber was installed on recirculation spray line from IA exchanger to 180 degree apray header Snubber to be replaced LACEY.W 5 Duquesne Light CO 80/07/21 1p
- 8007300383 Forwards LER 80-051/017-0 WERLING J A Duquesne Light Co 80/07/24 2pp
- --8007300388 LER 80-051/01T-0 on 800724.per IE Bulletin 79-14 review. found significant overstress condition would exist during seismic event on B low head safety injection pump recirculation line Cause unknown LACEY.W B Duquesne Light Co BO/07/24 1p
- DOCKET 50-339 BT LUCIE PLANT, UNIT 1
- F Security, medical, emergency & fire protection plans
- B007010379 Forwards BNL fire protection review re upgrading existing 197010379 Forwards BML Fire protection review to upgraving of fire pumps, cable spreading room, fire barrier, smoke detectors, reactor coolant pump oil collection sys & automatic sprintler sys for facility HALL:R E Brookhaven National Laboratory 80/06/24 App
- 8007200647 Advises that evacuation time estimates were submitted in 800717 ltr per 800702 request UHRIG.R E Florida Power & Light Co 80/07/22 lp
- 8007290624 Forwards proposed revision to emergency plan Apps will be forwarded under separate cover Complete implementation will depend on availability of essential resources Encl (140 pages) available in Central Files only UHRIG:R E Florida Power & Light Cn 80/07/23 ip
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UC9 780502 petition for reconsideration of 780413 memorandum & order UC5 771104 petition sought action re fire protection for electrical cables EISENHUT.D & Division of Litensing 80/06/25 89pp
- H General correspondence
- B007110306 Responds to 800512 ltr re encl L Starr ltr concerning plant DOVIDOUS RESPONSE to BOOSIE FOR REPRESENTATION OF THE CONTROL PROBLEMS FOR MULTER PLANT SERVICE OF MULTIPLE PLANT SERVICES OF TAGIOACTIVITY TO ENVIRON DIRECTOR FOR OPERATIONS BO/06/30 Spp
- --8007110314 Requests response to L Starr its concerning plant problems CHILES, L J Senate 80/05/12 ip
- 8007240444 Responds to R00521 ltr re S Corbin inquiry about plant safety aspects Safety design approach involves use of multiple physical barriers to prevent release of radioactivity to environ DIRCKS.W.J. Office of the Executive Director for Operations 80/07/15. 3pp

- --8007240468 Requests response to encl 8 Corbin inquiry about plant safety aspects STONE, R Senate 80/05/21 200
- M Antitrust correspondence
- 8007150719 Response stating no objection to Orlando Utils Commission 800620 withdrawal of intervention FL Cities 800707 comments re equal treatment will be addressed in Unit 2 antitrust proceeding Certificate Svc encl DEWEYLE 6 Antitrust Division 80/07/11 4pp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing fm redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D G Division of Licensing 80/06/11 62pp
- B00710013P Forwards Amend 35 to License DPR-67, safety evaluation & notice of issuance & availability
 CLARK.R A Operating Reactors Branch 3 B0/06/13 2pp
- ---B007100136 Amend 39 to License DPR-67, allowing Unit 1 to proceed from Mode 4 to Mode 3 to allow steam turbine driven auxiliary feedwater gump surveillance to be postponed CLARK, R.A. Operating Reactors Branch 3 80/06/13 Spp
- --BOO/100138 Safety evaluation supporting Amend 35 to License DPR-67
 * Office of Nuclear Reactor Regulation, Director 80/06/13 2
- --- 8007100141 Notice of issuance & availability of Amend 35 to License DPR-67 CLARK,R A Operating Reactors Branch 3 80/06/13 2pp
- 8007100161 Summary of B00620 meeting w/util & C-E in Bethesda,MD re B00611 reactor trip & cooldown on natural circulation NELSON,C C Operating Reactors Branch 3 80/06/25 21pp
- 8007030221 Requests NRC approval of encl plans to implement 810101 requirements of Leusons Learned Task Force Item 2 | 8 b Licensee will install four SPING-4 samplers by 810101 to monitor normal & high range noble gas at vent stack UNRIO.R E Finida Power & Light Co 80/06/27 3pp
- 800/110199 Advises NRC that NUREC-0578 requirement to measure chlorides & dissolved gases in RCS following accident is excessive & involves unnecessary personnel exposure to radiation Requests that NRC reconsider position UNRIO.8 F Floride Power & Light Co 80/06/27 1p
- 8007230001 Requests submittal of application for amend to license consisting of Tuch Spec changes & license conditions PHR Model Tuch Specs & Model license conditions for TMI-2 Lessons Learned Category A Itoms encl for guidance EISERNUT, D.O. Division of Licensing 80/07/02. 67ap
- 8007070286 Forwards explanation of selection of undervoltage relay & setpoint, in response to NRC 800529 request for add1 info re grid yoltage Discussion of consequences of spurious actuation of relays also encl.

 UNRIG.R E Florida Power & Light Co. 80/07/03 3pp
- 8007240280 Requests that response to Item 1 of encl request for add1 info re probable steam bubble created in reactor vessel on 800611 be submitted within 10 days of receipt of 1tr Response to Item 2-5 should be submitted within 60 days NOVAK.T M Assistant Director for Operating Reactors 80/07/08 4np
- BOO724033B Advises of NRC reorganization on 800428 which resulted in number of changes in ofc titles positions & assignments of personnel Also submits info for GETR NOVAN, T M Assistant Director for Operating Reactors 80/07/08
- BOO7R20374 Advises that Henry Pratt Co torque & stress analyses re containment purge have been delayed Upon completion & receipt of analyses.util will review & prepare response demonstrating volve ability to close during DBA-LOCA UMRIQ.R E Florida Power & Light Co 80/07/15 tp

- O Inspection reports. IE Bulletins & correspondence
- 8007240206 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "No response required O'REILLY, J P. Region 2. Atlanta. Office of the Director B0/05/08
- 800702023; Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007210458 Forwards IE Circular 80-13, "Grid Strep Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director (60/05/28
- 8007010206 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007100059 Forwards IE Insp Rept 50-335/80-12 on 800429-0502 No noncompliance noted
 LEMIB.RC Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch B0/05/29 2pp
- --8007100061 IE Insp Rept 50 335/80-12 on 800429-0502 No noncompliance NOVIDUOS I I I map kept to 333-20-12 on Noviet Amount and Indicaption on noted Major areas inspected pipe support & restraint sys including surveillance & test results

 UPRICHIT.C M Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch JOHNSON, A H Region 2, Atlanta, Office of the Director BO/05/29 4pp
- 8007020321 "Environ Gualification of Electrical Equipment in Harsh Environ Which is Required for Accident Mitigation/ Monitoring "
 * Florids Power & Light Co HO/06/01 20pp
- --8007020326 "Baint Lucie Unit i NRC IE Bulletin 79-018.Phase i." master list & component evaluation sheets * Ebasco Services, Inc (subs of Enserch Carp) 80/06/01
- B007220062 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/1
- 8007160265 Forwards IE Info Notice 80-27, Degradation of Reactor Coolant Pump Studs " No specific action or response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007020752 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Natification Bys (ENS) W/Loss of Offsite Power " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06 Region 2, Atlanta, Office of the Director 80/06/18
- 8007110102 Forwards IE Insp Rept 50-335/80-16 on 800603-05 No nuncompliance noted KENNA.W B Region 2. Atlants. Bafeguards Branch 80/06/19 ip
- --8007110117 IE Insp Rept 50-335/80-16 on 800603-05 No noncompliance noted Major areas inspected security & health physics control Details withheld (ref 100FR2 790)
 TOBINA J. TILLMAN.A Region 2. Atlanta, Office of the Director. GILLESPIE,F P Region 2. Atlanta, Safeguards Branch 80/06/18
- 8007290369 Forwards IE Investigation Rept 50-335/80-15 on 800410-0514 No noncompliance noted LONG.F J Region 2: Atlanta: Office of the Director 80/06/19
- --B007290380 IE Investigation Rept 50-335/80-15 on 800410-0514. No noncompliance noted Major areas investigated allegations re ASME code requirements for valves & installation of ABME CODE PEQUIPMENTS FOR VALVES & Instantation of containment penetrations
 LDNO,F J. MARBH,R J. Region 2. Atlanta, Office of the Director.
 HERDT.A R. Region 2. Atlanta, Reactor Construction & Engineering
 BUPPORT Branch B0/06/19 10pp

- 8007020454 Forwards IE Circular 80"15, "Loss of Reactor Coolant Func Cooling & Natural Circulation Cooldown " No written response required U'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007100021 Responds to IE Bulletin 80-06. "Engineered Safety Feature Reset Controls " Sys identified as returning to normal position after reset Safety injection tank isolation & check valve leak-off valves returned to normal position UMRIO.R E Florida Power & Light Co 80/06/20 3pp
- B007070097 Ack receipt of B00511 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/80-10 MCRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch B0/05/24 ip
- --8007070100 Responds to MRC 800512 ltr re violations noted in IE Insp Rept 50-335/80-10 Corrective actions examiner passed eye exam & schedule for recertification of vision tests established UMRIO.R E Florida Power & Light Co 80/06/11 2pp
- --8007070102 Forwards IE Insp Rept 50-335/80-10 on 800408-11 & notice of violation HMRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/12 2pp
- ~~8007070103 Notice of violation from insp on 800408-11 * Region 2, Atlanta, Office of the Director 80/04/30 lp
- --B007070107 IE Insp Rept 50-335/80-10 on B00408-ji Noncompliance noted staminer failed to meet eye exam requirements HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch CROMELY, B R Region 2, Atlanta, Office of the Director 80/04/30 Spp
- B007170109 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24 is
- B007220059 Ack receipt of 800612 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/80-07 LENIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/06/27 lp
- --B007220069 Responds to NRC B0051B ltr re violations noted in TE Inap Rept 50-335/B0-07 Corrective actions procedures will be changed to require signatures for disconnected lead & temporary jumper log reviews UHRIG,R E Florida Power & Light Co B0/06/12 3pp
- ---B007220075 Forwards IE Insp Rept 50-335/80-07 on B00415-18 & notice of violation LEHIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch B0/05/16 2pp
- --8007220079 Notice of violation from insp on 800415-18

 Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/15 1p
- 8007230243 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Butput Codes " Written response required IE Circular 80-16 also enci No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- B007160797 Ack receipt of 800612 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-335/80-14
 LEWIB,R C Region 2. Atlanta. Reactor Operations Nuclear Support
 Branch 80/06/30 ip
- --8007iA0BiO Responds to NRC B005iA ltr re violation noted in IE Insp Rept 50-335/B0-14 Corrective actions LER being prepared to report results of integrated test of engineered safety features UMRIG.R E. Florida Power & Light Co. B0/04/IR 2pp

- --8007160817 Forwards IE Insp Rept 50-335/80-14 on 800430-0502 & notice of violation LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 60/05/16 2pp
- --8007160826 Notice of violation from insp on 800430-0502 * Region 2. Atlanta. Office of the Director 80/05/16 1p
- --8007i60830 IE Insp Rept 50-335/80-14 on 600430-0502 Noncompliance noted failure to rept emergency diesel generator load sequence timers that did not meet Tech Specs during routine surveillance testing MESSITI.B R Region 2, Atlanta. Office of the Director UPRIGHT.C M Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/16 5pp
- 8007250312 Forwards response to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds" Containment boundary butt welds identified Field welds were made during const Shop welds were made by penetration assembly Fabricator UHRIG.R E Florida Power & Light Co 80/07/08 12ap
- 8007250272 Responds to 1E Bulletin 80-10, "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ "No addiroutine sampling or monitoring programs are required UHRIG.R E Florida Power & Light Co 80/07/09 ip
- B007220379 Responds to IE Bulletin 80-11. "Masonry Wall Design " Info is incomplete due to identification work still in progress Safety-related walls have been identified & evaluation program developed Rept will be provided by 800723 UHRIGIRE Florida Power & Light Co 80/07/16 ip
- R Periodic operating reports & related correspondence
- 8007080330 Forwards "Semiannual Radioactive Effluent Rolease Rept for Jul-Dec 1978 " UHRIQ.R E Florida Power & Light Co 79/03/01 1p
- --8007080335 "Semiannual Radioactive Effluent Release Rept for Jul-Dec 1976 " * Florida Power & Light Co 79/03/01 27PP
- 5 Reportable occurrences, LERs & related correspondence
- B0070104B3 Forwards LER 80-022/09L-0 SCHMIDT, A D Florida Power & Light Co B0/06/19 tp
- --800701049] LER 80-0,22/03L-0 on 800520, digital data processing sysmalfunctioned during power operation Caused by computer programing error Sys repaired & returned to svc Program will be revised to corroct software problem SCHOPPMAN, M A Florida Power & Light Co 80/06/20 1p
- 8007080284 Forwards LER 80-029/017-0 SCHMIDT, A D Florida Power & Light Co 80/04/25 ip
- ---B007080290 LER B0-029/01T-0 on 800611.st 100X power, ground occurred in circuit of valve MVC-14-6 causing valve to fail closed Caused by steam condensing on valve solenoid w/moisture invading terminal box Solenoid & terminal board replaced SCHOPPMAN.M A Florida Power & Light Co 80/06/25 2pp
- 8007140382 Forwards LER 80-026/03L-0 6CHMIDT, A D Florida Power & Light Co 80/06/29 1p
- --8007140389 LER BO-026/OSL-O on B00830, during normal power operations, noted that 31-day fire station insp required by Tech Spec had been exceeded Caused by personnel inadvertently overlooking insp BCHOPPMAN.M A Florida Power & Light Co BO/06/29 ip
- 8007140364 Forwards LER 80-028/03L-0 9008107, A D Florida Power & Light Co 80/06/30 lp
- --B007140372 LER 80-02B/O3t-O on 800531.during normal operations.channel A of 1A steam generator low pressure trip failed Caused by failure of power supply associated w/channel A Vendor contacted & new power supply installed & tested SCHOPPMAN.M A Florida Power & Light Co B0/06/30 1p
- 8007150627 Forwards LER 80-030/07L-0 SCHMIDT, A D Florida Power & Light Co 80/07/03 ip

- -8007130636 LER 80-030/03L-0 on 800603 during full power operation, CRT rud position display (metrascope) was briefly de-energized to permit replacement of failing power supply Control element assembly block circuit also disabled SCHOPPMAN. H A Florida Power & Light Co 80/07/03 ip
- -8007150536 LER 80-025/09X-1 on 800512, during planned secondary plant shutdown for turbine maint, main steam header would not depressurize following steam stop closure Cause unknown Valve stems were replaced & verified operable SCHOPPMAN, & A Florida Power & Light Co 80/07/07 2pp
- OCKET 50-336 MILLSTONE NUCLFAR POWER STATION, UNIT 2 Security, medical, emergency & fire protection plans
- DO7180194 Forwards NRC 800425 ltr to all power reactor licensees, in response to 800529 ltr re emergency response facilities at reactor sites Bites w/approval to use closed-circuit television link w/technical support ctr listed CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/07 2pp
- CO7010337 Comments on proposed rule 10CFR50 regulation for fire protection excessively specific & unjustifiably restrictive Suggested revisions to App R w/justifications encl COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Utilities 80/06/16 31pp
- 007030336 Comments on proposed rule iOCFR50 requirements for exceed those necessary to resolve generic issues & are excessively specific & restrictive Forwards alternative App R fire protection program COUNSIL, W @ Connecticut Yankee Atomic Power Co COUNSIL, W @ Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/16 16pp
- 007090231 Forwards responses to NUREG-0654 critoria & facilities emergency plans per NRC 800512 & 791010 ltrs Encls available in Central Files only Emergency plans withheld (ref
- 10CFR2 770)
 COUNSIL.W Q Connecticut Yankee Atomic Power Co CDUNSIL.W.Q
 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/06/30 2pp
- 107170425 Confirms position discussed in 800624 telcon re safeguards contingency plans NRC requested revisions are ill-advised & unnecessary Specifics of plan implementation can be detailed in procedures
 CDUNSIL.W G Connecticut Yankee Atomic Power Co CGUNSIL.
 Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/07/01 Rep COUNSTL. U. G.

Adjudicatory correspondence

07310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780302 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EIBENHUT, D G Division of Licensing 80/06/25 87pp

Financial information

- 007150A22 Forwards 1980 cash flow estimates for CT Light & Power Co, Hartford Electric Light Co & Western MA Electric Co Cash flows are adequate to meet potential premium requirements for 1975 amends to Price-Anderson Act D'CONNOR, L A Northeast Utilities 80/07/03 2pp
- Operating license stage documents & correspondence
- 107230099 Requests submittal of proposed Tech Spec changes providing for redundancy in deray heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EIBENHUT.D G Davision of Licensing 80/04/11 62pp
- 07140027 Summary of 800404 meeting w/util in Bethesda.MD re Cycle 4 reload at facility w/Westinghouse fuel List of attendees & agondo encl CONNERS.E L. Operating Reacture Dranch 3 80/06/16 Spp

- B007030362 Requests response to encl questions re fuel design & physics calculations to complete review of basic safety rept supporting Cycle 4 reload Requests that add1 info be provided by 800630 to meet review schedule CLARK.R A Operating Reactors Branch 3 80/06/20 3pp
- 8007020569 Clarifies 800506 response to NRC 791030 request for info concerning Lessons Learned Task Force Item 2 1 B a, improved post-accident sampling capability Info ensures accurate NRC understanding of design philosophy & intent COUNSIL.W 9 Connecticut Yankee Atomic Power Co COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/23 3pp
- 8007:1054! Forwards request for add1 info re adequacy of station electric distribution sys voltages,per review of 791:15 submittal Response requested within 60 days NOVAK.T M Assistant Director for Licensing 80/06/25 Spp
- 8007080164 Application to amend License DPR-65, consisting of proposed revisions to Tech Specs re containment electrical penetrations Procedure for fuel handling accident inside counsile W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/26 6pp
- ~~B007080169 Proposed revisions to Tech Specs 3 9 4 & 4 9 4 re containment electrical penetrations * Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/06/06 Zpp
- -B0070B0176 Procedure for Puel handling accident inside containment * Northeast Nuclear Energy Co (subs of Northeast Utilities) 77/06/08 App
- B007020557 Forwards "RCS Asymmetric Loads Evaluation Program," final rept in response to NRC 780125 ltr to PMR licensees re asymmetric LOCA loads C-E afPidavit for withholding encl Proprietary version of App A withheld (ref 10CFR2 790) LUNDVALL, A E C-E Operating Plants Owners Group 80/06/30 2pp
- --B007020874 "RCS Asymmetric Loads Evaluation Program," final rept. Val I * C-E Pawer Systems BO/06/30 20pp
- --8007020581 "RCS Asymmetric Loads Evaluation Program," final rept, * C-E Power Systems 80/06/30 300pp
- --8007020588 "RCS Asymmetric Loads Evaluation Program," final rept. Vol
 - * C-E Power Systems 80/06/30 300pp
- --8007020593 "RCS Asymmetric Loads Evaluation Program," final rept,App A, numerical results, evaluation of C-E fuel Non proprietary version App B. Palisades fuel analysis, encl # C-E Power Systems 80/06/30 26pp
- --8007020600 "RCS Asymmetric Loads Evaluation Program," App E.ECCR analysis approach w/reduced area coolant channels in peripheral assemblies. Final rept * C-E Power Systems 80/06/30 9pp
- 8007280001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT.D 0 Division of Licensing 80/07/02 69pp
- 8007100200 Forwards response to NRC 8000507 requests for addl info re propsed revisions to ETS State of CT Dept Environ Protection 800611 ltr approving Thermal Plume Study Rept COUNBIL, W O Northeast Utilities 80/07/03 27pp
- B007140344 Forwards addl info re fuel design & physics calculations per RA Clark 800620 request Response to Question 10 withheld (ref 10CFR2 790)
 COUNSIL.M G Northeast Utilities, B0/07/07 14pp Northeast Utilities, 80/07/07 14pp
- B007240350 Advises of NRC reorganization on 800428 which resulted in number of changes in off titles, positions & assignments of personnel Also submits info for GETR NOVAK.T M Assistant Director for Operating Reactors 80/07/08

- 8007210238 Application for amend to License DPR-45, revising Tech Spec door numbers in Table 3 9-1 & position of certain doors in auxiliary bldg during fuel movement in spent fuel area or crane operation over spent fuel pool CKCNBIL.W 0 . FEE.W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/10 3pp
- --8007210245 Proposed revisions to Tech Specs Table 3 9-1 revising door numbers & position of certain doors in auxiliary bldg during fuel supement in fuel storage areas or crane operation over spent fuel pool

 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 80/07/31 2pp
- B007220457 Application for amend to Licenses DPR-21 & DPR-65 to incorporate changes to Tech Specs re organizational title Class I fee encl COWNSIL.W. O. FEE.W F Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/14 3pp
- ---BO07220467 Proposed revised Tech Specs, incorporating organizational title changes # Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/14 10pp
- B007250300 Application to amend Licenses DPR-21 & DPR-65, clarifying Tach Specs to reflect recent organizational title changes License fee transmitted 800714 Affidavit encl COUNBIL.W O Mortheast Nuclear Energy Co (subs of Northeast Utilities) 80/07/15, 2pp
- ---8007250303 Proposed revisions to ETB, Pages 5 1-2 & 5 1-5, reflecting recent organizational title changes & Northeast Nurlear Energy Co (subs of Northeast Utilities) 80/07/15 3pp
- 8007280673 Requests extension of comment period re NUREG-0577, "Potential for Low Fracture Youghness & Lamellar Tearing on PMR Steam Generator & Reactor Coolent Pump Supports," until 800915, COUNSIL, N O Northeast Utilities 80/07/21 2pp
- **G** Inspection reports, IE Bulletins & correspondence
- 8007020146 Forwards IE Info Notice 80-22, "Breakdouns In Contamination Control Programs " No written response required ORIER.B H Region I, Philadelphia, Office of the Director 80/05/28 1p
- 8007010312 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps." No written response required ORIER.B H Region 1. Philadelphia, Office of the Director 80/05/29, ip
- B007020039 Advises that full response to IE Bulletin 80-12. "Decay Heat Removal 89s Operability." will be submitted by 800701 Delay necessitated by current heavy demand on operations personnel COLMBILL 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/04 2pp
- 8007210580 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required GRIEN.8 H Region 1, Philadelphia, Office of the Director 80/06/10 ip
- 8007160387 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required GRIER, B. H. Region 1, Philadelphia, Office of the Director 80/06/11, 1p.
- 8007170320 Reaponds to IE Bullstin BC-06, "Engineered Safety Feature (ESF) Reset Controls " Three facilities will have completed mods per IE Bullstin 80-06 by 810101 List of equipment & status of Criteria encl.

 COUNSIL, W. G. Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Utilities 80/06/13 43pp
- 8007020700 Forwards IE Bulletin 80-18, "Possible Loss of Emergency Notification Sys (ENB) W/Loss of Offsite Power " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/18, ip
- BOO71B0187 Submits reply to IE Bulletin 80-08 re examination of containment liner penetration welds Due to absence of abnormal conditions no further action planned CDUNBIL, N. G. Northeast Utilities BO/06/19 lipp

- 8007310361 Forwards IE Insp Repts 50-245/80-07 & 50-336/80-05 on 800501-31 No honcompliance noted BRUNNER, E. J. Region i, Philadelphia. Reactor Operations Nuclear Support Branch 80/06/19 2pp
- --B007310365 IE Insp Repts 50-245/80-07 & 50-336/80-05 on B00501-31 No noncompliance noted Major areas inspected control rooms & accessible portions of Unit ; reactor, turbine, radwaste, gas turbine generator & intake bldgs
 SHEBLOSKY, J T, ZIMMERMAN, R P. Region i, Philadelphia, Office of the Director KEIMIG, R R Region i, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/10 9pp
- 8007020494 Forwards IE Circular 80-15, "Loss of Reactor Coulant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/20 ip
- 8007160714 Forwards IE Circular HO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/06/24 1p
- 8007210207 Forwards IE Info Notice 80-24, "Low Level Radwaste Durial Criteria " No written response required CRIER,D H Region i, Philadelphia, Office of the Director 80/06/25 ip
- B007230146 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Output Codes" Written lesponse required IE Circular 80-16 also entl No written response required GRIER, B W Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- R Pariodic operating reports & related correspondence
- 8007210374 Forwards monthly operating rept for June 1980 MRCCZNA.E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/07/11 1p
- --8007210375 Monthly operating rept for June 1980 HDWLETT.Q H Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/02 Spp
- 8 Reportable occurrences. LFRs & related correspondence
- 8009230131 PNG-I-80-071 on 800905, significant number of security force personnel, contracted from Interstate Security Svcs. Inc. began taking leave at start of mid-shift Security supervisors working 12-b shifts will maintain full coverage ZIHMERMAN, R P. KEIMIG, R R. DEVLIN, J W. Region 1, Philadelphia, Office of the Director 80/05/05 ip
- 8007010445 Forwards updated LER 80-0i1/O3L-P MROC2KA:E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/24 lp
- --8007010450 Updated LER 80-011/03L-2 on 8003i3, following two plant trips & shutdown, daddle clamp bolts for two hangars were found broken Both hangers are hydraulic snubbors Failures caused by combination of fatigue & high impact loading CLEMENT, C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 80/06/24. 2pp
- BOO7070318 Forwards revised LER 90-018/01X-1 MRQC7KA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 80/04/27 1p
- ~-8007070324 Revised LER 80-018/01X-1 on 800508, during ingoing hanger base-plate analysis both svc water headers declared inoperable Caused by supports not providing factor of safety greater than two Redesign & mode completed 800621 * Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/27 2pp
- B007070361 Forwards LER 80-022/03L-0 MR0CZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/06/27 ip
- ---B007070372 LER 80-022/03L-U on 800529, during engineered safeguards actuation sys test, IA actuating module placed in tripped condition Fans did not shift to low speed Cause suspected to be sticking of module output relay K515A CLEMENT. C Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/27 Ip

- B007140556 PND-1-80-096 on 800701.72 new fuel bundles discovered fabricated w/design error in one dimension Cause unstated New Puel bundles being prepared for shipment hack to Westinghouse for mod Press release will be issued # Office of Inspection & Enforcement. Office of the Director 80/07/02 ip
- BOO7250409 Forwards LER 80-023/03L-0 HRDCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/18 1p
- --B007250410 LER B0-023/03L-0 on B00425, core barrel munitor declared inoperative when computer would not respond to input commands Caused by natural end of life of two circuit boards Circuit boards replaced CRISCIONE, J L Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/07/18 1p
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT t
- E. NRC Bafety Evaluation Report (SER), supple & correspondence
- B007300297 Forwards discussion of util B00711 & 18 responses to deficiencies listed in SER Full-power operation should be authorized upon obtaining FEMA approvable of state & local emergency plans GRIMES. B K Emergency Preparedness Task Force 80/07/22 Spp
- F Security, medical, emergency & fire protection plans
- 8007240005 Forwards amended physical security plan Plan withheld (ref 10CFR2 790)

 SYLVIA, B. R. Virginia Electric & Power Co. 80/06/03 1p
- B007170601 Forwards revised nuclear security personnel training qualification program & response to NRC B00519 ltr Program & response withheld (ref 10CFR2 790) BYLVIA, B R Virginia Electric & Power Co 80/07/14 ip
- B00724009P Forwards security info re B00609 ltr Info withheld (ref 100FRZ 790) BYLVIA.B R Virginia Electric & Power Co 80/07/18 1p
- BOO7220579 Forwards emergency plan Revision 4 in response to request made during BOO715 meeting w/FEMA & State of VA. to support full power license request BAUM, E A Virginia Electric & Power Co 60/07/22 22pp
- --B007220582 Facility emergency plan. Revision 4

 * Virginia Electric & Power Co B0/07/15 13pp
- BD07280196 Forwards emergency prepatedness requirements for full power license per review of 800419.0606.20 & 25 submittals Requests schedule for meeting requirements TEDESCO.R L. Assistant Director for Licensing 80/07/22 App
- 800/280432 Forwards revised emergency plan implementing procedures Procedures available in Central Files only BAUN.E A. Virginia Electric & Power Co. 80/07/22 1p
- 8007300297 Forwards discussion of util 800711 & 18 responses to deficiencies listed in BER Full-power operation should be authorized upon obtaining FFMA approvable of state & local emergency plans
 QRIMES.B K Emergency Prepusedness Task Force 80/07/22 Spp
- BOO7310193 Requests that ltr.similar to encl draft ltr.be forwarded to util re encl review of emergency action levels for facility emergency plan PAGANO.F O Emergency Preparedness Licensing Branch 80/07/22
- 8007250383 Forwards Revision 5 to station emergency plan.completing response to BK Grimes 800715 comments
 BAUM.E A Virginia Clectric & Power Co 80/07/24 2pp
- ---8007250385 Emergency plan.Revision 5
 * Virginia Electric & Power Co 80/07/24 2pp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 patition for reconsideration of 780413 momorandum & order UCS 771104 potition sought action re fire protection for electrical cobles EISENHUT, D & Division of Licensing 80/06/25 89pp

- 8007110337 Order granting extension until 800723 for Commission to elect whether to review decision taken under 10CFR2 208 on request for enforcement action. DD-80-23 HOYLE, J C Office of the Secretary of the Commission 80/07/09 to
- B007300412 Advises that effective B00801 address for coalition will be: 1105-C Olive St. Greensboro NC 27401 Related correspondence.
 ALLEN, J North Anna Environmental Coalition 80/07/15 ip
- H General correspondence
- 8007150047 Responds to 800327 itr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants, operating & under const & relative costs of coal vs nuclear energy YOUN080,000.8 J Operating Reactors Branch 1 80/05/13 5pp
- 8007070059 Forwards 800620 Director's Decision DD-80-23, denying 800218, 22,0425 & 0525 requests for action FR notice and DENTON, H R Office of Nuclear Reactor Regulation, Director 80706/20 2pp
- ---B007070064 Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ coalition for action DENTON:H R Office of Nuclear Reactor Regulation, Director 80/06/20 20pp
- --B007070069 FR notice of issuance of 800620 Director's Decision DD-80-23 denying 800218, 22, 28,0425 & 0525 requests by North Anna Environ Coalition for action DENTON-H R Office of Nuclear Reactor Regulation, Director 80/06/20 2pp
- --8007070075 Requests amend to 800218 ltr following discovery of additional problems in steam generator. Facility should be kept shut down pending resolution of noise, secondary chemistry, turbine cracks & demineralizer problems

 ALLEN, J. North Anna Environmental Coalition 80/02/22 1p
- ---8007070077 Requests action concerning defective demineralizer design, related corrosion & cracking in steam generators & turbine discs Commends NRC decision to require EIB re experimental replacement of steam generators
 ALLEN, J. North Anna Environmental Coalition 80/02/IB 4pp
- J Insurance & indemnity information
- 8007150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE D A Marah & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/07/10 3pp
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EIBENHUT, D. G. Division of Licensing 80/06/11 62pp
- 8007100078 Forwards request for add1 info re adequacy of station electric distribution sys voltages per review of 791009 & 791128 submittals Requests response within 45 days CLARK.R A Operating Reactors Branch 3 80/06/25 5pp
- 8007010422 Responds to NRC 800507 ltr re loss of offsite power, Review of history reveals two partial losses of offsite power occurred, SYLVIA.B R Virginia Electric & Power Co 80/06/26 3pp
- B007010430 Confirms agreement w/NRC ro review criteria to be used to evaluate results of rod swap tests & administration of physics test program should deviations occur THOMAS.H N Virginia Electric & Power Co B0/06/26 6pp
- B007020496 Forwards add1 info or corrective actions for Steam generator chemistry & corrosion, per NRC B00402 request SYLVIA.B R Virginia Electric & Power Go B0706/30 19pp
- 8007020392 Forwards "North Anna Unit i,Cycle 2 Startup Physice Test Rept " THOMAS,W N Virginia Electric & Power Co BO/06/30 ip
- --8007020398 "North Anna Unit 1. Cycla 2 Startup Physics Test Rept "
 KUN31T19. T J , LEBERSTIEN, J H , LOZITO, E J Virginia Electric &
 Power Co VEP-F8D-35 80/06/30 110pp

- 800707036B Forwards request for info re bypass & reset of engineered safety features Request revised per 80052B discussions w/NRC
 - CARFAONO, S P Franklin Institute/Franklin Research Center NRC-03-79-118 80/06/30 300
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tach Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT, D O Division of Licensing 80/07/02 69pp
- B007080069 Application for amend to License NPF-4, adding requirement that ECCB subsystems be demonstrated operable by verifying that manual valves in Tech Spec 4 5 2 g 2 are locked tagged in proper position following maint Fee encl FERGUSON, J H Virginia Electric & Power Co 80/07/03 3pp
- ---BOO70BOO72 Proposed revised Tech Spec 4 5 2 gladding requirements that ECCB subsystems be demonstrated operable by verifying that manual valves are locked & tagged in proper position following maint
 * Virginia Electric & Power Co 80/07/03 2pp
- 8007100250 "Sump Pump Discharge Piping Auxiliary Bldg to Containment" * Stone & Webster Engineering Corp 77/10/24 ip
- ---B007100284 "Flow Diagram Boron Recovery Sys " Sheet i * Stone & Webster Engineering Corp 80/07/07 ip
- --8007100288 "Flow Diagram, Containment Atmosphere Cleanup Bys "
 * Stone & Hebater Engineering Corp 77/10/22 11p
- --B007100298 "Flow Diagram, Waste Disposal Sys " Sheet 1 # Stone & Webster Engineering Corp 80/07/07 1p
- --8007100303 "Ventilation Thermal Recombiner * Stone & Webster Engineering Corp 80 80/04/07 1p
- --8007100309 "P&ID Liquid Bampling " Sheet 1 of 5 * NVS Corp BO/05/05 ip

NUS Corp

- ---B007100311 "P&ID Liquid Bampling " Sheet 2 of 5 * NUS Corp 80/02/19, 1p
- --8007100315 "P&ID Liquid Sampling Coolers " Bheet 3 of 5 * NVS Corp. 80/05/05 ip
- ---8007100321 "P&ID Liquid Sampling Panel " Sheet 4 of 5 * NUS Corp 80/05/05 ip
- ~~8007100323 "P&ID·Liquid Bampling " 5 of 5 ** NUS Corp 80/05/05 1p
- --- BO07100327 "P&JD Containment & Air Sampling Sys " Sheet 1 of 1 B0/05/05 1 p
- --8007100335 "Process Flow Diagram.Liquid Sampling " Sheet 1 of 2 * NUS Corp 80/05/22 ip
- ~-8007100338 "Process Flow Diagram'Liquid Bampling " Sheet 2 of 2 * NVB Corp 80/05/22 ip
- --8007100347 "Process Flow Diagram Containment Air Sampling " * NVS Corp 80/04/14, ip
- --8007100351 "General Arrangement Auxiliary Bldg. Drumming Room Plan. Elevation 274 Ft " Sheet I * NUS Corp 80/05/29 ip
- ---8007100359 "General Arrangement Auxiliary Bldg, Drumming Room, Section & Details, " Sheet 2 * NUS Corp. 80/05/29 Jp
- --8007100365 "General Arrangement High Radiation Sampling Sys Waste Tank & Pumps Plan Elevation 244 Ft.6 Inches & Section " Sheet 1 * NUS Corp 80/05/29 1p

- 8007280169 Advises of 800428 reorganization of DFc of Nuclear Reactor Regulation Lists personnel responsible for facility NOVAK, T.M. Assistant Director for Operating Reactors
- 8007140393 Application to amend License NPF-7 consisting of changes to Tech Spec setpoints & allowable values FERGUSON.J H Virginia Electric & Power Co 80/07/11 3pp
- --8007140400 Revised Tech Spers Table 2 2-1 for leactor trip sys instrumentation trip setpoints & Table 3 3-4 for engineered safety feature actuation sys instrumentation trip setpoints * Virginia Electric & Power Co 80/07/11 6pp
- B007150569 Notifies that util is using dual sys of notification for site & general emergencies in cooperation w/local counties at insistence of VA State Ofc of Emergency & Energy Sycs Tentative implementation schedule for NUREG-0654 encl BAUM.E A Virginia Electric & Power Co 80/07/11 20pp
- B007210102 Natification of 800724 meeting w/vtil in Bethesda.HD to discuss analysis of quadrant tilt CHATTERTON.M Core Performance Branch B0/07/11 2pp
- 8007240204 Notification of 800724 meeting ω/util in Bethesda.MD to discuss quadrant tilt in plant GHATTERTON.M Core Performance Branch 80/07/11 2pp
- 8007310421 Comments on NUREG-05/7, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports " Requests extension of review period to 800915 to review stress corresion cracking BROWN,S C Virginia Electric & Power Co 80/07/21 2pp
- 8007250415 Requests time extension to replace Barton Transmitters to DAY ENGINEER REQUESTS TIME EXECUTION TO PEPIACE NATION TRANSMITHING THE PROPERTY OF UNIT I.L. L. I Replacement of Unit wrocaeling consistent w/current transmitter availability as previously discussed

 SYLVIA, B. R. Virginia Electric & Power Co. 80/07/22 Rpp
- B0072B0A5i Provides summary of results of Phase I of multiple structure advance record sys evaluation of piping sys design Final detailed rept will be submitted upon completion of Phase II effort Category listing attached SYLVIA.B R Virginia Electric & Power Co 80/07/25 3pp
- 8007290700 Summarizes results of Phase I of multiple structure amplified response spectra evaluation of North Anna I piping sys design as described in 800606 ltr Final detailed rept will be submitted upon completion of Phase II effort BYLVIA, BR Virginia Electric & Power Co 80/07/25 Opp
- Q Inspection reports. IE Bulletins % correspondence
- 8007240230 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY.J P Region 2. Atlants. Office of the Director 80/05/08
- 0007020200 Forwards IE Info Natice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- BOO7210477 Forwards IE Circular 80-13. "Grid Strap Damage in Hestinghouse Fuel Assemblies" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director
- B007010239 Forwards IE Info Notice 80-23, "Losa of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007160732 Forwards IE Insp Repts 50-338/80-23 % 50-339/80-23 on NOVADOVAE rotumeros to trap repts Portugatores & 20-139780-43 on BOOS12-15 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch BO/06/09 2pp
- -8007160742 IE Inan Repts 50-338/80-23 & 50-339/80-23 on 800512-15 No noncompliance noted Major areas impected seismic analysis for as-built safety-related piping sys & licensee actions on licensee identified items COMPTON.R M Region 2. Atlanta. Office of the Director HERDIAR R Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/06/04 5pp

- Forwards 1E Info Notice 80-26. "Evaluation of Contractor ands IE 1940 Notice Mureo. Evaluation of Contractor No written response lequired Region 2. Atlanta. Office of the Director BO/06/10
- Forwards IE Info Notice 80-27, "Dogradation of Reactor Cump Btuds " No specific action or response
- JP Region 2, Atlanta, Office of the Biroctor 80/06/11
- Forwards revision to Page 2 of 800611 response to 1E 80-12. "Decay Meat Removal Rus Operability " R Virginia Electric & Power Co 80/06/16 2pp
- Responds to IE Bulletin 79-01B, "Environ Classification of nent" Class IE electrical equipment reviewed to inctioning during postulated accident Review of ems 1.2 % provided in encl repts W/o encl repts R Virginia Electric & Power Co 80/06/16 App
- Forwards IE Bulletin NO-15, "Possible Luse of Emergency fon Sys (ENS) W/Lous of Offsite Power " Nritten
- Region 2. Atlanta, Office of the Director 80/04/18
- Forwards IE Circular 80-15, "Loss of Reactor Cublant Pump Natural Circulation Couldown " No written response
- JP Region P. Atlanta, Office of the Director
- Forwards II Circular 60-14, "Radioactive Contamination of the alized Water Syst & Resultant Internal tion of Parsonnel" No written response required JP Region 2, Atlanta, Office of the Director B0/06/2 R070A724
- Responds to IF Bulletin 79-14. "Goismit Analysis for Safoty-Related Piping Sys " Const work complete on imited completion date for Unit 1 is 8009.31 Virgina Elettric & Power Co 80705/27 Spp
- Torwards IE Rulletin 60-16. "Potential Micapplication of Inc Models 1191 & 1192 Pressure Transmitters For B Output Codes " Britten response required T 80-16 also onel No written response required I P Region 2. Atlanta. Office of the Director 80/06/2 80/04/27
- orwards IE Insp Repts 50-930/80-24 & 50-339/80-24 on Ne noncompliance noted Details withheld 2 7901
- Region 2, Atlanta, Safaguarda Branch 80/07/01 Ip
- lt Insp Repte 50-408/80-24 t 50-339/80-24 on 600511-12 No lence noted Major areas inspected vital area searches t vital area access Datails withheld TR2 790)
 . If P Region 2: Atlanta, Dafeguards Branch (DBIN:W J Atlanta, Office of the Director 80/07/01 1p
- urwards response to violation mated in II. Insp Repts 32 & 50-319/80 (1) Corrective actions review of test control program & station mpt will lit by periodic test schoduling requirements. Virginia Electric & Power Co. 80/07/02. Spp
- rrwards "IF Bulletin 60-Day Roview." in response to action i Item 4 of IE Dulletin 80-li, "Masonry Wall of available in Contral Files only Virginia Electric & Power (a. 80/07/07 Ep
- numerus response to If Dollatin 80-08, "Exam of Containment ration Walds "Penetration assemblies of flued g design were used for penetrations listed in 2 for North Anna Virginia Electric & Power Co. 80/07/07 7pp
- sounds to IC Bulletin 80-10 re contamination of The Lys Lists sys considered numeral nactive but radioactive through interfaces w/radioactive through strength or monitored Virginia Riectric & Power Co. 89/07/07 2pp
- sponds to items (** 3) of IT Bulletin 79-27. "Loss of Non-strumentation & Control Power Sys Sus During Unit 1 inverter trip was not related to failure ibed in bulletin Virginia Electric & Power Co 80/07/09 Rep

- 8007230447 Forwards response to notice of violation item reported in JE Insp Repts 50-338/80-25 & 50-339/80-26 Infraction is not correct as stated Point-by-point rebuttal provided Insp repts contain no proprietary info SYLVIA.8 R Virginia Electric & Power Co 80/07/18 2pp
- R Periodic operating reports & related correspondence
- 8007220431 Forwards monthly operating repts for June 1980 SYLVIA:B R Virginia Electric & Power Co 80/07/15
- --9007220436 Monthly operating repts for June 1980 HADISON, W. R. Virginia Electric & Power Co. 80 B0/07/09
- S Reportable occurrences, LERs & related correspondence
- BOD7030265 Forwards LER 80-052/03L-0
 CARTHRIGHT, W R Virginia Electric & Power Co 80/06/30
- 8007030270 Folumends LER 80-050/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/06/30 ip
- ~~8007030271 LER 80-050/03L-0 on 800931 during steam generator 1A channel 3 narrow range level transmitter recalibr determined that transmitter had drifted 3A high Caused by normal instrument drift. Transmitter recalibr immediately CARTHRIGHT, # R Virgania Electric & Power Co 60/06/30 2pp
- B007090345 Forwards LER B0-046/03L-0 CARTHRIGHT, N R Virginia Electric & Power Co 80/07/02 ip
- --8007090353 LER 80-046/03L-D on 800612, Mode i level indicator, LI-1474, on A steam generator read 5% higher than other indicators Caused by steam leak on upper transmitter isolation root valve Steam leak treated w/furmanite CARTWRIGHT, W R Virginia Electric & Power Co 80/07/02 2pp.
- 8007210092 Part 21 rept re existence of nonconservative assumption in cold shutdown design basis boron dilution accident analysis in FSAR Caused by use of incorrect sys vol Revieu will be performed to identify & analyse addi accidents EYLVIA.B R Virginia Electric & Power Co 80/07/02 4pp
- 6007070373 Forwards LER 80-094/03L-0 CARTHRIGHT, N R Virginia Electric & Power Co 80/07/03 ip
- --8007070381 LER 80-054/03L-0 on 800603, containment internal air partial pressure exceeded Tech Spac limit Caused by air leakage past containment purge supply valve Valve subsequently verified closed & loak tested CARTURIGHT, NR Virginia Electric & Power Co 80/07/03 2pp
- 8007130686 Forwards tER 80-057/03L-0 CANTHRIGHT: N R Virginia Electric & Power Co 80/07/07 ip
- --8007150701 LER BO-057/09L-O on 800618 during Mode 2 operation, greater than twolve step disagrowment was noted between individual & group position indication for rod G-9 Caused by voltage drift in signal conditioning card CARTHRIGHT, W R Virginia Electric & Power Co 80/07/07 2pp
- BOO7150767 Forwards LFR 80-055/01T-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/07/10 ip
- --8007150777 LER 80-055/01T-0 on 800626, review of FBAR safety analyses for boron dilution accidents determined that nonconservative RCS vols were used for cold shutdown condition Cause undetermined Solution pending further evaluation CARTHRIGHT. W Virginia Electric & Power Co 80/07/10 3pp.
- 8007110300 RD 80-95/017-0 during review of FSAR safety analyses for boron dilution accident potential, ποποσηφεναtism in cold shutdown analysis determined Cause unknown Accident analysis eview initiated Virginia Electric & Power Co B0/07/11
- BOO7220575 Forwards LER BO-058/03L-0 CARTWRIGHT.W R Virginia Electric & Power Co BO/07/16 ip

- ---BO07220580 LER 80-058/03L-0 on 800619, while in Mode 1, post-accident hydrogon analyzer declared inoperable after surveillance testing performed Caused by dihydrogen analyzer T/C bridge failure to energize due to sample line low back pressure CARTHRIGHT, W R Virginia Electric & Power Co 80/07/16 2pp
- 5007220507 Forwards LER 80-054/03L-0 CANTERIOHT.W R Virginia Electric & Power Co 80/07/17 ip
- --\$CO7?"4512 LER 80-056/03L-0 on 800626, after trip caused by false over .com delta T signal, false delta T output discovered in charnol II DELTA T/TAVG protection sys Caused by summing amp card & load/log derivative card Cards replaced CAR[#RIQHF, W R Virginia Electric & Power Co 80/07/17 3pp
- 8007230493 Forwards LER 80-061/01T-0 CARTHRIGH), G R Virginia Electric & Power Co 80/07/17 (p
- #007270838 Forwards LER 80-059/03L-0 CARTMRIGHT, W R Virginia Electric & Power Co 80/07/22 1p

V Operator Examinations

- B007170348 Forwards revised, "Licensed Operator Requalification Program," in response to NRC 800328 request All training instructors are required to participate in program to maintain proficiency SYLVIA, BR Virginia Electric & Power Co 80/07/15 1p

DOCKET 50-339 NORTH ANNA POHER STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 8007240049 Responds to NRC B00718 request for addl info re GA list Air makeup for control room air conditioning sys is provided by vent fans No makeup fan motors erist in sys Diesel generator blig ventilation is provided by normal intake air BAM.E A Virginia Electric & Power Co 80/07/22 ip
- E. NRC Safety Evaluation Report (SER), supply & correspondence
- 8007070200 Responds to SER Suppl 10, Section 15 2 request for commitment re questions on analysis of postulated steam line & feedwater line breaks Westinghouse will provide requested info which is not directly applicable to feelily BYLVIA, B.R. Virginia Electric & Power Co. 80/07/01 1p
- 8007300297 Forwards discussion of util 800711 & 18 responses to deficiencies listed in SER Full-power operation should be authorized upon obtaining FCMA approvable of state & local emergency plans.

 ORIMGS B K Emergency Preparedness Fask Force 80/07/82 Spp
- BOO72B0444 Forwards supplemental info re full power SER Evidence of safety & relief valve capability from tests performed in EPRI/NBAC safety & relief valve test program will be forwarded by B10701
 BYLVIA, BR Virginia Electric & Power Co 80/07/25 2pp
- F. Security, medical, emergency & fire protection plans
- 8007240005 Forwards amended physical security plan. Plan withheld (ref 100FR2 790)

 BYLVIA, B, R Virginia Electric & Power Co 80/06/03 ip
- 8007170601 Forwards revised nuclear security personnel training qualification program & response to NRC 800519 ltr Program & response withheld (ref 10CFR2 790) SYLVIA.B R. Virginia Electric & Power Co 80/07/14 1p

- 8007240092 Forwards security info re 800609 ltr info withheld (ref 100FRR 790) SYLVIA.D R Virginia Electric & Power Cp 80/0//IB lp
- 8007220579 Forwards emergency plan Revision 4 in response to request made during B00715 meeting w/TEMA & State of VA.to support full power license request BAUM.E A Virginia Electric & Power Co 80/07/22 22pp
- --B007220582 Facility emergency plan Revision 4 * Virginia Electric & Power Co 80/07/15)3pp
- B007280156 Forwards emergency preparedness requirements for full power license per review of 800419.0608.20 % 25 submittals Requests schedule for meeting requirements B0/07/22 4pp
- B0072B043Z Forwards revised emergency plan implementing procedures Procedures available in Central Files only BAUM, E.A. Virginia Electric & Power Co. B0/07/22 1p
- B007310193 Requests that ltr.similar to entl draft ltr.bs forwarded to util re entl review of emergency action levels for facility emergency plan PAGANO,F O Emergency Preparedness Licensing Branch 80/07/22
- 8007250383 Forwards Revision 5 to station emergency plan.completing response to BK Grimes 800715 comments
 BAUH.E A Virginia Electric & Power Co. 80/07/24 2pp
- --B0072503B5 Emergency plan Revision 5
 * Virginia Electric & Power Co 80/07/24 2pp
- 8007290388 Advises that 800630 ltr contained error in describing date of most recent exercise of emergency plan Ltr stated that exercise conducted in Oct 1979 Correct history of emergency plan drills contained in 800711 ltr 8VLVIA.B R Virginia Electric & Power Co 80/07/24 ip
- BOO72H0440 Submits schedule for completion of fire protection mods Bmoke detections sys & reactor coplant pump oil collection sys will be completed during BO1101 outage Charging pump cross-connect will be completed during BO2401 outage BYLVIA, D R Virginia Electric & Power Co BO/07/25 ip
- O Adjudicatory correspondence
- 8007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780002 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D 0 Division of Licensing 80/06/25 67pp
- B007110339 Order granting extension until B00723 for Commission to elect whether to review decision taken under 10CFR2 206 on request for enforcement action, DD-B0-23
 HDVLE, J C Office of the Secretary of the Commission 80/07/09
- 8007300412 Advises that affective B00B01, address for coalition will be 1105-C Olive Bt. Greensboro, NC 27401 Related correspondence ALLEN, J North Anna Environmental Coalition B0/07/15 ip
- H General correspondence
- E007150047 Responds to 800327 ltr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants, operating & under const & relative costs of coal vs nuclear energy YOUNOBLOOD, B J. Operating Reactors Branch i 80/05/13 5pp
- 8007180458 Responds to 791203 ltr re licensing new nuclear power plants Licensing of new plants stopped after TM1 until criteria for improved safety could be devoloped Three units have been authorized to begin low level power testing DENTON.H R Office of Nuclear Reactor Regulation, Director 80/03/14 ip
- ---B007180464 Forwards misdirected 791203 ltr re licensing of new nuclear power plants
 RATHKOPF.C Energy, Dept of 80/01/21 App
- 8007070059 Forwards 800620 Director's Derision DD-80-23 denying 800218,22,0425 & 0525 requests for action FR notice encl DENTON-H R Office of Nuclear Reactor Regulation, Director 80/06/20 2pp

- 8007070064 Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ coalition for action DENTON. H R Office of Nuclear Reactor Regulation. Director BO/66/20 25pp
- 8007070069 FR notice of issuance of 800620 Director's Decision DD-80-23 denying 800218,22,28,0425 & 0525 requests by North Anna Environ Coalition for action DENIEN, R Office of Nuclear Reactor Regulation, Director B0/06/20 2pp
- 8007070079 Requests action concerning defective demineralizer design, related corrosion & cracking in steam generators & turbing discs Commends NRC decision to require EIS re experimental replacement of steam generators

 ALLEN.J North Anna Environmental Coalition 80/02/18 App
- NOTO205BB Responds to MB McDonald ltr directed to DDE North Anna full power license issuance will be discussed w/Commission in Jul-Aug 1980 Surry is in shutdown condition due to seismic piping supports mods & will return to power in Aug 1980 YDUNGDLEDD.C J Licensing Branch 1 80/06/25 1p
- 8007020693 Forwards HB McDonald ltr expressing concerns re continued operation of facilities
 BETANCOURT, B Energy, Dept of 80/06/06 2pp
- Insurance & indemnity information
- 07150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE: D. A. Marsh & McLennan. Inc., M & M Nuclear Consultants, Inc. 91v 80/07/10 3pp
- Operating license stage documents & correspondence
- 07090053 Notification of 800627 site visit to perform seismic design margin evaluation of safety-related equipment DROMERICK, A W. Licensing Branch 1 80/06/23 4pp
- 07100140 Discusses 800605 site visit NRC personnel found no visual wall cracks resulting from uneven settlements or shrinkage furing tours of svc bldg, turbine bldg, auxiliary bldg & fuel
- bldg BIAD CHOKSHI, N , RONNEY, N Structural Engineering Branch BO/O6/24 5pp
- J7070203 Forwards request for add1 info re FSAR Info is required to omplete NRC evaluation of QA list info requested by 800702 QUNGBLQQD.B J Licensing Branch 1 80/06/25 7pp
-)7080371 Lists topical repts for which responses to outstanding juestions will be provided to allow SER to proceed & to avoid delays in approval of full power operation includes (ACA-9226, -9230 & -9236 NDERSON, T M Westinghouse Electric Corp. 80/06/25 1p
- 17230001 Forwards statement of policy re requirements to be met for urrent OL applications as derived from NUREG-0660 & found nNREG-0694
 ISENHULD 0 Division of Licensing 80/06/24 2pp
- 17030156 Responds to request for add1 info re revision to Tech Spec 7-4 Low head safety injection sys piping mods on Unit 2 are different from mods on Unit 1 as result of experience ained during reanalysis of Unit 1 tylv18.8 R Virginia Electric & Power Co 80/06/27 3pp.
- 17030151 Forwards summary of response to NUREG-0660 full power & 980 requirements Items which apply to operator training & icensing have been implemented Work is proceeding to amplete items w[81010i implementation dates
 YLVIA, B R Virginia Electric & Power Co 80/06/30 i2pp
- 17070369 Forwards request for info re bypass & reset of engineered afety features Request revised per 800528 discussions /NRC ARFAGNO.8 P Franklin Institute/Franklin Research Center RC-03-79-118 80/06/30 3pp
- 7070201 Forwards response to NRC 800625 request for info re GA list. AUM E A Virginia Electric & Power Co 80/07/02 Sipp

- B007180039 Requests addl info re addition of 15 snubbers Info needed to complete review of FSAR YOUNOBLOOD, B J Licensing Branch 1 80/07/02 4pp
- 8007:70439 Forwards Amend 1 to License NPF-7, safety evaluation & notice of issuance & availability
 DENTON, H R Office of Nuclear Reactor Regulation, Director 80/07/03 3pp
- --B007170443 Amend 1 to License NPF-7, authorizing special low power test program DENTON, H R Office of Nuclear Reactor Regulation, Director 80/07/03 3pp
- --B007170445 Safety evaluation supporting Amend 1 to License NPF-7 * Office of Nuclear Reactor Regulation, Director 80/07/02 40pp
- --8007170449 Notice of issuance & availability of Amend 1 to License NPF-7 YOUNGILOOD,B J Licensing Branch 1 80/07/03 2pp
- 8007100273 Submits add1 info re implementation of short-term Lessons Learned requirements Status of remaining Category A items, mid-yr status of design & installation of Category B mods & schedule for implementation encl Forwards drawings SYLVIA.B R Virginia Electric & Power Co 80/07/07 180pp
- --8007100277 "Sump Pump Discharge Piping Auxiliary Bidg to Containment "
 * Stone & Webster Engineering Curp 79/05/15 ip
- --8007100280 "Sump Pump Discharge Piping Auxiliary Bldg to Containment "
 * Stone & Webster Engineering Corp 77/10/24 ip
- --B007100284 "Flow Diagram Boron Recovery Sys " Sheet i * Stone & Webster Engineering Corp B0/07/07 1p
- --B0071002BE "Flow Diagram Containment Atmosphere Cleanup Bys."

 * Stone & Webster Engineering Corp 77/10/22 lip
- --8007100293 "Flow Diagram Waste Disposal Sys " Sheet 2 * Stone & Webster Engineering Corp 80/07/07 ip
- --B007100278 "Flow Diagram Waste Disposol Sys " Sheet i * Stone & Webster Engineering Corp 80/07/07 ip
- --8007100303 "Ventilation Thermal Recombiner"
 * Stone & Webster Engineering Corp 90/04/07 ip
- --8007100315 "P&ID Liquid Sampling Coolers " Sheet 3 of 5 * NUS Corp 80/05/05 ip
- ---8007100321 "P&ID Liquid Bampling Panel" Sheet 4 of 5 * NUS Corp 80/05/05 ip
- --8007100323 "P&ID Liquid Bempling " 5 of 5 * NVS Corp 80/05/05 ip
- --8007100327 "P&ID Containment & Air Sampling Sys " Sheet 1 of 1 * NUS Corp 80/05/05 1p
- --8007100338 "Process Flow Diagram Liquid Bampling " Sheet 2 of 2 * NUB Corp. 80/05/22 ip
- --8007100347 "Process Flow Diagram Containment Air Sampling "
 * NUS Corp 80/04/14 ip
- --B007100351 "General Arrangement Auxiliary Aldg. Drumming Room Plan, Elevation 274 Ft " Sheet 1 * NUS Corp 80/05/29 1p
- --8007100359 "Oeneral Arrangement Auxiliary Bldg.Drumming Room, Section & Details " Sheet 2 * NUS Corp 80/05/29 1p
- --8007100365 "General Arrangement High Radiation Sampling Sys Waste Tank & Pumps.Plan Elevation 244 Ft.6 Inches & Section " Sheet 1 * NUS Corp 80/05/29. 1p
- BOO7110202 Provides summary of results of control room habitability review in accordance w/NUREO-0694 & in response to NRC BOO702 request Control room meets specs set forth in applicable SRP sections & reg puides BYLVIA.B R Virginia Electric & Power Co BO/07/07 ip

- 8007100159 Notifies that Westinghouse 800516 comments on power Action procedures have been theorporated into procedures
 Action satisfies NUREG-0660, Item I C 7 requirements
 SYLVIA, B R Virginia Electric & Power Co 80/07/08 1p
- 8007110364 Forwards "Steam Generator Water Hammer Demonstration Test," per Tech Spec 8 1 FERGUSON, J H Vi o . Virginia Electric & Power Co - 80/07/09 - App
- ---8007110365 "Steam Generator Water Hammer Demonstration Test "
 * Virginia Electric & Power Co 80/06/24 23pp
- BOO7i10359 Forwards response to NRC BOO3iO request for info re auxiliary feedwater sys design basis info & pump flow verification, for Unit 2 Unit 1 info will follow shortly BYLVIA.B R Virginia Electric & Power Co 80/07/10 15pp
- B007110361 Forwards descriptive info for Action Item II B 1 requested by NRC for full-power licensing review Response to NRC B00701 request for addl info re RCS vents will be provided as soon as possible BYLVIA.B R Virginia Electric & Power Co 80/07/10 8pp
- 8007140158 Forwards addl info requested in NRC 800618 ltr re use of safety-grade equipment to achieve cold shutdown SYLVIA.B R Virginia Electric & Power Co 80/07/10 16pp
- 8007140187 Lists addl TMI-related requirements which will be completed by 810101.in response to NRC request SYLVIA.B R Virginia Electric & Power Co 80/07/10 2pp
- 8007140393 Application to amend License NPF-7 consisting of changes to Tech Spec setpoints & allowable values
 FERGUSON.J H. Virginia Electric & Power Co. 80/07/11 3pp
- --B007140400 Revised Tech Specs Table 2 2-1 for reactor trip sys instrumentation trip setpoints & Table 3 3-4 for engineered safety feature actuation sys instrumentation trip setpoints * Virginia Electric & Power Co B0/07/11 App
- 8007140406 Responds to NRC 791214 ltr & forwards, "Summary of Unit 2 Motor Driven Auxiliary Feedwater Pump Endurance Test " SYLVIA.B R Virginia Electric & Power Co 80/07/11 1p
- --8007140411 "Bummary of Unit 2 Motor Driven Auxiliary Feedwater Endurance Tests "

 * Virginia Electric & Power Co 80/07/11 9pp
- 8007150869 Notifies that util is using dual sys of notification for site & general emergencies in cooperation w/local counties at insistence of VA State Ofc of Emergency & Energy Sycs Tentative implementation schedule for NUREG-0684 encl BAUM. E. A. Virginia Electric & Power Co. 80/07/11 20pp
- B007160507 Bubmits addl info requested by NRC re util 800618 request for amend of Tech Specs to include addl safety-related snubbers Design & const of safety injection sys where snubbers added is discussed One oversize drawing encl BYLVIA, B R Virginia Electric & Power Co 80/07/11 34pp
- 8007160671 Responds to NRC request for add1 info re residual heat removal sys Addresses use of pressurizer power-operated relief valve for pressure reduction of RCS & advises of blown rupture discs Precaution will be added BYLVIA,R R Virginia Electric & Pawer Co 80/07/14 2pp
- 8007170175 Forwards Operating Procedures 2-0P-12 1 & 2-0P-12 2 re interim post-accident sampling in response to NUREO-0660 Action Plan Item II B 3 SYLVIA:BR Virginia Electric & Power Co 80/07/14 2pp Virginia Electric & Power Co 80/07/14
- --8007170183 Operating Procedure 2-0P-12 1.Revision 1. "Sampling Sys " HARVEY,S L Virginia Electric & Power Co 80/07/11. 30pp
- --B007170189 Operating Procedure 2-DP-12 2, "Post-Accident Containment Atmospheric Sampling Sys " HARVEY, S.L. Virginia Electric & Power Co. 80/07/11 5pp
- 8007220487 Forwards proprietary version of App A info re turbine disc matls properties, per NRC request Westinghouse application for withholding encl Turbine disc info withhold (ref SYLVIA, B R Virginia Electric & Power Co 80/07/15 9pp

- 8007210244 Forwards revised Table 2-1 of 800710 response to NRC requestor info re auxiliary feedwater sys requirements Info available in Section 15.4.2.2 of FSAR does not include Westinghouse analysis of limited feedwater break
 BYLVIA.B R Virginia Electric & Power (o. 80707/16.17pp
- 8007280006 Notification of 800723 meeting w/otils in Bethosda,MD to discuss matters re TMI-2 dated requirements DROMERICK,A W. Licensing Branch 1 80707716 App
- 8007308099 Summary of 800630 site visit to observe appeal low power test program ANDERSON N R - Procedures & lest Heview Branch - 80/07/16 - 7pp
- 8007210377 Provides preliminary summary of special tests intended to characterize plant parameters during natural circulation conditions info will improve apprator training program & upgrade simulator facility Test rept to be forwarded SYLVIA: Il R Virginia Electric & Power Co 80/07/17 3pp
- 800721034/ Responds to NRC 800701 request for add1 info re full power licensing approval Detailed info & drawings in RCS vents SYLVIA.B R Virginia Electric & Power Co. 80/07/17
- B007220384 Forwards add1 info to util 800714 itr re RHR sys Simulation of use of pressurizer power-operated relief valve to depressurize RCS performed satisfactorily on 800717 k demonstrates alternate method of sys condition SYLVIA, B R Virginia Electric & Fower Co 80/07/16 2pp
- 8007310421 Comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports "Requests extension of review period to 800915 to review stress corrosion cracking BROWN S C Virginia Electric & Power Co 80/07/21 2pp
- 8007240115 Forwards suggested forh Sper changes for administrative controls, established as program to identify, secord & rept failures of or challonges to power operated relief valves program outlined in util 8006/80 response to NNEG-0660 SYLVIA.B R Virginia Electric & Power Co HO/07/22 ip
- --8007240116 Suggested Tech Spec changes for administrative controls * Virginia Electric & Power Co 80/04/11 Spp
- --8007240156 "10x8x10 Number 5350-1DDA6A Sories 1500. Welding Ends Outside Screw & Yoke Oato Valve W/Lip Seal & SMD-2-60 Limitorque Valve Control" * Darling Valvo & Mfg //2/05/05 Lp
- --8007240159 "10x8x10 Number 5.390-IDDASA Sories 1500. Holding Ends Outside Screw & York Oate Valve W/Lip Seal & EMB-2-60 Limitorque Valve Control "
 * Darling Valve & Mfg /2/02/23 Lp
- --8007240161 "300 1b Cast Alloy Steel Motor Operated Gate Valve W/Outsid Screw & Yoke Sphit Wodge Disc & Dunnet Joint for Seal Welding-General Assembly & Dimensions " * Stone & Webster, Inc. * Crane Co. 11715 72703702 1p
- ---8007240136 "Safety Injection Bys Seismic Mathematical Model " * Stone & Webster Engineering Corp. 78/12/94 Ip
- 8007230415 Requests time extension to replace Barton Transmitters to third refueling outage of Unit 1.Lot 1 Replacement of Unit w/refueling consistent w/current transmitter availability as previously discussed SYLVIA.8 R Virginia Electric & Power Co. 80/07/20 2pp
- 8007280395 Forwards "Natural Circulation Tent Rapt," conducted 800703-16, which completes requirements for NURFG-0660, Itam BYLVIA:B R Virginia Cleatric & Power Co. 80/07/PD
- --8007280400 "Natural Circulation Test Rept." conducted 800703-16 KANN.G A Virginia Electric N Power Co 80/07/87 30pp
- 8007250379 Informs of completion of full power requirements of SFR. Baction 10-2 % TMI action plan.NiRt(4-0560. Items II B 4 All licensed operators received training for degraded core conditions BYLVIA:B R Virginia Electric & Power (o 80/07/24 ip

- 8007290430 Submits listing of two groups of items yet to be resolved based on review of Class IE electrical equipment qualification using NUKEO-0988 guidance Marked-up R Tedesco 780228 memo te facility equipment qualification encl SYLVIA.B R Virginia Electric & Power Co 80/07/P4 13pp
- B007280367 Forwards nonproprietary version of Westinghouse low pressure turbine disc info Suppls proprietary info transmitted by licensee B00715 ltr SYLVIA.B R Virginia Electric & Power Co B0/07/25 21pp
- 8007280406 Forwards current installation schedule for NUREG-0660 itoms identified in NUREG-0694 Discussion of items that may be delayed beyond 910101 encl
 SYLVIA: B R Virginia Electric & Power Co 80/07/25 7pp
- BOO72B0423 forwards add1 info requested re periodic leak testing of pressure isolation valves SYLVIA.B R Virginia Electric & Power Ca BO/07/25 2pp
- 8007280651 Provides summary of results of Phase I of multiple structure advance record sys evaluation of piping sys design Final detailed rept will be submitted upon completion of Phase II effort Category listing attached SYLVIA, I R Virginia Electric & Power Co BO/07/25 3pp
- B007290700 Summerizes results of Phase I of multiple structure amplified response spectra evaluation of North Anna 1 piping sys design as described in 800606 ltr Final detailed rept will be submitted upon completion of Phase II offort SYLVIA, B 8 Virginia Electric & Power Co 80/07/25 3pp
- 8007300498 Submits list of add) design data re low head safety injection jump discharge piping stress problem in response to NRC request Jufo will be forwarded by 800730 SYLVIA.B R Virginia Electric & Power Co 80/07/25 2pp
- B007300183 Requests that facility be granted Full-power license w/o final verification of remaining MUREG-0588 items Items will perform intended functions under accident conditions pending completion of ongoing qualification review BYLVIA.B R Virginia Electric & Power Co 80/07/28 2pp
- BOO7300450 Notifies that of 48 items identified in response to NUREG-OBBB.most fall into categories which are used in safeguards sys & 90% of items are located outside containment BYLVIA.B R Virginia Electric & Power Co
- 8007310346 Forwards info in response to NRC questions re applicable codes & Fracture toughness requirements for ferritic steel parts of containment pressure boundary not supported by concrete holds info re carbon steel plates will be forwarded SYLVIA B R Virginia Electric & Power Co 80/07/39 65pp
- 8007310384 Forwards info supplementing 800722 design data for low head safety injection pump discharge piping analysis info includes model of sys showing may temp conditions within pipe & selsmic displacements for each support point SYLVIA:B R Virginia Electric & Power Co 80/07/30 2App
- @ Inspection reports. IE Bulletins & correspondence
- 8007240230 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Gapability at Pavis-Besse Unit 1 While in Refueling Mode " No response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007020200 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/28 ip
- B007210477 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Furl Assemblies" No written response required O'MEILLY.J P Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007010239 Forwards IF Info Notice 80-23, "Loss of Suction to Emergency Faedwater Pumps" No written response required O'REILLY. J P Region 2, Atlanta. Office of the Director 80/05/29 1p
- B007160732 Forwards IE Insp Repts 50-338/80-23 & 50-339/80-23 on B00912-15 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/05 2pg

- --B007160742 IE Insp Repts 50-338/80-23 & 50-339/80-23 on B00512-15 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys & licensee actions on licensee identified items COMPTON,R M Region 2, Atlanta, Office of the Director HERDI.AR Rogion 2, Atlanta, Reactor Construction & Engineering Support Branch B0/06/04 5pp
- B007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/16
- BO07160307 Forwards 1E Info Notico 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/11
- B007070037 Forwards revision to Page 2 of 800611 response to IE Bulletin B0-12. "Decay Heat Removal Sys Operability " SYLVIA.B R Virginia Electric & Power Co 80/06/16 2pp
- 8007020797 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENB) W/Loss of Offsite Power" Hritten response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/18
- 8007020434 Forwards IE Circular 80-15, "Lose of Reactor Coplant Fump Cooling & Natural Circulation Cooldown" No written response required U'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- BO07170119 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/24 to
- B007010413 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Const work complete on Unit 2 Estimated completion date for Unit 1 is B00831 BROWN, B C Virginia Electric & Power Co B0/06/27 Spp
- 8007230270 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosempunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Writton response required IE Circular 80-16 also encl No writton response required C'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- BOO7160745 Forwards IE lnsp Ropts 50-338/80-24 & 50-339/80-24 on BOO611-12 No noncompliance noted Details withheld traf 100FR2 790)
 KENNA, W B Regian 2, Atlanta, Safeguards Branch BO/07/01 ip
- --8007160761 IE Insp Repts 30-338/80-24 & 50-339/80-24 on 800611-12 No noncompliance noted Major areas inspected vital area harriers searches & vital area access Details withheld (ref 10CFR2 790)
 OILLEPIE, F P Region 2, Atlanta, Safeguards Branch TOBIN, W J Region 2, Atlanta, Office of the Director 80/07/01 ip
- 8007070283 Forwards response to violation noted in IE Insp Repts 50-338/80-22 & 50-339/80-13 Corrective actions review conducted of test control program & station mpt will distribute ltr re periodic test scheduling requirements SYLVIA.B R Virgania Electric & Power Co 80/07/02 2pp
- 8007170334 Forwards repts submitted in reponse to action required by Item 4 of IE Bulletin BO-11. "Masonry Wall Design " Repts prepared in compliance w/Bulletin requirement for submittal of 60-day rept SYLVIA.B R Virginia Electric & Power Co 80/07/07 201pp
- 8007250545 Forwards response to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds " Penetration assemblies of flued head forging design were used for penetrations listed in Tables 1 & 2 for North Anna BYLVIA.B R Virginia Electric & Power Co 80/07/07 7pp
- 8007290840 Responds to IE Bulletin 80-10 re contamination of nonradioactive sys Lists sys considered nonradioactive but potentially radioactive through interfaces w/radioactive sys All discharge paths are sampled or monitored BYLVIA: B R Virginia Electric & Power Co 80/07/07 2pp

- 8007150671 Responds to 800630 teleph re commitments made in response to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Submits info re protection sys design conformance w/Items 1,2 & 3 criteria SYLVIA,B R Virginia Electric & Power Co 80/07/11 5pp
- 8007230447 Forwards response to notice of violation item reported in IE Insp Repts 50-338/80-25 & 50-339/80-26 Infraction is not correct as stated Point-by-point rebuttal provided Insp repts contain no proprietary info BYLVIA, B R Virginia Electric & Power Co 80/07/18 2pp
- R Periodic operating reports & related correspondence
- BOO7220431 Forwards monthly operating rapts for June 1980 BYLVIA: B R Virginia Electric & Power Co BO/07/15 la
- 8 Reportable occurrences. LERs & related correspondence
- 8007010333 Forwards LER 80-021/03L-0 CARTHRIGHT,W R Virginia Electric & Power Co 80/06/24 ip
- --8007010375 LER 80-021/03L-0. on 800504, during Mode 3 operation, leaking valve on radiation monitor RMS-257 resulted in low flow to munitor Caused by routine failure of valve bonnet New valve bonnet installed.

 CARTWRIGHT.W R Virginia Electric & Power Cb 80/06/24 2pp
- 8007010398 Forwards LER 80-028/997-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/06/26 ip
- ---B007010415 LER 80-028/99T-0 on 800624, during beginning of core life, hot zero moderator temp coefficient found more positive than required Caused by positive moderator temp coefficient discovered during startup physics testing * Virginia Electric & Power Co 80/06/26 3pp
- B007110420 RD-80-027/01T-0.on 800627.pressurizer power operated relief Valve PCV-2456 inadvertently opened in Mode 3 following valve maint activities. Corrective action will be taken pending completion of investigation virginia Electric & Power Co 80/06/27 ip
- B007030262 Forwards LER B0-024/01T-0 GARTHRIGHT, W R Virginia Electric & Power Co B0/06/30 ip
- ---8007030267 LER 80-024/01T-0 on 800619, during low power physics testing in Mode 2, discovered that main feedwater flow transmitters FT-476,477,487,494 & 497 were isolated Cause could not be determined. Transmitters valved in & returned to svc # Virginia Electric & Power Co 80/06/30 3pp.
- BO07030273 Forward* LER BO-017/03L-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/06/30 ip
- ---B007030275 LER 80-017/03L-0 on B00601.inner containment hatch door leaked air past seals during test performance Caused by dirty seals Seals cleaned & air lock tested satisfactorily CARTMRIGHT.H R Virginia Electric & Power Co B0/06/30 2pp
- BOO7030281 Forwards LER 80-019/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co BO/06/30 ip
- ---BOO7030283 LER BO-019/03L-0 on 800602, radiation monitoring channel RM-RMB-259 was valved out as inoperable due to insufficient flow Caused by pump failure Pump removed, rebuilt & returned to svc. CARTWRIGHT,W R Virginia Electric & Power Co 80/06/30 2pp
- B007030285 Forwards LER 80-018/03L-0 CARTHRIGHT,W R Virginia Electric & Power Co 80/07/01 1p
- ---B0070302BB LER B0-01B/03L-0 on B00402, loss of C reserve station svc transformer occurred rendering C normal station ave & 20 intake structure buses inoperable Caused by open breakers Emergency buses energized & breakers closed CARTHRIGHT.W R Virginia Electric & Power Co. B0/07/01 Rpp

- 8007140585 Part 21 rept re containment electrical penetrations fault current protection devices Devices would not limit current to values below thermal limit Devices were changed or adjusted to protect penetrations
 HILD.P A Stone & Webster, Inc. 80/07/01 4pp
- 8007:40601 Part 21 rept re Colt Industries diese) generator battery racks which do not meet seismic design criterion Inadequate components replaced to meet design critorion HILD:P A Stone & Webstor, Inc. 80/07/01 4pp
- 8007070358 Forwards LER 80-016/03L-0 CARIMRIGHT.W R Virginia Electric & Power Co 80/07/02 1p
- --B007070363 LER B0-016/03L-0 on 800607, during hot standby, steam supply to steam driven auxiliary (eedwater pump was inclated Caused by attempt to repair cap to body leak on mainsteam check valve Valve repaired & steam supply to pump restored CARTWRIOHT, W R Virginia Electric & Power Co H0/07/02 2pp
- BO07070374 Forwards LER BO-029/01T-0 CARTWRIGHT, W R Virginia Electric & Power Co 80/07/02 1p
- --B007070379 LER 60-029/01T-0 on B00624, during Mode 3 operation, power operated relief valve PCV-2456 opened inadvertently & failed to reclose Caused by rucked bearing in valve actuator Upstream MOV-2535 closed to torminate relief flow CARTWRIGHT.W R Virginia Electric & Power Co B0/07/02 2pp
- B00/090296 Forwards LER B0-027/03L-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/07/02 ip
- --8007090304 LER 80-027/0JL-0 on 800620, w/unit at startup condition, one main steam flow transmitter found inoperable Caused by loose connection, resulting from stripped screw Borew replaced, connection tightened & transmitter callbr CARTHRIGHT, W R Virginia Electric & Power Co 80/07/02 ip
- 8007090308 Forwards LER 80-0P2/03L-0 CARTWRIGHT-W R Virginia Electric & Power Co 80/07/02 1p
- ~-B007090312 LER HO-()22/03L-0 on B00609, w/plant in Mode 3, containment sump flow indicator, FTO-UA-215, stopped measuring flow correctly Caused by cingged strainer located within instrument, preventing proper rotation of flow sensor CARTWRIGHT, W R Virginia Electric & Power Co B0/07/02 2pp
- 8007090317 Forwards tER 80-026/031-0 CARTWHIGHT,W R Virginia Electric & Power Co 80/07/02 ip
- --B007090.23 iER 80-026/03L-0 on 8006P0.w/reactor in Mode 2 & as part 5 2-80-31.channel F-497 was observed to require adjustment in order to lower feedwater flow indication Caused by zero shift in multiplier-divider card of feedwater channel F-497 CARTHRIGHT, W.R. Virginia Electric & Power Co. 80/07/02 2pp
- 8007070335 Forwards LER 80-014/031-0 CARTHRIGHT.W R Virginia Electric & Power Co 80/07/02 In
- 8007210072 Part 21 rept re existence of nonconservative assumption in cold shutdown design basis boron dilution accident analysis in FBAR Caused by use of incorrect sys vol Roview will be performed to identify a mallyre add accidents

 BYLVIA.B R Virginia Electric & Power Co 80/07/02 App
- 8007140209 Forwards LER 80-030/03L+0 CARTWRIGHT.W R Virginia Electric & Power Co 80/07/07 1p
- -8007140225 LER BO-030/03L O on 800524-25 on three occasions rod position indication disagreed more than 12 steps between individual position & demand position Caused by instrument drift for each event, sys realigned & returned to svc CARTHRIGHT.W R Virginia Electric & Power Co 80/07/07 2pp /
- 8007180808 Forwards LER 80-023/03L-0 CARTHRIGHT, W R Virginia Electric & Power Co 80/07/07 ip
- ---B007150815 LFR 80-023/03L 0 on B00410.A LCCS subsys was rendered inoperable by isolation of A LHGI pump Chused by need to repair leaking water fitting Scal water fittings reinstalled to pump returned to svc CARTWRIGHT.W R Virginia Electric & Power Ca 80/07/07 2pp

- 8007150810 Forwards LER 80-031/01T-0 CARTHRIGHT W.R. Virginia Electric & Power Co. 80/07/07 1p
- --8007150817 LEP 80-031/017-0 on 800626, uhils performing channel calibrs on pressurtize press protection channels, Channels 1, 2 & 3 eaund to indicate values below actual RCP pressure Caused by gressure set of bourdon tube within transmitters CARTMRIGHT.W R Virginia Electric & Power Co 80/07/07 3pp
- 8007110300 RO 80-55/DIT-O during review of FSAR safety analyses for boron dilution accident potential nonconservation in cold shutdown analysis determined Cause unknown Accident analysis review initiated

 4 Virginia Electric & Power Co. 8D/07/11 1p
- 8007220601 Forwards LER 80-012/03L-0 CARTHRIGHT, H R Virginia Electric & Power Co 80/07/17 lp
- --8007220611 LER 80-012/03L-0 on 800418 while in Mode 2.control rod demand position indication noted 19 steps higher than associated rod position indication Caused by drift of rod position indicator channel Channel recalibr CARTWRIGHT.W R Virginia Electric & Power Co 80/07/17 App
- V Operator Examinations
- BD07170348 Forwards revised, "Licensed Operator Requalification Program," in response to NRC 800328 request All training instructors are required to participate in program to maintain proficiency BYLVIA.8 R Virginia Electric & Power Co 80/07/15 ip
- --8007170350 Revised, "Licensed Operator Requalification Program "

 Virginia Electric & Power Co 80/07/31 lipp
- 8007250379 Informs of completion of full power requirements of SER, Section 10-2 & TMI action plan, NUREC-0660, Items II B 4
 All licensed operators received training for degraded core conditions
 SYLVIA.B R Virginia Electric & Power Co 80/07/24 Ip

DOCKET 50-340 SEABROOK NUCLEAR STATION, UNIT 1

- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 0 Division of Licensing 80/06/23 E9pp
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT. UNIT 2

 A Application/construction stage documents & correspondence
- 8007030239 Notification of 800702 meeting w/BWR licensing review group in Betheada, MD to discuss consensus position on reactor svc bldg open issue WILSON, J N Licensing Branch 1 80/06/18 9pp
- BD07010297 Supmary of B00613 meeting w/utils.KMC, Inc. GE. Bechtel. B&W & Sargent & Lundy in Bethesda. MD re consensus positions on reactor suc bldg & isolation cooling sus bldg open issues from La Salle decket Status repts ent!
 HILSON. J. N. Assistant Director for Licensing 80/06/19 44pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0640 & found in NUREG-0694 EISENHUT, D Q Division of Licensing 80/06/26 2pp
- 8007170339 Notification of rescheduling of 800702 meeting w/8WR licensing review group in Bethexda, MD to discuss consensus positions on Reactor Sys Branch open issues Meeting rescheduled for 800709 WILSON, J N Assistant Director for Licensing 80/07/03 ip
- ~-8007170347 Notification of 800722 meeting w/BHP licensing review group in Bethesda.MD to discuse TMI issues required for QL issuance
 WILSON.J N Assistant Director for Licensing 80/07/03, lp
- --8007170351 Notification of 800724 meeting w/DWR licensing review group in Bethesda. MD to introduce BWR licensing review group to present consensus positions for Power Bys Branch, Containment Bys Branch & Equipment Qualification Brack to Holling and Assistant Director for Licensing 80/07/03 9pp

- GOO7160607 Forwards FOAR fraction 5 2 10%s COLDERT, N F Petroit Edison (o 60/07/08 ip
- --B007168674 Ruspands to //ioi7 ltr to Procture toughness requirements.
 Tests on matts of reactor coolant pressure boundary comply
 w/App O Ambiguity re calibriquelification & record retention
 functions will be clarified
 MINDOUE.R B Office of Standards Development, Director 78/02/14
- ---8007140/03 Submits interpretation of 1001H30.App O Fracture toughness requirements Requests NRC concurrence that functions are in conformance w/intent of regulation SHERWOOD.G G General Plactric Co ///10/1/ Spp
- --8007160709 Revision 3 to nurveillance test program for 25t-inch BMR vecet e General Electric Co - 70/02/28 - 30pp
- G007230133 Notification of B00725 meeting w/BMR Licenting Review Group in Bethoods, MD to discuss concensus positions of BMR Licenting Review Group on ICBB open issues WILBON, J N Licenting Branch 1 80/07/16 10pp
- O Volunticators contembuugance
- 8007010243 Forwards Commission 100037 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 7/1104 petition sought action refere to the trotaction for electrical cobles EINEMOUT, D.O. Division of Licensing 80/06/25 879p
- B007100043 Joint notice of CP Woodbead appearance & Rt Black withdrawal from proceeding Curtificate of But enc.)
 40000E40.C P Hearing Branch 3 BLACK.R t Hearing Dranch 1,
 80/07/03 2pp
- H General correspondence
- 8007080183 Requests consideration of having Atomic finergy Council of Taiwan visit facility on 800882:-P Council interested in observing waste mpt activities Cooperation will be major contribution to NRC exchange arrangement LAFLER, J D Assistant Director for International Cooperation 80/09/13 Spp
- 8007270085 Responds to 800.028 ltr from Lawson, NO school students to President Cartor re adequacy of qualifications of personnel designing plant Cartain design activities failed to mest NRC requirements (Hil corrective actions under review DIRCKB, H J Office of the Executive Director for Operations 80/08/20 10
- P Operating license stage documents & correspondence
- B007230020 Bummary of 600207 meeting w/Mark I owners group in Bethesda, MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMED.C T Plant Bystems Branch B0/02/21 Jipp
- G Inspection reports. If Bulletins & correspondence
- 8007140510 Forwards IE Bullstin HO-13, "Cracking in Core Baray Spargers" No written response required REPPLER, J.O. Region 3: Chicago, Office of the Director BO/05/12 to
- 8007140557 Forwards II Bullstin 80-13, "Cracking in Core Opray
 Spargers " No written response required
 REPPLER, J O Region 3, Chicago, Office of the Director 80/07/12
- BOO7010107 Forwards IR Info Notice 80-23, "Loss of Buction to Emergency Feedwater Pumps" No written response required, REPPLER, J G. Region 3, Chicago, Office of the Director 80/05/29, ip
- 8007020081 Ack receipt of 800513 ltr informing NRC of steps taken to correct violation noted in IE Insp Rupt 50-341/80-02 FIDRELLI, D Region 3, Chicago, Reactor Construction & Engineering Support Branch 80704/09 lp
- BOO7820198 Forwards IE Info Notice 80-26. "Evaluation of Contractor DA Programs" No written response required.

 KEPPLER.J G Region 3: Chirago, Office of the Director 80/06/10

- B00714035B Forwards IE Bulletin 80~14. "Degradation of BWR Scram Discharge Vol Capability " No written response required MEPPLER.J Q Region 3. Chicago. Défice of the Director 80/06/12
- B007280644 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/13 1p
- 8007230059 Forwards IE Insp Rept 50-341/80-06 on 800430,0501,02 & 28-30 No noncompliance noted FIORELLI,0 Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/17 2pp
- -8007230066 IE Insp Ropt 50-341/80-06 on 800430.0501.02 & 28-30 No noncompliance noted Major areas inspected action on previous insp findings.organization & design change control KNOP.R C . BARRETT.P A Region 3. Chicago, Office of the Director 80/06/16
- 8007020559 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required MEPPLER.J G Region 3, Chicago, Office of the Director 80/06/20
- MEPPLER. J O Ragion 3. Chicago. Office of the Director 80/06/20
- 8007170486 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Personnal" No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/24 ip
- BOO7140470 Ack receipt of BOO607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-341/79-25 FIDRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch. BO/06/25 ip
- --80071404Bi Responds to NRC 800324 ltr re violations noted in IE Insp Rept 50-341/79-25 Corrective actions controlling procedure to notify GC personnel of needed pipe weld repair has been revised ... HINES,E Detroit Edison Co 80/06/09 Spp
- 8007230323 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER. J Q Region 3, Chicago, Office of the Director 80/06/27 is
- 8007140425 Forwards "Summary Rept Number EF2-49.457 of Response to IE Sulletin 80-08," in response to IE Bulletin 80-08. "Exam of Containment Liner Penetration Welds "
 HINES, E Datroit Edison Co 80/07/07 9pp
- 8 Reportable occurrences. LERs & related correspondence
- 8007070095 Ack receipt of 800605 ltr re final deficiency rept on Agastat relay base problem FIORELLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/17 1p
- --8007070098 Interim deficiency rept re Agastat relay base problem Subsequent investigation revealed that relay base is also used in five addl GE panels final rept will be forwarded by 600806 FARNNER, W. J. Detroit Edison Co. 80/06/05 ip
- B00717049B Ack receipt of B00613 final deficiency rept re defective Westinghouse switches Final rept encl FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/07/01 ip
- 8007210128 Ack receipt of 800512 interim deficiency rept re nonseismic equipment installed over seismic FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/01 ip
- ---8007210136 Interim deficiency rept re nonseismic equipment installed over seismic Affected equipment includes pieces of heating, ventilation & air conditioning ducts in reactor & auxiliary bldgs Final rept to be submitted by 800915
 FAHRNER, W. J. Detroit Edison Co. 80/06/12 ip
- B007i40326 Final deficiency rept re damaged penetration assemblies at facility Problem assembly engineering evaluation completed & changes made to penetration X-17 Bellows life not to be reduced below design specs Bellows have been leak tested FAHRNER, W J Detroit Edison Co 80/07/02 ip

- 8007170406 Final deficiency rept re problems w/terminations to receptacies in main control roum Panels 601,602 & 603 GE investigation complete Problems caused by improper crimping Pull-tests will be performed to assure satisfactory crimps FAHRNER.W J Detroit Edison Co 80/07/03 2pp
- B00721000B Ack receipt of B00610 final deficiency rept re seismic Category I instrumentation & control testing FIDRELL1.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/07/03 1p
- 8007220545 Interim deficiency rept re notification by Comsip of pump malfunction on similar containment gas monitoring sys Caused by deadheading, resulting in excessive pressure Vendor has agreed to provide kit for adding by-pass FAHRNER, H J Detroit Edison Co 80/07/10 1p
- DOCKET 50-344 TROJAN NUCLEAR PLANT, PORTLAND GENERAL ELECTRIC

 F Security, medical, emergency & fire protection plans
- 8007180196 Forwards NRC 800425 itr to all power reactor licensess in response to 800529 ltr re emergency response facilities at reactor sites Sites w/approval to use closed-circuit television link w/technical support ctr listed CRUTCHFIELD.D M Operating Reactors Branch 5 80/07/07 2pp
- 8007010334 Forwards comments on proposed rule iOCFR50 re fire protection program for nuclear plants Proposed rule is far too vague for effective implamentation, lacking definitions in particular Rule 1s subj to individual interpretation ODDDNIN.C Portland General Electric Co 80/06/27 10pp
- 8007090300 Forwards draft App 1-B, "Description of Public Notification Bys for Trojon Nuclear Plant," For radiological emergency plan procedures manual Review of adequacy of sirens in systequested Draft & drawings available in Central Files only GOODWIN,C Portland General Electric Co 80/07/01 2pp
- 8007140529 Notification of 800728 meeting w/util in Prescott, OR to discuss results of NRC emergency proparedness review team analysis of util 800516 draft radiological emergency response plan & to conduct site tour TRAMMELL, C M Operating Reactors Branch 3 80/07/07 2pp
- **Q** Adjudicatory correspondence
- 8007100051 Discusses licensee B00519 rept re inadequately connected wall & forwards DJ Broehl & WH Whito affidavits in response to B00602 order issued in control bldg proceeding JDHNBBN.R W Partland General Electric Co B0706/i6 2pp
- --8007100058 Affidavit re LER 60-007/01T-0, describing cause of auxiliary bldg wall inadequate connection & extent of deficiencies at top-of-wall interfaces Identifies manner & schedule of corrective action Description of deficiency encl BROEHL, B J Portland General Electric Co 80/06/16 7pp
- --B007100062 Affidavit describing limited significance of auxiliary bldg wall connection deficiency as related to structural adequacy of complex before & after completion of corrective actions Cartificate of Svc encl Related correspondence WHITE.W H Bechtel Power Corp (subs of Bechtel Corp) WHITE.W H Purtland General Electric Co B0/06/14 7pp
- 8007310243 Forwards Commission B0052/ memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & proor UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing B0/06/29 B9pp
- 8007020594 Affidavit in response to IE Info Notice 80-21 re control bldg proceeding Licensee will conduct systematic insp program for safety-related electrical equipment supports & anchorages, within 12 months
 BROEHLID J Portland General Electric Co 80/06/27 App
- 8007100039 Forwards licensee 800628 ltr to Region 5 documenting resolution of wall problem re-control bldg proceeding Util program will constitute full compliance w/Region 5 800417 ltr re-action requirement Celtificate of Syc end JOHNSON, R W. Portland General Electric Co. 80/06/30 App
- 8007300333 Forwards list of requests for design changes re mod program in "Rept on Dosign Mods for Control Bldg." PGE-1020 ASLB will be informed of activities per 790330 prehearing conference Certificate of Svc entl Related correspondence MCCARREL.9 F Portland General Electric Co 80/07/03 4pp

Į

- 8007300357 Notice of appearance & substitution of counsel in proposed amend for storage pool mod proceeding Certificate of Svc encl
 - DSTRANDER.F # Gregon, State of 80/07/03 2pp
- B007100029 Forwards R Clark B00703 itr to util transmitting IE Bulletin B0-ii & seeking util response to Items 2 b & 3 re masonry wall design problem Action requirements are no different from actions stated in control bidg proceeding record GRAY.J R Hearing Branch 1 80/07/07 2pp
- --8007100034 Transmits IE Sulletin 80-11, requesting response to Items 2 b & 3 re design criteria for walls & lung-turm confirmatory test program w/associated completion schedule Suggests specific items for test program CLARK, R A Licensing Branch 3 80/07/03 3pp
- 8007290789 Initial decision modifying OL immediately Exceptions may be filed within 10 days, briefs within 30 days & supporting or objecting briefs within 30 days of original briefs Decision shall constitute final action within 45 days MCCOLLON, K A, PAYTON, H C, MILLER, M E Atomic Safety and Licensing Board Panel 80/07/11 BOpp
- 8007280503 Forwards State of OR Dept of Energy rept re util issues related to Mount St Helens Based on rept. Energy Facility Siting Council denied petitions to revoke site certificate DIXON.B Oregon, State of BO/07/14 18pp
- 9007250428 Forwards NRC motions for extension of time to file exceptions to ASLB 800711 initial decision & other related requests NRC will issue isones amend per ASLB order issued w/initial decision due to desire to restore seismic margins ORAY, J R Hearing Branch 1 80/07/23 2pp
- ~-8007250403 Notion for 10-day extension to file exceptions to ASLB 800711 initial decision authorizing control bldg mods.NRC position re taking exceptions is dependent upon ASLB action on enci motion for clarification Cortificate of Syc encl. GRAY.J R Hearing Branch 1 80/07/23 4pp
- --B007290437 Motion for clarification of ABLB B007(1 initial decision authorizing mods of control bldg Requests ABLB intent reCondition 2 C 11 concerning restoration of originally intended design margins Certificate of Svc encl
 ORAY, J R Hearing Branch 1 80/07/23 7pp
- 3007300481 Forwards motion for reconsideration of initial decision, mamorandum of points & authorities in support of motion for reconsideration & proposed findings of fact & conclusions of law re design mods for control bidg OBTRANDER, F.W. Dregon, State of 80/07/23 ip
- -8007300490 Motion for reconsideration of ASLR BOO711 initial decision Decision does not provide ASLB findings, conclusions & rulings on math issues in State of DR BO0519 proposed findings of fact & conclusions of law OSTRANDER, F W Oregon, State of BO/07/23 1p
- -8007300494 Memorandum of points & authorities in support of motion for reconsideration of initial decision Decision does not discuss issues raised in State of OR proposed findings of fact & conclusions of law Certificate of Svc encl OSTRANDER.F W Oregon, State of 80/07/23 4pp
- 8007300500 Proposed findings of fact & conclusions of law re design mods for control bldg If ASLB will include proposed suppls & additions in initial decision, appeal and will concur in licensee proposed findings & conclusions OBTRANDER.F W Oregon, State of 80/07/23 5pp
- 8007300506 Memorandum of points & authorities in support of Statu of OR proposed findings of fact & conclusions of law Findings & conditions proposed by appellant will increase likelihood that mods will meet seismic safety stds

 OSTRANDER.F N Oregon, State of 80/07/23 4pp
- 07300408 Order granting extension of date for filing exceptions to MSLB 800711 initial decision re mode to control bldg Executive Legal Director requested to remind staff of Pacesaity for compliance w/App A requirements O
- 7310160 Order authorizing ASLB to act on merits of State of DR otion for reconsideration of ASLB 800711 initial decision tate of DR supporting brief on exceptions is toiled until 6 days after ASLB rules on motion 18HOP, C J Atomic Safety and Licensing Appeal Panel 80/07/28

- H General correspondence
- BOO7300364 Advises of withdrawl as counsel for State of OR in matters re facility Requests that name be deleted from NRC general svc last for docket & replaced w/name of FU Ostrander BANDVIK R M Oregon, State of 80/07/03 ip
- P Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in docay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D O Division of Licensing 80/06/11 42pp
- 8007250702 Forwards plant status re masonry wall problem & activities re Mount St Helens Meeting has been scheduled in Detheads.MD for 800666 to discuss NRC position re acceptability of plant startup NOVAK.T M Assistant Director for Operating Reactors 80/06/13
- B007020021 Notification of B00619 meeting w/util in Bethesda, MD to discuss status of resolution of IE immediate action ltr reducible wythe heavy weight block walls & consideration of walls not covered by ltr TRAMMELL.C Operating Reactors Branch 3 80/06/17 2pp
- 8007020288 Forwards safety evaluation re postulated fuel handling accident inside containment Specific equipment mode or revised refueling procedures are required to assure potential consequences are within guidelines CLARK, R A Operating Reactors Branch 3 80/06/17 3pp
- --8007020290 Safety evaluation re-postulated fuel handling accident inside containment

 * Operating Reactors Branch 3 80/06/17 App
- --8007020294 Spitoble Tech Specs for installation of charcoal filters on purge exhaust sys
 # Operating Reactors Branch 3 80/06/17 Rep
- B007010418 forwards list of design change requests for mod program described in PGE-1020. "Rept on Design Mods for Trojan Control Bidg" Piping support mods will not reduce shear capacity of major walls by more than 1% MCCARRELS F Portland General Electric Co 80/06/25 App
- 8007160365 Forwards Amend 45 to License NPF-1, safety evaluation & notice of issuance & availability
 CLARK,R A Operating Reactors Branch 3 60/06/27 4pp.
- --B007160372 Amend 45 to License NPF-1, allowing insertion into reactor core of two fuel assemblies each containing may of three dummy stainless steel rods for Cycle 3 operation . CLARK R A Operating Reactors Branch 3 B0/06/27 2pp
- --8007160376 Safety evaluation supporting Amend 45 to License NPF-1 * Operating Reactors Dranch 3 80/06/27 7pp
- --B007160379 Notice of issuance & availability of Amend 45 to License CLARK, R A Operating Reactors Branch 3 80/06/27, 2pp
- 8007170390 Summarizes Div of Power Supply & Reliability views re electric power sys reliability impacts in Pacific Northwest & northern CA should facility outage extend through Sept 1980, Genpration imadequate for CA Recommends Jul review MEINER, R & Energy, Dept. of 80/06/27 3pp
- 8007070273 Submits revised criteria to be used in analysis of out-of-plane behavior of heavyweight double wythe masonry walls Includes all masonry walls baving safety significance All masonry walls uill comply wirevised criteria by 801031, DROCHL.D J Portland General Electric Co 80/06/28 22pp
- 8007070340 Responds to 800514 request for add1 info re adequacy of station electric distribution sys voltages Responses to specific questions & plant voltage profile tables encl QDOMIN.C Portland General Electric Co 80/06/30 7pp.
- 8007170472 Forwards corrected Page 3/4 1-24 to Tech Spec submitted for Amend 44 to License NPF-1 CLARK,R A Operating Reactors Branch 3 80/06/30 3pp
- --8007170483 Tach Spec 3 1 3 5 for reactivity control sys * Portland General Electric Co 80/06/30 2pp

- B007090227 Forwards addl info re auxiliary feedwater sys per 800514 request

 OCCIDATION C Portland Commercal Electric Co 80/07/01
- 8007210123 Forwards evaluation of control rod guide thimble wear in facilities designed by Westinghouse Based on review, issue is resolved CLARK,R A Operating Reactors Branch 3 80/07/01 5pp
- BOO7070300 Forwards License Change Application 62 requesting amend to License NPF-1 Class III amend fee & Contificate of Svc encl QOODWIN, C Portland General Electric Co 60/07/02 2pp
- --8007070307 License Change Application 62 requesting amend to License NPF-1 to incorporate mods in reactor coolant pump breaker question inputs to reactor trig logic Proposed revisions to Tech Spec Pages 3/4 3-2, -4 & -7 encl GODDWIN.C Portland General Electric Co 60/07/02 opp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PHR Model Tech Specs & Model license conditions for TMI-2 Lessons Leained Category A items encl for guidance EISENHUT, D O Division of Licensing 80/07/02 69pp
- 80070903A0 Submits clarification of 800616 addl info re containment 07090360 Submits clarification or SUBMIA add: Into re-punge sys, submitted in response to S00318 request High radiation signal can be overridden manually by raising setpoint or holding reset on radiation monitors panel GDDDMIN.C Portland General Electric Co S0/07/03
- 8007160608 Submits clarifying info re License Change Application 62 re modifying logic to reactor coolant pump trip breaker position trip signal Upon approval, facility will no longer be vulnerable to reactor trips from loss of vital bus GDODHIN.C Portland General Electric Co 80/07/07 4pp
- 8007240304 Advises of NRC reorganization on 800420 which resulted in number of changes in ofc titles, positions & assignments of personnel Also submits info for GETA NOVAK, I N Assistant Director for Operating Reactors 80/07/08
- 8007180441 Forwards Amend 46 to License NPF-1.safety evaluation & notice of issuance & availability Related correspondence CLARK.R A Operating Reactors Branch 3 80/07/10 3pp
- --- 8007180448 Amend 46 to License NPF-1, changing Tech Specs by deleting from reactor protection systmeactor trip derived from opening of any single reactor coolant pump circuit breaker above 36% power Related correspondence
 CLARK,R A Operating Reactors Branch 3 80/07/10 App
- --8007180453 Safety evaluation supporting Amend 46 to License NPF-1 * Operating Reactors Branch 3 80/07/10 3pp
- --- 8007180454 Notice of issuance & availability of Amond 46 to License CLARK, R A Operating Reactors Branch 3 80/07/10 2pp
- B007170424 Forwards interim rept describing results of nondestructive examination of U-bends removed from steam generator D Axial cracks were detected in cold-leg transition at or near extrados surface QODDNIN.C Portiand General Electric Co 80/07/11 8pp
- 8007300047 Forwards 800617-19 trip rept to Portland, OR & Mount St Halens re effect of volcanic activity & related phenomena FEMA bullatin re volcanic hazards encl LEFEVRE.H E. JUSTUS.P S Geosciences Branch 80/07/14 2ipp
- B007220570 Forwards list of requests for design changes associated w/mod program described in PQE-1020 re design mods for control bldg Mods involve piping supports mecessary to qualify pipe sys for response spectra. Certificate of Syc oncl
 BROCHL.D J Portland General Electric Co 80/07/17 4pp
- 8007250474 Forwards License Change Application 63 requesting amend to License NFF-1 Certificate of Svc enc! CODDWIN.C Portland General Electric Co 80/07/22 3pp
- ~~8007250481 License Change Application 63 requesting amend to License NPF-1 deleting portions of ETS covered by EPA controls, per ASLAB decision re jurisdictional control for establishing water quality layels & monitoring requirements
 * Portland General Electric Co 80/07/22 59pp

- BOO73003H/ Forwards supplemental info re auxiliary foodwater sys.in response to Items B 2 & C & in encl to NRC 800914 ltr Submittal completes util responses GODDHIN.C Portland General Electric Co 80/07/25 8pp
- O Inspection reports. IE Bulletins & correspondence
- 8007030233 Submits add1 response to 1E Bulletin 79-066 Licensed operator assigned to control room is being replaced by unlicensed operator trained in amergency procedures until plant is returned to operation after Spring 1980 outage BROCHL.D. J. Portland General Flettric Co. 80/04/16 2pp
- BOO7280199 Forwards response to IE Bulletin /9-018. "Chviron Qualification of Class IE Equipment" Includes revised master list of engineered safety feature systemates of environ qualifications & list no outstanding items W/o enr GDODWIN.C Portland General Electric Co. 80/09/19. 2pp
- 8007020234 Forwards IE Info Notice 80-22, "Ureakdowns in Contamination Control Programs" No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director BO/05/28 ip
- BD07310472 Forwards response to IF Bulletin BO-O3 re loss of charcoal from tray adsurber cells investigations conducted found no evidence of carbon cell fulluros goodwing. C. Portland General Electric Co. 80/06/04 App
- BOO7350'30 Forwards response to IC Bulletin BO-12. "Decay Heat Removal Bys Operability " Instances of temporary decay heat removal degradation for short periods have been reported Prucedure developed to provide backup tore heat removal wRCS open GODDHIN.C Portland General Electric Co 80/05/09 4pp
- 8007360296 Responds to IE Butletin 80-05 re vacuum damage to chemical vol control sys tanks All tanks w/active vacuum protection devices have backup Tanks w/passive vacuum protection util be provided wildocking device & engraved wanting GDODHIN.C Portland General Electric Co 80/06/09 6pp
- 8007220241 Forwards IV Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required ENOFIKEN, R.H. Region 5. San Francisco. Office of the Director
- 80071805(B Recommends that encl IE info Notice B0-21. "Anchorage & Bupport of Safety-Related Flectrical Equipment." be distributed to appropriate Nowdo & parties EISLNUT.D O Division of Licensing (80706712 .)pp
- --B00718053B Discusses IE into Notice 80-21. "Anchorage & Support of Safety-Related Electrical Equipment" Written response is macessary since deficiencies found at other plants may have bearing on solomic qualification CLARK, R. A. Operating Reactors Branch 3 80/04/12 Ip
- 8007250360 Responds to IE Bulletin 79-18, "Audibility Problem Encountered on Evacuation of Personnal from High Notes Areas "Existing tys will be replaced w/Amproved in-plant communication network Interim measures taken GOODWIN.C Portland General Electric Co. 60/06/1/ 2pp
- 8007030018 Forwards JE Bulletin 80-19, "Phospile toss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required ENGELKEN, R is Region 5, San Francisco. Office of the Director B0/05/18
- 8007080470 Forwards IE Circular 40-19. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN.R H. Region 5. Sun Francisco. Office of the Director E0/06/20
- 8007180290 Forwards IE Cirtular 80 14, "Radioartive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personaul " No written response required ENGFLKEN.R H Region 5. Son francisco. Office of the f 80/06/24 ip
- BOO7290889 Follows up 7912'11 response Qualification of Class If Equipment Qualification of ASCO Solenoid Valve valves are being replaced

- 200
- B007240309 Forwards IE Insp Rept 50-344/80-08 on 600408-11,14-18 & 0505-09 No noncompliance noted SPENCER 6 S Region 3, San Francisco, Reactor Construction & Engineering Support Branch B0/06/26 2pp
- --B007240314 lE Insp Rept 50-344/80-08 on B0040B-11, 14-18 & 0504-09 No noncompliance noted Major areas inspected maint activities re pressurizer code safety valves & preparations for control bldg wall mods HAIST, D P . ELIN, J O Region 5, San Francisco, Office of the Director DEDDS, R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/06/26 lipp
- 8007010177 Ack receipt of 800604 ltr informing NRC of steps taken to correct violations noted in 800512 notice of violation NORDERHAUG, L R Region 5. San Francisco, Safeguards Branch 80706777 to
- B007230390 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required. ENGELKENR H Region 5. San Francisco, Office of the Director B0/06/27 | Ip
- 3007090327 Forwards response to IE Bulletin 80-10 re contamination of nonradioactive sys & potential for uncontrolled releases Primary plant interfaces between radioactive & nonradioactive sys examined for cross-contamination GDOPHIN, C. Portland General Electric Co. 80/07/01 Spp
- 1007190106 Ack receipt of 800612 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-344/80-07 on 800414-18
 BOOK.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 807/07/02 10
- -8007150120 Responds to NRC 800523 ltr re violation noted in IE Insp Rept 50-344/80-07 on 800414-18 Corrective actions radwaste program will be closely monitored to insure compliance w/ regulations & procedures GDODWIN-C Portland General Electric Co 80/06/12 2pp
- -8007150124 Forwards IE Insp Rept 50-344/80-07 on 800414-18 & notice of violation BDDK.H E Region 5. San Francisco. Fuel Facility & Materials Safety Branch 80/05/23 2pp
- 8007150126 Notice of violation from insp on 800414-18 * Region 5, San Francisco, Office of the Director, 80/05/22 ip
- 8007150130 IE Insp Rept 50-344/80-07 on 800414-18 Noncompliance noted radiation effluent exceeded Tech Spec limit & waste storage containers not labeled FIGH.R F. WENSLAHAKI.F A Region S. San Francisco. Office of the Director BOOK.H E Region S. San Francisco. Fuel Facility & Materials Safety Branch 80/05/22 Ip
- 07180482 Requests written response to Items R b & 3 of IE Bulletin 80-11 within 90 days Design criteria for single wythe & composite walls for consideration of all in-plane/out-ofplane loads should be provided & fully justified CLARK.R A Operating Reactors Branch 3 80/07/03 Spp
- 17300293 Forwards IE Insp Rept 50-344/80-12 on 800514-14 No Inncompliance noted REWS-J L. Region 5. San Francisco. Reactor Operations Nuclear upport Branch 80/07/08 2pp
- 007300295 IE Insp Rept 50-344/80-12 on 800514-16 No noncompliance noted Major areas inspected response to IE bulletine & circulars & followup on previous inspictems
 JOHNSON,P H. Region 5. San Francisco. Office of the Director STERNERG,D M. Region 5. San Francisco. Reactor Operations Nuclear Support Branch. 80/07/02. App
- /160661 Forwards "Preliminry Rept op Trojan EOC-2 Fuel Examination "
 opt documents results of End-of Cycle 2 (EOC-2) Fuel insp
 ROBHLID J Portland General Electric Co #0/07/09 7pp.
- 7300518 Farwards IE Insp Rept 50-344/80-13 on 800610-11 No oncompliance moted REMS, J. L. Region 5, 8ab Francisco, Reactor Operations Nuclear apport Branch 80/07/09 2pp

- --B007300325 IE Insp Ropt 50-344/B0-13 on 800610-11 No noncompliance noted Major areas inspected aperial announced insp of circumstances surrounding & corrective actions taken re LERs 80-07 & 79-15 MORRILL,P J Region 5. San Francisco, Office of the Director STERNBERG,D M Region 5. San Francisco, Reactor Operations Nuclear Support Branch 80/07/07 4pp
- BO07250413 Responds to IE Bulletin 79-13 "Insp of Feedwater Sys Piping " Exam of feedwater & suxiliary feedwater piping revealed no detrimental conditions Responses to remaining action items in IE bulletin submitted on 790719 CHRISTENSEN S , LENTSCH, J W , BROEHL, D J Portland General Electric Co 80/07/18 ip
- R Periodic operating reports & related correspondence
- 8007140312 Forwards monthly operating rept for June 1980 YUNDT, C.P. Portland General Electric Co. 80/07/01 ip
- --BD07140315 Monthly operating rept for June 1980 DAIR, 0 0 Portland General Electric Co 80/07/01 5pp
- 8007170862 Forwards "Mount St Helens Brucekly Rept 800602-15 " LENTSCH.J W Portland Opneral Electric Co 80/07/01 1p
- --8007170568 "Mount St Helens Diweekly Rept 800602-15 " One oversize drawing aveilable in Central Files only # Foundation Sciences, Inc 80/07/01 24pp
- ß Reportable occurrences. LEAs & related correspondence
- 8007070070 PNO-V-B0-052 on 800619,156 drums of low level radwaste received Examination of shipment determined that one drum was leaking No significant radioactive contamination found State of HA burial permit cancelled THOMS: RD Region 5. Ban Francisco, Office of the Director 80/06/19 1p
- --8007080420 LER 80-010/03L-O on 800929, following refusiing,RCS boron concentration dropped below Tech Specs Caused by personnel error in calculation resulting in insufficient boric acid being added to RCS More boric acid added PERRY,J C Portland General Electric Co 80/04/27 ip
- 8007180581 Followup rept re residual chlorine & pH reading out of spec for approx ii minutes Highest value of residual chlorine measured was 4 ppm: lowest pH measurement was 4 5 Caused by operator error YUNDI, C.P. Portland General Electric Co. 80/07/09 in
- 8007150820 Forwards LER 80-011/03L-0 YUNDT, C P Portland General Electric Co 80/07/09 2pp.
- --B007150826 LER B0-011/031-0 on B00611, during scheduled maint, both trains of emergancy generators were out of svc at same time Caused by personnel error Equalizing charge terminated & hattery returned to svc PERRY. J C Portland General Electric Co 80/07/07 ip
- 8007230203 PNO-V-80-036 on 80070B, effluent water w/high chloring & low pH outside Tech Spec limits was released to Columbia River Caused by operational error in addition of chlorine to evc mater FISH R Region 5, San Francisco, Office of the Director 80/07/09 2pp
- 8007280648 RD on 800709, residual chlorine & pH readings were out of spec for approx 11 minutes Highest residual chlorine measurement was 4ppm Lowest pH measurement was 4 5 Caused by operator error YUNDT.C P Portland General Electric Co 80/07/09 1p
- BOO7tB0347 Notifies that B00417 immediate action items re LER 79-15 have been completed Requests clearance to resume power operations
 BRDEHL.D J Portland General Clectric Co 80/07/12 ip

3

8007280545 Forwards LER 80-012/03L-0 YUNDT,C P Portland General Electric Co 80/07/16 2pp

- --B007280553 LER 80-012/03L-0 on B00701, during engineering walkdown of piping, three seismic restraints were found missing from steam drain line on steam turbing-driven auxiliary feedwater pump Caused by oversight during const PERRY, J C Portland General Electric Co 80/07/16 ip
- 8007280563 Forwards RO re plant svc water effluent ph exceeding ETS limits on 800708 YUNDT,C P Portland General Electric Co 80/07/16 1p
- --B007280573 RO on B00708, during chlorination of svc water systmore chlorine added than required resulting in exceeding of ph & chlorine limits of ETS Caused by personnel error Chlorination stopped & dilution flow increased * Portland General Electric Co 80/07/16 lp
- B007310433 Advises that all mods to masonry walls required prior to power operation resumption completed on B00712 NRC 800417 itr approving licensee action entl Power operation resumed B00720 JOHNSON, R W Portland General Electric Co 80/07/21 ip
- ---8007310437 Advises that licensee action to assure acceptable structural properties of masonry walls has satisfied terms of NRC 800417 immediate action ltr Certificate of SVC encl ENGELKEN.R H. Region S. Ban Francisco, Office of the Director 80/07/12 3pp
- 8007290554 Advises that all actions committed to in util 800428 ltr re resumption of power operations now completed Summary of results for wall mode re heavyweight doubleweight withe, std weight double mythe & single mythe walls ent! BROEKL,D J Portland General Electric Co 80/07/25 2pp
- MXKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8007090254 Forwards info re fire protection sys mods scheduled for completion prior to entering Mode 4 after current outage, to aid in evaluation of request for revision to License Gondition Rt(3)h Lists commitments for interim surveillance CROMSER P Toledo Edison Co 80/07/01 5pp
- 8007230083 Requests participation in study of people-related problems in nuclear safeguards Study involves collection of data on licensee security forces & practices. NRC wishes to interview security agt personnel at facility EISENHUT, D G Division of Licensing 80/07/1% 2pp
- 8007280107 Ack receipt of 800515 ltr submitting revision to fire hazards analysis rept Proposed alternative to install overhead sprinkler sys is acceptable REID.R W Operating Reactors Branch 4 80/07/17 2pp.

9 Adjudicatory correspondence

- 8007020310 Discusses 800328 ltr proposal for meeting requirements of NRC 800308 order to modify license. Section VII 2. Commitments referenced in 791206 draft ANS 3 1 are acceptable, w/ exception of Section 5 2 1 8

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11
- 8007310243 Forwards Commission B00527 mBmorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D B Division of Licensing B0/06/25 B9pp

H General correspondence

- 8007270048 Responds to inquiry re flooding of site. Natural phenomena considered in plant design & comst Access to & from plant during flood considered in emergency plan In flood emergency rail boat or DKW transportation will be utilized KEPPLER, J O Region 3. Chicago. Office of the Director 80/05/22 2pp
- M Antitrust correspondence
- 8007140231 Forwards Director of Nuclear Reactor Regulation order further modifying 800313 order w/respect to licenses & permits for facilities BALTZMAN,U Utility Finance Branch 80/06/11 1p

- 8007j40256 Forwards Director of Nuclear Reactor Regulation order further modifying 800513 order w/respect to licenses & permits for facilities 8ALTZMAN, J. Utility Finance Branch 80/06/11 lp
- --8007140265 Order granting extension until 800709, for Cleveland Electric Illuminating Co to file amend to tariff w/FERC as required by 800513 order DEMTON. HR Deffice of Nuclear Reactor Regulation, Director 80/06/11 2pp
- 8007140B75 Conditional request for hearing re Commission 800513 order re mod of transmission tariff Urges mod of order to bring consistency w/FERC tariffs in Opinion 84 or institution of hearing Util protest before FERC & Certificate of Svc encl ODLDBERG.R, WACNER, T & Cleveland, DH GOLDBERG.R Goldberg, Fieldman & Hjelmfelt 80/07/09 14pp
- 8007290533 Response in opposition to City of Cleveland, OH 800A09 request for hearing re Director of Nuclear Reactor Regulation 800513 order Filing, requesting tariff w/FERC, brings controversy to end w/o litigous course REYNOLDS, W B , ZAHLER, R E Cleveland Electric Illuminating Co
- P Operating license stage documents & correspondence
- B00724020B Forwards B&W licensees' responses to 790907 request for review of schedule for installing safety-grade anticipatory reactor trip for loss of feedwater & turbine trip Review should be completed by 791115
 CAPRA,R A TMI-2 Bulletins & Orders 79/10/24 lp
- 8007230099 Requests submittal of proposed Tech Spec changes providing Por redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENRUTID G Division of Licensing 90/04/11 62pp
- BO07100004 Denies 790929 Proposed Change 2 to Tech Specs to altersafety features actuation sys containment radiation instrumentation requirement Forwards requests for add1 infore bypass capabilities of engineered safety features NOVAX.T M Assistant Director for Operating Reactors 80/06/24
- B007010464 Forwards addl info re shift manning, licensing, testing of power operated relief valve isolation sys, automatic trip of reactor coalant pumps & small break LOCA methods, in response to NRC 800807 ltr
 CROUBE, R P Toledo Edison Co 80/06/26 4pp
- 8007180227 Dummary of B00610 meeting w/util & B&W in Bethesda.MD refuel assembly holddown spring failures Viewgraphs encl OARNER, D Operating Reactors Branch 4 80/06/30 33pp
- 8007210004 Forwards questions re fuel assembly holddown spring insps & safety significance of operating w/broken springs in core Requests response within &0 days
 NOVAK.T H Assistant Director for Operating Reactors 80/07/01
- 8007210039 Forwards request for add1 info for review of plant operation in Cycle 2 Responses should be received by 800715 to permit completion of review by projected startup date
 NDVAK.T H Assistant Director for Operating Reactors 80/07/01
- BOO7210119 Requests response to anci questions re fuel assembly holddown spring failures. Initial holddown spring failure was identified during underwater insps of fuel in reactor vassel during current refueling outage NOVAK-T M Assistant Director for Operating Reactors BO/07/01 San
- 8007170457 Forwards Amend 26 to License NPF-3, EIA & notice of issuance & availability REID,R W Operating Reactors Branch 4 80/07/02 2pp
- --8007170461 Amend R4 to License NPF-3.deleting satisfied App D ETS restudies on fish.fish eggs & larvae
 REID.R W Operating Reactors Branch 4 80/07/02 6pp
- --8007170467 EIA supporting Amend 26 to License NPF-3 State of DH 800616 ltr re mod of NPDES Permit B211*AD encl * Operating Reactors Branch 4 80/07/02 38pp
- --8007170477 Notice of issuance & availability of Amend 26 to License NPF-3 & negative deciaration REID,R W Operating Reactors Branch 4 80/07/02 2pp

- B007210329 Forwards Amend 25 to License APF-3, safety evaluation & notice of issuance & availability REID.R W Operating Reactors Branch 4 60/07/02 2pp
- --B007210333 Amend 25 to License NPF-3, modifying Tech Specs on surveillance frequency for venting ECCS pump casings & discharge piping high points Also corrects typographical error in Table 3 7-3 REID.R W Operating Reactors Branch 4 80/07/02 7pp
- --8007210335 Safety evaluation supporting Amend 25 to License NPF-3

 * Diffice of Nuclear Reactor Regulation, Director 80/07/02 2pp
- --8607210340 Notice of issuance & availability of Amend 25 to License REID,R W Operating Reactors Branch 4 80/07/02 200
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Hodel Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EISENHUT D G Division of Licensing 80/07/02 65pp
- 8007180125 Forwards Amend 27 to License NPF-3. safety evaluation & notice of issuance & availability
 REID.R H Operating Reactors Branch 4 80/07/07 2pp
- --8007180133 Amend 27 to License NPF-3. modifying Tech Specs to reflect REID.R W Operating Reactors Branch 4 60/07/07 14pp
- --8007180140 Safety evaluation supporting Amond 27 to License NPF-3 * Operating Reactors Branch 4 80707/07 2pp
- --8007180149 Notice of issuance & availability of Amend 27 to Licenso REID.R W Operating Reactors Dranch 4 BD/07/0/ 2pp
- G007150670 Forwards suppl to G00211 reload rept describing info supporting repairs made to failed springs in fuel assemblies CROUSE.R P Yoledo Edison Co 80/07/10 4pp
- B0072B0353 Advises of personnal changes resulting from reorganisation of Ofc of Nuclear Reactor Regulation NOVAK.TM Assistant Director for Licensing B0/07/10 2pp
- 5007210454 Responds to 780120 request for overall asymmetric LOCA load evaluation BAM-1621.re Phasm II analysis of LOCA loadings.provides acceptable demonstration of facility ability to maintain core coolability CROUSE.R P Toledo Edison Co 80/07/14 2pp
- 8007230581 Responds to NRL 800701 ltr requesting add1 info re Cycle 2 including design, transient analysis & startup testing Prior to fuel loading, insp is made to ensure assemblies are in proper storage location in spent fuel pool CROUSE.RP Toledo Edison Co 80/07/16 4pp
- 8007250427 Responds to NRC 800701 ltr re fuel assembly holddown spring failure per 800710 meeting w/NRC & B&H re proposed repair process Cycle 2 Reload Rept suppl on 800710 noted replacement of broken springs Detailed responses encl CROUSE.R P Toledo Edison Co 80/07/18 9pp
- 8007250382 Informs that util modifying current RCS flow indication scheme in manner similar to NRC acceptable method Effort will be completed prior to startup following current refueling outage CROUSE.R P Toledo Edison Co 80/07/21 1p
- 8007290434 Forwards Suppl 2 to "Davis-Besse Nuclear Power Station. Unit 1.5eismic Re-evaluation." completing qualification summary of all equipment listed in Attachment 1 to NRC 790130 ltr.
 CROUSE.R P Toledo Edison Co 80/07/22 2pp
- 8007280485 Commits to suppl 780320 license amend request by changing Tech Specs to ensure RCS overpressure protection for periods of imperability of alternate relief valve in Modes 4 to CROUSE, R P Toledo Edison Co 80/07/22 2pp

- 8007310380 Forwards response to NRC 800624 request for add1 info re bypass & reset of engineered mafety features Design goal of mafety features actuation my in to automatically prevent or limit fission product & onergy release from core CROUSE: R P Toledo Edison Co 80/07/23 5pp
- BOO7310350 Forwards request for add1 info for review of BOO211 proposed Tech Spec change to support operation during Cycle 2 Requests response by BOO729 NOVAK.T M Assistant Director for Operating Reactors 80/07/23
- G Inspection reports, IE Dulletine & correspondence
- B007140548 Forwards IE Insp Rept 50-346/80-10 on 600415-17.29-0501. 06-08 & 12-13 No noncompliance noted HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch B0/05/27 2pp
- --8007140558 IE Imap Rept 50-346/80-10 on 800418-17.29.30.0501.06-00 % 12 -13 No noncompliance noted Major areas inspected preparation for refueling outage, pre-fuel handling activites, fuel handling activities & maint during refueling outage JACKIN.I N. SMANSON, E.R. Region 3, Chicago, Office of the Director 80/05/23 5pp
- 8007020056 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28
- 8007210364 Forwards IE Circular 80-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies " No written response required KEPFLER, J G Region 3, Chicago, Diffice of the Director
- 8007010116 Forwardt IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLEA, J G Region 3, Chicago, Office of the Director 80/05/29
- 8007210322 Forwards IE Insp Rept 50-346/80-14 on 800408-11.15-25,29-30, 0501.02 & 05-09 & notices of violation HEISHMAN R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/09 2pp
- --8007210325 Notice of viglation from insp on 800408-11,15-25,29-30,0501, 02 & 05-09 # Region 3. Chicago. Office of the Director. 80/06/03 1p
- --8007210327 IE Insp Rept 90-346/80-14 on 800408-11.15-25.27-30.0501.02 & 05-09 Moncompliance noted failure to establish fire watch patrol REVES.L A , MCGREGOR.L G , TAMBLING.T N Region 3, Chicego, Office of the Director 80/06/03 Bpp
- B007010254 Notifies that info requested by IE Bulletin B0-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks," is boing compiled & evaluated Response will be available on B00627 CRO
- 8007820218 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/10
- B007160191 Forwards IE Info Notice 80-27, "Degradation of Reactor Collant Pumps Studs " No specific action or response KEPPLER, J 6 Region 3, Chicago, Office of the Director 80/04/11.
- 8007020040 forwards response to IE Bulletin 80-06, "Engineered Bafety Feature (ESF) Reset Controls " Re-review of all safety-related components affected by safety features actuation systhms that reset will not remove component from safe mode. CROUSE, R P Toledo Edison Co 80/06/13 3pp
- 8007130824 Forwards results of foliow-on analysis of identified discrepancies for normally accessible safety-related piping in response to Item 48 of IE Bulletin 79-14, "Seismic Analysis for As-Built Bafety-Related Figing Sys "CROUSE, R P Toledo Edison Co 80/06/16, 4pp
- 8007140464 Forwards IE Insp Rept 50-346/79-34 on 791218-19 No noncompliance noted

 DAVIS, A B Region 3, Chicago, Fuel Facility & Materials Safety
 Branch 80/06/17 2pp

- -8007140471 IE Insp Rept 50-346/79-34 on 791218-19 No noncompliance noted Hajor areas inspected actions taken in response to IE Bulletin 79-19 re low level radwaste packaging for transport & burial GREOGRAL R Region 3, Chicago, Office of the Director FISHER, W L Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/06/13 App
- 8007030046 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Bys (ENS) W/Loss of Offsite Power" Written response required KEPPLER, J @ Region 3, Chicago, Office of the Director 80/04/3 Region 3, Chicago, Office of the Director 80/05/18
- 8007170064 Forwards description of results of followon analytical work to IE Bulletin 79-14 Effect of discrepancies discovered in IE Bulletin 79-14 insp evaluated Conclusions in 791019 ltr still valid CRDUSE, R P Toledo Edison Co 80/06/18 App
- G007180310 Respands to Items 1,2 & 3 in IE Bulletin 79-03, Revision A No applicable piping components w/design pressure stresses greater than B5% of allowable code values identified CROUSE, R P Toledo Edison Co B0/06/18. 2pp
- B007140237 Forwards response to IE Bulletin 60-10. "Contamination of Monradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ "Unprotected sys are regularly sampled & tested for tritium CRDUSE.R P Toledo Edison Co. 80/06/19 2pp
- 8007230327 Forwards IE Insp Rept 50-346/80-11 on 8004:0-11,21-22, 0506-07 & 0604 No noncompliance noted FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/19 2pp.
- --8007230333 IE Insp Rept 50-346/80-ii on 800410-ii.21-22.0506-07 & 0604
 No noncompliance noted Major areas inspected GA/GC program,
 nondestructive examination evaluations & work activities
 MARD.K D Region 3. Chicago, Office of the Director
 DANIELBON.D H. Region 3. Chicago, Reactor Construction &
 Engineering Support Branch 80/06/18 7pp
- BOO7020571 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J O. Region 3, Chicago, Office of the Director 80/06/20
- 9007090013 Forwards notice of violation & notice of proposed imposition of civil penalties re 800430 radiation overexposure STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/20 3pp

- B007110214 Forwards notice of violation & notice of proposed imposition of civil penalities arrising from IE 800430 insp
 SYELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/20 3pp Эрр
- --B007110220 Notice of violation from insp on 800421-24,0502 & 06-08 Noncompliance noted them & rad tester received doses exceeding 3 rems & exposure rate evaluations made during sump tunnel entry were inadequate
 # Office of Inspection & Enforcement, Office of the Director
 BO/O6/20 2pp
- 8007170515 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminaralized Water Sys & Resultant Internal Contamination of Personnel " No written response required MEPPLER. J Q Region 3, Chicago. Office of the Director 80/06/24
- 8007300601 Forwards IE Insp Rept 50-846/80-15 on 800512-16,19-23,28-30, 0602-06 & 09-10 & notice of violation. HEISHMAN R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/06/25 2pp.

- --8007300604 Notice of violation from insp on 800512-16, 19-23, 28-3 06 & 09-10 * Region 3, Chicago, Office of the Director 80/06/24 in
- --8007300606 IE Insp Rept 50-346/80-15 on 800512-16.19-23.28-30.06
 09-10 Noncompliance noted feature to notify NRC apgrations
 ctr within 1-h of accidental radioactive release or event
 requiring initiation of emergency plan
 TAMBLING.T H. REYCS.L A. Region 3. Chicago, Office of the
 Director 80/06/24 App
- 8007230074 Responds to 1E Bulletin 79-17.Revision I. "Pipe Cracks Stagnant Borated Water Sys at PWR Plants " All welds examined & found to be clear of recordable indications CROUSE.R P Toledo Edison Co 80706/27 ip
- B007230141 Forwards response to IE Bulletin B0-05, "Vacuum Conditi Resulting in Damage to Chemical Vol Control Sys (CVGS) Holdup Tanks " Review shows corrective actions not required CROUSE.R P Toledo Edison Co 80/06/27 App
- 8007230340 Forwards IE Dulletin RO-16, "Potential Misopplication o Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No britten response required KEPPLERJ Q Region 3, Chicago, Office of the Director 80/06/
- B007170532 Responds to IE Bulletin 79-14. "Seismic Analysis for As Built Safety-Related Piping Sys " Insp of normally inaccessible piping completed B00522 Two deviations affecting sys operability will be corrected before startup CROUSE,R P Toledo Edison Co 80/06/30 2pp
- BO07180271 Advises that response to Items 1.2a & 3 of IE Bulletin 80-11. "Masonry Wall Design." will be delayed 1 wk beyond date specified in bulletin CROUSE.R P Toledo Edison Co 80/06/30 ip
- B007210216 Responds to IE Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts " Outstanding items have been completed except base plate accessibility which will be completed by 801101 CROUSE.R P Toledo Edison Co B0/07/01 Spp
- 8007240024 Ack reculpt of B00411 ltr informing NRC of steps taken correct violation noted in IC Insp Rept 80-346/80-13 Details withheld (ref 100762 790)
 HIND, J. A. Region B. Chicago, Safeguerds Branch 80/07/03 2pp.
- ---8007240028 Responds to NRC 800521 ltr re violation noted in IE I Rept 50-346/80-13 Corrective actions withheld (ref 10CFR2 770) CROUSE R P Toleda Edison Co 80/06/11 ip
- 8007230200 Forwards reply to IE Bulletin 80~08 re containment line penetration welds Repts results of const nondestructive examination of penetration welds CROUSE,R P Toledo Edison Co 80/07/10 App
- 8007230200 Ferwards reply to IE Bulletin 60-08 re containment line penetration welds Repts results of const nondestructive examination of penetration welds CROUSE, R P Taledo Edison Co 80/07/10 App
- 8007240307 Forwards corrected copy of notice of violation from ins 800312-16.19-23.28-30,0602-06 & 09-10 which was transmitted by NAC 800629 ltr HEISHMAN,R F Region O. Chicago, Reactor Operations Nuclear Sup HEISHMAN, R F Region 3. Chicago, Reactor Operations Nuclear Sup Branch 80/07/10 1p
- --8007240313 Corrected natice of violation from insp on 800512-16, 20-30,0602-06 & 09-10 * Region 3, Chicago, Office of the Director B0/07/10 ip
- B007250572 Forwards response to IE Bulletin G0-08. "Exam of Contactions Penetration Welds" List of all penetrations w/ containment boundary butt walds hetween ponetration sleeve & process piping as illustrated in ASHE code encl CROUSE.R P Toledo Edison CO 80/07/10 App
- B007270500 Forwards masonry wall design evaluation in response to 1.2a & 3 of IE Bulletin B0-11 Safety-related & nonsafety-related components identified on faces of walls Partial response to Item 2b & 3 will be filed by 601104 CROWSE.R P Toledo Edison Co 80/07/14 5pp

```
8007310348 Forwards response to NRC 800620 itr re 800430 personnel overexposure Corrective actions procedure now requires insporf cavity area surrounding reactor vessel to identify water leakage Payment of civil penalty encl CROUSE, R P Toledo Edison Co. 80/07/15 5pp
8007280429 Forwards IE Investigation Rept 50-346/80-14 on 800605-06 & notice of violation Notice of violation withheld (ref 10CFR2 790)

MEPPLER.J G Region 3. Chicago. Office of the Director 80/07/17
---80072B0435 IE Investigation Rept 50-346/80-18 on B00605-06
Noncompliance noted failure to assess adequacy of access
control & to meet security plan commitment App B rept
details withheld (ref IOCFR2 790)
WEIL. C H , MADEDA.T J , NORELIUS. C E Region 3, Chicago, Office of
the Director B0/07/11 178p
8007310534 Ack receipt of 800627 ltr informing NRC of steps taken to
correct violation noted in IE Insp Rept 50-346/80-14
HEISHMAN,R F. Region 3, Chicago, Reactor Operations Nuclear Support
Branch 60/07/22 ip
 --8007310536 Responds to NRC 800605 ltr re violation noted in IE Insp
Rept 50-346/80-14 Corrective actions appropriate personnel
will ensure that fire watch is established as required by
Tach Specs
CROUSE,R P Toledo Edison Co 80/07/08 2pp
R Periodic operating reports & related correspondence
8007140318 Forwards monthly operating rept for June 1980
MURRAY, T D Toledo Edison Co 80/07/08 1p
--8007140322 Monthly operating rept for June 1980
SARSOUR: D Toledo Edison Co 80/07/08 3pp
 S Reportable occurrences. LERs & related correspondence
8007010434 Forwards LER 80-043/03L-0
MURRAY, T D Toledo Edison Co 80/06/26 1p
--8007010439 LER 80-043/03L-0 on 800928.while testing safety features actuation sys.valve DH-11 closed & DH pump 1-1 was stopped Caused by procedural inadequacy Responsible personnel were made aware of problem ISLEY.T Toledo Edison Co 80/06/26 3pp
8007030260 Forwards LER 80-044/03L-0
MURRAY, T D Toledo Edison Co 80.
                                                                                                    B0/06/27 1s
--B007030264 LER B0-044/03L-0 on 800331 decay heat flow indication FI-DH2B dropped low off scale Caused by technician performing surveillance test on inservice flow transmitter string w/o shift supervisor knowledge MAKATURA-L Toledo Edison Co 80/06/27 2pp
BOO7150609 RD on 800627, pipe support HCB-40-41 on component cooling water supply to control rod drive mechanism found not installed Also, lateral restraint CCA-B-HI5 on pressurizer relief inlet located 9 inches from analyzed location MURRAY.T D Toledo Edison Co 80/06/27 ip
8007210573 Forwards questions to failure of holddown spring on fuel assembly Response should be submitted in time for NRC to include discussion in safety evaluation for reload NOVAK.T M Assistant Director for Operating Reactors 80/07/01
8007110427 Forwards revised LER 77-2/2/01T-2 MURRAY.T D Toledo Edison Co 80/07/02 ip
    -8007110434 Revised LER 77-222/01T-2 on 770805, during hot functional testing, pressurizer power operated relief valve was opened & severe movement of discharge piping was observed Caused by loop soals allowing water slug to cause pipe movement GUENNOZ:S M Toledo Edison Co 77/08/19 4pp
B007110391 Forwards revised LER 79-126/03L+1
MURRAY, T D Toledo Edison Co 80/07/03 ip
--8007110397 Revised LER 79-126/03L-1 on 791R09, during diesel generator
test, generator 1-1 experienced load swings as load was
increased No specific cause determined Gain & stability on
electric governor needed slight adjustments
HARTIGAN, J.P. Toledo Edison Co. 80/01/05. 2pp
```

```
BOO7110407 Forwards LER BO-045/03L-0
MURRAY, T D Toledo Edison Co BO/
                                                                                         B0/07/03 in
 --8007110416 LER 80-045/03L-0 on 800609, while preparing to perform ST 5091 01, NI-2 found partially disconnected from equipment in control room Apparently caused by personnel error Info tags hung on coax cables to insure proper connection WERNER, J Toledo Edison Co 80/07/03 2pp
 8007110418 Forwards LER 80~046/03L~0
MURRAY, T D Toledo Edison Co 80/07/03 1p
 ---B007110423 LER B0-046/03L-0 on B00606.during performance of BT 5095 01.
spent fuel pool level fell below Tech Spec requirement
Caused by improper alarm setpoint Alarm setpoint adjusted to
            prevent recurrence
CECH.L M Toledo Edison Co BO/07/03 2pp
 8007110440 Forwards LER 80-047/03L-0
MURRAY, T D Toledo Edison Co 80/07/03 ip
 ---R00711044R LER R0-047/03L-0 on B0040B, shift supervisors discovered
           dors 306 & 401a blocked open Apparently caused by lack of administrative controls when temporary signs on doors were prematurely removed before all permanent signs installed CECH:L. Toledo Edison CD 80/07/03 2pp
8007150560 Forwards LER 80-048/01T-0
MURRAY, T D Toledo Edison Co B0/07/10 1p
    -B007190566 LER 80-04B/01T-0 on B00627, during IE Bulletin 79-14 insp, pape support HCB-40-B1 found not installed & CCA-B-415 found mislocated Caused by instial const/installation error Supports will be installed in proper locations, MEKBEL.C Toledo Edison Co 80/07/10 2pp
8007240126 Replacement transmittal ltr for LER BO-048/01T-0
MURRAY.T D Toledo Edison Co 80/07/10 ip
8007170441 Forwards LER 80-049/03L-0
MURRAY, T D Toledo Edison Co 80.
                                                                                         B0/07/11 1b
--8007170450 LER 80-049/03L-0 on 800614, during restoration of containment pressure inputs to safety features actuation sys cabinets, actuation occurred Caused by deficient procedure ST 9061.01 App F not requiring trip bypass test ISLEY,T Toledo Edison Co 80/07/11 Spp
8007220375 Forwards LER 80-050/03L-0
MURRAY, T D Toledo Edison Co BO
                                                                                      BQ/07/17 1p
--B007220378 LER 60-050/03L-0 on 800623,while preparing to run 8T 5051 01,inboard & outboard bearing thermocouple wells found broken on HPI pump 1-1,rendering motor inoperable Probably caused by personnel stepping on line Hells replaced HARTIGAN.J P Toledo Edison Co 80/07/17 2pp
B007220458 Forwards LCR 80~051/03L~0
MURRAY, T D Toledo Edison Co 80/07/17 ip
     -8007220465 LER 80-051/03L-0 on 800619, while performing 8T 5031 07 Phase II, sequencer logic channels 2 % 4 did not operate as designed Caused by component failure of relay SEGX & CR-3X in C3618 Relay SEGX was replaced CR-3X was cleaned ISLEY, T Toledo Edison Co 80/07/17 2pp
B007280596 Forwards updated LER 80-050/03L-1
MURRAY.T D Toledo Edison Co 80/07/21
---B007280602 Updated LER B0-050/03L--i on 800623, inboard & outboard bearing thermocouple wells found broken on high pressure injection pump 1-1 Probably caused by someone accidentally stapping on line Wells replaced & vil reservoirs refilled HARTIGAN, J P Toledo Edison Co 80/07/17 ip.
8007280571 Forwards LER 80-053/01T-0
MURRAY, T D Toledo Edison Co 80/07/22 ip
     -8007280578 LER 80-053/0iT-0 on 800709.meeting held to discuss results of integrated safety features actuation sys test Bome of logic modules on sequencer steps 2,3.4 & 5 tripped before being blocked Caused by design deficiency ISLEY.T Toledo Edison Co 80/07/22 3pp
8007280630 Forwards LER 80-052/01T-0
MURRAY.T D Toledo Edison Co 80
                                                                                        80/07/22 1p
```

- ---B007280A43 LER 80-052/01T-0 on 800709, during review of seismic calculations, exhaust ductwork of emergency diesel generators created overstressed conditions at exhaust notites Caused by design deficiency Supports will be added HARTIGAN, J P Toledo Edison Co 80/07/22 2pp
- 8007280583 Forwards LER 80-054/03L-0 HURRAY, T D Toledo Edison Co 80/07/23 ip
- ---B007280589 LER 80-054/03L-0 on B00627.NI-1 output failed to zero during fuel assembly movement Assembly removed & put in support rack Cause unknown but may be intermittent grounding problem or component failure Ground problems under investigation WERNER.B J Toledo Edison Co 80/07/23 2pp
- 800/280609 Forwards revised LER 79-084/01T-1 HURRAY, T. D Toledo Edison Co 80/07/23 ip
- --8007280622 Revised LER 79-084/017-1 on 790806, containment air coolers svc water outlet valves failed to meet response time Caused by undersized air opening on pneumatic actuators Valves forced full open Actuating mechanisms redesigned RUDGLPH, J P Toledo Edison Co 79/08/17 29p
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1
 F Security, medical, emergency & fare protection plans
- B007280641 Responds to NRC 800702 ltr requesting info re evacuation times Util B00204 ltr w/State of AL & GA officials comments encl.
 CLAYTON.F L. Alsbams Power Co. 80/07/21 lp
- O Adjudicatory correspondence
- B007310243 Forwards Commission B00927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re-fire protection for electrical cables EISENMUT.Q O Division of Licensing B0/06/25 89pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007100261 Forwards Amend 73 to FSAR for Unit 1 & OL application for Unit 2 CLAYTON.F L Alabama Power Co 80/07/08 ip
- --8007100267 Application for Amend 73 to FSAR for Unit 1 & OL application for Unit 2 Certificate of Svc encl
 * Alabama Power Co 80/07/08 4pp
- --8007100276 Amend 73 to FSAR for Unit 1 & OL application for Unit 2 Revises Unit 2 completion of const & commercial operating dates updating section re emergency lighting sys & info partaining to GA program * Alabama Power Co 80/07/OB 400pp
- P. Operating license stage documents & correspondence
- 8007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT, D Q Division of Licensing 80/06/11 62pp
- 8007150714 Responds to NRC 800507 ltr re add1 TMI-2 related requirements & submits response for Unit 1 Shift manning, revised scope & criteria for licensing exams & procedures for feedback of operating experience to plant staff encl CLAYTON,F L Alabama Power Co 80/06/26 29pp
- 8007250001 Requests submittal of application for amend to license consisting of Tech Bpec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lessons Learned Category A items encl for guidance EIBENHUT, D 0 Division of Licensing 80/07/02 69pp
- 8007210499 Confirms 800711 agreements w/NRC re operability of auxiliary feedwater flow control valves at facility Commitments made re stroking listed valves as soon as possible & logging dc bus 14 & 18 voltages once per hr CLAYTON.F L Alabama Power Co 80/07/11 1p
- B007220510 Forwards process control program for radwaste solidification unit as discussed at 800709 meeting w/NRC CLAYTON,F L Alabama Power Co 80/07/14 1p

- --B007220515 Radiation Control & Protection Procedure FNP-0-RCP-474.
 Revision 1 "Mobile Salidatfiration Unit Operation"
 MCCRACKEN. & Alabama Power Co 80/01/10 59pp
- 8007220558 Forwards Revision I change pages to plant offsite dose calibr manual incorporates radiation monitor setpoint calculation methodology discoved during 800709 neeting w/NRC CLAYTON.F L Alabama Power Co 80/07/14 App
- 8007220554 Forwards auxiliary feedwater endurance test data & test info requested in NRC 800408 ltr CLAYIDN:F L Alabama Fower Co RO/07/16 20pp
- 8007/30403 forwards add1 info re degraded electrical power grid conditions in response to 800626 telcon Includes suppl to util 790115 ltr re assessmint of NRC Positions L.2 & 3 CLAYTONEF L. Alabama Power Co. 80/07/17 13pp
- BOO7230553 Forwards radiological Tech Spec info concerning hydrogenoxygen-nitrogen mixture curves & hydrogen recombiner instrumentation (alibr M/o encil CLAYTON.F L. Alabama Power Co. 80/07/17 Lp
- 8007300029 Forwards revised Pages 1 % 2 to NRC 800430 evaluation of util response to TMI Lessons Learned Category A Items
 VARGA.S A Operating Reactors Branch 1 80/07/23 4pp
- O Inspection reports, 1E Dulletins & correspondence
- 8007240108 Forwards IE Info Notice 80-20, "Less of Decay Hoat Removal Capability at Davis-Bosso Unit 1 While in Refueling Mode "
 No response required g'REILLY, J.P. Region 2, Atlanta, Office of the Pirector 80/05/08
- 8007020180 Forwards IF Info Nutrice 80-22, "Breakdowns In Contamination Control Programs" No written response required O'REICLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007210419 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assomblies " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/05/28 ip
- 8007010253 Forwards IC Info Notice 80-23, "Lass of Suction to Emergency Feedwater Pumps" No written response required 0'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/05/29
- 8007220040 Forwards IE Info Nutire 80-26, "Evaluation of Contractor GA Programs" No written response required 0 REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10
- B00/240369 Forwards IE Insp Rept 50-348/80-11 on 800527 No noncompliance noted \$70/84.0 P Region 2. Atlanta. Fuel facility & Materials Bafety Branch 80/06/10 2pp
- --B007240374 IE Insp Rept 40-340/80 ii on 800527 No noncompliance noted Major areas inspected major radiation emergency exercise TROJANDHSKI.R C. BRADFOKIJ.H H. Region 2. Atlanta. Bffice of the Director JONAINS.O R. Region 3. Atlanta. Fuel facility & Materials Safety Branch. 80/06/09 Spp
- 8007160218 Forwards IE Info Notice 80-77, "Degradation of Reactor Coolant Pump Stude " No specific action or response required O'RFILLY, J.P. Region 2, Atlanta, Uffice of the Director 80/06/11
- 8007020751 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Nobification Sys (FNS) W/Lnss of Officite Power " Written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/18
- 8007020785 Forwards IE Circular EO-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Conidens" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/20
- 8007070594 Forwards IE Insp Repts 50-548/80-10 t 50-364/80-11 on 800331-0425 No noncompliance noted LEMIS.R C Region & Atlanta. Reactor Operations Nuclear Support Branch 80/06/21 Spp

- --B007070397 IE Insp Repts 50-348/80-10 & 50-364/80-11 on B00331-0425 No noncompliance noted Hajor areas inspected hot functional testing. IE bulletin following & plant security MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch BRADFORD.W H Region 2. Atlanta, Office of the Director 80/05/21 6pp
- 8007160791 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLUJ P Region 2. Atlanta, Office of the Director 80/06/24 80/06/24
- 8007230206 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/2 80/06/27
- BOO7210265 Forwards response to IE Bulletin BO-OB. "Examination of Containment Liner Penetration Welds" All containment butt welds between penetration alseves & process piping in Unit i radiographed upon completion CLAYTON, F L Alabama Power Co 80/07/01 5pp
- 8007160549 Informs that requested actions re IE Bulletin 80-10 have been completed & are available for review at facility CLAYTON.F L Alabama Power Co 80/07/07 ip
- 8007290859 Responds to IE Bulletin 80-11. "Masonry Wall Design " All masonry walls, function of each wall & relation to safety-related equipment are listed & identified in encl walk-down summary sheets Sys supports sketch will be developed CLAYTON, F.L. Alabama Power Co. 80/07/07 9pp
- 8007250479 Responds to open items noted in 800324 rept of insp on 800226-29 re fire protection Obstructed sprinkler sys heads will be relocated per nat! fire protection stds CLAYION.F L. Alabama Power Co. 80/07/21 5pp
- R Periodic operating reports & related correspondence
- 6007070168 Forwards revised monthly operating repts for Mar 1979-May 1980 CLAYTON, F.L. Alabama Power Co. 80/06/30 1p
- ~~BC07070176 Revised monthly operating rept for Mar 1979 HAIRSTON,W G Alabama Power Co 79/04/01 1p
- --B007070180 Revised monthly operating rept for Apr 1979 HAIRSTON.W G Alabama Power Co 79/05/01 ip
- --B007070190 Revised monthly operating rept for May 1979 HAIRSTON, W O Alabama Power Co 79/06/01 ip
- --B007070194 Revised monthly operating rept for June 1979 HAIRSTON.W G Alabama Power Co 79/07/01 ip
- --B007070197 Revised monthly operating rept for July 1979 HAIRSTON.W G Alabama Power Co 79/08/01 1p
- --BO07070204 Revised monthly operating rept for Aug 1979 HAIRSTON.W G Alabama Power Co 79/09/01 ip
- ---8007070208 Revited monthly operating rept for Sept 1979 HAIRSTON.W G Alabama Power Co 79/10/01 ip
- --B007070214 Revised monthly operating rept for Oct 1979 HAIRSTON:W G Alabama Power Co 79/11/01 lp
- --BOD7070217 Revised monthly operating rept for Nov 1979 HAIRSTON,U G. Alabama Power Co. 79/12/01 ip
- --8007070219 Revised monthly operating rept for Dec 1979 HAIRSTON, U.G. Alabama Power Co. 80/01/01 ip
- --8007070223 Revised monthly operating rept for Jan 1980 HAIRSTON, W.C. Alabama Power Co. 80/02/01 lp
- -8007070226 Revised monthly operating rept for Feb 1980 HAIRSTON.W G Alabama Power Co 80/03/01 1p
- -B00707022B Revised monthly operating rept for Mar 1980 HAIRSTON,W G Alabama Power Co B0/04/01 ip

3

- --8007070230 Revised monthly operating rapt for Apr 1980 HAIRSTON, W G Alabama Power Co 80/05/01 ip
- --8007070232 Revised monthly operating rept for May 1980 HAIRBION, W G Alabama Power Co 80/04/01 ip
- 8007150662 Forwards monthly operating rept for June 1980 CLAYTON F L Alabama Power Co 80/07/11 ip
- -8007150468 Monthly operating rept for June 1980. HAIRSTON, 8 9 Alabama Power Co 80707/01
- S Reportable occurrences, LERs & related correspondence
- 8007160861 Part 21 rept re Westinghouse review of safety injection termination criteria following secondary side high energy line rupture w/potential for damage to centrifugal charging pumps Concerns are applicable to facility HAIRBYON.W G Alabama Power Co 80/06/13 2pp
- 8007010444 Forwards LER 80-036/03L-0 CLAYTON: F L Alabama Power Co 80/06/25 1p
- ~~B007010446 LER 80-036/03L-0 on 80052B, during performance of RHR valves inservice test, 1A RHR heat exchanger discharge valve failed to stroke close Gaused by cap screw connecting valve actuator to valve shaft coming out Cap screw replaced HAIRSTON, W G Alabama Power Co B0/06/25 2pp.
- 8007010404 Forwards LER 80-037/01T-0 CLAYTON,F L Alabama Power Co 80 80/04/27 in
- -8007010412 LER 80-037/01T-0 on 800613.Westinghouse notified util of potential for damage to centrifugal charging pumps due to inadequate flow following secondary side high energy line rupture Caused by inadequate consideration during design. HAIRSTON.H Q Alabama Power Co 80/06/27 3PP
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007020297 Forwards NRC Ofc of Nuclear Reactor Regulation B00428 raorganization chart Necessary period of transition made w/min disruption to angoing activities
 TEDESCO,R L Assistant Director for Licansing B0/06/19 2pp
- 8007210176 Forwards NRC evaluation of QE rept.NEDE-24010-P & Suppls I-3. "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SRSS) Mathod for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj.to certain constraints MATTBON.R J Division of Safety Technology 80/06/25 3pp
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EIBENHUT, D O Division of Licensing 80/06/26 2pp
- B007160451 Responds to ltr re facility Replacement power cost reported in NRC B00130 ltr is for fuel to operate plant Large part of replacement power would come from oil Intensity of recent earthquake was only fraction of DBE SCHMENCER: A Licensing Branch 2 80/06/27 11pp
- B00723062: Summary of B00612 meeting w/Mark II owners group in Bethesda.NO re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Visugraphs encl. ANDERSON.C J Generic Issues Branch 80/07/03 57pp
- 8007180285 Natification of 800711 meeting w/util in Bethesda, MD to discuss certain problems w/facility review SELLS.D Licensing Branch 2 80/07/11, 3pp
- 8007280471 Suggests 800704 meeting for presentation of info responding to NRC 800506 ltr re preliminary risk analysis Lists info to be presented Philadelphia Electric Co 80/07/21 ip.
- B007230175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago. IL to discuss lead Mark II plants chugging & C/O load space; ANDERSON. C Generic Issues Branch 80/07/23 2pp

O Adjudicatory correspondence

9007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
EISENHUT, D Q Division of Licensing 80/06/25 89pp

H Coneral correspondence

- B007100272 Ack receipt of itr re const of facility Station is not presently under active review Ltr will be kept on file & returned when util application for OL review is initiated SCHMENCER.A Licensing Branch 2 80/06/23 ip
- --8007100289 Requests that NRC reconsider opening facility PA has not improved radiation monitoring or emergency response since TMT Berious nuclear accidents can & will happen Homeowner insurence does not cover loss of life or damages CLARK.C Affiliation Unknown 80/06/23 2pp
- 8007110510 Responds to 800409 ltr re const of facility Environ & safety reviews will begin when util submits application for DL Ltr will be kept on file & referred to again when review initiated BCHMENCER.A Licensing Branch 2 80/06/23 2pp
- BO07140025 Ack receipt of B00610 ltr & resolution re const of facility Resolution will be considered along w/pther correspondence in future reviews relative to facility licensing BCHMENCER.A Licensing Branch 2 80/06/26 1p
- 8007160644 Forwards 800628 correspondence to President Carter, Governor Thornburgh, Senators Schweiker & Heinz, Representative Lederer, State Senator Fumo, State Representative Rappaport & MRC re haiting facility const HAMKINS, K.L. Pennsylvania, State of 80/06/28 7pp
- BOO7180345 Responds to 1tr re const of facility Ltr will be kept on file & referred to when NRC initiates OL review Facility will not be under active review until util submits OL application in late 1980 or warly 1981 SCHMENCER.A Licensing Branch 2 80/07/01 lp
- B007250004 Ack receipt of itr re const of plant Plant not under active review Public comments will be considered during review SCHMENCER.A Licensing Branch 2 80/07/14 ip
- 8007250475 Responds to 800630 1tr to NRC re const & operation of facility NRC welcomes citizen ltrs & takes them into consideration during environ & safety reviews Facility will not be reviewed until OL application is received SCHMENGER.A Licensing Branch 1 80/07/15 2pp

I. Financial information

- 800701013B Responds to 800605 1tr to 0 Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY, E Hearings Division 80/06/19 1p
- G Inspection reports: IE Bulletins & correspondence
- 8007140469 Forwards IE Bullstin 80-13, "Cracking in Core Spray Spargers" No written response required ORIER B H Region 1, Philadelphia, Office of the Director 80/05/12 1p
- 8007010258 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps." No written response required ORIER.8 H Region 1, Philadelphia. Office of the Director 80/05/29, ip
- 8007210604 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs " No written response required ORIER, B. H Region 1, Philadelphia, Office of the Director 80/06/10 1p
- 8007140280 Forwards IE Bulletin 80-14, "Degradation of BWR Stram Discharge Vol Capability " No written response required ' GRIER, B H Region i, Philadelphia, Office of the Director 80/06/12 ip
- 8007280608 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFRSO 55(e) " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/13 1p

- 8007020516 Forwards IE fircular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/06/20 1p
- 8007140728 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/05/24 ip
- B007210225 Forwards IE Info Notice B0-24, "Low Level Radwaste Burial Criteria " No written response required QRIER,B H Region 1, Philadelphia, Office of the Director BD/06/25 |p
- 8007210312 Ack receipt of 800410 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-352/79-12 & 50-353/79-11 ORIER, D H Region 1, Philadelphia, Office of the Director 80/06/26 200
- --8007210321 Responds to NRC 800312 ltr re violations noted in IE Intp Repts 50-352/79-12 % 50-353/79-11 Corrective actions Uncontrolled copies of pipe support drawing removed from field KEMPER.J S Philadelphia Electric Co 80/04/10 Spp
- --8007210326 Forwards IE Insp Repts 50-352/79-12 & 50-353/79-11 on 791120-30 & 1203-21 & notice of violation CARLSON:R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/03/12 2pp
- --8007210330 Notice of violation from insp on 791120-30 & 1203-21 * Region I, Philadelphia, Office of the Director 80/03/05 2pp
- --B00721033B IE Insp Repts 50-352/79-12 & 50-353/79-11 on 791120-30 & 1203-21 Noncompliance noted failure to control design documents for masonry walls & failure to provide GA program for masonry wall subcontractors

 MATTIA, J C Region 1, Philadelphia, Office of the Director MGGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/05 15pp
- 8007230159 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required ORIER, B H Region 1, Philadelphia, Uffice of the Director 80/06/27 Rpp
- 8007210567 Responds to IE Bulletin 80-08 Flued heads which are butt welded to containment penetration sleaves used in both units ASME Code Section III, 1974 through Winter 1974 addends, applied KEMPER.J S Philadelphia Electric to 80/07/02 7pp
- 8007210206 Ack receipt of 800623 ltr infurming NRC of steps taken to correct violations noted in IE Insp Repts 50-352/90-03 & 50-353/80-03 GARL80NR T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/03 lp
- --8007210214 Responds to NRC 800826 ltr re violations noted in IE Insp Repts 50-352/80-03 & 50-383/80-03 Corrective actions GA issued stop work orders on pipe restraint PR-279 MEMPER.J S Philadelphia Electric Co 80/06/83 2pp
- --8007210221 Forwards 1E Insp Repts 50-352/80-03 & 50-353/80-03 on B00225-0325 & notice of violation CARLBON,R T Region I. Philadelphia. Reactor Operations Nuclear Support Branch 80/05/26 2pp
- --8007210230 Notice of violation from insp on 800225-0325

 * Region 1, Philadelphia, Office of the Director 80/05/21 1p
- --B007210240 IE Insp Repts 50-352/80-03 & 90-35'J/80-03 on 800225-0325 Noncompliance noted failure to proheat weld joint prior to welding MATTIA-J C . FINKEL, A Region I. Philadelphia, Office of the Director MCGAUDIY. B W Region I. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/21 15pp

- S Reportable occurrences LERs & related correspondence
- 8007020155 Forwards survey or 800227 meeting wouth to discuss reporting requirements of significant design & const deficiencies No reply requested CARLSUNR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/27 Jp
- --8007020164 Summary of 800727 meeting w/util in Region 1 ofc to discuss reporting requirements of significant design & const deficiencies

 « Region 1. Philadelphia, Office of the Director 80/02/27 2pp
- 8007210015 Ack receipt of 800606 final deficiency rept re heating, ventilation & air conditioning damper Rept will be reviewed & evaluated CARLEGAR, PT Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 60,06/25 ip
- B007240226 Part II rept re defective Rosemount trip/calibr units & transmitters supplied by GE Caused by failure of essential switch that determines trip output logic Output of defective whits will be corrected per GE instructions

 KEMPER.J S Philadelphia Electric Co 80/07/01 5pp
- B007250152 Part 21 rept re defective GE trimp pins in electrical connectors Cause not stated Encl GE rept states that GA procedures have been modified to preclude defective crimping in foure

 WEMPER J S Philadelphia Electric Co B0/07/01 9pp
- 8007090265 Deficiency rept re Colt Industries emergency diesel gamerator heat exchangers Deviation between configuration of high heat exchanger stack on generator skid & configuration analyzed in sessamic rept detected KEMPER.J S Philadelphia Electric Co 80/07/02 2pp
- ---8007090270 Part 21 rept re Colt emergency diesel generator heat exchangers Deviation between configuration of high heat exchanger stack on generator skid & configuration analyzed in Seismic rept detected MORIARTY, J M Colt Industries, Inc 80/01/16 1p
- --B007090275 Part 21 rept re Colt emergency diesel generator heat exchangers Units & & 7 have been corrected by fitting shims at boiled interface between generator skid & heat exchanger mounting feet
 MORIARTY, J H Colt Industries, Inc 80/06/13 1p
- 8007250287 Ack receipt of 800620 final deficiency rept re 9 kV switchgear circuit breaker auxiliary switch crank assembly defect defect CARLSON,RT Region 1. Philadelphia. Office of the Director 80/07/03 1p
- 8007310281 Att receipt of 80070; final deficiency rept re defective crimps in electrical connectors CARLSON, T Region 1. Pulladelphia, Reactor Construction & Engineering Support Branch 80/07/fi ip
- ---B007310286 Gignificant Deficiency Rept 14 to defective crimps in electrical connectors GE rept submitted per JOCFR21 provides detailed sits insp info Rept encl KEMPER.J S Philadelphia Electric Co 80/07/01 2pp
- U Congressional/Elecutive Correspondence
- 8004280239 Requests appearance on behalf of subcommittee to testify on issues re emergency planning procedures & preparedness along wismpiscations of lessons learned from accident at TMI Hearing scheduled for 800527 UDALL-H K House of Rep . Interior & Insular Affairs 80/04/16
- 8007:1033B Responds to 800604 ltr expressing concerns about testimony of V Royer.util Senior Vice President HR Denton will meet w/ Royer on 800630 to discuss matter in greater detail DIRCKS.W J Office of the Excustive Director for Operations 80/06/30
- ---B007110343 Arquests that NRC seriously consider attitudes expressed by util during 800527 testimony & determine whether or not CP is consistent w/public health & safety KOSYMAYER, P H , MARKEY, E J House of Rep 80/06/04 3pp

- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8007020257 Forwards NRC OPC of Nuclear Reactor Regulation 900420 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 8007210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Bupple 1-3: "Technical Basis for Uso of Squaru-Root-of-Eum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark Il Plants "Rept acceptable subj.to certain constraints MATTSDN.R J Division of Safety Technology 80/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D. D. Division of Licensing 80/06/26 2pp
- 8007160491 Responds to ltr re facility Replacement power cost reported in NRC 800130 ltr is for funl to operato plant Large part of replacement power would come from oil Intensity of recent earthquake was only fraction of DBE BCHWENCER. A Licensing Branch 2 80/06/27 11pp
- 8007230621 Summary of 800612 meeting w/Mark II owners group in Bethesda.MD re lead plant closure & long-term program Moda should be made to generic lead plant condensation oscillation & chygging pool boundary leads Viougraphs encl ANDERSON.C J Generic Issues Branch 80/07/03 57pp
- 8007180285 Notification of 800711 meeting w/util in Bothesda, MD to discuss contain problems w/facility review SECLS, β Licensing Branch 2 80/07/11 3pp
- 8007250471 Suggests 800904 menting for presentation of info responding to NRC 800506 ltr re preliminary risk analysis Lists info to be presented BOYER. V S Philadelphia Electric Co 80/07/21 ip
- 8007290178 Notification of 800805 meeting w/representatives from Mark II swners group in Chicago. It to discuss lead Mark II plants chugging & C/O lead spacs ANDERSON.C Generic lasues Branch 80/07/23 #2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refire profection for electrical college EISENHUT.D G Division of Licensing 80/06/25 EISPP
- H General correspondence
- 8007100272 Ack receipt of itr re const of facility. Station is not grosently under active review Ltr will be kept on file & returned when util application for DL review is initiated. SCHMENCER, A Licensing Branch 2 80/06/23 ip
- --8007100287 Requests that NRC reconsider opening facility PA has not improved radiation monitoring or emergency response since TMI Berioth nuclear accidents can & will happen Hamsowner insurance does not cover loss of life or damages CLARK.C Affiliation Unknown 80/06/23 2pp
- 8007110510 Responds to 800409 ltr re const of facility Environ & safety reviews will bugin when util submits application for OL. Ltr will be kept on file & referred to again when review initiated SCHWENCER, A Licensing Branch 2 80/04/20 2pp
- BO07160644 Forwards BO0628 torrespondence to President Carter, Dovernor Thomburgh, Benators Bihweiker & Heinz, Representative Lederer, State Senator Fumo, State Representative Rappaport & NRC re halting Facility const HAMKINS, K L. Pennsylvania, State of 80/06/28 7pp
- 8007180345 Responds to itr re const of facility Ltr will be kept on file & referred to when NRC initiates OL review Facility will not be under active review until util submits DL application in late 1980 or early 1981 SCHMENCER, A Licensing Branch 2 80/07/01 ip
- 8007250004 Ack receipt of itr re const of plant Plant not under active review Public comments will be considered during review SCHWENCER.A Licensing Branch 2 80/07/14 ip

8007250475 Responds to 800630 ltr to NRC re const & operation of facility NRC welcomes citizen ltrs & takes them into consideration during environ & safety reviews Facility will not be reviewed untal OL application is received BCHMENCER, A Licensing Branch i 80/07/15 2pp

I Financial information

- BOO701013B Responds to 800405 ltr to G Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial incon stency identified CHRISTENBURY, E Hearings Division 80/06/19 ip
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7904120321 Rept on Zimmer Unit 1 Requests to be informed of NRC acceptance criteria & vaporization rate test results Considers NRC methodology of load combination acceptable CARBON, M M ACRS Advisory Committee on Reactor Safeguards 79/03/13 3pp
- O Inspection reports. IE Bulletins & correspondence
- B007140449 Forwards IE Bulletin B0-13, "tracking in Core Spray Spargers" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/05/12 1p
- 8007010258 Forwards IE Info Notice 80-29, "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/05/29 1p
- BG07210604 Forwards TE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director BD/06/10 ip
- BOO7140280 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director BO/06/12 ' 1p
- BOO7280608 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required ORIER. B H Region 1. Philadelphia, Office of the Director BO/06/13 ip
- BOO7020516 Forwards 1© Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required. ORIER.B H Region 1, Philadelphia, Office of the Director BO/06/20 1p
- 8007160728 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Hater Sys & Resultant Internal Contamination of Personnel " No written response required ORIER, B H Region I, Philadelphia. Office of the Director 80/06/24 ip
- SOO7210225 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/06/25 1p
- 8007210312 Ack receipt of 800410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/79-12 & 50-353/79-11 ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/26 2pp
- --8007210321 Responds to NRC 800312 ltr re violations noted in IE Insp Repts 50-352/79-12 & 50-353/79-11 Corrective actions uncontrolled copies of pipe support drawing removed from field KEMPER.J & Philadelphia Electric Co 80/04/10 5pp
- --B007210326 Forwards IE Insp Repts 50-352/79-12 & 50-353/79-11 on 79:120-30 & 1203-21 & notice of violation CARLSUN, R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch B0/03/12 2pp
- --B007210330 Notice of violation from insp on 791120-30 & 1203-21 * Region 1, Philadelphia, Office of the Director 80/03/05 2pi

- --8007210338 IE Insp Repts 50-352/79-12 & 50-353/79-11 on 791120-30 & 1203-21 Noncompliance noted failure to control design documents for misonry walls & failure to provide GA program for masonry wall subcontractors
 MATTIA.J C Region I. Philadelphia. Office of the Director MGGAUGHY, R W Region I. Philadelphia. Reacto: Construction & Engineering Support Branch 80/03/05 15pp
- 8007230159 Forwards IC Bulletin 80~16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes." Written response required IE Circular 80~16 also encl No written response required ORIER, 8 H Region 1 Philadelphia, Office of the Director 80/06/27 2pp
- 8007210567 Responds to IE Bulletin 80-08 Flued heads which are butt welded to containment penetration sleeves used in both units ABME Code. Section 111.1974 through Winter 1974 addends.applied KEMPER. J B Philadelphia Electric Co 80/07/02 7pp
- 8007210206 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-352/80-03 & 50-353/80-03 CARLSONR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/03 lp
- --8007210214 Responds to NRC 800524 ltr re violations noted in IE Insp Repts 90 382/80-03 & 50-351/80-03 Corrective actions GA issued stop work orders on pipe restraint PR-239 KEMPER.J S Philadelphia Electric Co 80/04/83 2gp
- --8007210221 Forwards 1E Insp Repts 50-352/80-03 t 50-353/80-03 on 800225-0325 t notice of violation CARLSON,R T Region I. Philadelphia, Reactor Operations Nuclear Support Branch 80/05/26 2pp
- --8007210230 Notice of violation from insp on 800225-0325
 * Region i, Philadelphia, Office of the Director 80/05/21 ip
- --8007210240 IE Insp Repts 50-332/80-03 & 50-35J/80-03 on 800225-0925 Noncompliance noted failure to preheat weld joint prior to welding MATTIA-J C , FINKEL,A Region 1, Philadelphia, Office of the Director MCGAUGHY.R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/21 15pp
- 8 Reportable occurrences. LFRs & related correspondence
- B007020155 Forwards summary of B00227 meeting w/util to discuss reporting requirements of significant design & const deficiencies Nu reply requested CARLSON, T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch B0/05/2/7 Ip
- --8007020164 Summary of 800227 meeting w/util in Region 1 ofc to discuss reporting requirements of significant design & const deficiencies * Region 1. Philadelphia, Office of the Director 80/02/27 2pp
- B007210015 Ack receipt of B00606 final deficiency vept re heating, ventilation & air conditioning damper Rept will be reviewed & evaluated CARLSON.R T Region 1. Philodelphia. Reactor Operations Nuclear Support Branch 80/06/25 ip
- B007240226 Part 21 rept re defertive Rosemount trip/calibr units & transmitters supplied by GE Caused by failure of essential switch that determines trip output logic Output of defective units will be corrected per GE instructions

 KEMPER, J 8 Philadelphia Electric Co 60/07/01 5pp
- 8007230152 Part 21 rept re defective GF crimp pins in electrical connectors Cause not stated Encl GE rept states that GA procedures have been modified to preclude defective crimping in feture
 KEMPER J B Philadelphia Flectric Co 90/07/01 9pp
- 8007090265 Deficiency rept is Colt Industries emergency diesel generator heat exchangers Deviation between configuration of high heat exchanger stack un generator skid & configuration analyzed in seismic rept detected KEMPER.J S Philadeiphia Electric Co 80/07/02 2pp

- --B007090275 Part 21 rept re Colt emergency diesel generator heat exchangers Units & & 7 have been corrected by fitting shims at bolted interface between generator skid & heat exchanger mounting feet MRRIARTY J M (olt Industries, Inc. 80/06/13 ip
- 8007250287 Ack receipt of 800620 final deficiency rept re 4 hV switchgear circuit breaker auxiliary switch crank assembly defect CARLSON, R T Region i, Philadelphia, Office of the Director 80/07/03 lp
- 80073102B1 Ack receipt of 800701 final deficiency rept re defective crimps in electrical connectors
 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 lp
- --BOO73102B6 Significant Deficiency Ropt 14 re defective crimps in electrical connectors OE rept submitted per 10CFR21 provides detailed site insp info Rept enc! KEMPER,J S Philadelphia Electric Co BO/07/01 2pp

U Congressional/Executive Correspondence

- BO04280239 Requests appearance on behalf of subcommittee to testify on issues re emergency planning procedures & preparedness along wimplications of lessons learned from accident at TMI Hearing scheduled for 800527 UDALL.M K House of Rep , Interior & Insular Affairs 80/04/16
- BOO7110338 Responds to BOO604 ltr expressing concerns about testimony of V Boyer, util Senior Vice President HR Denton will meet w/ Boyer on BOO630 to discuss matter in greater detail DIRCKS, W J Office of the Esecutive Director for Operations BO/06/30 lp
- --- BD07110343 Requests that NRC seriously consider attitudes expressed by util during 800527 testamony & determine whether or not CP is consistent w/public health & safety KOSTMAYER.P H , MARKEY.E J House of Rep B0/06/04 3pp

DOCKET 50-354 HOPE CREEK NUCLEAR STATION. UNIT 1

- A Application/construction stage documents & correspondence
- 8007010561 Forwards NRC reorganization thant for Oft of Nuclear Reactor Regulation effective 800428 Considerations of activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D G Division of Licensing 80/06/26 2pp
- 8007080191 Forwards Qualification Summary Repts 33-52260-QS for Hope Creek & 33-54237-QS for River Bend reflecting documentation of electrical equipment qualification Repts withheld (ref 10CFR2 790)

 BUVALL, D D Gould-Brown Bovers 80/07/01 lp

G Adjudicatory correspondence

- B007080086 Proposed findings of fact & conclusions of law responding to ASLAE questions on Battelle rept Findings are adopted by TMI-2/Peachbottom Intervenors & Ecology Action Urges suspension of QLs Certificate of Svc encl
 KEPFCRD.C Environmental Coalition on Nuclear Power B0/06/18
 12pp
- 8007080046 Response to ASLAB request re Deficiency 1 Urges reversal of decision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated CAPLAN.R Ecology Action of Oswego 80/06/20 2pp
- 8007080048 Proposed findings of fact endorsing Citizens for Safe Environ filing re radiation source terms from U mining & milling Rejects Perkins rationale & urges development of further evidence re failure mechanisms & human factors CAPLAN, R Ecology Action of Oswego 80/06/20 4pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 0 Division of Licensing 80/06/25 89pp

- B0070B0001 Proposed findings of fact & conclusions of law in form of memorandum & order affirming ASLD 7B0714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BDRDENICK.B M Hearing Branch 4 80/07/03 5Bpp
- --8007080003 Proposed corrections to 800226 transcript BORDENICK, B M Hearing Branch 4 80/07/03 2pp
- --8007080006 Motion to include de minimus theory of health effects in NRC 800703 findings of fact & conclusions of law presented in form of memorandum & order Inclusion is consistent w/ALAB-509, ALAB-540 & ALAB-542 Certificate of Syc encl BORDENIC. K Hearing Branch 4 80/07/03 7pp
- 8007100258 Order granting Ecology Action of Oswego motion to file 800620 submission re generic radon issue BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/07
- 800731012B Response in opposition of NRC B00703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from consideration Supporting news articles encl CAPLAN.R Ecology Action of Oswago 80/07/16 13pp
- 8007250353 Forwards revised Pages 7 & 16 to licensees reply to proposed findings of fact submitted by other parties filed on 800718 Revised pages required to correct typographical errors Svc list encl
 TRAVIESO-DIAZ Shaw, Pittman, Potts & Trowbridge 80/07/21 10pp

H General correspondence

- 8007180060 Responds to 800311 request for info needed for fuel cost study Forwards excerpts of WASH-740.WASH-1224.WASH-1230, WASH-1400.NUREG-0020 (Vol 4.Number 1).NUREG-0480.NUREG-0512.NUREG-0517.NUREG/CR-1040 & FES DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/14 153pp
- ---8007180063 Requests documents containing info needed for fuel cost study HILGER,W Affiliation Unknown 80/03/11 2pp
- P Operating license stage documents & correspondence
- B007230028 Summary of B00207 meeting w/Mark I owners group in Bethesda, MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-torm program GRIME8,C T Plant Systems Branch B0/02/21 3ipp
- Q Inspection reports, IE Bolletins & correspondence
- B007140431 Forwards IE Bullstin 80-13, "Cracking in Core Spray Spargers " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/05/12 ip
- 8007010271 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps." No written response required GRIER, B. H. Region 1. Philadelphia. Office of the Director 80/05/29 ip
- 800717026B Forwards IE Insp Repts 50-354/80-03 & 50-355/80-03 on 800303-28 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --8007170274 IE Insp Repts 50-354/80-03 & 50-355/80-03 on 800303-28. No noncompliance noted Major areas inspected weld rod control, stored equipment maint, structural steel welding & electrical work status
 BATEMAN.W H , MCGAUGHY,R W Region 1, Philadelphia, Office of the Director 80/05/28 8pp
- 800721030B Forwards IE Insp Repts 50-354/80-06 & 50-355/80-06 on 800423-25 & 27 No noncompliance noted CARLSON.R T Region t. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/04 2pp
- --8007210309 IE Insp Repts 50-354/80-06 & 50-355/80-06 on 800423-25 & 29
 No noncompliance noted Major areas inspected noncompliance control: trend analysis & control of field charge request.
 CHAUDHARY, S K Region i, Philadelphia, Office of the Director EDNETER, S.D. Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/23 App

- 8007210612 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ORIER. B H Region 1, Philadelphia, Office of the Director 80/06/10 ip
- B007140284 Forwards IE Bulletin 80-14. "Degradation of BMR Scram Discharge Vol Capability " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director B0/06/12 1p
- B007280514 Forwards IE info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required ORIER.9 H Region 1, Philadelphia, Office of the Director B0/06/13 ip
- 8007300317 Forwards IE Insp Repts 50~354/80~08 & 50~355/80~08 on 800512~16 No noncomplience noted CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/13 2pp
- 8007280242 Forwards IE Insp Repts 50-354/80-05 & 50-355/80-05 on 800421-25 No noncompliance noted CARLSON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/16 Zpp
- --8007280246 IE Insp Repts 50-354/80-05 & 50-355/80-05 on 800421-25 No noncompliance noted Major areas inspected reactor vessel nozzle safe end field changes & welding of safety-related piping REYNOLDB-8 D Region i, Philadelphia, Office of the Director TRIPP.L E Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 5pp
- B007170654 Ack receipt of B00428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-02 & 50-355/80-02 CARLBON.R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch B0/06/17 ip
- --8007170665 Forwards IE Insp Repts 50-354/80-02 & 50-355/80-02 on 800204-29 & notice of violation CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8007170670 Natice of violation from insp on 800204-29
 * Region 1, Philadelphia, Office of the Director 80/03/19 2pp
- --B007170482 IE Insp Repts 50-354/B0-02 & 50-355/B0-02 on B00204-29 Noncompliance noted failure to establish measures to maintain cleanliness of relief valve piping stored in suppression chamber & to maintain weld rod control BATEMAN.W H , MCOAUGHY.R W Region 1, Philadelphia, Office of the Director B0/03/19 9pp
- BO07020503 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIERS H Region 1, Philadelphia, Office of the Director BO/06/20 1p
- 8007140737 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER B H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- B007210278 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria." No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/25 ip
- 8007210274 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-02 & 50-355/80-02 CARLSON,R T Region i, Philadelphia. Reactor Construction & Engineering Support Branch 80/06/27 ip
- --8007210282 Responds to NRC 800324 ltr re violations noted in IE Insp Repts 50-354/80-02 & 50-355/80-02 Corrective actions documented interline cleanliness & hired GC inspector MARTIN.T. J Public Service Electric & Cas Co of New Jersey, 80/05/28 2pp

- 8007230170 Forwards IE Dulletin 80-16, "Potential Misapplication of Rosmount Inc Models 1151 & I152 Pressure Transmitters W/Either A or D Output Codes" Hitten response required IE Circular 80-16 also encl No written response required GRIER.D M Region I, Philadelphia, Office of the Director 80/06/27 2pp
- 8007250279 Submits reply to 16 Builetin BO-08 re containment liner penetration welds No flued heads have been installed to date Joints are considered Class II & radiography will be performed MARTIN.T J Public Service Electric & Gas Co of New Jersey BO/07/02 2pp
- B Reportable occurrences. LERs & related correspondence
- 8007310289 Ack receipt of 800629 interim deficiency rept re primary containment relief valves supplied by GPE Controls CARLSONR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/11 ip
- --B007310293 Potential significant deficiency rept re-primary containment relief valves supplied by GPE Controls Bechtel has completed review of reviseed stress analysis calculations Expected completion date of actions is 800815

 MARTIN.T J Public Service Flectric & Qas Co of New Jorsey
 B0/04/25 in
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8007230028 Summary of 800207 meeting w/Mark 1 owners group in Bathasda. NO.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES.C T Plant Systems Branch 80/02/21 31pp
- 8007010561 Forwards NRC reorganization chart for DFc of Nuclear Reactor Regulation, effective 800428 Considerations of activities should be made through assigned mpt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 3pp
- 8007230001 Forwards statement of policy re requirements to be mot for current OL applications, as derived from NUREG-0660 & found in NUREG-0674 EIBENHUT.D 9 Division of Licensing 80/06/26 2pp
- BOD7080191 Forwards Qualification Summary Repts 33-52260-08 for Hope Creek & 33-54237-08 for River Bend reflecting documentation of electrical equipment qualification Repts withheld (ref 10CFR2 790) DUVALL, D D Gould-Brown Boveri 80/07/D1 ip
- @ Adjudicatory correspondence
- 800708008A Proposed findings of fact & conclusions of law responding to ABLAB questions on Battelle rept Findings are adopted by TMI-2/Pacthottom Intervenors & Ecology Action Urges suspension of DLs Certificate of Svc encl
 KEPFORD, C Environmental Coalition on Nuclear Power 80/06/18
 12pp
- BOO7080046 Response to ABLAB request re Deficiency 1 Urges reversal of decision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated CAPLAN.R Ecology Action of Oswego 80/06/20 2pp
- 8007080048 Proposed Findings of fact endorsing Citizens for Bafe Environ filing to radiation source terms from U mining & milling Rejects Perkins rationals & urges development of further evidence re failure mechanisms & human factors CAPLAN.R Ecology Action of Oswago 80/06/20 4pp
- B007310243 Forwards Commission 800527 memorandom & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandom & order UCS 771104 potition sought action refire protection for electrical cables EISENRUT.D & Division of Licensing 80/06/25 B9pp
- 8007080001 Proposed findings of fact & conclusions of law in form of memorandum & order affirming ABLB 780714 partial initial decision & advising that radon releases associated w/U fuel cycle are insignificant in striking cost/benefit balance BORDENICK, B M Hearing Branch 4 80/07/03 58pp
- --B0070B0003 Proposed corrections to 800226 transcript BORDENICK.B M Hearing Branch 4 80/07/03 2pp

- ---B0070B0006 Motion to include de minimus theory of health effects in NRC 800703 findings of fact & conclusions of law presented in form of memorandum & order Includion is consistent U/ALAB--- 509. ALAB-540 & ALAB-562 Certificate of Svc encl BORDENIC, K Hearing Branch 4 80/07/03 7ap
- B007100258 Order granting Ecology Action of Oswego motion to file B00620 submission re generic radon issue BISHOP.C J. Atomic Safety and Licensing Appeal Panel B0/07/07
- 8007310128 Response in opposition of NRC 800703 pleading asserting validity of Perkins record on radon releases from U mining & milling Objects to NRC position eliminating health effects issues from consideration Supporting news articles encl CAPLAN.R Ecology Action of Oswego 80/07/16 13pp
- 8007250353 Forwards revised Pages 7 & 16 to licensees reply to proposed findings of fact submitted by other parties filed on 800718 Revised pages required to correct typographical errors Syc list enti
 7RAVIESO-DIAZ Shaw, Pittman, Potts & Trowbridge 80/07/21 10pp
- H General correspondence
- 8007180060 Responds to 800311 request for info needed for fuel cost study Forwards excerpts of WASH-740, WASH-1224, WASH-1250, WASH-1400, NUREG-0020 (Vol. 4, Number 1); NUREG-0480, NUREG-0512, NUREG-0517, NUREG
- --8007180063 Requests documents containing info needed for fuel cost study HTLGER: H Affiliation Uninown 60/03/11 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007140431 Forwards IE Bulletin BO-13. "Cracking in Core Spray Spargers." No written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/05/12 ip
- 8007010271 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required GRIER B H Region 1. Philadelphia, Office of the Director 80/05/29 ip
- B007170269 Forwards IE Insp Repts 50~354/80-03 & 50-355/80-03 on 800303-28 No noncompliance noted CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/30 2pp
- --8007170274 IE Insp Repts 50-254/80-03 & 50-255/80-03 on 800303-28 No noncompliance noted Major areas inspected weld rod control, stored equipment maint, structural steel welding & electrical work status
 BATEMAN.W.H. MCGAVCHY.R.W. Region 1, Philadelphia. Office of the Director 80/05/28 8pp
- 8007210308 Forwards IE insp Repts 50-354/80-06 & 50-355/80-06 on 800423-25 & 27 No noncompliance noted CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/86/04 2pp
- --B007210309 IE Insp Repts 50-354/80-08 & 50-355/80-06 on B00423-25 & 29
 No noncompliance noted Major areas inspected noncompliance
 control trend analysis & control of field change request
 CHAUDHARY, S K Region 1. Philadelphia. Office of the Director
 EBNETER, S D Region 1. Philadelphia. Reactor Construction &
 Engineering Support Branch 80/05/23 App
- B007210612 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required GRIER, B M Region I, Philadelphia, Office of the Director B0/06/10 Ip
- 3007140284 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required GRIER. B H Region 1, Philadelphia, Office of the Director BO/06/12 ip
- D7280614 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CR850 55(e)" No written response required RRIER. BH Region 1, Philadelphia. Uffice of the Director. 30/06/13 ip

- 8007300317 Forwards IE Insp Repts 50~354/80-08 & 50~355/80-08 on 800512-16 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/13 2pp
- --8007300321 IE Insp Repts 30-354/80-08 & 50-355/80-08 on 800512-16 No noncompliance noted Major areas inspected welding matl control reactor vessel nossle/safe-end field change welding & safety-related pipe welding REYNOLDS: D Region 1. Philadelphia, Office of the Director TRIPF L E Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 8pp
- 8007280242 forwards IE Insp Repts 80-354/80-05 & 50-355/80-05 on 800421-25 No noncompliance noted GARLEON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/14 Zpp
- --8007280246 IE Insp Repts 50-354/80-05 & 50-355/80-05 on 800421-25 No noncompliance noted Major areas inspected reactor vessel nozzle safe and field changes & welding of safety-related piping REYNOLDS, 8 D Region i, Philadelphia. Office of the Director TRIPP, L E Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 5pp
- 8007170654 Ack receipt of 800428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-02 & 50-355/80-02 CARLSON.R 7 Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/17 ip
- --8007170665 Forwards IE Insp Repts 50-354/80-02 & 50-355/80-02 on 800204-29 & notice of violation CARLSON, R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/03/24 2pp
- --8007170570 Notice of vialation from insp on 800204-29
 * Region 1, Philadelphia, Office of the Director 80/03/19 #ps.
- --80071706B2 IE Insp Repts 50-354/80-02 & 50-359/80-02 on 800204-29 Noncompliance noted failure to establish measures to maintain cleanliness of relief valve piping stored in suppression chamber & to maintain weld rod control BATEMAN, W H., MCGAUGHY, R W. Region 1, Philadelphia, Office of the Director, 80/03/19 9pp
- 8007020503 Forwards IE Circular 80-13, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director. 80/06/20 ip
- B007160737 Forwards IE Circular 80~14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER, 8 H Region 1. Philadelphia, Office of the Director 80/06/24 ip
- 8007210278 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/25 ip
- B007210276 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-354/80-02 & 50-355/80-02 CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/27 Ip
- ---8007210282 Responds to NRC 800324 ltr re violations noted in IE Insp Repts 50-384/80-02 & 50-385/80-02 Corrective actions documented interline cleanliness & hired GC inspector MARTIN.T J. Public Service Electric & Qas Co, of New Jersey 80/05/28 2pp
- B007230170 Forwards IE Bullstin 80~16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters WEither A or D Output Codes" "Further response required IE Circular 80~16 also encl No written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/06/27 2pp
- BOD7250299 Submits reply to IE Bullstin 80-08 re containment liner penetration wolds No Flued heads have been installed to date Joints are considered Class II & radiography will be performed MARTIN, T J Public Service Electric & Gas Co of New Jersey BO/07/02. 2pp

- 8 Reportable occurrences, LERs & related correspondence
- 8007310289 Ack receipt of 800625 interim deficiency rept re primary containment relief valves supplied by OPE Controls CARLBON.R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 80707/11 lp
- ---B007310293 Potential significant deficiency rept re primary containment relief valves supplied by GPE Controls Bechtel has completed review of revised stress analysis calculations Expected completion date of actions is B00815
 MARTIN.T J Public Service Electric & Gas Co of New Jersey B0/06/25 ip
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- BOO7170644 Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required MEPPLER.J & Region 3, Chicago, Office of the Director BO/06/24
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007020232 Forwards NRC Ofc of Nuclear Reactor Regulation 600428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDE600.R L. Assistant Director for Licensing B0/06/13 2pp
- 8007030239 Notification of 800702 meeting w/BWR licensing review group in Bethesda.MD to discuss consensus position on reactor svc bldg open issus HILBON, J N Licensing Branch i 80/06/18 9pp
- B007010297 Bummary of 800613 meeting w/utils.RMC.Inc.GE.Bechtel,S&W & Sargent & Lundy in Bethesda,MD re consensus positions on reactor svc bldg & isolation cooling sys bldg open issues from La Balle docket Status repts encl
 WILSON,J N Assistant Director for Licensing 80/06/19 46pp
- 8007210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls 1-3. "Technical Basis for Use of Square-Root-of-Sum-of-Bquares (SRSS) Nethod for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj. to certain constraints MATTSON.R J Division of Bafety Technology 80/06/25 Opp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0644
 EISENMUT, D G Division of Licensing 80/06/26 2pp
- B007170475 Summary of B00613 meeting w/Mark II lead plant applicants re definition of T-quencher load spec following safety/relief valve actuation Viewgraphs encl
 BU,T M Containment Systems Branch 80/06/27 App
- 8007230232 Bummary of 800613 meeting w/Mark II lead plant applicants re methodology proposed by applicants to define T-quencher load spec following safety relief valve actuation New methodology will be applicable to all Mark II lead plants BU.T M Queneric Issues Branch 80/06/27 3pp
- BOO70B0317 Submits comments in response to NRC 800307 ltr & NUREG-0619. re mods to BWR control rod drive sys NRC position re cutting capping & rerouting control rod drive not applicable to facility Voices concern on insp time required BORGMANN, E A Concinnati Gas & Electric Co 80/06/30 2pp
- 8007170339 Notification of reschoduling of 800702 meeting w/BWR licensing review group in Bethesde,MD to discuss consensus positions on Reactor Sys Branch open issues Meeting rescheduled for 800709 HILSON,J N Assistant Director for Licensing 80/07/03 1p
- --8007170347 Notification of 800722 meeting w/BWR licensing review group in Bethesda, MD to discuss TMI issues required for OL issuence WILBON, J N Assistant Director for Licensing 80/07/03 ip
- --8007170351 Notification of 800724 meeting w/BWR licensing review group in Bethesda, MD to introduce BWR licensing review group & present consensus positions for Power Sys Branch, Containment Sys Branch & Equipment Qualification Branch HILBON, J N Assistant Director for Licensing 80/07/03 9pp

- 8007230621 Summary of 800612 meeting w/Mark 11 owners group in Bothosds.MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON.C J. Generic Issues Branch 80/07/03 5/pp
- B007280123 Summary of B00624 meeting w/util % Sargent & Lundy in Bethesda.MD rc briefing on results of investigation & corrective actions on svc water pump noise & vibration & silt buildup in intake stieuture
 PECTIGN:I A Licensing Branch 2 B0/0//:5 54pp
- 8007230133 Notification of 800725 meeting w/DWR Licensing Review Order in BethesdarMD to discuss concensus positions of BWR Licensing Review Group on ICSB open issues WILBON.J N Licensing Branch 1 80/07/16 10ap
- BD07220280 Forwards drawings re Category I masonry wails, per NRC request for add) info Oversize drawings available in Central Files only FLYNN, J D Cincinnati Gas & Flectric Co 80/07/18 ip
- 8007290175 Notification of 800805 meeting w/iepiesentatives from Mark It numers group in Chicago,IL to discuss lead Mark II plants chugging & C/D load specs ANDERSON.C Generic Issues Branch 80/07/23 2pp
- F Security, medical, emergency & fire protection plans
- BOO707025B Forwards Amend 107,Revision 10 to andustrial security plan Plan withheld (ref 107FR2 770) BORGMARKNE A Cincinnati Gas & Electric Co 80/07/03 2pp
- O Adjudicatory correspondence
- BD07110094 Contentions per discussions w/HRC & applicant re GL application Allogen absence of adequate communication sysfor coordination & direction of evacuation Certificate of Svc encl DENNISON A B Zimmer Area Citizens Zimmer Area Citizens of KY DENNISON A B Dennison A B B0/05/13 15pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENRUT.D G Division of Licensing 80/06/25 87pp
- 8007080209 Memorandum & order granting Zimmer Area Citizens petition to intervene & subjecting contentions to LNP-EO-14 discovery schedule Modifies LBP-BO-14 re admittance BECHHOEFER, C Atomic Bafety and Licensing Board Panel 80/07/02 180a
- 8007110330 Older granting extension until 800715 for Commission to elect whether to review ALAB-195
 HDYLE.J C Office of the Springery of the Commission 80/07/09
- 8007220565 Motion & memoranoum speking admission of add1 cententions Augstions applicant financial capabilities & alleges errors in FES.NUREG-0625 Prucess used for cost/benefit analysis is contrary to NEPA Certificate of Svc encl MDLIVER, J Frankhauser, D D WOLIVER, J Woliver, J D 80/07/16 dap
- K Utility Final Safety Analysis Report (FSAR) & amends
- B0071403A9 Forwards Revision 66 to F9AR submitted as Amend 108 to 0L application in response to NRC 791812 % 27 & 800117 ltrs B0RGMANNEA Cincinnati Gas & Electric Co 90/07/11 2pp
- --B007140377 Revision 66 to FBAR, submitted as Amend 108 to DL application * Cincinnati Gar & Electric Cn 80/07/11 35pp
- B007210424 Furwards Certificate of Svt of Amend 108 to applications for OLs.in form of Revision 66 to FSAR
 BORGMANN,E A Cincinnati Gas & Electric Co 80/07/15 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007140554 Folwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required KEPPLER, J G Region 3, (hicago, Office of the Director 80/05/12 to

- BOO7110477 Forwards lE Insp Rept 50-358/80-10 on 800501-02 No muncompliance noted FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/27 2pp
- Universities and tracers and the sector Construction & Engineering Support Branch NAIDU, K.R. Region 3, Chicago, Office of the Director 80/05/21 App
- 8007020034 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required KEPPLER.J G Region 3: Chicago, Office of the Director 80/05/28
- 8007010071 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER.J O Region 3. Chirago. Office of the Director 80/05/29
- 8007220176 Forwards 1E Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/10
- 8007240236 Forwards IE Insp Rept 50-358/80-12 on 800501-02,05-09,12-16, 19-23 & 27-30 & notice of violation HEISHMAN,R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 80/06/10 2pp
- --- 8007240240 Natice of violation from insp on 800501-02,05-09,12-16, 7-23 & 27-30

 Region 3, Chicago, Office of the Director 80/06/06 ip
- --8007240253 IE Insp Rept 30-258/80-12 on 800501-02.05-09.12-16.19-23 & 27-30 Noncompliance noted failure to control cleanliness of cable trays DANIELB,F T , TAMBLING,T N Region 3, Chicago, Office of the Director 80/05/06
- 8007010084 Forwards info to complete response to IE Bulletin 79-02.

 "Pipe Support Base Plate Designs Using Concrete Expansion
 Anchor Bolts " Encl lists supports for assential & seismic
 namessential piping sys supported by expansion anchor bolts
 BOROMANN.E A Cincinnati Gas & Electric Co 80/06/11 2pp
- 800714040: Forwards [E Bulletin BO-j4, "Degradation of BWR Scram Discharge Vol Capability " No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/12
- 8007230072 Forwards 1E Insp Rept 50-358/80-13 on 800513:14 & 23 & notice of violation FIDRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/12 2pp
- ---B007230078 Notice of violation from insp on B00513,14 & 23 ** Region 3. Chicago, Office of the Director ** 80/06/11 80/06/11 1p
- --B007230087 IE Imap Rept 50-358/B0-13 on 800513,14 & 23 Noncompliance noted inadequate design consideration for pipe whip restraint connection bolts
 DANIELSON, DH Region 3. Chicago, Reactor Construction & Engineering Support Branch YIN, I T Region 3. Chicago, Office of the Director B0/06/11 4pp
- BO07280657 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(g)" No written response required KEPPLER, J. G. Regaon G. Chicago, Office of the Director 80/06/13
- 8007020335 Forwards 1E Circular 80-15, "Loss of Reactor Cociant Pump Gooling & Natural Circulation Cooldown " No written response required MEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/20
- 800/170459 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required REPLER.J G Region 3, Chicago, Office of the Director 80/06/24

- 8007230307 Forwards IE Bulletin 80-16, "Potential Misapplication of Resembunt Inc Models 1151 & 1152 Pressure Transmitters Weither A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/2; 80/04/27.
- 8007190102 Ack receipt of 800603 ltr informing NRC of steps taken to carrect violations noted in IE Insp Rept 30-358/80-08 HEISHMAN R F Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/30 2pp
- --B0D715010B Responds to NRC B00513 ltr re violations noted in IE Inep Rept 50-35B/80-0B Corrective actions nuclear engineering procedure revised requiring fuel assembly location verification & that insp & inventory records be microfilated BORGMANN,E A Cincinnati Gas & Electric Co BD/06/03. 4pp.
- 8007210313 Responds to NRC ltr re violation noted in IE Insp Rapt 50-358/80-12 Corrective actions debris & rubbish removed & cleaning crews assigned to reactor & auxiliary bidgs on westly schedule BOROMANN-E A. Cincinnati Gas & Electric Co 80/06/30 2pp
- B00725061& Supple B00321 response to IE Bulletin 80-03 re loss of chargoal from std adsorber cells Perforated plates connected to both top & bottom plates w/continuous weld, precluding any possibility for charcoal leakage.
 BDRGMANN,E A Cincinnati Gas & Electric Co. 80/06/30 2pp.
- 8007080374 Requests exception to requirement of ABME, Rection XI, 1974 edition or preservice insp program. Surface exam will be substituted for volumetric exam on piping support shear lugs welded by full penetration welding to Class I piping.

 BDROMANN, E A Cincinnati Gas & Electric Co. 80/07/01, Spp.
- B007250576 Responds to IE Bulletin 80-08 re examination of containment liner genetration welds. Joint detail on Penetration Types 38.44-0.6 & 5 does not parait meaningful radiographic insp. due to more complex geometry B0R0MANN.E A Cincinnati Cas & Electric Co 80/07/07 41pp.
- B007280096 Responds to IE Bulletin 79-03A, "Langitudinal Held Defects in ABME 8A-312, Type 304 Stainless Steel Pipe," 8A-312 or A-312. Type 300 series fusion welded pipe are not used at facility All BA-312 or A-312 piping used is seamless B0R0MANN.E A Cincinnati Gas & Electric Co 80/07/08, 1p.
- 8007R10297 Ack receipt of 800430 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/80-12. HEISHHAN, R F. Region S. Chicago, Reactor Operations Nuclear Support Branch 80/07/11 lg
- -8007210302 Responds to NRC 800610 ltr re violations noted in IE Insp Rept 50-358/80-12 Corrective actions cleanup crews dispatched to remove cable pan debris SOROMANN.E A Cincinnati Cas & Electric Co 80/06/30. Epp.
- BO07230437 Forwards rasponse to IE Bulletin BO-11 re Category I contrets masonry walls Hells are not subjected to wind, tornado, missile, pips whip restraint or impingement loads. Drawings forwarded under separate cover BORGMANN, E A Cincinnati Gas & Electric Co BO/07/18 18pp.
- S Reportable occurrences, LERs & related correspondence
- 8007020324 Ack receipt of 800527 interim deficiency rept re walds rejected upon radiographic review. FioRELI.G. Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/04/17 ip
- 8007110238 Ack receipt of 800611 ltr par 10CFR50.58(a) re fire in Gould-Brown-Boveri motor control ctr Review will be completed during future insp FIDRELLI.9 Region 3. Chicago: Reactor Construction & Engineering Support Branch 80/06/19 ip
- 8007(50029 Ack receipt of 8006): interim deficiency rept re failure of power shield relays Will review finel rept upon receipt. FloRELLI.G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/24 ip
- 8007180503 Ack receipt of 800527 final deficiency rept re design deficiencies Review will be completed during future inea FIGRELLI.G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/08 ip

- DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B007010560 Forwards NRC reorganization chart for Dfc of Nuclear Reactor Regulation, effective B00428 Considerations re activities should be made through assigned mgt representative Areas of disagreement may be discused through informal appeal TEDEBCO,R L Assistant Director for Licensing B0/06/13 2pp
- 8007070421 Bummary of 800528 meeting w/NRC consultant, Energy Technology Engineering Ctr,& applicant in Whittier, CA re Mechanical Engineering Branch open items re FSAR Draft safety evaluation, agenda & attendance list encl ROOD,# Licensing Branch 3 80/06/16 24pp
- 8007020208 Natification of 800702 meeting w/util in Dethesda.ND to discuss control room design review program RODD-H Licensing Branch 2 80/06/23 3pp
- 8007020673 Requests addl info to define underclad cracking potential in reactor vessel norzles Ultrasonic exams did not indicate explicit correlation between observed cracking & pre/post-heat treatment Info required within two weeks BCHWENCER, A Licensing Branch 3 80/06/24 4pp
- BO07010479 Forwards affidavit of svc attesting to completion & distribution of responses to NRC financial analysis Guestions 1-9
 BASKIN, K P Southern California Edison Co BO/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0640 & found in NUREG-0649
 EISENHUT.D C Division of Licensing 80/06/26 2pp
- B007010358 Forwards "Preliminary Rept on Geologic Drilling & Investigation San Onofre Nuclear Generating Station Units 2 & 3 & 61 geophysical maps (interpretations) prepared by PJ Fischer of CA State Univ sn.1
 BASKIN.K P Southern California Edison Co 80/06/27 lp
- --B007010364 "Preliminary Rept on Geologic Drilling & Investigation San Gnofre Nuclear Generating Station Units 2 & 3 " BANNEICH. J A , BROGAN, G E Woodward-Clyde Consultants, Inc B0/06/27 47pp
- --8007010374 Bixty-one 3 5 kHz high resolution seismic lines List of # California State Univ. Northridge 80/06/09 62pp
- 8007090234 Urgss extension of comment period for NUREC-0577 & 800319 amend until 800915 More stringent requirements broader applicability & EPRI study results warrant addl time OlLMAN,D W San Diego Gas & Electric Co 80/06/30 ip
- 0007230635 Forwards std order for DDE work MATTSON, R. J. Division of Safety Technology FIN A-1121-0 80/06/30 3pp
- --8007230652 Std order for DOF work "Review of Auxiliary Feedwater Sys Reliability Evaluation Studies for Diable Canyon i. McOure i.Summer i& Ban Onofer 2 & ECCS Reliability Analysis of Manual vs Automatic "Issued to Sandia Labs ORENIER. B i. Division of Safety Technology FIN A-1121-0 BD/06/27 9pp
- BOO7080081 Forwards response to NRC Question 361 65 in geoscience area Also forwards Woodward Clyde Consultants "Preliminary Rept on Geologic Drilling & Investigation Songs,Units 2 & 3, Ban Choffe,CA"

 BASKIN,K P Southern California Edison Co 80/07/01 18pp
- --8007080083 "Preliminary Rept on Goologic Drilling & Investigation Songs, Units 2 & 3, San Onofre, CA " * Woodward-Clyde Consultants, In: 80/07/01 40pp
- BOO7170693 Advises of NRC acreptance of Amend 3 to Topical Rept. 8CE-1-A, "GA Progrem " Topical rept must be referenced in Chapter 17 of BAR HAASS,W P Guality Assurance Brench 80/07/01 1p
- 8007210033 Notification of 800724 meeting w/util in Rosemead CA to discuss results of Imperial Valley Oct 1979 earthquake analysis wing Unit 1 analytical modeling technique ROOD H Licensing Blanch 3 80/07/11 702

- B007210463 Forwards supplemental calculations & Revision 1 pages to original calculations submitted to NRC on B00121 re design calculations of electrical tunnel BASKIN.K P Southern (alifornia Editon Co 80/07/16 35pp
- 8007280485 Ack receipt of NRC icspanse to Marine neview Committee 791009 rept re facility radiological monitoring program evaluation Detailed response will be submitted following matl review
 FISCHER.M L (alifornia, State of 80/07/18 ip
- B007290620 Forwards response to NRC 800624 request for info re potential for underclad cracking in reactor vessel noizles Noizle base mital math is SA-508 Class II Applicable math certification data sheets incl BASKIN.K P Southern California Edison Co 80/07/22 37pp
- 8007310465 Forwards NR(review of Marine Review Committee rept to CA Coastal Commission on adequacy of plant radiological monitoring program M/b encl
 CHANDLERs.L. J. Hearing Brench 1 80/07/29 1p
- F Becurity, medical, emergency & fire protection plans
- 8007080271 Advises that revisions to safequards contingency plan will be submitted by 800718 BASKIN.K P Southern California Edison Co 80/07/02 1p
- G Adjudicatory correspondence
- B007030006 Responds to to 800519 ltr % mailgram re NRC meeting practices on geology/seismology in CN proceeding Future meetings will be held in convenient locations NRC unable to honor request that meeting similar to 800520-21 be held CHANDLER.L. J. Hearing Branch 1 80/06/27 App
- B007310243 Forwards Commission 800527 memorandum to order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum to order UCS 771104 petition sought action re fire protection for electrical cobles EISENHUT, D.G. Division of Licensing 80706/25 89pp
- 8007090205 Proposes agenda for 800717 prehearing conference in response to ASLB 800624 order in OL proceeding CHANDLER, L.J. Hearing Branch 1 80/07/07 2pp
- 8007300359 Submits recommendations on behalf of Southern CA Edison & San Diego Gas & Electric for agenda items to be considered at prehearing conference to begin 800717 in San Diego CA Related correspondents
 PIGVOTT, D.R. Chickering & Greenry 80/07/07 3pp
- 8007140032 forwards for consideration, applicant, NRC % Friends of the Earth et al 800627 executed stipulation for extending response date to 800723 re applicants motion for summary disposition of Contentions to & 9 per M proceeding CHANDLER L J Hearing Branch 1 80/07/09 ip
- ---8007140034 Frecuted stipulation extending time to respond to applicant mutuon for summary disposition of dewatering U feel cost contentions until 800727 W/Proposed order PIODITO R Southern California Edison Co CHANDLER, L J Branch I WHARTON, R J Firend of the Earth 80/06/27 Hearing
- 8007210436 Forwards ruggrated new version of JA Patterson affidavit routin motion for summany disploition Return of affidavit w/signature t nutari.action requested if changes are suitable DAVISAL D. Hearing Branch 4 60/07/14 7pp
- 8007310470 Advises that NURL 2-0694 transmitted to proties on 800716 Extra copies will be sent to parties when available 970 CHANDLER, L. J. Hearing Branch | HO 07/20 1p
- H General correspondence
- 8007020181 Requests consideration of hasing Atomic Energy Council of Taiwan visit for thith on Bhobsea 10 council interested in observing what most most contribution to the extantice Cooperation will be major contribution to the extange arrangement LAFLEUBLA D. Assistant Director for international Cooperation B0/05/13 gqF

- Q Inspection reports. IE Bulleting & correspondence
- 800723001) Notifies that 800(18 response to IE Bulletin 79-13 Revision JULIANUM INTERPRETATE SUBJECT TEMPORED TO IN BILIETH TO P. L. Indicated will proposed withing ultrasions to substitute the techniques for inportably indications as alternative to radiography Util withdraws proposed use of ultrasonics BASKIN, P. Southern California Edison Co. BU/03/04. Ip
- 8007250361 Responds to IE Bulletin Bu-Od, "Loss of Charcoal from 9td Type II./-inch. Fray Adsorber (Ells) No charcoal adsorber cells have been received from manufacturer Charcoal adsorber fifters to be used are designed to prevent charcoal leakage BASRIN.K P Southern California Edison Co 80/03/31 1p
- 8007170530 Forwards iF Inso Rears 50-461/80-05 % 50-362/80-03 on 800324-27 No mancampliance hoted SPENCER, 0 S Region 5 Sem Francisco Reactor Construction & Engineering Support Reach - 80/05/20 - 2pp
- ~~8007170519 [F Insp Repts 50-341/80 05 % *0-342/80-03 on 800324-27 No noncomplainte noted Major rives lin pected previous open items, cable installation & page suppints & Pestraints ECKHAROT J H . HERNANDEL/O Region 5. San Francisco Office of the Director BBDDS.R I Region 5. San Francisco Reactor Construction & Engineering Support Branch 80/05/20 App
- BOO7240088 Forwards response to NRC 800429 itr re violations & deviations noted during 800303-17 & 21-28 inspiral constactivities Welding filler muth removed % dispositioned Bechtel work plan GC instructions revised PAPAY, L. T. Southern callebraia Edison Co. 80/09/28 Spp.
- -8007240093 Ack receipt of 800528 Itr informing NRC of steps taken to correct items in NRC 800428 Itr SPENCER.G S. Region 5. Son Francisco. Reactor Construction & Engineering Support Branch 80707711 tp
- 8007300303 Responds to 1E Bulletin 80-05 re vacuum damage to chemical vol control syntanks Table identifying sys t describing adequacy justification encl Tanks not currently protected will be provided woodequate pratection prior to fuel load BASKIN.K F Southern California Edison Co 80/06/06 3pp
- 8007220247 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required ENGELKEN, R. H. Region 5. Sub Francisco, Office of the Director 80/06/10
- 8007160223 Forwards Ik Info Notice 80-27 "Degradation of Reactor Coplant Pump Study No specific action or response
- O'REILLY J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007020131 Ack receipt of 800528 its informing NRC of steps taken to correct violations noted in IF Insp Repts 50-36/80-06 & 50-36/80-04 SPENCER, G.S., Region 5, San Francisco, Reactor Construction &
 - Engineering Support Branch 80.06/13
- --8007020149 Respinds to NRC 800429 Itr re violations noted in IE Insp Repts 50-361/80-06 & 50-362/80-04 Corrective actions welding filler math removed & dispositioned PAPAVIL T Southern California Edison Co 80/05/28 5pp
- --8007020158 Forwards IE lnsp Repts 50-361/80-06 & 50-362/80-04 on B00301-31 & notices of calation % deviation SPENCER.9 S Region 5: San Franciscu, Reactor Construction & Engineering Support Branch 80'04/29 2pp
- ---B007020166 Notice of violation from insp on 800301-31
 * Region 5 San Francisco, Office of the Director B0/04/24 in
- --8007020179 Notice of deviation from insp on 800301-31 # Region 5 San Francisco Office of the Director BO/04/24 1p
- --800702019] IE (nep Repts 50 361/80 06 % 50-362/89-04 on 800301-31 Noncompliance noted hadlore to store high strength bolds in monner assigning the feature to control E7018 welding electrodes at 30 St elevation PATE.R of Region 5, San Francisco, Office of the Director DODD RT Pagion 5, San Francisco, Reactor Construction & Engineering Support Branch 20/04/24 Spp
- 8007290088 Forwards if Into Notice 80 ed. Prompt Reporting of Info in Accordance Wilm 64'0 55'0' No written response required ENGELKEN, P. H. Fellon G. Gen Francisco Office of the Director 80'06, 13 by

- 8007270489 Responds to IE Bulletin 80-09 re potential defects in ITT General control hydramotor actuators Supplied actuators were functionally tested & exhibited no adverse operating defects Valves will perform functions as designed BASKIN,KP Southern California Edison Co 90/0 80/06/16 10
- 8007020470 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELMEN.R H Region 5. San Francisco. Office of the Director
- 8007180292 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Personnel" No written response required ENGELKENIR H. Region 5, San Francisco. Office of the Director 80/06/24 ip
- 8007230393 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also epcl No written response required ENGELKEN, R H. Region 5, San Francisco, Office of the Director 80/06/27 1p
- 8007310201 Responds to IE Bulletin 80-08 re containment line penetration welds examination Utils do not utilize flued head design for penetration connections Unacceptable welds repaired & radiographed until ASME code criteria met BASKIN.K P Southern California Edison Co 80/07/01 ip
- 8007300313 Forwards 1E Insp Repts 50-361/80-08 & 50-362/80-05 on 800407-0502 No nuncompliance noted SPENCER.0 & Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/07/03 2pp
- --8007300318 IE lasp Repts 50-361/80-08 & 50-362/80-05 on 800407-0502 No noncompliance noted Major areas inspected const activities, including reactor pressure vossel & internals protection & piping storage
 PATE,R J Region 4, Dallas, Office of the Director DODDB.F.
 Region 4, Dallas, Reactor Construction & Engineering Support
 Branch 80/07/02 App
- R Periodic operating reports & related correspondence
- 8007010216 Forwards "1979 Annual Dierating Rept, Sam Ompfre Nuclear Generating Station," Vol 5, Biological & Oceanographic Data Analyses Includes ETS for Unit 1, const & preoperational monitoring programs for Units 2 & 3 BASKIN, K P Southern California Edison Cp 80/06/25 ip
- --B007010226 "1979 Annual Operating Rept, San Unofra Nuclear Generating Station: "Vol 5, Biological & Oceanographic Daka Analysis "Includes ETS for Unit 1, const & preoperational monitoring programs for Units 2 & 3 "Brown & Caldwell "Lockheed Environmental Sciences "Marine Biological Consultants, Inc. 80-RD-100 80/06/25
- 8007100262 Forwards "Biological & Oceanographic Data Analyses ETB for Unit 1.Const Monitoring Program for Units 2 & 3, Preoperational Monitoring Program for Units 2 & 3 & Special Study re Inthépoplankton," Vol 5 for 1979 OTTOSON, H L Southern California Edison Co 80/06/30 2pp.
- --B007100268 "Biological & Oceanographic Data Analyses ETB for Unit i.
 Const Monitoring Program for Units 2 & 3. Preoperational
 Monitoring Program for Units 2 & 3 & Special Study re
 Ichthyplankton," Vol 5 for 1979
 AMBERGO.P J Brown & Caldwell ANDERSON, D T Lockheed
 Environmental Sciences ABGRABIK Marine Biological Consultants,
 Inc., 80-RD-100 80/06/30 800pp
- S Reportable occurrences. LERs & related correspondence
- 8007090330 Forwards final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing PAPAY.L T Southern California Edison Co 80/06/27 1p
- --800709033/ Final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing Deformed joints will be removed to returned to manufacturer for analysis Data sheet review will be completed by 800780 s Southern California Edison Ca 80/06/27 App
- 8007280143 Ack respire of 800All amended final deficiency rept to lack of qualification testing documentation for repaired power cable ENGELHEN.R H Region 5, San Francisco, Office of the Director 80/07/02 ip

- 8007210493 Confirms 800711 teleon re editorial error in 800627 final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing Failed expansion joint was in component cooling water sys NURN, D E Southern California Edison Co 80/07/11 ip
- BOO7230379 Final deficiency rept re lack of nondestructive surface examination of weld repair excavation cavities prior to rewelding Code Cases N274 t 275 approved to provide alternate acceptance criteria to ASME. Section 3
 PAPAY, L T Southern California Edison Co 80/07/15 4pp
- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B007010560 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mgt representative Areas of disagreement may be discused through informal appeal TEDESCO, R L Assistant Director for Licensing 80/06/13 2pp
- 8007070421 Summary of 800528 meeting w/NRC consultant.Energy Technology Engineering Ctr,& applicant in Whittier.CA re Mechanical Engineering Branch open items re FSAR Draft safety evaluation.agenda & attendance list encl RODD.H Licensing Branch 3 80/06/16 24pp
- 800702020B Notification of 800702 meeting w/util in Bethesda.MD to discuss control room design review program RODD.H Licensing Branch 2 80/06/23 3pp
- 8007020673 Requests additinfo to define underclad cracking potential in reactor vessel norrles Ultrasonic exams did not indicate explicit correlation between observed cracking & pre/post-heat treatment info required within two weeks SCHWENCER.A Licensing Branch 3 80/06/24 App
- B007010479 Forwards affidavit of svc attesting to completion & distribution of responses to NRC financial analysis Guestions 1-9
 BABKIN,K P Gouthern California Edison Co 80/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D @ Division of Licensing 80/06/26 2pp
- BOO7010358 Forwards "Preliminary Rept on Geologic Drilling & Investigation San Onofre Nuclear Generating Station Units 2 & 3 & 61 geophysical maps (interpretations) prepared by PJ Fischer of CA State Univ encl BASKINK P Southern California Edison Co 80/06/27 1p
- --8007010364 "Preliminary Rept on Geologic Drilling & Investigation San Onofre Nuclear Generating Station Units 2 & 3 " BARNEICH.JA, BROGAN,O E Woodward-Clyde Consultants, Inc 80/06/27 47pp
- --B007010374 Sixty-one 3 5 kHz high resolution seismic lines List of drawings encl * California State Univ.Northridge B0/06/09 6200
- 8007090234 Urges extension of comment period for NUREG-0577 & 800519 amend until 800915 More stringent requirements broader applicability & EPRI study results warrant addl time OILMAN,D W San Diego Gam & Electric Co 80/06/30 ip
- BOO70BOOB1 Forwards response to NRC Question 361 65 in geoscience area Also forwards Woodward Clyde Consultants "Preliminary Rept on Geologic Drilling & Investigation Songs, Units 2 & 3, San OnofreiCA"

 BASKIN.K P Southern California Edison Co BO/07/01 189p
- --8007080083 "Preliminary Rept on Groingic Drilling & Investigation Bongs, Units 2 & 3, San Onofre, CA " * Woodward-Clydo Consultants, Inc 80/07/01 40pp
- 8007170693 Advises of NRC acceptance of Amend 3 to Topical Rept. SCE-1-A, "AA Program " Topical rept must be referenced in Chapter 17 of SAR HAABS, W P Quality Assurance Branch 80/07/01 ip
- 8007210093 Notification of 800724 meeting w/util in Rosemead.CA to discuss results of Imperial Valley Oct 1979 earthquake analysis.using Unit I analytical modeling technique ROOD.H Licensing Branch 3 80/07/11 2pp

- 8007210463 forwards supplemental calculations of Revision 1 pages to original ralculations submitted to NRC on 800121 fr design calculations of electrical tonnel BASKIN.K.P. Southern California Edison Co. 80/47/16 39pp
- 8007280486 Ack receipt of NRC responses to Marine Review Committee 791009 rept re facility radiological monitoring program evaluation Detailed response will be submitted fullowing matt review Fischer, M. L. falifornia, State of 80/07/19 1p
- B007290620 Forwards response to NRC 800624 request for info repotential for underclad cracking in reactor zessel noizles Nozile base metal matl is SA 500 (lass II Applicable matl certification data sheets encl BASKIN.K.P. Southern California Editor Co. 60/07/22 37pp
- BOD7310465 Forwards NRC review of Marine Review Committee rept to CA Coastal Commission on adequacy of plant radiological monitoring program W/o encil CHANDLERIL J. Hearing Branin 1 80/07/29 ip
- F Security, medical, emergency & fire protection plans
- 80070802/1 Advises that revision: In Safeguards contingency plan will be submitted by 800718 BASKINK P. Southern California Edison Co. 80/07/02 ip
- Q Adjudicatory correspondence
- 8007030006 Responds to to 800519 ltt & morigram re DRC meeting practices on genlogy/seismology in Ol proceeding future meetings will be held in convenient locations NRC unable to honor request that meeting similar to 800520 21 be held CHANDLER, L. J. Hearing Branch ! 80706723 4pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re file grotection for olderingal cables EISENHUT, D 0 Division of ficensing 80/06/29 99pp
- 8007090205 Proposes agenda for 800717 prehearing conference in response to ASLB 800624 order in OL proceeding CHANDLER, L. J. Hearing Branch 2 800.07/07 2pp
- 0007300359 Bubmits recommendations on behalf of Southern CA Edison & San Diego Gas & Electric, for agenda items to be considered at prehearing conference to begin 800,17 in San Diego, CA Related correspondence
 PIGVOTT, D.R. Chickering & Gregory 80,07/07 App
- B007140032 Forwards for consideration applicant NRC & Friends of the Earth et al 800827 executed slipulation for ratending response dair to 800723 re applicants motion for summary disposition of Contentions la 1 9 per Ol proceeding CHANDLER L J Hearing Branch 1 80707709 ip
- ---B007140034 Executed stipulation extending time to respond to applicant motion for communy disposition of dewalering U fuel cost contentions until 8007/3 Who oposed order P10011.0 R. Southern Collection Edison Co. (HANDLER, L. J. Hearing Branch I. WHARTON, R. J. Ittends of the Earth 80/06/27 Epp.
- B007210436 Forwards ingrested new persion of JA Parterson affidavit reutil motion for summary & polition Meturi of affidavit w/ signature & notarijation requested it changes are suitable DAVIS.L D - Hearing Branch 4 - 80/07/14 - 7pp
- 8007310470 Advises that NUREG 0A94 transmitted to parties on 800716 Extra replies will be sent to parties when available W/o encl rept CHANDLER L J Hearing Branch t 80/07/20 1p
- H General correspondence
- 8007020181 Requests consideration of howing Atomic Energy Council of Taiwan visit facility on 804804-05 founcil interested in observing worth myt activities Cooperation will be major contribution to NRC exchange air-ingement

 LAFLEUR. J D Assistant Director for International (coperation 80/08/13 3nn

- @ Inspection reports, JE Bulletins & correspondence
- BOO723001! Natifies that BOO11B response to 1E Bulletin 79-13.Revision 2.indicated util proposed utilizing ultrasonic examination techniques for reportable indications as alternative to radiography Util withdraws proposed use of ultrasonics BASKIN, F P Southern California Edison Co 80/03/04 lp
- 8007250361 Responds to IE Bulletin BO-03, "Loss of Charcoal Prom Std Type II:2-Inch, Fray Adsorbet Cells " No charcoal adsorber cells have been received from manufacturer Charcoal adsorber filters to be used are designed to prevent charcoal leakage BASKIN,K P Southern California Edison Co 80/03/31 1p
- 8007170530 Forwards JE Insp Repts 40-361/80-05 & 50-362/80-03 on 800324-27 No monrompliance noted SPENCER, O S Region 5. Som Francisco. Reactor Construction & Engineering Support Branch #0/05/20 Spp
- --BOO7170939 (E Insp Repts 50-361/BO-05 & 50-362/BO-03 on BOO324-27 No noncompliance noted Major areas inspected previous open items.cable installation & pipe supports & restraints ECKHARDT, J. H. HERNANDEZ, G. Region 5. San Francisco. Office of the Director DODDS.R T. Region 5. San Francisco. Reactor Construction & Engineering Support Branch BO/05/20 App
- BOO7240088 Forwards response to IRC 800429 ltm re violations & deviations noted during 800303-17 & 21-28 insp of const activities Welding filler matl removed & dispositioned Bechtel work plan QC instructions revised PAPAY.L T Southern California Edison Co 80/09/28 Spp
- ~-B007240093 Ack receipt of 800528 ltr informing NRC of steps taken to correct items in NRC BO042B ltr SPENCER.Q S Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/07/11 lp
- 8007300303 Responds to IE Bulletin 80-05 re vacuum damage to chemical vol control sys tanks Table identifying sys & describing adequacy justification and lanks not currently protected will be provided w/adequate protection pilor to fuel load BASKIN.K P Southern California Edison Co 80/06/06 3pp
- 8007220249 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required ENGELKEN.R H. Region 5. San Francisco. Office of the Director 80/06/10 10
- 8007020131 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in it losp Repts 50-361/80-06 & 50-362/80-04 SPENCER. 6 S. Region 5. San Francisco Reactor Construction & Engineering Support Branch 80/06/13 lp
- --BOO7020149 Responds to NRC BO0429 ltr re violations noted in IE Insp Repts 50-361/BO-06 % 50-362/BO-04 Corrective actions welding filler matl removed & dispositioned PAPAYLL T Southern California Edison Co 80/05/28 Spp
- --8007020158 Forwards IE Insp Repts 50-361/80-06 & 50-362/80-04 on 800301-31 & notices of violation & deviation SPENCER.0 S Region 5. Sun Francisco, Reactor Construction & Engineering Support Branch 80/04/29 2pp
- --8007020166 Natice of violation from insp on 800301-31 * Region 5. San Francisco. Office of the Director 80/04/24 1
- --B007020175 Notice of deviation from insp on B00301-31
 * Region 5. San Francisco. Office of the Director 80/04/24 ip
- ---8007020191 IE Insp Repts 50-361/An-06 & 50-362/A0-04 on 800301-31
 Noncompliance world failure to store high strength bolts
 an manner avoiding corrosson & failure to control E7018
 welding electrodes at 30 ft elevation
 PATE/R J Acquen 5. San Francisco, Office of the Director
 DODDS/R T Region 6. San Francisco, Reactor Construction &
 Engineering Support Branch 80/04/24 5pp
- BOO729008B Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFF50 55(e)" No written response required ENGELKEN/R H Pegion 5. San Francisco, Office of the Director 80/00/13 1p
- 8007290489 Pesponds to IE Bullabin (NO-09 re patential defects in ITT Oeneral control hydramotor actualors Supplied actuators were functionally tested & exhibited no adverse operating defects Valves will perform functions as designed BASKIN.K P Southern California Edison Co 80/06/16 ip

- 8007020478 Forwards 1E Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN, R H Region 5. San Francisco, Office of the Director 80/04/20 lp
- B007180292 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Deminstalized Water Bys & Resultant Internal Contamination of Personnel" No written response required ENGELKENIR H Region 5, San Francisco, Office of the Director B0/06/24 ip
- 8007230393 Forwards IE Bulletin 80-16, "Potential Misapplication of Posemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/27 1p
- 8007310201 Responds to IE Bulletin 80-08 re containment line penetration welds examination Utils do not utilize flued heaf design for penetration connections Unacceptable welds repaired k radiographed until ASME cide criteria met BASKIN.K P Southern California Edison Co 80/07/01 1p
- 8007300313 Forwards IE Insp Repts 50-361/80~08 & 50-362/80-05 on 800407-0502 No noncompliance noted SPENCER G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/03 App
- --B00730031B IE Insp Repts 50-361/80-08 & 50-362/80-05 on 800407-0502 No noncompliance noted Major areas inspected const activities, including reactor pressure vessel & internals protection & piping storage PATE,R J Region 4, Dallas, Office of the Director DODDB,R T Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/02 bpp
- R Periodic operating reports & related correspondence
- B007010216 Forwards "1979 Annual Operating Rept, San Unofre Nuclear Generating Station," Vol 5. Biological & Oceanographic Data Analyses Includes ETS for Unit 1. const & preoperational monitoring programs for Units 2 & 3 BASKIN, K P Southern California Edison Co 80/06/25 1p
- --8007010226 "1979 Annual Operating Rept.San Onofre Nuclear Generating Station." Vol 5. Biological & Oceanographic Data Analysis "Includes ETS for Unit i.const & preoperational monitoring programs for Units 2 & 3

 * Brown & Caldwell * Lockhead Environmental Sciences. *
 Marine Biological Consultants, Inc., 80-RD-100 BO/06/25
 BOOpp
- 8007100262 Forwards "Biological & Oceanographic Data Analyses ETS for Unit 1.Const Monitoring Program for Units 2 & 3. Preoperational Monitoring Program for Units 2 & 3 & Special Study re Ichthyoplankton," Vol 5 for 1979 OTTOSON, H L Southern California Edison Co 80/06/90 2pp
- --8007100268 "Biological & Oceanographic Data Analyses: ETB for Unit 1, Const Monitoring Program for Units 2 & 3, Preoperational Monitoring Program for Units 2 & 3 & Special Study re Ichthyoplankton, "Vol 5 for 1979 AMBERG, P J Grown & Caldwell ANDERSON, D T Lockheed Environmental Sciences ABGRAB.K Marine Biological Consultants, Inc. 80-RD-100 80/06/30 800pp
- S Reportable occurrences, LERs & related correspondence
- B007090330 Forwards final deficiency rept re failure of expansion Joints in safety-related piping sys during startup testing PAPAY,L T Southern California Edison Co 80/04/27 1p
- ~-B007070337 Final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing Deformed joints will be removed & returned to manufacturer for analysis Data sheet review will be completed by 800720.

 * Southern California Edison Co 60/06/27 2pp
- B0072B0143 Ack receipt of B00611 amended final deficiency rapt re lack of qualification testing documentation for repaired power cable ENGELKEN, R H Region 5, San Francisco, Office of the Director B0/07/02 ip
- 8007210493 Confirms 800711 tolcon re editorial error in 800627 final deficiency rept re failure of expansion joints in safety-related piping sys during startup testing Failed expansion joint was in component cooling water sys. NUNN.D E Southern California Edison Co 80/07/11 ip.

8007230579 Final deficiency rept relack of nondestructive surface examination of weld repair excavation cavities prior to rewelding Code Cases N274 & 275 approved to provide alternate acceptance criteria to ASME. Section 3
PAPAY,L T Southern California Edison Co 80/07/15 4pp

DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8007020219 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Nocessary period of transition made w/min disruption to ongoing activities TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 8007230001 Forwards statement of policy re requirements to be mot for current OL applications as derived from NUREG-0660 & found in NUREG-0694 EIBENHUT, D Q Division of Licensing 80/06/26 2pp

9 Adjudicatory correspondence

BOO7310243 Forwards Commission 800827 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables
EISENHUT, D O Division of Licensing 80/06/25 87pp

H General correspondence

- BOO7180060 Responds to BOO311 request for info needed for fuel cost study Forwards excerpts of MABH-740, WASH-1224, WASH-1250, MASH-1400, NUREO-0020 (Vol. 4, Number 1), NUREG-0480, NUREG-0512, NUREO-0517, NUREO/CR-1060 & FEB Diffice of Nuclear Reactor Regulation, Director DENTON, H R Bff 80/05/14 153pp
- -- 8007180063 Requests documents containing info needed for fuel cost HILGER.W Affiliation Unknown 80/03/11 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007170593 Forwards IE Insp Rept 50-363/80-01 on 800506 No NOTITOSMS rotwers at any ma, noncompliance noted CARLBON,R T Region 1, Philadelphia, Reactor Construction & Smallmooring Support Branch 80/05/22 2pp
- --8007170599 IE Insp Rept 50-363/80-01 on 800504 No noncompliance noted Major areas inspected QA program for storage & maint of equipment matls & structures during suspension of const & status of outstanding items
 NARROW.L. Region 1. Philadelphia. Office of the Director MCGAUGHY, R W Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/05/20 Spp
- B007010283 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/03/27 1p
- 8007210568 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs "No written response required GRIER, B H Region i, Philadelphia, Office of the Director 80/06/10 lp
- 8007160346 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Study No specific action or response required
 ORIER, B M Region 1, Philadelphia, Office of the Director 80/06/11
- 8007280587 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required GRIER, B H Region 1. Philadelphia, Office of the Director BO/06/13 ip
- 8007020507 Forwards lE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/96/20 ip
- 8007140701 Forwards IE Circular 80~14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER.8 H Region 1. Philadelphia. Office of the Director 80.004.24. ORIER: 8 H R 80/06/24 1p

- 8007210192 Forwards IF Info Notice 80-24, 'Low level Raduasto Burial (Titeria' No willton response required GRIER, B.H. Region 1, Philadelphia, Office of the Director 80/06/25 | 1p
- 8007230121 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 % 1152 Pressure Transmitters W/Either A or D Dutput (odes " Written response required IE Circular 80 % also encl No written response required GRIER, B H. Region 1, Philadelphia, Office of the Director GRIER: B H Re: 80/06/27 2pp
- DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2 A Application/construction of genducinents & correspondence
- 8007070575 Requests assignment of reviewer * extinated completion date for TMI-2 artium plon items listed in attached tables Bubmits licensing schedule Requested date for safety evaluation input is 800625 TEDESCO. R. 1. Assistant Director for Livensing 80/08/07 9ab
- 8007020390 Advises of interim actions required for plant operation pending final resolution of ATMS concerns ATMS emergency operating procedure must be submitted by 800820 % approved prior to issuance of full power OL TEDESCO.R L Assistant Director for Licensing 80708713 3pp
- 8007020395 Requests addl into re-underclad cracking in reactor veosel nazzles for determination of role of heat treatments in cracks recently found by European foblicator SCHMENCER A. Licensing Branch 2. 80/06/13. 2pp
- 8007010287 Forwards request for add1 info needed for continuing review of DL application per 800623 telron Info must be submitted by 800627 or NRC informed of contraly in even days SCHMENCER.A. Licensing Branch & 80706717 bpp
- 800/020473 Forwards request for add1 info to continue review of OL application info should be submitted by 800670 SCHWENCER.A. Licensing Branch & 80/06/19 7pp
- 8007010424 Advises that annual usage factor for two unit processing using Unit 1 drumoing station is increased to 30% using values for expected wasto vols in updated fSAR Table 11 5-1 Basis for determining usage factor encl
 CLAYTON F L Alabama Power (or 80/06/23 Tpp
- B007070009 Notification of Ne0630 0709 meeting w/util to review applicant plans & personnil qualification for operation of facility

KINTNER, L. Licensing Branch 2 80/06/23 2pp

- B007100018 Notification of B00703 meeting wrutil in Bethesda.MD to discuss util response to NRC B00221 request for review of qualification documentation to safety-related electrical aguipment to disentify continuance to NUMPO OTES KINTER-L Licensing Branch 2 507067/23 3pp
- B007010489 Forwards info in response to B00A13 itr is reactor .essel nozzle underelad ciacking Ultrasonic crams not presently needed Claddiny destructive cram recommended CLAYTON F. L. Alabama Power to B070A75 dpp
- 8007230001 Forwards statement or policy of requirements to be mot for current OL applications as derived from NURES 0660 & found in NURES 0694 EISENHUT, D.G. Division of Licensing. 80706/26 2pp
- 80070/0292 Forwards requested addl into it steam generator tube integrity CLAYTON F L - Alabama Power to - 957(6/2/ - App
- BOO7210305 Notificiation of (00707+11 meeting white) in Dolthan.AL to import design reports of circled equipment becomes solution records.

 KINTMER.L. Licensing Branch 2 (60706/27) Spp.
- BOO70BO222 Forwards abnormal operating procedure, "Loss of Main Feedwater," emergency operating procedures, "Steam Generator Tube Repture & 'Inadequate Core (curing Due to mail LOCA" per NRC BOORS request CLAYTON F. L. Alabama Power to 80/06/39 Ip
- --B00708022B Abnormal operating procedure "fock of Main Feedwater," Vol 5.Revision 0 * Alabama Power Co 90'05 30 lpp

- --8007080232 Emergency operating procedure. 'Loss of Reactor Coolant." Vol 5. Revision O
 - Alahama Pawer Co 80/05/14 4200
- --8007080236 Emergency uperating procedure, "Steam Generator Tube Rupture," Vol 5, Revision 0 Alabama Fower Co 80/05/14 9pp
- ~~8007080243 Emergency operating procedure: "Anticipated Transients W/o Trip (ATWT):" Revision 0 ★ Alahama Power Co 80:06/04 4pp
- --8007080250 Emproperty operating procedure, "Inadequate Core Cooling Due to Small LOCA ' vol 5, Revision O # Alabam, Puwer to 80/06/12 4pp
- 8007070227 Forwards qualification summary info for non-NSSS mechanical & electrical equipment selected by selemac qualification review tram for evaluation CLAYTON.F L. Alabama Power Co. 80/06/30 114pp
- B007100(B5 Submits insponses to URC 800515 draft questions concerning containment purge valves Comparison of facility purge sys w/ Branch Technical Position C98 o-4 onc1 CLAYTON.F.L. Alabaras Power Co. 80706/30 12pp
- BOO7210304 Notification of BO0709 meeting w/otil in Bethesda, MD to discuss radiological fech Specs KINTNER.L Licensing Branch 2 85/06/30 3pp
- BOO7210593 Notification of 800716 mpeting w/util in Bethesda.MD to discuss response to NRC position on degraded grid voltage protection & sys voltages KINTNER-L Licensing Branch 2 80/07/02 3pp
- 8007210598 Notification of 800715 meeting w/util in Bethesda, MD to discuss control room design KINTNER.L.1 Licensing Branch & 60/07/02 3pp
- 8007100177 Forwards addl into requested by NRC 800617 ltr re preservice insp program CLAYTON,F L Alahama Power Co 80/07/03 25pp
- 8007140349 Forwards description of proposed modified startup physics test program Revived program resolves NRC concerns resolves back overficuation. Teorem criteria & actions needed should review (riteria) not be met CLAYTON, F.L. Alabama Power Co. 80/07/07 13pp
- 8007160579 Forwards response to (antainment Sys Branch Question 57 for facility Leak reduction program initiated to maintain leakage rates of sys outside containment to as low as practica) CLAYTONLF L. Alabama Power Co. 80/07/07. 3pp
- BOO7100261 Forwards Amend 73 to FSAR for Unit 1 & OL application for CLAYTUN.F.L. Alabami Power to 80/07/08 1p
- --B007100287 Application for Amend 73 to FSAR for Unit 1 & OL application for Unit 2 Centificate of Syc enci * Alabama Puwer Co B0/07/08 4pp
- --8007100276 Amend 73 to FSAR for Unit 1 & OL application for Unit 2 Reviser Unit 2 completion of const & commercial operating dates, updating section re-emergency lighting sys & info pertaining to GA program * Alabama Power Co. 80/07/08 400pp
- B0072B0121 Submith facility status rept as of 800704 Full nower licensing thodule advanced lemonth to meet scheduled 801101 start of full power operation Applicant asked to formally request fuel loading 'low power testing license KINTNER/L Licensing Branch 2 80207711 2pp
- 8007220510 Forwards process control program for radwaste solidification unit-as discussed at 800700 meeting w/ARC CLAYTON F (Althuma Hower Co 80 07/14 1p
- --8007220515 Radiation (ontic) & Protection Procedure FNP-Q-RCP-474, Revision 1. "Nobile Solidification Unit Operation " MCCRACKEN K W. Alabama Power Pa. 80/01/10 89pp
- 800722055B Corounds Revision 1 thange pages to plant offsite dose calibr manual incorporates radiction munitor setpoint calculation methodology distanced during 800709 meeting CLAYTON F L Alabama Power Co 80/u7/14 App

- 8007250185 Advises that near-term DL applicants should perform augmented low power startup tests similar to those proposed by TVA for Sequuyah, prior to exceeding 5% of rated thermal power EISENHUT,D G Division of Licensing 80/07/14 2pp
- 8007250320 Forwards info per NRC 800502 request re THI-2 action plan Items I A 2 I I A 2 3 & I A 3 1 CLAYTON,F L. Alabama Power Co. 80/07/15 4pp
- 8007220486 Forwards addl info re containment sump performance in response to NRC request CLAYTON, F.L. Alabama Power Co. 80/07/16 4pp
- 8007220954 Forwards auxiliary feedwater endurance test data & test info requested in NRC 800408 ltr CLAYION,F L Alabama Power Co 80/07/14 20pp
- 8007280379 Forwards request for addl info re containment sump performance under post-LOCA conditions Response to Items 1,2 & 3 due by 800808 Item 4 info should be provided by Mar TEDESCO.R L Assistant Director for Licensing 80/07/16 8pp
- 8007290202 Forward, request for addl info re 800620 response to TMI-2 action plan
 TEDESCO.R L Assistant Director for Licensing 80/07/16 9pp
- 8007220410 Forwards qualification repts & seiemic specs for five pieces of equipment.per NRC request during 800707-10 plant site visit for seismic qualification review CLAYTON,F L Alabama Power Co 80/07/17 ip
- G007220581 Responds to G00714 ltr re augmented low power startup test program Submits schedulg & procedure for test performance Util in process of writing detailed procedures & reserves option of combining tests No known safety issue involved CLAYTON,F L Alabama Power Co G0/07/17 1p
- B007230403 Forwards add1 info re degraded electrical power grid conditions, in response to B00626 telcon Includes suppl to util 790115 ltr re assessment of NRC Positions 1.2 & 3, CLAYTON,F L Alabama Power Co B0/07/17 13pp
- 8007230485 Responds to Action Plan Item III D 3 4 re control room babitability Room meets SRP specs & guidance No mods required CLAYTON,F L. Alabama Power Co. 80/07/17 ip
- B007230492 Forwards main control room design review commitments par NRC main control room review team 800715 discussions w/util CLAYTON,F L Alabama Power Co 80/07/17 9pp
- 8007230846 Informs that util will participate in EPRI/NSAC power safety & relief valvo performance verification test program Licenses will submit evidence re operability of installed safety & relief valves Evidence expected by 820101 CLAYION,F L Alebama Power Co. 80/07/17 1p
- B007P30553 Forwards radiological Tech Spec info concerning hydrogen-oxygen-nitrogen mixture curves & hydrogen recombiner instrumentation callor H/o encl CLAYTON.F L Alabama Fower Co B0/07/17 ip
- 8007230967 Requests that OL w/limited authorization for facility be issued by 800901 per requirements in NRC 800626 Itr Request includes fuel loading low power testing & power operations up to 5% thermal power Full power D. Preguested by 801201 CLAYTON, F. L. Alabama Power Co. 80/07/17 ip
- 8007230592 Forwards info re sys description of core thermocouples in response to TMI-2 action plan 1tem 11 F 2 on inadequate core cooling instrumentation CLAYTON: I Alabama Power Co 80/07/17 5pp
- 8007240071 Notifies that util in process of finalizing plans for instrumentation sys to relate reactor vessel water level to inadequate care Louling Provides list of commitments concerning instrumentation sys CLAYTON, F.L. Alabama Fower Co. 80/07/17 ip
- B007280357 Commits to guidance in Reg Guide 8 9 re establishment of bicassay program, w/mxception of interpretation of measurement results Problems of interpretation are stated in ICRP Publication 12, Paragraph 112 CLAYTON.F.L. Alabama Power Co. 80/07/18 1p

- BOO7280470 Suppls & supersedes util 800717 response to TMI-2 action plan items Util will participate in EPRI PWR safety & relief valve performance verification test program & will submit gvidence of valve operability by BOO701 CLAYTON, F. L. Alabama Power Co. 80/07/23 ip
- BOO7270637 Forwards requested info concerning TMI-2 action plan for facility Includes description of interim procedures & methods for qualifying high level accidental radioactivity releases for noble gas.particulates & radioactive effluents CLAYTON, F. L. Alabama Power Co. 80/07/24 5pp
- B007270642 Forwards requested info re core subcooling instrumentation Includes description of incore thermucouple measurement means available at facility CLAYTON,F L Alabama Power Co 80/07/24 7pp
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8007290525 Forwards SER input re TMI Action Plan Task I A 3-addressing revised scope & criteria for licensing exam MOORE, V A Division of Human Factors Safety 80/07/18 2pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT.D G Division of Licensing 80/06/25 89pp
- J Insurance & indemnity information
- 8007080261 Forwards MAELU Excess Binder XB-7.3 FIELDER, J Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/06/30 App
- G Imaportion reports. IE Bulletins & correspondence
- 800724010B Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Beste Unit I While in Refueling Mode" No response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8007020180 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007210419 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007010253 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Faedwater Pumps" No written response required O'NEILLY, J P Region 2. Atlanta, Office of the Director 80/05/29 is
- 8007220040 Forwards IE Info Notice 80~26. "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/10 200
- B00716021B Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required O'NEILLY, J.P. Region 2. Atlanta, Office of the Director B0/06/11
- 8007250338 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13 2pp
- 8007020385 Forwards IE Carcular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No wratten response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/20
- 8007270385 Forwards 1E Insp Rept 50-364/80-05 on 800604-06 No noncompliance noted KENNA, W B Region 2. Atlanta, Safeguards Branch 80/06/20 2pp

- ---B007290393 IF Insp Rept 50-364/80-05 on 800604-06 No noncompliance noted Major areas inspected matl routiol & accounting GILLESPIE, P. HODGES, J.W. Region 2, Atlantic Safeguards Branch B0/06/20 Sno
- 8007070394 Forwards IE Insp Rept* 50-348/80-10 & 50-364/80-11 on 800331-0425 No noncompliance noted LEWIS.R C Region 2. Atlanta. Peactor Operations Nuclear Support Branch 80/06/21 2pp
- --B007070399 IE Insp Repts 50-348/60-10 t 50-364/60-11 on B00331-0425 No noncompliance noted Najo: Area: inspected hot functional testing. IE buildetin follower & plant security MARTIN.R D Region 2. Atlanta. Reactor Uporations Nuclear Support Branch BRADFORD, W H Region 2. Atlanta. Office of the Director 80/05/21 6pp
- 8007160791 Forwards 1E Circular 80-14, "Radioactive (untumination of Plant Demineralized Water Sys & Rusultant Internal Contamination of Personnel "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24 is
- 8007230206 Forwards IE Bulletin BO-16, "Potential Misapplication of Rosemburt Inc Hodels 1951 % 1952 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular BO-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007210265 Forwards response to IL Bulletin 80-08. "Fixamination of Containment Liner Penetration Welds " All containment butt welds between punctration sleeve, & process piping in Unit I radiographed Unit 2 to be radiuguaphed upon rompletion CLAYION,F L. Alabama Power Co. 80/07/01 5pp
- 8007230510 Responds to IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Derration "Prior to initial feel loading.procedures to be revised to reflect annunciation & authomatic control functions CLAYTON.F L Alabama Power Co 80/07/17 ip
- BOO7310150 Submits add1 response to IF Bulletin 79-27 re loss of nonclass IE instrumentation & control power sys bus during operation Procedures will be revised to reflect affected annunciation & automatic control functions CLAYTON.F L. Alabama Power Co. 80/07/17 ip
- 8007310330 Forwards "Inservice lnsp Program for Class 1,2 & 3 Components" CLAYTON.F.L. Alabama Power (v. 80/0//25 2pp
- ---8007310374 "Inspivice Insp Piogram for Class 1.2 & 3 Components "
 * Alabama Power Co 80/07/25 78pp
- S Reportable occurrences, LERs & related correspondence
- 8007160861 Part 21 rept re Westinghouse review of sofuty injection termination criteria following recondary side high energy line rupture w/potential for damage to centrifugal charging pumps Concerns are applicable to facility HAIRSTON.W G Alabama Power Co 80/06/11 2pp
- V Operator Examinations
- 8007290525 Folwards SER input rv TMJ Action Plan Task 1 A 3.addrossing revised scope & critoria for licensing exams MOORE.V A Division of Human Factors Safety 80/0//18 2pp
- DOCKET 50-366 EDWIN 1 HATCH RUCH EAR PLANT, UNIT &

 F Security, medical, courgency & fire protection plans
- B007020488 Forwards request for and) info in B005/8 revised guard training & qualification plan End withheld (ref 105FR 790) REID.R W Operating Reactors Branch 1 80/06/19 2pp
- B007230104 Requests participation in study of people-related problems in nuclear safequards Study involves collection of data on licensee security forces & practices IRC wishes to interview socurity mgt personnel at facilities EISENHUT.D 0 Division of Licensing 80/07/11 2pp
- B0072B0514 Advisos that B0071H imergency plan Upgrading per NUREG-0454 will be delayed until 801901 Requests rept from B00422-23 Emergency Preparedness Team rovieu WIDNER, W.A. Georgia Power (o. 80707/21 1p.

- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 menorandum & order containing decisions on U.S 780502 petition for reconsideration of 780413 memorandum & order UCS 77(10) petition sought action fer fire protection for electrical captes EISENMUT.D G Division of Licensing 80/06/25 89pp
- P Operating license stage documents & correspondence
- 8007230028 Summary of 800207 neeting w/Mark I owners group in Bethesda, MD.re revisions to NRC acceptance criteria & outstanding issues relative to Mark I containment long-term program GRIMES C T Flant Systems Branch 80/02/21 31pp
- 8007140641 Advises that dates of responses to 79092/ generic ltr were 791025 for Peach Bottom 2 & 3 & 791115 for Hatch 1 & 2 Rept on valve operability program required only for plants desiring to justify unlimited jurging VERRELLI,D M Operating Reactors Branch 4 80/06/05 1p
- 8007010474 Advises that util will comply w/800507 ltr issuing five addl TMI-2 related requirements for operating reactors When implementation criteria is developed NRC will be notified of any variation from schedule Reserves three options WIDNER, W.A. Georgia Power Co. 80/06/20 ip
- 8007020629 Advises that review has been completed on 800513 rept of calibr results on seismic instrumentation Triaxial Time-History Accelerograph. 2Lbi-ND21 was returned to vendor for repair as recommended MANRY M. Georgia Power Co. 80/06/25 ip
- 8007070389 Notlfication of 800703 meeting u/util in Bethysda,MD to discuss util basis for delayed schedula for installing T-quenchers
 VERRELLI.D Operating Reactors Branch 4 80/06/26 2pp
- B007080287 Discusses applyrability of GE response to questions raised by C Michelson in response to NRC 800507 request Automatic isolation may occur for breaks outside or inside containment depending on break size & location HIDNER.W A Genrgia Power Co 80/06/30 2pp
- 8007180115 Forwards Amend 16 to License NPF-5, safety evaluation & notice of issuance & availability
 REID.R W Operating Reactors Branch 4 80/07/02 2pp
- --BOD7180134 Amend to to License NFF-O5, temporarily revising Tech Specs for MPCI sys to permit stortups w/inoperable MPCI, to conduct special test REID,R W Operating Reactors Branch 4 80/07/02 Bup
- ---B007iB0135 Sufety evaluation supporting Amend 14 to Licensa NPF-5 Operating Reactors Branch 4 80/07/02 2pp
- --8007180138 Notice of issuance & availability of Amend 16 to License
- REID.R W Operating Reactors Branch 4 80/07/02 2pp
- 8007180484 Confirms util commitments at 800703 meeting re schedule for completing mods for resolution of Mark I containment long-term program Meeting summary encl REID.R W Operating Reactors Dranch 4 80/07/07 2pp
- --8007180487 Summary of 800703 meeting w/util re licensee schedule for completing mods for resolution of Mark I containment long-VERRELLI, D.M. Operating Reactors Branch 4 80/07/07 App
- BOO7230656 Provides info re new DFC titles, positions & assignments of personnel resulting from 800428 reorganization of DFC of Nuclear Reactor Regulation NOVAK, T H Assistant Director for Operating Reactors 80/07/10
- 8007280634 Application to amend licenses DPR-57 & NPF-5, changing Tech Specs re torus water temp IF water temp cannot be restored within 24-h reactor shall shutdown using normal shutdown procedures WIDNER, W.A. Georgia Power Co. 80/07/17 3pp
- --8007280642 Proposed Tech Upocs Sections 1 0 t 3 7 rm torus water temp, If water temy cannot be restored within P4-h reactor shall shutdown using normal shutdown procedures # Georgia Power Co = 80/07/17 9pp

- 8007310336 Requests written confirmation of 800718 telcon re critical situation concerning electrical power generation in region served by util NDVAK.T M Assistant Director for Operating Reactors 80/07/22
- G Inspection reports, IE Bulletins & correspondence
- 8007240213 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007140490 Forwards IE Bullstin 80-13, "Cracking in Core Apray Spargers" Written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 90/05/12
- 8007020178 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28,
- 8007010220 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written, response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007100064 Forwards IE Insp Repts 50-321/80-22 & 50-366/80-22 on 800412-0512 No nancompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/29 2pp
- --8007100066 IE Insp Rupts 50-321/80-22 & 50-366/80-22 on 800412-0512 No noncompliance noted Major areas inspected Tech Bpec compliance. RDs, housekeeping. plant operations. GA practices & IE Bulletin 79-26
 DANCE.H C Region 2. Atlanta. Reactor Operations Nuclear Support Branch ROSERS, R F Region 2. Atlanta. Office of the Director BANCARD 50-20 Branch ROSERS, R F 80/05/30 5pp
- B007220072 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/10
- B007140294 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/0 80/05/12
- 8007020736 Forwards IE Bulletin 80~15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Hritten response required O'MEILLY.) P Region 2. Atlanta, Office of the Director 80/06/ Region 2. Atlanta, Office of the Director 80/06/18
- 8007020278 Forwards notices of violation & proposed imposition of civil penalty re IE insp on 800319
 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/19 2pp
- --8007020301 Notice of violation from insp on 800319 Noncompliance noted packages of licensed matis shapped on 800318 w/radiation levels in truck cab excueding regulatory limit

 * Office of Inspection & Enforcement, Office of the Director 80/04/19
- --B007020305 Notice of preposed imposition of ckvil penalty in amount of \$4,000 re violation noted during 800319 insp

 * Diffice of Inspection & Enforcement, Office of the Director 80/06/19
- 8007090074 Requests extension to 800718 to complete response to Itams i & 2 of IE Bulletin 80-10. "Contamination of Nonredicactive Sys & Resulting Potential for Unmonitored Uncontrolled Release of Redicactivity to Environ"
 WIDNER, W.A. Georgia Power Co. 80/06/19 1p
- 8007140180 Piscusses 800319 incident which revealed radiation levels exceeding limits on truck cab arriving at Barnuell site Forwards notice of violation & notice of proposed imposition of civil penalty STELLO, V Defice of Inspection & Enforcement, Office of the Director 80/06/19 2pp

- 8007020450 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'RRILLY, J P Region 2. Atlanta, Office of the Director 80/06/20
- 8007i10250 Ack receipt of 800604 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-32i/80-19 & 50-366/80-19 Region 2, Atlanta, Fuel Facility & Materials Safety Bronch 80/06/23 in
- ---B007i10259 Responds to NRC 8005i2 ltr re violation noted in IE Insp Repts 50--32i/80-19 & 50--366/80-19 Corrective actions full audit of emergency plan & implementing procedures completed HIDNER, W.A. Georgia Power Co. 80/06/04 ip
- --B007i10262 Forwards IE Insp Repts 50-321/B0-19 & 50-366/80~19 on B00421-25 & notice of violation BTOHRLJ P Region 2. Atlanta. Fuel Facility & Materials Safety Branch B0/03/12 2pp
- --8007110260 Notice of violation from insp on 800421-25
 * Region 2, Atlanta, Office of the Director 80/05/12 1p
- --8007i10276 IE Insp Repts 50-32i/80-19 & 30-366/80-19 on 80042i-29 Noncompliance noted failure to audit emergency implementing procedures every 2 yrs under cognizance of safety review foard.

 PERROTTI.D J. TROJANOMEKI.R Region 2. Atlanta, Office of the Director JENKINS, Q R Region 2. Atlanta, Fuel Facility & Materials Bafaty Branch 80/05/12 9pp
- B007300576 Forwards IE Insp Repts 50-321/80-14 & 50-366/80-14 on 900319,0429 & 30 Enforcement action disrussed in NRC B00619 ltr.
 0'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/23 2pp.
- ---8007300580 IE insp Repts 50-321/80-14 & 50-366/80-14 on 800319,0429 & 30 Noncompliance noted radiation levels on vehicle cab in excess of regulatory limits
 BTOHR.JP, WOODRUFF,RL Region 2. Atlanta. Fuel Facility & Materials Safety Branch LAGEY,LR Region 2. Atlanta. Office of the Director. 80/06/19 Bpp
- 8007170115 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/06/24 pc.
- 8007230249 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Written response required IE Circular 80-16 also encl No written response required O'RCILLY. J P Region 2. Atlanta. Office of the Director 80/06/27 ip.
- 8007220281 Bubmits final response to IE Bulletin 77-18 Noise evaluations performed for inaccessible areas following installation of evacuation signals Visual warning lights will be installed during Fall 1980 refueling outage HIDNER, W A Georgia Power Co 80/06/30 ip
- 8007090337 Forwards info in response to Items 1.2(a) & 3 required by IE Bulletin BO-11. "Masonry Wall Design " Item 2(b) to be addressed in final rept
 HIDNER, H. A Georgia Power Co BO/07/03 18pp
- 9007140384 Responds to 1E Bulletin BO-OB re containment liner penetration weld exam Requests 30-day extension for info submittal due to large number of flued head containment liner penetrations & heavy high priority work load WIDMER.W A Georgia Power Co BO/O7/O7 1p
- 8007280126 Ack receipt of 800623 ltr informing NRC of steps taken to correct deviations noted in IE Insp Repts 50-321/80-02 & 50-326/80-02 MURPHY,C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/09 ip
- --8007/280128 Responds to NRC 800208 & 0411 ltrs re deviations noted in IE Intp Repts 50-321/80-02 & 50-366/80-02 Corrective actions, submitted encl draft enganeering review of GA fire protection program at NRC 800602 meeting WIDNER, W A Georgja Power Co 80/06/23 42pp.

- 8007240252 Ack receipt of BOBal2 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/80-17 & 50-366/80-17 O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/07/11 1p
- --8007240264 Responds to NRC 800519 ltr re viblations noted in IE Insp. Repts 50-321/80-17 & 50-366/80-17 Corrective actions new airlock scheme installed Actions re event & deviation reportability justified WIDNER, W.A. Georgia Power Co. 80/06/12 4pp
- ---B007240277 Forwards IE Insp Repts 50-321/B0-17 & 50-366/B0-17 on B00309-0411 & notice of violation LEMIS.R C Region 2. Atlanta: Reactor Operations Nuclear Support Branch B0/75/19 2pp
- --8007240285 Notice of violation from insp on 800308-0411
 * Region 2. Atlanta, Office of the Director 80/05/19 2pp
- --8007240292 IE Insp Repts 50-321/80-17 & 50-366/80-17 on 800308-0411 Noncompliance noted failure to maintain secondary containment door integrity & to meet NRC reporting requirements ROCERS, R F Region 2. Atlanta, Diffice of the Director DANCE, H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 80/05/19 5pp
- 8007250292 Responds to IE Bulletin 80-17. "Failure of Control Rods to Fully Insert" Scram discharge vol (SDV) vont & drain operability verification test performed All drain & vent valves verified operable No residual water found in SDV WIDNER, W A Georgia Power Co. 80/07/11 1p
- 8007310275 Responds to HRC 800619 natice of violation re excessive radiation exposure rate inside cab of radwaste transport vehicle Radiation survey indicated radiation levels within code requirements Requests mitigation of violation severity WIONER W A Georgia Power Ca 80/07/14 2pp
- --8007310287 Responds to NRC 800619 notice of proposed imposition of civil penalty Radiation survey of vehicle indicated levelt within code requirements Requests mitigation of severity of violation treduction of civil penalty WIDNER, W.A. Georgia Power Co. 80/07/14 2pp
- 8007280538 Advises of proposed compensatory measures re 2-wk extension for scram testing required for IE Bulletin 80-17 Util will perform tests as soon as possible should critical load situation ease WIDNER, W.A. Georgia Power Co. 80/07/19 ip
- B0072B0541 Advises of completion of Items 1 & 2 of IE Bulletin B0-10, "Contamination of Nonradioactive Sys " Complete documentation of affected sys % associated monitoring procedures available for review during future onsite insps WIDNER, W A Georgia Power Co 80/07/18 ip
- 8007290618 Requests delay in performing scram tests required by IE Bulletin 80-17 due to high temps in region Removing large units from svc would place severe strain on electric generating capacity of region WIDNER, W.A. Georgia Power to 80/07/18 2pp
- R Periodic operating reports & related correspondence
- 8007280678 Forwards monthly operating repts for June 1980 MANRY.M Georgia Power Co 30/07/10 1p
- ---8007280686 Forwards monthly operating repts for June 1980 MANRY M Georgia Power to 80/07/10 1p
- ---B0072B0692 Monthly operating ropts for June 1980 BLACKWELL.R M Georgia Power Co B0/07/10 7pp
- B Reportable accurrences, LERs & related correspondence
- 8007010494 Forwards LER 80-089/03L-0 MANRY.M Georgia Power Co 80/06/24 ip
- --B007010503 LER 80-089/03L-0 on 800530, while performing HNP-2-3315, torus suction valves 2641-F041 & 2641-F042 failed when given open signal Torus valves shorted out due to Londensation in HPCI room Cause of condensation was strom leakage around seal NIX:R T Georgia Power Co 80/06/24 2pp
- 8007010510 Forwards revised FCR 80-068/03X-1 MANRY:M Georgia Power Co 80/06/24 ia

--80071506B5 LER 60-095/O3L-0 on B00617, during HNP-2-3123, loop control sys blower operability, inboard leadkage control sys flow indicator A pegged upscale & would not return to zero Caused by bent flow element float Float straightened & cleaned NIX,R T Georgia Power Co 80/07/07 2pp -8007010518 Revised LER 80-0681034-1 on 800422, while performing primary containment recombiner sys functional test, recombiner sheath temp failed to recain within Tern Spec Caused by setpoint being set too high BAYLEY'S X sentgia Power Co 80/06/24 2pp 8007030272 Forwards LER 80-090/03L-0 MANRY,M Georgia Power Co 80/96/24 1p 8007170405 Forwards LER 80-100/017-0 MANRY, M Georgia Power Co 80/07/08 Ip --8007170410 LER 80-100/01T-0 on 800702, during performance of high drywell pressure surveillance procedures, found switches set above Toch Spec limit Apparently caused by setpoint drift Switches recallbr NIX.R T Georgia Power Co 80/07/08 2pp --B007030274 LER B0-090703L-0 on B00604.while starting up Unit 2 reactor. HPCI auto isolation logic for Channel B did not reset until reactor pressure was 152 psig (aused by callor procedure w/overly conservative sitpoint Setpoint changed NIX.R 1 Georgia Power Co. 80/06/24 200 8007170453 Forwards LER 80-096/03L-0 MANRY, M Georgia Power Co 80/07 8007030280 Ferwards LFR 80-092/03L-0 MANRY M Georgia Power 40 80/06 20706724 1p 80/07/09 to --B007030282 LER B0-092/09L-0 on B00611 during surveillance checks at steady-state power operaturs found B rod block monitor bypassed while telecting rods Caused by component failure Power supply repaired & returned to svc NIX:R T Georgia Power Co B0/06/24 2pp --B00717046B LER B0-096/03L-0 on B00627, w/reactor mode switch in run, reactor bldg to torus vacuum breaker isolation valve.
2748-F31i,failed open Caused by failure of delta pressure switch, 2748-N21i, reactor bldg to delta pressure switch NIX,R T Georgia Power Ca 80/07/09 2pp B007030241 RG on B00522, licensee reviewed Kinemetrics, Inc B00513 calibr rept re seismic instrumentation Triacial Time-History Accelerograph 2L51-ND21 calibr indicates excessive change in longitudinal channel characteristics MANRY, M Georgia Power Co 80/06/25 ip 0-350/560-08 Hal sbrewrod 5650157608 och www. 2004 och warden by 2004 80/07/11 1p --8007210397 LER 80-093/03L-0 on 800612.during steady state power, HNP-2-1050 rounds procedure readings showed drywell avarage temp high Caused by high ambient temp & inadequate cooling. Chilled water flow increased COGGIN.C L. Georgia Power Co. 80/07/11 3pp 8007020520 Forwards 800627 NPDES rept made to State of GA re discharge of free available chloride in cooling tower blowdown MANRY,M Georgia Power Co. 60/06/26 lp B0072103B4 R0 on B00711.Unit 1 LPCI inverter tripped & Unit 2 4-kV bus 2F supply breaker & HPCI tripped Supply breaker trip caused by jumper missing from neutral leg Motor valve on HPCI replaced making it operable Events submitted per IEB B0-17 MANRY.M Georgia Power Co 80/07/14 2pp --8007020523 NPDES nencompliance notification on B00619, at full power operation, circulating water chlorination sequence was automatically activated, resulting in release of free available chloring in cooling water bloodown
BYERLEY, T E Georgie Power Co 80/06/27 2pp 8007280505 Forwards LER 80-098/03L-0 MANRY.M Georgia Power Co 80/07. B007030277 Forwards LER 80-094/03L-0 MANRY,M Georgia Power Co 80/06/26 Sp 80/07/14 10 ---8007280512 LER 80-098/03L-0 on 800626. w/reactor at 99% steady state power, HPCI pump failed operability Caused by HPCI pump suction pressure transmitter 2E41-N019 drifting out of televance causing 2E41-H606 to Indicate incorrectly NIX.R T Georgia Power Co 80/97/14 2pp --B007030277 LER B0-094/03L-0 on B00613, while performing routine surveillence on torus-drywell vacuum breaker valve, valve 2748-3238 failed to open Cause unknown Vacuum breaker valve will be repaired during neit reactor cold shutdown NIX.R T Georgia Power Co 80/06/26 2pp 8007240124 Forwards LER 80-097/03L-0 MANRY.M Georgia Power Co 80/07/15 ip B007110429 Forwards LER 80-091/03L-0 MANRY,M Georgia Power Co 80/06/ 80/06/30 1p --8007240128 LER 80-097/03L-0 on 800625,while performing surveillance procedure HNP-2-3307.HPCI steam line flow FT&C, flowswitch 2E41-N004 setpoints exceeded Tech Spec limits Caused by setpoint drift Switch was recalibr & returned to svc NIX.R T Georgia Power Co 80/07/15 2pp --8007110437 LER 80-091/03L-0 on 800605, while pulling rods to increase power-level core max fraction of limiting power density found higher than Tech Sprc allowed Caused by combination of low feedwater & low xenon NRC reviewed problem CDGGIN, C.L. Georgia Power to 80.06/20 2pp CDGGIN, C. L. 8007240165 Forwards LER 80-103/01T-0 B007110366 R0 50 366/1980-100 on 80070P, while performing surveillance procedures HNP-2-3002 & HNP-2-3172M, high drywoll pressure switches 2C71-N002A through D & 2E11-N011A through D found out of tolerance faused by setpoint drift Switches recalibr MANRY, M Georgia Power Co 80/07/02 2pp B0/07/17 ip. MANRY, M. Georgia Power Co. --8007240167 LER 80-103/01T-0 on 800709, determined 2E11 NOIOA through D high drywall pressure switches outside Tech Spec limit Caused by setpoint drift Switches recalibr NIX:R T Georgia Power Co 80/07/17 2pp 8007150635 Forwards updated LER 80-064/03X-1 MANRY.M Georgia Power Co 80/07/03 1p 8007250411 Forwards LER 80-099/03L-0 MANRY, M Georgia Power Co 80/07. ~-B007150642 Updated LER 80-064/03X-1 on B00419, w/unit in cold shutdown, while performing MSIV leakago control sys LEFT; bleed valve EEGZ-POOIR indicating lights went out Caused by defective tarque switch Turque switch has replaced COGGIN.C.L. Georgia Power Co. B0/07/03 2pp 80/07/17 1p --8007250412 LER 80-097/03L-O on 800626 during instrument check, found B drywell analyzer giving false dioxygen reading Caused by personnel error Regulators marked for double check of reagent gas flow while chanqing reagent gas bottles NIX.R T Georgia Power Co 80/07/17 2pp BO072B0450 Forwards updated LFR B0-045/01X-2 MANRY N Georgia Power Cn 80/07/03 1p 8007280518 Forwards revised LER 80-096/03L-1 MANRY, M Georgia Power Co 80/07/17 tp --8007280455 Updated LER 80-045/01X-2 on 800404 leakage rates found unacceptable during leak rate test Caused by heat damage from installation welding Valves will be replaced COGCIN.C.L. Georgia Power Co. 80/07/03 2pp --B0072B0526 Revised LER 80-096/03L-1 on 800619, w/reactor mode switch in run, reactor bldg to torus vacuum areaker isolation valve, 2748-F311, failed Caused by failure of delta pressure switch 2748-N211 Micro switch replaced NIX,R T Georgia Power Co 80/07/17 2pp 8007150578 Forwards LER 80-075/03L-0 MANRY,M Georgia Power Co 80/07/07 1p

DECRET 50-3A7 BALLLY GENERATING STATION

- A Application/construction stage documents & correspondence
- 8007010478 Forwards well charts for 800611-18, Bailly wells w/o recorders pand levels pneumatic pressure transducers & water metar readings for 800618 & USSS wells for 800617 BDMH.R J Northern Indiana Public Service Co 80/06/24 3 80/06/24 34pp
- 8007210174 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls i-3, "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj to certain constraints MATTSON,R J Division of Safety Technology 80/06/25 3pp
- 6007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
- EISENHUT, D O Division of Licensing 80/06/26 200
- 8007230621 Summary of B00612 meeting w/Mark II owners group in Bethesda.MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON.C J Generic Issues Branch 80/07/03 57pp
- B007250175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago, IL to discuss lead Mark II plants chugging & C/O load specs
 ANDERSON. C Generic Issues Branch 80/07/23 2pp
- Adjudicatory correspondence
- 8007140001 Response in appasition to ABLB provisional order in CP extension proceeding Urges immediate consideration of evacuation alternatives prior to const GRABDWSKI.A W . GRABDWSKI.G V Affiliation Unknown 80/06/24 4pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables Division of Licensing FISENHIIT, D O 80/06/25 89nn
- 8007020453 Response to opposition to ASLB 800530 provisional order ruling on interventions & scope of CP extension proceeding Urges revision or clarification re issues & stds which cannot abide OL proceeding Certificate of Byc encl SHEA, K H , FRANTZ, S P , EICHHORN, W H Northern Indiana Public Bervice Co 80/06/30 44pp
- B007090021 Submits statement of objections on behalf of util in response to ASLB special prehearing conference provisional order Urges ruling on contentions as previously filed due to unsuccessful negotiations Certificate of Svc encl SWEA, K H Lowenstein, Newman, Reis, Axelrad & Toll 80/06/30 80/06/30 4pp
- BOO7080026 Response to ASLB 800530 special prehearing conference provisional order Urges issuance of revised order to answer whort pilings questions Adopts reworded Contentions R-1 1-15 Certificate of Boy encl
 BEKULER.B N Illinois, State of 80/06/30 12pp
- 8007080055 Response in opposition to ASLB 800530 special prehearing 207080055 Response in opposition to ASLB 800330 special preheiconference provisional ander Requests revision of reworded contentions & urges that short pilings questions be answered within 10 days Winotice of appearance & Certificate of Svc VOLLEN, R J. OSANN, E W. lawk Walton League of America. Port County Chapter VOLLEN, R J. 80/06/30 21pp
- 8007150056 Notice of appearance in CP extension proceeding Certificate of Svc encl MURRAY.M J Illinois, State of 80/07/09 4pp

H. General correspondence

- B007:40028 Forwards J Seed Itr directed to S Eizenstat w/RD Folsom B00620 response & White House tracking worksheet re plant site & design Urges return of documents to agency liaison after appropriate action after appropriate action
 SEAL,M.M President of US & Executive Offices 80/06/24 App
- B007100235 Protests & appeals ruling that evacuation & other significant issues will not be admitted by NRC to facility CP hearings People must be allowed to speak at hearings Cartificate of Syc encl BCHULTZ,Q Affiliation Unknown B0/06/25 3pp

- @ Inspection reports IE Bulletins * correspondence
- 8007140509 Forwards IE Bulletin 80 13. "Cracking in Core Spray Spargers " No written recponse (equired KEPPLER, J.G. Region J. (bicago, Office of the Director 80/05/12
- B007010132 Forwards IE Info Notice 80-P3 "Loss of Section to Emergency Feedwater Pumps" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/29
- 8007220206 Forwards (E Info Notice 80-76. "Evaluation of Contractor GA Programs" No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/06/10
- B007140323 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Distharge Vol Lapability 'No writtin response lequired KEPPLER, J G Region 3, Chicago, Office of the Director B0/0 80704712
- G007280635 Forwards IE Info Notice 80-20, "Prompt Reporting of Info in Accordance W/10(FR50 55(e) " No written response required KEPPLER.J G. Region 3, Chicago Office of the Director 60/06/13
- 8007020587 Forwards IE (irrular 80-15, "Loss of Reactor Conlant Pump Cooling & Natural Circulation (poldown "No written response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/06/20
- B007170501 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required MEPPLER, J 9 Region 3. Chicago. Office of the Director B0/06/24
- 8007230332 Forwards IE Bulletin 80-14, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes "Written response required IE Circular 80-14 also encl No written response required WEPPLER, J G Region 3. Chirago, Office of the Director 80/06/2 80/06/27
- 8007250630 Informs that GE & Saryent & Lundy engineering has been stopped temporarily, due to project delays Util unable to obtain necessary info for response to IF Bulletin 80-09 Response will be submitted by 810601 SHORB, EM Northern Indiana Public Service Co 80/07/09 1p
- R Periodic operating reports % related correspondence
- 8007110438 Forwards well charts for 800618-25, Bailly Wells w/o recorders, pond levels, pneumitic pressure transducers & water meter readings for 800625 % USGS wells for 800624 80HN R J Northern Indiana Public Service Co. 80/07/07
- 8007280141 Forwards "1979-1980 Annual Rept Deilly Nuclear 1 Site. Encompassing Apr 1979-Mar 1980," eith annual ecological monitoring program rept PURCELL, J. F. Northorn Indiana Public Service Co. 80/07/07 1p
- --800728014/ "1979-00 Annual Rept Bailly Muclean I Site.Encompassing Apr 1979-Mar 1980." sixth annual ecological monitoring program rest
 - igram rept Texas Instruments, Inc. 80/06/30 425pp
- 8007210464 Forwards well charts for 800625-0702.Bailly wells w/o recorders.poid levels.pneumatic pressure transducers & water meter readings for 800702 & US65 wells for 800701 BDHN:R J Northern Indiana Public Service Co 8070716 39pp 80/07/16 3900
- 8007280482 Forwards well thatts for 800709 (6.Bailly wells w/o water meter reading for 800/16 & USGS wells for 800/15

 BOHN, R. J. Northern Indiana Public Service Co. 80/07/22 34pp

- DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2
- F Security, medical emergency & fire protection plans
- 800707014B Documents NRC telion & approval of temporary elemption to elisting emergency plan. Section 4 3 1 1-C requiring decontamination shower facilities in emergency control ctr TRIMBLE D.C. Arkansas Power & Light Co. 80/06/27 2pp
- 8007230073 Notification of 800722 meeting w/AR Power & Light Co in Bethesda.MD to review proposed early warning sys VISSING.G S Operating Reactors Branch 4 80/07/16 2pp

G Adjudicatory correspondence

- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refire protection for electrical cables
 EISENHUT, D. G. Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007110449 Requests response to encl R Lacewell ltr re plans to increase facility spent fuel storage pond site BETHUNE,E House of Rep 80/04/30 2pp
- 8007010024 Submits updated info re admittance of NRC personnel to facility Requests that permanent nonemployee picture badges & site orientation be provided Myu encl SEYFRIT, K V Region 4. Dallas. Office of the Director 80/06/16
- B007070020 Requests that util provide IE headquarters w/microfiche copy of listed P&iDs MADSEN,G L Region 4. Dallas. Office of the Director B0/06/16
- 5007250070 Responds to encl 600504 ltr to President Carter re nuclear energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl DENTON-HR Office of Nuclear Reactor Regulation, Director 80/06/27 22pp
- BOO7100148 Requests removal of TB Connet from list of correspondence recipients & addition of N Regoolds Licensee has changed legal representation
 TRIMBLE D C Arlansas Power % Light Co 80/07/03 ip
- 8007310331 Responds to B00623 itr re B00510 event at Unit 1 Forwards LER 80-015/01-0 & 1E Insp Repts 50-313/80-07 & 50-368/80-07 Discusses treatment of spilled water & radipactive content of water 4/0 encl SEYFRIT.K V Region 4. Dailes. Office of the Director 80/07/15
- P Operating license stage documents & correspondence
- B007230099 Requests submittal of proposed Tech Spec changes providing for redundancy in decay heat removal capability in all modes of operation Model Tech Specs which would provide acceptable resolution encl for guidance EISENHUT.D C Division of Licensing 80/06/11 62pp
- 8007010538 Summary of 800319 meeting w/util & C-E in Bethesda, MD record protection calculation syn software Six issues identified for further consideration before implementation in plant software List of attenders & six issues encl MARTIN, R Operating Reactors Branch 3 80/06/18 App
- B007080066 Responds to NRC B00515 request for info re GE turbing discs Unit 2 turbing is impolse reaction.i,800 rpm tandemcompound four flow, two-stage reheat unit Hours of operation, number of turbine trips & uverspeeds encl CAVANAUGH, W. Arkansan Power & Light Co. 80/06/26. Bpp
- 8007190489 Application to amend Licenses DPR-51 & NPF-6, deleting requirement for testing reactor bldg smake detectors while reactors remain critical Suggested changes to Tech Specpages & Class III fee enci CAVANAUGH. W Arkansas Power & Light Co 80/06/26 2pp
- --B007150494 Suggested changes to Tech Spec Pages 3/4 3-43 & 110p refire detection instrumentation

 * Arkansas Proper & Light Co B0/06/24 2pp

- 8007070253 Responds to NRC 800410 ltr requesting that all licensees amend Tech Specs so that definition of term "operable" would be consistent w/NRC STS Revision will require at least 90 days
 TRIMBLE D C Arkensas Power & Light Co 80/07/01 2pp
- 8007180429 Informs that util is interested in participating in NRC research program for interim reliability evaluation program, discussed in 800612 meeting TRIMBLE, D C Arkansas Power & Light Co 80/07/01 3pp.
- 8007250001 Requests submittal of application for amend to license consisting of Tech Spec changes & license conditions PWR Model Tech Specs & Model license conditions for TMI-2 Lassons Learned Category A items encl for guidance EISENMUT, D Q Division of Licensing 80/07/02 69pp
- B00716034B Submits info re RCP oil collection sys per R Martin request Sys not required to be seismically qualified TRIMBLE, D C Arkansas Power & Light Co 80/07/08 ip
- 8007210023 Requests info re 800624 loss of offsite power transient at Unit 1 Info includes description of switchward operation, process computer printouts of alarms during transient & strip charts for primary & secondary sys NDVAK,T M Assistant Director for Operating Reactors 80/07/08.
- 8007240311 Advises of NRC reorganization on 900428 which resulted in number of changes in ofc titles, positions & assignments of personnel. Also submits info for GETR NOVAK, T M Assistant Director for Operating Reactors 80/07/08
- 8007150394 Advises of continued compliance w/current regulations re hydrogen production from clad-water reaction after installation of RCB vents per NUREO-0578 Procedural guidelines will be submitted 810101 TRIMBLE, D C Arkanses Power & Light Co 80/07/10 2pp
- 8007270040 Responds to memo re fuel adjustment clause provision that would permit passing 90% of cost of replacement power on to ratepayers NRC would present any info at formal hearing No investigation planned VOECELIR J Office of the Executive Legal Director 80/07/18, 200
- B007280222 Tech Bpec change request to allow continued operation of plant Qualified radiation monitors will not be available in time to meet existing Tech Specs effective B00801 Class IJ fee encl STEEL.C L Arkansas Power & Light Co B0/07/21 4pp
- --B0072B0226 Proposed revisions to Tech Bpecs,Pages 3/4 3-39 through 3/4 3-42,constituting Amend 7 to OL Change allows continued operation beyond 800731 end date for interim method of determining post-accident radiation levels # Arkansas Power & Light Co 80/07/21. 4pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007020194 Responds to IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break w/Continued Feedwater Addition " Sufficient time would exist for operator to isolate affected oncethrough steam generator in event of overpressurfization. TRIMBLE.D C Arkansas Power & Light Co 80/05/27 5pp.
- 8007020269 Forwards IE Info Notice 80-22: "Breakdowns In Contamination Control Programs " No written response required. SEYFRIT.K. V Region 4: Dallas: Office of the Director 80/05/28:
- 8007210342 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required. SEYFRIT, K V. Region 4, Dallas, Office of the Director 80/05/29
- 8007010040 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required SEYFRIT, K V Region 4, Dallaw, Office of the Director. 80/05/29. ip
- 8007220177 Forwards IE Insp Repts 50-313/80-07 & 50-368/80-07 on B00422-0521 & notice of violation. MADSEN, 0 L Region 4, Dallas, Reactor Construction & Engineering Bupport Branch 80/06/05 2pp
- --8007220185 Notice of violation from insp on 800422-0521.
 * Region 4. Dallas, Office of the Director 80/06/04 ip.

```
007220197 IE Insp Repts 50-313/60-07 t 50-3268/80-07 on 800422-0521
    Noncompliance noted incomplete written procedures, insufficient adherence to procedures & poor housekeeping
   measures
WEBTERMAN,T F. JOHNSON,W D. CALLAHAN,L J. Region 4. Dallas.
Office of the Director BO/O6/04 18pp
```

- 7020201 Responds to 1E Bulletin 80-05, "Vacuum Condition Resulting n Damage to Chomical Vol Control Sys (CVCS) Holdup Tanks "unit I reactor cuolant make-up tank & Unit 2 vol ontrol tank could contain appractable amounts of hydrogen RIMBLE.D C Arkonsas Power & Light Co 80/06/10 Spp
- 7220074 Forwards IE Info Notice 80-26, "Evaluation of Contractor A Programs " No written response required EEVFRIT, K V Region 4. Dallas. Office of the Director 80/06/10
- 07160321 Forwards IE Info Notice 80-27, "Degradation of Reactor coolant Pump Studs " No specific action or response equired gEYFRIT.K V Region 4. Dallas, Office of the Director 80/06/11
- 07300349 Forwards IE Insp Repts 50-313/80-09 & 50-368/80-09 on 000527-30 & notice of violation MADSEN.O L. Region 4. Dallas. Reactor Operations Nuclear Support grant 80/06/12 2pp
- 8007300353 Notice of violation from insp on 800527-30
 * Region 4. Delias. Reactor Operations Nuclear Support Branch 80/06/11 ip
- __B007300334 IE Insp Repts 50-313/B0-09 & 50-368/B0-09 on B00527-30 Noncompliance noted failure to adhere to procedures for handling temporary mods to jumpers & bypasses YANDELL/L A . WESTERMAN.T F Region 4. Dallas. Befice of the Director B0/06/11 3pp
- 6007070172 Ack receipt of 800529 Itr informing NRC of steps taken to correct viblations noted in IE Insp Repts 50-313/80-06 & 50-368/80-06 MADDEN.O L Region 4, Dallas. Reactor Operations Nuclear Support Branch 80/06/17 ip
- EDO7230244 Forwards IE Investigation Repts 50-313/80-08 t 50-368/80-08 on 800510-12 No honcompliance hoted BRDHN, G D Region 4. Dallas. Fuel Facility t Materials Safety Branch 80/06/20 2pp
- --8007230257 IE Investigation Repts 50-313/80-08 & 50-368/80-08 on B00510-12 No moncompliance noted Major areas inspected radiological conditions & Environ impact associated w/main Coolant jump seal failure
 BRONN, G D Region 4, Dallas, Fuel Facility & Materials Safety
 Branch Wilbonn, L Region 4, Dallas, Office of the Director.
 80/06/18 5pp
- \$\forall 007240031 Forwards IE Circular 80-15, "Lost of Reactor Coulant Pump Cooling & Natural Circulation Cooldown" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/20
- 8007300320 Ack receipt of 800627 ltr informing NRC of steps taken to correct violation noted in 16 Insp Repts 50-313/80-07 & 50-366/80-07 MADSEN, 0 L. Region 4. Dallas, Reactor Operations Nuclear Support
 - MADBEN, Q L Regio Branch 90/07/22
- >8007300325 Responds to NRC 800A05 ltr re violation noted in IE Insp Repts 50-313/80-07 & 50-368/80-07 Corrective actions junction box cover replaced & door on end closed TRIMBLE.D C Arkansas Power & Light Co 80/06/27 2pp
- 9007300329 Ack receipt of 800702 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-313/80-09 t HADBEN O L Region 4, Dallas, Reactor Operations Nuclear Support Branch B0/07/22 ip
- -B007300333 Responds to NRC 800612 ltr re violation noted in IE Insp Repts 50-313/80-09 & 50-366/80-09 Corrective actions entries in jumper & bypass log were cleared Completed pages of log were forwarded to files TRIMBLE,D C Arkenses Power & Light Co 80/07/02 2pp

```
R Periodic operating reports to related concespondence
```

- 8007210381 Forwards monthly operating rept for June 1980 TRIMBLE.D C Arkansas Power & Light Lo 80/07/15 1;
- --8007210382 Monthly operating left for June 1980 PENDERGRAFT R Arkansas Power & Light (c . 8 80707715
- 8 Reportable occurrences, LERs & related correspondence
- 8007010527 Forwards LER 80-032/031-0 TRIMBLE D C Arkansas Power & Light Co 80/06/24 1p
- --B007010535 LER 80-032/03L-0 on 800525 during Mode 1 operation, plant ANY AVAILABLE BUTTURA VOLUME ON BUODED during Mode 1 aperation, computer failed on three ucrusions Cause undetermined Computer software diagnostic toutines or backup computer syswill be purchased to alloviate problems PENDERGRAFTER Arkinsas Power & Light Co 60/06/24 1p
- B007010434 Forwards LER 80-071/04L-0
 TRIMBLE D C Arkansas Power & Light Co 80/06/25 ip
- --B007010441 LER 80-031/04L-0 on 800527, during Mode 1 operation, condenser gas sample munitur 2RITS 6645 was found inoperable Radiation levels were normal per Tech Spics Caused by bearing failure on sample motor Engineering evaluation underway PENDERGRAFT, R Arkansas Fower & Light Co 60/06/25 1p
- 8007140621 PNO-IV-80-023 on 800624, all offsite power to both units was lost when two lines were tripped by dispatcher Third line was out of svc for maint HUNNICUTT, D. Region 4. Dallas, Offsite of the Director 80/06/25
- 8007010407 Forwards LER 80-034/03L-0 TRIMBLE.D C Arkansas Power & Eaght Co 80/06/26 ip
- --8007010414 LER 80-034/03L-0 on 800531 during Node 1 appration, leak developed on charging pump B suction pipe at coupling for capped test connection line Caused by vibration Defective pipe spool piper will be replaced SHIVELY.C N Artansas Power & Light to 80/06/26 ip
- B007280546 R0s 50-313/80-27 & 50-368/60-042 on 800624 events occurred on 800 ky power lines which resulted in loss of all 800 ky power lines & reactor trips of both units Cause not stated Both units stable Followup rept will be transmitted Q'HANLON.J P Arkansas Power & Light Co 80/06/26 2pp
- BOO7010437 Forwards updated LFR BO-025/03X-; TRIMBLE.D C Arkansas Power & Light Co 80/06/2/ ip
- --- 8007010440 Updated LER 80-0/5/03x-1 on 800507.during Made & operation. valve 200-5657 was isolated to facilitate maint work to alarm indicated volve open when valve was closed Caused by backed out strew leaving "witch micaligned Switch realigned PENDERGRAFT, R Arkansas Power to Light Co. 80/06/27 lp
- 8007080160 Forwards LER 80-033/03L-0 Arkansas Power & Light Co 80/06/27 ip TRIMBLE, D C
- --B0070B0166 LER B0-033/031-0 on B00530 during Mode 1 operation, plant protection sys C high B/O dolta P trip was bypassed Caused by Failed power supply on bistable card Bistable card replaced & plant protection sys to:tod PENDERGRAFT.R Arkansas Power & Light Co 80/06/27 ip
- B0070B0171 Forwards LER 80-036/031-0 TRIMBLE, D.C. Arkansas Power & Light Co. 80/06/27 1p
- --B007080178 LER H0-036/03L-0 or 800602 during Mode I operation steam driven emergency feedwater pump 2P7A tripped on overspeed following manual start Cause not determined Pomp will be tested frequently until trip problem resolved PENDERGRAFT. A Arkansas Power & Light Co 80/06/27 ip
- B007280646 Forwards LER 80-009/001-0 TRINBLE,D C Arkansas Power & Light Co 80/06/30 Ip
- --8007280655 LER 80-035/Off. O on BGO601, containment sump level indicator 2L1-5641 whiteated approx 30%, after n1) water bot been drained from sump Caused by magnets being detached from float ball on level suitch %LS-5641 Float ball replaced PENDERGRAFT.R Arkansas Power & Light Gn 80/06/30 ip

- 8007080144 Forwards LLR 80-040/0 (L-) Alkalisas Power & Light Co. 80/0//02 in
- --8007080154 LFR 80-0407051-0 on 800605 during normal shutdown operations in Mode 3 emergency freedwate supply valve 2CV-1075 failed to open on command Caused by loose connection on valve operator metal lead Connection (leaned 4 tightened SHIVELY, C.N. Arkansas Power & Light Co. 80/07/02 ip
- --8007090336 LTR 80-03870 H-O on 800607, safety injection tank found to have boron concentration less than Tech Sper Probably caused by boron stratification adequacy of sampling method
- 8007140395 Forwards LER 80-042/017-0
 TRIMBLE-D C Arkansas Power 5 Light Co 80/07/07 in
- --8007140405 LER BO 042/017-0 on 800707 w/Mayflower 500 kV transmission line out of svc.Mabrlvale 500 kV tripped on ground fault Caused by ground fault & resulting overload SHIVCLY.C N Arkansas Fower & Light (o 80/07/07 5pp
- 8007150647 Forwards LER 80-041/03L-0 TRIMBLE, D.C. Arkansay Power & Ligh Arkansas Power & Light Co 80/07/09 1p
- --8007150660 LER RO-041/03L-0 on 800610.during Mode I operation, plant computer was taken out of syl rendering CDLSS inoperable Computer was taken out of syl to bouble-hoot problem re CRT displays Backup plant computer will be installed PENDERGRAFT, R Arkansas Power & Light Cp 80/07/09 lp

- 8007150694 LER 79-100 has been rancelled COLLINS M. Arkansas Power & Light Co. 80/07/14 ip
- BOO7210396 Forwards updated LER BO-018/03X 1
 TRIMBLE D C Arkonsas Power & Light Co 80/07/14 1p
- --8007210400 Updated LER 80-018/03X-1 on 800407 following loss of offsite power transferat emergency frodwater flow become erratic Prubably Lauved by heating of feedwater train w/n forced Plow.allowing water to drain back to condensate pump CLOGUURN.T Arkansas Power * Light Co BO/07/14 2pp
- B007310334 Discusses B00704 routine surveillance test on emergency steam driven feedwater pump during which steam leak developed Requests that one of five failed study be delivered to Paramuters, inc for analyses MADEEN, 6 L. Region, 4, Dallas, Reactor Operations Nuclear Support Branch 80/07/15 2pp
- DOCKET 50-JA9 WILLIAM B MCGUIRF NUCLEAR STATION, UNIT 1 A Application/constituction stage decements & correspondence
- 8007110519 Notification of 1000514 meeting w/stil in Bethesda.MD to discuss util design review of control room BIRKELR A discensing Dranch i 80/04/30 2pp
- B007010571 Advise: that NRC 800409 request for independent plant-wide audit of installation of sufety-related equipment & cables need not be fulfibled based on addl info provided in util 800605 lts YOUNGBLOOK, B | | Legnsing Branch 1 80/06/20 3pp
- :007090091 Notsfication of 8006/5-27 meeting w/util to discuss TMI-2 action plan items Agunda encl BIRKELSR A Creensing Branch 1 90.06/20 Spp
- 8007230001 Forwards statement of policy to requirements to be met for current DL applications of derived from NURFG-0660 & found in NUREG-0694 EISENHUL D C Civision of Licensing 80/06/24 2pp

- 8007110583 Forwards request for add) info re reactor sys as result of review of application for OLs
 YOUNGBLOOD, B J Licensing Branch 1 80/06/30 5pp
- 8007160486 Forwards TMJ review stem schedule, designating principal branch review responsibilities BIRKELR A Licensing Branch 1 80/06/03 4pp
- 8007170696 Forwards schedule for review of TMI-2 task force items including designated principle branch review responsibilities
 BIRKEL.R A Licensing Branch 1 80/06/30 4pp
- 8007230635 Forwards std order for DDE work MATTSDN:R J Division of Safety Technology FIN A-1121-0 80706/30 3pp
- --8007230652 Std order for DOE work "Review of Auxiliary Fædwater Sys Reliability Evaluation Studies for Diablo Camyon 1, McGuire 1.Summer 1 & San Onofre 2 & ECCS Reliability Analysis of Manual vs Automatic " Issued to Sandia Labs GRENIER.B L Division of Safety Technology FIN A-1121-0 80/06/27 7pp
- 8007080345 Forwards info & drawings re use of Category I masonry walls for supporting piping & components in response to NRC 800421 ltr Drawings available in Central Files only Fourteen illegable drawings encl PARKER.W O Duke Power Co 80/07/02 27pp
- 8007170685 Requests addl info re reactor sys YGUNGBLOOD,B J Licensing Branch 1 BO/07/02 Spp
- 8007110309 Forwards Chem-Nuclear "Process Control Program for CNSI Mobile Solidification Units Using Dow Process" Affidavit for withholding oncl Program withheld (ref 10CFR2 790) PARKER, W. D. Duke Power Co 80/07/08 1p
- 8007180069 Requests that protection sys design be reviewed to determine degree of conformance to listed criteria Review results should be submitted by 800804 YOUNOBLOOD, B J Licensing Branch 1 80/07/09 5pp
- 8007230127 Forwards summary of 800602-06 human factors engineering control room review Certain deficiencies must be corrected Requests meeting w/utll to discuss matters before 800725 VOUNGBLOOD, B J licensing Branch | 80/07/10 19pp
- B007230198 Discusses augmented low power startup test program for near-term OL applicants Each applicant must perform tests similar to TVA proposed program for Sequoyah EISENHUT.D O Division of Licensing 80/07/10 3pp
- 8007210385 Forwards response to NRC 800625 request for addl info re secondary water chemistry monitoring program Info provides administrative control rept parameters PARKER.W D Duke Power Co B0/07/14 2pp
- 8007220535 Forwards revised draft environ protection plan (nonradiological) Also requests that NRC not incorporate document as part of QL for facility PARKER.W D Duke Power Co 80/07/17 Bpp
- 8007280166 Advises that NRC has completed review of info in 800616 ltr re reactor vessel noizles Reactor vessel fabricated using procedure for welding & pre & post-clad heat treatments that increase potential underclad cracking YQUNGBLOOD.B J Licensing Branch 1 80/07/17 3pp
- 8007220365 Forwards updated pages to util 800523 response to TMI concerns Matl addresses NUREO-0694 requirements Another revision scheduled for 800801 & fuel leading for mid-Bept 1980 PARKER. W D Duke Power Co 80/07/18 44pg
- 8007280011 Notification of 800730 meeting w/util in Bethesda,MD to discuss review of plant control room BIRKEL.R A Licensing Branch 1 80/07/18 4pp
- 8007300459 Forwards add1 info re justification for reducing steam generator low-low water level error allowance span, supplementing 791218 & 800507 ltrs Proprietary page withheld (ref 100FR2 790) Application for withhelding enc? PARKER.W O Duke Power Co 80/07/21 13pp

- BOO7230181 Discusses onsite emergency diesel generator reliability per NUREO/CR-0660 Reliability is sufficiently assured for operation through first refueling however, certain design & procedural modes are required YOUNGBLOOD, B J Licensing Branch 1 80/07/22 4pp
- 8007310338 Forwards request for addl info re RCS vents for review of OL application TEDESCO.R L Assistant Director for Licensing BD/07/23 Spp
- F. Security, medical, emergency & fire protection plans
- B007010309 Forwards security plan for on site storage & in transit requirements for SNN Plan withheld (ref 10CFR2 790) PARKER, W O Duke Power Co 80/06/24 1p
- BOD7240060 Reviews state & local emergency preparedness measures for facility Revisions per NUREO-0654/FEMA REP-1 95% complete & cumpliance w/NRC stds established prior to BO0101 Completion scheduled for Aug 1980

 MCCONNELL,J W Federal Emergency Management Agency 80/07/08 ip
- 8007300077 Forwards summary of recommendations from NRC review & 800617~18 meeting re facility emergency plan TEDESCO.R L. Assistant Director for Licensing 80/07/23 16pp

Adjudicatory correspondence

- 8007140461 Statement of Board of Commissioners' position in opposition to radwaste transportation through Gaston County, NC Urges transportation via Interstates 77 & 65 Encourages expending energy & money for recycling W/correspondence 9 Gaston County, NC 80/04/28 61pp
- ~~ 8007140473 Forwards add1 comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GASTON.H B Gaston County.NC 80/04/25 2pp
- --8007140488 Forwards position of Qaston County Board of Commissioners, NC, apposing spent nuclear fuel shipment through county & two proposed alternate routes W/o encl RHYNE.C A Gaston County.NC 80/04/15 ip
- BOO7030036 Response in opposition to applicant 800820 motion to tarminate stay of ABLB 790418 initial decision Suppl 3 to BER indicates that NRC review, re TMI-related requirements, is not complete Intervenor 800409 ltr to util encl RILEY, J L Carolina Environmental Study Group 80/06/09 App
- ~-B007030040 Motion to admit TMI-related new contentions & to reopen OL hearing Consequences of significant hydrogen rolease in Westinghouse containment, were not subj of adversary proceedings Contentions & Certificate of Svc encl RILEY, J L. Carolina Environmental Study Group 80/06/09 App
- 8007010282 Forwards BER, Suppl 3, per ASLB 790418 initial decision. LBP-79-13, which stayed issuance of rept W/o encl METCHEN.E O Hearing Branch 4 80/06/19 ip
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D O Division of Licensing 80/06/25 89pp
- BOO7020620 Order granting extension until BOO707 for applicant to respond to intervenor BO0609 motion re admission of new contentions & reopening of OL hearings record LAZO.R N Atomic Bafety and Licensing Board Panel 80/06/27 ip
- BOO7090320 Forwards, in response to BOO630 request in OL proceeding, NUREQ-0660, "NRC Action Plan Developed as Result of TMI-2 Accident," & BOO602 "Further Commission Guidance for Power Reactor OLs, Statement of Policy " W/o encls KETCHEN, E G Hearing Branch 4 BO/07/02 ip
- BOO7140004 Response in opposition to Carolina Environ Study Group motions to add new contentions & to reopen OL hearing Petitioner failed to comply when evidence criterion MCGARRY, J M Debevoise & Liberman, 80/07/09 13pp
- ---8007140007 Affidavit addressing issue of hydrogen generation & control following postulated TMI-type accident Action implemented effectively precludes excess hydrogen generation CAMADV, K 8 Consumers Power Co 79/07/09 5pp

- --8007140010 Affidavit attesting that EC(S meets acceptance criteria Mydrogen explosion will not present major damage to reactor vessel Charlotte Observer 791101 article & Certificate of Svc encl RASIN:W H Consumers Power Co PO/07/09 5pp
- 8007140019 Response in opposition to util 800530 motion seeking termination of stay of ASLB 790418 initial decision Opposes Carolina Environ Study Group 800609 motion to reopen record for addicantentions Certificate of Svc encl
 KEYCHEN.E G Hearing Branch 4 80/07/10 12pp
- B007160613 Forwards re-executed Certificate of Svc Correcting svc date to 800710 re NRC 800710 response to carolina Environ Study Group motion to recopen record & NRC 800710 response to util motion to terminate stay of initial decision DAVIS.L D Hearing Branch 4 80/07/15 2pp
- G Inspection reports, IE Bulletins & correspondence
- 8007240122 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2, Atlanta Office of the Director 80/05/08 2nn
- B007020204 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28 in
- B007210449 Forwards IE Circular B0-13, "Grid Strap Damage in Westinghouse Fuel Assemblies ' No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/05/28
- 8007010213 Forwards IE Info Nutice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/27 in
- 8007220048 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response lequired O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/10 200
- B007160235 Forwards IE Info Nutice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/1
- 8007250344 Forwards 1E Info Notice 80-2B, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required O'RESLLY, J P Region 2. Atlanta, Diffice of the Director 80/06/13 2nn
- B007020763 Forwards IE Bulletin 80~15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REJLLY, J.P. Region 2. Atlanta. Office of the Director 80/06/18 in
- B007100036 Responds to 1h Bulletin 79~16 re vital area access control Controls will be addressed in NNSS review of facility security plan, therefore specific response is unnecessary PARKER, W O Duke Power Co 80/06/18 ip
- 8007020459 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/20
- 8007090165 Forwards IE Insp Rept 30-369/R0 14 an 800602-04 No noncompliance noted KENNA/W B Region 2, Atlanta, Safeguards Branch 80/06/24 ip
- --m007090170 IE Insp Kept 50-,89780-14 on 800602-04 No noncompliance noted Major areas inspected prelicensing physical security survey.vital area protected area & physical barriers Details withheld (ref 10CFR2 790) GILLESPIE.F P , HDMELL J C Region 3. Chicago, Office of the Director 80/06/23 lp
- B007170104 Forwards IE Circulal Bu-14, 'Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel' No written response required D'REILLY, J P. Region 2, Atlanta, Office of the Director B0/06/24 to

- 8007230235 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosenount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/08/27
- 8007250598 Ack receipt of iE ln*p Repts 50~369/80-10 & 50-370/80-06 No proprietary info PARKER.W O Duke Power Co 80/06/30 ip
- --8007250603 Forwards (E Insp Repts 50-369/80-10 & 50-370/80-06 on 800514-16 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/10 3pp
- --8007250407 IE Insp Repts 50-369/80-10 & 50-370/80-06 on 800514-16 No nancompliance noted Major areas inspected unresolved items. IE bulietins & circulars & licensee identified items HUNT.M D Region 2. Atlanta. Office of the Director RAUSCH.J K Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/10 5pp
- B007240357 Ack receipt of IE lnsp Rept 50-369/80-09 on 800506-09 No proprietary info PARKER, W O Duke Power Co 80/07/03 ip
- --8007240368 Forwards IE Insp Rept %0-369/80-09 on 800506-09 No noncompliance noted LEHIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 80/06/13 App
- --BOO7240377 IE Insp Rept 50-369/80-09 on BOO506-09 No noncompliance noted Nagar areas inspected preoperational test program, procedure reviews & roviews of completed preoperational test packages

 DONAT.T J Region 2. Atlanta. Office of the Pirector GUICK, D Region 2. Atlanta. Reactor Operations Nuclear Support Branch 60/06/11 6pp
- 8007210114 Responds to IE Bulletin 80-08. "Framination of Containment Liner Penetration Welds " Welds in 22 penetrations repaired per nondestructive test performed during const Summary of types & sizes of penetrations encl PARKER.W O Duke Power Co 80/07/07 9pp
- 8007240469 Ack receipt of IE Insp Rept 50-369/80-09 No proprietary info PARKER, W D Duke Power Co 80/07/07 1p
- 8 Reportable occurrences. LERs & related correspondence
- 800&090319 Forwards Significant Deficiency Repts 369/80-06 & 370/80-05 re fire protection sys valve misapplication PARKER, # D Duke Power Co 80/05/16 ip
- BO07160366 Part 21 rept re Valcor Valvo Model V92600-594-1 not designed for continuous operation in energized mode Valves installed in diesel generator control air sys BDRGD.G J Valcor Engineering Corp 80/04/27 2pp
- BOO7160637 Forwards Significant Deficiency Repts 369/80-07 & 370/80-06 re centrifugal charging pump operation following secondary side high energy line rupture PARKER.W D Duke Power Co 80/07/07 tp
- --8007160663 Significant Deficiency Repts 369/80-07 & 370/80-06 recentrifugal charging pump operation following secondary side high energy line rupture Potential exists for inadequate min flow w/damage to pumps * Duke Power Co 80/07/07 ip
- 8007240333 Interim Part 21 rept to defective fTT actuators in dampers Customer notafication encl Jobs classified nonnuclear safety-related are not reportable Actuators supplied for other jobs are considered purchaser responsibility SLOAN.D, E American Warming & Ventilating. Inc. 80/07/08 50pp
- 8007300330 Significant Deficiency Repts 30-369/80-09 & 50-370/80-08 re solenoid valves On 800627, diesel generator instrument air pressure observed tower than normal Caused by leaking vent Valve stroke to be modified or coils replaced DONAT.T J Duke Pawer Co 80/07/25 2pp
- 8007300339 Deficiency rept re improper weld configuration on steam generator encl stiffener ring connections Cause not stated Melds have been modified to meet design drawings Fersonnel reinstructed to assure compliance widesign drawings PARKER.W O Duke Fower Co 80/07/25 2pp

- DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B007110519 Notification of B00514 meeting w/util in Bethesda. MD to discuss ptil design review of control room BIRMEL.R A Licensing Branch I 80/04/30 2pp
- 800701057; Advises that NRC 800409 request for independent plant-wide audit of installation of safety-related equipment & cables need not be fulfilled.based on additants provided in util 800605 ltr YOUN0816100b.8 J. Licensing Branch 1 80/06/20 3pp
- 8007090091 Notification of 800625-27 meeting w/util to discuss TMI-2 action plan items Agenda encl BIRKEL, RA Licensing Branch 1 80/06/20 Spp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D G Division of Licensing 80/06/26 2pp
- 8007110983 forwards request for add1 info re reactor sys as result of review of application for OLs'
 YOUNGBLOOD, B. J. Licensing Branch 1 80/06/30 5pp
- 8007160486 Forwards TMI review item schedule, designating principal branch review responsibilities
 BIRKEL.R A Licensing Branch 1 80/06/03 4pp
- B007170694 Forwards schedule for review of TMI-2 task force items including designated principle branch review responsibilities BIRKEL-R A Licensing Branch 1 80/06/30 4pp
- B007080345 Forwards info & drawings re use of Category I masonry walls for supporting piping & components in response to MRC B00421 ltr Drawings available in Central Files only Fourteen illegible drawings encl PARKER.W C Duke Power Co B0/07/02 27pp
- 8007170688 Requests addl info re reactor sys YOUNGBLOOD: B J Licensing Branch 1 80/07/02 5pp
- 8007110309 Forwards Chem-Nuclear "Process Control Program for CNSI Mobile Solidification Units Using Dow Process " Affidavit for withholding encl Program withhold (ref 10CFR2 790) PARKER.W O Duke Power Co 80/07/08 ip
- 8007180069 Requests that protection sys design be reviewed to determine degree of conformance to listed criteria Review results should be submitted by 800804
 YOUNOBLOOD, B J Licensing Branch 1 80/07/09 5pp
- 8007230127 Forwards summary of 800602-06 human factors engineering control room review Certain deficiencies must be corrected Requests meeting w/util to discuss matters before 800725 YOUNOBLOOD, B J Licensing Branch 1 80/07/10 19pp
- B00723019B Discusses augmented low power startup test program for nearterm OL applicants Each applicant must perform tests similar to TVA proposed program for Sequoyah EISENHUT.D G. Division of Licensing 80/07/10 3pp
- 8007210385 Forwards response to NRC 800625 request for add1 info re secondary water chamistry monitoring program Info provides administrative control rept parameters PARKER.W O Duke Power Co 80/07/14 2pp
- 8007220534 Forwards revised draft environ protection plan (nonradiological) Also requests that NRC not incorporate document as part of OL for facility PARKER, W O Duke Power Co BO/07/17 Spp
- 8007280166 Advises that NRC has completed review of info in 800616 ltr re reactor vessel noisles Reactor vessel fabricated using procedure for weiding & pre & post-clad heat treatments that increase potential underclad cracking YOUNGBLOOD, B J Licensing Branch i 80/07/17 Spp
- B007220365 Forwards updated pages to util B00523 response to TMI concerns Matl addresses NUREG-0674 requirements Another revision scheduled for 800801 & fuel loading for mid-Sept 1980 PARKER, H O Duke Fower Co 80/07/18 44pp

- B007280011 Notification of B007JO meeting w/util in Bethesda,MD to discuss review of plant control room BIRKEL,R A Licensing Branch 1 B0/07/18 4pp
- B007300459 Forwards add1 info to justification for reducing steam generator low-low water level error allowance span.
 sypplementing 791218 & 800507 Itrs Proprietary page withheld (ref 10CFR2 790) Application for withhelding encl
 PARKER, N O Duke Power Co 80/07/21 13pp
- 8007250181 Discusses onsite emergency diesel generator reliability per NUREG/CR-0660 Reliability is sufficiently assured for operation through first refueling, however, certain design 5 procedural mode are required YOUNGBLOOD, B J Licensing Branch 1 80/07/22 4pp
- 8007310338 Forwards request for addl info re RCS vents for review of OL application
 TEDESCO.R L Assistant Director for Licensing 80/07/23 5pp
- F Security, medical, emergency & fire protection plans
- 8007010307 Forwards security plan for on site storage % in transit requirements for SNM Plan withheld (ref 10CFR2 790) PARKER, W D Duke Power Co 80/06/24 ip
- 8007240040 Reviews state & local emergency preparedness measures for facility Revisions per NUREG-0454/FEMA REP-1 957 complete & compliance w/NRC stds established prior to 800101 Completion scheduled for Aug 1980 MCCONNELL, J W Federal Emergency Management Agency 80/07/08 ip
- B007300077 Forwards summary of recommendations from NRC review & B00617-18 meeting re facility emergency plan TEDESCO.R L Assistant Director for Licensing 80/07/23 16pp
- G Adjudicatory correspondence
- 8007140461 Statement of Agard of Commissioners' position in apposition to radwasto transportation through Gaston County, NC Urges transportation via Interstates 77 & 6° Encourages expending energy & money for recycling Wiccorrespondence # Gaston County, NC 80/04/28 61pp
- ---B007140473 Forwards addl comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GASTON.H B Gaston County,NC B0/04/25 2pp
- ~-8007140488 Forwards position of Gaston County Board of Commissioners, NC opposing spent nuclear fuel shipment through county & two proposed alternate routes W/o enci RHYNC C A Gaston County.NC 80/04/15 ip
- B007030036 Response in opposition to applicant 800520 motion to terminate stay of ASLB 770418 initial decision Suppl 3 to SER indicates that NRC review.re TMI-related requiryments is not complete Intervenor 800609 ltr to util encl RILEY.JL Carolina Environmental Study Group 80/06/09 6 B0/06/09 4pp
- ~-B007030040 Motion to admit (MI-related new contentions & to reopen CL hearing Consequences of significant hydrogen release in Hestinghouse containment were not Yubj of adversary proceedings Contentions & Certificate of Svc enc) RILEY.J L Carolina Environmental Study Group 80/04/09 App
- 8007010282 Forwards SER, Suppl 3, per ASLB 790418 initial decision. LBP-79-13, which stayed issuance of rept W/o encl KETCHEN,E 9 Heating Branch 4 80/04/19 ip
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition snught action re fire protection for electrical cables EISENHUI, D C Division of Licensing 80/06/25 87pp
- \$007020620 Order granting extension until 800707 for applicant to respond to intervenor 800609 motion re admission of new contentions & reopening of OL hearings record LAZO.R M Atomic Safety and Licensing Board Panel 80/06/27
- 8007090320 Forwards in response to 800630 request in OL proceeding, NUREO-0460, "NRC Action Plan Developed as Result of THI-2 Accident," & 800602 "Further Commission Guidance for Power Reactor OLs, Statement of Policy " W/o encls KETCHEN, E. G. Hearing Branch 4 80/07/02 1p

- --B00714000/ Affidavit addressing issue of hydrogen generation & control following postulated TMI-type accident Action implemented effectively precludes excess hydrogen generation CANADY.K S Consumers Power Co. 79(1)7709 Spp.
- --8007140010 Affidavit attesting that L/49 meets acceptance criteria Hydrogen explosion will not present major damage to reactor vessel Charlotte (Abserve) 791101 article & Centificate of Svc encl RASIN.W H Consumers Power Co 30/07/09 5pp
- E007140019 Response in apposition to util 800030 motion seeking termination of stay of ASIN 790418 initial decision Opposes Carolina Environ Study Group 800607 motion to reopen record for addl contentions Certific to 6 5% c. Encl. KETCHEN.E.G. Hearing Branch 1 80/07/10 12pp
- 8007160613 Forwards re-executed Certificate of Syc correcting svc date 30/140613 Forwards re-executed Certificate of SAC correcting to B00710 re NRC P00710 response to Carolina Envison Study Group motion to reopen record % NRC R00710 response to util motion to terminate stay of Justial decision DAVIS.L D Hearing Branch 4 80/07/15 2pp
- Q Inspection reports. IE Bulletins % correspondence
- 8007240122 Forwards IE info Notice 80-20. Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'RETILY: J.P. Region 2. Atlanta, Office of the Director 80/05/08
- 8007210449 Forwards IE Circular 80-13, 'Grid Strap Damage in Westinghouse Forl Assemblies 'No written response required Q'REILLY, J P Region 2, Atlanta, Office of the Director 'A
- 8007010213 Forwards IE Info Notice 80-23; "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2 Atlanta Office of the Birector 80/05/29
- 8007220048 Forwards IE Info Notice 80-26 "Evaluation of Contractor QA Programs 'No written response required
 O'REILLY.J P Region 2, Atlanta Office of the Director 80/06/10
- 8007160255 Forwards IE Info Notice 80-2" "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY J.P. Region 2. Atlanta Office of the Director BO/06/11 1 n
- 8007250344 Forwards It Info Notice 80-20. "Prompt Reporting of Info in Accordance W/100F880 55(e) " No written response required O'REILLY J.P. Region 2 Atlanta Office of the Director 80/06/13
- 8007020459 Forwards IE Circula: 80-15. Tost of Peactor Coolant Pump Cooling & Natural Circulation Couldows " He written response required O'REILL' J P Region P. Atlanta, Office of the Director 80/05/20
- B007170104 Forwards IC Circular 40-14 "Radioartive Contamination of Plant Demineralized Water bys & Posuitant Internal Contamination of Personnel "Ne unities response required O'REINLY, J.P. Argion Z. Atlanta, Office of the Director 80/06/24
- B007230235 Forwards IE Bolletin 80-16 (Pritential Misapplication of Rosemount Int Models 1191 & 1152 Printer bransmitters W/Either A or D Cutput Code (Written response required IE Circular 80-16 also and to writen response required O'REILLY, J.P. Region 2, Atlantia Orfice at the Director BO/06/ 80/05/27
- | BOD7250598 Ack receipt of tE imp Rept | 50-469 80 10 & 50-370/80-06 | No proprietary tofo | PARKER, V D | Duke Power Co | Research 0 | 1p |
- +8007250603 Forwards If Into Repts 10-369 (a.18) % 50-370/80-06 on 800514-16 No noncomplisher noted MRPHY.C E. Reptor E. Alloute, Reactor construction & Engineering Support Branch 80706/1). 2pp

- --8007250607 IF Insp Repts 50 359780-10 v 50-370780-06 on 800514-16 No uoverous IF Insp Repts 40 349/80-10 t 50-370/80-06 on 800514-16 No noncompliance noted Major areas inspected unresolved items. If buildishes to includer t licensie identified items. HUNT, M D Region 2 Atlants, Office of the Director RAUSCH, J K Region 2, Atlants Reactor Construction t Engineering Support Branch 80/06/10 Spp
- 8007210114 Responds to IE Bulletin 80-08. 'Examination of Containment Liner Penetration Welds' Wild; in 72 penetrations repaired per nondestruct; e test performed during const Gummary of types 8 sizes of pinetrations end. PARKER, W.O. Doke Power Co. 80'0'/0" 9pp
- S Reportable occurrences, LFRs o related correspondence
- BOOA090319 Forwards Significant Deficiency Repts 369/80-06 to 370/80-05 refire protection systalize mirapplication PARKERLH D. Duke Hower Co. 80/05/15 1f
- 8007160366 Part Pl tept re Valcor Valve Hadel V52600-554-1 not designed Transport of the control of the cont
- 8007160657 Forwards Significant Deficiency Repts 369/80-07 & 370/80-06 re-centrifugal charging pump operation following secondary side high energy line rupture PARKER, N.O. Duke Power Co. 90/07/07 ip
- --R007160663 Significant Deficiency Repts 359/80-07 & 370/80-06 re centrifugal charding pump operation following secondary side high energy line repture Potential exists for inadequate min flow w/damage to pumps * Duke Power Co 80/07/07 lp
- BOO7240353 Interim Part 21 rept re detective ITT actuators in dampers Customer notification encl Jobs (lassified nonnuclear safety-related are not reportable Actuators supplied for other jobs are considered purchaser responsibility SLOAN.D & American Warming & Vent)lating. Inc. 80/07/08 50pp
- 8007300330 Significant Deficiency Repts 50-349/80-07 & 50-370/80-08 re salenaid valves On 800627, dierol generator instrument air pressure observed Jower than normal (aused by Icabing vent Valve stroke to be modified or coll replaced BONAT.T J. Duke Power Co. 80/07/25 2pp
- DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1
- A Application/construction stage decuments & correspondence
- 8007030239 Notification of BOO/OC meeting w/BWR licensing review group in Bethesda.MD to dircuss consensus position on leactor SVE bldg open issue WILSON, J.N. Licensing Branch 1 80/06/18 9pp
- 8007010297 Surmary of B00613 meeting w/utils.KMC.inc.GE.Bechtel.StW & Sangent 't Lundy in Bethesda.MD re consensus positions on reactor svc bidg A isolation cooling sys bidg open issues from La Salle ducket Statu- repts enci Assistant Director for Licensing 80/06/19 46pp MITT BONG I M
- BO07210176 Forwards NRC evaluation of GE rept, NEDE-24010-P % Supple 1-3. "Technical Basis for Use of Square-Root-of-Gum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj to certain constraints MATISON.R J. Division of Safety Technology B0/06/25 3pp
- BOO723000: Forwards statement of policy or requirements to be met for current OL applications as derived from NUREG-0660 % found in NUREG-0660. EISEMUT.DG Division of Licensing 80/06/26 2pp
- \$0007170475 Summary of POO614 meeting w/Mark II lead plant applicants re definition of F-quencher load spec following safety/relief vol e arthustion Vicuyraphs enci | 1 Containment Systems Branch | 80/06/27 | 4pp

ceting w/Mark II lead plant applicants re irants to define T-quencher load value octuation New methodology rk II lead plants

hadding of 800702 meeting w/BMR thesda AD to discuss consensus ith open issure Meeting

03 for Licensing 80/07/03 in

- --8007170347 Not)+1cation of 800722 meeting w/BNR licensing review group in Bethesdo.HD to discuss THI issues required for OL ssuance
 - WILSON, J N Assistant Director for Licensing 80/07/03
- --8007/70351 Notification of 800724 meeting w/BWR licensing review group in Bethesda, MD to introduce BWR licensing review group & present consensus positions for Power Sys Branch, Containment Sys Branch & Equipment Qualification Branch MILEON, J N Assistant Director For Licensing 80/07/03 9pp
- 8007230621 Summary of 800612 meeting w/Mark II owners group in Bethesda: MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON: C.J. Generic Issues Branch 80/07/03 57pp
- 8007150529 Forwards response to NRC 800421 request for info re masonry wall design further review of masonry wall design is being conducted at LaSaile to complete response to LE Bulletin 80-11 Package of 231 oversize drawings not PEOPLES,D L. Commonwealth Edison Co. 80/07/08 23pp
- --8007150537 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming
 * Sargent & Lundy. Inc 80/07/08 231pp
- 8007160606 Forwards "Condensation Oscillation (CO) Load Data for Lacalle" & "Chugging Loads for Assessment of 4T CO Data " Repts withheld (ref IOCFR2 790) & available in Central Files DELGEORGE, L. O Commonwealth Edison Co BO/07/11 2pp
- 8007230133 Notification of 800725 meeting w/BWR Licensing Review Group in Bethesda-ND to discuss concensus positions of DWR Licensing Review Group on ICSB open issues WILSON, J N Licensing Branch 1 80/07/16 10pp
- B007220518 Responds to 800922 & 0604 info requests. Info re BHR jet pump holddown beam cracking will be submitted by 800915 & reactor vossel underclad crucking info by 800901 PEOPLES D. Commonwealth Edison Co. 80/07/17 ip
- 8007250448 Forwards facility emergency procedures Table of contents HOLYOAKAR H Commenwealth Edison Co 80/07/18 Ip
- --B007290455 Emergency procedures for Facility,including general abnormal procedures,general abnormal index & operating abnormal index # Commonwealth Edison Co 79/05/22 82pp
- 8007250175 Notification of 800805 meeting w/reprosentatives from Mark II owners group in Chicago, IL to discuss lead Mark II plants chugging % C/O load specs ANDERSON: C Generic Issues Branch 80/07/23 2pp
- B00729069B Forwards index for facility general procedures Index will suppl general abnormal procedures & operating abnormal procedure index already forwarded H/o encl HOLYOAK, R H Commonwealth Edinon Co B0/07/23 ip
- 8007300D33 Forwards request for add1 info to complete review of FBAR TEDESCO.R L Assistant Director for Licensing 80/07/23 3pp
- F Security, medical, emergency & fire protection plans
- BOO7010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES, D.L. Commonwealth Edison Co. BO/O6/27 1p
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D Q Division of Licensing 80/06/25 87pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007070767 Forwards 800630 affidavit re 800613 distribution of Amend 49 DFLGEORGF.L D Commonwealth Edison Co BO/06/27 2pp

- Q Inspection reports, IE Bulletins & correspondence
- 8007140537 Forwards IE Bulletin 80-13. "Cracking in Core Spray Bpargers" No written response required KEPPLER, J & Region 3. Chicago, Office of the Director 80/05/12 le
- 9007020045 Forwards IE Info Nutice 80-22. "Breakdowns In Contamination Control Programs " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/28
- 8007010086 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Faddator Pumps" No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/05/29 lp.
- B007170094 Forwards IE Insp Rept 50-373/80-24 on 800401-0509 & notice of violation
 KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/05/29
- --8007170103 IE Insp Rept 50-373/80-24 on 800401-0509 Nontompliance nuted no procedure provided for removing control rods from reactor vessel on 800412 resulting in potential damage to two control rods & drive mechanisms
 MALKER, D , EMEPLEY, S E , SPESSAD, R L Region 3, Chicago, Office of the Director 80/05/28 Bpp
- 9007220156 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required MEPPLER, J. 9 Region 3, Chicago, Office of the Director BO/06/10 to
- 8007140314 Forwards IE Bulletin 80-14, "Degradation of SWR Scram Discharge Vol Capability " No written response required KEPPLER: J © Region 3, Chicago, Office of the Director 80/06/12 in
- B007280709 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/13 to
- 6007100004 Forwards response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies," No safety-related sys or component at Drawden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators PEOPLES D L. Commonwealth Edison Co 80/06/16 3pp
- 8007230693 Forwards IE Insp Repts 50-373/80-24 & 50-374/80-16 on 800528-29 No noncompliance noted FICRELLI.6. Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --B007230700 IE Insp Repts 50-373/80-26 & 50-374/80-16 on 800528-29 No noncompliance noted Major areas inspected mod in Unit 1 suppression pool.welding on dc power panels & calibr of 4160-volt & 480-volt switch gears
 MEIBLER.J H. WILLIAMS,C C Region 3, Chicago, Office of the Director 80/06/18 4pp
- B007020589 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required KEPPLER.J 9 Region 3, Chicago. Office of the Director B0/06/20 tp.
- BO07230266 Forwards IE Insp Repts 50-373/80-28 & 50-374/80-17 on BO0610-11 No noncompliance noted FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Buggort Branch BO/06/23 2pp
- --BOO7230273 IE Insp Repts 50-379/80-28 & 50-374/80-17 on 800410-11 No moncompliance noted Major areas inspected preservice insp procedures, work activities & nondestructive examination test

 DANIELEGN. D. H., WARD, K. D. Region 3, Chicago, Office of the Director 80/06/20 Spp
- 8007170430 Forwards IE Circular BO~14, "Redicactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required MEPPLER.J G Region 3, Chicago, Office of the Director BO/06/24

- 8007230289 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Prossure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also enci No unitten response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/27
- B007230275 Ack receipt of 800806 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-373/80-15
 MEISHMANR F Region 3. Chicago, Reactor Operations Nuclear Support Branch B0/07/03 1p
- ~-8007290281 Responds to NRC 800509 ltr re violations noted in IE Insp Ropt 50-373/80-15 Corrective actions battery chargers have been cleaned Units 1 & 2 steam dryers require extensive mod PEOPLES.D L. Commonwealth Edison Co. 80/06/06. App
- 8007250638 Forwards response to IE Bulletin 80-08. "Examination of Containment Linor Penetration Welds " Dresden Unit i designs will be reviewed & feasibility of performing radiographic examinations unlibe assessed before unit returned to svc PEOPLES.D L Commonwealth Edison Co 80/07/09 7pp
- 8007210283 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/80-20 & 50-374/80-13 FIGRELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/14 ip
- --8007210292 Responds to NRC 800426 ltr re violations noted in IE Insp. Repts 50-373/80-20 & 50-374/80-13 Corrective actions design control program deficiencies are subj of request for ASME use Urges reconsideration of Item 3 infraction PEOPLES,D L. Commanuealth Edison Co. 80/06/06 App
- 8007250467 Submits supplemental response to IE Bulletin 80-09, "Mydramotor Actuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800829 PEOPLES.D L Commonwealth Edison Co 80/07/15 ip
- 8007280681 Ack receipt of 800625 ltr informing NRC of steps taken to correct violations noted in If Imap Rept 50-373/80-24
 KEPPLER, J G Region 3. Chicago, Office of the Director B0/07/17
- --8007880688 Responds to NRC 800529 ltm re violations moted in 1E Insp Rept 50-373/80-24 Corrective actions wrote formal equipment removal procedure PEOPLES,D L. Commonwealth Edison Co. 80/06/25 4pp
- B007310530 Ack receipt of B00A0A & 0707 ltrs informing NRC of steps taken to correct violations noted in IF lnsp Rept 50-373/20-15 HEISHMAN.R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 80/07/22 2pp
- --8007310933 Forwards supplemental response to NRC 800509 ltr reviolations noted in IE Insp Rept 50-373/80-15 Corrective actions util will perform visual insp of both dryer & separator prior to final installation in reactor tessel PEOPLES.D L Commonwealth Edison Co. 80/07/07 5pp
- S Reportable occurrences, LFRs & related correspondence
- 8007170214 Part 21 report re installed Tech-Sil, Inc matls containing 5% Gel which cannot be traced in original formulation Cause not stated Unused matl has been returned to vendor Noncompliance Rept 9 encl
 ACERRAL S TECH-SIL, Inc 80/06/20 App
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

 A Application/construction stage documents & regrespondence
- 8007210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls 1-3. "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SRS3) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj. to certain constraints MATTSON.R J Division of Safety Technology 80/04/25 3pp
- 8007230001 Corwards statement of policy re requirements to be mat for current OL applications as derived from NUREG-0560 & found in NUREG-0569 EIGENBUT, D G Division of Licensing 60/05/25 2pp

7170479 Summary of 800613 meeting w/Mark II lead glant applicants & dofinition of T-quencher lead spec following safety/elief valve actuation Viewgraphs encl
U.J M Containment Systems Branch 80/06/27 4pp

ì

7230252 Summary of 800613 meeting w/Mark II lead plant applicants re ethodology proposed by applicants to define T-quencher load per following safety relief valve actuation New methodology iII be applicable to all Mark II lead plants J.T.M. Generic Issues Branch 80/06/27 Jpp

7230621 Summary of 800612 meeting w/Mark II comers group in ethesda, ND re lead plant closure & long-term program Mods could be made to generic lead plant condensation scillation & chugging pool boundary loads Viewgraphs encl NDERSON, C J Generic Issues Branch 80/07/03 57pp

'150527 Forwards response to NRC 800421 request for info re masonry ill design Further review of masonry wall design is being unducted at LaBalle to complete response to IE Bulletin 3-11 Package of 231 oversize drawings end IEBULES.D.C. Commonwealth Edison Co. 80/07/08 23pp

107:505:37 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming
* Sargent & Lundy, Inc. 80/07/08 23ipp

'140605 Forwards "Condensation Oscillation (CO) Load Data for Isable" & "Chugging Loads for Assessment of 4T CO Data "
Ints withheld (rof 10CFR2 790) & available in Central Files LGEORGE.L O Commonwealth Edison Co 80/07/11 2pp

'220518 Rosponds to 800522 & 0604 info requests Info re BHR jet mp holddown beam cracking will be submitted by 800815 & actor vessel underclad cracking info by 8008901 OPLES.D.L. Commonwealth Edison Co. 80/07/17 1p

25044B Forwards facility emergency procedures Table of contents

LYDAK,R H Commonwealth Edison Co 80/07/18 ip

07250499 Emergency procedures for facility,including general abnormal procedures, general abnormal index & operating abnormal index = Commonwealth Edison Co 79/05/22 82pp

270.698 Forwards index for facility general procedures Index will pel general abnormal procedures & operating abnormal occidure index already forwarded W/o encl .YOAK, R H Commonwealth Edison Co 80/07/23 ip

300033 Forwards request for addl info to complete review of FSAR MESCO.R L. Assistant Director for Licensing 80/07/23 3pp

scurity, medical, emergency & fire protection plans

)10347 Forwards safequards contingency plan amend Plan withheld 10CPR2 7901

PLES. D L Commonwealth Edison Co 80/05/27 1p

ljudicatory correspondence

HO243 Forwards Commission 800527 momorandum & order containing isions on UCS 780502 petition for reconsideration of 413 memorandum & order UCS 771104 petition sought action fire protection for electrical cables
ENHUT, D C Division of Licensing 80/06/25 89pp

ility Final Safety Analysis Report (FSAR) & amends

170267 Forwards 800630 affidavit re 800613 distribution of Amend 49

ith Edison Co 80/06/27 2pp

rrespondence

king in Core Spray f the Director 60/05/12

> In Contamination tor 80/05/28

B0070100B6 Forwards IE Info Notice 80-23. "Loss of Suction to Easignate Feedwater Pumps" No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 'B0/UJ/A'

8007220156 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required KEPPLER.J 0 Region 3. Chicago. Office of the Director 90/06/10

8007140314 Forwards IE Bulletin 80-14, "Degradation of BHR Stram Distharge Vol Capability " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/12

8007280709 Forwards IE Info Notice 80-29, "Prompt Reporting of Info in Accordance W/100FR50 55(e)" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/13

8007100004 Forwards response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies." No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor PEOPLES, D. L. Commonwealth Edison Co. 80/06/16 3pp

8007230693 Forwards IE Insp Repts 50-373/80-26 & 50-374/80-16 on 800528-29 No moncompliance noted FIORELLI, 6 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/19 2pp

--8007230703 IE Insp Repts 50-373/80-26 & 50-374/80-16 on 800528-29 Renoncompliance noted Major areas inspected mod in Unit 1 suppression pool, welding on do power panels & calibr of 4160-volt & 480-volt switch goars
NETSLER, J H , WILLIAMS, C C Region 3, Chicago, Orfice of the Director 80/06/18 4pp

B007020989 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Godling & Natural Circulation Cooldown " No written response required required MEPPLER, J.G. Region 3, Chicago, Office of the Director 80/06/20

8007230266 Forwards IE Imsp Repts 50-373/80-28 & 50-374/80-17 on 800610-11 No noncompliance noted FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Bupport Branch 80/06/23 2pp

--8007230373 IE Insp Repts 50-373/80-28 & 50-374/80-17 on 800610-11 No noncompliance moted Major areas inspected preservice insp procedures, work activities & nondestructive examination test DANIELSON,D H , WARD,K D Region 3, Chicago, Office of the Director 80/06/20 Spp

8007170430 Forwards IE Circular 80-14, "Radinartive Contamination of Plant Demineralized Water 89s & Resultant Internal Contamination of Personnel "No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/24

8007230289 Forwards IE Bulletin 80-14, "Potential Misapplication of Rosemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-14 also encl No written response required MCPPLER.J 0 Region 3. Chicago, Office of the Director 80/06/2 80/06/27

8007230638 Forwards response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Helds" Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEDPLES.D L. Commonwealth Edison Co. 80/07/09 7pg

8007210283 Ack recoipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/80-20 & 80-374/80-13
FIGNELLI,O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/14 ip

--8007210292 Responds to NRC 800426 ltr re violations noted in IE Insp Repts 50-373/80-20 & 90-374/80-13 Corrective actions design control program deficiencies are subj of request for ASME use Unges reconsideration of Item 3 infraction PEOPLES.D.L. Communicalth Edison Co. 80/06/06 App

8007250467 Submits supplemental response to LE Bulletin 80-09. "Hydramotor Artuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800829 PEDPLES, D. Commonwealth Edinan Co. 80/07/15 19

DOCKET 50-379 NUCLEAR EXAMINATION REACTOR

- @ Inspection reports. It Bullotins & unriespondence
- 80071802B1 Forwards IC Circular DO-14. "Radioactive Contamination of Plant Demineralized Water 9ys & Resultant Internal Contamination of Personnel" No written response required ENSELMEN.R H Region 9. San Francisco. Office of the Director 80/06/24 1p

DOCKET 50-376 NORTH COAST NUC PLANT

- O Adjudicatory correspondence
- B007010143 Homorandum in response to ABLAN B00604 order re absence of authority to involuntarily dismiss CP application due to abandonment of const Issue must be remanded to ABLN to inquire into facts W/appearance notice & Certificate of Svc REISL J Healing Branch 3 LCSGY, R P Antitrust Division 80/06/27 19pp
- B007020604 Memorandum in response to ASLAB 800604 order Interlocutory reviaw of ASLAB ander denying 6 Fornos potition to dismiss application not warrented unless legal boundaries are not splored M/Gertificate of Svc AXELRAD.M Paerto Rico Electric Power Authority AXELRAD.M Lowenskein, Newanskein, Svk. Axelrad & Toll 80/06/27 21pp
- 8007090224 Order granting option for applicant to respond to NRC 800627 memorandum in CP proceeding, by 800718 BOOTER THEORY Atomic Safety and Licensing Appeal Panel 80/06/30 to
- B007160981 Motion socking aption to respond to applicant by 800808.if applicant responds to NRC 800627 memorandum by 800718.re
 ASLAD 800670 order Certificate of Svc enc)
 FERNOS C Citizens for the Conservation of Natural Resources, Inc
 80/07/09 1p
- 8007230535 Response to NRC RODGE7 memorandum, in reply to ASLAB 800630 order Interluciting review of ASLA arder re dismissal of CP application w/o hearing on health; safety & environ is not warranted Certificate of Svc and
- 8007230771 Memorandum in response to ASLAB B00604 order re validity of ASLAB B00029 order denying petition to intervene Urges reversol of ASLB urder & institution of hearings Certificate of Evc encl FERNOB, 6 Citizens for the Conservation of Natural Resources, Inc 80707710 11pp

DOCKET 50-378 CAURSD NUCLEAR STATION

- A Application/construction stage documents & correspondence
- B007/350175 Notification of B00800 meeting w/representatives from Mark II owners group in Chicago IL to discuss load Mark II plants chugging & C/O load specs ANDERSON, C Omneric Issues Branch B0/0//23 2pp

DOCKET 50 302 WATER-ORD GENERATING STATION, UNIT 3

- A Application/construction stage documents & correspondence
- 80070R031B Confirms discussions w/NRC re resumption of work by subcontractor.NICCB Work may resume in stop work area of A & B stops (pipe instrains) installation, pending completion of remaining NRC 800°09 prerequisites

 8EYFRIT.K V Region 4. Dellas, Office of the Director 80/06/11
- 8007230001 Forwards statement of policy re requirements to be met for current CL applications as derived from NUREG-0640 & found in NUREG-06494 EISENHUT, D G Division of Licensing 80/06/26 2pp
- 8007080179 Responds to NRC requests for addl info Licenses will provide amond to FSAR on 800731
 ASWELL,D L. Louisians Power & Light Co. 80/07/03 lp

- F Security, medical, emergency & fire protection plans
- 8007010341 Forwards evacuation time estimate to state & local officials involved in emergency planning for area around facility per NRC 791226 request "Evacuation Time Estimate" encl ASHELL.D L Louisiana Power & Light Co 80/06/25 10pp
- ---8007010343 "Evacuation Time Estimate"

 * Louisiana Power & Light Co 80/03/31 46pp
- 8007100163 Forwards Amend 10 to FSAR Radiological response plan has been revised & will be forwarded upon final approval ASWELL.D L. Louissana Power & Light Co. 80/08/27 1p
- --8007100166 Amend 10 to application for OL re upgraded emergency plans.
 ASMELL D L Louisiana Power & Light Co 80/06/27 2ap.
- --8007100168 Amend 10 to FSAR re upgraded emergency plans
 # Louisiana Power & Light Co 80/06/30 177pp
- 8007220373 Forwards response to NRC 800609 comments & revised pages to safeguards contingency plan Response & revised pages withhold (ref 100FR2 790)
 ASWELL-D L Louisiana Power & Light Co 80/07/15 ip
- B007250399 Forwards Aswell to Grimes B00625 ltr ASWELL,D L Louisiana Power & Light Co B0/07/21 lp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800327 memorandum & order centaining decisions on UCS 780302 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables.
 EISENHUT, D 0 Division of Licensing 80/06/25 89pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B007100163 Forwards Amend 10 to FBAR Radiological response plan has been revised & will be forwarded upon final approval. ASWELL.D L Louisiana Power & Light Co 80/06/27 1p
- --8007100166 Amend 10 to application for DL re upgraded emergency plans.
 ASMELL, D L. Louisiana Power & Light Co. 80/06/27 2pp.
- --8007100168 Amend 10 to FBAR re upgraded emergency plans * Louisiana Power & Light Co 80/06/30 177pp
- 8007160586 Certifies svc of Amend 10 to FSAR on 800710.upon parties in proceeding Related correspondence

 * Louisiana Power & Light Co 80/07/10 ip
- 8007160616 Certifies svc of Amend 10 to FSAR on 800710 . KAVANAUGH, F M Louisiana Power & Light Co 80/07/10 1p
- G Inspection reports, IE Bulletins & correspondence
- 8007280323 Forwards IE Info Notice 80-i2, "Instrument Failure Causes Opening of PDRV & Block Valve " No specific action or response necessary BEYFRIT,K V Region 4, Dallas, Office of the Director 80/03/3i.
- 8007240910 Forwards IE Info Notice 80-21, "Anchorage & Support of Safoty-Related Electrical Equipment " No written response required SEYFRIT, N V Region 4, Dalles, Office of the Director 80/05/16, in
- 8007110061 Forwards IE Insp Rept 50-382/80-09 on 800421-25 & notices of violation & deviation SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --B007110065 Notice of violation from insp on B00421-25
 * Region 4, Dallas, Office of the Director 80/05/20 3pp
- --B007110070 Notice of deviation from insp on B00421-25
 # Region 4, Dallas, Office of the Director. B0/05/20 ip

- --8007110076 IE Insp Rept 50-382/80-09 on 800421-25 Noncompliance noted failure to follow procedures for documentation of GA program. Paragraph 3 2 1 BEACH. A B., HALL, R E., CROSSMAN, W. A. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/05/20 Spp
- 8007020261 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs " No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- B007140436 Forwards IR Insp Rept 50-382/80-07 on 800402-04,09-11 & 0502 & notice of violation SEIDLE.W.C Region 4. Ballas, Reactor Construction & Engineering Support Branch. B0/05/28 2pp
- ---8007140441 Notice of violation from insp on 800402-04.09-11 & 0502 * Region 4. Dallas. Office of the Director 80/05/28 1p
- 8007210346 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director' 80. 80/05/28
- 8007010020 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Facebater Pumps." No written response required 98YFRIT.K.V Region 4. Dallas. Office of the Director 80/05/29
- B007100429 Responds to IE Bulletin 80-05 as applicable to tanks that hold radidactive liquid or gases All low pressure tanks containing radioactive liquids or gases either designed for full vacuum or to prevent vacuum in tanks
 ASMELL.D L Louisiana Power & Light Co 80/06/09 3pp
- 8007220113 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs" No written response required SEYFRIT.K.V Region 4, Dailas, Office of the Director 80/06/10
- 3007160327 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required SEYFRIT.K V Region 4. Dallas, Office of the Director B0/06/11
- OO729006B Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)," No written response reguired BEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/13
- OC7150417 Submits interim reply to IK Bulletin 80-09 re hydramotor actuator deficiencies ITT General Controls AH-90 & NH-90 werles hydramotor actuators will be used in safety-related says Test rept to be completed during who of 800627 ASHELL, D. L. Louisiana Power & Light Co. 80/06/17 p
- DO7240045 Forwards IE Circular 80~15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/06/20
- 107280144 Forwards 1E Inop Rept 50-382/80-10 on 800602-05 & notice of Violation

 BEIDLE: # C Region 4, Dallas, Reactor Construction & Engineering

 Support Branch 80/06/20 Rpp
- BOO7280148 Notice of violation from insp on 900602-09 # Region 4. Dallas. Office of the Director 80/06/18 2pp
- 8007280153 IE Insp Rept 50-382/80-10 on 800602-05 Noncompliance noted failure to follow procedures for control of design mods & failure to control use of calibr tool within necessary CROSHAN, W. A. Region 4, Dallas, Office of the Director TAPJA, J. I. TOMLINSON, D. P. Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/18 Spp

- 8007170680 Forwards IE Circulat 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No witten response required SEYFRIT, K V Region 4, Dallas. Office of the Dijector 80/06/24
- BOO7230369 Forwards IE Bulletin 80-16. "Potential Hisapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular BO-16 also encl No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/27
- 8007290433 Ack receipt of 800620 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 50-382/80-09 SEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/08 jp Support Branch
- ---B007270439 Responds to NRC 800521 ltr re violations noted in IE Insp Rept 50-382/80-09 Corrective actions NISCO housekeeping & insp procedures revised for clarity ASMELL.D.L. Louisiana Power & Light Co. B0/06/20 Spp
- 8007300391 Ack receipt of 800630 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/80-07 SEIDLE/W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/08 ip
- ---B007300395 Responds to NRC B00528 itr se violations noted in IE Insp Rept 50-382/80-07 Corrective actions D stop repairs to be accomplished by granding weld defects to sound metal & visually inspecting results ASHELLID L Louisiana Power & Light Co 80/06/30 2pp
- S Reportable occurrences, LERs & related correspondence
- B00729044B Part 21 rept re-potential interference in full function of Bergen-Paterson strut assembly w/Pacific Scientific Comechanical shock arrestor Customers will be notified of affected items & recommended solution

 BECKBTED, N.F. Bergen-Patterson Pipe Support Corp. 80/06/20. Spp.
- B007010319 Requests that completion date for submitting final deficiency rept re procedural & performance deficiencies in ultrasonic testing of structural welds performed by Industrial Engineering Morks be extended until 800731 ASWELL,D.L. Louisiana Power & Light Co. 80/04/27 ip
- 8007020397 Forwards Final Significant Const Deficiency Rept 16 re Control element drive mechanism guide cones off-set ASHELLID L Louisiana Power & Light Lo 60/06/27)p
- --B007020405 Final Significant Canst Deficiency Rept 16 re control element drive mechanism guide cone: & penetration assemblies interface Offset condition exists which could produce interference on control assembly chaft # Louisiana Power & Light Co 80/06/27 2pp
- 9007080234 Forwards interim rept of Significant Const Deficiency 17 re base metal defects in main steam & feedwater containment penetration anchors ASMELL,D L. Louisiana Power & Light Co. 80/07/03. 1p
- --B0070B0239 Interim rept of Significant Const Definiency 17 re base metal defects in main steam & fredwater containment penetration anchors Evaluation underway to establish repair techniques Final rept will be forwarded by 810301 CRNICH.J. MILHISER.R.J. HART.J. Louisiana Power & Light Co B0/07/02 3pp
- DOCKET 50-987 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8007030239 Notification of 800707, meeting w/BWR licensing review group in Bethesda, MD to discuss concensus position on reactor svc bldg open issue WILSON, J N Licensing Branch 1 80/06/18 7pp
- 8007010297 Summary of 800613 meeting w/utils.KMC. Inc. GE. Bechtel. S&W & Sargent & Lundy in Dethesda, MD re consensus positions on reactor svc bldg & isolation cooling sys bldg open issues from La Salle docket Status repts encl
 WILSON, J N Assistant Director for Licensing 80/06/19 46pp

- BOO7210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Buppls 1-3. *Technical Basis for Use of Square-Root-of-Sum-of-Gquares (SRSS) Method for Combining Dynamic Loads for Mark II Plants " Rept acceptable subj to certain constraints MATTBON,R J Division of Bafety Technology 80/06/25 3pp
- BCO7090391 Notification of B00714-17 meeting w/stil.GE & Bechtol in Bothesda-MD to review open items for facility FSAR gamerated by NRC Mechanical Engineering Branch BTARMER M Licensing Branch 1 80/06/26 5pp
- 9007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISEMUT, D.G. Division of Licensing 80/06/26 2pp
- BOO7090378 Forwards request for add1 info re reactor sys YCUNG8LOOD, B J Licensing Branch 1 60/06/27 2pp
- GOO7170339 Notification of rescheduling of 800702 meeting w/BWR licensing review group in Bethesda. MD to discuss consensus positions on Reactor Sys Branch open issues Meeting reschaduled for 800707 HILBON.J N Assistant Director for Licensing 80/07/03 1p
- -- 8007170347 Notification of 800722 meeting w/BWR licensing review group in Bethesda, MD to discuss TMT issues required for OL WILSON, J N Assistant Director for Licensing 80/07/03 ip
- BOO7230621 Bummary of 800612 meeting w/Mark II owners group in Bathesda, MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDEREON, C J Generic Issues Branch 80/07/03 57pp
- EPOC7230133 Natification of 800725 meeting w/BWR Licensing Review Group in Bothesda/MD to discuss concensus positions of BWR Licensing Review Group on ICSB open issues
 WILEDN, J N Licensing Branch i 80/07/14 10pp
- BOO7250529 Comments on BOO714-16 meeting w/NRC in Bethesds.MD to resolve issues & answer questions on FSAR Sections 3 6-10 Dpen issues were resolved & meeting was productive Licensing managers should have input in sulerting meeting location CURTIB.N W Pennsglvania Power & Light Co 80/07/18 2pp
- BOD7290019 Advises that withholding affidavit per 10CFR2 790 must be submitted to support 800609 request re Revision 2 to design assessment rept Affidavit must be transmitted within 30 days YOUNGBLOOD B J Licensing Branch 1 80/07/21
- BOC7250175 Notification of B00805 meeting w/representatives from Mark II duners group in Chicago IL to discuss load Mark II plants chugging k C/O load specs
 ANDERSON C Generic Issues Branch 80/07/23 2pp
- BOO7240006 Notification of 800821 meeting w/util in Bethesda.MD to discuss responses to Reactor Sys Branch questions BTARK.R.M Licensing Branch 1 80/07/23 3pp
- F. Security, medical, emergency & fire protection plans
- BOO7230325 Summary of 800616 meeting w/util in Bethesda.MD to receive applicant questions no technical support ctr & emergency operations facility Applicant wishes to clorify interpretation of certain NRC requirements
 STARK.R M Licensing Branch 1 80/07/10 4pp
- BOD7220441 Forwards "Study Rept for Susquehanna Steam Electric Station Mass Notification & Evacuation." Part 1, prepared by AM Vorbees & Associates Rept in response to NRC 800702 request CURTIS:N W Pennsylvania Power & Light Co 80/07/17 ip

- @ Adjudicatory correspondence
- 8007010276 Responds to 800607 ltr Transcripts of NRC technical mretings w/applicants are not available due to unofficial aspect Summaries of mactings available in LPDRs future ltrs on behalf of intervenors should be sent to NRC counsel CUTCHIN, J M Hearing Branch 3 80/06/16 lp
- B007010273 Forwards Commission "Statement of Interim policy on Nutlear Power Plant Accident Considerations under NEPA of 1969." gublished in B00613 FR Commission decision.CLI-80-08 & ASLAB decision.ALAB-387 entl Wo attachments CUTCHIN.J M Hearing Branch 3 80/06/17 2pp
- 8007310243 Forwards Commission 800527 memorandum t order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum t order UCS 771104 petition sought action re file protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25 89pp
- 8007150709 Advises that FES is scheduled to be issued in Dec 1980. safety evaluation in Feb 1981 & safety evaluation suppl in May 1981 Further significant changes will be provided per NRC 790129-31 prehearing commitmentlif necessary CUTCHIN.J M Hearing Branch 3 80/07/10 &pp
- K Utility Final Sofety Analysis Report (FSAR) & amends
- B007080240 Forwards marked-up copy of FSAR. Subsection 3 92 & Table 3 9-33, corrected to agree w/preoperational & startup tests program Changes will be discussed at draft SER meeting during wk of B00714 CURTIS.N W Pennsylvania Power & Light Co 80/07/03 11pp
- 8007240131 Forwards Amend 22 to application for OL consisting of Revision 16 to FSAR FURTIS.N W. Pennsylvania Power & Light Co. B0/07/11 Ip
- --8007240142 Amend 27 to application for OL consisting of Revision 16 to CURTIS-N W Pennsylvania Power & Light Co BO/07/14 1e
- --8007240143 Revision 16 to FSAR * Pennsylvania Power & Light Co 80/07/14 600pp
- O Inspection reports, IE Bulletins & correspondence
- R007140466 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers" No written response required ORIER, B H Region 1. Philadelphia, Office of the Director 80/05/12; ip
- G007170607 Forwards IE Insp Repts 50-387/80-07 & 50-388/80-05 on G00421-24 No noncompliance noted CARLSON,R T Region 1, Fhiladelphia. Reactor Construction & Engineering Support Branch 80/05/28 2pp
- --8007170645 IE Insp Repts 50-387/80-0/ & 50-388/80-05 on 800421-24 No NOTITIONS IN THE MAPER SUPERIOR OF SUPERIOR OF CONTROL OF CONTROL
- 8007010262 Forwards IE Info Natice 80-23, 'Loss of Suction to Emergency Feedwater Pumps" No written response required GRIER.B H. Region i, Philadelphia, Office of the Director 80/05/29 ip
- 8007170,49 Forwards IE Insp Repts 50-387/80-11 & 50-388/80-07 on 800513-16 No noncompliance noted CARLEON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/03 2pp
- --8007170257 IE insp Repts 50-387/80-11 t 50-388/80-07 on 800513-16 No noncompliance noted Major areas inspected site activities t review of MRC insp status
 DURR.J P Region 1. Philadelphia. Office of the Director MGGAUSHY.R W Region 1. Philadelphia. Reactor Construction t Engineering Support Branch 80/06/02 2pp
- 8007210606 Forwards IE Info Notice 80-26, 'Evaluation of Contractor OA Programs " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 80/66/10 19

- 8007140287 Forwards JE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/12 lp
- 8007280612 Forwards IE Info Notice 80-28 "Prompt Reporting of Info in Accordance M/10CFR50 55(e)" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/13 1p
- 8007020513 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required CRIER.B H Region 1, Philadelphia, Office of the Director
- 80/06/20 1p
- 8007160733 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel." No written response required GRIER, B H. Region I. Philadelphia. Office of the Director 80/06/24.
- 8007210271 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER B H Region 1 Philadelphia, Office of the Director 80/06/25 Ip
- 8007210334 Act receipt of 800613 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/80-01 & 50-389/80-01 CARLSON.R T CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/27 ip
- --8007210341 Responds to NRC 600514 ltr re violations noted in IE Insp Repts 50-387/80-01 & 50-388/80-01 Corrective actions all space heaters in motor control ctrs identified energized & checked periodically SABOL. A R Pennsylvania Power & Light Co 80/06/13 3pp
- --8007210345 Forwards IE Insp Repts 50-387/80-01 & 50-388/80-01 on 800121-0201 & 0211-29 & notice of violation CARLSON,R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/14 2pp
- --8007210349 Notice of violation from insp on B00121-0201 & 0211-29 * Region 1. Philadelphia. Office of the Director B0/04/09 Rep
- ---B007210355 IE Insp Repts 50-387/80-01 & 50-388/80-01 on 800121-0201 & 0211-27 Noncompliance noted failure to follow approved procedures during preventive maint & to establish proper test program for performance of hydrostatic testing GALLOR M. RHDADS.C G Region i. Philadelphia. Office of the Director McCAUGHY.R W Region i. Philadelphia. Reactor Construction & Engineering Support Branch B0/04/07 18pp
- B007230166 Forwards IE Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters WEither A or D Output Codes " Written response required IE Circular 80-16 also enc! No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/06/27 2pp
- BOO7180339 Advises that ASME Code Cases N-234 & N-235 have been approved for use in reactor pressure vessel preservice insp program YOUNGBLOOD, B J Licensing Branch 1 80/06/28 2pp
- 8007180440 Requests add1 info to aid in facility licensing review re IE Bulletin 80-07 requirements & to provide commitment to adopt whatever long-term solution is approved Any short-term actions & supporting justification should be described YOUNGBLOOD, B J Licensing Branch 1 80/06/30 2pp
- 5 Reportable occurrences, LERs & related correspondence
- 8007170671 Ack receipt of 800513 interim deficiency rept re pilot solenoid valve classification Resolution of deficiency panding receipt of final rept CARLBON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/11 1p
- 8007170610 Ack receipt of 800529 interim deficiency rept re pipe supports welded to containment liner plate Rept will be reviewed & evaluated CARLSON.R T Region i. Philadelphia, Office of the Director 80/06/12 ip

- B007210045 Ack receipt of 800613 interim deficiency rept re unauthorized weld on reactor pressure vesse! CARLSON.R T Region 1. Philadelphia. Reactor Operations Nuclear Support Branch B0706/26 ip
- 8007080213 Supplemental deficiency rept re Pacific theck valves
 Problems w/check valve operation in Unit 1 core spray pump
 discharge vertical pipe run will necessitate rework of
 bonnet stops Final rept will be provided by Sept 1980
 CURTIS,N.H Pennsylvania Power & Light Co 80/07/03, 2pp
- 8007140197 Interim deficiency rept re Anchor-Darling Valve yokes. Cracks discovered in four radia at yoke mounting flange/yoke vertical section interface on Anchor-Darling valves in residual heat removal sys Final rept will be forwarded CURTISIN W Pennsylvania Power & Light Co 80/07/07 Spp
- 8007140340 Interim deficiency rept re Anchor-Darling valve yokes. Cracks discovered in four radii at yoke mounting flange/yoke vertical section interface on Anchor-Darling valves in residual heat removal sys Final rept will be forwarded, CURTIS.N W Pennsylvania Power & Light Co 80/07/07 3pp
- 8007140340 Interim deficiency rept per 10CFR50 88(e) & Part 21 recracks in four radii at yoke mounting flange/yoke vertical section interface on Anchor-Darling valves in RHR sys Final rept date will be provided after further review CURTIS,N W Pennsylvania Power & Light Co 80/07/07 3pp.
- 8007140170 Forwards final deficiency mept me insulation damage & deficient pin crimps in power generation control complex/advanced control room panel connectors
 CURTIS.N W Pennsylvania Power & Light Co. 80/07/08 2pp
- --B007140179 Final deficiency rept re insulation damage & deficient pin crimps in power generation control complex/advanced control room panel connectors, Cause unidentified Visual insp & pull test initiated on Unit 1.
 * Pennsylvania Power & Light Co 80/07/08 2pp
- 8007180434 Interim rept.par iOCFR50 55(e) & Part 21,re premature time out & drifting set points for preumatic time delay relays associated w/Apastat 7000 & GE CR 2820 relays Bechts1 & util analyzing safety impact CURTIS.N W Pennsylvania Power & Light Co 80/07/11 2pp
- 8007290865 Ack receipt of 800616 final deficiency rept re Limitorque motor operated valve stem nut staking CARLBON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 ip
- B007180282 Advises that 800122 ltr describing potential RO re coped structural floor beams determined not reportable under 10CFR50 55(e)
 CURTIB,N W Pennsylvania Power & Light Co 80/07/14. 2pp.
- 8007180364 Potential deficiency rept re coped structural floor beams. Based on results of field insp & finite element analysis, conditions noted are nonconforming & are therefore not reportable per 10CFR55(e) Bochtel procedures revised CURTIS, N W Pennsylvania Power & Light Co 80/07/14 2pp.
- 8007250487 Interim deficiency rept re status of Anchor Darling valve yokes AE has advised final rept on cracked yokes on Anchor Darling valves will be available in Aug 1980 Final rept will be forwarded during Sept 1980
 CURTIS, N W Pennsylvania Power & Light Co 80/07/21 1p.
- 8007280215 Final Deficiency MCAR 1-58, per 10CFR50 55(e) & Part 21, rv QE equipment lacking proper slope Caused by Unclear design drawings & const failures All affected drawings will be revised & Unit 1 as-built completed by 801230, CURTIS N W Pennsylvania Power & Light Co. 80/07/21, 4pp
- BOO7280650 Final deficiency rept re improper sloping of QE piping & tubing Bechtel Nonconformance Rept 5807 lists 41 small pipe installations to GE equipment that do not meet min slope requirement Revised acceptance criteria developed * Pennsylvania Power & Light Co 80/07/21 4pp.
- B007290455 Interim deficiency rept re pipe support design drawings. Final rept will be provided in Apr 1781 CURTIS, N W Pennsylvania Power & Light Co 80/07/22. 2pp
- 8007270623 Supplements & updates projected completion date of corrections re pipe support design drawings Bechtel Power Corp will provide final rept on defective condition by Mar 1981 Util final rept will be provided by Apr 1981 CURTIS, N W Pennsylvania Power & Light Co. 80/07/22, 2pp

P290716 Supplemental deficiency rept updating status of improper to lenoid valve safety classification Dechtel Power Corp.

CAR 1-55 final rept will be available Oct 1980 & util final leficiency rept by Nov 1980

URTIS.N W Pennsylvania Power & Light Co. 80/07/23 19

MET 50-388 BUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2 Plication/construction stage documents & correspondence

7210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls -3. "Technical Basis for Use of Square-Root-of-Sum-of-Quares (SRSS) Method for Combining Dynamic Loads for Mark I Plants "Rept acceptable subj. to certain constraints STERMS J. Divasion of Safety Technology 80/06/25 3pp

'7090391 Notification of 800714-17 meeting w/util.GE & Bochtel in thesds,MD to review open items for facility FSAR thereated by NRC Mechanical Engineering Branch TARK,R M Licensing Branch 1 80/06/26 5pp

7230001 Forwards statement of policy re requirements to be mot for Green DL applications, as derived from NUREG-0660 & found n. NUREG-0694
I BENAUT, D 0 Division of Licensing 80/06/26 2pp

7090378 Forwards request for addl info re reactor sys

7230521 Summary of 800612 meeting w/Mark II owners group in thesda, MD re lead plant closure & long-term program Mods hould be made to generic lead plant condensation to thoughing pool boundary loads Viewgraphs encl NIDERBON.C J. Generic Issues Branch 80/07/03 57pp

PR50329 Comments on 800714-16 meeting w/NRC in Bethesds, MD to meeting tissues & answer questions on FSAR Sections 3 6-10 pern issues were resolved & meeting was productive Licensing enablers should have input in selecting meeting location persons to the second part of the second product of the second persons are second persons as a second person of the second persons are second persons as a second person of the second person

7290019 Advises that withholding affidavit per 100FR2 790 must be be being to apport 800609 request re Revision 2 to design as massment rept Affidavit must be transmitted within 30 n us. DUNGBLOOD, B J Licensing Branch 1 80/07/21 2pp

7250175 Notification of B00805 meeting w/representatives from Mark I owners group in Chicago IL to discuss lead Mark II plants tagging & C/O load specs
TDER80N.C Generic Issues Branch 80/07/23 2pp

7270006 Notification of 800821 meeting w/util in Bethesda, MD to Lucuse responses to Reactor Sys Branch questions FARK, R M Licensing Branch 1 80/07/23 3pp

Becurity, medical, emergency & fire protection plans

7230325 Summary of 800616 meeting w/util in Bethesda.MD to receive splicant questions re technical support ctr & emergency swrations facility Applicant wishes to clarify theretation of certain NRC requirements FARK.R M Licensing Branch 1 80/07/10 4pp

>07220448 "Study Rept for Susquehanna Steam Electric Station Mass Motification & Evacuation," Part I # PRC Planning & Economics, Alan M Voorhees & Associates Div #0/07/17. 59pp

ad judicatory correspondence

- 8007010273 Forwards Commission "Statement of Interim policy on Nuclear Power Plant Accident Considerations under NEPA of 1969," published in 800613 FR Commission decision, CLI-80-08 & ASLAD decision, ALAB-507 encl & I/o attachments CUTCMIN, J M Hearing Branch 3 80/06/17 2pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re-fire protection for electrical cables
 EISENHUT.D G Division of Licensing 80/06/25 89pp
- 8007150709 Advises that FES is scheduled to be issued in Dec 1980, mafety evaluation in Feb 1981 & safety evaluation suppl in May 1981 Further significant changes will be provided per NRC 790129-31 preheating commitment, if necessary CUTCHIN, J M Hearing Branch 3 80/07/10 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007080240 Forwards marked-up copy of FSAR, Subsection 3 92 & Table 3 9-33, corrected to agree w/preoperational 2 startup tests
 program Changes will be discussed at draft SER meeting
 during wk_of 800714
 CURTIS.N W Pennsylvania Power & Light Co 80/07/03 11pp
- 8007240131 Forwards Amend 22 to application for DL consisting of Revision 16 to FSAR CURTIS.N W Pennsylvania Power & Light Co 80/07/11 ip
- --8007240142 Amend 22 to application for OL consisting of Revision 16 to CURTIS:N W Pennsylvania Power & Light Co 80/07/14 ip
- ---8007240143 Revision 16 to FBAR

 * Pennsylvania Power & Light Co 80/07/14 400pp
- P Operating license stage documents & correspondence
- 8007100273 Submits add1 info re implementation of short-term Lessons Learned requirements Status of remaining Category A items, mid-yr status of design & installation of Category B mods & schedule for implementation encl Forwards drawings BYLVIA.8 R Virginia Electric & Power Co 80/07/07 180pp
- G. Inspection reports: IE Bulletins & correspondence
- 8007140466 Forwards IE Bulletin 80-13, "Cracking in Core Spray Byargers "No written response required GRIER.B H Region 1. Philadelphia Office of the Director BO/O5/12 1p
- 8007170637 Forwards IE Insp Repts 50-387/80-07 & 50-388/80-05 on 800421-24 No moncompliance noted CARLSON,R T Region I. Philadelphia. Reactor Construction & Engineering Support Branch 80/05/28 2pp
- ---8007170645 IE Insp Repts 50-387/80-07 & 50-388/80-05 on 800421-24 No noncompliance noted Major areas inspected site audit program & outstanding items
 DURR.J P Region 1. Philadelphia. Office of the Director
 TRIPPIL E Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/09/23 3pp
- 8007010262 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER.D H Region 1. Philadelphia. Office of the Director 80/03/29 ip
- 8007170249 Forwards IE Josp Repts 50-387/80-11 & 50-398/80-07 on 800513-16 No noncompliance noted CARLSON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/03 2pp
- --8007170257 IE Insp Repts 50-387/80-11 & 50-388/80-07 on 800513-14 No noncompliance noted Major areas inspected site activities & review of NRC insp status
 DURR, J P Region 1, Philadelphia, Office of the Director
 MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 60/08/02 2pp
- 8007210606 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required GRIER.O H Region 1. Philadelphia, Office of the Director 80/06/10 Ip

- 8007140287 Forwards IE Bulletin 80-14 'Degradation of BMR Scram Discharge Vol 'apability "No written response required ORIER.8 H. Region I. Philadelphia. Office of the Director 80/86/12 Ip
- 8007280612 Forwards IE (nfp Notice 80-28, 'Prompt Reporting of Info in Accordance W/100FR50 55(e) 'No written response required GRIER. B. H. Region 1, Philadelphia, Office of the Director 80/06/13 ip
- 8007020513 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling 'Natural Circulation Cooldown " No written response required GRIER.8 H Region 1. Philadelphia. Office of the Director 80/06/20 1p
- 8007160733 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required GRIER.B H Region I Philadelphia, Office of the Director 80/04/23
- 6007210271 Forwards IE Info Notice 80-24, "Low Leve) Radwaste Buriel Criteria " No written response required CRIER.B H Region 1, Philadelphia, Office of the Director 60/06/25 ip
- B007210334 Ack receipt of B00613 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-3B7/80-01 & 50-3B8/80-01 CARLBON R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/27 ip
- --8007210341 Responds to NRC 890514 ltr re violations noted in IE Insp Repts 50-387/80-01 & 50-388/80-01 Corrective actions all space heaters in motor control ctrs identified, enorgized & checked periodically SABCLIA R Pennsylvania Power & Light Co 80/06/13 3pp
- --8007210345 Forwards IE Insp Repts 50-387/80-01 & 50-388/60-01 on 800121-0201 & 0211-29 & notice of violation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/03/14 2pp
- --8007210349 Notice of violation from insp on 800121-0201 & 0211-29 * Region 1, Philadelphia, Office of the Director 80/04/09 2pp
- --B007210355 IE Insp Repts 50-3B7/B0-01 & 50-3B8/B0-01 on B00121-0201 & 0211-29 Noncompliance noted failure to follow approved procedures during preventive maint & to establish proper test program for performance of hydrostatic testing OALLO,R H, RHDADS,G G Region I, Philadelphia, Office of the Director HCCAUCHY,R W Region I, Philadelphia, Reactor Construction & Engineering Support Branch B0/04/09 18pp
- 8007230166 Forwards IE Bulletin BO-16. "Potential Misapplication of Roseaount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also and No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/27
- B007180939 Advises that ASME Code Cases N-234 & N-235 have been approved for use in reactor pressure vessel preservice insp program YOUNGBLOOD, B J Licensing Branch 1 80/06/28 2pp
- B007180440 Requests add1 info to aid in facility licensing review re IE Bullstin 80-07 requirements & to provide commitment to adopt whatever long-term solution is approved Any short-term actions & supporting justification should be described YOUNGBLOOD, B J Licensing Branch 1 80/06/30 2pp
- B00725008B Discusses action taken re allegations made by former welder trainee R Wilson Wilson has refused to provide specific info, therefore no further action is planned Ltr constitutes final followup to NRC 800123 ltr
 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/10 2pp
- --8007250076 Describes 800125 telcon w/R Wilson re allegations concerning underground gaping & passing unqualified individuals on welding tests Wilson refused to provide specific info Inquiry w/Bechtol revealed Wilson was not employed at site EMITHIR H Office of Inspection & Enforcement. Office of the Director 80/06/03 lp

- S Reportable occurrences, LERs & related correspondence
- 8007170671 Ack receipt of 800513 interim deficiency rapt re pilot solvenoid valve classification Resolution of deficiency pending receipt of final rept CARLSON, R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/11 lp
- 8007170610 Ack recoipt of 800329 interim deficiency rept re pipe supports welded to containment liner plate Rept will be reviewed & evaluated CARLSON, R T Region 1. Philadelphia, Office of the Director 80/06/12 ip
- B0070B0213 Supplemental deficiency rept re Pacific Check valves.
 Problems w/check valve operation in Unit 1 core apray pump
 discharge vertical pape run will necessitate rework of
 bonnet stops Final rept will be provided by Sept 1980
 CURTIS.N W Pennsylvania Power & Light Co 80/07/03 2pp
- B007140170 Forwards final deficiency rept re insulation damage & deficient pin crimps in power generation control complex/advanced control room panel connectors CURTIS,N W Pennsylvania Power & Light Co B0/07/08 2pp
- --8007140179 Final deficiency rept re insulation damage & deficient pin crimps in power generation control complex/advanced control room panel connectors Cause unidentified Visual insp & pull test initiated in Unit i * Pennsylvania Power & Light Co 80/07/08 2pp
- 8007180434 Interim rept, per iOCFR50, 55(e) & Part 21, re premature time out & drifting set points for pneumotic time delay releva associated w/Agastat 7000 & OE CR 2820 relays Bechtel & util analyzing asfety impact CURTIS:N W Pennsylvania Power & Light Co 80/07/11 2pp
- 8007290865 Ack receipt of 800616 final deficiency rept re Limitorqua motor operated valve stem nut staking CARLSONR T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/11 1p
- 8007180364 Potential deficiency rept re coped structural floor beams Based on results of field insp & finite element analysis, conditions noted are nonconforming & are therefore not reportable per 10CFR95(s) Bechtel procedures revised CURTIS.N W Pennsylvania Power & Light Co. 80/07/14 2pp
- 8007290487 Interim deficiency rept re status of Anchor Darling valve unles AE has advised final rept on cracked yokes on Anchor Darling valves will be available in Aug 1980 Final rept will be ferwarded during Sept 1980 CURTIS, N W Pennsylvania Power & Light Ca 80/07/21 1p
- BOO7280215 Final Deficiency MCAR 1-58.per 10CFR90 55(a) & Part 21.re QE equipment lacking proper slope Caused by unclear design drawings & const failures All affected drawings will be revised & Unit 1 as-builts completed by 801230 CURTIS.N H Pennsylvania Power & Light Co 80/07/21 4pp
- B007280550 Final deficiency rept re improper sloping of OE piping & tubing Becktel Nonconformance Rept 5807 lists 41 small pipe installations to GE equipment that do not meet min slope requirement Revised acceptance criteria developed * Pennsylvania Power & Light Co 80/07/21 4pp
- 8007290455 Interim deficiency rept re pipe support design drawings. Final rept will be provided in Apr 1981 CURTIS.N W Pennsylvania Power & Light Co 80/07/22 App
- 8007290623 Supplements & updates projected completion date of corrections re pipe support design drawings Bachtel Power Corp will provide final rept on defective condition by Mar 1981 Util final rept will be provided by Apr 1981 CURTIS:N W Pennsylvania Power & Light Co 80/07/22 2pp
- 8007290264 Interim deficiency rept re improper safety classification for solenoid valves Final rept will be provided in Nov 1980. CURTIS N W Pennsylvania Power & Light Co 80/07/23 lp
- 8007290716 Supplemental deficiency rept updating status of improper solenoid valve safety classification Bechtel Power Corp MCAR 1-35 final rept will be available Oct 1980 & util final deficiency rept by Nov 1980 CURTIS, N W. Pennsylvania Power & Light Co. 80/07/23 | 10

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- B007030175 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO.8 L Assistant Director for Licensing 80/06/12 2pp
- \$00722.3' 'I Forwards statement of policy re requirements to be met for curren. OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D G Division of Licensing 80/06/26 2pp
- F Security, medical, emergency & fire protection plans
- . BOO7010379 Forwards BNi fire protection review re upgrading existing fire pumps, cable spreading room, fire barrier, smoke detectors, reactor coolant pump oil collection sys & automatic sprinkles sys for facility HALL.R E. Brookhaven National Laboratory 80/06/24 6pp
 - B007280647 Advises that evacuation time estimates were submitted in 800717 ltr per 800702 request WHRIG.R E Florida Power & Light (u 80/07/22 1p
 - Adjudicatory correspondence
 - 8007310243 Forwards Commission 800527 memorandum & order centaining decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENHUT, D. G. Division of Licensing 80/06/25 89pp
 - H General correspondence
 - 8007110306 Responds to 800512 ltr re encl L Starr ltr concerning plant problems Nuclear plant safety design approach involves use of multiple physical barriers to prevent release of radioactivity to environ DIRCKS, H J Office of the Executive Director for Operations 80/06/30 3pp
 - --- GOO7110314 Requests response to L Starr ltr concerning plant problems CHILES.L J Senate 80/05/12 ip
- BOO7240444 Responds to BOO521 ltr re S Corbin inquiry about plant safety aspects Safety design approach involves use of multiple physical barriers to prevent release of radioactivity to environ
 DIRCKS.W J Office of the Executive Director for Operations
 BOO7775 Son
- ---8007240468 Requests response to encl S Corbin inquiry about plant safety aspects STONE,R Senate 80/05/21 2pp
- M Antitrust correspondence
- BOO7090051 Comments on Orlando Utils notice of withdrawal re-order modifying CPs Other intervening cities must be given similar nuclear access opportunities Urges establishment of procedures allowing author to be heard W/Certificate of Svc JABLON.R A Florida Cities JABLON.R A Spiegel & McDiarmid BO/07/07 4pp
- B007150719 Response stating no objection to Orlando Utils Commission B00620 withdrawal of intervention FL Cities 800707 comments re equal treatment will be addressed in Unit 2 antitrust proceeding Certificate Syc encl DEWEY.L S Antitrust Division 80/07/11 4pp
- 8007230798 Advises of extension until 800916 for FL Cities & util to respond to interrogatories NRC & DOJ have no objection to extension ASLD approval requested Certificate of Svc encl ROTH.A J Florida Cities BOUKNIGHT.J A Florida Power & Light Co 80/07/18 3pp
- B007270004 Forwards notice of receipt of addl antitrust info which is to be published in FR
 YOUNGBLOOD, B J Licensing Branch 1 80/07/21 1p
- B007270753 Order granting extension until B00716 for FL Cities & util to respond to interrogatories
 SMITH: I W Atomic Safety and Licensing Board Panel 80/07/23 ip

- 8007250407 Discusses util % FL cities 800718 ltr to ASLB re completion of document production NRC will not agree on completion until documents are obtained & reviewed NRC is willing to postpose util answers to interrogatorios indefinitely DEMEY.L S Autitrust Division 80/07/21 2pp
- G Inspection reports, If Bulletins & Correspondence
- 8007240206 Forwards IE Info Notice 80-20. "Loss of Detay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY.J P Region 2 Atlanta, Office of the Director 80/05/08
- B007070165 Forwards IE Insp Rept 50-389/80-06 on 800430-0502 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/05/19 2pg
- --8007070169 IE Insp Rept 50-189/80-06 on 800430-0502 Na noncompliance noted Major areas inspected electrical & instrumentation GA implementing procedures review for Class IE components & sys & For Class IE cables & terminations

 MALTERS,D K. Region 2. Atlanta, Office of the Director CONLOWITE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/19 Spp
- 8007020231 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28 1p
- 8007210458 Forwards IE Circular 80-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28 ip
- 800701020A Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director 80/05/29 to
- 8007220062 Forwards IF Info Notite 80-26 "Evaluation of Contractor GA Programs" No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/06/10 2pp
- 8007160265 Forwards IE Info Nutice 80-27. Degradation of Reactor Coulant Pump Stude "No specific action or response required O'REILLY: J.P. Region 2. Atlanta, Office of the Director 80/06/1
- 8007250372 Forwards IE Info Nutice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 95(e)" No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/13 200
- 8007020454 Forwards IC Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required O'REILLY.J.P. Region 2, Atlanta, Office of the Director 80/06/20 ip
- 8007170107 Forwards It Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Prisonnel "No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/24
- 8007230243 Forwards IE Bulletin 80-15. "Potential Hisapplication of Rosemburt inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes." Written response required IE Circular 80-16 also encl No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/27
- 8007210060 Provides interim response to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Facility utilizes flued head design genetration connections Records under review Tables encl
 UHRIG.R E Florida Power & Light Co 80/07/07 13pg
- BOO7310212 Ack receipt of 800707 ltr informing NRC of steps taken to correct violation noted in IE Investigation Rept 50~389/ 80~05 MURPHY.C C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/21 ip

- B007310220 Responds to NRC 800609 1tr re violation noted in IE Investigation Rept 50-389/80-05 Corrective actions back of each individual ID badge will be stamped w/certification held UHRIG.R E Florida Power & Light Co 80/06/27 2pp
 - •
- 8007310223 Forwards 1E Investigation Rept 50-389/80-05 on 800408 & 21-24 & notice of violation O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/09 2pp
- 8007310228 Notice of violation from investigation on 800408 & 21-24 * Region 2. Atlanta, Office of the Director 80/04/09 ip
- B007310235 JE Investigation Rept 50~389/80~05 on B00408 & 21~24
 Noncompliance noted failure to follow procedure requirement
 to use certified mondestructive examination personnel
 LONG.F W. MCGUIRE.D R. Region 2. Atlanta. Office of the Director
 VANDORN.P W. Region 2. Atlanta. Reactor Construction &
 Engineering Support Branch. 80/06/07 App
- Reportable occurrences, LERs & related correspondence
- 07160599 Advises that final deficiency rept re diesel generator control panels will be delayed until 800731 JHRIO.R E Florida Power & Light Co 80/06/17 jp
- 'KEY 50-390 HATTE BAR NUCLEAR PLANT, UNIT 1
 Application/construction stage documents & correspondence
- 7010148 Requests add1 info within two wks.needed to determine otential for underclad cracking in reactor vessel noticles litrasonic exams did not indicate explicit correlation etween observed cracking & pre/post-clad heat treatment CHMENCER.A Licensing Branch 2 80/06/18 2pp
- 7020707 Forwards request for info re confirmatory piping analysis exponse should be submitted to ANL by B00703 Includes info piping layout & isometric drawings sufficient to model ys & support drawings wispport & hanger spring rates CHWENCER, A Licensing Branch 2 80/06/23 3pp
- 7010386 Advises that util has received no response to 790928 request or extensions until Mar & Dec 1981 for Watts Bar I & 2 Addl lefety requirements may result in completion by Jan 1981 for Sequoyah 2.May 1981 for Watts 1 & Feb 1982 for Watts 2 ILLS.L M Tennessee Valley Authority 80/06/26 ip
- 7230001 Forwards statement of policy re requirements to be met for Jrrent DL applications, as derived from NVREG-0660 & found NVREG-0699
 SENHUT, D @ Division of Licensing 80/06/26 2pp
- '090253 Forwards add1 request re ultrasonic exam of welds LLS.L M Tennessee Valley Authority 80/07/01 3pp
- 300584 Notification of contract execution.Mod 2 to "Evaluation of chiling Stress Criberia for Stepl Containment at Hatts r." Contractor Intl Structural Engineers AGESSER.C M Purchasing Section FIN 8-6581 80/07/02 1p
- O7300587 Mod 2. changing completion date, to "Evaluation of Buckling Stress Criteria for Steel Containment at Watts Bar " International Structural Engineers, Inc. PERLMAN, J Administrative Contracts Branch FIN 8-6581 80/07/02 ip
- djudicatory correspondence
- 310243 Forwards Commission 800527 memorandum & order containing isions on UCS 780502 petition for reconsideration of 2413 memorandum & order UCS 771104 petition sought action fire protection for electrical cables SENHUT.D 0 Division of Licensing 80/06/25 89pp

- O Inspection reports. JE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007020192 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28, In
- 8007210488 Forwards IE Circular 80-13. "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28 in
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Syction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29 ib
- B007220029 Forwards IE Info Notice 80~24, "Evaluation of Contractor 9A Programs " No written response required 0'REILLY, J.P. Region 2. Atlanta, Diffice of the Director 80/06/10
- 8007i60287 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/11 to
- 80072503B4 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance H/10CFR50 55(e)" No written response required, O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/13 Jpp
- 8007270400 Forwards IE Insp Rept 50-390/80-17 on 800527 & 30 No noncompliance noted STDHR. J P Repion 2. Atlanta. Fuel Facility & Materials Hafety Branch 80/04/17 2pp
- ~-8007290404 IE insp Rept 50-390/80-17 on 800529 & 30
 No noncompliance noted Major areas inspected environ
 monitoring programs & environ protection program
 JENKINS, G R Region 2, Atlanta, Fuel Facility & Materials Bafety
 Branch CUNNINGHAM, A L Region 2, Atlanta, Office of the
 Director 80/06/17 3pp
- 800702039: Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20,
- 8007170070 Forwards IE Circular 80-14, "Radinactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/24,
- 8007230293 Forwards IE Bulletin HD-16. "Potential Misapplication of Rosemount Inc Models 1181 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007210036 Forwards response to IE Bulletin 80-08 re-examination of containment lincr penetration welds Penetrations at Sequoyah Watts Bar & Bellefonte contain flued head design Design for Yellow Creek not yet completed MILLS.L M Tennessee Valley Authority 80/07/08, 5pp.
- 8007170272 Responds to NRC 800617 ltr re violations noted in IE Insp Repts 50-390/80-14 & 50-391/80-10 Corrective actions weld procedure changed to allow use of 1/8-inch filler metal for root pass & inspectors instructed to follow instructions MILLS:L M. Tennessee Valley Authority 80/07/10 3pp
- 8007230582 Responds to NRC ltr re violation noted in IE Insp Rept 50-390/80-16 Corrective actions starting on 800418, items in room identified by engineering were cleaned & returned to warehouse per WRNF-0CP-16
 MILLS,L H Tennessee Valley Authority 80/07/15 4pp.

- GOO7270B13 Responds to BOO626 request for addit actions to avoid further noncompliance & date full compliance achieved re plant areas w/open pipe ends & manways left unattended GA program initiated to check coverage Full compliance by BOO714 MILLS,L H Tennessee Valley Authority BO/07/23 2pp
- § Reportable occurrences, LERs & related correspondence
- 8007020619 Fifth interim deficiency rept re refueling water storage tank overflow line not fabricated to ASME code Pittsburgh-Des Moines Steel Co & TVA discussing repairs Next rept will be provided by 800905 MILLS.L M Tennessee Valley Authority 80/06/18 ip
- 8007160571 Forwards final deficiency rept re chemical & vol control syscentrifugal charging pumps MILLB.1, M Tennessee Valley Authority 80/04/18 ip
- ---B007i60578 Final deficiency rept re potential for degradation of one or more chemical & vol control sys centrifugal charging pumps

 Design & plant emergency operating procedures will be modified, as recommended by Westinghouse

 # Tennessee Valley Authority B0/06/18 Zpp
- B007170664 Part 21 final rept re Westinghouse chemical & vol control sys centrifugal charging pumps Following secondary side high energy line rupture & associated reactor trip:min flow may not be met Emergency operating procedures modified HILLS.L N Tennessee Valley Authority 80/06/18 4pp
- B007090222 Becond interim deficiency rept re radiation qualification of safety-related cables encl in conduit inside containment. Util continuing to investigate Rept detailing results of syalvation & corrective actions expected by B00719 MILLS, L. M. Tannessee Valley Authority 80/07/01. Ip
- B007140422 Forwards first interim deficiency rept re insufficient analysis of 3-inch fire protection lines Will submit next rept by 800902 HILLS.L M Tennessee Valley Authority 80/07/03 ip
- --B007140427 First interim deficiency rept re insufficient analysis of 3-inch fire protection lines Layout drawings did not provide sufficient dimensions Three-inch fire protection lines will be rigorously analysed & supports will be added Tennessee Valley Authority 80/07/03 ip
- 8007170513 Forwards first interim deficiency rept re cutting of conduit supports w/o cutting release MILLS.L.M. Tennassee Valley Authority 80/07/11 ip
- ---8007170525 First interim deficiency rept re cutting of conduit supports \(\psi \)/O cutting release Investigation underway Addl info expected by 800827

 # Tennesses Valley Authority. 80/07/11 ip.
- 8007170891 Fourth interim deficiency rept re incorrect analysis of total temp range for essential raw cooling water piping Incorrect analysis confined to piping in auxiliary & reactor bldgs. New thermal analyses underway MILLB.L M Tannessae Valley Authority 80/07/11 2pp
- 8007230487 Second interim deficiency rept re inadequate documentation for miscellaneous mechanical equipment Applicable GC procedures written or revised to include omitted equipment Available documentation to be revisued for further action MILLS,L.M. Tennessee Valley Authority 80/07/15 ip.
- 8007230505 First interim deficiency rept re inability of GE breakers to withstand design impulse levels. Caused by possible problem in assembly of breaker bushings, Circuit breakers will be returned to GE HILLS.L. M Tennessee Valley Authority 80/07/18 2pp
- B0072305B7 Forwards revised final deficiency rept re potential to avarluad containment cooling sys pump discharge mozzles MILLS.L M. Tennesses Valley Authority 80/07/18 1p.
- --B007230591 Revised final deficiency rept re potential to overload containment cooling sys pump discharge nozzles. Design modified by replacing some grid supports with be properly installed as required by 801205 a Tennessee Valley Authority 80/07/18 ip
- B007290610 Second interim deficiency rept re defective reactor vessel upper internals guide tube support pins Westinghouse has not completed evaluation of pins taken from operating plant Next rept will be forwarded by 800911

 O'REILLY, J P Tennessee Valley Authority B0/07/24 ip

V Operator Examinations

B007080388 Notifies that response to NRC B00603 ltr re operator training was submitted in JR Calhoun B00416 ltr to P Collins
MILLS,t. M Tennessee Valley Authority 80/07/01 ip

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- BD0701014B Requests add1 info within two wks.needed to determine potential for underclad cracking in reactor vessel nuisles. Vitrasonic exams did not indicate explicit correlation between observed cracking & pre/post-clad heat treatment SCHWENCER.A Licensing Branch 2 80/06/18 2pp
- B007020707 Forwards request for info re confirmatory piping analysis
 Response should be submitted to ANL by 800703 Includes info
 re piping layout & isometric drawings sufficient to model
 sys & support drawings utsupport & hanger spring rates
 SCHENCER, A Litynsing Branch 2 80/06/23 3pp
- 8007010386 Advises that util has received no response to 790928 request for extensions until Mar & Dec 1981 for Watts Bar 1 & 2 Add1 safety requirements may result in completion by Jan 1901 for Sequeyah 2.May 1981 for Watts 1 & Feb 1982 for Watts 2 MILLS:L M Tennessee Valley Authority 80/06/26 ip
- BOO7230001 Forwards statement of policy is requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EISENHUT, D O Division of Licensing 80/06/26 2pp
- 8007080253 Forwards addl request to ultrasonic exam of welds MILLS, L.M. Tennessee Valley Authority 80/07/01 Spp
- 80073005B4 Natification of contract execution, Mod 2 to "Evaluation of Buctling Stress Criteria for Steel Containment at Watts Bar " Contractor Intl Structural Engineers TRAGESSER, C M Purchasing Section FIN B-45B1 80/07/02 1p
- --8007300587 Mod 2, changing completion date, to "Evaluation of Buckling Stress Criteria for Steel Containment at Watts Bar " • International Structural Engineers, Inc PERLMAN. J Administrative Contracts Branch FIN 8-4581 80/07/02 ip

G Adjudicatory correspondence

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 87pp

H General correspondence

- 8007230081 Responds to 790425 request for info re nuclear energy Radiation doses from power plants is small fraction of dose from natural environ sources FEB excerpt & White House 800212 message to Congress encl DENTON-HR Office of Nuclear Reactor Regulation, Director 80/04/27 1889
- Q Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice BO-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"
 No response required
 D'REILLY, J P Region 2, Atlanta, Diffice of the Director 80/09/08
- 8007210488 Forwards IE Circular 80-13, "Grid Strap Damage in Hestinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/28 ip
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 8007220029 Forwards IE Info Notice 80-24, "Evaluation of Contractor QA Programs " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/10 300

- 007160287 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response
- required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/11
- 107250384 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required 8'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/13
- 07020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required 0°REILLY.J P Region 2, Atlanta, Office of the Director 60/06/20
- 07170070 Ferwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel "No written response required PREILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20 R070A724
- 17230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1851 & 1852 Pressure Transmitters WEIther A or D Output Codes " Written response required (E Circular 80-16 also encl No written response required 19REILLY.J P Region 2. Atlanta. Office of the Director 80/06/2 80/06/27
- 7210036 Forwards response to IE Bulletin 80-08 re-examination of ontainment liner penetration welds Penetrations at equoyah. Watts Bar & Bellefonte contain flued head design esign for Yellow Creek not yet completed ILLS.L M Tennessee Valley Authorsty 80/07/08 Spp
- 7170272 Responds to NRC 800617 ltr re violations noted in IE Inspepts 50-390/80-14 & 50-391/80-10 Corrective actions weld vocadure changed to allow use of i/8-inch filler metal for not pass & inspectors instructed to follow instructions ILLS-L M Tennessee Valley Authority 80/07/10, 3pp
- leportable occurrences, LERs & related correspondence
- 020519 Fifth interim deficiency rept re refueling water storage ink overflow line not fabricated to ASME code Pittsburgh-s Maines Steel Co & TVA discussing repairs Next rept will provided by 800905 LLS-L M Tennessee Valley Authority 80/06/18 ip
- 160971 Forwards final deficiency rept re chemical & vol control sys ntrifugal charging pumps .18.L M Tennessee Valley Authority 80/04/18 ip
- 0716057B Final deficiency rept re potential for degradation of one or more chemical & vol control sys centrifugal charging pumps lesign & plant emergency operating procedures will be nodified as recommended by Westinghouse
 Tennessee Valley Authority 80/06/1B ⊋pp
- 70664 Part 21 final ropt re Westinghouse chemical & vol control centrifugal charging pumps Following secondary side high rgy line rupture & associated reactor trip, min flow may be met Emergency operating procedures modified LG.L M Tennossee Valley Authority 80/06/18 App
- 90222 Second interim deficiency rept re radiation qualification of ety-related cables encl in conduct inside containment l continuing to investigate Rept detailing results of luation & corrective actions expected by 800919

 -S.L M Tennessee Valley Authority 80/07/01 ip
- 10422 Forwards first interim deficiency rept re insufficient yess of 3-inch fire protection lines Will submit next by 800902 S.L.M. Tennessee Valley Authority 80/07/03 ip
- 140427 First interim deficiency rept re insufficient analysis of inch fire protection lines Layout drawings did not provide ffizient dimensions Three-inch fire protection lines will rigorously analyzed & supports will be added Tennessee Valley Authority 80/07/03 1p
-)513 Forwards first interim deficiency rept re cutting of conduit orts w/a cutting release .L M Tennessee Valley Authority 80/07/11 !p

- --8007170525 First interim deficiency rept re cutting of conduit supports w/o cutting release investigation underway Addl info expected by 800829 Tennessee Valley Authority 80/07/1: 1p
- 8007170591 Fourth interim deficiency rept re incorrect analysis of total temp range for essential raw cooling water piping Incorrect analysis confined to piping in auxiliary & reactor bldgs New thermal analyses underway MILLS.L M Tennessee Valley Authority 80/07/11 2pp
- 8007230487 Second interim deficiency rept re inadequate documentation for miscellaneous mechanical equipment Applicable GC procedures written or revised to include anitted equipment Available documentation to be reviewed for further action MILLS,L M Tennesses Valley Authority 80/07/15 ip
- 8007230505 First interim deficiency rept re inability of QE breakers to withstand design impulse levels Caused by possible problem in assembly of breaker bushings Circuit breakers will be returned to GE MILS.L M Tennessee Valley Authority 80/07/18, 2pp
- B007230597 Forwards revised final deficiency rept re potential to overload containment cooling sys pump discharge nozzles MILLS.L M Tennessee Valley Authority 80/07/18 1p
- --8007230591 Revised final deficiency rept re potential to dverload containment cooling sys pump discharge notiles. Design modified by replacing some grid supports w/snubbers Supports will be properly installed as required by 801205 * Tennessee Valley Authority 80/07/18 1p
- 8007290610 Second interim deficiency rept re defective reactor vessel upper internals guide tube support pins Hestinghouse has not completed evaluation of pins taken from operating plant Next rept will be forwarded by 800911 O'REILLY, J.P. Tennessee Valley Authority 80/07/24 1p
- V Operator Examinations
- B007080388 Notifies that response to NRC 800403 ltr re operator training was submitted in JR Calhoun B00414 ltr to P MILLS.L M Tennessee Valley Authority 80/07/01 ip
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8007020061 Summary of 800613 meeting w/util re structúral & geotechnical engineering review w/emphasis on syc water intake structure HOUGHTGN.T C Licensing Branch 3 80/06/23 5pp
- 8007140229 Notification of 800708-10 meeting w/util in Columbia, SC to review qualifications of util to operate plant List of agenda items encl KANE, WF Licensing Branch 2 80/06/26 5pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D @ Division of Licensing 80/06/26
- B007180334 Forwards request for add1 info in connection w/NRC review of OL application Info covers areas of matls engineering, secondary water chemistry control & seismology Seismology questions replace those numbered 361 12 to 361 17 BCHWENGER, A Licensing Branch 3 B0/06/30, 14pp
- 8007230635 Forwards and order for DOE work MATTSON R J Division of Safety Technology FIN A-1121-0 BD/06/30 3pp
- --8007230452 Btd order for DOE work "Review of Auxiliary Feedwater Sys Reliability Evaluation Studies for Diable Cangon i, McQuire 1. Summer i & San Onofre 2 & ECCS Reliability Analysis of Manual vs Automatic " Issued to Bandia Labs ORENIER, B L. Division of Bafety Technology FIN A-1121-0 SD/06/27 9pp
- 8007070011 Notifies that two Westinghouse plants w/reactor vessel internals similar to facility have experienced fuel rod damage due to water jetting through reactor vessel lower internals baffle gaps Notes Westinghouse recommendation CREWB, E H South Caroline Electric & Oss Co 80/07/01 2pp

- \$007080393 Notifies of delay in response to NRC B00618 ltr on underclad cracking in reactor vassel notiles Westinghouse info will not be available for approx 3 wks
 TREMB.E.H. South Carolina Electric & Gas Co. 80/07/02 ip
- 8007160252 Forwards add1 info re syc water intake structure in response to NRC 800623 request All load combinations & loads specified for reinforced concrete strength design satisfied CREWS.F H Bouth Carolina Electric & O
- B007170607 Forwards response to NRC 800630 ltr w/questions re secondary water chemistry control program FSAR amend will be filed in Aug 1980
 CREMB.E H South Carolina Electric & Gas Co 80/07/14 16pp
- --8007170612 "Chemistry Procedure CHP-612,Out-Df-Spec Handling & Reporting," Revision O LEACH,F J , CROLEY,B O Bouth Carolina Electric & Oas Co 80/03/27 17pp
- BO07220428 Forwards May 1980 status rept re NUREQ-0660 & NUREQ-0694 CREWS E H South Carolina Electric & Gas Co B0/07/18 70pp
- 8007250308 Forwards "Environ Exposure of Low Voltage Power Cable," to suppl response to FSAR Guestions 31 71-73 Rept withheld tref 10CFR2 790)
 CREWS,E H South Carolina Electric & Gas Co 80/07/21 1p
- 8007250491 Forwards Drawing R31E50290. Sheets 1-9, in response to FSAR electrical Question 31 67. Drawings withheld (ref 10CFR2 790)
 CREMB.E H South Carolina Electric & Gas Co 80/07/21 ip
- C Utility Environmental Report (ER), amends & correspondence
- 8007070269 Forwards Amend 5 to environ rept Certificate of Compliance encl CREMB.E H Bouth Carolina Electric & Oas Co 80/07/03 4pp
- F Security, medical, emergency & fire protection plans
- G007090050 Notification of 800722 & 23 meetings w/util in Jenkinsville, BC to roview facility emergency planning HOUGHTON.T C. Licensing Branch 2 80/06/23 3pp
- BOO7220390 Forwards Revision 1 to facility radiation emergency plan CREWB, E H South Carolina Electric & Gas Co 80/07/18 ip
- ---8007220392 Radiation emergency plan.Revision 1 * South Carolina Electric & Oas Co 80/07/18 200pp
- 6007290626 Forwards "Evacuation Time Estimates," in response to NRC 600702 request CREMB, E H South Carolina Electric & Oas Co 60/07/24 ip
- --8007290627 "Evacuation Time Estimates " Lexington, Fairfield & Neuberry Counties, 8C commente encl * South Carolina Electric & Qas Co 80/02/26 10pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp
- M Antitrust correspondence
- 8007020897 Hemorandum & order setting forth facts re General Electric Power Cooperative petition for significant changes determination under Atomic Energy Act, Requests Atty General assistance for final determination.

 CHILK.S J Office of the Secretary of the Commission 80/06/30 3200
- B007070223 Requests info to be provided within 10 days in response to Commission B00630 order, CLI-B0-28 Request does not relieve recipient from compliance w/order, Response must include competitive status since Dec 1978 & latest annual rept CHANANIA, F. D Antitrust Division. B0/07/08 2pp

- 8007090248 Requests info to be provided within 10 days in response to Commission 800630 order, CL1-80-28 Request does not relieve recipionts from compliance w/order Response must include competitive status since Dec 1778 & latest annual rept CHANANIA.F D Antitrust Division 80/07/08 Zpp
- B007090252 Requests info to be provided within 10 days, in response to Commission 8000630 order, CLI-80-28 Request does not relieve recipients from compliance w/order Response must include conjective status since Dec 1978 & latest annual rept CHANANIA.F D Antitust Division 80/07/08 2pp
- B007250485 Motion for 20-day extension to file comments BEENY,S T Central Electric Fower Cooperative. Inc. BEENY,S T Brand & Hall B0/07/24 2pp
- --B007250502 Affidavit stating that Brand & Hall has received 100,000 documents from 90 Electric & Gas Co Many documents relate to NC & SC cases & may include inconsistent info Certificate of Svc anc 15
 BRAND, W E Brand & Hall 80/07/23 4pp
- B007310424 Responds to B00708 request for info re B00630 memorandum & order Discusses St Clettric & Gas Co competitive relationship w/Central Electric Power Cooperative Inc Correspondence oncl
 CONNERT ID Conner, Moore & Corper B0/07/28 7pm
- G. Inspection reports. IE Bulletins & correspondence
- B007240220 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Desse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08 is
- 8007240222 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08 2pp
- 8007020170 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007020171 Forwards IE Info Notice 80-22. "Greakdowns In Contamination Control Programs " No written response required O'REILLY, J F Region 2, Atlanta, Office of the Director 80/05/28
- 8007210471 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fur! Assemblies " No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28 in
- 8007210472 Forwards IE Circular 80-13, "Grid Strap Damage in Mestinghouse Fuel Assemblies " No written response required D'REILLY, J P Region 2: Atlanta, Office of the Director 80/05/28
- 8007010242 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29 ip
- 8007010248 Forwards JE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 19 B0/05/29 19
- 8007220017 Forwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10
- B0072200B3 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director B0/06/10 Zpp
- 8007160281 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/06/11

- B007250378 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/IOCFR90 55(s) " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13
- B007250380 Forwards 1E Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director B0/06/13
- 8007020741 Forwards IE Builetin 80-19, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/18
- 8007020748 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/18
- 8007020381 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/20
- 8007020384 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/20
- B007160781 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLYJ P Region 2. Atlanta, Office of the Director 80/06/24
- BOO7160784 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required G'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/24 80/06/24
- 8007180256 Ack receipt of IE Insp Rept 50-395/80-14 No proprietary info JOHNSON,M C South Carolina Electric & Gas Co 80/06/24 1p
- --8007180265 Forwards IE Insp Rept 50-395/80-14 on 800513-14 No purposed formands is insp kept 30-373/80-14 on 3003/8-14 no noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/04 2pp
- --8007180275 IE Insp Rept 50-395/80-14 on 800513-16 No moncompliance UD/1802/5 (E Insp kept 30-393/80-14 on Bublid-16 No Hohompilance noted Major areas inspected instrumentation cables termination work & work activities termination quality records electrical components & sys quality records CONLON.T E Region 2. Atlanta, Reactor Construction & Engineering Support Dranch (1880NB, T D . MERRIHEATHER, N Region 2. Atlanta, Office of the Director 80/06/04 6pp
- 8007230213 Forwards LE Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/04/97
- B007230217 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/2 80/06/27
 - vonse to IE Bulletin BO-05 Action Items 1 & o plant atmosphere or lines Size of yent 1up Co 80/07/02 2pp

ied on

Брр

- 8007010499 Supplement 3 to Part 21 rept re failed thrust bearing, Insp. complete Crankshaft thrust bearings on two diesel generators are free of reported potential defect MORIARTY, J M Colt Industries, Inc., Fairbanks Morse Engine Div. 80/06/26
- 8007010357 Deficiency rept re possible improper rocker arm prelube pump operation Pump could fail to start as result of hydraulic lock in cylinder Instituting further review of other installation electrical schematics & instruction manuals MORIARTY, J M Colt Industries, Inc., Fairbanks Morse Engine Div. 80/06/27 2pp
- 8007250459 Final deficiency rept re diesel generator prelube oil gump continuous operation Pump controls will be revised to operate for short period of time each day Length of time to be determined by mfg CREWB,E H South Carolina Electric & Oas Co BO/07/21 4pp
- DOCKET 50-376 UNIV OF VIRGINIA CAVALIER REACTOR
- F Security, medical, emergency & fire protection plans
- 8007210429 Forwards physical security plan & proposed changes to Tech Specs Plan withheld (ref 10CFR2 790) SHRIVER, D i. Virginia, Univ of 80/07/15 2pp
- -8007210433 Tech Specs 3 3.4 1.4 2.4 8.6.2 & 6 3 re mafety limits.
 Ilmiting conditions for operation & surveillance requirements Virginia, Univ of 80/07/15 Ppp
- Q Inspection reports, IE Bulletins & correspondence
- B007170173 Forwards IE Circular B0-14, "Radicactive Contamination of Plant Demineralized Mater Sus & Resultant Internal Contamination of Personnel " No written response required. O'REILLY, J P Region 2. Atlanta, Diffice of the Director 80/04/24.
- DOCKET 50-997 MPRSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- B007030196 Forwards organization charts for Oft of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO,R L Assistant Director for Licensing 80/06/12. 2pp
- 8007010002 Forwards drawings in response to Round One, Set Eight, Questions 031 104 & 031 105 Control room panels revision status sheet encl RENBERGER D L Washington Public Power Supply System 80/06/16.
- ---8007010004 "Radwaste & Control 81dg Elevations 501 Ft & 507 Ft.Lighting Plan " * Burns & Ros Co 79/12/11 1p
- ---80070100D7 "Radwaste & Control Bldg Elevations 501 Ft & **507 Ft,Power** Conduit & Tray Plan " * Burns & Roe Co 80/04/16 1p
- --8007010018 "Radwaste & Control Bldg Elevations 501 Ft & **507 Ft,** Instrumentation & Control Conduit & Tray Plan * Sheet 1 * Burns & Roe Co = 80/06/11, 1p
- ---B007010021 "Radwaste & Control Bldg Elevations 501 Ft & 507 Ft, Instrumentation & Control Conduit & Tray Plan " Sheet 2, * Burns & Ros Co B0/06/12 Ip
- --8007010023 "Radwaste & Control Eldg Elevations 501 Ft & 507 Ft, Instrumentation & Control Conduit & Tray Plan " Sheet 3 * Burns & Roe Co = 80/04/16 Ip
- --8007010032 "Radwastr & Control Bldg Elevations 501 Ft & 507 Ft, Instrumentation & Control Conduit & Tray Plan " Bhest 4. * Burns & Roe Co 80/03/06 ip
- --8007010033 "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray " Sheet 1 * Burns & Roe Co 80/03/06 1p

- ---8007010041 "Radwaste & Control Bldg Cablo Tables, Instrumentation & Control Conduit & Tray " Sheet 3
 * Burns & Ros Co 80/03/24 1p
- ---B007010045 "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray." Sheet 4

 * Burns & Roe Co 60/03/24 1p
- -8007010049 "Radwaste & Control Bldg Cable Tables,Instrumentation & Control Conduit & Tray " Bheet 5 * Burns & Roe Co 80/03/24 lp
- -8007010032 "Radwaste & Control Bidg Cable Tables, Instrumentation & Control Conduit & Tray " Bheet 6 * Burns & Roe Co 80/03/24 ip
- -BOO7010054 "Radwaste & Control Bldg Cable Tables.Instrumentatioπ & Control Conduit & Tray " Sheet 7 * Burns & Roe Co = BO/03/12 ip
- ---800701005B "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray " Bheet B Burns & Roc Co 80/03/11 1p
- -8007010059 "Radwaste & Control Bldg Cable Tables,Instrumentation & Control Conduit & Tray," Sheet 9 * Burns & Roe Co 90/03/11, ip
- --8007010061 "Madwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray." Sheet 10 # Burns & Roc Co. 80/01/03 1p
- ---8007010064 "Radwaste & Control Bldg Cable Tables, Instrumentation & Control Conduit & Tray " Sheet ii * Burns & Ros Co 80/03/24 ip
- --B007010069 "Radwaste & Control Bldg Control Room & Remote Shutdown Room, Arrangaments, " Sheet 1 * Burns & Roe Co. 80/01/14 1p
- --- B007010073 "Radwaste & Control Room Arrangements Elevation 467 Ft " Sheet 2. # Burns & Ros Co. 80/03/24
- --- B007010076 "Balance of Plant Remote Shutdown Board (DD-R5) " Sheet RB1 of RS2 * Burns & Ros Co 75/08/08 1p
- --8007010090 "Engraving Remote Shutdown VB" # General Electric Co 75/06/30 1p
- --8007010095 "Engraving Remote Shutdown VS "
 # General Electric Co 75/05/12 ip
- Qeneral Electric Co 75/12/15 1p
- 8007030239 Natification of 800702 meeting w/BWR licensing review group in Bethesda.ND to discuss consensus position on reactor svc bldg open issue MILBON, J. N Licensing Branch 1 80/06/18 7pp
- 8007010297 Bummary of 800613 meeting w/utils.KMC. Inc. OE. Rechtel. S&W & Bargent & Lundy in Bethesda. MD re consensus positions on reactor syc blog & isolation cooling sys blog open issues from La Balle docket. Status repts encl
 HILSON, J N Assistant Director for Licensing 80/06/19 44pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0640 & found in NUREG-0694 EIBENHUT, D Q Division of Licensing 80/04/26 2pp
- 8007160511 Forwards comments re adequacy of site archaeological investigations & Bonneville Power Administration survey & teating along Asche-Blatt transmission routs CONDON, Q J Interior, Dept of 80/07/03 3pp

- 8007170339 Notification of B00702 meeting w/BWR licensing review group in Bethesda/MD to discuss consensus positions on Reactor Sys Branch upen issues Meeting rescheduled for 800709 WILBON. J N Assistant Director for Licensing H0/07/03 1p
- --8007170347 Notification of 800722 meeting w/BWR licensing review group in Bethesda.MD to discuss TMI issues required for OL issuance
 WILSON.J N Assistant Director for Licensing 80/07/03 ip
- ---8007170331 Notification of 800724 meeting w/BWR licensing review group in Bethesda-MD to introduce BWR licensing review group A present consensus positions for Power Sys Branch, Containment Sys Branch & Equipment Qualification Branch WILSON, J N Assistant Director for Licensing 80/07/03 9pp
- 8007230621 Summary of 800612 meeting w/Mark II cumers group in Bethesda.MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON.C J Generic Issues Branch 60/07/03 57pp
- B0071506B0 Requests meeting w/NRC to discuss containment hydrodynamic loads & chugging data becoming available from 4TCO tests RENBERGER, D.L. Washington Public Power Bupply System B0/07/10
- 8007230371 Forwards repts referenced in NRC 800602 Question 360 005 RENBERGER, D.L. Washington Public Power Supply System 80/07/11
- --B007290393 "Evaluation of Faulting in Warm Spring Canyon Area Southeast HA," Dec. 1979 Oversize drawings encl Prepared for HA Public Power Supply Sys FAROGOULS M Shannon & Wilson. Inc 79/12/31 28pp
- --B007250396 "Geologic Reconnaissance of Wallula Gap,WA Blue Mountains LaGrande.OR Region," Dec 1979 Oversize drawings & map encl Prepared for WA Public Power Supply Gys
 KIENLE,C F. HAMILL,M L., CLAYTON,D N. Ghannon & Wilson,Inc
 79/12/31 91pp
- --800725039# "Geologic Evaluation of Sciected Faults & Lineaments, Pasco & Walla Walla Basins, WA." May 1980 Oversize drawings encl Prepared for WA Public Power Supply Sys FAROGOUI, 6 M , THOMAS.R E Shannon & Wilson, Inc 80/05/31 45pp.
- --B007250400 "Seramological Review of 360716 Milton-Freewater Earthquake Source Region," Jan 1980 Prepared for WA Public Power Supply
 - Woodward-Clyde Consultants: Inc BO/01/31 64pp
- --8007250402 "Recent Spismicity of Hanford Region," Feb 1980 Prepared for MA Public Power Supply Sys * Woodward-Clyde Consultants, Inc. 80/02/29 98pp
- --8007250403 "Paleomagnetism & Age Dating." Jul 1978 Prepared for United Engineers & Constructors.inc # Woodward-Clyde Consultants. Inc 78/07/31 53pp
- 8007310409 Responds to Round One Questions. Set 9. Questions 211 049 -RENDERGER, D.L. Washington Public Power Supply System 80/07/11
- 8007210392 Ack receipt of NRC 800430 ltr approving request to discontinue certain aquatic monitoring & requesting copies of util submittals to Blate of WA re water quality NRC does not have authority to require water quality filings RENBERGER.D L Washington Public Power Supply System 80/07/14
- 8007230133 Notification of 800725 meeting w/BWR Licensing Review Group in Bethesda.MD to discuss concensus positions of BWR - Licensing Review Group on ICSB open issues HILSON,J N Licensing Branch 1 80/07/16 10pp
- 8007310447 Confirms 800718 telton re adequacy of work control & QA sys of mochanical contractor Wright Schuchart, Harbor, Boecon, GERI Litensee stop work directive will remain in effect until NRC has examined re-evaluation ENGELMEN, R H Region 5, San Francisco, Office of the Director 81/70/08 10

Adjudicatory correspondence

07310243 Forwards Commission 800527 memorandum & order containing ecisions on UCS 780502 petition for reconsideration of (80443 memorandum & order UCS 771104 petition sought action e fire protection for electrical cables ISENHUT, D G Division of Licensing 80/06/25 89pp

Inspection reports, JE Bulletins & correspondence

17250354 Responds to IE Bulletin 80-03, "Loss of Charcoal from 8td ype II.2-Inch Tray Adsorber Cells" Visual insp of adsorber ells tube installed in control room pneigency filter units of possible since delivery has not been made ENBERGER, D. L. Washington Public Power Supply System 80/03/18

7230003 Responds to 1E Bulletin 80-02 Marvin Engineering Co did not upply internal feedwater spangers or thermal sleeves for eactor pressure vessel at Unit 2 ENDERGER, D.L. Machington Public Power Supply System 80/04/28

7140097 Responds to S Meyers 800314 ltr to Genator Magnuson re Brown allegations dealing w/GC Rosults of investigation eviewed w/Brown on 800227 Since each inspector may look at arious code aspects, findings may differ TELLO, V Office of Inspection & Enforcement, Office of the irector 80/05/05 lp

007140098 Responds to DDE 800122 memo to NRC re R Brown 790821 & 0919 ltrs alleging faulty GC at site Reply will be made directly to Brown upon completion of investigation STELLO, V Defice of Inspection & Enforcement, Office of the Director 80/02/29 ip

307140102 Forwards response to R Brown 790919 ltr alleging faulty GC of site Investigation determined one allegation having no safety significance was substantiated Other allegation, having safety significance partially substantated DIRCKB.W J Office of the Executive Director for Operations 80/04/25 Bpp

71405B7 Forwards IE Bulletin BO-13, "Cracking in Core Spray largers " No written response required GELKEN, R E Region 5, San Francisco, Office of the Director)/05/12 ip

'220252 Forwards IC Info Notice 80-26, "Evaluation of Contractor Programs " No written response required BGELKEN, R H Region 9. San Francisco, Diffice of the Director '/06/10 ip

140414 Forwards IE Bulletin 80-14. "Degradation of BMR Scram scharge Vol Capability " No written response required GELMEN.R H Region 5. San Francisco. Office of the Director V06/12 Ip

300544 Reponds to IE Bulletin 80-09 re damage to chemical volutrol systems. Bulletin inapplicable since facility is R not PWR

NBERGER, D.L. Washington Public Power Supply System 80/04/12

290090 Forwards It Info Notice 80-28. "Frampt Reporting of Info in cordance W/100FR50 55(#)" No written response required OELKEN.R H Region 5. San Francisco. Office of the Director /06/13 ip

020466 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump oling & Natural Carculation Cooldown" No written response question of the Region 5. San Francisco. Office of the Director /06/20 1p

180299 Forwards IE Circular 80-14, "Radioactive Contamination of ant Demineralized Water 9ys % Resultant Internal abadination of Personnel " No written response required BELKEN.R H. Region 5, San Francisco, Office of the Director 06/24 ip

23040: Forwards IE Bulletin BO-16. "Potential Misapelication of semant Inc Models 1991 & 1952 Pressure Transmitters ither A or D Output Codes " Written response required Circular BO-16 also encl No written response required ELKENR H Region 5. San Francisco, Office of the Director, '06/27 1p

- 80072304iB Ack receipt of 800305 & 0611 ltrs informing NRC of steps taken to correct violations noted in IE Investigation Rept 50-397/79-10
 SPENCER.0 S. Region 4, Dallas, Reactor Construction & Engineering Support Branch
- --B007230623 Forwards revised response to violations noted in IE
 Investigation Rept 50-397/79-10 Transient analysis indicates
 math adjacent to weld & under heating blanket were not
 excessively overheated
 RENBERGER.D L. Washington Public Power Supply System 80/06/11
 200
- --8007230629 Forwards IE Investigation Rept 50-397/79-10 on 790917.0529-0601.11-14 & 0910-14 & notice of violation SPENCER.O S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/01/21 2pp
- --8007230632 Notice of violation from insp on 790517.0529-0601,11-14 & 0910-14 * Region 5. San Francisco, Office of the Director 80/01/21
- --B007230639 IE Investigation Rept 90-397/79-10 on 790517,0529-0601.11-14 & 0910-14 Noncompliance noted failure to qualify post-weld neat treatment procedure Procedures for equipment operations not provided
 BIGHUP,T W., HERNANDEZ, G. Region 5. Ban Francisco, Office of the Director DODDS, R. T. Region 5. Ban Francisco, Reactor Construction & Engineering Support Branch B0/01/21 Spp
- BOO7310171 Forwards status of flued head containment penetration welds in response to IE Bultetin BO-08 Work on flued heads covered by ASME code Completed welds examined radiographically Defects re incomplete fusion & surface porosity repaired RENBERGER.D L. Washington Public Power Bupply System BO/07/10 3pp
- 8007310498 Answers notice of proposed imposition of civil panalties dtd 800617 Majority of findings reflect deficiencies found by contractor.util & NRC Region 5 Encl Exhibit A details profests against imposition of certain proposed penalties 8TRAND,N 0 Washington Public Fewer Supply System 80/07/11 58pp
- BOO7310502 Provides response to notice of violation & request for addl info Outlines short-term intermediate & continuing phases of evaluations Supporting decimentation encl STRAND N O Washington Public Power Supply System BO/07/17 36pp
- S Reportable occurrences, LERs & related correspondence
- 8007290704 Interim deficiency rept re gaps & voids in sacrificial shiwld wall Corrective action plan described in 800620 ltr Implementation as pending NRC concurrence RENBERGER, D. L. Washington Public Power Supply System 80/07/23 2pp
- U Congressional/Executive Correspondence

B007210370 Discusses NRC B00617 issuance of Escalated Enforcement Act in form of penalty to util Interest expressed in correlation between schedule delays & cost overruns in rest of industry & financial ariangements similar to util WEAVER, J House of Pep 80/0//14 3pp

8007300367 Submits questions re unusual financing arrangement between util & Bonneville Power Administration Related correspondence WEAVER.J House of Rep. 80/07/14 2pp

DOCKET 50-400 SHEARDN HARRIB NUCLEAR POWER PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8007020427 Forwards computer magnetic tape of onsite meteorological data supporting FSAR Submitted in format described in DB Vassatle 790810 ltr Format description & tape dump of first 65 records encl Tape available in Central Files only MCDUFFIE.M A Carolina Power & Light Co 60/06/26 12pp
- 8007170628 Forwards FSAR,Vols i-20.amended OL application & environ rept for OL stage OL application only encl
 JONES.J A Carolina Power & Light Co 80/06/26 3pp
- --8007170639 Application for GL Annual financial rept & prospectus encl * Carolina Power & Light Co 80/06/26 99pp

- 8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694.
 EISENAUT.D G Division of Licensing 80/06/26 2pp
- 9007150535 Requests clarification of ANSI N45 2 10 as invoked by Reg DV/DUDGED REQUESTS CLATTRICATION OF ANNI NAD 2 10 AS INVOKED Quide 1 74.as to whether or not certificates of conformance, certificates of compliance & certified test repts must contain longhand signature
 HEODUFFIEM A Carolina Power & Light Co B0/07/09 1p
- BOOT220456 Forwards schedules of const milestones & activities as of 800630 Milestone network schedule will be affected by 800618 revisions in schedule Fuel leading for Units i & 2 will be delayed 1 yr & Units 3 & 4 delayed 3 yrs HCDRFFIE.H A Carolina Power & Light Co 80/07/11 13pp
- C. Utility Environmental Report (ER), amends & correspondence
- 8007170652 Forwards FSAR.Vols 1-20.amended OL application & environ rept for OL stage Environ rept only encl JONES, J A Carolina Power & Light Co 80/06/26 3pp
- ---8007170663 Environ rept for facility.Vol 1 * Carolina Power & Light Co 80/06/26 350pp
- --8007170678 Environ rept for facility, Vol 2 & Carolina Power & Light Co 80/06/26 300pp
- -8007170686 Environ rept for facility, Vol 3 a Carolina Power & Light Co. 80/06/26 300pp
- # Security, medical, amorgoncy & fire protection plans
- 8007010332 Forwards industrial security safeguards contingency & security personnel training & qualification plans for review Plans withheld (ref 10CFR2 790) JONEG, J.A. Carolina Power & Light Co 80/06/26 2pp
- O Adjudicatory correspondence
- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 9 Division of Licensing 80/06/25 87pp.
- H General correspondence
- 8007020198 Responds to 800515 ltr re Kudzu Alliance concerns about 007020198 Responds to MEMOID ITT TO NUTTO ALLIANCE CONTROL BABILITY OF UTILITY OF UTILITY OF THE NUTL OF THE POWER THE MEMOID ALLIANCE CONTROL OF THE MEMOID OF THE MEMOID OF THE MEMOID OF THE POWER OF THE EXECUTIVE DIRECTOR OF
- ---8007020217 Requests response to entl Kudzu Alliance 800512 ltr commenting on ability of util to safely utilize nuclear power ANDREWS, I House of Rep 80/05/16 2pp
- K Utility Final Safety Analysis Report (FBAR) & amonds
- 8007170366 Forwards FSAR.Vols 1-20.amended DL application & environ tept for DL stage Only FBAR encl JONES, J. A. Carolina Power & Light Co 80/04/26 3pp
- ---8007170367 FSAR, Vols 1-20 * Carolina Power & Light Co 80/06/26 7800pp
- 9007170372 Chapter 1 to Shearon Harris 1.2.3 & 4 FSAR. "Introduction & General Description of Plant"

 * Carolina Power & Light Co 60/06/26 500pp
- 8007170377 Chapter 2 to Shearon Harris 1.2.3 & 4 FSAR, PSite Characteristics " * Carolina Power & Light Co 80/06/26 700pp
- B007170541 Chapter 3 to Bhearon Harris 1.2.3 & 4 FSAR. "Design of Structures: Components, Equipment & Bys " # Carolina Power & Light Co 80/06/26 700pp
- 8007170572 Chapter 4 to Shearon Harris 1,2,3 & 4 FSAR, "Reactor "
 Carolina Power & Light Co 80/06/26 200pp

- 8007170578 Chapter 5 to Shearon Harris 1.2.3 & 4 FSAR, "RCS & Connected
 - Sys " * Carolina Power & Light Co 80/06/26
- 8007170594 Chapter & to Shearon Harris 1.2.3 & 4 FSAR. "Engineered * Carolina Power & Light Co 80/05/26 550pp
- 8007170600 Chapter 7 to Shearon Harris 1.2.3 & 4 FSAR, "Instrumentation & Controls " * Carolina Power & Light Co 80/06/26 500pp
- 8007170515 Chapter B to Bhearon Harris 1, 2, 3 % 4 FSAR, "Electric
- Carolina Power & Light Co 80/06/26 125pp
- 8007170627 Chapter 9 to Shealon Harris 1.2.3 & 4 FSAR. "Auxiliary Sys "
 * Carolina Power & Light Co 80/06/26 700pp
- 8007170643 Chapter 10 to Shearon Harris 1,2,3 & 4 FSAR, "Steam & Power Conversion Sys " * Carolina Power & Light Co 80/06/26 150pp
- 8007170650 Chapter i1 to Shearon Harris i, 2, 3 & 4 FSAR. "Radwaste Mgt " * Carolina Power & Light Co 80/06/26 175pp
- 8007170655 Chapter 12 to Shearon Harris 1,2,3 & 4 FSAR, "Radiation otection " Carolina Power & Light Co 80/06/26 200pp
- 8007170661 Chapter 13 to Shearon Harris 1,2.3 & 4 FSAR, "Conduct of
- Carolina Power & Light Co 80/06/26 250pp
- 8007170672 Chapter 14 to Shearon Harris 1,2,3 & 4 FSAR. "Initial Test * Carolina Power & Light Co. 80/06/26 75pg
- 8007170677 Chaster 15 to Shearon Harris 1.2.3 & 4 FBAR. "Accident
- alysis " Carolina Power & Light Co 80/06/26 400pp
- 8007170684 Chapter 16 to Shearon Harris 1.2.3 & 4 FSAR, "Tech Specs" * Carolina Power & Light Co 80/06/26 500pp
- 8007170687 Chapter 17 to Shearon Harris 1.2.3 t 4 FGAR. "GA "
 * Carolina Power & Light Co 80/06/26 37pp
- 8007170690 App 1 to Shearon Harris 1,2,3 & 4 FSAR, "TMI "
 # Carolina Power & Light Co 80/06/26 37pp
- G Inspection reports, IE Bulletins & correspondence
- B007240113 Forwards lE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007210422 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies "No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director
- B007010179 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director B0/05/29
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/10
- 8007160223 Forwards IE Info Notice 80-27, "Degradation of Reactor Coplant Pump Studs " No specific action or response required O'REJLLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007250339 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/13

- 307100297 Ack receipt of IE Insp Repts 50-400/80-13, 30-401/80-11, 30-402/80-11 & 50-403/80-11 on 800513-16 No preprietary
- HOWE, P W Carolina Power & Light Co 80/05/15 19
- B007100301 Forwards IE Insp Repts 50-400/80-13, 50-401/80-11, 50-402/80-11 & 50-403/80-11 on B00513-16 & notice of violation MURPhy, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/05 2pp
- 8007100305 Notice of violation from insp on 800513-16 Region 3, Chicago, Office of the Director 80/00 80/04/05 10
- 8007100313 IE Insp Repts 50-400/80-13,50-401/80-11,50-402/80-11 & 50-403/80-11 on 800513-16 Noncompliance noted tack welds
- deposited over heavy rust HERBY, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINSORGE, W P Region 2, Atlanta, Office of the Director BO/O6/05 9pp
- 107020440 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response
- required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 07100412 Ack receipt of 800609 ltr informing NRC of steps taken to entrect violation noted in IE Insp Repts 50-400/80-11, 50-401/80-08, 50-401/80-08, 50-401/80-08 MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch -60/06/23 lp
- B007100416 Responds to NRC B00513 ltr re violation noted in IE Insp Repta 30-400/80-11.50-401/80-08.50-402/80-08 & 50-403/80-08 Corrective actions investigation held of collected test data re backfill math affecting Cotagory I piping HOME,P W Carolina Power & Light Co B0/06/05 3pp
- 1007100422 Ack receipt of 1E Insp Repts 50-400/80-11.50-401/80-08, 50-402/80-08 & 50-403/80-08 on 800422-24 No proprietary HOWE,P W Carolina Power & Light Co 80/05/22 ip.
- 9007100428 Forwards IE Insp Repts 50~400/80-11,90-401/80-08, 50~402/80-08 & 50~403/80~08 on 800422-24 & notice of violation

 WURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering

 Busbort Branch 80/05/13 2pp
- 3007100430 Notice of violation from insp on 800422-24 * Region 2, Atlanta, Dffice of the Director 80/0 RO/05/12 1p
- 3007100435 IE Imap Repts 50-400/80-11.50-401/80-08.50-402/80-08 & 50-403/80-08 on 800482-24 Noncompliance noted failure to consider offect of backfill settlement analysis of Category I piping
 CONLON.T F Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch LENAHAN, J Fegion 2, Atlanta, Office of the
 Director 80/05/12 App
- 7150000 Forwards IE Circular 80-14. "Radioactive Contamination of lant Deminoralized Water Sys & Resultant Internal antamination of Personnel " No written response required "REILLY. J P Peyton 2. Atlanta, Office of the Director 80/06/20 80706724
- 7230220 Forwards IE Bulletin BO-16. "Potential Misapplication of Damount Inc Models 115% & 1152 Pressure Transmitters /Either A or D Output Codes" Written response required E Circular BO-16 also encl No written response required 'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/2 80/04/27
- 7220210 Responds to IE Dulletin 80-08 Review of containment liner enetration would designs verified by applicable drawings, alds not complete as plant is under const CDUFFIE.M A Carolina Power & Light Co 80/07/02 2pp
- Periodic operating reports & related correspondence
- 728050/ Forwards "Quarterly Data Ropt, Shearon Harris Nuclear Power lant Monitoring Program, Api-June, 1980" CDUFFIE, M. A. Carolina Power & Light Co. 80/07/21 ip
- 007280513 "Quarterly Data Rept. Shearon Harris Nuclear Power Plant Monitoring Program, Apr-June 1980 * Caroline Power & Light Co 80 80/07/21 ip

- S Reportable occurrences, LERs & related correspondence
- 8007080249 Forwards final deficiency mept me omission of addl meinforcing steel in Unit i containment bldg exterior wall adjacent to const opening for equipment hatch CHIANOI,N J Carolins fower & Light Co. 80/06/30 ip
- --B0070B0287 Final deficiency rept re omission of add1 reinforcing steel in Unit 1 containment bldg exterior wall adjacent to const opening for equipment hatch Design review & mod to steel completed Craft work & insp procedures revised \$ Carolina Power & Light Co 80/06/24 3pp
- 8007140377 Interim deficiency rept re significant failure of reactor protection sys following main feedline break Hestinghouse has indicated corrective action cannot be completed before Dec 1981 Final rept will be issued upon completion CHIANGI.N J Carolina Power & Light Co 80/07/08, 1p
- 8007230247 Part 21 rept re lack of stud base qualification for angle arc shield Evaluation will be completed by 801001 CHIANGI.N J Carolina Power & Light Ca 80/07/11 2pp
- V Operator Examinations
- B0071B042B Requests review & concurrence w/Senior Reactor Operator Certification program & retraining program per HR Denton B0032B ltr Certification program effective B00630 Retraining effective in 1981 Description of both programs encl COLLING.J M Carolina Power & Light Co 80/06/23 5pp
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007020427 Forwards computer magnetic tape of onsite meteorological data supporting FSAR Submitted in format described in DB Vassatlo 790810 ltr.Format description & tape dump of first 65 records encl Tape available in Central Files only MCDUFFIE.M A Carolina Power & Light Co 80/06/26 12pp
- B007i70628 Forwards FSAR.Vols 1-20.amended DL application & environ rept for GL stage OL application only encl JONES.J A Carolina Power & Light Co 80/06/26 3pp
- -8007170639 Application for DL Annual financial rept & prospectus encl, * Carolina Power & Light Co 80/06/26 99pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUMEQ-0660 & found
- B007190535 Requests clarification of ANSI N45 2 10 as invoked by Reg Guide 1 74.as to whether or not certificates of conformance, certificates of compliance & certified test repts must contain longhand signature MCDUFFIE.H A Carolina Power & Light Ca 80/07/09 1p
- 8007220456 Forwards schedules of const dilestones & activities as of 800630 Milestone network schedule will be affected by 800618 revisions in schedule Fuel loading for Units 1 & 2 will be delayed 1 yr & Units 3 & 4 delayed 3 yrs MCDUFFIE.H A Carolina Power & Light Co 80/07/11 13pp
- C Utility Environmental Report (ER), amends & correspondence
- B007170692 Forwards FSAR.Vols 1-20.amended OL application & environ rept for DL stage Environ rept only encl
 JONES.J A Carolina Pawer & Light Co B0/06/26 3pp
- ---8007170663 Environ rept for facility, Vol 1 * Carolina Power & Light Co 80/06/26
- --8007170678 Environ rept for facility, Vol 2 * Carolina Power & Light Co 80/06/26 Эоорр
- ---8007170686 Environ rept for facility, Vol 3
 * Carolina Power & Light Co 80/04/26

- F. Security, medical, emergency & fire protection plans
- 8007010352 Forwards industrial security safeguards contingency & security personnel training & qualification plans for review Plans withheld (ref 10CFR2 790)
 JONES J A Carolina Power & Light Co 80/06/26 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 patition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for alectrical cables EIBENHUT, D 9 Division of Licensing 80/06/25 89pp
- H Ceneral correspondence
- 8007020198 Responds to 800516 ltr re Kudzu Alliance concerns about ability of util to safety utilize nuclear power NRC monitors Shearon Harris const to assure conformance w/requirements Levels of contamination from Brunswick no threat to public DIRCKB.W J Office of the Executive Director for Operations 80/06/18 2pp
- ---BOO7020217 Requests response to encl Kudiu Alliance 800512 ltr commenting on ability of util to safely utilize nuclear power ANDREWS, I House of Rep 80/05/16 2pp
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8007170366 Forwards FSAR.Vols 1-20.amended OL application & environ rept for OL stage Only FSAR encl JONES.J A Carolina Power & Light Cr 80/06/26 3pp
- G007170372 Chapter 1 to Bhoaron Harris 1,2,3 & 4 FSAR, "Introduction & General Description of Plant"

 * Caroline Power & Light Co 80/06/26 500pp
- 8007170377 Chapter 2 to Shearon Harris 1.2.3 & 4 FSAR, "Site Characteristics " & Carolina Power & Light Co 80/06/26 700go
- 8007170541 Chapter 3 to Shearon Harris 1,2,3 % 4 FSAR, "Design of Structures, Components, Equipment & Sys "

 e_ Caroline Power & Light Co 80/06/26 700pp
- 8007170372 Chapter 4 to Shearon Harris 1,2,3 & 4 FSAR, "Reactor " 9 Carolina Power & Light Co 80/06/26 200pp
- 8007170578 Chapter 5 to Shearon Harris 1,2,3 % 4 FSAR, "RCS & Connected 8ys = * Carolina Power & Light Co 80/06/26 175pp
- 8007170394 Chapter 6 to Sheeron Harris 1.2.3 & 4 FBAR. "Engineered Safety Features"

 * Carolina Power & Light Co 80/04/26 650pp
- 8007170400 Chantan 7 to Sheavan Harris t.D.S & A ESAD.
- 8007170600 Chapter 7 to Shearon Harris 1,2,3 & 4 FSAR, "Instrumentation & Controls " # Carolina Power & Light Co 80/06/26 500pp
- 8007170615 Chapter B to Shearon Harris 1.2.3 & 4 FSAR, "Electric Pumer." * Carolina Power & Light Co 80/06/26 125pp
- 8007170627 Chapter 9 to Shearon Harris 1,2.3 & 4 FSAR, "Auxiliary Sys." * Carolina Power & Light Co. 80/06/26 700pp
- 8007170643 Chapter 10 to Shearon Harris 1,2,3 & 4 FSAR, "Steam & Power Conversion Sys" " Carolina Power & Light Co 80/06/26 150pp
- 8007170650 Chapter 11 to Shearon Harris 1,2,3 & 4 FSAR. "Radwaste Mgt "
 * Caroline Power & Light Co 80/06/26 175pp
- 8007170655 Chapter 12 to Shearon Harris 1.2.3 & 4 FSAR. "Radiation Protection." * Carolina Power & Light Co 80/06/26 200pp

- B007170661 Chapter 13 to Shearon Harris 1, 2, 3 & 4 FSAR, "Conduct of Operations" # Carolina Power & Light Co 80/06/26 250pp
- 8007170672 Chapter 14 to Shearon Harris 1.2.3 & 4 FSAR. "Initial Test
- Program " * Carolina Power & Light Co BO/06/26 75pp
- 8007170677 Chapter 15 to Shearon Harris 1,2,3 & 4 FSAR, "Accident
- * Carolina Pawer & Light Co 80/06/26 400pp
- 8007170684 Chapter 16 to Bhearon Harris 1.2.3 & 4 FSAR. "Tech Specs" * Carolina Power & Light Co 80/06/26 500pp
- 8007170687 Chapter 17 to Shearon Harris 1.2,3 & 4 FSAR, "GA" * Carolina Power & Light Co 80/06/26 37pp
- B007170690 App i to Shearon Harris 1.2.3 & 4 FSAR. "TMJ" * Carolina Power & Light Co B0/06/26 37pp
- O Inspection reports. IE Bulletins & correspondence
- 8007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007210422 Forwards IE Circular 80-13, "Grid Strap Damage in Hustinghouse Fuul Assemblies " No written response required, O'REILLY J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010179 Forwards IE Info Notice 80-23, "Loss of Suction to Emergen Faedwater Pumps " No written response required O'REILLY. J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 200
- 8007160223 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude," No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007250339 Forwards IE Info Notice 80-28, "Prompt Reporting of Info i Accordance W/10CFR50 55(e) " No written response required D'REILLY, J P Region 2, Atlanta, Defice of the Director 80/04/13 200
- 8007100297 Ack receipt of IE Insp Repts 50-400/80-13, 50-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 No preprietary infa HOME.P W Carolina Power & Light Co 80/06/16 1p
- --B007100301 Forwards 1E Insp Repts 50-400/80-13:50-401/80-11:50-402/80-11 & 50-403/80-11 on 600013-16 & notice of violation MURPHY, C E Region 2: Atlanta. Reactor Construction & Engineerin Buyport Branch B0/06/05 2pp
- --8007100305 Notice of violation from insp on 800513-16 * Region 3. Chicago, Office of the Director 80/06/05 ip
- --B007100313 IE Insp Repts 50-400/60-i1,50-401/80-11,50-402/80-11 & 50-403/80-11 on 600313-16 Noncompliance noted tack welds deposited over heavy rust HERDT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch KLEINBORGE W P Region 2, Atlanta, Office of th Director 60/06/05 9pp
- 8007020440 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump, Cooling & Natural Circulation Cooldown" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007100412 Ack receipt of 800605 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/80-11. SO-401/80-08. SO-402/80-08 to 50-403/80-08 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 60/06/23 ip

- -8007100418 Responds to NRC 800513 ltr re violation noted in IE Insp Repts 50-400/80-11,50-401/80-08,50-402/80-08 & 50-403/80-08 Corrective actions investigation held of collected test data re backfill matl affecting Category I piping HDME,P W Carolina Power & Light Co 80/06/05 3pp
- -8007190422 Ack receipt of 1E Insp Repts 50-400/80-11,50-401/80-08, 50-402/80-08 % 50-403/80-08 on 800422-24 No proprietary info HOME,P W Carolina Power & Light Co 80/05/22 lp
- -8007100428 Forwards IE Insp Repts 50-400/80-11,50-401/80-08, 50-402/80-08 & 50-403/80-08 on 800422-24 & notice of violation MURPHY.C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/13 2pp
- -8007100430 Notice of violation from insp on 800422-24

 * Region 2, Atlanta, Office of the Director 80/05/12 ip
- -8007100435 IE Insp Repts 50-400/60-11.30-401/80-08.50-402/80-08 & 50-403/80-08 on 800422-24 Noncompliance noted failure to consider effect of backfill settlement analysis of Category I piping CONLON.TE Region 2, Atlanta, Reactor Construction & Engineering Support Branch LENAHAN.J J Region 2, Atlanta, Office of the Director 80/05/12 App
- 007160800 Forwards IE Circular 80-14, "Redicactive Contamination of Plant Demineralized Water 89s & Resultant Internal Contamination of Personnel " Nu written response required O'REILLY, J.P. Region 2, Atlants. Office of the Director 80/06/24
- J07230220 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 to 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also each No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/27
- J07220210 Respands to IE Bulletin 80-08 Review of containment liner penetration weld designs verified by applicable drawings Helds not complete as plant is under const MCDUFFIE, H A Carolina Power & Light Co 80/07/02 2pp
- Periodic operating reports & related correspondence
- 107280507 Forwards "Guarterly Data Rept.Shearon Harris Nuclear Power Plant Monitoring Program. Apr-Jung. 1980" MCDUFFIE,M Λ Garolina Power & Light Co 80/07/21 1p
- 8007280513 "Guarterly Data Rept, Shearon Harris Nuclear Power Plant Monitoring Program, Apr-June 1980 " * Carolina Power & Light Co 80/07/21 1p
- Reportable occurrences, LERs & related correspondence
- NOTIAO377 Interim deficiency rept re significant failure of reactor protection sys following main feedline break Westinghouse has indicated corrective action rannot be completed before Dec 1981 Final rept will be issued upon completion CHIANGI.N J Carolina Power & Light Co 80/07/08 ip
- 107230247 Part 21 rept re lack of stud base qualification for angle arc shield Evaluation will be completed by 801001 CHIANGI N J Carolina Power & Light Co 80/07/11 2pp
- Operator Examinations
- 07180428 Requests review & concurrence w/Senior Reactor Operator Certification program & retraining program per HR Denton 800328 ltr Certification program effective 800630 Retraining effective in 1781 Description of both programs encl COLLINS, J M Carolina Power & Light Co 80/06/23 5pp
- CMET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

 Application/construction stage ducuments & correspondence
- O7020427 Forwards computer magnetic tape of ensite meteorological data supporting FSAR Submitted in format described in DB Vassatle 790810 ltr Format description & tape dump of first 55 records encl lape available in Central Files only MCDUFFIE.M A Carolina Power & Light Co 80/06/26 12pp

- 8007170628 Forwards FSAR,Vols 1-20,amended CL application & environ rept for CL stage CL application only encl JONES,J A Carolina Power & Light Co 80/06/26 3pp
- --8007170639 Application for OL Annual financial rept & prospectus encl.
 * Carolina Power & Light Co 80/06/26 99pp
- 8007230001 Forwards statement of policy re requirements to be est for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EIBENHUT.D G Division of Licensing 80/06/26 2pp
- 8007150535 Requests clarification of ANSI N45 2 10 as invaked by Reg Ouide 1 74, as to whether or not certificates of conformance, certificates of compliance & certified test repts must contain longhand signature MCDUFFIEM A Carolina Power & Light CO 80/07/09 1p
- 8007220456 Forwards schedules of const milestones & activities as of 800630 Milestone network schedule will be affected by 800648 revisions in schedule Fuel loading for Units 1 & 2 will be delayed 1 yr & Units 3 & 4 delayed 3 yrs MCDUFFIE,M A Carolina Power & Light Co 80/07/11 13pp
- C Utility Environmental Report (ER), amends & correspondence
- 8007170652 Forwards FSAR, Vols 1-20, amended OL application & environ rept for OL stage Environ rept only encl JONES, J A Carolina Power & Light Co 80/06/26 3pp
- ---8007170669 Environ rept for facility.Vol 1 * Carolina Power & Light Co 80/06/26 350pp
- ---8007170678 Environ rept for facility.Vol 2 * Carolina Power & Light Co 80/06/26 300pp
- --8007170686 Environ rept for facility.Vol 3 * Carolina Power & Light Co 80/06/R6 300pp
- f Security, medical, emergency & fire protection plans
- 8007010332 Forwards industrial security safeguards contingency & security personnel training & qualification plans for review Plans withheld (ref 10CFR2 790) JONES, J A Carelina Power & Light Co 80/04/26 2pp
- Q Adjudicatory correspondence
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIGENHUT.D & Division of Licensing 80/06/25 E9pp
- H General correspondence
- 8007020198 Responds to 800516 ltr re Kudzu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearen Harris const to assure conformance w/requirements Levels of contamination from Brunswick no threat to public, DIRCKS, H J Office of the Executive Director for Operations 80/06/18 2pp
- --8007020217 Requests response to encl Kudzu Alliance 800512 ltr commenting on ability of util to safely utilize nuclear pawer ANDREWS, I House of Rep 80/05/16 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007170366 Forwards FBAR.Vols 1-20.amended CL application & environ rept for CL stage Only FBAR encl
 JDNES.J A Carolina Power & Light Co 80/06/26 3pp
- --8007170347 FBAR, Vols 1-20 * Carolina Power & Light Co 80/04/24 7800pp
- 8007170372 Chapter 1 to Shearon Harris 1.2.3 & 4 FBAR. "Introduction & General Description of Plant "

 * Carolina Power & Light Co 80/06/26 500pp
- B007170377 Chapter 2 to Shearon Harris 1,2,3 % 4 FBAR, "Site Characteristics " * Carolina Power & Light Co B0/06/26 700pp

- 6867170341 Chapter 3 to Shearon Harris 1.2.3 & 4 FSAR, "Design of ructures, Components, Equipment & Sys " Carolina Power & Light Co 80/06/26 700pp
- 8007170572 Chapter 4 to Shearon Harris 1.2.3 & 4 FSAR. "Reactor" Carolina Power & Light Co 80/06/26 200pp
- B007170578 Chapter 5 to Shearon Harris 1,2,3 & 4 FBAR, "RCS & Connected Carolina Power & Light Co 80/06/26 175pp
- 8007170594 Chapter 6 to Shearon Harris 1,2,3 & 4 FSAR, "Engineered Safety Features "
 # Carolina Power & Light Co 80/06/26 650pp
- B007170600 Chapter 7 to Shearon Harris 1.2.3 & 4 FSAR.
 "Instrumentation & Controls "
 Carolina Power & Light Co 80/06/26 500pp
- 8007170615 Chapter 8 to Shearon Harris 1,2,3 & 4 FSAR, "Electric Power " * Carolina Power & Light Co 80/06/26 125pp
- 8007170627 Chapter 9 to Shearon Harris 1.2.3 & 4 FBAR. "Auxiliary Sys" # Carolina Power & Light Co 80/06/26 700pp
- 9007170443 Chapter 10 to Shearon Harris 1,2,3 & 4 FSAR, "Steam & Power Conversion Sys " * Carolina Power & Light Co 80/06/26 150pp
- 8007170650 Chapter 11 to Bhearon Harris 1.2,3 & 4 FSAR. "Radwaste Mgt " * Carolina Power & Light Co 80/06/26 175pp
- 8007170655 Chapter 12 to Shearon Harris 1, 2, 3 & 4 FSAR, "Radiation Carolina Power & Light Co 80/06/26 200pp
- 8007170661 Chapter 13 to Shearon Harris 1, 2, 3 & 4 FSAR. "Conduct of Carolina Power & Light Co 80/06/26 250pp
- 8007170672 Chapter 14 to Shearon Harris 1, 2, 3 & 4 FSAR, "Initial Test * Carolina Power & Light Co 80/06/26 75pp.
- 8007170677 Chapter 15 to Shearon Harris 1.2.3 & 4 FSAR. "Accident
- nalysis." Garolina Power & Light Co 80/06/26 400pp
- 8007170684 Chapter 16 to Shearon Harris 1.2.3 & 4 FBAR. "Tech Specs" * Carolina Power & Light Co 80/06/26 500pp
- 8007170687 Chapter 17 to Shearon Harris 1, 2, 3 & 4 FSAR, "GA" * Carolina Power & Light Co 80/06/26 37pp
- 8007170490 App 1 to Shearon Harris 1,2,3 & 4 FSAR. "TM1 " * Caralina Power & Light Co 80/04/26 37pp
- Q Inspection reports, IE Bulletine & correspondence
- 8007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08
- 8007210422 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fual Assemblies " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director (80/05/28
- 9007010179 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required, O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 6007220043 Forwards 16 Info Notice 80-26, "Evaluation of Contractor GA Programs "No written response required O'REILLY.J.P. Region 2. Atlanta. Office of the Director 80/06/10

- 8007160223 Forwards IE linfo Notice 80-27, "Degradation of Reactor Contant Pump Stude " No specific action of response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director (10/06/11
- 8007250339 Forwards 1E Info Notice 80-20, "Prompt Reporting of Info in Accordance W/10CFR90 55(e)" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/13
- 8007100297 Ack receipt of IE Insp Repts 50 400780-13,40-401780-11, 50-402780-11 & 50-403780-11 on 800513-16 No propiletary HOWE.P W Carolina Power & Light Co 80/06/16 Lp
- --8007100301 Forwards IF Insp Repts 50-400/80-1.), 50-401/80-11. 50-402/80-11 & 50-403/80-11 on B00517-16 & notice of TO-MORROWS A REGION 2, Atlanta, Reactor (onstruction & Engineering Support Branch 80/06/05 2pp
- ---8007100305 Notice of violation from insp nn 800510-14 * Region 3, Chicago, Office of the Director 80/06 00/06/00 10
- ---8007100313 IE Insp Repts 50-400/80-11.50-401/80-11.50-402/80 11 & 50-403/80-11 on 800513-16 Noncompliance noted task wolds deposited over heavy rust HERDIAR Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch KLEINBORGE WP Region 2, Atlanta, Office of th Director BO/05/05 9pp Region 2. Atlanta, Office of the
- 8007020440 Forwards 1E Circular H0-15, "Loss of Reactor (colant Pump Cooling & Natural Circulation Cooldown " No written response D'REILLY, J.P. Region 2, Atlanta, Office of the Director 10/06/20
- B007100412 Ack receipt of 800605 ltr informing NRC of steps taken to correct violation noted in IE Imag Repts 50-400/(IO-11, 50-401/06-0B; 50-402/(IO-0B) MURPHY.C E Re Bupport Branch Region 2. Atlanta. Reactor Construction & Engineering th 80/06/23 ip
- ---8007100418 Responds to NRC 800913 ltr re violation noted in It Insp.
 Repts 50-400780-11,50-401780-08,50-402780-08 & 50-403780-08
 Corrective actions investigation held of collected test
 data re backfill math affecting Cutegory I piping
 HOME,P W Carolina Power & Light Co. 80706709 3pp
- ---8007100422 Ack receipt of IC Inap Repts 50-400/H0 11.70-401/H0 08.50-402/80-08 & 50-403/H0-08 on 800427-24 No proprietory HOWELP W Carelina Power & Light Co 80/05/22
- --8007100428 Forwards IE Insp Repts 50-400/80-11,30-401/80 08, 50-402/80-08 & 50-403/80-08 on 800422-24 & notice of violation
 MURPHy.C C Region 2, Atlanta, Reactor Construction & Engineering
 Support Branch 80/05/13 Ppp
- --8007100430 Notice of violation from insp on 600422 24 * Region 2, Atlanta, Office of the Director (074 80705712 In
- --8007100435 IE Insp Repts 50-400/BO-11:50 401/H0 (BL 40-402/BO (B & 50-403/BO-08 on 800422-24 Noncompliance noted foilure to consider effect of backfill settlement analysis of (atogory CONLONIT C Region 2. Atlanta, Reactor (onativition & Engineering Support Branch LENAHAN, J.) Region 2. Atlanta, Office of the Director 80/05/12 App
- 8007160800 Forwards IE Circular H0-14 "Radinactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel" No weither response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/64/24 B0/04/24
- B007230220 Forwards 1E Bulletin flo-14. "Putintial Hisapplication of Resemburt Inc Models 1151 & 1159 Pressure Transmittors, W/Either A or D Dutput Codes." Written response required IE Circular 80-16 also until No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 60/04/2 60/06/27
- B007220210 Responds to IC Bulletin 80-00 Review of containment liner penetration weld designs verified by applicable drawings Welds not complete as plant is under const MCDUFFIE, H A Carolina Power & Light (a) 80/0//02 2pp

eriodic operating reports & related correspondence

280907 Forwards "Quarterly Data Rept, Shearon Harris Nuclear Power ant Monitoring Program Apr.,June,1980" DUFFIE,M A Carolina Power & Light Co 80/07/21 ip

00/280513 "Guarterly Data Rept.Shearon Hairis Nuclear Power Plant Monitoring Program Apr-June 1780 " * Carolina Power & Light Co 80/07/21 ip

Reportable occurrences, LERs & related correspondence

716037/ Interim duficiency rept re significant failure of reactor retection sys following main feedling break Westinghouse is indicated corroctive action cannot be completed before to 1981 Final rept will be issued upon completion HANGLAN J. Carolina Power & Light Co. 80/07/08 ip

7230247 Part 21 rept re lack of stud base qualification for angle c shield Evaluation will be completed by 801001 NANOI,N J Carolina Power & Light Co 80707/11 2pp

Jperator Examinations

/180428 Requests review & concurrence w/Senior Reactor Operator ortification program % retiaining program per HR Denton 20080 ltr Certification program effective BOOSOO Retraining ffective in 1981 Description of both programs encl 2LLINS,J M Carolina Power & Light Co BO/06/23 Spp

ET 50-403 BHEARDN HARRIS NUCLEAR POWER PLANT, UNIT 4 pplication/construction stage documents & correspondence

702042/ Forwards computer magnetic tape of onsite meteorological ta supporting FSAR Bubmitted in format described in 4 Vassatin 790810 ltr Format description & tape dump of ret 65 records encl Tape available in Central Files only TDUFFIF.M A Carolina Power & Light Co 80/06/26 12pp

170628 Forwards FSAR.Vols 1-20.amended OL application & unviron .pt for OL stage OL application only encl NEG.J A Carolina Power & Light Co 80/06/26 3pp

107170639 Application for DL Annual Financial rept & prospectus encl * Carolina Power & Light Co. 80/06/26. 99pp

230001 Forwards statement of policy re requirements to be met for prent OL applications as derived from NUREG-0660 & found NUREG-0694

EENHUT, D 0 Division of Licensing 90/06/26 Epp

i905.95 Requests clarification of ANSI N45 2 10 as invoked by Reg pido 1 74, as to whether or not cortificates of conformance, prtificates of compliance & certified test repts must putain langhand signature PUFFIF.M A Corolina Power & Light Co 80/07/09 lp

/220456 Forwards schodules of const milestones & activities as of 20630 Milestone network schedule will be affected by B00618 2018 June 10 schodule Foel loading for Units (& 2 will be 21 agod (yr & Units 3 & 4 dolayed 3 yrs 2007FIFMA Carolina Power & Light Co 80707/11 13pp

Itility Environmental Report (ER), amonds 4 correspondence

AR. Vols 1-20, amended OL application & environ viron rept only encl er A Light Co 80/06/26 3pp

r facility, Vol 1 80/04/74 350pp

F Security, medical, emergency & fire protection plans

8007010352 Forwards industrial security safeguards contingency & security personnel training & qualification plans for review Plans withheld (ref 10CFR2 790)

JONES JA Carolina Power & Light Co 80/06/26 2pp

9 Adjudicatory correspondence

8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
EISENHUT, D Q Division of Licensing 80/06/25 89pp

H General correspondence

B007020198 Responds to B00516 ltr re Kudzu Alliance concerns about ability of util to safely utilize nuclear power NRC monitors Shearon Harris const to assure conformance w/requirements Levels of contamination from Brunswick no threat to public DIRCKS.H J Office of the Executive Director for Operations B0/06/18 2pp

--8007020217 Requests response to entl Kudzu Alliance 800512 ltr communting on ability of util to safely utilize nuclear power ANDREWS, I House of Rep 80/09/16 2pp

K Utility Final Safety Analysis Report (FSAR) & amends

8007170366 Forwards FSAR.Vols 1-20.amended OL application & environ rept for OL stage Only FSAR encl
JONES, J.A. Carolina Power & Light Co. 80/06/26 3pp

--B007170367 F8AR.Vols 1-20
** Carolina Power & Light Co 80/06/26 7800pp

B0071703/2 Chapter 1 to Shearon Harris 1.2.3 & 4 FSAR. "Interduction & General Description of Plant"

* Carolina Power & Light Co 80/06/26 500pp

8007170377 Chapter 2 to Shearon Harris 1,2,3 & 4 FSAR, "Site Characteristics" * Carolina Power & Light Co BD/06/26 700pp

8007170541 Chapter 3 to Shearon Harris 1.2.3 & 4 FSAR. "Design of Structures. Components. Equipment & Sys " * Carolina Power & Light Co 80/06/26 700pp

8007170572 Chapter 4 to Shearon Harris 1,2,3 & 4 FSAR, "Reactor" * Carolina Power & Light Co 80/06/26 200pp

8007170578 Chapter 5 to Shearon Harris 1,2,3 & 4 FBAR, "RCS & Connected Sys " * Carolina Power & Light Co 80/06/26 175pp

8007170594 Chapter 6 to Shearon Harris 1.2.3 & 4 FSAR. "Engineered Safety Features "
* Carolina Power & Light Co 80/06/26 650cc

8007170600 Chapter 7 to Shearon Harris 1.2.3 & 4 FSAR. "Instrumentation & Controls " # Carolina Power & Light Co B0/06/26 500pp

8007170615 Chapter 8 to Shearon Harris 1.2.3 & 4 FSAR. "Electric

Carolina Power & Light Co 80/04/26 125pp

B007170627 Chapter 9 to Shearon Harris 1.2.3 & 4 FSAR, "Auxiliary Sys "

* Carolina Power & Light Co B0/06/26 700pp

8007170643 Chapter 10 to Shearon Harris 1.2.3 & 4 FSAR: "Steam & Power Conversion Sys " * Garolina Power & Light Co BO/06/26 150pp

8007170450 Chapter 11 to Shearon Harris 1,2,3 & 4 FSAR, "Radwaste Mgt "
* Carolina Power & Light Co 80/04/26 175pp

8007170655 Chapter 12 to Shearon Harris 1,2,3 & 4 FSAR, "Radiation Carolina Power & Light Co 80/04/24 200pp

- 9007170661 Chapter 13 to Shearon Harris 1.2.3 & 4 FSAR. "Conduct of Carolina Power & Light Co 80/06/26
- 8007170672 Chapter 14 to Shearon Harris 1, 2, 3 & 4 FSAR, "Initial Test * Carolina Power & Light Co BO/06/26 75pp
- 8007170677 Chapter 15 to Shearon Harris 1,2,3 & 4 FBAR, "Accident Ca) Jina Power & Light Co 80/06/26 400pp
- 8007170684 Chapter 16 to Sheardn Harris 1.2.3 & 4 FSAR, "Tech Specs" a Carolina Power & Light Co 80/06/26 500pp
- | 8007170687 Chapter 17 to Shearon Herris 1,2,3 & 4 FSAR. "GA " | Carolina Power & Light Co | 80/06/26 | 37pp
- 8007170690 App 1 to Shearon Harris 1.2.3 & 4 FBAR, "TMI " * Carolina Power & Light Co 80/06/26 37pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007240113 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08 Region 2, Atlanta, Office of the Director 80/05/08
- 8007210422 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010179 Forwards IE Info Notice 80-29, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J.P Region 2. Atlanta, Office of the Director 80/05/29
- 8007220043 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10.
- B007160223 Forwards IE Info Notice 80-27. "Degradation of Reactor Goolant Pump Studs." No specific action or response O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/11
- B007250339 Forwards IE Info Notice 80~28. "Prompt Reporting of Info in Accordance W/10CFR50 95(e) " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13
- B007100297 Ack receipt of IE Insp Repts 50~400/80~13, 50~401/80~11. 50~402/80~11 & 50~403/80~11 on 800513~16 No proprietary info. HOME:P W. Carolina Power & Light Co 80/06/16
- -8007100301 Forwards IE Insp Repts 50-400/80-13, 50-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 & natice of violation MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/05 2pp
- 80/04/05 in
- ---8007100313 IE Insp Repts 50-400/80-13, 50-401/80-11, 50-402/80-11 & 50-403/80-11 on 800513-16 Noncompliance noted tack walds deposited over heavy rust HERDTA R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/06/05 9pp.
- 8007020440 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown." No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007100412 Ack receipt of 800605 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-400/80-11, 50-401/80-08, 50-402/80-08 & 50-403/80-08 MURPHY, C.E. Region 2, Atlanta. Reactor Construction & Engineering Bupport Branch 80/04/23 ip

- --B007100418 Responds to NRC B00513 ltm: e violations noted in IE Repts 50-400/B0-11,50-401/B0-0B,50-402/B0-0B & 50-403/B0-0B Corrective actions investigation held of collected test data re backfill mall affecting Cotegory I piping HOWE.P W Carolina Power & Light Co B0/06/05 Jpp
- ---8007100422 Ack receipt of 1E Insp Repts 50-400/80-11,50-401/80-08 50-402/80-08 % 50-403/80-08 on 800422-24 No proprietary HOWE.P W Carolina Power & Light Co 80/05/22
- --8007100428 Forwards IE Insp Repts 50-400/80-11.50-401/80-08. 50-402/80-08 & 50-403/80-08 on 800422-24 & notice of violation MURPHY,C E Region 2, Atlanta. Reactor Construction & Engineen Support Branch 80/05/13 2pp
- --8007100430 Notice of violation from insp on 800422-24
 * Region 2, Atlanta, Office of the Director 80/0 80/05/12 1p
- --8007100435 IE Insp Repts 50-400/80-31.50-401/80-08.50-402/80-08 50-403/80-08 on 800422-24 Noncompliance moted failure to consider effect of backfill settlement analysis of Category Region 2. Atlanta. Reactor Construction & Engineer ich BO/05/12 ópp Support Branch
- 8007160800 Forwards IE Circular 80-14, "Radioactive Contamination Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06,
- 8007230220 Forwards IE Bulletin 80-16. "Potential Misapplication o Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY.J P Region 2. Atlants. Office of the Director 80/06.
- BOO7220210 Responds to IE Bulletin BO-08 Review of containment lin penetration weld designs verified by applicable drawings Melds not complete as plant is under const MCDUFFIE.MA Carolina Power & 1.19ht Co BO/07/02 2pp
- R Periodic operating reports & related correspondence
- 8007280507 Forwards "Guarterly Data Rept, Shearon Harris Nuclear Pol Plant Monitoring Program, Apr-June, 1980 " #CDUFFIE.M A Carolina Power & Light Co 80/07/21 ip
- ---8007280513 "Quarterly Data Rept. Shearon Harris Nuclear Power Plan Monitoring Program. Apr-June 1980 " * Carolina Power & Light Co 80/07/21 1p
- S Reportable occurrences, LERs & related correspondence
- 8007160377 Interim deficiency rept re significant failure of reacti protection sys following main feedline break Westinghouse has indicated corrective action cannot be completed before Dec 1981 Final rept will be issued upon completion CHIANGIN J. Carolina Power & Light Co. 80/07/08 1p
- BOO7230247 Part 21 rept re lack of stud base qualification for anguard shield Evaluation will be completed by BO1001
 CHIANOI,N J Carolina Power & Light Co BO/07/11 2pp
- V Operator Examinations
- 8007180428 Requests review & concurrence w/Benior Reactor Operator Certification program & retraining program per HR Denton 800328 itr Certification program effective 800630 Retraining effective in 1981 Description of both programs encl COLLING.J M Carolina Power & Light Co 80/06/23 5pp
- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be a current OL applications, as derived from NUREQ-0560 & found in NUREQ-0594 EISENHUT.D © Division of intensing 80/06/26 2pp

B007010363 Responds to NRC B00421 request for info on Category I masonry walls Design criteria will be developed utilizing acceptable methodology No masonry walls installed at present BROWN.5 C Virginia Electric & Power Co B0/06/27 1p

H General correspondence

8007150047 Responds to 800327 ltr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants operating & under const & relative costs of coal vs nuclear energy YDUNOBLOOD, B J Operating Reactors Branch i 80/05/13 5pp

J Insurance & indempity information

8007150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE, D A Marsh & McLennan, Inc., M & M Nuclear Consultants, Inc Div 80/07/10 3pp

Q Inspection reports, IE Bulletins & correspondence

8007240230 Forwards IE Info Nutice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/05/08

8007210477 Forwards IE Circular 80-13. "Grid Strap Damage in Wastinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/28

8007010239 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29

8007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10

8007160307 Forwards IF Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/11

8007250381 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/13 208

8007020434 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 60/04/RO.

8007170119 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/24

8007230270 Forwards IE Rulletin 80-14. "Putential Misapplication of Rosemount Int Models 1151 % 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-14 also encl No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/27

DOCKET 50-405 NORTH ANNA POWER STATION, UNIT 4

- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0894
 ETEENHUT.D G Division of Licensing 80/06/26 2pp

8007010363 Responds to NRC 800421 request for info on Category I masonry walls Design criteria will be developed utilizing acceptable methodology No masonry walls installed at

present
BROHN, B C Virginia Electric & Power Co 80/06/27 1p

H General correspondence

B007150047 Responds to 800327 ltr to President Carter re granting VEPCO authority to build another nuclear plant Discusses util plants.operating & under const & relative costs of coal vs nuclear energy VDUNGSLOOD, B. J. Operating Reactors Branch 1 80/05/13 5pp

J Insurance & indemnity information

BOO7150490 Forwards Endorsements 28 & 29 to NELIA Policy NF-240 PIERCE,D A Marsh & McLennan,Inc., M & M Nuclear Consultants,Inc. Div BO/07/10 3pp

@ Inspection reports, IE Bulletins & correspondence

BOO7240230 Forwards IE info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/05/08 2pp

8007210477 Forwards IE Circular 80-13, "Grid Strap Damage in Hastinghouse Fuel Assemblies" No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28

8007010239 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/05/29 in

8007220066 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10, 250

BOO7160307 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/08/11 1p

800725038) Forwards IE Info Notice 80-26. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/13

8007020434 Forwards JE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20

8007170119 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director. 80/06/24

BOO7230270 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Dutput Codes " Hritten response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/27.

DOCKET 50-406 TUSKEGEE INST RESEARCH REACTOR

- G Inspection reports, IE Bulletins & correspondence
- 8007170188 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Mater Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/24

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8007020402 Forwards revised Pages 5-11,-12,-17 & -31 to FES including corrections re occupational radiation exposure CRUTCHFIELD,D Operating Reactors Branch 5 80/06/11 2pp

- --B007020411 Revised Pages 5-11,-12,-17 & -31 to FE9, including corrections re occupational radiation exposure

 # Operating Reactors Branch 5 80/06/11 5pp
- 8007230594 Requests that add1 info on concerns re excessive radioactive releases & inadequacy of dose assessment analysis expressed in DES be included in final ETS info should be available to all participants in review process for project TAYLOR.8 J Environmental Protection Agency 80/07/03 2pp
- 8007180337 Submits State of WI Dept of Administration comments on final EIB for facility Increase in spent fuel assemblies should have received explanation & documentation in final EIB Description re age of fuel assemblies is unclear NIELBEN, Q.A. Wisconsin, State of 80/07/08 2pp
- F. Security, medical, emergency & fire protection plans
- BOO7170240 Notifies that FEMA/NRC steering committee reconsidered size of emergency planning zone for water cooled reactors of leas than 250 MW thermal & adopted encl position Proposed rule & NAMES/0654/FEMA-REP-i will be modified in conformance GRUTCHFIELD, D M Operating Reactors Branch 5 80/06/13 3pp
- BOO7180079 Requests add1 info re fire protection mads, Status of evaluation encl. Response requested within 30 days of receipt of ltr
 LAINAB.O C Assistant Director for Safety Assessment 80/06/16
 15pp.
- 8007290634 Forwards results of fire protection review re Items 3.1.27 & 3 2 2 on water demand analysis Licenser should be requested to modify high pressure soc water/fire protection water sys to provide protection for turbine lube nil tank HALL: R E Brockhaven National Laboratory 80/07/23 Spp

Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISEMHUT. D © Division of Licensing 80/06/25 87pp
- 8007140012 Second prehearing conference order outlining matters discussed re new policy for procedural assistance to intervenors, special circumstances in severe accidents & Goulee Region Energy Goalition presentation on full-term OL BECHNOEFER, C Atomic Safety and Licensing Board Panel 60/07/08 App.
- BOO7150505 Order granting extension until 800616 for Coulee Region Energy Coalition to respond to interrogatories Supplemental responses must be filed by 800716 & applicant/NRC summary disposition motions by 800804 Anticipates 800706 prehearing BECHMOEFER.C. Atomic Bafety and Licensing Board Panel 80/07/10 2pp.
- BOO717036B Response to questions of ASLB 800521 memorandum & order reprehearing conference in full term OL proceeding Addresses offgas emissions discrepancies in FEB workers' exposure & environ monitoring Affidavit & Certificate of Svc encl BTEELE, T A . HIESTAND, O. S. Dairyland Power Cooperative BO/07/11
- 8007280656 Forwards supplemental response to NRC interrogatories Related correspondence encl MORSE, A Affiliation Unknown 80/07/17 26pp
- ---B007280659 Supplemental response to NRC interrogatories Witnesses listed & specific incidents at facility cited MORSE,A K , NYGAARD,O Affiliation Unknown 80/07/17. 25pp
- --B007280672 Transcript of D Raphael before Senate Subcommittee on Rural Development RAPHAEL.D Rural America. 79/11/30 lipp.
- ---8007280677 Transcript of DL Ostendorf before House Subcommittee on Conservation & Credit OBTENDORF, D. L. Rural America 80/03/19 7pp
- ---BO07280684 "Nuclear Waste Time Bomb in Our Bones "
 DIXON.0 A Affiliation Unknown 80/03/25 23pp

- --8007280696 Rept before 39th annual meeting of util LINDER,F Dairyland Power Cooperative 80/06/18 14pp
- 8007310101 Supplemental response to NRC interrogatories Identifies individuals to be called in support of contentions Submits elaborate discussion of radiation effects & energy conservation Affidavit & Certificate of Svc encl MORSE,A K., NYGAARD,O R. Affiliation Unknown 80/07/17 19pp
- 800730042B Motion to file second round of interrogatories directed to Couler Region Energy Coalition Intervenor lengthy supplemental response to NRC discovery requests will not be adequately addressed unless clarified M/Certificate of Svc MODDHEAD.C P Hearing Branch 3 80/07/28 App
- 800731046F Order designating ASLB to consider & rule upon requests for hearing re Ofc of Nuclear Reactor Regulation 800225 order to show cause re dewatering sys Adjudicatory hearing.if determined should be limited to two issues stated in order CMILK.S J. Office of the Secretary of the Commission 80/07/29

H General correspondence

- 8007140221 Responds to 800320 ltr re licensee withholding of info from public on reactor operation decisions Licensee not required to provide documents to concerned party since issue is not under litigation
 EISCMHUT.D G Division of Licensing 80/06/26 5pp
- --8007140227 Expresses displeasure w/licensec withholding of info from public re reactor operation decisions Repeated requests to be included on svc list for correspondence to NRC have been ignored FANTLE.W Couloe Region Energy Coalition 80/03/20 2pp

1 Financial information

- 8007310434 Forwards Annual Financial Rept 1979 & certified financial statements for 1978 & 1979
 LINDER:F Dairyland Fower Cooperative 80/07/24 1p
- --80073:0443 Annual Financial Rept 1979 Certified financial statements for 1978 & 1979 encl * Dairyland Power Cooperative 80/05/15 47pp
- P Operating license stage documents & correspondence
- 8007010120 Forwards final rule published in B00509 FR amending 10CFR50 71 to require periodic updating of FSARs Compliance is not required until completion of SEP CRUT(HFIELD,D Operating Reactors Branch 5 80/06/10 5pp
- 8007100379 Responds to B00229 ltr which expressed opposition to ACR8 recommendation to restructure SEP Role of licensees in program will expand Ltr forwarded to Commissioners DENTON, HR Defice of Nuclear Reactor Regulation, Director 80/04/18 4pp
- ---B007100420 Expresses apposition to ACRS recommendation to restructure SEP For SEP owners to perform safety analysis as outlined.

 cost in dollars & manpower would increase dramatically SCHAFFSTALL, R SEP Owners Group 80/02/29 2pp
- BOO7010070 Responds to FOIA request for 57 documents referenced in M Takar memo to ACR9 concerning pellet-cladding interaction Forwards documents Missing records are duplicative, superseded or available elsewhere FELTON, J M Division of Rules and Records 80/06/20 2pp
- --8007010088 Discusses similarities in fuel fod failures for DWRs resulting from control blade movements Failure gettern w/Dresden & LACOWR fuel rads was associated w/location of fuel rads relative to control rods SIEGEL, B. L. Atomic Energy Commission, Directorate of Licensing 73/09/20 2pp
- 8007240079 Requests addl info to continue review of adequacy of station electric distribution sys voltages Response requested within 45 days of receipt of ltr CRUTCHFIELD.D M Operating Reactors Branch 5 80/06/27 App
- 8007210608 Forwards "SEP Technical Evaluation Topic VIII-4, Electrical Penetrations of Reactor Containment LACSWR " CRUTCHFIELD, D.M. Operating Reactors Branch 5 80/07/01 2pp

- --B007210640 "SEP Technical Evaluation Topic VIII-4, Electrical Penetrations of Reactor Containment LACBHR" * Operating Reactors Branch 5 80/07/01 App
- 8007080300 Forwards drawings providing add1 info to safe shutdown, requested by NRC 800610 telecopy
 SHIMSHAK.R Dairyland Power Cooperative 80/07/02 3pp
- --B007080305 Requests drawings or diagrams re-safe shutdown by B00707 NAYS, 9 Commission B0706/10 2pp
- 8007140305 Notifies that Item 1 of TMI Lessons Learned requirements was not forwarded w/NRC 800507 itr 4 has not yet been received LINDER, F. Dairyland Power Cooperative 80/07/07 ip
- 8007210447 Forwards review of RCS pressure boundary stainless steel piping & fitting matl LINDER, F Dairyland Power Cooperative 80/07/10 19pp
- BOO72B0190 Forwards NRC evaluation of SEP Topics III-10 A.V-11 A.VI-7 C i & III-3 D Evaluations will be basic inputs to integrated sofety asseasments unless changes are needed to reflect as-built conditions CRUTCHFIELD.D Operating Reactors Branch 5 80/07/i0 18pp
- 8007220525 Forwards "Response to NRC Review Guestions" re util answer
- to BOO325 order to show cause LINDER,F Dairyland Power Cooperative BO/07/14 Ppp
- --BO07220526 "Response to NRC Review Questions." prepared for util SINGH.H Dames & Moore BO/07/11 74pp
- 8007280076 Responds to 800318 ltr to J Absorbe objecting on behalf of owners of plants under SEP review, to current plans for expedited review of environ qualification of electrical equipment Forwards applicable memorandum & order DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 80/07/16
- @ Inspection reports, IL Bulletins & correspondence
- BOO7140523 Forwards IE Bulletin BO-13. "Cracking in Core Spray Spargers " Hritten response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/05/12
- 8907020058 Forwards IE Info Notice 80-22, "Bleakdowns In Contemination Control Programs" No written response required KEPPLER, J. O. Region 3, Chicago, Dffice of the Director 80/05/28
- 8007010112 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J G Region 3. Chicago, Diffice of the Director 80/05/29
- 8007020679 Submits further response to IF Bulletin 80-07, "BWR Jet Pump Assembly Failure" LINDER:F Dairyland Power Cooperative 80/06/02 ip
- 007100085 Forwards IE Insp Rept 50-409/79-24 on /91227-28 No
- noncompliance noted
 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety
 Branch 80/06/05 2pp
- --8007100089 IE Inso Rept 50-409/79-24 on 791227-28 No popoamaliance noted Major areas inspected licensee actions per IE Bulletin 77-19 re packaging of low lovel radwaste for transport & GUTIAL
 FIGHER. W.L. Region 3. Chicago, Fuel Facility & Materials Safety
 Branch QREGER.L. R. Region 3. Chicago, Défice of the Director
 80/06/03 4pp
- 9007220195 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required XEPPLER.J G Region 3, Chicago, Office of the Director 80/06/10
- 0007140571 Responds to IE Bulletin 79-03A. "Longitudinal Weld Defects in ASME 9A-312.Type 304 Stainless Steel Pipe " Np A-312 stainless steel fusion welded piping is in use in safety-related piping at facility LINDER.F Dairyland Power Copperative 80/06/13 2pp

- 8007180355 Responds to IE Builetin 80-08. "Examination of Containment Liner Penetration Welds "Facility has no containment penetrations utilizing flued head design Three penetrations w/containment boundary but welds used LINDER.F Dairyland Power Conperative 80/06/13 3pp
- 8007030032 Forwards IE Bulletin 80-15, "Possible Loss of Emery#ncy Notification Sys (ENS) W/Loss of Offsite Pawer " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/18
- 8007020578 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/20
- 8007180362 Responds to IE Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Safety-related functions noted to reset upon removal of actuating signal listed in encl App A, w/proposed mode defined LINDER,F Dairyland Power Cooperative 80/06/20 5pp
- 8007170479 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J O Region 3. Chicago. Office of the Director 80/06/24
- 8007180092 Responds to IE Bulletin 80-15 re possible loss of emergency notification sys w/loss of offsite power Emergency notification sys is powered offsite from reliable power supply backed by batteries & diesel generator LINDER.F Dairyland Power Cooperative 80/06/25 2pp
- 8007230320 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Elther A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/2: 80/06/27
- B007220096 Bubmits reply to IE Bulletin B0-16 re misapplication of certain Rusemount pressure transmitters Transmitters are not used in safety-related or other circuits LINDER:F Dairyland Power Cooperative B0/07/09 ip
- 8007280090 Responds to IE Bulletin 80-10 re contamination of nonradicactive sys & resulting potential for unmonitored. Uncontrolled release of radioactivity to environ Instrument air used in containment bldg is protected by check valves LINDER: F Dairyland Power Cooperative 80/07/11 App
- 8007290480 Responds to IE Bulletin 80-11 LACBUR containment bldg has no masonry walls Four identified in turbine bldg No 85E established No separate masonry walls re-evaluation planned at present Evaluation will be part of SEP LINDER, F Dairyland Power Cooperative 80/07/16 3pp
- 8007300244 Verifies that action specified in util 800711 ltr re Item 2 of IE Bulletin 80-10, "Contamination of Nonradioactive Sys & Resulting Potential for Unmonitored, Uncontrolled Release of Radioactivity to Environ," completed on 800714
 LINDER.F Dairyland Power Cooperative 80/07/18 ip
- R Periodic operating reports & related correspondence
- B007160677 Forwards monthly operating rept for June 1980 LINDER.F Dairyland Power Cooperative 80/07/08 ip
- --8007160681 Monthly operating rept for June 1980 GDDDMAN.L B Dairyland Power Cooperative 8 80/07/07 12pp
- DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 8007210176 Forwards NRC evaluation of GE rept.NEDE-24010-P & Suppls I-3, "Technical Basis for Use of Square-Root-of-Sum-of-Squares (SRSS) Method for Combining Dynamic Loads for Mark II Plants "Rept acceptable subj to certain constraints MATTSON.R J Division of Safety Technology 80/06/25 3pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0860 & found in NUREG-0894 EISENHUT, D.G. Division of Licensing 80/06/26 2pp

- B007080337 Responds to SA Varga 800421 request for info on Category I mesonry walls Concrete masonry walls will not be used in Category I structures RHODE, 9 K Niagara Mohawk Power Corp 80/07/02 ip
- 9007230621 Summary of B00612 meeting w/Mark II owners group in Bethesda,MD re lead plant closure & long-term program Mods should be made to generic lead plant condensation oscillation & chugging pool boundary loads Viewgraphs encl ANDERSON,C J Goneric Issues Branch 80/07/03 57pp
- 8007180520 Forwards request for addl info re geologic investigation of site
 YOUNGBLOOD, B J Licensing Branch 1 80/07/09 5pp
- 8007210624 Bummary of 800610 meeting w/util in Bethesda,MD re welding defects in biological shield wall KIPER.K L Licensing Branch I 80/07/09 5pp
- 8007250472 Informs of util schedule for setting biological shield wall & reactor pressure vessel Biological shield wall setting scheduled for B00728-0829 & reactor pressure vossel for LEMPGES, T E Niagara Mohawk Power Corp 60/07/18 1p
- 8007250175 Notification of 800805 meeting w/representatives from Mark II owners group in Chicago, IL to discuss lead Mark II plants chugging & C/O load specs AMDERBON. C Oemeric Issues Branch 80/07/23 Zpp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D Q Division of Licensing 80/06/25 89pp
- I. Financial information
 - BO07250275 Forwards util Annual Financial Rept for 19 LEMPOES, T.E. Niagara Mohawk Power Corp. 80/07/22
 - M Antitrust correspondence
- 8007290533 Response in opposition to City of Cleveland, DH 800609 request for hearing re Director of Nuclear Reactor Regulation 800513 order Filing, requesting tariff w/FERC, brings controversy to end w/o litigous course REYNOLDS, W B , ZAHLER, R.E. Cleveland Electric Illuminating Co
- O Inspection reports, IE Bulletins & correspondence
- 8007140459 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers" No written response required ORIER.B H. Region 1, Philadelphia, Office of the Director. 80/03/12 ip
- 8007210201 Forwards IE Insp Rept 50-410/80-02 on 800319-21 & 0410-11. No noncompliance noted CARLEON, R T Region 1. Philadelphia, Reactor Construction & Engineering Bupport Branch 80/04/03 2pp
- ---8007210209 IE Insp Rept 50-410/80-02 on 800319-21 & 0410-11 No noncompliance noted, Major areas inspected reactor pressure vessel internals storage, biological shield wall status & vessel internals storage, Diological shield wall status & plant insp tours CERNE, A C . McDREARTY, R. A Region 1, Philadelphia, Office of the Director McGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/07 9pp
- 8007020302 Requests add1 info re actions taken to preclude occurrence of cracking described in IE Bulletin 80-07 Also requests commitment to adopt whatever long-term solution is approved TEDESCO.R L. Assistant Director for Licensing. 80/06/10. 2pp
- BOO7210570 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required GRIER, B H Region i, Philadelphia, Office of the Director. BO/06/10 ip
- 8007140264 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required, ORIER.B H Region i, Philadelphia, Office of the Director 80/06/12. ip

- 8007180552 Forwards IE Insp Rept 50-410/80-03 on 800424 No NOTIBUTE FORWARDS IE INSPINED REPT SUFFICIONOUS BIT WOULD NOT INCOME THE WASHINGTON OF THE CONSTRUCTION & Engineering Support Branch 80/06/12 2pp
- --8007180561 IE Insp Rept 50-410/80-03 on 800424 No noncompliance noted Major areas inspected reactor bidg.primary containment turbine bidg.water intake structure area & area of ground fault fault CERNE,AC . FEIL.R A Region i. Philadelphia. Office of the Director MCGAUGHY,R W Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/09 2pp
- B0072B0603 Forwards 1E Info Notice 80-2B, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/06/13 1p
- 8007020511 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required GRIER.B H Region 1. Philadelphia. Uffice of the Director 80/06/20 ip
- 8007160717 Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- 8007210210 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region i, Philadelphia. Office of the Director 80/06/25 ip
- 8007230151 Forwards IE Bulletin 80-14. "Potential Missonlication of NOVESCOURT FORWARDS IN MULICIA BO-16, "Potential Misapplica Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ORIER. B H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- 8 Reportable occurrences, LERs & related correspondence
- B007020111 Ack receipt of B00512 ltr forwarding interim deficiency rept re environ & seismic qualification of electrical aquipment Rept will be reviewed & evaluated CARLSON: T Region 1. Philadelphia. Office of the Director B0/05/30 ip
- 8007020004 Forwards summary of 800807 meeting re biological shield wail weld defect problem Util was informed that NRC would conduct insp on 800512 to review work in progress CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/03 3pp
- BOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2 A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0560 & found in NUREG-0564 EIBENHUT, DG Division of Licensing 80/06/26 Rpp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D O Division of Licensing 80/06/25 87pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007010294 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER,B H Region i, Philadelphia. Office of the Director 80/05/29 ip
- 8007210563 Forwards IE Info Notice 80-26. "Evaluation of Contractor AA Programs " No written response required GRIER.B.H Region 1. Philadelphia, Office of the Director 80/06/10 ip

- 8007160345 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response GRIER, B H Region 1, Philadelphia, Office of the Director
 - 00/06/11
- 8007280581 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required GRIER.B H Region 1. Philadelphia, Office of the Director 80/06/19 1p
- 8007180055 Responds to IE Bulletin 80-07 "Hydramotor Actuator Deficiencies " Dumpers W/ITT General Controls NH-90 actuators purchased but not shipped Vendors re-evaluating selections & will restify that steel is Type 1060-1070 WOGLEVER: C J Duquesne Light Co 80/06/17 2pp
- 0007020504 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Conling & Natural Circulation Conldown " No written response required required Office, D.H. Region 1, Philadelphia, Office of the Director
- 8007160673 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GHIER. II the Region I. Philadelphia. Office of the Director 80/06/24 ip
- 800701034B Responds to NRC 000827 ltr re violation noted in IE Insp Rept 50-412/80 04 Corrective actions nine welds were re-radingraphed & manually processed Machine will not be utilized on film applicable to ABME Section III welds MOOLEVER.E J Duquesne Light Co 80/06/25 6pp
- 8007210178 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Oriteria " No written response required ORIER, D H Region i, Philadelphia, Office of the Director 80/06/25 ip
- B007230115 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Cither A or D Output Codes" Written response required IE Circular 80-16 also seci No written response required CRIER, B H Rogion 1. Philadelphia. Office of the Director ORIER, B H Ros 80/06/2/ 2pp
- BOD/210016 Responds to IF Bulletin 79-03A re longitudinal weld defects in ASME 8A-312 type stainless steel Pipe 304 Piping sys is subj to design stresses greater than 85% of allowance No action reguired WOOLEVER, E.J. Duqueene Light Co. 80/07/07 ip
- 8 Periodic operating reports & related correspondence
- 8007290540 Forwards magnetic tape containing meteorological data for 1979 Tape evailable at Hydrology-Meteorology Branch only BIEBFA. J D Duquesna Light Co B0/07/21 Spp
- B Reportable occurrences, LERs & related correspondence
- 8007010459 Supplement 3 to Port 21 rept re failed thrust boaring Insp complete Crankshaft thrust bearings on two dissel generators are free of reported potential defect MRRIARTY, J It Colt Industries, Inc., Fairbonks Marse Engine Div. 80/06/26 Ip
- 8007180834 Ack receipt of 800521 final deficiency rept re crane wall reinforcing steel NRC has no further questions CARLBON,R Y Region 1. Philadelphia. Reactor Operations Nuclear Buyport Branch 80706/27 ip
- 800727086D Ack receipt of 600616 final deficiency rept re weld discrepancies in reactor vessel support structure CARLSON, R. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/07 ip
- DOCKET 50-410 CATAMBA NUCLEAR STATION. UNIT 1
- A Application/construction stage documents & correspondence
- 8007010186 Advises of reorganization of Ofc of Nuclear Reactor Regulation effective 800428 Mgt of all licensing matters for facility has been assigned to J Matero Organizational description encl TEDESCO, R L Assistant Director for Licensing 80/06/13 Assistant Director for Licensing 80/06/13 11pp

- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D 0 Division of Licensing 60/06/26 2pg
- B007030185 Forwards application for amend to CPPR-116 consisting of addition of co-owners & co-applicants PURTER: W L Duke Power Co B0/07/01 3pp
- ---B007030189 Application for amend to CPPR-116 re sale of 56.25% undivided ownership in Unit 1 & 28 15% interest of support facilities to NC Electric Membership Corp & 18 75% undivided ownership to Saleda River Electric Cooperative DAIL, L C Duke Power Co HUBBARD, J M North Carolina Muncipally Owned Electric Systems Association 80/07/01 45pp
- 8007210474 Forwards revised application for amend to CPPR-116 adding co-numers & co-applicants PORTER:N L Duke Power Co 80/07/14 ip
- --B007210486 Revised application for amend to CPPR-116 adding NC Electric
 Membership Corp & Saluda River Electric Cooperative, Inc. as
 co-amers & co-applicants
 DAIL.L C Duke Power Co HUBBARD. J M North Carolina Electric
 Membership Corp FARIS.H M Saluda River Electric
 Gooperative, Inc 80/07/01 .17pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 momental was a control of 780413 momental was a color of 77104 petition sought action refer protection for electrical cables EISENHUT, D 0 Division of Licensing 80/06/25 87pp
- M Antitrust correspondence
- BO07160607 Forwards info requested by Atty General re util B00701 application for CP amend adding co-owners & co-applicants Antitruct advice per Atmmic Energy Act requested H/o encl BHAPAR, H K Office of the Executive Logal Director 80/07/11
- O Inspection reports. IE Bulletins & correspondence
- 8007240122 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 8007020204 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007210449 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director
- 8007010213 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J F Region 2, Atlanta, Office of the Director. 80/05/29
- 8007220048 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs "No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director BO/06/10
- 8007160255 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required

 O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/11.
- 8007230344 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR30 55(e)" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/13
- 8007020459 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Capling & Natural Circulation Cooldown "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/06/20

- S007100417 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-05 & 50-414/80-05 MRRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering
 - Support Branch 80/04/23
- --BOO7100419 Responds to NRC 800505 ltr re violations noted in IE Insp Repts 50-413/80-05 & 50-414/80-05 Corrective actions individual cited in insp rept has met all requirements for Level 2 & has been so certified PARKER.W D Duke Power Co 80/05/28 3pp
- -8007100423 Forwards IE Insp Repts 50-413/80-05 & 50-414/80-05 on 800305-31 & notice of violation MRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/05 2pp
- ---8007100426 Notice of violation from insp on 800305-31 * Region 2. Atlanta, Office of the Director 80/0 BO/04/05 2nn
- -8007100432 IE Insp Repts 50-413/80-05 & 50-414/80-05 on 800305-31
 Noncompliance noted failure to provide adequate procedure for rigging near Class IE equipment & failure to follow drawing requirements
 MAXMELL.0 F Region 2. Atlanta, Office of the Director
 RAMSCH.J K Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch 80/05/05 ilpp
- BO07170104 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required UREILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/24
- 8007230235 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also enci No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/2 80/06/27
- 8007210261 Responds to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds " Welds in 13 penetrations repaired as result of nondestructive examination Summary of types & sizes of penetrations encl PARKER, W D Duke Power Co 80/07/07 7pp
- 9. Reportable occurrences. LERs & related correspondence
- BOO7020537 Deficiency rept re faulty connections in electrical equipment As described in BOO201 Deficiency Rept
 BD 413-414/80-01.all Unit 1 safety-related motor control ctr equipment has been inspected & necessary mods completed PARKER.W O Duke Power Co BO/06/18 ip
- 8007160514 Forwards deficiency rept re rejectable indications in welding of containment vessel equipment habch PARKER, N. O Duke Power Co 80/07/11, ip
- 8007280501 Significant deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture, initially reported 800617 Inadequate min flow may result in degraded pump performance Hestinghouse reviewing problem PARKER, H O. Duke Power Co 80/07/17 2pp.
- DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8007010186 Advises of reorganization of Oft of Nuclear Reactor Regulation, effective 800428 Mgt of all licensing matters for factility has been assigned to J Matore Organizational description encl. TEDESCO, R L. Assistant Director for Licensing. 80/04/13 11pp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREO-0640 & found in NUREO-06494
 EIBEN#NT,D. 9. Division of Licensing 80/06/26 2pp.
- 8007030183 Forwards application for amend to CPPR-116 consisting of addition of co-owners & co-applicants PORTER, W. L. Duke Power Co 80/07/01 3pp

- -8007030189 Application for amend to CPPR-116 re sale of 56 25% DOVIGUIBLY Application for amend to CPPM-116 re sale of 56 25% undivided ownership in Unit 1 & 28 15% interest of support facilities to NC Electric Membership Corp & 18 75% undivided ownership to Saluda River Electric Cooperative DAIL.L C Duke Power Co HUBDARD, J M North Carolina Munc: Dwned Electric Systems Association 80/07/01 45pp North Carolina Muncipally 07/01 45pp
- B007210476 Forwards revised application for amend to CPPR-114 adding co-owners & co-applicants
 PORTER.W L Duke Power Co B0/07/14 lp
- ~~B007210486 Revised application for amend to CPPR-116 adding NC Electric Membership Corp & Saluda River Electric Cooperative,Inc.as co-owners & co-applicants DAIL.L C Duke Power Co HUBBARD.J M North Carolina Electric Membership Corp FARIS.H II Soluda River Electric Cooperative,Inc 80/07/01 17pp

O Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 Memorandum & Order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/04/25 87pp
- M Antitrust correspondence
- 8007160607 Forwards info requested by Atty General re util 800701 application for CP amend adding co-buners & co-applicants Antitrust advice per Atomic Energy Act requested W/o encl SHAPAR: H K Office of the Executive Logal Director 80/07/11 80/07/11 1p
- O Inspection reports. IE Bulletins & correspondence
- 8007240122 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Desse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08
- B007210449 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director E B0/05/28
- 8007010213 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/29
- 8007220048 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required O'REILLY. J P Region 2. Atlanta. Office of the Director 80/06/10
- 8007140255 Forwards IE Info Notice 80~27, "Degradation of Reactor Coolant Pump Studs " No specific action or response renutred O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- B007250344 Forwards IE Info Notice B0-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/13
- B007020459 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta. Office of the Director 80/06/20
- 8007100417 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/80-05 & 50-414/80-05 NURPHY.C E Region 2. Atlanta. Reartor Construction & Engineering Support Branch 80/06/23 ip
- ---8007100419 Responds to NRC 800505 ltr re violations noted in IE Insp Rapts 50-413/80-05 & 50-414/80-05 Corrective actions individual cited in insp rept has met all requirements for Level 2 & has been so certified PARKER, W O Duke Power Co 80/05/28 3pp
- ---B007100423 Forwards IE Insp Repts 50-413/B0-05 & 90-414/B0-05 on B00303-31 & notice of violation MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/05/05 2pp

- --8007100425 Notice of violation from insp on 800305-31 * Region 2: Atlanta, Office of the Director 80/04 80/04/05 2pp
- --8007100432 IE Insp Repts 80-413/80-05 & 50-414/80-05 on 800305-31 Noncompliance noted failure to provide adequate procedure for rigging near Class IE equipment & failure to follow drawing requirements

 MAXMELL.G F Region 2, Atlanta, Office of the Director

 RAUSCH.J K Region 2, Atlanta, Reactor Construction & Engineering

 Support Branch 80/05/05 11pp
- 8007170104 Forwards 1E Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel 'No written response required O'REILLYJ P Region 2, Atlanta, Office of the Director 80/06/24
- B007230235 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters
 W/Either A or D Gutput Codes " Written response required
 IE Circular 80-16 also enc! No written response required
 O'REILLY, J P Region 2, Atlanta, Office of the Director 60/06/27
- 8007210261 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Welds in 13 penetrations repaired as result of mondestructive examination Summary of types & sizes of penetrations encl PARKER, W O Duke Power Co 80/07/07 7pp
- S Reportable occurrences. LERs & related correspondence
- B007020537 Deficiency rept re faulty connections in electrical equipment As described in 800201 Deficiency Rept BD 413-414/B0-01.all Unit i safety-related mater control ctracquipment has been inspected & necessary mods completed PARKER.W D Duke Power Co 80/06/18 ip
- 8007280501 Signsficant deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture, initially reported 800617 Inadequate min flow may result in degraded pump performance Westinghouse reviewing problem PARKER, W O Duke Power Co 80/07/17 2pp
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- A Application/construction stage decuments & correspondence
- 8007160610 Forwards correction to fuel load date in 800514 ltr Correct date for Unit 1 is 810831 DALE,L F Mississippi Power & Light Co 80/06/11 lp
- --B007160617 Corrects 800514 ltr requesting updated & complete schedule of safety review Correct fuel load date is 810831 DALE, L. F. Mississippi Power & Light Co. 80/05/14 lp
- 8007010237 Forwards NRC reorganization chart of Dfc of Nuclear Reactor NO/01023/ Forwards New reorganization chart or DEC New Regulation.effective 800428 Facility activities should be made through assigned mgt representative Areas of disagraement may be discussed through informal appeal TEDESCO.R L. Assistant Director for Licensing 80/06/13 80/06/13 Zpp
- BOO7010087 Notification of 800708 meeting w/util, BNML, GE & Bechtel Power Corp in Gaithersburg, ND to review Mechanical Engineering Branch draft SER HOUGHTON.T C Licensing Branch 3 80/06/14 3pp
- BOO7010100 Notification of 800625 meeting w/util,GE,Bechtel Power Corp & Savannah River Lab in Gaithersburg,MD to discuss FSAR Saction 7. "Instrumentation & Control" HDUGHTDN.7 C Licensing Branch 3 80/06/16 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694 in NUMER-1094 EISENHUT.D.G. Division of Licensing 80/06/26 2pp
- 8007030245 Forwards structural drawings supplementing technical info submitted on 800529 % 0606 DALE, L. F. Mississippi Power & Light Co. 80/06/30 2pp
- --800703024B Package of 72 structural drawings to be recalled at later date for microfilming * Bechtel Corp 80/06/30 72pp

- 0007240287 Summaly of B00625 meeting w/applicant in Gaithersburg, MD re instrumentation & control sys questions & response & discussion of review schedule HDUGHTON, T.C. Licensing Branch 3 80/07/03 7pp
- 8007280494 Forwards response to 10 remaining open issues in diaft SER Info covers seismic subsystem analysis, acceptance criteria for steady state piping vibration & preservice & inservice pump & valve testing
 DALE.L F Mississippi Power & Light Co 80/07/08 13pp
- 0007220569 Forwards "Cultural Resources Survey of Ray Draswell Transmission Line Route Warren & Claiberne Counties, MS," per NRC 800118 request DALE,L F Mississippi Power & Light Co 80/07/17 1p
- ---8007220573 "Cultural Resources Survey of Ray Braswell Transmission Line Routs Warren & Claiborne Counties.MS " D'HEARL V , ARKINSON.J P Mississippi Power & Light Co 80/06/09 22pp
- 8007290322 Forwards comments to amplify previous questions rainstrumentation & controls raised at 800625 meeting SCHWENCER.A Licensing Branch 3 80/07/21 3pp
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B007070245 Forwards response to open issues for use at 800708 meeting w/Mechanical Engineering Branch re draft SER for FBAR Sections 3 6-3 to Responses to remaining ten issues will be provided on 800707 DALE.L.F. Mississippi Fower & Light Co. 80/07/02 26pp
- 8007140388 Forwards partial transmittal of responses to draft SER for FSAR Sections 3 6-3 10 DALE.L F Mississippi Power & Light Co 80/07/08 13pp
- F Security, medical, emergency & Pire protection plans
- 8006300375 Forwards Amend 40 to application for OLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FBAR, App 98 BTAMPLEY, N.L. Mississippi Power & Light Co. 80/06/27 1p
- --8004300382 Amend 40 to application for OLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FSAR App 98 Certificate of Svc encl STAMPLEY.N L Mississippi Power & Light Co 80/06/27 2pp
- ---BOD&3003B4 Amend 40 to FBAR, providing revisions to fire protection plan & emargency plan * Mississippi Power & Light Co 80/06/27 85pp
- 8007010361 Forwards omergency & radiological response plans for State of MS,Port Gibson/Claiborne County,MS, & State of LA,in support of util revised emergency plan submitted on 800627 as part of Amend 40 to FGAR DALE,L F Mississippi Power & Light Co 80/06/27 2pp
- 8007180293 Forwards response to NRC 800702 itr re estimated evacuation times Estimated evacuation times for 10-mile emergency planning zone prepared by Clairborne County, MS & Tenses Parrish, LA, encl
 DALE, L F Mississippi Power & Light Co 80/07/11 33pp DALE L F
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D 9 Division of Licensing 80/06/25 89pp
- K Utility Final Gafety Analysis Report (FSAR) & amends
- 8007110412 Forwards affidavit of svc for Amend 40 to FSAR.per NRC 780627 ltr DALE:L F Mississippi Power & Light Co 80/07/07 2pp
- Q Inspection reports. IE Bulletins & correspondence
- B00724021B Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/05/08.

- BOO7140484 Forwards IE Builetin 80-13, "Cracking in Core Spray Spargers " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/12
- B007020173 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs " No written responso required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28 is
- 8007010200 Forwards IE Info Notice 80~23, "Loss of Suction to Emergency Feedwater Pumps" No written response required G'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- 9007100119 Forwards IE Insp Rept 50-416/80-11 on 800512-15 No noncompliance noted LEMIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 80/05/30 2pp
- 8007220078 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10 200.
- B007160278 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/11
- B007140299 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability," No written response required D'REILLY. J P. Region 2. Atlanta. Office of the Director B0/06/12 in.
- 8007250377 Forwards IE Info Notice 80-2B. "Prompt Reporting of Info in Accordance W/10CFR50,55(e)" No written response required U'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13 2pp
- 8007020374 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director BO/06/20
- 8007310240 Forwards IE Insp Repts 50-416/80-13 & 50-417/80-09 on 800603-06 No noncompliance noted MARPHY, C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 80/06/23 2pp
- 8007160789 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/24 is
- B007230213 Forwards IE Bulletin 80-16, "Potential Misapplication of Roseacunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 1p.
- BOO7140B40 Ack receipt of 800517 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-416/80-08 MURPHY.C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. BO/07/01 ip.
- ---BO07i60B62 Revised response to NRC 800401 ltr re violation noted in IE
 Insp Rept 50-416/80-08 Corrective actions, insp program
 instituted by constructor & all nonconformances will be
 documented.
 HCGAUGHY, J. P. Mississippi Power & Light Co. 80/06/17 7pp

- --8007i60866 Responds to NRC 800401 ltr re violation noted in IE Insp Rept 50-416/80-08 Corrective actions all personnel have been reinstructed in installation & insp procedures MCGAUOHY. J P hississippl Power & Light Co 80/05/19 2pp
- --8007160869 Forwards 1E Insp Rept 50-416/80-08 on 800303-06 & notice of violation
 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/04/01 2pp
- --B007i60870 Notice of violation from insp on B00303-06 * Region 2, Atlanta, Reactor Construction & Engineering Support Branch 60/03/31 2pp
- --B007160B72 IE Insp Rept 50-416/B0-0B on 800303-06 Noncompliance noted failure to follow pape support installation & insp procedures ANG.W P., WILCOX, J.D. Region 2. Atlanta, Office of the Director HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/03/31 App
- 8007210270 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Evaluation not complete Requests extension to 800015 DALE:L F Mississippi Power & Light Co 80/07/03 ip
- 8007250432 Forwards response to NRC BOD624 ltr ro violations noted in IE Insp 50-416/80-12 on 800527-30 Corrective actions responsible field engineers have been instructed to obtain sequential number from respective discipline cut rebar log MCGAUGHY.J P Mississippi Power & Light Co 80/07/21 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007020619 Status deficiency rept re effects of loss of site power on rod position indication & neutron munitaring Deficiency still under investigation Final rept will be forwarded on 800723 DALE, LF Mississippi Power & Light Co 80/05/21 2pp
- G007170592 Part 21 rept re potentially defective dissel generator control panels mfg by Intl Control & Switchgear Co Insp underway to determine applicability of deficiency Final rept will be submitted by B00625 MCGAUGHY.J P Mississippi Fower & Light Co B0/05/22 2pp
- 8007160585 Interim deficiency rept re incorrect pape supplied by TX Pipe Bending Heavier wall would not cause overstressed condition General implications in other applications under investigation Final rept will be submitted by 800829 MCGAUGHY.J P Mississippi Power & Light Co 80/05/23 2pp
- B007140642 Second interim deficiency rept (PRD-B0/07) re inadequate Fisher Controls QA program re safety-related controls for nonpressure retaining parts & components QA program evaluation continues Final rept will be submitted by 800624 MCGAUGHY.J P Mississippi Power & Light Co 80/05/23 ip
- B007020579 Status Deficiency Rept 4 re GE failure to implement proper GA program for electrical work Util is reviewing reinsp of GA program Final rept will be submitted by 800714 MCGAUGHY, J P Mississippi Power & Light Co B0/09/30 2pp
- 8007020640 Status Deficiency Rept 2 re mod to dragon valve manifolds Review of application of valve manifolds & safety-related impact still under investigation Final rept will be forwarded by 800702 MCGAUHY.J P Mississipp Power & Light Co 80/06/02 2pp
- 8007160611 Interim doficiency rept re mods to Dragon valve manifolds Review of MCAR-GONS 26 in M Gauge 800306 site insp concluded that deficiency was improperly evaluated Final rept will be submitted by 800702 MCGAUGHY, J P Nicsissippi Power & Light Co 80/06/02 2pp
- 800bi90B77 Deficiency rept (PRD-B0/24) re GE Type SB-12 switches Guestions rationals that safety function of breaker was to trip on signal from reactor protection sys Re-evaluation will be conducted & final rept filed by 800710 MCGAUGHY.J P Mississippi Power & Light Co 80/06/12 2pp
- B007020601 Forwards interim deficiency rept re GE failure to provide qualified instrumentation in safety-related sys
 MCGAUGHY.J P Mississippi Power & Light Co 80/06/13 2pp
- --8007020403 Interim deficiency rept re GE failure to provide spismically & environmentally qualified instruments for use in nuclear safety-related sys in balance-of-plant power generation control complex Corrective action plan expected by 800711 * Mississippi Power & Light Co 80/06/13 4pp

- 800702053B Forwards interim deficiency rept (PRD-80/11) re Rosemount Model 510 DU trip unit & Final deficiency rept (PRD-80/11) re Model 1152 pressure transmitters MCGAUGHY, J P Mississippi Power & Light Co 80/06/24 2pp
- --B007020539 Final deficiency rept (PRD-B0/11) re Model i152 pressure transmitter u/common mode failure of capacitor at greater than 175 F or when damping potentiometer is lotated clockwise GE issued field disposition instructions

 + Mississippi Power & Light Co 80/06/24 ip
- --8007020541 Interim rept (PRD-80/11) re Rosemount Model 910 DU trip/calibr unit w/common mode failure of essential switch that determines trip output logic GE has issued field disposition instructions for onsite repair * Mississippi Power & Light Co 80/06/24 ip
- 8007020630 Forwards final deficiency rept re defects in diesel generator control panels MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/25 ip
- --B007020632 Final deficiency rept re defects in diesel generator control panels mfg by Intl Control & Switchgear Co Equipment being repaired by Morrison-Knudsen GA activity will be increased Applicability of 10CFR21 under evaluation # Mississippi Power & Light Co 80/06/25 lp
- B007070298 Status Deficiency Rept 3 re inadequate GA program for nonpressure retaining parts & components Detail of AE investigation under evaluation Final rept will be forwarded by B0072B
 - by BG0728 MCGAUGHY, J.P. Mississippi Power & Light Co. BO/06/27 2pp
- 8007110413 Forwards final deficiency rept re mod to Dragon Valves, Inc. valve manifolds MCGAUGHY.JP Hississippi Power & Light Co 80/07/02 2pp
- --8007110417 Final deficiency rept re mod to Dragon Valves, Inc. valve manifolds Failure of valve would not cause malfunction during emergency operation of standby liquid control sys & not considered reportable per 100FR50 55(e)

 * Mississippi Power & Light Co 80/07/02 2pp
- 8007110430 Status Rept 1 re procedural violation in cutting rebar Stop work order issued on 800530 to stop hole drilling operations for electrical support Craft & field engineering personnel trained Final rept will be submitted by 800117 MCGAUGHY.J P Mississippi Power & Light Co 80/07/02 2pp
- 8007150093 Part 21 rept.supplementing info previously filed under IOCFR50 55(e).re Rosemount. Inc Model 51000 master & slave trip units Info should have been included in review of deficiency repts filed since 1977 MCGAUGHY.J P Mississippi Power & Light Co 80/07/02 9pp
- BOO7150079 Part 21 rept. supplementing info previously filed under 10CFR5D 55(e).re Gould-Brown Boveri solid-state trip devices Rept should have been included in review of deficiencies filed since 1977 MCGAUGHY.J P Mississippi Power & Light Co 80/07/02 4pp
- 8007150105 Part 21 rept, supplementing info previously filed under 10CFR50 55(e).re Westinghouse electrical penetration assemblies Rept should have been included in review of deficiencies filed since 1977 MCGAUGHY.J P Mississippi Powor & Light Co 80/07/02 4pp
- G007170396 Forwards Final Deficiency Rept PRD-B0/26 re defective GE SB-12 switches; orginally reported 800512 Rept on applicability of 10CFR21 will be submitted upon completion of evaluation MCGAUGHY, J.P. Mississippi Power & Light Co. 80/07/10 1p
- ---B007170400 Final Deficiency Rept PRD-80-24 re defective GE SD-12 switches identified in IE Circular 79-17 Switches found to be installed in switchgear supplied by vendor Vendor will furnish new switches to correct condition # Mississippi Power & Light Co 80/07/10 ip
- 8007170290 Forwards first Interim Deficiency Rept PRD-80/32 re standby svc water sys design deficiency Final rept will be submitted by 801020 MCGAUGHY, J P Mississippi Power & Light Co 80/07/11 ip
- --B007170274 First Interim Deficiency Rept PRD-B0/32 re standby svc water sys design deficiency Debris picked up by standby svc water & HPCB svc water pumps transferred into sys No provision exists for filtering Sys design will be analyzed & Mississippi Power & Light Co. B0/07/11 1p

- 8007170435 First interim deficiency rept (PRD-80/31) re failure of HPCB switchgoar to comply w/seismic requirements NSSS vendor evaluation of effects on safety has not been completed Final rept will be submitted by 800923 MCGAUGHY, J P Mississippi Power & Light Co 80/07/11 ip
- BOO722038B Status Deficiency Rept 6 re failure to establish GA program GE has not completed review of insp results & evaluation of safety implications Final rept to be provided by BOO908 MCGAUGHY, J P Mississippi Power & Light Co BO/07/14 2pp
- 80072203B9 Status Deficiency Rept 2 re damage to intermediate metallic conduit Extent & safety implications remain under investigation Final rept to be provided no later than 801006 MCGAUGHY.J.P. Mississippi Power & Light Co. 80/07/15 3pp
- 8007230510 Status Rept 2 to deficiency rept re design nomographs related to ITT General Controls hydramotor electrohydraulic actuators Evaluation by NSSS vendor incomplete Final rept should be forwarded by 800915 MCGAUGHY, J P Missiasippi Power & Light Co 80/07/21 2pp
- --8007250520 Responds to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies." Two NH90 series hydramotor actuators in use, Evaluation indicates that no mode required DALE.L.F. Hississippi Power & Light Co. 80/06/16 2pp
- 8007280866 Potential deficiency rept re nonconformences associated w/calibr svcs provided by Computer Sciences Corp Nonconformances noted during util Apr 1780 audit of calibr facility Final rept will be submitted by 800822 MCGAUGHY, J F Mississippi Power & Light Co 80/07/22 lp
- 8007290655 Provides status of potentially reportable deficiency re fractured value body on jacketwater thermostatic value of standby dissel generator Magnetic particle examination performed Reportability will be determined by 801010 MCGAUGHY, J P Mississippi Power & Light Co 80/07/23 2pp
- 8007270666 Forwards Status Rept 2 of potentially reportable deficiency re maifunctions of Limitorque valve operators Caused by excessive threading of stem protectors Final rept by 801103 MCGAUGHY. P Mississippi Power & Light Co 80/07/23 Zpp
- B007290671 Forwards status of potentially reportable deficiency re incorrect translation of weld requirements from design drawings to field sketches Investigation continuing Final rept will be submitted by B00917 MCGAUGHY.J P Mississippi Power & Light Co B0/07/23 2pp
- 8007290714 Provides status of potentially reportable deficiency reloss of offsite power accident & offects on rod position sys & neutron monitoring sys Deficiency still under investigation Final rept will be provided by 801230 MCGAUGHY. J P Mississippi Power & Light Co 80/07/23 2pp
- 8007290791 Deficiency Status Rept 1 re damaged stator coil for standby diesel generator Deficiency investigation incomplete Repurtability determination & final rept will be submitted by 801217 MCGAUGHY.J P Mississippi Power & Light Co 80/07/23 1p
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage decuments & correspondence
- 8007160610 Forwards correction to fuel load date in 800514 ltr Correct date for Unit 1 is 810831 DALE.L F Mississippi Power & Light Co 80/06/11 ip
- --8007160617 Corrects 800814 ltr requesting updated & complete schedule of safety review Correct fuel load date is 810831 DALE:t. F. Mississippi Power & Light Co. 80/05/14 ip
- BO07010237 Forwards NRC reorganization chart of Dfc of Nuclear Reactor Regulation, effective B00428 Facility activities should be made through assigned mgt representative Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- B007010087 Notification of 800708 meeting w/vtil,BNWL,GE & Bechtel Power Corp in Gaithersburg,MD to review Mechanical Engineering Branch draft SER HDUOHTON,T C Licensing Branch 3 80/06/16 3pp

- BOO7010100 Notification of 800625 meeting w/util.GE.Bechtel Power Corp & Savannah River Lab in Gaithersburg.HD to discuss FSAR Section 7, "Instrumentation & Control" HOUGHION.T C Licensing Branch 3 80/06/14 2pp Licensing Branch 3 80/06/16 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0674
 EIGENVILD O Division of Licensing 80/06/26 2pp

- 8007030245 Forwards structural drawings supplementing technical info submitted on 800527 & 0606 DALE, L F Mississippi Power & Light Co 80/06/30 2pp
- --8007030248 Package of 72 structural drawings to be recalled at later date for microfilming # Bechtel Corp 80/06/30 72pp
- 8007240287 Summary of 800623 meeting w/applicant in Gaithersburg.MD re instrumentation & control sys questions & response & discussion of review schedule HONOHTON.T C Licensing Branch 3 80/07/03 7pp
- 8007280494 Forwards response to 10 remaining open issues in draft BER Info covers seismic subsystem analysis, acceptance criteria for steady state piping vibration & preservice & inservice pump & valve testing DALE.L F Mississippi Power & Light Co 80/07/08 13pp
- 8007220569 Forwards "Cultural Resources Survey of Ray Braswell Transmission Line Route, Warren & Claiborne Counties, MS," NRC 800118 request E.L.F Mississippi Power & Light Co 80/07/17 1p
- ---B007220573 "Cultural Resources Survey of Ray Braşwell Transmission Line Route Warpen & Clasborne Counties, MS " D'HEAR.J W , ATKINBON.J P Mississippi Power & Light Co B0/06/09 22pp
- 8007290322 Forwards comments to amplify previous questions re instrumentation & controls raised at 800625 meeting SCHWENCER.A Licensing Branch 3 80/07/21 3pp
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- B007070245 Forwards response to open issues for use at 800700 meeting w/Methanical Engineering Branch re draft SER for FSAR Sections 3 6-3 io Responses to remaining ten issues will be provided on 800707 DALE, L.F. Mississippi Power & Light Co. 80/07/02 24pp
- 8007140368 Forwards partial transmittal of responses to draft SER for FSAR Sections 3 6-3 10
 DALE-L F Mississippi Power & Light Co 80/07/00 13pp
- F Security, medical, emergency & fire protection plans
- 8007010361 Forwards emergency & radiological response plans for State of MS.Port Gibson/Claiborne County.MS. & State of LA.in support of util revised emergency plan submitted on 800627 as part of Amend 40 to FSAR DALE.L F Mississippi Power & Light Co 80/06/27 2pp
- 8007180273 Forwards response to NRC 800702 ltr re estimated evacuation times for 10-mile emergency planning zone prepared by Clairborne County.MS & Tensas ParrishtLA.encl Mississipp: Power & Light Co 80/07/11 33pp
- O Adjudicatory correspondence
- B007310243 Forwards Commission B00927 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 potition sought action re fire protection for electrical cables EISENHUT.D O Division of Licensing 80/04/25 89pp
- K, Utility Final Bafety Analysis Report (FSAR) & amonds
- 8006300379 Forwards Amend 40 to application for OLs for Licenses CPPR-11B & CPPR-119, consisting of revisions to FSAR. App 9B STAMPLEY.N L Mississippi Power & Light Co 80/06/27 lp
- ---8006300382 Amend 40 to application for DLs for Licenses CPPR-118 & CPPR-119, consisting of revisions to FSAR App 98 Certificate of Syt encl. BTAMPLEY,N L Mississippi Pawer & Light Co 80/06/27 2pp

- --B006300384 Amend 40 to FSAR, providing revisions to fire protection plan
- 9007110412 Forwards affidavit of svc for Amend 40 to FSAR, ser NRC 780627 Itr DALE: L. F. Mississippi Power & Light Co. 80/07/07 2pp
- @ Inspection reports: IE Bulletins & correspondence
- 8007240218 Forward» IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08
- 8007140484 Forwards IE Bulletin 80-13, "Crarking in Core Spray Spargers " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director BO/05/12
- 8007010250 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No writton response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/29
- 8007220078 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required O'REILLY, J & Region 2, Atlanta, Office of the Director 80/06/10
- B007160278 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required O'REILLY,JP Region 2, Atlanta, Office of the Director BO/06/11
- 8007140299 Forwards IE Bulletin GO-14, "Degradation of BWR Scram Discharge Vol Cagability " No written response required O'REILLY: J P Region 2. Atlanta, Office of the Director 80/06/12
- 8007250377 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR90 55(e)" No written response required U'REILLY/J P Region 2, Atlanta, Office of the Director 80/06/13
- 8007020374 Forwards IE Circular 80-15. "Loss of Reactor Coplant Pump Copling & Natural Circulation Cooldown" No writton response required D'RETLLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- B007310240 Forwards IE lnsp Hepts 50-416/80-13 & 50-417/80-09 on B00603-06 No noncompliance noted MURPHY,C C Region 2. Atlanta. Reactor Construction & Engineering Support Branch B0/06/23 2pp
- ---B007310245 IE Insp Repts 50-416/B0-13 & 50-417/B0-09 on B00603-06
 No noncompliance noted Major areas inspected radiography,
 welding, pitrasonic exemination & previous insp findings
 HERDT, A R Region P. Atlanta, Reactor Construction & Engineering
 Support Branch VANDORN, P. K., ZA, JAC. D. Region 2, Atlanta,
 Office of the Director B0/06/20 App
- 8007160789 Forwards IE Circular 80-14, "Additionative Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " No written response required D'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/2
- 8007230213 Forwards IE Bulletin 80-i6, "Potential Misapplication of Resembunt Inc Models 1151 to 1152 Pressure Transmitters W/Elther A or D Dutput Codes " Written response required IE Circular 80-16 also enri No written response required D'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/6
- 8007210270 Responds to IE Bulletin 80-08. "Examination of Containment Liner Penetration Wolds " Evaluation but complete Requests extension to 800815 DALE, L.F. Mississippi Power & Light Co. 80/07/03 1p

- 8 Reportable occurrences, LERs & related correspondence
- B007020615 Status deficiency rept re effects of loss of site power on rod position indication & neutron monitoring Deficiency still under investigation Final rept will be forwarded on 800702 DALE/L F Mississippi Power * Light Co 80/05/21 2pp
- 8007170592 Part 21 rept re potentially defective diesel generator control panels mfg by Intl Control & Switchgear Co Insp underway to determine applicability of deficiency Final rept will be submitted by 800625 MCGAUGHY. J P Hississippi Power & Light Co 80/05/22 2pp
- 8007160885 Interim deficiency rept re incorrect pipe supplied by TX Pipe Bonding Hoavier wall would not cause overstressed condition Generic implications in other applications under investigation Final rept will be submitted by 800829 MCGAUGHY, J P Mississippi Power & Light Co 60/05/23 2pp
- B007i60642 Serond interim deficiency rept (PRD-B0/07) re inadequate Fisher Controls GA program to safety-related controls for numpressure retaining parts & components GA program evaluation continues final rept will be submitted by B00626 MCGAUGHY, J P Mississippi Power & Light Co 60/05/23 ip
- BOO70205/9 Status Deficiency Rept 4 re GE failure to implement proper GA program for electrical work Util is reviewing reinsb of GA program Final rept will be submitted by BOO714 MCGAUGHY.JP Hississippi Power & Light Co BO/05/20 2pp
- FIGOTO20640 Status Deficiency Rept 2 re mod to dragon valve manifolds Review of application of valve manifolds & safety-related impact still under investigation Final rept will be forwarded by 800702 MCGAUHY, J P Mississippi Power & Light Co 80/06/02 2pp
- BOO7160611 Interim deficiency tent re mods to Dragon valve manifolds
 Review of MCAR-GONS 26 in M Couge BOO306 site inspiconcluded
 that deficiency was improperly evaluated final rept will be
 submitted by BOO702
 MCGAUGHY.JP Mississippi Powrt & Light Co BO/06/02 2pp
- 8007020601 Forwards interim deficiency rept re QE feilure to provide qualified instrumentation in safety-related sys MCGAUGHY, J P. Mississippi Power & Light Co. 60/06/13 2pp
- --8007020603 Interim deficiency rept re GE failure to provide seismically & environmentally qualified instruments for use in nuclear safety-related sys in balance-of-plant power generation control complex Corrective action plan expected by 800711 * Mississippi Power & Light Co 80/06/13 4pp
- B00702053B Forwards interim deficiency rept (PRD-B0/11) re Rosemount Model 510 DU trip unit & final deficiency rept (PRD-B0/11) re Model 1152 pressure transmitters MCGAUGHY, J P Mississippi Power & Light Co 80/06/24 2pp
- --8007020537 Final deficiency rept (PRD-80/11) re Model 1152 pressure transmitter w/common mode failure of capacitor at greater than 1/5 F or when damping patentionactor is rotated clockwise OE issued faild disposition instructions # Mississippi Power & Light Co 80/06/24 1p
- --BG07020541 Interim rept (PRD-80/11) re Rosemount Model 510 DU trip/ collibr unit w/common mode failure of escential switch that determines trip output logic GE has issued field disposition instructions for onsite repair * Mississippi Power & Light Co 80/06/24 ip
- 8007020630 Forwards final deficiency rept re defects in dissal generator control panels MCGAUGHY, J.P. Mississippi Power & Light Co. 80/06/25 ip
- --8007020632 Final deficiency rept re defects in diesel generator control panels m/g by Intl Control & Switchgear Co Equipment being repaired by Morrison-Knodsen GA activity will be increased Applicability of 1007881 under evaluation # Mississippi Fower & Light Co 80/06/25 ip
- 8007070298 Status Difficiency Rept 3 re inadequate GA program for nonpressure retaining parts & components Detail of AE investigation under evaluation Final rupt will be forwarded by 800728 MCGAUGHY.J P Mississippi Power & Light Co 80/06/27 2pp
- 8007110413 Forwards final deficiency rept re mod to Dragon Valves, Inc. valve manifolds
 MCGAUGHT, J P Mississippi Power & Light Co 80/07/02 2pp

- --8007110417 Final deficiency rept re mod to Dragon Valves, Inc. valve manifolds Failure of valve would not cause malfunction during emorgency operation of standby liquid control sys & not considered reportable per 100(PA50 55(e) * Mississippi Power & Light Co 80/07/02 2pp
- 8007110430 Status Rept 1 re procedural violation in cutting rebar Stop work order issued on 800530 to stop hole drilling operations for electrical support Craft & field engineering personnel trained final rept will be submitted by 800117 MCGAUGHY.JP Mississippi Power & Light Co 80/07/02 2pp
- B007150093 Part 21 rept, supplementing info previously filed under 1QCFR50 55(e), re Rosemount, Inc Model 510DU master & slave trip units Info should have been included in review of deficiency repts filed since 1977
 MCGAUGHY, J P Mississippi Power & Light Co \$00/07/02 9pp
- B007150099 Part 21 rept, supplementing info previously filed under 10CFR50 55(e), re Gould-Brown Bovori solid-state trip devices Rept should have been included in review of deficiencies filed since 1977

 MCGAUGHY, J P Mississippi Power & Light Co 80/07/02 4pp
- 8007190105 Part 21 rept, supplementing info previously filed under 10CFR50 59(e), re Westinghouse electrical penetration assemblies Rept should have been included in review of deficiencies filed since 1977
 MCGAUGHY, J P Mississippi Power & Light Co 80/07/02 4pp
- 8007170376 Forwards Final Deficiency Rept PRD-80/26 re defective QE 88-12 switches orginally reported 800912 Rept on applicability of 10CFR21 will be submitted upon completion of evaluation MCGAUGHY.J P Mississippi Power & Light Co 80/07/10 ip
- --B007170400 Final Deficiency Rept PRD-80-26 re defective GE 88-12 switches identified in IE Circular 79-17 Switches found to be installed in suitchgear supplied by vendor Vendor will furnish new switches to correct condition # Mississippi Power & Light Co 80/07/10 1p
- 8007170290 Forwards first Interim Deficiency Rept PRD-80/32 re standby svc water syb design deficiency Final rept will be submitted by 801020 MCGAUGHY.J P Mississippi Power & Light Co 80/07/11 ip
- --8007170294 First Interim Deficiency Rept PRD-80/32 re standby syc water sys design deficiency Debris picked up by standby syc water & HPCS syc water pumps transferred into sys No provision exists for filtering Sys design will be analyzed # Mississippi Power & Light Co 80/07/11 ip
- B007170435 First interim deficiency rept (PRD-80/31) re failure of HPCB switchgear to comply w/solamic requirements NBSS vendor evaluation of effects on safety has not been completed Final rept will be submitted by 800923 MCGAUGHY, J.P. Mississippi Power & Light Co. 80/07/11 ip
- B0072203BB Status Deficiency Rept & ro failure to establish QA program QE has not completed review of insp results & evaluation of safety implications Final rept to be provided by E0090B.

 MCGAUGHY, J P Mississippi Powor & Light Co B0/07/14 2pp
- 8007220389 Status Deficioncy Rept 2 re damage to intermediate metallic conduit Extent & safety implications remain under investigation Final rept to be provided no later than 801006 MCGAUGHY.J P Mississippi Power & Light Co 80/07/19 3pp
- H007230510 Status Rept 2 to deficiency rept re design nomographs related to ITT Coneral Controls hydramotor electrohydraulic actuators Evaluation by NSSS vendor incomplete, Final rept should be forwarded by 800915
 MCGAUGHY, J P Mississippi Power & Light Co 80/07/21 2pp
- --8007250520 Responds to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies " Two NH90 series hydramotor actuators in use Evaluation indicates that no mods required OALE.L.F Hississippi Power & Light Co 80/05/15 2pp
- B007280566 Potential deficiency rept re nonconformances associated w/calibr sycs provided by Computer Sciences Corp Nonconformances noted during util Apr 1980 audit of calibr facility Final rept will be submitted by B00822. MCGAUGHY.J P Mississippi Power & Light Co 80/07/22 lp

- **O7290655 Provides status of potentially reportable deficiency refractured valve body on jacketuater thermostatic valve of **tandby diesel generator Magnetic particle examination **Performed.Reportability will be determined by 801010 **CAUGHY.JP **Mississpoi Power & Light Co **80707/23 **2pp
- >O>290666 Forwards Status Ropt 2 of potentially reportable deficiency for malfunctions of Limitorque valve operators Caused by excessive threading of stem protectors Final rept by 801103 PGGAUGHY, J P Hississippi Power & Light Co 80/07/23 25p
- PO7290671 Forwards status of potentially reportable deficiency re incorrect translation of weld requirements from design drawings to field sketches Investigation continuing Final trapt will be submitted by 800917 at 1000117 Mississippi Power & Light Co. 80/07/23 2pp
- PO7290714 Provides status of potentially reportable deficiency reliques of offsite power accident & affects on red position mays & neutron monitoring sys Deficiency still under threstigation final rept will be provided by 801230 Property. J P Mississippi Power & Light Co 80/07/23 2pp
- DO7290791 Deficiency Status Rept 1 re damaged stator coil for standby diesel generator Deficiency investigation incomplete Reportability determination & final rept will be submitted by 801217
 PCGAUGHY.J P Mississippi Power & Light Co 80/07/23 1p
- DCMET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
 - Application/construction stage documents & correspondence
- DO7230001 forwards statement of policy re requirements to be met for Current OL applications, as derived from NUREO-0660 & found in NUREO-0694
 EISENNUT, D G Division of Licensing 80/06/26 2pp
- Adjudicatory Correspondence
- OO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action the fire protection for electrical cables EISENHUT.D G. Division of Licensing 80/06/25 89pp
- . Financial information
- O-O-7150622 Forwards 1980 cash flow estimates for CT Light & Power Co.
 Hartford Electric Light Co & Hestern MA Electric Co Cash
 flows are adequate to meet potential premium requirements
 for 1975 amends to Price-Anderson Act
 D: CONNOR. L A Northeast Utilities 80/07/03, 2pp
- . Imspection reports. IE Bulletins & correspondence
- O-O-7010312 Forwards IE Info Notice BD-23, "Lpss of Suction to Emergency Fewedwater Pumps" No written response required O-RIER, BH Region 1. Philadelphia, Office of the Director BO-705/29 1p
- ICOP7170519 Forwards response to IE Bulletin BO-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Bys (CVCB)
 Holdup Tanks "Provides list of sys in facility containing tanks that can be valved to contain primary sys water COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) BO/06/09 7pp
- CO7210880 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs." No written response required ORIER, BH Region 1. Philadelphia, Office of the Director BO/Q6/10 1p
- PO7160337 Forwards IE Info Notice BO-27, "Degradation of Reactor Coplant Pump Studs " No specific action or response required QRIER B H. Region 1. Philadelphia. Office of the Director (20/06/11) ip
- ### O 7280600 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance #/10CFR50 55(e)" No written response required, OFIER.B H Region i, Philadelphia, Office of the Director, 80/06/13

- 8007010354 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" No ITT General Controls Model AH-90 % NH-90 hydramotor actuators have been purchased for use at util COUNSIL.M g Northeast Nuclear Energy Co (subs of Northeast Utilities) 80/06/16 2pp
- B007020494 Forwards IE Circular B0-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/04/20 ip
- B007i60734 Forwards IE Circula: B0-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER: B H Region 1, Philadelphia. Office of the Birector B0/06/24 1:
- B007210207 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director B0/06/25 1p
- B007230146 Forwards IE Bulletin B0-16, "Potential Misapplication of Rosemount Inc Hodels i151 k 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also enci No written response required GRIER. B H Region 1. Philadelphia. Office of the Director B0/06/27 2pp
- 8007210533 Forwards IE Insp Rept 50-423/80-03 on 900423 No noncompliance noted CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/12 2pp
- --B007210545 IE Insp Rept 50-423/80-03 on 800423 No noncompliance noted Major areas insported containment & reactor area.control bldg.turbine bldg & other svc areas Newly assigned inspector introduced CERNE.A C , FEIL.R Region I, Philadelphia, Office of the Director MCGAVGHY.R W Region I, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/10 3pp
- S Reportable occurrences, LERs & related correspondence
- BOO7210457 Ack receipt of BOO614 deficiency rept to possible inadequacy of charging pumps following secondary sys high energy line rupture CARLBON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/01 1p
- --B007210320 Interim deficiency rept confirming B00515 telcon
 Westinghouse centrifugal charging pumps may not deliver min
 flow at valve set goint pressure Action will be delayed
 until Westinghouse analysis completed
 COUNSILW 6 Northeast Nuclear Energy Co (subs of Northeast
 Utilities) B0/06/14 ip
- DOCKET 50-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT | A Application/cunstruction stage documents & correspondence
- BO07230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D G Division of Licensing 80/06/26 2pp
- F Security, medical, emergency & fire protection plans
- B007290774 Forwards evacuation time estimates per NRC 791226 & 800702 requests EHRENSPERGER, W. Georgia Power Cn. 80/07/23 ip
- G Adjudacatory correspondence
- 8007310243 Forwards Commission 800827 memorandus & order containing decisions on UCS 780802 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT D O Division of Licensing 80706728 89pp

H General correspondence

- 9007090344 Requests that NRC revise correspondence distribution. changing addressee to WE Entensperger EMRENSPERGER, W. Georgia Power Co. 80/06/30 tp
- Q Inspection reports. IE Bulletins & correspondence
- 8007240213 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required G'REILLY, J P. Region 2. Atlanta. Office of the Director 80/05/08
- B00721046B Forwards IE Circular 80~13, "Orid Strap Damage in Westinghouse Fuel Assemblies" No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director E 80/05/28
- 8007010220 Forwards 1E Info Notice 80-23, "Loss of Surtion to Emergency Feedwater Pumps " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007220072 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required O'REILLY-U P Region 2, Atlanta, Office of the Director 80/06/10
- 8007140274 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/11
- B007250375 Forwards IL Info Notice B0-28, "Prompt Reporting of Info in Accordance W/10CFR50 95(e)" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director B0/06/13
- 8007020218 Responds to IE Bulletin 80-09, "Mydromotor Actuator Deficiencies" Util does not use ITT General Controls AK90 series hydromotor actuators for any safety-related sys or DUTTON, D Georgia Power Co 80/06/14 2pp
- B007290409 Forwards IE Insp Repts 50-424/80-09 & 50-425/80-09 on 800522 & 23 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 80/06/16 2pp
- --8007290414 IE Insp Repts 50-424/80-09 & 50-425/80-09 on 800522 & 23 No noncompliance noted Major area inspected licenses identified
 litem re erosion of Category | backfill
 CONLON.F Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch HARRIS.J R Region 2. Atlanta Coffice of the 80/04/13
- B007020450 Forwards IE fircular B0-15, "loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20

8007110315 Ack receipt of 800605 ltr informing NRC of steps taken to correct viulation noted in IE Insp Repts 50-424/80-07 & 50-425/80-07 MURPHY, C.E. Region J. Atlanta, Reactor Construction & Engineering

Support Branch 90/04/24

- ~~8007110521 Responds to NRC 800501 ltr re violation noted in IE Insp Repts 30-424/80 07 4 50-425/80-07 Corrective actions records from Sept 19 10-Apr 1980 were reviewed & correlation curves were generated & evaluated DUTTON.D Georgia Power Co 80/06/05 2pp
- --8007110527 Forward: IE Insp Repts 50-424/80-07 & 50-425/80-07 on 800414-16 & notice of violation HURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 50/05/01 2pp
- --8007110531 Notice of violation from insp on 900414-16
 * Region 2. Atlanta, Office of the Director 80/0 BO/05/01 1p

- -860/110536 IE Insp Repts 50-424/80-07 & 90-429/80-07 on 800**414-16** Noncompliance noted failure to evaluate moisture check test results LENAHAN, J. Region 2, Atlanta, Office of the Director CANLUN, L. E. Region 2, Atlanta, Heactor Construction & Engineering Support Branch 80/05/01 5pp
- 80071/0119 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 89s & Resultant Internal Contamination of Personnel" No written response required O'REILLV.J P. Region 2, Atlanta, Office of the Director 80/06/2 80/05/24
- 8007220275 Responds to IE Bulletin 80-08 Flued head panetration walds installed & examined according to ASME requirements DUTTON,D Georgia Power Co 80/06/26 2pp
- 8007230249 Forwards IE Bulletin 80-16, "Putential Misapplication of Rosempurt Inc Models 1991 & 1952 Prossure Transmitters W/Either A or D Output Codes " Writton response required IE Greular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/2 80/04/27
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2 A Application/construction stage decuments & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694 EIBENHUT, D G Division of Licensing 80/04/24 Ppp
- F Security, medical, emergency & fire protection plans
- 8007290774 Forwards evacuation time estimates per NRC 791226 & 800702 EHRENSPERGER. W. Georgia Power Co. 80/07/23 1p
- --8007290777 Evacuation time estimates for facilities Maps encl * Georgia Power Co 80/0//23 App
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 8005// memorandum & order containing decisions on UCS /80502 petition for reconsideration of 780413 memorandum & order US //1104 petition sought action to fire protection for electrical colles
- H General correspondence
- 8007080344 Requests that NRC revise correspondence distribution. Changing addresses to WE Ehrensperger EHRENGPERGER.W. Georgia Power to 80708730 ip
- a Inspection reports. It Bulleting & currespondence
- 800/240213 Forwards IL Info Notice 80 20, "Loan of Decay Heat Removal Capability at Davis-Basso Unit I While in Refueling Mode "No response required No response required O'REILLY, J.P. Region P, Atlanta Office of the Director 180/05/00 Region 2, Atlanta Office of the Director 180/05/08 Zpp
- 800/210468 Forwards It Circular 90 1%, "Grid Strap Damage in Hastinghouse Fuel Assemblies" No written insponse required O'REILLY, J.P. Rugion 2, Atlanta, Affice of the Director 60705728
- 8007010220 Forwards IE Info Motice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REHLY, J.P. Region 2, Atlanta, Office of the Director 60/03/29
- B007220072 Forwards to Info Notice 80-26, "Eviluation of Contractor OA Programs" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director H0/06/10
- 8007160274 Forwards IF Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific artion or response required
 O'REILLY, J.P. Rogson 2, Atlanta, Office of the Director 80/06/11

- 8007250375 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/13 2pp
- 8007020218 Responds to IE Sulletin 80-09. "Hydromotor Actuator Deficiencies" Util does not use IFT General Controls AM90 series hydramotor actuators for any safety-related sys or components
 DUTTON D Georgia Power Co 80/06/16 2pp
- 8007290409 Forwards IE Insp Repts 50-424/80-09 & 50-425/80-09 on 800522 & 23 No noncompliance noted MARPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/14 2pp
- --B007290414 IE Insp Repts 50-424/80-09 & 50-425/80-09 on 800522 & 23 No noncompliance noted Major area inspected licenses identified item re erosion of Category I backfill CONLON.TE Region 2. Atlanta. Reactor Construction & Engineering Support Branch HARRIS.JR Region 2. Atlanta, Office of the Director B0/06/13 2pp
- 8007020450 Forwards IE Circular BO-15, "Loss of Reactor Coplant Pump Gooling & Natural Circulation Cooldown" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007110515 Ack receipt of 800405 ltr informing NRC of steps taken to currect violation noted in IE Insp Repts 50-424/80-07 & 50-425/80-07 MRPPN,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/24 ip
- --8007110521 Responds to NRC 800501 ltr re violation noted in IE Inap Repts 50-424/80-07 t 50-425/80-07 corrective actions records from Bept 1979-Apr 1980 were reviewed & correlation curves were generated & evaluated DUTTON: D Georgia Power Co 80/06/05 2pp
- --8007110527 Forwards IE Insp Repts 30-424/80-07 & 50-425/80-07 on 800414-16 & notice of violation MAPPy CE Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/01 2pp
- --8007110531 Notice of vialation from imap on 800414-16
 * Region 2, Atlanta, Office of the Director 80/05/01 lp
- --8007110336 IE Insp Repts 50-424/80-07 & 50-425/80-07 on B00414-16 Noncompliance noted failure to evaluate moisture check test results LENAHAN.J Region 2, Atlanta, Office of the Director CANLON,L E Region 2, Atlanta, Reactor Construction & Engineering Rupport Branch B0/05/01 Spp
- 8007170115 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required O'REIULY. J P Region 2. Atlanta. Office of the Director 80/06/24 ip
- 800/220275 Responds to IE Bulletin 80-08 Flyed hoad panetration welds installed & examined according to ASME requirements
 DUTTON.D Georgia Power Co 80/06/26 2pp
- 8007230249 Forwards IE Bullstin 80-16. "Potential Misapplication of Rosenount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Written response required IE Circular 80-16 also encil No written response required C'REILLY. J P Region 2. Atlants. Office of the Director 80/06/27
- DOCKET 50-433 UC-SANTA BARBARA RESEARCH REACTOR

 O Inspection reports, IE Bulletins & correspondence
- 8007180263 Forwards IE Circular 80-14. "Radinactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personne) " No written response required ENGELKENR II Region 5, San Francisco. Office of the Director 80/06/24 ip

- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- A Applacation/construction stage documents & correspondence
- 8007020566 Submits summary of 800613 meeting for W Butler briefir Commissioner Gilinsky on alternate methods for controlling hydrogen in ice condenser containment Serves as notification for parties to floating nuclear plant proceeding AUSTIN, J H Property & Supply Branch 80/06/26 19
- 8007230001 Forwards statement of policy reliequirements to be met current DL applicitions as derived from NUREG-0640 & found in NUREG-06494 EISENHUT. D.C. Division of Licensine 80/06/26 20a
- 8007210395 Forwards 36AF3, "OPS Responses to Post-TNI NRC Requirements," Revision 1 Rept represents vast anjority of new info required to support issuance of mgt license Requests meeting w/NRC at earliest possible convenience HAGGA,P B Offshore Power Systems (subs of Westinghouse Electr Corp.) 80/07/15 3pp
- --8007210404 "OPS Responses to Post-TMT NRC Requirements " Revisi
 * Offshare Power Systems (subs of Hestinghouse Electric Corp.
 36473 R1 80/07/31 122pp
- Q Adjudicatory correspondence
- B007310243 Forwards Commission 800327 momorandum & order containing decisions on UCS 780502 petition for reconsideration of 760413 memorandum & order UCS 771104 petition sought action as fire protection for electrical cables EISENHU1.0 G Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007150019 Ack receipt of encl 800407 ltm to President Carter reomployment opportunities offered by offshore floating nuclear plant project Decisions on commercial projects are made by private sector, w/NRC approval MATEON, J. H. President of US 9 Executive (liftices 80/05/16 4g
- 8007140106 Ack recript of 800407 ltm to White House Final decision license floating nuclear plants will not be made until roview is complete. ACRS makes finding re safety & ASLB authorizes issuance of license DENTON. H R Office of Noclear Reactor Regulation, Director BO/06/19 Spp
- ---B007140108 Requests reply to CT Brown 800407 ltr expressing supp fluating nuclear power plant project BEAL,N M President of US & Executive Offices 80/05/21 Op
- O Inspection reports. IE Bulletins & correspondence
- 8007240084 Forwards II Info Notice 80-20. "Loss of Decay Hoot Remo Capability at Davis Desse Unit i While in Refueling Mode " No response required O'REILLV-J P Rogion 2, Atlanta, Office of the Director 80/05
- B007210414 Forwards IF Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required O'REILLY, J.P. Region P. Atlanta, Office of the Director 80/0
- 8007010179 Forwards JE Into Notice 80-23, "Loss of Suction to Emer Fooduater Pumps" No written response required D'REJLLY, J.P. Region 2, Atlanta, Défice of the Director 80/03
- 8007220026 Forwards IE Info Natice 80-26, "Fyalvation of Contracto GA Programs " No written response required O'REILLY, J.P. Reginn 2, Atlanta, Office of the Director 80/06, is
- 9007160315 Forwards IE Info Nutice 90-27, 'Degradation of Reactor Coolant Pump Stude ' No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director HO/06,
- 8007250309 Forwards IE Info Nutire 80~20, "Prompt Reporting of Info Accordance W/100FR50 556e)" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06, ip

- 8007020380 Forwards JE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required G'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007170134 Forwards IE Circular B0-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required D'REILLY, J P. Region 2, Atlanta. Office of the Director 80/06/2/
- 8007230199 Forwards IE Bulletin 80-16. "Potential Misapplication of Rusemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Quiput Codes " Written response required IE Circular 80-16 also enci No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/06/27 in
- DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B007010426 Submits info re INRYCO, inc tendon installation operations & related GA/GC activities, in response to NRC BC0424 ltr
 Training activities satisfactorily completed as confirmed in BO0417 telcon Work will be resumed on buttonheading
 MILLS,L M Tennessee Valley Authority B0/06/23 1p
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0674
- EISENHUT. D & Division of Licensing 80/06/26 2pp
- 8007180296 Notification of 800723-24 meeting w/util & ANL in Bethesda, MD to review electrical, instrumentation & control drawings for conformance w/separation, redundancy & single failure criteria BDURNIA: A Licensing Branch 1 80/07/07 4pp
- 8007130546 Advises that facility diesel drawings have been transmitted under separate cover to A Bournia, per NRC 800701 request MILLS.L M Tennessee Valley Authority 80/07/08 ip
- 8007150551 Advises that facility diesel generator frawings are being transmitted under separate cover to 8 Halverson.per NRC request
 MILLS,L M Fennessee Valley Authority 80/07/08 ip
- 8007300080 Forwards request for addl info re QA progrem
 TEDESCO.R L Assistant Director for Licensing 80/07/23 3pp
- Adjudicatory correspondence
- 9007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISEMHUT, D G Division of Licensing 80/06/25 B9pp
- Q. Inspection reports, IE Bulletins & correspondence
- BOO7240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit : While in Refueling Mode" No response required O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/05/08 See
- 8007020192 Forwards IE Info Notice β0-22, "Breakdowns In Contamination Control Programs" No written response required O'RETLLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28 to
- 8007210488 Forwards JE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28 ip
- 8007010225 Forwards IE Info Natice 80-22, "Lose of Buction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29 1p
- 8007220029 Forwards IE Info Notice 80~26, "Evaluation of Contractor GA Programs," No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/10 3nn

- 8007160287 Forwards IE Info Notice 80-27, "Degradation of Reactor Coulant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11 is
- 8007230384 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR30 35(e)" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 90/06/13, 3pp
- 8007270344 Forwards IE Insp Repts 50-438/80-08 & 50-439/80-08 on 800527-30 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/16 2pp
- --8007290361 IE Insp Repts 50-438/80-08 & 50-439/80-08 on 800327-30. No noncompliance noted Major areas inspected containment prestressing, receiving & storage insp & IE Bullatins 79-28 & 80-03 CANTRELL, F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch WRIGHT, R W Region 2, Atlanta, Office of the Director 80/06/16 Spp
- 8007020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Gooldown " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director, 80/04/20,
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel." No written response required. O'REILLY, J. P. Region 2. Atlanta, Office of the Director 80/06/24, to
- 8007230233 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required. IE Circular 80-16 also encl. No written response required. O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/2 in.
- 8007100205 Responds to NRC 800606 ltr re violations noted in IE Insp Repts 50-438/80-07-02,50-439/80-07-02,50-438/80-07-01 & 50-439/80-07-01 Corrective actions welder & rod room attendants retrained to Welding matl control requirements MILL8,L M. Tennessee Valley Authority 80/06/30, 4pp.
- 8007100169 Forwards revision to 800602 response to infraction noted in IE Insp Rept 50-438/80-06 QC Investigation Rept 3619 was written to disposition improperly routed cables. Mork release was written to eliminate conduit misrouting MILLS, L M Tennessee Velley Authority 80/07/01. 3pp.
- 8007210036 Forwards response to IE Bulletin 80-08 re-examination of containment liner penetration walds Panetrations at Sequoyah, Watts Bar & Bellefonte contain flued head design, Design for Yellow Creek not yet completed MILLS, L. M. Tennessee Valley Authority 80/07/08 5pp.
- 8 Reportable occurrences, LERs & related correspondence
- 8007300167 Fourth interim deficiency rept re upper stressing head for rock anchor Util & post-tensioning contractor metallurgical investigations are incomplete Record of matl furnished by contractor will appear in final rept OILLELAND, J E Tennessee Valley Authority 76/04/12, 2pp.
- 8007100233 Forwards interim deficiency rept re const QA audit. MILLS.L M Tennessee Valley Authority 80/06/30 ip
- --8007100236 Interim deficiency rept re failurs to document required insps of all permanent mechanical equipment since Jul 1979 Util reviewing available insp records & reinspecting equipment to determine possible damage # Tennessee Valley Authority 80/06/30 ip
- B007100209 Forwards second interim deficiency rept re const **GA audit** deficiency
 MILLBil M Tennessee Valley Authority B0/07/02, ip.
- --B007100213 Second interim deficiency rept re const @A audit deficiency.
 Welders & foremen retrained on B00522 Plan is being
 developed to ensure training for every certified welder &
 foreman
 * Tennessee Valley Authority B0/07/02. 1p

- 6007160650 Forwards final deficiency rept re violation of Inryco field installation procedures
 HILLS.L.M Tennessee Valley Authority 80/07/07 ip
- --8007160656 Final deficiency rept re violation of Inryco field installation procedures Inryco GC documentation was signed by individuals other than those performing work Util issued stop work order for all quality related work on 800423 * Tennessee Valley Authority 80/07/07 2pp
- 8007160424 Eighth interim deficiency rept re failure of expansion anchors to pass qualification tests final resolution to NCR 871 was provided in 790720 rept NCR 898 will be resolved w/final resolution to IE 801letin 79-02 Next rept by 810114 MILLS.L. M Tennessee Valley Authority 80/07/08 1p
- 8007280660 Suppls 800630 response to deficiency noted in IE Insp Repts 50-438/80-07 & 50-439/80-07 Util is investigating time between discovery of potential concern & issuance MILLS,L M Tennessee Valley Authority 80/07/22 2pp
- 8007270725 Fourth interim deficiency rept re seismic response for primary branch lines Found not conservative for all pipe sizes under 1/2 of BBE loadings per Revisions i & 2 of B&W Spec 1391 Revision 3 to verify response spectra MILLS.L M Tennessee Valley Authority 80/07/23 2pp
- 8007290749 Third interim deficiency rept re two welds found lacking sufficient internal purge, during rework operations of chemical addition & boron recovery sys Caused by inadequate maint. Program being developed to check purging process MILLB.L.M Tennesses Valley Authority 80/07/23 2pp
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 8007230001-Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0674 EIBENAUT, D Q Division of Licensing 80/06/26 2pp
- 8007180276 Notification of 800723-24 meeting w/util & ANL in Bethesda. MD to review electrical instrumentation & control fraulings for conformance w/separation redundancy & single failure BOURNIA, A. Licensing Branch 1 80/07/07 4pp
- 8007150546 Advises that facility diesel drawings have been transmitted under separate cover to A Bournia, per NRC 800701 request MILLS,L M Tennessee Valley Authority 80/07/08 ip
- 8007130551 Advises that facility diesel generator drawings are being transmitted under separate cover to 9 Halverson per NRC request MILLS, L. M. Tennessee Valley Authority 80/07/08 1p
- BOO73000B0 Forwards request for add1 info re GA program TEDESCO.R.L Assistant Director for Licensing 80/07/23 3pp
- 9 Adjudicatory correspondence
- 8007310249 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UGB 771104 petition sought action re fire protection for electrical cables EISENMAT.D.Q. Division of Licensing. 80/06/25 89pp.
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 7905140021 Forwards portion of Bellefonte Subcommitte meeting transcript questioning whether operator could diagnose accident & assess core status.

 BENDER, M ACS Advisory Committee on Reactor Safeguards 79/04/05.
- 9. Inspection reports, IE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/05/08

- 8007210488 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/28
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 8007220029 Forwards 1E Info Notice 80-26. "Evaluation of Contractor OA Programs" No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director 80/04/10
- 8007160287 Forwards IE Info Notice 80-27. "Degradation of Reactor Coplant Pump Studs " No specific action or response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/04/11
- 8007250384 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance M/10CFR50 55(e)" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/13
- 8007290344 Forwards IE Insp Repts 50-438/80-08 % 50-439/80-08 on 800527-30 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/16 2pp
- --8007290361 1E Insp Repts 50-438/80-08 & 50-439/80-08 on 800527-30 No noncompliance noted Major areas inspected containment prestressing receiving & storage insp & IE Bulletins 79-28 & 80-03 80-03 CANTRELL.F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch WRIGHT.R W Region 2, Atlanta, Office of the Director 80/04/14 Spp
- 8007020391 Forwards IC Circular 80-15, "Loss of Reactor Coulant Pump Cooling & Natural Circulation Couldown " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 8007170070 Forwards IE Circular 80-14, "Radicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written rosponse required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/24
- 8007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Notatives robusts to be the bords. Treathers in isappire Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Gutput Codes " Hritten response required IE Circular 80-16 also encl No written response required C/REILLY.J P Region 2. Atlanta. Office of the Director B0/06/27
- 8007100203 Responds to NRC 800606 ltm re violations noted in IE Insp Repts 50-438/80-07-02,50-439/80-07-02,50-438/80-07-01 & 30-439/80-07-01 Corrective actions welder k rod room attendants retrained to welding matl control requirements MILLS, L M Tennessee Valley Authority 80/06/30 App
- 9 Reportable occurrences, LERs & related correspondence
- 8007300167 Fourth interim deficiency rept re upper stressing head for rock anchor Util & post-tensioning contractor metallurgical investigations are incomplete Record of matl furnished by contractor will appear in final rept OILLELAND.JE Tennessee Valley Authority 76/04/12 2pp
- 8007100233 Forwards interim deficiency rept re const 0A audit MILLS,L M Tennessee Valley Authority 80/06/30 ip
- --8007100236 Interim deficiency rept re failure to document required insps of all permanent mechanical equipment since Jul 1979 Util reviewing available insp records & reinspecting equipment to determine possible damage # Tennessee Valley Authority 80/06/30 ip
- 8007100209 Forwards second interim deficiency rept re const QA audit deficiency MILLS.L M Tennessee Valley Authority 80/07/02 ip
- ~-8007100213 Second interim deficiency rept re const QA audit deficiency Welders & foremen retrained on 800522 Plan is being developed to ensure training for every certified welder &
 - Tennessee Valley Authority B0/07/02

- 8007140650 Forwards final deficiency rept re violation of Inryco field installation procedures
 MILLS.L M Tennessee Valley Authority 60/07/07 1p
- --8007160656 Final deficiency rept re violation of Inryco field installation procedures Inryco QC documentation was signed by individuals other than those performing work Util issued stop work order for all quality related work on 800423 * Tennessee Valley Authority 80/07/07 2pp
- B007160424 Eighth interim deficiency rept re failure of expansion anchors to pass qualification tests Final resolution to NCR B71 was provided in 790720 rept NCR 898 will be resolved w/final resolution to IE Bulletin 79-02 Next ispt by 810114 MILLS.L M Tennessee Valley Authority 80/07/08 ip
- 8007280660 Suppls 800630 response to deficiency noted in IE Insp Repts 50-438/80-07 & 50-439/80-07 Util is investigating time between discovery of putential concern & issuance MILLS.L M Temnessee Valley Authority 80/07/22 2pp
- 8007290725 Fourth interim deficiency ropt re sgismic response for primary branch lines Found not conservative for all pipe sizes under 1/2 of SSE loadings per Revisions 1 & 2 of B&W Spec 1391 Revision 3 to verify response spectra MILLS.L M Tennessee Valley Authority 80/07/23 2pp
- 8007270749 Third interim deficiency rept re two welds found lacking sufficient internal purge during rework operations of chemical addition & boron recovery sys Caused by inedequate maint Program being developed to check purging process MILLG.L M Tennessee Valley Authority 80/07/23 2pp
- DOCKET BO-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007020214 Forwards NRC Ofc of Nucleor Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCORL Assistant Director for Licensing 80/06/13 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT,D Q Division of Licensing 80/06/26 2pp
- 8007150540 Submits list of changes util plans to make re environ monitoring program during const Rationale for changes encl DAVIDSON.D R Cleveland Electric Illuminating Co 80/07/07 Spp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007230542 Forwards NRC 1979 Annual Rept in response to 800621 request re progress of nuclear power & regulations on power plants Unit I will start operation in 1984 & Unit 2 in 1988 Cover sheet only encl DENTON, H R OF BO/06/27 2pp Office of Nuclear Reactor Regulation, Director
- BOO7230109 Forwards, under separate cover, acceptance review copy of OL application, consisting of application & environ ropt for placement in Perry, ON Public Library Util will submit FBAR on 800904 for review BOUDER. J. Division of Rules and Records 80/07/07 ip
- M Antitrust correspondence
- B007140231 Forwards Director of Nuclear Reactor Regulation order further modifying B00313 order w/respect to licenses & parmits for facilities BALTZMAN,J Utility finance Branch B0/06/11 1p
- 8007140256 Forwards Director of Nuclear Reactor Regulation order further modifying 800913 order w/respect to licenses & permits for facilities SALTZMAN.J Utility Finance Branch 80/06/11 ip

- --8007140265 Order granting extension until B00709. For Cloveland Floctric Illuminating to to file amend to tariff w/FERC as required by 800513 order DENTON.H R Dffice of Nuclear Reactor Regulation, Director B0/06/11 2pp
- 80071408/5 Conditional request for hearing re Commission 800513 order re mod of transmission tariff Urges mod of order to bring consistency w/FERC tariffs in Opinion 84 or institution of hearing Util protest before FERC & Certificate of Svc encl GOLDBERG, R. WAONER, T. E. Cleveland, CM, GOLDBERG, R. Goldberg, Fieldman & Hjelmfelt 80/07/09 14pp
- @ Inspection reports, IE Bulletins & correspondence
- 8007140551 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers "No written response required KEPPLER,J G Region 3, Chicago, Office of the Director 80/05/12
- 8007090154 Forwards IE Insp Repts 50~440/80-07 & 50-441/80-07 on 800805-07 & notice of violation FIDRELLI,G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --B007090156 Notice of violation from insp on 800505-07 * Region 3. Chicago, Office of the Director 80/0 80/05/19 2pp
- --8007090159 IE Insp Repts 50-440/80-07 & 30-441/80-07 on 800505-07
 Noncompliance noted inadequate issuance of documents,
 inadequate quality records, inadequate instructions & failure
 to follow procedures for soil placement
 HAYES, D.W. Region 3, Chicago, Reactor Construction & Engineering
 Support Branch GALLAOHER, E. J. LANDSMAN, R.L. Region 3, Chicago,
 Office of the Director 80/05/19 App
- 8007090176 Forwards IE Insp Repts 50-440/80-06 & 50-441/80-06 on 800421-24 & notice of violation FIDRELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- --8007090178 Notice of violation from insp on 800421-24 * Region 3, Chicago, Office of the Director 80/0
- --8007090179 IE Insp Repts 50-440/80-06 & 30-441/80-06 on 800421-24
 Noncompliance noted failure to identify component to be
 covered by GA program & inadequate indectrination &
 training of personnel
 HAYES,D W Region 3. Chicago, Reactor Construction & Engineering
 Support Branch HUGHES,J, LANDSMAN,R B Region 3. Chicago.
 Office of the Director 80/05/16 App
- 8007010137 Forwards IE Info Notice 80-23, "Loss of Suction to Emergancy Feedwater Pumps" No written response required KEPPLER, J.G. Region 3, Chicago, Office of the Director 80/05/29
- 8007160725 Forwards IE Insp Repts 50-440/80-08 & 50-441/80-08 on 800506-07 & notice of violation FIGRELLI, 0 Region 3 Chicago, Reactor Construction & Engineering Support Branch 60/04/04 2pp
- --B007160734 Notice of violation from insp on 800506-07 * Region 3, Chicago, Office of the Director B0/0
- --B007160741 IE Insp Repts 50-440/80-08 & 50-441/80-08 on B00506-09 Noncompliance noted failure to specify appropriate codes or stas in purchase order LCE,E W Region 3, Chicago, Office of the Director DANIELSON,D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/02 App
- 8007220178 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/10
- 8007140360 Forwards IE Bulletin 80-14. "Degradation of BWR Beram Discharge Vol Capability " No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/12
- 8007280653 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR90 95(e) " No written response required KEPPLER.J 9 Region 3, Chicago, Office of the Director 80/06/13

- 8007020565 Forwards IE Circular 80-15, "Loss of Reactor Loolant Pump Cooling & Natural Circulation Cooldown" No written response required KEPPLER.J 9 Region 3, Chicago, Office of the Director 80/06/20
- 8007170465 Forwards IE Circular 80-14, "Radigactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KFPPLFR. J @ Ragion 3, Chicago. Office of the Director 80/06/24 io
- 8007230310 Forwards IE Bulletin 80-16, "Potential Misapplication of Resemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/27
- 8007:90353 Submits addl info re response to IE Bulletin 80-09 Litton Industrial Products. Inc & Fisher Co. Inc supplying Model NH-90 series hydramotor actuators Deficiencies described in IE Bulletin 80-09 will not affect performance of valves DAVIDSON, D R Cleveland Electric Illuminating Co 60/07/03 2pp
- 8007230101 Forwards suppl info to 800618 response to IE Bulletin 80-09 re hydramotor actuator deficiencies Litton Industrial Products, Inc. actuators use Number 2 springs & have no possibility of being fabricated from incorrect matl DAVIDSON, D R Cleveland Electric Illuminating Co 80/07/03 2pp
- 8007180588 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-06 & 50-441/80-06 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --B0071B0591 Responds to NRC 800521 ltr re violations noted in IE Insp. Repts 50-440/B0-06 & 50-441/B0-06 Training program complies w/NRC requirements Drawing D-220-002 to be revised to show seismically dequate lighting supports DAVIDBON.D.R Cleveland Electric Illuminating Co B0/06/23 4pp
- B007180406 Forwards response to IE Bulletin 80-08 re examination of containment liner penetration welds Lists penetrations w/ flued head design DAVIDSON.D R Cleveland Electric Illuminating Co 80/07/10 5pp
- 8007180582 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-07 & 50-441/80-07 FIORELI, @ Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/10 ip
- --B0071B05B5 Forwards response to NRC B00521 ltr re violations noted in IE Insp Repts 50-440/B0-07 & 50-441/B0-07 Corrective actions CC Procedure B revised analyzed compaction equipment & GC procedure for soil insp being revised DAVIDBON,D R Cleveland Electric Illuminating Co B0/06/23 App
- B007230313 Ack receipt of B00703 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-08 & 50-441/80-08 FIORELLI-0. Region 3. Chicago. Reactor Construction & Engineering Support Branch
- --B007230321 Responds to NRC 800604 ltr re violations noted in IE Insp Repts 50-440/80-08 & 50-441/80-08 Corrective actions obtained codes & stds for Pullman Power Products welding matl. DAVIDBON.D R Cleveland Electric Illuminating Co 80/07/03 3pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007180495 Ack receipt of 800630 final deficiency rept re Rosemount Model 510 DU trip calibr units/1152 pressure transmitters Review will be completed during future insp. FIURELIT, 6 Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/14 ip
- 8007140534 Part 21 rept re deficiencies of Cutler-Hammer motor control ctrs Causs undetermined Proposes that starter units u/improper wire be returned to manufacturer for rewiring & that splice plate carriage bolts be replaced DAVIDSON, D. R. Cleveland Electric Illuminating Co. 80/06/25, 2pp
- B007080294 Final deficiency rept re Rosemount Models 510 DU trip/calibr Units & 1152 pressure transmitters Originally reported by GE per Part 21 in May 1780 Amplifier boards & trip units will be replaced beginning Sept 1780 w/completion by 810101 DAVIDSON: D R Cleveland Electric Illuminating Co 80/06/30 2pp

- 800716059B Interim deficiency cept re use of Mone-sol 7-0015-7 CWS polyvinyl alchohol film, water soluble purge dam matl Util is in process of identifying deficient matl & having chemical analysis performed hinal rept provided by 801215 DAVIDSON, D.R. Cleveland Electric Illuminating Co. 80/07/11 3pp
- 8007180545 Ack receipt of 800625 interim deficiency rept re Cutler-Hammer mater control ctrs Final rept will be reviewed upon receipt FIDRELLI, G Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80707714 ip
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007020214 Forwards NRC OFc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to engoing activities TEDEBCO, R L Assistant Director for Licensing 80/06/13 2pp
- 8007230001 Forwards statement of policy ro requirements to be met for current OL applications as derived from NURCG-0660 & found in NURCG-0674
 EISENHUT, D O Division of Licensing 80/06/26 2pp
- 8007150940 Submits list of changes util plans to make re environ monitoring program during const Rationale for changes encl DAVIDSION, D R Cleveland Electric Illuminating Co 80/07/07 5pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCG 780902 pottton for reconsideration of 780943 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT,D Q Division of Licensing 80706/25 87pp
- H Conoral correspondence
- B007230542 Forwards NRC 1979 Annual Rept in response to B00621 request re-progress of nuclear power & regulations on power plants Unit i will start operation in 1984 & Unit 2 in 1988 Coversheet only encl
 DENTON.H R Dffice of Nuclear Reactor Regulation, Director B0706/27 2pp
- 8007230109 Forwards under separate cover, acceptance review copy of OL application, consisting of application & environ rept for placement in Perry, OH Public Library Util will submit FSAR on 800904 for review SOUDER, J. L. Division of Rules and Recurds 80/07/07 ip
- M Antitrust correspondence
- B007140251 Forwards Director of Nuclear Reactor Regulation order further modifying B00313 order w/respect to licenses & permits for facilities BALTZMAN, J Utility Finance Branch B0/06/11 lp
- 8007140286 Forwards Director of Nuclear Reactor Regulation order further modifying 800813 order w/respect to licenses & permits for facilities BALTZMAN,U Utility Finance Branch 80/06/11 ip
- --8007i40265 Order granting extension until B00709, for Cleveland Electric Illuminating Co to file amend to tarriff w/FERC as required by B009i3 order DENTON, HR Office of Nuclear Reactor Regulation, Director 80/04/11 2pp
- 8007140B75 Conditional request for hearing re Commission B00510 order re mod of transmission tariff Urges mod of order to bring consistency w/FERC tariffs in Opinion B4 or institution of hearing Util protest before FFRC & Certificate of Svc oncl ODLDBERG.R , WAONER,T E Cleveland, ON GULDBERG.R Goldberg, Fieldmen & Hjelmfelt 80/07/09 14pp
- 8007270533 Response in opposition to City of Cleveland, DR 800609 request for bearing re Director of Nuclear Reactor Regulation 800513 order filing, requesting tariff w/FERC, brings controversy to end w/o litigous course REYNOLDS, W B , IAHLER, R E Cleveland Electric Illuminating Co REYNOLDS, W B , Shaw, Pittman, Potts & Trembridge 60/07/25 9pp

- @ Inspection reports. IE Bulletins & correspondence
- 8007140551 Forwards IE Bulletin 80~13, "Cracking in Core Spray Spargers" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/12
- BO07090154 Forwards IE Insp Repts 50-440/80-07 & 50-441/80-07 on BO0505-07 & notice of violation FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch BO/05/21 2pp
- --8007070156 Notice of violation from insp on 800505-07 * Region 3. Chicago, Office of the Director 80/05/19 2pp
- --8007090199 IE Insp Repts 50-440/80-07 & 50-441/80-07 on 800505-07
 Noncompliance noted inadequate issuance of documents,
 inadequate quality records, inadequate instructions & failure
 to follow procedures for soil placement
 HAYES, D W Region 3, Chicago, Reactor Construction & Engineering
 Support Branch GALLAGHER, E. J., LANDSMAN, R. L. Region 3, Chicago,
 Office of the Director 80/05/19 6pp
- 8007090176 Forwards IE Insp Repts 50-440/80-06 & 50-441/80-06 pn 800421-24 & notice of violation FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/05/21 2pp
- ~-8007690178 Notice of violation from insp on 800421-24 * Region J. Chicago, Office of the Director 80/05/16 !p
- --8007090179 IE Insp Repts 50-440/80-06 & 50-441/80-06 on 800421-24
 Noncompliance noted failure to identify component to be
 covered by 6A program & inadequate indoctrination &
 training of personnel
 HAYES.D W Region 3. Chicago, Reactor Construction & Engineering
 Support Branch HUGHES, J. LANDSHAN.R B Region 3. Chicago,
 Office of the Director 80/05/16 App
- B007010139 Forwards IE Info Notice 80-29, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/05/29
- B007160725 Forwards IE Insp Repts 50-440/80-08 & 50-441/80-08 on B00506-09 & notice of violation FIGRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/06/04 2pp
- --8007160734 Notice of violation from inse on 800506-07
 # Region 3, Chicago, Office of the Director 80/06/02, ip
- --8007160741 IE Insp Repts 50-440/B0-08 & 50-441/B0-08 on 800506-09.
 Noncompliance noted failure to specify appropriate codes or stds in purchase order
 LEE,E W Region 3, Chicago. Office of the Director
 DANIELSON,D H Region 3, Chicago. Reactor Construction &
 Engineering Support Branch 80/06/02 4pp
- 8007220178 Forwards IE Info Notice 80-24, "Evaluation of Contractor QA Programs" No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/06/10
- B007140360 Forwards IE Bulletin B0-14, "Degradation of BHR Scram Discharge Vol Capability " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/12
- 8007280653 Forwards IE Info Notics 80-28, "Prompt Reporting of Info in Accordance W/106FR50 55(e) " No written response required XEPPLER, J G Region 3, Chicago. Office of the Director 80/06/13 ip
- 8007020365 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required
- KEPFLER.J G Region 3. Chicago, Diffice of the Director 80/06/20.
- 8007170465 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24

- 8007230310 Forwards IE Sulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters WEIther A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER.J G. Region 3. Chicago. Office of the Director 80/06/27.
- 8007150553 Submits addl info re response to IE Sulletin 80-09.Litton Industrial Products Inc & Fisher Co.Inc supplying Model NH-90 series hydramotor actuators Deficiencies described in IE Bulletin 80-09 will not affect performance of valves DAVIDSON,D R Cleveland Electric Illuminating Co 80/07/03 2pp
- 8007230101 Forwards suppl info to 800618 response to IE Bulletin 80-09 re hydramotor actuator deficiencies Litton Industrial Products. Inc. actuators use Number 2 springs & have no possibility of being fabricated from incorrect matl DAVIDSON, D R Cleveland Electric Illuminating Co 80/07/03.
- 8007180388 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-06 & 50-441/80-06 FIGRELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --B007180591 Responds to NRC 800521 ltr re violations noted in IE Insp Repts 50-440/80-06 & 50-441/80-06 Training program complies w/NRC requirements Browing 0-220-002 to be revised to show seismically adequate lighting supports DAVIDSON, D R Cleveland Electric Illuminating Co. 80/06/23 4pp.
- B007180406 Forwards response to IE Bulletin 80-08 re examination of containment liner penetration welds Lists penetrations w/ flued head design DAVIDSON, D R Cleveland Electric Illuminating Co. 80/07/10. Spp.
- 8007180582 Ack receipt of 800623 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/80-07 & 50-441/80-07 FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/10 ip
- --8007180585 Forwards response to NRC 800521 ltr re violations noted in IE Insp Repts 50-440/80-07 & 50-441/80-07. Corrective actions GC Procedure 8 revised, analyzed compaction equipment & GC procedure for soil insp being revised.

 DAVIDSON, D. R. Cleveland Electric Illuminating Co. 80/06/23. App
- B007230313 Ack receipt of B00703 ltr informing MRC of staps taken to correct violations noted in IE Insp Repts 50-440/80-08 & 50-441/80-08 FICRELLI,O Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/07/15 ip.
- --800723032i Responds to NRC 800604 ltr re violations noted in IE Insp Repts 90-440/80-08 & 50-441/80-08 Corrective actions: obtained codes & stds for Pullman Power Products welding matl DAVIDBON, D. R. Cleveland Electric Illuminating Co. 80/07/03. 3pp.
- B Reportable occurrences, LERs & related correspondence
- 8007180495 Ack receipt of 800630 final deficiency rept re Rosemount Model 510 DU trip calibr units/1152 pressure transmitters. Review will be completed during future insp FIDRELLI, 2 Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/14 ip
- 8007080294 Final deficiency rept re Rosemount Models 510 DU trip/calibr units & 1132 pressure transmitters Originally reported by 9E per Part 21 in May 1980 Amplifier boards & trip units will be replaced beginning 8ept 1980, w/completion by 810101. DAVIDSON, D R Cleveland Electric Illuminating Co. 80/06/30. 2pp.
- 8007160398 Interim deficiency rept re use of Mono-8ol 7-0013-3 CMB polyvinyl alchohol film water soluble purge dam matl. Util is in process of identifying deficient matl & having chemical analysis performed final rept provided by 801215. DAVIDBON.D R Cleveland Electric Illuminating Co. 80/07/11. 3pp.
- 8007180545 Ack receipt of 800625 interim deficiency Pept re Cutler-Hammer motor control ctrs. Final rept will be reviewed upon receipt.
 FIORELLI, 0 Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 80/07/14 ip

į

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B007210013 Confirms request for B00703 meeting w/util in Seabrook.NN to introduce NRC senior resident inspector & discuss quality matters re const CARLBON.R T Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch B0/06/25 1p

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0440 & found in NUREG-04594
EISENHUT, D @ Division of Licensing 80/04/24 2pp

8007180062 Notifies that ABME Code Case N-103-1 (1715-1) is acceptable & may be used in const of components for facilities Use of code case should be documented in FSAR
YDUNGBLODD,B J Licensing Branch 1 B0/07/09 2pp

B007280439 Submits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURGH.D Yankee Atomic Electric Co 80/07/24 7pp

O Adjudicatory correspondence

B007020602 Order granting extension until B00711 for Commission to elect whether to review ALAB-422 & ALAB-561
CHILK.B J Dffice of the Secretary of the Commission B0/06/27

8007140409 Submits Town of Salisbury, MA Article 13, approved at 800513 town meeting, re F Kramer petition opposing OL for Public Bvc Commission of MH Area surrounding facility cannot be safely syacuated & no town funds will be spent MORSE, W T Salisbury, MA 80/06/30 1p

8007140497 Order granting extension until 800801 for Commission to review ALAB-422 & ALAB-561
HOYLE, J C Office of the Secretary of the Commission 80/07/10 in.

H General correspondence

B007020090 Responds to 791011 ltr requesting const of plant be halted until safe evacuation plan can be achieved. Licensee must subsit evacuation study for NRC review & approval before OL is issued.

DENTON, H R Office of Nuclear Reactor Regulation, Director B0/06/11 2pp

--8007020096 Requests that NRC reply to SC Dunfey 79:01: 1tr opposing plant const until adequate evacuation plan is achieved Supporting documentation encl SEAL.M M President of UB & Executive Offices 79/10/19 App

B007100421 Responds to 791011 ltr to President Carter asking that const of facilities be halted until evacuation plan can be achieved Emergency planning reviews of plants under const will start within next yr BENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/11 2pp

8007100424 Responds to 791011 ltr to President Carter asking that const of facilities be halted until evacuation plan can be achieved Emergency planning reviews of plants under const will start within nest yr DENYON, H R Office of Nuclear Reactor Regulation, Director 80/06/11 2pp

8007250519 Forwards IE Insp Repts 50-443/R0-01 & 50-443/80-04 citing violations re Cadwell spliting & weld rod control in containment bldg W/o encl CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 80/06/30 ip

B007230622 Responds to 800508 ltr to President Carter re facility licensing NRC reviewed environ impacts of project prior to making decision on CP issuance. Facility poses no threat to environ or public health & safety YOUNGBLOOD, B J Licensing Branch | 80/07/15 2pp

BOO7240474 Partial response to FDIA request for five categories of documents re facility licensing proceeding Forwards NURES-0348 & 800311 & 0702 ltrs Request has been circulated for addit mat that may be available. Ltrs only encl FELTON.J M Division of Rules and Records 80/07/21 ip

I Financial information

8007080010 Forwards Annual Financial Rept 1979 for each owner of facility RITBHERJ A Ropes & Gray 80/07/03 2pp

--8007080011 Annual Financial Rept 1979 * Public Service Co of New Hampshire 80/07/03 25pp

--8007080012 Annual Financial Rept 1979
* United Illuminating 80/01/04 30pp

--8007080014 Annual Financial Rept 1979

* New England Power Co 80/01/25 20pp

---8007080016 Annual Financial Rept 1979 * Central Maine Power Co 80/02/14 34pp

--8007080018 Annual Financial Rept 1979
* Central Vermont Public Service Corp 80/02/15 33pp

--8007080019 Annual Financial Rept 1979
* Fitchburg Gas & Electric Light Co 80/02/07 23pp

--8007080020 Annual Financial Rept 1979
* Eastern Utilities Associates 80/03/06 33nn

---B0070B0022 Annual Financial Rept 1979

* New Bedford Gas & Edison Light Co B0/03/28 46pp

--80070B0025 Annual Financial Rept 1979 * Hudson Light & Power Dept 80/07/03 14pp

--8007080028 Annual Financial Rept 1979
* Vermont Electric Cooperative, Inc. 80/03/07 24op

--8007080031 Annual Financial Rept 1979 * Bangor Hydro-Electric Co 80/02/26 25pp

--B007080033 Annual Financial Rept 1979
* Taunton Hunicipal Lighting Plant 80/02/22 19pp

--8007080037 Annual Financial Rept 1979
* Massachusetts Municipal Wholesale Co 80/03/03 16pp

--8007080038 Annual Financial Rept 1979 * Maine Public Service Co 80/03/15 21pp

--8007080040 Annual Financial Rept 1979
* Connecticut Light & Power Co 80/03/14 21pp

Q Inspection reports, IE Bulletins & correspondence

8007010265 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER, B H Region i, Philadelphia, Office of the Director 80/05/29 ip

8007010219 Ack receipt of 800505 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-443/80-03 & 50-444/80-03 CARLSION: T Region 1, Philadelphia, Office of the Director 80/05/30 ip

--8007010223 Responds to NRC 800401 ltr re violations noted in IE Insp Repts 50-443/80-03 & 50-444/80-03 Corrective actions procedures re stud welding insp instituted DEVINCENTIS, J Public Service Co of New Hampshire 80/05/05 300

--8007010229 Forwards IE Insp Repts 50-443/80-03 & 50-444/80-03 on BOD226-28 & notice of violation CARLSON,R T Region I, Philadelphia, Reactor Construction & Engineering Support Branch BO/04/01 2pp

--8007010232 Notice of violation from insp on 800226-28 * Region 1, Philadelphia, Office of the Director 80/03/31 ip

- --8007010235 IE Insp Repts 50-443/80-03 % 50-444/80-03 on 800226-28 Noncompliance noted util failed to conduct stud welding insp as required & failed to control changes to aspure affected contractor procedures R Region I. Philadelphia. Office of the Director 80/03/31 7pm
- 8007210613 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs " No written response required GRIER,8 M Region J. Philadelphia, Diffice of the Director 80/06/10 1p
- 8007160363 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Study ' No specific action or response Conjant rough State

 required

 GRIER, B H Region i, Philadelphia, Office of the Director

 80/06/11 ip
- BO07280616 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/100FR 50 55(e) " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director BO/06/13 1p
- 8007020524 Forwards IE Circular 80~15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/20 ip
- 8007160740 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/06/24 1p
- 8007210281 Forwards IE Info Notice 80-24. "Low Level Radwaste Burisl Criteria " No written response required QRIER, B H Region I. Philadelphia. Office of the Director 80/04/25 lp
- 8007250623 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Each unit has 19 penetrations of flued head design All flued head penetrations to be butt welded to sleeves using consumable inserts DEVINCENTIS.J Public Service Co of New Hampshire 80/06/25 2pp
- 8007230178 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1191 & 1152 Pressure Transmitters M/Either A or D Output Codes " Written response required IE Carcular 80-16 also encl No written response required GRIER. B H Region 1. Philadelphia. Office of the Director BO/06/27 2pp
- B Reportable occurrences, LERs & related correspondence
- 8007010192 Ack recespt of 800515 final deficiency rept re undetected failure in engineered safety features actuation sys CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/05/06 1p
- 8007170589 Ack receipt of 800530 interim deficiency rept on use of invalid seismic amplified response spectra Rept will be reviewed & evaluated CARLSON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/06/12 ip
- ---B007170596 Advises that final deficiency rept re use of invalid seismic amplified response spectra originally promised for 800601 will be delayed until 800901 Ongoing corrective action not sufficiently complete to render final rept DEVINCENTIS. J Public Service Co of New Hampshire 80/05/30
- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8007210013 Confirms request for 800703 meeting w/util in Seabrook.NH to introduce NRC senior resident inspector & discuss quality matters re const CARLSON.R T Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 80/06/25 1p
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D G Division of Licensing 80/06/26 2pp

- 8007180062 Notifies that ASME Code Case N-103-1 (1715-1) is accaptable & may be used in const of companents for facilities Use of rode case should be documented in FSAR YOUNDBLOOD. II J Licensing Branch I 80/07/09 2pp
- BOO7280439 Submits alternate method of mitigation effects of grid degradation on safety-related electrical equipment Engineering for mods will be completed by Nov 1980 VANDENBURGH, D Yankee Atomic Electric Co 80/07/24 7pp
- **G** Adjudicatory correspondence
- 8007020602 Order granting extension until 800711 for Commission to elect whether to review ALAB-422 & ALAB-561 CHILK,S J. Office of the Secretary of the Commission 80/06/27
- B007140409 Submits Town of Salisbury, MA Article 13, approved at 900313 town meating, re F Kramer petition opposing OL for Public Svc Commission of NH Area surrounding facility cannot be wafely evacuated & no town funds will be spent MORBE. W T Salisbury, MA 80/06/30 1p
- BD07140457 Order granting extension until B00801 for Commission to review ALAB-422 & ALAB-561
 HDYLE, J C Office of the Secretary of the Commission 80/07/10
- H General correspondence
- B007020070 Responds to 791011 ltr requesting const of plant be halted until make evacuation plan can be achieved Licensee must submit evacuation study for NRC review & approval before OL. 16 1850ed DENTON,H R Office of Nuclear Reactor Regulation, Director 80/06/11 Zoo 80/06/11
- --B007020076 Requests that NRC reply to SC Dunfey 791011 ltr opposing plant canst until adequate evacuation plan is achieved Supporting documentation encl SEAL.M M President of US & Executive Offices 79/10/19 App
- 8007100421 Responds to 791011 ltr to President Carter asking that const oversomer nesponds to 791011 ltr to President Carter asking of facilities be halted until evacuation plan can be achieved Emergency planning reviews of plants under const will start within next yr DENTON.HR Office of Nuclear Reactor Regulation. Director 80/06/11 2pp
- B007100424 Responds to 771011 ltr to President Carter asking that const of facilities be halted until evacuation plan can be achieved Emergency planning reviews of plants under const will start within next yr DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/11 2pp
- 8007230622 Responds to 800808 ltr to President Carter re facility licensing NRC reviewed environ impacts of project prior to making decision on CP issuance Facility poses no threat to environ or public health & safety YOUNOBLOOD, B J Licensing Branch 1 80/07/15 2pp
- 8007240474 Partial response to FDIA request for five categories of documents re facility licensing proceeding Forwards NUREO-0348 & 800311 & 0702 ltrs Request has been circulated for addl matt that may be available Ltrs only encl FELTON.J M Division of Rules and Records 80/07/21 1p
- I Financial information
- 8007080010 Forwards Annual Financial Rept 1979 for each owner of facility RITSHER, J A Ropes & Gray 80/07/03 2pp
- --8007080011 Annual Financial Rept 1979
 * Public Service Co. of New Hampshire 80/07/03 28ne
- ~~B0070B0012 Annual Financial Rept 1977 * United Illuminating 80/01/04 30pp
- -8007080014 Annual Financial Rept 1979 * New England Power Co 80/01/25 20pp
- --8007080016 Annual Financial Rept 1979 * Central Maine Power Cp 80/02/14

- --8007080019 Annual Financial Rept 1979
 * Fitchburg Gas & Electric Light Co 80/02/07 25pp
- ---8007080020 Annual Financial Rept 1979
 # Eastern Utilities Associates 80/03/04 33pp
- --8007080022 Annual Financial Rept 1979 * New Bedford Gas & Edison Light Co 80/03/28 46pp
- --8007080025 Annual Financial Rept 1979 * Hudson Light & Power Dept 80/07/03 16pp
- --8007080028 Annual Financial Rept 1979
 * Vermont Electric Conserative, Inc. 80/03/07 24nn

- --8007080037 Annual Financial Rept 1979
 * Massachusetts Municipal Wholesale Co 80/03/03 15pp
- --8007080040 Annual Financial Rept 1979
 * Connecticut Light & Power Co 80/03/14 21pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007010265 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/05/29 ip
- 8007010219 Ack receipt of 800505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/80-03 & 50-444/80-03 CARLSON R T Region 1, Philadelphia, Office of the Director 80/05/30 ip
- --8007010223 Responds to NRC 800401 ltr re violations noted in IE insp Repts 50-443/80-03 & 50-444/80-03 Corrective actions procedures re stud welding insp instituted DEVINCENTIS.J Public Service Co of New Hampshire 80/05/05
- --8007010227 Forwards IE Insp Repts 50-443/80-03 & 50-444/80-03 on 800226-28 & notice of violation CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 80/04/01 2pp
- --8007010232 Notice of violation from insp on 800226-28
 * Region 1. Philadelphia, Office of the Director 80/03/31 1p
- --8007010235 IE Insp Repts 50-443/80-03 & 50-444/80-03 on 800226-28 Noncompliance noted util failed to conduct stud welding insp as required & failed to control changes to assure affected contractor procedures

 CERNE. A C . MCGAUGHY, R W Region i, Philadelphia. Office of the Director 80/03/31 7pp
- B007210613 Forwards IE Info Notice B0-26, "Evaluation of Contractor GA Programs " No written response required ORIER, B H Region 1, Philadelphia. Office of the Director B0/06/10 1p
- 8007160363 Forwards IE Info Notice 80-27, "Degradation of Reactor Coclant Pump Studs " No specific action or response required GRICE, B H Region 1, Philadelphia, Office of the Director BO/O6/11 1p
- 8007280616 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR90 95(e) " No written response required ORIER, D. M Region i, Philadelphia, Office of the Director 80/06/13 ip

- 8007020524 Forwards IE Circulat 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER/B H Region 1. Philadelphia, Office of the Director 80/06/20 10
- 8007160740 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- B007210281 Forwards IE Info Notice 80-24, "Low Level Radwaste Durial Criteria " No written response required GRIER.B H Region i, Philadelphia, Office of the Director 80/06/25 ip
- B007250623 Responds to IE Bulletin 80-08, "Examination of Containment Liner Penetration Welds " Each unit has 19 penetrations w/ flued head design All flued head penetrations to be butt welded to sleeves using consumable inserts DEVINCENTIS.J Public Service Co. of New Hempshire B0/06/25 2pp
- 8007230178 Forwards 1E Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRICR, B H Region 1. Philadelphia. Office of the Director 80/06/27 2pp
- S Reportable occurrences, LERs & related correspondence
- 8007010182 Ack receipt of 800515 final deficiency rept re undetected failure in engineered safety features actuation sys CARLSON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/06 1p
- 8007170889 Ack receipt of 800530 interim deficiency rept on use of invalid seismic amplified response spectra Rept will be reviewed & evaluated CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/06/12 ip
- --8007170596 Advises that final deficiency rept re use of invalid seismic amplified response spectra originally promised for 800601 will be delayed until 800901 Ongoing corrective action not sufficiently complete to render final rept DEVINCENTIS. J. Public Service Co. of New Hampshire 80/05/30 2pp
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 1
- A Application/construction stage documents & correspondence
- B007020224 Advises of filing of detailed electrical, instrumentation & control drawings submitted by TX Utils Conerating Co Action taken in conformance w/NRC FM Operating Procedure 208, Revision I Drawings in Central Files only BURWELL.S Licensing Branch P 80/06/06 tp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREQ-0560 & found in NUREQ-05694
 EISENBUT, D. G. Division of Licensing 80/06/25 2pp
- 8007180366 Forwards Freese & Nichols Inc 800620 ltr in response to NRC 800415 request for additional reflection in the first separate of the order of the first separate of the order of the first separate of the first separating Co. 80/07/10 3pp
- B007240066 Summary of 870625 meeting brtween Assistant Director for Environ Technology & Assistant Director for Licensing remgt. technical oversight & mechanics of environ review performance MULLER D R Assistant Director for Environmental Technology TEDESCO, R L Assistant Director for Licensing B0/07/14 App
- 8007210478 Forwards electrical, instrumentation & control drawings to assist in plant review GARY.R J Texas Utilities Generating Co 60/07/15 2pp
- --8007210485 "Control Panel Schematic" Sheet 1 of 8 * De Laval Turbine Inc 76/07/16 ip
- ---8007210490 "Control Panel Schematic " Sheet 2 of 8 * De Laval Furbine Inc 76/07/16 1p

- --8007210496 "Control Panel Schematic" Sheet 3 of 8 • De Laval Turbine Inc 76/07/16 1p
- --B007210500 "Control Panel Schematic " Sheet 4 of 8 * De Laval Turbine Inc 76/07/16 Ip
- --8007210504 "Control Panel Schematic" Sheet 5 of 8 * De Laval Turbine Inc 76/07/16 1p
- --8007210508 "Control Panel Schematic " Sheet & of 8 * De Laval Turbine Inc 76/07/16 1p
- --8007210510 "Control Panel Schematic" Sheet 7 of 8 # De Laval Turbing Inc 76/07/16 ip
- --8007210914 "Control Panel Schematic" Sheet 8 of B * De Laval Turbine Inc 76/07/16 tp
- --8007210517 "Interconnection Diagram " Sheet 1 of 2 * De Laval Turbine Inc 77/04/06 1p
- --B007210519 "Interconnection Diagram" Sheet 2 of 2 * De Laval Turbine Inc 77/04/06 ip
- --8007210527 "Schematics Diesel Generator Local Panel," as-built * De Laval Turbing Inc * Delta Switchboard Co * Gibbs & Hill, Inc (subs of Dravp Corp) 76/07/16 1p
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8007140053 Provides background info on schedule, content & form of facilities OL stage environ review for initiation of appropriate NEPA review & technical oversight functions List of reviewers, review schedule & DES outline encl SCHKENCER, A Licensing Branch 2 80/06/26 Bpp
- F Security, medical, emergency & fire protection plans
- BOO7110976 Requests revisions & add1 info to safeguards contingency plan re evaluation of util application for DL Forwards statement of NRC positions Response should be submitted within 60 days Statement uithheld (ref 10CFR2 790) BCHWENCER.A Licensing Branch 2 80/06/23 2pp
- 8007080282 Advises that upgraded emergency plan for facility will be submitted by 800930 OARY, R J Texas Utilities Generating Co 80/04/30 ip

9 Adjudicatory correspondence

- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCS 7B0802 petition for reconsideration of 7B0413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 87pp
- B007090327 Exceptions to ASLB 800616 order re B00430 prehearing conference Order erred in rejecting intervenor Contentions 1.3.6(b)(e).8 % 10 % conditioning acceptance of Contentions 5 % 23 Certificate of Svc encl ELLIS,J Citizens Association for Sound Energy B0/06/30 4pp
- BOO7030246 Response in opposition to ASLB BO0616 order re BO0430 prehearing conference ruling on admissibility of contentions Urges mad of order to delete Contentions 3, 4, 7, 11 & 17 & to reword Contention 23 Certificate of Svc enci REYNOLDS.N 9 . HORIN.W A Texas Utilities Generating Co REYNOLDS.N S Debevoise & Liberman 80/07/01 17pp
- 8007100255 Nemorandum & order dismissing Citizens Association for Bound Energy appeal from unpublished ASLB 800616 prehearing conference order rejecting contentions Interlocutory appeal is not permitted unless petition is denied in entiroty BISHOP.C J Atomic Safety and Licensing Appeal Panel, 80/07/03 2pp
- 8007300366 Requests that missing pages from FBAR Amends 1-10, listed in encl. be forwarded along w/any addl amends Also requests that name be added to mailing list Certificate of Svc encl Related correspondence
 ELLIS.J Citizens Association for Sound Energy 80/07/07 5pp
- 8007310123 First set of interrogatories directed to applicant Requests details of signed sale negotiations Cartificate of Svc encl Related correspondence ELLIB. J Citizens Association for Bound Energy 80/07/07 dop

- 8007310167 Order affirming grant of additime for Citizens Association for Sound Energy to respond to applicant 800701 motion & to file position to ASLB 800616 order Five-day extension for Citizens for Fair Util Regulation re NURES-0694 granted BDMERB.E S Atomic Safety and Licensing Board Panel 80/07/10 2no
- 8007170261 Forwards NUREG-0674. "TMI-Related Requirements for New GLs." per 800710 telcon Copies forwarded to Citizens for Feir Util Regulation & Association of Community Organizations for Reform Now W/o enc! TURK, S E Hearing Branch 1 80/07/11 ip
- 8007220946 Motion for reconsideration of ASLB 800430 order for certification of denied contentions Maintains validity of contentions, especially Class 9 accident scenario Certificate of Svc encl
 ELLIS, J Citizens Association for Sound Energy 80/07/14 20pp
- 8007220559 Suppl to intervenor 800714 motion for reconsideration or certification of denied contentions re ASLB 800430 order Submits new info in support of Contention 1 re Btate of TX vs TX Utils companies Certificate of Bvc encl ELLIS,J Citizens Association for Sound Energy 80/07/14. 7pp.
- 8007180437 Response in opposition to TX Association of Community Organizations for Reform Now 800701 motion seeking reconsideration of 800616 order denying cetain proposed contentions Rewording must be denied W/Certificate of 8vc. REYNDLDS,N S HORIN,W A Texas Utilities Generating Co
- B007230741 Response in apposition to TX Association of Community Organizations for Reform Now B00701 motion for reconsideration of ASLB B00616 order Urges denial of alternative motion for certification W/Gertificate of Svc TURK, S E Hearing Branch 1 80/07/21 24pp
- 8007230748 Response to applicants' 800701 objections re prehearing conference order & to applicants' motion for mod Urges denial of requests re Contentions 3.4.9, i7 & 23 Motion to delete Contention il must be granted W/Certificate of 8vc TURK, 8 E Hearing Branch I 80/07/21 18pp
- 8007290758 Order extending time until 800808 for Commission to review ALAB-599 CHILK, B J Office of the Secretary of the Commission, 80/07/24 1a
- 8007310328 Response to Citizens Association for Sound Energy 800707 first set of interrogatories & requests for clarification. Explains communication w/public re electric util matters. H/affidavis. Certificate of Svc & supporting documentation REYNOLDS, N S . HORIN. H A Texas Utilities Cenerating Co REYNOLDS, N S . Debevoise & Liberman 80/07/28 36pp

M Antitrust correspondence

- B007010247 Forwards work order extending Hartley contract to B00531 W/o sncl BLUME.M B Antitrust Division B0/04/14 ip
- B007010264 Forwards signed stipulation abiding by ASLB B00331 protective order re Houston Lighting & Power corporate study W/o encl BLUME. H B Antitrust Division B0/04/14 ip
- 8007010298 Forwards documents mistakenly omitted from Hartlay documents W/o encil HODDON, A P. Antitrust Division 80/05/07 ip
- 8007210388 Reviews 800702 draft transmission svc settlement agreement.

 Document found to be unacceptable due to provisions making
 Austin jurisdictional as practical matter for wheeling
 "Postage stamp" wheeling rate is not proper in TX
 BALOUGH.R.C Austin. TX 80/07/10 2pp
- 8007180425 Status rept advising that absent change in DOJ policy position, util will not be able to reach settlement w/dept. Differences w/NRC re license conditions not yet resolved. Certificate of Svc encl GREEN, D O Houston Lighting & Power Co * Baker & Botts. * Lowenstein, Newman, Reis, Axelrad & Toll 60/07/11 7pp
- 800718043: Status rept on settlement negotiations Urges 60-day suspension of proceedings, including hearing date, due to continued negotiations w/Public Utils Board of City of Brownsyille. TX. W/Cortificate of Svc & pleading before FERC. STAHL.D M. Central & South West Corp STAHL.D M. Isham, Lincoln & Seale. 80/07/11 Zopp

ł

- 8007130449 Status rept by Public Utils Board of City of Brownsville, TX re settlement progress City would not object to further extension limited to 30 days although negotiations do not appear to be fruitful Certificate of Svc encl PDIRIER. M R Brownsville, TX POIRIER. M R Spiegel & McDiarmid 80/07/11 dpp
- 8007150300 Third status rept on settlement progress Suggests 30-day min extension to pursue negotiations & to present proposed license conditions re transmission svcs & other areas Certificate of Svc encl CHANANIA, F D Antitrust Division 80/07/11 8pp
- 8007160625 Status rept re settlement negotiation progress Expresses no optimism for agreement w/DDJ but agreement w/NRC may be reached re license conditions dealing w/bulk power wheeling rates. Certificate of Svc encl
 BAMPLES,M D , KNOTTS, J B Texas Utilities Generating Co
 SAMPLES,M D Worsham, Forsythe & Sampels 80/07/11 6pp
- 8007170364 Status rept re development of settlement discussions Urges denial of add1 extension of time due to belief that no settlement will be reached between DOJ & applicants Cartificate of Boc encl
 CYPHERT.S B Justice.Dept of BO/07/11 App
- 8007170388 Second status rept re settlement negatiations progress Urges further antitrust settlement efforts to proceed apace w/FERC settlement due to similarity of issues Certificate of Svc encl
 UNHN.D F Affiliation Unknown JOHN.D F Medinaelectric
 Cooperative.Inc JOHN.D F McDermott.Will & Emery 80/07/11 App
- 8007210455 Bubmits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Mod of joint ownership agreement drafts exchanged Certificate of Bvc encl BURCHETTE, W H , RITTB, F H Northcutt Ely B0/07/11 4pp
- 8007160547 Motion seeking renewal of DOJ 800521 motion to establish trial & other procedural dates Suggests 800708 for brings & 801006 for commencement of evidentiary hoaring Settlement does not appear to be possible Certificate of Svc encl
 CYPHERT,S B , PARMENTER,F Justice,Dept of 80/07/14 App
- B007220500 Buggests reconsideration of 800307 discovery order in light of extensive settlement negotiations subsequently conducted by all parties & counsel on 800402 MILLER, M E Atomic Safety and Licensing Board Panel B0/07/16. ip
- 8007220556 Order denying petitions for directed certification w/p prejudice to resubmission following ASLB determination BISHOP.C J Atomic Safety and Licensing Appeal Panel BO/07/18 2pp
- BOO7300418 Withdrawal of 7705k1 notice of appearance R Fabrikant responsible for all communications until further notice Certificate of Svc encl CYPHERT, S B Justice. Dept of 60/07/23 4pp
- 8007280620 Draws attention to two pleadings that should be treated separately although stapled together NRC motion for extension of time & NRC/DOJ joint motion for clarification & for establishment of production schedule CHANANIA.F D Antitrust Division 80/07/25 1p
- 8007280627 Motion for extension until 800731 to file objections ω/ proposed revision to ASLB 800717 prehearing conference order & notice of final prehearing conference Discussions ω/ parties have commenced & must proceed LEHI8:9 H Hearing Branch 2 80/07/25 2pp
- --B007280636 Joint motion for clarification of ABLB 800716 memorandum containing decision to reconsider ABLB 800307 order resettlement documents Moves for order establishing schedule for production of settlement documents W/Certificate of Syc FABRIKANY, R. Justice, Dept of CHANANIA, F. D., GLUME, H. B. Antitrust Division 80/07/25 Gpp
- 8007300356 Order granting extension until 800731 for NRC to submit objections & proposed revisions to 800717 final prehearing conference order MOLFE, B J Atomic Safety and Licensing Board Panel 80/07/25. ip.

N. Antitrust hearing transcripts

8007180009 Transcript of 800714 prehearing conference in Bethesda. MD re-settlement negotiations Pp 891-946 * Atomic Safety and Licensing Board Panel, 80/07/14 78pp

- B007250441 Proposed correction to 800409 prehearing transcript Certificate of Svc encl
 CREEN, D 0 Houston Lighting & Power Co * Belor & Botts *
 Lowenstein, Newman, Reis, Axelrad & Toll B0/07/22 Spp
- **G** Inspection reports, IE Bulletins & correspondence
- 9007250328 Forwards 1E info Notice 80-12. "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYFRIT.K V Region 4, Dallas. Office of the Director 80/03/31
- 8007180490 Discusses IE Insp Repts 50-445/80-11 & 30-446/80-11 on B00404 & forwards notice of violation SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/09 2pp
- --B007180499 Notice of violation from insp on 800404 Noncompliance noted failure to follow piping installation procedures * Region 4, Dallas, Office of the Director 80/04/09 1p
- 8007240509 Ferwards IE Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/16
- 8007110227 Forwards IE lnsp Repts 30-445/80-14 & 50-446/80-14 on B00913-16 No noncompliance noted SEIDLE:W C Region 4. Dallas. Reactor Construction & Engineering Support Branch B0/05/23 2pp
- --B007110234 IE Insp Repts 50-448/80-14 to 50-446/80-14 on B00313-16 No nancompliance noted Major areas inspected constractivities, RCPB piping work & other safety-related piping work GREBERT, L D , HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch CROSSMAN, W A Region 4, Ballas, Office of the Director B0/05/23 App
- 8007020255 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required SEYFRIT.K V Region 4, Dallas. Office of the Director 80/05/28 in
- 8007210351 Forwards 1E Circular 80-13, "Grad Strap Damage in Westinghouse Fuel Assemblies " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- B007010024 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feeduator Pumps" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director B0/03/29
- B007170196 Responds to IE Bulletin B0-09. "Hydramotor Actuator Deficiencies " Six vendors identified as potential suppliers of equipment containing ITT Owneral hydramotor actuators Vendors confirmed no actuators supplied to facilities GARY.R J Texas Utilities Generating Co B0/06/10 ip
- 8007220128 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/10 in
- 8007110592 Ack receipt of IC Insp Repts 50-445/80-13 & 50-446/80-13 No proprietary info GARY.R J Texas Utilities Generating Co 80/06/11 ip
- 8007160334 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant PUmp Studs " No specific action or response required SEYFRIT.K V Region 4, Dallas. Office of the Director 80/06/11
- 8007290077 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required SEYFRIT.K V Region 4, Dallas. Defice of the Director 80/06/13
- 8007180567 Forwards JE Insp Repts 50-445/80-11 & 50-446/80-11 in Apr-May 1780 No nuncompliance noted BEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/17 2pp

- --8007180574 IE Insp Repts 50-445/80-11 % 50-446/80-11 in Apr-May 1980 No NO/1805/4 IE Insp Regits 30-445/80-11 v 30-445/80-11 in Apr-monoumpliance noted Major areas inspected safety-related pipe & equipment installation.concrete repair activities, electrical installation & protection of major components TAYLOR, R G. CROSSMAN W A Region 4. Dallas, Office of the Director 80/06/16 10pp
- 8007140455 Ack receipt of IE Insp Repts 50-445/80-14 % 50-446/80-14 on 800523 No proprietary info OARY/R J Telas Utilities Generating Co 80/06/18 Ip
- B007140497 Ack receipt of B00606 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/80-13 & 50-446/80-13 SEIDLE.N C Region 4. Dallas. Reactor Construction & Engineering Support Branch B0/06/19 Ip
- 8007240057 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response SEYFRIT, K V Region 4, Dallas, Uffice of the Director 80/06/20
- 8007170683 Forwards IE Circular 80-14, "Redirective Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No writton response required SEYPRIT.K V Region 4. Dallas, Office of the Director 80/06/24
- 9007230370 Forwards IE Bulletin 80-16, "Potential Misapplication of Resembnor inc Models 1151 to 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circuler 80-16 also encl No written response required SEYFRIT, K V Region 4, Dollas, Office of the Director 80/06/27
- S Reportable occurrences, LERs & related correspondence
- #2007210162 PNS-IV-80-010 group of approx twolve people harassing security force over period of five days State & local law enforcement authorities have been actively supporting security force KELLY,J Region 4, Dallas, Office of the Director 80/07/09 ip
- 8007210352 Updates 800421 deficiency rept re discrepancies involving installation & insp requirements for Class 5 non-nuclear safety-related piping supports F5AR is being revised Final rept will be forwarded by 800932 GARY.R J Texas Utilities Generating Co 80/07/14 ip
- DUCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 2 A Applacation/construction stage documents & correspondence
- 8007020224 Advises of Filing of detailed electrical, instrumentation & control drawings submitted by TX Utils Generating Co Action taken in conformance w/NRC Ph Operating Procedure 208, Revision 1 Brawings in Central Files only UURWELL'S Licensing Branch 2 80/06/06 1p
- BOO7230001 Forwards Statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT. D G Division of Licensing 80/06/24 2pp
- 8007180366 Forwards freese & Nichols Inc 800620 ltr in response to NRC 800419 request for addl info re floodplain mpt Response will be incorporated into util environ rept GARYR J Texas Utilities Generating Co 80/0//10 3pp
- 8007240066 Summary of 800625 meeting between Assistant Director for Environ Technology & Assistant Director for Licensing reads, technology & Assistant Director for Environ review performance MULLER.D.R. Assistant Director for Environmental Technology TEDESCO.R i. Assistant Director for Licensing 80/07/14 4pp
- 8007210478 Forwards glactrical instrumentation \ control drawings to assist in plant review
 GARY, R J Texas Utilities Wenerating Co 80/07/15 2pp

- --8007210490 "Control Panel Schematic" Sheet 2 of 8 * De Laval Turbine Inc 76/07/16 ip
- --8007210496 "Control Panel Schematic" Sheet 3 of 8 # De Laval Turbine Inc 76/07/16 ip
- --8007210500 "Control Panel Schematic" Sheet 4 of 8 * De Laval Turbine Inc 76/07/16 1p
- ---8007210504 "Control Panel Schematic" Sheet 5 of B * Dc Laval Turbine Inc 76/07/16 1p
- --8007210508 "Control Panel Schematic" Sheet 6 of 8 * De Laval Turbing Inc 76/07/16 1p
- ~8007210510 "Control Panel Schematic " Sheet 7 of 8 * De Laval Turbine Inc 76/07/16 ip
- --8007210514 "Control Panel Schematic " Sheet 8 of 8 * Do Laval Turbine Inc 76/07/16 ip
- --8007210517 "Interconnection Diagram" Sheet 1 of 2 * De Laval furbine Inc 77/04/05 1p
- ~~8007210519 "Interconnection Diagram" Sheet 2 of R * De Laval Turbine Inc 77/04/06 1p De Laval Turbine Inc
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8007140093 Provides background info on schedule, content & form of facilities OL stage environ review for initiation of appropriate NEPA review & technical overeight functions List of revieuers, review & technical DES outline encl
 SCHWENCER, A Licensing Branch 2 80/06/26 8pp
- F Security, medical, emergency & fire protection plans
- 8007110574 Requests royisions & addl info to safeguards contingency plan re evaluation of util application for GL Forwards statement of NRC positions Response should be submitted within 60 days Statement withheld (ref 10CFR2 790) SCHWENCER, A Licensing Branch 2 80/06/23 2pp
- 8007080282 Advises that upgraded emergency plan for facility will be submitted by 800930 GARY,R J Trass Utilities Generating Co 80/06/30 1p
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition aought action re fire protection for electrical cables EISENHUT. D & Division of Licensing 80/06/25 89pp
- 8007090327 Exceptions to ASLB 800416 order re 800430 prehearing conference Order erred in rejecting intervenor Contentions 1.3.6(b)(e).8 & 10 & conditioning acceptance of Contentions 5 & 23 Certificate of Syc encl CLLS.J Citizens Association for Sound Energy 80/06/30 4pp
- 8007030246 Response in apposition to ASLB 800616 order re 800430 preheaving conference ruling on admissibility of contentions Urges mod of order to delete Contentions 3, 4, 9, 11 & 17 & to reword Contention 23 Certificate of Svc encl REYNOLDS, N S . HORIN, W A Texas Utilities Generating Co REYNOLDS, N S . Debryoise & Liberman 80/07/01 i7pp
- 8007100295 Memorandum & order dismissing Citizens Association for Bound Energy appeal from unpublished ABLB 800616 prehearing conference order rejecting contentions Interlocutory appeal is not permitted unless petition is defied in entirety BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/03.
- 8007300366 Requests that missing pages from FBAR Amends i-10, listed in encl, be forwarded along w/any addl amends Also requests that name be added to mailing list Certificate of Svc encl Related correspondence.
 ELLIB, J Citizens Association for Sound Energy 80/07/07

- 8007310123 First set of interrogatories directed to applicant Requests details of signed sale negotiations Pertificate of Svc encl Related correspondence
 - Citizens Association for Sound Energy 80/07/07 4pp
- 8007310167 Order affirming grant of addl time for Citizens Association for Sound Energy to respond to applicant 800701 motion & to file position re ASLB 800616 order Five-day extension for Citizens for Fair Util Regulation re NUREG-0694 granted BOMERS, E S Atomic Safety and Licensing Board Panel 80/07/10
- 8007170261 Forwards NUREG-0694, "TMI-Related Requirements for New OLs," per BOO710 telcon Copies forwarded to Citizens for For Util Regulation & Association of Community Organizations for Reform Now W/o encl
 TURK, S E Hearing Branch 1 90/07/11 1p
- 9007220546 Motion for reconsideration of ASLB 800430 order for certification of denied contentions Maintains validity of contentions. especially Class 9 accident scenario Certificate of Svc encl Citizens Association for Sound Energy 80/07/14 20pp
- 8007220559 Suppl to intervenor 800714 motion for reconsideration or cartification of denied contentions re ASLB 800430 order
 Submits new info in support of Contention 1 re State of TX
 ys TX Utils companies Certificate of Syc encl
 ELLIS.J Citizens Association for Sound Energy 80/07/14 7pp
- 8007180437 Response in opposition to TX Association of Community Organizations for Reform Now 800701 motion seeking reconsideration of 800416 order denying cetain proposed contentions Rewording must be denied W/Certificate of Svc REYNOLDS, N S , HORIN, W A Fexas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 80/07/16 12pp
- 8007230741 Response in opposition to TX Association of Community Urganizations for Reform Now 800701 motion for reconsideration of ASLB 800616 order Urges denial of alternative motion for certification W/Certificate of Syl
- 8007230748 Response to applicants' 800701 objections re prehearing conference order & to applicants' motion for mod Urges denial of requests re Contentions 3.4.9.17 & 23 Motion to delete Contention 11 must be granted U/Certificate of Svc TURK.S E Hearing Branch 1 80/07/21 18pp
- 8007290758 Order extending time until 800808 for Commission to review ALAB-599 CHILK, S.J. Office of the Secretary of the Commission 80/07/24
- 8007310328 Response to Citizens Association for Sound Energy 800707 first set of interrogatories & requests for clarification Explains communication w/public re electric util matters W/affidavit, Certificate of Svc & supporting durumentation REYNOLDS, N S , HORIN, W A Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 80/07/28 36pp

M. Antitrust correspondence

- 9007010247 Forwards work order extending Hartley contract to 800531 W/a enci BLUME, M B Antitrust Division 80/04/14 1p
- 8007010244 Forwards signed stipulation abiding by ASLB 800331 protective order re Houston Lighting & Power corporate study M/o encl BLUME. H B Antitrust Division 80/04/14 Ip
- 8007010298 Forwards documents mistakenly omitted from Hartley documents W/o encl HODODON, A P Antitrust Division 80/05/07
- 8007210388 Reviews 800702 draft transmission svc settlement agreement Document found to be unacceptable due to provisions making Austin jurisdictional as practical matter for wheeling "Postage stamp" wheeling rate is not proper in TX BALOUGH.R C Austin, TX 80/07/10 2pp
- 8007150425 Status rept advising that absent change in DDJ policy position, util will not be able to reach settlement w/dept Differences w/NRC re license conditions not yet resolved Certificate of Svc enc. | GREEN, D. G. Houston Lighting & Power Co * Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/07/11 7pp

- 9007150431 Status rept on settlement negotiations Urges 60-day suspension of proceedings, including hearing date, due to continued negotiations w/Public Utils Board of City of Brownsville, TX W/Certificate of Svc & pleading before FERC STAHL, D M Central & South West Corp STAHL, D M Isham, Lincoln & 80/07/11
- 8007150449 Status rept by Public Utils Board of City of Brownsville,TX re settlement progress City would not object to further extension limited to 30 days although nagotiations do not appear to be fruitful Certificate of Svc entl PDIRIER, H R Drownsville,TY POIRIER, H R Spiegel & McDiarmid 80/07/ii 6pp
- B007150500 Third status rupt on settlement progress Suggests 30-day min extension to pursue negatiations & to present proposed license conditions re transmission svcs & other areas Certificate of Svc encl CHANANIA.F D Antitrust Division 80/07/11 Gpp
- 8007160629 Status rept re settlement negotiation progress Expresses no optimism for agreement w/DOJ but agreement u/NRC may be reached re license conditions dealing w/bulk power whoeling rates Cortificate of Svc encl SAMPLES.M D. KNOTTS, J B. Texas Utilities Generating Co SAMPLES.M D. Worsham, Forsythe & Sampels 80/07/11 6pp
- 800/170344 Status rept re development of settlement discussions Urges denial of addl extension of time due to belief that no settlement will be reached between DOJ & applicants Certificate of Svc encl CYPHERT. 9 Justice Dept of 80/07/11 app
- 8007170388 Second status rept re settlement negotiations progress Urges further antitrust settlement efforts to proceed apace WFERC settlement due to similarity of issues Certificate of Svc JOHN, D F Affiliation Unknown JOHN D F Medinael e.The JOHN D F McDelmott, Hill & Emery Medinaelectric Cooperative, Inc. 80/07/11 6pp
- 8007210455 Submits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Mod of joint ownership agreement drafts exchanged Certificate of Svc enci DURCHETTE.W H . RITIS.F H Northcutt Ely 00/07/11 4pp
- 8007160547 Hotton seeking reneval of DOJ 800521 motion to establish trial & other procedural dates Suggests 800908 for briefs & 901006 for commencement of evidentiary hearing Settlement does not appear to be possible Certificate of Svc encl CYPHERT, S D . PARMENTER, F Justice, Dept of 80/07/14 App
- 8007220500 Suggests reconsideration of 800307 discovery order in light of extensive settlement negotiations subsequently conducted by all parties & counsel on 800402 NILLER, M E Atomic Safety and Licensing Board Panel 60/07/16 ip
- 8007220596 Order denying petitions for directed certification w/o projudice to resubmission following ASLB determination BISHOP,C J Atomic Safety and Licensing Appeal Panel 80/07/18
- 800730041B Withdrawal of 790511 notice of appearance R Fabrikant responsible for all communications until further notice Cortificate of Svc encl CYPHERT, S B Justice.Dopt of 80/07/23 App
- 0007280620 Draws attention to two pleadings that should be treated neparately although stapled together NRC motion for extension of time & NRC/DOJ joint motion for clarification & for establishment of production schedule CHANANIA.F D Antitrust Division 80/07/25 ip
- 8007280627 Motion for extension until 900731 to file objections w/ proposed revision to ASLB 800717 prehearing conference order & notice of final prehearing conference Discussions w/ parties have commenced & must proceed LEMIS.9 H Hearing Branch 2 80/07/25 2pp
- --B007280636 Joint motion for clarification of ASLB 800716 memorandum containing decision to reconsider ASLD 800307 order resettlement documents Moves for order establishing schedule for production of settlement documents W/Certificate of Svc FABRIKANT, R Justice Dept of CHANANIA, F D, BLUME, M B Antitrust Division 80/07/25 8pp
- 8007300354 Order granting extension until 80073; for NRC to submit objections & proposed revisions to 800/17 final prehearing conference order WOLFE,S J Atomic Safety and Licensing Board Panel 80/07/25 ip

N Antitrust hearing transcripts

- 8007180008 Transcript of 800714 prehearing conference in Bethesday MD re settlement negotiations Pp 891-946 * Atomic Safety and Licensing Board Panel 80/07/14 78pp
- 8007250441 Proposed correction to 800409 prohearing transcript Cartificate of Svc encl OREEN, D G Houston Lighting & Power Co * Baker & Botts * Lowenstein: Newman-Reis: Azelrad & Toll 80/07/22 Spp
- @ Inspection reports, IE Bullatins & correspondence
- 8007250328 Forwards IE Info Notice 80-12. "Instrument Failure Causes Opening of PCRV & Block Valve " No specific action or response necessary SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/31
- BOO7180490 Discusses IE Insp Repts 50-445/80-11 & 30-446/80-11 on BOO404 & forwards notice of violation SEIDLE,H C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/04/09 2pp
- ---8007180499 Notice of violation from insp on B00404 Noncompliance noted failure to follow piping installation procedures * Region 4. Dallas. Office of the Director 80/04/09 ip
- BOO7240509 Forwards IE Info Notice 80-21, "Anchorage & Support of Bafety-Related Electrical Equipment "No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/16 in
- BO07110229 Forwards IE Insp Repts 50-445/B0-14 & 50-446/B0-14 on BO0313-14 No noncompliance noted BEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch BO/05/23 2pp
- --8007i10234 IE Insp Repts 50-445/80-14 & 50-446/80-14 on 800513-16 No noncompliance noted Major areas inspected const activities, RCPB piping work & other safety-related piping work, GILBERT.4 D . HALL.R E Region 4. Dallas, Reactor Construction & Engineering Support Branch CROSSMAN, W A Region 4. Dallas, Office of the Director 80/05/23 App
- 8007020299 Forwards IE Info Notice 80-22. "Breakdowns In Contamination Control Programs" No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/05/28
- B007210351 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required SEYFRIY.K V Region 4, Dallas, Office of the Director 60/05/28
- 8007010026 Forwards IE Info Notice 80-20, "Loss of Suction to Emergency Feedwater Pumps" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director. 80/05/29
- 8007:70196 Responds to IE Bulletin BO-09, "Hydramotor Actuator Deficiencies " Six vendors identified as potential suppliers of equipment containing ITT General hydramotor actuators Vendors confirmed no actuators supplied to facilities GARY,R J Texas Utilities Generating Co BO/06/10 ip
- 8007220128 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/10, Ip.
 - 1 Repts 50-445/80-13 & 50-446/80-13

~ ~ '11. ip

↓ of Reactor

tor, 80/06/11

ACCOMENDATE HISTORY AND ACCOMENTATION OF THE ACCOUNTY OF THE ACCORDANCE OF THE ACCOUNTY OF THE A

- 8007180367 Forwards IE Insp Repts 50-445/80-11 & 50-446/80-11 in Apr-May 1980 No noncompliance noted SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 80/06/17 200
- --8007180574 IE Insp Repts 50-445/80-11 & 50-446/80-11 in Apr-May 1980, %s noncompliance noted Major areas inspected safety-related pipe & equipment installation, concrete repair activities, electrical installation & protection of major components TAYLOR, R G . CROSSMAN, W A Region 4. Dallas, Office of the Director 80/06/16 iOpp
- 8007140455 Ack receipt of IE Insp Repts 50-445/80-14 & 50-446/80-14 on 800523 No proprietary info OARY,R J Texas Utilities Generating Co 80/06/18 ip.
- 8007140497 Ack receipt of 800808 itr informing NRC of steps teten to correct violations noted in IE Insp Repts 50-445/80-13 & 50-445/80-13 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Bupport Branch 80/06/19 ip
- --8007140502 Responds to NRC Itr re violations noted in IE Imap Repts 50-445/80-13 & 50-446/80-13 Corrective actions, mgt met w/welders to reaffire importance of strict adherence to specified weld procedures.

 GARY, R J Texas Utilities Generating Co 80/06/06 4pp
- 8007240057 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/20.
- 8007170683 Forwards IE Circular 80-14, "Radioactive Contomination of Plant Demineralized Water Syx & Resultant Internal Contomination of Personnel " No written response required SEYFRIY.K.V Region 4, Dallas, Office of the Director \$0/06/24
- 8007R30370 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes" Written response required. IE Circular 80-16 also encl No written response raquired. SEYFRIT.K V Region 4. Dallas, Office of the Director. 80/06/R7
- S Reportable occurrences, LERs & related correspondence
- 8007080062 Final deficiency rept re Unit 2 reactor vessel outlet nozzles w/short safe-ends Investigation determined that matter not reportable per 10CFR50 55(e) Bupporting records available at site OARY, R, J Texas Utilities Generating Co B0/06/26 1p.
- 8007210162 PNS-IV-80-010 group of approx twelve people harassing security Porce over period of five days. State & local law enforcement authorities have been actively supporting security force.

 KELLY, J Region 4, Dallas, Office of the Director 80/07/04, is
- B007210352 Updates B00421 deficiency rept re discrepancies involving installation & insp requirements for Class 5 non-nuclear safety-related piping supports FSAR is being revised Final rept will be forwarded by B00722 QARY.R.J Texas Utilities Generating Co 80/07/14 1p
- DOCKET 50-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D @ Division of Licensing 80/06/26 2pp
- DOCKET 50-449 DOUGLAS POINT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0674 ETSENHUT, D G Division of Licensing 80/06/26 2pp.

! !

1

DOCKET 50-452 GREENHOOD ENERGY CENTER, UNIT 2

A Application/construction stage documents & correspondence

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694

EXSENSELL D 9. Division of Licensing 80/06/26 2pp

O. Adjudicatory correspondence

8007080008 Motion to compel withdrawal of application due to unwarranted delays Requests rules & regulations that will govern proceeding & necessary funds to retain legal counsel Cartificate of Bvc encl ABPERGER, R O Citizens for Energy & Employment. 80/06/02 App.

8007090297 Forwards Concerned Citizens for Employment & Energy 800402 motion to compel withdrawal of application & NRC response, to ARLB for appropriate action CHILK.S J. Office of the Secretary of the Commission 80/07/03

8007140370 Forwards request for withdrawal of application orging termination of proceeding w/o prejudice & extension of time to respond to Citizens for Employment & Energy motion, VOIGT.H H Lebosuf, Lamb, Leby & MacRes 80/07/09 2pp

--8007140378 Request for withdrawal of 730604 application w/o prejudice to future rights. Urgas continuation of withholding confidential documents from public disclosure or to be notified of contrary determination. Certificate of Svc encl VOIOT.H H Detroit Edison Co VOIOT.H H LeBoeuf, Lamb, Leiby & MacRae. 80/07/09 App.

DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3

A. Application/construction stage documents & correspondence

BOO7230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694.
EISENBUT, D G. Division of Licensing. 80/06/26 2pp.

9, Adjudicatory correspondence

8907080008 Motion to compel withdrawal of application due to unwarranted delays Requests rules & regulations that will govern proceeding & necessary funds to retain legal counsel Certificate of Svc encl.

ABPERGER, R O Citizens for Energy & Employment 80/06/02 4pp

8007090297 Forwards Concerned Citizens for Employment & Emergy 800602 motion to compel withdrawal of application & NRC responses to ABLB for appropriate action CHILK.S J Office of the Secretary of the Commission 80/07/03

8007140370 Forwards request for withdrawal of application urging termination of proceeding w/o prejudice & extension of time to respond to Citizens for Employment & Energy motion VOIQT, H H LeBbeuf, Lamb, Leiby & MacRae 80/07/09 2pp

--8007140378 Request for withdrawal of 730604 application w/o prejudice to future rights Urges continuation of withholding confidential documents from public disclosure or to be notified of contrary determination Certificate of Byc encl VOIQT.H H. Detroit Edison Co VOIQT.H H. LeBoeuf, Lamb, Leiby & MacRae. 80/07/09. App.

DOCKET 50-454 BYRON STATION: UNIT 1

A. Application/construction stage documents & correspondence

BOG7010411 Forwards documentation of safety-related electrical equipment qualification Addresses NRC Questions 40 01 & 40,77. Requests NRC approval of response format prior to incorporation into FBAR NAUGHTON, W.F. Commonwealth Edison Co. BO/06/25. 2ipp

8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREO-0660 & found in NUREO-06494
EISEMBUT, D Ø Division of Licensing 80/06/26 2pp.

8007180529 Forwards response to NRC 800421 request for info re masonry wall design Further review of masonry wall design is being conducted at LaBalle to complete response to IE Bulletin 80-ii Package of 231 oversize drawings enci PEOPLES, D. L. Commonwealth Edison Co. 80/07/08 23pp

~-8007150537 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming
* Sargent & Lundy, Inc 80/07/08 23ipp

F Security, medical, emergency & fire protection plans

8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 100FR2 790)
PEOPLES D L Commonwealth Edison Co 80/06/27 lp

Q Adjudicatory correspondence

8007310243 Forwards Commission 800527 memorandum & order containing decisions on VCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D 9 Division of Licensing 80/06/25 89pp

K Utility Final Safety Analysis Report (FSAR) & amends

B00702040B Forwards Amend 26 to FSAR NAUGHTON, W F Commonwealth Edison Co 80/04/27 Spp

--B007020420 Amend 26 to FBAR, containing portion of responses to GA Branch & Reactor Sys Branch addl first round questions * Commonweal th Edison Co B0/06/30 200pp

B0070B0R99 Forwards B00630 affidavit certifying distribution of FSAR Amend 26 NAUGHTON, W F Commonwealth Edison Co 80/06/30 2pp

8007160599 Forwards addl FSAR drawings & info for auxiliary & containment bldg structures & components in response to NRC 800616 ltr
NAUGHTON, W F Commonwealth Edison Co 80/07/03 107pp

--8007160566 "Transient Thermal Analysis of Reactor Bldg Dome Ring Section "

* Sargent & Lundy, Inc 75/09/22 74pp

--8007160569 "Thermal Transient Analysis of Reactor Didg Structural Sections "
WHITE, J G . KHARANA, S B Sargent & Lundy, Inc 79/05/05 77pp

--8007160574 Package of 182 structural drawings to be recalled at later date for microfilming * Sargent & Lundy. Inc 80/03/31 182

8007290678 Forwards drawings listed in FSAR, Subsection 1 7, per NRC request NAUGHTON W F Commonwealth Edison Co 80/07/07 1p

--8007290607 Package of 63 drawings to be recalled at later date for filming
* Westinghouse Electric Corp 72/08/04 63pp

8007140320 Forwards Amend 27 to FBAR, amending application for CPs & DLs DLs MAUGHTON, H F Commonwealth Edison Co 80/07/11 2pp

---B00714032B Amend 27 to FSAR, amending application for CPs & OLs Consists of responses to addi first round Questions 421 6-421 18, inadvertently unitted from Amend 26 * Commonwealth Edison Co B0/07/31 14pp

BOO7220540 Forwards affidavit stating that distribution of facility FSAR. Amend 27 has been made per Encl 1 to R8 Boyd 791029 ltr to C Reed NAUOHTUN, W.F. Commonwealth Edison Co. BO/07/16. Rpp

@ Inspection reports. IE Bulletins & correspondence

B007210356 Forwards IE Circular B0-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J & Region 3, Chicago, Office of the Director B0/05/28 to

- 800701008A Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/05/29 in
- 8007020050 Forwards response to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Ziom holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES, D L Commonwealth Edison Co 80/06/04 3pp
- 8007150113 Forwards IE Imsp Repts 50-454/80-08 & 50-455/80-07 on 800508-07 No noncompliance noted FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/06 2pp
- --8007150118 IE Insp Repts 50-454/80-08 & 50-455/80-07 on 800508-09 No noncompliance noted Major areas inspected licensee action on previous insp findings re employee qualification & certification & concrete coating thickness HILLIAMS C C . JONES C E Region 3, Chicago, Office of the Director 80/06/05 3pp
- 8007220154 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPLER, J.O. Region 3, Chicago, Office of the Director 80/06/10 in
- 8007160165 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11
- 8007280709 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/13 ip
- 8007100004 Forwards response to IE Bulletin 80-09, "Hydremotor Actuator Deficiencies," No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators
 PEOPLES:D L Commonwealth Edison Co BO/06/16 3pp
- 8007020589 Forwards IE Circular 80-15, "Loss of Reactor Coulant Pump Cooling & Natural Circulation Cooldown" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/20
- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/24
- B007300138 Forwards IE Insp Repts 50-454/80-11 & 50-455/80-10 on B00413 No noncompliance noted FIORELLI, C Region 3, Chicago, Reactor Construction & Engineering Support Branch B0704/25 2pp
- --B007300143 IE Insp Repts 50-454/80-11 & 50-455/80-10 on B00613 No noncompliance noted Major areas inspected results of investigation into cause of matl failure of containment post-tension sys anchor heads & corrective actions planned GALLAGHEN, E. J., KANKLIN, J. E. Region G. Chicago, Office of the Director HAVES, D.W. Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/06/23 3pp
- 8007230289 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region S. Chicago, Office of the Director 80/06/27
- 8007250638 Forwards response to LE Bulletin 80-08, "Examination of Containment Liner Penetration Welds" Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D L Commonwealth Edison Co BO/07/09 7pp
- 8007250467 Submits supplemental response to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800829 PEOPLES.D L Commonwealth Edison Co 80/07/15 ip

- S Reportable occurrences. LERs & related correspondence
- 8007020631 Interim deficiency rept re failure of post-tension103 anchorheads Generally concurs w/INRYCO 800530 rept All Category B heat treat lots will be tested Replacement anchorheads from accepted heat treat lots will be installed NAUGHTON,W F Commonwealth Edison Co 80/06/27 2pp
- 8007270061 Concurs w/anchorhead evaluation & acceptance plan proposed in 800627 final deficiency rept Implementation will be examined during future insps
 KEPPLER, J G Region 3, Chicago, Office of the Director. 80/07/18
- 8007280670 Deficiency rapt re intermittent contact operation of 神堂 switch Util will not implament interim fix unless no permanent solution is available prior to fuel load Util will monitor Westinghouse recommendations.

 NAUGHTON, W F Commenwealth Edison Co BO/07/23, 契pp

DOCKET 50~455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007010411 Forwards documentation of safety-related electrical equipment qualification Addresses NRC Guestions 40 01 & 40 77 Requests NRC approval of response format prior to incorporation into FBAR NAUGHTON, H F Commonweelth Edison Co 80/06/25 21pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISEMAUT, D @ Division of Licensing. 80/06/26. 2pp
- 8007180529 Forwards response to NRC 800421 request for info re masonry wall design Further review of masonry wall design is being conducted at LaBalle to complete response to IE Bullstin 80-ii Package of 231 oversize drawings encl PEOPLES, D. L. Commonwealth Edison Co. 80/07/08 23pp.
- --8007150537 Package of 231 concrete masonry wall drawings to be recalled at later date for microfilming
 # Sargent & Lundy, Inc 80/07/08, 231pp
- F Security, medical, emergency & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790).
 PEOPLES D. L. Commonwealth Edison Co. 80/06/27 1p.
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables.

 EISENHUT.D 9 Division of Licensing 80/06/25 89pm
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8007020408 Forwards Amend 26 to FBAR
 NAUGHTON, W F Commonwealth Edison Co 80/06/27 5ep
- --8007020420 Amend R& to FSAR, containing purtien of responses to GA Branch & Reactor Sys Branch addl first round questions. • Commonwealth Edison Co 80/06/30 200pp
- B0070B0299 Forwards B00630 affidavit certifying distribution of FBAR Amend 26 NAUGHTUN, W F Commonwealth Edison Co 80/06/30 2pp.
- 8007160359 Forwards addl FSAR drawings & info for auxiliary & containment bldg structures & components in response to NMC 800616 ltr NAUGHTON, W F Commonwealth Edison Co 80/07/03, 107pp
- ----8007160566 "Transient Thermal Analysis of Reactor Oldy Dome Ring Section"

 * Sargent & Lundy, Inc 75/09/22, 74pp.
- --807140869 "Thermal Transient Analysis of Reactor Øldg Structural Sactions " WillELJ G . KHARANA, S S Sargent & Lundy, Inc 79/03/03. 77pp

- 8007290678 Forwards drawings listed in FSAR, Subsection 1 7, per NRC NAUGHTON, W F Commonwealth Edison Co 80/07/07 ip
- filming * Westinghouse Electric Corp 72/08/04 63pp
- 8007140320 Forwards Amend 27 to FSAR amending application for CPs & NAUGHTON.W F Commonwealth Edison Co 80/07/11 2pp
- --8007140328 Amend 27 to FBAR, amending application for CPs & OLs Consists of responses to addl first round Questions 421 6-421 18, inadvertently omitted from Amend 26 commonwealth Edison Co 80/07/31 14pp
- B007220540 Forwards affidavit stating that distribution of facility FSAR, Amend 27 has been made per Encl 1 to RS Boyd 791029 ltr NAUCHTON, W.F. Commonwealth Edison Co. 80/07/16 2pp
- G. Inspection reports, IE Bulletine & correspondence
- 8007210396 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J G Region 3, Chicago. Office of the Director 80/05/28
- 8007010086 Forwards IE info Notice 80-23, "Loss of Suction to Emergency Faedwater Pumps " No written response required KEPPLER.J & Region 3, Chicago. Office of the Director 80/03/29
- B007020030 Forwards response to IE Bullotin B0-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Zion holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES, D L Commonwealth Edison Co 80/06/04 3pp
- 8007150113 Forwards IE Insp Repts 50-454/80-08 & 50-455/80-07 on 800508-09 No honcompliance noted FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/06 2pp
- --8007150118 IC Insp Repts 50-454/80-08 & 50-455/80-07 on 800508-09 No noncompliance noted Major areas inspected licensee action on previous insp findings re employee qualification & cortification & concrete coating thickness WILLIAMS C C . JONES C E Region 3, Chicago, Office of the Director 60/06/05 3pp
- 8007220156 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/10
- B007160145 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11
- 8007280709 Forwards 1E Info Notice 80-28. "Prompt Reporting of Info in Accordance W/1007R90 55(e) " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/13
- 8007100004 Forwards response to 1E Bulletin 80-09. "Hydramotor Actuator Deficiencies." No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor PEOPLES, D. L. Commonwealth Edison Co. 80/06/14 3pp
- 8007020599 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required MEPPLER. J G Region 3. Chicago, Office of the Director 80/06/20
- 8007170430 Forwards IE Circular 80-14, "Radiuactive Contamination of Plant Deminerolized Water Sys & Resultant Internal Contamination of Personnol " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24

- 800730013B Forwards IE Insp Repts 50-454/80-11 & 50-455/80-10 on 800413 No noncompliance noted FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 80706/25 2pp
- --8007300143 IE Insp Repts 50-454/80-11 & 50-455/80-10 on 800613 No noncompliance noted Major areas inspected results of investigation into cause of matl failure of contains post-tension sys anchor heads & corrective actions planned GALLAGHER.C J. KANKLIN, J E Region 3. Chicago. Office of the Director HAYES, D W Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/23 Jpp
- 8007230289 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular BO-16 also encl No written response required KEPPLER.J Q Region 3, Chicago, Office of the Director
- 800725063B Forwards response to IE Bulletin 80-08. "Examination of Containment Liner Penetration Welds" Dresden Unit I designs will be revioued & feasibility of performing radiographic examinations will be associated before unit returned to ave PEOPLES,D L Commonwealth Edison Co 80/07/09 7pp
- 8007250467 Submits supplemental response to IC Bulletin 80~09, "Hydramotor Actuator Deficioncies" Util review remains incomplete due to necessity of consulting equipment suppliors Response will be submitted by 800829 PEQPLES.D L Commonwealth Edison Co 80/07/15 ip
- 8 Reportable occurrences, LERs & related correspondence
- B007020631 Interim deficiency rept re failure of post-tensioning anchorheads Generally concurs w/INRYCO 800530 rept All Category B heat treat lots will be tested Replacement anchorheads from accepted heat treat lots will be installed NAUGHTON.W F Commonwealth Edison Co 80/06/27 2pp
- 8007270061 Concurs w/anchorhead evaluation & acceptance plan proposed in 800627 final deficiency rept Implementation will be examined during future insps
 KEPPLER.J G Region 3. Chicago, Office of the Director 80/07/18
- BO07280670 Deficiency rept re intermittent contact operation of W-2 switch Util will not implement interim fix unless no permanent solution is available prior to fuel load Util will monitor Hestinghouse recommendations

 NAUGHTON, W F Commonwealth Edison Co BO/07/23 2pp
- DOCKET 50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007010411 Forwards documentation of safety-related electrical equipment qualification Addresses NRC Questions 40 01 & 40 77 Requests NRC approval of response format prior to incorporation into FSAR NAUGHTON.W F Commonwealth Edison Co 80/06/25 21pp
- BOO7230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 & found in NUREG-0694 EISENHUT.DG Division of Licensing 80/06/26 2pp
- 8007150529 Forwards response to NRC 800421 request for info re masonry wall design Further review of masonry wall design is being conducted at LaSalle to complete response to IE Bulletin 80-11 Package of 231 oversize drawings encl PEOPLES.D L Commonwealth Edison Co 80/07/08 23pp
- --8007150537 Pockage of 231 concrete masonry wall drawings to be recalled at later date for microfilming
 * Sargent & Lundy: Inc 80/07/08 231pp
- F Security, medical, emergency & fire protection plans
- 8007010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES, D. Commonwealth Fdison Co. 80/06/27 Jp

- G Adjudicatory correspondence
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UC9 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT.D G Division of Licensing 80/06/25 89pp
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8007020408 Forwards Amend 26 to FSAR NAUGHTGN:W F Commonwealth Edison Co 80/06/27 5pp
- --8007020420 Amend 26 to FSAR, containing portion of responses to GA Branch & Reactor Sys Branch add1 first round questions * Commonwealth Edison Co 80/06/30 200pp
- B0070B0299 Forwards B00630 affidavit certifying distribution of FSAR Amend 25 NAUGHTON W F Commonwealth Edison Co 80/06/30 2pp
- BOO7160559 Forwards add1 FSAR drawings & info for auxiliary & containment bldg structures & components in response to NRC BOO616 1T
 NAUGHTON W F Commonwealth Edison Co BO/07/03 107pp
- --8007160566 "Transient Thermal Analysis of Reactor Bldg Dome Ring Section "
 - * Sargent & Lundy, Inc 75/09/22 74pp
- --8007160569 "Thermal Transjent Analysis of Reactor Bldg Structural Sections" WHITC, J G . KHARANA: S B Sargent & Lundy, Inc 79/05/05 77pp
- ---8007±60574 Package of 182 structura) drawings to be recalled at later date for microfilming
 * Sargent & Lundy. Inc. 80/03/31 182
- 8007290678 Forwards drawings listed in FSAR. Subsection 1 7. per NRC request NAUGHTON. W F Commonwealth Edison Co 80/07/07 1p
- --80072905B7 Package of 63 drawings to be recalled at later date for filming
 * Westinghouse Electric Corp 72/08/04 63pp
- 8007140320 Forwards Amend 27 to FSAR, amending application for CPs &
- OLs
 NAUGHTON-W F Commonwealth Edison Co 80/07/11 2pp
- --8007140J28 Amend 27 to FSAR, amending application for CPs & OLs Consists of responses to addi first round Questions 421 6-421 18, inadvertently omitted from Amend 26
 * Commonwealth Edison Co 80/07/31 14pp
- BO07220340 Forwards affidavit stating that distribution of facility FSAR.Amend 27 has been made per Encl 1 to RS Boyd 791029 ltr to C Reed NAUGHTON, W F Communealth Fdison Co BO/07/16 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007210356 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER, J G Region 3, Chicago, Deffice of the Director 80/05/28, to
- 8007010086 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written rosponse required XEPPLER.J G Region 3, Chicago, Office of the Director 80/05/29 Ip
- B007020050 Forwards response to IE Bulletin B0-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Zion holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES.O L Commonwealth Edison Co H0/06/04 Spp
- 8007180508 Forwards IE Insp Repts 50-456/80-05 & 50-457/80-05 on 800429 & 0520 & natice of violation FIGRELLIG Region 3. Chicago. Reactor Construction & Engineering Bupport Branch 80/06/05 Upp
- --B007iB05i3 Notice of violation from insp on B00429 & 0520
 * Region 3, Chicago, Office of the Director 90/06/03, 2pp

- ---B007180519 IE Insp Repts 50-456/80-05 & 50-457/80-05 on 800429 & 0520.

 Noncompliance noted failure to perform surveillance on valves in storage & failure to meet walding or storage procedure requirements

 LEE,E W Region 3, Chicago, Office of the Director DANIELSON, D H Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/03 Spp
- B007220196 Forwards IE Info Notice 80~26, "Evaluation of Contractor GA Programs" No written response required KEPPLER.J O Region 3, Chicago, Office of the Director B0/06/10, in
- 8007230002 Forwards IE Insp Repts 50-456/80~04 & 50-457/80-04 on 800514-15 & notice of violation FIORELLI, C Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/10 2pp
- --8007230006 Notice of violation from insp on 800514-15 a Region 3, Chicago, Office of the Director 80/06/09 ip
- --B007230019 IE Insp Repts 50-456/B0-04 & 50-457/B0-04 on B00514-15.
 Noncompliance noted failure to assure design basis
 correctly translated into specs
 SCHMEIBINZ, E R. GALLACHER, E J., WILLIAMS, C C. Region 3. Chicage,
 Office of the Director B0/06/09 9pp
- 8007160163 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER.J G Region 3. Chicago. Office of the Director 80/06/11
- 8007280709 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR90 95(e) " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director 80/06/13
- 8007100004 forwards response to IE Bulletin 80-09. "Hydramotor Actuator Deficiencies." No safety-related sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators PEDPLES.D L. Commonwealth Edison Co. 80/06/16. 3pp
- 8007020989 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/06/20.
- 8007170430 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No writton response required KEPPLER, J. G. Ragion 3, Chicago, Office of the Director BO/06/24 to
- 8007230289 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Mritten respanse required IE Circular 80-16 also entl No written respanse required KEPPLER, J G Region 3. Chicago. Office of the Director 80/06/27.
- 8007280638 Forwards response to IE Bulletin 90-08, "Examination of Containment Liner Penetration Welds" Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to svc PEOPLES.D L. Commonwealth Edison Co 80/07/09 7pp.
- 8007250467 Submits supplemental response to IE Bullotin 80-09, "Hydramotor Actuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800829 PEOPLES.D L. Commonwealth Eduson Co 80/07/15 1p
- 8007240340 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/80-05 & 50-457/80-05 FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/16 ip
- --B007240351 Responds to NRC B00605 ltr re violations noted in IE Insp Repts 50-456/B0-05 & 50-457/B0-05 Corrective actions, weave would procedures reviewed & rod oven calibr checked PEOPLES, D. L. Commonwealth Edison Co. 80/07/09 App

- B Reportable occurrences. LERs & related correspondence
- GOO7280670 Deficiency rept re intermittent contact operation of W-2 switch Util will not implement interim fix unless no permanent solution is available prior to fuel load Util will monitor Westinghouse recommendations

 NAUOHTON.W F Commonwealth Edison Co BO/07/23 2pp

DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007010411 Forwards documentation of safety-related electrical equipment qualification Addresses NRC Questions 40 01 & 40 77 Requests NRC approval of response format prior to incorporation into FSAR Commonwealth Edison Co 80/06/25 21pm
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NRREG-0694 EIBENHUT, D 0 Division of Licensing 80/06/26 2pp

- 8007180529 Forwards response to NRC B0D421 request for info re masonry wall design Further review of masonry wall design is being conducted at LaBalle to complete response to IE Bulletin 60-ii Package of 231 oversize drawings encl PEOPLES, D. L. Commonwealth Edison Co. 80/07/08 23pp
- F. Security, medical, emergency & fire protection plans
- BO07010347 Forwards safeguards contingency plan amend Plan withheld (ref 10CFR2 790)
 PEOPLES D L: Commonwealth Edison Co 80/06/27 in
- Q. Adjudicatory correspondence
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENNUT, D Q Division of Licensing 80/06/25 89pp
- M. Utility Final Safety Analysis Report (FSAR) & amends
- B00702040B Forwards Amend 26 to FSAR MAUGHTON, W. F. Commonwealth Edison Co 80/06/27 5pp
- 8007080299 Forwards 800630 affidavit certifying distribution of FBAR NAVOHTON, W.F. Commenwealth Edison Co. 80/06/30 2pp
- 8007140559 Forwards addl FHAR drawings & info for auxiliary & containment bldg structures & components in response to NRC 800616 ltr NAUGHTON, W F Commonwealth Edison Co 80/07/03 107pg
- * Sargent & Lundy, Inc 75/09/22 74pp
- --- 8007160569 "Thermal Transient Analysis of Reactor Bldg Structural Sections " WHITE.J G Sargent & Lundy, Inc 79/05/05 77pp
- --8007i60574 Package of 182 structural drawings to be recalled at later date for microfilming * Sargent & Lundy, Inc 80/03/31 182,
- 8007290678 Forwards drawings listed in FBAR, Subsection 1, 7, per NRC request. NAUGHTON:W F Commonwealth Edison Co 80/07/07, ip
- --8007290687 Package of 63 drawings to be recalled at later date for Westinghouse Electric Corp 72/08/04 63pp

- 8007140320 Forwards Amend 27 to FSAR amending application for CPs & NAUGHTON.W F Commonwealth Edison Co 80/07/11 2pp
- --B007140328 Amend 27 to FSAR.amending application for CPs & OLs Consists of responses to addl first round Questions 421 6-421 10, inadvertently omitted from Amend 26
 * Commonwealth Edison Co 80/07/31 14pp
- 8007220540 Forwards affidavit stating that distribution of facility FSAR, Amend 27 has been made per Encl i to R5 Boyd 791029 ltr to C Reed NAUGHTON, W.F. Commonwealth Edison Co. 80/07/16 2pp
- O Inspection reports, IE Bulletins & correspondence
- B007210356 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director 8 B0/05/28
- B007010086 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/05/29
- B007020030 Forwards response to IE Bulletin B0-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Three Zion holdup tanks can be valved to contain primary sys water Positive pressure is maintained PEOPLES.D L Commonwealth Edison Co 80/06/04 3pp
- 8007180908 Forwards IE Insp Repts 50-496/80-05 & 50-457/80-05 on 800429 & 0520 & notice of violation FigRELLI, Q Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/05 2pp
- --B007180513 Notice of violation from insp on 800427 & 0520 * Region 3. Chicago, Office of the Director B0/06/03
- --8007180519 IE Insp Repts 50-456/80-05 & 50-457/80-05 on 800429 & 0520 Noncompliance noted failure to perform surveillance on valves in storage & failure to meet welding or storage valves in storage & railore to meet weiling or storage procedure requirements
 LCE.E W Region 3, Chicago, Office of the Director
 DANIELSON.D H Region 3, Chicago, Reactor Construction &
 Engineering Support Branch 80/06/03 5pp
- 8007220196 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required REPLER.J G Region 3, Chicago, Dffice of the Director 80/06/10
- 8007230002 Forwards IE Insp Repts 50-456/80-04 & 50-457/80-04 on B00314-15 & notice of violation FIGRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/10 2pp
- --8007230006 Notice of violation from insp on 800514-15
 * Region 3, Chicago, Office of the Director 80/0 80/06/09 in
- -8007230019 IE Insp Rupts 50-494/80-04 & 50-497/80-04 on 800514-15 Noncompliance noted Failure to assure design basis correctly translated into specs SCHWEIBINZ, E. R., OALLAGHER, E. J., WILLIAMB, C. C. Region 3, Chicago. Office of the Director 80/06/09
- B007160165 Forwards IE Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response REPPLER, J G Region 3. Chicago, Office of the Director 80/06/11
- 8007280709 Forwards IE Info Notice BO-28. "Prompt Reporting of Info in Accordance W/100FR50 95(e) " No written response required KEPPLER, J & Region 3, Chicago, Office of the Director 80/04/13
- B007100004 Forwards response to IE Bulletin B0-09, "Hydramotor Actuator Deficiencies," No safety-rolated sys or component at Dresden 2 & 3 uses AH-90 or NH-90 series hydramotor actuators PEOPLES, D.L. Commonwealth Edison Co 80/04/14 3pp
- B007020589 Forwards IE Circular 80-15, "Loss of Reactor Coalant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3, Chicago, Office of the Director B0/04/20

- 8007170430 Forwards IE Circular 80-14, 'Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel ' No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/24
- 8007230289 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Butput Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3. Chicago, Office of the Director ip
- 800725063B Forwards response to IE Bulletin 80-0B. "Examination of Containment Liner Penetration Welds" Dresden Unit 1 designs will be reviewed & feasibility of performing radiographic examinations will be assessed before unit returned to syc PEOPLES, D. L. Commonwealth Edison Co. 60/07/09 7pp
- 8007250467 Submits supplemental response to 1E Bulletin 80-09, "Hydramotor Actuator Deficiencies" Util review remains incomplete due to necessity of consulting equipment suppliers Response will be submitted by 800827 PEOPLES,D L Commonwealth Edison Co 90/07/15 lp
- 8007240340 Ack receipt of 800709 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/80-05 & 50-457/80-05 FIORELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/16 ip
- ~~800724035; Respond= to NRC 800605 ltr re violations noted in IE Insp Repts 50-456/80-05 & 50-497/80-05 Corrective actions weave weld procedures reviewed & rod oven calibr checked PtOPLES,D L Commonwealth Edison Co 80/07/09 4pp
- 5 Reportable occurrences. LERs & related correspondence
- B0072B0670 Deficiency rept re intermittent contact operation of W-2 whitch Util will not implement interim fix unless no permanent solution is available prior to fuel load Util will monitor Nestinghouse recommendations

 NAUGHTON, W F Commonwealth Edison Co 80/07/23 2pp

DOCKET 50~458 RIVER BEND STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8007010558 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO,R L Assistant Director for Licensing 80/06/13 2pp
- .0007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREQ-0660 & found in NUREQ-0694 EISENHUT.D Q Division of Licensing 80/06/26 2pp
- 8007080191 Forwards Qualification Summary Repts 33-52260-QS for Hope Creek & 33-54237-QS for River Bend reflecting documentation of electrical equipment qualification Ropts withheld (ref 10CFR2 790)

 DUVALL.D D Gould-Brown Bovers 80/07/01 ip
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800327 memorandum & order containing decisions on UFS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp
- H General correspondence
- B007140638 F01A request for documents re three Mar 1980 violations occurring at facility
 KRAUSE.L. Affiliation Unknown B0/06/15 1p
- 8007020684 Responds to 800611 request for clarification re alteration of property mentioned on Page 14 of prelimary case rept on Port Hudson Battlefield Landmark in LA Alteration referred to is widening of electrical transmission line corridor REGAN, W.H. Siting Analysis Branch 80/06/18 ip
- 8007140635 Responds to FOIA request for documents re three Mar 1980 violations occurring at facility Forwards listed documents FELTON.J M Division of Rules and Records 80/07/07 ip

- Q Inspection reports. IE Bulletins & correspondence
- B007250316 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYFRIT,K V Region 4, Dallas, Office of the Director 80/03/31
- 8007210137 Ack receipt of 800305 ltr informing NRC of steps tolen to correct items of noncompliance noted in IE Insp Rept 50-458/79-06 on 791118-21 & 1204-07 Requests addl info rs Items A-1 & B-2 SEIDLE-W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/04/01 2pp
- --8007210148 Responds to violations noted in IE Insp Rept 50-498/79-04 en 791118-21 & 1204-07 Mortar bar tests are being conducted to determine if high alkalai cement may be used w/util source aggregate in future
 WEIGAND.J O Guif States Utilities Co 80/03/05 4pp.
- 8007140968 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required BEYFRIT,K V Region 4, Dallas, Office of the Director 90/05/12,
- 8007240511 Forwards IE Info Notice 80~21, "Anchorage & Support of Safety-Related Electrical Equipment " No written response required SEYFRIT.K V Region 4, Dallas. Office of the Director 80/05/16
- 8007020249 Forwards IE Info Notice 80-22, "Breakdowns In Contemination Control Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- 8007010028 Forwards IE Info Notice 80-23, "Loss of Suction to Emergancy Feedwater Fumps" No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/29,
- 8007220104 Forwards IE Info Notice 80-R6. "Evaluation of Contractor GA Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/04/10
- 8007140404 Forwards IE Bulletin 80-14, "Degradation of BMR Scram Discharge Vol Capability " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/12 tp
- 800/290057 Forwards IE info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/13
- 8007240035 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/20
- 8007170669 Forwards IE Circular 80-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel" No written response required. SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/24
- 8007290376 Forwards IE Dulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes" Written response required IE Circular 80-16 also uncl No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/27.
- 8007220594 Submits response to IE Bulletin 80-11 re Category 1 masonry walls employed by plants under CP & IL review Station engineering design criteria indicate that no piping or equipment will be supported from masonry walls.

 DRAPER.E L Gulf States Utilities Co 80/07/15, ip

SOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8007010958 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation effective BODARB Considerations re activities should be made through assigned mgt representatives Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing BO/06/13 B0/06/13 2pm
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0860 & found in NUREG-0894 EISENMUT. D G Division of Licensing 80/06/26 2pp
- 8007080191 Forwards Qualification Summary Repts 33-52260-GS for Hope Creek & 33-54237-GS for River Bend reflecting documentation of electrical equipment qualification Repts withhold (ref 10CFR2 770)

DUVALL, D.D. Gould-Brown Dovert 60/07/01 1p

O Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UC9 780302 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action refree protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007280316 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary Region 4. Dallas, Office of the Director 60/03/31
- 8007140568 Forwards 1E Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/12
- 8007240811 Forwards IE Info Notice 80-21. "Anchorage & Support of Bafety-Related Electrical Equipment" No written response BEYFRIT.K V Region 4. Dellas, Office of the Director BO/05/14
- B007020249 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- 8007010028 Forwards IE Info Notice 80-23, "Lass of Suction to Emergency Feedwater Pumps " No written response required BEYFRIT, K V Region 4, Dallas, Office of the Director 80/05/29
- 8007220104 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/10
- 8007140404 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/12
- 8007270057 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required SEYFRIT.K V Region 4, Dollas, Office of the Director, 80/06/13
- B007240035 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No writton response required SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/20
- 8007170669 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/24

- 8007230376 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters
 W/Either A or D Output Codes " Written response required
 IE Circular 80-16 also ent No written response required
 SEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/27
- DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007030197 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO.R L Assistant Director for Licensing 80/06/12 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694 EISENHUT D C Division of Licensing 80/06/26 2pp
- 8007210392 Ack receipt of NRC 800430 ltm approving request to discontinue certain aquatic munitoring & requesting copies of util submittals to State of HA re water quality TAC does not have authority to require water quality filings RENBERGER,D L. Washington Public Power Supply System 80/4
- B007250544 Forwards "Reliability Evaluation of WPPS9 Nuclear Projects Numbers 1 & 4." in response to NRC 800124 request for evaluation of loss of main feedwatter event RENBERGER.D L Washington Public Power Supply System 80/07/22
- --BOO7250552 "Reliability Evaluation of WPP59 Nuclear Projects Numbers 1 & 4." Vol 1 main rept MCBRIDE, A.F., MINARICK, J.W., BOZARTH, D.P. Science Applications, 60/07/15 21400
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800927 memorandum & order containing rerwards Commission 800927 memorandum & order contidecisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- O Inspection reports, IE Bulletins & correspondence
- 8007270444 Responds to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II, Two-Inch, Tray Adsorber Colls " Standardized 31 5 X 23 inch, flat bed, Type II charcoal adsorber cell units used in all cleanup sys RENBERGER,D L Washington Public Power Supply System 80/03/19
- 8007220252 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required ENGLIKEN, R H. Region 5. San Francisco. Office of the Director 80/04/10
- B007300299 Forwards response to IE Bulletin 80-05 re vacuum damage to chemical control sys tanks Design changes to low pressure process tanks not required Table describing subj tanks & protection provided encl RENBERGER.D L. Washington Public Power Supply System 80/06/12
- B007290090 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/IOCFR50 55(t)" No written response required ENGELKEN.R H Region 5. San Francisco, Office of the Director 80/06/13 ip
- 8007020466 Forwards IE Circular 80-ib. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/06/20
- B007180299 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralized Water 9ys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN,R H Region 5. San Fiancisco. Office of the Director B0/06/24 lp

- B007230401 Forwards IE Bulletin B0-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Hritten response required IE Circular B0-16 also encl No written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director B0/06/27 10
- 8007290518 Responds to IE Bulletin 80-08 Problems re containment liner pentration weld do not exist at facility Design for primary piping typical of ASME code configurations Process pipe/flued head assemblies not installed RENBERGER, D.L. Washington Public Power Supply System 80/07/10
- S Reportable occurrences, LERs & related correspondence
- BOO7170577 Forwards interim deficiency rept re defective condition in design of floor supporting component cooling & makeup pump area heating, ventilation & air conditioning sys Train B equipment
 BENBERGER, D. L. Washington Public Power Supply System BO/07/11
- ---8007170885 Interim deficiency rept re defective condition in floor supporting component cooling & makeup pump area Caused by usage of incorrect vertical amplified response spectra Structural frame designed for installation

 * Hashington Public Pawer Supply System 80/07/11 2pp
- U Congressional/Executive Correspondence
- B007300367 Submits questions re unusual financing arrangement between util & Bonneville Power Administration Related correspondence WEAVER.J House of Rep. 80/07/14 2pp
- DOCKET 50-461 CLINTON POWER STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007010243 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activites should be made through assigned mpt representative Areas of disagreement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- B007020433 Notification of cancelled 800624-26 site visit w/util to determine status of completion of const BUCKLEY.B Licensing Branch 3 B0/06/17 3pp
- B007230001 Forwards statement of policy re requirements to be met for current CL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT.D G Division of Licensing 80/06/26 2pp
- 8007250559 Advises NRC that util is planning repairs to reactor pressure vessel GE has been authorized to perform work, which has been subcontracted to Reactor Controls, inc Defective ellow on reactor drain line will be replaced KDCH.L J Illinois Power Co E0/07/02 ip
- 0. Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT.D & Division of Licensing 80/06/25 89pp
- O Inspection reports, IE Bulletins & correspondence
- 8007140495 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required 3. Chicago: Office of the Director 80/05/12

900414-18 & 21-22 & tion & Engineering

4-18 & 21-22 80/05/16 2pp --B00711016B IE Insp Rept 50~461/B0-06 on 800414-18 & 21-22 Noncompliance noted measures not established for control of purchased matl or for 80 of identified structrues HESCHTI,H M. GALLAGHER,E J. KNOP,R C. Region 3, Chicago, Office of the Director 80/05/16 14pp

1

- 8007010104 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J O Region 3. Chicago. Office of the Director 90/05/29, 1p
- 8007220204 Forwards IE Info Notice 80~26, "Evaluation of Contractor GA Programs" No written response required KEPPLER.J O Region 3. Chicago, Office of the Director 80/06/10 to
- 8007160751 Forwards IE Insp Rept 50-461/80-09 on 800520-23 & notice of violation FIORELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/11 2pp
- ---8007160756 Notice of violation from insp on 800520-23 * Region 3, Chicago, Office of the Director 80/06/07 ip
- --8007160764 IE Insp Rept 50-461/80-09 on 800520-23 Noncompliance noted inadequate insp during concrete work activities HESCOTT.H M . GALLAOHER.E J . KNOP.R C Region 3. Chicago. Office of the Director 80/06/09 7pp
- B007140325 Forwards IE Bulletin 80-14. "Degradation of DWR Scram Discharge Vol Capability " No written response required KEPPLER.J Q Region 3, Chicago, Office of the Director 80/06/12
- 8007030215 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies " Licensee does not utilize actuator models in sefety-related applications, WULLER.0 E Illinois Power Co 80/06/13 lp
- 8007280638 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required REPPLER, J G Region 3, Chicago, Office of the Director 80/06/13, 1b
- 8007110228 Ack receipt of 800607 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/80-07. FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/19 ip
- --8007110233 Responds to NRC 800509 ltr re violations noted in IE Insp Rept 50-461/80-07 Corrective actions removed sandwich & all weld rods stored in oven & destroyed flux coated rod to prevent possible use GERSTNER.W C Illinois Power Co 80/06/09 2pp
- 8007020594 Forwards IE Circular 80-19, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/20 ip
- B007310363 Forwards IE Insp Rept 50-461/80-10 on B00501-30 & notice of viglation FIDRELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch B0/06/23 2pp
- --8007310366 Notice of violation from insp on 800501-30
 # Region 3, Chicago, Reactor Construction & Engineering Support
 Branch 80/06/17 ip
- --B007310367 IE Insp Rept 50-461/B0-10 on B00501-30 Noncompliance noted: control rod drive penetration rework activity performed w/o written approved instructions or approved design change. LIVEMORE, H H , KNOP, R C Region 3. Chicago, Defice of the Director B0/06/19 4pp
- B007170495 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnal" No written response required KEPPLER: J G Region 3: Chicago: Office of the Director B0/06/24 ip
- 8007210516 Ack receipt of 800617 ltr informing NRC of staps taken to correct violations noted in IE Insp Rept 50-461/80-06 FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/24 ip

- 9007230330 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also enci No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/27
- 8 Reportable occurrences, LERs & related correspondence
- 8007140202 Ack recuipt of 800613 interim deficiency rept re concrete embeds that failed to meet designer specs FIDRELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/24 ip
- 80071805i1 Ack receipt of 800624 interim deficiency rept re control rod drive genetrations through drywall FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/07 ip
- 8007160626 Forwards deficiency repts inadvertently sent to Region 3 instead of IE headquarters HMXLER, G E Illinois Power Co 80/07/08 2pp
- ---BOO7160651 Deficiency rept re breakdown in GE C&ID quality sys Improper or inadequate GA documentation was provided for antety-related equipment (local panels) delivered to site Product quality certifications revised accordingly KOCH.L J Illinois Power CO 80/04/30 2pp
- ---8007i60679 Potential deficiency rept re control rod drive penetrations through drywell wall Util requires approx 3 wks to make reportability determination KCCH.L J Illinois Power Co 80/06/24 ip
- 8007230518 Interim deficiency rept re nonconforming elbow in two-inch drain line from reactor pressure vessel Foreign matl found in elbow Removal of elbow scheduled for wk of 800714 Final rept will be submitted late Aug 1980 KOCH.L J Illinois Power Co 80/07/14 2pp
- 8007300427 Supplemental deficiency rept re Sargent & Lundy soil characteristics error in facility design Investigations revealed use of incorrect value of soil modules for compacted backfull Reportability determination not complete.

 KOCH.L J Illinois Power Co 80/07/15 2pp
- BOO7280506 Final deficiency rept re control rod drive (CRD) penetrations through drywell wall Control drive tubes which have been adversely affected by welding are being replaced KOCH.L J Illinois Power Co BO/07/18 5pp
- DOCKET 50-462 CLINTON POWER BYATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8007010243 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activites should be made through assigned mgt representative Areas of disappeement may be discussed through informal appeal TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREQ-0660 & found in MUREQ-0674 EISENHUT, D Q Division of Licensing 80/06/26 2pp

G Adjudicatory correspondence

- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780902 potation for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EIBENHUT, D G Division of Licensing B0/06/25 89pp
- O Inspection reports. IE Bulletins & correspondence
- 8007140495 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/12
- 8007010104 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/29 in
- 8007220204 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/10 in
- 8007140325 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/12
- B007030215 Responds to IE Bulletin B0-09, "Hydramotor Actuator Deficiencies" Licensee does not utilize actuator models in safety-related applications WULLER.G E Illinois Power Co B0/06/13 1p
- 8007280638 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 58(p)" No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/13, to
- B007020584 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/20
- 8007170495 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/24
- B00723030 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/27
- 8 Reportable occurrences, LERs & related correspondence
- B0071B051i Ack receipt of B00624 interim deficiency rept re control rod drive penetrations through drywall FIORELLI,Q Region 3. Chicago, Reactor Construction & Engineering Bupport Branch B0/07/07 lp
- 8007160626 Forwards deficiency ropts inadvertently sent to Region 3 instead of IE headquarters WULLER, 6 E 111nois Power Co 80/07/08 2pp
- DOCKET 50-463 FULTON GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B007110274 Forwards add1 questions re alternative sites If util intends to pursue CP application.NRC should be advised of schedule for submitting required info MILLERJ R Standardization & Special Projects Branch 80/04/25
- I Financial information
- B007010138 Responds to 800605 ltr to Q Cunningham transmitting util 8-7 ragistration statement No inaccurate statements or financial inconsistency identified CHRISTENBURY.E Hearings Division 80/06/19 ip

DOCKET 50-444 FULTON GENERATING STATION, UNIT 2

A Application/construction stage documents & correspondence

8007110274 Forwards addl questions re alternative sites If util intends to pursue CP application.NRC should be advised of schedule for submitting required info MILLER.J R Standardization & Special Projects Branch 80/04/25

I Financial information

8007010138 Responds to 800605 ltr to 6 Cunningham transmitting util 8-7 registration statement No inaccurate statements or financial inconsistency identified CHRISTENDURY,E Hearings Division 80/06/19 1p

••••••

DOCKET 50~466 ALLENS CREEK NUCLEAR STATION, UNIT I

A Application/construction stage documents & correspondence

800703039 Comments on proposed rules 10CFR50 & 51 requirement that Class 9 accidents be considered in EIG should be applied retroactively to plant since site has not been fully determined DOHERTY, J.F. Doherty, J.F. 80/05/04 1p

B007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0650 & found in NUREG-0654
EISENHUT.D G Division of Licensing 80/06/26 2pp

G Adjudicatory correspondence

BOO7030025 Response in apposition to applicant notice of deposition Urges that applicant be ordered to informally contact D Marrack for deposition arrangements after answering encl interrogatories & request for production of documents MARRACK, D Harrack, D 80/06/11 ip

--8007030029 Interrogatories & requests for production of documents re intervenor Contention 2E that £18 do not address power line impacts on migratory waterfool Certificate of Syc encl MARRACK,D Marrack,D 80/86/11 5pp

8007110080 Motion to compel applicant answers to intervenors' 800908 interrogatories & request for production of documents Certificate of Svc encl Related carrespondence MARRACK, D Marrack, D RENFRD, W Affiliation Unknown 80/06/16

8007100174 Concurs w/800611 proposal to consolidate interrogatories Baker 1. Cumings 1. TX PIRO Addl 32. Doggett 4 & Perronod 1 w/ Baker as representative Confirms that Doggett will lead party on consolidated contentions Bishop 14 & Doggett 1(b) DDGGETT. B A Doggett. B A 80/06/20 2pp

8007020471 Response to JF Doherty fourteenth set of interrogatories Includes info re anticipatd enrichment of spent fuel stored in pool racks, self-sufficiency of fuel pool cooling sys & applicant position on Reg Guide i 13 M/Gertificate of Svc BIDDLE, C T. NEWMAN, J. R. Houston Lighting & Power Co. BIDDLE, C T. Baker & Botts BO/04/24 37pp

8007020636 Order denying B Daker 800611 motion to compel discovery from applicant, consolidating certain of Baker, Cumings, Tx PIRO, Doggett & Perrenod contentions & granting partial lelef to Rentfro & Marrack re motion to compel applicant answers MDLFE, S J Atomic Safety and Licensing Board Panel 80/06/27 Spp

800703006: Protective order allowing JF Doherty to inspect specific safety-related items from vendor OE "Reed Rept," in possession of util Insp is conditioned on confidential treatment per encl agreement HOLFE.S J Atomic Safety and Licensing Board Panel 80/06/27 App

B007230246 FOIA request for 20 documents for use as intervenor in facility proceeding DOHERTY, J. F. Doherty, J. f. 80/06/27 4pp

> orwards Page 12 to be inserted in applicant response to JF th set of interrogatories Related correspondence Baker & Botto BO/06/30 ip

- --8007080019 Page 12 of applicant response to JF Doberty 14th set of interrogatories Includes info re rod drop analysis & performance BIDDLE,C T Houston Lighting & Power Co 80/06/30 ip
- --B007080017 Response to JF Doherty 15th set of interrogatories. Contains statements re neutron data.clad swelling calculation.control rod drop accident & reactor pressure vessel pedestal Affidavit & Certificate of Svc encl BIDDLE.C T, NEHMAN.J R Houston Lighting & Power Co BIDDLE.C.T. Baker & Botts B0/06/20 21pp
- 8007090290 Request to withdraw portion of intervenor 800611 motion to compel discovery from applicant due to availability of certain documents for inspire most recent rate case H/Ceptificate of Svc encl Rolated correspondence BAKER, 8 Affiliation Unknown 80/06/30 2pp
- --8007070298 Accepts suggested financial qualification contentions Saler i.Cumins i.Doggett 4.Perrenod 1 & TX PRIO Addl 31 Agraes to be lead party provided that applicant answers Doggett First set of interoggatories W/Certificate of Syc BAKER.B Affiliation Unknown 80/06/30 2pp

800708005B Motion for issuance of subpoens directed to D Marrack for 800708 deposition, per ASLR 800623 memorandum & order Certificate of Svc & draft subpoens w/deposition schedule encl Related correspondence CULP, R H, COPELAND, J G Houston Lighting & Power Co CULP, R H Lowenstein, Newman, Reis, Axelrad & Toll 80/07/01 9pp

B007090189 Answers to SA Doggett & WM Perrenod interrogatories Identifies H Dean as witness anticipated to testify re financial qualifications Includes info ra cost of delays & GA funding W/affidavit & Certificate of Svc GDPELAND, J O , NEWHAN, J R Houston Lighting & Power Co GDPELAND, J O Baker & Botts 80/07/01 21pp

8007080030 Confirms 800702-03 teleons & advises of 800710 meeting at Travelodge Astrodoms to discuss contentions motions for summary disposition & proposals for hearing schedule Input & suggestions are beneficial BLACK,R L Hearing Branch 1 80/07/03 2pp

8007080044 Confirms telcon agreement NRC responses to 13th set of interrogatories will be filed by 800721 & to 14th set of interrogatories by 800728
SDHINKL'S M Hearing Branch 3 80/07/03 ip

B007310116 Interrogatories & requests for production of documents directed to util Requests identification of witnesses & expert testimony-related documents w/factual basis for expert opinion
BISHOP J M , BISHOP, M Affiliation Unknown 80/07/05 ip

800731010B Interrogatories & request for documents directed to util Requests most recent population projection data & methodology used for updating projection Related correspondence BISHOP,J M , BIEHOP,M Affiliation Unknown 80/07/06 8pp

8007160360 Response to applicant first set of interrogatories & request for production of documents re impact of transmission lines & FES MARRACK D Marrack.D 80/07/08 ip

--8007160565 Response to applicant second set of interrogatories & request for production of documents re intervenor pleadings before ASLD & ASLAB Certificate of Svc encl MARRACK, D MArrack, D 80/07/08 3pp

8007160570 Response to D Marrack first set of interrogatories, Includes statements re transmission lines & alternative transmission sites & routes Prospective witness FJ Schlight prof qualifications, affidavit & Certificate of Svc encl HANCOCK, D , NEHMAN, J R Houston Lighting & Power Co HANCOCK, D Baker & Botts 80/07/08 lipp

B007170159 Fourth set of interrogatories directed to util re financial qualifications includes questions on disciplinary actions & role of Houston Industries Related correspondence BAKER:B L. Affiliation Unknown 80/07/08 9pp.

--8007170171 First set of interrogatories directed to NRC re financial qualifications, hearing expectation & witnesses intended to be called BAKER 8 L Affiliation Unknown 80/07/08 4pp

1

- 6007i60645 Response to intervenor D Marrack 800508 interrogatories Identifies expert witnesses expected to be called in support of consolidated Rentfro Contention 2 Affidavit & Certificate of Six encl HANCOCK,D , NEWMAN, J R Houston Lighting & Power Co HANCOCK,D Baker & Botto 80/07/09 13pp
- BOO7170374 Interrogatories & request for production of documents directed to NRC Requests factual basis of anticipated testimony re natural gas use as fuel & subsequent costs of electricity W/Certification of Svc Related correspondence BCOTT.J M Texas Public Interest Research Group BO/07/09 B0/07/09 4pp
- B007140015 Advises of Chairman of ASLB suggestion that parties meet on B00710 to present schedule agreement to Board B0HINKI.5 M Hearing Branch 3 B0/07/10 2pp
- BOO7160639 Response in opposition to intervenor JF Doherty BO0627 motion for financial assistance ASLB authority does not eitend to appropriation of funds Certificate of Svc encl COPELAND.J O . NEMMAN.J R Houston Lighting & Power Co COPELAND.J O Baker & Botts BO/07/11 5pp
- 8007220552 Response in opposition to applicant 800626 request for denial of intervenor 800611 motion to compel Applicant & NRC did not raise timely objections to intervenor due right to discovery W/supporting documents & Certificate of Svc MARRACK, D Marrack, D RENTERO, W Affiliation Unknown 80/07/12
- 8007180432 Response to JF Doherty 19th request for documents Literature on applicant turbine, NEDO 21,617 re analog transmitter trip unit sys, Figures 15 1-38 2 % 7 7-2 of FSAR & other documents are available for insp & copying Certificate of Byc encl BIDDLE, C T, NEWMAN, J R Houston Lighting & Power Co BIDDLE, C T Baker & Botts 80/07/15 4pp
- B007180260 Forwards FH Potthoff B00709 hand-serviced first set of interrogatories directed to Houston Lighting & Power BLACK:R L Hearing Branch 1 80/07/16 ip
- ---B007180276 First set of interrogatories directed to Houston Lighting & Power Requests factual info re U fuel sources, costs, method of mining & stripping, site & extent of mining & feasibility of manne biofarm for synthetic natural gas supply POTTHOFF,F H Affiliation Unknown B0/07/09 2pp
- B007220004 Order advising that AGLB will dismiss R Framson Contention i & will permit litigation of JF Doherty Contention II Directs FH Potthoff to respond to applicant first interrogatories by B00729 Marrack motion to quash subpoema denied as mot WOLFE.S J Atomic Safety and Licensing Doard Panel 80/07/16 2pp
- 8007230240 Partial response to FOIA request for 20 documents for use as intervenor in facility proceeding Forwards documents listed in App A No documents have been located suby to Items 1 & 2 Bearch is continuing W/o encls
 FELTON,J M Division of Rules and Records 80/07/14 3pp
- 8007230603 Objections to applicant & NRC schedule proposal given at 800710 meeting Dates of responses re summary disposition & prehearing conference re financial qualifications, unreasonably early Questions rewriting of contentions BAKER. B Affiliation Unknown 80/07/16 2pp
- 8007180426 Forwards notice of RL Black appearance & CP Woodhead withdrawal in proceeding BLACK.R L Hearing Branch 1 80/07/17 4pp
- \$007220021 Response in opposition to JF Doherty 800427 motion for financial assistance from funds appropriated by Congress Forthcoming change in rules will provide relief per Commission 791210 approval Certificate of Svc encl SOHINKI.S M Hearing Branch 3 80/07/17 4pp
- 8007220159 Forwards NRC proposed schodule & NRC proposed revised schedule suggesting 800808 prehearing conference Tentative contentions encl for prehearing framework re summary disposition & simplification of text 80HINKI
- 8007240010 Partial response to JF Doherty 13th set of interrogatories Includes statements & discussions re transport theory, rod drop accident & spent fuel pool loss of water Explains fuel rod bilboning & swelling Waffidavit & Certificate of Svc MOON, C W Assistant Director for Licensing 80/07/21 38pp

- 8007250424 Response to Potthoff 900716 motion for extension of discovery Applicant will respond to untimely interrogatories & other discovery requests by 800731 Certificate of Svc enc1 COPELAND, J G , NEWMAN, J R Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/07/21 4pp
- 8007300116 Motion for preparation of suppl to FFS adequately assessing Class 9 accident impact Alleges that FES will violate NEPA if Class 9 is not addressed Urges review of environ contentions W/Certificate of Svc 9COTT.J M Texas Public Interest Research Oroup 80/07/21 8pp
- B007250703 Order scheduling B00B13-14 prohearing conference in Houston,
 Tx Schedule for responses to motions for summany disposition
 & for testimony & commentement of evidentially hearing will
 be set during conference Contentions will be simplified
 WOLFE,S J Atomic Safety and Licensing Board Panel 80/07/22 2pp
- B007270082 Response to Potthoff first set of interrogatories Objects to majority of interrogatories on basis of irrelevancy Applicant has not commissioned study on marine bio farm feasibility to provide synthetic gas W/Certificate of Svc COPELAND. J G . NEWMAN. J R Houston Lighting & Power Co B0/07/23
- 8007290746 Order admitting defeired contentions re adequacy of emergency evacuation plans Directs consolidation of contentions & initiation of discovery by 800905 Schoussler admitted as intervening party Defines actions re final rule LINENBERGER. G. A. WOLF, S. J. Atomic Safety and Licensing Board Panel 80/07/24 2pp
- 8007300413 Response to Daker request for documents Most recent rate filing before TX Public Util Commission available for insp & copying Certificate of Svc encl Related correspondence COPELAND, J G . NEWMAN, J R . Houston Lighting & Power Co COPELAND, J G . Baker & Botts 80/07/24 Spp
- B007300449 Response to Doherty requests for admissions Admits presence of small blowdown load due to BWR pipe rupture Admits lack of automatic mouns to place RHR sys in cooling mode W/ Certificate of Svc & affidavit Relatid correspondence COPELAND, J G Metropolitan Edison Cu NEWMAN, J R Houston Lighting & Power Co COPELAND, J G Baker & Botts 80/07/24 14pp
- BOOTSOO4OR Response to BOOTO9 interrogatories & request for production of documents includes info re natural gas alternative, conservation & interconnect.orror in computer program & technical qualifications Certificate of Soc encl
 COPELAND, J. G. Houston Lighting & Power Co CUPELAND, J. G. Baker & Bootst Colorate and Society Colorates and Colorates a B0/07/25 Зірр
- B007300435 Response to B00706 interrogatories & requests for production of documents includes info re movement of Brazes River toward proposed pipeline route & max peak overpressure for each critical structure Certificate of Svc encl CDPELAND, J @ Houston Lighting & Power Co COPELAND, J @ Baker & Botts 60/07/25 17pp
- B007310094 Response to JM & M Bishop B00705 interrogatories & requests for production of documents Identifies witnesses & summarizes substance of testimony Certificate of Svc & profqualifications encl Related correspondence COPELAND, J G , NEWMAN, J R Houston Lighting & Power Co COPELAND, J G , Baker & Botts B0/07/25 17pp
- B00731030B Response to JF Doherty 1Ath set of interrogatories Submits info re qualification of welder & procedures for cadwelding Describes scram reactivity function & coefficient Affidavit & Certificate of Svc encl Related correspondence COPELAND, J G , NEWMAN, J R Houston Lighting & Power Co COPELAND, J G , NEWMAN, J R Bouston Lighting & Power Co
- B007300397 Partial response to fourteenth set of interrogatories
 Includes info re application of North Anna criteria, pressure
 vessel integrity & fracture toughness surveillance program
 CW Moon affidavit & Certificate of Svc encl
 SDHIMKI, S M Hearing Iranch 3 MOGN, C W Assistant Director for
 Licensing 80/07/28 13pp
- 8007300404 Partial response to fifteenth set of interrogatories
 Includes info re control rod drift out resonance parameters
 & gadolinia distribution in furl pellets (W Hoon affidavit
 & Certificate of Svc encl
 SOHINKI,8 M Hearing Branch 7 MOON, (W Assistant Director for
 Licensing 80/07/28 15pp

300423 Response to intervenors' first set of interrogatories re mancial qualifications SER Suppl 2 contains out-of-date fo NRC will present analysis when util updates filings of qualifications, affidavit & Certificate of Svc encl JN.C W Assistant Director for Licensing SCHINKI,S M Hearing anch 3 80/07/28 13pp

300424 Response to JF Doherty 800708 second request for admissions mits that NRC misstated info provided in Amend 2 to ilication Discusses failure to scram on routine shutdown Jul 1980 Affidavit & Certificate of Svc encl
ANC W Assistant Director for Licensing SORINKI,S N Hearing anch 3 80/07/28 5pp

310312 Partial responses to TX PIRG interrogatories & production of cuments includes statements re FES.PSAR & QA program scusses reduction of occupational radiation exposures sinst Reg Guide 8 OS W/affidavit & Gertificate of Svc ⇒N.C W Assistant Director for Licensing BO/07/29 ⊋7pp

310473 Forwards NUREO-0594, "Occupational Radiation Exposure at mmercial Nuclear Power Reactors 1978," re NRC 800729 sponse to TX PIRO interrogatories & production of cuments W/o encl ACK.R L Hearing Branch 1 80/07/30 ip

meral correspondence

300348 Requests change of addressee on NRC correspondence from Turner to GH Oprea, Jr Address is unchanged IEA,0 H Houston Lighting & Power Co 80/07/23 1p

T 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2 ljudicatory correspondence

110243 Forwards Commission 800527 memorandum & order containing Essions on UCS 780502 petition for retonsideration of 1419 memorandum & order UCB 771104 petition sought action fire protection for electrical cables 38NHUT,D G Division of Licensing 80/06/25 89pp

230246 FDIA request for 20 dacuments for use as intervenor in ility proceeding HERTY.JF Doherty.JF 80/06/27 4pp

30240 Partial response to FOIA request for 20 documents for use as ervenor in facility proceeding Forwards documents listed App A No documents have been located subj to Items 1 & 2 rich is continuing Mro entle.
TON.J M Division of Rules and Records 80/07/16 3pp

neral correspondence

18034B Requests change of addressee on NRC correspondence from Turner to 8M Oprea, Jr Address is unchanged EA.8 W Houston Lighting & Power Co 80/07/23 1p

T 50-47) PILGRIM NUCLEAR POWER STATION. UNIT 2 plication/construction stage documents & correspondence

3000i Forwards statement of policy re requirements to be met for rent OL applications, as derived from NUREO-0660 % found NUREO-0694 EMHUT.D G Division of Licensing 80/06/26 2pp

judicatory correspondence

10243 Forwards Commission B00327 memorandum & order containing isions on UCS 780502 petition for reconsideration of 41 memorandum & order UCS 771104 petition sought action fire protection for electrical cables ENHUT.D G Division of Licensing 80/06/25 87pp

inn reports, IE Bulletins & correspondence

Reporting of Info in required e Director

DOCKET SYN-50-482 WOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- 8007250046 Summary of 800401 meeting w/util in Bethesda.MD re review plans for utils OL applications
 LICITRA-E A Licensing Branch 3 80/04/85 5pp
- G007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 ETSENHUT, D. G. Division of Licensing G0/06/26 2pp
- B007170313 Discusses Dames & Moore & KS Ocological Survey evaluations of possible pop-up in floor of ultimate heat sink Pop-ups mapped in floor are montectonic & pose no hazard to integrity of safety-related structures LEFEVRE: H Geosciences Branch 80/07/02 3pp
- --B007170317 Forwards photographs of two minor pop-up features in upper part of Plattsmouth Limestone in ultimate heat sink excavation at facility Concurs w/D Fenster & site geologists that pop-ups were caused by differential thermal expansion, WILSON,F W Kansas, Univ of 80/06/02 7pp
- B007300337 Forwards Union Electric & KS Gas & Electric responses to NRC questions re facility design & const GA programs Revised GA program incorporating util commitments & agreements, will be available within 90 days

 BEIKEN, S J Nuclear Power Plant Standards Committee 80/07/28
- 80073005ii Forwards info & drawings re Category i masonry walls,in response to 80072i itr Calculations and PETRICK,N A Standardized Nuclear Unit Power Plant Bystem 80/07/27 79pp
- --8007300514 "Architectural Auxiliary & Reactor Bldg Floor Plan. Elevation 1,974 Ft " * Bechtel Corp 10466 79/04/04 1p
- --B007300317 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 2.000 Ft " * Bechtel Corp 10466 79/04/04 19
- --B007300520 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 2.026 Ft " * Bechtel Corp 10466 79/11/05 1p
- --B007300521 "Architectural CMU Wall Penetrations, Auxilary Bldg " * Bechtel Corp 10466 79/04/14 1p
- --8007300522 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 2.047 Ft.6 Inches " * Bechtel Corp 10466 79/04/04 ip
- ~-8007300524 "Architectural CMU Wall Penetrations, Control Bldg *
 * Bechtel Corp 10466 79/08/19 1p
- --B007300524 "Architectural Auxiliary & Reactor Bldg Floor Plans, Elevations 1,988 ft, 1,989 ft & 2,013 ft, 6 Inches " * Bechtel Corp 10466 79/04/04 1p
- ---8007300528 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor" 4 Bechtel Corp 10466 80/01/23 lp.
- --B007300529 "Architectural Auxiliary Blóg, Btairs A-1 & A-1A, Plans & Boctions " * Bechtel Corp 10466 78/10/04 1p
- --B007300533 "Architectural.CMU Hall Penetrations.Control Bldg & Communication Corridor" * Bechtel Corp 10466 79/03/29 1p.
- ---8007300534 "Architectural, Auxiliary Bldg, Stair A-2, Plans & Sections "
 * Bechtel Corp 10466 78/10/04 ip
- --8007300535 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor"

 * Bechtel Corp 10466 80/03/13, 1p
- ---8007300536 "Architectural. Auxiliary Bldg, Elevator2, Plans & Sections." * Dechtel Corp 10466 78/10/04 ip

- ---B007300538 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor "

 Bechtel Corp 10466 79/03/29 ip
- ---B007300539 "Architectural\CMU Wall Penetrations, Control Bldg & Communication Corridor" # Bechtel Corp 10466 80/03/05 ip
- -8007300540 "Architectural Control & Diesel Generator Bldgs & Communication Corridor, Floor Plans, Elevations 1,974 & 1,984
 - Bachtel Corp 10466 78/09/11 1p
- -8007300342 "Architectural Control & Diesel Generator Bidgs & Communication Corridor,Floor Plans,Elevations 2,000 & 2,016
 - Bechtel Corp 10466 79/04/04 ip
- --B007300546 "Architectural Control & Diesel Generator Bldgs & Communication Corridor, Floor Plans, Elevations 2, 032 & 2, 047
 - Bechtel Corp 10466 79/04/04 1p
- ---B007300547 "Architectural General Masonry Details " * Bechtol Corp 10466 80/01/28 ip

- --- 8007300554 "Architectural Access Control Floor Plan. Elevation 1, 984
 - # Bechtel Corp 10466 78/08/29 1p
- --- B007300554 "Architectural Access Control & Control Room Areas, Interior Elevations *
 * Bechtel Corp 10466, 79/04/19 1p

- -8007300564 "Architectural Computer Room & Control Room Detailed Floor Plans,Elevation 2,047 Ft.6 Inches " & Bechtel Corp 10466 80/01/28 ip
- ---8007300566 "Architectural Control Bldg, Stair C-1, Plans & Section " * Bechtel Corp 10466 78/08/24 ip
- --- 8007300568 "Architectural Communication Corridor, Stair CC-1, Plans & * Bechtel Corp. 10466 80/01/07 1p
- --8007300570 "Architectural Elevator 1 Communication Corridor Plans. Sections & Details " * Bechtel Corp 10466 80/02/26
- F Security, medical, emergency & fire protection plans
- 8007110137 Informs that responses have not been received to Encl 1 of 800320 request for add1 info on QA program for fire protection VOLWOBLOOD, B J Licensing Branch 1 80/06/30 2pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D & Division of Licensing 80/06/25 89pp

- 8007220140 Forwards final response to 791102 ltr re concerns on ACCEPTING PURPOSES FINAL RESPONSE to 791102 Its reconcerns of facility Areas of response include extended time for Commission decision. location & condition of PDR in Burlington. 49 & corruption allegations
 STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/03 3pp
- --8007220145 Advises that Commissioners Kennedy & Hendrie & Chairman Ahearne agree that Director's decision re const activities need not by reviewed Commissioner Bradford proferred Commission to make review Problems w/contractor sited CHILK.8 J Office of the Secretary of the Commission B0/03/31
- --8007220154 Requests reason forr time extension for investigation into revoking CP for progosed facility Suggests transfer of LPDR to more accessible library NRC should not depend on util to rept internal personnel corruption
 WHITE,T Affiliation Unknown 79/11/02 2pp
- H General correspondence
- 8007250633 Responds to 790904 ltr to DOE re const problems at facility NRC 790718 ltr to Christy attempted to dispel concern re adequacy of concrete in base mat Ltr from KB State Bldg Trades Council encl in support of NRC position STELLO.V Office of Inspection & Enforcement, Office of the Director 80/07/07 App
- --B007250649 Responds to KS State Bldg & Const Trades Council 79080B ltr
 No NRC base mat acceptance decisions were based on concrete
 samples made from base mat test mis Structure will meet
 intended safety function Related documentation encl
 STELLO,V Office of Inspection & Enforcement, Office of the
 Director 79/10/02 14pp

M Antitrost correspondence

- 8007250698 Requests util suppl antitrust info submitted w/800506 ltr Requests response within 30 days NASH,D Utility Finance Branch 80/07/08 3pp
- 8007230547 Forwards FR notice of receipt of info for antitrust review of QL application Notice will be published simultaneously in listed newspapers & trade journals YOUNGBLOUD.B J Licensing Branch i 80/07/10 2pp
- --8007230552 Notice of receipt of info for antitrust review of DL application
 YOUNGBLOOD, B. J. Licensing Branch 1 80/07/10 2pp
- 8007280013 Forwards FR notice re receipt of info for antitrust review of OL application, YOUNGBLOOD, B J. Licensing Branch 1 80/07/10 1p
- 8007280015 Forwards FR notice of receipt of info for antitrust review of OL application YOUNGBLOOD,B J Licensing Branch 1 80/07/10 ip
- Q. Inspection reports, 1E Bulletins & correspondence
- B00725032) Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve "No specific action or response necessary BEYFRIT, K V Region 4, Dallas, Office of the Director B0/03/31
- 8007240513 Forwards IE info Notice 80-21. "Anthorage & Support of Safety-Related Electrical Equipment " No written response required BEYRIT.K V Region 4. Dallas. Office of the Director B0/05/16
- 8007070083 Forwards 1E Insp Rept 50-482/80-08 on 800407-11 & 28-29 & notice of deviation

 BEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering

 Support Branch 80/05/23 App
- ---8007070087 Notice of deviation from insp on 800407-11 & 28-27 * Region 4. Dallas, Office of the Director 80/05/22 ip
- --8007070091 IE Insp Rept 50-482/80-08 on 800407-11 & 28-29
 Noncompliance noted failure to designate cable tray for use
 in Class IE & 11/1 as safety-related
 CROSSMAN, W. A., OBERG, C. R., MARTIN, L. E. Region 4, Dallas, Office of
 the Director 80/05/22 11pp

- 8007110187 Forwards IE Insp Rept 50-482/80-09 on 800429-0502 & notice
 - SEIDLE, W.C. Ri Support Branch
- ---8007110192 Notice of violation from insp on 800429-0502 * Region 4. Dallas, Office of the Director 80/05/2 80/05/22 3nn
- ~~8007110198 IE Insp Rept 50-482/80-09 on 800429-0502 Noncompliance
 - DOJIIO198 IE Insp Rept 50-482/80-09 on 800429-0502 Noncompliance noted improper storage of safety-related items, failure to identify nonconforming conditions % failure to provide adequate test procedures CROSSMANW A. DEERG.C R. TAPIA.J I Region 4. Dallas, Office of the Director 80/05/22 9pp
- 8007020259 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/28
- 8007210348 Forwards 1E Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required SEYFRIT.X V Region 4, Dallas, Office of the Director 80/05/28
- B007010025 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required SEYFRITK V Region 4. Dallas, Office of the Director 80/05/29
- 8007010162 Responds to 1E Bulletin 79-28. "Possible Malfunction of NAMCO Mode) EA180 Limit Switches at Elevated Temps " Top cover gaskets on switches w/applicable date codes will be replaced on valves listed in encl PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/02 2pp
- B007100441 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "SNUPPB recycle holdup tanks do not depend on pressure regulators to compensate for lovel variations
 PETRICKIN A Standardized Nuclear Unit Power Plant System 2pp 80/06/06
- B007220109 Forwards 16 Info Notice 80-26. "Evaluation of Contractor OA Programs " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director B0/06/10
- 8007160324 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required BEYFRIT, K V Region 4. Dallas, Office of the Director 60/06/11
- 8007290066 Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in Accordance W/100FR50 95(e) " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/13
- B007020378 Responds to IE Bulletin 80-07, "Hydramotor Actuator Deficiencies" Two safety-related uses of ITT General Controls Models AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICK.N A Standardized Nuclear Unit Power Plant Gystem 80/06/16 1p
- 8007280724 Forwards It Insp Rept 50-482/80-11 on 800527-30 & notice of Notaborner, ... violation SEIDLE:W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 90/06/17 2pp
- --8007280728 Notice of violation from insp on 800527-30 * Region 4. Dallas, Office of the Director 80/06

50-482/80-11 on 800527-30 Noncompliance noted ation welds in accordance w/NE-4000

ruction &

Pumb

720

- 8007170673 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required SEYFRITIK V Region 4. Dallas. Office of the Director 80/06/24
- 8007230373 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/27
- 8007290013 Act receipt of 800624 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50~482/80-09 SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/07/09 ip
- --B007290017 Responds to NRC B00523 ltr re violations noted in IE Insp Rept 90-402/80-09 Corrective actions Daniel mechanical supervision instructed by const manager re WP-I-01 procedures KDESTER.G L. Kansas Gas & Electric Co. 80/06/24 400
- B Reportable occurrences. LERs & related correspondence
- 8005090053 Interim deficiency rept re Ruskin vertical fire dampers. Due to problems identified after B00215 rept.add1 design mode are required for dampers & will be described by 800515 PETRICK.N Λ Standardized Nuclear Unit Power Plant System. E0/04/03 . 2рр
- 8007020048 PNO-IV-80-022 on 800610, five craftsmen were terminated as result of investigation by site mgt & Level 1 QC civil inspector terminated for entry of false test info OBERG.C R. CROSSMAN.W A Region 4, Dallas, Office of the Director 80/06/11 Rpp
- 800721004B Ack receipt of B00612 final deficiency rept re Bunker Ramo Corp electrical penetration assemblies. Rept will be reviewed & evaluated CARLSON R T Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/25 ip
- 8007210231 Ack receipt of 800606 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated CARLSON.R T Region in Philadelphia. Reactor Operations Nuclear Support Branch 80/06/26 ip
- 8007070325 Biscusses 800620 rept of potential deficiency re excessive pressure in feedwater lines following postulated high energy line break Excessive pressure does not constitute deficiency per 10CFR50 55e PETRICK,N A Standardized Nuclear Unit Power Plant System 60/04/30
- 8007270245 Ack receipt of 800612 ltr re pipe support sway strut defiriency Rept expected by 800731 CARLSON,R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07703 ip
- --8007290254 Confirms 800611 telcon requesting extension until 800731 to submit rept of significant deficiency re-pipe support sway struts Add1 time required for further engineering examination & study SEIKEN, S J Standardized Nuclear Unit Power Flant System 80/06/12 8EIKEN, 8 J
- 8007310297 Ack receipt of 800630 final deficiency rept re postulated feedwater line piping break CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/11 ip
- -8007310302 Deficiency rapt re postulated feedwater line piping break
 Excessive peak pressure calculations performed by Bechtel
 considered part of normal design evolution Does not consider
 matter reportable per 10CFR\$0 55(e)
 PETRICK.N A Standardized Nuclear Unit Power Plant System
 80/06/30 1p
- 8007290590 Final deficiency rapt re generic deficiencies in Corner & Lada. Inc pipe support sway struts Onsite insp &/or tests will assure that assemblies are acceptable for use Corner # Lada generic rept encl PETRICK.N A Standardized Nuclear Unit Power Plant System 80/07/24 9pp

U Congressional/Executive Correspondence

- B007ii0346 Responds to B005i6 ltr re delays in DL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J F Commission 80/06/23 ip
- ---B007i10552 Responds to 800516 itr re delays in DL application reviews
 Full review schedules are being developed for licensing of
 docketed applications Delays resulted from TMI-2 accident
 AMEARNE, J F Commission 80/06/23 1p
- --8007110566 Responds to 800516 ltr re delays in OL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AMEARNE.JF Commission 80/06/23 Ip
- --8007ii0568 Responds to 800516 ltr re delays in OL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AMEARNE.J.F Commission 80/06/23 ip
- ---8007110571 Discusses concerns about delays in NRC review of DL applications NRC failure to carry-out review in timely manner increases cost of electricity supplied to constituents

 EAQLETON, T. F. DANFORTH, J. C., KASSEBAUM, N. L. Senate 80/05/16

DOCKET STN-50-483 CALLOWAY PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 8007250046 Summary of B00401 meeting w/util in Bethesda, MD re review plans for utils DL applications
 LICITRA, E A. Licensing Branch 3 80/04/25 5pp
- 8007100379 Forwards Bachtel rept BLUE-700 & Daniel Intl Corp 800529 telcon record sheet & GC Procedure GCP-507.Revision 5.per MRC 800529 request for addl info on embed rept Number of embeds involved to be determined by Jul 1980 BCHNELL.D P Union Electric Co 80/06/19 40pp
- B007140574 Confirms B00626 meeting w/util in Glen Ellyn, IL to discuss proposed reorganization of Daniels Intl GA/GC function KEPPLER, J. 9 Region 3. Chicago, Office of the Director 80/06/24
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREQ-0660 & found in NUREQ-0649
 EIBERMUT, D G Division of Licensing 80/06/26 2pp
- 8007290034 Declines 800618 invitation to attend State of MD Dept of Natural Resources 800716 public hearing re NPDES application due to prior commitments Requests copy of hearing testimony DENTON,H. R Office of Nuclear Reactor Regulation, Director 80/07/21 2pp
- ---B00729003B Invites NRC participation in 800716 public hearing re NPDES application Legal notice of meeting encl LAFBER.F A Missouri, State of 80/06/18 2pp
- 8007300337 Forwards Union Electric & KS Gas & Electric responses to NRC questions re facility design & const GA programs Revised GA programs incorporating util commitments & agreements, will be available within 90 days

 BEIKEN, 8 J Nuclear Power Plant Standards Committee 80/07/28
- B007300511 Forwards info & drawings re Category 1 masonry walls, in response to B00721 ltr Calculations encl PETRICK.N A Standardized Nuclear Unit Power Plant System 80/77/29. 79pp
- ---8007300514 "Architectural Auxiliary & Reactor Bldg Floor Plan. Elevation 1,974 Ft " * Bechtel Corp 10466 79/04/04 ip
- ---B007300517 "Architectural Auxiliary & Reactor Bldg Floor Plan, Flevation 2,000 Ft " # Bechtel Corp 10466 79/04/04 ip
- ---8007300520 "Architectural Auxiliary & Reactor Bldg Floor Plan. Elevation 2,026 Ft " * Bechtel Corp. 10466 79/11/05 1p

- ~~8007300521 "Architectural CMU Wall Penetrations.Auxilary Bldg " * Bechtel Corp 10466 79/04/13 1p
- ~-8007300522 "Architectural Autiliary & Reactor Bldg Floor Plan, Elevation 2,047 Ft.6 Inches " * Bechtel Corp 10466 79/04/04 1p
- ~-8007300524 "Architectural CMU Wall Penetrations, Control Bldg " * Bechtel Corp 10466 79/08/19 ip
- ~-8007300526 "Architectural Auxiliary & Reactor Bldg Floor Plans, Elevations 1.988 Ft, 1.989 Ft & 2.013 Ft. 6 Inches " * Bechtel Corp 10466 79/04/04 1p
- --B007300528 "Architectural CMU Wall Penetrations.Control Bldg & Communication Corridor"

 * Bethtel Corp 10466 80/01/23 1p
- --B007300529 "Architectural Auxiliary Bldg, Stairs A-1 & A-1A, Plans & Bechtel Corp 10466 78/10/04 lp
- ~-B007300533 "Architectural CMU Wall Penetrations,(ontrol Bldg & Communication Corridor "

 * Bechtel Corp 10466 79/03/29 Ip
- ~-8007300534 "Architectural Auxiliary Bldg. Stair A-2, Plans & Sections "
 * Bechtel Corp 10466 78/10/04 tp
- --B007300535 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor "

 * Bechtel Corp 10466 80/03/13 1p
- --8007300536 "Architectural Auxiliary Bidg, Elevator2, Plans & Sections "
 # Bechtul Corp 10466 78/10/04 ip
- --800730053B "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor"

 * Bechtel Corp 10466 79/03/29 1p
- --8007300539 "Architectural CHU Wall Penetrations, Control Bldg & Communication Corridor"

 * Bachtel Corp 10466 80/03/05 1p
- Communication Corridor, Floor Plans, Elevations 1,974 & 1,984 Ft " --8007300540 "Architectural Control & Diesel Generator Bldcs &
 - # Bechtel Corp 10466 78/09/11 1p
- ---B007300542 "Architectural Control & Diesel Generator Bldgs & Communication Corridor, Floor Plans, Elevations 2,000 & 2,016 Ft "
 - * Bechtel Corp 10466 79/04/04 ip
- --B007300543 "Architectural CMU Wall Penetrations, Control Bldg, Communication Corridor & Radwaste Bldg * Bechtel Corp 10466 BO/03/12 1
- -8007300546 "Architectural Control & Diesel Generator Didgs & Communication Cerridor, Floor Plans, Elevations 2, 032 & 2, 047
 - Bechtel Corp 10466 79/04/04 1p
- --8007300549 "Architectural Control Bldg & Communication Corridor Floor Plan Elevations 2,073 ft.6 Inches & Roof Plan Elevation 2,087 ft.2 Inches " * Bechtel Corp 10464 79/04/04 1p
- --8007300551 "Architectural General Masonry Details " * Bechtel Corp 10466 79/10/22 1p
- --8007300554 "Architectural Access Control Floor Plan, Elevation 1, 984
 - * Bechtel Corp 10466 78/08/29 1p
- --8007300556 "Architectural Access Control & Control Room Areas, Interior
 - Elevations " * Bechtel Corp 10466 79/04/19 1p
- --B007300559 "Architectural Control Bldg & Communication Corridor, Miscollaneous Details & Stairs C-2, CC-2 & CC-3 " * Bechtel Corp 10466 79/03/07 ip

- --8007300562 "Architectural Hot Lab Equipment & Furniture Layout, Elevations & Details, Elevation 1.984 Ft " * Bechtel Corp 10466 78/09/15 1p
- --8007300564 "Architectural Computer Room & Control Room Detailed Floor Plans.Elevation 2.047 Ft.6 Inches " * Bachtel Corp 10466 80/01/28 1p
- --8007300366 "Architectural Control Bldg. Stair C-1, Plans & Section "
 * Bechtel Corp 10466 78/08/24 ip
- --- 8007300568 "Architectural Communication Corridor, Stair CC-1, Plans &
 - Bechtel Corp 10456 80/01/07 1p
- --8007300570 "Architectural Elevator 1 Communication Corridor Plans. Sections & Details " * Hechtel Corp 10466 80/02/26 1p
- F Security, medical, emergency & fire protection plans
- B007ii0154 Informs that responses have not been received to Encl 1 of B00320 request for addl info on QA program for fire protection YQUNQBLQQD.B J Licensing Branch 1 B0/06/30 2pp
- 8007150534 Informs that guard training plan required by 10CFR73, App B. will be submitted by 801101 BRYAN, J K. Union Electric Co. 80/07/08 2pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT, D @ Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007290085 Responds to 800028 ltr from Lawson.MD school students to NUMBRICATION RESPONDS to BOOSES ITM From Lawson-MO school studen President Carter re adequacy of qualifications of personnel designing plant Certain design activities failed to meet MRC requirements Util corrective actions under review DIRCKS, U Defice of the Executive Director for Operations 80/05/30 lp
- 8007250070 Responds to encl 800904 itr to President Carter re nuclear energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/27 22pp
- O Inspection reports, IE Bulletins & correspondence
- 8007140522 Forwards IE Insp Rept 50-483/80-12 on 800407-25 & notice novinouse rerwards is insp Rept 30-483/80-12 on 800907-25 & notice of violation of Properties of Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/05/19 2pp
- --8007140526 Notice of violation from insp on 800407-25 * Region 3. Chicago, Office of the Director 80/0 80/05/16
- --B007140541 IE Insp Rept 30-483/80-12 on 800407-25 Noncompliance noted failure to assure that applicable regulatory requirements are correctly translated into drawings procedures & instructions

 XNOP,R C . HANSEN,W A Region 3. Chicago, Office of the Director 80/05/16 Bpp
- 8007210401 Forwards lE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies" No written response required KEPPLER. J G Region 3. Chicago, Office of the Director 80 80/05/28
- 8007010123 Forwards JE Info Notice 80-23, "Loss of Section to Emergency Feedwater Pumps" No written response required KEPPLER.J G Region 3, Chicago, Office of the Director, 80/05/29
- BOO7010162 Responds to 1E Bulletin 79-28, "Possible Matfunction of NAMCO Model EA180 Limit Suitches at Elevated Temps " Top cover gaskets on swatches w/applicable date codes will be replaced on valves listed in enci PETRICK. N A Standardized Nuclear Unit Power Plant System. BO/06/02 2pp

- 8007190017 Forwards IE Insp Rept 50~483/80~13 on 800806~09, No noncompliance noted FIOIRELLI, C. Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/04 2pp
- --8007150023 IE Insp Rept 50-483/80-13 on 800506-09 No noncompliance noted Major areas inspected followup of 10CFR50 55e repts & procedures & work on seal welds for control rod drive nochanisms ERH,C A , VARDEL,T E , KNOP,R C Region G, Chicago Bffice of the Director BO/06/04 Epp
- BOO7100441 Responds to IE Bulletin BO-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 BNUPPS recycle holdup tanks do not depend on pressure regulators to compensate for level variations
 PETRICK.N A Standardized Nuclear Unit Power Plant System.
 BO/06/06 2pp
- 8007210116 Forwards IE Insp Rept 50-483/80-10 on 800326-27 & 0502, No noncompliance noted

 KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/10,
- --8007210125 IE Insp Rept 50-483/80-10 on 800326-27 & 0502 No noncompliance noted Major areas inspected allegation of detection of weld crack in section of stainless steel pipe leading from accumulator tank BURTON R M . HANSEN W A . NORELIUS, C A Region 3, Chicago, Office of the Director 80/06/07 7pp
- 8007220222 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required HEPPLER.J G Region 3, Chicago. Office of the Director 80/06/10
- 8007160200 Forwards IE Info Notice 80 27, "Degradation of Reactor Coplant Pump Studs " No specific action or response KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/11
- 8007280628 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required KEPPLER,J G Region 3, Chicago, Office of the Director 80/06/13
- 8007020378 Responds to IE Bullatin 80-09. "Hydramotor Actuator Deficiencies " Two safety-related uses of ITT General Controls Models AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICK:N A Standardized Nuclear Unit Power Plant System 80/06/16 lp
- 9007100436 Forwards exhibits which were omitted from IE Insp Rept 50-483/80-10
 KEPPLER, J G Region 3, Chicago, Office of the Director B0/06/17 13ap
- 8007020570 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLERJ G Region 3. Chicago. Office of the Director 80/06/20
- 8007:1709:8 Forwards JE Circular 80-14, "Radioactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required.

 KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24. BO/06/24.
- 8007300131 Forwards IE Insp Rept 50-483/80-16 on 800610-12 No noncompliance noted FIORELLIO Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/24 2pp
- --8007:300:57 IC Insp Rept 50-483/80-16 on 800610-12 No noncompliance noted Major areas inspected Followup of 10CFR50 55(e) repts & unresolved item WESCOTT, H M . OALLAGHER, E J . KNOP, R C Region B, Chicago, Dffice of the Director 80/04/24 3pp
- 8007300160 Forwards IE Insp Rept 50-483/80-15 on 800501-30 & notice of violation FIGRELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/24 2pp
- ---8007300164 Notice of violation from insp on 800501-30, * Region 3. Chicago. Office of the Director 80/0 80/06/23 1p

- ---B007300169 IE Insp Rept 50-483/B0-15 on 800501-30 Noncompliance noted failure to essure that electrical components stored in place were properly protected from damage or deterioration HANSEN, H A. KNOP.R C Region 3. Chicago, Office of the Director B0/06/23 11pp
- BOO7230343 Forwards IE Bulletin 80~16, "Potential Misapplication of Roseaount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Writton response required IE Circular 80~16 also encl No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/27
- 9007150002 Ack receipt of 800606 & 13 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/80-09 on 800423-24 FIORELLI, G Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/30 ip
- --B007150006 Responds to NRC B00314 Itr re violations noted in IE Insp Rept 50-483/B0-09 Corrective actions civil & mechanical GC conducted training review sessions w/insp personnel BRYAN.J.K Union Electric Co B0/06/06 4pp
- ---B007150010 Supplements 800606 response to NRC 800514 ltr re violations noted in IE Insp Rept 50-483/80-09 Corrective actions all safety-related surface-mounted plates installed prior to 800501 will be reinspected.

 BRYAN.J.K. Union Electric Co 80/06/13 3pp
- BOO7210198 Responds to IE Bulletin 90-08, "Exam of Containment Liner Penetration Welds " Forwards Apps D & E of Bechtel Power Gorp Bact 10466-M-203 providing details re weld joints, page ant & size for flued head penetration assemblies.

 BRYAN, J K. Union Electric Co 80/07/01 5pp
- BD07150456 Ack receipt of 800606 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/80-12 FIORELLI, © Region 3, Chicago, Reactor Construction & Engineering Support Branch. B0/07/07 ip
- B. Reportable occurrences. LERs & related correspondence
- BO07140198 Ack receipt of 800616 interim deficiency rept re surface mounted plates Final rept will be reviewed upon receipt FIORELLI, @ Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/24 ip
- 800721004B Ack receipt of B00612 final deficiency rept re Bunker Ramo Corp electrical penetration assemblies Rept will be reviewed & evaluated. CARLEON,R T Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch 80/06/25 ip
- 8007210231 Ack receipt of 800604 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated GAMLSON, R. T. Region 1, Philadelphia, Reactor Dperations Nuclear Support Branch 80/04/26 ip
- 8007070325 Discusses 800620 rept of potential deficiency re excessive pressure in feedwater lines following postulated high energy line break. Excessive pressure does not constitute deficiency per 10CFR50 55e PETRICK, N. A. Standardized Nuclear Unit Power Plant System 80/06/30 ip
- 8007290245 Ack recaipt of 800612 ltr re pipe support sway strut deficiency. Rept expected by 800731. CARLSON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/03 ip
- --8007290254 Confirms 800611 teleon requesting extension until 800731 to submit rept of significant deficiency re pipe support sway struts. Addl time required for further engineering examination k study SEIMEN.B J. Standardized Nuclear Unit Power Plant System 80/06/12, 1p
- 8007310297 Ack receipt of 800630 final deficiency rept re postulated feedwater line piping break CARLSON,R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/11 Ip
- ---BOO7310302 Deficiency rept to postulated Feedwater line piping break Excessive peak pressure calculations performed by Bechtel considered pert of normal design evolution Does not consider matter reportable per iOCFR50 55(e) PETRICK,N A Standardized Nuclear Unit Power Plant System. BO/06/30. 1p.

- 8007250336 Interim deficiency rept re out-of-tolerance conditions on major bolt & minor nut diameters for matls supplied by Industrial Mechanics Inc Insp program established & equipment on order Final rept expected by B01201 BRYAN.J K Union Electric Co. 80/07/18 1p
- B007290590 Final deficiency rept re generic deficiencies in Corner & Lada. Inc pipe support sway struts Onsite insp &/or tests will assure that assembles are acceptable for use Corner & Lada generic rept encl
 PETRICK.N A Standardized Nuclear Unit Power Plant System
 B0/07/24 9pp
- U Congressional/Executive Correspondence
- B007110346 Responds to B00516 itr re delays in OL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from THI-2 accident AHEARNE.J F Commission B0/06/23 ip
- --B007110552 Responds to B00516 itr re delays in OL application reviews Full review schedules are being devoloped for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J F Commission B0/06/23 ip
- --BOO7110566 Responds to 800516 ltr re delays in OL application reviews Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J F Commission 80/06/23 ip
- ---B007i1056B Responds to B005i6 ltr re delays in OL application reviews Full review schedules are buing developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J F Commission 80/06/23 ip
- ---BOO7110571 Discusses concerns about delays in NRC review of OL applications NRC failure to carry-out review in timely manner increases cost of electricity supplied to constituents

 EAGLETON: T F , DANFORTH, J C , KASSEBAUM, N L Senate 80/05/16
- BOO7280509 Responds to 800530 itr re assignment of NRC project manager for facility & delay in NRC review of OL applications for plants under const in MO Project manager has been assigned to facility Licensing delays resulted from THI-2 DIRCKS W J Office of the Executive Director for Operations 80/07/07 Ip
- DOCKET STN-90-484 TYRONE ENERGY PARK, UNIT 1
- A Application/construction stage documents & correspondence
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0694 EISENHUT.D O Division of Licensing 80/06/26 2pp
- Q. Adjudicatory correspondence
- B007010256 Forwards NRC B00616 order requiring licenses to show cause why CP should not be revoked since util intends to cancel project
 DENTON H R Office of Nuclear Reactor Regulation, Director B0/06/16 2pp
- --8007010263 Order to show cause why CP should not be revoked since licensee intends to cancel project DENTON.HR Office of Nuclear Reactor Regulation, Director 80/06/16 Jpp
- B007010272 Grants 790815 request that CP be revoked because of licensee decision to cancel project Forwards NRC B00416 order that licensees how cause why license should not be revoked DENTON, HR Office of Nuclear Reactor Regulation, Director B0706414 Ln
- B007080086 Proposed findings of fact & conclusions of law responding to ABLAB questions on Battelle rept Findings are adopted by TM1-2/Peachbottom Intervenors & Ecology Action Urges suspension of Ots fertificate of Syc encl KEPFDRD.C Environmental Coalition on Nuclear Power 80/06/18
- BD07070310 Forwards response to NRC 800616 ltr & order to show cause why License CPPR-157 should not be revoked No objection raised B0/07/01 ip

- --B007070315 Response stating no objection to 800616 to order to show cause why License CPPR-197 should not be revoked BAXTER, T A Northern States Power Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 80/07/01 1p
- BOO7150475 Ack receipt of NRC 800616 ltr w/encl show cause order issued to applicants Phone number & new address submitted for further correspondence ltmRIG.R Badger Safe Energy Alliance, Inc. 80/07/07 1p
- BOO7180458 Petition for late intervention & motion to defer revocation of CP Cancellation of unit will have substantial & negative impact on present & future electric interstate market due to being integral part of development Certificate of Size encl FRANCIS: F E South Dakota. State of FRANCIS: F E North Dakota. State of FRANCIS: F E North Dakota. State of FRANCIS: F E Spiegel & McDiarmid 80/07/11 9pp
- 8007250408 Response in opposition to Dakota Commissions' 800711 motion to defer action on petition to intervene re 800516 order to show cause Commissions did not actually request hearing & do not have requisite interest Certificate of Svc encl BAXTER.T A Northern States Power Co BAXTER.T A Shaw, Pittman, Potts & Trowbridge 80/07/22 Bpp
- 8007270703 Comments in opposition to Dakota Commissions' 800711 untimely motion to intervene Petitioners failed to assert interest NRC has no jurisdiction CP should be revoked W/ certification of svc GALAZEN. J Northern Thunder 80/07/23 2pp
- I Financial information
- 8007010421 Annual Rept 1979

 * Cooperative Power Association 79/12/31 29pp
- DOCKET STN-50~4B5 STERLING POWER PROJECT NUCLEAR, UNIT 1
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current (L. applications, as derived from NUREC-0660 & found in NUREC-0644
 EIGENHUT, D & Division of Licensing B0/06/26 2pp
- Q Adjudicatory correspondence
- 8007080086 Proposed findings of fact & conclusions of law responding to ASLAB questions on Batbelle rept Findings are adopted by TMI-2/Peachbottom Intervenors & Ecology Action Urges suspension of OLs Certificate of Svc encl
 KEPFORD, C Environmental Coalition on Nuclear Power 80/06/18
 12pp
- 8007080046 Response to ASLAB request re Deficiency 1 Urges reversal of decision rejecting deficiency re correlation between U mine radon releases & amount of U fuel Portion of Perkins decision re correlation must be vacated CAPLAN.R Ecology Action of Oswego 80/06/20 2pp
- BOO70B004B Proposed fandings of fact endorsing Citizens for Safe Environ filing re radiation source terms from U mining & milling Rejects Porkins rationals & urges davelopment of further evidence re failure mechanisms & human factors CAPLAN, R Ecology Action of Oswego 80/06/20 4pp
- Q Inspection reports. IE Bulletins & correspondence
- 8007010269 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Faedwater Pumps " Na written response required ORIER B H Region 1, Philadelphaa, Office of the Director 80/05/29 ip
- 8007010162 Responds to IE Bulletin 79~28: "Possible Malfunction of NAMCO Model EALBO Limit Switches at Elevated Temps " Top cover gaskets on switches w/applicable date codes will be replaced on valves listed in ent!
 PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/02 2pp
- 8007100441 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "SNUPFS recycle holdup tanks do not depend on pressure regulators to compensate for level variations PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/06 2pp

- 8007210615 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 80/06/10 ip
- 8007160367 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs" No specific action or response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/11 ip.
- 8007280619 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(a) " No written response required GRIER.B H Region 1, Philadelphia. Office of the Director 80/06/13 1p
- 8007020378 Responds to IE Bulletin 80-09, "Hydramotor Actuator Deficiencies" Two sofety-related uses of ITT General Controls Models AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/16 1p
- 800702050B Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/20 15
- B007160744 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 80/06/24 ip
- 8007210284 Forwards IE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required ORIER.B H Region 1, Philadelphia. Office of the Director. 80/06/25 p
- 8007230180 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region I. Philadelphia. Office of the Director, 80/06/27 2pp
- S Reportable occurrences. LERs & related correspondence
- B007210231 Ack receipt of B00606 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated CARLSON.R T Region i. Philadelphia. Reactor Operations Nuclear Support Branch 80/06/26 ip
- 8007070325 Discusses 800620 rept of potential deficiency re excessive pressure in feedwater lines following postulated high energy line break Excessive pressure does not constitute deficiency per 100FR80 55e
 PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/30 ip
- 8007310297 Ack receipt of 800630 final deficiency rept re postulated feedwater line piping broak CARLSONR T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 80/07/ii ip
- --8007310302 Deficioncy rept re postulated feedwater line piping break Excessive peak pressure calculations performed by Bechtel considered part of normal design evolution Does not consider matter reportable per 10CFR50 55(e) PETRICK.N A Bendardized Nuclear Unit Power Plant System. 80/06/30 ip
- DOCKET BTN-50-486 CALLOWAY PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007250046 Summary of 800401 meeting w/util in Bethesda.MD re review plans for utils OL applications
 LICITRA.E A Licensing Branch 3 80/04/20 5pp
- 8007100379 Forwards Bechtel rept BLUE-700 & Daniel Intl Corp 800529 telcon record sheet & GC Procedure GCP-507, Revision 5, per NRC 800529 request for addl into on ambed rept Number of embeds involved to be determined by Jul 1980 SCHNELL D F Union Electric Co. 80/06/19 40pp

- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NRREG-0694 in M.REG-0694 EIBENAUT,D 9 Division of Licensing 80/06/26 2pp
- 8007300337 Forwards Union Electric & KS Gas & Electric responses to NRC questions re facility design & const GA programs Revised GA programs incorporating util commitments & agreements.will be evaliable within 90 days
 EEIKEN.8 J Nuclear Power Plant Standards Committee 80/07/28
- B007300511 Forwards info & drawings re Category 1 masonry walls, in response to B00721 ltr Calculations encl PETRICK, N. A Standardized Nuclear Unit Power Plant System 80/07/29 77pp
- -8007300514 "Architectural Auxiliary & Reactor Bldg Floor Plan, Elevation 1,974 Ft " # Bechtel Corp. 10466. 79/04/04 1p
- ---B007300517 "Architectural Auxiliary & Reactor Bldg Floor Plan. Elevation 2,000 Ft " # Bechtel Corp 10466 79/04/04 ip
- -9007300520 "Architectural Auxiliary & Reactor Dldg Floor Plan, Elevation 2,026 Ft " 10466. 79/11/05 1p Bechtel Corp
- -8007300522 "Architectural: Auxiliary & Reactor Bldg Floor Plan. Elevation 2.047 Ft.6 Inches " * Bechtel Corp 10466. 79/04/04 1p
- --8007300524 "Architectural CMU Wall Penetrations, Control Bldg." * Bechtel Corp 10466 79/08/19 ip
- -8007300524 "Architectural Auxiliary & Reactor Bldg Floor Plans, Elevations 1,988 Ft, 1,989 Ft & 2,013 Ft, 4 Inches " # Bechtel Corp. 10466 79/04/04 1p.
- --B007300529 "Architectural Auxiliary Bldg.Stairs A-1 & A-1A.Plans & Bechtel Corp 10466 78/10/04 ip

- ---8007300524 "Architectural Auxiliary Bldg, Stair A-2, Plans & Bections "
 * Bechtel Corp 10466 78/10/04 ip
- ---8007300535 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor,"
 + Bechtel Corp 10466 80/03/13 1p
- ---B00730033B "Architectural CMU Wall Penetrations, Control Bidg & Communication Corridor."

 * Bechtel Corp. 10466 79/03/29 1p
- -8007300539 "Architectural CMU Wall Penetrations, Control Bldg & Communication Corridor." * Bachtel Corp. 10466 80/03/08 ip
- --8007300540 "Architectural Control & Dissel Generator Bldgs & Communication Corridor, Floor Plans, Elevations 1.974 & 1.984 Ft."
 - Bechtel Corp. 10466 78/09/11 1p
- - Bechtel Corp. 10466 79/04/04 ip
- --8007300543 "Architectural CMU Wall Penetrations, Control Bldg. Communication Corridor & Radwaste Bldg " * Bechtel Corp 10466 80/03/12 ip

- --B007300546 "Architectural Control & Diesol Generator Bidgs & Communication Corridor Floor Plans Elevations 2,032 & 2,047 Ft "
 - Bechtel Corp 10466 79/04/04 1p
- --8007300547 "Architectural General Masonry Details " * Bechtel Corp 10466 80/01/28 tp
- --B007300549 "Architectural Control Bldg & Communication Corridor Flo Plan, Elevations 2,073 Ft.6 Inches & Roof Plan, Elevation 2,087 Ft.2 Inches " * Bechtel Corp 10466 79/04/04 ip
- --8007300551 "Architectural General Masonry Details "
 * Bechtel Corp 10466 79/10/22 lp
- --8007300554 "Architectural Access Control Floor Plan Elevation 1,984 Bechtel Corp 10466 78/08/29 1p
- --8007300556 "Architectural Access Control & Control Room Areas, Interi Elevations "
 * Bechtel Corp 10466 79/04/19 1p
- --8007300559 "Architectural Control Bldg & Communication Corridor, Miscellaneous Details & Stairs C-2.00-2 & CC-3 " * Bechtel Corp 10466 79703/97 1p
- --8007300562 "Architectural Hot Lab Equipment & Furniture Layout, Elevations & Betails, Elevation 1, 984 Ft " * Bechtel Corp 10466 78/09/15 ip
- --B007300564 "Architectural Computer Room & Control Room Detailed Flor Plans, Elevation 2.047 Ft. 6 Inches " * Bechtel Corp 10466 80/01/28 ip
- --8007300566 "Architectural Control Bldg, Stair C-1, Plans & Section "
 * Bechtel Corp 10966 78/08/24 ip
- --8007300568 "Architectural Communication Corridor, Stair CC-1, Plans & Section " # Bechtel Corp 10466 B0/01/07 ip
- --B007300570 "Architectural Elevator i Communication Corridor Plans. Sections & Details " * Bechtel Corp 10466 B0/02/26 ip
- F Security, medical, emergency & fire protection plans
- 8007150534 Informs that guard training plan required by 10CFR73, App D, will be submitted by 801101
 BRYAN, J K Union Electric Co 80/07/08 2pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing fecisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D @ Division of Licensing 80/06/25 89pp
- H General correspondence
- B007270085 Responds to 800328 ltr from Lawson, MD school students to President Carter re adequacy of qualifications of personnel designing plant Certain design activities failed to meet NRC requirements Util corrective actions under roview DIRCKS W J Office of the Executive Director for Operations 80/05/30 lp
- B007250070 Responds to encl 800504 itr to President Carter re nuclear energy Use of both coal & nuclear power necessary to free US of overdependence on foreign oil President Carter 791207 press release & energy plan encl DENION.H R Office of Nuclear Reactor Regulation, Director 80/06/27 22pp
- O Inspection reports, IE Bulletins & correspondence
- 8007210401 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J. G. Region 3. Chicago, Office of the Director 80/05/28.

- 8907010123 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER.J G Region 3. Chicago. Office of the Director BO/05/29
- 8007010162 Responds to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model PA180 Limit Switches at Elevated Temps " Top cover gaskets on switches w/applicable date codes will be replaced on valves listed in encl PETRICK.N A Standardized Nuclear Unit Power Plant System 80/06/02 2pp
- 8007100441 Responds to IE Builetin 80-05. "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "SNUPPS recycle holdup tanks do not depend on pressure regulators to compensate for level variations PETRICK.N A Standardized Nuclear Unit Power Plant System 80708/04
- 8007220222 Forwards IE Info Notice 80-26. "Evaluation of Contractor QA Programs" No written response required MEPPLER, J. G. Region 3. Chicago, Office of the Director 80/06/10 in
- 8007160200 Forwards IE Info Notice BO 27. "Degradation of Reactor Coolant Pump Studs " No specific action or response required KEPPLER. J G Region 3. Chicago. Office of the Director 80/06/11
- 800728062B Forwards 16 Info Notice 80-2B, "Frompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/13
- 8007020378 Responds to IE Bulletin BO-09, "Hydramotor Actuator Deficiencies" Two safety-related uses of ITT General Controls Models AH-90 & NH-90 series hydramotor actuators have been identified ITT is testing actuators PETRICK.N A Standardized Nuclear Unit Power Plant Bystem BO/06/16 ip
- 8007020570 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required KEPPLER, J O Region 3. Chicago, Office of the Director 80/06/20
- 800717051B Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J Q Region 3. Chicago, Office of the Director 80/06/24 ip
- 8007230343 Forwards 1E Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required KEPPLER, J O Region 3, Chicago, Office of the Director BO/06/27. Ip
- B007D10198 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds "Forwards Apps D & E of Bechtel Power Corp Spec 10466-H-200 groviding details re weld joints, pipe math & size for flued hoad penetration assemblies BRYAN.J K Union Electric Co 80/07/01 Spp
- 8 Reportable occurrences, LERs & related correspondence
- B00714019B Ack receipt of 800616 interim deficiency rept re surface mounted plates Final rept will be reviewed upon receipt FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/06/24 1p
- 800721004B Ack receipt of B00612 final deficiency rept re Bunker Ramo Corp electrical penetration assemblies Rept will be reviewed & evaluated CARLSON.R T Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 80/06/25 tp
- 8007210231 Ack receipt of B00606 interim deficiency rept re centrifugal charging pump operation following secondary side high energy line rupture Rept will be reviewed & evaluated CARLSON R T Region i. Philadelphia. Reactor Operations Nuclear Support Branch B0/06/26 ig

- B007070325 Discusses 800620 rept of potential deficiency re-excessive pressure in feedwater lines following postulated high energy line break Excessive pressure does not constitute deficienty per 10CFR50-55e PETRICK,N A Standardized Nuclear Unit Power Plant System B6/06/30 ip
- 8007270245 Ack receipt of 800612 ltr re pipe support sway strut deficiency Rept expected by 800731 CARLSON.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 80/07/03 1p
- --B007270254 Confirms B00611 telcon requesting extension until 800731 to submit rept of significant deficiency re pipe support sway struts. Add1 time required for further engineering examination & study SEIKEN, S J Standardized Nuclear Unit Power Plant System 00/04/12 1
- B007310297 Ack receipt of B00630 final deficiency rept re postulated feedwater line piping break CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch B0/07/11 ip
- --B007310302 Deficiency rept re postulated feedwater line piping break Excessive peak pressure calculations performed by Bechtel considered part of normal design evolution Does not consider matter reportable per 10CFR50 55(e) PETRICK, N A Standardized Nuclear Unit Power Plant Bystem, 80/06/30 ip
- 8007250336 Interim deficiency rept re out-of-tolerance conditions on major holt & minor nut diameters for matls supplied by Industrial Mechanics, Inc Insp program astablished & equipment on order Final rept expected by 801201 BRYAN, J K Union Electric Co 80/07/18 Ip
- 8007290390 Final deficiency rept re generic deficiencies in Corner & Lada, Inc pipe support sway struts Onsite insp &/or tests will assure that assumblies are acceptable for use Corner & Lada generic rept encl.
 PETRICK.N A Standardized Nuclear Unit Power Plant Bystem BO/07/24 9pp
- U Congressional/Executive Correspondence
- B007ii0546 Responds to B005i6 ltr re delays in OL application reviews. Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE, J.F. Commission B0/04/93 1p
- --8007i10552 Responds to 8005i6 ltr re delays in DL application reviews. Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident. AHEARNE.J F. Commission 80/06/23 ip
- ---B007110566 Responds to 800516 ltr re delays in DL application reviews. Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE.J F. Commission B0/06/23 ip
- --B00711056B Responds to 800516 ltr re delays in OL application reviews.
 Full review schedules are being developed for licensing of docketed applications Delays resulted from TMI-2 accident AHEARNE.JF Commission 80/06/23 ip
- --B007i1037i Discusses concerns about delays in NRC review of OL applications NRC failure to carry-out review in timely manner increases cost of electricity supplied to constituents

 EAQLETON, T F , DOLE, R Senate B0/05/16 4pp
- BOO7280509 Responds to BO0530 ltr re assignment of NRC project manager for facility & delay in NRC review of OL applications for plants under const in MD Project manager has been assigned to facility Licensing delays resulted from TMI-2.

 DIRCKB, M J Office of the Executive Director for Operations BO/07/07 ip
- DOCKET STN-50-408 PERKINS NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for CUrrent OL applications as derived from NUREG-0640 & found in NUREG-0649
 EISENHUT.D G Division of Licensing 80/06/26 2pp

O Adjudicatory correspondence

- BOOA200066 Forwards Pages 4.5 & 6 which were inadvertently omitted from Exhibit A of High Rock Lake Association BOO521 affidavit
 BPRINGER.D High Rock Lake Association BO/05/23 1p
- ---B006200071 Pages 4.5 & 6 for Exhibit A of High Rock Lake Association B00521 affidavit BPRINGER:D High Rock Lake Association 78/11/16 4pp
- BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables
 EISENAUT.D Q Division of Licensing 80/06/25 B9pp
- BO07020475 Request for 30-day extension to file brief in support of D Bpringer B00415 petition to intervene & request for hearing Certificate of 8vc encl BPRINGER, D Affiliation Unknown 80/06/27 2pp
- B007030243 Suppl withdrawing argument presented in NRC B00626 response in opposition to intervenors' motion to reconsider or reapen record Untimely filing is no longer asserted per ALAB-597 but motion still fails to meet stds Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/01 4pp
- 8007090311 Comments on D Springer 800321 affidavit advancing Lake Norman as best site in proceeding Adheres to prior position for denial stated in NRC 800505 response to D Springer 800415 petition Certificate of Svc enc1 BARTH.C A Hearing Branch 3 80/07/08 4pp
- 800711034B Order granting 20-day extension for Springer to file brief in support of 800415 petition Extension begins upon receipt of NRC 800708 response to Springer affidavit filed in CP proceeding BOMERS, E.B. Atomic Safety and Licensing Board Panel 80/07/09 ip

O Inspection reports: IE Bulletins & correspondence

- 8007240139 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required G'RETLLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- 19007210439 Forwards IE Circular 80-13, "Orid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 80/03/28
- B007010188 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Fedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29 ip
- 8007220054 Forwards IE Info Notice 80-26, "Evaluation of Contractor 84 Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10 2pp
- 8007160230 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pumps Btuds " No specific action or response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/11 ip.
- 8007250368 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR80 55(e)" No written response required U/REILLY, J P Region 2. Atlanta, Office of the Director 80/06/13 2pp
- 8007020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required, O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/20
- B007170096 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/06/24 to

- 8007230228 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/27 in
- B007290532 Forwards response to IE Bulletin 80-08, "Exam of Containment Liner Penetration Helds" Piping penetrations are designed & fabricated in accordance w/1977 edition of ASME Boiler & Pressure Vessel Code, including Bummer 1977 addenda DAIL-L C Duke Power Co 80/07/07 App

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 800723000; Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENMUT, D Q Division of Licensing 80/06/26 2pp

O Adjudicatory correspondence

- B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISEMHUT, D & Division of Licensing 80/06/25 89pp
- B007020475 Request for 30-day extension to file brief in support of D Springer 800415 petition to intervene & request for hearing Certificate of Svc encl BPRINGER, D Affiliation Unknown B0/05/27 2pp
- 8007030243 Suppl withdrawing argument presented in NRC 800626 response in opposition to intervenors' motion to reconsider or reapen record Untimely filling is no longer asserted per ALAB-597 but metion still fails to meet stds Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/01 4pp
- B007090311 Comments on D Springer 800521 affidavit advancing Lake Norman as best site in proceeding Adheres to prior position for denial stated in NRC 800505 response to D Springer B00415 petition Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/08 App
- B00711034B Order granting 20-day extension for Springer to file brief in support of 800415 petition Extension begins upon receipt of NRC 80070B response to Springer affidavit filed in CP proceeding BDMERS, E.S. Atomic Safety and Licensing Board Panel 80/07/09 ip

@ Inspection reports, IE Bulletins & correspondence

- 8007240139 Forwards IE Info Notice BO-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No reaponse required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/05/08 2pp
- 8007210439 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY.) P Region 2. Atlanta, Gffire of the Director 80/05/28 ip
- 8007010188 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29 ip
- B007220054 Forwards IE Info Notice 80-26, "Evaluation of Contractor QA Programs " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/10
- 8007160230 Forwards IE Info Notice 80-27, "Degradation of Reactor Goolant Pump Studs " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11 in
- 800725036B Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/06/13 200

- 8007020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Matural Circulation Cooldown " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20
- 8007170096 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24
- 8007230228 Forwards IE Bulletin 90-16, "Potential Misapplication of Rosenount Inc Models 1151 % 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IF Circular 90-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/3 80/06/27
- BOO/250532 Forwards response to 1E Bulletin BO-08. "Exam of Containment Liner Penetration Welds " Piping penetrations are designed & fabricated in accordance w/1977 edition of ABME Boiler & Pressure Vessel Code, including Emmer 1977 addende DAIL.L.C. Duke Power Co. 80/07/07 opp
- DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0674 EJSENIUT, B & Division of Liconsing 80/06/26 2pp
- G Adjudicatory correspondence
- BOD7020479 Request for 20-day extension to file brief in support of D Springer B00415 petition to intervene & request for hearing Certificate of Svc ancl SPRINGER D Affiliation Unknown 80/06/27 2pp
- B007030243 Suppl withdrawing argument presented in NRC 800626 response in opposition to intervenors' motion to reconsider or reopen record Untimely filing is no longer asserted per ALAB-597 but motion still fails to meet atds Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/01 4pp
- 8007090311 Comments on D Springer 800521 affidavit advancing Lake Norman as best site in proceeding Adheres to prior position for denial stated in NRC 800505 response to D Springer 800415 petition Certificate of Svc encl BARTH.C A Hearing Branch 3 80/07/08 4pp
- 8007110348 Order granting 20-day extension for Springer to file brief in support of 800415 petition Extension begins upon receipt of NRC 800708 response to Springer affidavit filed in CP proceeding BOWERS,E S Atomic Safety and Licensing Board Panel BO/07/09 ip
- @ Inspection reports, IE Bulletins & correspondence
- BOO7240139 Forwards JE Info Notice 80-20, "Loss of Deray Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director BO/05/08
- 8007210439 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/28
- 8007010188 Forwards IE Info Notice 80-23, "Loss of Surtion to Emergency Feedwater Pumps" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29
- B007220054 Forwards IE Info Notice B0-26, "Evaluation of Contractor OA Programs" No whitten response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10
- 8007160230 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required O'RESLLY. J P Region 2: Atlanta, Office of the Director 80/06/11,

- 8007250368 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) "No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 89/04/13
- BOO7020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required required

 O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/20.
- BOO7170096 Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J P. Region 2, Atlanta, Diffice of the Director BO/06/24
- 8007230228 Forwards IE Bulletin 80-i6, "Potential Misapplication of Rosembunt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-i6 also encl No written response required O'/REILLY, J P. Region 2. Atlanta. Office of the Director 80/06/2 80/06/27,
- 8007250532 Forwards response to IE Bulletin 80-08. "Exam of Containment Liner Fenetration Welds" Piping penetrations are designed & fabricated in accordance w/1977 edition of ASME Boiler & Pressure Vessel Code: including Summer 1977 addenda DAIL.L C Duke Pawer Co 80/07/07 App
- DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007030201 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO,R L Assistant Director for Licensing 80/06/12 2pp
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREG-0694 EISENHUT D O Division of Licensing 80/06/26 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing DOT310243 Forwards Commission 800027 memorandum & order conta decisions on UCS 780502 petition for reconsideration of 780943 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT,D 9 Division of Licensing 80/06/25 89pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007240139 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08 Region 2, Atlanta, Office of the Director BO/05/08
- 8007210439 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required, D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/05/28.
- 8007010188 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Faedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director, 80/05/29
- 8007220054 Forwards (E Info Notice 80-26. "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10
- 8007160230 Forwards IE Info Notice 80-27. "Degradation of Reactor Conlant Pump Stude " No specific action or response O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/11
- 800725036B Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required. D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13

- 8007020445 Forwards IE Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required
 - required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/06/20
- B007170096 Forwards IE Circular B0-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel "No written response required C'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/24
- 800723022B Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-14 also encl No written response required O'REILLY,J P Region 2, Atlanta, Office of the Director 80/06/2
- 8007250532 Forwards response to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Piping penetrations are designed & fabricated in accordance w/1977 edition of ABME Boiler & Pressure Vessel Code, including Bummer 1977 addenda DAIL:L C Duke Power Co 80/07/07 6pp

DOCKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007030201 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCG, R. L. Assistant Director for Licensing 80/06/12 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 % found in NUREG-0694
 EIGENHUT, D G* Division of Licensing 80/06/26 2pp
- 0, Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EISENHUT.D.Q Division of Licensing 80/06/25 87pp
- Q Inspection reports, IE Bulletins & correspondence
- BOO7240139 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required CHEILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007210439 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required D'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/05/28
- 8007010188 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/05/29
- 8007220054 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required D'REILLY, J. P. Region 2, Atlanta, Diffice of the Director 80/06/10
- 8007160230 Forwards IE Info Notice BO-27, "Degradation of Reactor Coolant Pumps Studs " No specific action or response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/11
- 8007250368 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required O'REILLY, J P Region 2, Atlants, Office of the Director 80/06/13 200
- 8007020445 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/20

- BOO7170096 Forwards IE Circular BO-14. "Redicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Persunnel" No multten response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/04/24 to
- B00723022B Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes "Written response required IE Circular 80-16 also encl No written response required O'REILLY.JP Region 2, Atlanta, Office of the Director 80/06/27 in
- B007250532 Forwards response to JE Bulletin B0-0B. "Exam of Containment Liner Penetration Welds " Piping senetrations are designed & fabricated in accordance w/1977 edition of ASME Boiler & Pressure Vessel Code, including Bummer 1977 addenda DAIL,L C Duke Power Ca 80/07/07 App
- DOCKET STN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8007030201 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO,R L Assistant Director for Licensing 80/06/12 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISCHNUT.D G Division of Licensing 80/06/26 2pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action regire protection for electrical cables
 EISENRUT, D O Division of Licensing 80/06/25 89pp
- O Inspection reports. IE Bulletins & correspondence
- BOO7240139 Forwards IE Info Notice BO-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode " No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director GO/05/OB
- 8007210439 Forwards IE Circular 80-13. "Grid Strap Damage in Mestinghouse Fuel Assemblies " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director BO/05/28 in
- 8007010188 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Foedwater Pumps." No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29 in
- B007220094 Forwards IE Info Notice 80-26. "Evaluation of Contractor OA Programs" No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/10 2pp
- B007i60230 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pumps Studs" No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/11 to
- 8007250368 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/100FR90 95(e) " No written response required.

 D'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/04/13
- 8007020445 Forwards JE Circular 80-15, "Loss of Reactor Coplant Pump Cooling & Natural Circulation Cooldown " No written response required D'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/20
- 8007170096 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY.JP Region 2. Atlanta, Office of the Director 80/06/24

- 8007230228 Forwards IE Bulletsn 80-16, "Potential Misapplication of Resemburt Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes ' Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- 8007250532 Forwards response to IE Bulletin 80-09. "Exam of Containment Liner Penetration Welds " Piping penetrations are designed & fabricated in accordance w/1977 edution of ABME Boiler & Pressure Vessel Code.including Summer 1977 addenda DAIL.t.C. Duke Power Co. 80/07/07. App
- DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION. UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUF, D G Division of Licensing 80/06/26 2pp
- DOCKET 50-497 MONTAQUE NUCLEAR POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT.D G Division of Licensing 80/06/26 2pp
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007020675 Responds to 800514 request for revision of items contained in NRC 800417 immediate action 1tr Inacturacies in preliminary info initially provided to Region 4 were included in immediate action 1tr SEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/10 200
- --8007020678 Requests revision of items contained in NRC 800417 immediate action ltr to ensure that correct info is transmitted & misinterpretations are minimized Imaccurate info provided to NRC included in immediate action ltr TURNER.E A Houston Lighting & Power Co 80/05/14 2pp
- 8007020227 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D G Division of Licensing BO/06/26 2pp
- BOO7300375 Requests specific direction & instructions for qualification of stress analysis computer code Code is planned to be released from AO Little lnc & will be used in calculations for piping sys (ABME III &/or ANBI B31 1)
 BARKER.D & Houston Lighting & Power Co BO/07/23 ip
- **G** Adjudicatory correspondence
- B007020605 Confirms understandings re withdrawals of Brown & Root brochure on implementation of GA program at job site & associated videotape Copies will be available as evidence in order to show cause & pending DL application COWAN, F E Baker & Botts B0/06/10 App.
- 8007110001 Answers to NRC interrogatories & request for documents
 Identifies DE Swayse as witness intended to be called re
 nonconformance repts of Contention 1 DG Bridenbaugh & R
 Hubbard will be called re Contention 3 W/Certificate of Svc
 SINKIN, L A Committee for Application of Nuremberg Principles to US
 Nuclear Power Production 80/06/13 9pp
- BO07310243 Forwards Commission BO0527 memorandum & order containing decisions on UCS 780302 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action as fire protection for electrical cables EISENHUT, D G Division of Licensing BO/06/25 B9pp

- B007300415 Discusses B00618 deposition & request for documents Requests reasons for document request within 14 days & change in date of deposition to last wk in Jul in San Antonio, TX Related correspondence
 SINKIN, L Citizens Concerned About Nuclear Power, Inc. 80/07/02
- 8007300406 Requests confirmation that meeting notes, members names, documents & records, position papers, taped conversations, consent of interviewes, by-laws & notes will be provided as agreed in deposition Related correspondence COWAN,F Baker & Botts 80/07/07 App
- B007160553 Identifies documents to be produced within 30 days per P Buchorn deposition testimony re application for GL Related correspondence HUDSON, T B Baker & Botts 80/07/08 4pp
- 8007310145 Motion for discovery schedule extension until 801201 NRC 800430 order to show cause wording parallels Contention 1 7 which may be resolved by util corrective actions in answer to order W/Certificate of Svc Related correspondence SINKIN,L A Citizens Concerned About Nuclear Power. Inc 81NKIN,L A Citizens for Equitable Utilities 80/07/08 4pp.
- 8007180246 Forwards notice of appearance in proceeding SLACK, R L. Hearing Branch 1 80/07/16 2pp
- G007220013 Submits rept re status of unforcement action Early hearing schedule discussions re OA/OC issues should abide enforcement action resolution Bay City TX BOOB19 public hearing will be held per ASLB 800430 order BLACK.R L Hearing Branch i 80/07/18 Zpp
- B007240485 Advises of status of enforcement action per NRC commitment Houston Lighting & Power responded to IE 800430 notice of violation & civil penalty by paying amount imposed Affirms postion re discussions of RA/CC early hearing schedule BLACK, R L Hearing Branch 1 80/07/18 2pp
- 8007300417 Discovery rept for June-Jul 1980 Received 800616 Rentfro & Marrack interrogatories & replied on 800707 Received 800706 Marrack motion to quash subposna for deposition. Deposition taken by agreement on 800716 Related correspondence COPELAND; J G Baker & Botts 80/07/18 1p
- B007300070 Response stating no opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utils motion for discovery extension until B01201 Certificate of Bvc encl HUDSON, T B Houston Lighting & Power Co HUDSON, T B Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/07/23 2pp
- 8007290748 Response stating no objection to issuance of order extending discovery period until 801201 upon request of Citizens Concerned About Nuclear Power No hearings re IE enforcement action are imminent Certificate of Svc encl BLACK, R 1. Hearing Branch 1 80/07/28 2pp
- H General correspondence
- 8007300948 Requests change of addressee on NRC correspondence from EA Turner to GW Oprea. Ir Address is unchanged OPREA. O W Houston Lighting & Power Co 80/07/23 1p
- M Antitrust correspondence
- 80D7010247 Forwards work order extending Hartley contract to 800531 W/o encl BLUME.M B Antitrust Division 80/04/14 1p
- 8007010264 Forwards signed stipulation abiding by ASLB 800331 protective order re Houston Lighting & Power corporate study H/o encl BLUME.M II Antitrust Division 80/04/14 1p
- 8007010298 Forwards documents mistakenly omitted from Hartley documents W/o onci HODODON.A P Antitrust Division 80/05/07 lp
- 8007020577 Ack receipt of 800530 ltr to TX Parks & Wildlife Dept advising that TX Utils Generating Co is not prepared to anter into lease agreement w/Dept covering Squaw Creek Reservior. Requests info re util intentions PREISTER, D J Texas, State of 80/06/10 2pp.

- BO07210388 Reviews B00702 draft transmission svc settlement agreement Document found to be unacceptable due to provisions making Austin jurisdictional as practical matter for wheeling "Postage stamp" wheeling rate is not proper in TX BALOUGH.R C Austin. TX B0/07/10 2pp
- 8007150425 Status rept advising that absent change in DOJ policy position, util will not be able to reach settlement w/dept Differences w/NRC re license conditions not yet resolved Certificate of Svc encl GREEN.D O Houston Lighting & Power Co * Baker & Botts * Lowenstein.Newman.Reis.Axelrad & Toll 80/07/11 7pp
- 8007i30431 Status rept on settlement negotiations Urges 60-day suspension of proceedings, including hearing date, due to continued negotiations w/Public Utils Doard of City of Brownsville, TX W/Certificate of Svc & pleading before FERC BTAHL, D M Central & Bouth West Corp STAHL, D M Isham, Lincoln & Beale 80/07/11 26pp
- BOO7130449 Status rept by Public Utils Board of City of Brownsville,TX re-settlement progress City would not object to further extension limited to 30 days although negotiations do not appear to be fruitful Certificate of Svc encl PDIRIER.M R Brownsville,TX POIRIER.M R Spiegel & McDiarmid 80/07/11 6pp
- 6007150500 Third status rept on settlement progress Suggests 30-day min extension to pursue negotiations & to present proposed license conditions re transmission svcs & other areas Certificate of Svc encl CHANANIA.F D Antitrust Division 80/07/11 Spp
- B007160625 Status rept re sattlement negotiation progress Expresses no optimism for agreement w/DDJ but agreement w/NRC may be reached re license conditions dealing w/bulk power wheeling rates Certificate of Svc encl SAMPLES,M D KNOTTS.J B Texas Utilities Generating Co SAMPLES,M D Worsham, Forsythe & Sampels 80/07/11 App
- B007170364 Status rept re development of settlement discussions Urges deniel of addl extension of time due to belief that no settlement will be reached between DOJ & applicants Certificate of Svc encl
 CYPHERT, S B Justice, Dept of E0/07/11 App
- 80071703BB Second status rept re settlement negotiations progress Urges further antitrust settlement efforts to proceed apace w/FERC settlement due to similarity of issues Certificate of Svc encl JOHN.D F Affiliation Unknown JOHN.D F Medinaelectric Coperative, Inc. JOHN.D F McDermott, Will & Emery B0/07/11 App
- B007210495 Bubmits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Mod of Joint ownership agreement drafts exchanged Certificate of Byc encl BURCHETTE.H H , RITTS, F H Northcutt Ely 80/07/11 4pp
- B007160547 Motion seeking renewal of DOJ 800521 motion to establish trial & other procedural dates Suggests B00708 for briefs & B01006 for commencement of evidentiary hearing Settlement does not appear to be possible Certificate of Svc encl CYPHERT, B B, PARMENTER, F Justice Dept of 80/07/14 6pp
- 8007220300 Suggests reconsideration of 800007 discovery order in light of extensive settlement negotiations subsequently conducted by all parties & counsel on 800402 MILLER, M. E. Atomic Safety and Licensing Board Panel 80/07/16 ip
- BOO7220556 Order denying petitions for directed certification w/o prejudice to resubmission following ABLB determination BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/18 Zpp
- 8007300418 Withdrawal of 770511 notice of appearance R Fabrikant responsible for all communications until further notice Certificate of Svc encl CYPHERT, S D Justice, Dept of 80/07/23 4pp
- 8007280620 Draws attention to two pleadings that should be treated separately although stapled together NRC motion for extension of time & NRC/DOJ joint motion for clarification & for establishment of production schedule CHANANIA.F D Antitrust Division 80/07/25 ip
- \$007280627 Motion for extension until 800731 to file objections \(\sigma \) proposed revision to ASLB 800717 prehearing conference order \(\mathbb{k} \) notice of final prehearing conference Discussions \(\sigma / \) parties have commenced \(\mathbb{k} \) must proceed LEWIS.8 \(\mathbb{H} \) Hearing \(\mathbb{l} \) rench 2 \(\mathbb{B} \) 80/07/25 \(2pp \)

- --B007280636 Joint motion for clarification of ASLB 800716 memorandum containing decision to reconsider ASLB 800307 order resettlement documents Moves for order establishing schedule for production of settlement documents W/Certificate of Svc FABRIKANT.R Justice, Dept of CHANANIA.F D. BLUME.M B Antitrust Division 80/07/25 Epp
- B007300356 Order granting extension until 800731 for NRC to submit objections & proposed revisions to 800717 final prehearing conference order
 WOLFE,S J Atomic Safety and Licensing Board Panel 80/07/25 1g

N Antitrust hearing transcripts

- B007180D08 Transcript of 800714 prehearing conforence in Bethesda, MD re settlement negotiations Pp 891-946 * Atomic Safety and Licensing Board Panel 80/07/14 78pp
- BO0725044i Proposed correction to BO0409 prehearing transcript Certificate of Syc encl
 GREEN.D G Houston Lighting & Power Co * Bater & Botts of Communication Newman.Reis. Axelrad & Toll 80/07/22 Spp *
- G Inspection reports, IE Bulletins & correspondence
- 8007250319 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve " No specific action or response necessary SEYFRIT.K V Region 4. Dallas. Office of the Director 80/03/31 in
- 8007150064 Ack receipt of 800109 & 0308 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 SEIDLE-W C Region 4. Dallas. Reactor Construction & Engineering Bupport Branch 80/04/04 ip
- --8007150075 Responds to NRC 791212 & 800220 ltrs re violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 Corrective actions const procedure CCP-4 revised on 800317 to incorporate baffle board use TURNER.E A Houston Lighting & Power Co 80/03/18 2pp
- 8007010072 Updates 800331 response to IE Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" No addl info has been received from vendors TURNER, E A Houston Lighting & Power Co 80/04/20 2pp
- 8007230718 Ack receipt of 800430 ltr from NRC Responses to notice of violation notice of proposed imposition of civil penalties & Bection 6 of order to show cause will be submitted within periods specified in NRC notice & orders OPREA, G W Houston Lighting & Power Co 80/05/14 lp
- 8007240505 Forwards IE Info Notice 80-21, "Anchorage & Support of Safety-Related Electrical Equipment" No written response required SEYFRIT.K V Region 4, Dellas, Office of the Director 80/05/16 in
- 8007010203 Forwards IE Insp Repts 50-498/80-06 & 50-499/80-06 during Apr 1980 No noncompliance noted SEIDEL, W C Region 4. Dalias, Reactor Construction & Engineering Support Branch 80/05/19 3pp
- --8007010212 IE Insp Repts 50-498/80-0& & 50-497/80-0& during Apr 1980
 No noncompliance noted Major areas inspected previous items
 of noncompliance, site tour, safety-related piping, containment
 structurel steel & fellowup on const deficiency
 PHILLIPS.H B . CROSSMAN.W A Region 4. Dallas. Office of the
 Director 80/05/13 App
- B007100342 Forwards IE Insp Repts 50~498/B0~11 & 50-499/B0~11 on 800505-08 No noncompliance noted BEIDLE.W C Region 4. Dalles, Reactor Construction & Engineering Support Branch B0/05/23 2pp
- --8007100346 IE Insp Repts 50-498/80-11 & 50-499/80-11 on 800505-08 No noncompliance noted Major areas inspected constlactivities, stop work order for RCPB welding & reactor containment liner dome welding CROBEMAN A Ragion 4. Dallas, Reactor Construction & Engineering Support Branch GILBERT.L D. MARTIN.L E Region 4. Dallas, Office of the Director 80/05/22 App
- 8007020253 Forwards IE Info Notice 80-22, "Breakdowns in Contamination Control Programs" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/05/28 in

- 8007010037 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required SEYFRIT,K V Region 4, Dallas, Office of the Director 80/05/29
- 6007240333 Forwards IE Insp Repts 50-498/80-12 & 50-499/80-12 on 800512-15 No noncompliance noted SEIDLE:N C Region 4. Dollas: Reactor Construction & Engineering Support Branch 80/06/03 2pp
- --8007240337 IE Insp Repts 50-498/80-12 & 50-497/80-12 on 800512-15 No noncompliance insted Major areas inspected observation of work & review of records repearthwork & concrete TAPIA.J I , CROSSMAN.W A Region 4. Dallas. Office of the Director HALLARE Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/06/03 6pp
- 8007100493 Updates response to IE Bulletin 79-28 re use of NAMCO Model EA 180 stem-mounted limit switches No corrective action required for majority of vendors the vendor still conducting review & other amplemented corrective action recommended TURNER, E A Houston Lighting & Power Co 80/06/04 2pp
- 8007220078 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required SEFRIT.K V Region 4, Dallas, Office of the Director 80/06/10 in
- B007020104 Ack receipt of B00523 ltr informing NRC of steps taken to correct violations noted in B00430 notice of violation & order to show causa Implementation of existing GA/GC procedures will be focus of followup insp STELLD,V Office of Inspection & Enforcement, Office of the Director 80/06/11 2pp
- 8007170203 Responds to IC Bulletin 80-09 "Mydramotor Actuator Deficiencies" No safety-related sys or component in South TX Project uses subj actuators OPREA.0 W Houston Lighting & Power Co 80/06/13 1p
- 8007270059 Forwards IE Info Natice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 95(e) " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/13
- 8007230278 Forwards 1E Insp Repts 50-498/80-10 & 50-499/80-10 during May 1980 No noncompliance noted SEIDLE, H C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/06/19 2pp
- ---8007230292 lE Insp Repts 50-498/80-10 & 50-499/80-10 during May 1980 No noncompliance noted Major areas inspected structural backfill: structural concrete-containment tendons, component storage & followup on const deficiencies CROSSMAN.W.A. PHILLIPS.H S. Region 4. Daltas. Office of the Director 80/06/17 App
- B007R40039 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director B0/06/20
- 8007280132 Forwards IE Investigation Repts 50~498/80-09 & 80-499/80-09 on 800415-18 No noncompliance noted SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/23
- --B0072B0137 IE Investigation Repts 50-498/B0-09 & 50-499/80-09 on 800415-18 No noncompliance noted Major area investigated allegation that Brown & Root Inc attempted to intimidate GC inspectors & employees into covering up const defects BEYFRIT.K V . PRISKILL, D D . BACI, P E Region 4. Dallas. Office of the Director B0/06/19 iOpp

lication of

ed red r 80/05/27

- 8007150007 Forwards IE Investigation Repts 50-498/80-15 & 50-499/80-15 on 800605-66 No noncumpliance noted SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/30.
- --8007150009 IC Investigation Repts 50-498/80-15 & 50-499/80-15 on 800605-06 No noncompliance noted Major areas inspected altegations that consultant firm had recommended const be discontinued at site for one yr HERR, R K, DRISKILL, D D., SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/30 App
- 8007090246 Revises IE Bulletin B0-08 review submittal date from 800707 to 0804 OPRCA.0 W Houston Lighting & Power Co 80/07/03 2pp
- 8007220578 Responds to IE Bulletin 79-28 re use of NAMCO Model EA 180 stem-mounted limit switches. Review of all vendors indicates only one affected Recommended corrective action implemented OPREA, G W Houston Lighting & Pawer Co 80/07/14 2pp
- 9 Reportable occurrences. LERs & related correspondence
- 8007100443 Second interim deficiency rept re damage to Unit 2 reactor containment bldg steel liner plate Plate removal & mapping completed Next interim rept to be submitted by 800711 TURNER, E A Houston Lighting & Power Co 80706/06 4pp
- 8007160219 Second interim Part 21 rept re steel liner plate in reactor containment bldg. Progress on repair includes completed removal of deformed liner plate & detailed mapping of removed plate submitted to contractor TURNER, E A Houston Lighting & Power Co 80/06/06 6pp
- 8007070304 Second interim deficiency rept re polar crane rail tie-down studs Investigation by vendor concludes that acceptability of polar crane hold-down studs are questionable Brown & Root will further evaluate sys Next report to be sent 800801 TURNER, E A Houston Lighting & Power Co 80/06/23 5pp
- 8007020618 RO on BO0529, during design review, seismic qualification of essential cooling water intake structure gantry crane & diesel generator fuel storage tank found w/deficient response spectra values New seismic evaluation in progress.

 OPREA. G W Houston Lighting & Power Co 80/06/26 App
- 8007090365 Interim deficiency rept re breakdown in quality program for concrete placement CII-490 Brown & Root continuing investigation of conditions & examining documentation & physical quality of placement OPREA.O W Houston Lighting & Power Co 80/07/03 2pp
- R007110337 Advises that 800605 potentially reportable deficiency reconcrete placement in diesel generator bldg is not reportable under 10CFR50 55(e)

 OPREA.O W Houston Lighting & Power Co 80/07/03 3pp
- 8007130645 Final deficiency rept re reactor vessel outlet nozzle safeends Evaluation shows that condition would not adversely affect safety of plant operation Matter considered not reportable under 10CFR 80, 35(s) DPREA
- B007160604 Forwards interim deficiency rept re linear plate bulge repair Next rept will be submitted 801001 OPREA, G W Houston Lighting & Power Co 80/07/11 3pp
- --8007160607 Interim deficiency rept re linear plate bulge consisting of logic for linear plate bulge repair * Houston Lighting & Power Co 80/07/11 lp
- BOO7210511 Third interim deficiency rept re damage to steel liner in reactor containment bldg Logic for liner bulge repair encl Next rept will be forwarded by BO1001 OPREA.O W Houston Lighting & Power Co BO/07/11 4pp
- 8007290441 Part 21 rept re latent math noncompliances in ASME Section III pipe supports supplied by NPS Industries Initial review indicates no deficiency since supports are used in nonwelding applications RICE, H M Brown & Root Corp (subs of Halliburton Corp) 80/07/11 3pp
- 8007230512 First interim deficiency rept re breakdown in Brown & Root QA program re procurement cycle of purchased matls at facility Procedures for procurement cycle control & all vendor-related activities & records under review OPREA, Q W Houston Lighting & Power Co 80/07/14 5pp

- 8007230525 Interim deficiency rept re diesel generator fuel oil tank room exhaust fans Por commitments in PSAR & FSAR, fans must be connected to Class IE power fans not supplied from Class IE source Corrective actions being evaluated OPREA, Q W Houston Lighting & Power Co 80/07/14 3pp
- 8007230476 Interim deficiency rept re min/max soil density test on assential cooling water backfill Detailed info re deficiency will be provided to NRC as part of response to Item 2, App A. of 800430 order to show cause GPREA. G W Houston Lighting & Power Co 80/07/17 3pp
- BOO7230540 Interim deficiency rept re matl control of ASTM A-325 structural steel bolts improper segregation of Category I & non-Category I structural steel bolts in field resulted in bolts procured under non-Category I specs OPREA, G W Houston Lighting & Power Co 80/07/17 4pp
- BOO7300382 Interim deficiency rept re re-evaluation of piping welds previously found acceptable Liquid penetrant retest by Bouthwest Research determined that eight welds exhibited lines indications in excess of code limitations OPREA.O W Houston Lighting & Power Co 80/07/24 3pp

U Congressional/Executive Correspondence

B007300365 Requests testimony prosented at B00629 committee hearing re issues relating to const of nuclear power plants ECKHARDT, B House of Rep , Interst & Foreign Commerce B0/07/11

DOCKET STN-50-499 BOUTH TEXAS PROJECT. UNIT 2

A. Application/construction stage documents & correspondence

- 8007020675 Responds to 800514 request for revision of items contained in NRC 800417 immediate action ltr Inaccuracies in preliminary info initially provided to Region 4 were included in immediate action ltr SEYFRIT, K'V Region 4, Dallas, Office of the Director 80/06/10 200.
- --800702067B Requests revision of items contained in NRC B00417 immediate action ltr to ensure that correct info is transmitted & misinterpretations are minimized Inaccurate info provided to NRC included in immediate action ltr TURNER, E A Houston Lighting & Power Co B0/05/14 2pp.
- B007020227 Forwards NRC Dfc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to engoing activities TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 9007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EIBEMHUT, D © Division of Liconsing 80/06/26 2pp
- BO07300375 Requests specific direction & instructions for qualification of stress analysis computer code Code is planned to be released from AD Little. Inc & will be used in calculations for piping sys (ABME III &/or ANSI B31 i)
 BARKER, D 0 Houston Lighting & Power Co BO/07/23 ip

O Adjudicatory correspondence

- BOO7020605 Confirms understandings re withdrawals of Brown & Root brochure on implementation of GA program at job situ & associated videotape. Copies will be available as evidence in order to show cause & pending GL application GOHAN: FE Bakar & Botts 80/06/10 3pp
- 8007110001 Answers to NRC interrogatories & request for documents
 Identifies DE Swayze as witness intended to be called re
 nonconformance repts of Contention 1 DO Bridenbaugh & R
 Hubbard will be called re Contention 3 W/Certificate of Svc.
 BINKIN,L A Committee for Application of Nuremberg Principles to US
 Nuclear Power Production BO/06/13 9pp
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on VCS 780502 petition for reconsideration of 780413 memorandum & order VCS 771104 petition sought action re fire protection for electrical cables, EISENHUT; D G Division of Licensing 80/06/25 89pp.

- B007300415 Discusses B00618 deposition & request for documents Requests reasons for document request within 14 days & change in date of deposition to last wk in Jul in San Antonio,TX Related correspondence
 SINKIN.L Citizens Concerned About Nuclear Power, Inc. 80/07/02
- 8007300406 Requests confirmation that meeting notes, members names, documents & records, position papers, taped conversations, consent of interviouses, by-laws & notes will be provided as agreed in deposition Related correspondence CDWAN.F Baker & Botts 80/07/07 4pp
- 8007160553 Identifies documents to be produced within 30 days per P Buchorn deposition testimony re application for OL Related correspondence HUDSON, T.B. Baker & Botts 80/07/08 4pp
- B007310145 Motion for discovery schedule extension until 801201 NRC 800430 order to show cause wording parallels Contention 1 7 which may be resolved by util corrective actions in answer to order W/Certificate of Svr Related correspondence BINKIN.L A Citizens Concerned About Nuclear Power, Inc. SINKIN.L A Citizens for Equitable Utilities 80/07/08 4pp
- 8007180246 Forwards notice of appearance in proceeding BLACK,R L. Hearing Branch i 80/07/14 2pp
- 8007220013 Submits rept re status of enforcement action Early hearing schedule discussions re GA/GC issues should abide enforcement action resolution Bay City TX 800817 public hearing will be held per AGLB 800430 order BLACKER L. Hearing Branch 1 80/07/18 2pp
- 80072404BB Advises of status of enforcement action per NRC commitment Houston Lighting & Power responded to IE 800430 notice of violation & civil penalty by paying amount imposed Affirms position re discussions of GA/GC early hearing schodule BLACK/R L. Hearing Branch 1 80/07/18 2pp
- 8007300417 Disrovery rept for June-Jul 1980 Received 800616 Rentfro & Marrack interrogatories & replied on 800709 Received 800706 Marrack motion to quash subpoena for deposition Deposition taken by agreement on 800716 Related correspondence COPELAND, J O Baker & Botts 80/07/18 1p
- 8007300070 Response stating no opposition to Citizens Concerned About Nuclear Power & Citizens for Equitable Utils motion for discovery extension until 801201 Certificate of Svc encl HUDSON, T B Houston Lighting & Power Co HUDSON, T B Baker & Botts * Lowenstein, Newman, Reis, Axelrad & Toll 80/07/23 29p
- 8007290748 Response stating no objection to issuance of order extending discovery period until 801201 upon request of Citizens Concerned About Nuclear Power No hearings re IE enforcement action are imminent Certificate of Svc encl BLACK.R L Hearing Branch i 80/07/28 2pp

- 8007300348 Requests change of addressee on NRC correspondence from EA Turner to GW Oprea. Ur Address is unchanged OPREA. O W Houston Lighting & Power Co 80/07/23 ip
- M Antitrust carrespondence
- 8007010247 Forwards work order extending Hartley contract to 800531 W/o encl BLUME.M B Antitrost Division 80/04/14 ip
- 8007010264 Forwards signed stipulation abiding by ASLB 800331 protective order re Houston Lighting & Power corporate study W/o enci BLWE.M B Antitrust Division 80/04/14 Ip
- 8007010298 Forwards documents mintakenly omitted from Hartley documents M/o encl HDD002N,A P Antitrust Division HO/05/07 1p
- 8007020577 Ack receipt of 800530 ltr to TX Parks & Wildlife Dept advising that TX Utils Generating Co is not prepared to enter into lease agreement w/Dept covering Squaw Creek Reservior Requests info re util intentions PREISTER, D J Texas, State of 80/06/10 2pp

- B007210388 Reviews B00702 draft transmission avoisettlement agreement Document found to be unacceptable due to provisions making Austin jurisdictional as practical matter for wheeling "Postage stamp" wheeling rate is not proper in TX BALDUON.R C Austin, TX 80/07/10 2pp
- B007150425 Status rept advising that absent change in DOJ policy position, util will not be able to reach settlement w/dept Differences w/NRC re license conditions not yet resolved Certificate of Syc encl GREEN.D Q Houston Lighting & Power Co 80/07/11 7pp
- 8007150431 Status rept on settlement negotiations Urges 40-day suspension of proceedings.including hearing date.due to continued negotiations w/Public Utils Board of City of Brownsville-TX W/Certificate of Svc & pleading before FERC. STAHL, D M Central & South West Corp 80/07/11 26pp
- 8007190449 Status rept by Public Utils Board of City of Brownsville, TX re settlement progress City would not object to further sitension limited to 30 days although negotiations do not appear to be fruitful Certificate of Syc encl PDIRIER, M R Brownsville-TX 80/07/11 opp
- B007150500 Third status rept on settlement progress Suggests 30-day min extension to pursue negotiations & to present proposed license conditions re transmission sycs & other areas Certificate of Syc encl CHANANIA.F D Antitrust Division 80/07/11 8pp
- B007160625 Status rept re settlement negotiation progress Expresses no optimism for agreement w/DDJ but agreement w/NRC may be reached re license conditions dealing w/bulk power wheeling rates Certificate of Svc enci SAMPLES.M D Texas Utilities Generating Co KNOTTS.J B Debevoise & Liberman B0/07/11 App
- 800/170344 Status rept re development of settlement discussions Urges denial of addl extension of time due to belief that no settlement will be reached between DDJ & applicants Certificate of Syc encl
 CYPHERT, 8 B Justice, Dept of 80/07/11 App
- 8007170388 Second status rept re settlement magnifications progress. Urges further antitrust settlement efforts to proceed apace w/FERC settlement due to similarity of issues Certificate of Svc encl JOHN: D F Affiliation Unknown 80/07/11 App
- 8007210455 Submits status rept of settlement negotiations in Houston Lighting & Power Co et al & TX Utilities Generating Co Mod of joint ownership agreement drafts exchanged Certificate of Syc enc! BURCHETTE, # H Northcutt Ely 80/07/11 4pp
- 8007160547 Motion seeking renewal of DOJ 800521 motion to establish trial & other procedural dates Suggests B00708 for briefs & 801006 for commencement of evidentiary hearing Settlement does not appear to be possible Certificate of Svc encl CYPHERT,S B Justice, Dept of 80/07/14 App.
- 8007220500 Buggests reconsideration of B00307 discovery order in light of extensive settlement negotiations subsequently conducted by all parties & counsel on 800402 MILLER, M E Atomic Safety and Licensing Board Panel 80/07/16 ip
- 8007220556 Order denying petitions for directed certification w/o prejudice to resubmission following ASLB determination BISHOP.C J Atomic Safety and Licensing Appeal Panel 80/07/18
- BOO730041B Withdrawal of 790511 notice of appearance R Fabrikant responsible for all communications until further notice Certificate of Svc encl CYPHERT-S B Justice.Dept of BO/07/23 App
- 8007280620 Braws attention to two pleadings that should be treated separately although stapled together NRC motion for extension of time & NRC/DDJ joint motion for clarification & for establishment of production schedule CHANANIA.F D Antitrust Division 80/07/25 ip
- B007280627 Motion for extension until B00731 to file objections w/ proposed revision to ASLB 800717 prehearing conference order & notice of final prehearing conference Discussions w/ parties have commenced & must proceed LEWIS.S H Hearing Branch 2 80/07/25 2pp

- --8007280636 Joint motion for clarification of ASLB 800716 memorandum containing decision to reconsider ASLB 800307 order resettlement documents Noves for order establishing schedule for production of settlement documents W/Certificate of Svc FABRIKANT, R Justice, Dept of 80/07/28 8pp
- 8007300356 Order granting extension until 800731 for NRC to submit objections & proposed revisions to 800717 final prehearing conference order MDLFE,S J Atomic Safety and Licensing Board Panel. 80/07/25 ip
- N Antitrust hearing transcripts
- 8007180008 Transcript of 800714 prehearing conference in Bethesda. MD re-settlement negotiations Pp 891-946 * Atomic Safety and Licensing Board Panel 80/07/14 78pp
- 8007250441 Proposed correction to 800409 prehearing transcript Certificate of Svc encl GREEN, D C Houston Lighting & Power Co 80/07/22. 5pp
- Q Inspection reports, IE Bulletins & correspondence
- B007250319 Forwards IE Info Notice 80-12, "Instrument Failure Causes Opening of PORV & Block Valve," No specific action or response necessary SEYFRIT, K V Region 4, Dailas, Office of the Director B0/03/31.
- B007150064 Ack receipt of B00109 & 0308 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 BEIDLE-W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/04/04 ip
- --B007150075 Responds to NRC 791212 & B00220 ltrs re violations noted in IE Insp Repts 50-498/79-20 & 50-499/79-20 Corrective actions const procedure CCP-4 revised on B00317 to incorporate baffle board usp TURNER.E A Houston Lighting & Power Co 80/03/18 2pp
- 8007010072 Updates 800331 response to 1E Bulletin 79-28, "Possible Malfunction of NAMCO Model EA180 Limit Buitches at Elevated Temps "No addl info has been received from vendors TURNER, E A Houston Lighting & Power Co 80/04/30 2pp
- B00723071B Ack receipt of 800430 ltr from NRC Responses to notice of violation notice of proposed imposition of civil penalties & Section & of order to show cause will be submitted within periods specified in NRC notice & orders OPREA.0 W Houston Lighting & Power Co 80/00/14 ip
- 8007240505 Forwards IE Info Notice 80-21, "Anchorage & Bupport of Safety-Related Electrical Equipment " No written response required. SEYFRIT,K V Region 4, Dallas. Office of the Director 80/05/14
- 8007010203 Forwards IE Insp Repts 50-498/80-06 & 50-499/80-06 during Apr 1980 No noncompliance noted SEIDEL.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/05/17 3pp
- B007100342 Forwards IE Insp Repts 50-499/80-11 & 50-499/80-11 on 800505-09 No noncompliance noted BEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch B0/05/23 2pp
- --8007100346 IE Insp Repts 50-498/80-11 & 50-499/80-11 on 800505-08.No noncompliance noted Major areas inspected const activities, stop work order for RCPB welding & reactor containment liner dome welding CRUSSMAN, W A Region 4, Dallas, Reactor Construction & Engineering Support Branch 01LBERTI, D , MARTIN, L E Region 4, Dallas, Office of the Director 80/05/22 App
- 8007020259 Forwards IE Info Notice 80-22, "Breakdowns In Contamination Control Programs" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director. 80/05/28. ip
- 8007010037 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required SEFRIT.K V Region 4, Dallas, Office of the Director 80/05/29.

- 8007240333 Forwards IE Insp Repts 50-498/80-12 & 50-499/80-12 on BOO\$12-15 No noncompliance noted BEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/03 2pp
- --B007240337 IE Insp Repts 50-498/80-12 & 50-499/80-12 on 800512-15 No noncompliance noted Major areas inspected observation of work & review of records re earthwork & concrets.

 TAPIA: J I , CROBSMAN, W A Region 4, Dallas, Diffice of the Director HALL: R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 80/06/03 6pp
- BOO7100433 Updates response to IE Bulletin 79-28 re use of NAMCO Model EA 180 stem-mounted limit switches No corrective action required for majority of vendors One vendor still conducting review & other implemented corrective action recommended TURNER, E A Houston Lighting & Power Co 80/06/04 2pp
- BOO7220078 Forwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs " No written response required BEYFRIT.K V Region 4. Dallas. Office of the Director 80/06/10 in
- BO07020104 Ack receipt of B00523 ltr informing NRC of steps taken to correct violations noted in B00430 notice of violation & order to show cause, Implementation of existing GA/GC procedures will be focus of followup insp BTELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/11 2pp
- BO07170203 Responds to IE Bulletin BO-09 "Hydramotor Actuator Deficiencies " No safety-related sys or component in South TX Project uses subjactuators DPREA.G W Houston Lighting & Power Co 80/06/13 ip
- BOO7270059 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required. SEYFRIT.K V Region 4, Dallas, Office of the Director 80/06/19 in
- 8007230278 Forwards IE Insp Repts 50-498/80-10 & 50-499/80-10 during May 1980 No noncompliance noted SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 80/06/17 2pp
- --BOO7230292 IE Insp Repts 50-498/80-10 & 50-499/80-10 during May 1980 No noncompliance noted Major areas inspected structural backfill, structural concrete, containment tendons, component storage & followup on const deficiencies CROSSMAN, W.A., PHILLIPS, H.S. Region 4, Dallas, Office of the Director 80/06/17 6pp.
- BOC7240039 Forwards IE Circular HC-15, "Loss of Reactor Coolant Pump Gooling & Natural Circulation Cooldown " No written response required BEYFRIT,K V Region 4, Dallas, Office of the Director BO/06/20
- BOO7280132 Forwards IE Investigation Repts 50-498/80-09 & 50-499/80-09 on 800415-18 No noncompliance noted SEYFRIT, K V Region 4, Dallas, Office of the Director 80/06/23.
- --8007280137 IE Investigation Repts 50-498/80-09 & 50-499/80-09 en 800415-18 No noncompliance noted Major area investigated allegation that Brown & Root! Inc attempted to intimidate GC inspectors & amployees into covering up const defects BEVFRIT.K V , DRIGKILL,D D , BACI,P E Region 4. Dallas, Office of the Director 80/06/19 10pp
- BOO7170676 Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel" No written response required BEYFRIT.K V Region 4, Dallas, Office of the Director 80/05/24 is.
- 8007230364 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Quéput Codes." Whitten response required IE Circular 80-16 also entl No written response required BEYFRIT.K V. Region 4. Dallas, Dffice of the Director 80/06/27
- BOO7150007 Forwards 1E Investigation Repts 50-498/80-15 & 50-499/80-15 on 800605-06, No noncompliance noted.

 BEYFRIT, K. V. Region 4, Dalles, Office of the Director 80/06/30 is

- --8007150009 fE Investigation Repts 50-498/80-15 & 50-499/80-15 on 800605-06 No noncompliance noted Major areas inspected allegations that cuisuitant farm had recommended const be discontinued at site for one yr HERR, R K. DRISKILL.D D. SEYFRIT.K V. Region 4. Dallas, Office of the Director 80/06/30 6pp
- BOO7090246 Revises IE Bulletin BO-08 review submittal date from BO0707 to 0804 TPREA, G W Houston Lighting & Power Co 80/07/03 2pp
- 8007220978 Responds to IE Bulletin 79-28 re use of NAMCO Model EA 180 stem-mounted limit switches Review of all vendors indicates only one affected Recommended corrective action implemented OPREA.O W Houston Lighting & Power Co BO/07/14 2pp
- 8 Reportable occurrences, LERs & related correspondence
- BOO7100443 Second interim deficiency rept re damage to Unit 2 reactor containment bldg steel liner plate Plate removal & mapping completed Next interim rept to be submitted by BOO711 TURNER,E A Houston Lighting & Power Co 80/06/06 4pp
- 8007160219 Second interim Part 21 rept re steel liner plate in reactor containment bldg Progress on repair includes completed removel of deformed liner plate & detailed mapping of removed plate submitted to contractor TURNER.E A Houston Lighting & Power Co 80/06/06 App
- 800707030A Second interim deficiency rept re polar crane rail tie-down studs Investigation by vendor concludes that acceptability of polar crane hold-down stude are questionable Brown & Root will further evaluate sys Next report to be sent 800801

 TURNER.E A Houston Lighting & Power Co 80/06/23 5pp
- 8007020618 RO on 800529, during design review, seismic qualification of essential cooling water intoke structure gantry crans & diesel generator fuel storage tank found u/deficient response spectra values New seismic evaluation in prograss OPREA, G W Houston Lighting & Power Co 80/06/26 4pp
- BOO7090365 Interim deficiency rept re breakdown in quality program for concrete placement CI1-W90 Brown & Rost continuing investigation of conditions & examining documentation & physical quality of placement OPREA. G W Houston Lighting & Pownr Co BO/07/03 2pp
- BO07ii0337 Advises that 800b05 potentially reportable deficiency re concrete placement in diesel generator bldg is not reportable under 10CFR50 55(e) GPREA.8 W Houston Lighting & Power Co 80/07/03 3pp
- 8007150645 Final deficiency rept re reactor vessel outlet nozzle safeends Evaluation shows that condition would not adversely affect safety of plant operation Natter considered not reportable under 10CFR50 55(e) OPREA. G W Houston Lighting & Power Co 80/07/03 3pp
- 8007160604 Forwards interim deficiently rept to linear plate bulge repair Next rept will be submitted 801001 OPREA.G W Houston Lighting & Power Ca 80/07/11 3pp
- --8007160609 Interim deficiency rept re linear plate bulge consisting of logic for linear plate bulge repair
 # Houston Lighting & Power Co 80/07/11 lp
- 8007210511 Third interim deficiency rept re damage to steel liner in reactor containment bldg Logic for liner tulge repair encl Next rept will be forwarded by 801001 OPREA.O.W Houston Lighting & Power Co 80/07/11 4pp
- 800729044) Part 21 rept re latent math noncompliances in ASME Section III pipe supports supplied by NPS Industries Initial review indicates no deficiency since supports are used in nonwelding applications
 RICE.W M Brown & Root Corp (subs of Halliburton Corp)
 80/07/11 3pp
- 8007230812 First interim deficiency rept re breakdown in Brown & Root GA program re procurement cycle of purchased matis at facility. Procedures for procurement cycle control & all vendor-related activities & records under review OPREA. O W Houston Lighting & Power Co 80/07/14 5pp
- B007230525 Interim deficiency sept re diesel generator fuel oil tank room exhaust fans Per commitments in PSAR & FSAR, fans must be connected to Class IE power Fans not supplied from Class IE source Corrective actions being evaluated OPREA.Q W Houston Lighting & Power Co B0/07/16 Opp

- 8007230476 Interim deficiency rept re min/max soil density test on essential cooling water backfill Detailed info re deficiency will be provided to NRC as part of response to Item 2.App A. of 800430 order to show cause OPREA.9 W Houston Lighting & Power Co 80/07/17 3pp
- 8007230540 Interim deficiency rept re mati control of ASTM A-325 structural steel bolts Improper segregation of Category I & non-Category I structural steel bolts in field resulted in bolts procured under non-Category I specs
 OPREA, 0 W Houston Lighting & Power Co 80/07/17 4pp
- B0073003B2 Interim deficiency rept re re-evaluation of piping welds previously found acceptable Liquid penetrant retest by Southwest Research determined that eight welds exhibited lineal indications in excess of code limitations OPREA.G W. Houston Lighting & Power Co. B0/07/24 3pp

U Congressional/Executive Correspondence

8007300365 Requests testimony presented at 800629 committee hearing re issues relating to const of nuclear power plants ECMHARDT, 8 House of Rep , Interst & Foreign Commerce 80/07/11

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREO-0660 & found in NUREO-0694 EISENHUT, D & Division of Licensing 80/06/26 2pp

Q Adjudicatory correspondence

- 8006200066 Forwards Pages 4.5 % 6 which were inadvertently omitted from Exhibit A of High Rock Lake Association 800921 affidavit
 SPAINGER, D. High Rock Lake Association 80/05/23 ip
- --8006200071 Pages 4.5 & 6 for Exhibit A of High Rock Lake Association 800521 affidavit 8PRINGER.D High Rock Lake Association 78/11/16 App

H General correspondence

- 800727004B Responds to inquiry re flooding of site Natural phenomena considered in plant design & const Access to & from plant during flood considered in emergency plan in flood emergency rail boat or DKW transportation will be utilized KEPPLER.J G Region 3. Chicago. Office of the Director 80/05/22 2ng
- 8007020053 Responds to 800520 ltr re J Branum inquiry about facility expansion Counsel for applicants requested that ASLAB terminate proceedings on CP applications due to reduced growth projections & financial constraints No action taken DIRCKS, W J Office of the Executive Director for Operations 80/04/20 Ip

DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

- A Application/construction stage documents & correspondence
- BOO723D001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREQ-0660 & found in NUREQ-0694 EIGENHUT, D G Division of Licensing 80/06/26 2pp

- B007290048 Responds to inquiry re flooding of site Natural phenomenal considered in plant design & const Access to & from plant during flood considered in emergency plan In flood emergency rail. boat or DKW transportation will be utilized KEPPLER. J @ Region 3. Chicago. Office of the Director 80/05/22 Zpp
- 8007020053 Responds to 800520 itr re J Bronum inquiry about facility expansion Counsel for applicants requested that ASLAG terminate proceedings on CP applications due to reduced growth projections & financial constraints No action taken DIRCKS, UJ Diffice of the Executive Director for Operations 80/06/20 1p

- DOCKET STN-50-502 HAVEN NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be mot for current GL applications, as derived from NUREG-0460 & found in NUREG-0694 EISENHUT.D G Division of Licensing 80/04/24 2pp
- 9 Adjudicatory correspondence
- 8007230802 Hotion for termination of proceeding Director of Ofc of Nuclear Reactor Regulation notified on 800517 re withdrawal of application Certificate of Bvc encl CHURCHILL, B W Hisconsin Electric Power Co CHURCHILL, B W Shaw, Pittman, Potts & Trombridge 80/07/17 4pp
- 8007310314 Responds to applicants' 800717 motion to terminate proceeding No objection to termination or to applicants 800517 withdrawal of application Centificate of Svc encl ODLOBERG, B C Hearing Branch 2 80/07/29 3pp
- DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 8007R3D001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D G Division of Licensing 80/06/26 2pp
- F Security, medical, emergency & fire protection plans
- 8007300344 Forwards map. overlay, table & methodology basis re emorgency evacuation time estimates per NRC 800702 request RENBERGER.D L Washington Public Power Supply System 80/07/24
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables
 EIBENHUT, D G Division of Licensing 80/06/25 87pp
- Q Inspection reports, IE Bulletins & correspondence
- 8007230007 Forwards suppl info to 790825 response to IE Bulletin 78-12 Record search in response to C-E rept. "Atypical Weld Matl in Reactor Vessel Welds." produced no evidence of use of atypical wold matl in reactor prossure vessels RENBERGER.D L Washington Public Power Supply System 80/03/17.
- 8007290405 Forwards insp program committed to in 790710 response to IE Bulletin 79-03 re longitudinal weld defects in stainless steel pips spools No evidence of longitudinal weld defects was found RENBERGER.D L. Washington Public Power Supply Bystem 80/04/15 33pp.
- B007180023 Forwards IE Insp Repts 50-508/80-05 & 50-509/80-05 on B00513-15 No noncompliance noted B00K,H E Repion 5. Ban Francisco, Fuel Facility & Materials Safety Branch B0/05/23 2pp
- --8007180025 IE Insp Repts 50-509/80-05 & 50-509/80-05 on 800513-15 No noncompliance noted Major areas inspected organization & administration.procedures.audits & CP requirements YUHAS,O P , WENSLAWSKI,F A Region 5, San Francisco, Office of the Director. BOOK,H E. Region 5, Ban Francisco, Fuel Facility & Materials Safoty Branch 80/05/28 9pp
- 8007220252 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ENGELMEN.R H Region 5. San Francisco. Office of the Director 80/06/10 ip
- B007300306 Responds to IE Bulletin B0-05 re damage to chemical vol control sys tanks Tanks adequately protected against vacuum damage Holdup tanks equipped w/vacuum breakers Equipment drain tank designed for full vacuum w/nitrogen cover gas. RENBERGER, D L Washington Public Power Bupply System B0/06/12 Rpp

- 9007290090 Forwards IE info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR30 85(e) " No written response required ENGELKEN:R H Region 5, San Francisco, Office of the Director BO/06/13 1p
- 8907020466 Forwards IE Circular 80-15, "Loss of Reactor Coolent Pump Cooling & Natural Circulation Cooldown" No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/04/20 in
- BOO7180299 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENDELKENR H Region 5. San Francisco, Office of the Director BO/06/24 ip
- 8007230401 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Guéput Codes " Hritten response required IE Gircular 80-16 also encl. No written response required ENGELKEN,R H. Region 5, San Francisco, Office of the Director 80/06/27. 1p
- B007180329 Responds to NRC 800609 ltr re violations noted in IE insp on 800520-23 Corrective actions util has established hold point to visually inspect all accessible interior/exterior ASPMC Section III spool welds RENBERGER.D L Washington Public Power Supply System 80/07/11 400
- U Congressional/Executive Correspondence
- 8007300367 Submits questions re unusual financing arrangement between util & Bonneville Power Administration Related correspondence MEAVER.J House of Rep. 80/07/14 2pp
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- 800723000: Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0640 & found in NUREG-0694
 EIBENRYLD G. Division of Licensing 80/06/26 200
- F Security, medical, emergency & fire protection plans
- BOO7300344 Forwards map.overlay, table & methodology basis re emergency evacuation time estimates per NRC 800702 request
 RENBERGER, D. L. Washington Public Power Supply System 80/07/24
- Q. Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 77104 petition sought action re fire protection for electrical cables EISENHUT.D G Division of Licensing 80/06/25, 89pp
- Q Inspection reports, IE Bulletins & correspondence
- BOO7230007 Forwards suppl info to 790525 response to IE Bulletin 78-12
 Record search in response to C-E rept, "Atypical Weld Hat!
 in Reactor Vessel Welds," produced no evidence of use of
 atypical weld math in reactor pressure vessels
 RENBERGER,D L Washington Public Power Bupply Bystem 80/03/17
 1p.
- BOO7290405 Forwards insp program committed to in 790710 response to IE Bulletin 79-03 re longitudinal weld defects in stainless steel pipe spools No evidence of longitudinal weld defects was found RENBERGER, D.L. Washington Public Power Supply Bystem BO/04/15-330p
- 8007180023 Forwards JE Insp Repts 50-508/80-05 & 50-509/80-05 on 800513-15 No noncompliance noted BOOK, H E. Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch 80/05/23 2pp

- --8007180025 IE Insp Repts 50-508/80-05 % 50-509/80-05 on 800513-15 No noncompliance noted Major areas inspected organization & administration procedures, audits & CP requirements YUHAS.0 P. WENSLAWSKI.F.A. Region 5. San Francisco, Office of the Director BOOK.H E. Region 5. San Francisco, Fuel Facility & Materials Safety Branch BO/05/28 9pp
- 8007220252 Forwards IE Info Notice 80-26, "Evaluation of Contractor OA Programs " No written response required ENGLIKEN,R H Region 5, San Francisco, Office of the Director 80/06/10 ip
- 8007300306 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks Tanks adequately protected against vacuum damage Holdup tanks equipped w/vacuum breakers Equipment drain tank designed for full vacuum w/nitrogen cover gas RENBERGER, D L. Washington Public Power Supply System 80/06/12
- 8007290090 Forwards IE Info Notice BO-28, "Prompt Reporting of Info in Accordance W/IOCFR50 95(e) " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/13 lp
- 8007020466 Forwards JE Circular BO-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/06/20 Ip
- 8007180299 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKENR H Region 5. San Francisco, Office of the Director 80/06/24 1p
- 8007230401 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ENGELKENR H Region 5. San Francisco, Office of the Director 80/06/27 1p
- 8007180329 Responds to NRC 800609 ltr re violations noted in IE inspon 800520-23 Corrective actions util has established hold point to visually inspect all accessible interior/exterior ASME Secton III spoot welds.

 RENBERGER, D L Hashington Public Power Supply System 80/07/11 4pp
- DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4
- A Application/construction stage documents & correspondence
- 8007030197 Forwards organization charts for Ofc of Nuclear Reactor Regulation effective 800428 States means of appeal of staff position TEDESCO, R L. Assistant Director for Licensing 80/06/12 2pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0674
 EIBENHUT.D @ Division of Licensing 80/06/26 2pp
- 8007210392 Ack receipt of NRC 800430 ltr approving request to discontinue certain aquatic monitoring & requesting copies of util submittals to State of WA re water quality NRC does not have authority to require water quality filings RENBERGER, D.L. Washington Public Power Supply Bystem 80/07/14
- B007250544 Forwards "Reliability Evaluation of WPPSS Nuclear Projects Numbers i & 4." in response to NRC B00124 request for evaluation of loss of main feedwater event RENBERGER, D L Washington Public Power Supply System B0/07/22 200
- ---8007250552 "Reliability Evaluation of MPP99 Nuclear Projects Numbers 1 & 4," Vol Limain rept MCBRIDE, A F , MINARICK. J W , BOZARTH. D F Science Applications, Inc 80/07/16 214pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission B00927 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D © Division of Licensing 80/06/25 89pp

Q Inspection reports, IE Bulletins & correspondence

- 8007270444 Responds to IE Bulletin 80~03, "Loss of Charcoal from Std Type II.Two-Inch, Tray Adsorber Cells " Standardized 31 5 X 23 inch.flat bed.Type II charcoal adsorber cell units used in all cleanup sys RENBERGER.D L Washington Public Power Supply System 80/03/19 2pp
- 8007220252 Forwards IE Info Notice 80-24, "Evaluation of Contractor QA Programs " No written response required ENGELKEN.R H Region 5, San Francisco, Office of the Director 80/06/10 in
- 8007300299 Forwards response to IE Bulletin 80-05 re vacuum damage to chemical control sys tamks Design changes to kow pressure process tamks not required Table describing subj tamks & protection provided encl
 RENBERGER.D 1. Washington Public Power Supply System 80/06/12
- 8007270070 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance #/10CFR50 55(e) " No written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director 80/06/13 1p
- 8007020466 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/20 ip
- 8007180299 Forwards IE Circular BO-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required. EMPELKEN.R H Region 5, San Francisco, Office of the Director 80/04/24 ip
- B007230401 Forwards IE Bulletin B0-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular B0-16 also entl No written response required ENGELKEN, R H Region 5, San Francisco, Office of the Director 80/06/27 ip
- 800729051B Responds to IE Bulletin BO-08 Problems re containment liner pentration weld do not exist at facility Design for primary piping typical of ASME cade configurations Process pipe/flued head assemblies not installed RENHERGER, D. L. Washington Public Power Supply System 80/07/10
- S Reportable occurrences, LERs & related correspondence
- 8007170577 Forwards interim deficiency rept re defective condition in design of floor supporting component cooling & makeup pump area heating ventilation & air conditioning sys Train B equipment
 BENBERGER.D.L. Washington Public Power Supply Gystem BO/07/11
- --B0071703B5 Interim deficiency rept re defective condition in floor supporting component cooling & makeup pump area Caused by usage of incorrect vertical amplified response spectra. Structural frame designed for installation

 * Washington Public Power Supply System 80/07/ii. 2pp
- DOCKET 50-514 PERBLE SPRINGS NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 8007020265 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCO.R L Assistant Director for Licensing 80/06/13, 2pp
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0640 & found in NUREG-05694 EISENHUT, D G Division of Licensing B0/06/26 2pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 9007070028 FOIA request from Atty General, State of IL, for documents re NRC decision to issue suppl to final EIB for facility HANSELL, D Illinois, State of 80/05/28 2pp

- 8007070026 Responds to Atty General, State of IL request for documents re NRC decision to issue suppl to final EIS for facilities. Forwards documents listed in App A FELTON, J H Division of Rules and Records 80/06/19 2pp
- ---8007070031 Discusses alternate site reviews on pending cases reassessment of effort & impacts involved in upgrading alternative site analysis section of FEB Provides detailed description of active cases REGAN.W H Assistant Director for Environmental Projects 78/06/08 4pp
- --B007070033 Discusses facilities alternative site reviews. Requests review of alternative site issues including comments as to deficiencies in light of Board decisions
 BALLARD.R L. Environmental Projects Branch 1. 78/07/18, 1p.
- --B007070036 Discusses facilities' alternative site analysis.
 FEB is insufficient Lists deficiencies under Pilgrim &
 Beabrook Applicant has not made explicit environ comparison
 of alternative sites investigated
 LAWRENCE, J.F. Hearing Branch 4 78/07/24 2pp
- ---B007070040 Discusses facilities' alternate site reanalysis.Lists deficiencies in FEG needing correction.Forwards appropriate methodology for conducting alternative site analysis in light of recent adjudicatory decisions.

 LAWRENCE, J.F. Hearing Branch 4. 78/08/01 2pp
- --B007070044 Discusses review of alternative wite record in light of Board decisions Recommends need to supplement precent record, indicating further explication of processes used the bases for view of relative desirability of available sites LAWRENCE, J.F. Hearing Branch 4 78/08/02 2pp.
- --B007070046 Motion for leave to supplement record re alternative sites, based on guidance found in Pilgrim decision BORDENICK.B M . LAWRENCE.J F Hearing Branch 4. 78/08/02 2pp.
- --B007070049 Forwards schedule for alternative site review for facilities. Verbal assessment of deficiencies have been provided Ltr of authorization is being drafted WATKING.D Building & Operations Branch 78/08/11 2pp.
- ---8007070050 Order approving 780802 motion for leave to supplement record as to alternative sites for facilities, YORE: J R Atomic Safety and Licensing Board Panel 78/08/17
- --B0070700B3 Forwards tentative schedule for conduct of addl alternative site assessment & NRC technical & legal questions as result of preliminary review of FEB:CP & environ rept on alternative sites Provides authorization to pruceed w/work. MODRE.V A Assistant Director for Environmental Projects 78/09/25. 5pp
- --8007070035 Responds to 780928 request Forwards info re cases consisting of or having potential of addl alternative site studies.

 MORENY A Assistant Director for Environmental Projects 78/09/28 4pp
- F Becurity, medical, emergency & fire protection plans
- 8007270825 Forwards "Evacuation Time Estimates For Gilliam & Morrow Counties. OR & Klickitat County, WA in response to 800702 request. Advises that NRC responded to 771226 request on 800404 Study found no unusual evacuation problem.

 LINDBLAD, W J Pacific Gas & Electric Co. 80/07/25 1p.
- --8007270832 Forwards "Evacuation Time Estimates for Gilliam & Morrow Gounties.OR & Klickttat County.WA per 791226 request.
 Preliminary study revealed no unusual evacuation problems.
 LIND#LAD.W J Pacific Oas & Electric Co
- ---B007290B35 "Evacuation Time Estimates For Gilliam & Morrow Counties, DR & Klickitat County, WA"

 * Parific Gas & Electric Co B0/03/31. 21pp.
- @ Adjudicatory correspondence
- B007310243 Forwards Commission B00527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables.
 EISENHUT, D 0 Division of Licensing. B0/06/25 89pp.

- 8007170201 Motion for postponement of B00723 pretrial conference re early site suitability hearing issues Suggests conference call to hear applicant objections State of OR & LK Marbet have no objection to postponement Certificate of Svc encl BDRDENICK.B M Hearing Branch 4 80/07/15 6pp
- @ Inspection reports, IE Bulletins & correspondence
- 9007220239 Forwards IE Info Notice BO-26, "Evaluation of Contractor GA Programs " No written response required ENGELKEN R H Region 5, San Francisco, Office of the Director BO/06/10 ip
- DOCKET 30-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007020265 Forwards NRC Dfc of Nuclear Reactor Regulation 800428 reorganization chart Necessary period of transition made w/min disruption to ongoing activities TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0674
 ETBERHUT, D Q Division of Licensing 80/06/26 2pp
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- B007070028 FGIA request from Atty General, State of IL. for documents re NRG decision to issue suppl to final EIS for facility.

 HANSELL,D Illinois, State of 80/05/28, 2pp.
- BOO7070026 Responds to Atty General, State of IL request for documents re NRC decision to issue suppl to final EIS for facilities Forwards documents listed in App A FELTON, J M Division of Rules and Records BO/06/19 2pp
- --B007070031 Discusses alternate site reviews on pending cases re assessment of effort & impacts involved in upgrading alternative site analysis section of FEG Provides detailed description of active cases REGAN, M H. Assistant Director for Environmental Projects 78/06/08 App
- ---B007070033 Discusses facilities alternative site reviews Requests review of alternative site issues including comments as to deficiencies in light of Board decisions.

 BALLARD.R L Environmental Projects Branch 1 78/07/18 lp.
- --8007070036 Discusses facilities' alternative site analysis FEB is insufficient.Lists deficiencies under Pilgrim & Beabrook Applicant has not made explicit environ comparison of alternative sites investigated LAWRENCE, J F Hearing Branch 4 78/07/24 2pp
- ---8007070040 Discusses facilities' alternate site reanalysis Lists deficiencies in FEB needing correction. Forwards appropriate methodology for conducting alternative site analysis in light of recent adjudicatory decisions LAMRENCE, J.F. Hearing Branch 4 78/08/01 2pg
- --BO07070044 Discusses review of alternative site record in light of Board decisions Recommends need to supplement present record, indicating further explication of processes used & bases for view of relative desirability of available sites LAHRENCE, J.F. Hearing Branch 4 78/08/02 2pp
- --BO07070046 Motion for leave to supplement record re alternative sites, based on guidance found in Pilgrim decision BORDENICK, B M . LAWRENCE, J F Hearing Branch 4 78/08/02 2pp
- --B007070049 Forwards schedule for alternative site review for facilities Verbal assessment of deficiencies have been provided Ltr of authorization is being drafted HATKINB, D. Building & Operations Branch 78/08/11 2pp
- ---BOO7070050 Order approving 780802 motion for leave to supplement record as to alternative sites for facilities YORE, J.R. Atomic Safety and Licensing Board Panel 78/08/17
- --B007070053 Forwards tentative schedule for conduct of add1 alternative site assessment & NRC technical & legal questions as result of preliminary review of PES, CP & environ rept on alternative sites Provides authorization to proceed w/work MODRE, V A Assistant Director for Environmental Projects 78/09/25. Spp

- ----8007070055 Responds to 78092B request Forwards info re cases consisting of or having potential of addl alternative site studies MODRE, V A Assistant Director for Environmental Projects 78/09/2B 49p
- F Security, medical, emergency & fire protection plans
- 8007270825 Forwards "Evacuation Time Estimates For Gilliam & Morrow Counties.OR & Klickitat County.WA in response to 800702 request Advises that NRC responded to 791226 request on 800404 Study found no unusual evacuation problem LINDBLAD.W J. Pacific Gas & Electric Co. 80/07/25 1p
- --8007290832 Forwards "Evacuation Time Estimates for Gilliam & Morrow Counties.OR & Klickitat County.WA per 791226 request Preliminary study revealed no unusual evacuation problems LINDBLAD.W J Pacific Gas & Electric Co 80/04/04 1p
- --B007290835 "Evacuation Time Estimates For Cilliam & Morrow Counties.OR & Klickitat County, MA"

 * Pacific Gas & Electric Co 80/03/31 21pp
- @ Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 potation for reconsideration of 780413 memorandum & order UCS 771104 potition sought action refire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- 8007170201 Motion for postponement of 800723 pretrial conference re early site suitability hearing issues Suggests conference call to hear applicant objections State of OR & LK Marbet have no objection to postponement Certificate of Svc encl BORDENICK, B M Hearing Branch 4 80/07/15 App
- O Inspection reports. IE Bulletins & correspondence
- BOO7220239 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required ENGELKEN.A H Region 5. San Francisco, Office of the Director 80/06/10 ip
- DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0560 & found in NUREG-0594 ETBENHUT,D G Division of Licensing 80/06/26 2pp
- H General correspondence
- 8007180042 Responds to 800123 ltr ve NRC approach to emergency planning around nuclear plants Commission endorsed NUREG-0396 for development of state t local radiological plans Exact configuration of zones will be decided during plant review DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/03 2pp
- --8007180047 Requests that NRC amend proposed regulation re formulation of evacuation plan to include all territory east of facility Proposed 10-mile radius is unworkable for people of Long Island Responsible plan should be developed BEHAN,J L New York, State of 80/01/23 ip
- Q Inspection reports, 16 Bulleties & correspondence
- 8007010280 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency , Feedwater Pumps " No written response required GRIER.B H Region i. Philadelphia. Office of the Director 80/05/29 ip
- 8007010066 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "Engineering activities have been curtailed to point where detail design data requested as unavailable PLASKON, R E Long Island Lighting Co 80/06/05 ip
- 8007210571 Porwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs " No written response required GRIER, B # Region i. Philadelphia, Office of the Director 80/04/10 1p

- 8007160401 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant fump Stude " No specific action or response required GRIER, B H Region i, Philadelphia, Office of the Director 80/86/11 ip
- 8007280594 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required ORIER.8 H Region 1. Philadelphia. Office of the Director BO/06/13 ip
- 8007020509 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER, N H Region 1. Philadelphia. Office of the Director 80/06/20 ip
- 8007140704 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER. B H Region I. Philadelphia, Office of the Director 90.04.23 in
- 8007210199 Forwards JE Info Notice 80-24, "Low Level Radwaste Burial Criteria " No written response required GRIER.B H Region I, Philadelphia, Office of the Director. 80/06/25 ip
- 8007230128 Forwards IE Bulletin HO-i6, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER,B H Region i. Philadelphia. Office of the Director 80/06/27 2pp
- 80072:0515 Responds to IE Bulletin 90-08 re containment liner penetration weld examinations Penetrations will be fabricated per Reg Guide 1 19 Butt welds will be radiographed PLASKON-R E Long Island Lighting Co 80/07/01 2pp
- DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D. G. Division of Licensing 80/06/26 2pp
- H General correspondence
- 8007180042 Responds to 800123 ltr re NRC approach to emergency planning around nuclear plants Commission endorsed NUREO-0395 for devalopment of state & local real-ological plans Exact configuration of zones will be decided during plant review DENTON, H R Office of Nuclear Reactor Regulation, Director 80/06/03 2pp
- --BOO71B0047 Requests that NRC amend proposed regulation re formulation of evacuation plan to include all territory east of facility Proposed (O-mile radius is unworkable for people of Long Island Responsible plan should be developed BEHAN.JL New York. State of 80/01/23 19
- G Inspection reports. IE Bulletins & correspondence
- 8007010280 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required ORIER.B H Region 3. Philadelphia, Office of the Director 80/05/29 1p
- G007010066 Responds to IE Bulletin 60-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks "
 Engineering activities have been curtailed to joint where detail design data requested is unavailable PLASKON.R E Long Island Lighting Co 80/06/05 ip
- 8007210571 Forwards TE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required GRIER.D H Region 1, Philadelphia. Office of the Director 80/06/10 ip
- 8007140401 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs " No specific action or response required GRIER.B H Region I, Philadelphia, Diffice of the Director 80/06/11 Ip

- 8007280594 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance M/10CFR50 35(e)" No written response required GRIER. II H Region 1. Philadelphia. Office of the Director 80/06/13 1p
- 8007020509 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required GRIER. H H Region 1, Philadelphia, Office of the Director BO/06/20 ip
- 8007160704 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel "No written response required CRIER, II H Region 1, Philadelphia. Office of the Director 80/06/24 1p
- 8007210199 Forwards IE Info Notice 80-24. "Low Level Radwaste Burial Criteria" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director. 80708723 1p
- 8007230128 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters H/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/27 2pp
- 8007210515 Responds to IE Bulletin 80-08 re containment liner penetration weld examinations Penetrations will be fabricated per Reg Guide 1 19 Butt welds will be radiographed PLABKON.R E Long Island Lighting Co 80/07/01 2pp
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage decuments & correspondence
- 8007020252 Forwards NRC Ofc of Nuclear Reactor Regulation B00428 reorganization chart Mecessary period of transition made w/min disruption to ongoing activities
 TEDESCOR L Assistant Director for Licensing 80/06/13 2pp
- 800701033B Forwards "Socioeconomic Monitoring & Mitigation Rept." Continuing info will be provided on semiannual basis MILLS, L M Tennessee Valley Authority 80/06/25 ip.
- --8007010350 "Socieeconomic Monitoring & Mitigation Rept," data as of 790930
 - * Tennessee Valley Authority 80/05/31 52pp.
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D G Division of Licensing 80/06/26 2pp
- O Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D & Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007110570 Responds to encl 800506 ltr addressed to President Carter 14 safety measures being taken to protect citizens of TN Faccility is subj. to stringent const controls Radiation exposure will be kept to as low as reasonably achievable TEDESCO.R.L. Assistant Director for Licensing 80/06/26 2pp
- Q. Inspection reports. JE Bulletins & correspondence
- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit i While in Refueling Mode " No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
- 8007140479 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/12

- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/29
- 6007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required U'RCILLY, J P Region 2, Atlanta, Office of the Dijector 80/06/10
- B007140301 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Distharge Vol Capability " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/0
- 8007230384 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/100FR50 55(a)," No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/13
- B007020499 Forwards response to IE Bulletin 80-09 transmitted by JP O'Reilly 800417 itr Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLB, L M Tennessee Vailey Authority B0/06/16 2pp
- 8007300589 Forwards IE Insp Repts 50-518/80-10, 50-519/80-10, 50-520/80-10 & 50-521/80-10 on B00428-0930 No noncompliance
 - MARPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/06/17 2pp Bupport Branch
- ---B007300594 IE Insp Repts 50-518/80-10, 50-519/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No nuncompliance note: Major areas inspected earth compaction structural concrete & ereak anyperter team compared to the previous insp findings CANTRELL.F. 8 Region 2. Atlanta. Reactor Construction & Engineering Support Branch SWAN.W B Region 2. Atlanta. Office of the Director 80/06/17 App
- 8007020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- B007170070 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Damineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P. Region 2. Atlanta, Office of the Director B0/06/2 BO704724
- 8007230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Rither A or D Dutput Codes " Written response required IE Circular 80-16 also enci No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/06/3 90/06/27
- 8007R20R36 Responds to IE Bulletin 79-28, "Possible Malfonction of NAMCO Model EA180 Limit Switches at Elevated Temps "
 Investigations show no NAMCO EA180 switches are installed or planned for installation.
 MILLB.L M Tennessee Valley Authority 80/07/01 1p
- 8007280615 Responds to IE Bulletin 80-98. "Examination of Containment Penetration Wolds "Results of investigation encl MILLB.L M Tennessee Valley Authority 80/07/97 5pp
- 8007240265 Ack receipt of B00624 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-08, 50-519/80-08, 50-520/80-08 to 50-521/80-08 MRPHY,C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/07/08 ip
- ~~8007240279 Responds to NRC 800330 ltr re violations noted in IE Insp Repts 50-518/80-08, 50-519/80-08, 50-520/80-08 & 30-521/80-08 Corrective actions temp & humidity monitoring equipment unsite & ready for installation on next vessel MILLS,L M Tennessee Vallay Authority 80/06/24 4pp
- --8007240293 Forwards IE Insp Repts 50-518/80-08, 50-519/80-08, 30-520/80-08 & 50-521/80-08 on 800331-0425 & notice of violation MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/30 Rpp
- --B007240305 Notice of violation from insp on 800331-0425
 * Region 2, Atlanta, Office of the Director 80/05/ 80/05/30 1a

- ~8007240329 IE lnsp Repts 50-518/80-08.50-519/80-08.50-520/80-08 & 50-521/80-08 on 800331-0425 Noncompliance noted reactor pressure vessel stored in dusty area CONTRELL.F S Region 2. Atlanta. Reactor Construction & Engineering Support Branch SMAN.W B Region 2. Atlanta, Office of the Director 80/05/30 App Region 2, Atlanta, Office
- S Reportable occurrences. LERs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in faculities Detailed info will be provided to assist determination of significant safety hozard OIROUX, E. J. Carrier Corp. Carrier Air Conditioning Div. 80/06/17
- 8006250275 Forwards final deficiency rept re incorrect root face on MOSTORY Coderld sleaves MILLS, L. M. Tennessee Valley Authority 80/06/19 ip
- 8007170247 Part 21 rept of potentially defective Rosemount, Inc transmitter in control sys of air conditioning units Info is provided to absist in determination of significance as safety hazard Carrier Corp Carrier Air Conditioning Div 80/05/20
- B007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before 800917 MILLS.1 M Tennessee Valley Authority 80/07/02 ip
- --8007110328 First interim deficioncy rept on Rosemount Model 1152 pressure transmitter defects During testing. GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennessee Valley Authority 80/07/02 ip
- 8007140349 Forwards second interim defactency rept re cracks in reactor pressure vessel shirld wall Final rept to be submitted before 801003 Will provide addl info re repair of shield wall & corrective actions
 MILLS, L M Tennessee Valley Authority 80/07/03 ip
- --8007140353 Second interim deficiency meptine cracks in reactor pressure vessel shield wall Discovered base metal cracks in shield wall inner shell plates Evaluation revealed crack initiated at the of tack well bead of backing strip
 * Tennessee Valley Authority 80/07/03 2pp
- 8007230528 Final deficiency rept re omitted heaters from Reliance Electric Co motor operator Deficient motor will be replaced by B01130 9E will review vendor QA program to assure proper Alementation LS,L H Tennessee Valley Authority 80/07/18 2pp
- B007290734 Final Deficiency Rept 4 re deficient welds found on anchor bolt chair & containment shell & base plato Caused by QA/QC imapectors not allowing welds to pass inso Task force & retraining & recertification program initiated # Tennessee Valley Authority B0/07/24 3pp
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B007020252 Forwards NRC Ofc of Nuclear Reactor Regulation 800428 reorganization chart Mecessary period of transition made w/min disruption to ongoing activities
 TEDEBCO.R L. Assistant Director For Licensing 80/06/13 2pp
- B007010338 Forwards "Socioeconomic Monitoring & Mitigation Rept " Continuing info will be provided on semiannual basis MILLS.L M Tennessee Valley Authority B0/06/25 ip
- --8007010350 "Socioeconomic Monitoring & Mitigation Rept." data as of Tennessee Valley Authority 80/05/31 52ps
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D G Division of Licensing 80/06/26 2pp

9 Adjudicatory_correspondence

BOD7310243 Forwards Commission BOO527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 potition sought action re fire protection for electrical cables
EISENHUT,D G Division of Licensing BO/06/25 89pp

- BOD7:10970 Resounds to encl 800506 ltr addressed to President Carter re safety measures being taken to protect citizens of TN Facility is subj to stringent const controls Radiation exposure will be kept to as low as reasonably achievable TEDESCO,R L Assistant Director for Licensing 80/06/2 80/06/26
- @ Inspection reports, IE Bulletins & correspondence
- B007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required D'REILLY, J P Region Region 2, Atlanta. Office of the Director 80/05/08
- 8007140479 Forwards IE Bulletin 80-13, "Cracking in Core Spray Bpargers " No written response required O'REILLY-J P Region 2, Atlanta, Dffice of the Director 80/05/12
- 8007010225 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required D'REILLY,J P Region 2. Atlanta. Office of the Director 80/05/27
- 8007220029 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required G*REILLY, J P Region 2, Atlanta. Office of the Director 80/06/10
- 8007140301 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required Q'REILLY.J P Region 2, Atlanta, Office of the Director 80/6
- 8007250384 Forwards IE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 80/06/13
- B007020499 Forwards response to IE Bulletin 80-09 transmitted by JP D'Reilly 800417 itr Final rept for Hartsville & Phipps Bend glants will be sent on or before 801017 MILLS, L.M. Tennessee Valley Authority 80/06/16 2pp
- B007300589 Forwards IE Insp Repts 50-518/80-10,50-819/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance notes MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 89/06/17 2pp
- --8007300594 1E Insp Repts 50-518/80-10,50-519/80-10,50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance noted Hajor areas inspected earth compaction structural concrete & areas inspected earth compatition structural continuous a previous insp findings
 CANTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch SHAN. H B Region 2. Atlanta, Office of the Director 80/06/17 6pp
- B007020391 Forwards IE Circular B0-15. "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown" No written response required 0'REILLY.J P Region 2: Atlanta, Office of the Director 80/06/20.
- B007170070 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demaneralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director B0/06/2 80/06/24.
- 8007230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J F Region 2, Atlanta, Office of the Director 80/06/ 80/06/27.

- 8007220234 Responds to 1E Bulletin 79-28, "Possible Malfunction of UNIVERSITY OF THE BUILTING THE PROPERTY OF THE STATE OF T
- 8007280615 Responds to IE Bulletin 80-08, "Examination of Containment Penetration Wolds " Results of investigation encl MILLS,L M Tennessee Valley Authority 80/07/07 5pp
- 8007240265 Ack receipt of 800624 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-518/80-08, 30-519/80-08, 30-520/80-08 & 50-521/80-08 MMRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/07/08 ip
- --B007240279 Responds to NRC 800530 ltr re violations noted in IE Insp. Repts 50-518/80-08, 50-519/80-08, 50-520/80-08 & 50-521/80-08 Corrective actions temp & humidity monitoring equipment onsite & ready for installation on next vessel Tennessee Valley Authority 80/06/24 Ann MILLE, L M
- --8007240293 Forwards IE Insp Repts 50-518/80-08, 50-519/80-08, 50-520/80-08 & 50-521/80-08 on 600331-0425 & notice of violation MURPHY/C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/05/30 2рр
- --B007240305 Notice of violation from insp on B00331-0425 * Region 2. Atlanta. Office of the Director B0/05/
- --B007240327 IE Insp Repts 50-518/80-0B, 50-519/80-0B, 50-520/80-0B & 50-521/B0-0B on 800331-0425 Nancompliance noted reactor pressure vessel stored in dusty area CONTRELL.F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch SMAN.H B Region 2, Atlanta, Office of the Director 80/05/30 App
- S Reportable occurrences, LERs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in facilities Detailed info will be provided to assist determination of significant safety hazard gIROUX.E J Carrier Corp Carrier Air Conditioning Div 80/06/17
- 8007170247 Part 21 rept of potentially defective Rosemount.Inc transmitter in control sys of air conditioning units.Info is provided to assist in determination of significance as safety hazard Carrier Corp Carrier Air Conditioning Div 80/04/20
- B007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before B00917 MILLS,L M Tennessee Valley Authority 80/07/02 ip
- --8007i10328 First interim deficiency rept on Rosemount Model 1:52 pressure transmitter defects During testing, GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennessee Valley Authority 80/07/02 1p
- 8007290734 Final Deficiency Rept 4 re deficient welds found on anchor bolt chair & containment shell & base plate Caused by GA/GC inspectors not allowing welds to pass insp Task force & retraining & receptification program initiated # Tennessee Valley Authority 80/07/24 3pp
- DOCKET SYN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- A Application/construction stace documents & correspondence
- 8007020252 Forwards NRC Ofc of Nuclear Reactor Regulation 800426 reorganization chart Necessary period of transition made w/min disruption to ongoing activities TEDESCO.R L Assistant Director for Licensing 80/06/13 2pp
- 8007010338 Forwards "Socioeconomic Monitoring & Mitigation Rept " Continuing info will be provided on semiannual basis MILLS.L M. Tennessee Valley Authority 80/06/25 ip
- --- 8007010350 "Socioeronemic Monitoring & Mitigation Rept." data as of
 - Tennessee Valley Authority 80/05/31, 52pp

6007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NAREG-0694 EISEMANT, D O Division of Licensing 80/08/26 2pp

Asjudicatory correspondence

BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 potition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action as five protection for electrical cables EISENHUT; D Q Division of Licensing 80/06/25 89pp

H General correspondence

BOO7110370 Responds to enci 800506 itr addressed to President Carter re safety measures being taken to protect citizens of TN Facility is subj to stringent const controls Radiation asposure will be kept to as low as reasonably achievable TEDESCO.R L. Assistant Director for Licensing 80/06/26 2pp

& Imagection reports, IE Bulletins & correspondence

- 8007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode "No response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/08
- B007140479 Forwards IE Bulletin 80-13. "Cracking in Core Spray Beargers " No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/05/12
- 6007010225 Forwards IE Info Notice 80-23. "Loss of Buction to Emergency Foedwater Pumps " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/29
- 8007220027 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director. 80/06/10
- 6007140301 Forwards IE Bulletin 80-14, "Degradation of BMR Scram Discharge Vol Capability " No written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director 80/06/12
- BQ07230384 Forwards IE Info Notice 80-28, "Frompt Reporting of Info in Accordance W/10CFR30 05(e)" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/13
- B007020499 Forwards response to IE Bulletin 80-09 transmitted by JP O'fheilly 800417 itr Final rept for Hartsville & Phipps Bend plants will be sent on or before B01017 MILLS-L M Tennessee Valley Authority 80/06/16 2pp
- 8007300589 Forwards IE Insp Repts 50-518/80-10, 50-519/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance moted.

 MRPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering

 Bupport Branch 80/06/17 2pp
- --8007300594 IE Insp Repts 50-518/80-10, 50-519/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance noted Major areas inspected earth compaction, structural concrete & areas inspected earth compaction structure; control a previous insp findings CANTRELL,F B Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch BHAN,W B Region 2, Atlanta, Office of the Director 80/06/17 App
- 8007020391 Forwards IE Circular 80-15, Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- BO07170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24

- 8007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inr Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also entil No written response required O'REILLY, J.P. Region 2, Atlanta. Office of the Director 80/06/2 80/06/27
- 8007220236 Responds to JE Bulletin 79-26. "Possible Malfunction of NAMCO Model EAIBO Limit Switches at Elevated Temps " Investigations show no NAMCO EAIBO switches are installed or planned for installation MILLS, L M Tennessee Valley Authority 80/07/01 1p
- 8007280615 Responds to 1E Bulletin BO-08, "Examination of Containment Penetration Welds " Results of investigation encl MILLS.L M Tennessee Valley Authority 80/07/07 5pp
- 8007240265 Ack receipt of 800624 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-518/80-08, 50-519/80-08, 50-527/80-08 \$ 50-521/80-08 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Bupport Branch 80/07/08 1p
- --B007240279 Responds to NRC 800530 ltr re violations noted in IE Insp Repts 50-518/80-08,50-519/80-08,50-520/80-08 & 50-521/80-08 Corrective actions temp & humidity monitoring equipment ansite & ready for installation on next vessel MILLS.L M Tonnessee Valley Authority 80/06/24 App
- --B007240293 Forwards IE Insp Repts 50-518/80-08, 50-519/80-08, 50-520/80-08 & 50-521/80-09 on 800331-0425 & notice of violation violation MURPHY.C E Region 2, Atlanta Reactor Construction & Engineering Support Branch BO/05/30 2pp
- -8007240305 Notice of viglation from insp on 800331-0425 * Region 2. Atlanta, Office of the Director 80/05/ 80/05/30
- --8007240327 It Insp Repts 50-518/80-08,50-519/80-08,50-520/80-08 & 10/24/0327 It they hepts 50-518/180-08.50-517/80-08.50-52/78 50-52/180-08 on 800331-0425 Noncompliance noted reactor pressure vossel stored in dusty area CONTRELL.F S Region 2. Atlanta, Reactor Construction & Engineering Support Branch SWAN, W B Region 2. Atlanta of the Director 80/09/30 App Region 2, Atlanta, Office
- 8 Reportable occurrences, LERs & related correspondence
- 6007170236 Part 21 rept re potential defect in air conditioning units in facilities Detailed safe will be provided to assist determination of significant safety hazard QIRDUX.E J Carrier Corp Carrier Air Conditioning Div 80/06/17
- 8007170247 Part 21 rept of potentially defective Rusemount. Inc transmitter in control sys of air conditioning units Info is provided to assist in determination of significance as safety hazard QIRDUX.E.J. Carrier Corp. Carrier Air Conditioning Div. 80. Carrier Corp Carrier Air Conditioning Div 80/06/20
- G007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 600403 Final rept will be submitted on or before 800917 MILLS, L.M. Tennessee Valley Authority 80/07/02 ip
- ~-B00711032B First interim deficiency rept on Rosemount Model 1182 pressure transmitter defects During testing GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennessee Valley Authority 90/07/02 ip
- DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8007020252 Forwards NRC Ofc of Nuclear Reactor Repulation 800428 rearganization chart Necessary period of transition made w/min disruption to ongoing activities
 TEDESCORL Assistant Director for Licensing 80/06/13 2pp
- 8007010339 Forwards "Sectoeconomic Monitoring & Mitigation Rept " Continuing info will be provided on semiannual basis MILLS.L M Tennessee Valley Authority 80/06/25 ip
- --8007010350 "Socioeconomic Monitoring & Nitigation Rept." data as of
 - Tennessee Valley Authority 80/05/31 52pp

B007230601 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
EISENHUT, D 0 Division of Licensing 80/06/26 2pp

Adjudicatory correspondence

8007310243 Forwards Commission B00527 memorandum & order containing docisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D 0 Division of Licensing 80/06/25 89pp

H General correspondence

B007110570 Responds to encl 800505 ltr addressed to President Carter re safety measures being taken to protect citizons of TN Facility is subj to stringent const controls Radiation exposure will be kept to as low as reasonably achievable TEDESCO.R L Assistant Director for Licensing 80/05/26 2pp

O Inspection reports. IE Bulletins & carrespondence

- B007240089 Forwards IE Info Notice B0-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode"
 No response required
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/05/08
 Sno
- 8007140479 Forwards IE Dulletin 80-13, "Cracking in Core Spray Spargers " No written rosponse required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/12 ig
- 8007010225 Forwards JE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required O'REILLY,, P Region 2. Atlanta. Office of the Director 80/05/29 is
- B007R20029 Forwards IE lafo Notice 80-26, "Evaluation of Contractor GA Programs " No written response required O'REILLY, J P. Region 2, Atlanta, Office of the Director B0/04/10 Jon
- 8007140301 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/12
- 9007250384 Forwards IC Info Notice 80~28, "Prompt Reporting of Info in Accordance W/IOCFR50 55(e) " No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director BO/06/13 Jpp
- 8007020499 Forwards response to IE Bulletin 80-09 transmitted by JF D'Reilly 800417 Itr Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLS, L. H. Tennessee Valley Authority 80/06/14 2pp
- 8007300589 Forwards 1E Insp Repts 50-518/80-10,50-519/80-10, 50-520/80-10 & 50-521/80-10 on 800428-0530 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/17 2pp
- --8007300594 IE Insp Repts 50-518/80-10,50-519/80-10,50-520/80-10 & 50-521/80-10 on 800428-0330 No noncompliance noted Major areas inspected earth compaction, structural concrete & previous insp findings CANTRELL, F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/17 App
- B007020391 Forwards IE Circular 80-18, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director B0/06/20
- 8007170070 Forwards IE Circular 80-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24

- 8007230253 Forwards IE Bulletin 80-16. "Potential Misopplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Dutput Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/27
- 8007220234 Responds to IE Bulletin 79-28, "Passible Malfunction of NAMCO Model EA180 Limit Switches at Elevated Temps" Investigations show no NAMCO EA180 switches are installed or planned for installation MILLS-L M Tennessee Valley Authority 80/07/01 ip
- 8007280615 Responds to IE Bulletin 80-08, "Examination of Containment Penatration Welds " Results of investigation and MILLS-L M Tennessee Valley Authority 80/07/07 5pp
- 8007240265 Ack receipt of 800624 ltr informing MRC of steps taken to correct violations noted in IE lnmp Repts 50-518/80-08, 50-519/80-08. 50-520/80-80 & 50-521/80-08 MNRPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --8007240279 Responds to NRC 800530 ltr re violations noted in IE Insp Repts 50-518/80-08,50-519/80-08,50-520/80-08 & 50-521/80-08 Corrective actions temp & humidity monitoring equipment onsite & ready for installation on next vessel HILLS.L M Tennessee Valley Authority 80/06/24 App
- --8007240293 Forwards IE Insp Repts 50-518/80-08,50-519/80-08, 50-520/80-08 & 50-521/80-08 on 800331-0425 & notice of violation MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 80/05/30 2pp
- --8007240305 Notice of violation from insp on 800331-0425, * Region 2. Atlanta, Office of the Director 80/05/30. 1p
- --B007240327 IE Insp Repts 50-518/B0-08,50-519/B0-08,50-520/B0-08 & 50-521/B0-08 on B00331-0425 Noncompliance noted reactor pressure vessel stored in dusty area CANTRELL,F S Region 2, Atlanta, Reactor Construction & Engineering Support Branch G0/05/30 App
- B Reportable occurrences, LERs & related correspondence
- 8007170234 Part 21 rept re potential defect in air conditioning units in facilities Detailed info will be provided to assist determination of significant safety hazard GIRDUX.E J Carrier Corp Carrier Air Conditioning Div 80/06/17 3pp
- 8007170247 Part 21 rept of potentially defective Rosemount, Inc transmitter in control sys of air conditioning units Info is provided to assist in determination of significance as safety hazard OIROUX, E.J. Carrier Corp. Carrier Air Conditioning Div. 80/06/20. 27pp
- 8007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603. Final rept will be submitted on or before 800917 MILLS, L. M. Tennessee Valley Authority 80/07/02 ip
- ---800711032B First interim deficiency rept on Rosemount Model 1152 pressure transmitter defects During testing, 9E found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway # Tennessee Valley Authority 80/07/02 ip
- DOCKET BIN-50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8007030305 Comments on proposed rules 10CFR30 & 51 w/Swinomish Tribal Community endurses position for Full consideration of Class 9 accidents Urges consideration of Class 9 accident in Skagit proceedings W/Certificate of Svc OENDLER; M W Skagitonians Concerned About Nuclear Power MEANS, D, 8 Affiliation Unknown 80/06/17 App
- B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EJSENHUT.D G Division of Licensing B0/06/26 2pp

- 8007150737 Informs NRC that four private utils have formed wholly-owned ehgineering & comst company to perform engineering.licensing & comst syss for major generating projects Company will be activated on 800715 Press release encl FERQUEEN, N J Affiliation Unknown 80/07/08 4pp
- O. Adjudicatory correspondence
- 9007010257 Forwards ABLB 800306 memorandum summarizing hearing status & FT Thomson 800414 1tr to ABLB indicating site change possibility W/o encl BANKSON.D T Hearing Branch 1 80/04/16 ip
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISEMAUT.D © Division of Licensing 80/06/25 89pp
- 8007100171 Bubmits third status rept concerning progress made in remolving USOS/NRC BOO306 requests for add1 info re geology/ seismology of plant site Requests for add1 info remain unchanged due to incomplete rept THOMSEN,F T. Perkins, Coie, Stone, Olsen & Williams BO/96/27
- 8007010330 Advises of no development re NRC or US9S review of application. NRC is unable to predict date for rescheduling hearings BLACK, R. L. Hearing Branch 1 80/06/30. 1p
- 8007300372 Forwards notice of withdrawal of counsel RM Sandvik & appearance of FW Ostrander as counsel for State of OR SAMOVIK.R.M Oregon, State of 80/07/03 ip.
- Byc enci. OSTRANDER,F W Gregon, State of 80/07/03 3pp
- B007110042 Schedule setting 800731 for applicants & NRC to submit repts in response to ABLB 800304 order, Paragraph 14 C Applicants must indicate intention to change site & NRC must explain status of response to applicants' 800215 submittal DEALE, V. B. Atomic Safety and Licensing Board Panel 80/07/08 is
- 8007230797 Motion for order evidencing current status & setting schedule for further proceeding Amend to application will be filed by 800930 Anticipated schedule for environ rept & PBAR amends may be filed on same date Wdraft order & release. THOMSEN, F. T. Portland General Electric Co THOMSEN, F. T. Perkins. Cale. 3 None. Clasen & Williams 80/07/16 7pp.
- 8007250351 Forwards 800216 certificate of svc inadvertently omitted from 800716 correspondence THOMSEN, F. T. Perkins, Cole, Stone, Olsen & Williams 80/07/17
- Q Inspection reports, IE Bulletins & correspondence
- 8007220244 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs "No written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 80/06/10, 1p.
- 8007140418 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability," No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/12 ip.
- DOCKET STN-50-523 SKAGIT NUCLEAR POWER PROJECT: UNIT 2
- A Application/construction stage documents & correspondence
- 8007030303 Comments on proposed rules 10CFR50 & 51 m/Swinomish Tribel Community endorses position for full consideration of Class 9 accidents Urges consideration of Class 9 accident in Skagit proceedings. M/Certificate of Svc CENDLER, M. W. Skagitonians Concerned About Nuclear Power. 80/05/17
- 9007230001 Forwards statement of policy re requirements to be met for current OL applications as derived from NUREG-0660 & found in NUREG-0694 EISEMANT, D G Division of Licensing 80/06/26 2pp

- 8007150737 Informs NRC that four private other have formed wholly-numed engineering & const company to perform engineering. Licensing & const sycs for major generating projects Company will be activated on 800715 Press release encl
 FERGUSON, W.J. Affiliation Unknown 80/07/08 4pp
- G Adjudicatory correspondence
- 8007010257 Forwards ASLB 800306 memorandum summarizing hearing status & FT Thomsen 800414 ltr to ASLB indicating site change possibility W/o encl SWANSON.D T Hearing Branch 1 80/04/16 ip
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D O Division of Licensing 80/04/25 89pp
- 8007100171 Submits third status rept concerning progress made in resolving USGS/NRC 800306 requests for addl info re geology/ seismology of plant site Requests for addl info remain unchanged due to incomplete rept THOMSEN.F T Perkins, Cole. Stone, Olsen & Williams 80/06/27
- 8007010330 Advises of no development re NRC or USGS raview of application NRC is unable to predict date for rescheduling hearings BLACK, R.L. Hearing Branch ! 80/06/30 Ip
- 8007300372 Forwards notice of withdrawal of counsel RM Sandvik & appearance of FW Ostrander as counsel for State of CR SANDVIK.R M Gregon, State of 80/07/03 ip
- --8007300377 Notice of withdrawal of counsel RM Sandvik & appearance of FW Ostrander as counsel for State of OR Certificate of Syc encl OSTRANDER, F W Oregon, State of 80/07/03 3pp
- 8007110042 Schedule setting 800731 for applicants & NRC to submit repts in response to ASLB 800306 order.Paragraph 14 C Applicants must indicate intention to change site & NRC must explain status of response to applicants 800215 submittal DEALE.V.B Atomic Safety and Licensing Board Panel 80/07/OB 1p
- 8007230797 Motion for order evidencing current status & setting schedule for further proceeding Amend to application will be filed by 800930 Anticipated schedule for environ rept & PSAR amends may be filed on same date H/draft order & release THOMSEN.F T Portland Openeral Electric Co THOMSEN.F T Parkins. Goie. Stone. Olsen & Williams 80/07/16 7pp
- 8007250351 Forwards 800214 certificate of sys imadvertently omitted from 800714 correspondence THOMSEN, FT Perkins, Coie, Stone, Olsen & Williams 80/07/17
- G Inspection reports, 18 Bulletins & correspondence
- B007220244 Forwards IE Info Notice B0-26. "Evaluation of Contractor GA Programs " No written response required ENGELMEN.R H Region 5. San Francisco. Office of the Director B0/06/10 1p
- 8007140418 Forwards IE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " Ne written response required ENGELKEN.R H Region 5, San Francisco. Office of the Director BO/06/12 ip
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8007210237 Bummary of 800311 meeting w/utfl in Bethesda.MD re review plans for OL applications LICITRA.E.A Light Water Reactors Branch 3 80/04/25 4pp
- 8007010850 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 800428 Considerations re activities whould be made through assigned mpt representatives Areas of disagreement may be discussed through informal appeal TEDESCO, R. L. Assistant Director for Licensing 80/06/13 2pp

- 8007020209 Ack receipt & docketing of 791001 joint application for OLs Forwards list of incomplete sections following preliminary review of FBAR & environ rept Discusses licensing procedures & importance of timely communication EISENHUT.D G Division of Licensing 80/06/16 7pp
- 8007020196 Notification of 800709-10 meeting w/util in Bethesda,MD to discuss ac power us KERRIGAN,J Licensing Branch 2 80/06/20 2pp
- 8007230001 Forwards statement of policy re requirements to be mpt for current OL applications, as derived from NUREO-0660 & found in NUREO-0674
 EISENHUI.D & Division of Licensing 80/06/26 2pp
- 8007080227 Requests authorization under CPPR-141.CPPR-142 & CPPR-143 to use ASME Code Cases N-274, alternative rules for examination of weld repairs & N-275, repair of welds
 VAN BRUNTLE E Arizona Public Service Co 80/06/27 ip
- 8007090285 Forwards Bechtel Power Corp & util responses to open items of Class IE dc power sys review Responses have been submitted to review board & final resolution will be submitted to NRC when completed VAN IRUNT. E E Arizona Public Service Co 80/06/30 10pp
- 8007110398 Forwards proofs of svc for applicant FSAR.OL application. general info & environ rept.required by NRC 800618 ltr VAN BRUNT.E E Arizona Public Servico Co 80/07/01 8pp

O Adjudicatory correspondence

- 8007020680 Forwards 800519 ltr.FR notice & Director's decision under iOCFR2 206 denying Friends of the Earth 771024 petition to require supplemental environ statements on Class 9 accidents at facilities
 DENTON.H R Office of Nuclear Reactor Regulation, Director B0/06/19 2pp
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- 8007170539 Forwards 800702 FR notice re opportunity for hearing on application for OLs SCHMENCER. A Operating Reactors Branch 3 80/07/02 3pp
- --B007170542 Notice of receipt of application for facility Districts of availability of applicant environ reptinotice of consideration of issuance of facility DLs & notice of opportunity for hearing Newspaper notice encl SCHMENCER.A Licensing Grench 3 B0/07/02 10pp
- 8007110002 Order greating extension until 800722 for Commission to elect to review decision on enforcement action request. DD-80-22 HOYLE,J C Office of the Secretary of the Commission 80/07/08
- B007300105 Notices of appearance in proceeding Certificate of Bvc encl GEHR.A C . BISCHOFF.C A Arizona Public Service Cu B0/07/23 3pp

- S007110526 Responds to 800407 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area, spent fuel pool, shipping cask area & fuel pool cooling & cleanup sys Detailed description may be found in FSAR, Section 9 1 SCHWENCER, A Licensing Branch 2 80/06/26 App
- 8007210018 Advises that accepted version of application for OLs for facilities is being forwarded Listed previously submitted 3-ring binders may be discarded SOUDER, J L Division of Rules and Records, 80/07/07 ip
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8007280585 Notifies that FBAR & environ rept complete & no further action required Forwards revised & now pages to be incorporated in next FBAR amend & environ rept suppl VAN BRUNT.E E Arizona Public Service Co 80/07/23 ip.
- --B0072B0390 "Addl Info for Amend 2 to FSAR," re geology, seismology & geotechnical engineering of structural design. & integrity of reactor coolant pressure boundary Preliminary version "
 * Arizona Public Service Co 80/07/23 19pp

- ---B0072B0598 "Addl Info for Suppl 1 to Environ Rept," re need for power, geography & demography. & applicant preoperational environ programs Proliminary version * Arizona Public Service Co 80/07/23 29pp
- Q Inspection reports, IE Bulletins & correspondence
- BOO7280063 Suppls BOO208 response to IE Bulletin 79-28, "Possible Malfunction of NAMCO EA180 Limit Switches at Elevated Temps" Bub; switch is supplied on 1 5-inch pneomatic operated gate valve. Gaskets replaced prior to shipment VAN BRUNT.EE Arizona Public Service Co 80/03/11 ip
- 8007250357 Responds to IE Bulletin 80-03, "Loss of Charcoal from 8td Type II.2-Inch Tray Adsorber Cells " Type II tray adsorber cells are not used at facility Filtration units used are rechargeable.permanent.single-unit adsorbers. VAN BRUNT.E E Arizona Public Service Co 80/03/18 1p
- 8007170265 Forwards IE Insp Repts 50-528/80-05.50-529/80-05 & 50-530/80-05 on 800303-14 No noncompliance noted BPENCER,0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch, 80/05/20 2pp.
- --8007170270 IE Insp Repts 50-528/80-05, 30-529/80-05 & 50-530/80-05 en 800303-14 No noncompliance noted Major areas inspected:Unit i control bidg cable tray, concrete records & Unit 3 containment basemat concrete placement VORDERBRUGGEN Region 5, San Francisco, Office of the Director DODDS:R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/20 App
- 8007010016 Forwards IE Info Notice 80-23, "Loss of Suction to Emergancy Feedwater Pumps " No written response required ENGELMEN, R H Region 5, San Francisco, Défice of the Director 80/05/29 ip
- 8007220205 Forwards IE Info Notice 80-24, "Evaluation of Contractor GA Programs" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/10 1p
- 8007300516 Responds to 1E Bulletin 80-05 re damage to chemical vol control sys tanks Thirty addl days needed to obtain info requested in Item 2 VAN BRUNT.E E Arizona Public Service Co 80/06/10 ip
- B007290000 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/100FR50 55(a) " No written response required ENGELKEN.R.H Region 5, San Francisco, Office of the Director. B0/06/13 1p.
- 8007270523 Responds to IE Bulletin 80-09 Two suppliers make use of hydramotor actuators. Thirty-day extension necessary to determine if actuators are used in safety-related sys & if corrective actions required.

 VAN BHUNT, E E Arizona Public Service Co 80/06/17 ip
- 8007020477 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required. ENGELMENT H Region 5, San Francisco, Office of the Director, 80/06/20 jp.
- 8007180284 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel," No written response required ENGELKENR H Region 5, San Francisco, Office of the Director 80/04/24 ip
- B0072303B1 Forwards IE Bulletin B0-16, "Potential Misapplication of Rosemount Inc Models 1551 & 1152 Pressure Transmitters Mr/Either A or D Output Codes " Hritten response required IE Circular B0-16 also encl. No written response required. ENGLKBN.R H Region 5. San Francisco, Office of the Director B0/06/27 Ip
- 8007300530 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks No addl vacuum features needed for justification LRS holdup tanks cannot collapse due to vacuum VAN BRUNT, E E Arizona Public Service Co
- 8007290516 Responds to IE Bulletin 80-09 re hydromotor actuator deficiencies Field adjustment of present units necessary Springs used have stroke length precluding permanent set problem VAN BRUNT, E.E. Arizone Public Service Co. 80/07/03 2pp

- 8007210543 Ack receipt of 800624 ltr informing of steps taken to correct item of noncompliance noted in IE Insp Repts 50-528/80-06.0-529/80-06 Corrective actions will be verified during future insp BPENCER.Q S Region 5. Ban Francisco. Reactor Construction & Engineering Support Branch 80/07/08 ip
- ~-8007210546 Forwards response to item of noncompliance noted in IE Insp Repts 50-528/80-06,50-529/80-06 & 50-530/80-06 on 800415-18 Notice of violation was more misunderstanding than emission to rept.as situation was potentially reportable deficiency VAN BRUNT,E E Arizona Public Service Co 80/06/24 3pp

- 8007310505 Forwards IE Insp Repts 50~528/80~07.50-529/80~09 & 50~530/80-09 on 800801-23.No noncompliance noted BPENCER.0 S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/07/11. 2pp
- --8007310516 IE Insp Repts 50-528/80-09, 50-529/80-09 & 50-530/80-09 on B00501-23 No noncompliance noted, Major areas inspected Unit i cadwelder qualification, containment bldg closure, pipe hangers & supports & electrical cable installation program VORDERBRUEGGEN Region 5, San Francisco, Office of the Director. DODDB, R T Region 5, San Francisco, Reactor Operations Nuclear Support Branch. B0/07/10 Spp
- B Reportable occurrences. LERs & related correspondence
- 800702053: Forwards final deficiency rept re inadequate size of Figure 21: Sway strut assemblies
 VAN BRUNT, E E Arizona Public Service Co 80/06/25 2pp
- BOO7020525 Forwards interim deficiency rept re undersized fillet welds for structural steel.

 VAN BRUNT;E.E. Arizona Public Service Co 60/06/26 2pp
- --8007020529 Interim deficiency rept re undersized fillet welds for structural steel Caused by personnel error Welding procedures & qualification repts of five suppliers being reviewed & evaluated # Arizona Public Bervice Co 80/06/26 20p
- 8007140207 Forwards final deficiency rept re NAMCO controls Series EA 180 limit switches VAN BRUNT,E E Arizona Public Service Co 80/07/03 2pp
- ---B007140217 Final deficiency rept to NAMCO controls Series EA 180 limit switches Top cover gasket math emits resin vapor which forms deposit on internal components of switch Caused by improper curing of gasket math Gaskets will be replaced # Arizona Public Service Co 80/07/03 ip
- 8007140339 Forwards interim deficiency ropt re operability failure of vertical fire dampers VAN BRUNT, E E Arizona Public Service Co 80/07/03 2pp
- ---8007140341 Interim deficiency rept re operability failure of vertical fire dampers Caused by lack of design tolerance on sheet matel sides preventing full closure of damper door Tests & design changes are being implemented Final rept by 800915 a Arizona Public Service Co 80/07/03 ip
- BO07160632 Forwards final deficiency rept re closure of Comsip.Inc containment gas analysis pump valve VAN BRUNT, E E Arizona Public Service Co 80/07/09 2pp

- --8007160658 Final deficiency rept re Comsipilic containment gas analysis sys pump Protection for pump is inadequate in case of inadvertent closure of outlet valve w/pump running Units will be modified per Comsipilic instructions

 * Arizona Public Service Co 80/07/09 3pp
- B007170470 forwards final deficiency rept re visual insp rather than insp by liquid penetrant of circumferential wold joints on ABME Section 111.Class 3 piping sys

 VAN BRUNTLE E Arizona Public Service Co B0/07/09 2pp
- --Boo7170493 Final deficiency rept re visual insp rather than insp by liquid penetrant of circumferential weld joints on ASME Section III.Class 3 piping sys Welds reinspected by liquid penetrant Three deficient welds discovered & repaired * Arizona Public Service Cn 80/07/09 2pp
- 8007290722 Final deficiency rept re inadequate embedment of anchor bolts for seal tables Caused by umission of anchor bolt extension in design drawings Design change will be implemented to reflect proper anchoring in concrete VAN BRUNTLE E Arizona Public Service Co 80/07/21 App
- 8007290773 Final deficiency rept re inadequately designed reinforcing steel in walls of main steam support structure Caused by failure to use dynamic load factor of 2 0 in design Design change package will be implemented VAN DRUNT, E E Arizona Public Service Cn 80/07/21 4pp
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8007210237 Summary of 800311 meeting w/util in Bethesda,MD re review plans for OL applications LICITRA:E A Light Water Reactors Branch 3 80/04/25 4pp
- 8007010550 Forwards NRC reorganization chart for Ofc of Nuclear Reactor Regulation, effective 80042B Considerations relactivities should be made through assigned mgt representatives Areas of disagramment may be discussed through informal appeal TEDESCOR L. Assistant Director for Licensing 00/06/13 2pp
- 8007020209 Ack receipt & docketing of 791001 joint application for OLs Forwards list of incomplete sections following preliminary review of FSAR & environ rept Discusses licensing procedures & importance of timely communication EISENHUT.D © Division of Licensing 80/06/14 7pp
- 8007020194 Notification of 800709-10 meeting w/util in Bethesda.MD to discuss ac power sys KERRIGAN.J Licensine Branch 2 80/06/23 200
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694
 EISENHUT, D G Division of Licensing B0/06/26 2pp
- B007080227 Requests authorization under CPPR-141, CPPR-142 & CPPR-143 to use ASME Code Cases N-274, alternative rules for examination of weld repairs & N-275, repair of welds VAN BRUNT, E E Arizona Public Service Co 60/06/27 ip
- B007090285 Forwards Bachtel Power Corp & util responses to open items of Class IE dr power sys review Responses have been submitted to review board & final resolution will be submitted to NRC when completed VAN BRUNT, E E Arizona Public Service Co 80/06/30 10pp
- 8007110398 Forwards proofs of syc for applicant FBAR.DL application, general into & environ rept, required by NRC 800618 ltr
 VAN BRUNT, E.E. Arizona Public Service Co. 80/07/01 8pp
- G Adjudicatory correspondence
- 8007020680 Forwards 800519 ltm.FR notice & Director's decision under 10CFR2 206 denying Friends of the Earth 791024 petition to require supplemental environ statements on Class 9 accidents at facilities DENTON.H R Office of Nuclear Reactor Regulation. Director 80/06/19 2pp
- 8007310243 Forwards Commission 800827 memorandum & order containing decisions on UCS 780802 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT, D O Division of Licensing 80/06/25 89pp

- 8007170538 Forwards 800702 FR notice re opportunity for hearing on application for OLs SCHWENCER, A Operating Reactors Branch 3 80/07/02 3pp
- --BO07170542 Notice of receipt of application for facility (Ls:notice of availability of applicant environ reptinotice of consideration of issuance of facility (Ls & notice of apportunity for hearing Newspaper notice encl
 SCHWENCER, A Licensing Branch 3 BO/07/02 10pp
- BOO7:10002 Order granting extension until 800722 for Commission to elect to review decision on enforcement action request, DD-80-22 HOYLE, J C Office of the Secretary of the Commission 80/07/08
- B007300106 Notices of appearance in proceeding Certificate of Svc encl QENR.A C , B190H0FF.C A Arizona Public Service Co 80/07/23 3pp

- 8007110526 Responds to 800407 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area, spent fuel pool, shipping cask area & fuel pool cooling & cleanup sys Detailed description may be found in FSAR, Section 9 1 SCHWENCER, A Licensing Oranch 2 80/06/26 App
- 800721001B Advises that accepted version of application for OLs for facilities is being forwarded Listed previously submitted 3-ring binders may be discarded SOUDER, J. L. Division of Rules and Records 80/07/07 ip
- K Utility Final Safety Analysis Report (FSAR) & amends
- B0072B0589 Notifies that FSAR & environ rept complete & no further action required forwards revised & new pages to be incorporated in next FSAR amend & environ rept suppl VAN BRUNT,E E Arixona Public Service Co 80/07/23 ip
- --B0072B0B90 "Add1 Info for Amend 2 to FSAR," re geology, seismology & geotechnical engineering of structural design, & integrity of reactor coulant pressure boundary Preliminary version "

 w Arizona Public Service Co B0/07/23 19pp
- --B0072B0598 "Add1 Info for Suppl 1 to Environ Rept," re need for power, geography & demography, & applicant preoperational environ programs Preliminary version # Artiona Public Service Co B0/07/23 29pp
- A Inspection reports: IE Bulletins & correspondence
- 8007280068 Suppls H00208 response to IE Bulletin 79-28, "Possible Malfunction of NAMCO EALBO Limit Switches at Elevated Temps" Subj switch is supplied on 1 5-inch pneumatic operated gate valve Gaskets replaced prior to shipment VAN BRUNTLE E Arizona Public Service Co 80/03/11 ip
- 8007250337 Responds to IE Bulletin 80-03. "Loss of Charcoal from 9td Type II.2-Inch Tray Adsorber Cells " Type II tray adsorber cells are not used at facility Filtration units used are rechargeable, permanents single-unit adsorbers VAN BRUNT.E E Arizona Public Service Co 80/03/18 ip
- 8007170265 Forwards IE Insp Repts 50-528/80-05,50-529/80-05 & 50-530/80-05 on 800303-14 No noncompliance noted SPENCER.0 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/20 2pp
- ---B007170270 IE Insp Repts 50-528/80-05, 50-529/80-05 & 50-930/80-05 on B00303-14 No noncompliance noted Major areas inspected Unit i control bidg calle tray, concrete records & Unit 3 containment basemat concrete placement VORDERBEAUESGEN Region 5, San Francisco, Office of the Director DDDDS.R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch B0/03/20 App
- 8007010016 Forward* IE Info Notice 80-23, "Loss of Suction to Emergency Foodwater Pumps " No written response required. ENGELKEN, R H Region 5, San Francisco, Défice of the Director 80/05/29 ip
- BOO7220235 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required ENGELKEN.R H Region 5. San Francisco. Office of the Director 80/06/10 ip

- 8007300516 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks Thirty add1 days needed to obtain info requested in Item 2 VAN BRUNTLE E Arizona Public Service Co 80/06/10 1p
- 8007270080 Forwards IE Info Nutice 80-28, "Prompt Reporting of Info in Accordance M/10CFRSO 95(e)" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/13 ip
- B007290523 Responds to IE Bulletin 80~07 Two suppliers make use of hydramotor actuators Thirty-day extension necessary to determine if actuators are used in safety-related sys & if corrective actions required VAN BRUNTLE E Arizona Public Service Co 80/06/17 ip
- BOO7020477 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80706/20 ip
- 8007180286 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required ENGELKEN,R H Region 5, San Francisco, Office of the Director 80/06/24 1p
- 80072303Bi Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required ENGELKEN R H Region 5, San Francisco, Office of the Director 80/06/27 19
- 8007300530 Responds to IE Bulletin 80-05 re damage to chemical vol control sys tanks No addl vacuum foatures needed for justification LRS holdup tanks cannot collapse due to vacuum VAN BRUNT, E E Arizona Public Service Co
- 8007270516 Responds to IE Bulletin 80-09 re hydromotor actuator deficiencies Field adjustment of present units necessary Springs used have stroke length precluding permanent set problem VAN BRUNT, E E Arizone Public Service Co 80/07/03 2pp
- 8007210543 Ack receipt of 800624 ltr informing of steps taken to correct item of noncompliance noted in IE Insp Repts 50-528/80-06, \$0-527/80-06 & 50-530/80-06, Corrective actions will be verified during future insp SPENCER, 9 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/08 ip
- --8007210346 Forwards response to item of noncompliance noted in IE Insp Repts 50-529/80-06,50-529/80-06 & 50-530/80-06 on 800415-18 Notice of violation was more misunderstanding than omission to rept. as situation was potentially reportable deficiency VAN BRUNT,E E Arizona Public Bervice Co 80/06/24 3pp
- --8007210556 Forwards IE Insp Repts 50-528/80-06,50-529/80-06 & 50-539/80-06 on 800415-18 & notice of violation SPENCER,0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/23 2pp
- --8007210565 Notice of violation from insp on 800415-18
 * Region 5, San Francisco, Office of the Director 80/05/23 1p
- --B007210578 [E Insp Repts 50-528/80-06.50-529/80-06 & 50-530/80-06 on 800415-18 Noncompliance noted failure to rept deficiency within required reporting period ECKHARDT.J H . HERNANDEZ.G Region 5, San Francisco, Office of the Director DODDS.R T Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/05/23 App.
- 8007310505 Forwards IE Insp Repts 50-528/80-09,50-529/80-09 & 50-530/80-09 on 800501-23 No noncompliance noted SPENCER, C B Region 5, San Francisco, Reactor Construction & Engineering Support Branch 80/07/11 2pp
- --B00731051& IE Insp Repts 50-528/B0-09, 50-529/B0-09 & 50-530/B0-09 on B00501-23 No noncompliance noted Major areas inspected Unit 1 caluelder qualification.containment bldg closure.pipe hangers & supports & electrical cable installation program. VORDERURUEGGEN Region 5. Ban Francisco. Office of the Director DODDER T Region 5. Ban Francisco, Roactor Operations Nuclear Bupport Branch 80/07/10 Spp

occurrences. LERs & related correspondence orwards interim deficiency rept re undersized fillet welds
foral steel
for Arizona Public Service Co 80/06/26 2pp Interim deficiency rept re undersized fillet welds for all steel Caused by personnel error Helding for a qualification repts of five suppliers being to evaluated a Public Bervice Co. 80/06/26 2pp. prwards final deficienty rept re NAMCO controls Series it switches Arizona Public Service Co 80/07/03 2pp Final deficiency rept re NAMCO controls Series EA 180 limit Top cover gasket matl emits resin vapor which posit on internal components of switch Caused by curing of gasket matl Qaskets will be replaced for Public Service Co. 80/07/03 ip Forwards interim deficiency rept re operability failure of fire dampers

E E Arizone Public Bervice Co 80/07/03 2pp as Interim deficiency rept re operability failure of vertical agers Caused by lack of design tolorance on sheet addes preventing full closure of damper door Tests & Changes are being implemented final rept by 800715 con Forwards final deficiency rept re closure of Comsip. Inc. ent gas analysis pump valve.
T.E.E. Arizona Public Service Co. 40/07/09 2pp. 50 Final deficiency rept re Comsip. Inc containment gas analysis ppy rames vericiency rept re comstp.inc containment mp Protection for pump is inadequate in case of repent closure of outlet valve w/pump running Units madified per Comstp.inc instructions zone Public Service Co 80/07/09. 3pp Forwards final deficiency rept re visual insp rather than iquid penetrant of circumferential weld joints on tion III. Class 3 piping sys.
7.EE Arizona Public Service Co 60/07/09 2pp 93 Final deficiency rept re visual into rather than into by penetrant of circumferential weld joints on ASME is III.Class 3 piping sys Welds reinspected by liquid ment Three deficient welds discovered & repaired wone Public Service Co 80/07/09 2pp Final deficiency rept re inadequate embedment of anchor re seal tables Caused by omission of anchor bolt in deaign drawings Design change will be ted to reflect proper anchoring in concrete

T-EE Arizona Public Service Co. 80/07/21 4pp

- 50-530 PALD VERDE NUCLEAR STATION, UNIT 3

Summary of B00311 meeting w/util in Bethesda,MD re review to DL applications
A Light Water Reactors Branch 3 80/04/25 4pp

Forwards NRC reorganization chart for Ofc of Nuclear Reactor Oh.effective 800428 Considerations re activities made through assigned mgt representatives Areas of ment may be discussed through informal appeal R.L. Assistant Director for Licensing 80/06/13 2pp.

Ack receipt & docksting of 791001 joint application for rds list of incomplete sections following by review of FBAR & environ rept Discusses procedures & importance of timely communication 0 of Division of Licensing 80/06/16 7pp

Notification of 800709-10 meeting w/util in Bethesda, MD to C power sys Licensing Branch 2 80/06/23 2pp.

Porwards statement of policy re requirements to be met for applications, as derived from NUREG-0660 & found 0474

O Division of Licensing 80/06/26 269

BCO70B0227 Requests authorization under CPPR-141, CPPR-142 & CPPR-143 to use ABME Code Cases N-274, alternative rules for examination of weld repairs & N-275, repair of welds

VAN BRUNT,E E Arizona Public Service Co 80/06/27 ip

8007090285 Forwards Dechtel Power Corp & util responses to open items of Class IE of power sys review Responses have been submitted to review board & Final resolution will be submitted to NRC when completed VAN BRIVITE E Artisona Public Service Co 80/06/30 10pp

8007110398 Forwards proofs of svc for applicant FSAR.OL application, general info & environ reptirequired by NRC 800618 ltr. VAN BRUNT,€ € Arizona Public Service Co. 80/07/01 8pp

Adjudicatory correspondence

8007020ABO Forwards BCO519 ltr.FR nutice & Director's decision under 10CFR2 206 denying Friends of the Earth 791024 petition to require supplemental environ statements on Class 9 accidents at facilities DENION.HR Office of Nuclear Reactor Regulation, Director BO/06/19 2pp

8007310243 Forwards Commission 800527 momorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D @ Division of Licensing 80/06/25 879p

8007170538 Forwards 800702 FR notice re opportunity for hearing on application for OLs
SCHWENCER, A Operating Reactors Branch 3 80/07/02 3pp

--8007170942 Notice of receipt of application for facility OLs; notice of availability of applicant environ rept; notice of consideration of issuance of facility OLs & notice of opportunity for hearing Newspaper notice encl
BCHWENGER, A Licensing Branch 3 80/07/02 10pp

8007110002 Order granting extension until 800722 for Commission to elect to review decision on enforcement action request, DD-80-82 HOYLE, J C Office of the Secretary of the Commission 80/07/08 to

8007300104 Notices of appearance in proceeding Certificate of Svc encl GEHR.A C . BISCHOFF.C A Arizona Public Service Co 80/07/23 3pp

H General correspondence

8007110526 Responds to 800409 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area spent fuel pool shipping cask area & Ruel pool cooling & cleanup sys Detailed description may be found in FSRR Section 9 1 SCHWENCER.A Licensing Branch 2 80/06/26 4pp

800721001B Advises that accepted version of application for OLs for facilities is being forwarded Listed previously submitted 3-ring binders may be discarded BOUDER, J. L. Division of Rules and Records 80/07/07 ip

K Utility Final Safety Analysis Report (FBAR) & amends

B007280585 Notifies that FSAR & environ rept complete & no further action required Forwards revised & new pages to be incorporated in next FSAR amend & environ rept suppl VAN DRUNT.E E Arizona Public Service Co 80/07/23 ip

--8007280590 "Add1 Info for Amend 2 to FBAR," re geology, seismology & gaotochnical engineering of structural design, & integrity of reactor coolant pressure boundary Preliminary version "
* Arizona Public Service Co 80/07/23 19pp

--BOO7280598 "Add1 Info for Suppl 1 to Environ Rept," re need for power, geography & demography, & applicant preoperational environ programs Preliminary version

* Artiona Public Service Co 80/07/23 29pp

Q Inspection reports, IE Bulletins & correspondence

BOO7280063 Suppls 800208 response to IE Bulletin 79-28, "Possible Malfunction of NAMCB EAISO Limit Switches at Elevated Temps" Subj switch is supplied on 1 3 inch pneumatic operated gate valve Gastats replaced prior to shipment VAN BRUNT, E Arizona Public Service Co BO/03/11 ip

07250357 Responds to IE Bulletin BO-03, "Loss of Charcoal from Std ype II.2-Inch Tray Adsorber Cells " Type II tray adsorbor ells are not used at facility Filtration units used are echargeable.permanent.single-unit adsorbers VAN BRUNT.E E Ariiona Public Service Co 80/03/18 1p

07170265 Forwards IE Insp Repts 50-528/80-05.50-529/80-05 & 30-530/80-05 on 800303-14 No noncompliance noted spences of Region 5. San Francisco. Reactor Construction & ingineering Support Branch 80/05/20 2pp

CO7170270 IE Insp Repts 50-528/80-05.50-529/80-05 & 50-530/80-05 on 800303-14 No noncompliance noted Major areas inspected Unit 1 control bildy cable tray, concrete records & Unit 3 containment basemat concrete placement VORDERBRUEGGEN Region 5. San Francisco. Office of the Director DODDS, T Region 5. San Francisco. Reactor Construction & Engineering Support Branch 80/05/20 4pp

07010D16 Forwards 1E Info Notice 80-23. "Loss of Suction to Emergency redwater Pumps " No written response required RNGELKEN.R H Region 5. San Francisco. Office of the Director 10/05/29 ip

07220235 Forwards IE Info Notice 80-26. "Evaluation of Contractor A Programs " No written response required KNOELKEN,R H Region 5. San Francisco, Office of the Director 10/06/10 ip

17300516 Responds to IE Bulletin 80-05 re damage to chomical vol control sys tanks Thirty addl days needed to obtain info equested in Item 2 'AN BRUNT, E E Arizona Public Service Co 80/06/10 ip

7290000 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in accordance W/10CFR50 55(e)" No written response required MCELKEN,R H Region 5, San Francisco. Office of the Director 80/06/13 1p

.7290523 Responds to IE Bulletin 80-07 Two suppliers make use of gdramotor actuators Thirty-day extension necessary to etermine if actuators are used in safety-related sys & if corrective actions required VAN BRUNT, E E Arizona Public Service Co 80/06/17 lp

7020477 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump coling & Natural Circulation Cooldown " No written response equired NGELKEN,R H Region 5. San Francisco, Office of the Director

0/06/20

07180286 Forwards IE Circular 80-14, "Radioactive Contamination of lant Demineralized Water Sys & Resultant Internal ontamination of Personnel " No written response required NOCLKEN, R H Region 5, San Francisco, Office of the Director 10/04/24 1p

7230381 Forwards IC Bulletin 80-16. "Potential Misapplication of osemount Inc Models 1151 & 1152 Pressure Transmitters (Veither A or D Output Codes " Whitten response required E Circular 80-16 also encl No written response required (NOELKEN, R H Region 5, San Francisco, Office of the Director 0/06/27 1p

7300530 Responds to IE Bulletin 80-05 re damage to chemical vol ontrol sys tanks No addl vacuum features needed for ustification LRS holdup tanks cannot collapse due to

AN BRUNT, E E Arizona Public Service Co 80/04/27 2pp

17270516 Responds to IE Bulletin 80-09 re hydromotor actuator eficiencies Field adjustment of present units necessary prings used have stroke length precluding permanent set roblem

AN BRUNT, E E Artiona Public Service Co 80/07/03 2pp

7210543 Ack receipt of 800624 ltr informing of steps taken to orrect item of noncompliance noted in IE lnsp Repts 50-528/0-06,50-529/80-06 to 50-530/80-06 Corrective actions will be rerified during future insp PENCER,0 8 Region 5. San Francisco, Reactor Construction & ngineering Support Branch 80/07/09 in

007210546 Forwards response to item of noncompliance noted in IE Insp Repts 50-538/80-06.50-529/80-06 & 50-530/80-06 on 800415-18 Notice of violation was more misunderstanding than omission to rept as situation was potentially reportable deficiency VAN BRUNT.E E Arizona Public Service Co 80/06/24 3pp

- --8007210556 Forwards 1E Insp Repts 50-528/80-06.50-529/80-06 & 50-530/80-06 on 800415-18 & notice of violation SPENCER.6 S Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/05/23 2pp
- ~~8007210365 Notice of violation from insp on 800415-18 * Region 5, San Francisco, Office of the Director 80/05/23 ip
- --8007210578 IE Insp Repts 50-528/80-06.50-529/80-06 & 50-530/80-06 on 800415-18 Noncompliance noted failure to rept deficiency within required reporting period ECKHARDT, J H . HERNANDEZ. Q Region 5, Ban Francisco, Office of the Director DODDS,R T Region 5. San Francisco, Reactor Construction & Engineering Support Branch 80/05/23 6pp
- B007310505 Forwards IE Insp Repts 50-528/80-09,50-529/80-09 & 50-530/80-09 on 800501-23 No noncompliance noted SPENCER. © S Region 5, Ban Francisco, Reactor Construction & Engineering Support Branch 80/07/11 2pp
- --8007310516 IE Imap Repts 80-528/80-09.50-527/80-09 & 50-530/80-09 on 800501-23 No noncompliance noted Major areas inspected Unit i cadwelder qualification, containment bldg closure.pipe hangers & supports & electrical cable installation program VORDERBRUEGGEN Region 5. Sam Francisco. Office of the Director BODDS, R T Region 3. Sam Francisco, Reactor Operations Nuclear Support Branch 80/07/10 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 8007020525 Forwards interim deficiency rept re undersized fillet welds for structural steel VAN BRUNT,E E Arizona Public Service Co 80/06/26 2pp
- --8007020527 Interim deficiency rept re undersized fillet walds for structural steel Caused by personnal error Welding procedures & qualification repts of five suppliers being reviewed & evaluated * Arizona Public Service Co 80/06/26 2pp
- 8007160546 Forwards final deficiency rept re dowel omission during concrete placement
 VAN BRUNT.E E Arizona Public Service Co 80/07/08 2pp
- further investigations necessary * Arizona Public Service Co 80/07/08 1p
- B007160852 Forwards final deficiency rept re closure of Comsip.Inc containment gas analysis pump valve VAN BRUNT,E E Arizona Public Bervice Co B0/07/09 2pp.
- ---8007160638 Final deficiency rept re Comsip. Inc containment gas analysis sys pump Protection for pump is inadequate in case of inadventent closure of putlet valve w/pump running Units will be modified per Comsip. Inc instructions

 * Arizona Public Service Co 80/07/09 3pp

DOCKET 50-537 CLINCH RIVER DREEDER REACTOR

- B. Utility Preliminary Safety Analysis Roport, amends
- E007080264 Forwards affidavit confirming distribution of PSAR Amend 55 to local public officials & EPA representatives COPELAND,R L. Energy, Dept of, Clinch River Breeder Reactor Plant 80/07/03 2pp

ł

- F Security, medical, emergency & fire protection plans
- B007010366 Forwards physical security plan Plan withheld (ref 10CFR2 790)
 CUPELAND,R L Energy, Dept of, Clinch River Breeder Reactor Plant. B0/06/27 4pp
- 8007100194 Forwards revised responses to Quastions 421 3 & 421,10 re physical security plan Responses withheld (ref 100FR2 790) Related correspondence COPELAND,R L. Chergy, Dept of, Clinch River Breeder Reactor Plant, 80/06/27 App

- DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8007280286 Forwards physical security plan for SNM of low strategic significance Plan withheld (ref 10CFR2 790)

 JONES.D W Memphis State Univ 80/07/23 1p
- G. Inspection reports: IE Bulletins & correspondence
- B007170177 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director B0/06/24 to
- DOCKET BIN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- | 8007010096 Forwards util revised project GA manual Contains resolution of IE comments from review of previous manual Project mgt procedures & ASME GA manual will be reviewed for consistency w/project GA manual. H/O ancil SHIELDS.8 W Public Service Co of Indiana, Inc 80/06/04 ip
 - 8007210058 Advises of readiness for NRC review & evaluation of Itams A 1.c.,d. & B 1 of app to V Stello 800515 ltr re graduated revision of order dated 790815 BHIELDS,B W Public Service Co of Indiana, Inc 80/06/17 ip
 - BO07140581 Confirms 800627 meeting w/MD Menscer & HA Barker at site to discuss const related activities

 KEPPLER, J. 9 Region 3. Chicago. Office of the Director 80/06/24
 - 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0594
 EIBENHUT.D.Q Division of Licensing 80/06/26 2pp
 - BOO7250142 Notifies that licensee revised GA program & prerequisites necessary for receipt insp.under restart program Items A 2 & B.3. have been satisfactorily completed Util is authorized to begin receipt insps for Item B.4.

 STELLO.V. Office of Inspection & Enforcement. Office of the Director. 80/07/07 5pp.
 - F Security, medical, emergency & fire protection plans
 - BOO7280571 Requests confirmation that divisional personnel located onsite would not be covered by NUREO-0554 & FEMA REP-1 unless specific onsite amergency assignments were involved BHIELDS.S.W Public Service Co. of Indiana, Inc. 80/07/18 2pp
 - 9. Adjudicatory correspondence
 - BOO7310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 patition for reconsideration of 780413 memorandum & order UCS 771104 patition sought action re fire protection for electrical cables
 EISENHUT.D. Q. Division of Licensing. 80/06/25 89pp
 - 8007100275 Discusses Save the Velley add1 comments to Commissioner re resumption of work at facility, docketed on 800514 NRC will review document to determine whether add1 enforcement measures are appropriate STELLO,V Office of Inspection & Enforcement, Office of the Director. 80/06/26 2pp
 - --8007100308 Notice that Save the Valley addl comments to Commissioner re resumption of work at facility, docksted on 800514, will be treated under 100FR2 206 BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/06/26 lp
 - H General correspondence

1

8007110598 Forwards response to questions & comments presented at 800325 public meeting. Util required to adhere to ASME code for safety-related piping sys Revised GA program description encl. W/o description.

STELLO:V Office of Inspection & Enforcement, Office of the Director 80/05/23 Upp.

- B007010031 Submits addl info allsing from Sassafras Audubon Society 790901 request for hearing re heavy faults & forwards B00610 ltr to DG Fry STELLOV Office of Inspection & Enforcement, Office of the Director B0/06/16 2gp
- --8007010046 Ack receipt of 800515 reply to request for background info on statement re heavy faults made in 790901 request for hearing Term was inappropriate Concrete structures will exhibit cracks which do not affect integrity SHEMMAKER.R E Office of Inspection & Enforcement, Office of the Director 80/06/10 2pp
- ---8007010055 Responds to 800508 inquiry re statement in 790901 request for hearing on confirming suspension of const re heavy faults Forwards 790111 Indianapolis Star news article in which statement appeared Requests any info on subj FREY.D G Sassafras Audubon Society 80/05/15 2pp
- BOO7110544 Notifies that action per 10CFR2 296 is being taken to consider comments ducketed on BOO507 & 14 re resumption of const at plant Notice of request for action will be published in FR SIELLD,V Diffice of Inspection & Enforcement, Office of the Director BO/06/26 4pp
- 8007220549 Forwards summary of latest (June 1980) organizational change Info includes revised organization charts & provides overview identifying individual changes which affect overall QA program
 SHIELDS, S W Public Service Co of Indiana, Inc 80/07/09 Spp
- SHIPPON A I DOLLE DELLICE DO GLINGTONN THE COLUMN
- Q Inspection reports, IE Bulletins & correspondence
- 8007210363 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/05/28
- 8007010074 Forwards IE Info Notice 80-23. "Loss of Section to Emergency Feedwater Pumps " No written response required KEPPLER.J G Region 3. Chicago, Office of the Director 80/05/29 to
- 8007100096 Forwards IE Insp Repts 50-546/80-19 & 50-547/80-19 on BODD13 No noncompliance noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch BO/04/03 2pp
- --B007100099 IE Insp Repts 50-546/80-19 & 50-547/80-19 on 800513 No noncompliance noted Major areas inspected environ monitoring program & environ protection program EBSIG.T H. GREER.R H. Region 3. Chicago. Office of the Director 80/06/02 3pp
- 8007160469 Forwards IE Insp Repts 50-546/80-17 & 50-547/80-17 on 800422-29, 30 & 0513 No noncompliance noted FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/10 2pp
- --B007160479 IE Insp Repts 50-546/80-17 & 50-547/80-17 on 800422-25.30
 0513 No noncompliance noted Hajor areas inspected project GA
 manual, personnel qualifications & physical verification of
 structural steel activities
 SCHMEIBNINZ.E . HARRISON.J J . WILLIAMS.C C Region 3, Chicago,
 Office of the Director 80/06/06 9pp
- 8007220215 Forwards IE Info Nutice 80-26, "Evaluation of Contractor GA Programs" No written response required KEPPLER, J G Region 3. Chicago, Office of the Director 80/06/10
- BOO71601B7 Forwards IE Info Notice 80-27, "Degradation of Reactor Coolants Pump Studs " No specific action or response required KEPPLER.J O Region 3, Chicago, Office of the Director BO/06/11
- 8007020027 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-546/79-02 & 50-547/79-02, 50-546/79-04 & 59-547/79-04 FigReLLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/06/13 ip
- --8007020031 Responds to NRC 1tr re violations 50-546/79-02.50-547/79-02.50-546/79-03.50-50-546/79-04 & 50-547/70-04 Corrective at re GC insp have been rewritten to clarify SHIELDS.S W Public Service Co of India

- 007280631 Forwards IE Info Notice 80~28. "Prompt Reporting of Info in Accordance W/100FR50 55(e)" No written response required MEPPLER, J. G. Region D. Chicago, Office of the Director 80/06/13 1p
- B00714050A Responds to IE Bulletin B0-09, "Hydramotor Actuator Deficiencies " Vendor will not utilize incorrect spring math in facility actuators having greater than 3-inch stroke No mad needed for equipmont qualification or test programs SHIELDS.6 W Public Service Co of Indiana. Inc 80/06/18 ip
- 3007230704 Forwards IE Insp Repts 50~546/80~22 & 50-547/80~22 on B00501-31 No noncompliance noted FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 80/06/19 2pp
- ---B007230710 IE Insp Repts 50-546/B0-22 & 50-547/B0-22 on B00501-31 No nuncompliance noted Major areas inspected auxiliary & fuel handling bldgs & containment HARRISON, J. J. WILLIAMS.C. C. Reginn 3, Chicago, Office of the Director 80/06/18 4pp
- 8007020548 Forwards 1E Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Matural Circulation Cooldown " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/20, is
- 3007170510 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Sys % Resultant Internal Contamination of Personnel " Ma written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/24 ip
- 9007230308 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also oncl Na written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/2 1p
- 1007P30238 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Penetrations will be installed per ASME code Radiographic examinations of Types 1 & 2 flued head penetrations will be performed SHIELDS,S W Public Service Co of Indiana, Inc 80/07/03 2pp
- 3007230093 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Syn (CVCS) Holdup Tanks "Design features & proper operating procedures ensure adequate protection against vacuum damage SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/07/07 2pp.
- 8007280083 Forwards restart program w/NRC hold points Dased on insp findings.which confirm info reported in 800427 ltr.concludes Items A 2 & B 3 of restart program meet QA requirements Program acceptable STELLQ.V Office of Inspection & Enforcement, Office of the Director 80/07/07 App
- . Reportable occurrences. LERs & related correspondence
- 3007100229 Interim deficiency rept re certified matl test repts for weld filler matl ASME has not provided code interpretation of requirements re repts to date, but util expects to file final rept on or before 801001
 Si
- 2007210012 Ack receipt of 800430 final deficiency rept re damage to containment liner on Unit ! FIORELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- R007210021 Ack receipt of 800602 interim deficiency rept re problem in operation of centrifugal charging pumps at min allowable flow rate FIDRELLI.G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 3007210025 Ack recopt of 800425 interim deficiency rept re-certified matl test repts for weld filter matl FIDRECLIFO Region 3, Chirago, Reactor Construction & Engineering Support Branch 80/07/03 to
- OOTE10031 Ack recipt of 800428 final deficiency mapt re-concrete auxiliary bldg slab FIGRCLLI.0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 lp

- 8007210054 Ack receipt of 800425 final deficiency rept re joints in safety-related structural steel FIORELLI, 8 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007230615 Ack receipt of 800429 final deficiency rept re use of noncode math in certain code.Category I component supports FIORELLI,G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007180536 Ack receipt of 800813 final deficiency rept re failure to meet PBAR basis secondary cooling flow rate due to main feedwater line rupture w/concurrent failure of steam generator blowdown isolation valve on another loop FIGREALI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/07 Ip
- B007240319 Ack receipt of B00627 interim deficiency rept re incorrect weld filler used in welding of safety-related pipe spool pieces
 FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/10
- 8007250397 Interim deficiency rept re automatic actuation function of Mestinghouse Type W-2 switch Util will consider vendor findings & determine any corrective actions Final rept will be forwarded by 801i21
 SHIELDS,S W Public Service Co of Indiana, Inc. 80/07/21 2pp
- 8007280667 Interim deficiency rept re reinforcing steel installations not meeting spec requirements Cause not stated Engineering evaluation will be performed on pertinent reinforced concrete elements
 SHIELDS.S W Public Service Co of Indiana, Inc. 80/07/24 2pp
- U Congressional/Executive Correspondence
- 900711031B Discusses concerns re DDJ investigation of alleged coverup of const flaws Stop work order should not be lifted w/o release of final FDI rept Independent engineer should be allowed continued access to site if const resumes FORD.W H Senate 80/05/08 ip
- 8007080159 Responds to 800313,0417 & 0508 ltrs re facility const resumption Use of consultant to perform regular insp functions would not provide add1 safety assurance AHEARNE: J F Commission 80/06/16 3pp
- **B007R502R5 Provides five main topics of considerations re resumption of safety-related const work, in response to B00515 request Includes verification of adequacy of previously placed concrete & ratios & numbers of GA/GC personnel DIRCKB. H J Office of the Executive Director for Operations 80/07/02 5pp
- --8007250246 Requests info re IE recommendation to allow gradual resumption of const & issues discussed in related Commission briefing
 DECKARD. J House of Rep., Government Operations 80/05/15 3pp
- DOCKET STN-50-547 MARDLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- B007010096 Forwards util revised project GA manual Contains resolution of IE comments from review of previous manual Project mgt procedures & ASME GA manual will be reviewed for consistency w/project GA manual W/o encl
 B
- B00721005B Advises of readiness for NRC review & evaluation of Items A 1 c .d. & B 1 of app to V Stello B00515 ltr re graduated revision of order dated 770815 SHELDS:SW Public Service Co of Indiana, Inc B0/04/19 ip.
- 8007140581 Confirms 800627 meeting w/MD Menscer & HA Barker at site to discuss const related activities KEPPLER, J G Region 3, Chicago, Office of the Director. 80/06/24
- BOO7230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT.D © Division of Licensing 80/06/26 2pp

- 8007230142 Notifies that licensee revised QA program & prerequisites nacessary for receipt insp.under restart program ltems A 2 & B 3, have been satisfactorily completed Util is authorized to begin receipt insps for Item B 4
 BTELLO,V Office of Inspection & Enforcement, Office of the Director 80/07/07 5pp
- F Security, medical, emergency & fire protection plans
- B007280591 Requests confirmation that divisional personnel located onsite would not be covered by NUREG-0654 & FEMA REP-I unless specific onsite emergency assignments were involved SHIELDS.S W. Public Service Co of Indiana, Inc. 80/07/18 2pp

Adjudicatory correspondence

- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D 0 Division of Licensing 80/06/25 89pp
- 8007100295 Discusses Bave the Valley addl comments to Commissioner re resumption of work at facility, docketed on 800514 NRC will review document to determine whether addl enforcement measures are appropriate BTELLO, V Office of Inspection & Enforcement, Office of the Director 80/06/26 2pp
- ---B00710030B Notice that Save the Valley addl comments to Commissioner re resumption of work at facility, docketed on B00514.will be treated under 100FR2 206 STELLO.V Office of Inspection & Enforcement, Office of the Director 80/06/26 ip

- B007110588 Forwards response to questions & comments presented at 800325 public meeting Util required to adhere to ABME code for safety-related piping sys Revised GA program description encl W/o description
 STELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/23 8pp
- 8007010031 Submits add1 info arising from Sassafras Audubon Society 790701 request for hearing re heavy faults & forwards 800610 ltr to DO Fry STELLD, V Office of Inspection & Enforcement, Office of the Director. 80/06/16. 2pp
- --B007010046 Ack receipt of 800515 reply to request for background info on statement re heavy faults made in 790901 request for hearing. Term was inappropriate Concrete structures will swhibit cracks which do not affect integrity BHEHMAKER, R E Office of Inspection & Enforcement, Office of the Director 80/06/10 2pp.
- --8007010033 Responds to 800308 inquiry re statement in 790901 request for hearing on confirming suspansion of const re heavy faults Forwards 790111 Indianapolls Star news article in which statement appeared Requests any info on subj FREY, D Q Sassafras Audubon Society 80/09/13 2pp
- 6007:10544 Notifies that action per iOCFR2 206 is being taken to consider comments docketed on 800507 & 14 re resumption of const at plant Notice of request for action will be published in FR STELLO, V Office of Inspection & Enforcement, Office of the Director 60/06/26 4pp
- 8007220549 Forwards summary of latest (June 1980) organizational change. Info includes revised organization charts & provides overview identifying individual changes which affect overall GA program
 SHIELDS, S. W. Public Service Co. of Indiana, Inc. 80/07/09 Bp
- G Inspection reports, IE Bulletins & correspondence
- 8007210363 Forwards IE Circular 80-13, "Orid Strep Damage in Hestinghouse Fuel Assemblies " No written response required KEPPLER.J 9 Region 3, Chicago, Office of the Director 80/05/28
- B007010074 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps" No written response required KEPPLER, J. 9 Region 3, Chicago, Office of the Director 80/05/29 to.

- 8007100094 Forwards IE Insp Repts 50-446/80-19 & 50-547/80-19 on B00513 No noncompliance moted DAVIS,A B Region 3. Chicago Fuel Facility & Materials Safety Branch 80/06/03 2pp
- --8007100099 IE Insp Repts 50-546/80-19 & 50-547/80-19 on 800513 No noncompliance noted Major areas inspected environ monitoring program & environ prutection program ESSIGIT H. OREGRAR H. Region 3. Chicago, Diffice of the Director 80/06/02 3pp
- 8007160469 Forwards IE Insp Repts 50-546/80 17 & 50-547/80-17 on B00422-25,30 & 0513 No noncompliance noted FIGRELLIG Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/06/10 2pp
- --8007160479 IE Insp Repts 50-546/80-1/ & 90-547/80-1/ on 800422-25.30 0513 No noncompliance noted Major areas inspected project GA manual, personnel qualifications & physical verification of structural steel activities SCHMEIDNINZ, E., HARRISON, J. J., WILLIAMS, C.C. Region 3, Chicago, Office of the Director 80/06/06 9pp
- 8007220215 Forwards IE Info Nutice 80-26, "Evaluation of Contractor GA Programs " No written responso required KEPPLER, J G Rugion 3, Chicago, Office of the Director 80/06/10 lp
- B007140187 Forwards IE Info Notice 80-27, "Dogradation of Reactor Compants Pump Stude" No specific action or response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/11, to
- B007020027 Ack receipt of 800528 ltr informing NRC of steps taken to correct violations noted in IE Imp Repts 50-546/79-02 & 50-546/79-03 & 50-547/79-03, 50-546/79-04 & 59-547/79-04 PIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch B0/06/13 ip
- --B007020031 Responds to NRC ltr re violations noted in IE Insp Repts 50-546/79-02, 50-547/79-02, 50-546/79-03, 50-547/79-03, 50-546/79-04 & 50-547/70-04 Corrective actions procedures re GC insp have been rewritten to clairly process SHIELDS.S.W. Public Service Co. of Indiana. Inc. 80/05/28 3pp
- 8007280631 Forwards 1E Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required KEPPLER, J 9 Region 3, Chicago, Office of the Director 80/06/13
- 8007140506 Responds to 1E Bulletin 60-09, "Hydramotor Actuator Deficiencies " Vendor will not utilize incorrect apring mati in facility actuators having greater than 3-inch strake No mod needed for equipment qualification or test programs SHIELDS, S.W. Public Service Co. of Indiana, Inc. 80/06/10 ip
- B007230704 Forwards IE Insp Repts 30-546/80-22 & 90-547/80-22 on B00501-31 No noncompliance hoted FIURELLI & Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/06/19 2pp
- --8007230710 IE Insp Repts 50-546/80-22 & 50-547/80-22 on 800501-31 No noncompliance noted Major areas inspected auxiliary & fuel handling blugs & containment HARKERON, J. J. WILLIAMS, C. C. Region 3, Chicago, Office of the Director 80/06/18 4pp
- 8007020548 Forwards 3E Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required KEPPLER.J G Region 3, Chirago, Office of the Director 80/06/20
- 8007170510 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Rosultant Internal Contamination of Personnel " No written response required KEPPLER, J Q Region 3, Chicago, Office of the Director 80/06/24 tp
- B007230338 Forwards IE Builetin B0-16. "Potential Rosemount Inc Models 1151 & 1152 Proseure Trans W/Either A of D Output Codes "Writton respons IE Circular B0-16 also encl No written response KEPPLER.J G Region G. Chicago, Office of the D Ip

- 8007230238 Responds to IE Bulletin 80-08, "Exam of Containment Liner Penetration Welds " Penetrations will be installed per ASME code Radiographic examinations of Types i & 2 flued head penetrations will be performed SHIELDS,S W Public Service Co of Indiana, Inc. 80/07/03 2pp
- 8007230093 Responds to IE Bulletin 80-05, "Vacuum Condition Resulting in Damage to Chemical Vol Control Sys (CVCS) Holdup Tanks " Design features & proper operating procedures ensure adequate protection against vacuum damage SHIELDS,S W Public Servico Co of Indiana, Inc 80/07/07 2pp
- BOO72800B3 Forwards restart program w/NRC hold points Based on insp findings.which confirm info reported in BOO627 ltr.concludes Items A 2 & B 3 of restart program meet GA requirements Program acceptable STELLO.V Office of Inspection & Enforcement, Office of the Director BO/07/07 App
- S Reportable occurrences. LERs & related correspondence
- 8007100229 Interim deficiency rept re certified matl test repts for weld filler matl ASME has not provided code interpretation of requirements re repts to date, but util expects to file final rept on or before 801001
 SHIELDS, S W Public Service Co of Indiana, Inc 80/06/27 ip
- 8007210021 Ack recespt of 800602 intersm deficiency rept re problem in operation of centrifugal charging pumps at min allowable flow rate FIGRELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/07/03 lp
- 8007210025 Ack receipt of 800425 interim deficiency rept re certified matl test repts for weld filter matl FIORELLI,O Region 3: Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007210031 Ack reciept of B00428 final deficiency rept re concrete auxiliary blog stab FIORELLI,O Region 3. Chicago, Reactor Construction & Engineering Bupport Branch 80/07/03 ip
- 8007210054 Ack receipt of 800425 final deficiency rept re joints in safety-related structural steel FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007230615 Ack receipt of B00425 final deficiency rept re use of noncode math in certain code.Category I component supports FIDRELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 80/07/03 ip
- 8007180536 Ack receipt of 800513 final deficiency rept re failure to meet PSAR basis secondary cooling flow rate due to main feedwaker line rupture w/concurrent failure of steam generator blowdown isolation valve on another loop.
 FIORELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/07 ip
- 8007240317 Ack receipt of 800627 interim deficiency rept re incorrect weld filler used in welding of safety—related pipe spool
- pieces.
 FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 80/07/10 ip
- 8007250397 Interim deficiency rept re automatic actuation function of Westinghouse Type W-2 switch Util will consider vendor findings & determine any corrective actions Final rept will be forwarded by 801121 BHIELDS.S W Public Service Co of Indiana, Inc. 80/07/21 2pp
- 9007280667 Interim deficiency rept re reinforcing steel installations not meeting spec requirements Cause not stated Engineering evaluation will be performed on pertinent reinforced concrete elements
 SHIELDS.S W Public Service Co of Indiana, Inc. 80/07/24, 2pp.
- ! Congressional/Executive Correspondence
- 8007110318 Discusses concerns re DOJ investigation of alleged coverup of const flaws Stop work order should not be lifted w/o release of final FBI rept Independent engineer should be allowed continued access to site if const resumes FDRD,W H Senate 80/05/08 ip
- B0070B0159 Responds to B00313,0417 & 0508 ltrs re facility const resumption Use of consultant to perform regular insp functions would not provide addl asfety assurance AHEARNE, J F Commission B0/06/16 3pp.

- DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be set for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISEM-UT, D G Division of Licensing 80/06/26 2pp
- DOCKET STN-50-553 PHIPPS BEND NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B00701022B Advises of reorganilation of Ofc of Nuclear Reactor Regulation effective B0042B Mgt of all licensing matters for facilities has been assigned to D Scaletti Organizational description encl TEDESCO.R L Assistant Director for Licensing B0/06/13 10pp
- 8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0640 & found in NUREG-0674
 EIBENHUT.D Q Division of Licensing 80/06/26 2pp
- Q Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT, D G Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007180481 Responds to encl 800228 ltr to President Carter re nuclear power plants Radiation exposure considered as part of EIB before CP issued Every effort made to protect public health & safety at all nuclear plants DENTON, H R Office of Nuclear Reactor Regulation, Director 80/05/05 2pp
- O Inspection reports, IE Bulletins & correspondence
- BOO7240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability of Davis-Besse Unit i While in Refueling Mode "
 No response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director BO/05/08
- 8007140479 Forwards IE Bulletin 80-13, "Cracking in Core Spray Spargers " No written response required. O'REILLY.J P Region 2, Atlanta, Office of the Director 80/05/12
- 8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29.
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/10
- 8007140301 Forwards JE Bulletin 80-14, "Degradation of BWR Scram Discharge Vol Capability " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/0
- 8007250384 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)" No written response required C/REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/13.
- B007020499 Forwards response to IE Bulletin 80-09 transmitted by JP O'Reilly 800417 ltr Final rept for Hartsville & Phipps Bend plants will be sent on or before 801017 MILLS,L M Tennessee Valley Authority 80/06/16 2pp
- BOO7170559 Responds to TV Abbatiello 800606 telcon re IE Investigation Repts 50-353/80-05 & 50-554/80-04 Error in Paragraphs 2 & 3 of Attachment A of subj repts has been corrected changing assistant const engineer to assistant const superintendent.

 ALDERSON.C E Region 2, Atlanta, Office of the Director. 80/06/19

- ---8007170584 IE Investigation Repts 50-553/80-05 & 50-554/80-04 from insp on 800220-22. Major areas inspected allegation that welding QC inspector was instructed by supervisor to exceed permissible weld bead widths. LONG.F J . MARSH.R J Region 2, Atlanta, Office of the Director 80/05/28 10pp
- 6007020391 Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/20
- 6007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24
- 8007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Reseasunt Inc Models 1151 & 1152 Pressure Transmitters M/Either A or D Dutput Godes " Written response required IE Gircular 80-16 also encl No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/27
- B007220236 Responds to IE Bulletin 79-28, "Possible Malfunction of MAMCO Model EA180 Limit Switches at Elevated Temps " Investigations show no NAMCO EA180 switches are installed or planned for installation.
 MILLS.L.M. Tennessee Valley Authority. 80/07/01, 1p.
- 8007180189 Ack receipt of 800619 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-553/80-08 & 50-554/80-07. MRFHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/07/02. ip.
- -- 6007180220 Notice of violation from insp on 800507-09
 Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/05/21. 1p
- --8007180234 TE Insp Repts 50-553/80-08 & 50-554/80-07 on 800507-09.
 Noncompliance noted inadequate concrete batch plant insp
 LEMMHAN, J Region 2. Atlants, Office of the Director
 COMLON.T.E. Region 2. Atlants, Reactor Construction & Engineering
 Support Branch 80/05/21. 5pp.
- 8007280615 Responds to IE Bulletin 80-08, "Exemination of Containment Penetration Welds," Results of investigation encl HILLS, L. M Tennessee Valley Authority 80/07/07, 5pp
- 9. Reportable occurrences: LERs & related correspondence
- 8007170236 Part 21 rept re potential defect in air conditioning units in facilities. Detailed info will be provided to assist determination of significant safety hazard 91ROUX.E J Carrier Corp Carrier Air Conditioning Div 80/06/17 3pp.
- B007170247 Part 2i rept of potentially defective Rosemount, Inc transmitter in control sys of air conditioning units Info is provided to assist in determination of significance as safety hazard OIRDUX, E. J. Carrier Corp. Carrier Air Conditioning Div. 80/06/20 29pp.
- 8007100252 Fifth interim deficiency rept re high pressure core spray diesel generator switchgear wiring discrepancies 9E has not provided to util revised/corrected drawings or replacement parts to complete actions Final rept to be filed by 801001 MILLS.L M Tennessee Velley Authority 80/06/27 ip
- 8007110320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before 800917. MILLS, L. M. Tennessee Velley Authority 80/07/02. ip

- --B007ii0328 First interim deficiency rept on Rosemount Model 1152 pressure transmitter defects During testing GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennessee Valley Authority 80/07/02 1p
- B007220490 First interim deficiency rept re reactor pressure vessel shroud head & moisture separator assembly fire Reactor pressure vessel assembly was initially hydroblasted w/demineralized water Assembly will be cleaned thoroughly # Tennessee Valley Authority 80/07/14 3pp

DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8007010228 Advises of reorganization of Ofc of Nuclear Reactor Regulation, effective 800428 Mgt of all licensing matters for facilities has been assigned to D Scaletti Organizational description encl TEDESCO,R L Assistant Director for Licensing 80/05/13 10pp
- 8007230001 Forwards statement of policy re requirements to be met for current DL applications as derived from NUREG-0660 % found in NUREG-0674 EISENHUT, D G Division of Licensing 80/06/26 2pp
- 9 Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 77104 petition sought action re fire protection for electrical cables EISENHUT.D Q Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007180481 Responds to entl 800228 ltr to President Carter re nuclear power plants Radiation exposure considered as part of EIS before CP issued Every effort made to protect public health & safety at all nuclear plants DENTON, HR Office of Nuclear Reactor Regulation, Director 80/05/05 2pp
- Q Inspection reports. IE Bulletins & correspondence
- B007240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Epase Unit 1 While in Refueling Mode " No response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/05/08
- 8007140479 Forwards IE Bulletin 80-13. "Cracking in Core Spray Spangers " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/12 in
- 8007010225 Forwards IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 80/05/29 ip
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs" No written response required O'REILLY, J P Region 2. Atlanta. Office of the Director 80/06/10 3pp
- 8007140301 Forwards IE Bulletin 80-14. "Degradation of BWR Scram Discharge Vol Capability " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/12 1p
- 8007290384 Forwards JE Info Notice 80-28. "Prompt Reporting of Info in Accordance W/10GFR50 95(e) " No written response required O'REILLY, J P Region R. Atlanta. Office of the Director 80/06/13
- 8007020497 Forwards response to IE Bulletin 80-09 transmitted by JP D'Reilly 800417 Itr Final rept for Martsville & Phipps Bend plants will be sent on or before 801017 MILLS,L M Tennessee Valley Authority 80/06/16 2pp
- 8007170559 Responds to TV Abbatiello 800606 telcon re lE Investigation Repts 50-553/80-05 & 50-554/80-04 Error in Paragraphs 2 & 3 of Attachment A of subj repts has been corrected, changing assistant const engineer to assistant const superintendent ALDERSON, C E Region 2, Atlanta, Office of the Director, 80/06/19.

- 007170567 Forwards IE Investigation Repts 50~553/80-05 & 50-554/80-04 on 800220-22 No noncompliance noted LONG,F J Region 2. Atlanta, Office of the Director 80/05/29
- 007170584 JE Investigation Repts 50-553/80-05 & 30-554/80-04 from insp JU/170584 IE Investigation Repts 50-553/80-05 & 30-554/80-04 from on 800200-82 Major areas inspected allegation that welding GC inspector was instructed by supervisor to exceed permissible weld bead widths LONG, FJ MARSK, RJ Region 2. Atlanta, Office of the Director 80/05/28 10pp
- 7020391 Forwards IE Circular 80-15. "Loss of Reactor Coolant Pump Joling & Natural Circulation Cooldown " No written response equired 'REILLY.J P Rogion 2. Atlanta. Office of the Director 80/06/20
- 7170070 Forwards If Carcular 80-14, "Radioactive Contamination of lant Demineralized Water Sys & Resultant Internal intomination of Personnel" No written response required 'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/04/2 80/05/24
- 7230203 Forwards IE Bulletin 80-16. "Potential Misapplication of isemount Inc Models 1151 & 1152 Pressure Transmitters "Either A or D Output Codes" "Written response required. Circular 80-16 also encl No written response required REILLY. J P Region 2. Atlanta. Office of the Director 80/06/ 80/04/27
- 220236 Responds to 1E Bulletin 79-28, "Possible Malfunction of MCO Model EAIBO Limit Switches at Elevated Temps " vestigations show no NAMCO EAIBO switches are installed or anned for installation Tennessee Valley Authority 80/07/01
- 180187 Ack receipt of 800619 ltr informing NRC of steps taken to rrect violation noted in IE Insp Repts 50-559/HO-08 & -554/BO-07
 RPHY.C E Region 2, Atlanta, Reactor Construction & Engineering
- RPHY C E 60/07/02
- 07180199 Forwards IE Insp Repts 50-553/80-08 & 50-554/80-07 on 300507-09 & notice of violation TURPHY, C E Region 2. Atlanta. Reactor Constitution & Engineering Support Branch 80/05/28 2pp
- 07180220 Notice of violation from insp on 800507-09 Region 2: Atlanta: Reactor Construction & Engineering Support Tranch 80/05/21 ip.
- 17180234 IE Insp Repts 50-553/80-08 & 50-554/80-07 on B00507-09. Incompliance noted inadequate concrete batch plant insp ENAHAN.J J Region 2. Atlanta. Diffice of the Director IONLON.T E Region 2. Atlanta. Reactor Construction & Engineering upport Branch 80/05/21 Spp
- '80615 Responds to IE Bulletin 80-08, "Examination of Containment letration Welds" Results of investigation encl LS,L M Теяпезsee Valley Authority 80/07/07 Эрр
- portable occurrences, LERs & related correspondence
- 70236 Part 21 rept re potential defect in air conditioning units facilities Detailed info will be provided to assist ermination of significant safety hazard OUX,E J Carrier Corp Carrier Air Conditioning Div 80/04/17
- 50275 Forwards final deficiency rept re incorrect root face on wed cadweld sleeves LS.L M Tennessee Valley Authority 80/06/19 ip
- 70247 Part 21 rept of potentially defective Rosemount. Inc nsmitter in control sys of air conditioning units Info is vided to assist in determination of significance as etu hazard
- Carrier Corp Carrier Air Conditioning Div 80/06/20
- 00252 Fifth interim deficiency rept re high pressure core spray sel generator switchgear wiring discrepancies OE has not vided to util revised/corrected drawings or replacement to to complete actions Final rept to be filed by 801001 LS.L M Tannessee Valley Authority 80/06/27 1p

- BO07:10320 Forwards first interim deficiency rept on Rosemount Model 1152 pressure transmitter defects initially reported 800603 Final rept will be submitted on or before 800917 MILLS.L.M. Tennessee Valley Authority 80/07/02 1p.
- ---8007110328 First interim deficiency rept on Rosemount Model 1152 pressure transmitter defects During testing, GE found ambiguous output to over & underpressure conditions Review to determine number of transmitters on location underway * Tennesses Valley Authority BO/07/02 ip
- B007220450 First interim deficiency rept re reactor pressure vessel shroud head & moisture separator assembly fire Reactor pressure vessel assembly was initially hydroblasted w/demineralized water Assembly will be cleaned thoroughly a Tennessee Valley Authority 80/07/14 Spp
- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1
- A Application/construction stage documents & correspondence
- EDOA3003AB Advises that list of matls to be used in const of fire stops & characteristics re flammability & fire retordancy will be provided I yr subsequent to receipt of CP MMENCH. 8 W Public Bervice Co of Oklahoma 80/06/20 2pp.
- B007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREO-0660 & found in NUREO-0694 Division of Licensing 80/06/26 2pp
- O Adjudicatory correspondence
- BOO7020613 Motion to intervene as interested state in Case 80-1566 before US Court of Appeals for DC Circuit NRC regulations grant states legal right to intervene at appeal stage Certificate of Svc enci Related correspondence BERGER, R F, CARTHRIGHT, J E Oklahoma, State of 80/06/24 10pp
- BO07310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 700502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISENHUT.D 0 Division of Licensing 80/04/25 87pp
- 8007310153 Notices of JO Thomas & CS Rogers withdrawal & RF Berger appearance in proceeding. Certificate of Svc encl
 THOMAS.J G . ROGERB.C S : BERGER.R F Oklahoma. State of 80/06/30
- 8007170369 Forwards SH Hanauer of Accident Task Force 711005 memo. designated Number 22, re telcon w/P Bray of QE, in response to H00709 ltr PATON, W D Hearing Branch 4 80/07/15 1p
- ---8007170371 Advises of telcon w/R Selvatori of Westinghouse to Classes
 2-8 accidents & probable causes Official use only,
 HANAUER, S H Atomic Energy Commission 71/10/05 1p
- H General correspondence
- 8007030013 Responds to 800905 ltr re emergency planning for facilities Requirements for emergency planning are being revised in response to recommendations of NRC/EPA Joint Task Force on Emergency Planning & TMI Lessons Learned Task Forces. GRIMES, B K Emergency Preparedness Program Office. 80/06/23, Rep
- --B007030019 Opposes const of facilities until adequate emergency response plan can be developed Recommends responsibility for emergency response plan be placed w/independent consulting svc.not State of OK MALONE, K Affiliation Unknown 80/05/05 2pp
- Q Inspection reports, IE Bullatins & correspondence
- 8007220118 Forwards IE Info Notice 80-25, "Evaluation of Contractor GA Programs " No written response required BEYFRIT, K V Region 4, Dalles, Office of the Director 80/06/10
- 8007290075 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 80/06/13

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT, D G Division of Licensing 80/05/26 2pp

F. Becurity, medical, emergency & fire protection plans

800630036B Advises that list of matls to be used in const of fire stops & characteristics re flammability & fire retardancy will be provided 1 yr subsequent to receipt of CP MVENCH, Q W Public Bervice Co of Oklahoma 80/06/20 2pp

O Adjudicatory correspondence

8007020613 Motion to Intervene as interested state in Case 80-1566 ow/outed instant to intervene as interested state in Case 80-1 before US Court of Appeals for DC Circuit NRC regulations grant states legal right to intervene at appeal stage Certificate of Svc encl. Related correspondence BERGER F., CARTHRIGHT, J.E. Oklahoma, State of 80/06/24

8007310243 Forwards Commission 800927 memorandum & order containing decisions on UCB 780502 petition for reconsideration of 780413 memorandum & order UCB 771104 petition sought action re fire protection for electrical cables EISENHUT.D © Division of Licensing 80/06/25 89pp

B007310183 Notices of JQ Thomas & CS Rogers withdrawal & RF Berger appearance in proceeding Cartificate of Svc encl THOMAS, J Q., ROGERS, C. S., BERGER, R F Oklahoma, State of 80/06/30

8007170369 Forwards 8H Hanauer of Accident Task Force 711005 memodesignated Number 22.re telcon w/P Bray of GE, in response to 800709 ltr.
PATON.W.B Hearing Branch 4 80/07/15 ip

---B007170371 Advises of telcon w/R Salvatori of Westinghouse re Classes 2-B accidents & probable causes Official use only HANAUER, B. H. Atomic Energy Commission 71/10/05 ip

H General correspondence

8007030013 Responds to 800505 ltr re emergency planning for facilities Requirements for emergency planning are being revised in response to recommendations of NRC/EPA Joint Task Force on Emergency Planning & TMI Lessons Learned fask Forces ORIMES, B. K. Emergency Preparedness Program Office 80/06/23 2pp

-8007030019 Opposes const of facilities until adequate emergency response plan can be developed Recommends responsibility for emergency response plan be placed w/independent consulting svc. not State of OK MALONE.K Affiliation Unknown 80/05/05 2pp

@ Inspection reports, IE Bulletins & correspondence

8007220118 Forwards IE Info Notice 80-26. "Evaluation of Contractor GA Programs " No written response required SEYFRIT, K V Region 4, Dallas. Office of the Director 80/06/10

8007270075 Forwards IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e) " No written response required BEYFRIT, K. V. Region 4, Dallas, Office of the Director 80/06/13

DOCKET STN-50-541 B-848-205

H General correspondence

8007280149 Ack receipt of wasay on "Excellence in Operations " Commends attitude toward work on nuclear power DENTON.HR Diffice of Nuclear Reactor Regulation, Director BO/07/14 ip.

DUCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT UNIT 1

A Application/constitution stage documents & correspondence

8007310537 Confirms 800701 telcon is placement of earthfill in ERCW spray pond Concurs in resumption of earthfill placement, based on final rept in util 800711 ltr O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/16

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 EISENHUT.D G Division of Licensing 80/04/24 2pp

@ Adjudicatory correspondence

B007310243 Forwards Commission 800527 memorandum & order containing decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771014 petition sought action re fire protection for electrical cables EISENHUT,D G Division of Licensing B0/06/25 89pp

H General correspondence

B007300013 Responds to 790405 ltr re nuclear power State of IL has seven nuclear power plants Reasons for use of nuclear power plants in IL listed in encl excerpt from util annual rept President 791207 statement re Kemeny Commission Rept encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80706/26 28pp

8007220027 Responds to DO Jourdan B00328 ltr to J Schlesinger Regulations require that extensive studies be performed to show that proposed plants will not endanger health & safety DENTON.H R Dffice of Nuclear Reactor Regulation, Director 80/07/01 2pp

--8007220030 Forwards DO Jourdan B00328 ltr for consideration KENDRICK, H Energy, Dept of 80/05/03 Jpp

Q Inspection reports, IE Bulletins & correspondence

8007240089 Forwards IE Info Notice 80-20. "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, P Region 2, Atlanta, Office of the Director 80/03/08

8007210488 Forwards IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response require O'REILLY, J P Region 2. Atlanta, Office of the Director

8007010225 Forwards IE Info Notice 80-23, "Loss of Suction to Emergency Feedwater Pumps " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/05/29

8007190447 Forwards 1E Inap Repts 50-566/80-08 & 50-567/80-08 on 800913-16 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 80/06/05 2pp

-8007150452 IE Inse Repts 50-566/80-08 & 50-567/80-08 on 800513-16 No DO/ID0452 IE Insp Repts 50-36/80-08 & 50-36/780-08 on 800 moncompliance noted Major areas inspected licenses identified items, insp followsp item, warehouse storage & observation of safety-related concrete activities THOMAS M Region 2, Atlanta, Office of the Director CANTRELL F 8 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/04 App

8007220029 Forwards IE Info Nutice 80-26, "Evaluation of Contractor GA Programs "No written response required
O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/10

8007160287 Forwards 1E Info Notice 80-27. "Degradation of Reactor Coolant Pump Studs " No specific action or response O'REILLY. J.P. Region 2. Atlanta, Office of the Director 80/

8007250384 Forwards 16 Info Notice 80-28, "Prompt Report Accordance W/JOCFR50 55(e) " No written response requi O'REILLY, J P Region 2, Atlanta, Office of the Direct

- 8007020391 Forwards 1E Circulat 80-15. Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown "No written response required

 O'REILLY, J P Region & Atlanta, Office of the Director 80/06/20
- B007290422 Forwards IE Insp Repts 50-566/80-09 & 50-567/80-09 on 800602-06 No noncompliance noted MURPHY.C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. B0706/23 2pp
- --8007290432 IE Insp Repts 50-566/80-09 % 50-567/80-09 on 800602-06
 No noncompliance noted Major areas inspected steel
 structures & supports in containment welding, welding matl
 control,welder qualification & procedures
 HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering
 Support Branch CROWLEY, B R Region 2. Atlanta, Office of the
 Director 80/06/20 App
- 8007170070 Forwards 1E Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24 80706724
- B007230253 Forwards IE Bulletin 80-16. "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters W/Either A or D Output Codes " Written response required IE Circular 80-16 also entl No written response required O'REILLY.J P Region 2, Atlanta. Diffice of the Director 80/06/2 80/06/27
- 8007210036 Forwards response to JE Bulletin 80-08 re-examination of containment liner penetration welds Penetrations at Sequovah. Watts Bar & Bellefonte contain Flued head design Design for Yellow Croek not yet completed MILLS.L M Tennessee Valley Authority B0/07/08 5pp
- 9 Reportable occurrences. LERs & related correspondence
- 8007160473 Forwards second interim deficiency rept re const QA audit Next rept will be submitted by 800820 W/o encl MILLS.L M Tennessee Valley Authority 80/07/09 ip
- 8007230255 Part 21 rept re Bristol structural steel framing for control bldg Rework of fillet welds is being performed Next rept will be submitted by 800815
 MILLS-L M Tennessee Valley Authority 80/07/09 3pp
- 8007170342 Forwards final deficiency rept re placement of earthfill in ERCW spray pond MILLS.L M Tennessee Valley Authority 80/07/10
- ---8007170344 Final deficiency rept re placement of earthfill in ERCW spray pond GA audit revealed eight items of noncompliance re placement & insp of earthfill taborers will be assigned to remove all visible unsuitable math during fill placement * Tennessee Valtey Authority 80/07/10 4pp
- 8007170356 Forwards final deficiency rept re const GA audit MILLS, L M Tennesses Valley Authority 80/07/10 ip
- ~8007170358 Final deficiency rept re const OA audit Concrete placement evaluated & found acceptable Inspectors instructed in requirements of general const spec * Tennessee Valloy Authority 80/07/10 ip
- 8007150659 Forwards revised final deficiency rept re placement of earthfill in essential raw cooling water spray pend MILLS.L M Tennessee Valley Authority 80/07/11
- --8007150663 Revised Final deficiency rept re placement of earthfill in essential raw cooling water spray pond Insufficiently compacted mat was removed & replacement fill recompacted Util will use penetrometer tests for fill operations # Tennessee Valley Authority 80/07/11, App
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8007310537 Confirms B00701 telcon re placement of earthfill in ERCW spray pond Concurs in resumption of earthfill placement, based on final rept in util 800711 ltr O'REILLY, J.P. Regron 2. Atlanta, Office of the Director 80/06/14

- 8007230001 Forwards rtatement of policy re requirements to be met for current OL applications, as derived from NURE9-0660 & found in NURE9-0694
 - EISENHUT, D.G. Division of Licensing 80/06/26 2pp
- G Adjudicatory correspondence
- 8007310243 Forwards Commission 800527 memorandum & order containing 30/31/243 Foregars Commission BOOSE/ Memoranes a cross consideration of decisions on UCS 780502 petition for reconsideration of 780413 memorandum & order UCS 771104 petition sought action re fire protection for electrical cables EISEN#UT.D G Division of Licensing 80/06/25 89pp
- H General correspondence
- 8007300013 Responds to 790405 ltr re nuclear power State of IL has seven nuclear power plants Reasons for use of nuclear power plants in IL listed in encl excerpt from util annual rept President 791207 statement re Kemeny Commission Rept encl DENTON: HR Office of Nuclear Reactor Regulation, Director BO/04/24 28pp
- 8007220027 Responds to DD Jourdan 800028 ltr to J Schlesinger. Regulations require that extensive studies be performed to show that proposed plants will not endanger health & sefety DENTON.H R Office of Nuclear Réactor Regulation, Director 2p p 80/07/01
- --8007220030 Forwards DO Jourdan 800328 ltr for consideration. KENDRICK:H Energy.Dept of 80/06/03 Spp
- G Inspection reports. IE Bulletine & correspondence
- BOO7240089 Forwards IE Info Notice 80-20, "Loss of Decay Heat Removal Capability at Davis-Besse Unit 1 While in Refueling Mode" No response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 80/05/08.
- 8007210488 Forwards IE Circular 80-13. "Grid Strap Damage in Westinghouse Fuel Assemblies " No written response required, O'REILLY, J.P. Region 2. Atlanta, Office of the Director, E 80/05/28
- B007010225 Forwards IE Info Notice 80-23, "Loss of Buction to Emergency Fredwater Pumps " No written response required D'REILLY. J P Region 2, Atlanta, Office of the Director B0/05/29
- BOO7150447 Forwards IE Insp Repts 50-546/80-08 & 50-567/80-08 on BOO513-15 No noncompliance noted MURPHY.C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch BO/06/05 2pp
- --8007150452 IE Insp Repts 50-566/80-08 & 50-567/80-08 on 800519-16. No noncompliance noted Major areas inspected licensee identified items, insp followup item, warehouse storage & observation of safety-related concrete activities THOMAG. M. Region 2. Atlanta, Office of the Director CANTRELL, F. B. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 80/06/04 4pp
- 8007220029 Forwards IE Info Notice 80-26, "Evaluation of Contractor GA Programs " No written response required D'REILLY, J.P. Region 2, Atlanta, Diffice of the Director. 80/06/10
- BOO71402B7 Forwards IE Info Notice BO-27, "Degradation of Reactor Coolant Pump Stude " No specific action or response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/11
- 8007280384 Forwards 1E Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR30 95(e) " No written response required.

 G'REILLY-J P Region 2. Atlanta, Office of the Director. 80/06/13.
- 800702039: Forwards IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown " No written response D'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/06/20.
- 8007290422 Forwards IE Insp Repts 50-566/80-09 & 50-567/80-09 en 800602-06 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 80/06/23 2pp

--B007290432 IE Insp Repts 50-566/80-09 & 50-567/80-09 on 800602-06
No noncompliance noted Major areas inspected steel
structures & supports in containment welding, welding matl
control/welder qualification & procedures
HERDT, A R Region 2. Atlanta, Reactor Construction & Engineering
Support Branch CROWLEY, B R Region 2. Atlanta, Office of the
Director 80/06/20 opp

8007170070 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required O'REILLY, J P. Region 2, Ablanta, Office of the Director B0/06/24

B007230253 Forwards IE Bulletin 80-16, "Potential Misapplication of Rosemount Inc Models 1151 & 1152 Pressure Transmitters "M/Either A or D Output Codes " Written response required IE Circular 80-16 also encl No written response required O'REILLY. J P Region 2, Atlanta, Office of the Director B0/06/2 80/06/27

8007210036 Forwards response to IE Bulletin 80-08 re-exemination of containment liner penetration welds Penetrations at Bequoyah, Hatts Bar & Bellefonte contain flued head design Design for Yellow Creek not yet completed HILLS: L M Tennessee Valley Authority 80/07/08 5pp

8 Reportable occurrences, LERs & related correspondence

8007160473 Forwards second interim deficiency rept re const QA audit. Next rept will be submitted by 800820 M/o encl MILLB.L M. Tennessee Valley Authority 80/07/09 ip

B007230255 Part 21 rept to Bristol structural steel framing for control bldg Rework of fillet welds is being performed Next rept will be submitted by B00815 MILLS,L M Tennessee Valley Authority B0/07/09 3pp Tennessee Valley Authority 80/07/09 3pp

8007170342 Forwards final deficiency rept re placement of earthfill in ERCW spray pand
MILLS, L. M Tennesses Valley Authority 80/07/10

--BO07170344 Final deficiency rept re placement of earthfill in ERCW spray pond GA audit revealed eight items of noncompliance re placement & insp of earthfill. Laborers will be assigned to remove all visible unsuitable math during fill placement # Tennessee Valley Authority B0/07/10. 4pp

8007170356 Forwards final deficiency rept re const QA audit MILLS.L.M Tennessee Valley Authority 80/07/10 1p

--8007i70358 Final deficiency rept re const QA audit Concrete placement evaluated & found acceptable Inspectors instructed in requirements of general const spec.

Tennesses Valley Authority 80/07/10 1p

DOCKET STN-50-968 NEP NUCLEAR, UNIT 1

A. Application/construction stage documents & correspondence

8007230001 Forwards statement of policy rs requirements to be met for current OL applications, as derived from NUREG-0550 & found in NARCG-0544
EISENHUT, D 9 Division of Licensing 60/05/25 2pp

DOCKET BIN-50-569 NEP NUCLEAR, UNIT 2

A Application/construction stage documents & correspondence

8007230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NARGO-0694 EISENHUT.D.Q Division of Licensing 80/06/26 2pp

DOCKET STN-50-580 ERIE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

BOO7230001 Forwards statement of policy re requirements to be met for current DL applications, as derived from NUREG-0660 & found in NUREG-0674 EIBENNUT.D D. Division of Licensing BO/06/26 2pp

DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8007230001 Forwards statement of policy re requirements to be met for current (L applications, as derived from NUREG-0660 & found in NUREG-0660.

EISENHUT, D.C. Division of Licensing 80/06/26 2pp

DOCKET 50-582 SUNDESERT, UNIT 1

A Application/construction stage documents & correspondence

8007230001 Forwards statement of pulicy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0660. EISENHUT, D G Division of Licensing 80/06/26 2pp

DOCKET 50-583 SUNDESERT, UNIT 2

A Application/construction stage documents & correspondence

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0560 & found in NUREG-05674 EISENHUT, D G Division of Licensing 80/06/26 2pp

DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4

A Application/construction stage documents & correspondence

8007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREG-0660 & found in NUREG-0694 E1BENHUT, D G Division of Licensing 80/06/26 2pp

H General correspondence

8007110526 Responds to 800409 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area, spent fuel pool, shipping cask area & fuel pool cooling & cleanum sys Detailed description may be found in FSAR Section 9 1 SCHWENCER, A Licensing Branch 2 BO/06/26 App

DOCKET BIN-50-593 PALD VERDE NUCLEAR BEATION, UNIT 5

A Application/construction stage documents & correspondence

B007230001 Forwards statement of policy re requirements to be met for current OL applications, as derived from NUREO-0660 & found in NUREO-0844 EISENHUT, D.G. Division of Licensing BG/06/26 2pp

H General correspondence

BOO7110526 Responds to BOO409 ltr to R Ryan Each unit will include separate fuel bldg for housing new fuel area spent fuel pool shipping cask area & fuel pool cooling & tleanup sys Detailed description may be found in FSAR Section 9 1 SCHWENCER.A Licensing Branch 2 BO/06/26 App

DOCKET 50-594 MO-R1, UNITS 3 & 4

A Application/construction stage documents & correspondence

8007280479 Requests license to export steam generator components to Bouth Korea HE88.R J Westinghouse Electric Corp 80/07/15 2pp

--8007280487 Advises that amend request should remain active Vendor is applying for separate components license rather than waiting for amend approval HEMBY,E Q Office of International Programs, Director 80/07/15

--- 8007280495 Submits application to amend license to add intermediate consignee HEBS,R J Westinghouse Cleatric Corp. A0/04/10 ip

- DOCKET STN-50-596 NEW HAVEN, UNIT 1
- A Application/construction stage documents & correspondence
- 8007230001 Forwards statement of policy re requirements to be met for current (L. applications.as derived from NVREG-0660 & found in NVREG-0694
 EISENHUT, D.G. Division of Licensing 80/06/26 2pp
- DOCKET STN-50-597 NEW HAVEN, UNIT 2
- A Application/construction stage documents & correspondence
- B007230001 Forwards statement of policy re requirements to be met for turrent (L. applications, as derived from NUREG-0660 & found in NUREG-0694 E19EMHUT, D G Division of Licensing B0/06/26 2pp

BOCKET 50-599 CARROLL FACILITY I

- C Utility Environmental Report (ER), amends & correspondence
- B007140627 Forwards affidavit of svc for distribution of site suitability environ rept.Revision 3. Buppl 2.in response to NRC 790404 request NAU094707.W F Commonwealth Edison Co B0/05/23 2pp
- 6 Adjudicatory correspondence
- B007010131 Request for extension until 800710 to file brief in opposition to Catizens Against Nuclear Power & E Gogol 800812 notice of appeal from ABLB B00830 memorandum & order NRC was anvolved in other adjudication W/Certificate of Svc. GOLDBERG.S C Hearing Branch 2 B0/06/27 4pp
- B007020462 Brief in opposition to Citizens Against Nuclear Power et al appeal from ASLC 800330 order re denial of Contentions 1.2. 4-11 & 13 Early site review need not include full review required under NEPA W/contentions & Certificate of Syc NILLER, M 1. DIELAHSKI, A P Commonwealth Edison Co MILLER, M 1 Isham. Lincoln & Beale 80/06/27 26pp
- 8007100244 Request for extension until B00718 to file brief in opposition to Citizens Against Nuclear Power, J Runyon & E Ougol B00612 appeal from ASLB 800930 memorandum & order recontentions Winotice of appearance & Certificate of Syc JONES, B W Hearing Branch 2 80/07/09 5pp
- 8007220110 Brief in opposition to Citizens Against Nuclear Power, J Runyon & E Gogol 800612 notice of appeal from ASLB 800530 memorandum & order denying intervention Argument re EIS constitutes impermissible challenge to NRC regulations GOLDBERG.S C , JONES.B W Hearing Branch & 80/07/18 27pp
- --8007220121 Summarizes veius on early site review proposed regulations Supports idea in general but opposes application to reprocessing facilities & expresses concerns re-certain technical issues Certificate of Syc encl SPETMA Council on Environmental Quality 77/04/27 5pp
- DDCKET 50-600 CARROLL FACILITY II
- C Utility Environmental Report (ER), amends & correspondence
- B007160627 Forwards affidavit of svc for distribution of site suitability environ rapt.Revision 3.Suppl 2.in response to NRC 790404 request NAUCHTON.W F Commonwealth Edison Co 80/05/23 2pp
- O Adjudicatory correspondence
- 8007010131 Request for extension until E00710 to file brief in opposition to Citizens Against Nuclear Power & E Gogol B00612 notice of appeal from ARLB B00530 memorandum & order NRC was involved in other adjudication W/Certificate of Bvc GOLDBERG.S C Hearing Branch 2 B0/06/27 App
- 8007020462 Brief in opposition to Citizens Against Nuclear Power et al appeal from ASLB 800530 order re Menial of Contentions 1.2. 4-11 & 13 Early site review need not include full review required under NEPA W/contentions & Certificate of Svc HILLER, M I . BIELAWSKI, A F Commonwealth Edison Co MILLER, M I isham. Lincoln & Beale 80/06/27 26pp

- BOO7100244 Request for extension until BOO718 to file brief in opposition to Citizens Against Nuclear Power, J Runyon & E Gugol BOO612 appeal from ASLB BOO530 memorandum & order recontentions Windtice of appearance & Certificate of Svc JONES, B W Hearing Branch 2 BO/07/09 5pp
- BOO7220110 Brist in opposition to Citizens Against Nuclear Power, J Runyon & E Gogol BOO612 notice of appeal from ASLB BOO530 memorandum & order denying intervention Argument re EIB constitutes impermissible challenge to NRC regulations GOLDBERG, S C , JONES, B W Hearing Branch 2 80/07/18 27pp
- ---8007220121 Summarizes veiws on early site review proposed regulations
 Supports idea in general but opposes application to
 reprocessing facilities & expresses concerns re certain
 technical issues Certificate of Svc enc!

 SPETH-0 Council on Environmental Quality 77/04/27 Spp
- DOCKET 50-754 GENERAL ELECTRIC TEST REACTOR
- 9 Adjudicatory correspondence
- 8007020468 Forwards May 1780 safety evaluation re QETR SWANSON, D T Hearing Branch 1 80/06/27 1p

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

- DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES
- BO07140D35 Forwards IE Insp Repts 70-0008/80-01 & 30-05728/80-01 on B00422-24 No noncompliance noted DAVIB.A B Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/06/03 2pp
- --8007140041 IE Insp Repts 70-0008/80-01 & 30-05728/80-01 on 800422-24.
 No noncompliance noted Major areas inspected organization, operations review facility changes & mods, safety committees & internal & external exposure control FISHER, W. L. Region 3, Chicago, Fuel Facility & Materials Bafety Branch 80/06/02 App
- 8007170609 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director, 80/06/24 10.
- BOO7180502 Notifies of fee required for review of 791218 request for route approval for shipment of Monticello spent fuel MILLER.U D License Fee Management Branch 80/07/02 tp
- 8007250049 Forwards 800602 for request for NRC review of physical protection plan for SNM of moderate & low strategic significance Fayment is requested within 15 days M/o encl. WEISS.D License Fee Management Branch 80/07/16 1p
- DOCKET 70-0025 ROCKHELL INTERNATIONAL CORP
- 8007030005 Forwards 1E Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power." Written response required, ENGELKEN,R H Region 5, San Francisco, Office of the Director 800/06/18 10
- 8007310542 Forwards revised pages to 800507 increment of analysis of effects of natural phenomene & environmental character surrounding plant Revisions include significant changes in demography & minor changes in dispersion metaprology ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 80/06/18 6nm
- 8007180281 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sqs & Resultant Internal Contamination of Personnel " No written response required ENGELKENR H Region 5, San Francisco, Office of the Director 80/06/24 1p
- 8007240475 Forwards IE Insp Rept 70-0025/80-07 on 800630-0702 of activities under License SNM-21 No noncompliance noted Hajor areas inspected physical protection against industrial sabotage Encl withheld (ref 10CFRZ 790) NORDERHAUG, L R Region 5, San Francisco, Safeguards Branch, 80/07/10 ip

- 8007250580 Responds to 800612 request for reconsideration of amend fea submitted for NRC review of 800519 physical security plan Plan will require major amend to License SNM-21 Therefore, NRC fee assessment is justified MILLER,W O License Fee Management Branch 80/07/11 2pp
- ---8007250588 Forwards safeguards amend fee for NRC review of physical security plan Requests reconsideration of fee Licensee submitted plan in response to regulatory requirement & was not applying to amend License SNM-21

 REMLEY.M.E. Rockwell International Corp., Energy Systems Div 80/06/12 in
- 8007310452 Amends License SNH-21.Section 9 0 by correcting administrative errors in License Condition 9 A 1 A & adding 800314 page change to security plan Approves 800314 request to use specific type of shotgun at facility MCCORKLE.Q W Physical Security Licensing Branch 80/07/16 lp
- 8007310475 Forwards request for addl info & revisions to E90-80-17, "Physical Becurity Plan for Protection of Moderate Strategic Quantities of BNM at Hot Labs of Energy Sys Group of Rockwell Intl " Encl withheld (ref 10CFR2,790) MCGORKLE, G W Physical Becurity Licensing Branch 80/07/16 ip

DOCKET 70-0027 BABCOCK & WILCOX CD

- 8007020339 Forwards revised application for amend to Licenso SNM-42, replacing 790931 application All refs to alloy shop pickle operations have been deleted. CORDANJER A Babcock & Hilcox Co., Naval Nuclear Fuel Div 80/05/30
- --B007020358 Replaces 790B31 ltr by forwarding Revision 4 to License SNM-42 Revision deletes hight shift mgt audit incorporates conditions during power outage & changes emergency plan Fee encl.

 CORDANI, R A Babcock & Wilcox Co , Naval Nuclear Fuel Div B0/09/30 4nn
- --8007020365 Application for amend to License SNM-42, deleting night shift mgt audit, incorporating conditions during power outage & changing omergency plan as noted

 * Babcock & Wilcox Co., Naval Nuclear Fuel Div 80/05/30 App
- B007280220 Discusses IE insp of License BNM-42 on 800513-16 & forwards IE Insp Rept 70-0027/80-07 KENNA:W B Region 2, Atlanta, Safeguards Branch 80/06/03 2pp
- --B007280223 IE Insp Rept 70-0027/80-07 on B00313-16 No noncompliance noted Major areas inspected operations, organization, facility changes & mods, internal audits & followup of previously identified items
 CONYELL, Q P Region 2, Atlanta, Office of the Director KAHLE, J B Region 2, Atlanta, Bafeguards Branch 80/06/03 5pp
- 8007020721 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification 8ys (ENB) W/Loss of Offsite Power " Hritten response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 80/96/18
- 8007170149 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 80/04/24 is.
- 8007240119 Amend 11 to License SNM-42, authorizing deletion of night shift manager audit, Audible alarm requirement examption request denied FAGE, R. G. Uranium Fuel Licensing Branch 80/07/01 ip
- ---8007240125 Discusses review of 800530 license amond application.
 Recommends deletion of night shift mgt audit requirement
 Denies exemption from audible alarm requirements under
 postulated conditions.
 KETZLACH,N , CROW,W T Uranium Fuel Licensing Branch 80/07/01
- 8007210097 Notifies that 791109 request for route approval involving spent fuel shipment to Nuclear Engineering Co in Hanford Works, MA is subj to license fee schedule Review completed on 800326 MILLER, W D License Fee Management Branch 80/07/03 ip

- 8007250648 Forwards revised NUREG-0561 amending interim rule for physical protection of spent fuel in transit Addl areas have been designated as heavily populated Routes approved for BAU encl New requirements apply 800703 M/o encl NCCORKLE.G W Physical Security Liconsing Branch 80/07/03 ip
- 8007250053 Requests notification of approx meeting date to discuss status of possible scrap recovery contract between NRC & facilities NRC has proposed Aug or Sept 1980 meeting date in Silver Bpring, MD PARTLOW, J G Material Control Licensing Branch 80/07/15 lp
- DOCKET 70-0033 TEXAS INSTRUMENTS, INC.
- 800707004B Forwards page changes to fundamental nuclear math control plan Changes include organizational revisions, NRC review recommendations & current operational procedures Changes withheld (ref 10CFR2 790)
 8CHWENSFEIR,R Toxas Instruments, Inc 80/05/27 2pp
- 8007030389 Recommends approval of page changes to fundamental nuclear matl control plan submitted 791126.800227 & 0527 Liconse Conditions 1 i,2 3,3 1,3 1 i,3 2,6 3 & 8 1 should be deleted Ltr to vendor & amend enci HUFF,D Material Control Licensing Branch 80/04/13 1p
- --8007030395 Amend MPP-1 to License SNM-23 permitting use of shipper values for U-308 receipts Licensee shall report all intentional discards & met) unaccounted for on monthly basis
 - * Material Control Licensing Branch 80/06/16 3pp
- 8007020625 Forwards IE Bulletin BO-15, "Possible Loss of Emergency Notification Sys (ENS) W/Lows of Offsite Power " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director BO/06/18 ip
- 8007160842 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER.8 H Region 1, Philadelphia, Office of the Director 80/06/24 ip
- 8007210167 Ack receipt of 800612 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 70-0033/80-06 BMITH.Q H Region 1. Philadelphia Fuel Facility & Materials Bafety Branch 80/06/24 ip
- --8007210179 Responds to NRC 800522 ltr re violations noted in IE Imap Rept 70-0033/80-04 Corrective actions route card for metal drums revised to show drums are approved only for contaminated metal waste SCHMENSFEIR, R Toxas Instruments, Inc. 80/06/12 2pp
- --8007210180 Forwards IE lnsp Rept 70-0033/80-06 on 800421-25 & notice of violation BHITH,0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/22 2pp
- --8007210184 Notice of violation from insp on 800421-25 * Region 1. Philadelphia, Office of the Director 80/05/22 1p
- --B007210195 IE insp Rept 70-0033/80-06 on 800491-25 Noncompliance noted failure to fullow posted max safe quality at work station KINNEY, W Region i, Philadelphia, Office of the Director CROCKER, H H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/22 9pp
- 8007210098 Requests payment of administrative amond fee in connection w/800618 request for delay in submitting safeguards plan WEISS, J D License Fee Management Branch 80/07/09 ip
- 8007220527 Advises that requirements for IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys w/Loss of Offsite Power" have been completed SHERNAN.F L. Texas Instruments, Inc. BO/07/16 Jpp
- 8007250445 Responds to IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power" Bulletin requirements have been completed Phone operating on emergency power was successfully tested w/NRC on 800716 SHERMAN, F L lexas Instruments, Inc. 80/07/21 3pp

- DOCKET 70-0036 COMBUSTION ENGINEERING, INC.
- BO07170619 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Hater Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER. J Q Region 3. Chicago. Office of the Director BO/06/24

DOCKET 70-0135 BARCOCK & WILCOX CO

- B007140644 Forwards IE Insp Rept 70-0135/80-08 & 70-364/80-07 on B00303-28 No noncompliance noted MARTIN, W C Region 1, Philadelphia, Safeguards Branch 80/05/21 200
- 800714064B IE Insp Repts 70-0135/80-08 & 70-0364/80-07 on 800303-28 No noncompliance noted Hajor areas inspected matl control & accounting, physical security, health & industrial safety info withheld (ref 10CFR2 790) JOYNER, J H. KUSHNER, N L Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/05/08 9pp
- B007020002 Ack receipt of 800512 ltr informing NRC of steps taken to satisfy commitment made per IE lnsp Repts 70-0135/80-09 & 70-034/80-08 MARTIN.W. O Region 1. Philadelphia, Safeguards Branch 80/05/28
- --8007020005 Confirms action taken to implement commitment made per IE Insp Repts 70-0135/80-09 & 70-0364/80-08 Corrective actions revised low enriched U physical inventory to incorporate commitment to remeasure each uranyl nitrate tank AUSTIN.M A. Babcock & Wilcox Co., Nuclear Material Div. 80/05/12 is
- --8007020012 IE Insp Repts 70-0135/80-09 & 70-0364/80-08 on 800317-20 & 24-24. No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref IOCFR2 790)

 JOYNER, J.H. Region 1. Philadelphia, Bafeguards Branch HOLODY, D. J. Region 1, Philadelphia, Office of the Director 80/04/17. ip
- 8007170522 Forwards IE Insp Repts 70-0135/80-13 & 70-0364/80-12 on 800505-09.No noncompliance noted MARTIN.W. O Region 1. Philadelphia, Safeguards Branch 80/05/28 Zap.
- 8007140598 Responds to 800114 ltr requesting exemption from 100FR73 requirements Applicability of regulation should be determined for various types of BNN waste & appropriate application should be made MCCORKLE. G W. Physical Security Licensing Branch 80/06/12 2pp
- B007220211 Forwards Amend 8 to License SNM-145, revising Spec 1-4 (organization) & Spec 1-5 (Tech Specs & control sys) of conditions section of application FAGE, R. O Uranium Fuel Licensing Branch 80/06/23 2pp

- BOO7170632 Responds to 800625 ltr re request for extension to complete requirements of 10CFR/O 51 for low enriched U math balance period ending 800611 Licensee shall complete math balance by 800725
 PARTLOWIJ G Material Control Licensing Branch 80/07/O3 1p
- BOO71BO372 Ack receipt of BOO625 ltr requesting amend to License SNM-145 Approval was granted on BOO703 Amend requires administrative fee WEISGD License Fer Management Branch 80/07/08 ip
- DOCKET 70-0143 NUCLEAR FUEL SIRVICES, INC
- 8007170620 Appoints NJ Direks to coordinate personnel to evaluate MUF discrepancy at facility R Burnett will supervise NRC personnel at site Requests advisement of any resource problems to administrative t/or personnel support QUBSICKLE V Office of the Exerctive Director for Operations 79/09/18 ip
- 8003250864 Discusses 800205-07 site visit to assess effectiveness of new process monitoring requirements Due to incomplete feedstock dissolution, it of 15 dissolution batches alarmed Further review will be made during 800205 site visit JOY.D R Material Control Licensing Branch 80/03/03 ip
- BOO7110006 F01A request for 11 documents concerning facility COCHRAN.T B Natural Resources Defense Council 80/04/10 2pp
- 8007140513 Forwards 1E Insp Rept 70-0143/80-12 on 800317-0424 KENNA,W 8 Region 2, Atlanta, Safeguards Branch 80/05/16 2p
- --8007140527 IE Insp Rept 70-0143/80-12 on 800317-0424 No noncompliance noted Major areas inspected physical inventory observations & verification Details withheld (ref 10CTR2 790) CLAY.C.L., GILLFSPIE.F.P. Region 2. Atlanta. Safeguards Branch HODGES.J.W. Region 2. Atlanta. Office of the Director 80/05/15 to
- 8007280179 Safety evaluation re NFS proposed remedial actions & other alternatives re soil contamination Recommends contaminated Namnor Epring Branch stream bed be fenced until final action at decommissioning CROW, W T , SHUM, E Y Uranium Fuel Licensing Branch 80/06/06 13pp
- --8007280184 Forwards "Investigation Progress Rept of Soil Contamination (Former Croek Bod) at NFG-Erwin " HICHELIC J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) BO/02/04 1p
- --8007880187 "Investigation Progress Rept of Soil Contamination (Former Creek Bed) at NFS-Erwin " * Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80/01/31
- B007250376 Disapprovos of decision reached by NRC re continued operations of NFB facility Due to labor conflict & licensing violations, facility operated less than six months during 1979 Quality production important in such facility SHERBONDY, B.N. Affiliation Unknown 80/06/10 3pp
- B007010105 Ack receipt of 800514 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-08 KENNA.W B Region 2, Atlanta. Safeguards Branch 80/06/11 1p
- --B007010109 Responds to NRC B0042B lir re violations noted in IE Insp Rept 70-0143/60-08 Corrective actions withheld (ref 10CFR2 790) MANSER.W C Nuclear Fuel Services. Inc (subs of Gotty Dil Co) B0/05/14 in
- --B007010117 Forwards IE (nsp Rept 70-(143/80-08 on 800311-14 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA W II Region 2, Atlanta, Safeguards Branch 80/04/28 2pp
- ~-8007010125 IE Insp Rept 70-0143/60-08 on 8003(1-14 Nancompliance noted failure to follow procedures Details withheld (ref 100FR2 790) PERNY, C. D., GULLESPIE. F.P. Region 2. Atlanta, Safeguards Branch 80/04/28 Ip
- 8007010221 Responds to 800603 request for change in mot1 balance area structure re Plant [I Change is arceptable Lirense Condition 2 6 is added to Amend MPP-1 of License SNM-124 PARTLOW, J O Material Control Licensing Branch 80/06/17 ip

!

- 8007030292 Ack receipt of IE Insp Rept 70-0143/80-15 No proprietary info MANSER.M C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 80/06/17 ip
- ---8007030295 Forwards IE Insp Rept 70--0143/80-15 on 800513-16 No noncompliance noted KENNA, W B Region 2. Atlanta, Safeguards Branch 80/06/03 2pp
- B007020729 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 80/06/18
- 8007180555 Forwards Revision 14 to fundamental nuclear mati control plan.Ltr & revision withheld (ref 10CFR2 770) HENSLEY.K D Nuclear Fuel Services, Inc (subs of Getty Oil Co > 80/06/18 2pp.
- 8007020258 Reports manhours used in reviewing 790828 application for amend of License BNM-124
 DELANEY, J. C. Uranium Fuel Licensing Branch 80/06/19 ip
- 80070R0304 Reports manhours used in reviewing 790330 application for amend of License SMN-124
 DELANEY.J.C Uranium Fuel Licensing Branch 80/06/19 ip
- 8007070010 Ack receipt of 800309 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-04 O'REILLY, J. P. Region 2. Atlanta. Office of the Director 80/06/19 is.

- ---8007070017 Notice of violation from insp on 800221 * Region 2, Atlanta, Office of the Director 80/04/16 2pp
- ---B007070019 IE Imap Rept 70-0143/80-04 on 800221 Noncompliance noted failure to transfer SMM in accordance w/terms & conditions of recipient radioactive math license & to adequately survey package prior to shipment & transfer.

 DAVIS.J H Region 2. Atlanta, Office of the Director GIBSON, A Region 2. Atlanta, Fuel Facility & Materials Bafety Branch B0/04/14 Spp.
- 8007140078 Forwards IE Insp Rept 70-0143/80-17 on 800424-0523 No noncompliance noted KENNA, M. B. Region 2, Atlanta, Safeguards Branch 80/06/24. 1p.
- 8007180852 Discusses Commission order allowing resumption of operation w/relaxed conditions & granting post-hearing alternative for which NRDC responded w/o Commission subsequent action Urges that willtany function exception not be invoked WEIBB.E R Sheldon, Harmon & Weiss 80/06/24 2pp
- 8007170154 Forwards IE Circular 80-14, "Radioective Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required. O'REILLY, J. P., Region 2, Atlanta, Office of the Director 80/06/24 1p.
- 8007140038 Ack receipt of 800603 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/80-14 KENNA: H. B. Region 2. Atlanta. Bafeguards Branch 80/06/25 ip

- ---8007140064 Responds to NRC 800514 ltr re violations noted in IE Insp Rept 70-0143/80-14 Corrective actions withheld (ref 10CFR2 790) HANSER, W C Huclear Fuel Services, Inc (subs of Getty Dil Co) 80/06/03 1p
- --B007140047 Forwards IE Insp Rept 70-0143/B0-14 on B00422-25 & notice of violation Notice of violation withheld (ref 10CFR2 770)

 KENNA.W B Region 2. Atlanta, Safeguards Branch B0/05/14 2pp
- --8007140073 IE Insp Rept 70-0143/80-14 on 800422-25 Noncompliance noted failure to notify NRC of change made to matl control & accounting program within 2 months of change Details withheld (ref 10CFR2 790)

 BATES.J W Region 2, Atlanta. Office of the Director GILLESPIE, F P Region 2, Atlanta, Safeguards Branch 80/05/14
- 8007110584 Grants 800613 request, w/NRC mods, for delay in determining U inventory difference value re 800527 highly enriched U physical inventory of Plant 1 Conditions added to Amend MPP-1 of License SNM-124 BURNETT, R F Division of Safeguards 80/06/26 2pp
- 8007020637 Forwards process monitoring charts which provide summary required by NRC 800626 ltr Encl withheld (ref 10CFR2 790) MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Dil Co) 80/06/27 ip
- 8007020445 Note forwarding corrected version of Commission 800626 memorandum & order, CLI-80-27 & Commission 800627 notice of hearing in Liconse SNM-124 proceeding # Docketing & Services Branch 80/06/27 1p
- --8007020547 Corrected memorandum & order.CLI-80-27, granting NRDC 800205 request for hearing re whether License SNM-124 should be revoked Contemplates informal procedural framework due to sensitive military issues re weapons enriched w/U CHILK.S J Office of the Secretary of the Commission 80/05/25
- --8007020556 Corrected notice of legislative hearing in response to NRDC 800206 request, re revocation of License SNM-124 Written factual & legal testimony due by 800901, suggestions by 800915 Oral argument scheduled for 801015-1101 CHILK, S. J. Office of the Secretary of the Commission 80/06/27
- --8007020460 "Amend to Rules of General Applicability Providing Exception from Procedues for Adjudications re Conduct of Military or Foreign Affairs Functions." IOCFR2 immediately offective final rule Permits more flexible due process limits
 CHILK.S J Office of the Secretary of the Commission BD/06/26
- 8007070333 Forwards NFS QA program re shipping packages for radioactive math per 800424 request MICHEL-C J Nuclear Fuel Services. Inc (subs of Getty Dil Co) 80/06/27 io
- --8007070335 GA program for shipping packages for radioactive matl

 * Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/06/13,
 21nc.
- BOO710000B Add1 response to FOIA request for documents re licensing of facility & transcripts of closed Commission meetings App A documents available in FDR Document I of App B & portions of Documents 2-21 withheld (ref FOIA Exemptions 3.4 & 5) FELTON.J M Division of Rules and Records 80/06/27 5pp
- --B007100013 Discusses application of inventory difference regression equation to Aug inventory Info withheld procedures for safeguarting nuclear matl & NRC prodectional advice, opinions & recommendations (ref FOIA Exemptions 4 & 5) MESSINDER, M Naterial Control & Accountability Development Branch 79709/26 Spp
- ---B007100020 Summary of B00102-03 meeting between util & NRC in Silver Bpring,MD re MCA license conditions applicable for resumed highly enriched U operations info partially withheld (ref FOIA Exemptions 4 & 5) Charts entl JOY,D Material Control Licensing Branch B0/01/10 ip
- --B007100023 Forwards matl balances covering inventory for 790B14-1004 Info withheld safeguards & security measures (ref FOIA Exemptions 3 & 4) HENSLEY, R.D. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 79/12/03 5pp

- --8007100028 Forwards detailed rept on current % planned projects designed to improve facility accountability sys & associated inventory difference results Rept withheld (ref FOIA Exemptions 3 & 4)
 TAYLOR, C.W. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/10/23 ip
- --B007100032 Discusses SECY-79-650A. "NRC Regulation of Highly Enriched U Operations at Facility " Lists add1 requirements needed if position taken by JF Ahearne in B00109 memo is adopted Info partially uithheld (ref FDIA Examption 3) HANRAHAN. E J Material Control Licensing Branch B0/01/11 2pp
- --B00710003B Sunmary of Commission 800114 meeting re SECY-79-650 & SECY-79-650A concerning facility Scope & quality of matl control & accounting elements would be improved Summarizes proposed actions Info partially withhald (ref FOJA Exemption 3) HANRAHAN, E. J. Material Control Licensing Branch B0/01/15 2pp
- --B007100044 Discusses 771004 inventory difference of high enrithed U exceeding limit of error constraint Forwards rept detailing causes contributing to inventory differences & corrective actions taken Rept withheld (ref FDIA Exemption 3) TAYLOR: C W Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) 7971/102 2pp
- --8007100052 Forwards comments on J9 Partlow 790525 ltr to KD Hensley Info withheld safeguards & security measures (ref FOIA Exemption 3) HENSLEY,K D Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 79/07/06 3pp
- ---9007100057 Submits list of recent mods at facility which upgraded matl accountability & control program Info withheld procedures for safeguarding licensed SNH (ref FOIA Exemption 4)

 JOY, D.R. Material Control Licensing Branch 79709/ii 2pp
- --B007100069 Forwards info status rept re 770814 inventory differences of highly enriched U exceeding limit of error constraint Info withheld procedures for safeguarding suctear matl (ref FDIA Exemption 4)
 HENSLEY,K D Nuclear Fuel Services, Inc. (subs. of Oetty Oli Co.)
 77/10/02 3pp
- --B007100076 Notifies of 790816 meeting w/util to discuss highly enriched U inventory difference past.present & Future Forwards
 listing of topics to inventory differences which will be included in discussions W/o encl
 BNITH.C N Hearing Branch 2 79/08/01 lp
- --B007100072 Summary of 790B16 meeting between util & NRC in Bethesda.MD re concerns of highly enriched U inventory difference behavior inventory difference is licensee problem info partially withheld (ref F01A Exemption 5)
 JOY.D Material Control Licensing Branch 79/08/21 2pp
- ---80071000B1 Summary of 790B16 meeting w/util Lists major util concerns including improving of accounting sys Majority of meeting spont on reporting status of NRC questions Info partially withhold (ref FOIA Exemption 5)
 PARTLOW.J G Material Control Licensing Branch 79/08/17 2pp
- 8007110004 Responds to FOIA request for 11 documents concerning facility Items 2.3 & 5-10 have been addressed in earlier NRC responses Attachment II of Document 11 withheld (ref FOIA Exemption 4 & 100FR2 790)
 FELTON, J M Davision of Rules and Records 60/06/27 2pp
- ---B007110007 New & revised conditions to Amend MPP-1 to License SNM-124 * Commission 80/01/21 11pp
- B007160B3B Ack receipt of B00603 % ii ltrs informing NRC of steps taken in response to concerns noted in IE Insp Repts 70-0143/79-47 & 70-0143/80-12 KENNA.H D Region 2, Atlanta. Safeguards Branch 80/06/27 ip
- --8007160843 Requests 60-day extension to respond to concerns identified in IE Insp Rept 70-0143/79-49
 MANSER,W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co)
 80/04/08 1p
- B007070191 Requests that Attachment A of Insp Rept 70-0143/B0-01 be withheld (ref 10LFR2 790) MANER, W C Nuclear Fuel Services, Inc (subs of Oetty Dil Co) B0/06/30 2pp
- B007070350 Responds to request for info pe contamination control program in SNM-0124. Amend 5 Provides revised personnel exit procedures & personnel surveys MANSER, U C Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/06/30 2pp

- B007150563 Forwards site security training plan, Revision 1 Changes make corrections on site-specific implementation & do not lessen effectiveness of site security training or physical protection plan Revision 1 withheld (ref 10CFR2 770) MICHELC J Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) B0/07/01 1p
- BOO7210039 Notifies that fee submitted w/790330 application for Amend 5 to License SNM-124 will be partially refunded in accordance w/manpower expenditures review MILLER.W D License Fee Management Branch 80/07/01 ip
- BOO71B030B Forwards 1E Insp Rept 70-0143/B0-19 on B00616-19 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA,W B Region 2, Atlanta, Safeguards Branch B0/07/07 2pp
- --B007iB0316 IE Insp Rept 70-0143/B0-19 on B00616-19 Noncompliance noted failure to annually recertify one new std in each NDA series & failure to make process & engineering studies Details withheld (ref IOCFR2 790)

 DATES, J W Region 2, Atlanta, Office of the Director GILLEBPIE.F P Region 2, Atlanta, Safeguards Dranch 80/07/03 to
- B007150518 Forwards revised Page 139 to Amend Request 78-5 submitted 780829 & resubmitted as Amend Request 80-1 on 800124 Amend can be issued wetermption from Licenso SNM-124 Condition 29 requested on 791107 MICHELC.J Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/07/09 2pp
- --8007150520 Requests License SNM-124 be amended to allow transport of enriched V outside confines of plant Shipments will be limited to 5 kg U-235 MICHEL,C F Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) 78/06/27
- BD07220003 Answer to Commission notice of hearing stating NRC willingness to participate as party Svc may be made on QH Cunningham & RL Funner on behalf of NRC Certificate of Svc encl
 CUNNINGHAM. G H Regulations Division 80/07/14 2pp
- B007220243 Add1 response to F01A request for info concerning facility
 Nonexempt portions of documents listed in app are located in
 DC PDR Documents i.2 & 3 partially withheld (ref F01A
 Exemptions 4 & 5) Documents 5 & 6 are undergoing review
 FELTON,J M Division of Rules and Records 80/07/16 3pp
- --800722024B Revised conditions to Amend MPP-1 to License SNM-124 BURNETT.R F Division of Bafeguards 80/02/01 3pp
- ---8007220251 Discusses 800227-29 site visit to further evaluate effectiveness of new process monitoring license conditions. Info partially withheld (ref FOIA Exemptions 4 & 5) Rosponses to M Udall questions 4td 800306 encl
 JOY.D R Material Control Licensing Branch 80/03/11 4pp
- 8007290072 Notifies of issuance of Amend 7 to License SNM-124, providing exemption from requirement that emergency evacuation drill be conducted at least annually for each shift PAGE.R G Uranium Recovery Licensing Branch 80/07/16 ip
- --8007290083 Safety evaluation supporting Amend 7 to License SNM-124 DELANEY.J C Uranium Recovery Licensing Branch CROW.W T Uranium Fuel Licensing Branch 80/07/16 ip
- BOO7300092 Add1 response to FOIA request for mat1 received, considered or approved by Commission during consideration of facility inventory Info partially withheld security measures & restricted data (ref FOIA Examptions 3 & 4)
 FELTON, J M Division of Rules and Records BO/07/16 3p
- --8007300094 Discusses reporting of facility 790818-1004 inventory difference Draft physical protection license conditions encl License condition partially withheld safeguarding procedures (ref FOIA Exemption 4) DIRCKS,W J Office of Nuclear Material Safety & Safeguards 79/10/22 2pp
- ---8007300103 Discusses facility inventory difference for 790618-0818 NFB is ceasing all production operations & preparing for plant inventory in accordance w/NMSS orders Info partially withheld restricted data (ref FOIA Exemption 3) DIRCKS, H J Office of Nuclear Material Safety & Safeguards 79/09/17 1p

- 6007280552 Forwards response to NRC 800624 itr re violations noted in IE Insp Rept 70-0143/80-20 Response withheld (ref 10CFR2 790)
 MANSR, W C Nuclear Fuel Services, Inc. (subs. of Cetto Dil Co.)
 - MANSER, W.C. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/07/18 1p
- BOO7250464 Forwards response to IE Insp Rept 70-0143/80-19 Response withheld (ref 10CFR2 790) MANSER,W C Nuclear Fuel Services, Inc (subs of Oetty Gil Co) 80/07/21 1p
- B007270713 Responds to NRC 800626 ltr re IE Insp Rept 70-0143/80-13 Attachment states corrective action takes W/o encl MANBER.W C Nuclear Fuel Services, Inc (subs of Oetty Oil Co) 80/07/21 ip
- 6007290847 Forwards general soil decontamination plan.per 800715 request MICHEL.C J Nuclear Fuel Services. Inc (subs of Getty Dil Co) 80/07/23. 4pp

DOCKET 70-0157 TEXAS, UNIV. OF

- 8007210320 Responds to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " Wastes are deposited in plastic bag in lined steel containers Waste collection contractor is responsible for ultimate disposal BURACK, J A Texas, Univ of. 79/09/04 2pp

DOCKET 70-0184 WESTINGHOUSE ELECTRIC CORP

- B007230014 Advises of correct address for future correspondence in response to 800602 Itr Revised radiation safety manual has been forwarded to Hatle Licensing Branch KINNEMAN.J D Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/07/02. 19

DOCKET 70-0203 NOTRE DAME, UNIV OF

- 8007010047 Ack receipt of 800528 ltr informing NRC of steps taken to correct noncompliance identified in 800513 ltr.Discusses licensee denial of noncompliance Item 10, 81x-month leak test is required Supporting documentation encl KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/09
- ---8007010060 Requests that provision for possession of Pu-beryllium be removed from License SNM-198 Also requests designation of TJ Hirons as course instructor & only person responsible for handling leak testing.

 GAY, N. R. Notre Dame, Univ. of 61/12/21 ip

DOCKET 70-0364 PARKE TOWNSHIP SITE, BABCOCK & WILCOX CD

- B007150809 Forwards application for amend to License SNM-414, consisting of revised pages to Chapter 3 of license re site & facilities description
 AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div B0/05/09
 20e
- 8007140644 Forwards IE Insp Rept 70-0135/80-08 & 70-364/80-07 on 800303-28, No noncompliance noted MARTIN, W G Region 1, Philadelphia, Safeguards Branch 80/05/21 2pp.

- --B007140648 IE Insp Repts 70-0135/80-08 % 70-0364/80-07 on B00303-28
 No moncompliance noted Major areas inspected math control & accounting, physical security, health % industrial safety Info withhold (ref 10CFR2 770)

 JOYNER, J. H. KUSHNER, W.L. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/05/08 9pp
- B007020002 Ack receipt of 800512 ltr informing NRC of steps taken to satisfy commitment made per IE Insp Repts 70-0135/80-09 & 70-0364/80-08

 MARTIN, W. G. Region i, Philadelphia, Safeguards Branch. 80/05/28
- --8007020005 Confirms action taken to implement commitment made per IE Insp Repts 70-0135/80-09 & 70-0364/80-08 Corrective actions revised low enriched U physical inventory to incorporate commitment to remeasure each uranyl nitrate tank AUSTIN, M A Babcock & Wilcox Co , Nuclear Material Div 80/05/12
- --8007020008 Forwards IE Insp Repts 70-0135/80-09 & 70-0344/80-08 on 800317-20 & 24-26 No noncompliance noted MARTIN.W C Region 1, Philadelphia, Safeguards Branch 80/04/22 20e
- --8007020012 IE Insp Repts 70-0135/80-09 & 70-0364/80-08 on 800317-20 & 24-26 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 10GFR2 790)

 JOYNER, J H Region i, Philadelphia, Safeguards Branch HOLODY, D J Region i, Philadelphia, Office of the Director 80/04/17 ip
- 8007170622 Forwards IE Insp Repts 70-0135/80-13 & 70-0364/80-12 on B00505-09 No noncompliance noted MARTIN.W G Region I, Philadelphia, Safeguards Branch B0/05/20 200
- --B007170630 IE Insp Repts 70-0135/80-13 & 70-0364/80-12 on 800505-09 No noncompliance noted Major areas inspected physical inventory & Internal controls Details withheld (ref 10CFR2 790) BISSETT,P H , JUYNER, J H Region 1, Philadelphia, Office of the Director 80/03/27 ip
- 800714059B Responds to 800116 ltr requesting exemption from 10CFR73 requirements Applicability of regulation should be determined for various types of SNM waste & appropriate application should be made MCCORKLE, G W Physical Security Licensing Branch 80/06/12 2pp
- 8007020612 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power" Written response required GRIER, B H Region I, Philadelphia, Dffice of the Director 80/06/18 1p
- 8007150128 Ack receipt of 800611 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/79-24 GRIER.B H Region 1, Philadelphia, Office of the Director 80/06/19 ip
- --B007150135 Responds to NRC B00115 ltr re viblations noted in 1E Insp. Rept 70-0364/79-24 Corrective actions justification submitted re noncompliance
 AUSTIN,M A Babcock & Wilcox Co , Nuclear Material Div B0/06/11
- --8007150141 Ack receipt of 791203 ltr informing of corrective actions taken re IE Insp Rept 70-0364/79-24 Requests written statement re Item B including corrective stops taken & date when full compliance will be achieved GRIER.B.H. Region 1. Philadelphia, Office of the Director 80/01/15 2pp
- --B00715014B Provides specific responses & corrective actions redisclosed items resulting from IE Insp 70-0364/79-24 on 790924-28 Routine surveys of Nuclear Matls & Mfg Div vault area being performed & cited organizational changes begun AUSTIN M A Babcock & Wilcox Co , Nuclear Material Div 79/12/03 App
- ---B007150150 Forwards IE Insp Rept 70-0364/79-24 on 790924-2B & notice violation
 SMITH O H Region 1, Philadelphia, Fuel Facility & Materials |
 Safety Branch 79/11/08 2pp
- --B007150156 Notice of violation from insp on 790924-28
 * Region 1, Philadelphia. Office of the Director 79/11/06 29:

- --8007150163 IE [nsp Rept 70-0364/79-24 on 790924-28 Noncompliance noted failure to prescribe special measures to control personnel dose to radiation in vault & failure to have written evaluation for organizational change CROCKER.H W Region i. Philadelphia. Fuel Facility & Materials Safety Branch ROTH, J Region i. Philadelphia. Office of the Director 79/11/06 ISpp
- 8007160780 Forwards IE Circular 80~14. "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/24 | 19
- B007210109 Responds to 800618 meeting re decommissioning & decontamination of Facility NRC will not proceed w/reviews of 800225 fundamental nuclear math control plan for License SMM-414 Revised plan expected by 800731 PARTLOW, J Q Material Control Licensing Branch 80/07/03 ip
- 8007210094 Advises licensee that NRC will refund portion of fee paid for review & approval of 800212.0318 & 0415 applications for license amend License Condition 2 i 2 was added to Amend MPP-1 to License SNM-414 on 800604 MILLER.W D License Fee Management Branch 80/07/10 ip
- 8007230712 Responds to 800624 request for reduction in number of nondestructive assay stds to be maintained during decommissioning Three stds are sufficient for calibr & control of nondestructive measurement sys PARTLOW.J 9 Material Control Licensing Branch 80/07/16 ip

DOCKET 70-0371 UNITED NUCLEAR CORP

- 8007230119 Forwards IE Insp Rept 70~0371/80-08 on 800512-15 No noncompliance noted MARTIN.W G. Region 1, Philadelphia, Safeguards Branch 80/06/11 2pp
- --8007230124 IE Insp Rept 70-0371/80-08 on 800512-15 No noncompliance noted Major areas inspected licensee action on previous insp findings & records & repts MOLTNER,E , JOYNER,J H Region i, Philadelphia, Safeguards Branch 80/04/09 ip
- 8007020617 Forwards TE Bulletin BO-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required ORIER, B H Region 1, Philadelphia. Office of the Director 80/96/18 1p
- 8007160846 Forwards IE Circular 80-14, "Redioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required GAIER, B H Region 1, Philadelphia, Office of the Director 80706/24 1p
- B007180058 Ack receipt of 800610 ltr informing NRC of steps taken to meet commitment per IE lasp Rept 70-0371/80-04 MARTIN W G Region 1. Philadelphia. Safeguards Branch 80/06/27 in
- --9007180066 Responds to NRC B00920 ltr re-commitment made in response to IE Insp Rept 70-0371/80-06 Corrective actions attached form used to record receipt of bottles of sludge W/o form GANLEY.D C United Nuclear Corp Naval Products Div B0/06/10, in
- --8007180071 Disrusses IE insp of Liconse SNM-368 & forwards IE Insp Rept 70-0371/80-06 on 800407-11 & 14-18 No noncompliance noted MARTIN-W O Region 1, Philadelphia, Bafeguards Branch 80/05/20 Epp
- --8007;80082 IE Insp Rept 70-0371/80-06 on 800407-11 & 14-18 No noncompliance noted Major areas inspected inventory verification. Reconciliation. Measurement & statistical control Details withheld (ref 10CFR2 790)

 JOYNER, J. H., BISSETT. P. Region 1. Philadelphia, Safeguards Branch HOLGOY. D. Region 1. Philadelphia, Office of the Director 80/05/12 1p
- B007280090 Notifies that 800616 request for amend to License SNN-368 requires fee
 WEISS: D License Fee Management Branch 80/07/03 ip
- 8007250363 Notifies that 800626 request re shutdown & scrap processing has been classified as minor amend to License SNM-368 Minor amend fee is required

 WEISS.D License Fee Management Branch 80/07/08 ip

attendal \

- BOO7250053 Requests notification of approx meeting date to discuss status of possible scrap recovery contract between NRC & facilities NRC has proposed Aug or Sept 1780 meeting date in Silver Spring.MD PARTLOW.J G Material Control Licensing Branch 80/07/13 1p
- DOCKET 70-0398 COMMERCE, DEPT OF
- BOO7140B31 Forwards IR Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required. GRIER, B H Region 1, Philadelphia, Office of the Director BO/06/24 1p

DOCKET 70-0474 UPBALA COLLEGE

- BO07310291 Notifies of expired License SNM-450 & discusses actions to be taken by licenses CROCKER, H & Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 80/05/07 2pp
- DOCKET 70-0572 MONSANTO RESEARCH CORP
- 8007020476 Advises that request for exemption to reduce allowable isotopic concentration of Pu-238 from 80% to 78% has been granted BURNETT.R F Division of Safeguards 80/04/17 ip

DOCKET 70-0625 HOWARD UNIV

- B0070101B0 Ack receipt of B00425 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 30-11063/80-01.
 30-01321/80-01.40-6789/80-01 & 70-0625/80-01
 BMITH, 0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch B0/05/28 ip
- ---B007010185 Responds to NRC 800328 ltr re violations noted in IE Insp Repts 30-11063/80-01,30-01321/80-01,40-6789/80-01 & 70-0625/80-01 Corrective actions efficient concentrations evaluated & Cf-232 source tosted ALEXIB.C P Howard Univ 80/04/25 2pp
- --8007010197 Discusses IE Insp Repts 30-11043/80-01,30-01321/80-01, 40-6789/80-01 & 70-0625/80-01 on 800320-21 & forwards notice of violation SHITH, 0 H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/03/28 2pp
- --8007010209 Notice of violation from insp on 800320-21 Noncompliance noted failure to conduct required surveys, Cf-252 source stored in unlocked room & food stored in refrigerator w/radioisotopes
 * Region i, Philadelphia, Office of the Director 80/03/28 2pp

DOCKET 70-0687 UNION CARBIDE CORP

- 80070R0341 Reports completion of criticality review of 800602 application Recommends that nuclear criticality safety aspects of application be approved PAGE.R 9 Uranium Fuel Licensing Branch 80/06/19 2pp
- 8007i40849 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required GRIER, B H Region i, Philadelphia, Office of the Director, 80/06/24 ip
- B007210289 Ack receipt of B00520 itr informing NRC of steps taken to correct violations noted in IE Imap Rept 70-0487/80-03 ORIER, B Region i, Philadelphia, Office of the Director, 80/04/30 ip
- --8007210293 Responds to NRC 800423 ltr re violations noted in IE Insp Rept 70-0687/80-03 Corrective actions will maintain air sampling records MCODVERN.J J Union Carbide Corp 80/05/20 ip
- ---9007210295 Forwards IE Insp Rept 70-0687/80-03 on 800227-29 & notice of violation SNITH, G H. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 80/04/23 2pp.

- -- 8007210298 Notice of violation from insp on BOOR27-29 Region 1, Philadelphia, Office of the Director 80/04/16 1p
- \$807210074 Notifies that 791129 request for route approval involving spont fuel shipment from Tuxedo.NY to Bavannah River reprocessing site in SC is subj to license fee schedule Review completed on B00903 MILLER,W 0 License Fee Management Branch 80/07/03 1p
- 8007230148 EN-BO-012A on B00711, order imposing civil penalty of \$1,000 mas issued. After consideration of licensee response, IE concluded that one item of noncompliance did occur BROCKETT, T W. THOMPSON, D. Office of Inspection & Enforcement, Office of the Director 80/07/11 ip
- 8007300038 Ack receipt of 800428 ltr in response to NRC 800407 notice of violation & notice of proposed imposition of civil penalties Also forwards order imposing civil monetary penalty. STELLO, V. NRC Regional Offices 80/07/11 2pp
- G007280101 Returns check which accompanied B00707 ltr Fes for same request was received on B00413 WEIBS.D License Fee Management Branch. 80/07/17 1p.

DOCKET 70-0734 GENERAL ATOMIC CO.

- 800701025# Advises that fee for approval of highly enriched U shipment has not been received Management Branch 80/06/10 ip
- @007030009 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Netification Sys (ENS) M/Loss of Offsite Power " Written response required.
 ENGELEBIN R. H Region 5, San Francisco, Office of the Director 80/06/18 1p
- B007240076 Responds to NRC B00424 site-specific questions re details of physical protection sys Response withheld (ref 10CFR2 770) MCCORKLE. 0 W Physical Becurity Licensing Branch B0/06/20 ip
- 8007180274 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 8ys & Resultant Internal Contamination of Personnel," No written response required ENPELMENT H. Ragion 5, Ban Francisco, Office of the Director MR/OA/24, 1p.
- 8007230081 Requests resolution of outstanding fee issues for cartain physical security-related documents & emergency plans Memo dtd 790910 re 790220 guard training plan submitted by GA Co License Fee Management Branch B0/07/16 2pp
- DOCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO.
- B007240072 Responds to B00421 ltr requesting change to spent fuel routs approved by NRC B00417 ltr Proposed change has been reviewed & approved Attachment to B00421 withheld (ref 100FR2 790) HCCORKLE, Q W. Physical Security Licensing Branch 80/04/30 ip
- 8007180305 Forwards IE Circular 80~14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination be Personnel " No written response required EMGELKEN.R H. Region 5, Ban Francisco, Uffice of the Director. 80/06/24.
- 8007170621 Notifies that 791228 request for route approval involving apent fuel shipment from Waterford.CT to Pleasanton.CA is subj to Commission license fee schedule Raview completed on 800417. MILLER, W. Q. License Fee Management Branch 80/07/03 ip.
- 8007280027 Notifies that amend fee is required for 800620 request reuse of SNM putside secured areas
 WEISS, D. License Fee Management Branch 80/07/08, ip

8007250161 Forwards NRC 800522 fee request for review of physical protection plan for SNM of moderate strategic significance Requests payment within 15 days WEISS.D License Fee Management Branch 80/07/16 ip

DOCKET 70-0820 UNITED NUCLEAR CORP

- 8007250486 Forwards IE insp Rept 70-0820/80-06 on 800513-15 No noncompliance noted Cover sheet only encl (ref 10CFR2 770) MARTIN. W O Region 1, Philadelphia, Safeguards Branch 80/0 80706/17
- --B007250494 IE Insp Rept 70-0820/80-06 on B00513-15 No noncompliance noted Major areas inspected organization, shipping & receiving, measurements & statistical controls Details withheld (ref IOCFR2 790) COHEN, I., ZIBULSKY, H., JOYNER, J. H. Region i, Philadelphia, Office of the Director 80/06/13 ip
- 8007020622 Forwards IE Bulletin 80-15. "Possible Loss of Emergency Nutification Sys (ENS) W/Loss of Offsite Power " Written rasponse required GRIER, B H Region 1, Philadelphia, Office of the Director 80/06/18 1p
- 8007160845 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Deminoralized Water Bys & Resultant Internal Contamination of Personnel" No written response required GRIER,8 H Region 1, Philadelphia, Office of the Director BO/06/24 ip
- 8007210106 Requests payment of minor safeguards amend fee in connection w/800626 request for exemption from requirements of 10CFR73 20.73 45 & 73 46 Request has been classified as requiring minor amend to Liconso SMM-777 H6168,D Licenso Fee Management Branch 80/07/08 Ip

DOCKET 70-0824 BABCOCK & WILCOX CO

- B007010006 Forwards replacement pages to BAM-381 for License SNM-778 Encl responds to NRC questions arising from 800218 request to amend license to allow const & use of temporary waste storage facility DLSENAF Babo Babcock & Wilcox Co 80/03/25 tp
- ---BD07010010 Replacement pages for BAW-381, "Demonstration & Conditions for License SNM-778," May 1970 * Babcock & Wilcox Co BAW-318 A12 R10 70/03/31 7pp
- --8007020350 Replacement page for BAW-381, "Demonstration & Conditions for License SNM-778," Dec 1978 * Babcock & Wilcox Co BAW-381 78/12/31 9pp
- B007150839 Lists costs incurred & menhours expended in review of 800218 application & 800325 & 0408 suppls for amend to License SNM-78 KETZLACH, N Uranium Fuel Licensing Branch 80/05/30 ip
- 8007020337 Forwards proposed license conditions & comments on license ranswal application W/o encl CRDW,W T Uranium Fuel Licensing Branch 80/06/10 3pp
- 8007010293 Requests extension until 800701 to satisfy Item 3 of Insp Rept 70-0824/80-01 Required forms re hazardous math not yet received from printer
 DLBEN, A.F. Babcock & Wilcox Co 80/06/13 tp
- --8007010295 Forwards IE Insp Rept 70-0824/80-01 No noncompliance noted KENNA: W R Region 2: Atlanta: Safeguards Branch 80/05/21, 2pp
- --8007010301 |E Insp Rept 70-0824/80-01 on 800429-0502 No mancampliance outcloser in imag nept to being an BOD929-0502 No mancompliant noted Major areas imagected facility changes & mode, operations review, followup on unresolved items & followup on items of noncompliance with the Birector KENNA, W B Region 2. Atlanta, Office of the Director KENNA, W B Region 2. Atlanta, Gafeguards Branch 80/05/19 7pp
- 8007020723 Forwards IE Dulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, y P. Ragion 2, Atlanta, Office of the Director. 80/06. Region 2, Atlanta, Office of the Director. 80/06/18

- 8007170148 Forwards IE Circular 80-14, "Radinactive Contamination of Plant Demineralised Water Sys & Resultant Internal Contamination of Personnel "No written response required O'REILLY, J.P. Region 2. Atlanta. Office of the Director 80/06/24 ip
- B00721003B Notifies of fee required for review of 791205 request for route approval for shipment of spent fuel assemblies from Lynchburg Rosearch Ctr to Oconee Nuclear Power Station MILLER.W O License Fee Management Branch 80/07/02 ip
- 8007230648 Forwards revised NUREG-0561 amending interim rule for physical protection of spent fuel in transit Addl areas have been designated as heavily populated Routes approved for 864 encl New requirements apply 800703 W/o encl MCCORKLE, G.W. Physical Security Licensing Branch 80/07/03 ip
- DOCKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP
- 8007170300 Forwards IE Insp Repts 70-0925/80-02 & 70-1193/80-02 on 800407-08 & notice of violation DAVIS:AB Region 3. Chicago, Fuel Facility & Materials Gafety Branch 80/06/16 2pp
- ---8007170305 Notice of violation from insp on 800407-08
 * Region 3. Chicago. Office of the Director 80/06/12 19
- -8007170310 IE Insp Repts 70-0929/80-02 & 70-1193/80-02 on 800407-08 Noncompliance noted empty.open 55-gallon drums were found in waste shipment storage Room 12i DUBRY.NE Region 3. Chicago. Office of the Director FIBHER.W | Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/06/12 10pp
- 8007030023 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Natification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 80/06/18
- 8007110513 Forwards IE Insp Rept 70-0925/80-04 on 800610-12 No noncompliance noted MIND.J A Region 3. Chicago, Safeguards Branch 80/06/23 ip
- --8007110518 IE Insp Rept 70-0925/80-04 on 800610-12 No noncompliance noted Major areas inspected facility organization & operation, measurement & statistical details & physical inventory Details withheld (ref 10CFR2 790) HIMD, J.A. Region 3, Chicago, Safeguards Dranch PATTERSON, J.P. Region 3, Chicago, Diffice of the Director 80/06/20 ip
- 8007170800 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel "No written response required MEPPLER, J G Region 3, Chicago, Office of the Director 80/06/24
- 8007250626 Forwards survey map inadvertently omitted from IE Insp Repts 70-0925/80-02 & 70-1193/80-02 W/o encl DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Bafety Branch 80/07/08 ip
- 8007280710 Forwards survey map inadvertently omitted from IE Insp Repts 70-0725/80-02 & 70-1193/80-02 DAVIS,A B Region 3. Chicago, Fuel Facility & Materials Safety Branch 80/07/14 2pp
- 8007230549 Ack receipt of 800627 ltr informing NRC of steps taken to correct violations noted in IE imap repts
 DAVIS, A. B. Region 3. Chicago, Fuel Facility & Materials Safety
 Branch 80/07/15 ip
- --8007230564 Responds to NRC 800616 itr re violation noted in IE insp repts Corrective action empty drums removed from Room 121 r-NcGee Nuclear Corp 80/06/27 ip,

DOCKET 70-0984 PACIFIC NORTHWEST LAB

B007180283 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater Bys & Resultant Internal Contamination of Personnel " No written response required. ENGELKEN, R H Region 5, Ban Francisco, Office of the Director 80/06/24 ip

DOCKET 70-0997 WESTINGHOUSE ELECTRIC CORP

8007180338 Discusses IE Insp. Rept 70-0997/80-01 conducted on 800606 No noncompliance noted Major areas inspected, selective examinations of procedures & representative records, interviews w/personnel & measurements by inspector KINNEMAN.J D. Region i. Philadelphia, Fuel Facility & Materials.

Safety Branch 80/06/30 ip

DUCKET 70-1062 TODD SHIPYARDS CORP.

- 8007240228 Responds to IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial." No radwaste has been generated over past 5 yrs under License 8NM-1015. Radwaste generated under State of TX Licenses 8-871 & 9-1231, WINTERB.C E Todd Shipyards. 79/09/04 1p
- --B007240348 Forwards IE Bulletin 79-19, "Packaging of Low Level Radwaste for Transport & Burial " Bulletin requires action of licensee SEYFRIT,K V Region 4, Dallas, Office of the Director. 79/08/10
- 8007010056 Responds to 800422 memo by forwarding 800609 ltr to Todd Shippards w/guideline describing decontamination requirement to be met prior to termination of License BMT-1015, State of TX responsible for decontamination re raduate storage PAGE.R G Uranium Fuel Licensing Branch. 80/06/09 1p
- ---B007010281 Forwards "Quidelines for Decontamination of Facilities & Equipment Prior to Release for Unrestricted Use or Termination of Licenses for Byproduct Squres or BMM."
 Requirements to not apply to activities under TX license.
 PAGE.R 0 Uranium Fuel Licensing Branch. 80/06/09 ip

DOCKET 70-1100 COMBUSTION ENGINEERING, INC

- B007020097 Ack receipt of B00305 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-1100/80-02 & 30-03754/80-01 ORIER, B H Region i, Philadolphia, Office of the Director 80/09/30 Zpp
- --B007020103 Responds to NRC 800417 ltr re violations noted in IE Insp Repts 70-1100/80-02 & 30-03754/80-01 Facility does not concur w/inspector opinion requiring response to IE Bulletin 79-19 LICHTENBERGER Combustion Engineering, Inc. 80/05/05. ip.
- --8007020106 Forwards IE Insp Repts 70-1100/80-02 & 30-03754/80-01 on 800310-12 No noncompliance found Certain aspects of operation not conducted per IE Bulletin 79-19 requirements. SMITH/G H Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/04/17 2pp
- --B007020121 IE Insp Repts 70-1100/80-02 & 30-03754/80-01 on B00310-12
 No noncompliance nated Major areas inspected licensee
 response to IE Bulletin 79-19
 ROTH.J Region 1. Philadelphia, Office of the Director.
 CROCKER.H W Region 1. Philadelphia, Fuel Facility & Materials
 Gafety Branch 80/04/14 9pp
- 8007020107 Forwards add1 info supporting 800111 renswal application for Certificate of Compliance 9022, per NRC 800501 request Revised pages encl.

 LICHTENBERGER.H C-E Power Bystems 80/06/06 6pp

1

1 .

1

- ---8007020114 "Shipping Container "
 * C-E Power Systems 7499-776030. 79/06/13. ip
- B007160840 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Bys & Resultant Internal Contamination of Personnel " No written response required ORIER.B H Region 1. Philadelphia, Office of the Director. B0/06/24 1p

- 8007200733 Ack receipt of 800605 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70~1100/80-03 MARTIN, W. O Region i, Philadelphia, Safeguards Branch 80/07/09.
- --8007280743 Forwards IE Insp Rept 70-1100/80-03 on 800428-0501 & natice of violation. Notice of violation withheld (ref 10CFR2 790) MARTIN. W G. Region 1, Philadelphia, Safeguards Branch 80/05/22 20a.
- ---B0072B0746 IE Insp Rept 70-1100/80-03 on 800428-0501 Noncompliance noted failure to reject results outside calibr range of measurement sys Betails withheld (ref 10CRR 270) COMEN. I , DELLA RATTA, A Region i, Philadelphia, Office of the Director UDYNER, J. H. Region i, Philadelphia, Bafaguards Branch 80/05/17 ip.
- B007220423 Advises that quarterly reporting level of 18 uCi of airborne particulates was exceeded. During period B00330-0628, total quantity discharged was 22 23 uCi low enriched U Problem attributed to undersized absolute filters Filters replaced LICHTENBERGER. C-E Power Systems 80/07/10 2pp
- 8007290001 Forwards summary of 800617 meeting relactions to dispose of radwaste found in remote location on Windsor site SMITH.O.H. Region i, Philadelphia, Fuel Fecility & Materials Safety Branch. 80/07/11. 1p.
- --B007270003 Bummary of 800617 meeting w/C-E in King of Prussia PA reactions to dispose of radwaste matl found in remote location on Mindsor sits.

 ROTH J Region i, Philadelphia, Office of the Director B0/07/11

SOCKET 70-1113 GENERAL ELECTRIC CO.

- 9007150027 Ack receipt of 800407 & 0613 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/80-03 KENNA, W. B. Region 2, Atlanta, Befeguards Branch 80/06/17 ip
- ---8007180033 Responds to NRC B00304 ltr re-violations noted in IE Insp. Rept 70-1113/80-03 Corrective actions trailer returned to Wilmington and dept correctly placarded & labels affixed to overpack surface.

 KAPLAN, A L. General Electric Co. 80/04/07. Bpp
- ---8007150038 Forwards IE Insp Rept 70-1113/80-03 on 800129-30 & 0211-12 & notice of violation O'REJLLY, J P Region 2, Atlanta, Office of the Director 80/03/04 3pp.
- --8007150043 Notice of violation form insp on 800127-30 & 0211-12 * Region 2, Atlanta. Office of the Director 80/03/03 2pp
- --B007180049 IE Insp Rept 70-1113/80-03 on 800129-30 & 0211-12
 Noncompliance noted failure to properly label, provide
 placerds & describe in shipping documents shipment of SNM
 STEELE,P W , CLAY,F L Region 2, Atlanta, Office of the Director
 KAHLE,J B Region 2, Atlanta, Safeguards Branch 80/03/03 24pp
- B007020732 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required.

 O'REILLY.J P. Region 2, Atlanta, Office of the Director 80/06/18
- 8007030228 Responds to 800327 itr concerning NRC request for emend fee for review of physical security plan for SNM. Amend fee is due Upon completion of review.cost will be reviewed & any overpayment refunded.

 MILLER.W.D. License Fee Menagement Branch 80/06/19 2pp.
- --8007030231 Discusses inconsistency of fee schedule. Assumes that discense amend fees would be charged for amends initiated by licensee rather than for new or revised requirements set upon licensee by NRC.
 KAPLAN: A L. General Electric Co 80/05/29 ip

- 8007070187 Approves Amend 13 to License SNM-1097, revising completic date for add1 details of decommissioning plan Details must be provided within 90 days after publication of Battelle model decommissioning plan PAGE,R G Uranium Fuel Licensing Branch 80/06/24 ip
- --8007070195 Bafety evaluation supporting Amend 13 to License SNMrevising completion date for add details of decommissioning plan STEVENBON.R L . CROW.W T Uranium Fuel Licensing Branch 80/06/24 2pp
- 8007170152 Forwards IE Circular 80-14, "Radicactive Contamination Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No westten response required O'REILLY.J P Region 2. Atlanta, Dffice of the Director 80/06, in
- 8007140718 Forwards IE Insp Rept 70-1113/80-08 on 800417 No noncompliance noted Details withheld (ref 10CFR2 790) KENNA,W B Region 2, Atlanta, Safeguards Branch 80/04/27
- --B007160727 IE Insp Rept 70-1113/B0-08 on 800617 No noncompliance Major areas inspected facility organization & mgt of matl control sys Details withheld (ref 100FR2 790) HODOES.J W., GILLESPIE, F.P. Region 2, Atlanta, Safeguards Brai B0/06/25 ip
- 80070B0212 Responds to IE Bulletin 80-15, "Possible Loss of Emerger Notification Bys (EMB) w/Loss of Offste Power " No emergency notification sys exists at facility KAPLAN, A L. General Electric Co B0/06/30 lp
- 8007250673 Responds to requests for changes to License SNM-1097.Am MPP-2.Condition 2 i re fundamental nuclear math control plan Corrections & revised amends encl Encls withheld (ref 10CFR2 790)
 PARTLOW-J G Material Control Licensing Branch 80/07/03 2pp

DOCKET 70-1143 WEBTINGHOUSE ELECTRIC CORP

- 8007020221 Forwards moderate socurity plan suppl Suppl withheld (ref 10CFR2 790)
 PIPIAZZA,R P Westinghouse Electric Corp 80/05/20 1p
- B007020015 Ack receipt of 800428 ltr informing NRC of steps taken correct violations noted in IE Insp Rept 70-1143/80-05 Ltr to be withheld tref 10CFR2 7901 MARTIN.W 9 Region 1. Philadelphia. Safeguards Branch 80/05/2
- --8007020017 Forwards IE Insp Rept 70-1143/80-05 on 800226-28 & nc of violation Notice of violation withheld (ref IOCFR2 790) MARTIN: W G Region 1, Philadelphia, Safeguards Branch 80/04 Res.
- --B007020022 IE Insp Rept 70-1143/B0-05 on B00226-2B No noncomplia noted failure to document testing & maint of securityrelated equipment Details withheld (ref 10CF82 790) MADDEN,W Region 1, Philadelphia, Safeguards Branch 80/04/C lp
- 8007210185 Forwards JE Insp Rept 70-1143 on 70-1143/80-09 on 80051 No noncompliance noted BMITH.9 H Region 1: Philadelphia. Fuel Facility & Materials 9: Branch 80/06/09 2pp
- --8007210190 [E Insp Rept 70-ii4.]/80-09 on 800513-16 No noncomplianoted Major areas inspected licensee action on previous insp findings, organization, nuclear safety & instrument calibr & safety committee activities
 KINNEY, W M Region I, Philadelphia, Office of the Director CROCKER, H W Region I, Philadelphia, Furl Facility & Materia Safety Branch 80/06/06 IEpp
- 800702068) Forwards IE Bulletin 80-19, "Possible Loss of Emergenc Notification Sys (ENB) W/Loss of Offsite Power " Written response required ORIER, B H Region 1, Philadelphia. Bffice of the Director, 80/06/18 | 19
- B00716078B Forwards IE Circular B0-14, "Radioactive Contamination Plant Deminoralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ORIER.B H Region 1, Philadelphia, Office of the Director | B0/06/24 | 19

-)7210287 Requests elemption to requirements of IE Bulletin 80-15 rp lossible loss of emergency notification sys w/loss of offsite power Faculities being decontaminated No matl sctivity underway or planned Decommissioning set for 1782 GODRE. J S Westinghouse Electric Corp 80/08/27 ip
- 07230288 Amend 19 to License SNM-1120 authorizing decontamination decommissioning of glove boxes QUUSE.L.C. Advanced Fuel & Spent Fuel Licensing Branch 80/07/03
- 07280282 Informs of partial refund of fee accompanying 800612 application for Amand 19 to License SNM-1120 MILLER.W D License Fee Management Branch 80/07/14 ip
- CRET 70-1151 WESTINGHOUSE ELECTRIC CORP
- 07100362 Ack receipt of 800401 ltr informing NRC of steps taken to correct violation noted in IE Inap Rept 70-1191/80-09 KENNA, W D Region 2, Atlanta, Safeguards Branch 60/04/30 ip
- 8007100370 Responds to NRC 800313 ltr re violations noted in IE Inap Rept 70-1151/80-05 Corrective actions withheld (ref 10CFR2 790)
 - QUODWIN.W L Westinghouse Electric Corp 80/04/01 1p
- B007100374 Forwards IE Insp Rept 70-1151/80-05 on 800211-15 & notice of violation Notice of violation withheld (ref 10CFR2 790)
 KENNA-W D Region 2. Atlanta, Safeguards Branch 80/03/13 2pp.
- 8007)003B1 IE insp Rept 70-1151/80-05 on 800211-15 Noncompliance noted NDA measurement control procedures failed to describe requirements for reporting program data Datails withheld (ref 10GFR2 770)
 BATES.J W Region 2. Atlanta. Office of the Director GILLESPIE.F P Region 2. Atlanta. Safeguards Branch 80/03/04
- IDEGO0292 Forwards revised manual, "Fundamental Muclear Matl Control Plan - Columbia Plant " Requests approval Manual withheld (ref 100FR2 790) DIPIAZIA.N P. Westinghouse Electric Corp., PMR Systems Div
- 07020213 Forwards IE Insp Rept 70-1151/80-12 on 800415-18 No nancompliance noted KENNA, W D Region 2, Atlanta, Safeguards Branch 80/05/00 2pp
- 800702020 IE Insp Rept 70-iibi/80-12 on 800415-18 No noncompliance noted Major areas inspected operations nuclear criticality safety, internal review & audit facility mode & loCFR21 programs CORYELLO P Region 2. Atlanta, Office of the Director KAHLE.J B Region 2. Atlanta, Bafeguards Branch 80/05/00 4pp
- 206300017 Forwards site physical security plan for approval Fee encl Plan withheld (ref 10CFR2 790) DIPIAZZA.R P Westinghouse Electric Corp . PWR Systems Div BO/05/15 ip
- 307020735 Forwards IE Dulletin 80~15, "Possible Loss of Emergency Notification 59: (EMS) W/Loss of Offsite Power " Written response required D'REILLY.J P Region 2. Atlanta. Office of the Director 60/06/18 16.
- 007030022 Advises of issuance of Amend 5 to SNM-1107, deleting requirement for gross beta analyses of environ air particulates Table for Sendition 39 replaced w/encl tables PAGE; R Q Uranium Fuel Licensing Dranch 80/06/19 3pp
- --8007030028 Safety evaluation supporting amend to License SNM-1107, deleting requirement for gross beta analyses for air particulates
 SHUM.E Y . CROW. VI T Uranium Fuel Licensing Branch 80/06/19
- 007170141 Forwards IE Circular 80-14, "Radicactive Contamination of Plant Demineralized Water 89s & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director 80/06/24, in
- 007180365 Forwards addl info supporting request for amend to License SNM-1107 to authorize use of SNM in advanced waste treatment process Ltr & addl info withheld (ref 10CFR2 790)
 DIPIAZZA.R P Westinghouse Electric Corp 80/06/24 2pp

- 800718007B Ack receipt of 800929 ltr re survey & release of 1,200 lb of molybdenom scrap Release should not be made until JE has had opportunity to make independent evaluation CROW. Of Uranium Fuel Licensing Branch 80/06/25 lp
- 8007190818 Lists costs incurred & manhours expended in review of 800514 application for amend to License SNM-1107 SHUMLE Y Uranium Fuel Licensing Branch 80/06/26 1p
- B007210062 Ack receipt of 800625 itr informing NRC of atems taken to correct violation noted in IE Insp Rept 70-1151/80-14

 9TOHR, J P Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 80/07/08 lp
- ---8007210077 Responds to NRC GOOGCA ltm re violation noted in IE Insp Rapt 70-1151/80-14 Corrective actions first aid training program scheduled & attended by shift supervisors & health physics technicians GOODWIN.W.L., D'AMORE.M. Westinghouse Electric Corp. 80/06/25 20n
- --B007210082 Forwards IE Insp Rept 70-1151/80-14 on 800519-23 & notice of violation STOMR, J.P. Region 2, Atlanta, Fuel Facility & Materials Rafety Branch 80/06/06 2pp
- ---8007210086 Notice of violation from insp on 800519-23 * Region 2. Atlanta, Office of the Director 80/06/06 ip
- --B007210093 IE Insp Rept 70-1151/80-14 on 800519-23 Noncompliance noted failure to complete first gid training for all shift sugervisors & health physics technicians PERROTTI.D J Hegion 2. Atlanta, Office of the Director JENKINS.G R Region 2. Atlanta, Fuel Facility & Materials Safety Branch 80/06/06 9pp

DOCKET 70-1177 DAVIS & ELKINS COLLEGE

- 8007280298 IE Insp Findings & Licensee Ack dtd 800611 of License SNK-1119 Insp findings no noncompliance noted. BROWN, R A Region 2. Atlanta, Office of the Director 80/06/11
- DOCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP.
- 8007020244 Responds to 800509 ltr to LC Rouse re changes to Cimarron standby physical security plan Changes do not decrease effectiveness of plan. & are therefore being inserted into plan Encls to 800509 ltr withheld (ref 100F82 790) MCCORKLE, Q W Physical Security Licensing Branch 80/06/02 1p.
- 8007170300 Forwards IR Insp Repts 70-0925/80-02 & 70-1193/80-02 on 800407-08 & notice of violation DAVIS,A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/06/16 2pp
- --8007170300 Notice of violation from insp on 800407-08 * Region 3, Chicago, Office of the Director 80/06/12 1
- --B00/170310 IC Insp Repts 70-0925/80-02 & 70-1193/80-02 on 800407-08. Nuncompliance nated empty open 55-gallon drums were found in waste thipment storage Room 121 DURRY.N E Region 3. Chicago. Office of the Director FISHER, W L. Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/06/12 10pp
- 8007030023 Forwards IF Bulletin 80-15. "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required KEPPLER, J Q Region 3. Chicago, Offsice of the Director 80/06/18 1p
- 8007170800 Forwards IC Circular 80-14. "Radidactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required KEPPLER. J. O Region 3. Chicago, Office of the Director. 80/06/24. ip.
- 8007140679 Forwards It insp Rept 70-1193/80-03 on 800612-13 No noncompliance noted HIND.J A Region 3. Chicago, Safeguards Branch. 80/07/02 ip
- --8007140682 IC Insp Rept 70-1193/80-03 on 800612-13 No noncompliance noted Major areas inspected nuclear mat1 control & accounting Details withheld (ref 10CFR2 790) HIND. J A Region 3. Chicago, Edifepuads Branch PATTERSON, J P. Region 3. Chicago, Office of the Director 80/07/01 ip.

- 8007230626 Forwards survey map inadvertently omitted from IE Insp. Repts 70-0923/80-02 & 70-1173/80-02 W/o encl DAVIS.A.B. Region 3. Chicago, Fual Facility & Materials Safety Branch 80/07/08 ip
- 2007280710 Forwards survey map inadvertently omitted from IE Insp Repts 70-0925/80-02 & 70-1193/80-02 DAVIB, A B Region 3. Chicago, Fuel Facility & Materials Safety Branch B0/07/14 Zpp
- 8007230549 Ack receipt of 800627 ltr informing NRC of steps taken to correct violations noted in IS insp repts DAVIS.A B. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 80/07/15 1p.
- DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO
- B007100390 Ack receipt of 800421 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1201/80-04
 KENNA, M. B Region 2, Atlanta, Safeguards Branch 80/04/30 ip.
- -8007100397 Responds to NRC B00401 ltr re violation noted in IE Insp Rept 70-1201/80-04.Corrective actions withheld (ref 10CFR2 790) ZEFF,D M. Babcock & Wilcox Co , Nuclear Material Div. B0/04/21
- -8007100404 Forwards lE Insp Rept 70-1201/80-04 on 800304-07 & notice of violation. Notice of violation withheld (ref 10CFR2,790).
 KENNA, H B Region 2, Atlanta, Bafeguards Branch 80/04/01 2pp
- -8007100410 le Insp Rept 70-1201/80-04 on 800304-07 Noncompliance noted: Amilure to notify NRC of change made to matl control & accounting program within aix months of change Details withheld (ref 10CFR2 790). BATES, J. W., QILLESPIE, F.P. Region 2, Atlanta, Safeguards Branch 80/04/01 2pp
- B00703036B Forwards IE Insp Rept 70-1201/80-06 on 800330-0404 No nencompliance noted BTOMR.J.P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 80/05/07 2pp
- -8007030370 IE Insp Rept 70-1201/80-06 on 800330-0404 No noncompliance noted, Major areas inspected, followup on previous insp findings, internal & external exposure control, respiratory protection & instrument calibr.

 MILLSAP, W.J. Region 2. Atlanta, Office of the Director.

 GIBSON.A.F. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 80/05/07 9pp
- B007020080 Revises License Conditions 1 i, 2 1, 3, i, 5, 2 & 8 1 of License BMM-116B. Adds License Conditions 3 i 1 & 4 10 to License Amend HPP-2, authorizing changes to pages of nuclear matl control plan & exemptions from 10CFR70 BURNETT, R. F. Physical Becurity Licensing Branch. 80/05/29. 1p
- 8007020725 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 80/06. Region 2, Atlanta, Office of the Director. 80/06/18
- 8007170144 Forwards IE Circular 80-14, "Radioactive Contamination of Flant Deminaralized Mater Sus & Resultant Internal Contamination of Personnel" No written response required O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 80/06/24
- 9007240106 Amends License SNM-1168 authorizing revision of action level for airborns concentration of radioactivity in fuel-rod-and weiding area & liquid effluent release Also adds dates of 800109 & 0612 to Item 9.
 PAGE,R. 9 Urenium Fuel Licensing Branch 80/07/01 ip
- --8007240110 Discusses review of 800109 license amend application & 800612 suppl. Recommends issuance of license amend METZLACH.N . CROW.W.T. Uranium Fuel Licensing Branch 80/07/01
- 9007310493 Adds license conditions to License SNM-116B.Amend MPP-2 re use of stds for measurement calibr & storage of certain matis, in response to 800626 request for exemptions from code requirements.

 BURNETT, R. F. Division of Safeguards 80/07/18 1p

DOCKET 70-1220 GENERAL ELECTRIC CO.

- 8007170422 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water 9ys & Resultant Internal Contamination of Personnel " No written response required KEPPLER.J G Region 3. Chicago. Defice of the Director 80/05/24
- DOCKET 70-1252 EDLOW INTERNATIONAL CO
- 8007240080 Advises that request for 30-day extension for submittal of security plan has been granted Submission date is changed to 800617 MCCORKLE.O W Physical Security Licensing Branch 80/05/29 1p
- DOCKET 70-1257 MIXED OXIDE FABRICATION PLANT, EXXON NUCLEAR CO / INC
- 8007240322 Forwards IE Insp Rept 70-1257/80-04 on 800331,0401 & 22-23 No noncompliance noted

 No noncompliance noted

 BOOK.H E Region 5. San Francisco, Fuel Facility & Materials Safety

 Branch BO/Ob/11 2pp
- --8007240331 lE Insp Rept 70-1257/80-04 on 800331,0401 & 22-23 No noncompliance noted Major areas inspected facility mods, radwaste mgt & internal review & audit (CDOLEY,N J. THOMAS,R D. BOOK,H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch BO/06/10 7pp
- 8007030008 Forwards IE Bulletin 80-15, "Possible Loss of Emergency Notification 8ys (ENS) W/Loss of Offsite Power " Written response required ENGELKEN R H Region 5, San Francisco. Office of the Director. t M Region 5, San Francisco, Office of the Director, 80/06/18
- 8007090183 Recommends endorsement of encl review of estimate of release of Pu from Exxon nuclear mixed oxide fuel plant at Richland. HA as staff position & basis for succeeding increments of analysis of effects of natural phenomena on Pu fabrication AYER, J E , BURKHARDT, W Advanced Fuel & Spent Fuel Licensing Branch 80/06/24 ip
- ---B007070186 "Increment of Analysis Estimated Airborne Release of Pu from Exxon Nuclear Mixed Oxide Fuel Plant at Richland. WA as Result of Postulated Damage from Severe Wind & Earthquake Hazard "
 MISHIMA.J., SCHWENDIMAN.L.C., AYER.J.E. Battélle Memorial Institute, Pacific Northwest Laboratory PNL-3340 80/02/29
- 8007180304 Forwards IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel " No written response required ENGELKEN,R H Region 5. San Francisco, Office of the Director, 80/06/24 ip
- B0072103i0 Forwards BNWL rept, "Increment of Analysis Estimated Airbourne Release of Pu from Exxon Nuclear Mixed Oxide Fuel Plant at Richland, MA as Result of Postulated Damage from Severe Wind & Earthquake Hazard" ROUBE,L C Advanced Fuel & Spent Fuel Licensing Branch 80/06/24
- --8007210315 "Increment of Analysis, Estimated Airbourne Release of Pu from Exxon Nuclear Mixed Oxide Fuel Plant at Richland.WA as Result of Postulated Damage From Bevere Wind & Earthquake Hazard " MISHIMA, J . SCHWENDIMAN, L C Battelle Memorial Institute, Pacific Northwest Laboratory AYER, J E Advanced Fuel & Spent Fuel Licensing Branch PNL-3340 80/02/29 45pp
- 8007240032 Discusses IE insp of License 8NM-1227 on 800512-16 No noncompliance noted Major areas inspected selective exam of procedures & records, interviews w/personnel & observations by inspector Details withheld (ref 10CFR2 790)
 NORDERHAUG, L. R. Region 5, Ban Francisco, Safeguards Branch 80/07/07
- 8007210089 Advises licensee that NRC will refund portion of fee paid for review & approval of 800123 application for license amend License Condition 2 i of MPP-2 to License SNM-1227 was revised on 800530 in response to application MILLER.W O License Fee Management Branch 80/07/10 ip
- BOO7250044 Returns payment which accompanied BOO619 request to amend renewal application for License SNM-1227 Request has been combined w/790531 renewal application
 WEIBS,D License Fee Management Branch BO/07/16 1p

DOCKET 70-1278 PUBLIC SERVICE OF COLORADO

- B007290629 Forwards Endorsement 52 to ANI Policy NF-192 & Endorsement 45 to MAELU Policy MF-69
 GASCHLER, J. A. Public Service Co. of Colorado. B0/07/22 Spp
- DOCKET 70-1308 MURRIS OPERATIONS. GENERAL ELECTRIC CD
- B007150057 Forwards calculations of temp change estimates from max heat discharge at nearest ground level location to coolers, in support of statements in EIA CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 80/05/29
- 8007020608 Forwards GE 800606 ltr to NMBS re proposed addition to pump room at facility RODNEY,M A Mayer, Brown & Platt 80/06/12 ip
- --8007020611 Forwards add1 info re proposed addition to pump room, per NRC 791004 request After completion of project, appropriate revision of NEDO-21026C, "Consolidated 9AR" will be submitted DAMBON.D M General Electric Co 80/06/04 7pp
- 8007010573 Forwards JE Insp Rept 70-1308/80-03 on 800520-82 & notice of violation Notice of violation withheld (ref 10CFR2 790) HIND, J A Region 3, Chicago, Safeguards Branch 80/06/16 2pp
- --8007010578 IE Insp Rept 70-1308/80-03 on 800570-22 Noncompliance noted some vital barriers not properly maintained Details withheld (ref 10CFR2 790)
 CREED, J.R., PIRTLE, G.L. Region 3, Chicago, Office of the Director HIND, J.A. Region 3, Chicago, Safeguards Branch 80/06/13 2pp
- 8007170422 Forwards IE Circular BO-14. "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel" No written response required KEPPLER, J. G. Region 3, Chicago, Diffice of the Director BO/06/24 in
- G007140038 Memorandum in opposition to State of IL B00620 motion for reconsideration of ASLB 800604 order ruling on IL B00320 contentions NRC B00609 interim policy does not grant ASLB jurisdiction to review Class 9 accident W/Certificate of Svc SIMAJKOWSKI.R , ROTNEY, M A General Electric Co SIMAJKOWSKI.R Hayer, Brown & Platt 80/07/07 9pp
- 8007280035 Summary of 800610 meeting w/GE in Silver Spring.MD re 800123 request for license amend CLARK.A T Core Performance Branch 80/07/09 2pp
- 8007140023 Response in opposition to State of IL 800620 motion for reconsideration re Contentions 9 % 11 % in support of motion re Contention 1(a) & request for clarification Requests add1 discovery M/notice of appearance & Certificate of Svc ORAY, J R Hearing Branch 1 80/07/10 17pp
- BO07160587 Notice of GE AcGrath of GE 800725 deposition in Chicago, IL Requests production of documents & tangible evidence re adopted contentions SEKULER/S N . SCOTT, W J Illinois, State of 80/07/11 1p
- 8007180387 First set of interregatories directed to applicant Requests identification of comployees & representatives w/knowledge about operation of spent fuel federal repository Certificate of Svc encl
 9COTT, W J , SEKULER.S N Illinois, State of 80/07/14 7pp
- B007170215 Interrogatories & request for production of documents directed to intervenor Rorem et al Requests identification of witnesses & documents re Contentions ((b), 2 & 6, definition of terms & description of basis for allegations GRAY, J R Hearing Branch 1 B0/07/15 15pp
- --8007170220 Interrngatories & request for production of documents directed to State of IL Requests views, positions on proposed testimony on Contentions I-7 w/witnesses intended to be called Certificate of Sv. encl GRAY, J R Hearing Branch I 80/07/15 28pp
- 800722013B Request for production of documents in form of notice directed to State of IL Relates to GE interrogatories. State of IL Contentions 1-7. expert watcasses' apinions & State of IL 800320 second amended contentions W/Certificate of Svc SZMAJKOWSKI.R. ROONEY.H A General Electric Co SZMAJKOWSKI.R Mayer, Orown & Platt 80/07/15 3pp

- 8007220147 Interrogatories directed to intervenor Rorem et al.Requests identification of independent & employed expert witnesses intended to be called in license renewal proceeding Certificate of Svc encl ROONEY.M A. 92MAJKDMSKI.R General Electric Co ROONEY.M A Mayer. Brown & Platt 80/07/15 6pp
- B007220168 Interrogetories directed to State of IL Requesta identification of all independent & employed expert witnesses intended to be called during hearing. Demands basis upon which contentions were formed Certificate of Svc encl RDONEY, M A . 92MAJKOMSKI.R W General Electric Co ROONEY, M A Mayer. Brown & Platt 80/07/15 10pp
- 8007220170 Request for production of documents in form of notice directed to intervenor Rosem et al Relates to intervenor answers to GE intervenoralswers to GE intervenoralswers to GE intervenor intended testimony W/Certificate of Byc ROONEY, M A: SZMAJKOWSKI, R General Electric Ca ROONEY, M A Mayer. Brown & Flatt 80/07/15 3pp
- 8007220015 Corrects 800715 svc list re NRC interrogatories directed to intervenor Rorem et al & NRC interrogatories & request for production of documents directed to State of IL Documents served 800715, sent via certified mail-receipt requested ROTHSCHILD, M U Hearing Branch 1 80/07/17 ip
- 8007220007 Forwards NRC objections to State of IL 800711 notices of depositions & request for production of documents NRC will not object to untimely motions if filed during discovery phase ROTHSCHILD, M U Hearing Branch 1 80/07/18 ip
- --8007220011 Response in opposition to State of IL 800711 notices of depositions & request for production of documents MRC willing to discuss reasonable arrangements w/IL members w/specializef knowledge
 ROTHSCHILD.M U Hearing Branch 1 80/07/18 App
- 8007230519 Advises Assistant Atty General that OE will respond to all interrogatories & document production requests on 800804 QE reserves right to object to deposition of any individual who is not proper deponent Certificate of Svc encl 9XWAJKDHSKI.R Mayer, Brown & Platt 80/07/18 2pp
- DOCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL
- 8007170422 Forwards IE Circular BO-14, "Radicactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" No written response required KEPPLER.J & Region 3. Chicago. Office of the Director 90/06/24 to

DDCKET 70-1319 U S NUCLEAR, INC

- B007020733 Forwards IE Bulletin B0-15, "Possible Loss of Emergency Notification Sys (ENS) W/Loss of Offsite Power " Written response required O'REJLLY, J P Region 2, Atlanta, Office of the Director B0/06/18
- 80072B0320 Advises that License BNM-1315 is terminated & facilities & equipment released for unrestricted use
 PAGE-R 9 Uranium Fuel Licensing Branch 80/06/19 1p
- --8007280327 Discusses review of US Nuclear, Inc request for termination of License SNM-1315 & release of facility for restricted use Recommends that license be terminated SOONG, A L . CROW. W T Uranium Fuel Licensing Branch 80/06/19
- 8007170131 Forwards 1E Circular 80-14, "Radioactive Contemination of Plant Demineralized Water Sys & Resultant Internal Contemination of Personnel" No written response required D'REILLY, J P Region 2. Atlanta, Office of the Director 80/06/24

DOCKET 70-1333 METROPOLITAN EDISON CO

- 8007110009 Responds to FDIA request for all indemnity agreements, insurance policies & associated info between util,NRC &/or AEC re facility Forwards documents listed in App A FELTON,JM Division of Rules and Records B0/06/23 7pp
- --8007110015 Forwards Amend 1 to Indomnity Agreement B-64 W/o encl MILLER, J G Metropolitan Edison Co 74/04/03 1p

- --B007110022 Forwards amend to indemnity agreement effective 740301 reflecting amend to 10GFR140. "Financial Protection Requirements & Indemnity Agreements" Amend increases nuclear energy liability insurance to \$110 million BALTZHAN. J Atomic Energy Commission. Directorate of Licensing 74/03/08 1p

DOCKET 70-1359 IRT CORP

- 8007240098 Amend 14 to License SNM-1405, changing expiration date to 811031. FAGE.R O. Urenium Fuel Licensing Branch 80/06/26 ip

DOCKET 70-1489 QUODYEAR AEROSPACE CORP

8007170623 Forwards IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Mater 89s & Resultant Internal Contamination of Personnel" No written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 80/06/24

BOCKET 70-1738 PACIFIC GAS & ELECTRIC CO

- 9007240282 Issues Amend 8 to License SNM-1503, authorizing use of neutron sources & specifying expiration date of 801231 or date of conversion of CPPR-30 to OL or whichever comes earlier
 PAGE.R 9 Uranium Fuel Licensing Branch 80/06/30 2pp
- --B007240290 Discusses B0010B & 0604 license amend applications requesting authorization to store neutron sources & extension of license expiration date Amend requests should be approved
 DELAMEY, J. C., CROW, W. T. Uranium Fuel Licensing Branch 80/06/30

DOCKET 70-1739 TRI-BTATE MOTOR TRANSIT CO

BOO7020505 Advises of approval of 800530 request for temporary amend to SAM Security Transportation Plan II Vendor ltr to be withheld (ref 10CFR2 790)
MCGORKLE, Q W Physical Security Licensing Branch 80/06/09 Ip

DOCKET 70-1869 RADIATION MANAGEMENT CORP

- 8007170264 Add1 response to FOIA request for records concerning Hittman Nuclear & Development Corp.RAD Svcs.Inc & Radiation Mgt Corp Forwards balance of documents (143 pages) listed in app FELTON.J. M Division of Rules and Records 80/06/02 2pp
- ---8007170324 Notice of violation from insp on 751009 Noncompliance noted licenses possessed excessive amount of Co-60 in unsealed sources * Atomic Energy Commission, Directorate of Regulatory Operations 75/10/20 Ip

- --8007170337 IE Insp Rept 75-01 on 690916 of activities under Licenses 37-13129-01 & SNM-1524 Noncompliance noted licensee exceeded license authorization of 10 mCl of Co-60 in unsealed sources
 SLOBODIEN.M J , MCCLINTO(K.R O Atomic Energy Commission, Directorate of Regulatory Operations 69/09/16 6pp
- ~~8007170341 Discusses IE Insp 77-0) of Licenses 37-13129-01 & SNM-1524 on 771129 No noncompliance noted Major areas inspected procedures & representative records, interviews w/personnel, measurements made by inspector & observations MCCLINTOCK.R D Region i, Philadelphia, Fuel Facility & Materials Safety Branch 78/01/03 2pp
- --8007170345 IE Insp Rept 77-01 on 771127 No noncompliance noted Major areas inspected organization, internal audits, training & employee instructions, radiation protection procedures, matls, facilities & instruments & receipt & transfer of matls MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 77/12/23 12pp
- --8007170349 IE Insp Rept 78-01 on 780228 No noncompliance noted Major areas inspected circumstances re loss & recovery of contaminated resin drum, including examination of procedures & representative records COSTELLO,F, MCCLINTOCK,R (I Region 1. Philadelphia, Office of the Director 78/03/06 lipp
- --8007170407 Discusses Insp Rept 78-01 of Licenses 37-13129-01 & 8NM-1524 on 780228 No noncompliance noted Major areas inspected loss & recovery of contaminated resin drum including examination of procedures & representative records MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 78/03/13 2pp

DOCKET 70-2000 MT SINAI HOSP HARTFORD, CT

- B007230597 Act receipt of B00611 ltr informing NRC of steps taken to correct violations noted in IE insp of licenses 06-14734-01 & BNM-1559 on B00424 KINNEMAN.J D Region 1. Philadelphia. Fuel Facility & Materials Safaty Branch B0/06/25 ip
- --8007230601 Responds to NRC 800527 ltr re violations noted in IE insp of Licensus 06-14737-01 & SNM-1559 on 800424 Corrective actions will perform routine hand & radiopharmaceutical preparation area surveys
 BRUNER, R B Mount Sinal Hartford, CT 80/06/11 2pp
- --B007230608 Discusses 1E insp of Licenses 06-14734-01 & GNM-1859 on B00424 & forwards notice of violation CROCKER.H W Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/05/27 2pp
- --8007230611 Notice of violation from insp on 800424 Noncompliance noted failure to conduct routing radiopharmaceutical & hand surveys
 * Region 1. Philadelphia, Office of the Director 80/05/27 ip

DOCKET 70-2153 UNITED NUCLEAR CORP

- 8007240383 Responds to 800623 request for meeting w/NRC to discuss decommissioning of United Nuclear Corp Wood River Junction, RI operation NMSB personnel will meet w/Governor's ofc on 800708 & attend public meeting later in Charlestown, RI AMEARNE, J F Commission 900708 Ip
- --B0072403B9 Requests mosting w/NRC to discuss concerns re developments affecting operations at & decommissioning of United Nuclear Corp Wood River Junction.RI operation List of questions to be discussed encl
 GARRAHY.J J Rhode Island, State of B0/05/23 lp

DOCKET 70-2175 UNITED NUCLEAR CORP

- B0072403B3 Responds to 800623 request for meeting w/NRC to discuss decommissioning of United Nuclear Corp Wood River Junction, RI operation NMBS personnel will meet w/Governor's ofc on 800708 & attend public meeting later in Charlestown.RI AHEARNE.J F Commission 80/07/02 1p
- --B0072403B9 Requests meeting w/NRC to discuss concerns re developments affecting operations at & decommissioning of United Nuclear Corp Wood River Junction, RI operation List of questions to be discussed encl
 GARRAHY.J J Rhode Island, State of 80/05/23 ip

DOCKET 70-2375 PACIFIC GAS & ELECTRIC CO

- 8007230056 Natifies util that License SNM-1667 is amended in accordance w/800625 application.extending expiration date until 801231 or upon conversion of CPPR-69 to OL-whichever is earlier PAGE.R O Uranium Fuel Licensing Branch 80/06/30 ip
- ---8007230062 Safety evaluation re 800625 application to amend license.
 extending expiration date until 801231 Extension is needed
 to complete remainder of NRC facsility licensing process
 Recommends approval of application
 DELANEY.J C. CRUM.W T Uranium Fuel Licensing Branch 80/06/30
 1p

DOCKET 70-2478 TRANSNUCLEAR, INC.

- 8007070003 Forwards IE Insp Rept 70-2478/80-03 on 800417-18 & 22-23 No noncompliance noted KENNAN B Region 2. Atlants, Safeguards Branch 80/05/09 2pp
- --8007070005 IE Insp Rept 70-2478/80-03 on 800417-18 % 22-23 No montempliance noted Major areas inspected physical protection of irradiated fuel in transit Details withheld (ref 10CFR2 790)
 HOORE D E Region 2. Atlanta, Office of the Birector QILLESPIE,F P Region 2. Atlanta, Safeguards Granch 80/05/09
- B007030004 Partial response to FBIA request for documents re transportation of spent nuclear fuel from Portsmouth,VA to Alken.SC Forwards listed documents Other documents available in PDR NRC review of request is continuing FELTON.J M Division of Rules and Records 80/06/23 ip
- --8007030011 Confirms 800318 teleon re notification of NRC required by Condition 5 of License ISNM-01698 STONEBURNER: W Transnuclear, Inc 80/03/18 1g
- --800703001å Confirms 800318 telcon re notification of NRC required by Condition 5 of License ISNM-01å98 Pegase Cask 2 contains 3å irradiated fuel elements & is scheduled to arrive at Portsmouth, VA on 80041å STONEBURNER, W Transnuclear, Inc 80/03/18 ip
- --B007030020 Confirms on 800414 telcon re notification of NRC required by Condition 5 of License IBNM-01698 Essor flask contains 14 irradiated furl elements & is scheduled to arrive at Portsmouth, VA on 800305 STONEBURNER.W Transnuclear, Inc. 80/04/16 ip
- 8007310481 Response to FOIA request for documents re transportation of spent fuel from Portsmouth, VA to Savannah River Plant in Aiken, 86 Encl info partially withheld safeguarding procedures & security feasures (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/07/22 3pp
- --8007310485 Confirms 800320 telcon notifying NRC that Pegese Cask 1 contains 36 irradiated fuel elements & will arrive in Portsmouth. VA Info partially withheld date of arrival (reffold Exemption 4) NRC fee determination encl STONEBURNER, W. Transnuclear, Inc. 80/05/20 2pp
- --8007310496 Confirms 800521 telcon notifying NRC that Pegase Cask 4 contains one irradiated fuel plement & will arrive in Portamouth. VA Info partially withhold date of arrival(ref FOIA Exemption 4) NRC fee determination encl STONEOURNER, W Transpoclear, Inc 80/05/21 2pp

DOCKET 70-2574 CARLIBLE HOSP CARLIBLE, PA

8007010597 Discusses IE Insp Repts 30-00472/80-01,30-03018/80-01 & 70-2374/80-01 on 800522 of activities under Licenses 37-02385-01, 37-02385-02 & SNM-1762 No noncompliance noted Major areas inspected air supply & exhaust sys CROCKER.H W Region 1. Philadelphia, Office of the Director 80/04/02 2pt

DOCKET 70-2609 COMMONWEALTH EDISON CO

8007020429 Amends License SNN-1802, extending expiration date until 810639 in response to util 800403 request PAGE.R G Uranium Fuel Licensing Branch 80/06/13 ip.

- --8007020431 Discusses 800403 amend application for License 2001-1802 requesting extension of expiration date until 810630 Recommends license extension DELANEY, J C Uranium Fuel Licensing Branch 80/06/13 % Ap
- 8007150092 Forwards IE Insp Rept 70-2609/80-01 on 800624 No noncompliance noted HIND.J A Region 3. Chicago, Hafeguards Branch 80/07/02 2p
- --BOO7:50094 IE Insp Rept 70-2609/80~01 on BOO424 No noncompliance noted Major areas inspected security procedures & organization, previous items of nuncompliance & communication Details withheld (ref iOCFR2 790)
 PIRTLE, G L , KNICELEY, J R Region 3, Chicago, Office of the Director HIND, J A Region 3, Chicago, Bafeguards Branch 80/07/01 *ip

DOCKET 70-2423 HOGUIRE SPENT FUEL POOL, DUKE POHER CO

- 8007140461 Statement of Board of Commissioners' position in opposition to radwaste transportation through Caston County,NC Urges transportation via Interstates 77 & 85 Encourages expending energy & money for recycling Wrorrespondence * Caston County,NC 80/04/28 61pp
- ---B007140473 Forwards add1 comments to Gaston County Board of Commissioners' position opposing spent nuclear fuel shipment through county & two proposed alternate routes Author does not oppose shipment if adequate safeguards are provided GASTON, H B Gaston County.NC 80/04/25 2pp
- --B007140488 Forwards position of Caston County Board of Commissioners. NC. apposing spent nuclear fuel shipment through county & two proposed alternate routes H/o encl RHYNE.C A Caston County.NC 80/04/15 ip
- 8007180510 Forwards responses to Pages 4-6 of Caston County Spard of Commissioners 800428 questions addressed to ASLB re util application to transfer & store spent fuel from Oconee Nuclear Station RDBERTS.J P Advanced Fuel & Spent Fuel Licensing Branch. 80/06/25
- B007230706 Forwards response to questions contained in B00429 position document Responses contern safe transport & storage of spent fuel RDBERTE.J P Advanced Fuel & Spent Fuel Licensing Branch 80/06/25. 12pp
- 8007280045 Ack receipt of 800702 ltr forwarding spent fuel transportation security plan. Revision 3 Request for proposed primary route is subj to fee Will notify of amount WEISG.D License Fee Management Branch 80/07/17 1p

DOCKET 70-2651 MANCHESTER MEMORIAL HOSP MANCHESTER, CT

- 8007150314 Act receipt of 800227 ltr informing NRC of steps taken to correct violations noted in IE Rept 70-2651/80-01 CROCKER.H W Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch 80/04/10 ip
- --8007150318 Responds to NRC 800220 ltr re violation noted in IE Insp Rept 70-2651/80-01 W/g encl corrective actions ABBOTT, W S Manchester Memorial Hosp Manchester.CT. 80/02/27
- --B007150325 Forwards notice of violation from IE Insp Rept 70-2651/80-01 on B00207 MCCLINYOCK,R O Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 80/02/20 2pp
- ---B007150332 Notice of violation from insp on 800207 Noncompliance noted failure to continue followup on patient in whom pacemaker was implanted during Jul 1977

 * Region J. Philadelphia. Office of the Director 80/02/20 ip

DOCKET 70-2838 CINCINNATI QAS & ELECTRIC CO

BOO7010189 Notifies util that Item 4 of License 8NM-1823 is amended in accordance w/800410 request Expiration date for license is extended until 811130.
PAGE.R. Q Uranium Fuel Licensing Branch 80/06/13 ip

,

DOCKET 70-2860 BOUTH CAROLINA ELECTRIC & GAS CO

9007310428 Application for renewal of License 9NM-1834 NICHOLS,T C South Carolina Electric & Gas Co 80/07/28 1p

DOCKET 70-2005 COMMONWEALTH EDISON

8007010094 Advises of Amend 2 to License SNM-1833.extending expiration date to 820331 or conversion of CPPR-100 to OL, whichever is earlier PAGE.R.Q Uranium Fuel Licensing Branch 80/06/13 ip

DOCKET 70-2902 NORTH MEMORIAL MEDICAL CENTER MINNEAPOLIS, MN

8007270024 IE Insp Findings & Licensee Ack dtd 800609 of License BNM-1854 Insp findings no noncompliance noted BURGIN,R E. Region 3, Chicago, Office of the Director 80/06/09

DOCKET 70-2909 WESTINGHOUSE ELECTRIC CORP POWER SYSTEMS

8007020038 Responds to 800409 request for list of threatened & endangered species in vicinity of proposed plant Endangered species most likely to accur is American alligator (mississippiemsis)
HICKMAN, O. L. Interior, Dept of, Fish & Wildlife Service 80/05/22

9007020514 Forwards comments & questions re environ rept per 800521 discussion in Bilver Spring, MD Requests that responses be submitted by 800710 to maintain review schedule 84006/03 lipp

B007010027 Responds to G00421 ltr requesting scoping meeting to accept addl public comments on DES re proposed const & operation of Westinghouse plant Another meeting is not warranted. Required expense & effort would not outweigh any benefits CROW.W T Uranium Fuel Licensing Branch 80/06/06 2pp

BO07110003 Amended petition to intervone & request for hearing re AL nuclear fuel fabrication plant application Certificate of Byc.designation-authorizations in lieu of notice of appearance & board of directors resolution encl CAMPBELL, R H. Bafe Energy Alliance MCPHILLIPS, J McPhillips, J L 80/06/11 9pp

8007:10055 Motion for order relieving petitioner from 20-copy requirement in AL nuclear fuel fabrication plant application proceeding due to limited resources Certificate of Bvc encl MCPHILLIPS, J. L. Safe Energy Alliance MCPHILLIPS, J. L. 80/06/12 2pp

B007030291 Response in support of Safety Energy Alliance of Central AL.Inc B00612 petition to intervene re SNM license application for AL plant near Prattville.AL Intervention must be conditioned upon showing of common interests TURK.S.E Hearing Branch 1 80/07/02 13pp

---8007030274 Response in support of Safety Energy Alliance of Central AL, Inc 800612 motion requesting relief from 20 conformed capies filing requirement Recommends order containing spec of those to be serviced W/Certificate of Svc TURK S E Hearing Branch 1 80/07/02 4pp

8007250456 Forwards Stats of OR 770311 petition to intervens.NRC 770801 stipulation w/Portland General Electric & Stats of OR & ASLB 770920 order ruling on contentions Documents intended to serve as examples for drafting contentions W/o encis TURK, S.E. Hearing Branch i 80/07/23 2pp

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY

8007020230 Notifies of issuance of Amend 1 to License SNM-1861, increasing possession limit, authorizing use of high density fuel storage racks & incorporating specified organizational changes
PAGE.R G Uranium Fuel Licensing Branch 80/06/17 1p

--8007020233 Safety evaluation supporting Amend 1 to License SNM-1841 Increases possession limit authorizes use of high density fuel storage racks & incorporates specified organizational changes

DELANEY, J C , CROW, W T Uranium Fuel Licensing Branch 80/06/17

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0002 CHEM-NUCLEAR SYSTEMS, INC

8007170471 Requests add1 info re QA program per 790427 Itr Requests reply within 30 days
MACDONALD, C.E. Transportation Branch 80/07/03 ip

DOCKET 71-0005 MAGNAFLUX CORP

B007020044 Forwards GA program revised in accordance w/NRC B00509 ltr for Model MX-IC-100 exposure device Response to NRC NRC B00509 questions re GA program encl RDSAUER.P J Magnaflux Corp (subs of Peabody Galion Corp) B0/06/12 4pp

--8057020047 GA program for Model MX-1C-100 exposure device

* Magnaflux Corp (subs of Peabody Galion Corp) 80/06/12
iipo

8007140706 Forwards GA program approval for radioactive mat1 package MACDENALD, C E Transportation Branch 80/07/01 ip

--8007140709 GA program approval for radidactive mat1 package 0005, Revision 0 MACDONALD,C E Transportation Branch 80/07/01 1p

DOCKET 71-0017 RHODE ISLAND ATOMIC ENERGY COMMISSION

B00721011B Responds to B00430 request for add1 info re GA program for BMI-1 shipping package & forwards QA manual DIMEGL10.A F Rhode Island, State of 80/07/01 ip

--B007210130 0A manual for BMI-1 shipping package * Rhode Island, State of B0/07/01 'sipp

DOCKET 71-0002 KERR-MCGSE NULLEAR CORP

B007170476 Requests addl info re QA program per B00131 ltr Requests reply within 30 days
MACDDNALD C E Transportation Branch B0/07/03 ip

DOCKET 71-0109 UNION CARBIDE CORP

B007170480 Requests add1 info re QA program per 790926 ltr Requests reply within 30 days
MACDDNALD.C E Transportation Branch 80/07/03 in

DOCKET 71-0121 NEUTRON PRODUCTS: INC

8007230349 Forwards Revision 3 to GA program SMEDIRA:C Neutron Products: Inc 80/06/24 3pp

--B007230354 QA program, Revision 3 SHEDIRA, C., RANBOHDFF, J.A. Neutron Products, Inc. 80/04/24,

8007220099 Forwards QA program approval for radinactive mati package MACDONALD,C E Transportation Branch 80/07/10 ip

--9007220106 GA program approval for rodicactive matl package 0121, Revision 0 MACDONALD.C E Transportation Branch B0/07/10 ip DOCKET 71-0139 TULSA GAMMA RAY, INC.

8007210200 Forwards revised GA program
STEWART, K. L. Tulsa Gamma Hay, Inc. 80/06/27 ip

--8007210209 GA program for radwaste packaging * Tulsa Gamma Ray, Inc 80/06/27 Spp

8007240186 Forwards GA program approval for radioactive matl package MACDONALD, C.E. Transportation Branch 80/07/15 ip

~~8007240193 (A program approval for radioactive matt parkage 0139, Revision O MACDIMALD,C E Transportation Branch 80/07/15 ip

DOCKET 71-0143 RANCHERS EXPLORATION & DEV CO

B007170485 Requests addl info re GA program per 790427 1tr Requests reply within 30 days
MACDDNALD,C E Trainsportation Branch GD/07/03 1p

DOCKET 71-0170 GENERAL ELECTRIC CO

8007280058 Requests extension until 801001 for implementation of QAP-1.Revision I Significant reduction in engineering & operating personnel procludes generation of program procedures

CUNNINGHAM. G F General Flectric Co 80/07/08 ip

DOCKET 71-0173 BATTELLE-PACIFIC NORTHWEST LADS

8007310013 Forwards QA program approval for radipactive mat1 package MACDDNALDs C E Transportation Branch 80/07/i1 ip

--8007310015 (A program approva) for radioactive mat1 package 0173. Revision O MACDOMALD, C E Transportation Branch 80/07/11 ip

DOCKET 71-0179 NUCLEAR CONTAINERS, INC

8007170487 Requests add1 info re QA program per 791009 ltr Requests reply within 30 days
MACDONALD.C € Transportation Branch 80/07/03 1p

DOCKET 71-0189 TODO SHIPYARDS CORP

B007020026 Confirms that NRC considers 780626 application for GA program withdrawn Facility may not conduct transportation activities in Non-Agreement State per 10CFR190 20 MACDUNALD, C.E. Transportation Branch 80/06/17 lp

DOCKET 71-0192 NUCLEAR PACKAGING, INC.

B007280125 Advisos that revised GA program description will be resubmitted by 800801 per 800701 telcor OLIVADDTI.J R Nuclear Packaging, Inc. 80/07/01 1p

DOCKET 71-0221 ALLIS CHALMERS CORP

8007110014 Ferwards GA program for industrial radiography licensees OILL,8 A Allis-Chalmers Corp. 80/06/13 ip

--8007i10016 QA program for industrial radiography licensees * Allis-Chalmers Corp 60/06/13 3pp

NC

ing packages for radioactive c (subs of Cetty Dil Co) ---8007180483 QA program for shipping packages for radioactive matl.
Revision 3
* Ruclear Fuel Services. Inc (subs of Getty Oil Co) 80/06/13
2100

8007220055 Forwards GA program approval for radioactive mat1 package. MACDONALD,C E Transportation Branch 80/07/10 1p

---B007220067 QA program approval for radioactive matl package 0249, Revision O MACDONALD,C E Transportation Branch 80/07/10 lp

DOCKET 71-0251 WESTINGHOUSE ELECTRIC CORP

8007240450 Forwards 9A program approval for radioactive matl package MACDDNALD,C E Transportation Branch 80/07/09 1p

--8007240457 GA program approval for radioactive matl package 0251, Revision O MACDONALD,C E Transportation Branch 80/07/07 ip

DOCKET 71-0252 DAYTON X-RAY CO

8007010876 Forwards GA program approval for redirective matl package MACDDNALD,C E Transportation Branch 80/06/12 ip

--BOO7010579 OA program approval for radioactive matl package 0252. Revision O MACDONALD, C E Transportation Branch 80/06/12 1p

DOCKET 71-0271 RIDIHALOH, EGGERS & ASSOCIATES

B007170492 Requests addl info re QA program per 791019 itr Requests reply within 30 days MACDONALD,C E Transportation Branch 80/07/09 ip

DOCKET 71-0346 PUBLIC SERVICE CO DF COLORADO

8007140698 Forwards GA program approval for radioactive mat1 package
MACDDNALD.C E Transportation Branch 80/07/01 1p

--B007140702 QA program approva) for radioactive matl package 0346. Revision i MACDUNALD, C E Transportation Branch 80/07/01 ip

DOCKET 71-0348 BRANCH RADIOGRAPHIC LABORATORIES

ED07290929 Forwards Revision 1 to GA program for industrial radiography
BRANCH.W H Branch Radiographic Laboratories, Inc. 80/07/11 ip

---B007270931 Revision 1 to GA program for industrial radiography * Branch Radiographic Laboratories, Inc 80/07/11 3pp

DOCKET 71-0370 AMEREHAM CORP

BOD7290932 Forwards GA program for packaging radioactive matls.
BELGRAIR, D P Amersham Corp 80/07/14 1p

--8007270934 OA program for packaging radioactive matls BELGRAIR.D P Amersham Corp 80/07/14 lipp

DOCKET 71-0371 MODEL NNFD-10, UNIFIED NUCLEAR CORP

8007230053 Forwards request for add1 info to complete review of GA program MACDONALD.C E Transportation Branch 80/07/10 3pp

DOCKET 71-0381 E L CONWELL & CO

B007020650 Forwards GA program for transportation of licensed matls, in response to NRC 800416 ltr CAPPER.W E E L Conwell & Co 80/06/04 1p

- 8007020518 Forwards 0A program approval for radioactive matl package MACDONALD, C E Transportation Branch 60/06/17 1p

DOCKET 71-0383 MODEL NLT 1/2 LWT CASK, NL INDUSTRIES, INC

- 8007230025 Responds to NRC 800418 & 0508 ltrs re QA program Radioactive matls shipped pursuant to 10CFR50.App B GA program satisfies provisions of 10CFR71 51 Date of approval concurrent w/approval date of license LUNDVALL.A E. Baltimore Gas & Electric Co 80/05/19 1p
- BOO7240175 Forwards QA program approval for radioactive matl package MACDONALD, C E Transportation Branch BO/07/15 1p
- --8007240179 GA program approval for radioactive mati package 0383. Revision 0 MACDONALD, C E Transportation Branch. 80/07/15 ip

DOCKET 71-0384 NEW ENGLAND NUCLEAR CORP

- 8007010570 Forwards QA Program approval for radioactive mat1 package MACDONALD.C E Transportation Branch 80/06/13 1p

DOCKET 71-0387 MASSACHUSETTS MATERIALS RESEARCH, INC

- 8007090061 Forwards GA program approval for radioactive matl package MACDONALD.C.E. Transportation Branch 80/06/12 1p
- ---8007090066 GA program approval for radioactive matl package 0387.
 Revision O.
 HACDONALD, C E. Transportation Branch 80/06/12 ip

DOCKET 71-0389 GEORGIA, UNIV OF

- 8007100347 Forwards GA program for handling, storage & transportation of shipping containers. MUSE.L A Georgia, Univ of, B0/06/17 1p
- ---B007100353 GA program for handling storage & transportation of shipping containers. * Deorgia: Univ of:. 80/06/17 3pp
- 9007160322 Forwards GA program approval for radioactive mati package MACDONALD, C E Transportation Stanch. 60/07/01 ip
- --B007160335 GA program approval for radioactive matl package 0389, Revision 0, MACDONALD,C E Transportation Branch 80/07/01 ip

DOCKET 71-0391 NAVY, DEPT OF

- 8007160310 Forwards GA program approval for radioactive matl package. MACDONALD, C E Transportation Branch 80/07/01 1p
- ---B007160317 GA program approval for radioactive matl package 0391, Revision 0.

 MACDONALD, C E. Transportation Branch 80/07/01 ip

DOCKET 71-0392 BAKER TESTING SERVICES, INC.

800707012B Forwards GA program & shipping papers to accompany transported packages of radioactive matls
KENNETH, B F Baker Testing Services, Inc 80/06/13 1p

- --8007070133 GA program for facility * Baker Testing Services, Inc. 80/06/13 4pp
- BO07160767 Forwards Cm program approval for radioactive matt pack MACDONALD:C E Transportation Branch B0/07/07 1p
- ---8007160772 GA program approval for radioactive matl package 039 Revision 0 MACDDMALD.C E Transportation Branch 80/07/07 ip

DOCKET 71-0393 ALLIS-CHALMERS CORP

- 8007160343 Forwards GA program approval for radioactive matt pack MACDONALD.C E Transportation Branch 80/07/01 tp
- —8007160347 GA program approval for radioactive matl package 039 Revision O MACDONALD, C E Transportation Branch 80/97/01 ip

DOCKET 71~4824 MODEL HA-10. BABCOCK & WILCOX CO

- BOO7230047 Notifies of expiration of Certificate of Compliance 48 for Model HA-10 To continue using package, should submit consolidated application & drawings
 MACDONALD.C E Transportation Branch 80/07/10 ip
- DOCKET 71~4888 MODEL SENTINEL-25A, B, C, C3, D, E, F, TELEDYNE
- 8007010240 Forwards fee for renewal of three certificates of compliance Requests renewal of current revision of Certificate of Compliance 4888 for 5-yr period ending 850731
 MCGREW.J W Teledyne Energy Systems 80/06/13 1p
- 800716038; Forwards Revision 4 to Certificate of Compliance 4888 Model's Sentinel 29A.25B.25C.25C3,25D.25E.25F & LCG-25A.25B & 25C MACDDNALD,C E Transportation Branch 80/07/07 2pp
- --8007160387 Certificate of Compliance 4888, Revision 4, for Model Sentinel 254, 258, 250, 2503, 250, 258, 258 & LCG-254, 258 & 250 MACDONALD, C E Transportation Branch 80/07/07 3pp

DOCKET 71-4986 MODEL RA-R. EXXDN NUCLEAR CD . INC

- 8007280077 Requests extension of expiration date to 801031 for Certificate of Compliance 4986 due to add1 time required for NRC approval of renewal application KAPLANA L General Electric Co., Nuclear Energy Products Div 80/07/01 1p
- 8007160409 Forwards Revision 6 to Certificate of Compliance 4986 Models RA-1,RA-2,RA-3 & RA-J MACDONALD,C E Transportation Branch 80/07/07 2pp
- --8007160412 Certificate of Compliance 4986 Revision 6 for Model RA-2.RA-3 & RA-3 MACDQNALD.C E Transportation Branch 80/07/07 6pp
- B0072B0718 Forwards Revision 7 to Certificate of Compliance 498/ Models RA-1.RA-2.RA-3 & RA-J shipping containers MACDDNALD,C E Transportation Branch B0/07/21 2pp
- --B007280720 Certificate of Compliance 4986. Revision 7. for Mode RA-2.RA-3 & RA-J shipping containers MACDUNALD.C E Transportation Branch 80/07/21 6pp

DOCKET 71-908B MODEL D347[0-1, U S NUCLEAR, INC

- 8007100080 Advises that Certificate of Compliance 3088 for Mode D34710-1 expires on 800930 in order to continue using package, should submit renewal application & Pse MACDDNALD.C E Transportation Branch 80/06/16 2pp
- 8007240157 Requests withdrawal of Certificate of Compliance 508 no longer has use for Model D24710-1 VOIGHT.A F Ames Laboratory, Energy & Mineral Resources Res Institute 80706724 lp

BOCKET 71-5341 MODEL NEP-55, BABCOCK & WILCOX CO

- 8007010533 Application to amend (extificate of Compliance 9341.Revision 3, revising Itom 5 (a)(2) re exceptions to DOT Spec AM & deleting Item & Results of addl testing including 30-ft drop test encl CORDANI, A A Babcock & Wilson Cp . Naval Nuclear Fuel Div 80/05/14 | lopp
- 8007170093 Forwards Revision 4 to Certificate of Compliance 5341 for Model NFP-55 Mode: NrP-22 MACDONALD.C E Transportation Branch 80/07/07 lp
- --B007170097 Certificate of Compliance 5341, Revision 4, for Model NFP-55 MACDONALD, C E Transportation Branch B0/07/07 2pp
- DOCKET 71-5450 MODEL RCC-1,-2,-3, WESTINGHOUSE ELECTRIC CORP
- B007110281 Forwards Revision 9 to Certificate of Compliance 5450 for Modols RCC.RCC-1.RCC-2.RCC-3 & RCC-4 MACDDNALD.C E Transportation Branch 80/06/27 2pp
- --8007110290 Certificate of Compliance 5450 Revision 9, For Models RCC-RCC-1.RCC-2.RCC-3 & RCC-4 MACDONALD, C E Transportation Branch 80/06/27 5pp
- 8007240094 Application for amend to Certificate of Compliance 5450 extending expiration to 801021 Request necessary to assure shipments requiring IAEA authorization after 800701 DIPIAZZA,R P Westinghouse Electric Corp 80/06/27 Jp
- 8007180084 Notification of registration as user of Model RCC in response to request KACDONALD.C E Transportation Branch BO/07/09 ip
- DOCKET 71-5607 MODEL OF Y-2, GENERAL ELECTRIC CO
- BOO7240090 Forwards Revision 1 to Certificate of Compliance 56077, suppl to safety analysis rept & independent engineering evaluation of changes to package RDSS.D M Energy.Dept of 80/06/20 6pp
- ---BOD7240094 Certificate of Compliance 5607.Revision 1 for Model GE T-2 BAUCE.R H Energy.Dept of BO/05/31 3pp
- DOCKET 71-5768 MODEL DB-250-2, COMBUSTION ENGINEERING CO : INC
- 8007010101 Application for renewal of Certificates of Compliance 5768, 6087 & 6581 for Models 88-230-2.60 & 51032-1, respectively HICHEL, C. J. Nuclear Fuel Services: Inc. (subs. of Gebty Oil Co.) 80/05/22 ip

- --B007010106 Requests add1 fees to 800022 application for renewal of Certificates of Compliance 5768,6387 & 6581 MCISS,U D License Fee Management Branch 80/06/02 ip
- --B007010121 Forwards odd1 fees no 800522 application for renewal of Centificates of Compliance 5768,6387 & 6581 in response to NRC 800602 request MICHEL.C J. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 80/06/13
- EQ07220131 Forwards Revision 4 to Certificate of Compliance 576B for Model BB-250-2 MACDONALD,C E Transportation Branch 80/07/10 2pp
- --8007220135 Certificate of Compliance 5768, Revision 4 for Model BB-250-MACDONALD, C E Transportation Branch 80/07/10 App

DOCKET 71-5926 MODEL 100. GENERAL ELECTRIC CO

- B007110473 Forwards Revision 5 to Certificate of Compliance 5926 for Model 0E-100 MACDONALD, C E Transportation Branch 80/06/23 2pp
- --8007i10476 Certificate of Compliance 5926 Revision 5, for Model 9E-100 MACDDNALD, C E Transportation Branch 80/06/23 2pp
- DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO
- 8007020500 Forwards Revision 4 to Certificate of Compliance 5942 for Model GE-700 MACDDNALD,C E Transportation Branch 80/06/18 2pp
- -8007020506 Certificate of Compliance 5942.Ravision 4.for Model 9E-700 MACDDNALD.C E Transportation Branch 80/06/18 3pp.

DOCKET 71-5957 MODEL BMI-1, ENERGY, DEPT OF

- 8007250110 Application for renewal of Certificate of Compliance 5957 for Model BMI-1 shipping cask BAR encl BURIAN,R J Battelle Memorial Institute, Columbus Laboratories BO/06/11 5pp
- --8007250115 "SAR for Model BMI-1 Shipping Cask," Revision A Oversize drawings encl

 # Hattelle Memorial Institute, Columbus Laboratories, 8D/03/28
- 8007020003 Requests registration as user of Model SN-1 TRIMBLE, D.C. Arkansas Power & Light Co. 80/06/06 ip
- 8007020001 Requests registration as user of Model BMI-1 BYLVIA:B R Virginia Electric & Power Co 80/04/10 1p
- DOCKET 71-5971 MODEL GE-200, GENERAL ELECTRIC CO
- 8007220115 Forwards Revision 2 to Certificate of Compliance 5971 for Model QE-200 HACBONALD, C E Transportation Branch 80/07/09 2pp
- ---8007220125 Certificate of Compliance 5971, Revision 2, for Model GE-200. MACDONALD, C E Transportation Branch 80/07/09 3pp
- DOCKET 71-5979 MODEL 9979, ALPHA-OMEGA SERVICES, INC
- 8007280151 Forwards application for Revision 2 to Certificate of Compliance 5979 consolidating original application & subsequent suppls referenced in certificate BECK,E J Alpha-Dmega Bervices, Inc. 80/06/30 2pp
- ---B0072B0199 Application for Revision 2 to Certificate of Compliance 9979, consolidating original application & subsequent suppls referenced in certificate * Alpha-Omega Services, Inc 80/06/30 150pp
- ---B007280160 "General Arrangement -- Contain * Alpha-Dmega Bervices Inc 80/05/16 Container
- --8007280165 "Container/Transfer Cask"
 # Alpha-Omega Services, Inc 80/05/18 ip
- * Alpha-Dmega Services, Inc 80/06/30 1p.
- ---8007280177 "Details Overpack & Pallet Ship/Transfør Cask." * Alpha-Omega Bervices,Inc. 80/05/21 ip.
- 8007230038 Forwards Revision 3 to Certificate of Compliance 5979 for Model 5979 MACDONALD, C & Transportation Branch 80/07/09. 1p.
- --8007230040 Certificate of Compliance 5979, Revision 3, for Model 5979 MACDONALD, C. E. Transportation Branch 80/07/09 2pp.

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO

8007010395 Requests issuance of Certificate of Competent Authority 5980 per 1973 IAEA regulations for Model 600 shipping container Issuance will restrict foreign shipments to special form matts & limit fissile contont of Pu & U-235 GUNNINGHAM,O E General Electric Co 80/05/14 58pp

--8007010600 "Model 600 Shipping Cask "

---8007010602 "Special Control Drawing Model 600 Cask Seal " Sheet i * General Electric Co 79/09/28 ip

--8007010605 "Jacket Model 600 Cask " # Qameral Electric Co 79/09/28 ip

9007210041 Notifies that fee submitted w/79100B application for Revision 4 to Certificate of Compliance 5980 will be partially refunded in accordance w/manpower expenditures review MILLER, W C License Fee Management Branch 80/07/01 1p

DOCKET 71-5998 MODEL GE-400, GENERAL ELECTRIC CO.

9007210593 Forwards Revision 2 to Certificate of Compliance 5998 for Model 9E-400 MACDONALD, C.E. Transportation Branch 80/07/09 1p

DOCKET 71-6078 MODEL 927 AT & CT. COMBUSTION ENGINEERING, INC.

BOO7020102 Forwards info & revised drawings re C-E Model 927A1 & 927C1 containers in support of application for renewal of 791210 Certificate of Compliance 6078 LICHTENBERGER.H C-E Power Systems BO/08/30 App

--B007020108 "Shipping Container" Sheet 2 of 4 # C-E Power Bystems 774040 80/05/29

--B007020112 "Base & Cover Assembly " Bheet 3 of 4 * C-E Rower Systems 776060 80/05/29 ip

-9007020115 "Strongback Assembly " Sheet 4 of * C-E Power Systems 776060 80/05/29

8007110452 Forwards Revision 7 to Certificate of Compliance 6078 for Models 927A1 & 927C1 MACDONALD, C.E. Transportation Branch 80/06/23 1p

-- BO07110461 Certificate of Compliance 6078, Revision 7, for Models 927A1 & 92701 MACDONALD.C E Transportation Branch, 80/06/23 2pp

DOCKET 71-6144 MODEL 6144, NUCLEAR ENGINEERING CO

9007020495 Notification of registration as user of Model B-2 in response to request MACDONALD, C E Transportation Branch 80/06/17 ip

DOCKET 71-6294 MODEL UNC-2901, COMBUSTION ENGINEERING, INC

G007140613 Forwards application for renewal of Certificate of Compliance 6294 for Model UNC-2901 shipping package ESHRIDGE.H E C-E Power Bystems 80/06/20 ip

--8007140620 Application for renewal of Cortificate of Compliance 6294 for Model UNC-2901 shipping package Three oversize drawings enc l

C-E Power Systems 80/06/20 51pp

8007240201 Forwards Revision 4 to Certificate of Compliance 6294 for Model UNC-2901
MACDONALD,C E Transportation Branch 80/07/15 2pp

--B007240207 Certificate of Compliance 6294. Revision 4. for Model UNC~2901 MACDONALD, C.E. Transportation Branch 80/07/15 2pp

DOCKET 71-4375 MODEL PB-1, CHEM-NUCLEAR SYSTEMS, INC

8007110245 Forwards Revision 8 to Certificate of Compliance 4375 for Model CNS 4-45
MACDONALD, C E Transportation Branch 80/06/23 3pp

--8007110270 Certificate of Compliance 6375. Revisson 8. for Model CNS MACDONALD, C E Transportation Branch 80/06/23 3pp

DOCKET 71-A387 MODEL 60, BATTELLE MEMORIAL INSTITUTE

8007010101 Application for renewal of Certificates of Compliance 5768. 6387 & 6581 for Models BB-250-2.60 & 51032-1, respectively ree enci MICHEL,C J Nuclear Fuel Services, Inc. (subs. of Getty Cil Co.) 80/05/22

--B007010106 Requests addl fees re B00922 application for renewal of Certificates of Compliance 9768.6387 & 6581 WEIGS, J D License Fee Management Branch 80/06/02 ip

--8007010121 Forwards add) fees to 800322 application for renewal of Certificates of Compliance 5760,6387 & 6581 in response to NRC 800602 request Neclear Fuel Services, Inc. (subs. of Getty Oil Co.) ip MICHEL, C J 80/06/13

8007140646 Forwards drawings in support of recentification of Model 60 shipping container SMITH.F M Hanford Engineering Development Laboratory 80/07/02

--- 8007140649 "Shipping Container Fuel Pin Model 60 Assay & Details " Sheet 1 of 7

* Hanford Engineering Development Laboratory 78/09/31

--8007140654 "Shipping Container Fuel Pin Model 60 Assay & Details " Hanford Engineering Development Laboratory 78/05/31 ip

--800714065B "Shipping Container Fuel Pin Model 60 Assay & Details " Bheet 3 of 7 * Hanford Engineering Development Laboratory 78/02/23 lp

--8007140662 "Shipping Container Fuel Pin Model 60 Assay & Details "

Hanford Engineering Development Laboratory 78/07/18

--8007140666 "Shipping Container Fuel Pin Model 60 Assay & Details "
Sheet 5 of 7 Hanford Engineering Development Laboratory /8/07/18 ip

--8007140668 "Shipping (ontainer Fue) Pin Model &O Assay & Details " Sheet 6 of 7 * Manford Engineering Development Laboratory 78/02/23 ip

---8007140673 "Shipping Container Fuel Pin Model 60 Assay & Details " Hanford Engineering Development Laboratory 78/02/23, ip

--8007140678 "Pin Holder Assembly " Sheet 1 of 1 Hanford Engineering Development Laboratory 78/09/29 10

--8007140687 "Liner Shipping Container Fuel Pin Model 120 A Details " Sheet 1 of 2 * Hanford Engineering Development Luboratory 76/0

--8007140690 "Liner Shipping Container Fuel Pin Model 120 p

Sheet 2 of 2 * Hanford Engineering Development Laboratory 76/04/1.

- 8007220143 Forwards Revision 6 to Certificate of Compliance 6387 for Model 60
 MACDDNALD,C E Transportation Branch 80/07/10 2pp
- --8007220152 Certificate of Compliance 6387, Revision 6, for Model 60 MACDONALD.C E Fransportation Branch 80/07/10 5gp
- B007280776 Forwards Revision 7 to Certificate of Compliance 6387 for Model 60 shipping package MACDDNALD, C E Transportation Branch 80/07/23 2pp
- --8007280779 Certificate of Compliance A387.Revision 7.for Model 60 shipping package MACDOMALD.C E Transportation Branch 80/07/23 Box
- DOCKET 71-6400 HODEL SUPER TIGER, WESTINGHOUSE ELECTRIC CORP
- 8007100100 Responds to B00603 ltr re proposed GC Bpec 85-21 69 for insp of Model 6400 package Spec does not assure compliance GA program must be submitted re procurement maint ropair & use Acceptance criteria encl MACDONALD.C E Transportation Branch 80/06/17 12pp
- DDCKET 71-6568 MODEL LL-60-150, TVA
- 800727000B Forwards Revision 1 to Curtificate of Compliance 656B for Model 1.L~60~150 shipping container MACDONALD,C C Transportation Branch 80/07/21 2pp
- ---8007290011 Certificate of Compliance 4560,Revision I.for Model LL-60-190 shipping container, superceding Cortificate of Compliance 9093 entirely MACDONALD,C E Transportation Branch 80/07/21 3pp
- DOCKET 71-6581 MODEL 51032-1 & 1A. EXXON NUCLEAR CO. INC
- B007010101 Application for renewal of Certificates of Compliance 5769, 6387 & 6581 for Models BB-230-2,60 & 51032-i,respectively Fee encl
 - MICHEL,C J Nuclear Fuel Services, Inc (subs of Getty Oil Co) 80/05/22 ip
- --B007010106 Requests add1 fees re B00522 application for renewal of Certificates of Compliance 5768,6787 & 6581 WEISS.J.D. License Fee Management Branch 80/06/02 1p
- --8007010121 Forwards add1 fees re 800522 application for renewal of Certificates of Compliance 5768,6387 & 6381 in response to NRC 800602 request MICHELC J Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) 80/06/13 ip
- 8007100040 Forwards Revision 12 to Certificate of Compliance 6581 for Models 51002-1 & 51002-1a MACODNALD,C E Transportation Branch 80/06/24 1p
- ---B007100041 Certificate of Compliance 65B1.Revision 12.for Models 51032-1 & 51032-1a MACDONALD.C E Transportation Branch 80/06/24 App
- 8007160386 Requests Cartificate of Compliance 6581 be extended for 3-month period until 801031 HANSEN-L E Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/06/24 ip
- B007220046 Forwards request for add1 info re 790615 application requesting amend for Model 51032-1 & 51032-1a packagas Info should be incorporated as revised pages into application MACDONALD, C E Transportation Branch 80/07/07 2pp
- DOCKET 71-6679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CD
- BOD7240155 Application to renew Certificate of Compliance 6679
 BACR, T S Nuclear Engineering Co , Inc., (subs of Teledyne, Inc)
 BO706/27 ip
- DOCKET 71-6697 MODEL 8500 PKG, GENERAL ELECTRIC CO
- 8007220039 Notification of registration as user of Model GE 8500 MACDONALD.C E Transportation Branch 80/07/10 lp

- DOCKET 71~6698 MODEL NFB-4, NUCLEAR FUEL SERVICES, INC
- B007300001 "Safety Analysis of Modified NAC-1 Spent Fuel Shipping Cast" * Nuclear Assurance Corp NAC-E-801 R1 80/07/15 500pp
- 8007020422 Forwards Revision 10 to Certificate of Compliance 6698 for Model NF8-4
 MACDONALD.C E Transportation Branch 80/06/19 3pp
- ~~8007020428 Certificate of Compliance 6698 Revision 10.for Model NFS-4 MACDONALD.C E Transportation Branch 80/06/19 App
- 8007180469 Application for revision of Certificate of Compliance 6698 to provide schedular flexibility in performance of inner shell measurements & to include prenotification requirement to NRC of time & location of measurement operations

 JDHNSGN. C R Nuclear Assurance Corp 80/07/03 2pp
- 8007280532 Forwards Revision il to Certificate of Compliance 6698 for Model NFS-4 MACDONALD.C E Transportation Branch 80/07/14 3pp
- --8007280543 Certificate of Compliance 6698, Revision 11, for Model NFS-4
 MACDUNALD C E Transportation Branch 80/07/14 App
- DOCKET 71-6717 MODEL 6717 B
- BOO7290277 Advises of name & address change from Contra Costa Industrial X-Ray Co in Martines.CA to Contra Costa Insp Co in Concord.CA DAMBON.R B Contra Costa Inspection Co BO/05/01 1p
- ---8007290282 Requests registration as user of Model 533 DAWSON, R Contra Costa Inspection Co 80/07/01 1p
- BOO7220086 Notification of registration as user of Model 6717-B MACDDNALD, C E Transportation Branch 80/07/10 1p
- DOCKET 71-9009 MODEL FL 10-1. GENERAL ELECTRIC CO
- E007;10161 Forwards Revision B to Certificate of Compliance 7009 for Model FL 10-1 MACDONALD, C E Transportation Branch B0/06/13 2pp
- ---B007110166 Certificate of Compliance 9009, Revision 8, for Model FL 10-1 MACDONALD, C E Transportation Branch B0/06/13 4pp
- DOCKET 71-9010 MODEL NLI-1/2. NL INDUSTRIES.INC
- 8007280313 Requests Revision A to Certificate of Compliance 9010 to authorize shipment of PHR U oxide Fuel assemblies HILLIAMS.C E NL Industries, NL Nuclear Div 80/06/23 3pp
- 8007270016 Forwards Revision 7 to Certificate of Compliance 9010 for Model NLI-1/2 shipping package MACDONALD.C E Transportation Branch 80/07/16 2pp
- ---B007290018 Certificate of Compliance 9010, Revision 7, for Model NLI-1/2 shipping package, Superceding Certificate of Compliance 9010 Revision 6 entirely MACDOMALD, C E Transportation Branch 80/07/16 5pp
- DOCKET 71-9015 MODEL TN-B. TRANSNUCLEAR. INC
- 8007020527 Forwards Revision 2 to Certificate of Compliance 9015 for Model TN-8 MACDONALD, C E Transportation Branch 80/06/18 ip
- ---B007020532 Certificate of Compliance 9015.Revision 2.for Model TN-8. MACDONALD.C E Transportation Brench B0/06/1B 3pp
- DOCKET 71-9016 MODEL, TN-9 , TRANSNUCLEAR, INC
- 8007020512 Forwards Revision 2 to Certificate of Compliance 9016 for Model TN-9 MACDONALD C E Transportation Branch 80/06/18 ip

- DOCKET 71-9018 MODEL 8U-6, GENERAL ELECTRIC CO
- 8007280056 Advises of intention to ship radioactive matls from listed facilities using Package Model CNSI AL-33-90
 MAYER.L O Northern States Power Co 80/07/03 ip
- DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO
- 8007210043 Advises that fee submitted w/800314 application for Revisions 3 & 4 to Certificate of Compliance 9019 will be partially refunded in accordance w/manpower expenditures review MILLER.W O License Fee Management Branch 80/07/01 1p
- DOCKET 71-9022 MODEL CE-250-2, COMBUSTION ENGINEERING CD . INC
- 8007020107 Forwards add1 info supporting 800111 renewal application for Certificate of Compliance 9022,per NRC 800501 request Revised pages encl
 LICHTENBERGER, N. C-E Power Systems 80/06/06 6pp
- ---8007020114 "Shipping Container" * C-E Power Bystems 7499~776030 79/06/13 1p
- 8007020484 Forwards Revision 4 to Certificate of Compliance 9022 for Model CE-250-2 MACDONALD, C. E. Transportation Branch 80/04/19 2pp
- R007280211 Notifies that company no longer requires registration as user of Model CE-250-2 AUBTIN.M A Babcock & Wilcox Co , Nuclear Material Div 80/07/08
- DOCKET 71-9027 MODEL: 741, TECHNICAL OPERATIONS, INC
- 8007030367 Requests registration as user of Models 650,660,680 & 741 JOHNSON, M Navy, Dept of 80/05/27 ip
- DOCKET 71-9030 MODEL BENTINAL-8, 3, & MW-3000, TELEDYNE, INC
- 8007010245 Forwards for for renewal of three certificates of compliance. Requests renewal of current revision of Certificate of Compliance 9030 for 5-yr period ending 850731.

 MCOREW, J. W Teledyne Energy Systems 80/06/13 1p
- 8007280561 Forwards Revision 2 to Certificate of Compliance 9030 for Models MM-3000, Sentinel-3 & Sentinel-8 MACDONALD, C E Transportation Branch 80/07/14 ip
- ---B007280545 Certificate of Compliance 9030.Revision 2.for Models MM-3000.Sentinel-3 & Sentinel-8 MACDONALD.C E Transportation Branch 80/07/14 2pp
- DOCKET 71-903R MODEL 650, TECHNICAL OPERATIONS, INC
- 9007030367 Requests registration as user of Models 650,660,680 & 741 JOHNSON, M Navy, Dept of 80/05/27 ip
- DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC
- BOO7030367 Requests registration as user of Models 650,660,680 & 741 JOHNBON, M Navy, Dept of 80/05/27 ip
- DOCKET 71-9035 MODEL 680, TECHNICAL OPERATIONS, INC.
- 8007030367 Requests registration as user of Models 650,660,680 & 741 JOHNSON, M Navy, Dept of 80/05/27 ip

- DOCKET 71-9039 MODEL 715, TECHNICAL OPERATIONS, INC
- B007030375 Forwards consolidated drawings re 800520 ltr conterning application for renewal of Certificate of Compliance 9039 MUNRO.J J Tech/Ops (Technica) Operations. (nc.) 80/06/13 [p
- --8007030376 "Model 533 Projector Descriptive Assembly " Sheet 1 of 2 * Tech/Ops (Technical Operations, Inc.) 80/06/06 1p
- --8007030378 "Model 533 Projector Descriptive Assembly " Sheet 2 of 2 * Tech/Ops (Technica) Operations, Inc.) 80/06/06 1p
- ~-8007030379 "Model 713 Projector Discriptive Assembly " Sheet i of 2 * Tech/Ops (Technical Operations, Inc.) 80/06/09 ip
- --B007030381 "Model 713 Projector Descriptive Assembly " Sheet 2 of 2 * Tech/Ops (Technical Operations, Inc.) 80/06/09 1p
- --B007030384 "Model 616 Gamma Ray Projector Descriptive Assembly " Sheet
- 1 of 2 * Tech/Ops (Technical Operations, Int) 80/06/03 ip
- --8007030385 "Model 616 Gamma Ray Projector Descriptive Assembly " Sheet 2 of 2 * Tech/Ops (Technical Operations, Inc.) 80/06/03 1p
- --8007030384 "Model 644 Iridium Pipe Crawler Descriptive Assembly " Sheet 1 of 2 * Tech/Ops (Technical Operations, Inc) BO/06/10 ig
- ---B007030387 "Mode) 644 Iridium Pipe Crawler Descripti∨e Assembly " Sheet 2 of 2 * Tech/Ops (Technical Operations, Inc.) 80/06/11 ip
- B007220279 Advises that registration as user of Model 715, as indicated in NRC 800520 ltr.is not necessary No radioactive matl shipped
 DAMSON.R 8 Contra Costa Industrial X-Ray Co B0/06/16 in
- B007170178 Notification of registration as user of Model 715 in response to request
 MACDDNALD.C E Transportation Branch B0/07/09 1p
- DOCKET 71-9044 MODEL GE-1600, GENERAL ELECTRIC CO
- B007240200 Forwards Revision 5 to Certificate of Compliance 9044 for Model 0E-1400 MACDDNALD.C E Transportation Branch B0/07/15 3pp
- --B007240215 Certificate of Compliance 9044 Revision 5, for Model QE-1600 MACDONALD, C E Transportation Branch 80/07/15 5pp
- DOCKET 71-9049 MODEL GE-500, GENERAL ELECTRIC CD
- BOO7ZBO575 Forwards Revision 2 to Certificates of Compliance 9049 for Model 6E-500 MACDONALD,C E Transportation Branch 80/07/14 ip
- --8007280580 Certificate of Compliance 9049. Revision 2. for Model GE-500 MACDONALD.C E Transportation Branch 80/07/14 2pp
- DOCKET 71-9053 MODEL 683, TECHNICAL OPERATIONS, INC.
- B007100373 Forwards application for renewal of Certificate of Compliance 9053 for Model 683 Type B MUNRO.J J Tech/Ops (Technical Operations, Inc.) B0/06/14 3pp
- --8007100376 Application for renewal of Certificate of Compliance 9053 for Model 683 Type B
 * Tech/Ops (Technical Operations, Inc.) 80/06/13 52pp
- 8007280A98 Forwards Revision 2 to Certificate of Compliance (Model 683 MACDDNALD, C.E. Transportation Branch 80/07/14 2pp
- --8007280703 Certificate of Compliance 9053 Revision 2, for M MACDONALD, C.E. Transportation Branch 80/07/14

- 8007290116 Advises that Model 683 package.Certificate of Compliance 9053/meets IACA requirements
 MACDONALD.C C Transportation Branch 80/07/14 ip
- BOCKET 71-9070 MODEL N-55, ENERGY DEPT OF
- BOO7160417 Requests registration as user of Model N-55 CORDETT, J S Chem-Nuclear Bystems, Inc. BO/06/26 1
- BOO722CO91 Notification of registration as user of Model N-55 MACDONALD,C E Transportation Branch 80/07/10 1p
- DOCKET 71-9080 MODEL HN-600: HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8007180088 Notification of registration as user of Model HN-600 in response to request MACDDMALD, C E Transportation Branch 80/07/09 ip
- 8007280762 Forwards Revision 4 to Certificate of Compliance 9080 for Model HN-600 shipping package MACDONALD,C E Transportation Branch 80/07/21 3pp
- ---B007280766 Certificate of Compliance 9080, Revision 4 for Model HN-600 shipping package MACDUNALD, C.E. Transportation Branch 80/07/21 3pp
- 8007030222 Natifies NRC of intention to ship radioactive matl from facilities using Model HN~600 MAYER,L O Northern States Power Co 80/06/13 1p
- DOCKET 71-9081 MODEL CNSI-1400, CHEM-NUCLEAR SYSTEMS, INC
- 8007220478 Requests registration as user of Model CN81 1-13C HERBEIN, J G Metropolitan Edison Co 80/07/11 2pp
- DOCKET 71-9094 MODEL CNSI-14-195-H. CHEM-NUCLEAR SYSTEMS, INC.
- 8007100461 Submits payment for extensions of Certificates of Campliance 9094. Revision 5 & 9096. Revision 2 providing for required transition of gasket seal change CORBETT. J 5 Chem-Nuclear Tystems. Inc 80/06/16 1p
- ---8007100462 Requests payment for extensions of Certificates of Compliance 9094. Revision 5 & 9096. Revision 2. providing for required transition of gasket seal changes WEIBS,D License Fee Management Branch 80/06/11 1p
- DOCKET 71-9096 MODEL CNS1-21-300: CHEM-NUCLEAR SYSTEMS, INC
- B0071004&1 Submits payment for extensions of Certificates of Compliance 9094. Revision 5 & 9096. Revision 2 providing for required transition of gasket seal changes CORRETTIJ S Chem-Nuclear Systems. Inc. 80/06/16 1p
- --8007100462 Requests payment for extensions of Cortificates of Compliance 9094. Revision 5 & 9096. Revision 2. providing for required transition of gasket seal changes MCT88.D License Foe Management Branch 80/06/11 1p
- --- -- +9108 MODEL AL-33-90, ATCOR, INC
 - Requests registration as User of Model CNS 6-75 C Arteners Cower & Light Co 80/06/27 lp
 - radinactive matls from listed -33-90 BO/07/03 ip
 - PACKAGING, INC
 - for certificate of compliance 30/06/06 in

- --B007020685 Revision 3 amends to Model NP-S0xxL application.deleting stainless steel liner & including full-scale drop test rept * Nuclear Packaging. Inc 80/06/06 13pp
- 8007070177 Forwards Revision 3 pages to SAR (application) for Model NP-50xxL casks HANSEN,L J Nuclear Packaging, Inc. 80/06/06 1p
- --8007070179 Revision 3 to pages SAR (application) for Model NP-50ssL casks * Nuclear Packaging, Inc 80/06/06 9pp
- --B0070701B2 "Transportation Shield.Type A.Models 50-1 5L.50-2 5L. 50-3 OL & 50-4 OL " Sheet 1 of 2 * Nuclear Packaging. Inc 79/01/16 1p
- --8007070185 "Transportation Shield Type A.Models 90-1 51.50-2 5L, 50-3 OL & 90-4 DL " Sheet 2 of 2 * Nuclear Packaging, Inc 80/04/06 ip
- B007110464 Forwards Revision O to Certificate of Compliance 9130 for Model NP-50-2 5L MACDDNALD.C E Transportation Branch B0/05/23 1p
- --B00711046B Certificate of Compliance 9130.Revision O.for Model NR-SO-2 MACDONALD. C E Transportation Branch 80/06/23 7pp
- DOCKET 71-9132 MODEL T-3, NUCLEAR PACKAGING, INC
- 8007240154 Requests registration as user of Model T-3 FITZBIMMONS, T Energy, Dept of 80/06/19 is
- B007220184 Requests registration as user of Hodel T-3 KEENEY, W P Argonne National Laboratory - Argonne West 80/06/27
- B007240212 Forwards Revision 1 to Certificate of Compliance 9132 for Model T-3 MACDMALD,C E Transportation Branch 80/07/15 200
- --B007240217 Certificate of Compliance 9132, Revision 1, for Model T-3 MACDONALD, C C Transportation Branch 80/07/15 4pp
- DOCKET 71-9136 GENERAL ELECTRIC
- BOO7180460 Notifies of minor corrections & clarifying changes to Drawing 9086615. "GE Packaging Model 9136." originally submitted w/800331 approval request CUNNINGHAM.G E General Electric Co 80/06/11 2pp.
- --8007180470 "GE Packaging Model 9136"
 MUNIS General Electric Co 80/01/30 1p
- BO07220089 Authorizes delivery to carrier for transport of up to 30 hoods & glove boxes containing low level solid radwasts in accordance w/statements & representations made in 800331 ltr. Bafety syaluation enci MACDONALD.C E Transportation Branch 80/07/02 lp
- --B007220097 Safety evaluation re delivery of up to 30 hoods & glove boxes containing low level solid radioactive matl to carrier for transport in Model GE-9136 packaging MACDUANLD C E Transportation Branch 80/07/02 4pp
- DOCKET 71-9139 MODEL GE-589, GENERAL ELECTRIC CO
- BOO6190915 Forwards add1 info on Model 589 re application (NEDU-24613) for NRC certification for inclusion in 800324 submittal Oversize drawings available in Central Files only CUNNINGHAM, 0 E Ceneral Electric Co 80/05/29 44pp
- BOO6190921 "Lead Shielded Shipping Casks "
 # PX Engineering Co , Inc 80/05/07 ip
- # PX Engineering Co . Inc 80/05/07 1
- # PX Engineering Co , Inc 80/05/05 ip

80072B0771 Forwards Revision O to Certificate of Compliance 9139 for Model 5B9 shipping package MACDONALD,C E Transportation Branch 80/07/22 ip

--B007280773 Certificate of Compliance 9139.Revision 0.for Model 589 shipping package MACDDNALD.C E Transportation Branch 80/07/22 Spp

		! !
		;
		1

```
COMMISSION MEETING RECORDS
 10CFR
B007010022 Marked up transcript of 770331 Commission policy session in
Washington, DC re NRC & intl physical protection stds
    Pp 1-28
* Commission 77/03/31 28pp
B007010589 Transcript of 800624 public meeting in Washington.DC to
discuss ASLB rept on clearance rule Pp 1-49 L Bickwit 791109
memo to Commissioners encl
* Commission B0/06/24 67pp
8007020150 Transcript of 800619 public meeting re briefing on rept on potential threat to nuclear activities from insiders & DOE study on effectiveness of security clearances Pp 1-50 Q Heisz statement & viewgraphs encl * Commission 80/06/19 89pp
8007030347 Transcript of 800626 public meeting w/representatives of Conference of Radiation Control Program Directors re Agraement States program in Washington, DC Pp 1-38 Morning session, Related correspondence encl
# Commission 80/06/26 40pp
8007070011 Transcript of 800625 public briefing for Commissioner
Gilinsky by AIF on Pinancial status of utils in Washington.
DC Pp 1-67 Horning session Viewgraphs encl
* Commission 80/06/25 98pp
8007070013 Transcript of Affirmation Bession 80-30 on 800626 in Washington, DC Pp 1-4 Morning session * Commission 80/06/26 6pp
80070700i6 Transcript of 800625 public meeting w/industry, state & local & special interest group panels on emergency planning & preparedness rulemaking & NRC response Pp i-131 Afternoon session Related statements & correspondence encl * Commission 80/06/25 600pp
8007090028 Transcript of 800516 open Affirmation Session 80-23 in Washington, DC re order in Tarapur export Pp 1-3 * Commission 80/05/16 4pp
--8007090030 Informs of correction to SECY-80-238 re proposed exports of
fuel & components to Tarapur Commission SECY papers cited
are incorrectly referenced Draft memorandum & order encl
SHEA.J R Office of International Programs, Director 80/05/13
                                                                                                                                                                                                            800616
--B007090033 BECY-B0-23BA
Forwards NMBB technical review for Commission's
consideration in conjunction w/review of pending Tarapur
fuel & component exports
SMEA.J R Office of International Programs. Director B0/05/13
 --8007090038 Forwards proposed NMSS technical review for Commission consideration re proposed exports of fuel & components to
          Tarapur
BURNETT,R F Division of Bafeguards 80/05/12 4pp
8007090406 Transcript of 800421 closed meeting in Washington DC re
UB-Canada agreement Pp 1-4
* Commission 80706/20 5pp
B007110142 Transcript of 800513 closed meeting in Washington, DC re
discussion of Tarapur export license Pp 1-14
* Commission 80/06/19 14pp
8007110486 Transcript of 800710 breefing by Executive Branch on Intl
Bafeguards in Washington.DC Pp 1-62
* Commission. 80/07/10 64pp
```

```
8007110494 Transcript of 790621 closed discussion re intl safeguards matters in Washington, BC Pp 1-47 * Commission 79/06/21 51pp
8007140065 Transcript of 800626 discussion of SECY-80-107 re proposed interim hydrogen control requirements for small containments in Washington DC Pp 1-56 * Commission 80/06/26 58pp
--8007140068 Requests participation in 800626 Commission meeting re
hydrogen control Substantial hydrogen generation is
effectively prevented in BWR due to unique inherent design
          Features
SHERWOOD, G G General Electric Co 80/06/23 1p
B007i40074 Transcript of 8006iB staff presentation on final rulemaking on emergency preparedness in Washington, DC Pai-90 Viewgraphs & FEMA 800602 ltr encl * Commission 80706/18 9lpp
--B007140079 Supports final rule on emergency preparodness Rule is consistent w/FEMA proposed procedures for review of state plans & preparedness NRC will be furnished copies of FEMA approval of state & local plans as appropriate
JETT, Q Federal Emergency Management Agency 80/06/02 1p
8007140250 Transcript of 800626 Affirmation Session EO-31 in Washington ID CP 1-19 Certification & disclaimer encl * Commission 80/06/26 lipp
8007140277 Responds to FOIA request for all info which directed or discussed any changes of proposed fire protection rule in SECY-80-088 App documents have been forwarded J Guibert 800311 memo withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 80/06/26 2pp
  --8007140291 Staff requirement memo re 800423 ppen Affirmation Bession
80-18 in Mashington DC Includes overall records of
Commission votes re SECY 80-166, SECY 80-177 & BECY-80-088
CHILK.S J Office of the Secretary of the Commission 80/05/01
8007140491 Responds to FOIA request for rept on potential threat to nuclear activities from insiders, DOE study on effectiveness of security clearances & supporting documents used at 800619 briefing re repts Documents available at PDR, DOE & CIA FELTON, J Division of Rules and Records 80/07/10 kp
   -- BD07140504 Sunshine FR Notice of Commission meetings during wk of
           MAGEE.W Office of the Secretary of the Commission BO/Ob/16
800714049B FOIA request for rept on potential threat to nuclear activities from insiders, DOE study on effectiveness of security clearances & supporting documents used at 800619
      briefing re repts
COCHRAN, T D Natural Resources Defense Council 80/06/24
8007140589 Transcript of 790531 clased meeting re Task Force on NRC
     Safeguards Policy Pp 1-40
* Commission 80/07/03 42pp
8007170282 Commission determination statement Submits list of portions of transcript of 790308 discussions to be withheld from public disclosure (ref 10CFR9 104) CHILK.S J Office of the Secretary of the Commission 80/07/03
---B007170296 Transcript of Commission 790308 discussion re export matter in Washington, DC Pp 1-49 Portions withheld (ref 10CFR9 104) * Commission 79/03/08 49pp
```

- B007170315 Transcript of Commission 800608 closed discussion retestimony to be given 800611 in Washington, BC Pp 1-53
 * Commission 60/06/08 55pp
- 8007170527 Advises that Commission determined that transcript of 771019 briefing on special safeguards implementation repts should be withheld (ref 100FR9 104) HDYLE.J C Office of the Secretary of the Commission 80/07/08
- 8007170554 Advises that Commission determined that transcript of 770921 briefing on special safeguards implementation repts should be withheld per 10CFR9 10B(c) & 10CFR9 10B(a)(i) HOYLE.J C Office of the Secretary of the Commission 80/07/6
- 8007170587 Commission determination statement releasing portions of Transcript of Commission 771215 bruefing by C Bennett in Washington DC Pp 1-41 * Commission 80/06/30 43pp
- 8007170590 Unofficial transcript of Affirmation Bession 80-32 on 800703 in Washington, DC Pp 1-3 * Commission 8000703 5pp
- 8007170597 Unoffical transcript of 800703 public meeting re NRC response to panel presentations on emergency planning in Washington, DC Pp 1-50

 ** Commission 80/07/03 60pp
- --BOD7170604 SECY-BO-275B
 Proposes mods to FR & final rule changes on emergency
 preparedness submitted for Commission approval in
 SECY-BO-275 Changes do not effect cost estimates Replacement pages entl MINOQUE, R B Office of Standards Development, Director 80/07/02
- BO07180027 Commission determination statement releasing portions of transcript of 770908 legislative testimony in Washington, DC Pp 1-113
 - Commission B0/07/02 114pp
- 8007180091 Transcript of 800131 Affirmation Session in Washington, DC
 - Pp 1-11 * Commission BO/01/31 12pp
- 8007240384 Unofficial transcript of 800715 briefing in Washington, DC re analysis of alternatives for conducting independent verification testing on environmentally qualified equipment
 - Pp 1-71 * Commission 80/07/15 74pp
- 8007240425 Transcript of Commissioners/ACRS joint meeting on 800711 in Mashington, DC Pp 1-28 * ACRS Advisory Committee on Reactor Safeguards 80/07/11 30pp
- B007240439 Unofficial transcript of B00717 public meeting re safety issues in Washington.DC Pp 1-60 Handout encl # Cummission B0/07/17 66pp

- 8007240449 Unofficial transcript of 800711 public meeting in Hashington,DC to nuclear data link Pp 1-74 * Commission 90/07/11 77pp
- 8007230014 Transcript of 800711 Affirmation Session 80-33 re SECY-80-274 in Washington.DC Pp 1-2 * Cammission 80/07/11 3pp
- --8007250019 SECY-80-274
 - 207230019 SECY-80-874
 Recommends approval of publication of regulations re
 implementation of IAEA requirements for licensees Draft FR
 notice & press release & summary of comments encl
 MINOGUE, R B Office of Standards Development, Director SHEA, J R
 Office of International Programs, Director DIRCKB, W J Office
 of Nuclear Material Safety & Safeguards B0/06/02 127pp

- 8007300020 Transcript of 800529 public meeting on personnel dosimetry performance testing in Washington.DC Pp 176-275 * Commission 80/05/29 100pp
- 8007300024 Transcript of 800723 meeting in Washington DC re discussion & vote on emergency preparedness rule Pp 1-135 Supporting documentation entl

 * Commission 80/07/23 280pp
- B007300537 Sunshine FR notice of Commission 800721-23 open meetings in Washington, DC for budget presentations TWEED, R M Office of the Secretary of the Commission 80/07/16
- B007300545 Bunshine FR notice of Commission B00718 & 18 open meetings in Washington, DC to discuss matters outlines, including identification of new & unresolved safety issues TWEED.R M Dffice of the Secretary of the Commission B0/07/10
- 8007300952 Sunshine FR notice of Commission 800715,21 & 22 meetings in Washington DC to discuss outlined matters including Browns Ferry problem budget & export issue (closed session)
 THEED.R M Office of the Becretary of the Commission 80/07/15
- ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
- 8005150676 NRC is examining action plan items & judging applicability & scheduling which leave some sites w/o applicable criteria. PLESSET, M S ACRS Advisory Committee on Reactor Safeguards BO/05/04 200
- 8006160057 Discusses draft final rules 10CFR30 & 70 on emergency planning NRC-FEMA approach should be developed & implemented to encourage state & lucal agencies to incorporate federal efforts into their emergency planning PLESSET.M S ACRS Advisory Committee on Reactor Safeguards 80/06/11 2pp
- 8006300097 Responds to ACRS 800418 memo forwarding BL Cohen 800324 ltr re loss of water supply from refueling water storage tank Describes design provisions & operational security measures making total loss of water during LOCA unlikely DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/23 3pp
- ---8006300112 Forwards draft of study, "Physics of Reactor Heltdown Accident " Requests review COHEN.B L. Pittsburgh, Univ of 80/03/24, 1p
- 8007010359 Summary of R4Rnd ACRS meeting on 800403-07 in Washington,DC Lists items scheduled for consideration at 243rd ACRS meeting on 800710-12 PLESSET,M S ACRS Advisory Committee on Reactor Safeguards SL-0251 80/04/19 3pp
- B007020215 Notice of change of date of ACRS Subcommittee on Concrete & Concrete Structures B00325-26 meeting New date is B00422-23 HOYLE, J.C. Office of the Secretary of the Commission B0/03/14
- 8007030340 Transcript of ACRS Subcommittee on Safeguards & Security 800626 public meeting in Washington, DC Pp 1-129 Morning session Sandia Labs viewgraphs entitled. "Nuclear Power Plant Design Concepts for Sabotage Protection," encl * ACRS Advisory Committee on Reactor Safeguards. 80/06/26 175pp
- 8007030361 Transcript of ACRS Subcommittees on Waste Mgt & Fuel Cycle 800626 joint meeting in Washington DC Pp i-32 Afternoon session
 - ACRB Advisory Committee on Reactor Safeguards 80/06/26, 33pp.
- 8007100149 Forwards meeting agends for 242nd ACRS meeting on 800605-07 in Washington, DC ZECH, G G Technical Support Branch 80/09/19 5pp
- 8007110431 Transcript of ACRS Subcommittee on Reliability & Probabilistic Assessment 800701 meeting in Inglewood, CA Pp 1-286 Slide presentation by Nuclear Safety Analysis Ctr encl ACRS - Advisory Committee on Reactor Bafeguards 80/07/01
- 8007110435 Transcript of ACRS 800702 meeting in Inglewood,CA re Class 9 accidents Pp 1-329 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 80/07/02

- 8007140928 Summary of ACRS Subcommittee on ECCS 800329 meeting in Washington.DC re Westinghouse upper head injection adequacy re ECCS model or small break LOCAs Supporting documentation enc 1
- ACRB Advisory Committee on Reactor Safeguards 80/06/06
- 8007140531 Summary of ACRS Power & Electrical Sys Subcommittee 800407 meeting in Washington. DC re-possible response to Gilinsky 800307 ltr re-nuclear data link in emergencies * ACRB Advisory Committee on Reactor Safeguards 80/06/06 10p
- --8007140540 Comments on nuclear data link sys between NRC & operating nuclear power plants Supports NUREG-0640 objective but does not agree w/utilization of data for issuance of NRC orders Industry input & need basis should be considered ANDERSON,T M Westinghouse Electric Corp NB-TMA-2228 80/04/09
- B007140547 Bummary of ACRS Ad Hnc Subcommittee on NRC Action Plans Developed as Result of TMI-2 Accident B00401-02 meeting in Bathesda, MD re Draft 3 of NUREO-0660 * ACRS Advisory Committee on Reactor Safeguards B0/06/07
- 8007150005 Transcript ACRS Subcommittee of Reactor Safety Research 800708 morning meeting in Washington.DC Pp 1-293 Supporting encl ACRS - Advisory Committee on Reactor Safeguards 80/07/08
- 8007190026 Transcript ACRS Subcommittee on Fire Protection 800709 afternoon meeting in Washington DC Pp 1-122 * ACRS Advisory Committee on Reactor Safeguards 80/07/09
- B007150439 Summary of ACRS ATMS Subcommittee B00326 meeting in Washington, DC w/NRC & industry representatives re resolution
- ACRB Advisory Committee on Reactor Safeguards 80/05/16 25pp
- 8007150443 Summary of ACRS Ad Hoc Subcommittee on NRC Action Plans Developed as Result of TMI-2 Accident 800305 meeting in Washington, DC re near-term CL items identified in plan ACRS - Advisory Committee on Reactor Safeguards 80/06/05
- B007170301 Transcript of ACRE Subcommittee on Advanced Reactors B00630 meeting in Lou Angeles, CA Pp 1-262 Slide presentation encl ACRS - Advisory Committee on Reactor Bafeguards 80/06/30
- 8007180002 Transcript of ACRB 243rd meeting in Hashington, DC rs FY62 safety research budget & venting of TMI-2 containment Pp 1-246 Supporting matt encl * ACRB Advisory Committee on Reactor Bafeguards 80/07/10
- 8007180024 Summary of 235th ACRS meeting on 791108-10 in Washington, DC List of attenders, agenda & Apps 1 through 34 enc1 * ACRS Advisory Committee on Reactor Safeguards 80/02/26
- 8007180028 Summary of 237th ACRS meeting on 800110-12 in Washington, BC List of attendees, agenda & Apps 1 through 24 encl * ACRB - Advisory Committee on Reactor Safeguards 80/04/28
- 8007180603 Comments on revised draft emorgoncy plans proposed by NRC Offsite plan would be improved if coordinated through FEMA, w/other types of emergencies that occur more frequently HEALY, J W Los Alamos Scientific Laboratory 80/05/28 3pp
- B007210027 Comments on proposed rule. "Fire Protection Progra Nuclear Power Plants Operating Prior to 790101 " Rule shoul be supplemented by reg guides to reduce range of interpretations Rule should not be condensed LIPINSKI,W C Argonne National Laboratory 80/06/19 3pp Rule should
- B007210029 Comments on ACRB Subcommittee on Concrete & Concrete Structures 800422-23 meeting Industry should be responsible for certain kinds of research NRC should suppl that effort by research related to own mission
 WHITE, M White, M P Consulting Engineer CCB-1 B0/05/25
- B007210050 Notice that closed sessions will not be necessary for previously announced ACRS subcommittee meetings listed Affected meetings include Safeguards & Security on B00626 & Waste Mgt & Fuel Cycle on B00626-27 HOYLE,J C Diffice of the Becretary of the Commission B0/06/23

- 8007210139 Discouses development of valve blocks using rine dwide instead of vilicon carbide Zine oxide valve columns can be readily connected in parallel for increased thermal capacity Paper re rine oxide variator protoctive sys encl JOHNSON: I S Affiliation Unknown 80/06/09 lipp
- 800/210332 Summary of ACRS B&W Water Reactors Subcommittee 800429 meeting in Washington DC re NUREG-0867. "Transient Response of B&W Designed Reactors"
 - ACRS Advisory Committee on Reactor Safeguards 80/06/05 9pp
- 8007210354 Responds to Commission 800401 ltr requesting clarification of ACRS concerns w/present reactor coolant pump trip & #[P] termination criterion Emphasis on immediacy of pump trip & on eventual automatic may not be desirable PLESSET.M B ACR5 — Advisory Committee on Reactor Safeguards BO/07/16 Jpp
- 8007210523 Responds to Commission 800604 request for views on use of overtones responds to commission BOUGHA request for Views On D in-core thermocouples as aid in detection of off-normal conditions & in-arcident analysis Instituments displaying readings should be readily available in control rooms PLESBETM S ACRS - Advisory Committee on Reactor Safeguards 80/07/16 2pp
- 8007210524 Summary of ACRS Subcommittee on Regulatory Activities 800430 meeting in Washington.DC * ACRS Advisory Committee on Reactor Safeguards 80/06/05 23pp
- 8007210534 Summary of ACRS Subcommittee on Extreme External Phenomena 791115-16 meeting in Los Angeles, CA je matters concerning NRC research on external phonomena * ACRS - Advisory Committee on Reactor Sefeguards 80/03/25
- 8007210388 Summary of ACRS Subcommittee on Concrete & Concrete
 Structures 800422-23 meeting in Washington DC re research,
 technical assistance & seismic sefety programs
 * ACRB Advisory Committee on Reactor Safeguerds 80/06/03
- B007220057 Transcript of ACRS Subcomm, there on Advanced Reactors B00709 meeting in Washington, DC Pp. 1-145

 * ACRB Advisory Committee on Reactor Sufeguerds 80/07/09
- 0007230012 Natice of ACRB subcommittees & working groups' preliminary schedule of Jul-Bept 1980 proposed meetings
 HDYLE, J C Office of the Secretary of the Commission 00/06/17
- B007P30023 Notice of ACRS Subcommittee on Advanced Reactors B00709 meeting in Washington DC to discuss continued review of NRC funding b direction for annual ACRS repts H0YLE, J C Office of the Secretary of the Commission B0/06/19
- 800/230026 Notice of ACAS Subcommittee on Fire Protection 800709 meeting in Washington DC to discuss proposed fire protectively for facilities operating prior to 790101 per SECY-80-HOYLE, J C Office of the Secretary of the Commission
- B007230090 Notice of ACRS Subcommittee on Class 9 Accidents B00702 meeting in Inglewood.CA to discuss Class 9 role in licensing processinged for depraded Lore mitigation features & FYB1-82 NRC research budget for severe accident phenomena HDYLE.J C Office of the Berretary of the Commission 80/06/ii
- B007230112 Notice of ACRS Subcommitted on Reactor Safety Research 800708 meeting in Washington, DC to discuss continued review of NRC research program HOYLE, J C Bffice of the Sucretary of the Commission 80/06/18
- 8007230120 Notice of indefinite postponement of ACRS Subcommittee on ECCS 800624-25 meeting noted in 800609 FR HDYLE, J.C. Office of the Secretary of the Commission 80/06/11
- B007230125 Notice of ACRS Bubcommittee on Reliability & Probabilistic Assessment B00701 meeting to discuss continued evaluation of quantitative safety goals CHILK.6 J. Office of the Secretary of the Commission. B0/06/10
- 8007230134 Notice of ACRB Hubicommittee on Advanced Reactors 800630 meeting in Inglewood.GA to NRC funding & program direction CHILK, B J. Office of the Secretary of the Commission. 80

- 8007230729 Notification of ACRS BOOTIO meeting in Washington,DC to discuss proposed rept re NRC safety research budget for FY82
 - HOYLE, J.C. Office of the Georetary of the Commission 80/06/19 Spp
- 8007240425 Transcript of Commissioners/ACRS joint meeting on 800711 in Washington DC Pp 1-28
 * ACRS Advisory Committee on Reactor Safeguards 80/07/11 30pp
- 8007240475 Comments on fire protection Reg Guide i 120 excess automation may present hazards greater than fire Flooding & collepse of trays may be serious Water resistance of aged dry cables unknown EDERSOLE J C ACRS - Advisory Committee on Reactor Safeguards 76/08/16 2pp
- 8007250521 [ranscript of 243rd ACRS meeting on 800711 in Washington.DC Pp 460~586.Part 2

 * ACRS Advisory Committee on Reactor Safeguards 80/07/11
- 8007300002 Transcript of ACRS 243rd meeting on 800711 in Washington, DC Pp 323-459
 * ACRS Advisory Committee on Reactor Safeguards 80/07/11
- 8007300026 Transcript of ACR6 243rd meeting on 800710 in Washington. BC Pp 247-322 Viewgraphs encl * ACR8 Advisory Committee on Reactor Bafeguards 80/07/10 95pp
- 8007310524 Notification of ACRS Subcommittee on Safety Philosophy & Criteria 800806 meeting in Washington.DC to discuss progress regrequirements for near-term CP plants
 HOYLE, J. C. Office of the Secretary of the Commission 80/07/17

COMMISSION NRC COMMISSIONERS

- 7909110639 Responds to 790703 ltr re approval of NRC actions HENDRIE. J M Commission 79/07/16 ip
- 7909260557 Responds to 790821 ltr re transport of radwaste from TMI & air shipment of nerve gas bombs from Co to UT States are not routinely notified of radwaste shipments DOD has jurisdiction over transport of nerve gas explosive weapons HENDRIE. J M. Commission 79/09/11 12pp
- 8007010278 Responds to 790306 memo re revised civil penalties proposal Suggests Section 234(c) be worded "Commission shall afford to person notified per subsection (b) apportunity for hearing "
 STOIDER.C R Office of the Coneral Counsel 79/03/08 5pp
- 8007010552 Responds to 791113 ltr requesting assessment of Washington Post 791111 article re "Radiological Assessment of WiYL Muclear Power Plant " Ofc of Nuclear Reactor Regulation completing detailed review of rept AHEARNE. J F Commission 80702/20 4pg
- BO07010554 Advises that Commissioner Bradford will assume speaking responsibility at B00924 ALI-ABA course on atomic energy licensing & regulation H0/06/11 ip
- 8007020023 Weekly info rept for wk ending 800613 REHM.T A Office of the Executive Director for Operations 80/06/18 28pp
- G007020129 Forwards response to questions in B00512 ltr re NRC resource allocations for FY81 & 82 Includes post-TMI licensing requirements, resource allocations for CP reviews vs QL reviews & number of QL reviews Processed AHEARNE, J F Commission 80/06/05 4pp
- ---800702018B Requests response to questions on behalf of Senator Bellmon, re NRC resource allocations for FYB1 & 82 Includes post-TMI licensing requirements resource allocations for CP reviews vs GL reviews & number of DL reviews processed HATFIELD, M D Senate, Appropriations 80/08/12 1p
- BOO7020168 Requests response to J Hendries concerns expressed in 790226 memo rg revised civil penalties legislative proposal KENNEDY.R f Commission 79/03/06 29p

- 8007020325 Responds to Commission 800512 request for estimate of NRC & applicant resources needed to identify extent to which OL applications comply w/current NRC regulations Two addit manyrs per applicanton would be required by NRC & applicant DENTON.H R Office of Nuclear Reactor Regulation, Director 80/06/13 6pp
- --B007020331 Forwards procedure for documentation of deviations from SRP SERs issued after 770101 for plants under OL review & issued after 770801 for CP applications under review are to document deviations from SRP RUSCHE, B C Office of Nuclear Reactor Regulation. Director 76/09/20 11pp
- --B007020336 Forwards revised procedure for documentation of deviations from SRP, supersoding 760920 memo Procedure remains unchanged for CP reviews, but requires only limited liconsee participation in OL reviews RUSCHE, B C Office of Nuclear Reactor Regulation, Director 77/01/31 15pp
- 8007020672 Ack receipt of invitation to participate in round table at cancluding plenary session of intl conference on current nuclear plant safety issues in Oct 1980 Round table discussion is excellent idea HENDRIE.J M Commission 80/06/11 1p
- --B007020674 Notifies of B01020-24 intl conference on current nuclear plant safety issues in Btockholm, Sweden Conference will include round table discussion to identify current views & issues related to conference EKLUND, S International Atomic Energy Agency (Austria) 80/05/27 200
- 8007030355 Draft NRC reorganization plan. Number 1 of 1980 * Commission 80/05/01 App
- BOO70BOO76 Comments on B 1860.9mall Business Innovation Act of 1979, requiring federal agencies w/research & develoment budget in greess of \$100,000,000 to establish small business innovation research program Discussion of problems encl AHEARNE, J F Commission 80/06/12 5pp
- 8007080082 Requests comments on encl 8 1860. Small Business Innovation Act of 1979, requiring federal agencies w/research & development budget in excess of \$100,000.000 to establish small business innovation research program NELSON, @ Senate, Small Business 80/03/11 68pp
- 8007070104 Responds to Subcommittee on Nuclear Regulation 800501 ltr posing questions re Commission approach to foreign health & safety issues Commission issued decision on reactor export to Philippines on 800506 W/response to specific questions AHEARNE, J. F. Commission 80/06/06 lipp
- --8007090114 Order granting issuance of licenses to Westinghouse for export of reactor to Philippines Separate Commissioner oginions encl CHILK:B J Office of the Secretary of the Commission 80/05/06
- 0007090122 Weekly info rept for wk ending 800627 REHM, T A Office of the Executive Director for Operations 80/07/02 34pp
- 800711001B Weekly info rept for wk ending 800620 REHM.T A Office of the Executive Director for Operations 80/06/25 28pp
- #2007110266 Provides Subcommittee on Oversight & Investigations w/ detailed responses to questions re role & impact of GMB in administration of laws & NRC operation AHEARNELJ F Commission B0/06/12 iOpp
- --H007110270 Requests response to questions or role & impact of DMB in administration of laws & NRC operation ECKHARDT,B House of Rep., Interst & Foreign Commerce B0/03/21 7ss
- --8007110282 Discusses legal basis for NRC budget referral to DMB W/ supporting documentation STDIBER.C.R. Office of the General Counsel 78/07/28 20pp
- --8007110296 Discusses interagency comments on NRC Mill Tailings Bill Includes matters raised by EPA DOE & DOI STDIBER, C R Diffice of the General Counsel 78/06/22 i4pp
- --B007110297 Statement of JF Ahearns on President's Reorganization Plan 1 of 1980 AHEARNE, J F Commission 80/07/08 8pp

- 8007i10278 Responds to request for info re impact of Nuclear Nonproliferation Act institutional arrangements on decision about proposed U exports to India KENNEDY,R T Commission B0/06/13 ip
- 8007110377 Informs Subcommittee on Nuclear Regulation of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL AHEARNE, J F Commission 80/06/24 2pp
- --8007110382 Informs Subcommittee on Environ Energy & Natural Resources of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Bignificant program deficiencies found in CA & FL AHEARNE, J F Commission 80/06/24 2pp
- --B007i103B7 Informs Subcommittee on Energy & Environ of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL AHEARNE. J F Commission 80/06/P4 2pp
- --B007i10392 Informs Subcommittee on Energy & Power of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL AMEARNE.J F Commission 80/06/24 2pp
- --8007110393 Discusses status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY77 Bignificant program deficiencies found in CA & FL RYANIR O Office of Management and Program Analysis 80/06/19 200
- B007110399 Provides Subcommittee on Nuclear Regulation w/responses to 800620 quostions re licensing & const of new onsite spent fuel storage pools
 KAMMERER, C Office of Congressional Affairs B0/06/24 lipp
- 8007110538 Provides Bubcommittee on Nuclear Regulation w/comments on actions taken in amending S 2358 Requested funds for casework personnel loan assistance program & TMI-related work are much needed Add comments forthcoming AHEARNE, J F Commission 80/06/25 2pp
- 8007140120 Responds to 800620 ltr re Commission 800616 statement of policy on TMI-related OL requirements Commission has no intention of restricting littigation of TMI-related issues Change would permit parties to raise more, not fewer, issues AHEARNE, J F Commission 80/06/30 2pp
- 8007130829 Submits contribution to Commission decision process re access clearance rule for SNM by reviewing setting for decision, presenting observations on state of record & legal issues & outlining principle options available BICKWIT, L Office of the General Counsel 79/09/11 17pp
- 8007160516 Weekly info rept for wk ending 800620 REHM, T A Office of the Executive Director for Operations 80/06/25 36pp
- 8007160716 Responds to request for NRC views on DDE legislative proposals re extension of NRC licensing authority over certain DDE facilities for radwaste mgt NRC does not support DDE proposals due to inconsistency w/NRC recommendations AHEARNE, J F Commission 80/06/16 7pp
- 8007140848 Expresses appractation for 800522 ltr to NRC re future role of Ofc of State Programs Views expressed will be carefully considered in any reorganization which may affect Ofc of State Programs
 DIRCKS.W J Office of the Executive Director for Operations 80/04/04 in
- --8007160851 Expresses concern re future role of Ofc of State Programs
 Ofc is vital source of current info & regulations on nuclear
 power facilities in Northeast Urges continued operation of
 Ofc of State Programs
 LADD.E Massachusetts, State of 80/05/22 ip
- 8007160854 Expresses appreciation for 800523 ltr to NRC re future role of QFc of State Programs Views expressed will be carefully considered in any reorganization which may affect Ofc of State Programs

 DIRCKSIW J Office of the Executive Director for Operations
 80/06/04 ip

- --8007160858 Expresses concerning future role of Ofc of State Programs
 Ofc has been of great assistance to State of CT in
 addressing several pressing nuclear-related issues Urges
 continuation of Ofc of State Programs
 FIT2PATRICK.T. Connecticut. State of 80/05/23 ip
- B007170415 Responds to request for views & recommendations re enrolled bill to authorize appropriations to NRC for FYBO Commission has reviewed & found bill acceptable Two notes technical corrections should be made AHEARNE.JF Commission B0/06/20 lp
- --8007170418 Requests views & recommendations re encl enrolled bill to authorize NRC appropriations for FY60 FREY, J M Office of Management & Budget 80/06/17 14pp
- 8007180029 Forwards comments made during South American Conference on Small & Hedium Size Reactors in Montevideo, Uraguay re future of nuclear power in US.in response to 800602 ltr KENNEDY,R T Commission 80/06/12 ip
- ---B0071B0034 Comments on B00417 testimony before Subcommittee on Energy & Water Development Majority of US utils employ good people, but attentions are diverted & diluted in responding to regulatory details

 LEE, B Commonwealth Edison Co 80/05/02 1p
- B007180036 Forwards Representative Udall 781128 itr re nuclear accident review board proposal ACRS should be asked to set up suitable subgroup to make trial review of incidents & occurrences per H Lewis recommendation HENDRIE, J M Commission 78/12/05 app
- --8007180427 Comments on H Lewis suggestion for creation of nuclear accident review board adequate consideration has not been given to benefits that might result from analysis of AOs or other accidents by independent review group UDALL.M K House of Rep 78/11/28 App
- --B007180431 Requests views on encl H Lewis suggestion for improved nuclear accident analysis & prevention by creation of statutorily independent quasi-judicial board UDALL, M K House of Rep , Interior & Insular Affairs 78/01/27 400
- 8007180164 Declines invitiation to participate in World Congress of Metallurgy in Lima,Peru Invitation passed to other members of Commission & NRC staff for anyone interested in attending Congress KENNRDY,R T Commission 80/05/08 ip
- --B0071B0169 Extends invitation to participate in World Congress of Metallurgy in Lima, Peru, 800616-21 BETETA, P.M., NAVARRO, C.C. Peru, 80/04/08 1p
- 8007180216 Ack receipt of 800505 itr commenting on talk given at Brown Univ on 800327 re energy & providing info on cancer risks KENNEDY, R T Commission 80/05/12 ip
- --8007180221 Commends 800327 speech at Brown Univ re energy Realisms are being instructed into US energy considerations Provides info re UT cancer claims H/a encl LAPP:RE Lapp.Inc 80/05/03 tp
- BOO7/BO4HB Ack receipt of 800404 ltr providing brief description of proposed instrumentation sys for measuring water level in core of PMR Addl exchange of info necessary to compare proposal w/others
 KENNEDY,R T Commission BO/09/28 &pp
- BOO7180494 Ack receipt of 800623 ltr Nuclear power can achieve full potential & help to meet nath energy needs only of continuing dialogue between regulators & plant operators exists
 KENNEDY.R T Commission 80/06/30 ip
- --8007180579 Ack receipt of addl info on civilian nuclear power industry
 Nuclear power is vital to US & world energy needs Wellregulated & operated nuclear plant presents very low level
 risk
 LEE, B Commonwealth Edison Co 80/06/23 2pp
- 8007180501 Expresses gratitude for valuable contributions to nuclear research over last 5 yrs
 KENNEDY,R T Commission 80/05/06 ip
- B007180544 Weekly info rept for wk ending B00703 REHM,T A Office of the Executive Director for Operations B0/07/10 20pp

- 8007180550 Responds to 800418 telegram Gross error in telegram should be corrected Reason for postponement of NRC 800421 meeting on Philippine export applications was that some Commissioners were not ready to release opinion on issues KENNEDY.R T Commission 80/05/22 ip
- B007230224 Responds to FOIA request for H Denton B00613 memo to Commissioners entitled, "Compliance of OL Applications H/Current NRC Regulations.Reg Guides & Branch Technical Positions 'Forwards memo bivision of Rules and Records 80/07/16 1p
- 8007230229 FOIA request for H Denton 800613 memo to Commissioners entitled, "Compliance of OL Applications W/Current NRC Regulations, Reg Guides & Branch Technical Positions" WEISS.E A Sholdon, Harmon & Weiss 80/07/11 1p
- 8007230735 Ack receipt of 800512 itr re progress in cooperative efforts to reduce packaging & transport problems Full time insp coverage at Beatty should be discontinued Contract re transportation surveillance will be forwarded shortly AHEARNE.JF Commission 80/06/12 1p
- --8007230739 Advises that full-time NRC inspector will no longer be needed at Beatty.NV waste disposal site State will provide appropriate insp surveillance as of 800401 LIST.R Nevada, State of 80/05/12 ip
- 8007230749 Responds to BCC222 ltr re strengthening & clarifying federal laws related to physical security at nuclear facilities Comments on specific areas in itr re sabotage, guards, personnel selection & protection of safeguards info AHEARNE, J.F. Commission 80/06/12 12pp
- --B007230751 Expresses concern re physical security of nuclear facilities Need to strengthen & clarify federal law exists in areas of sabotage guards, personnel selection & screening & protection of safeguards info WALSKE, C Atomic Industrial Forum 80/02/82 App
- 8007240027 Ack receipt of 800609 ltr commenting on policy statement for TMI-related OL requirements Statement does not diminish intervenors present rights to litigate TMI-related issues before ASLS & ABLAS AHEARNE. J F Commission 80/06/30 2pp
- --B007240034 Ack receipt of B00609 ltr commenting on policy statement for TMI-related OL requirements Statement does not diminish intervenors present rights to litigate TMI-related issues before ASLO & ASLAS AHEARNE, J.F. Commission 80/06/30 2pp
- --B007240044 Comments on policy statement for TMI-related III.
 requirements intervenors should be allowed to litigate TMIrelated issues
 HEISSER Sheldon, Harmon & Weiss B0/06/09 3pp
- --8007240050 Comments on policy statement for TMI-related OL requirements NRC fails to understand requirements of administrative due process
 JORDAN, U.S. Sheldon, Harmon & Weiss 80/06/13 App
- 8007240209 Heekly info rept for wk ending 800711 HEHM.T A Office of the Executive Director for Operations 80/07/17 28pp
- 8007240480 Forwards description of actions re use of existing nuclear sites for new power plants & for radwaste storage,per QAO BO0401 rept recommendations W/o encl AHEARNE, J F Commission 80/07/10 lp
- --BOO7240481 Provides Subcommittee on Energy & Environ w/description of actions re use of existing nuclear sites for new power plants & for radwaste storage, per GAO BOO401 rept recommendations W/o encl
 AHEARNE.J F Commission BO/07/10 ip
- --B007240483 Provides Subrammittee on Nuclear Regulation w/description of actions re use of existing nuclear sites for new power plants & for radwaste storage.per GAD 800401 rept recommendations W/o encl AHEARNE.J F Commission 80/07/10 1p
- --B007240487 Provides Subcommittee on Energy & Power w/description of actions re use of existing nuclear sites for new power plants & for radwaste atorage, per GAD B0040; rept recommendations W/o encl.

 AHEARNE, J F Commission B0/07/10 ip

- --B007240491 Provides Gubcommittee on Environ Energy & Natural Resources w/description of actions re use of existing nuclear sites for now power plants & for radwaste storage, per GAO B00401 rept recommendations W/o encl
 AHEARNE, J.F. Commission 80/07/10 1p
- ---B007240493 forwards description of actions reluse of existing nuclear sites for new power plants & for radwaste storage.per GAO B00401 rept recommundations W/a encl AHEARNEJ F Commission B0/07/10 ip
- --8007/40476 Forwards description of actions re use of existing nuclear sites for new power plants & for radwaste storage, per GAD 800401 rept recommendations H/o encl AHEARNE, J F Commission 80/0//10 ip
- --8007240497 Forwards description of actions re use of existing nuclear sites for new power plants & for radwaste storage.per GAD 800401 rept recommendations AHEARING.J F Commission 80/07/10 5pp
- B007250007 Ack receipt of 800523 ltr re new IAEA training program course Schedule commitments would limit availability to give requested informal lecture
 HENDRII.J N Commission 80/07/02 lp
- --B007250010 Extends invitation to give informal lecture on 800924 for new IAEA nuclear power training program Course calendars & outline enci ROCHB.1 Argonne National Laboratory B0/06/23 ip
- 8007290029 Forwards Commissioner Konnedy lecture given at Brown Univ Ctr for Energy Studies, in response to request Mitre Corp study referenced in Kennedy lecture is C Zraket & M Scholl Oct 1779 "Solar Energy bys & Resources " W/o encl SCIFERT, C W Commission 80/05/20 ip
- --1007250028 Requests written copy of 800°327 lecture presented before Brown Univ Ctr for Energy Studies Also requests identification of Mitre Corp study referenced in lecture CORRIGAN.J J Indiana State Univ 80′05/14 Jp
- BOD72900/9 Forwards "NRC Semiannual Rept to Congress on Status of Damestic & Intl Evaluations of Nuclear Fuel Cycle Sys "Congress should relieve NRC of responsibility for further repts due to other resource prioryties W/o encl AHCARNC. J.F. Commission 80/07/09 Ip
- ---BOO72900D2 Forwards "NRC Semiannual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys "Congress should relieve NRC of responsibility for further repts due to other resource priorities W/o encl AMEARNE.J F Commission 80/07/09 ip
- ---8007250085 Provides Subcommittee on Energy Nuclear Proliferation & Federal Sycs w/ "NRC Semiannual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Evel Cycle Sys "
 H/o encl
 AHFARNE, J P Commission 80/07/09 1p
- --8007230089 Provides Subcommittee on Arms Control Oceans & Intl Environ w/ "NRC Seminanual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys "NRC should be relieved of responsibility for further repts W/o encl AMFARNE, J.F. Commission 80/07/09 ip
- --8007230098 Forwards "NRC Bemtaunual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Bys "
 Congress should relieve NRC of responsibility for further repts due to other resource prierities We encl
 AMEARNE.J [Commission 89/0//09 ip
- --8007280101 Provides Bubcommittee on Environ Energy & Natural Resources

 W/ "NBC Semiannual Rept to Congress on Status of Domestic &

 Intl Lyaluations of Nuclear Fuel Cycle Sys "NRC should be
 relieved of responsibility for further repts W/o encl

 AMEARNE.J F Commission 80/07/09 ip
- --B007250105 Provides Bubcommittee on Energy & Power w/"NRC Semiannual Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Syn " NRC should be relieved of responsibility for further repts W/o encl AMFARNE.J C Commission 89/07/09 ip.
- ---B007290114 Provided Subcommittee on Energy & Environ
 ω/ "NRC Semiannum! Rept to Congress on Status of Domestic &
 Intl Evaluations of Nuclear Fuel Cycle Sys " NRC should be
 relieved of responsibility for further repts Η/ο enc!
 AMEARNC.Jf Commission 60/07/09 ip

- ----B00725011B Provides Subcommittee on Nuclear Regulation

 w/ "NRC Semiannual Rept to Congress on Status of Domestic &

 Intl Evaluations of Nuclear Fuel Cycle Sys " NRC should be
 relieved of responsibility for further repts H/o encl

 AHEARNE, J F Commission B0/07/09 1p
- --8007250137 "NRC Rept to Congress on Status of Domestic & Intl Evaluations of Nuclear Fuel Cycle Sys " * Commission 80/04/30 3pp
- 8007250111 Responds to Samford Univ 800627 invitation to speak on Cordell Hull Speakers Forum program Requests to be listed as possible speaker approx 801113, due to schedule commitments
 HENDRIE, J M Commission 80/07/07 ip
- --8007250117 Extends invitation to speak on Cordell Hull Speakers Forum at Samford Univ during Sept-Nov 1980 WILLIAMS.JE, MILLER.JG Affiliation Unknown 80/06/27 1p
- ---8007250215 Requests views on cncl H R 6745.Radiation Control Act of 1977 8TACGERS.H O House of Rep 80/03/21 12pp
- 8007250611 Discusses 800402 ltr to NRC stating that Figure 4 of SECY-80-107 is erroneous Thermodynamics of zirconium-steam reaction were in fact considered in NRC calculations Discussion paper re thermodynamic considerations encl DENTON.H R Office of Nuclear Reactor Regulation, Director 80/05/29 12pp
- --8007250621 Expresses opinion that that Figure 4 of SECY-80-107 is erroneous because thermodynamics of zirconium-steam reaction were not considered Supporting documentation encl LEYSE.R H Affiliation Unknown 80/04/02 20pp
- 8007250721 Response to inquiry re BWR relief valve discharge piping Requirements for fabrication & inservice insp of containment components are being developed by ASME Code Containment Morking Groups
 DENTON.H R Office of Nuclear Reactor Regulation. Director 80/07/07 3pp
- 8007280157 Responds to 800R20 & 0513 ltrs expressing concern re procedures in proposed rulemaking on storage & disposal of nuclear waste Forwards 800528 order re working group to monitor development of record AHEARNE.J F Commission 80/06/12 1p
- 8007280162 Ack receipt of 800522 ltr expressing concern re future role of Ofc of State Programs NRC romains committed to preserving class working relations w/states & Conference AHEARNE.J F Commission 80/06/19 ip
- --8007280170 Forwards resolution requesting Commission proceed w/caution in deliberation & actions re reorganization of NRC Ofc of State Programs has provided agreement states w/info vital to programs & improved NRC/state relations PARROTT.M W Conference of Radiation Control Program Directors, Inc. 80/05/22 2pp
- 8007280722 Responds to 800121 request for rept on plans for full-time monitoring of vital nuclear power plant operations Presently planned resident inspector program in conjunction \(\omega/\)nuclear data link will provide sound program Related data enci AHEARNE.J F Commission 80/06/12 5pp
- --8007280725 Requests views re desirability of installing nuclear data link & characteristics if installed GILINSKY:V Commission 80/03/07 ip
- --B0072B0729 Requests rept on full-time monitoring of vital nuclear power plant operations Resource requirements of plan should be specified Range of alternatives for insuring continued federal presence in control room should be provided * Office of Management & Budget # 80/01/21 jp
- 8007270347 Discusses NRC concerns re State of NM program for regulating U mills & mill tailings Lists provisions not approved by Environ Improvement Board which should be included in program to comply w/UMTRCA by 811111 A

- --B007290359 Discusses () mill regulations that should be adopted to enable State of NM to meet requirements of UMTRCA State should take action on differences between RTAX & Environ Improvement Div recommendations as discussed in entl KERR, G W Office of State Programs. Director 80/03/20 4pp
- BOO730006B Ack roceipt of ltr expressing appreciation for NRC assistance in healing last fall Advises of Commissioner inability to attend SSEB meeting KENNEDY.R T Commission BO/05/06 ip
- --B00730074 Expresses appreciation for Commission assistance on emergency radiological planning environ monitoring & transportation hearings Final rept available from hearings CARTER.A R South (arolina, State of 80/04/24 lp
- 800730008B Weekly info rept for wk ending 800717 REHM,T A Office of the Executive Director for Operations 80/07/23 30pp
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- B007010580 Notification of contract execution, Mod 2 to "Sys Analysis of Shallow Land Burial" Contractor Science Applications, Inc.
 SMITH.P A Technical Assistance Contracts Branch FIN B-6428-9-80/06/08 ip
- ~-8007010582 Mod 2.deleting ref to VP Dura in Article 8 & substituting JA Stoddard: to "Sys Analysis of Shallow Land Burial" TREVIND.T Science Applications. Inc. DDUGHERTY.D J Division of Contracts FIN B-6428-9 NRC-02-79-032 80/06/08 ip
- 8007010413 Notification of contract execution.Mod 6 to "Commercial LMFBR Safety Study " Contractor Univ of CA at Los Angeles JACOBS: A Research Contracts Branch FIN 0-3019 80/06/16 ip
- --8007010619 Mod 6, revising scape of work for Tasks 1 & 2 extending period of performance until 800930 & providing addl funding, to "Commercial LMFDR Safety Study"

 DHILLON,H California Univ of, Los Angeles MORTON, X V
 Research Contracts Branch FIN B-3019 NRC-04-76-246 80/06/16
 200
- 8007010624 Notification of contract execution, Mod 3 to "Evaluation of Retention & Mignation Data from Natural & Inadvertent Repositories " Contractor Stanford Univ JACOUS.A Research Contracts Branch FIN 8-6341 80/04/16 ip
- --B007010627 Mod 3, extending period of performance to 800630, to
 "Evaluation of Retention & Migration Data from Natural &
 Inadvertent Repositories"
 GUSTAFSON,F A Stanford Univ MDRTON,K V Research Contracts
 Branch FIN 0-6341 NR(-04-78-266 80/04/14 2pp
- 8007020007 Notification of contract execution Mod 2 to "Historical Seismicity & Late Cenozoic Faulting in AZ,Part I," Contractor AZ Board of Regents HAGEY,H A Research Contracts Branch FIN B-6798 NRC-04-79-212 BO/05/15 ip
- --B007020009 Mod 2.extending period of performance to B01231.to
 "Historical Seismicity & Late Ceneroic Faulting in AZ.Part
 I "
 CARR.S E Arizona, State of MORTON, K V Research Contracts
 Branch FIN B-6798 NRC-04-79-212 80/05/15 1p
- 8007020024 Notification of contract execution, Mod 3 to "Guantification Classification of Two-Phase Flow Regimes Using Global & Local Neutronic Perturbations " Contractor Univ of WA JACOBS.A Research Contracts Branch FIN B-6324 NRC-04-78-245 80/05/28 1p
- ---8007020025 Mod 3.extending period of performance to 800930.to
 "Quantification Classification of Two-Phase Flow Regimes
 Using Global & Local Neutronic Perturbations "
 TREIDEL, W C Washington, Univ of MORTON, K V Research
 Contracts Branch FIN B-6324 NRC-04-78-245 80/05/28 2pp
- B0070203B6 Notification of contract esecution, Mod 3 to "Source Document Microfiche & Duplicates " Lontractor Microtech Industries, Inc HAGAN, T F Administrative Contracts Branch FIN B-6357 NRC-10-79-651 B0/06/10 1p
- --8007020398 Mod 3 revising billing procedures for pickups & delivery to "Source Document Mirrofiche & Duplicates "
 * Microtech Industries, Inc. MATTIA, M J Administrative Contracts Branch FIN 8-6457 NRC-10-79-651 80/06/03 2pp

- BO07020542 Notification of contract execution.Mod 3 to "Measurement & Stds Development for Nuclear Matl Safguards " Contractor
 - NBS GUSTAVE.R P Research Contracts Branch FIN B-60169 NRC-01-79-011 B0/06/10 Ip
- ~ -8007020553 Mod J. revising scope of work to include changes proposed in NBS 790103 ltr, to "Measurement % 5tds Development for Nuclear Matl Safeguards" SHREVE, D B Commerce. Dept of MDRTON, K V Research Contracts Branch FIN 3-60169 NRC-01-79-011 80/06/10 ip
- 8007020572 Notification of contract execution.Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor BDM Corp SMITH.P A Diffice of Nuclear Material Safety & Safeguards NRC-02-77-201-17 80/06/18 ip
- B007020730 Notification of contract execution, Mod 2 to "Subscriptions to Inside NRC" Contractor McGraw Hill Publishing Co. Inc FLYNN, M. J. Administrative Contracts Branch NRC-10-79-663 80/06/06 1p
- --B007020731 Med 2, increasing total number of subscriptions from 45 to new total of 49 to "Subscriptions to Inside NRC"

 COLLINS, P McGraw-Hill Publications Co MATTIA, M J
 Administrative Contracts Branch NRC-10-79-463 80/04/06 2pp 80/06/06 2pp
- 8007030068 Notification of contract execution.Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Southwest Research Inc 8M174,P A Technical Assistance Contracts Branch NRC-02-77-20 NRC-02-77-201-46
- --8007030071 Mod 2, extending period of performance through 800631, to "Technical Assistance in Development of Regulator Framework for Nuclear Waste Mgt "
 BIROEL, S H Southwest Research Institute DDUGHERTY, D J
 Technical Assistance Contracts Branch NRC-02-77-201-44 00/06/13 Soo
- 8007030336 Notification of contract execution "Statistical Analysis Study to Assist NRC Senior Personnel Hearing Counsel in Preparing for Pending Equal Employment Opportunity Class Litigation " Contractor SL Wolfbein FLYNN-M J Administrative Contracts Branch NRC-10-80-694 80/06/12 by
- --B007030346 Centract "Statistical Analysis Study to Assist NRC Senior Personnel Hearing Counsel in Preparing for Pending Equal Employment Opportunity Class Action Litigation," awarded to SL Wolfbein Wholfbein, S. L. NRC-10-80-694 80/06/12 55pp
- 8007030337 Notification of contract execution "Licensing Technical Assistance," awarded to Boience Applications.Inc ED08WORTH.P J Technical Assistance Contracts Branch FIN 8-4955-0 NRC-02-80-03505 80/06/05 1p
- 8007030353 Notification of contract execution, Mod 3 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor WAPDRA Inc SMITH, P.A. Technical Assistance Contracts Branch NRC-02-77-201 80/04/13 1p
- --B007030357 Mod 3, extending period of performance for one addl yr to "Terhnical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt" KING, W A WAPGRA. Inc. DOUGHERTY, D J Technical Assistance Contracts Brench NRC-02 77-201-36 80/06/13 5pp
- 8007030369 Notification of contract execution, Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Hgt " Contractor Teknekron Inc BMITH.P A Technical Assistance Contracts Granch NRC-02-77-201-18 80/06/19 ip
- ou/v/voel Notification of contract execution.Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor SCS Engineers SMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-21 80/06/18 19 BOO7070021 Notification of contract execution, Mod 5 to "Technical
- 8007070032 Notification of contract execution "Licensing Technical Assistance, "awarded to Science Applications, Inc EDGEMORTH, F J Technical Assistance Contracts Branch FIN D-6947-0 NRC-02-80-03506 80/06/05 1p

- B007070037 Notification of contract execution "Licensing Technical Assistance." awarded to Science Application, Inc EOGENORTH-P J Technical Assistance Contracts Branch FIN-8-8984-0 NRC-02-80-03504 B0/06/05 1p
- BOO7070052 Mod 5.extending period of performance until 810630 to "Technical Assistance in Development of Regulatory Fromework for Nuclear Waste Mgt " PICKARD, W C Squergy, Inc DOUGHERTY, D J Technical Assistance Contracts Branch NRC-02-77-201-23 80/06/18 1p
- --B007070094 Mod 4, extending period of performance until 810630 to "Technical Assistance in Development of Regulatory Framework for Nuclear Haste Mgt "
 HELWIG,R A Donovan, Hamester & Rattien, Inc DDUGHERTY,D J
 Technical Assistance Contracts Branch NRC-02-77-201-34
 80/06/18 2pp
- -8007070057 Hod 5, extending period of performance until 810630 to "Technical Assistance in Development of Regulatory Framework for Nuclear Wate Mgt " CCHEN, S Teknekron, Inc DDUGHERTY,D J Technical Assistance Contracts Branch NRC-02-77-201-18 80/06/18 1p
- -8007070058 Mod 5, extending period of performance until 810430, to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " CONRAD,E T SGS Engineers, Inc DOUGHERTY,D J Technical Assistance Contracts Branch NRC-02-77-201-21 80/04/18 1p
- --B007070060 Mod 5, extending period of performance until 810630, to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " WALSH.B G BDM Corp DOUGHERTY, D J Technical Assistance Contracts Branch NRC-02-77-201-17 80/06/18 1p
- --B007070062 Mod 4, estending period of performance until 810630, to
 "Technical Assistance in Development of Regulatory Framework
 for Nuclear Waste Mgt "
 BTDLLER.B M 9 M Stoller Corp (subs of Arthur D Little, Inc.)
 DUOHERTY.D J Technical Assistance Contracts Branch
 NRC-02-77-201-27 80/06/18 ip
- 8007070065 Natification of contract execution Mod 4 to "Yochnical Assistance in Development of Regulatory Framework for Nuclear Weste Mgt " Contractor Donovan Hammester & Rettien, Inc.
 Inc.
 BMITH,P A Technical Assistance Contracts Branch NRC-02-77-201-34
 80/06/18 ip
- 8007070129 Notification of contract execution, Mod 1 to "Computer Output Microfilming & Production of 35 mm, Aperture Cards " Contractor Microtech Industries, Inc HAGAN, T E Administrative Contracts Branch NRC-10-80-361 80/06/10 1p
- --8007070134 Mod 1.revising billing procedures for pickups & delivery to "Computer Output Microfilming & Production of 35 mm Aperture Cards" RUCCHZOJ P Microtech Industries, Inc. MATTIA, M J Division of Contracts NRC-10-80-361 80/06/10 2pp
- 8007070414 Notification of contract execution, Mod 2 to "Implementation of Executive Development " Contractor Projects Associates, Inc. HDYLE.A Administrative Contracts Branch NRC-10~79-368, 80/06/18
- ---B007070418 Mod 2.oxtending expiration date to 800930 to "Implementation of Executive Development"

 CDNVERSAND, E Project Associates PERLMAN, J Division of Contracts NRC-10-79-368 80/06/18 ip
- GOO709084 Notification of contract execution "Licensing Technical Assistance," awarded to Science Applications, Inc EDOEMORTH.P.J. Technical Assistance Contracts Branch FIN B-6982-0 NGC-02-80-035 80/06/05 1p
- BOO7100010 Notification of contract execution Mod 4 to "Technical Assistance in Development of Regulatory Framework for Nuclear Haste Mpt " Contractor EM Stoller Corp SMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-27 80/04/18 lp
- 8007100011 Notification of contract execution Mod 5 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Synorgy, Inc BMITH-P A Technical Assistance Contracts Branch NRC-02-77-201-23 90/06/18 ip

- 8007100109 Natification of contract execution Mod 2 to "Review of San Unofre Units 2 & 3 Slip Rate vs Magnitude Study "Contractor DB Slemmons TRAOESER.C M Purchasing Section FIN D-6870 NRC-03-79-146 B0/06/18 Ip
- --B007100112 Mod 2: increasing funds, extending expiration date to 800730 & increasing manday effort from 40 to 59 mandays to "Review of San Onofre Units 2 & 3 Silp Rate vs Magnitude Study "SLEMNONS, D B Slemmons, D B PERLMAN, J Division of Contracts FIN B-6870 NRC-03-79-146 80/06/18 lp
- 8007100304 Notification of contract execution.Mod 1 to "Purchase & Maint of Multichannel Analytical Equipment for NRC Regions"
 Contractor Nuclear Data.Inc
 HAGAN, T T Administrative Contracts Branch FIN 3-1005
 NRC-05-80-254 80/06/10 1p
- --8007100312 Mod 1, revising acceptance & billing provisions & correcting administrative error, to "Purchase & Maint of Multichannel Analytical Equipment for NRC Regions"
 RIZZO,R R Nuclear Data, Inc MATTIA,M J Administrative Contracts Branch FIN B-1005 NRC-05-80-254 80/06/10 2pp
- 8007100361 Notification of contract execution "Nondestructive Examination (NDE) Nobile Van.Region 1." awarded to Mobile Bys WIGOINS.E J Administrative Contracts Branch NRC-05-80-259 BD/06/18 1p
- --8007100368 Contract "Nondestructive Examination (NDE) Mobile Van. Region 1." awarded to Mobile Sys KIMMEL.JJ Mobile Systems MATTIA.M J Administrative Contracts Branch NRC-05-80-259 80/06/18 43pp
- 8007110535 Natification of contract execution, Mod 6 to "Coordination of Federal/State Radiation Control Activities & Assistance in Solving Radiation Control Problems " Contractor FDA FLYNN.M J Administrative Contracts Branch FIN B-1620 NRC-04-76-247 80/06/20 ip
- --8007110539 Mod 6, setting forth effort for 1980, extending period of performance & providing addl funds, to "Coordination of Federal/State Radiation Control Activities & Assistance in Solving Radiation Control Problems"

 CROWN.H M HEW.Dopt of. Food & Drug Administration MATTIA, M J Administrative Contracts Branch FIN B-1420 NRC-04-74-247
- 8007110559 Notification of contract execution, Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Maste Mgt " Contractor Kaman Sciences Corp SHITH, P A Technical Assistance Contracts Branch NRC-02-77-201-43 80/06/19 ip
- 8007110572 Notification of contract execution.Mod 2 to "Consulting Bycs in Connection W/NRC Antitrust Hearings " Contractor Miner & Miner FOSTER, J Technical Assistance Contracts Branch FIN 8-1119 NRC-03-76-273 80/06/13 1p
- --B007i10975 Med 2.deobligating funds & closing out contract, to "Consulting Svcs in Connection W/NRC Antitrust Hearings" MEYERG, C W Miner & Miner, Inc DOUGHERTY, D J Technical Assistance Contracts Branch FIN 8-1119 NRC-03-76-273 RO/O/J/13 In
- H007140200 Notification of contract execution "ADP 9ys Support," awarded to Technassociates Inc FLYNN, M J Administrative Contracts Branch NRC-10-80-673 H0/04/30 1p
- --8007140203 Contract "ADP Sys Support," awarded to Technassociates, Inc ZENTNER, M A Technassociates, Inc COLLINS, F M Division of Contracts NRC-10-80-673 80/06/30 79pp
- 8007140210 Open Solicitation RS-ADM-80-669 for contractor to place new & renewal subscriptions for domestic & foreign periodicals, serials & other related svcs at agency price & guarantee delivery of all issues on each subscription MATTIA.M J Administrative Contracts Branch 80/06/16 69pp
- B007140512 Notification of contract execution, Mod 3 to "Loan Agreement Between State of IL, DDT & NRC to Conduct Joint Study on Transportation of Radioactive Matl in IL " Contractor IL Dept of Public Health FLYNN.M J Administrative Contracts Branch NRC-06-78-358 90/07/03 1p

- ---8007140521 Mod 3.extending period of performance & adding add1 reporting requirements to "Loan Agreement Between State of It.DUT & NRC to Conduct Joint Study on Transportation of Radinactive Matt in It."

 KEMPINERS.W L Illinois. State of MATTIA.N J Administrative Contracts Branch SANTMAN.L D Transportation. Dept of NRC-06-78-358 80/07/03 2pp
- 8007140590 Notification of contract execution Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Myt " Contractor IRT Corp SMITH.P A Administrative Contracts Branch NRC-02-77-201-40
- 8007140626 Notification of contract execution "Licensing Technical Assistance," awarded to Science Applications, Inc EDGEHORTH.P L Technical Assistance Contracts Granch FIN B-6953-0 NRC-02-BO-035 80706/05 lp
- --8007140633 Contract "Licensing Technical Assistance," awarded to Science Applications. Inc * Science Applications. Inc DDUGHERTY, D J Tochnical Assistance Contracts Branch FIN 8-4953-0 NRC-02-80-035 80/06/05 5pp
- B00715004B Nutification of contract execution. Mod 2 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor Social Research Application Corp BHITH P A Technical Assistance Contracts Branch NRC-02-77-201-42 B0/06/19 1p
- 8007150055 Notification of contract execution Med 4 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor GED-Ctrs. Inc SMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-35 80/06/19 ip
- 8007150040 Notification of contract elecution, Mod 4 to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt " Contractor R Stone & Co BMITH.P A Technical Assistance Contracts Branch NRC-02-77-201-28 80/04/19 1p
- 800716020B Notification of contract execution.Mod 2 to "Consulting Svcs in Connection W/NRC Antitrust Hearings" Contractor Barbay Engineers 8HEW.D Technical Assistance Contracts Branch FIN B-1119 NRC-03-76-272 80/07/02 ip
- --8007160229 Mod 2, closing out contract, to "Consulting Svcs in Connection W/NRC Antitrust Hearings" BROOKS,F M Darbay Engineers, Inc FIN D-1119 NRC-03-76-272 BD/07/02 ip
- B007160490 Mod 2.extending period of performance until 810630, to "Technical Assistance in Dovelopment of Regulatory Framework for Nuclear Waste Mgt "BOWNE,W D IRT Corp DDUOHERTY.D J Tochnical Assistance Contracts Branch NRC-02-77-201-40 B0/04/19 ip
- --8007160476 Mad 2.extending period of performance until B10630, to
 "Technical Assistance in Development of Regulatory Framework
 for Nuclear Waste Mgt "
 LEMIS C Social Research Applications Corp DOUGHERTY, D J
 Technical Assistance Contracts Branch NRC-02-77-201-42
 B0/06/19 10
- --8007160498 Mod 2.extending period of performance until 910630, to "Technical Assistance in Development of Regulatory Framework for Muclear Haste Mgt"
 MARRAM E P Geo-Centers, Inc. DDUGHERTY, D J Tochnical Assistance Contracts Branch NRC-02-77-201-35 80/06/19 1p
- --8007160504 Mod 4, extending period of performance until B10630, to "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt"
 KAHLE: R Ralph Stone & Co DOMOHERTY.D J Technical Assistance Contracts Branch NRC-02-77-201-28 80/06/19 1p
- --8007160513 Mod 2.extending persod of performance until 810630.to
 "Technical Assistance in Development of Regulatory Framework
 for Nuclear Waste Mgt "
 BRIDGES.A P Kaman Sciences Corp DOUGHERTY.D J Technical
 Assistance Contracts Branch NRC-02-77-201-43 80/06/19 [p
- 8007170122 Notifiration of contract execution, Mod 5 to "Survey Instruments " Contractor Eberling Instrument Corp MEDROW.L A K Administrative Contracts Branch (IN B-1215 NRC-05-79-242 80/07/08 Ip

- 0129 Nod 2.decreasing funds to "Survey Instruments" R Eberline Instrument Corp. MATTIA.M J. Administrative racts Branch FIN 8-1215 NRC-05-79-242 80/07/08 lp
- 15 Notification of contract erecution, Mod 1 to "Dovelopment of Repulatory Program in Support of UNIRCA" Contractor of CA
 J Administrative Contracts Branch FIN B-1653
 -80-308 80/07/10 Ip
-)145 Mod I.incrpasing funds to "Development of State Regulatory ram in Support of UHIRCA" alifornia. State of MATIIA.N J Administrative Contracts b FIN B-1653 NRC-06-80-308 80/07/07 5pp
- of Notification of contract execution, Mod 5 to "Mobile Lab." ter Mobile Sys

 E Administrative Contracts Brunch FIN B-1014
 79-257 80/07/08 1p
- J141 Mod 5.decreasing funds to "Mobile Lab " L.J.J. Mobile Systems MATTIA.M.J. Administrative Contracts th FIN 8-1014 NRC-05-79-257 80/07/08 lp
- 7 Notification of contract execution.Mod 1 to "Cost of ound Tests" Contractor American Mine Svcs.Inc $^{\rm LR}$ Administrative Contracts Branch $^{\rm NRC-02-80-055}$ 7 $^{\rm LR}$
-)172 Mod i,adding J Germundson to key personnel under "Cost of iground Tests "
 [GALL.A J American Mine Services, Inc MATTIA.H J isstrative Contracts Branch NRC-02-88-095 80/06/09 ip
- 2 Notification of contract elecution, Mod 1 to "Development of legulatory Programs in Support of U Mill Tailings on Control Act " Contractor State of TX i J Administrative Contracts Branch FIN 8-1652 80-307 80/06/30 ip
-)216 Mod 1.extending period of performance & increasing funding, evelopment of State Regulatory Programs in Support of 1 Tailings Radiation Control Act "
 xas. State of MATTIA.M J Administrative Contracts Branch 1652 NRC-06-80-307 80/06/30 1p
- / Notification of contract execution Hod 4 to "Word Processing Contractor Automated Correspondence Sys. Inc. R. Administrative Contracts Branch NRC-10-78-598
- 222 Mod 4.providing add1 funds, to "Word Processing Svcs "tomated Correspondence Systems, Inc. MATTIA: M.J. strative Contracts Branch NRC-10-78-598 80/06/30 1 80/06/30 1n
- 6 Notification of contract electric "Development of Automated Selection Sys." awarded to Gasser Associates, P.A. Administrative Contracts Branch FIN B-1214 BO-253 BO/06/27 ip
- 193 Contract "Development of Automated Vendor Selection Sys." ed to Gasser Associates, P A. R.E.R. Gasser Associates, P A. MATTIA.M J. Administrative acts Branch FIN B-1214 NRC-05-80-253 80/06/27 224pp,
- i Notification of contract execution. Mod 1 to "Davelopment of spulatory Programs in Support of U Mill Tailings on Control Act " Contractor State of DR J Administrative Contracts Branch FIN B-1652 80-309 80/06/30 tp FIN R-1452
- 524 Mod 1. extending period of performance & increasing funding, evelopment of State Regulatory Programs in Support Hill Tailings Redustion Control Act "egon. State of MATTIA, M.J. Administrative Contracts Branch N-1652 NRC-04-80 309 80/04/30 Spp
- 5 Notification of contract execution, Mod I to "Development of equiatory Programs in Support of U Hill Tailings on Control Act " Contractor State of WA J Administrative Contracts Branch FIN 0-1652 30-306 80/06/30 Ip
- 113 Mod Lincreasing Funds, to "Development of State Regulatory ams in Support of U Mill Tailings Radiation Control
- shington, State of MATTIA,M J Administrative Contracts , FIN 8-1652 NRC-06-80-306 80/06/30 8pp

- 8007210122 Notification of contract elecution. Mod 1 to "Development of MUZZIUZZ Notification of contract elecution Mod I to "De" State Regulatory Programs in Support of U Mill Tailings Radiation Control Act " Contractor State of NM FLYNN,M J Administrative Contracts Branch FIN B-1652 NRC-96-80-676 80/06/30 Ip
- ~~B007210135 Mod 1, adding funds, to "Development of State Regulatory Programs in Support of U Mill Tailings Radiation Control
 - t " New Mexico, State of MATTIA,N J Administrative Contracts anch FIN 8-1652 NRC-06-80-676 B0/06/30 Spp
- 8007210154 Notification of contract execution, Mod 1 to "Development of State Regulatory Programs in Support of U Mill Tailings Radiation Control Act " Contractor State of CO FLYNN, M J Administrative Contracts Branch FIN 9-1652 NRC-06-80-311 80/06/30 1p
- --8007210160 Mod i,adding funds to "Development of State Regulatory Programs in Support of U Mill Tailings Radiation Control
 - t" Colorado, State of MATTIA.M J Administrative Contracts anch FIN 8-1652 NRC-06-80-311 80/06/30 Spp
- 8007210253 Notification of contract execution "Steam Generator Modeling During Reflood Stage of LOCA:" awarded to MIT BROMBERG.B Research Contracts Branch FIN B-7229 NRC-04-6 80706/26 1p NRC-04-80-219
- --B007210258 Contract "Steam Generator Modeling During Reflood Stage of LDCA." awarded to MIT DUMNER.O H Massachusetts Institute of Technology MORTON, K V. Research Contracts Branch FIN N-7229 NRC-04-80-219 80/06/24
- B007210263 Notification of contract execution "Environ Monitoring Program w/State of NY." awarded to State of NY BAISDEAL Research Contracts Brench FIN B-5109 NRC-05-80-271 80/01/01 1p
- --8007210267 Contract "Environ Monitoring Program w/State of NY," awarded to State of NY LANAHAN, H P New York, State of MORTON, K V Research Contracts Branch FIN B-5109 NRC-03-80-271 80/01/01 16pp
- 8007210317 Notification of contract execution "ADP Sys Support," awarded to Small Business Administration Subcontractor Technossociates Inc FLYNNM J Administrative Contracts Branch NRC-10-80-673 80/06/24 jp
- --8007210331 Contract "ADP Bys Support," awarded to Small Business Administration Subcontractor Technassociates, Inc COLLINS,F M Small Business Administration CHILK,S J Office of the Secretary of the Commission ZENTNER,M A Technassociates, Inc 89/06/24 77pp
- B00724016B Notification of contract execution Mod 2 to "Cost of Underground Tests" Contractor American Mine Svcs.Inc COLEMAN.R Administrative Contracts Branch NRC-02-80-055 B0/08/09 ip
- --8007240170 Mad 2.extending contract term by i wk.to "Cost of Underground Tests" * American Mine Services.Inc MATTIA.M J Administrative Contracts Branch NRC-02-80-055 80/06/09 ip
- --8007240173 Confirms agreement w/proposed extension until 800728 for contract completion MCDOUGALL.J American Mine Services, Inc NRC-02-80-055 80/07/11 ip
- 8007250556 Notification of contract execution, Mod 1 to "Site Characterization Test Programs " Contractor.Golder Associates
 COLEMAN, R Administrative Contracts Branch NRC-02-80-256.
 B0/06/09 19
- --B007230362 Mod 1.extending period of performance, to "Site Charactersiation Test Programs " * Colder Associates MATTIA,M J Administrative Contracts Branch NRC-02-80-236 B0/06/07 2pp
- B007250549 Nutification of contract execution, Mod 7 to "Steam-Water Interfacial Transport " Contractor Northwestern Univ HAGEY,H Research Contracts Branch FIN B-6188 NRC-04-77-052 80/07/02 ip

- --8007250578 Mod 7.providing funds for addl work scope.to "Steam-Water Interfactal Transport "
 HINTZER, D. Northwestern Univ HORTON, K.V. Research Contracts
 Branch FIN 8-6188 NRC-04-77-052 80/07/02 4pp
- B007280234 Notification of contract execution "Characterization of Existing Surface Conditions at Sheffield Low Level Waste Site Disposal Facility," awarded to Harding-Lawson Associates
 LITTLE.N Administrative Contracts Branch FIN B-6970-0
 NRC-02-80-057 80/07/09 ip
- --8007280236 Contract "Characterization of Existing Surface Conditions at Sheffield Low Level Waste Site Disposal Facility."

 awarded to Harding-Lawson Associates
 HEIM.0 E Harding-Lawson Associates PERLMAN.J Administrative
 Contracts Branch FIN B-6970-0 NRC-02-80-057 80/07/09 10pp
- 8007280338 Submits Progress Rept 30 for June 1980 Site visit task underway Itinerary encl PLATO P Michigan, Univ of NRC-01-77-180 80/04/27 4pp
- 8007280520 Notification of contract execution, Mod 4 to "Effluent Inventory Bys on Sheffield Low Level Waste Disposal Site " Contractor NUS Corp Contractor ...
 SMITHS A T Technical Assistance Contracts Branch NRC-02-78-035
- --8007280527 Mod 4.adding addressme, to "Effluent Inventory Sys on Sheffield Low Level Waste Disposal Site " EDMONDBON L R NUB Corp DOUGHERTY, D J Technical Assistance Contracts Branch NRC-02-78-035 80/07/03 2pp
- 8007280712 Notification of contract execution, Mod 1 to "Site Characterization Test Programs " Contractor Goler Associates Administrative Contracts Branch NRC-02-80-056 COLEMAN, R 80/06/09
- --8007280717 Requests 1 wk extension to "Site Characterization Test PENTZ, D L Golder Associates NRC-02-80-056 80/06/09 1p
- BOO7300577 Notification of contract execution "Development of Communications Console Design," awarded to Bendix Field Engineering Corp HUYLE:A Administrative Contracts Branch FIN D-1259 NRC-03-80-290 80/07/10 ip
- ---B007300590 Contract "Development of Communications Console Design," awarded to Bendix Field Engineering Corp ENOLE,N J Bendix Corp PERLMAN,J Administrative Contracts Branch FIN B-1259 80/07/10 5pp
- B007300579 Notification of contract execution.Mod 6 to "Electrostatic Copyling Sycs " Contractor Potomac Research Inc FLYNN,M J Administrative Contracts Branch NRC-17-77-152 B0/07/11 ip
- -80073005B1 Mod 6,extending period of performance.to "Electrostatic Copying Svcs " BAUMANN,R 0 Potomac Research, Inc MATTIA.M J Administrative Contracts Branch NRC-17-77-152 B0/07/11 1p
- B007300595 Notification of contract execution, Mod 3 to "Personnel Neutron Dosimetry for Nuclear Power Plants" Contractor Rennselaer Polytechnic Inst JACOBS, A Research Contracts Branch FIN 8-6451 NRC-04-78-263 B0/06/27 Ip
- --8007300598 Mod 3, extending period of performance for seven months; to "Personnel Neutron Dosimetry for Nuclear Power Plants" LUGIUDICE, J M Rensselaer Polytechnic Inst MORTON: K V Research Fin B-665 NRC-04-78-263 80/04/27 Rpp.
- BOO7310006 Notification of contract execution Mod 2 to "Presentation of General & Refresher Courses in Concrete Technology & Codes " Contractor Portland Cement Association BAISDEN, L. Research Contracts Branch FIN X-1175 NRC-05-79-261 BO/07/01 ip
- --8007310010 Mod 2, changing personnel, to "Presentation of General & Refresher Course in Concrete Technology & Codes "

 » Portland Cement Association MORTON.K V Research Contracts
 Branch FIN X-1175, NRC-05-79-261 80/07/01 ip

- FINANCIAL DISCLOSURE INFORMATION
- 8007020737 informs that confidential statement of employment & financial interests has been revioued Exemption from provisions of IOCFRO 735-21 must be granted in order to allow work on licensing matters involving GE VOLLMER.R H Division of Engineering 80/06/11 ip
- 8007130061 Forwards list of Day of Safety Technology employees in grades GS13-15 & employees below GS-13 an occupational codes of interest for whom submission of confidential financial statements are required MATTSDN,R J Division of Safety Technology 80/07/01 4pp
- B007300030 Advises that request for exemption from 10CFRO 735-21 is granted & participation in matters before NRC affecting Westinghouse permitted Interest in pension fund not so substantial as to affect impartiality VOLLMER.R H Division of Engineering B0/07/16 1p
- FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES FOIA
- 7812210553 Forwards IE Insp Rept 30-12052/78-01 on 781011 No items of noncompliance noted Insp included exam of activities at Pittsburgh office re radiation safety & compliance w/rules & regulations W/out rept MCCLINTOCK, R O Region 1. Philadelphia. Fuel Facility & Materials Safety Dranch 78/10/31 lp
- 7906200225 Requests Executive Branch position re GC application for license to export six detector assemblies to India Forwards 790507 application H/o encl Assistant Director for Export/Import & International OPLINGER, 0 0 Assist Safeguards 79/05/15
- 7909110639 Responds to 790703 ltr re approval of NRC actions HENDRIE, J M Commission 79/07/16 ip
- 8005070523 Ack receipt of 800130 ltr informing NRC of steps taken to correct violations noted in IE Insp 79-01 on 791212 MCCLINTOCK,R O Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 80/02/24 lp
- --8005090524 Responds to NRC 800109 ltr re violations noted in IE insp on 791212 Corrective actions discussed infractions \(\text{w} \) technicians involved Classes planned \(\text{w/all} \) technicians on requirements \(\text{terministans} \) restrictions CARMEL, \(P \) Rad Services, Inc 80/01/30 ip
- --8005090527 Discusses IE Insp 79-01 on 791212 & forwards natice of violation MCCLINTOCK,R O Region 1, Philadelphia, Fuel Facility & Materials Safety Branch BO/01/09 2pp
- --8005090529 Notice of violation from insp on 791212 Noncompliance noted required radiation surveys not performed on packages
 - Region 1. Philadelphia. Office of the Director 80/01/09 2pm
- 8005200366 Ack receipt of 800312 resolution in support of nuclear NOSCOUGH ARE PRESENT OF BOUGHZ PESSIONS IN SUPPORT OF MUCL energy adopted by Northumberland County Board of Supervisors Certain short-term tasks, identified in TMI Action Plan, must be completed prior to OL Issuance KANMERER: C Office of Congressional Affairs BD/04/2B 2pp
- 8005270154 Submits legal opinion on two questions re operation of U Mill Tailings Radiation Control Act of 1978 NRC has legal authority to impose groundwater protection conditions & concurrent jurisdiction over nonradiological hazards SHAPAR. H K Dffice of the Executive Legal Director 80/04/28
- 8005270603 Ack receipt of 800421 itr informing NRC of steps taken to correct violations noted in IE insp of License 37-13129-01 CROCKER, HW Region 1, Philadelphia, Office of the Director 80/05/07
- --8005299A07 Responds to NRC 800328 ltr re violations noted in IE insp of License 37-13128-01 on 800228 Corrective actions new procedures will be developed to improve coordination in receipt of incoming radioactive samples KIM.S M Raduation Management Corp 80/04/21 28pp
- --8005290612 Discusses IE insp of License 37-13129-01 on 800228 & forwards notice of violation CROCKER.H W Region 1. Philadelphia. Office of the Director . 2pp 80/03/28

- --B005290615 Notice of violation from insp on B00228 Noncompliance noted failure to keep records showing receipt of radioactive samples
 - Region 1. Philadelphia, Office of the Director 80/03/28 1p
- 8006±20402 Discusses reasons for delays in licensing new nuclear plants.in response to 800424 requests re WA Cosgrove comments Delays caused by post-TMI efforts to improve safety at Operating plants KAMMERER.C Office of Congressional Affairs 80/05/20 2pp
- BOO6120419 Responds to 800423 re i. Nutter concerns about nuclear plant siting & evacuation plans NRC not responsible for decision re wheather on not nuclear power should exist in US Proposals to stop nuclear power development not enacted HAMMERER, C Dffice of Congressional Affairs 80/05/07 2pp
- 8007010082 "AECL/BNWL Cooperative Pellet/Cladding Interaction Program" PANKASKIE.P J Brookhaven National Laboratory MEYER.R 0 Core Performance Branch 77/11/30 18pp
- ~~B007010093 Summary of 740116 meeting w/GE re fuel performance Onsite inspite techniques reactor history & failure mechanisms were discussed Lists GE conclusions.AEC impressions & recommended actions Lists of attendees encl
 COFFMAN.F. D. Atomic Energy Commission. Directorate of Licensing 4рр
- --8007010108 Forwards summary of NRC 750305 meeting w/8E in San Jose to discuss GE fuel failure experience & preconditioning interim operating mgt recommendations Discussion nutline & list of meeting attendees encl W/o encls
 COFFMAN,F D Core Performance Branch 75/03/19 1p
- ---BOO7010114 Forwards summary of NRC 750417 meeting w/B&H in Bethesda.MD to discuss pellet-cladding mechanical interaction Discussion outline & list of meeting encl W/o encls COFFMAN.F D Core Performance Branch 75/04/23 lp
- --8007010126 Summary of 750805 meeting w/GE, Comm Ed, BNML. Northern States Power Co & Boston Edison Co re preconditioning interim operating mgt recommendations Known patterns of reactor operations have caused fuel failures Agenda encl COFFMAN.F D Core Performance Branch 75/08/15 5pp
- --BOO7010145 Discusses need for prompt NRC action re pellet-clad interaction Recommends that encl ltr be sent to each licensee Lists other factors to be considered M/o encl ROBS.DF Assistant Director for Reactor Bafety 75/08/25 75/08/25 2en
- --8007010149 Summary of 760309 meeting w/Westinghouse & BNWL in Bethesda. MD re pellet-clodding interaction Meeting agenda & attendees list encl SIEGEL.B L Core Performance Branch 76/04/01 7pp
- --B007010152 Expresses thanks for info & cooperation afforded B Siegel & F Coffman during recent trip to labs Pellet-cladding interaction model discussions & data analysis provided clearer understanding of Canadian results
 ROSS.D F Assistant Director for Reactor Safety 76/04/14 ip
- -8007010158 Forwards summary of NRC 740318 meeting w/AECL in Ontario, Canada re pellet-cladding interaction Intent of meeting was to discuss current Canadian fuel operating recommendations for CANDU-DHW reactors & basis for recommendations COFFMAN.F D Reactor Safety Branch 76/06/01 7pp
- --8007010161 Summary of 760408 meeting w/GE & BNML in Bethesda,MD to review pellet-cladding interaction failures & effects on reactor design & operation List of ettendees encl GIEGEL,D L Care Performance Branch 76/04/26 Spp
- --8007010165 Summary of 760421 meeting w/Exxon Nuclear Co in Sethesda, MD to discuss pellet-cladding interactions Exxon Nuclear has had no fuel failures on bundles being irradiated Meeting agenda & list of attendees encl

 SIEGEL, B L Core Performance Branch 76/04/30 4pp
- --B007010168 Summarizes NRC 760519 meeting w/BAW in Bethesda.MD to discuss pellet-cladding interactions B&W has experienced flow primary coolant activity levels indicative of few failures Neeting agenda & attendes list encl BIEGEL.B L Core Performance Branch 76/05/26 App
- ---B007010173 Summarizes NRC 760521 meeting w/C-E in Bethesda, MD to discuss pellet-cladding interactions Lists data presented From overpower ramp tests Meeting agenda & list of attendees encl SIEGEL.B L Core Performance Branch 76/07/09 4pp

- --8007010176 Submits description of data for proposed joint pallet-cladding interaction program Lists items for review.prior to signing program agreement w/BNWL CHECK.P S Core Performance Branch 77/02/08 2pp
- --8007010181 Summary of 770615 moeting w/LWR fuel vendors in Bethesda.MD re LWR fuel damage criteria.mechanisms & limits List of attendees,agonda & excerpts from SRPs encl TCKAR.M Core Performance Branch 77/06/23 14pp
- --B007010187 Forwards brief summary of pellet-cladding info reviewed at Chalk River Nuclear Labs Lists questions which arose from efforts to establish fuel rod failure probabilities from Pickering-B bundle shift data PANKASKIE, P J Battelle Memorial Instituto, Pacific Northwest Laboratory 77/12/09 2pp
- --8007010191 Updates evaluation of applicability of FUELDORAM to LWR pellet-cladding failures Model will generate failure probabilities for CANDU data subset which will provide reasonable fuel bundle to fuel rod failure correlation PANKASKIE, P J Battelle Memorial Institute, Pacific Northwest Laboratory 78/01/23 10pp
- --8007010194 Forwards examples of carrespondence w/US fuel vendors concerning contributions to AECL program w/FUELOGRAMB Description of contract: "LWR Fuel Pellet-Cladding Interaction & Failure Limits," encl MEYER, R G Core Performance Branch FIN 8-1195 78/02/14 3ρρ
- ---8007010198 Requests data presented at 760519 pellet/cladding interaction meeting between NRC & B&W. Data needed for assessment of applicability of AECL pellet/cladding interaction model to LWR fuels ROSS.D F Assistant Director for Reactor Safety 77/11/30 ip
- --8007010204 Confirms telcons identifying addl QE info needed for use in joint BMML/AECL program to assess applicability of FUELDGRAMS to LMRs RDBS,DF Assistant Director for Reactor Safety 77/03/01 1p
- --8007010207 Forwards agenda for 780302 pellet/cladding interactions meeting in Richland Requests notification if changes CHECK, PS Core Performance Branch 78/02/15 2pp
- ---8007010210 Recommends final meeting & rept re cooperative pellet/ cladding interactions effort w/Canadians Rept should be nonproprietary & contain descriptions of relevant FUELOGRAMS & predictive models MEYER, R O Core Performance Branch 78/07/12 ip
- --8007010215 Requests add1 fuel behavior data re pellet/cladding interaction Data will be used for developing improved fuel damage limits for licensing of PWRs & BWRs Lists current needs for program, present status & licensing impact DENTON.H R Defice of Nuclear Reactor Regulation, Director 79/08/07 7pp
- --8007010218 Speech entitled "Development of Improved LWR Fuel Damage Limits for Reactor Licensing," presented at ANS 781114 meeting in Washington, DC TOKAR, M Core Performance Branch 78/11/14 37pp
- --B007010222 Summary of 781212 meeting w/AECL & BNWL in Ontario Canada re draft rept on BNHL/AECL cooperative technical assistancy program on pellet/cladding interaction FVELOGRAM Lists meeting objectives Heeting agenda encl TOKAR.M Core Performance Branch 78/12/15 3pp
- ~8007010227 Notifies of 790503 meeting in Portland.OR to discuss utilization of data re fuel failure caused by pellet/ cladding interactions Forwards draft rept for review W/o TEDESCO.R L Assistant Director for Reactor Safety 79/03/27
- --8007010230 Provides procedure for transmittal of data requested for ENML consultant use in PROFIT pellet/cladding interaction model KNIEL,K Core Performance Branch 79/08/02 1p
- ~-8007010233 Comments on "Draft Rept on Joint Program by BNML & AECL, Mar 1977 " PROFIT data base is strongly biased toward high failure rate Independent variables are ambiguously defined OLDBERG. T Electric Power Research Institute 79/05/07 App

- --8007010238 Submits tabulation of estimates of fuel failure probability for control rod withdrawal ATMS in PMR Hot standby to 20% rated power & full (100%) to averpower (110%) were considered in estimates PANKASKIE,P J Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/08 2pp
- --8007010241 Requests proposal from BNWL to provide technical assistance re fuel failure to Div of Sys Bafety Forwards statement of work Authorization to commence work becomes effective upon acceptance of executed NRC Form 173
 SHRUEDER, F Division of Systems Safety 79/08/07 7pp
- ---8007010244 "Pellet/Cladding Analysis of Turbine Trip W/o Bypass," final rept.Jan 1979, prepared for BNWL POMERDY, D L , SAVAR, T O , WARING, J P Scanpower, Inc 79/01/31 B5nc
- --8007010249 Requests proposals from INEL to provide technical assistance refuel performance to Div of Sys Safety Forwards statement of work Authorization to commence work becomes effective when NRC Form 173 accepted SCHROEDER.F Division of Systems Safety FIN A-4268 79/08/24
- 8007010079 FOIA request for 57 documents referenced in M Toker memo to ACRB re pellet-cladding interaction KIQQINB,S R Westinghouse Electric Corp 80/05/06 7pp
- 8007020122 Responds to FOIA request for documents re US radiation monitoring or related activities of French nuclear weapons testing since 1966 Documents are being referred to CIA for disclosure determination & direct response FELTON, J M Division of Rules and Records 80/06/25 ip
- 8007020127 FOIA request for documents re UB radiation monitoring or related activities of French nuclear weapons testing since 1946 by Wheeling T AGM US Instruments ship or other vessel TREAKLE.K Greenpeace Foundation 80/05/29 ip
- 8007020132 Responds to FOIA request for all memos, ltrs & records concerning organization, People Generating Energy NRC has no files indexed or maintained under organization Other relevant info may be available in LPDRs FELTON, J M Division of Rules and Records 80/06/25 lp
- 8007020136 FOIA request for all memos.ltrs & records concerning organization.People Generating Energy Affidavit encl BELIN.A Center for Law in the Public Interest 80/06/11 2pp
- 8007020284 Add1 response to FOIA request for info re award of contract NRC-10-77-140 issued to Damans & Associates Forwards documents listed in encl Info partially & completely withheld NRC advice & opinions (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records 80/02/12 3pp
- --8007020287 Proposal evaluation rept. Solicitation RS-77-38, "Audit of Supergrade Positions." Info partially withheld NRC advice & opinions (ref FOIA Exemption 5)
 JONES. C C. Commission MATTIA, M. J. Administrative Contracts
 Branch 77/06/23 App
- --8007020272 Final proposal evaluation rept & recommendation. Solicitation RS-77-38, "Audit of Bupergrade Positions" Info partially withheld NRC advice & opinions (ref FDIA Exemption 5) JONES, C C Commission MATTIA, M J Administrative Contracts Branch 77/06/23 14pp
- B007020460 Responds to FOIA request for info re dates for scheduled & unscheduled outages for plants located in continents! US & info related to maint operations being performed on plants Forwards NUREO-OORO, Vol 4 W/o enc!
 FELTON.J M Division of Rules and Records B0/06/25 ip
- 8007020463 FOIA request for info re dates for scheduled & unscheduled outages for plants located in continental US & info related to maint operations being performed on plants
 SKORDHOD, P M Briggs Engineering & Testing 80/06/04 ip
- 8007030007 FOIA request for documents re transportation of spent fuel from Fortsmouth, VA to Sevennah River plant in Aiken, SC MEYER, K A Affiliation Unknown 80/06/03 Rpp
- 8007030033 Addi response to FDIA request for documents listing nuclear plant locations, accidents occurring at each location, environ impact results, radiation leaks, & nuclear waste depots around US, Forwards J Braun 800612 memo FELTON, J M. Division of Rules and Records 80/06/23 ip

- --800703003B Provides response to FOIA Request 80-27B for list of nuclear waste depots around US locations & cost Request is interpreted to reference commercial high & low level & U mill tailings BRAUN.J Licensing Process & Integration Branch BO/04/12 &pp
- BOO7030064 Responds to FDIA request fin summaries of all radiation exposure data & NRC or ACRS position papers leading to NRC adoption of 0 1 as max radiation permissible Forwards documents listed in App A No position papers exist W/o encl FELTON.J M Division of Rules and Records 80/06/25 3pp
- 8007030064 FDIA request for summaries of all radiation exposure data & NRC or ACRB position papers leading to NRC adoption of O 1 as max radiation permissible dose ICE.R D Dilahoma. Univ of 80/05/27 2pp
- 8007030331 Responds to FOIA request for NRC telephone directory Forwards directory W/o encl FELTON,J M Division of Rules and Records 80/06/26 App
- BOO703032 FOIA request for NRC telephone directory
 GONCALVEB, A National Employee Benefit Associates 80/06/20 lp
- 8007080036 BECY-78-429
 Discusses procedure by which NRC can determine whether matters of alleged or suspected criminal violations of law should be referred to DOJ Recommends that Inspector & Auditor Office accept full responsibility
 BHAPAR.H K Office of the Executive Legal Director 75/08/11 3pp
- B007090377 FOIA request for winning proposal in response to RFP R8-NRR-B0-102. "Energetic Thermal Interactions Recriticality & HTGR Accident & Transient Coolant Flow "RAUNER: L M Advanced Technology, Inc. 80/02/29 1p
- 8007090380 Response to RFP R8-NRR-80-102, "Energetic Thermal Interactions, Recriticality & HTGR Accident & Transient Coolant Flow " Describes proposed technical approach, research plans, schedules & milestones THCOFANUS, T O Purdue Univ R8-NR-80-102 79/12/15 54pp
- BOO71000DB Add1 response to FDIA request for documents to licensing of facility & transcripts of closed Commission meetings App A documents available in PDR Document I of App B & purtions of Documents R-21 withheld (ref FDIA Exemptions 1.4 & 5)
 FELTON J M Division of Roles and Records 80/06/27 5pp
- --8007100019 Discusses application of inventory difference regression equation to Aug inventory Info withheld procedures for safeguarding nuclear meth & NRC predectational advice, opinions & recommendations (ref fDIA Exemptions 4 & 5) MEBSINGER, M. Haterial Control & Accountability Development Branch 79/09/24 3a
- --B007100020 Summary of 800102-03 meeting between util & NRC in Silver Spring.MD re MCA license conditions applicable for resumed highly enriched U operations Info partially withhold (ref FDIA Exemptions 4 & 5) Charles encl JOY.D Material Control Licensing Branch 80/01/10 ip
- --8007100023 Forwards mat1 balances covering inventory for 790814-1004
 Info withheld safeguards & security measures (ref FOIA
 Exemptions 3 & 4)
 HENSLEY.K D Nuclear Fuel Services. Inc. (subs. of Getty Oil Co.)
 NFE 79-1385 79/12/05 5pp
- --8007100028 Forwards detailed rept on current & planned projects designed to improve facility accountability sys & associated inventory difference results Rept withheld (ref FOIA Exemptions 3 & 4)
 TAYLOR, C W Nuclear Fuel Services, Inc. (subs. of Outty Oil Co.)
 NFE 79-081 79/10/23 ip
- --8007100032 Discusses BECY-79-650A. "NRC Regulation of Highly Enriched U Operations at Facility" Lists additequirements needed if position taken by JF Absente in 800109 memo is adopted info partially withheld (ref FOIA Exemption 3)
 HANRAHAN.E J Haterial Control Licensing Branch 80/01/11 Rpp
- --B007100038 Summary of Commission R00116 meeting re BECY-79-680 & SECY-79-650A concerning facility Scape & quality of matl control & accounting aloments would be improved Bummarizes proposed actions Info partially withheld (ref FD1A Exemption 3), HANRAHAN.E J Material Control Licensing Branch 80/01/15 Rpp

- --8007100044 Discusses 791004 inventory difference of high enriched U exceeding limit of error constraint Forwards rept detailing causes contributing to inventory differences & corrective actions taken Rept withheld (ref FDIA Exemption 3) TAYLOR,C W Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.) NFE-79-083 79/11/02 2pp
- --B007100052 Forwards comments on J0 Partiow 770525 itr to KD Hensley Info withheld safeguards & security measures (ref FOIA Exemption 3) HEMBLEV.K D Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.
 - Nuclear Fuel Services, Inc (subs of Getty Dil Co) 79/07/05 300
- --8007100057 Submits list of recent mods at facility which upgraded matl accountability & control program Info withheld procedures for safeguarding licensed SNM free FOIA Exemption 4)

 JOY-D R Material Control Licensing Granch 79/09/11 Zpp
- --B007100069 Forwards info status rept re 790814 inventory differences of highly enriched V exceeding limit of error constraint Info withheld procedures for safeguarding nuclear matl (ref FOIA Elemption 4)
 HENSLEY.K D Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/10/02 3pp
- --B007100072 Summary of 790816 meeting between util & NRC in Bethesda. MD re concerns of highly enriched U inventory difference behavior Inventory difference is licensee problem Info partially withheld (ref FOIA Exemption 5)

 JOY. D Material Control Licensing Branch 79/08/21 2pp
- --B0071000Bi Summary of 790BiA meeting w/util Lists major util concerns including improving of accounting sys Majority of meeting apent on reporting status of NRC questions Info pertially withheld (ref FGIA Exemption 5)
 PARTLOW.J G Material Control Licensing Branch 79/0B/17 2pp
- 8007100327 Notifies that JF Ahearne concurs in wording of fire protection rule SECY-80-088 as revised by J Parry 800317 memo subj to listed changes EAUTER, Q Commission 80/04/16 ip
- --8007100334 Forwards draft memo summarizing individual Commissioner comments on SECY-80-088 fire protection actions Requests comments or concurrence in time to affirm paper on 800319 Draft memo-moutised pages & draft FR notice encl PARRY. S J 8 Office of the Secretary of the Commission 80/03/17
- B007110004 Responds to FOIA request for 11 documents concerning facility Items 2.3 & 5-10 have been addressed in earlier NRC responses Attachment B of Document 11 withheld (ref FOIA Exemption 4 & 100FR2 770) FELTON, J.M. Division of Rules and Records 80/05/27 200
- 8007110149 Responds to FDIA request for 1979 quarterly repts for GM Co Po-210 static elimination devices Info withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/07/09 1p
 - Division of Rules and Records 80/07/09 ip
- BOO7110159 FOIA request for 1979 quarterly repts for 3M Co Po-210 static elimination devices
 MILEHAM.J Mark IV Industries. NRD Div 89/06/20 1p
- 8007110242 Advises that RT Kennedy concurs in changes to SECY-BO-OBB, fire protection rule proposed in 0 Souter 800416 memo, subjuto attached revisions 0UILBERT, J Commission 80/04/17 4pp
- --8007110246 Notifies that JM Hendrie concurs w/800416 version of fire protection rule circulated by G Gauter as modified by RT FONTECILLA, H Commission 80/04/18 ip
- BOO7110496 Requests Commission approval to publish for comment, amend to 10CFRBO in form of App R.w/fire protection requirements for plants in operation prior to 790101 Amend would facilitate implementing BTP 9 5-1 FONTECILLA, H M Commission 80/03/14 2pp
- BOO7110504 Discusses status of App R to 10CFR50 re impact of requiring all fire protection features installed by B01101 Eleven plants will not complete Section 3 i mods & Section 3 2 open items by B01101

 LAINAS.G Plant Bystems Dranch 80/04/11 3pp
- 8007110547 Describes status of alternate/dedicated shutdown mys as of 600328 CASE.E Office of Nuclear Reactor Regulation, Director 80/07/10

- 8007110586 Forwards info requested by JF Ahearne re status of fire protection review program alternate/dodicated shutdown systatus as of 800331 & other outstanding lasues LAINAS.G Assistant Director for Safety Assessment 80/04/02 7pp
- 8007140212 Responds to FQIA request for page from WASH-740 update 650413.consisting of DN Sunderman memo to 82 Szawlewicz, Document 136 Forwards memo FELTON, J.M. Division of Rules and Records 80/06/26
- --8007140220 Discusses revision to HASH-740 Comparison of ground rules in two analyses & effects is instructive in pointing out real differences Forwards table consisting of comparison of selected input & output items in HASH-740 & revision SUNDERHAN.D N Battelle Memorial Institute, Columbus Laboratories 65/04/13 3pp
- 8007140214 FOIA request for page from WASH-740 update, 650413, consisting of DN Sunderman memo to BZ Szawlewicz, Document 136 GROSSMAN, K Island Closeup News Service 80/06/18 ip
- 8007140226 Responds to FDIA request for documents re M Belisle Forwards documents listed in App A M/o encls FELTON.J M Division of Rules and Records 80/07/01 2pp
- 8007140228 FOIA request for documents re M Belisle M Belisle affidavit enci BELIN,A Center for Law in the Public Interest 80/06/11 3pp
- 8007140237 Responds to FOIA request for records re five categories of info concerning proposed fire protection rule All documents relative to request are available in Washington, DC PDR FELTON, J M Division of Rules and Records 80/06/27 2pp
- 8007140243 FOIA request for records re five categories of info concerning proposed fire protection rule MCGARRY.J M Debevoise & Liberman 80/06/16 Zpp
- 8007140245 Responds to FOIA request for Contract NRC-08-80-338, "Study of US Nuclear Health & Bafety Info Dissemination," awarded to Franklin Inst Contract is available in Washington, DC PDR FELTON, J M Division of Rules and Records 80/07/08 1p
- 8007140248 FOIA request for Contract NRC-08-80-338, "Study of US Nuclear Health & Safety Info Dissemination," awarded to Franklin Inst
 NOCELLA'S J Advanced Technology, Inc 80/07/01 1p
- 8007140277 Responds to FDIA request for all info which directed or discussed any changes of proposed fire protection rule in BECY-BO-OBB App documents have been forwarded J Guibert 800311 meno withheld (ref FDIA Exemption 5) FELTON J M Division of Rules and Records 80/06/26 2pp.
- --B007140291 Staff requirement memo re 800423 open Affirmation Session 80-18 in Washington, BC, Includes overall records of Commission votes re SECY 80-166, SECY 80-177 & SECY-80-088 CHILK, S J Office of the Secretary of the Commission.
- --8007140297 Discusses fire protection rule proposed in SECY-80-088, Lists
 JF Ahearne recommendations re provisions which should be
 incorporated in rule Includes info re public comment
 period & implementation of nonshutdown sys mods.
 SAUTER, O Commission 80/04/10 lp
- --8007140302 Discusses fire protection rule proposed in SECY-BO-088 Commission affirmed. w/comments, proposed fire protection rule delineating certain min fire protection requirements at 800423 Affirmation Session 80-18, Lists recommended changes NOTLEY.D P Engineering Metholology Standards Branch 80/06/03
- 8007140286 FOIA request for all info which directed or discussed any changes to proposed fire protection rule in BECY-80-088 & record of Commission's vote re changes
 KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp).
- B007140491 Responds to FOIA request for rept on potential threat to nuclear activities from insiders, DOE study on effectiveness of security clearances & supporting documents used at B00619 briefing re repts Documents available at PDR.DDE & CIA FELTON, J Division of Rules and Records 80/07/10 ip.
- --- 8007140504 Bunshine FR Notice of Commission meetings during wk of MAGEE.W Office of the Secretary of the Commission 80/06/16.

- 8007140498 FOIA request for rept on potential threat to nuclear activities from insiders.DOE study on effectiveness of security clearances & Supporting documents used at 800619 briefing re repts
 COCHRAN.T B Natural Resources Defense Council 80/06/24 ip
- B007140645 Responds to FOIA request for winning technical proposal in response to RFP RB-NMS-80-024, "Development of Advanced Matl Accounting Sys Simulation (AMASS) Model "Forwards proposal FELTON, J M Division of Rules and Records B0/07/09 ip
- --B007140656 Response to RFP RS-NMS-B0-024. "Development of Advanced Matl Accounting Sys Simulation (AMASS) Model " Objective is mod of MCLAMS simulation model for broad application to wide variety of licensee facilities * NUBAC.Inc RS-NMS-B0-024 80/01/04 70pp
- 8007140650 FOIA request for winning technical proposal in response to RFP RS-NMS-80-024, "Development of Advanced Matl Accounting Sys Simulation (AMASS) Model "TREVIND.T Science Applications, Inc TT-860 80/06/27 ip
- 8007140664 Responds to FOIA request for 5 documents re state U mill incidents Forwards documents
 FELTON, J M Division of Rules and Records 80/07/07 ip
- 8007140674 FOIA request for 5 documents re state U mill incidents BURKS, N Black Hills Alliance 80/06/16 2pp
- 8007i50743 Responds to appeal re denial of FOIA request for records re Abalone Alliance & info concerning FBI Director 770804 memo to Deputy Atty General NRC has no further documents subj to request DIRCKS,W J Office of the Executive Director for Operations
- 8007150749 Appeals denial of FOIA request for all records re Abalone Alliance & info concerning FBI Director 770804 memo to Deputy Atty General FBI 770804 memo encl VARON, C Affiliation Unknown 80/06/03 7pp
- 8007150756 Responds to FDIA request for records re Abalone Alliance & info concerning FBI director 770804 memo to Deputy Atty General Forwards document ro Abalone Alliance Other documents may be available in CA PDRS W/A encls FELTON, J M Division of Rules and Records 80/05/05 1p
- 8007150786 Submits addl response to FOIA request for five categories of info concerning proposed fire protection rule Documents listed in app are available in Washington.DC PDR Five documents re request are still under review FELTON, J M Division of Rules and Records 80/07/09 2pp
- BOO7170197 Responds to FOIA request for Region 2 list used for distributing bulletins info notices & circulars & Region 4 list for distributing quarterly publication re contractor/ vendor insp info Forwards lists W/o encls FELTON.J H Division of Rules and Records BO/07/14 ip
- 8007170202 FGIA request for Region 2 list for distributing bulletins, info notices & Eirculars & Region 4 list for distributing quarterly publication re contractor/vendor insp info KEENAN.T Inside D O E , McGray-Hill Publication 80/06/13 ip
- 8007170292 Discusses IE Insp Rept 30-13219/78-01 of License 19-17039-01 on 780425 No moncompliance noted Major areas inspected procedures & representative records, personnel interviews & observations by inspector MCCLINTOCK, R O Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 78/05/18 2pp
- --8007170278 IE Insp Rept 30-13219/78-01 of License 19-17039-01 on 780425 No noncompliance noted Major areas inspected procedures & representative records, personnel interviews & observations by inspector * Region 1, Philadelphia, Office of the Director 78/05/10 3pp
- --B007170304 IE Insp Rept 79-01 of License 19-17039-01 on 790111 No noncompliance noted Major areas inspected procedures & representative records, personnel interviews & observations by inspector MCCLINTOCK, R O. Region 1, Philadelphia, Office of the Director 79/0/11 4pp
- ---B007170304 IE Insp Rept 78-01 conducted on 781011 No noncompliance noted Major areas inspected procedues & representative records, personnel interviews & observations by inspector CAMPBELL, M., MCCLINTOCK, R.O. Region 1, Philadelphia, Office of the Director 78/10/17 13pp

- --8007170314 IE Insp Rept 79-01 of RAD Svcs.lnc on 791212 Noncompliance noted failure to keep records of receipt transfer storage, survey & monitoring of matis CAMPBELL.M. MCCLINTOCK.R O Region 1. Philadelphia. Office of the Director 80/01/02 12pp
- --8007170318 IE Insp Findings & Licensee Ack dtd 690916 of License 37-13129-01 Insp findings no noncompliance noted STEARNS,C F Atomic Energy Commission 69/09/16 9pp
- --B007170326 Ack receipt of 751105 ltr informing NRC of steps taken to correct violation noted in IE insp on 751009 Actions will be examined during subsequent insp of licensed program NRLSDN.P R Atomic Energy Commission, Directorate of Regulatory Operations 75/11/12 lp
- --800717032B Informs NRC of steps taken to correct violation noted in IE insp on 751009 Corrective action complete inventory of Co-60 has been taken & new procedure is under preparation to avoid future problems

 LINNEMAN.R E Radiation Management Corp 75/11/05 ip
- --8007170379 Discusses IE Insp Repts 30-06309/79-01 & 30-14546/79-01 of Licenses 37-13129-01 & 37-13129-02 on 790201 & forwards notice of violation MCCLINTOCK. R O Region 1, Philadelphia, Office of the Director 79/02/12 Zoo
- --8007170402 Notice of violation from insp on 790201 Noncompliance noted failure to instruct all individuals working in restricted area of precautions & procedures to minimize exposure to radiation & radinative matls

 * Region 1. Philadelphia, Office of the Director 79/02/12 2pp
- --8007170411 Ack receipt of 790305 ltr informing NRC of steps taken to correct violations noted in IE insp of Licenses 37-13129-01 & 37-13129-02 on 790201 HCCLINYGCK, 60 Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/03/23 1p
- ---8007170416 Responds to NRC 790201 1tr re violations noted in IE insp of Licenses 37-13129-01 & 37-13129-02 on 790201 Corrective actions add1 instructions given new employees & surveys made & records maintained KIM.S N Radiation Management Corp 79/03/05 4pp
- --8007170432 IE Insp Rept 79-01 on 790201 Noncompliance noted failure to instruct all individuals working in restricted area of precautions & procedures to minimize exposure to radiation & radioactive matls

 MCCLINTOCK.R O Region 1. Philadelphia, Office of the Director 79/02/05 9pp
- ---8007170438 IE Insp Rept 80-01 on 800228 Noncompliance noted no records found showing receipt of samples from customers COSTELLO.F. CAMPIELL.M Region I. Philadelphia, Office of the Director 80/03/19 lipp
- B007220207 Addi response to FOIA request for documents re proposed nuclear reactors incated near Gyaema. Korea Forwards JR Shea draft memo to Commissioners SECY-80-239 is located in DC PDR Info partially withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 80/07/15 2pp
- --8007220214 Draft Commission paper re licensee for GE to export two reactors. KNU 7 & 8 to Korea Reactors would be located on Qyaeme Forwards final Executive Branch views Info partially withheld (ref FOIA Exemption 5)
 SHEA. J R Office of International Programs, Director 80/07/15
- 8007220243 Add1 response to FDIA request for info concerning facility Nonexempt portions of documents listed in app are located in DC PDR Documents 1.2 & 3 partially withheld (ref FDIA Exemptions 4 & 5) Documents 5 & 6 are undergoing review FELTON.J M Division of Rules and Records 80/07/16 3pp
- --8007220251 Discusses 800227-29 site visit to further evaluate effectiveness of new process monitoring license conditions. Info partially withheld (ref FOIA Exemptions 4 & 5) Responses to M Udall questions dtd 800306 encl
 JOY, D R Material Control Licensing Branch 80/03/11 4pp
- 8007220326 FOIA request for "Submerged Demineralizer Bys Technical Evaluation Rept " HONTAGUE.P National Compaign for Radioactive Waste Safety. 80/06/23 ip

- BOO7230224 Responds to FDIA request for H Denton 800613 memo to Commissioners entitled, "Compliance of DL Applications W/Current MRC Regulations.Reg Ouides & Branch Technical Positions "Forwards memo FELTON.J M Division of Rules and Records 80/07/14 1p
- --8007230234 Requests estimate of NRC & licensee resources involved in implementing proposed requirements of encl draft memo re new OLs compliance wicurrent NRC rules, reg guides & branch technical positions Response expected by 800323 CHILK-8 J Defice of the Secretary of the Commission COMPS-80-13 80/03/12 2pp
- 8007230229 FOIA request for H Denton 800613 memo to Commissioners antiklod. "Compliance of OL Applications W/Current NRC Regulations Reg Guides & Branch Technical Positions " WEISS.E R Sheldon. Harmon & Weiss 80/07/11 ip
- 8007230250 Add1 response to FOIA request for all info re changes to proposed fire protection rule in SECY-80-088 & record of Commissions's vote Commissioner Bradford concurrence encl.

 Bix documents withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 80/07/16 2pp
- --8007230256 Notifies that Commissioner Bradford concurs w/revisions in BO0416 memo re fire protection rule (SECY-80-088) Excerpt of rule enc! THOMPSON.H L Commission 80/04/21 3pp
- BOO7230635 Requests comments on encl memo describing results of corresion tests for commercial grade mild steel partially embedded in DBN vinyl ester-styrene waste form containing NS-1 decontamination waste concentrate

 NEILBON,R M Brookhaven National Laboratory 79/12/04 7pp
- 8007240183 Add1 response to FOIA request for five categories of info re proposed fire protection rule Consultant rept.CT-1256 & ACR8 member rept are available in PDR Forwards R Ferguson 791026 mamo & GA Arlotto 800516 memo FELTON.J M Division of Rules and Records 80/07/18 1p
- --8007240188 Forwards brisf description of evaluation program & guideline documents for proposed fire protection rule Braft proposed rule enci FERGUSCN.R Plant Systems Branch (Pre 791030) 79/10/26 49pp
- 8007240193 Add1 response to FGIA request for three categories of documents re Union Carbide U mill facility in Gas Hills.HY Forwards documents listed in App A H/o encls FELTON, J M Divisium of Rules and Records BO/07/17 3pp
- 8007240431 Responds to FOIA request for records developed in course of NRC investigations of 12 corporations & seven individuals NRC has no documents subj to request FELTON.J H Division of Rules and Records 80/07/17 1p
- 8007240437 FOIA request for records developed in course of NRC investigations of 12 corporations & seven individuals. BOMMER, J C Stroock, Stroock & Lavan 80/07/03 ip
- 8007240453 Responds to FOIA request for any addl insp documents re US Radium Corp No further documents are available FELTON. J H Division of Rules and Records 80/07/22 ip
- 6007240462 FOIA request for any addl insp documents re US Radium Corp HEGARTY, W Self-Powered Lighting, Ltd 80/07/01 ip
- 8007240479 Ltr to all applicants for CPs & OLs requesting info re evacuation time estimates around proposed nuclear plants Requested info should be submitted by 900801 EIGENHUT.D 9 Division of Licensing 80/07/02 ip
- 80072B0022 Responds to FDIA request for R Burnett speech delivered at Inst of Nuclear Matla Mgt annual meeting Forwards three speeches presented by R Burnett at annual meeting FELTON.J M Division of Rules and Records 80/07/22 ip
- --B007280065 "Physical Protection Rules & Requirements What Drives Them " ERICKSON,R A., BURNETT,R Physical Security Development Branch B0/07/22 Spp
- --8007250058 "NRC Response to Bignificant Inventory Differences "BURNETT:R Physical Security Development Branch 80/07/22 6pp
- --8007250061 "Future Outlook for US Nuclear Safeguards " DIRCKS.W J Office of Nuclear Material Safety & Bafeguards 80/07/22 "Spp

- 8007250043 FOIA request for R Burnett speech delivered at Inst of Nuclear Hatls Mgt annual meeting WEISS.E R Sheldon. Harmon & Weiss 80/07/08 ip
- 8007230069 Responds to FOIA request for info re availability of NRC mostang records Provides list of available NRC meeting records All documents are available in PDR FELTON.J M Division of Rules and Records 80/07/22 2pp
- 8007250072 FOIA request for info re availability of NRC meeting records ETHEREDOE, L California, Univ of Berkeley 80/06/20 ip
- B0072500B3 Addl response to FDIA request for all documents involved in preparation of NUREG-0459 & upgraded physical protection regulations in 10CFR73 Provides list of 55 unclassified NRC documents & 236 unclassified open source documents FELTON.J M Division of Rules and Records 80/07/16 8pp
- 80072B0197 Addl response to FOIA request for certain proposals submitted under RFP-RS-NMS-024 Forwards nonproprietary versions of proposals submitted by NUBAC, Inc. BNNL, Los Alamos Technical Associates, Inc & Science Applications, Inc FELTON, J M Division of Rules and Records 80/07/21 lp
- --8007280202 Nonproprietary response to RFP-RS-NMS-024, "Development of Advanced Matl Accounting Sys Bimulation Model "Proposal develops simulation model for evaluating current accounting practices & to study data analysis

 Battelle Memorial Institute, Pacific Northwest Laboratory RS-NMS-80-024 79/12/28 27pp
- --8007280209 Nonproprietary response to RFP-RS-NMS-024, "Development of Advanced Matl Accounting Sys Simulation Model " Describes technical approach, related experience & capabilities, organization & mgt & personnel

 * Los Alamos Technical Associates, Inc RS-NMS-80-024 80/01/04 32pp
- --80072B02I3 Nonproprietary revised response to RFP-RB-NMB-024,
 "Development of Advanced Matl Accounting Sys Bimulation
 Model " Develops computer program for use in analysis of
 matl balance period inventory results.

 * Science Applications, Inc. RB-NMS-80-024 80/04/16 19pp
- 8007280267 Responds to FOIA request for 1tr identifying individual who informed Region 3 of possible radioactive matl deposited in disposal dump in Newburgh Heights. OH NRC was informed by telcon No documents are available FELTON. J M Division of Rules and Records 80/07/22 ip
- 8007280270 FOIA request for 1tr identifying individual who informed Region 3 of possible radioactive matl deposited in disposal dump in Newburgh Heights.OH ZELLNER.R J McGean Chemical Co , Inc 80/07/03 ip
- B0072B0272 Responds to FOIA request for NRC contracts awarded for FYB0 Forwards list of contracts executed in FY78,FY79 & FYB0 All contracts are available in PDR FELTON.J M Division of Rules and Records 80/07/16 ip
- --8007280279 Lists all contracts executed in FY78.79 & 80
 FELTON.J M Division of Rules and Records 80/06/19 24pp
- B0072B0274 F0IA request for NRC contracts awarded for FYBO, VERREGCHIA.P Critical Mass Energy Project 80/07/07 ip
- 8007280283 Responds to FDIA request for records re Scott Luminous, Inc Forwards documents listed in App A Deletions of info pertaining to other companies have been made in Documents 1,2,10 & 18 H/o encis FELTON, J M Division of Rules and Records 80/07/17 3pp
- B007280285 FOIA request for records re Scott Luminous.Inc TAYLOR, J S Affiliation Unknown 80/06/25 2pp
- G0072B0290 Responds to FOIA request for Commissioner Gilinsky 1979 telephone logs & related documents Requested info is available in PDR FELTON.J M Division of Rules and Records 80/07/17 ip
- 8007280294 FOIA request for all Commissioner Gilinsky telephone lags, calendars & memos IRVINE,R J Accuracy in Media 80/07/10 1p,

- BO073000B2 Add1 response to FOIA request for mat1 received considered or approved by Commission during consideration of facility inventory Info partially withheld security measures & restricted data (ref FOIA Exemptions 3 & 4) FELTON, J M Division of Rules and Records 80/07/16 3p
- BO07310232 Responds to FOIA request for documents re export of SNM & replacement parts to India Forwards documents listed in App A Documents will be placed in PDR FELTON.J M Division of Rules and Records BO/07/24 3pp
- --8007310247 Updates 800403 analysis of fuel requirements for Tarapur I & II Analysis is based on more detailed & current info Provides discussion.conclusions.refueling schedule & projected operating schedule for reactor OB Dedi Itr encl PEDERSEN.X Office of Policy Evaluations 79/01/16 9pp
- --8007310250 Provides supplementary info re Tarapur reactor fuel requirements, in response to Commissioner Abearne question re basis for fuel fabrication time DOS provided 9-month fabrication period Inadequate data available for analysis PEDERSEN, K. Office of Policy Evaluations 79/01/18 2pp
- --8007310260 Lists questions re review of License XSNM-1379 conterning proposed export of low enriched fuel to India Requests Executive Branch response SHEA, J R Office of International Programs, Director 79/05/25
- --B007310266 Forwards updated analysis of estimated fuel requirements for Tanapur reactors reflecting fuel covered by application X9NM-1379 M/o encl
 DEVINE.J Office of Policy Evaluations 79/06/07 ip
- ---B007310270 Application by OE for license to export six traversing incore probe detector assemblies to India WILSON, B D General Electric Co DDW-79122 79/05/07 1p
- 8007310237 FOIA request for documents re export of SNM & replacement parts to India BARNES, J N Center for Law & Social Policy 80/06/30 4pp
- BO07310258 Responds to appeal re FOIA request for list of environmentally qualified equipment Forwards nonproprietary portions of Franklin Research Ctr rept & complete Wyle Lmbs rept & NUREO-0370 NUREO-0370 not encl DIRCKS,W J Office of the Executive Director for Operations 60/07/24 1p
- ---B007310265 "Equipment Qualification Test Bummary of Bome Equipment Tested at Franklin Research Ctr." nonproprietary version * Franklin Institute/Franklin Research Conter 80/07/24 57pp
- ---B007310269 44250-1
 "Accident Qualification Test Summary of Qualification
 Testing," prepared for EO&G ID.Inc
 CARRISON, A , HALL, R A , KIMBRELL, H J Wyle Laboratories
 B0/07/24 72pp
- BO07310262 Appeals denial of FOIA request for list of environmentally qualified equipment NRC failure to adhere to procedural requirements of FOIA constitutes illegal denial of request KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) BO/O6/18 2pp
- 8007310274 Responds to FOIA request for info re industrial use of radioactive magnesium-thorium allog & any work-related problems associated w/use No records available subjic request Forwards documents listed in App A W/o encl FELTON, J M Division of Rules and Records 80/07/24 2pp
- B007310280 FOIA request for info re industrial use of radioactive magnesium-thorium alloy & any work-related problems associated w/use FARNAN.J Affiliation Unknown B0/07/07 ip
- 8007310481 Response to FOIA request for documents re transportation of spent fuel from Portsmouth, VA to Bavannah River Plant in Aiken, 8C Encl info partially withheld safeguarding procedures & security measures (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records 80/07/22 3pp

- ---BOO7310496 Confirms BOO921 toleon notifying NRC that Pegase Cask 4 contains one irradiated fuel element & will arrive in Portsmouth, VA Info partially withheld date of arrivaliref FOIA Exemption 4) NRC fee determination encl STONEBURNER, W Transnucleur, Inc. 16486 80/05/21 2pp
- --B007310503 Requests extension until B00530 re route approval Two casks, Model SB/23 are expected to arrive & no alternative southern ports are available to spont fuel shapments w/svc from Sweden Info partially withheld (ref FOIA Exemption 4) HARMON, D W Edinw International Co 80/02/22 1p
- --B007310506 Confirms B00421 notification of spent fuel shipment from Sweden arriving in Portsmouth.VA Info partially withheld dates & times (ref FDIA Exemption 4)
 RAVENBORDFI,N Ediow International Co AB 24 2 80/04/21 2pp
- 80073i0483 Responds to FOIA request for proposal RS-NRR-80-111.
 "Characterization of Nuclear Power Plant Protective Costing
 Sys Under DBA Conditions "Forwards proposal
 FELTON.J M Division of Rules and Records D0/07/24 ip
- --8007310492 Solicitation for RS-NRR-80-111. "Characterization of Nuclear Power Plant Protective Conting Sys Under DBA Conditions" Proposals should be submitted to NRC Div of Contracts DDUUMERTY.D J Technical Assistance Contracts Branch RS-NRR-80-111 80/01/18 94pp
- 8007310488 FOIA request for proposal RS-NRR-80-111, "Characterization of Nuclear Power Plant Protective Coating Sys under DBA Conditions "PUSCIEL NA Consumers Power Co PUSC 25-80 80/07/07 1p
- 8007310544 Add1 response to FOIA request for 57 documents referenced in M Tokar memo to ACRS re pellet-cladding interaction GE preparation of nonproprietory version of Document 3 delayed. Request for Document 17 withfraum Forwards Document 52 FELTON, J H Division of Rules and Records 80/07/22 ip
- ---BOD7310549 Draft request for add1 data re reactivity initiated accident fuel behavior Data will be used in developing improved fuel damage limits & acceptance criteria for licensing PWRs & HWRs DENTON. ALR Office of Nuclear Reactor Regulation, Director
- GEN TEC 19 GENERIC TECHNICAL ISSUES
- 8004120855 Forwards NUREO/CR-1321 GE Commings will be added to svc list for future repts emanating from generic task re sys interaction W/o encl COFFMAN.F D Systems Interaction Branch 80/05/28 1p
- B007030015 "Cnde Assessment & Applications Program Piping Bys Stress Dependent Damping Study " GRUBB.R L & EGRO Idaho.Inc FIN A-6156 79/10/31 20pp
- H007070249 Forwards comments on NUREG-0619 Bys changes such as low flow feedwater control & rerouting of reactor water cleanup systemated only be implemented based on plant unique evaluations demonstrating performance improvement ORIDLEY.R L General Electric Co. MFN-111-080 80/06/19 11pp
- BOO72:0423 Summary of third technical BOO9:5-iå meeting in Bethesda.MD re task action plan A-11 progress & future plans JOHNSON.R E Generic Isques Branch BO/06/13 App
- --8007210430 Notification of third technical 900515-16 meeting in Bethesda, MD to discuss task action plan A-11 progress & future plans JDHNSQN, R C Generic Issues Branch 80/05/06 4pp
- BOO7310286 Notification of BOO730-31 meetings w/vendors & consultants in San Jose CA to discuss Narv III LOCA-related pool dynamic load critoria FIELDS.M Containment Systems Branch BO/07/21 4pp
- INSPECTION AND ENFURCEMENT
- 7710250495 IE Circular BO-13, "Grid Strap Damage in Westinghouse Fuel Assemblies " * Office of Inspection & Enforcement. Office of the Director 80/05/28 2pp

- BOO4240210 PND-BO-Ol on BOO313. Westinghouse notified IE of pending 10CFR21 ltr re-potential cracking of control rod guide tube support pins in foreign PWR Vendor proposes pin inspering two domestic plants currently down WDDDS.R Office of Inspection & Enforcement. Defice of the Director NOONAN.V Engineering Branch 80/03/13 2pp
- BO0424025B PNG-III-80-43 on B00306.litensee 22-00057-06 received Po-210 static eliminator bar from SD Warren Co.West Brook, ME, that was leaking Delivery truck found contaminated DDT, state.
 Region 1 & carrier notified
 PAPERIELLO.C J. DAVIS.A B Region 3. Chicago. Office of the Director 00/03/07 ip
- 8004240278 PND-11I-BO-46 Licenser 48-00537-06 reported employee working in radiation therapy dept w/Co-60 unit had whole body badge rept of 5 2 rems for period BO0110-0210 Licensee will conduct formal review & submit 30 day rept PAPERIELLO. C. DAVIS.A B Region 3. Chicago. Office of the Director BO/03/13 18
- 8004240316 EN-80-001A on 800310 order imposing civil penalties issued for License 29-09814-01 Action based on six items of noncompliance re loss of 55 C: Ir-192 source, exposure to individual k failure to rept loss BROCKETY.T Office of Inspection & Enforcement. Office of the Director THOMPSON.D Executive Officer for Operations Support 80/03/10 ip
- 8005020572 PNO-I-B0-052 on 800331. Region I was notified by Info Technology, Inc of receipt of vial labeled Xe-133 Vial had been included in shipment from licensee Vial was shielded Only background levels of radiation measured at surface OLENN, J E , SMITH, G H Region I, Philadelphia, Office of the Director 80/04/01 ip
- 8005050047 IE Info Notice 80-24. "Low Level Radwaste Burial Criteria" * Office of Inspection & Enforcement. Office of the Director 80/05/30 5pp
- 8005050056 IE Bullatin 80-14, "Degradation of BWR Stram Discharge Vol Capability " * Office of Inspection & Enforcement, Office of the Director 80/06/12 2pp
- 8005050059 lE Info Notice 80-22, "Breakdowns in Contamination Control Programs" * Office of Inspection & Enforcement, Office of the Director 80/05/28 200
- 8005050061 IE Info Notice 80-23. "Loss of Suction to Emergency Feedwater Pumps " * Office of Inspection & Enforcement, Office of the Director 80/05/29 | 1p
- BO05050063 IE Info Natice 80-28, "Prompt Reporting of Info in Accordance W/IOCFR50 55(e)" * Office of Inspection & Enforcement, Office of the Director 80/08/13 ip
- 8005050064 IE Info Notice 80~26. "Evaluation of Contractor GA Programs" * Office of Inspection & Enforcement. Office of the Director 80/06/10 2pp
- 8005050066 IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc. Models 1151 & 1152 Pressure Transmitters" * Office of Inspection & Enforcement, Office of the Director 80/06/27 6pp
- 8005050067 IE Circular BO-16. "Operational Deficiencies in Rosempunt Model 510DU Trip Units & Nodel 1:52 Pressure Transmitters " * Office of Inspection & Enforcement. Office of the Director \$\text{con} \text{(1)} \text{(2)} \text{(2)}\$
 - e 90-27, "Degradation of Reactor Coolant Pump

 1 & Enforcement, Office of the Director
 - iss of Emergency Notification fice of the Director
 - >r Coolant Pump Cooling &
 ice of the Director

- 8005050074 IE Circular 80-14, "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel" * Office of Inspection & Enforcement, Office of the Director 80/06/24 2pp
- BO07140621 FNO-IV-80-023 on BO0624, all offsite power to both units was lost when two lines were tripped by dispatcher Third line was out of svc for maint HUNNICUTT.D Region 4. Dallas. Office of the Director 80/06/25
- 8007230143 EN-BO-02B on 800703, order issued requiring prompt repactaging of waste byproduct matl & prompt transfer to authorized land burial facility Action based upon licensee agreements in 800701 meeting w/Region 1 ofc BROCKETT, T, THOMPSON, D Office of Inspection & Enforcement, Office of the Director 80/07/03 ip
- 8007230216 PNO-I-80-099 on 800710,80 Bluestein reported that package containing 4 4 mCi I-131 had been stolen from private automobile
 KINNEMAN.J D. SMITH.O H Region 1. Philadelphia. Office of the Director 80/07/10 ip
- 800724013B PNO-V-BO-059 on BOO717, Region 5 ofc notified that two shipments of 14 mCi I-125 had been damaged in shipment Inspectors dispatched to inspect shipment Radiological survey detected no contamination THOMAS.R D Region 5, Ban Francisco, Office of the Director BO/07/18 ip
- 8007250197 PND-I-80-102 on 800717, pressure transient caused triple low water level signal followed by reactor low water level stram Cold shutdown underway for further analysis of incident KEIM19.R R Region 1. Philadelphia. Office of the Director. 80/07/18 2pp
- B00729005B PNO-I-80-101 on 800715, plant tripped from 100% power due to water leakage on coolant pump penetrations Possible damage to coolant pumps & penetrations is being investigated REBELOWEKI, T Region 1, Philadelphia, Office of the Director 80/07/16 ip
- 8007290331 PNO-IV-80-024 on B00716, plant was shut down due to primary to secondary leak Max radioactivity detected was below Tech Spec limit
 JOHNSON, W D Region 4, Dallas, Office of the Director 80/07/17

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8004010434 Buggests that rushes toward opening existing power plants or starting const on new plants should be weighed w/precautions for safety & safe disposal of nuclear wasts NEILBONL E Affiliation Unknown 80/03/31 1p
- 8003200366 Ack receipt of BO0312 resolution in support of nuclear energy adopted by Northumberland County Board of Supervisors Certain short-term tasks identified in TMI Action Plan. must be completed prior to UL issuance KAMMERER.C Office of Congressional Affairs 80/04/28 2pp
- BO06:20402 Discusses reasons for delays in licensing new nuclear plants in response to BO0424 requests re MA Cosgrave comments Delays caused by post-TMS efforts to improve safety at operating plants
 KAMMERER.C Office of Congressional Affairs 80/05/20 2pp
- 8006120419 Responds to 800423 re L Nutter concerns about nuclear plant siting & evacuation plans NRC not responsible for decision re wheather on not nuclear power should exist in US Proposals to stop nuclear power should exist in US Hopposals to stop nuclear power development not enacted. HAMMCRER.C Office of Congressional Affairs 80/05/07 2pp
- 8006170304 Informs that Ofc of Technology Assessment has been assigned to review & evaluate current status of nuclear power plant standardization NRC assistance is requested to ensure that views of all parties of interest are represented.

 JOHNS, L. S. Congress (Joint & Rotating Committees, etc.) 80/06/11
- B007020069 Responds to uncl MW Will B00430 inquiry re safety aspects of military nuclear plants vs commercial nuclear plants NRC not responsible for licensing military plants DOE, Div of Naval Reactors, should be contacted DIRCKS, M J Office of the Executive Director for Operations B0/06/24 2pp

æ

---B007290086 informs that form has been selectd by major power company to design new nuclear power plant operator training facility Requests meeting to discuss how firm may be of assistance to NRC O'NEILL.TY Lester B Knight & Associates, Inc. B0/06/26 ip

BOO72700B9 Responds to BOO324 ltr re nuclear power Forwards Chapter 5 of of President Carter's Second Natl Energy Plan DENTON:H R Office of Nuclear Reactor Regulation, Director BO/05/14 15pp

NUREG REPORTS AND RELATED CORRESPONDENCE

8007010498 Forwards comments of Interorganizational Advisory Committee on Radiological Emergency Planning & Preparedness on NUREO-O654 & NRC statement of interim NRC policy on stockpiling potassium indide, in response to 800505 & 09 ltrs
MANCUSD.F Connecticut, State of 80/06/25 Spp

BOO7020396 Advises that ltrs to OL applicants, CP holders & licensees, which contain NUMEG-0660 requirements are being prepared for OL applicants & CP holders, NRC will use requirements presented in Encl 1 of SECY 80-230

EISENHUT, D G Division of Licensing 80/06/02 2pp

BOO7030350 NUREQ/CR-1314
"Solubility Classification of Airborne U Products Collected at Perimeter of Allied Chemical Plant Metropolis, IL"
KALLMARF.D R Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-21239 PNL-3288 BO/05/31 34pp Available at

8007030359 Advises that C Michelson concerns, originally addressed to C-E Sys 80 designs, should be forwarded to B&W Responses necessary by 791011 for NUREG-0565 witteup ROSZTGCZY, Z R TM1-2 Bulletins & Orders 79/09/06 2pp

8007030373 NUREG-0597

"User's Guide to GASPAR Code"

ECKERMAN.K F , CONGEL.F J Assistant Director for Environmental
Technology RECEKLEIN.A K Occupational Health Standards Branch
80/06/30 98pp Available at GPO \$3 75

B007030374 NUREG-0561 RI
"Physical Protection of Shipments of Irradiated Reactor
Fuel, Interim Guidance"

Office of Nuclear Material Safety & Safeguards 80/06/30 74pp
Available at GPO \$3.75

BOO7070249 Forwards comments on NUREO-0619 Bys changes such as low flow feedwater control & rerouting of reactor water cleanup sys should only be implemented based on plant-unique evaluations demonstrating performance improvement GRIDLEY, R.L. General Electric Co. MFN-111-080 80/06/19 11pp

BOO7070351 Comments on NURFG-0588 "Interim Staff Position on Environ Qualification of Safety-Related Electrical Equipment "
Generic requirement for typo testing may restrict available means for qualification w/o positive validity of results SCHERER.A F C-E Power Systems LO-BQ-038 BQ/06/27 3pp

B007070015 BECY-80-275
Discusses finalization of emergency planning rule changes, including consideration of public comments Recommends FR publication re final rulemaking Related documentation entl MINDOUE.R D Office of Standards Development, Director 80/06/03 147ap

--B007090017 NUREO-0685

Draft "Environ Assessment for Effective Changes to 10CFR30 & App E of 10CFR30. Emergency Planning Requirements for Nuclear Power Plants" Related documentation encl OTI.N R Division of Giting, Health & Bafeguards Standards 80/06/30 54pp

B007090163 Forwards "Human Engineering Quide to Control Room Evaluation." Pinal rept.Vols 1 & 2 re control room evaluation process & human engineering guidelines. respectively MALONE.7 B Essex Corp 80/06/30 1p

~-8007090166 NUREO/CR-1580 V1
"Human Engineering Guide to Control Room Evaluation,"
Vol 1 re control room evaluation process
MALLORY.X. FLEGER,S., JDHNSON,J Easex Corp NRC-04-79-209
80/08/31 100pp

--B007090167 NUREG/CR-15B0 V2
"Human Engineering Guide to Control Room Evaluation." Vol 2
"e human engineering guidelines
MALLORY,K , FLEGER,S , JOHNSON,J Essex Corp NRC-04-79-209
B0/09/31 140pp

BOO7090214 Requests extension of comment period until at least 800915 re NUREG-0577 & amends covered in 800519 ltr Significance & possible impact of both documents may not presently be recognized & justified CLAYTON.F L Alabama Power Co 80/07/02 1p

8007070331 Comments on NRC 800520 ltr re addl guidance on NURE9-0577 Proposed review procedure should be revised to reflect applicants of plants w/o CP who have fabricated RC8 component supports
LENTSCH.J W Portland General Electric Co JWL-269-80 80/07/02

B007090362 Summary of B00612 meeting w/BWR owners group re plans for satisfying safety & relief valve test requirements per NUREG-037B. Section 2 1 2 MEMMINGER. E @ Mechanical Engineering Branch B0/06/26 6pp

8007070371 NUREG/CR-1523
"EFACTOR Computer Code for Calculating Dose Equivalent to Target Organ per uC1-Day Residence of Radionuclide in Source Organ. Supplementary Rept"
DUNNING, DE , PLEASANT, U C , KILLDUOH, G G Oak Ridge National Laboratory FIN B-0188 DRNL/NUREG/TM/- 80/05/31 130pp Available at NTS

8007100363 NUREG/CR-0208 Ri
"Pulsed Neutron Activation Measurement of Emergency Core
Coolant Bypass Flow on LOFT Reactor"
KEMLER.P Argonne National Laboratory SOLBRIG.C W EG&G. Inc
ANL-CT-78-37-2 80/06/30 94pp Available at NTIB

B007100349 NUREG-0448 DRFT

"Staff Review of Radioecological Assessment of Wyhl Nuclear
Power Plant." draft summary
BRANAGAN.E F. CONGEL.F J. CARDILE.F P. Assistant Director for
Environmental Technology B0/06/30 17pp

B007110195 Ack receipt of 800915 ltr expressing concern w/proposed approach to ATHS in NUREO-0460.Vol 4
DENTON.H R Office of Nuclear Reactor Regulation, Director B0/06/04 lp

--B007110203 Expresses concern on behalf of owners of C-E designed & operating NSBS plants re approach to ATHB in NUREG-0460, Vol 4 NRC on course that will prescribe resolution to ATHB issue w/o due regard to industry comments LUNDVALL, A E Daltimore Gas & Electric Co B0/09/15 2pp

--8007110207 Forwards comments on NUREC-0460.Vol 4 re ATM8 on behalf of owners of C-E N888 power plants Issue about to be resolved by NRC w/o consideration of many relevant views More detailed comments will be submitted in Jul 1980 LUNDVALL.A E Baltimore Gas & Electric Co 80/05/15 4pp

B007110439 Responds to B0011B ltr transmitting resolution re public health implications of nuclear power plants NUREG-0654 requires that public info program be developed jointly by utilistate & local officials GRIMEB. I K Emergency Preparedness Task Force 80/06/23 2pp

--8007110443 Forwards resolution re public health implications of nuclear power plants NRC should support future legislation dealing w/safety & guidelines for safe handling of nuclear matls & wastes Requests that response be sent to H Whitman BAKCR. T Student Nurses Association of Pennsylvania 80/01/18 3pp

B007110453 Bubmits comments on NUREQ-0577, addl guidance re major component support low-alloy bolting NRC should consider reduction in max postulated flaw depth & include acceptable conversion table between yield strength & matl handness CDOPER. H E Teledyne Engineering Services B07-042 B0/07/03

BOO7110560 NUREO-0480
"TMI-1 Restart, Evaluation of Licensee Compliance W/
Short- & Lohg-Term Items of Section II of NRC Order
Dtd 790809 Met Ed. ot al "
* Office of Nuclear Reactor Regulation, Director * Division of
Licensing 80/06/30 250pp Available at NTIS

8007140083 Forwards comments on NUREG/CR-1280 Rept shows that writer is not aware of many positive aspects of civilian protram Differences between Navy & civilian programs were not discussed
PARKER.W D Duke Power Co 80/06/11 bpp

B007140092 NUREG/CR-1459
"Experiment Data Rept for Bemiscale Mod-3 Small Break Test
Beries (Tests S-SB-2 & S-SB-2A) "
MIYABAKI,D H E000 Idahoi.nc E00-2036 80/06/J0 221pp

B007140396 Forwards "Emergency Protedure Guidelines" for BWR owners group, per NUREG-0578, Requirement 2 i 9 Description of how analyses of NEDO-24708 & emergency protedure guidelines apply to all FSAR Chapter 15 events forthcoming BUCHHOLZ, R H General Electric Co MFN-117-80 80/06/30 40pp

8007140357 Requests extension of completion date, until 600915, for comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PWR Steam Generator & Reactor Coolant Pump Supports "WIDNER, W A Georgia Power Co 80/07/07 ip

B007140375 Forwards comments on NNREG-0577 Sandia rept considers only matls used in component supports at responding nuclear plants & classifies plants according to susceptibility to brittle fracture w/o considering all factors ZARAKAB,P Consolidated Edison Co of New York B0/07/07 2pp

BOO7140610 NUREQ/CR-1464

"Review of Nuclear Power Plant Offsite Power Bource
Reliability & Related Recommended Changes to NRC Rules &
Regulations "
BATTLE.R E , CLARK,F H , REDDOCH,T W Dak Ridge National Laboratory
FIN 8-0235 ORNL/NUREO/TM-3 80/05/31 113pp Available at NTIS

B007140617 NUREG/CR-1258 V2
"Insp Methods for Physical Protection Project Annual Rept.
Mar 1979 through Feb 1980"
BRADLEY,R T . BOWDEN.D D . OLBUN.A W Lawrence Livermore Laboratory
FIN A-0143 UCID-18123-79-4 B0/06/30 58pp Available at NTIS

B0071504B6 Forwards comments on NUREO-0577 Main yield strength used to determine susceptibility of matl to stress corrosion cracking should be IBO ksi.for consistency w/Sandia rept (Page C-23) recommendations LOOMIS, J S Sargent & Lundy, Inc 80/07/07 2pp

8007160457 Comments on NUREO-75/087 NRC personnel drafting BRPs are confusing responsibilities NRC is incorrectly providing design details & design philosophy HALTER, J F Energy Products Group 80/06/06 3pp

8007160489 Responds to NRC 800520 request for comments on NUREG-0577 Request requires significant engineering effort due to util five plants w/three different designs Add1 three months (until Oct 1980) required to develop thorough comments RENBERGER.D L Washington Public Power Supply System 002-80-143 80/07/09 1p

9007160491 Comments on NUREG-0577, "Potential for Low Fracture Toughness & Lamellar Tearing on PHR Steam Generator & Reactor Coolant Pump Supports " Every path to integrity demonstration should be left open to licensees SCHERER, A E C-E Power Systems LD-80-041 80/07/09 2pp

BOO7160495 Requests extension of comment period until BOO915 for reviewing "For Comment" edition of NUREG-0577 & providing significant comments DRAFER, E L Gulf States Utilities Co RBG-7964 BO/07/07

BO07170311 NUREG/CR-1253
"Methods for Assessing Background Levels of Radiation & Radioactive Matls in Environ Around U Mills "
WAGMAN,N A , SILKER,W B , GLISSNEYER,J A Battelle Memorial Institute, Pacific Northwest Laboratory FIN D-2121-B PNL-9256 B0/04/30 98pp Available at NTIS

8007170618 NUREG/CR-1512
"Evaluation of Matls Interactions for Advanced Reactor Sys,"
annual progress rept
SHAMSON,D 0, VAN FAASSEN,H L. Aerospace Corp. FIN 8-1130
ATR-80(7814)-1 80/06/30 73pp Available at NTIS

8007180031 NUREG/CR-1460
"LMR Safety Research Program Quarterly Progress Rept Oct-Dec 1979"
MASSEY. W.E., KYGER. J. A. Argoine National Laboratory FIN A-2014
ANL-80-43 80/05/31 37pp Available at NTIS

BO07180049 NUREG-1385
"Development of 'Good' Physical Protection Plan Capability
73 45(b)"
BENNETT, H A. GLASCOAGA, M T Sandia Laboratories BLOEDEL, S A
Allied General Nucleor Services FIN A-1153 SAND80-7027
B0/03/31 150pp Available at NTIS

8007180065 NUREG/CR-1413 "Radionuclide Docay Data Base Index & Summary Table " KOCHER.D C Cak Ridge National Laboratory FIN 8-0188 DRNL/NUREG-70 80/05/31 29pp Available at GPO

8007180072 NUREQ/CR-1169 V3
"Bareguards Vulnerability Analysis Program (SVAP) User's
Hanual"
DRVIS.W J Lawrence Livermore Laboratory FIN A-0115 UCRL-52730
80/05/31 97p Available at NTIS

8007210391 Discusses 800713 & 17 telcon re definition & implementation of NUREO-0660 requirements for modifying HPCI/RCIC setpoints BHR owners group recommendations probably not to include mods to setpoints, due to negligible reduction BUCHHOLZ,R H General Elective Co., Nuclear Energy Products Div RHB-057-80 80/07/11 2pp

BOO7210491 NUREG/CR-1500
"Bersmicity & Tectons, Relationships of Nemaha Uplift in OK Part III"
LUZA:K V , LAMSON, J E Oklahoma, Univ of FIN 8-5967 BO/06/30 79pp Available at GPO 3 75

8007220019 NUREG/CR-0830
"Monitoring Random Errors of Nuclear Math Measurements"
BROUNS, R J , ROBERTS, F P , MERRILL. J A Battelle Memorial Institute.
Pacific Northwest Laboratory FIN B-20149 PNL-3022 B0/06/30
39pp Available at NTIS

B007220024 NUREO/CR-1234 "Insider Threat to Secure Facilities Data Analysis " HEINEKE, J.M. Lawrence Livermore Laboratory FIN A-0132 UCRL-52744 80/06/30 74pp

B007220034 NUREO/CR-1118
"Distribution of Illegal Incident Characteristics Cases of Bank Fraud & Embozilement Computer-Related Crime & Insider Theft from Drug Manufacturers & Distributors "
HEINEKE.J M Laurence Livermore Laboratory FIN A-0132 UCRL-52742 B0706/30 126pp

BOO722036B NUREG-0694
"TMI-Related Requirements for New Ols"
* Commission 80/06/30 43pp

8007230201 NUREG/CR-1555
"Critical Experiments, Measurements & Analyses to Establish
Crack-Arrest Methodology for Noclear Pressure Vessel
Steels," progress rept June-Doc 1979
ROSENTIELD, A R., ABOU-9AYED, I., GILLOT, R. Dattelle Memorial
Institute, Columbus Laboraturies FIN A-4046 DMI-2064 80/06/30
48pp Available at NTIS

BOO7230205 NUREC/CR-1440 "LUR Status Monitoring During Accident Conditions " VONNERMANN, J. BROWN, R. TOMF, A. EG&G Idaho, Inc. FIN A-6294 EGG-CA-5153 BO/06/30 205pp Available at NTIS

8007230625 NUREO/CR-1361
"Drag Devices for Two-Phase Mass Figw Measurements"
ANDERSON, J L CORO Idaho. Inc FIN A-6038 EGG-2025 80/05/31
56pp

B007240132 Ack receipt of B00612 ltr to Chairman Hendrie expressing concern re NRC approach to AfM5 (NUREO-0640) & requesting to address Commission on same day as NRC presentation first session will be devoted to NRC personnel only DIRCRS, W.J. Office of the Executive Director for Operations 80/07/01 lp

--B007240135 Expresses concern re NRC approach to ATWS issues Requests response to enci comment. & opportunity to make presentation on day that NRC presents issue for consideration LEG. B. Atomic Industrial Forum. B0/06/12 1p

--8007240137 Forwards paragraph to be included in response to AIF request to address NRC on ATMS issue
TRUBATCH.5 OFFice of the General Counsel 80/06/24 2pp

8007240262 NUREG-0030 v3 NO2

Yellow Book "Const Status Rept Nuclear Power Plants," data
as of B00430

* Defice of Nunagement and Program Analysis 80/04/30 50pp
Available at NITS

8007240283 NUREG/CR-0570 V2 APP

307240283 NUMEC/CM-05/0 V2 APP
"Technology, Safety & Costs of Decommissioning Ref Low Level
Waste Burial Ground," App.Vol 2
MURPHY,E 5 , HOLTER, G M Rattelle Nemorial Institute, Pacific
Northwest Laboratory FIN A-2136 80/06/39 167pp

8007240394 NUREG/CR-1557
"Bteam-Hater Miring & Sys Hydrodynamics Program.Task 4."
quarterly progress rept Apr-June 1979
GOLLIER.R.P. BISHGP.T A. DWORAK.J A. Battelle Memorial Institute,
Columbus Laboratories FIN A-4048 BMI-2038 80/07/31 114pp
Available at NTIS \$4.25

8007240409 NUREG/CR-1486
"Beasonal Variation of 10 Square Mile Probable Max
Precipitation Estimates - US East of 105th Meridian,"
Hydrometeorological Rept 53
HD.F P , RIEDEL, J T Commerce, Dept of, National Decanographic &
Atmospheric Administration 90/06/30 98pp Available at NTIS
\$4 00

B007240439 NUREG/CR-1504

"User Guide to EPIC.Compute: Program to Calculate Antion of Fuel & Coolant Subsequent to Pin Failure in LMFBR" PIZZIGA: PA . GARNER.P L . ABRAMSON.P B Argonne National Laboratory FIN A-2015 ANL-80-47 79/10/31 123pp Available Available at

8007240478 NUREQ/CR-1489

007240478 NUREO/CR-1489
"Best Extimate Method vs Evaluation Method Comparison of Two
Techniques in Evaluating Seismic Analysis & Design " Seismic
safety mangins research program
BUMPUS.S E. JOHNSON.J J. SMITH.P D. Lawrence Livermore Laboratory
FIN A-0130 UCRL-32746 80/07/31 116pp Available at NTIS
44.0%

BOO728050B NUREO/CR-1440

"LWR Status Monitoring During Accident Conditions"

VONHERRMANN, J. BROWN, R. TOME, A EG&O, Inc. FIN A-6294
EGO-EA-5153 BO/06/30 209pp Available at NTIB #6.00

8007280567 Submits comments on NUREG-0619 Bys changes for both feedwater & control and drive sys cannot be implemented by proposed dates June 1983 Forecast as earliest completion JANECEK.R F Commonwealth Edison Co 80/07/23 2pp

8007280683 NUREG/CR-1520
"Experiment Data Rept for LOFT Anticipated Transient
Experiment 16-5 " EGRO forwarding itr encl
STJIT-18 D , CARPENTER, J M | Idaho National Engineering Laboratory
FIN A-6048 EGG-2045 80/07/31 155pp

8007270145 NUREG/CR-0508

"Security Communication Bys for Nuclear Fixed Site Facilities"
HOWINGTON.L C Union Carbide Corp TAYLOR.L L Johnson.Inc FIN D-0218-7 Y/DW-128 80/07/31 YLOR, L Bernard 80/07/31 1920p

B007290152 NUREG/CR-1396

Prompt Burst Energetics Experiments Fresh U Carbide/Sodium Beries " REIL.K O . YOUNO.M F Sandia Laboratories FIN A-1016 BANDBO-0820 BO/08/31 I36pp /

B007290251 NUREG/CR-0743

NOVEYDEST NUMESIAN-0743
"Transportation of Radionuclides in Urban Environs Draft
Environ Assessment "
FINLEY,N C , DANIEL,S L , HENNING-BACHS,C Sandia Laboratories FIN
A-1077 SAND79-0369 BO/07/31 500pp

8007270689 Comments on NUREO-0577 Large weld repairs made under restraint & possibly poor access could crack Structure could possibly become unsafe & fail KASCSAKR M Long Island Lighting Co 80/07/23 2pp

8007290781 Request for stay of effectiveness of Commission 800614 statement of policy to guidance for power reactor OLs, pending judicial review Commission action endorsing NUREG-0694 may be unlawful Certificate of Svc encl WEISS.E R Union of Concerned Scientists LATHAM, S B Shoreha Opponents Coalition WEISS.E R Sheldon, Harmon & Weiss 80/Cibps Shorehad

--B007290B03 Affidavit stating that current NRC regulations re hydrogen control measures are not adequate to insure health & safety NUREO-0694 does not correct hydrogen control deficiencies Prof qualifications encl POLLARD, R D Union of Concerned Scientists 80/07/18 12pp

---8007290809 Affidavit re need to analyze sys interaction due to insufficient info for unresolved Safety Issue A-17
MINOR.G C Shoreham Opponents Coalition 80/07/11 9pp

8007300041 NUREG/CR-1260
"Evaluation of Docket Files for Terminated SNM Licenses"
HOLOMAY, C F, LANTZ:P M, DICKSON,H W Oak Ridge National
Laboratory FIN A-9085-7 DRNL/NUREG/TM-3 80/06/30 5
Available at NTIS

8007300152 Forwards comments on proposed SRP 3 9 6. Revision 2 increased costs appear to be greater than those described in impact assessment Paragraph 1 i a re valve & pump testing should be VAN BRUNT, E. E. Arizona Public Service Co. 45FR3626 002 80/06/27

8007300575 NUREO/CR-1483
"Blowdown Heat Transfer Separate Effects Program for Jan-Mar 1980." quanterly progress rept CRADDICK.W G , ANKLAM.T M , BUHANAN,R F Oak Ridge National Laboratory FIN 8-0125 ORNL/NUREG/TM-3 80/06/30 18pp Available at NTIS

8007310004 NUREG-0304 V4
"Regulatory & Technical Repts," compilation for 1979
OLIU,W E , MCKENZIE,L , ARAGON,R Systematic Evaluation Program
Branch (Pre 791030) 79/12/31 300pp

8007310007 NUREG/CR-1184 "Evaluation of Similator Adequacy for Radiation Gualification of Safety-Related Equipment " BONZON.L. BUCKALEM.H Bandia Laboratories FIN A-1051-0 BAND79-1787 B0/05/31 201pp

8007310009 NUREG/CR-1520 MEXPERIMENT Data Rept for LOFT Anticipated Transient
Experiment L6-5 "
BIIII.B D. CARPENTER.J M EG&G Idaho,Inc FIN A-6048 EGG-2045 151pp

8007310113 Notice of extension of public comment period for NUREQ-0577, re-potential for low fracture toughness & lamellar tearing on PMR steam generator & reactor coolant pump supports, from 800721 to 0808 ERNST, M.L. Assistant Director for Environmental Technology 80/07/18 2pp

B007310210 NUREG/CR-1301

"Analysis of Organohalogen Products from Chlorination of Natural Waters Under Simulated Biofouling Control Conditions BEAN, R M. MANN, D C., RILEY, R G. Battelle Memorial Institute Pacific Northwest Laboratory FIN 8-R098 PNL-3275 80/06/ 50pp Available at NTIS \$4.25

8007310216 NUREG/CR-1289

POVIDED NOREO CK-1209

"Evaluation of Isotope Migration - Land Burial, Water
Chemistry at Commercially Operated Low Level Radwaste
Disposal Sites," status rept through Sept 1979

WEISB, A J. COLCHBO, P. Brookhaven National Laboratory FIN A-3042
BNL-NUREG-51143 80/03/31 294pp

8007310217 NUREG/CR-1439
"One Dimensional Neutron Kinstics Model for THOR Code,"

A-3014 BNL-NUREG-51187 B0/04/30 36pp

8007310225 NUREQ/CR~1119

30/310225 NOREGYCK-1119 "Piping Inelastic Fracture Mechanics Analysis " CHANG.C I , NAKAOAKI.M , ORIFFIB.C A Navy,Dept.of, Naval Research Laboratory FIN B-6587 4259 80/06/30 91pp Available at NTIS

8007310231 NUREG/CR-0742 "Review & Integration of Existing Literature Concerning Potential Social Impacts of Transportation of Radioactive Matis in Urban Areas "
QCRDON, C , GESSELL, T F
Rice Univ FIN A-1077 Sandia Laboratories / SAND78-7017 80/07/31 ANDERSON, C. Um Marsh

8007310234 NUREG/CR-1357

DO/310434 NURLEY/RF-1337
"Heat Removal Characteristics of Vol Heated Boiling Pools
W/Inclined Boundaries "
GREENE, G A , JONES, D C , BCHWARZ, C E Brookhaven Nationa
Laboratory FIN A-3024 BNL-NUREG-51137 60/04/30 17 Brookhaven National

8007310241 NUREQZCR-1198 VI 007310241 NUMEU7CK-1178 VI
"Design Quidance & Evaluation Methodology for Fized Site
Physical Protection Sys"
DENNETT,H A , CLASCOAQA,M T Sandia Laboraturies FIN A-11
SAND79-2378/1 B0/07/31 100pp Available at NTIS #7 50 FIN A-1153-9

8007310246 NUREQ/CR-1295)07310246 NUMES/CR-1249
"ORNL State Level Electricity Demand Forecasting Model"
CHERN, W S , DICK, J W , OALLGHER, C A Gak Ridge National Laboratory
FIN 8-0190-8 GRNL/NUREG-63 80/07/31 100pp Available at NTI8

8007310255 NUREQ/CR-1425 DO/310255 NOREG/CH-1425
"Cracking & Relocation of U Dioxide Fuel During Initial
Nuclear Operation"
APPELHANS.A D. MILLER.R W EG&O Idaho.Inc DAGBJARTSSON.8
Opermany, Federal Republic of FIN A-4041 EGG-2032 BO/05/31

8007310471 NUREG/CR-1513 007310471 NUREO/CR-1513
"Evaluation of Isotope Migration - Land Burial Water
"Evaluation of Isotope Migration - Land Burial Water
Chamistry at Commercially Operated Low Lavel Radwasta
Disposal Sites," quarterly progress rept. Jan-Mar 1980
CZYBCINSKI,K S. WEISS,A J. Brookhaven National Laboratory &
A-304Q BNL-NUREG-51219 80/05/31 30pp Available at NTIS

8007310554 NUREQ/CR-1477 007310734 NUMBO/CK-14// "Heavy-Bection Steel Technology Program," quarterly progress rept for Jan-Mar 1980 WHITMAN,O D. BRYAN,R H. Oak Ridge National Laboratory FIN B-0119 DRNL/NUREG/TM-3 80/07/31 53pp Available at NTIS

CORRESPONDENCE WITH OTHER ORGANIZATIONS ORG

8006120770 Clarifies comments made at ANSI-N351 Steering Committee on Pumps 800421 meeting in Pittsburgh PA re qualification issue Functional qualification by experience has merit but practical verification aspects pose problems Minutes encl BROWN.E J Director's Office 80/05/30 4pp

8007010013 Forwards fully executed std order for DOE work "ARAC Site Installations at Nuclear Power Plants," issued to LLL DICKINSON, P Energy, Dept of FIN A-0351-0 80/06/10 1p

-- HD07010017 Executed std order for DDE work "ARAC Site Installations at Nuclear Power Plants," issued to LLL
KERR, O W Assistant Director for State Agreements Programs *
Energy, Dept of FIN A-0351-0 80-80-006 80/06/10 ip

8007010157 Advises that IC Info Notice 80-23, "Loss of Buction to Emergency Feedwater Pumps," was sent to listed utils on 800528 PAPPAB, H Region 3, Chicago, Office of the Director BO/05/30

8007010284 "Looking But Not Seeing Federal Nuclear Power Plant Insp Program " TYE.L B Union of Concerned Scientists BO/06/30 163pp

8007010607 Advises that IE Circular 80-03, "Protection From Toxic Oas Hazards," was inadventently sont w/o encl NUREO-75/087, Sections 2 2 1,2 2 8,2 2,3 & 6 4 encl CARROLL, D E Region 3, Chicago, Office of the Director 80/04/03

B007020130 Forwards std order for DOE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Power Plants." for acceptance RYAN.R G Office of State Programs, Director 80-80-011 B0/06/12

--B007020443 Std order for DOE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Power Plants." issued to ID Natl Engineering Lab RYAN, R G Defice of State Programs, Director FIN 8-1604-0 80-19-08-02 80/04/12 ip

8007030054 Advises that IE Bulletin 80-15. "Possible Loss of Emergency Notification Syn (ENS) W/Loss of Offsite Power," was sent to listed utils on 800618 PAPPAG.H Region 3. Chicago Office of the Director 80/06/19 200

B007070132 Forwards std order for DDE work "Offsite Emergency Instrumentation for Accidents Involving Light Water Nuclear Power Plants." for acceptance RYAN.R G Office of State Programs, Director 80/06/12

8007110543 Discusses choice of NBS x-ray techniques & choice of Cr values L-G should be included as one of five x-ray techniques Cr values published in final version of law should be defensible in court PLAFO.P Michigan, Univ of 80/06/10 2pp

8007140421 Advises that IE Bulletin 80-14, "Degradation of BWR Scram Distharge Vol Capability," was sent to listed utils on B00613 PAPPAS.H Region 3. Chicago, Office of the Director

B007140597 Advises that IE Bulletin 80-13, "Cracking in Core Spray Spargers," was sent to listed utils on 800512 PAPPAS,H Region 3, Chicago, Office of the Director 80/05/13

8007150770 Advises that IE Info Notice 80-27, "Degradation of Reactor Coolant Pump Studs," was sent to listed utils on 800411 PAPPAS.H Region 3, Chicago, Office of the Director 80/04/12

--8007150778 Advises that IE info Notice 80-27. "Degradation of Reactor Conlant Pump Studs." was transmitted for issuance on 800611 Notice should be issued to all PHR facilities holding CLs or CPs Draft itr encl MOSELEY.N C Division of Reactor Operations Inspections 80/04/10 200

B007170343 Advises that IE Circular 80-14. "Radioactive Contamination of Plant Demineralized Water Sys & Resultant Internal Contamination of Personnel." was sent to listed utils on PAPPAS.H Region 3. Chicago. Office of the Director 80/06/25

8007210334 Advises that IE Circular 80-13, "Grid Strap Damage in Westinghouse Fuel Assemblies," was sent to listed utils on 800528 PAPPAS.H Region 3, Chicago, Office of the Director 80/05/30

8007220261 Advises that 1E Info Notice 80-26, "Evaluation of Contactor GA Programs." was sent to listed licensees on 800410 PAPPAS.H Region 3. Chicago. Office of the Director

8007240065 Advises that IE Circular 80-15, "Loss of Reactor Coolant Pump Cooling & Natural Circulation Cooldown," was sent to listed licensees on 800620 PAFPAB.N Region 3. Chicago, Office of the Director BO/06/24

BOO7280079 Ltr to all power reactor applicants & licensees re Commission memorandum & order on UCB 780502 petition for reconsideration of previous memorandum & order dtd 780413 EISENHUI.D G Division of Licensing BO/06/25 ip

--8007280084 Hemorandum & order affirming prior decision to deny UCS requested relief in view of add) improvement of fire safety CHILMS J Office of the Sacretary of the Commission CLI-80~2: 80/03/23 25pp Office of the Secretary of the Commission CLI-80-21

8007290104 Advises that IE Info Notice 80-28, "Prompt Reporting of Info in Accordance W/10CFR50 55(e)," was sent to listed utils on 800613 PAPPAG.H Region 3. Chicago, Office of the Director 80/06/16

B007290771 Forwards summary of B00619 meeting w/AIF Bubcommittee on Bafety Parameter Integration in Bethesda.MD re draft emergency facilities functional requirements MINNERB.W Division of Systems Safety B0/07/09 [p

--8007290782 Summary of 800519 meeting w/AIF Subcommittee on Safety Parameter Integration in Bethesda ND re draft emergency facilities functional requirements * Division of Systems Safety 80/07/09 7pp

- B0072907BI Request for stay of effectiveness of Commission 800616 statement of policy reguldance for power reactor OLs. pending judicial review Commission action endorsing NUREG-0694 may be unlawful Certificate of Svc encl WEISS, E.R. Union of Concorned Bijentists LATHAM, S.B. Shoreha Opponents Coalition WEISS, F.R. Sheldon, Harmon & Weiss 80/0 LATHAM.S B Shoreham
- --8007290803 Affidavit stating that current NRC regulations re hydrogen control measures are not adequate to insure health & safety NUREG-0894 does not correct hydrogen control deficiencies Prof qualifications enci POLLARD.R D Union of Concerned Scientists 80/07/10 12pp
- --8007290809 Affidavit re need to analyze sys interaction due to insufficient info for unresolved Safety Issue A-17 MINOR, G.C. Shoreham Opponents Coalition 80/07/11 9pp
- 8007300005 Requests review of encl safety guide re maint of nuclear power plants by 800811 MORRISON,W M Assistant Director for General Engineering Standards 80/07/10 2pp
- --R002300007 Se+07 orsoood, seer "Maint of Nuclear Power Plants," Revision 7 * International Atomic Energy Agency (Austria) - 50-90-07 52рр

PROPOSED RULE

- 8004110323 Comments on proposed rules 10CFR2.19.20.21.30.40.51.60. & 70 rules are inadequate re-participation of Indian Tribal govts Failure to involve tribes in initial process will result in later practical & political difficulties STONE.R J Energy, Dept of 80/03/24 2pp
- B004280218 Freliminary statement in response to Chairman Ahearne B00312 ltr re proposed rulemaking on radwaste storage & disposal Bolid radwaste may be disposed of w/o risk based on fundamental earth science processes Interior Dept of Geological Survey 80/04/15 14pp
- 8005300283 Comments on proposed rules 10CFR20 & 50 10CFR50 72(a b) should be clarified to permit plant operation pursuant to Tech Specs w/o requiring that repts be sent to NRC COUNSIL.W G. Wortheast Nuclear Energy Co. (subs. of Northeast Utilities). B0/05/02 2pp
- 8006110406 Hemprondum in support of State of AN motion for 60-day extension of schedule dates be proposed rulemaking on radwaste storage & disposal NRC delay of core bibliography filing was not anticipated W/Certificate of Svc MUCHNICKI,E D Ohio, State of 800/05/14 10pp
- 8006270352 Requests ACRS comments on SECY-80-088 re proposed fire protection rule for nuclear power facilities operating prior to 790101 Division of Engineering Standards 80/05/14 ip
- 8007010005 Comments on proposed rule ICCFRS1 agrees w/AIF position that inclusion of safety matters in comparision & ranking of alternate sites in NEPA review process is not appropriate
 ANDERSON.T M Westinghouse Electric Corp NS-TMA-2256 B0/06/09

- 8007010403 Comments on proposed rule 10CFR31 utils should be allowed to include enisting sites on slates of candidate sites. Application of proposed changes to existing inventoried or banked sites is unclear VANDENBURGH, D. Yankee Atomic Electric Co. WYC 80-17 80/06/10
- 8007020030 Notice to recipients of PR-20 advises that Comment δ was miscoded δ will not be used again Correction notice replaces comment.
- Docketing & Services Branch 80/09/20
- 8007020046 Notice to recipients of PR-20 45FR18023 advises that Comment 4 was miscoded & will not be used again Correction should replace comment

 * Docketing & Services Branch 80/05/30 1p
- B007020100 Memo to rectpients of comments re proposed rules 10CFR50, 44FR75167 & 45FR3913 Lists comments previously filed in 10CFR50, 44FR75167, now cross-filed w/loCFR50, 45FR3913, * Dacketing & Services Branch 80/06/05 ip

- 8007020203 Comments on proposed rule 10CFR51 should be amended to state reactor type & thermal power capacity to which regulation applies & specifically exclude others
 FISHER.C.R. General Atomic Co. (subs. of Gulf Gil Co.) 80/06/05
- BD07020212 Comments on proposed rule 10CFR51 definition of term
 "Physiographic Unit" should be included Penalty for failure
 to provide notice of intent 3 months in advance should only
 be 3-month delay in commencement of review

 * LeBoeuf, Lamb, Leiby & MacRae B0/06/09 4pp
- 8007020226 Comments on proposed rule 10CFR51 proposed penalties for failure to provide notice of intent within time specified are inappropriate Penalties are irrelevant to objectives stated in introduction & scope COOK.J W Consumers Power Co 80/06/09 App
- B007020296 Forwards comments on proposed rule 10CFR51 environ density should be explicitly defined & included in Section 2 NRC has no logal requirement to expand alternate sites review to include safety as NEPA issue

 UHRIG.R E Florida Fower & Light Co L-80-185 80/06/13 13pp
- 8007020300 Comments on proposed rule 10CFR20 certification of personnel dostmetry processors is major step forward in radiation protection programs Commends NRC actions STOCKS:H B Indiana, State of 80/06/03 ip
- 8007020307 Forwards comments on proposed rule 10CFR20 Choice of measurement quantities must be made by considering practical limitations & biological parameters Processor should be required to test only for type of radiation produced DARIOS.E L. Yankee Atomic Electric Co. 80/04/22 3pp
- 800702030B Correction notice for recipients of proposed rule 10CFR20 re performance testing for personnel dosimetry Comment 4 miscoded & will not be used again Correction notice should replace Commont 4 # Dacketing & Services Branch 80/05/30 lp
- 8007020312 Comments on proposed rule 100FR20 processor must be given JUPICEUSIE comments on propused ruse towner processors ample time & trial desimeter expessors to permit calibr of processing equipment Expresses gratitude for apportunity the discuss proposed std w/other in-house desimetry processors JAMORSKI,R L. Omaha Public Power District 80/04/30 2p;
- 8007020315 Forwards comments on proposed rule iOCFR20 Item 5 re eye protection makes compliance difficult & should be deleted Neutron source should be standardized Photon component should be well defined CAULDHELL,F S Yankse Atomic Electric Co RDS 34/80 80/04/18
- 8007020327 Comments on proposed rule 10CFR20 rule must apply to all thermoluminescent dosimetry if user is to be effective Certification should be matched to monitoring purpose GIBSONJ D Stone & Webster Engineering Corp 80/05/27 2pp
- B007020329 Comments on proposed rules iOCFR20 distrepancy stemming from tissue depth at which doses are recommended to be measured prohibit fair & meaningful dosimetry std Advises of plans to attend 800423 meeting DARDIS
- 8007020332 Comments on proposed rule 10CFR20 voluntary program not effective Dept of Health & Environ Science supports mandatory testing & certification program Health economic & legal considerations demand dose assessments be accurate LLOYD.L L Montana, State of 80/06/02 2pp
- 8007020340 Comments on proposed rule 10CFR20 certification of processors is not appropriate way of improving quality of pursonnel dosimetry Arguments suggest need for more uniform application of std webbadology FAY.C W
- 8007020342 Comments on proposed rule 10CFR51 NRC should carefully consider AIF communts, representing consensus among utils & YERLEY, T.E. Georgia Power Co. 80/06/06
- BO07020345 Comments on proposed rule 10CFR20 unjustifiable expense to regulate radiation exposures when 95% are below 1 25 rem/yr Voluntary commitments working GERB1,B J Affiliation Unknown 80/05/16 2pp

!

- 8007020352 Comments on proposed rule 10CFR50, submitted by Logistics Enterprises Corp NPRDS does not have substantial incentives for useful involvement by utils Sys should be streamlined & LERs & NPRD-46 combined * Affiliation Unknown P-0152 80/06/05 13pp
- 8007020348 Comments on proposed rule 10CFR51 Requests 30~day extension of comment period Extension would not significantly impact implementation of regulation since new applications for early review are not likely to be filed QRAY,FS Lowenstein,Newman,Reis,Axelrad & Toll 80/04/03 1p
- BOO702038B Comments on proposed rule 10GFR51 safety & emergency planning should not be admitted as 1550ES in NEPA alternative site review Recommends continued use of Reg Quide 4 7 PEOPLES.D 1. Commonwealth Edison Co. BO/06/09 400
- 8007020400 Comments on proposed rule 10CFR51 explicit statements about critical nature of reactor siting to public safety & pravision for scoping should be included HEDEMAN.W N Environmental Protection Agency 80/06/09 2pp
- 8007020406 Forwards corrected 800606 ltr commenting on proposed rule 10CFR51 Original was mailed w/important sentence inadvertently deleted PATTERBON.J D Middle South Servaces, Inc 80/06/10 1p
- --BOO7020413 Corrects 800606 comments on proposed rule 10CFR51 application to existing inventoried or banked sites is not clear Status of sites which are part of ongoing review are not reviewed Endorses AIF comments
 PATTERSON, J D Middle South Bervices, Inc. 80/06/10 3pp

ì

- BD07020407 Comments on proposed rule iOCFR51 proposed rule should be clarified re procedures & substantive requirements for alternative site decisions in pending cases METTERHARN, M. J. Conner, Moore & Corber 80/06/05 2pp
- 8007020412 Comments on proposed rule 10CFR51 min requirements for alternative site analysis on proposed rule will greatly assist applicants in siting nuclear facilities Varisty of methodologies should be taken into account REEVES,R W American Electric Power Co , Inc 80/04/06 Spp
- 8007020414 Forwards comments on proposed rule 100FR51 regulations concerning alternative site review should be coordinated w/ 800303 proposed regulations concerning E18
 LODNIB.J B Bargent & Lundy. Inc. 80/06/03 2pp
- BOO7020421 Comments on proposed rules 10CFR2 & 50 regulations in Part 2 should be revised to incorporate proposed requirement Option B w/mods Part 50 10 should be replaced w/encl proposed regulation
 WILSON.J N Licensing Branch 1 80/06/12 4pp
- 8007020424 Comments on petition for rulemaking 2-10 proposed rule could require Commission to hold unnecessary hearings & cause delays in approval of proposed licensing action which does not present significant hazards ORAY,FS Lowenstein, Newman, Reis, Axelrad & Toll 80/06/16 3pp
- 8007020438 Comments on proposed rule 10CFR20 on behalf of Zimmer Area Citizens any met) which exceeds level of radiation found normally in that met) in natural environ should be considered as radwaste & disposed of accordingly FIBSE, LR Affiliation Unknown 80706/13 11pp
- BOO7020439 Comments on proposed rule 10CFR20 NRC should sponsor mandatory dosimetry test program for all civilian personnel dosimetry processors Advises of inability to attend 800423 meeting of in-house dosimetry processors KLOTZ.A S Northeast Utilities NEE-80-RA-236 80/04/16 3pp
- 8007020441 Comments on proposed rule 10CFR20 NRC should set performance std such that any processor not meeting std is prohibited from performing personnel dosimetry KLOTZ A S Northeast Utilities NEE-80-RA-296 80/04/16 2pp
- BOO7020444 Forwards comments on proposed rule iOCFR20 should include explanation why linear no-threshold assumption of effects selected Consideration should be given to retaining current limits for concentrations in air & water CULVER.J F Air Force, Dept of 80/06/10 App
- 8007020447 Comments on proposed rules 10CFR50 & 51 issues in NRC 800312 request for comments are outside DOT field of expertise Supports President Carter 800212 program on radwaste mgt White House press release & radwaste mgt program encl GOLDSCHMIDT, N Transportation, Dapt of 80/04/07 29pp

- B007020449 Comments on proposed rulo 10CFR29 guidelines should be included to be used in training sessions for radiation workers, informing of clinical % cytological indicators of higher than normal risk of serious health damage BERTELL, R Ministry of Concern for Public Health 80/05/21 3pp
- 8007020452 Comments on proposed rule 10CFR20 use of robots to carry out routine work at nuclear power plant would free human employees to concentrate attention on tasks that can not be carried out by machine ABLER, W.L. Affiliation Unknown 80/06/08 2pp
- B007020457 Comments on proposed rule 10CFR20 exposure stds should be made as low as possible PECK.H Affiliation Unknown 80/06/09 ip
- B007020461 Comments on proposed rule 10CFR20 special consideration should be given to exposure of embiyo. Fetus & minors implementation should be sufficiently flexible to allow radiation protection programs to be adapted to situations STEBBING.0 E Army. Dept of Diffice of Surgeon General DASG-PSP-E 80/06/09 2pp
- 8007020464 Comments on proposed rule iOCFR20 emphasis should be put on mgt commitment to radiation safety program & expert qualifications of radiation safety mgt & personnel HALEMAN. G R Yale Univ 80/06/11 2pp
- B007020465 Comments on proposed rule (OCFRS) approves of advertising in local newspapers, if all local newspapers are included Emergency planning in early site review should include planning for future population LEWIS.M I Affiliation Unknown 80/06/09 2pp
- B007020472 Comments on proposed rule 10CFR91 practical implementation appears to fail short of stated objectives Licensee believes implementation will impact adversely on siting process COUNSIL.W O Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) B0/06/09 3pp
- BOO7020556 Comments on proposed rule 10CFR51 second alternative of exclusionary safety stds.w/inclusion of safety issues in alternative site consideration.is preferable Stds will permit flexibility in candidate site proposal POND, G D Connecticut, Blate of BO/06/11 2pp
- 8007020585 Comments on proposed rule 10CFR90 & provides status of fire protection mode Requests reconfirmation of commitment dates outlined in safety evaluation:
 BYLVIA, B R Virginia Electric & Power Co 2541/061478 80/06/30 Bpp
- BOO7020635 Notifies of issuance of FE5 re proposed rulemaking on storage & disposal of nuclear waste FES transmitted to persons on encl svc list DROWN, DF Energy, Dept of 80/06/10 /pp
- 8007020659 Submits Progress Rept 29 for May 1980 re performance testing for personnel dosimetry "PLATO.P Michigan. Univ of NRC-01-77-180 NRC-01-77-180 80/06/02 6pp
- 8007020661 Responds to 800418 Itr requesting opportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations Meeting will be scheduled in near future wistate officials t public CHILK.B J Office of the Secretary of the Commission 80/06/11
- B007020663 Responds to B00403 ltr requesting opportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations Meeting will be scheduled in near future w/state officials to public CHILK.8 J. Office of the Secretary of the Commission B0/06/11
- 8007020664 Responds to 800409 lts requesting opportunity to assemble group from nucleas industry or utils to brief Commission on proposed emergency planning regulations Meeting will be scheduled in near future w/state officials & public CHILK.S J Office of the Secretary of the Commission BO/06/11 is
- 8007020665 Responds to 800424 ltr requesting opportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations Meeting will be scheduled in near future wistate officials & public CHILK.S J Office of the Secretary of the Commission 80/06/11 in

- BOO7020667 Requests apportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations
 KNUTH, D F Kerr-McGes Chemical Corp (subs of Kerr-McGes Corp)
- 8007020660 Requests opportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations
 OHEN.W H Duke Power Co. 80/04/09 2pp
- BOO7020671 Requests opportunity to assemble group from nuclear industry or utils to brief Commission on proposed emergency planning regulations
 KEARNEY, J. J. Edison Electric Institute 80/04/18 1p

- BOO70,206B2 Comments on proposed rule IOCFR20 neutron testing w/Pu-beryllium source should be reinstated for use w/cf-252 source distinctry test Unable to attend Apr meeting of commencial processors HOLDEN.8 H Radiation Detection Co 80/04/25 App
- 8007020689 Comments on proposed rules IOCFR2,19,20,21,30,40,51.60 & 70 on behalf of Radwaste Mgt Group.consisting of listed utils NRC underestimates cost of site characterization Perfection being established as std for siting decisions SILBERG, J. E. Shaw, Pittman. Potts & Trowbridge 80/03/04 Bpp
- 8007020695 Forwards comments on proposed rule 100FR20 neutron source should be standardized at facility to eliminate groblems w/ dose determination Advises of plans to attend 800421. meeting CAULDWELL,FS Yankee Atomic Electric Co RDS-34/80 80/04/18
- 8007020701 Comments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70 unnecessary to address policy-related issue as to number of fully characterized high level radwaste sites Addl comments encl RDBINSON.R K Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/02/29 Эрр
- 8007020728 Forwards comments on proposed rule 10CFR51 single delay period of 3 months should be applied regardless of whether detailed studies have been performed Section 8 2 should be VAN BRUNT, E.E. Artigna Public Service Co. ANPP-15636 80/06/12
- 8007020742 Comments on proposed rule 10CFR20 sys failing to provide satisfactory measurement could still provide satisfactory control Timeliness vital to support requirements of control Std does not give due credit to personnel domimetry Tennessee Valley Authority 80/04/23 App
- B007020746 Comments on proposed rule 10CFR20 processor certification is step in right direction & formation of testing & certification lab is needed Processors need access to specialised calibr sources Lab must be highly aukonomous BARTLETT, W T Affiliation Unknown B0/06/06 3pp
- GOD7030001 Comments on proposed rule 10CFREO Univ of HI testing program results demonstrate operational difficulties in passing personnel dosimetry performance test Passing of std does not ensure good personnel dosimetry University (1000) 200
- 8007030003 Comments on proposed rules 100FR2, 19, 20, 21, 30, 40, 51, 60 & 70 wasknesses are further testimony to NRC unwillingness to east aside past prejudices & demonstrate political courage requisite to successful geologic disposal program DIEHL.D S Sierra Club 80/03/03 5pp
- B007030012 Comments on greposed rules 10CFR2,19,20,21,30,40,51.40 & 70 licensing philosophy based on hest site, best waste form or best waste package should be avoided Overall sys approach should be adopted instead Detailed comments encl JORNBON, N T Westinghouse Electric Corp 80/02/25 3pp
- 8007030024 Comments on proposed rules (OCFR2, 19, 20, 21, 30, 40, 51, 60 & 70, submitted by AR Archeological Survey statement re timing of state historic preservation officer review should be made in final procedures for radwaste disposal DAVIS, H A Arkensas, State of 80/02/26 1p
- 8007030045 Requests listing of NM Environ Evaluation Group as interested party to NRC generic waste disposal rulemaking proceeding Requests receipt of past repts & future meeting natices & repts NEILL.R H New Moxico, State of 80/05/13 ip

- --8007030050 Requests placement on svc list for generic proceeding on confidence in storage & disposal of nuclear wastes

 DAVIS.J P Consolidated Edison Co of New York 80/05/06 ip
- --B007030059 Requests transcript of B00129 first general meeting of participants in proceeding & that Sensible ME Power co-counsel be placed on distribution list for transcript & all future distributions Miller, D S 80/05/06 in
- 8007030082 Comments on proposed rule 10CFR51 should not apply to CP applications docketed before effective date or to related OL applications Safety issues should not be considered in alternative site analysis GRAY.FS Lowenstein, Newman, Reis, Azelrad & Toil 80/06/19 3pp
- 80070300B4 Comments on proposed rule 10CFR50 NRC should support further testing re use of water extinguishing sys over energized electrical equipment QSA 1979 limited test rept encl HUTTON, J R Energy, Dept of 80/06/11 19pp
- 8007030087 Comments on proposed rule 10CFR20 mandatory program not Justified Implementation should be delayed until problems are resolved 8td ANSI NI3 11 should be used for test LEWIB: L Duke Power Co 80/06/11 2pp
- 8007030095 Comments on proposed rules 10CFR50 & 51 applications not yet reviewed by Licensing Board should include Class 9 accidents in EIS
 JOHNSON, C Texas Public Interest Research Group 80/04/30 3pp
- BOO7030104 Comments on proposed rules 10CFR2.19.20.21.30.40.51.60 & 70 submitted by CA Energy Resources Conservation & Development Commission Proposed procedures are significant improvement over NRC Nov 1978 proposed general statement of policy VARANINI.E E . GREW.P C California. State of 80/03/03 5pp
- BOO7030107 Comments on proposed rules iOCFR2, 19, 20, 21, 30, 40, 51, 60 & 70 rules are deficient in several key aspects & continue to reflect passive approach of Commission in dealing w/DOE program in 1978 general statement of policy BERICK.D Environmental Policy Institute 80/03/03 3pp
- 8007030113 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 submitted by CT Dept of Environ Protection Provisions should be made for federal funding to support monitoring program administered by state after decommissioning HEUBNER.A T Connecticut. State of 80/02/28 1p
- B007030119 Comments on proposed rules 100FR2, 19, 20, 21, 30, 40, 51, 60 & 70 on behalf of Util Waste Mgt Group & EEI Endorses change in Commission approach which would eliminate formal step of provisional Const authorization AXELRAD.M Lowenstein, Newman, Reis, Axelrad & Toll 80/03/03 9pp
- 8007030127 Comments on proposed rules 10CFR2, 19, 20, 21, 30, 40, 51, 60 & 70 major concerns are in areas of site characterization, consultation & concurrence w/states & public participation Reserves final comments
 HANCOCK.D Southwest Research and Information Center 80/02/28
- 800703013B Forwards comments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70 Bite characterization rept should be made on site by site basis NRC should not be involved in screening of sites for site characterization MCCRAY,J Q Arizona. Univ of 80/02/20 2pp
- E007030158 Comments on proposed rules 10CFR2,19,20,21,30,40,51,40 & 70 Indian trabal govts should be provided adequate opportunity to participate in licensing process GABRIEL. E Council of Energy Resource Tribes B0/03/03 App
- 800703017i Forwards comments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70, submitted by League of Women Voters of US Mandatory hearings should be required before repository is authorized for const PDWERS,D Affiliation Unknown 80/02/28 2pp
- BOO7030179 Comments on proposed rule IOCFR20 derived limits for concentration in air & water should be retained & updated to reflect most current technical data Use of limits for intakes would provide add problem solving flexibility COPELAND.R L Energy.Dept of. Clinch River Breeder Reactor Plant ь. Эрр 80/06/17

- 8007030190 Comments on proposed rule 10CFR20 care should be exercised in adopting statements of scientific advisory bodies directly into regulatory framework Adoption of Sys Intlunits will not make contribution to laymen understanding RODERS W L Gulf Oil Corp., Oulf Mineral Resources Co 80/06/10
- 8007030173 Comments on proposed rules 10CFR2,17,20,21,30,40,51,60 & 70 supports requirements re-characterizing number of sites in appropriate media by in situ tests at depth before selection of repository site & issuance of license to construct MENARD,H W Interior,Dept of, Geological Survey 80/02/29 2pp
- B007030200 Comments on proposed rules 10CFR2.19.20.21.30.40.51.60 & 70 unclear whether two or more repository sites must be rejected for each site accepted All US waste generated to yr 2000 could be accommodated in two natl repositories FAIRHURST.C Minnesota. Univ of Minnesolis 80/02/21 2pp
- 8007030204 Comments on proposed rule 10CFR20 natural radiation is only one component of environ radiation that also includes manmented & manmade radiation Unly measurement of particular area must be done in field w/addl doses based on findings MASBERBACH. A E New York Federation for Safe Energy 80-59 80/06/17. 10pp
- --B007030207 Comments on EPA DRP-91D 72-1. "Natural Radiation Exposure in US," by DT Oakley no such thing as true measurement of background radiation average permissible dose or population dose Requests that NRC review rept HABGERBACH. A E New York Federation for Safe Energy EPA ORP-BID-72 80/04/25 App
- 8007030341 Comments on proposed rule 10CFR73: reiterates 790B17 request that spent fuel or irradiated reactor fuel be carried on special trains NRC & DOT opinions influenced ICC denial of restrictions on transport of raduaste
 BMITH.R L Consolidated Rail Corp 80/04/14 3pp
- 8007030343 Comments on proposed rule iOCFR20 assumptions should be clearly identified & be accompanied where appropriate by full explanation of attendant applications. Full definition of ALARA should be retained in any revision SCHERER. A E C-E Power Systems LD-80-033 80/06/18 5pp
- 8007030348 Comments on proposed rule 10CFR20 Sys Intl units should not be used in regulatory program unless used as secondary units & appear in parentheses NRC should provide detailed procedures for dose determination when required LARSON.H J Atomic Industrial Forum 80/06/18 10pp
- B007030349 Comments on proposed rule 10CFRBO experience at fire five yrs ago demonstrates that 2-h supply of water is inadequate Bpecial protective features should include properly designed & separated trays w/cabling sue
- B0070303BI Forwards comments on proposed rule 10CFR20 stds should be consistent w/applicable federal protection guidance & should include consideration of work of recognized natl & intl advisory organizations.

 BATES,A Affiliation Unknown H0/06/16 24pp
- 8007030334 Comments on proposed rule 1907R20 social & economic factors must be considered Balance must be maintained between social benefits & associated risks Recommends that ALARA not be used as numerical guides ALLMENDINGER.P Affillation Unknown 80/04/18 3pp
- 8007030365 Comments on proposed rules iOCFR50 & 51 Class 7 events should be considered in NEPA reviews for all reactors SECY-90-131 concluded that NEPA environ reviews should include analysis of all possible radiolgical accidents WRIOHT,F B Massachusetts, State of 80/04/22 6pp
- B007030366 Comments on proposed rule 10CFR20 recognition of differences in susceptibility to radiation is virtually absent NRC should halt advancement of nuclear technology until scientists have better understanding of long-term affects DRAKE, Q A Affiliation Unknown B0/06/16 2pp
- 8007070043 Comments on proposed rule 10CFR73 2-day notice to delay scheduled shipment is not adequate to allow shipper to modify plans NRC should notify shipper within 24-h of receiving 7-day notice from shipper MANGUSI.
- 6007070063 Comments on proposed rule 10CFR20 licensee has no concerns w/required reporting of doses to public from fuel cycle.

 Implementation of discharge limits for Kr-85 k I-129 in 1983 should be clarified tEHIG.1. Duke Power Co 60/06/12 lp.

- B00707006/ Comments on proposed rule 10CFR73 restrictions on shipment of moderate strategic significance SNM will significantly impede commerce Factors influencing delay of conflicting shipments should be given FLDMERG.F D. General Electric Co. FDE. 80-56 80/04/01 2pp
- B0070700B4 Comments on proposed rules 10CFR2.19.20.21.30.40.51.60 & 70 supports proposed step-by-step process for reviewing DDE development of geologic repositories Final regulations require discussion of presence & potential of lossurces LASH.T.R. YUAN.G. Natural Resources Defense Council B0/02/29 1300
- 8007070085 Comments on proposed rules 10CFR30 & 35 suggests rewording to clarify that Mo-99 breakthrough tests would be required only for elutions from Mo 99/Ir-99m generator BRODXS.T R Maryland, State of 79/08/31 1p
- B007070092 Comments on proposed rule 10CFR20, on behalf of Comm Ed major changes in sus of radiation protection stds should only be made if & when warranted by new info from responsible acientific bodies

 BTRELOW, R., ELLIOTT, E.D. Levy, Gutman, Goldheig & Kaplan B0/06/18
- B007070112 Comments on proposed rule 100FR20 assumption of linear dose response near zero effect-zero dose intercept is scientifically unsupportable More practical Inmitations are ambient radiation & natural incidence of biological effect MODBON.W L Vet Admin Hosp Northport.NY B0706/16 2pp
- 8007070i18 Comments on proposed rule 10CFR20 numerical exposure guidelines should be consistent w/ICRP Publication 26, w/ dose guidelines of 5 rem/yr from external & internal sources combined PALE.L F Mississippi Power & Light Co AECM-80/130 80/06/16
- 8007070121 Comments on proposed rule 10CFR20 important to emphasize need to make use of newly available capabilities represented by Radiation Policy Council
 NEY, MR National Council on Radiation Protection & Measurements 80/06/12 2pp
- B007070174 Comments on proposed rule 10CFR20 technical bases for numerical limits should be readily identifiable & primary consideration in proposed stds Highly controversial results should not be basis for imposing more restrictive limits CADENA, D 0 Bouthwest Research Institute 80/06/16 3pp
- B00707017B Comments on proposed rule 10CFR20 Commission should limit responsibility to specific & substantive regulations & refrain from issuing ambiguous & highly interpretative policy statements which may paralyze advancements in field MURPHY.R Medi-Physics, Inc. B0/06/17 3pp
- B007070402 Comments on proposed rule 10CFR20 placing guidance into regulations that should be placed in reg guides to referencing reg guides in regulations can short circust intended review & approval process
 NILBON.R Exxon Nucloar Co. Inc. (subs. of Exxon Corp.) 80/06/10
- B007070406 Comments on proposed rule iOCFR20 recognition should be given to alternative threshold nonlinear effect point of view Assumption of linear dose-effect relationship is not universally accepted except as conservative upper limit SANDERS.C I Armstrong Cork Co 80/06/16 ip
- 8007070407 Comments on proposed rule 10CFR20 proposed personnel review of numerical dose limits for internal & external exposures in combination appears to be unnecessary Use of engineering controls has resulted in no significant dotectable burdens VANDENBURGH.D E Yankee Atomic Electric Co. MYC 80-18 60/06/13 2nn
- 8007080009 Statement of position on proposed rulemaking re-storage & disposal of radwaste Urges serious study of nontechnical criteria & requirement that consultation & concurrence procedure be consolidated in 50 states H/Contificate of Svc ANDALMAN, E Mississippians Against Disposal 80/06/25 6pp
- 8007080249 Forwards Scientists & Engineers for Secure Energy statement of position re storage & dispusal of nuclear waste To ensure waste disposal facilities will exist when needed, demonstration projects should be begun immediately RICHARDS.J R Capital Legal Foundation 80/07/01 28pp

- 8007080347 Comments on proposed rule 10CFR20 on behalf of util Occupational Radiation Stds Group licenses should establish specific procedures to implement emergency occupational exposures w/expusive limited to one time only Repts encl GALLO.J Isham. Lincoln & Beale 80/06/18 13pp
- --8007080393 'Radiation Canter Risks & Linear Hypothesis " Brief author biography enc 3 GOLDMAN, M. California, Univ. of, Davys 80/06/18 17pp
- --B007080357 "Practical Threshold for Radiation " WHIPPLE G H Michigan Valv of 80/06/10 12pp
- --8007080360 Memorandum of discrimination issues raised by special occupational radiation exposure stds for women HOLZMEIG, 5 F Isham Lincoln & Beale 80/06/18 19pp
- 8007090048 Comments on proposed rule 10CFR20 requests that name be added to mailing list in connection w/rulemaking procedure STENSYAAG. J M Vanderbilt Univ 80/06/18 1p
- 8007090098 Forwards 800514 errata to 800415 statement of position re proposed rules 100FR30 % 51 Svc list encl BROWN, O F Energy, Dept of 80/05/19 6pp
- --8007090103 Errata to 800415 statement of position reproposed rules accesso & 51

 * Energy, Dept of DOE/NE-0007 80/05/14 App
- 8007090113 Forwards corrected Pages 3.7 & 10 to 800229 comments on proposed rules 100FR2,19,20,21,30,40,51,60 & 70 JONES,KA Natural Resources Defense Council US 9D 901-1 80/03/03 4pp
- 8007090145 Comments on proposed rules 10CFR50 & 51 although decision to defer commercial reprocessing in US was based primarily on economic considerations delay was also intended to encourage other countries to consider deferral KEENY. B H Unknown Affiliation 80/04/11 4pp
- --8007090148 Comments on proposed rules 10CFR50 & 51 supports conclusions of Interagency Review Group on Nuclear Waste Mgt in Mar 1979 rept to President
 SPEIM.G Council on Environmental Quality 80/04/15 9pp
- B007090399 Comments on proposed rule iOCFR20 orgss that NRC view low level isotopes used in medicine with context & not delay promutgation of appropriate requirements for disposal until problems of reactor waste disposal can be solved LINTON.O W Affiliation Unknown 80/06/18 2pp
- B007090402 Comments on proposed rule 10CFR19 success of conferences is largely due to informal nature which allows candid discussion between NRC & licensee mgt Proposed rule is unnecessary & would intrude on mgt responsibility PARKER. W O Duke Power Co 80/06/04 2pp
- 8007100001 Comments on proposed rule 10CFR20 changes ought to be made only when overwhelmingly required Major rewrite.as proposed,would be counterproductive to purpose of radiation protection

 BRITIS: J S Health Physics Society 80/06/12 3pp
- 8007100005 Forwards comments on proposed rule 10CFR50 rule is very vague & does not fully identify specific fire protection as intended Implementation deadlines are unrealistic & should be re-evaluated Proposed rule encl
 QIBBS, D C Middle South Services, Inc. 80/06/13 13pp
- B007100007 Comments on proposed rule 10CFR20 anything beyond performance std based on abjectives of acquiring info through measurement would be unduly restrictive Regulations should be written in terms meaningful for implementation ZELAC,R E Temple Univ 60/06/11 2pp
- 8007100013 Comments on proposed rules 10CFR2:19,20.21,30,40,51.60 & 70 technical criteria should be established to limit releases to biosphere to less than is now legally acceptable MASON, D C Rockwell International Corp., Atomics International Div BOESQ-1978 80/02/28 3pp
- 8007100017 Comments on proposed rule 10CFR20 any changes from concentrations to annual intake limits must be carefully worded to ensure age & sex differences are well understood by public Clear instrument calibi info should be included WINANG. L.F. Oregon, State of 80/06/10 App

- 8007100024 Comments on proposed rules 10CFR2,19,20,21,30,40,51,60 & 70 proposed prelicensing process introduces unnecessary & redundant elements into otherwise sound program for geologic investigations & determinations of site suitability MEYERS,8 Energy,Dept of 80/03/03 10pp
- 8007100030 Comments on proposed rule 10CFR20 provision should be made for rational disposal of small activities of radionuclides used in diagnostic nuclear medicine procedures Situation is presently chaotic EVANS.R D Massachusetts Institute of Technology 80/06/16 4pp
- 8007100035 Comments on proposed rule 10CFR20 suggests extending 30-day reporting requirements to 60 days following month during which radiation levels or radioactive matt releases were in excess of limits COUNSIL.W 6 . LEE.W F Connecticut Yankee Atomic Power Co COUNSIL.W 6 Northeast Nuclear Energy Co (subs of Northeast Utilities) 810006 80/05/29 3pp
- 8007100046 Comments on proposed rule 10CFR73 regulation should indicate how NRC will obtain relevant info & what factors will influence decision on which shippers & consignees will be delayed HIGAN.J P General Atomic Co (subs of Gulf Dii Co) 80/03/04 20p
- 8007100047 Forwards util statement of position re proposed relemaking on storage & disposal of radwaste SANGER.H S Tennescee Valley Authority 80/07/07 1p
- --8007100050 Statement of position re proposed rulemaking on storage & disposal of radwaste Spent fuel may be stored safely onsite & offsite based on available & emerging suitable technology SANGER, H S , BURGER, J F , BUSTION, R R Tennessee Valley Authority 80/07/07 13pp
- ---8007i00D54 "Spent Fuel Mgt Program Study Summary Rept." Sept 1979 Certificate of Svc encl * Tennessee Valley Authority 79/09/30 36pp.
- 8007100079 Comments on proposed rules 10 CFR 2,30,40,50,51,70 & 110 rules do not indicate procedures for identification, evaluation & protection of historical &/or archaeological properties which may be affected by NRC licensing DINCAUZE,D F Massachusetts, Univ of 80/04/07 1p
- 80071000B3 Comments on proposed rule iOCFR20 terminology used to express amount of radiation & degree of exposure should be uniform & made clear for lay people Specific means for obtaining other exposure info should be provided PRITCHARD. G C Interior. Dept of, Bureau of Mines 80/06/13 App
- 8007100086 Comments on proposed rule 10CFR20 San Diego County concurs w/reporting requirements Reporting process should be linked to local govt which would respond to emergency situation HONDERGER.R F California, State of 80/06/17 lp
- 8007100090 Comments on proposed rule 10CFR140 discusses effects of TMI-2 accident on physical & mental health of family & local citizens Disagrees w/Galtzman statement that determination of damages would be difficult under present regulations MOSES.V R Affiliation Unknown 80/01/18 5pp
- 8007100092 Comments on proposed rule 10CFR20 requests combination of code requirements for dose & radioactive release to eliminate duplicate regulations & redundant reporting Literal enforcement of code would be costly & redundant HOFFMAN, D.P. Consumers Power Co. 80/06/12 2pp
- 8007100094 Comments on proposed rule 10CFR73 clarifies 800212 ltr re DOE license-exempt shipments for matl of low strategic significance Rewording was not intended to suggest NRC has authority to order DOE shipper actions WEI8Z.9 Energy.Dept of 80/03/05 2pp
- B007100104 Comments on proposed rule iOCFR70 clarification of intentions re (a)(1) is essential w/respect to carrier obligations & growing number of states seeking to regulate transportation of radioactive matts

 JORDAN.A G Affiliation Unknown 5048611 80/06/12 3pp
- 8007100160 Forwards summary statement of position of Util Nuclear Waste Mgt Group & EEI, "Copability for Disposing of High-Level Wastes Safely," "Long-Term Safety of Nuclear Waste Disposal" & "Capability for Bafe Interim Storage of Fuel" AXELRGD.M Lowenstein, Newman, Reis, Axelrad & Toll 80/07/07 7pp

-

- --8007100180 Summary statement of position of Util Nuclear Waste Mgt Group & EEl Spent nuclear fuel from licensed facilities can be disposed of in safe & environmentally acceptable manner * Edison Electric Institute * Lowenstein Newman, Reis, Axelrad & Toll 80/07/07 32pp
- --8007100184 "Capability for Disposing of High Level Wastes Safely "
 * Nuclear Safety Associates 80/07/07 160pp
- --8007100188 TR-3195-1
 "Long Term Bafety of Nuclear Waste Disposal Basis for Confidence"
 BARTLETT.J W , OSTON, S G , GIVFFRE.H S Affiliation Unknown RO/07/07 100bp
- --8007100191 "Capability for Bafe Interim Storage of Spent Fuel "
 LAMBERT, R General Electric Co HALEY, J Westinghouse Electric
 Corp SILBERG, J E Shaw, Pittman, Potts & Trowbridge 80/07/07
 Sign
- 8007100246 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges that reliable date he set by which repository sys will be in operation Adequate storage guarantee must be commensurate willfe of plant BROWN,W J , MUCHNICKI.E D Ohio, State of BO/07/07 Rápp
- 8007100248 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges exclusion of consideration of offsite disposal & extended onsite storage from individual licensing proceedings * Atomic Industrial Forum 80/07/07 59pp
- B007100254 Forwards ANS statement of position re proposed rulemaking on nuclear waste storage & disposal MONBOISBE,R M American Nuclear Society MONBOISSE,R M Pacific Legal Foundation B0/07/03 ip
- --8007100257 Statement of position of ANS proposing that NRC reach finding of confidence re-safe nuclear waste storage & disposal w/o danger to man or environ MONBOISSE.R M. ZUMBRUN.R A. American Nuclear Society MONBOISSE.R M. Pacific Legal Foundation 80/07/03 38pp
- 8007100327 Notifies that JF Ahearne concurs in wording of fire protection rule.SECV-80-088.as revised by J Parry 800317 memo subj to listed changes BAUTER.Q Commission 80/04/16 lp
- --8007100334 Forwards draft memo summarizing individual Commissioner comments on SECY-80-088, fire protection actions Requests comments or concurrence in time to affirm paper on 800319 Draft memo: modified pages & draft FR notice encl PARRY, S J S Office of the Secretary of the Commission 80/03/17 170s
- 8007100328 "Spent Fuel Mgt Program Study Summary Rept"
 DAVIDSON, R H , MOEGLING, J B Tennessee Valley Authority 79/09/30
- 8007100348 Comments on proposed rule 10CFR20 items should be added to provide for involvement of workers & representatives in auditing & controlling exposures & to provide for worker access to medical & exposure records

 HICKE, M M Utility Workers Union of America 80/06/16 4pp
- 8007100352 Comments on proposed rule 10CFR&O comparative evaluations of alternate waste forms for every repository are not justified DOE should specify allowable waste forms or set spacs
 MCELMURRY, B R Affiliation Unknown BO/06/13 2pp
- B007i10005 Forwards RR Lund 800324 ltr re Commission proposed rule on emergency planning Requests comments on concerns that rule is overbroad for medical licensees BIMPBON, A K Senate, Judiciary Committee B0/05/08 5pp
- 8007110019 Comments on proposed rules iOCFR2, 19, 20, 21, 30, 40, 51, 60 & 70 site characterization rept should include discussion of mineral resource conflicts, geologic conditions below repository level & regional geologic conditions HANCOCK, D , HECTOR, A G Gouthwest Research and Information Center 80/03/03 '4pp
- 8007110026 Comments on proposed rules 10CFR2, 19,20,21,30,40,51,60 & 70 site acceptabilty criteria should be defined to avoid ambiguity & to assure proper attention & informed decisions at each critical step of investigation HEDEMAN, W N Environmental Protection Agency, 80/03/07 2pp

- 8007110031 Forwards comments on proposed rules 10(FR2, 19.20, 21, 30, 40, 51, 60 & 70 NRC responsibility in determining licenseability should be based solely on whether particular site meets certain predetermined criteria WIGOIN.E A Atomic Industrial Forum 80/03/06 4pp
- B007110048 Statement of position re proposed rulemaking on storage & disposal of radwaste Historical experience offers no basis for confidence in DOE or nuclear industry ability to achieve goals & does not justify long-term projections
 JDRDAN, 8 & BISHOP, L New England Coalition on Nuclear Follotion
 JORDAN, 8 Sheldon, Harmon & Moiss 80/07/07 175pp
- B007110056 Comments on proposed rule 10CFR50 requests that ltr & attachments be read into record as testimony when Commission considers proposed rule on emergency planning Regulations for planning should only addrcss needed capabilities COX.F Y Texas. State of 80/04/28 7pp
- B007110067 Statement of position re proposed rulemaking on storage & disposal of radwaste Any alternative for radwaste disposal in geologic disposal site will be unacceptable due to unpredictable consequences Certificate of Svc encl LOCHSTET, W A Affiliation Unknown 80/07/03 dep
- 8007110087 Statement of position re proposed rulemaking on storage & disposal of radmaste Declines to state present comments but reserves right to offer cross-statements when appropriate HILSON.R P South Carolina. State of 80/07/03 1p
- 8007110101 Statement of position re-proposed rulemaking on storage & disposal of radwaste Deep geologic disposal uncertainties require further evaluation Disagreements between levels of govt must be solved DOE must provide assurance re-schedule GRIFFIN.W., DIAMOND.M.J. Vermant, State of 80/07/01 3pp
- B007110121 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges imposition of moratorium on new nuclear plants until technical & institutional problems are resolved Factual gaps & known problems still present ABRAMS.R., CORWIN.J.W., BIALIK.E 1 New York, State of 80/07/07 12Ann
- 8007110225 Comments on progosed rules 10CFR70 & 73 application of rule to nonpower reactors will have devastating effect on research reactors & associated education & research activities carried on at univ research reactors
 WILSON.W E Washington State Univ 79/10/0B 13pp
- --8007ii023i Forwards comments on proposed rules 10CFR70 % 73 facility will be shut down rather than incur costs for upgrade Faculty/staff positions will be eliminated MILSON.W E Washington State Univ 79/08/30 3pp
- ---BO07110239 Forwards comments on proposed rules 100FA70 & 73 no detailed impact statement or cost-benefit analysis is available to predict effects of proposed rulemaking on US educational sys
 WILSON.W E Washington State Univ 79/08/30 3pp
- B007110242 Advises that RT Kennedy concurs in changes to BECY-B0-08B, fire protection rule, proposed in 0 Bouter 800416 memo. subj to attached revisions GUILBERT. J Commission 80/04/17 4pp
- --B007ii0246 Notifies that JM Hendrie concurs w/B004i6 version of fire protection rule circulated by G Sauter as modified by RT Kennedy FONTECILLA.H Commission B0/04/IB 1p
- 8007110257 Forwards WI Ad Hor Radinactive Waste Disposal Committee comments on proposed rules 10/FR2.19.20.21.30.40.51.60 & 70 application.environ rept & amonds shall be filed w/ufficials designated by governor State of WI 790727 ltr to DOE encl HALSTEAD.R J Wisconsin. State of 80/06/04 19pp
- 8007110345 Statement of position re proposed relemaking on storage & disposal of radwaste Joins in New England Coalition on Nuclear Pollution & NRDC statements of position W/certification of svc MILLER, D S Sensible Maine Power MILLER, D S Miller, D S 80/07/07 ip
- 8007110492 Comments on proposed rule 10CFR20 NRC should draft NUREG rept to accompany regulation which details technical basis for numerical limits & quantitative requirements in revised rule
 TAYLOR J J Westinghouse Electric Corp. WRD-1097 80/04/18 22na

- BOO7110496 Requests Commission approval to publish for comment, amend to 10CFR50 in form of App R.w/fire protection requirements for plants in operation prior to 790101 Amend would facilitate implementing BTP 9 5-1
 FONTECILLA.H M Commission 80/03/14 2pp
- B007i10497 Comments On proposed rule IOCFR20 party other than operating util should be responsible for monitoring all radioactive releases from nuclear plants
 STAMIRIS.B Affiliation Unknown 80/06/17 1p
- 8007:10504 Discusses status of App R to iOCFR50 re impact of requiring all fire protection features installed by 80:101 Eleven plants will not complete Section 3 1 mods & Section 3 2 open items by 80:101

 LAINAS. 0 Plant Systems Branch 80:004/11 3pp
- B007110507 Forwards comments on proposed rule 10CFR51 from RC Pevear of NH State Legislature
 DURKIN, J A Senate 80/04/19 ip
- 8007110534 Comments on proposed rule IOCFR20 additreporting requirements should be initiated only if well defined benefit is to be derived GERTH, 0 E Mallinckrodt, Inc. 80/06/18 Jpp
- 8007110547 Describes status of alternate/dedicated shutdown sys as of 800328 CASE, E Office of Nuclear Reactor Regulation. Director 80/07/10 200
- 8007110553 Motion to produce documents forthwith & extend date for submitting comments on proposed rule 10CFR50 until at least 30 days following date info requested in KMC Inc 1980 FOIA request is made available CONNER.T B KMC. Inc 80/06/24 9pp
- 8007110586 Forwards info requested by JF Ahearnø re status of fire protection review program, alternate/dedicated shutdown sys status as of 800331 & other outstanding issues LAINAS, C Assistant Director for Safety Assessment 80/04/02 7pp
- BOO7140002 Statement of position re proposed rulemaking on storage & disposal of radwaste Complete set of acceptability criteria may not be possible due to lack of successful site studies Detailed tests needed for actual site risk assessment # Interior,Dept of: Geological Survey 80/07/07 38pp
- BOO7140011 Statement of position re proposed rulemaking on storage & disposal of radwaste NRC should find that no conclusions can be drawn as to whether or not spent fuel can be safely stored until germanent disposal sites are available SENCEHAL, M E . OLSON, J F , SPANNAUS, W Minnesota, State of BO/07/07 9no
- --BO07140014 Comments re proposed rulemaking on storage & disposal of radwaste No scientific basis may be advanced for safe 40-yr spent fuel storage ABRAHAMSON.D Minnesota, Univ of, Minneapolis 80/07/02 40pp
- 8007140036 Statement of position re-proposed rulemaking on storage & disposal of radwaste Urges establishment of positive finding of confidence Notes evidence of demonstrated waste agt technology re-potential toxicity & full-core discharge GRAMER, EN Neighbors for the Environment 80/07/04 3pp
- --B007140040 "Demonstrated Technology Three Examples From History & Analysis of Nuclear Waste Mgt." by JB Rae.of Harvey Mudd College of Engineering & Technology in Claremont, CA RAE.J B Affiliation Unknown 77/07/08 23pp
- ---8007140046 ISBN 0-87448-106-1
 Evaluating Hazards of Disposing of Wastes from Energy
 Production." Bureau of Radiation Protection, Harrisburg, PA
 Presented as part of ANS 800227-29 topical meeting re
 technical assessment of nuclear power & alternative
 DDRNSIFE.W P
 Memrican Nuclear Bocsety
 DRNSIFE, W P
 Pennsylvania. State of 80/02/29 19pp
- --B007140051 I D 77-11-07
 "Relative Spent Fuel Storage Hazard," prepared for ANS
 winter meeting in Ban Francisco.CA
 STRANL.J F NUS Corp BROSNAN,D F Los Angeles, CA CRAMER.E N
 Southern California Edison Co 77/11/30 28pp
- BOO7140043 Statement of position re proposed rulemaking on storage & disposal of radwaste Urges determination re recycling technique & location Interim away-from-reactor sites should be avoided Geological survey list of publications encl MACARTOR, J D Delaware, State of BO/07/03 20pp

- 8007140045 Forwards statement of position re proposed rulemaking on storage & disposal of radwaste O'DONNELL,A J Bechtel Corp 80/07/03 ip
- --B007140049 Statement of position re proposed rulemaking on atorage & disposal of radwaste Radioactive waste can be safely disposed of in mined geologic repository, in basalt & granite chambers & in different host media

 * Bechtel Corp 80/07/03 6pp
- B007140096 Comments on proposed rule tOCFR20 single agency should have responsibility for radiation related matters Recordseeping requirements should be streamlined COLLIER.R E Affiliation Unknown B0/06/18 2pp
- 8007140277 Responds to FDIA request for all info which directed or discussed any changes of proposed fire protection rule in SECY-BO-OBB App documents have been forwarded J Ovibert BO0311 meno withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 80/06/26 2pp
- --B007140291 Staff requirement memo re 800423 open Affirmation Session 80-18 in Washington, DC Includes overall records of Commission votes re SECY 80-166, SECY 80-177 & SECY-80-088 CHILK, 9 J Office of the Secretary of the Commission B0/05/01
- --8007140297 Discusses fire protection rule proposed in SECY-80-08Q Lists

 JF Ahearne recommendations re provisions which should be
 incorporated in rule Includes info re public comment
 period & implementation of nonshutdown sys mods
 SAUTER. G Commission 80/04/10 ip
- --B007140302 Discusses fire protection rule proposed in BECY-80-08B Commission affirmed, w/comments, proposed fire protection rule delineating certain min fire protection requirements at B00423 Affirmation Session B0-18 Lists recommended changes NOTLEY, D.P. Engineering Metholology Standards Branch B0/06/03, 200
- 8007140286 FOIA request for all info which directed or discussed any changes to proposed fire protection rule in BECY-80-088 & record of Commission's vote re changes
 KNUTH.D F Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)
 80/05/30 1p
- 8007140387 Statement of position on proposed radwaste storage & disposal rulemaking No aspect of DDE program provides reasonable assurance reliable offsite waste disposal syswill be available before current nuclear licenses spring SHELDON, K.P. Natural Resources Defense Council SHELDON, K.P. Bheldon, Hermon & Weiss 80/07/07 95pp
- 8007140402 Comments on DOE position re proposed radwaste disposel & storage rulemaking Technical facts inadequately addressed or improperly interpreted DOE defense in depth approach not as strong as position paper purports
 MUDREY: M O Wisconsin, State of 80/07/10 13pp
- --B007i4040B Comments on DOE B004i3 statement of position re proposed radwaste disposal & storage rulemaking Transportation impacts through reliance on railroads could significantly add to consumer cost LEVERANCE, J. Wisconsin: State of B0/07/07 3pp
- --8007140417 Testimony re DDE statement of position re proposed radwaste storage & disposal rulemaking DDE position does not deal adequately w/social.political & institutional aspects of radwaste mpt ML Symon 800805 itr to RW Riley encl KELLY,J E Wisconsin, State of 80/07/10 3ipp
- B007140432 Forwards statement of position re proposed rulemaking on storage & disposal of radwaste Requests addition of MJ Murray & removal of D Hansell & S Bekuler from svc list MURRAY.M J Illinois, State of 80/07/07 ip
- --8007/40439 Statement of position re proposed rulemaking on storage & disposal of radwaste DQE conclusions that waste packaging methods will be developed when need arises are meaningless due to insufficient data & technical uncertainties HURRAY,M J, SCOTT,W J, VRANKEN,J V Illinois, State of 80/07/07 5pp
- --8007140449 Affidavit stating that DDE position re waste packaging matls is misleading DDE statements re interim spent fuel storage inadequate W/bibliography & proof of syc RDY.R Illinois, State of RDY.R Pennsylvania State Univ 80/07/03 8pp

- 8007140454 Comments on proposed rules iOCFR2 & 50 prefers current regulations rather than proposed options A-D which would prolong licensing schedule W/o assuring timely decisions ROBINSON.H J Black & Veatch 80/06/16 2pp
- 800714046B Forwards comments on proposed rule 10CFR50 rule is vague & Unenforceable Updating existing reg guides rather than implementation of App B would better serve safety, fire protection & financial interest of consumer DUNCAN,K W Affiliation Unknown 80/06/19 App
- 8007140538 Comments on proposed rules 10CFR2.19,20,21,30,40,51.60 & 70 State of WI Ad Hoc Radioactive Waste Disposal Committee agrees w/rulemaking rationale Supports decision to withdraw proposed Nov 1978 general statement of policy HALSTAD.R J Wisconsin, State of 80/05/27 2pp
- BOO7140543 Comments on proposed rules 10CFR20 & 50 disagrees w/immediate effectiveness requirement for significant & nonsignificant events
 HOFFMAN.D P Consumers Power Co 80/05/29 5pp
- B007140549 Comments on proposed rule iOCFRi9 iOCFRi9 14(h), as proposed, not necessary & language used does not explicitly define public access or individuals w/legitimate interests Informal conferences w/licenses mgt would be beneficial RAGDEN, 0 Western Nuclear. Inc (subs of Phelps Dodge Corp) B0/04/28 2pp
- B007140559 Comments on proposed rules 10CFR20 & 50 consolidated reporting requirement list should be developed & obsolete & repetitious requirements should be cancelled Addl burden could distract plant operators
 FAY, C W Wisconsin Electric Power Co 80/06/04 3pp
- 8007140564 Comments on proposed rule 10CFR20 commends NRC action to have NRC certified lab w/continual monitoring by NBS STEIN.E L Delaware, State of 80/05/29 ip
- 8007140575 Comments on proposed rules 10CFR2 & 80 favors proposed rule change to 10CFR2 105,10CFR50 58 & 10CFR50 91 NRC capable of determining significant hazard considerations & 30-day wait before amend issuance unnecessary DALE, L. F. Mississippi Power & Light Co. 80/05/28 ip
- BOO71405B2 Comments on proposed rule 10CFR20 proposes that manufacturer be tested & certified before TLD clips are allowed on market.eliminating film processing problems MALEK.F A Gulf Nuclear, Inc. BO/05/29 1p
- 8007140591 Comments on proposed rule IOCFR20 personnel desimetry problem might be helped by periodic insp of personnel & facilities & personnel monitoring establishments Standardization lab could result in greater errors NURNBERGER,C E Affiliation Unknown 80/05/19 2pp
- 8007140599 Comments on proposed rule iOCFR20 supports NRC position that certification lab be self-supporting or operated under contract to govt agencies
 LANDOVER.R B. WHEELER.R V Affiliation Unknown 80/05/30 ip
- 8007140611 Forwards final rept of technical review of draft 10CFR60, Bubpart E technical criteria DAVIS.S Arizona, Univ of NRC-04-80-217 80/02/20 135pp
- 8007140640 Comments on proposed rule 10CFR20 NRC efforts to revise rule must proceed in concert w/studies performed by other govt agencies
 VILLFORTH.J C HEW.Dept of, US Public Health Service 80/06/23
- 8007:140691 Comments on proposed rule iOCFR20 NRC rediation protection stds should be consistent w/applicable federal guidance & include consideration of work of recognized natl & intl organizations
 8ATES.A Farm Legal TN 80/06/20 16pp
- 8007140695 Comments on proposed rule 10CFRAO radwaste should be categorized by thermal characteristic, as well as radioactive characteristic w/distinction of time period during which media temp increases

 DYER O H Affiliation Unknown 80/06/26 App
- 8007150004 Comments on proposed rule IOCFR20 NRC has not adequately demonstrated need for personnel dosimetry testing & certification program Citing improper use of dosimetry data in apidemiological studies as argument is invalid MOFFITT.A E Bathlehem Steel Corp 80/06/24 IOpp

- 8007130046 Corrects Comment 3 which was miscoded in rulemaking Requests placement of corrected notice in file * Docketing & Services Branch 80/06/30 1p
- B007150051 Corrects Comment 19 which was miscoded in rulemaking Requests placement of corrected notice in file * Docketing & Services Branch B0/06/30 1p
- BOO7150067 Comments on proposed rule IOCFR20 Items B (4) & C (3) should contain ref to soil concentration stds & Item D (7) should also include effluent monitoring DEBOER.T K New York. State of BO/06/18 ip
- 800715006B Comments on proposed rule 10CFR51 Dept of Natural Resources supports requirement that applicants provide notice of intent to tender application for CP J months prior to submittal Reduced duplication & insures coordination # Georgia, State of 80/06/27 2pp
- 8007150070 Comments on proposed rule 10CFR20 cost/benefit equation of added certification regulation should be considered Certification does not guarantee improvement Tosting labs should be established by processors & not under NRC control LINTON.O W Affiliation Unknown 80/06/26 1p
- 8007180072 Comments on proposed rule iOCFR20 program will be large expense for limited benefit Testing is overemphasized Requirements for processors should begin w/committee of experienced experts

 JONES DE Affiliation Unknown 80/06/24 App
- BOO7150077 Comments on proposed rule 10CFR20 supports mandatory processor cortification process.certification by category. establishment of certification board & change in beta exposure testing process DEHART.R H Air Force.Dept of 80/06/26 3pp
- 8007150080 Comments on proposed rule IOCFRRO testing program may cause processors to design dosimeter merely to pass test Program must evaluate processor in intangible areas Accuracy requirements are everly restrictive JACKSON.P G Army.Dept of 80/06/23 3pp
- B0071500B4 Comments on proposed rule 10CFR20 NRC program should permit integration w/similar federal & state programs All elements of certification program should be available to all processors & implementing agencies
 VILLFORTH. J C HEW. Dept of, US Public Health Service 80/06/27
- BOO71500B9 Comments on proposed rule 10CFR50 objects to requirements of Bubpart P to proposed App R No reasonable basis exists for requiring either reactor coolant pump fire suppression system or lube oil components to utilistand SSE VAN BRUNTLE E Arizona Public Service Co 80/06/30 lp
- 8007150075 Comments on proposed rule 10CFR50 concurs w/need for fire safety rules & to upgrade existing facilities Program should not rely on existing NFPA stds NRC should develop new fire codes especially new fire sprinkler codes especially new fire prinkler codes PATTON.R M Affiliation Unknown 80/06/16 9pp
- BOO7180103 Comments on proposed rule 10CFR50 supports proposed regulations Existing fire extinguishers are inferior fire fighting tools Fixed suppression sys for cables should be automatic & primary reliance should be water spray PATTON.R M Affiliation Unknown BO/06/17 2pp
- 8007150104 Comments on proposed rule 10CFR20 should incorporate ICRP-26 W/o exception, provided incorporation would be compatible W/federal acceptable radiation risk policy BUCHHOLZ:R M General Electric Co ANT-16-80 80/06/16 3pp
- 8007180110 Comments on proposed rule 10CFR20 present radiation stds unsafe Federal govt should initiate energy program to promote conservation & renewable energy sources ROMIC.B Affiliation Unknown 80/06/16 lp
- 8007190112 Comments on proposed rule IOC/R30 opposes adoption in present form Daadline of 801101 for implementation is unreasonable Preparation of EIS needed since shutdown would cause adverse consequences to environ by pollution CONNER,T B Affiliation Unknown 80/06/30 4pp
- 8007150116 Comments on proposed rule IOCFR20 specific elements of radiation protection program should be developed in reg guides or other suitable documents Requirements for transportation of radioactive matts already covered by DOT BERNSEN.B A Dechtel Power Corp (subs of Bechtel Corp) RO/06/17 20s

- B007150119 Comments on proposed rule IOCFR50 impact of rule on plants w/acceptable fire protection plan should be investigated Section II.Part A.Paragraph 2f will allow inadequate protection against expusive fires COHN.B M Gage-Babcock Associates, Inc. B0/06/26 2pp
- 8007150122 Comments on proposed rule 10CFR20 for vast majority of individuals, no significant internal exposure is accumulated Reporting of internal exposure should only be required for situations exceeding 40-h control measure

 DISE.D P Niagara Mohawk Power Corp 80/06/17 4pp
- ROO715013J Comments on proposed rule 10CFR5D strongly disagrees w/need for proposed rule Alternative designs should remain acceptable Proposed rule is overly specific [mplementation date of B01101 cannot be met YAWN, A D Georgia Power Co 80/06/27 3pp
- 8007(50134 Comments on proposed rules lOCFR2 & 50 suggests rewording of Paragraph 30 91(b) to reflect const & operation considerations SP & power level increase not relevant to significant herards finding HOFFMAN.D P Consumers Power Co. 80/06/23 1p
- BOO7150140 Comments on progosed rule 10CFRAO geologic setting requirement should indicate detailed investigation necessary to define actual & potential impacts Oradients vary due to thermal conductivisty & boundary condition changes MCGRAY, J G Arizona, Univ of 80/06/26 2pp
- 8007150143 Comments on proposed rule IOCFR50 concerns include applicability, schedule & overall effect on fire protection Rule should not apply to mods resolved in SER issued prior to effective date implementation schodule unreasonable HEIDER, L H Yankee Atomic Electric Co WYC 80-22 80/06/25
- 8007150152 Comments on proposed rule 10CFR50 30-day review period inadequate in light of excessively specific & restrictive requirements Outage time required for mode systematic Cost outweighs benefits Alternate methods not permitted HOWARD.J E Boston Edison Co VP-N 80-69 80/06/27 App
- B00719015B Comments on proposed rule 10CFR90 stds should result in high level of fire safety Quidelines slanted toward use of water for all tire protection problems Fire brigade training ravision suggested BUNSTROM,R F Affiliation Unknown B0/06/R4 2pp
- 8007150166 Comments on proposed rule 10CFR50 manually actuated fire suppression sys should not be specified fire barriers & suppression sys must be inspected to maintain integrity Min fire brigade size questionable MELOTT,R X Affiliation Uninown 80/06/23 3pp
- B007160196 Forwards comments on proposed rule 10CFR50 wording is vague & unenforceable Fire protection terms mentioned in app are improperly used & inadequately explained Comment period of 30 days is insufficient DUNGAN.K # Affiliation Unknown B0/06/19 6pp
- 8007160402 Comments on proposed rule 10CFR70 requests NRC simplify licensing of nuclear pacemakers
 SMYTH:N P D Affiliation Unknown 80/04/29 2pp
- 9007160405 Comments on proposed rule 10CFR61,approach to regulation by performance objectives is highly commendable RODGERS.J. WHEELER.M., DEPUORTER.J. Los Alamos Scientific Laboratory 80/05/14 Opp
- 8007160415 Comments on proposed rule 100FR50 concerned w/subjective nature of many requirements HATHAWAYL R Marsh & McLennan.inc , M & M Nuclear Consultants.Inc Div 80/06/23 4pp
- B007160420 Comments on proposed rule 10CFR50 in general too vague for effective implamentation Significant lack of definitions & usage of many terms
 GDODHIN.C Portland General Electric Co 80/06/27 10pp
- 8007150593 Advises of CPC adoption of EEJ 800707 statement of position re-proposed rulemaking on storage & disposal of radwaste QALLO.J Isham, Lincoln & Beale 80/07/11 1p
- 8007160619 Comments on proposed rules 10CFR2 & 50 concurs w/proposed rule change NRC can make significant hazards determination No public interest is served by requiring 70-day wait before issuing amends of OLS & CPs DALE.L F Mississippi Pawer & Light Co AECH-80/106 80/05/28

- 8007160779 Comments an proposed rule 10tFRAO objects to storing high level nuclear waste in rock formations Hastes should be stored in retrieval storage facilities until genuine disposal method is found MASSERBACH.A & Affiliation Unknown 80/06/11 ip
- 8007170105 Comments on proposed rule 10CFR20 promulgation of major change would be disruptive & not advance cause of occupational radiation safety Licensees should not be required to defend NRC does stats LEHIS.L Duke Power Co 80/06/17 11pp
- B007170179 Forwards I Remson 800518 comments on proposed rule 19CFR60 to BMI Hydrology can perform containment function for period as short as 1,000 yrs Geochemistry provides backup solution to transport problem
 NICHOLSSUNT J Site Safety Standards Branch 80/06/26 5pp
- 8007170491 Comments on proposed rule 10CFR50 on behalf of utils listed in Attachment A Expresses concern that most utils will be unable to meet implementation date being mandated by Commission Pages missing from Comment 8 docketed 800630 KNUTH.D F Kerr-McGee Corp 80/06/27 41pp
- B00721016B Comments on proposed ruls 10CFR50 objects of proposed stds on procedural & substantive grounds General objections concern imadequacy of technical data & justification supporting proposed rules
 KEARNEY.J Edison Electric Institute 80/06/30 28pp
- 8007R10259 Comments on proposed rule 10CFR20 pilot study conducted by Univ of MI does not accurately reflect capabilities of all processors Clerical errors which accurred during study do not reflect performance of commercial processors TODD.WE Affiliation Unknown 80/06/12 Spp
- 8007220093 Comments on proposed rule 100FR50 fixed supression sys for cables should be automatic, not manual & primary Reliance should be placed on water spray Conventional fire sprinkler sys should not be used PATTON, R M, Affiliation Unknown 80/06/17 2pp
- --9007220102 Comments on proposed rule 10CFR50 should not rely overly an existing NFPA stds NRC should establish program to ascertain viability of existing codes & begin to develop new fire rules Vendor fire protection repts encl
 PATYON,R M Affiliation Unknown 80/06/16 9pp
- 8007220439 Comments on proposed rule 10CFR50 to require same spacing of clear air space horizontally & vertically is inconsistent Harizontal spacing of 50 ft is considered very extreme FULLER, J K Public Service Co of Colorado P-80200 80/07/03
- 8007220539 Notice of appearance in proposed rulemaking proceeding re storage & disposal of radwaste Certificate of Syc encl BERGER.R F Oklahoma, Btate of 80/07/09 5pp
- B007230042 Comments on proposed rule 10CFR50 high priority status for adol changes to fire protection programs & design features of existing operating plants uncertain CAHN: A L Bechtel Power Corp (subs of Bechtel Corp) B0/06/27
- H007230044 Comments on proposed rule 10CFR50 overly specific & in present form could force changes reducing safety of plants ZARAKAB:P Consolidated Edison Co of New York B0/06/30 3pp
- B007230147 Comments on proposed rule iOCFR50 proposed rule would not allow for Flexibility or alternatives Regulation should specify requirement & intent of fire protection program CURTIS,N W Pennsylvania Power & Light Co 80/06/27 2pp
- 8007230175 Comments on proposed rule 10CFR50 implementation dates unreasonable & impracticable Fire protection requirements impose financial burden on customers & subvert util earlier compliance efforts
 POINDEXTER.C H Daltimore Gas & Electric Co 80/06/30 16pp
- 8007230181 Comments on proposed rule 10CFR50 insufficient comment period.conflicts could exist re previously approved requirements & value/impact assessment Proposed rule overprescriptive & inadequate
 UHR10.R E Florida Power & Light Co L-80-207 80/06/30 6pp
- 8007230187 Comments on proposed rule 10CFR50 BER documented agreements should not be subj to another review or mod implementation schodule unreasonable Previously approved agreements should not be rescinded PEOPLES, D. L. Commonwealth Edison Co. 80/06/27 7pp

- 8007230193 Comments on proposed rule 10CFR50 requirements impractical & excessive Implementation costs & schedule unrealistic BAYNARD.P Y Florida Power Corp 3-F-2 80/06/27 5pp
- 8007230250 Add1 response to FOIA request for all info re changes to proposed fire protection rule in SECY-80-088 & record of Commission's vote Commissioner Bradford concurrence encl 3ix documents withheld (ref FOIA Exemption 5)
 FELTON.J M Division of Rules and Records 80/07/16 2pp
- ~-8007230236 Notifies that Commissioner Bradford concurs w/revisions in 800416 memo re fire protection rulo (SECY-80-088) Excerpt of rule enci THOMPSON,H L Commission 80/04/21 3pp
- B007230262 Comments on proposed rule iOCFR50 specific fire protection sys imposition will have severe impact on licensees complying w/previously approved programs & will retard implementation PRATT.C M Power Authority of the State of New York 80/06/30 9pp
- B007230583 Forwards affidavit of svc omitted from statement of position of State of MN submitted 800703 QLSON, J F Minnesota, State of 80/07/07 2pp
- BOO7240003 Comments on proposed rule 10CFRBO concurs in comments filed by licensees implementation time insufficient Addl criteria should be identified for redundant sys separation DALTROFF, B L Philadelphia Electric Co 80/06/30 épp
- B007240136 Comments on proposed rule 10CFR30 min fire protection issue should be reopened Arbitrary implementation date unfair
 HDFFHAN, D.P. Consumers Power Co. 80/06/27 Bpp
- 8007240140 Comments on proposed rule 10CFR50 comment period & implementation schedule should be extended Comprehensive value/impact & environ analyses re fire protection should be conducted MCGARRYJ H Debeyoise & Liberman 80/06/30 55pp
- BOO7240145 Comments on proposed rule iOCFR50 rule substantial & unjustified deviation from past rulemaking practices

 Gpecific App R requirements revoke approved alternate approaches Implementation dates arbitrary

 HHITE.L D Rochester Gas & Electric Corp BO/06/27 9pp
- 8007240147 Comments on proposed rule 10CFR61 federal & state govts should stimulate addl low level radwaste disposal site development Supports matabilishing min radioactivity level New & efficient sites should be developed JENNINGS, J Affiliation Unknown 80/07/02 3pg
- 8007240151 Comments on proposed rule 10CFR30 statement that prior agreements w/NRC re fire protection are invalid not reasonable Power plants have expended significant time & money for mods to improve fire protection UTLEY.E E. Carolina Power & Light Co NO-80-1001 80/06/30 8pp
- 8007240357 Comments on proposed rule IOCFR50 30-day comment period not adequate opportunity nor proper machanism for setting forth fire protection provisions Adjudicatory hearing would be preferable PORTER.W L Duke Power Co 80/06/30 App
- 8007240367 Comments on proposed rule 10CFR50 previously accepted fire protection altenatives should continue to be accepted Alternate shutdown capability implementation negates positive mod aspects
 THORPE.J R Denoral Public Utilities QPU Bervice Corp E&L-2534
 80/06/27 9nn
- 8007240375 Comments on proposed rule 10CFR50 opposes proposed rule refire protection because it circumvents reiterated peer review comments & is not directed toward power plant safety enhancement Rule should be withdrawn
 PIELAGE.H W Affiliation Unknown 80/06/28 5pp
- 8007240381 Comments on proposed rule 100FR20 Dept of Commerce Natl Voluntary Accreditation Program is possible alternative for identifying competent testing labs Forwards 800123 FR notice defining personnel dosimetry criteria for accredited labs LOCKE, J W Commerce. Dept of 80/06/27 45pp
- 8007250524 Comments on proposed rule 1905R&O quoting annual rate quantitatively apprear premature Concept of relative risk should be addressed JOHNSON.R E Affiliation Unknown 455R31393 024 80/07/11 ip

- B007250703 Comments on proposed rule 19CFR20 urges NRC to identify scientific & technical info used as basis for rewriting 10CFR20 or terminate agency action re proposed rulemaking LANDNER,R R Dow Chemical CG , Dow Chemical U S A Div 45FR18023 035 80/04/06 2pp
- B007250710 Comments on proposed rule 10CFR20 Financial cost of mandatory dosimetry testing program should be kept as low as possible w/o jeopardizing validity of program HDLDEN-R H Affiliation Unknown 45FR20493 032 80/04/25 5pp
- 8007280007 Comments on proposed rule 10CFR60 NRC should establish criteria & stds for overall age of high level radwaste disposal-rather than defining specific performance values for individual components RDBINSON,R V Exxon Nuclear Co , Inc (subs of Erxon Corp) 45FR21393 015 80/07/11 Jpp
- 8007280016 Forwards comments on proposed rule 100FR60 NRC should establish criteria & stds for overall sys of high level radwaste disposal-rather than defining specific performance values for individual components
 WALSKE.C Atomic Industrial Forum 45FR31393 014 80/07/11 5pp
- 8007280024 Comments on proposed rule 10CFR60 rule represents significant progress toward defining technical criteria for high level wasto repositories Performance of required barriers constitutes sound approach to licensing MENARD. If W. Interior, Dept. of, Geological Survey 45FR31373 012 80/07/10 6pp
- 8007280032 Comments on proposed rules 10CFR2 & 10 requests petition be denied Requirement to conduct informal public bearing in every instance would inhibit improvements in facility design &/or appration by diverting important resources
 OIBBS.D C Atomic Industrial Forum 45FR26071 011 80/07/01 2pg
- 8007280037 Comments on proposed rule 10CFR60 draft technical criteria will provide regulatory means to implement requirements of environ stds EPA will propose in near future HEDEMAN.4 N Environmental Protection Agency 45FR31393 023 80/07/18 3pp
- B0072B0044 Comments on proposed rule 10CFR40 submitted by CA Energy Commission draft technical critoria demonstrate that NRC is aware of issues relevant to repository licensing VARANINI.E E California. State of 45FR31393 022 80/07/14 3pp
- BOO7280052 Comments on proposed rule 10CFR50 rule reflects NRC vacillation After establishing specific fire protection programs. NRC is proposing shift in groundrules Resulting safety benefits are few MCDDNALD. R P Alabama Power Cn 45FR34082 041 BO/06/27 lipp
- 8007280099 Comments on proposed rule 10CFR50 NRC is hampered because original rule did not concentrate on dedicated remote shutdoun capability as solution to fire risk Schedule for completion may be unrealistic CARNEY, J. J. American Nuclear Insurers 45FR36082 040 80/06/30 200
- --8007280067 Comments on draft reg guide. "Qualification Test for Cable Penotration Fire Stops for Use in Nuclear Power Plants " Worst case for generic acceptance is valid method BANYER, G , BORNHOEFT, W H American Nuclear Insurers 79/08/30 200
- 8007280713 Ack receipt of 800214 ltr & petition on behalf of vendor & 17 utils, re NRC proposal for interim emergency planning upgrade repulation Ltr & petition treated as comments on proposed rule Comments will be considered DIRCKS.W.J. Office of the Ejecutive Director for Operations 80/07/14 lp
- 8007280716 Ack receipt of petition for rulemaking on behalf of Duke Power Co.TX Utils & Generating Co & WA Public Power Sys., requesting deferral of promulgation of final rule on proposed emergency plan regulations
 DIRCKS:N J Office of the Executive Director for Operations
 80/07/14 to
- 8007270002 SECY-80-291
 Recommends that Commission approve notice of denial of Petition for Rulemaking 2-9 filed by Union of Concerned Scientists & Natural Resources Defense Council Draft documentation encl
 8HAPARIH K Office of the Executive Legal Director 43FR48621
 80/06/17 15pp

- --8007270005 Forwards petition for rulemaking 2-8 & comments on proposed rule IGCFR21 RDISHANA 2 Natural Resources Defense Council 43FR48621 21
- --B007290012 Petition for rulemaking on amond to 10CFR21, re exempting commercial grade component suppliers from regulation, submitted as comment Safety significance unfounded & inconsistent w/past NRC activities POLLARD, R. Union of Concerned Scientists ROISMAN, A Z. Natural Resources Defense Council 43FR48621 21 79/03/02 14pp
- 8007270235 Forwards quarterly rept on proposed rules for period ending 800430 Rept provides public winfo re NRC rulemaking activities Related FR notice forthcoming FELTON.J M Division of Rules and Records 80/06/24 26pp
- 8007270286 "Security Facility Approval & Safeguarding of Natl Security Info & Restricted Data:" & "Financial Protection Requirements & Indemnity Agreements:" 100F895 & 140 final rule Reflects revised Canal Zone status DIRCKS.W J Office of the Executive Director for Operations 80/05/23 4pp
- 8007290424 Comments on proposed rule 10CFR80 proposed App R re fire protection specific for regulation Regulations should provide policy or statement of position implementation schedule is unrealistic DRAPER.E L Gulf States Utilities Co 45FR36082 045 GO/06/26
- 8007270852 Comments on proposed rule iOCFR20 recommendations of nat1 & intl bodies must be followed Revisions must not be issued until EPA guidance is established Suggests costbanefit study COUMBIL-W 2 Connecticut Yankee Atomic Power Co COUNSIL-W 2 Northeast Nuclear Energy Co (subs of Northeast Utilities). 45FR18023 71 80/06/26 3pp
- BOO729085B Comments on proposed rule 10CFR34 fully supports proposed change
 KOVACS.B Foster Wheeler Corp 45FR39855 003 B0/07/10 1p
- 8007290887 Comments on proposed rule 100FR50 Niagara Hohawk Power Corp andorses comments re fire protection filed on 800630 on of various utils MCGARRY.J M Debevoise & Liberman 45FR36082 052 80/07/14 ip
- 8007290927 Requests that util 790725 comments on "Study of Nuclear Power Plant Const During Adjudication" be considered as comments on proposed rules 10CFR2 & 50 MILLS.L M Tennessee Valley Authority 45FR34279 003 B0/07/02
- 8007300009 Forwards comments on proposed rule 10CFR20 hasty rulemaking may result in adoption of rule before sound certification program has been established Suggestions on establishment of test & certification program included EDWARDS, D W Yankee Atomic Electric Co 45FR20493 020 80/06/26
- B007300014 Comments on proposed rule 10CFH20 supports certification of dosimetry processors Several facets of Health Physics Society Stds Committee/ANSI stds will restrict influence on determination of individual doses
 YODER, R C Battelle Memorial Institute, Pacific Northwest Laboratory 45FR20493 049 60/06/25 19pp
- 8007300018 Comments on proposed rule 10CFR20 strongly supports requiring licensess to use tested & certified personnel dosimetry svc Insting lab should be monitored by NBB PARROTTH W Conference of Radiation Control Program Directors, Inc 45FR20493 048 80707/03 2pp
- B007300027 Comments on proposed rules ICCFR2 & 50 on behalf of Boston Edison Co-Houston Lighting & Power Co & Puget Sound Power & Light Section 2 754 should be reinstated Immediate effectiveness rule should not be amended OARY.F B Lowerstein, Newman, Rais, Axelrad & Toll 45FR34279 008 B0/07/03 3pp
- 8007300032 Comments on proposed rules IOCFR2 & 30 on behalf of utils reimmediate effectiveness rule Fifth option, retention of present sys. should be adopted w/mod + LeBoeuf, Lemh, Leiby & MacRae 45FR34279 006 80/07/07 3pp
- B007300039 Forwards comments on proposed rules 10CFR2 & 50 on behalf of UCS re immediate effectiveness rule Option C.repeal of rule. Is most appropriate action Gross unfairness of rule examplified by Seabrook proceeding. WEISS, E.R. Bheldon, Harmon & Weiss 45FR34279 007 80/07/07 6pp

- 8007300043 Comments on proposed rules 10CFR2 & 50 on behalf of New England Coalition on Nuclear Pollution re immediate effectiveness rule Urges implementation of Option C. total repeal Const should crase during ASLAG proceedings MEISS, E. R. Sheldon, Harmon & Weiss 45 FR34279 004 8D/07/07 7bo
- 8007300049 Comments on proposed rule 10CFR30 endorses EEI comments
 Improvement of previously approved schedules is
 unreasonable Short implementation schedule may limit careful
 consideration of fire safety provisions
 DISE.D P Niagara Mohawk Power Corp 45FR36082 039 80/06/30
- B007300055 Comments on proposed rule 10CFR50 fire protection rule imposes backfitting requirements w/o affording licenses opportunity to legally protect interests Requests withdrawal of App R regulations requiring specific factual bases IRIMBLE.D C Arkansas Fower & Light Co 49FR36082 037 B0/06/30
- 8007300064 Comments on proposed rule 10CFR50 case-by-case review preferable to litgation which would result from proposed rule Addl manpower requirements for fire brigade definitions & potential litigation costs excessive JACCDS.8 B Stone & Hebster Engineering Corp. 45FR36082 038 80/07/07 4pp
- B007300066 Forwards comments on proposed rule iOCFR20 formalizing test procedure may result in processors designing dosimeter to pass test instead of providing best possible dosimeter TARAS, D N Army, Dept of Headquarters Material Development & Readiness Command 45FR20493 047 80/06/24 3pp
- 8007300072 Comments on proposed rule iOCFR50 modifies & voids existing agreements between util & NRC Rule includes new requirements not within scope of original fire hazard analysis & safety evaluation
 MATTINUELY J. Sacramento Municipal Utility District 45FR36082 044
- 8007300081 Forwards comments on proposed rule 10CFRSO requests change not be adopted as written Required completion date is unreasonable Deadline does not consider overall fire protection in existence at facility
 MATTIME, J J Sacramento Municipal Utility District 45FR36082 048 80/07/03 10pp
- 8007300085 Cumments on proposed rule 10CFR50 proposed rule on fire protection too ambiguous to provide desired results Implementation date for new mods & rescinding of previously agreed upon completion dates are unacceptable FAY.C W Wisconsin Electric Power Co. 45FR36082 049 80/06/30 6pp
- 8007300113 PNL-2882
 "Disruptive Event Analysis Valcanism & Igneous Intrusion"
 CROHE,B M Battelle Memorial Institute, Pacific Northwest
 Laboratory II-182 79/10/31 47p
- 8007300141 Comments on proposed rule 10CFR50 App R should be abendoned Overspecification of detailed design & procedural requirements are inappropriate Overspecification voids efforts to upgrade fire protection capability CROUSE.R P Toledo Edison Co 45FR36082 051 80/Q6/30 2pp
- 8007300234 Comments on proposed rule iOCFR50 sound technical bases may not exist to support emergency planning zones noted in rule Fifteen-minute notification requirement is unrealistic Specific comments encl
 CLUBEN.R C Energy.Dept of 45FR75167 203 80/07/09 9pp
- 8007300249 DNHI-18
 "Bummany Characterization & Recommendation of Study Areas
 for Gulf Interior Region"
 * Dattelle Memorial institute III-016 79/05/31. 70pp
- 8007300411 Comments on proposed rule 10CFR73 re-physical protection of irradiated spent fuel in transit unnecessarily duplicative routing requirements may confuse carriers & interfere w/ private competition in shipping industry CUNNINGHAM. O W Energy, Dept of 45FR37399 CO2 80/07/11 2pp
- B007300469 Comments on proposed rules 10CFR2 & 30 only acceptable option is Option E which would retain present sys unchanged. Present sys impacts on decisionmaking felt only w/respect to environ.not safety-related concerns PEOPLES.D L Commonwealth Edison Ca 45FR34279 010 B0/07/07 Ann

- 8007300475 Comments on proposed rules 10(FR2, 19, 20, 21, 30, 40, 51, 40 & 70 on behalf of Americans for Indian Opportunity Part of rules entitled, "Participation by State Govts," should mention Indian tribes
 - HARRIBL Affiliation Unknown 44FR70408 033 80/06/27 ip
- 8007300565 Comments on proposed rule 10CFR34 submitted by Hughes Airwest Supports limiting requirements for retention of records of daily readings of pocket dustmeters No need for retention of records for more than 1 yr MEIER, M O Affiliation Unknown 49FR39856 002 80/07/10 1
- 8007300569 Comments on proposed rules 10CFR2 & 90 Commission stds for granting stays should be relaxed Basic procedures of licensing process, including immediate effectivenes rule, are sound CALLO, J. WILLIAMS, F. C. Public Service Co. of Oklahoma 45FR34279 009 80/07/07 10pp
- BOO7300571 Comments on proposed rules iOCFR50 & 51 strongest regulations possible should be applied to development of any EIS required by NEPA Supports Commissioners Gilmsky & Bradford postition
 CURRY.J B Affiliation Unknown 45FR40101 005 BO/07/03 ip
- 8007300573 Comments on proposed rules 10CFR50 & 51 all nuclear projects where CP has not been issued, should be required to undergo investigation of full range of consequences possible from Class 9 accident
 KEESE, B Texas, State of 45FR40101 006 60/07/18 ip
- 8007310277 Comments on proposed rule 100FR90 implementation schedule for fire protection unreasonable App R should reflect intent of reg guide while allowing flexibility re compliance methods Proposed revisions uncl
 EYLVIA.8 R Virginia Electric & Power Co 49FR96082 043 80/06/30
- BOO7310441 Comments on proposed rules 10CFR2 & 50 present immediate effectiveness rule re const during adjudication should be retained Recommends adoption of Option E re retaining present sys
 WALSKE, C Atomic Industrial Forum 45FR342/9 OIL 80/07/0/ 1p
- --B0D7310445 Comments on "Study of Nuclear Power Plant Const During Adjudication" Immediate affectiveness rule should be retained as it is currently being interpreted & implemented Rule balances reactor const needs & public safety WALSKE, C Atomic Industrial Forum 79/01/30 2pp
- 8007310456 Comments an proposed rules 10CFR2 & 50 Findings 2.5.6.10 & 13 do not present convincing case for change in immediate effectiveness of rule re const during adjudication VAN DRUNT, E E Arizona Public Service Co 45FR34279 012 80/07/10
- 8007310464 Forwards comments on proposed rules 10CFR2 & 50 Seabrook case is no reason to change sym of immediate effectiveness.

 More delay in nuclear licensing process is intolerable Delay is chief weapon of antinucles; movement.

 VANDENBURGH, D. Yankee Atomic Electric Co. 49FR34279 019 80/07/16

PRM PETITION FOR RULEMAKING

- 8007030078 Comments on potition for rulemaking 51-6 Part 51 already contains provision requiring EIS in appropriate cases Guigg petition should be denied because no NRC proposal for major federal action is identified THOMAS.W N Virginia Electric & Power Co 534 80/06/16 App
- 8007030184 Comments on petition for rulemaking 51-6 EIS of use of high burnup nuclear fuel would not be significant NRC review of generic environ analysis aboutd not delay issuance of amends which are conditioned to times when fuel undergoes exposure PARKER.W O Duke Power Co 80/06/13 9pp
- 8007090274 Comments on Citizens Advisory Board of Metropolitan Area Planning Agency petition for rulemaking 2-10 Opposes request due to addl burden on licensing process w/o benefit of procedure effectiveness Present regulations fulfill request COUNBIL.W & Northeast Utilities 810023 80/04/14 3pp
- 8007100077 Comments on petition for rulemaking 2-10 requirement for informal hearing would apply License amend involves no significant safety issue
 VAN BRUNT, C. E. Arijona Public Service Co ANPP-19662 80/06/16

- B007100120 Comments on petition for rulemaking 140-2 by Washington Legal Foundation Proposed rule would substantially increase costs to industry & consumers Price-Anderson approach is best for situation, involving slight chance of diaster POPEO.D J. BENSING.D Affiliation Unknown B0/06/18 App
- 8007100125 Comments on petition for rulemaking 140-2 supports petition Liability insurance should be paid for by stockholders not rate payers EDDLEMAN Affaliation Unknown 80/06/08 Ip
- 8007100126 Comments on petition for relemaking 140-2 by Association of Bar of City of NY Providing only liability insurance would not be in public interest % would jeopardize nuclear power LEDERER.P D. Affiliation Unknown 80/06/18 Spp
- 8007100130 Comments on petition for rulemaking 140-2 endorses axisting rule Petition does not raise policy issues requiring additions ideration Price-Anderson Act & amends inflect Congressional intent NEXON-8 H Commonwealth Edison Co 80/06/13 2pp
- 8007100134 Comments on petition for rulemaking 140-2 defends Price-Anderson Insurance & Indemnity Program by describing backgrounds of program & history of nuclear insurance pools PROOM. B.C. American Nuclear Insurers KELLY. A. Mutual Atomic Energy Liability Underwriters 80/06/13 9pp
- BOD7100290 Comments on potition for rulemaking 2-10 proposed mods to regulations are unneeded detrimental to officiency & contrary to requirements of law Petition should be demied KNOTFS.J B Dobeyoise & Liberman BO706/16 Bpp
- B007100343 Comments on petition for rulemaking 2-10 frequent public hearings of trivial matters would divert mot attention & engineering resources away from plant operations & would be significant drain on licensee & NRC resources
 PEOPLES.D L. Commenwealth Edison Co. 80/06/14 2pp
- B007100345 Comments on petation for rulemaking 2-10 existing rules for formal intervention are sufficient to ensure that persons w/bona fide interests get full opportunity to partiripate in proceedings Cost-henefit aspects compel domail BROCHL,D J. Portland General Electric Lo. 80/06/11 2pp
- 8007100355 Comments on petition for rulemaking 2-10 budgetary & personnel impact on NRC would be significant & would obstruct & delay licensing Proposed changes would not raise quality of public participation or regulatory process PATTERSON, J D Middle South Services, Inc. 60/06/12 2pp
- 8007100357 Comments on petition for rulemaking 51-6 test programs should be developed in reactors at remote sites to evaluate cladding & fuel damage & emission of airborne & liquid afflicents before increasing nuclear fuel assembly burnup GULBRANSEN,E A Fittsburgh. Univ of 80/06/04 2pp
- 8007100359 Comments on petition for rulemaking 2-10 hearings should be nocessary only in cases where licensing or regulatory action roquires EIA Petitioners' concerns are adequately addressed by current regulatory plans
 DIPLAZZA:R P Hestinghouse Electric Corp 80/06/16 2pp
- 8007100366 Comments on petition for relemaking 51-6 better U utilization (less mining & milling) will have positive effect on environ improved assembly designs will result from current extended burnup programs

 CAVANAUGH, W. Arkansas Power & Light Co. 1-160-10 80/06/13 4pp
- 8007100378 Comments on petition for rolemaking 51-6 plans underway to subject high-bornup assemblies from inventory to periodic surveillance to characterize behavior during water pool storage Proposes combination reactor & pool surveillance JOHNSDN.A B Battello Momorsal Institute, Parific Northwest Laboratory 80/06/12 3pp
- BOO7100385 Comments on petition for rulemaking 51-6 high burnup fuel might produce more radinactive gas from reactors & spent fuel pools & produce deteriorated Lladding on spent fuel rods NRC should support petition to require full FIS KRICHIVER.R Affiliation Unknown BO704/16 1p
- BOO7100437 Comments on petition for rulemaking 2-10 on behalf of Detroit Edison Niagara Muhauk PS(of IN Rochester Gas & Electric current NRC practice re public hearings is adequate No amend to regulations is necessary LEBOEUF,R J. LAMB.H R. LITTY.A C LeBoeuf. Lamb, Leiby & MacRaa BO/06/16 App

- 8007110451 Comments on petition for rulemaking 51-6 petition takes statements out of conteit & leaves incorrect implication that greater fission gas releases are projected to occur to environ w/use of high burnup fuel LANG.P M Energy, Dept of SU/06/10 Zpp
- 8007110502 Comments on petition for rulemaking 140-2 since liability insurance provided by nuclear insurance pools is max amount available no change in regulations re financial protection warranted 80000N.T.J. Alabama Power to 80/06/23 ip
- BOO7110509 Comments on patition for rulemaking 140-2 requests
 initiation of rulemaking proceeding to investigate
 possibility of Amending regulations or financial protection
 requirements for nuclear facilities
 UDALL,M K. House of Rep. Interior 's Insular Affairs BO/06/20
- 8007110522 Comments on petition for rulemaking 51-6 since high burnup nuclear fuel program is currently under development & not fully implemented, petition is gremature DIPIAZZA.R P Westinghouse Electric Corp WRD-LA-151 80/06/16
- 8007110529 Connents on petition for rulemaking 51-6 preparation of generic EIS for high burnup nuclear fuel unwarranted Petition should be denied EDHARDS, D. W. Yorkee Atomic Electric Co. MYC 80-21 80/06/20 2pp
- 8007140030 Comments on petition for rulemaking 2-10 requiring formal public hearings for every amend, and & suspension of OL would place immense burden on util 5. NRC MODDY. J H Yankee Atomic Electric Cp. NYC 80-19 80/06/19 2pp
- 8007140047 Comments on petition for rulemaking 140-2 results sought by petitioners are beyond NRC authority unworkable & unwise To advocate mandatory conversion of property insurance to liability insurance is irresponsible MALSKE.C Atomic Industrial Forum 80/06/23 3pp
- 8007i40052 Comments on patition for rulemaking 140-2 NRC should increase amount of primary layer financial protection licensess are required to maintain CHAMBERLAIN WM California, State of 80/06/20 lopp
- BO07140235 Comments on petition for rulemaking 51-6 petition should be denied High burnup fuel should not increase impact on environ since fuel & cladding in pool environ are relatively stable & conditions in fuel storage pool less severe PEOPLES, D. L. Commonwealth Edison Co. 80/06/19 6pp
- 8007140240 Comments on petition for rulemaking 51-6 petition should be denied Developmental program for high burnup fuel not intended to change existing regulatory limits of radioactive release MILLS,L M Tennessee Valley Authority 80/06/19 2pp
- B007140448 Comments on petition for rulemaking 140-2 opposes proposed change Nuclear liability insurance available from American Nuclear Insurers is mat available from private sources at cost to on reasonable terms
 W00DS.T G Arizona Public Service Co 80/06/20 3pp
- B007140410 Comments on petition for rulemaking 20-6 requests 5 minutes during 800115 meeting to present view on occupational radiation exposure stds

 FLEISCHAKER: D 9 Natural Resources Defense Council B0/01/11 5pp
- B007170275 Comments on petition for rulemaking 51-6 much of petition is based on misinterpretation of technical terminology & apparent lack of knowledge of contemporary, worldwide nuclear fuel cycle research
 SHIELDS,R & Affiliation Unknown 80/06/13 4pp
- BO072102/3 Comments on petition for rulemaking 2-10 change could prove counterproductive to public health & safety Establishment of min criteria on intervention should be designed to encourage groups wilegituate interest in proceedings to participate UTLEY.E E Consumers Power Co BO/OA/16 Zpp
- 8007230048 Comments on petition for rulemaking 140-2 rationals for petitioners conclusion that present liability incurance not max insurance available premised on faulty analysis of insurance market

 COUNSIL W 3 Northeast Utilities WGC-80-0-413 80/06/23 2pp
- 8007280187 Comments on petition for relemaking 140~2 strongly urges relemaking to reform Price-Anderson Act BINGHAM. J. Mouse of Rep. 45FR26973 012 80/07/03 Lp.

- 8007290002 SECY-80-291
 Recommends that Commission approve notice of denial of
 Petition for Rulemaking 2-9 filed by Union of Concerned
 Scientists & Natural Resources Defense Council Braft
 documentation encl
 SHAPARIN N Office of the Executive Legal Director 43FR48621
 80/06/17 15pp
- --8007290003 Forwards petition for rulemaking 2-8 & comments on proposed rule 10CFR21
 RDISMAN, A Z Natural Resources Defense Council 43FR48621 31
 79/03/02 10
- --B007290012 Petition for rulemaking on amend to IOCFR21, re exempting commercial grade component suppliers from regulation, submitted as comment Safety significance unfounded & inconsistent w/past NRC activities PDLLARD.R Union of Concerned Scientists ROIBMAN.A Z Natural Resources Defense Council 43FR48621 21 79/03/02 14pp
- BOO7300003 Comments on proposed rule 10CFR51 proposed amends should clarify treatment of existing reactor sites as candidates for addl reactors & whether product or process-oriented review is required
 MILLS, L M Tennessee Valley Authority 45FR24168 027 80/07/09 20p
- 8007300294 Comments on patition for rulemaking 91-6 generic EIS not appropriate re use of high burnup nuclear fuel in commercial nuclear reactors since overall environ impact will be positive Discusses misconceptions in petition TAYLOR, J H Babcock & Wilcox Co 45FR2555/014 80/07/02 4pp
- PROJ PROJECTS PREDOCKET LICENSING
- 8007100192 Forwards corrected version of Exhibit 1 to answers to CA Dept of Water Resources fourth set of interrogatories MEISS,R L. Pacific Gas & Electric Co. 80/06/16 1p
- --8007100;54 Corrected Exhibit 1 to answers to fourth set of interrogatories re reliability calculations * Pacific Gas & Electric Co 80/06/16 23pp
- 8007160671 Advises NRC that proposal to extend LWDR operation was discussed at 241st ACRS meeting ACRS believes it is acceptable to operate reactor core to 24.000 EFPH as proposed PLESSET. M S ACRS ~ Advisory Committee on Reactor Safeguards 80/05/06 200
- B007230075 Requests review of encl final GEIS on U milling Also requests statement of concurrence in those sections contributed by respective ofts Final GEIS has been prepared in response to public comments re draft GEIS W/o encl MARTIN. J B Division of Waste Management 80/07/03 2pp
- B007250440 Forwards Amend 43 to FSAR SCHAPE, A R Hanford Engineering Development Laboratory 80/05/04
- --8007250444 Amend 43 to FSAR

 * Hanford Engineering Development Laboratory 00278 80/06/04
- 8007290039 Ack receipt of 800512 ltr forwarding essay, "Fxcellence in Operations" NRC shares hope that attitude will become general in nuclear field W/o encl NRC to C Eberle ltr DENTON.H R Office of Nuclear Reactor Regulation, Director 80/07/14 tp
- --B007290042 Forwards essay, "Excellence of Operations" from contest inspired by quote in recent Inside NRC newsletter Hopefully philosophy can eventually be general attitude of nuclear field SUMMERS. J. Affiliation Unknown B0/05/12 2pp
- E007290463 Suggests that ANL subcontract w/RAE Corp for Jul-Sept 1980 to finalize App P (radon attenuation models) & App U (radon control cost-benefit analysis) for GEIS

 MARTIN.D E Uranium Recovery Licensing Branch 80/06/18 2pp
- --B007290470 Advises that NRC has no need for further assistance from Stanley Consultants, Inc at present Requests extension of contract until 800730 in case assistance is required for review of finalized matl

 MARTIN, D E Uranium Recovery Licensing Branch 80/06/18 ip

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- 8007210079 Part 21 rept re recall of welding fittings containing J55 grade drill casing matl Armco Steel Co has completed testing of all raw matls in plantiall in-process matl & in-process of checking field complaints & matl returned to Tube Turns HAYDEN, L E Chemtron Corp , Tube Turns Div 80/07/03 3pp
- B007240371 Part 21 rept re defective Atomic Energy of Canada Limited commercial products Models Theratron 40 & 80 & Eldonado 6 & 8 teletherapy units Cause not stated Affected subsystem is radiation field light systems by RIDOUT, E.F. Atomic Energy of Canada, Ltd QA80-7-129 80/07/03 App
- B007250277 Forwards Part 21 rept re Valcor valve Part V52600-554-1, which failed to cycle immediately following sustained period of continuous energization Caused by use of Valves not designed for operating condition BORGO

PT9 LOCER, PART 9 -

- 7812210563 Forwards IE Insp Rept 30-18052/78-01 on 781011 No items of noncompliance noted Insp included exam of activities at Pittsburgh office re radiation safety & compliance w/rules & regulations W/out rept MCCLINTOCK, R O Region i. Philadelphia. Fuel Facility & Materials Bafety Branch 78/10/31 ip
- 8005070523 Ack receipt of 800130 ltr informing NRC of steps taken to correct violations noted in IE Insp 79-01 on 791212 MCCLINTOCK.R O Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 80702/26 ip
- --B005090524 Responds to NRC 800109 ltr re violations noted in IE insp on 791212 Corrective actions discussed infractions w/ technicians involved Classes planned w/all technicians on requirements & restrictions CARMEL, P Rad Services. Inc 80/01/30 ip
- --8005090527 Discusses IE Insp 79-01 om 791212 & forwards notice of violation MCCLINTOCK,R O Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 80/01/09 2pp
- --B005090529 Notice of violation from insp on 791212 Noncompliance noted required radiation surveys not performed on packages received
 - * Region 1. Philadelphie, Office of the Director 80/01/09 2pp
- BOO5290403 Ack receipt of 800421 ltr informing NRC of steps taken to correct violations noted in IE insp of License 37-13129-01 on 800228 CROCKER, H W Region 1. Philadelphia, Office of the Director 80/05/07 ip
- ---8005290607 Responds to NRC 800328 ltr re violations noted in IE insp of License 37-13128-01 on 800228 Corrective actions new procedures will be developed to improve coordination in receipt of incoming radioactive samples KIM. S M Radiation Management Corp 80/04/21 2pp
- --8005290412 Discusses IE insp of License 37-13129-01 on 800228 & forwards notice of violation CROCKER, H W Region 1, Philadolphia, Office of the Director 80/03/28 2pp
- --8005270616 Notice of violation from insp on 800228 Noncompliance noted failure to keep records showing receipt of radioactive samples * Region 1, Philadelphia, Office of the Director 80/03/28 ip

GA999 QUALITY ABBURANCE INSPECTIONS

- B007010015 Ack receipt of B00523 ltr re discrepancy between notice of deviation contained in QA Program Insp Rept 97900340/80-01 & Procedure GAI-021-002 Notice of deviation should have been discussed during exit meeting P
- --8007010029 Discusses discrepancy between notice of deviation & item noted & discussed by WK Kelley during 800422-24 audit & exit interview Procedure @AI-021-002 referenced in notice contains six deficiences Procedures uncl
 MYERS.F 8 Yerway Corp 80/05/23 12pp

- --8007010034 Forwards GA Pingram Insp Rept 99900340/80-01 on 800422-24 & notice of deviation POTAPOVS.U Region 4, Dallas. Vendor Inspection Branch 80/05/08 200
- --800/010039 Notice of deviation from insp on 800422-24
 * Region 4. Dallas. Office of the Director 80/05/06 ip
- --8007010051 GA Program Insp Rept 99900340/80-01 on 800422-24
 Noncompliance noted GA instructions for control of magnetic
 patricle exams did not contain all info specified by ASME
 Codes
 KELLEY,W D , WHITESELL,D E Region 4, Dallas, Vendor Inspection
 Branch 80/05/06 9pp
- 8007010135 Ack receipt of 800422 & 0515 ltrs informing NRC of steps taken to correct violation noted in GA Program Insp Rept 99700384/80-01
 PDTAPOVS.U Region 4. Dallos. Vendor Inspection Branch 80/06/04
- --8007010142 Responds to NRC 800502 ltr requesting add1 info re previous response to Insp Rept 99900384/80-01 Apologizes for error in response due to typing mistake Product audit does exist in GA sys manual HUPPERT.W W Gulf & Western Industries. Inc 80/05/15 2pp
- --8007010147 Ack receipt of 800422 ltm informing NRC of steps taken to correct violation & deviation noted in GA Program Insp Rept 9990384/80-01 Requests addl info POTAPOVS, U Region 4. Dailas, Vendor Inspection Branch 80/05/02 to
- --8007010151 Responds to NRC 800328 ltr re violation & deviation noted in GA Program Insp Rept 99900384/80-01 Corrective actions bulletin re 100FR21 to employees & dealers has been distributed Marking procedures will be updated by 800601 HUPPERT.W W Gulf & Western Industries, Inc 80/04/22 12pp
- ~~8007010154 Forwards QA Program Insp Rept 99900384/80~01 on 800303-07 & notices of violation & deviation POTAPDVB.U Region 4, Dallas, Vendor Inspection Branch B0/03/28 2pp
- --8007010163 Notice of violation from insp on B00303-07
 * Region 4. Dallas. Office of the Director 80/03/26 ip
- --B007010167 Notice of deviation from insp on 800303~07
 * Region 4. Dallas, Office of the Director 80/03/26 App
- --8007010171 GA Program Insp Rept 99900384/80-01 on 800303-07 Noncompliance noted failure to follow 10CFR21 procedures Receiving insp had not been done using sample tables of insp manual FOSTER.W E . HUNNICUTT, D M Region 4. Dallas. Vendor Inspection Process 80/03/26 10pg
- 8007100326 Ack receipt of 800530 Ir informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900048/80-01 POTAPQVS,U Region 4. Dallas, Vendor Inspection Branch 80/06/05
- --8007100330 Responds to NRC 800519 ltr re deviation noteed in QA Program
 Insp Rept 99900048/80-01 Corrective actions will make every
 effort to ensure that audits are conducted on time
 SHAYNE, R W Anchor/Darling
 Industries) 80/05/30 in
- --B007100333 Forwards QA Program Insp Rept 99900049/80-01 on 800421-25 & notice of deviation F0TAPDVB.U Region 4, Dallas. Vendor Inspection Branch 80/05/19
- --8007100336 Notice of deviation from insp on 800421-25 * Region 4, Dallas, Vendor Inspection Branch 80/05/13 ip
- --8007100339 GA Program Insp Rept 99900048/BG-01 on 800421-25
 Noncompliance noted followup corrective actions for audits
 not taken within specified timeFrame
 WHITESELL.P E , HUNTER,V H Region 4, Dallas, Vendor Inspection
 Branch 80/05/13 5pp
- B007140033 Ack receipt of 800530 ltr informing NRC of steps taken to correct deviation noted in 3A Program Insp Rept 9790401/80-01
 PDTAPDVS.U Region 4, Dallas, Vendor Inspection Branch 80/06/12 to

- --8007140037 Responds to NRC 800502 ltr re deviation noted in QA Program Insp Rept 99900401/80-01 Corrective actions all 1980 internal audits have been reviewed & published within 30 days of post-audit conferences
 FTHERIDGE.NR Combustion Engineering, Inc. 80/05/30 3pp
- --B007140039 Forwards GA Program Insp Rept 99900401/B0-01 on 800408-10 & notice of deviation PDTAPOVS.U Region 4, Dalias, Vendor Inspection Branch B0/05/02
- --B007140042 Notice of deviation from insp on B00408-10 * Region 4, Dallas, Vendor Inspection Branch B0/05/01 2pp
- --BOO7140048 GA Program Insp Rept 99900401/80-01 on 800408-10
 Nuncompliance noted audit repts not issued within required
 time & corrective action on previous insp not taken as
 committed
 HALE.C J. PRICKLEY, R H., AGEE, J R. Region 4, Dallas, Vendor
 Inspection Branch 80/03/01 17pp
- BOO7140057 Ack receipt of BOOAOU itr informing NRC of steps taken to correct violation noted in GA Program Insp Rept 970052//Go-Ol POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch BO/O6/11
- --B007140063 Forwards Bechtel response to item of noncompliance noted in GA Program Insp Rept 99900521/80-01 Corrective action initiated however Part 21 evaluation not conducted Requests comments PGTAPOVS.U Region 4. Dailas. Vendor Inspection Branch 80/04/30
- --8007140075 Responds to NRC 800211 ltr re violation noted in QA Program Insp Rept 99900521/80-01 Corrective actions amended 10CFR95(e) rept includes corrective actions & provisions for closed loop actions will be incorporated into procedures CARACU-I R Bechtel Power Corp (subs of Bechtel Corp.) 80/04/08 4pp
- --8007140082 Forwards GA Program Insp Rept 99900521/80-01 on 800107-10 & notice of violation PGTAPOVS, U. Region 4. Dailes. Vendor Inspection Branch 80/02/11
- --8007140087 Notice of violation from insp on 800107-10.
 * Region 4. Dallas. Vendor Inspection Branch 80/02/08 2pp
- ~-B007140088 GA Program Insp Rept 97900521/80-01 on 800107-10 Noncompliance noted design of safety-related components not evaluated HALE.C J. DRICKLEY, R H. DREAUX, D G Region 4. Dailas, Vandor Inspection Branch 80/02/08 12pp
- BOO7160096 Ack receipt of BOO609 ltr informing NRC of steps taken to correct deviation noted in GA Program Imap Rept 99900503/ BO-01 POTAPOVB.U Region 4. Dallas, Vendor Inspection Branch BO/06/17
- --B007160109 Responds to NRC 800507 ltr re deviation noted in QA Program
 Insp Rept 99900903/80-01 Corrective actions mod of drawing
 & spec modified for clarification of design review & check
 process
 HENDRICKSON,T A Burns & Rue Co 80/06/05 7pp
- --8007160115 Forwards QA Program Insp Rept 99900503/80-01 on 800414-18 & notice of deviation POTAPOVS, U. Region 4. Dallas, Vendor Inspection Branch 80/05/07 2pp
- ~-8007160121 Notice of deviation from insp on 800414-18 * Region 4. Dailas, Office of the Director 80/05/06 2pp
- --B007160126 GA Program Insp Rept 99905503/B0-01 on B00414-19
 Nuncompliance noted cortain safety-related calculations
 lacked verification statement & some audits improperly done
 FDX.0 F. BREAUX.D G. HALE.J. Region 4. Dallas, Vendor
 Inspection Branch B0/05/06 9pp
- 8007160133 Forwards GA Program Insp Rept 99900021/80-01 on 800421-24 No honcompliance noted POTAPOVB,U Region 4. Dallas, Vendor Inspection Branch 80/05/01 2no

- --B007160146 GA Program Insp Rept 99900021/B0-01 on 800421-24 No noncompliance noted Major areas inspected heat treatment, nonconformances & corrective action & implementation of 10CFR30,App B criteria BARNES, I, HUNNICUTT, D M Region 4, Dallas, Office of the Director B0/04/30 App
- 8007160190 Forwards GA Program Insp Rept 99900026/80-01 on 800414-18 No noncompliance noted POTAPGVS.U Region 4, Dallas, Vendor Inspection Branch 80/05/14
- --B007160157 GA Program Insp Rept 99900026/B0-01 on B00414-18 No noncompliance noted Major areas inspected implementation of 10CFR50.App B criteria OLLER E : HUNNICUTT.D M Region 4, Dallas, Vendor Inspection Branch 80/04/28 Bpp
- B007160161 Forwards GA Program Insp Rept 99900521/80-02 on 800428-0501 No noncompliance noted POTAFOVS.U Region 4, Dallas, Vendor Inspection Branch B0/05/19 280
- --8007160171 GA Program Insp Rept 99900521/80-02 on 800428-0501 No noncompliance noted Major areas inspected implementation of requirements of 10CFR50. App '0. in area of design inputs & design insp BRICKLEY.R H , AGCE.J R , HALE.C J Region 4. Dallas, Vendor Inspection Branch 80/05/19 9pp
- 8007160177 Ack receipt of 800606 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900104/80-01 POTAPUVS.U Region 4. Dallas. Vendor Inspection Branch 80/06/17
- ---8007160188 Responds to NRC 800507 ltr re deviation noted in GA Program
 Insp Rept 99900104/80-01 Corrective actions welders
 reinstructed re bardfacing
 HYLAND.F B Westinghouse Electric Corp 80/06/06 5pp
- ---B007160193 Forwards GA Program Insp Rept 99900104/80-01 on B00421-25 & notice of deviation PDTAPOVS.U Region 4, Dalles, Vendor Inspection Branch 80/05/07
- ~~8007160202 Notice of deviation from insp on 800421-25 * Region 4. Dallas. Office of the Director 80/05/05 2pp
- --8007160207 (A Program Insp Rept 99900104/80-01 on 800421-25 Noncompliance noted welding performed outside parameters of essential variables ELLEGBHAWL E, HUNNICUTT,D M Region 4. Dallas, Vendor Inspection Branch 80/05/05 App
- B007160393 Ack receipt of B00613 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900001/ B0-01 P0TAPEUVS, U Region 4. Dallas, Vendor Inspection Branch B0/06/18
- --B007160397 Responds to NRC 800513 ltr re deviation noted in QA Program Insp Rept 99900001/80-01 Corrective actions deviated fuel rods in tray tagged as to nonconforming condition BARDCH-C J Babcock & Wilcor Co , Nuclear Material Div 80/06/13 App
- --8007160404 Forwards GA Program Insp Rept 99900001/80-01 on 800429-0502 & notice of deviation POTAFOVS,U Region 4, Dallas, Vendor Inspection Branch 80/05/13 2pp
- --B0071A0408 Notice of deviation from insp on B00429-0502

 * Region 4, Dallas, Vendor Inspection Branch 80/05/09 2pp
- --8007160411 QA Program Insp Rept 99900001/80-01 on 800429-0302 Noncompliance noted 15 fuel rods not properly tagged MCNEILL.W M , WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/05/09 7pp
- 8007210257 Forwards GA Program Insp Rept 99900390/80-01 on 800513-16 No noncompliance noted POTAPDVS.V Region 4. Dallas. Vendor Inspection Branch 80/05/27 200

- --8007210244 GA Program Insp Rept 99900390/80-01 on 800513-14 No noncompliance noted Major areas inspected implementation of 10CFR50. App B including control of nonconformances & corrective actions weld control & audits
 BROWN, R L. WHITESELL, D E Region 4. Dallas, Vendor Inspection Branch 80/05/23 App
- 8007210269 Forwards QA Program Insp Rept 99900289/80-02 on 800505-09 No noncompliance noted POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch 80/05/28 2pp
- --8007210275 GA Program Insp Rept 99900289/80-02 on 800505-09 No moncompliance noted Major areas inspected implementation of 10CFR50.App B & applicable codes % stds & action on previous insp findings
 SUTTON, J W., WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 80/05/21 &pp
- B007210536 Forwards QA Program Insp Rept 99900716/80-01 on B00513 No nencompliance noted FOTAPDVS.U Region 4. Dallas. Vendor Inspection Branch B0/05/29 2pp
- --8007210539 GA Program Insp Rept 99900716/80-01 on 800513 No noncompliance noted Major areas inspected implementation of cause, corrective action & generic considerations re closure problems in NIBD23 fire dampers OLLER, R E . HUNNICUTT. Q M Region 4, Dallas, Vendor Inspection Oranch 80/05/22 5pp
- 8007220136 Ack receipt of BD0623 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900089780-01
 PDTAPOVB,U Region 4, Dallas, Vendor Inspection Branch BD/07/07
- --8007220142 Responds to NRC 800528 lr re deviation noted in GA Program Insp Rept 99900089/80-01 Corrective actions personnel from other depts will be trained to perform internal audits HAN,K Huico, Inc. 80706/23 2pp
- ---B007220145 Forwards GA Program Insp Rept 99900089/80-01 on 800905-08 & notice of deviation FOTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 80/05/28
- --8007220150 Notice of deviation from insp on 800505-08 * Region 4. Dallas, Office of the Director 80/05/27 ip
- --8007220155 GA Program Insp Rept 99900089/80-01 on 800505-0B
 Noncompliance noted dept heads did not include probable
 cause or effective date of corrective action in response to
 adverse findings
 HUNTER,V H., WHITEBELL,D E Region 4, Dallas, Vendor Inspection
 Branch 80/05/27 App
- 8007220182 Ack receipt of 800627 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900325/80-01
 PDTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/07/07

tp

- --B0072201B9 Responds to NRC 800604 ltr re deviation noted in QA Program Insp Rept 99700325/80-01 Corrective actions initialed book for new extruder for all active orders run on that machine Procedures for scheduling shop orders are being written AIRQLA.E Q Brand-Rex Co 800/06/27 3pp
- --BO07220196 Forwards GA Program Insp Rept 99900325/80-01 on 800520-22 & notice of deviation POTAPDV8.V Region 4. Dallas, Vendor Inspection Branch 90/06/04 200
- --8007220202 Notice of deviation from insp on 800520-22 * Region 4, Dallas, Vendor Inspertion Branch 80/06/04 3pp
- --BOO722020B OA Program Insp Rept 99700325/BO-01 on 800520-22
 Noncompliance noted no clear & complete documented instructions for shop urders initiated & no extruding guidelines generated for several tasks in progress HUNNICUTI, D M . FOSTER, W t Region 4, Dallas, Vendor Inspection Branch 80/06/04 7pp
- 800723013B Forwards comments to be incorporated in D&H procedures implementing iOCFR21 Remaining actions stated in 800520 ltr re safety matters appear to be adequate Addl verfication of proper implementation will be undertaken BTELLO.V Office of Inspection & Enforcement, Office of the Director 80/07/09 3pp

- 0007230153 Ack receipt of 800619 ltr informing NRC of steps taken to torrect deviation noted in GA Program Insp Rept 99900507/80-01
 POTAPOVS.U. Region 4. Dallas Vendor Inspection Branch 80/07/02
- ---B007230160 Responds to NRC 800522 ltr re deviation noted in GA Program Insp Rept 97900507/80-01 Corrective actions due to other commitments.corrective action will be delaged until 800701 MCFARLAND. J E Sargent ', Lundy Inc 80/06/19 1p
- 8007250052 Ack receipt of 800522 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900036/80-01
 POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 80/06/10 to
- --8007250097 Responds to NRC 800424 itr re deviation noted in GA Program Insp Rept 99900036/80-01 Corrective actions personnel & supervisors have been reinstructed re importance of weld math segregation BATES.B J. MILLER.L C. STONE.W A Combustion Engineering, Inc 80/05/22 Spp
- --B007250095 Forwards GA Program Insp Rept 99900036/B0-01 on 800407-11 & notice of deviation POTAPDV9.U Region 4. Dallas, Vendor Inspection Branch 80/04/24 20n
- ---8007250100 Notice of deviation from insp on 800407-11 * Region 4. Dallas, Office of the Director 80/04/23 3p;
- --8007250109 GA Frogram Insp Rept 99900036/80-01 on E00407-11
 Nuncompliance noted signoff on certain shop traveler was not
 in accordance w/Criterion 5 of 10CFR50
 BARNES, 1. ELLERSHAW.L C., HUNNICUTT.D M Region 4, Dallos, Vendor
 Inspection Branch 80/04/23 15pp
- 8007250184 Forwards GA Program Insp Rept 99900713/80-01 on 800429-30 No noncompliance noted POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch BO/05/14 2pp
- B007290582 Ack receipt of 800620 ltr informing NRC of staps taken to correct deviation noted in OA Program Insp Rept 99700398/80-01 POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch B0/06/26 in
- --8007290587 Responds to NRC 800522 ltr re deviation noted in GA Program
 Insp Rept 99900398/80-01 Corrective actions revised Section
 1 4.1ssue A of product design engineering manual to conform
 w/current practices
 CONNELLY,D 0 General Electric Co 80/06/20 App
- --8007250589 Forwards GA Program Insp Rept 99900398/80-01 on 800505-09 & notice of deviation PDTAPOVS.V Region 4, Bailas, Vendor Inspection Branch 80/05/22
- --B007250592 Notice of deviation from insp on B00505-09
 * Region 4. Dallas, Office of the Director 80/05/20 2pp
- ~8007250594 On Program Insp Rept 9990039B/80-01 on BC0505-09
 Nancompliance noted practices not consistent w/Criterion 5,
 App B to 10CFR50 & Section 1 4 Issue A of product design
 engineering manual
 HUNNICUTI.D M , FOBTER.W E Region 4, Dallas, Vendor Inspection
 Branch BENNETT.A B Region 4, Dallas, Office of the Director
 BO/05/20 9pp
- 80072800B5 Forwards QA Program Insp Rept 97900519/B0-01 on B00324-2B No noncompliance noted POTAPOVS.U Region 4, Dallas. Vendor Inspection Branch B0/04/29 2pp
- ~~B0072800B8 GA Program Insp Rept 99900519/60-01 on 800324-28 No noncompliance noted Major areas inspected design insp, potential IOCFR21 items & action on previous insp findings BRICKLEY,R H. AGEE. J R. HALE. C J Region 4. Dallas. Vendor Inspection Granch 80/04/24 21pp

- B007270030 Forwards Volgenau 780428 itr to Gore & SECY-79-4488.cmitted from V Steilo 800709 itr W/o encl PERANICH.H W Division of Reactor Construction Inspection 8007047 to
- 8007270307 Forwards GA Program insp Rept 79700404/80-01 on 800121-24 No noncompliance noted POTAPOVS: V Region 4. Dallas Vendor Inspection Franch 80/06/06
- --B007290321 GA Program Insp Rept 99900404/B0-01 on B00121-24 No noncompliance noted Major areas inspected review of procedures & controls adopted to implement requirements of IOCFR21 ANDERSON, D G . BRICKLEY.R H . HALE.C J Region 4. Dallas. Vendor Inspection Branch 80/06/06 17pp
- B007290327 Forwards GA Program Insp Rept 99700404/B0-02 on 800512-16 No noncompliance nated POTAPOVS U Region 4. Dallas, Vendor Inspection Branch B0/04/03 Zep
- --8007290337 GA Fragram Insp Rept 99900404/80-02 on 800312-16 No noncompliance noted Major areas inspected design corrective action.interfaces & inputs BRICKLEY.R H. AGEE.J R. HALE.C J Region 4, Dallas, Vendor Inspection Branch 80/06/04 lopp
- B007290398 Ack receipt of B00508 & 0707 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 79900216760-01 POTAPOVS.U Region 4. Dallus. Vendor Inspection Branch 80/07/21
- ~-B007290368 Responds to NRC R00617 Itr re deviation noted in GA Program Insp Rept 9990216/80-01 Corrective actions Procedure H-306, available in fraft form during insp.was completed & distributed to personnel involved KATZ.L Tubeco. Inc 80/07/07 2pp
- --8007290378 Ack receipt of 800508 itr informing NRC of steps taken to correct deviation noted in OA Program insp Rept 99900216/80-01 Addl info requested re Item H PUTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/06/17 to
- ~-8007290392 Responds to NRC 800414 ltr re deviation noted in GA Program Insp Rept 99900216/80-01 Corrective actions area of pipe attachment was ground to depth sufficient to remove possible contamination & examined by liquid penetrant GOLDSHITH.W Tubeco, Inc. 80/05/08 15pp
- 8007290474 Ack receipt of 800415 & 0515 ltrs informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 979900355/80-01 PGTAPGVS.U Region 4. Dallas, Vendor Inspection Branch 80/06/06
- --B007290477 Responds to NRC 800429 ltr re deviations noted in GA Program
 Insp Rept 99900355/80-01 Corrective actions GA manager
 assigned responsibility for effectiveness of personnel
 training & inductrination re calibr program requirements
 HIRATA.Y Hirata Valve Industry Co . Ltd . Kawaski Div SH-360
 80/05/15 lp
- --B007290481 Act receipt of B00415 ltr in response to NRC B00322 ltr Requests addition relations taken to assure effectiveness of personnel training & inductionation recontinued compliance w/calibr program POTAPOVS.U Region 4. Dallas. Vendor Inspection Dranch B0/04/29
- --B007290487 Forwards response to NRC B00222 Itr re deviations noted in GA Program Intel Rept 99900395/80-01 Corrective actions GA program for culibr control procedure for targue wrenches has been revised HIRATA.V Hirata Valve Industry Co . Ltd , Kawaski Div SH-359 80/04/15 10pp
- --8007290492 Forwards GA Program Insp Rept 99900355/80-01 on 800121-25 & notice of deviation SEYFRIT.K V Region 4. Dallas. Office of the Director 80/02/22 2pp
- ---8007290497 Notice of deviation from insp on 800121-25 * Region 4. Dallas, Office of the Director 80/02/21 3pp

- --8007290504 GA Program Insp Rept 99900355/80-01 on 800121-25
 Noncompliance noted revised welding procedure spec not
 submitted to customer for approval GA program not in
 accordance w/code requirements
 BARNES I. HUNNICUTT, D M Region 4, Dallas, Vendor Inspection
 Branch 80/02/21 13pp
- 8007270836 Forwards GA Program Insp Rept 79700316/80-01 on 800528-30 No noncompliance noted FOTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 80/06/11 200
- --80072708A2 GA Program Insp Rept 99900316/80-01 on 800528-30 Major areas inspected action on previous findings nonconformances & corrective action trainings records & procurement controls OLLER, R E . POTAPOVS. U Region 4, Dallas, Vendor Inspection Branch 80/06/12 7ns
- B007300173 Ack receipt of 800516 & 0709 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900712/80-01 POTAPOVS,U Region 4: Dallas, Vendor Inspection Branch 80/07/17 ip
- -- 8007300178 Responds to NRC 800611 ltr re deviation noted in QA Program Insp Rept 99700712/80-01 Corrective actions internal audit forms revised to include all depts Certified matl test repts obtained for 10 spoals of wold wire in question CAPRA.L A Bystems Control, Inc. 80/07/09 6pp
- --R007300182 Ack receipt of 800516 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 9900712/BO-O1 Requests add1 info re actions taken to prevent exclusion of any dept from twice yearly audits, POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/06/11
- --8007300188 Responds to NRC 800414 ltr re deviations noted in QA Program Insp Rept 99900712/80-01 Corrective actions all certification on welding matis shall be obtained prior to releasing to shop Current frauding policy is boing revised CAPRALL A Systems Control, Inc 80/05/16 28p
- --8007300192 Forwards QA Program Insp Rept 99700712/80-01 on 800325-26 & notice of deviation POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 80/04/14 2pp
- --8007300194 Notice of deviation from insp on 800323-24 • Region 4. Dallas. Office of the Director 80/04/11 App
- --80073G0198 GA Program Insp Rept 99900712/80-01 on 800325-26
 Noncompliance noted failure to conduct internal audits of
 all depts & to have available certifications for weld wire
 issued to shop
 ELLERSHAW, L E . HUNNICUTT, D M Region 4, Dallas, Vendor Inspection
 Branch 80/04/11 ijpp
- 6007300308 Ack receipt of 800709 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700214/80-01 POTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 80/07/21
- --8007300315 Provides followup to 800509 ltr re deviation noted in GA Program Insp Rept 99900214/80-01 Forwards quality procedure directives re training program for nuclear product quality & visual Insp ac welds pDNEGAN. C C Anderson-Greenwood & Co 80/07/09 13pp
- B007300310 Forwards GA Program Insp Rept 99900209/80-01 on B00506-09 No noncompliance noted POTAPOVS, U Region 4, Dallas. Vendor Inspection Branch 80/06/04 2pp
- --B007300314 QA Program Insp Rept 99900209/B0-01 on B00306-09 Major areas inspected previous insp findings & identified problem areas ELLERSHAW. E . PUTAFOVS. V Region 4, Dallas, Vendor Inspection B7006/04 bpp
- 8007310174 Ack receipt of 800219 & 0425 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900039/79-02 POTAPOVS, U Region 4. Dallas, Vendor Inspection Branch, 80/06/10 lp

- --8007310179 Responds to NRC B00324 ltr re deviation noted in QA Program Insp Rept 9990039779-02 Corrective actions error in sketch requirement was result of human crior, corrective actions not possible QA manual modified SLUIS, B J , VAN DE POLL W N Rhine-Scholds-Verolme Zware Apparatenbouw KD B0019 80704/25 2pp
- --8007310176 Ack receipt of BODR19 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900039/79-02 Requests addl info PUTAPOVS.U Region 4, Dallas. Vendor Inspection Branch 80/03/24
- --B007310182 Responds to NRC 800114 ltr re deviation noted in GA Program Insp Rept 99900039/79-02 Corrective actions missing revision numbers on master travelers filled in & design review of stress repts will be conducted LODDER.M Rhine-Schelde-Verolme Zware Apparatenbouw KD 80013-80/02/19
- --B007310188 Forwards GA Program Insp Rept 99900039/79-02 on 791105-08 & notice of deviation POTAPDVS, U Region 4, Dallas, Vendor Inspection Branch 80/01/14 Pon
- --B007310189 Notice of deviation from insp on 791105-08 * Region 4, Dallas, Office of the Director 80/01/11 2pp
- --8007310195 GA Program Insp Rept 99900039/79-02 on 791105-08
 Noncompliance noted failure to include process spec revision
 number on master traveler & incorrect definition of test
 specimen depth from forging surface recorded
 BARNES, I. POTAPOVS, U. HUNNICUTT, D. M. Region 4, Dallas, Vendor
 Inspection Branch 80/01/11 10pp

REQULATORY GUIDES

r

- 7909210176 Comments on proposed revision to Reg Guides 5 7,5 14,5 44 & 5 57 one person adequate as observer of offloading & opening of metls & parkages as long as second employee present Specified califor stds should be permitted NILSON, R Exxon Nuclear Co , Inc (subs of Exxon Corp) 79/08/02 7nn
- 8007010308 Forwards FR notice of issuance & availability of draft reg guide. "Instruction Concerning Risk From Occupational Radiation Exposure " Requests publication at earliest possible date CHILK, S J Diffice of the Secretary of the Commission 80/05/22
- BOO7020118 Communts on Reg Guide 1 125, "Physical Models for Design & Operation of Hydraulic Structures & Sys for Nuclear Power Plants" portions exist which applicants may not be able to follow LEX.B L Bechtel Power Corp (subs of Bechtel Corp) 77/09/30
- BOO7090395 Comments on proposed Reg Guide B XX guide would be valuable assist to operating personnel Minor reorganization would improve usefulness Presentation as currently organized may scare potential worker off before understanding situation HAMPBON.D C Oak Ridge National Laboratory 90/06/11 1p
- 8007090398 Comments on proposed Reg Guide 8 XX dissemination of info should be considered prior to employment to minimize difficulties of Question 31 Same program to inform local citizens would be appropriate for guide NELSON, R R Firex Corp 80/06/11 ip
- 9007090400 Comments on proposed Reg Guide 8 XX statement that estimates of radiation risks are as reliable as estimates from any other important hazard is patently false People should be made aware of different views of highly qualified experts CHILDERS.8 Affiliation Unknown 80/05/29 ip
- B007090408 Forwards rept commenting on proposed Reg Quide i 97 Comments by students do not represent opinion of faculty Increasing amount of info reactor operator must know during accident is not beneficial Computers should be considered SAVAGE.M R , MILLER.D W Obio State Univ 80/05/09 159pp
- B007090413 Comments on proposed Reg Guide B 14 response of Tracy Etch devices should be determined in environ where used Power reactor health personnel should be required to make spectra measurements & calculate response of survey meter RYAN.R M Rensselaer Polytechnic Inst B0/06/02 2pp

- 9007090416 Comments on proportd Ring Guide 8 XX NRC has obligation to present controversy on both sides relies estimates Info is presently stated in one-sided manner Guide is necessary step in right direction EVDDXIMOFF, V N Boston Univ Medical Center Boston, MA 80/06/10 is
- G00709041B Comments on proposed Reg Guide B XX mention of genetic effects should be deleted since data shows no effect & Fear serves no useful purpose Risk instructions seem unnecessary when patients are not advised during x-ray procedures CDRNELL D A Principla College 80/06/03 ip
- 8007100053 Comments on proposed Rey Guide 8 XX NRC regulation of 40 mps-hr/wk is legal requirement that bears no relationship to dose received for most radionuclides HEALY, J William Alamos Scientific Laboratory HH-32 80/06/04 200
- 8007100101 Comments on proposed Reg Guide 8 XX sufficient emphasis should be plut on fact that levels of exposure resulting in detectable offects are higher, by orders of magnitude, than doses allowed by current regulation or actually received BAYNARD, P Y Florida Power Corp 80/06/11 2pp
- 8007100113 Comments on proposed Reg Guide 8 XX some discussion on public perception of risk should be incorporated People need to be shown that perception of nuclear risk is greater than threat FORD.C H Reuter-Stokes. Inc 80/06/10 2pp
- 8007100116 Comments on proposed Reg Guide 8 XX cigarette smoke & natural radiation are lumped together as cancer causes, implying relatively equal magnitude Such statements are misleading & detract from realistic evaluation of risk TUMA:A T Popular Bluff Hosp Popular Bluff:MO 80/06/03 2pp
- 8007100122 Comments on proposed Reg Guide 8 XX word "generally" should be added to Question 14 Evidence exists to support hady repair especially at low levels of exposure & for large numbers of people exposed DRABTER, J J Affiliation Unknown 80/06/03 10pp
- BOO7100127 Comments on proposed Reg Guide B XX guide fills vital need of supplying sober-accurate 4 comparative data re risks of life work Reasonable charge to users would not be out of line Highly recommends policy LUND, R R Memorial Hosp of Natrona County Casper, WY BO/OA/10
- B007100133 Comments on proposed Reg Guide B XX prudence of zero threshold should be presented anoner w/some explanation of controversy about assumption Argument presented on medical vs occupational exposure dilemma is weak PRIES.B A Chevron Research Cu 80/06/17 ip
- 8007100135 Comments on proposed Reg Guide B XX Question 24, Answer(C), should be eliminated entirely Effect of paragraph will be to touch off another series of attempts to force women out of nuclear industry

 HEGNER. M S General Electric Co 80/06/03 3pp
- B007100137 Comments on proposed Reg Quide 8 XX extending analysis to future generations may result in substantial long-range damage Question 4 should draw distinction between procreating & nonprucreating workers
 KRAMER.P B Williams College, Massachusetts B0/06/11 2pp
- 8007100170 Forwards comments on proposed Reg Guide & XX clearly written & superior to instruction classes on radiation effects
 Bibliographic data should be given for "independent study"
 BDELDT,E J Affiliation Unknown 80/06/17 4pp
- 8007100181 Comments on proposed Reg Guide 8 XX total body radiation should never occur other than for that done by chiropracters, etc Presentation should be reversed to prevent individuals becoming overly frightened HENRY. G W Affiliation Unknown 80/05/29 2pp
- B007100196 Comments on proposed Reg Guide 8 XX instructional sheets will be very helpful in trying to explain risks of radiation to personnel Table 2 is especially valuable in relating risks to other necessary things in life

 BERKEBILE, R D Elyria Memorial Hosp Elyria, GH 80/06/12 ip
- B007100386 Comments on proposed Revision 1 to Reg Guide 1 131 in implementation of ongoing qualification programs, environ conditions of cables that will be used for subsequent tests should be monitored & documented BASKIN, K P Southern California Edison Co 80/05/30 2pp

- B007100416 Comments on proposed Reg Guide 8 XX good attempt to instruct occupational radiation workers but entire field of medical occupational radiation exposure has not been addressed properly RANDOLL H G St Elizabeth Hosp Appleton. HI NRC 80/05/27 1p
- RANDALLI (F W
- BOO7100425 Comments on proposed Reg Guide 8 XX guide should mention that NRC licensees presently are not required to provide neutron dosimeters for workers 5 that mai dose does not reflect exposure which worker may also experience DREV.L A Affiliation Unknown BO/05/30 1p
- BOO7100427 Comments by Rio Algom Corp.Lisbon Mine.on proposed Reg Guide B XX info is greatly needed not only for workern but general public Supports NRC in introducing info in form of reg guide LAMTON.M D Affiliation Unknown 80/06/02 2pp
- BOO7100434 Comments on proposed Reg Guide B XX draft is well written, concise & comprehensive enough for general instruction of radiation workers Should include difference in effects of whole-body or critical organ dose & partial body dose QRANLUND.R W Pennsylvania State Univ 80/06/04 ip
- 8007140475 Comments on proposed Reg Guide 8 XX to eliminate wide-spread irrational fear on part of public info re nuclear sys & policies should be disseminated CHAPIN.D Smithsunian Institute 80/06/12 2pp
- BO07140483 Comments on proposed reg guide, "Instruction Concerning Risk from Occupational Radiation Exposure" Population base in Tables 2 & 3 does not include estimated number of days of lost life expectancy CEMBER, Northwestern Univ 80/06/26 ip
- BOO7140572 Comments on possible use of util load dispatch microwave links to insure communication between NRC & plant & role of Reg Guide 1 97 in determining safety vector IE developing list of util load dispatcher telephone numbers DENTON: AR Office of Nuclear Reactor Regulation. Director BQ/07/01 2pp
- --B007140578 Draft specs. "Functional Requirement for Safety Parameter Display Technical Support Ctr Emergency Offsite Facility Nuclear Data Link " * Commission 80/06/07 30pp
- 8007140586 Comments on proposed Reg Guide 4 14.Revision 1 introduction needs clarification Respondent does not understand what kind of environ impact NRC expects after decommissioning at U mills HASHINOTO, K Affiliation Unknown 80/06/09 ip
- 8007150085 Comments on Reg Guide 1 97.Revision 2 original choice of fission chamber was prodent 8F3 & 810 detectors inadequate for measuring neutron sensitivity LINGREN.C L. Affiliation Unknown 80/06/21 2pp
- 8007150153 Comments on proposed Reg Guide 4 14.Revision i NRC a priori assumptions that radiation protection programs designed for man are adequate for wildlisfe are unfounded Proposes assures to monitor wildlife DANIELEON.L J National Wildlife Federation 80/06/18 5pp
- BOO7150159 Comments on proposed Reg Quide 4 14,Revision 1 environ data units should be appropriate for control level ref. effluent & environ monitoring data should be appraised & drinking water monitoring requirements are unreasonable MOGNEY.R R . PETERSON, D S Washington, State of 80/06/24 2pp
- 8007150342 Comments on draft reg guide, "Instructions Concerning Risk from Occupational Radiation Exposure" Guestion & answer format unsatisfactory More complete presentation could be made in shorter test by avoiding leading questions SLABACK.L A Defense, Dept of. Defense Nuclear Agency 80/06/17 50e.
- 8007160446 Comments on proposed Reg Guide 7 XX, "Measurement of Radiation Levels on Surfaces of Packages of Radioactive Hatis "Surface dose rate should be redefined as that when geiger tube of survey meter touches package surface FRIES.8 A Catalytic, Inc (subs of Air Products & Chemicals, Inc.) 80/06/13 2pp
- 8007160798 Comment» on proposed Reg Guide 1 08 re selection & training of nuclear plant personnel qualifications needed in plant personnel underestimated Operators should meet airline pilot level requirements WILLIS:CA Philippines 79/06/11 10

- B007160805 Offers no comments on Reg Guide 4 16: "Effluent Monitoring at Nuclear Fuel Processing & Fabrication Plants," in response to 800522 memo KNIGHTON.Q W. Research & Standards Coordination Branch 80/06/19
- --8007160814 Summary of 800528 meeting w/C~E owners group in Dethesda.ND re tradequate core cooling List of attendees & viewgraphs encl
 PHILLIPS, L E Care Performence Branch 80/06/23 31pp
- 8007180174 Responds to request for concurrence re Reg Guide 1 141, Revision 1. "Containment Isolation Provisions for Fluid Sys " Regulatory position section of guide satisfactory Should not designate implementation on case-by-case basis DENTON.H R DFfice of Nuclear Reactor Regulation. Director 80/07/03 4pp
- ~-8007180179 Responds to HM Morrison 800417 memo re Rag Guide i 141.
 "Containment Isolation Provisions for Fluid Bys " Approval
 w/comments recommended Guide should be updated to reflect
 latest version of ANSI/ANS 56 2 when available
 BUTLER:W R Containment Systems Branch 80/05/08 2pp
- 8007:80175 Comments on proposed Revision 1 to Reg Guide 8 12 concurs w/ guide position that dosimetry requirements can generally be met by quick screening techniques SHITH.DR Los Alamos Scientific Laboratory Q-14-18-C8-76, 80/06/19 2pp
- 8007180230 Comments on proposed Reg Quide B XX. "Instructions re Risk from Occupational Radiation Exposure" Approach to risk snalysis & training fails in its mission to educate Identifies style.content.emphasis & syntax problems ANDREMS.J P Catalytic, Inc (subs of Air Products & Chemicals. Inc.) 80/06/19 4pp
- BOD7240475 Comments on fire protection Reg Guide i 120 excess automation may present hazards greater than fire Flooding & collapse of trays may be serious. Hater resistance of aged dry cables unknown EBERBOLE. J. C. ACRS Advisory Committee on Reactor Bafeguards 76/08/16 2pp
- 8007250060 Responds to 800701 request for clarification re use of Level I personnel to perform direct insps Level I personnel may perform tests using approved procedures Level II personnel can evaluate & rept test results MAASS, W.P. Guality Assurance Branch 80/07/16 lp
- B007280059 Comments on proposed rul# 10CFRBO NRC is hampered because original rule did not concentrate on dedicated remote shutdown capability as solution to fire risk Schedule for completion may be unrualistic CARNEYLJ J American Nuclear Insurers 45FR36082 040 80/06/30
- --B007280067 Comments on draft reg guide. "Qualification Test for Cable Penetration Fire Stops for Use in Nuclear Power Plants " Worst case for generic acceptance is valid method SAMYER,R G . BDRNHOEFT,W H American Nuclear Insurers 79/08/30
- 8007310120 Notice of issuance & availability of Revision 1 to Reg Quide 5 57. "Shipping & Receiving Control of Strategic BNM," incorporating recent changes to Commission physical protection regulations SMITH.R 0 Office of Standards Development. Director. B0/07/08
- RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS
- BD05130445 "LWR Thermal Hydraulic Development Program," munthly highlight ltr for Feb 1980 JONES,O C Brookhaven National Laboratory FIN A-3045 B0/02/29
- BOO70200ii "Nuclear Power Plant Design Concepts for Bebotage Protection," fifth quarterly progress rept.Apr.June 1979 ERICSON.D M Sandia Laboratories FIN A-1210 79/08/20 lipp
- 8007020016 "Experimental Criticality Data for Code Validation." informal monthly progress rept for May 1980 BIERMAN S R Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2094 80/06/02 Spp

- B0070200B5 "Vapor Source Distribution Electrically Heated Vol-Boiling Bys." to be presented at B00813-15 ASME Century 2 meeting symposium on polyphase flow & transport technology OlNSBERG. T Brookhaven National Laboratory BNL-NUREG-27461 B0/05/15 12pp
- 8007020356 "Safeguards Analysis for Byproduct Matls & Small Quantities of SNN," monthly progress rept Mar 1980 CHESTER,R D , KANAK,K K , RANDQLPH.M L Dak Ridge National Laboratory FIN B-6108 DRNL/HASRD-75 B0/04/14 Opp
- 8007020364 "Shutdown Heat Removal Sys Reliability in Thermal Reactors " SUN,Y H , BARI,R A Strockhaven National Laboratory BNL-NUREG-27595 80/06/30 8pp
- BQ07030015 "Code Assessment & Applications Program Piping Sys Stress Dependent Damping Study " GRUBER L EG&G Idaho.Inc FIN A-6156 79/10/31 20pp
- B007110148 "Physical Protection of Nuclear Facilities," monthly progress rept for May 1980 CHAPMAN.L D. Sandia Laboratories FIN A-1060 80/06/18 6pp
- 8007110591 "Bandia Core Melt & Separate Effects Program," monthly ltr for May 1980 BERMAN,M Sandia Laboratories 80/06/23 8pp
- B007140031 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for May 1980
 HDLQHAY.C F. DICKSON.H W Oak Ridge National Laboratory FIN A-9085-7 GRNL/HASRO-81 B0/05/31 18pp
- BO07140044 "Safeguards Analysis for Byproduct Matls & Small Quantities of BMM," monthly progress rept for May 1980 CHESTER.R O , KANAK, K & RANDQLPH.M L Dak Ridge National Laboratory FIN B-6108 QRNL/HASRD-82 BO/06/11 App
- BO07140503 "Environ Statements Project," monthly progress rept for May 1980 ZITTEL.H E Oak Ridge National Laboratory FIN 8-0001 ORNL/ED/EIS-131 80/05/31 Spp
- 8007140507 "Div of Reactor Safety Research ORNL Programs." May 1980 monthly highlights
 MYNATTIF R Oak Ridge National Laboratory 80/06/10 36pp
- BO07140634 "Technology & Costs of Termination Surveys Associated H/Decommissioning Nuclear Facilities," monthly progress rept for May 1980 DICKBON.H W , MOLONAY.C F Dak Ridge National Laboratory FIN A-9042 ORNL/HABRD-B3 BO/05/31 Spp
- BOO7140642 "Investigation of Post-CHF Heat Transfer for Water-Cooled Reactor Application & Development of Two-Phase Flow Instrumentation." monthly progress rept for May 1780 CHEN.J C , SUNDARM,R K , NIJHAWAN.S Lehigh Univ FIN A-4055 NRC-04-74-180 BO/06/17 App
- B007180016 "Advanced Instrumentation for Reflood Studies," foreign trip rept HERBKOUITZ,M B , MCCOLLOUGH,N D , ROBERTS,M J Dak Ridge National Laboratory FIN 8-0413 ORNL/FTR-850 B0/06/05 7pp
- 8007190059 "Licensing Audit Calculation (LACE) Models in FRAP-T4 Code Description & Developmental Assessment," interim rept for Apr 1980 BDHN, M P., BIEFKEN, L. J., LDATS, E.T. EG&G Idaho, Inc. FIN A-6050 EGG-CDAP-5144 80/04/30 202pp
- 8007150066 89007150066
 "Effect of Dispersed Condensed Phase on Rayleigh-Taylor
 Instability of Gas-Liquid Interface," informal rept,
 Ham 1980
 HGGZYNSKI,J R , GINSBERG,T Brookhaven National Laboratory FIN
 A-3024 80/03/31 41pp
- B007150407 "BWR Blowdown/ECC Program Fifty-Fifth Monthly Progress
 Repte" Hay 1980
 BURNETTE, G W General Electric Co NRC-04-74-215 80/05/31 92pp
- 8007150409 "Guick-Look Rept on LOFT Nuclear Experiment L6-5."

 Experiment data presentation rept

 REEDER, D. L. EG&G Idaho, Inc. FIN A-6048 EE0-L0FT-5165 80/06/30

 44pp
- 8007160280 Progress Rept 28 for Apr 1980 re value/impact statement for dosimetry testing program PLATD; P Michigan, Univ of NRC-01-77-180 80/04/30 8pp

- 8007170460 "Investigation of Post-CHF Heat Transfer for Water-Cooled Reactor Application & Development of Two-Phase Flow Instrumentation." monthly progress repts for Mar-Apr 1980 CHEN.) C. SUNDARAM.R.Y. NIJHAWAN.S. Lehigh Univ. FIN A-4055 NRC-04-74-180 80/04/22 /pp
- 800717064B "Environ Assessments of Fuel Cycle Facilities," monthly progress rept
 ZITTEL.H E Dak Ridge National Laboratory FIN B-0279
 ORNL/ED/EIS-130 80/05/31 App
- 8007180233 "Stress Corrosion Cracking of PWR Steam Generator Tubing," monthly highlights for May 1980 BULISCHECK.T. VAN ROOYEN.D Brookhaven National Laboratory FIN A-3208 80/06/17 App
- 8007180240 "HTGR Safety Program." monthly highlights for May 1980 BASTRE,C Brookbaven National Laboratory FIN A-3016 80/06/07
- 9007180245 "TRAL Assessment & Model Development," monthly highlights for May 1980 SAMA,P Brookhaven National Laboratury FIN A-3215 80/05/31
- 8007180253 "Thermal Reactor Safety Code Development," monthly highlights for May 1980 LEVINE:M M. Brookhayan National Laboratory FIN A-3014 80/05/31
- 8007180330 "Mathematical Simulation of Sediment & Contaminant Transport in Surface Waters," quarterly rept for Oct-Dec 1979 * Battelle Memorial Institute, Pacific Northwest Laboratory F3N B-2271 79/12/31 26pp
- 8007180352 "Evaluation of Docket Files of Terminated Licenses," monthly progress rept for Apr 1980 HDLDWAY,C F. DICKSDN.H H Oak Ridge National Laboratorg FIN A-9085-7 ORNL/HASRD-77 B0/04/30 15pp
- 8007180354 "Forerasting Electricity Demand by State & by Util Svc Area." progress rept for May 1980 CHERN.W S Clak Ridge National Laboratory FIN B-0190-8 ORNL/ED/EAS-807 80/06/11 7pp
- 8007180361 "LWR Thermal Hydraulir Development Program." monthly highlight itr for May 1780 ABUAF.N Brookhaven National Laboratory FIN A-3045 80/05/31 7bp
- 8007210001 "Mathematical Simulation Sediment & Containment Transport in Surface Waters." quarterly rept for Jan-Mar 1980 * Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2271 80/03/31 34pp
- B007210003 "SBC Code Development & Validation." monthly highlight ltr for June 1980 AGRAMAL.A K , GUPPY.J P Bronkhaven National Laboratory F3N A-3015 80/06/13 700
- BOO7210005 "NRC Nuclear Waste Mgt Technical Support in Development of Nuclear Waste Form Criteria." interim rept for May 1980 CZYBCINSKI,K S , SHYLER.K J , KLAMUT,C J Brookhaven National Laboratory FIN A-3158 BD/05/31 95pp
- 8007210007 "NRC Nuclear Waste Mpt Technical Support in Development of Nuclear Waste Form Criteria." Interim rept for Apr 1980 BIDA, O. DAVIS.R F. MACKENZIF, D.R. Brookhaven National Laboratory FIN A-3158 80704/30 9App
- 8007210010 "Evaluation of LVR Residual Heat Removal Under Accident Conditions," monthly highlights for May 1780 BARI,R A Broukhaven National Laboratory FIN A-3315 80/06/05 780
- 8007210014 "Thermal Hydraulic LMFBR Safety Experiments," monthly highlight ltr for May 1980 GINBBERG,T Brookhaven National Leboratory FIN A-3024 80/05/31 406
- 8007210017 "LOFT Program Davisson." pretest prediction rept for June 1980 KEE.E J., TAYLUR.O A. CONDIE.K G. FOSG, Inc. FIN A-6048 EGG-LOFT-5172 80/06/30 Bipp
- BOO7210602 "LWR In-Plant Measurement Program." informal monthly progress rept for May 1980
 MANDLER.J W EGEG. Inc FIN A-60/5 80/06/24 App

- 8007210607 "Investigation of Ventilation Component Response to Large Pressure Polses." informal monthly progress rept for May 1980
 - OREGORY, W.S. Los Alamos Scientific Laboratory FIN A-7028 80/06/27 3pp
- 8007220045 "LOFT Program D.v." quick-look rept on LOFT Nuclear Experiment L3-7 MCCREENY.G E EG&G idaho.lnc FIN A-6048 EGG-LOFT-5192 80/06/30 44no
- 8007220047 "Methods for Determination of Inorganic Constituents in Trench Leachates from Shallow Land Radwaste Disposal Sites," informal rept GARBER, S. L. Brookhaven National Laboratory FIN 3042 BNL-NUREG-27591 80/03/31 55pp
- 8007220053 "Stress Corrosion Cracking of Alloy 600 Using Constant Strain Rate Test." informal rept for Mar 1980 BULISCHECK.T S. VAN RODYEN, D. Brookhaven National Laboratory BNL-NUREG-27759 B0/03/31 24pp
- 8007220058 "Acoustic Emission/Flaw Relationships for Inservice Monitoring of Nuclear Pressure Vessels." monthly progress rept for May-June 1980 HUJTON/P H Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2088 80/07/07 35pp
- B007220065 "FRIDA Computer Code for Dynamic Longitudinal Response of Fuel Rods Subjected to Thermal Transients," interim rept SINGH.J N , BOHN,M P , ENGELMAN.O P EG&O Idaho.inc FIN A-6050 EGO-CDAP-5173 B0/06/30 66pp
- B007230177 "LOFT Monthly Progress Rept for Apr 1980 "
 KAUFHAN, N C EG&G Idaho, Inc LO-MR-006 B0/05/31 114pp
- 8007230185 "LOFT Small Break Test Thermosouple Installation " FORS.R M EG&O Idaho, Inc RE-A-80-044 80/05/28 12pp
- 8007230194 "Stress Analysis of Modified Pulsed Neutron Activation Sys Downstream Shield Support Structure " MOSBY, 4 R EG&G Idaho, Inc RE-A-80-047 80/05/28 48pp
- 8007230223 "Site Visits to Eight Major Dosimetry Processors " PLATO,P., HUDSON.G. Michigan, Univ. of 79/05/31 App
- 8007230231 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incipient Cracking of Eypass Lines & Pipes in BWR Piping Sys." Progress Rept & for 800524-0420 * Daedalman Associates, Inc. NRC-04-78-242 80/07/31 Bpp
- B007240257 "Water Reactor Research Directorate Monthly Rept for May 1980 "
 - * Idaho National Engineering Laboratory 60/05/30 189pp
- 8007240294 "Advanced Reactor Bafety Analysis Technical Assistance, Reactor Projects," monthly highlights for May 1980 BARIAR A Broothaven National Laboratory FIN A-2000 80/06/05 4pp
- 8007280002 "Accident Aeroso) Characterization," informal monthly progress report for June 1980 OHZAHSKI P C Battelle Nemorial Institute, Pacific Northwest Laboratory FIN B-2287 80/07/15 4pp
- 8007280004 "Shipping Cask Sabotage Source Ferm Investigation," informal monthly progress rept for June 1980 SCHMIDIA: W Battelle Memorial Institute, Columbus Laboratories FIN B-6012 80/07/07 10pp
- 8007280081 "Sandia Core Melt & Separate Effects Program," monthly progress ltr for June 1980 BERMAN.M Sandia Laboratories 4441/NL~13 80/07/10 7ap
- 8007280092 "Operational Aids for Reactor Operators." foreign trip rept KIBNER,R A Dak Ridge National Laboratory FIN 8-0438-9 ORNL/FTR-859 80/06/16 17pp
- 8007280095 "Dosimetry & Biotransport Models to Implement ALARA." quarterly progress rept Apr-June 1980 KOCHER, D C. MCDMELL-BOYER, RYAN, M T Dak Ridge National Laboratory FIN 8-0188 (BRNL/HASR)-84 80/06/30 5pp
- 8007280164 "PBF LOC-58 Test Experiment Safety Analysis " 0055MANN.6 R EGNO Idaho, Inc FIN A-6041 EGG-TF0P-5043 79/11/30 40pp

- 8007280171 "LOFT Monthly Progress Rept for May 1980 " KAUFMAN, N C EG&G Idaho, Inc LO-MR-007 80/06/30 114pp
- 8007280174 "Modular Drag Disc Turbine Qualification Tests " FLITTON,V E EG&G Idaho,Inc LTR 141-109 80/06/06 14pp
- BOO728017B "TRAC-PIA Calculations for 2007 Hot Leg Break & 200% Hot Leg Break Simultaneous W/Rupture of 14 Steam Generator Tubes in PMR " BOLANDER, M A EG&G Idaho, Inc FIN A-6047 EGG-CAAP-5191 80/08/30 7400
- B007200186 "TRAC-PiA Calculations for 200% 0 25 Meter Diameter & 0 10 Meter Diameter Cold Leg Break in PWR "
 WHEATLEY,P D . B0LANDER,M A EG&G Idaho,Inc FIN A-6047
 EGG-CAAP-5190 B0/06/30 90pp
- 8007290174 "PBF TC-1 Test Experiment Safety Analysis " GOSSMANN:S R Energy Dept of, Idaho Operations Office FIN A-6041 EGG-TFBP-TR-502 79/10/31 35pp
- 8007270191 "Measurement of Velocity Vectors in Two-Phase Flows Using Five Hale Stagnation Probe " DEASON,V A , FINCKE, J R EG&G Idaho, Inc USNRC-P394 80/06/06 3489
- 8007270201 "PBF PR-1 Test Experiment Safety Analysis " GGSSHANN, B R EG&G Idaho, Inc FIN A-6041 EGG-7FBP-5080, 80/01/31 28pp
- 8007290224 "Calculations of Large Cold Leg Break W/Steam Generator Tube Rugtures in PMR using JRAC-Pla Computer Program," preliminary assessment rept LARSON J R E08:0 Idaho, Inc FIN A-6047 E00-CAAP-5189 80/06/30, 83pp
- 8007290233 "Physical Protection of Nuclear Facilities." monthly progress rept for June 1980 CHAPMAN.L D. Bandia Laboratorias FIN A-1060 80/07/09 App
- 8007270241 "Definition of Parameters for Major Accidents at Waste Solidification & Spent Fuel Storage Facilities," monthly progress rept for June 1780 FREDERICK, E. J. Oak Ridge National Laboratory FIN B-0425 80/07/14 App
- 6007290246 "Decontamination as Presursor to Decommissioning," monthly progress rept for June 1980 PERRIGO,L D Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2303 B0/07/07 3pp
- B007310181 "Shipping Cask Sabotage Source Term Investigation," informal monthly progress rept for May 1980 BCHMIDY.E W Battelle Memorial Institute, Columbus Laboratories FIN B-6012 B0/04/10 17pp
- 8007310183 "Shipping Cask Sebotage Source Term Investigation." informal monthly progress rept for Apr 1980 SCHMIDT.E W Battelle Memorial Institute, Columbus Laboratories FIN N-6012 80/05/13 4pp
- 8007310187 "Experimental Criticality Data for Code Validation," informal monthly progress rept for June 1980 BIERNAN, S R Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2074 80/07/03 3pp
- 8007310251 "Technology & Costs of Termination Surveys Associated W/ Decommissioning Nuclear Facilities," monthly progress rapt for June 1980 DICKBON, H W. HOLOHAY, C F Dak Ridge National Laboratory FIN A-9042 ORNL/HASRD-86 80/06/30 App
- REVIEW ORP NRG RESEARCH REVIEW GROUPS
- BOO7220041 Forwards graphs & executive summary from five recent fire suppression tests discussed within review group Objective was to obtain fully developed cable tray fire in donor cable tray Add Lipsts under consideration W/Halon FEIT.R Division of Reactor Safety Research 80/07/07 7pp

POSITION PAPERS BEFORE THE COMMISSION SECY

8007010589 Transcript of 800624 public meeting in Washington, DC to discuss ABLB rept on clearance rule Pp 1-49 L Dickwit 791109 memo to Commissioners encl * Commission 80706/24 67pp

B00702024B SECY-79-371A
Informs Commission of current status of activities in Ofc
for Analysis & Evaluation of Operational Data Mission
statement.personnel assignments, task action plan description
& status of selected activities encl
HELTEMES.C J Director's Office 79/11/21 Bpp

B007020262 SECV-R-74-132

OUVOLOURDE NECY-R-74-132

Discusses formation of regulatory requirements review
committee Program for controlling ratcheting, charter for
regulatory requirements review committee & press
announcement encl

MUNTZING.L M Atomic Energy Commission 74/03/05 19p Atomic Energy Commission 74/03/05 19ap

8007020270 SECY-R-74-095

007020270 SECY-R-74-095
Discusses regulatory program for minimizing & controlling
ratcheting Ratcheting can be minimized & controlled but no
completely eliminated Program will make ratcheting part of
licensing process Program encl
MUNTZING.L N Atomic Energy Commission 73/12/19 12pp

8007070598 SECY~80-153

Forwards traff FR notice of proposed rulemaking re revision of reactor siting criteria & draft ltrs to PIRG & Congress Recommends approval MINOGUE.R B Office of Btandards Development, Director 80/03/19 3600

00/080036 BECY-75-429
Discusses procedure by which NRC can determine whether matters of alleged or suspected criminal violations of law should be referred to DOJ Recommends that Inspector & Auditor OP: accept full responsibility SHAPAR.H K, Office of the Executive Legal Director 75/08/11 3pp

8007090015 SECY-80-275
Discusses finalization of emergency planning rule changes, including consideration of public comments Recomments for publication re final rulemaking Related documentation encl MINGOUE, R B Office of Standards Development, Director

--8007090017 NUREG-0685

00/00/001/ NUREG-0885
Draft "Environ Assessment for Effective Changes to 10CFR50
& App E of 10CFR50; Emergency Planning Requirements for
Nuclear Power Plants " Related documentation encl
OTT.W R Division of Biting, Health & Bafoguards Standards
80/06/30 54pp

~-8007090019 Concurs in proposed final rule on emergency planning, pending resolution of IE comments Resource impact on NRC for full implementation of rule must be addressed in Commission Paper
STELLO,V Office of Inspection & Enforcement, Office of the Director HO/05/14 Ip

--8007090021 Concurs in sending revised emergency preparedness rule to Commissioners Supplementary Info section should contain add1 info on technical justification for i5-minute notification requirement

DENTON, N R Office of Nuclear Reactor Regulation, Director 10

--8007090023 Concurs in final rulemaking on emergency preparedness
Requirements for implementation of federal state & local
govt exercises apply to nuclear reactors & not to operations
licensed by NMSS
DIRCKS,W J Office of Nuclear Material Safety & Safeguards
80/05/19 19

--B007090025 Supports final rule on emergency planning NRC final rule is consistent w/proposed FEMA procedures for review of state emergency plans JETI.9 Foderal Emergency Management Agency B0/06/02 ip

800709002B Transcript of 800515 open Affirmation Session 80-23 in Washington, DC re order in Tarapur export Pp 1-3 + Commission 80/05/16 4pp

--8007090030 Informs of correction to SECY-80-238 re proposed exports of fuel & components to Tarapur Commission SECY papers cited are incorrectly referenced Draft megod andow & order encl SHEAJR Office of International Programs, Director 80/05/13

--8007090033 SECY-80-238A 007090033 SECY-BO-200A
Forwards NNSS technical review for Commission's
consideration in conjunction w/review of pending Tarapur
fuel & component exports
SHEALUR Office of International Programs, Director 80/05/13

--800709003B Forwards proposed NMSS technical review for Commission consideration re proposed exports of fuel & components to

BURNETT,R F Division of Safeguards 80/05/12

8007100098 SECY-79-299
Informs Commission of results of NR(study of generic financial qualifications issue & requests decision on encl proposed rulemaking Recommends approval of Alternative 1 c & publication of proposed rulemaking in FR
DENTON.H R Office of Nuclear Reactor Regulation, Director 84pp 79/04/27

8007100264 SECY-80~171
Requests Commission comments on proposed legislation to establish state planning council on radwaste mgt Major changes proposed by DOE would give council budgetary & spending authority Recommends sending encl ltr to DOE BTAIBER, C.R. DEFice of the General Counsel 80/03/21 Звв

8007110484 SECY-80-1078

007110484 SECY-80-1078
Provides balance of addl info requested re proposed interim hydrogen control requirements for small containments Advisable to require inerting of all Mark I & Mark II containments pending rulemaking proceeding DENTON.H R Office of Nuclear Reactor Regulation, Director Containment DENTON H R OF

---B0071104B7 Forwards summary of Probablistic Analysis Staff views on value of inerting to overall risk reduction based on 791003 presentation before ACRS Subcommittee on TMI-2 Inerting has small value in terms of overall risk reduction BERNEROLR M Probabilistic Analysis Branch (Pre 791030) 1000 80/06/10

--8007110495 Discusses Reliability & Risk Assessment Branch evaluation of relative impact of inerting Mark I containments from overall risk standpoint Inerting containment would not appear to have significant effect on reducing overall risk MATISON,R J Division of Safety Technology 80/05/27 lipp

--B007110498 Forwards "BWR Perspective on Interim Hydrogen Control Measures," as add1 info on accident prevention for IMRs Substantial hydrogen generation is effectively prevented in IMR due to unique inhorent design features
SHERWOOD, Q G General Electric Co MFN-049-80 80/04/21 1

--8007110503 "BWR Perspective on Interim Hydrogen Control Measures " * General Electric Co = 80/04/15 19pp

8007110532 SECY-80-220

00/110322 SECY-BO-220 Bubmits analysis of basic legal issue in emergency planning rulemaking NRC has sufficient authority to promulgate rules premised on Commission judgment re significance of adequate smergency plans as essential to public health & safety BICKHIT.4. Office of the General Counsel 80/04/27 17pp

B00711054B SECY-79~106

JULY JUDGE SECY-79-106
Provides Commission w/results of further leview of extent
that licensing or other regulatory actions relied on WASH1400 No reason exists to alter previous recommendations
Synopses of items identified in NRC survey encl
DENTON-H Office of Nuclear Reactor Regulation, Director
79/02/09 114pp

8007140055 SECY-RO-275A

Provides proposed changes to FR notice re final rule on emergency preparedness in response to Commission directives from BOO418 meeting Forwards replacement pages to SECY-80-MINDGUE.R B Office of Standards Development, Director 80/06/23

--8007140059 SELY-80-275
Replacement Pages 31, 25, 25a, 50, 51, 71a & 47 modifying FR notice & final rule changes re emergency preparedness
* Office of Standards Development, Director 80/06/25

0007140121 SECY-79-424

Requests Commission approval of FR notice inviting public comment on NRC value-impact guidelines Recommends approval Draft FR notice, draft ltr to Congress & draft public announcement end! HALLER,N M Office of Management and Program Analysis 79/07/02

```
-9007140122 Adviser that Cornic ioners have agreed to adopt guidelines contained in SPC,-77-323A for use in value-impact analysis CHILK,9 J. Office of the recretary of the Compission 78/01/23
               -900/140130 Requests NAC to rendurt review of Baram study, "Cost-Banefit
Analysis in Energy Decision-Making of NRC " Also requests
preparation of draft FR initice unich would solicit public
comment on vision-impact Guidelines
CHILK S.J. Office of the Secretary of the Commission 79/01/18
           --8007140135 Distuisses importance of Value/inpact assessments in meeting fundamental safety & other statutory mandates Recent value/impact assessments are well prepared although there is room
                      for improvement ANDERS U.A. ...
                                                        ve~mission 76/04/19 1p
          8007140539 SECY-90-301
Requests review of proposed issuance of license for GE to export components to Finland Equipment destined for country not previously authorized to export per Nuclear Nonproliferation Act of 1978 Recommends issuance SHEA.J R Office of International Programs. Director 80/06/20
       BOO7140352 SECY-BO-294
Informs of Frecutive Branch response on pending license for Union Carbide Corp to export U-235 to France
SHEA.J R Office of International Programs Director BO/05/18
     --8007140560 Frecutive Branch position re application by Union Carbide
Corp to export 9 85 kg U-235, enriched to 93% U to France
License should be issued Lir of assurance encl
NOSENZO, L V State, Dept of, Bureau of Oceans & Internati Environ
& Scientific Affairs 80/06/11 2pp
      8007140576 SECY-80-153A
           MO7140376 SECY-BU-13JA
Forwards revised stredule for proposed rulemaking on reactor
siting Distusses need for greater deliberation
MINDOUE:R D Office of Standards Development, Director 80/06/17
   8007150050 SECY-BO-298
Recommends return of Rockwell Intl application for license to export specially-designed valve to india w/o action Riecutive Branch prefers returning w/o action as opposed to denial due to political differences involved Draft itr encl SHEA, J.R. Office of International Programs. Director BD/06/19 6mb
   BOO7150054 SECY-BO-307
Advises of intention to forward nuclear safety cooperation arrangement w/Argentina to Argentine Natl Energy Commission (CNEA) in response to CNEA request for cooperation proposal Cooperation arrangement enci SHEA.J R Office of International Programs, Director 80/06/24
  BO07150069 SECY-BO-306
Informs of proposed retransfer of 5.126 kg U.in form of spent fuel from Spain to United Kingdon Staff analysis currently being prepared & uill be forwarded DOF BO0617 retransfer analysis enc!
SHEA.J R Office of International Programs. Director 80/06/23
 ---8007150074 Forwards DDE analysis of proposed retransfer of 5,126 kg
U.in form of spent fuel from Spain to United Kingdom
Recommends approval
MCCOLURICK F Energy, Dept of 80/06/17 22pp
BOO7160786 SECY-BO-107A

Provides add1 info per Commission request re proposed interim hydrogen control requirements Forwards eight listed documents

DENION.H R Office of Nuclear Reactor Regulation. Other
```

Office of Nuclear Reactor Regulation. Director

80/04/22 3pp

```
BOD7170244 SECY-BO-317
Forwards Executive Branch responses re two pending export
license applications for Taiwan
SHEA, JR Office of International Programs, Director 80/07/01
      --8007170251 Forwards Executive Branch analysis re Hestinghouse
application for license to export 8,845 kg U-2,15, contained
in 325,822 kg U. to Taiwan
NOSENZO.L V State.Dept of Bureau of Oceans & Internati Environ
& Scientific Affairs 80/06/12 13pp
      --8007170258 Application by Westinghouse for license to export U dioxide sintered pellets.encapsulated in scaled fivel rods to assembled into fuel assembles, to Tajwan # Westinghouse Electric Corp | ICB-7823 | 78/11/17 | 1p
      815~08-Y238 ESC7-80-318
          ייטיאיט פורעי-אטייטיט Recommends approval of proposed license to allow Nigsho-lwai American Corp to export 47 ול2 kg U & 44 003 kg ערבטיט to
           American corp to expose 4/ 102 mg o m 4- 000 mg o 20. ...
Uspan
SHEA.J R Office of International Programs, Director 90/07/01
           5<sub>0</sub>0
     --8007170534 License for Nissho-Iwai American Corp to export 44 003 kg
U-235, contained in 47 162 kg U, to Japan
PETERSON M R Office of International Programs, Director
80/07/01 2pp
    8007170597 Unoffical transcript of 800703 public meeting re NRC response to panel presentations on emergency planning in Washington, 80 Pp 1-50 tommission 80/07/03 40pp
   --8007170604 RECY-80-2758
Proposes mods to FR & final rule changes on emergency
preparedness submitted for Commission approval in
SECY-80-275 Changes do not offect cost estimates Replacement
             pages encl
MINODUE: R B Office of Standards Development, Director B0/07/02
  8007180004 SECY-80-132E
Discusses approval of release of Kr-85 from reactor bidg
atmosphere by controlled purging Recommends authorization
for controlled purging Draft negative declaration re purging
& prest release ancl
DENTON:H R Office of Nuclear Reactor Regulation: Director
  B007210009 BECY-80-316
Recommends issuance of proposed license for Transnuclear, Inc to expert 39 077 kg U. enriched to 93 3% to Japan Forwards Executive Branch views re proposed export
SHEAL J R Office of International Programs, Director 80/07/01
   noted
NOSENZO,L V State,Dept of, Bureau of Oceans & Internet! Environ
& Scientific Affairs 80/01/29 opp
 --B007210083 License for Transnuclear Inc to espert 39 077 kg U.enriched
to 93 3% to Japan
PETERSON, M R Assistant Director for Esport/Import & International
Safeguards NUK-231 78-169 B0/07/01 2pp
  8007830026 Notice of ACRS Subcommittee on Fire Protection 800707 meeting in Washington, DC to discuss proposed fire protection rule for facilities operating prior to 790101 per SECY-80-89
      HOYLE, J C Office of the Secretary of the Commission 80/06/19
8007230179 SECY-80-242
Responds to RT Hennedy BOOR13 request for info re
independent safety engineering group Existence of industry-
wide groups does not alleviate need for independent safety
angineering group or other util review groups
BENTON, RR Office of Nuclear Reactor Regulation, Director
BO/05/13 6pp
8007250014 Transcript of 800711 Affirmation Session 80-33 re

SECY-80-274 in Washington. bC Pp 1-2

# Commission 80/07/11 3pp
```

-

--- 8007250019 SECY-80-274 DO7290019 SECY-80-274

Recommends approval of publication of regulations to implementation of IAEA requirements for licensees Draft FR notice & press release & summary of comments enci MINDOUE, R B Office of Standards Development, Director SHEA, J R Office of International Programs, Director DIRCUS, W J Office of Nuclear Material Safety & Safeguards 80/06/02 127pp

B007250176 SECY-80-278

207250176 SECY-80-27B
Informs Commission of current status of resources & projected end-uf-yr position No financial plan changes being recommended, pending several decisions, most significantly, Congressional action on NRC FYBO supplemental DARRY, L W Office of the Controller 80/06/04 2pp

--8007250180 "FY80 Mid-Yr Resource Review * Division of Budget 80/09/30 65

8007280062 SECY-80-308

DO7280062 SECY-80-308
Advises of near-signature status of NRC info exchange arrangement w/Japan Nuclear Safety Bureau & Agency of Natural Resources & Energy Arrangement will be signed in Japanese & English Textural authenticity verified BO0613
BHEA.J R Office of International Programs, Director 80/06/24

B0072800B6 \$ECY~80-313

Informs of Executive Branch position re application by DDE to export mixed oxide fuel pins to United Kingdom Recommends license be granted BMEA.JR Office of International Programs, Director 80/06/30

B007290002 SECY-80-291

007270002 SECY-80-271
Recommends that Commission approve notice of denial of Petition for Rulemaking 2-9 filed by Union of Concerned Beientists & Natural Resources Defense Council Draft documentation end!

BHAPAR: H K Office of the Executive Legal Director 4: documenta BHAPAR H K OF 15pp ABERARADI.

--B007270005 Forwards petition for rulemaking 2-8 & comments on proposed rule 10cFR21
ROISHANA 2 Natural Resources Defense Council 43FR48621 21
79703702 1p

--B007290012 Petition for rulemaking on amend to iOCFR21, re exempting commercial grade component suppliers from regulation, submitted as comment Safety significance unfounded & inconsistent w/past NRC activities POLLARD, R Union of Concerned Scientists ROISMAN, A Z Natural Resources Defense Council 43FR48621 21 79/03/02 14pp

8007290023 SECY-80-299

JOYAYOUAN SECTION APPROVE MOD to portion of security clearance processing policy to permit certification of other federal agency security clearances to serve as basis for NRC certifications Security agreements w/DOE encl DDNOGHUE.D J Office of Administration 80/06/19 13pp

8007290028 Draft Commission paper re approval of FR publication of "Guide for Evaluation of Agreement State Raduation Control Programs." as proposed policy statement w/request for comments Draft notice & guide encl
KERRIO W Office of State Programs. Director DIRCKS.W J of the Executive Director for Operations 80/06/02 38pp

~~8007270029 Discusses proposed criteria revisions for evaluation of agreement states Fundamental issues requiring resolution include ability of agreement states to bring proper technical skills to bear on radiological issues DIRCKS.W J Division of Safeguards 80/05/23 2pp

STATE PROG STATE PROGRAMS

8007010039 Forwards specific comments & recommendations re program for control of agreement matls Program adequate to protect health & safety w/some improvement suggested Requests review & comments on recommendations KERR.Q W Office of State Programs. Director 80/06/11 App

8007010128 Ack receipt of 800602 ltr to JM Hendris, praising Ofc of Btate Programs past efforts & expressing concerns re future role Close working relations w/states will be preserved DIRCKS, W J Office of the Exercitive Director for Operations 80/06/17 ip

--8007010133 Praises Ofc of State Programs past efforts & expresses concerns re future role
MUELLER, E W Alaska, State of BO/06/02 1p

8007010159 Commends organization of annual meeting of Conference of Radiation Control Program Directors held May 1980 in Louisville, KY JANINEK,M Office of State Programs Director

8007020099 Ack receipt of 800428 its imquesting MRC assistance at MD Commission on Intergovernmental Cooperation 800403 meeting Witness who will be prepared to answer questions to spent fuel will be provided J Cladater will accompany witness RYANLR G Office of State Programs. Director 80/05/21

--8007020338 Requests that NRC testify before MD Commission on Intergovernmental Cooperation 8005/3 / 17 hearing in Annapolis.MD on nuclear waste mgt problems Specific questions encl EASTER: J H M. Maruland, State of 80/04/29

BOO7020113 Act receipt of BOOS21 itr expressing concern re future role of Ofc of State Programs NRL temains committed to preserving closs working relations witates

DIRCKS, U Office of the Executive Director for Operations B0/06/12 10

B007020156 Forwards info requested re 1950 Houston Gamma Ray Co-incident Release limit for contamination at that time was 0.5 millirems/h & instruments were less sensitive than those used today
MERR, O. W. Office of State Programs, Director SA/ECA 80/06/11

8007020316 Discusses Div of Mints & Geology fault evaluation program for Livermore Valley Preliminary special study zone maps will be prepared by B10701 & fault evaluation repts will be issued Supporting documentation end

8007020690 Confirms Schneider discussion w/GA Christianson of ND Dept of Health re NRC veriew of radiation control program & notes adequacy of program to protect health & safety Improvements re written enforcement procedures recommended RYAN.R G Office of State Programs, Director 80/06/11 13pp

B007020699 Responds to 800529 ltr requesting info re U milling operations & NRC Agreement State program Provides address for obtaining draff GEIS Forwards NUREG-0511 & brochure re Agreement State program W/o encis
MERR, G W Office of State Programs, Director SA/CG 80/06/11

8007020764 Informs that under Scition 274 of Atomic Energy Act.NRC is authorized to transfer to states through agreement some regulatory authorized were byproduct source & SNM Twenty-Four states have compatible programs

RYAN,R Q Office of State Programs, Director 80/06/19 2pp

8007030347 Transcript of 800626 public meeting w/representatives of Conference of Radiation Control Program Directors re Agreement States program in Washington, DC Pp 1-39 Morning session Related correspondence ent.1 * Commission 80/06/26 40pp

8007070016 Transtript of 800625 public meeting w/industry.state & local & special interest group panels on emergency planning & preparations to lemaking & NRC response Pp 1-131 Afternoon session Related statements & correspondence encl # Commission 80/06/25 600pp

8007110(85 Forwards list of state bills not received Requests that copies be forwarded ORAMBAU.G Office of State Programs. Director 80/06/25 ip

B007110377 Informs Subcommittee on Nuclear Regulation of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL AHEARNE, J F Commission 80/06/24 2pp

--8007110382 Informs Subcommittee on Environ Energy & Natural Resources of status of Agroement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program defiriencies found in CA & FL
AHEARNE, J F Commission 80/86/24 2pp

-8007110387 Informs Subcommitter on Frengy & Environ of status of Agreement State regulatory programs Programs in all 25 states determined adequate for CV79 Significant program deficiencies found in CA & El AHEARNE.J F Commission 80/06/24 2pp

- ~-8007110392 Informs Subcommittee on Energy & Power of status of Agreement State regulatory programs Programs in all 25 states determined adequate for 6779 Significant program deficiencies found in 6.4 °FL AHEARNE.J F Commission. 80/06/24 2pp
- ~-8007110395 Discusses status of Agreement State regulatory programs Programs in all 25 states determined adequate for CY79 Significant program deficiencies found in CA & FL RYAN, R G Office of Management and Program Analysis 80/06/19
- 8007140569 Forwards comments & recommendations on State of NC radiation control program KERR.G W Office of State Programs, Director 80/06/27 3pp
- 8007150044 Responds to 800325 itr by forwarding marked-up rept on state transportation surveillance program & updated versions of Apps I & II Suggests 800708-11 meeting to discuss approach Office of State Programs, Director 80/06/24 24pp
- 8007170234 Discusses results of NRC review of state radiation control program Program for regulation of agreement math adequate to protect public health & safety & compatible w/Commission program Full-time prof should be hired RYAN,R G Office of State Programs, Director 80/06/27 2pp
- 8007170254 Confirms info provided in 800617 telton in response to 800611 ltr Responsibility for mgt of training programs for state & local emergency planning & response personnel transferred from NRC to FEMA RYAN.R G Office of State Programs. Director 80/07/02 2pp
- --8007170277 Requests assistance in training local law enforcement, matrgenty response & health personnel Cartland County Resolution 186 encl FEUSS.J V New York, State of 80/06/11 5pp
- B007180017 Expresses appreciation for B00526 ltr to NRC re future role of Office of State Programs Views expressed in 1tr will be carefully considered in any reorganization which may affect Office of State Programs
 DIRCKS.W.J. Office of the Executive Director for Operations 80/06/04 1p
- --8007180022 Expresses concern re future role of Ofc of State Programs Single point of contact which can work effectively w/all levels of NRC is vital Contact should have sufficient status to deal directly w/Commissioners & Executive Director MYERS, I L. Alabama, State of BO/05/26 1p
- B0071B0021 Forwards Nuclear Engineering Co. Inc B00404 application for remewal of State of NV radioactive matl license at Beatty low level waste disposal site State of NV has requested NRC tomment
 KERN, G H
 Assistant Director for State Agreements Programs SA/RJD
 80/06/03 350p
- B007180214 Ack receipt of B00624 ltr expressing concern about future role of Ofc of State Programs Views expressed will be carefully considered in any future reorganization DIRCKS.W.J. Office of the Executive Director for Operations B0/07/03 10
- -8007180217 Supports continuation of Ofc of State Programs as viable unit in NRC organizational structure Ofc of State Programs has consistently provided readily accessible source of technical legal & policy advice COHEN.J C New York State of 80/06/24 4pp
- BOO7180558 Ack receipt of 800521 ltr w/schedule .ions for radiological emergency response operations col | for FYB1 NRC chooses Option 1. regardless of who has runding From the Chooses operon in regardies or who has reliating by responsibility RYAN R G Office of State Programs, Director 80/07/01
- BOO7210068 Advises that actions to adopt 10CFR71 revisions re packaging a transportation of radioactive matls, should be initiated as soon as possible due to high degree of public focus on issue Requests plans

 MERR. Q W Office of State Programs Director BO/07/07 ip
- BOG7210263 Notification of cuntract execution "Environ Menitoring Program of State of NY," awarded to State of NY RAISBENL Research Contracts Branch FIN B-5109 NRC-05-80-271

- --8007210267 Cuntract "Environ Monitoring Program w/State of Ny," awarded to State of NY LANAHAN,M P New York, State of MORTON,K V Research Cuntracts Branch FIN 8-5109 NRC-05-80-271 80/01/01 14pp
- 8007230735 Ack receipt of 800512 ltr re progress in cooperative efforts to reduce packaging & transport problems Full time insp coverage at Beatty should be discontinued Contract re transportation surveillance will be forwarded shortly AMEARNE. J F Commission 80/06/12 ip
- --8007230739 Advises that full-time NRC inspector will no longer be needed at Beatty, NV waste dispusal site State will provide appropriate insp surveillance as of 800601 LIST, R Nevada: State of 80/05/12 lp
- 9007250301 Advises that F Young will be NRC representative to State Planning Council meetings beginning w/800721 meeting RYAN,R G Office of State Programs, Director 80/07/09 ip
- 8007250926 Recommands that written procedures be developed for escalated enforcement action Written procedures are necessary so that state can respond adequately & in timely manner to incidents involving agreement matls
 RYAN.R G Diffice of State Programs, Director 80/07/02 2pp
- BOO7250639 Confirms comments made at BOO603-06 regulatory program review Submits addi comments & recommendations designed to improve & strengthen radioactive matls grogram KERR.6 W Office of State Programs, Director BA/JOL 80/07/02
- 8007280162 Ack receipt of 800520 ltr expressing concern re future role of Ofc of State Programs NRC remains committed to preserving cluse working relations wistates & Conference AHEARNE, J F Commission 60/06/19 lp
- --BOO72BO17O Forwards resolution requesting Commission proceed w/caution in deliberation & actions re reorganization of NRC Dec of State Programs has provided agreement states w/info vital to programs & improved NRC/state relations PARROITIM W Conference of Radiation Control Program Directors, B0/05/22
- 8007290028 Draft Commission paper re approval of FR publication of "Guide for Evaluation of Agreement State Radiation Control Programs," as proposed policy statement w/request for comments Draft notice & guide encl
 KERR, O M Office of State Programs, Director DIRCKS, W J of the Executive Director for Operations 80/06/02 38pp Offica
- --8007290029 Discusses proposed criteria revisions for evaluation of agreement states Fundamental Issues requiring resolution include ability of agreement states for fing proper technical skills to bear on radiological Issues DIRCKS,W J Division of Bafeguards 80/05/23 2pp
- 8007270041 Forwards third quarterly transportation surveillance progress rept.first yr. submitted by State of WA under contract w/DDT & NRC
 JANINEK.M Dffice of State Programs, Director 80/07/16 15pp
- --8007290045 Submits rept for third quarter of transportation contract, 800310-0607 All shipments accepted No inspector onsite during wk of 800519 STRONG,T R Washington, State of 80/07/09 2pp
- --B007290050 Forwards third quarter, first yr, transportation contract progress rept for B00310-0609 W/o encl GRONENYER, E.L. Washington, State of B0/07/09 ip
- 8007290060 Forwards third quarterly transportation surveillance progress rept, third yr, submitted by State of MI under contract w/NRC & DDT covering 800301-0531

 JANINEK.M Office of State Programs, Director 80/07/16 19pp
- --8007290065 Forwards third quarter, third yr transportation surveillance progress rept for 800301-0531 W/o encl REIZEN.M S Michigan, State of NRC-06-77-051 80/06/30 lp
- 8007290347 Discusses NRC concerns re State of NM program for regulating U mills & mill tailings Lists provisions not approved by Environ improvement Board which should be included in program to comply w/UMTRCA by 8111111

 AHEARNE, J F Commission 80/06/12 3pp

- ---8007290359 Discusses U mill regulations that should be adopted to enable State of NM to meet requirements of UMTRCA State should take action on differences between RTAX & Environ Improvement Div recommendations as discussed in encl
 NERR, O W Office of State Programs, Director 80/03/20 4pp
- B-007300068 Ack recript of 1tr expressing appreciation for NRC assistance in hearing last fall Advises of Commissioner inability to attend SSEB meeting KENNEDY, R T Commission 80/03/06 lp
- --B007300074 Expresses appretiation for Commission assistance on emergency radiological planning shviron monitoring & transportation hearings Final rept available from hearings CARTER:A R South Carolina, State of 80/04/24 lp
- B007310295 Updated list of State liaison officers

 Office of State Programs, Director 80/07/31 11pp
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- BO07010236 Requests reply to 800221 inquiry re-status of technical review of topical rept on Fox Nawlett rebar coupler, submitted 780322 Coupler approved by every major code writing agency FGX.C J. Fox Industries 80/06/25 1p
- 8007010349 Notifies that info requested in NRC 800610 ltr will be forwarded on 800718 Affirmation encl DARMITZEL,R W General Electric Co 80/06/23 2pp
- B007010507 Requests participation at Commission B00626 meeting on hydrogen control Bubstantial hydrogen generation effectively prevented in BHR due to design features
 BHERNOOD, G.G. General Electric Co. 80/07/01 lp
- 8007020089 Forwards status of TMI Bulletins & Orders Task Force work Discusses B&M operating plant response to IE Bulletins 79-05,79-058 & 79-050 HELTEMES, C.J. YMI-2 Bulletins & Orders IEB-79-05 79/09/13 8pp
- --R007020095 Forwards summary of 790910 meeting re status of IE Bulletins 79-06B & 79-06C & generic issues pertaining to C-E designed reactors VILLALVA, I. TMI-2 Bulletins & Orders IEB-79-06B 79/09/12 7pp
- 8007020322 Requests add1 info to complete review of CE-1-A. "Comm Ed QA Program." Revision ii Response requested by 800627 HAASB,W P Quality Assurance Branch CE-1-A.R 11 80/06/11 2pp
- 8007020570 Forwards HCAP-9748 & WCAP-9749, "Westinghouse Gwners Group Asymmetric LOCA Load Evaluation, Phase C " Proprietary version withheld (Ref 10CFR2 790) Application for witholding proprietary into encl ANDERSON, T M Hastinghouse Electric Corp , Nuclear Energy Bystems NS-TMA-2266 80/06/30 lipp
- --B007020596 WCAP-9749
 "Westinghouse Dumers Group Asymmetric LOCA Load Evaluation,
 Phase C." non-proprietary version
 CAMPBELL.T E Westinghouse Electric Corp , Nuclear Energy Systems
 B0/06/30 220pp
- BOO7020641 Forwards MCAP 955B. Revision 1 & MCAP 9570. Revision 1.
 "Mechanistic Fracture Evaluation of Reactor Coolant Pips
 Containing Postulated Circumferential Through-Wall Crack "
 Affidavit encl Proprietary rept withheld (ref 100cR2 790)
 ANDERSON.T M Hestinghause Clectric Corp NS-TMA-R265 BO/06/30
- --B007020644 HCAP-9570 RI
 "Machanistic Fracture Evaluation of Reactor Coolant Pipe
 Containing Postulated Circumferential Through-Wall Crack,"
 Revision innonprogrietary version
 FALUSAMY, S. S. HARTMANN.A. J., ANDERSON, T. M. Westinghouse Electric
 Corp. B0/06/30 200pp
- 8007020724 Notification of 800627 meeting w/Westinghouse & NAI in Bethesda, MD to discuss WCAP-9500 review Westinghouse will present Section 4 4 design of 17 x 17 optimized fuel as described in rept PHILLIPS, L.E. Core Performance Branch 80/06/23 2pp
- 8007030211 Discusses concerns re requirement for immediate trip of reactor toolant pumps in event of reactor trip & safety injection initiation caused by low pressure condition . WILBON B A TMI-2 Bulletins & Orders IEB-79-050 79/10/09 5pp

- 8007030220 Provides status rept/schedule for issuance of NRC evaluations of B&W licensee responses to IE Bulletins 79-05. 79-05% t79-05% t79-05% t79-05% t79-05% t79-05% tFB-79-05 79/08/31 2pp
- 8007030359 Advises that C Michelson concerns, originally addressed to C-E Sys 80 designs, should be forwarded to 82M Responses necessary by 791011 for NUREG-0565 writtenp ROSZYDCZY, Z R TMI-2 Bulletins & Orders 79/09/06 2pp
- B007070106 GAI-TR-106 R2A
 Corrections to Feb 1980 GAI-TR-106 Revision 2A, "GA Program
 for Nuclear Power Plants"
 * Gilbert/Commonwealth Cos B0/06/23 1p
- B007070290 Ack receipt of NRC 800630 ltr re corporate organization WP Rausch has been named director of project support & GA divs & DJ McCormick is manager of corporate GA Corporate operations manual, Part 11 Organization encl HENDRICKSON, T Surns & Roe Co 80/06/30 9pp
- 8007080248 Notifies that Hestinghouse study re inadequate core cooling conditions will be submitted by mid-Jul 1980 REED, C Commonwealth Edison Co OG-35 80/07/01 1p
- 8007080274 Forwards input for 1979 fuel performance annual rept including table summary of C-E fuel arradiated &/or discharged in 1979 & "Performance of C-E fuel in Operating PWRs" SCHERER, A E C-E Power Systems LD-80-039
- --80070B0285 T18-6171

 "Performance of C-E Fuel in Operating PWRs "
 ANDREWS, M G . FREEBURN, M R . MDHLSEN, W D C-E Power Systems 79/05/02 5pp
- 8007080312 Responds to NRC request for info re "Fuel Parformance Annual Rept " Includes info re current B&W design fuel performance programs underway in 1979 & summery of B&W fuel performance for 1979 TAYLOR, J H Babcock & Wilcox Co 80/07/03 15pp
- B00709019B Forwards "Effects of Asymmetric LOCA Loadings, Phase 11 Analysis " Rept updates "Effects of Asymmetric LOCA Loadings, Phase 31 Status," submitted Feb 1980 TAYLOR, J H Babcock & Milcox Co ESC-186 60/07/01 1p
- --B0070902D1 BAH-1621 "Effects of Asymmetric LOCA Loadings.Phase II Analysis " ALLEN.R b., ANTOUN.R L., AU-YANG.M K. Babcock & Wilcor Co B0/07/31 B00pp
- 8007090310 Forwards GR rept.NEDE-24757-P. "Caorso Safety Relief Valve Discharge Tests Phase 2 Test Rept " Test rept withhe" (ref 10CFR2 790) BUCHHOL2,8 H General Electric Co 8HB-051-80 8C /03 5pp
- 8007100075 Notification of 800528 meeting w/C-E others group in Bethesda.MD to discuss group obligations for instrumentation recore cooling PHILLIPS.L. Core Performance Branch 80/05/23 1p
- BO07100210 Forwards Amend 1 to CENPD-183, "C-E Methods for Loss of Flow Analysis"

 BCHERER, A E Combustion Engineering, Inc. LD-80-035 80/06/24
 is
- --8007100212 CENFD-183 R1
 "C-E Methods for Loss of Flow Analysis," Amend 1
 * Combustion Engineering, Inc. LD-80-035 80/06/30 12pp
- 8007100219 Forwards "Class IE Qualification Qualification of Class IE Instrumentation," Revision 1.301 1980 9CHERER.A E C-E Power Systems LD-80-040 80/07/03 1#
- --8007100220 CENPD-255 Ri
 "Class IE Qualification Qualification of Class IE Instrumentation." Revision 1.Jul 1980 W C-E Power Systems 80/07/21 87pp
- 8007100253 Forwards Revision 9 to WCAP-8183, "Operational Experience w/Westinghouse Cores (up to 791231)"
 ANDERSON.T M Westinghouse Electric Curp ELM-80-006 80/04/21
 2pp.

- --B007100296 WCAP-B183 R9
 Revision 9 to "Operational Experience w/Westinghouse Cores
 (up to 79123) "
 SKARITKA, J. JORILJ A Westinghouse Electric Corp. 80/04/30
- 80071102|5 Forwards "Oadolinia Fuel Properties for LHR Fuel Bafety Evaluation " Rept withheld (ref 10CFR2 790) Affidavit encl UHSLEY, O F Ezzon Nuclear Co., Inc. (subs. of Ezzon Corp.) GFD 099 80 80/06/09 4pp
- 8007110243 Forwards Revisions 1-P & 1-NP to CENPD-153-P & NP.

 "Evaluation of Uncertainty in Nuclear Power Peaking
 Heasured by Self Powered Fixed In-Core Detection Sys "
 Revision 1-P withheid (ref 10CFR2 790), Affidayit enci
 BCHERER, A C Combustion Engineering, Inc LD-80-024 80/05/16
- --800711024B CENPD-153-NP RI
 "Evaluation of Uncertainty in Nuclear Power Peaking
 Measured by Self Fowered.Fired In-Core Detection Sys,"
 Revision 1-NP nonproprietary version
 JUNSEIN,A., TERNEY, U.B., CRUMP, M. H. Combustion Engineering, Inc.
 80/05/31 250pp
- 8007110341 Forwards XN-NF-80-17(P), Vols 1, 2, 2A, 20, & 3, XN-NF-79-59(F), XN-NF-524(F) & XN-NF-79-71(P), Revision 1 Repts withheld (ref 10CFR2 790)
 ONSLEY, 0 F Exim Nuclear Co . Inc (subs of Exxon Corp.)
 OFO 096 80 800/05/30 3pp
- 8007110499 Requests response to encl NRC position re CE-1-A. "Comm Ed OA Program for Nuclear Generating Stations " Yrs of experience required for position of manager of GA not described HAASS.W P Quality Assurance Branch 80/05/08 2pp
- 8007110550 Notification of 800612 meeting w/GE BWR owners group to discuss current plans of group to satisfy L2 requirements for relief valve testing TELFORD. J T Operating Reactors Assessment Branch. 80/06/03 2pp
- 8007110578 Notifies of NRC approval of XN-NF-1A, Revision 3, "QA Program Topical Rept for Nuclear Fuel Design & Fabrication " Program may be implemented upon issuance of revision HAABB, N P Guality Assurance Branch 80/06/27 ip
- 8007140354 Forwards "Emergency Procedure Guidelines" for BWR owners group, per NUREG-0578, Requirement 2 1 9 Description of how analyses of NEDD-24708 & emergency procedure guidelines apply to all FSAR Chapter 15 events forthcoming BUCH/DLZ, R II General Electric Co. MFN-117-80 80/06/30 40pp
- 8007140367 Forwards supply to equipment qualification test repts.

 revised equipment qualification data package, application
 for withholding & affidavit re commitments made in
 MCAP-0567

 ANDERSON, T.M. Westinghouse Electric Corp. NS-TMA-2260 80/06/16
- --8007140373 E00P-E8E-15 R2
 "Recorders Post-Accident Monitoring Equipment Qualification
 Data Package: "Revision 2 Submitted as part of Suppl 1 to
 HCAP-B587
 ANDERSON," M. Westinghouse Electric Corp. Nuclear Energy Systems
 80/05/31 17pp
- --8007140379 WCAP-8587 SR
 "HCID OPTIMAC 100 Recorders Equipment Qualification Test
 Rept." Suppl 2 Nonproprietary version of HCAP-8687
 MCELIANEY, D 1. MILLER B 1. ANDERSON, T M. Nestingbouse Electric
 Corp EISA 80/08/31 42pp
- OQ7140407 Purwards "Equipment Qualification Test Rept Barton Pressure Transmitters-Qualification Group D " Application for withholding proprietary info & affidavit encl Proprietary version withhold (ref IOCTR2 790) ANDERSON. T M Westinghouse Electric Corp NS-TMA-2258 80/06/16 10an
- -8007140416 MEAP-8587 BR-607A

 "Equipment Qualification Test Rept Darton Pressure
 Transmitters Qualification Group B " Nonproprietary
 Version
 MCELHANEY, D. L. MILLER, R. B., ANDERSON, T. M. Westinghouse Electric
 Corp. 80/05/Ji 30pp
- 8007140420 WcAP-8587 81 "Equipment Qualification Data Package," Suppl 1.Revision 2. * Westinghouse Flectric Corp. EQDP-ESE-2 80/05/91 15pp

- B007140426 Forwards addl copies of NEDD-25224, "GESSAR Assessment Rept, Review of BHR/6 Protection In-Depth for Transient & Accident Events"
 BUCHHOLZ, R H General Electric Co RHB-049-B0 80/06/30 1p
- 8007140630 Forwards topical rept evaluation of BAM-10123, "Nuclear Applications Software Package," re nuclear analysis for reactor cores MILLER, J. R. Standardization & Special Projects Branch B0/06/19
- --8007140637 Topical rept evaluation of BAW-10123, "Nuclear Applications Boftware Package" Rept acceptable BROOKS,W Core Performance Branch 80/06/19 5pp
- 8007140639 Forwards tupical report evaluation for NEDE-24010-P re use of square root of sum of squares method for combining dynamic loads for Mark II plants
 MILLER, J R Standardization & Special Projects Branch 80/06/19
- --B007140643 Topical rept evaluation of NEDE-24010-P, "Technical Basis for Use of Square Root of Sum of Squares Method for Combining Dynamic Loads Por Mark II Plants " Rept acceptable & Mechanical Engineering Branch B0/06/19 Spp
- B007130526 Requests NRC attention to PPI-TR-7701.Revision I Sys described in topical rept sold to applicant Review of submittal requested as soon as possible HALL.H C Teledyne Energy Bystems PPD-UCH-263 80/07/10 ip
- 8007150646 Forwards proprietary version of WCAP-8687, Suppl 2, nonproprietary version of WCAP-8587, Suppl 2 & Equipment Gualification Data Package EBE-10, Revision 2, which is part of nonproprietary WCAP-8587, Suppl 1 ANDERSON, T M Westinghouse Electric Corp NS-TMA-2257 80/06/16
- --8007150652 WCAP-8587 S2-E10A Nonproprietary version "Equipment Qualification Test Rapt, Nuclear Instrumentation Sys (Normal & Abnormal Temp & Humidity Testing) " VOGEDING,E L Westinghouse Electric Corp 80/05/31 26pp
- ~~8007150656 WCAP-8587 R1
 Revision 2 of "Equipment Qualification Data Program Nuclear
 Instrumentation Sys (NIS) Consols (Power Range Channel) "
 nonproprietary version
 ANDERSON, T M Westinghouse Electric Corp EGDP-ESE-10 80/05/31.
- 8007150724 Summarizes 800619 NRC/GE meeting re ECC8 licensing issues concerning LDCA analysis model & amends.0ESTR model.ECC9 input reverification program & core sprau program BUCHHOLZ,R H general Electric Co LFR-030-80 80/07/08 4pp
- BOO7160743 Forwards proprietary WCAP-8687, Suppl 2-E04A, nonproprietary WCAP-8587, Suppl 2-E04A & Revision 2 to Equipment Gualification Data Package ESE-4, part of nonproprietary MCAP-8587, Suppl 1 Info withheld (ref 100FR2 790) ANDERSON, T M Westinghouse Electric Corp NS-TMA-2259 80/06/16
- --B007i60755 WCAP-8587 B2-E04A

 "Equipment Qualification Test Rept.Barton Differential
 Pressure Transmitters Qualification Group B (Seismic
 Design Verification Testing)," nonproprietary version
 MCELHANEY, D L , MILLER, R B Westinghouse Electric Corp
- --8007160765 WCAP-8587 R2 81 Revision 2 Suppl 1 to, "Equipment Qualification Data Package ESE-4," nonpropietary version ANDERSON.T M Westinghouse Electric Corp EGDP-ESE-4 80/05/31
- 8007160805 Offers no comments on Reg Guide 4 16. "Effluent Monitoring at Nuclear Fuel Processing & Fabrication Plants." in response to 800522 memo KNIGHTON, G W Research & Standards Coordination Branch 80/06/19, Pag.
- ~-8007160814 Summary of 800528 meeting w/C~E owners group in Bethesds. MD re inadequate core cooling List of attendees & viewgraphs encl
 PHILLIPS.L E Core Performance Branch 80/06/23 3ipp

ł

- 8007170417 Forwards "BUKIN Nuclear Reactor Core Kinetics Code B&W version of MEKIN" & affidavit re request for proprietary classification TAYLOR, J H Babcock & Wilcox Co 80/07/07 1p
- --BOO7170421 Affidavit re proprietary classification of "BWKIN Nuclear Core Kinetics Code, B&W Version of MEKIN" TAYLOR, J H Babcock & Wilcox Co 80/07/09 7pp
- BO07180471 Forwards generic 1tr to all operating PWRs requesting amend to Tech Specs for each three PWR types onel EIBENHUT.D 0 Division of Licensing 80/06/11 lq
- --BD07180479 Ltr to all operating PWRs requesting amend to Tech Specs redecay heat removal capability Amend is necessary to provide permanent long-term assurance that redundanty will be maintained EIBENHUT, DQ Division of Licensing 80/06/11 ip
- --8007180486 BTS for RCS:providing for redundancy in decay heat removal capability in all modes of operation * Babcock & Wilcox Co 60/06/11 Spp
- ---BOO7tBO496 STB for RCS, providing for redundancy in decay heat removal capacity in all modes of operation & Combustion Engineering, Inc. BO/O6/11 9pp
- --8007180504 STS for RCS, providing for redundancy in decay heat removal capability in all modes of operation

 * Westinghouse Electric Corp = 80/06/11 Spp
- B007210051 Advises that Dfc of Controller will be billing OE for review of NEDO-11207-04A. "Nuclear Energy Business Oroup DWR QA Program Description," Revision 1
 HILLER W D License Fee Management Branch 80/07/01 (#
- 8007210229 Forwards Amend Sa to 21A, "Nuclear GA Manual," consisting of revised Page 5 HAABS,W F Quality Assurance Branch 80/07/17 2pp
- --8007210233 21A A05A Amend 5a to 21A: "Nuclear QA Manual," consisting of revised Page 5 * C F Braun & Co 80/07/17 1p
- 8007210366 Forwards Acurex Corp 800531 response to NRC questions on NEDE-24778-P. "Vent Bys Compressibility Effects on Mark I Paol Bwell "
 BUCHHOLZ, R H General Electric Co RHB-058-80 8D/07/14 47pp
- 8007210410 Forwards written notification supplied to customers on 800708 repotential for inadvertent boron dilution event while shutdown & operating on RHR sys Modifies previously reported interim actions ANDERSON. T M. Hestinghouse Electric Corp., PHR Systems Div NG-TMA-2272 80/07/08 7pp
- 8007220134 Forwards review of CENPO-153-P & revision describing method used to establish overall measurement uncertainty of core power distribution components Rept is acceptable for reference in license applications
 MILLER.J.R Standardization & Special Projects Dranch 80/07/02
- BC0722032? Forwards nonproprietary version of NEDO-24781-1, "Comparison of Single & Multivent Chugging at Two Bcales." submitted on behalf of Mark II owners group
 BUCMHCLZ,R H General Clectric Co MFN-122-80 80/07/08 ip
- --8007220334 NEDO-24781-1
 "Comparison of Bingle & Hultivent Chunging at Two Bceles."
 nonproprietary version
 PATEL.B.R. DOLAN,F.X. BLOCK,J.A. Creare. Inc. CREARE-TN-307
 80/01/31 84pp
- 8007220352 Forwards procedure guidelines for plants w/high & low head high pressure safety injection systemergency procedures & interim adequate core cooling instructions & ref instructions for post-LOCA cooldown & depressurization REED.C Gommonwealth Edison Co 00-37 80/07/15 2pp
- ---8007220354 "Interface Quidelinks Between Emergency Procedures & Inadequate Core Cooling Instructions,"

 * Commonwealth Edison Co 80/07/15 lp.
- --8007220357 "Ref Instructions for Past-LOCA Cooldown & Depressurization," Revision 0 # Commonwealth Edison Co #80/04/30 13pp.

- --8007220059 "Ref Emergency Operating Instructions (HP), 'Revision 2 B Commonwealth Edison Co. 1538n 80/04/30 89pp
- --8007220361 "Ref Emergency Operating Instructions (LP)," Revision 2 # Commonwealth Edison Co 80/04/30 /2pp
- 8007220482 Forwards MCAP-9753 % WCAP-9754 re inadequate core cooling studies & vendor 600711 application for withholding info w/ supporting affidavit Repts will provide analytical basis for guidelines re inadequate core cooling detection & remedy REED.C Westinghouse Operating Plants Owners Group EG-36 80/07/17 3pp
- --G00722048B Applies for withholding proprietary info in HCAP-9753 from public disclosure (ref 10CFR2 790) Previously submitted affidavit & application.AB-77-18-enc1 WIEEEMANN, R A Hestinghouse Electric Corp., Nuclear Energy Systems CAM-80-38 80/07/11 1p
- --8007920494 Affidavit justifying withholding of proprietary info in vendor ECCS repts from public disclosure (ref 10CFR2 790) WEISEMANN.R A Westinghouse Electric Corp AW-77-18 77/04/20 App
- --8007220499 HCAP-9744
 "Loss of Feedwater Induced LGCA Analysis Rept"
 TAUCHE, W Bestinghouse Electric Corp., Nuclear Energy Systems
 80/05/21 182pp
- --B007220503 WCAP-9754

 "Inadequate Core Cooling Studies of Scenarios w/Feedwater
 Available.Using NOTRUMP Computer Code "
 THOMPSON.C M , MARK,R H , HILL.G E. Westinghouse Electric Corp .
 Nuclear Energy Systems 80/06/30 410pp
- B007240001 Forwards BAW-1623, "Control Rod Guide Tube Wear Measurement Program " Rept documents wear measurements in response to NRC 791123 itr to owners of BAW designed reactors TAYLOR.J H Bebook & Wilcox Co 80/07/18 ip
- --B007240000 BAW-1623
 "Control Rod Guide Tube West Measurement Program"
 Babcock & Wilces Co 80/06/30 25pp
- 9007250476 Advises that NRC had accepted DNS-RSS-001P, "Dow Sys for Solidification of Low Level Radwaste from Nuclear Power Plants " Final rept to be submitted pending incorporation of amends per encl NRC guidelines DDNQVAN.L J Dow Chemical Co. 80/07/21 ip
- --80072504B3 Informs of NRC acceptance of DNS-RSS-001P re radwaste solidification Fire protection & interfaces U/plant sys should be considered interface requirements that will be addressed by applicants referencing rept MILLER, J. R. Standardization & Special Projects Branch 80/06/19
- 8007250515 Requests approval of proposed change in fuel design analysis described in NEDE-24011-P-A-I. "Generic Reload Fuel Application." Aug 1979 Change would allow GE to respond to IMR will requests in high capacity 18-month operating cycle ENGEL.R E General Electric Co MFN-127-80 80/07/21 2pp
- BOO72BOB99 Forwards errata sheet to EDAC+117-253 Of. "Evaluations for O & g Ground Acceleration Case Suppl 2 to Addl Investigations to Determine Effects of Combined Vibratory Verona Fault," Revision 1, Suppl 2 GILLIAND
- --8007280606 EDAC-117-253 O1 Ri
 Errata sheet to "Evaluation for O 6 g Ground Acceleration
 Case Suppl 2 to Add1 Invectigations to Determine Effects
 of Combined Vibratory Verona Fault." Revision 1. Suppl 2
 # Engineering Decision Analysis Company, Inc. 90/07/28 Rpp
- 8007290733 Advises of decision not to participate in pretest prediction of LDFT LS-1 experiment, since reasons for prediction do not apply to licensing work ECCS analyses will continue to be provided to reload fuel customers

 OHSLEY, G F Exon Nurlear (o , Inc (subs of Exxon Corp)

 OFO 115 80 80/07/24 ip
- B007300086 Notification of B00808 meeting w/Human Performance Technologies & Sandia Lab in bilver Spring, MD to develop checklist for emergency procedures BTONE, J C Office of Inspection & Enforcement, Office of the Director 80/07/22 2pp

- 8007300399 Forther discusses specific info in MCAP-8480 re upper head injection Quantitative info needed re high resistance of flow path in transferring steam to upper head when pressure is lower than RCS
 WALLES.O B Dartmouth College 80/07/24 2pp
- 9007300452 Forwards "NRC Benchmark ME101 Verification Rept.Apr 1980 "
 ME101 calculations agree within 2% of answers provided
 w/benchmark problems except for answers to Problem 3
 Rept available in Central Files only
 CAHN, A L Bechtel Power Corp (subs of Bechtel Corp) BD/07/23
 in
- 800/310256 Notification of 800/30-31 meetings w/vendors & consultants in San Jose,CA to discuss Mark III LOCA-related pool dynamic load criteria FIELDS,M Containment Systems Branch 80/07/21 4pp

WASTE MOT NUCLEAR WASTE MANAGEMENT

- 8007010270 Responds to 800513 request for separate MILDOS computer output for San Miguel ore buying station Tailings mgt program & radiological impact assessment underway Preliminary results & dose estimates entol SCARANO.R A Uranium Recovery Excensing Branch 80/06/16 5pp
- --8007010274 Requests offsite dose commitment output from HILDDS for ore stockpiles, receiving hopper, belt conveyor & sampling plant Comparison of ore buying station to offsite dose estimates for complete mill will be useful to vendor & NRC HAZLE-A J Colorado, State of 80/05/13 2pp
- 6007020092 Advises that NRC is unable to participate in Homestake Mining Co Pitch project on continuing basis requested in 800219 ltr due to limited resources for technical assistance to Agreement States Suggests review on state level 8CARANO:R A Uranium Recovery Licensing Branch 80/06/09 ip
- 8007020128 Forwards "Simulation Study of Evaporation Pond Seepage at Mount Taylor U Mill Project." In partial response to State of NM Environ Improvement Div. 800609 request for addl info re proposed groundwater discharge plan ROSERS, W.L. Gulf Oil Corp., Gulf Mineral Resources Co. 14569. 80/06/10 ip
- --8007020135 441TL337
 "Simulation Bludy of Evaporation Pond Seepage at Mount
 Taylor U Mill Project"
 MUNHERVEE, H Gulf Science & Technology Co 16569 80/05/30
- 800702014B Biscusses review of proposed Nose Rock U Mill Mill was proposed for const in State of NM & anviron & tailings mgt review was conducted in response to technical assistance request Case considered complete as of Mar 1980 MILLER: H J Uranium Recovery Licensing Branch 80/09/21 2pp
- 8007020264 Provides info in response to J Welze inquiry re United Nuclear Corp. Church Rock U Mill tailings 790716 dam failure Failure caused some radioactive tailings solution to be released into Rig Fuerco Released FR excerpts encl DIRCKS.W J Office of the Executive Director for Operations 80/06/09 26pp
- --8007020277 Testimony of WJ Direks before Subcommittee on Energy & Environ re Church Rock U mill tailings dam failure
 DIRCKS,W J Office of the Executive Director for Operations
 House of Rep , Interior & Insular Affairs 79/10/22 14pp
- 8007020281 Forwards response to Item 1 discussed at 8004[7 meeting, completing responses to 17 items identified during 800512 meeting Requests meeting during wk of 800609 Oversized drawings ent THOMPSON, M A Cypros Mines Corp 16568 80/06/02 10pp
- 8007020359 Requests that Union Carbide & Acres American consider enclitems in submitting tailings pond stability analysis to Btate of CD Dept of Health Includes careful presentation of all assumptions made during modeling

 JUNGE, H. R. Colorado: State of 16582 80/03/21 25pp.
- 8007020708 Corrects typographical errors in 800602 response to Item 1 Replacement Page 3 enci THOMPSON M A Cyprus Mines Corp 16566 80/06/07 2pp
- --8007020712 Corrected Page 3 in 800602 response to Item 1 + Cyprus Mines Corp 16566 80706709 ip

- 8007070195 Lists prioritized directives in order to expedite contract completion Further statistical analysis need not be undertaken EADIE.8 Uranium Recovery Licensing Branch FIN 8-2214 80/06/02
- 8007100431 Responds to 800226 request for review of Cotter Corp proposal re disposal of contaminated trash in U mill tailings impoundment Disposal will have no adverse effect on function of impoundment M/o encl consultant comments GCARAND. R A Uranium Recovery Licensing Branch 80/05/19 200
- 6007110454 Forwards 800613 testimony presented at Railroad Commission of TX hearing on application for surface mining & reclamation permit for project Requests issuance of permit as soon as possible DAVIS.0 R Anaconda Co , Anaconda Copper Co Div 16616 80/06/16
- --B007i10457 Testimony of Anaconda Copper Co by GR Davis on 800613,before flailroad Commission of TX Pp 1-11 Draft affidavit & resume encl DAVIS.O R Anaconda Co , Anaconda Copper Co Div 16616 80/06/16 14pp
- --8007110459 Testimony of Camp Dresser & McKee by ED Sethness on 800413, before Railroad Commission of TX Pp 1-5 Resume encl SETHMESS ED Camp Dresser & McKee, Inc., Environmental Sciences, D.v. 16616 80/06/13 7pp
- --8007i10462 Testimony of EL Reed & Associates by EL Reed on 800613, before Railroad Commission of TX Pp 1-7 Resume encl REED.E L Ed L Reed & Associates. Inc 14616 80/06/13 7pp
- 8007150045 "Principle Parameters for Radiological Assessment " # Dawn Mining Co 14708 80/05/31 22pp
- 8007170660 Forwards "Low Level Waste Licensing Branch Raview of Nuclear Engancering Co. Inc Application for Renewal of Beatty, NV License." In response to request SMITH.R D Low Level Waste Licensing Branch 80/07/03 ip
- --8007170468 "Low Level Waste Licensing Branch Review of Nuclear Engineering Co.Inc Application for Renewal of Beatty.NV License "

 * Low Level Waste Licensing Branch 80/07/03 40pp
- 8007180021 Forwards Nuclear Engineering Co, Inc 800404 application for renewal of State of NV radioactive matl license at Beatty low level waste disposal site State of NV has requested NRC comment KERR, G W Assistant Director for State Agreements Programs SA/RJD 800/06/03 350pp
- B0071B052B Requests establishment of waste mgt docket file WM-I3 at H Street PDR Docket file concerns technical assistance to State of NV for state renewal of Beatty, NV low level waste facility license HEDDINOS, TP Low Level Waste Licensing Branch B0/07/09 ZPP
- 8007210104 Forwards completed Page 4 of Operational Monitoring Rept 3-80. CAIN.J Cotter Corp 16748 80/06/30 2pp
- 8007210138 Ack receipt of 800619 ltr re proposed study of potential U development in CO Total impact study should be conducted rather than case by case evaluation Requests moral & financial support for study REMPLE.L Citizens for Safe Environment 16797 80/06/22 1p
- BOD7220025 Forwards long range plan for processing of Uravan mineral belt ores & supporting documentation submitted to Radiation & Halardous Waste Control Div of CD Dept of Health REXEMEYER, P.C. Union Carbide Corp. 16693, 80/06/19 4pp
- --8007220032 NUS-3594 "Facilities Stack Audit,Uravan U Mill " * NUS Corp 16693 80/05/23 84pp
- ---8007220036 NUS-3582
 "40CFR190 Related Radiological Doses Due to Operation of Uravan U Nill "BARTRAM, B W. ENGLEHART, R W., CONWAY, T W NUS Corp 16693
- --8007220042 "Cost Rept Tailings Storage & Evaporation Pond Evaluation, Long Park & Paradox Valley Sites Uravan U Mill.Montrose County,CD." for Union Carbide Corp BUDDY,J R Dames & Moore 16693 80/05/23 65pp

- --B007220049 "Tailings Storage / Evaporation Pond Evaluation,Long Park & Paradox Valley Sites, Uravan U Mill, Montrose County, CO." for Union Carbide Corp BDDDY, J R Dames & Moore 16693 80/05/23 200pp
- --8007220056 "Uravan Tailings Piles Prior to Reclamation " BROWN.R Union Carbide Corp 16693 80/06/09 ip
- --8007220074 "Proposed Plans & Estimated Costs for Tailings & Reclamation Mill Decommissioning & Pond Reclamation at Uravan Mill for Surety Purposes " Memo dtd 800530 re requirements for sub-surface disposal permit encl # Union Carbide Corp 16693 80/05/30 19pp
- ~~8007220081 "First Quarter, 1980 Summary, Environ & Health Physics Monitoring Uravan.Co " JONES, R. K. Union Carbida Corp. 16693 80/03/31 63pp
- ---B0072200B7 "1979 Annual Summary,Environ & Health Physics Monitoring, Uravan,CO " * Union Carbide Corp 16693 79/12/31 200pp

"Review of Available Meteorological Data Representative of Uravan U Hill Bite Vicinity " COFFEY,H E . MAXMELL,D R . CONMAY,T W NUB Corp 16693 BO/05/07 21pp

--8007220111 NUB-0544

107220111 NUS-1944
"Correlation Analysis of Variables Affecting Airborns
Radioactive Particulate Concentration Near Uravan U Hill "
Intl Engineering Co. Inc ltr forwarding preliminary const
satimates of proposed disposal sites and I
BARTRAM. B W., DOUGHERTY, D X., ENGLEHART, R W. NUS Corp. 16493
B0/03/13 200pp

- --8007220119 "Preliminary Gentechnical Investigation of Proposed Spring Creek Mesa Tailings & Effluent Disposal Site Near Uravan.
 - CO ... KING.K B. Morrison Knudsen Co , Inc. 16493 80/05/31 150pp
- 8007230145 Responds to 800623-24 memos transmitting State of NM response to Church Rock tailings dam stability issues raised in NRC 791210 Itr NRC geotechnical consultant is reviewing response to determine if issues are addressed properly SCARAND, R A Uranium Recovery Licensing Branch 80/06/30
- B007230720 Forwards R Kinneson review of NM Environ Improvement Div proposed verification sampling scheme W/o encl EADIE.Q Urantum Necovery Licensing Dranch 80/07/09 ip
- B007250150 Requests confirmation of 800418 telcon re application for source matls license NRC will not require revised amended application under new guidelines since environ work was based on ald guidelines SHERMAN, II D Arnold & Porter 16779 80/06/25 2pp
- 8007280194 Forwards as-built plans for breach repair & tailings dam expansion W/o encl United Nuclear Corp 14817 80/06/27 1p
- B0072902PB Confirms that B0062b ltr accurately describes NRC opinion refiling of amended application w/State of CO Radiation & Hazardous Waste Control Div for matls license BCARAND, R A. Uranium Recovery Licensing Branch 80/07/08 ip
- 8007310497 Forwards "Solid Waste Disposal Rept." for June 1980 to Dept of Health-Radiological & Hazardous Waste Div JONES.R K Union Carbide Corp 16854 80/07/15 1p
- --8007310800 "Rolld Woste Disposal Rept," for June 1980 * Union Carbide Corp 80/07/15 67pp
- XPORTLIC EXPORT AND IMPORT LICENSES
- 7906200225 Requests Executive Branch position re GE application for license to export six detector assemblies to India Forwards 790507 application M/o encl DPLINGER, 0 Q Assistant Director for Export/Import & International Bafeguards 79/05/15 ip

- B007010009 Executive Branch position re DOF application for license Solventy 22 & kg U.containing & 45 U-235 to France Ltr of assurance encl License should be granted
 NOSENZO,L V State, Dept of Bureau of Oceans & Internat) Environ & Scientific Affairs 80/06/18 3pp
- 8007010012 Executive Branch position re Dept of Navy application for license to export 3.019 kg depleted U to Australia License should be granted NOSENZO,L V State. Dept of Bureau of Oceans & Internati Environ
- anteo State Dept of Bureau of Oceans & Internati Environ & Scientific Affairs 80/06/11
- 8007010014 License for Marubeni America Corp to export & g Pu.l g Pu-242.10 g U-233 & 100 g U oxide to Japan PETERSON,M R Assistant Director for Export/Emport & International Bafeguards 2H0126-OH 80/06.19 2pp
- 8007010019 Executive Branch position re application for licenses to export highly enriched U to Japan Since no intermediate consignee is used, license condition requiring specific modes of transport is no longer necessary NOSENDOL V State, Dept of, Bureau of Doeans & Internatl Environ & Scientific Affairs 80/06/18 ip
- B007010102 Application by Westinghouse for license to export one BF3 proportional counter to West Germany POCHAL, W.F. Westinghouse Electric Corp. ZE-10302 80/06/09 1p
- B007010170 License for Borg-Warner Corp to export carbon & stainless steel globe & check gate valves to Belgium PETERSON,M R Assistant Director for Export/Emport & International Bafeguards 60/06/18 ip
- 8007010972 Requests extension of expiration date of license to 810630, because of delay on some items due to inability to acquire raw matl ROGERS.W F Metal Bellows Corp 80/06/19 1p
- 8007010577 Application by Aldrich Chemical Co for license to export 5 kg deuterium in 20 kg deuterium oxide-to Belgium EDELSTEIN,B Aldrich Chemical Co , Inc (subs of Sigma-Aldrich Corp) 12/80 80/06/12 ip
- B007020014 Application by Aldrich Chemical Co.Iπc for license to export I kg deuterium in 5 kg deuterium oxide to New Zealand EDELBTEIN B Aldrich Chemical Co , Inc (subs of Sigma-Aldrich Corp) 10/80 BO/06/12 ip
- B007020020 License for Panalpina Airfreight, Inc to export 7 g U. containing 1 &i g U-225, to Finland
 PETERSON, M R Assistant Director for Export/Import & International Safeguards B0/06/18 2pp
- 8007020057 Requests assistance in obtaining necessary ltr of assurance for application for export license PETERSON.M R Assistant Director for Export/Import & International PETERSON, M R Assist. Bafeguards 80/06/18
- 8007020084 Application by GA Co to amend license to extend expiration data until Jul 1982
 MDHRY,W R General Atomic Co (subs of Gulf Oil Corp) IEL-1185-B0/06/05 ip
- 8007020093 Advises that NRC 800516 formal vote determined that applications to export SNM to India did not meet criterie for issuance Applications were referred to President for further consideration Office of International Programs, Director 80/05/12
- 8007020123 Advises that application to export specially designed parts to components to India was referred to President for addiction of the Components to India was referred to President for addiction makes criteria of Atomic Energy Act
 SHEA, J R Office of International Programs. Director 80/06/16
- 8007020153 Application by Kawecki Berylco industries.Inc for license to export 414 4 ft Zirconium II seamless tubing to West TRIOLO.K Kawecki Berylco Industries. Inc 78408 80/06/03 1p
- 8007020238 Forwards DRG Intl.Inc 1tr re export license W/D encl PETERSON.N R Assistant Director for Export/Import & International Safeguards 80/06/18 lp

- 7020260 Frecutive Branch position re DOE application for license to aport 610 mixed oxide fuel pins to United Kingdom Ltrs of ssurance encl License should be granted COENZOL. V State, Dept of Bureau of Oceans & Internati Environ & _ientific Affairs 80/06/18 App
- 7020274 License for Transnuclear.Inc to export 30,746 kg U. ontaining 1.274 kg U-235.& 129,224 kg natural U to Germany ETERSON.M R Assistant Director for Export/Import & International afeguards NUM-319 80-059/ 80/06/19 2pp
- 7020277 Forwards 800726 license application & favotable recutive Branch views for review Under 10CFR110.Commission eview no longer required M/o encls ETERSON.M R Office of International Programs, Director 80/04/23
- 7020283 Amend 4 to license for GA Co extending expiration date rom 800701 to 820701 ETERSUN.M R Assistant Director for Export/Import & International afeguards IEL-740 80/06/19 1p
- 7020289 Amend 3 to Litense 3 for Eastman Kodak Co extending spiration date from 800701 to 820701 ETERSON.M R Assistant Director for Export/Import & International afeguards 80/06/20 ip
- 7020344 Requests assistance in obtaining necessary ltr of assurance or application for export license ETERSON.M R Assistant Director for Export/Import & International afaguards 80/06/18 ip
- 7020346 Submits application to amend license to extend expiration ate until 800630.to transfer 0 231 mC; tritium to United ingdom
 UTTME.O KMS Fusion, Inc. (subs. of KMS Industries, Inc.)
- 0/05/05
- 17020349 Requests assistance in obtaining necessary ltr of assurance or application for export license EYERSON.MR Assistant Director for Export/Import & International afeguards 80/06/18 lp
- 17020351 License for Marubeni America Corp to export 27,195 kg U.
- ontaining 800 kg U-235. to Japan
 'ETERSON'N R Assistant Director for Export/Import & International afeguards AHOIMAW 80/06/18 2pp
- 7020373 License for Edlow Intl Co as agent for Heridian Enterprises a expant 508 kg U.contained in 600 kg depleted U oxide lowder, to Taiwan "ETERSON.N R Assistant Director For Export/Import & International lafeguards IM-1 80/06/24 2pp
-)7020379 Application by CERAC, Inc. For license to export 43 94 Eg horium contained in 50 kg thorium oxide, to West Germany, OLTON, E. Cerat, Inc. 80/04/20 ip
- 17020383 Application by Isotope Products Labs for license to export g solid corium metal oxide as source w/beryllium holder, o France
- ELM.K Isotope Products Laboratories W/O 7853 80/06/19 1p
- 17020425 Forwards license application, favorable Executive Branch /iews & proposed license for export of 27 1 kg U to West Permany for fuel element fabrication License will be issued
- R Assistant Director for Export/Import & International BO/06/19 ip Bafeguards
- 0702065B forwards China Natl Instruments 800606 ltr re use of selfnowered detectors Westinghouse 800611 memo encl POCHAL, W.F. Westinghouse Electric Corp. 80/06/16 3pg.
-)7020734 Forwards Esecutive Branch response re encl pending export license application for advance info Requests initiation of final review to facilitate early response to forthcoming action paper W/o encls SHEA, J R Office of International Programs, Director 80/06/18
- Office of International Programs, Director 80/06/18
- D7030063 Application by Aldrich Chemical Co.Inc for license to export) kg deuterium.in 5 kg deuterium oxide to South (orea
- vorea EDELSTEIN, B Aldrich Chemical Co . Inc (subs of Bigma-Aldrich Jorp) 14/80 80/06/12 1p

- 8007030236 Requests assistance in obtaining necessary ltr of assurance for entl 800606 export license application W/o encl PETERSON, M R Assistant Director for Export/Import & International Safaguards 80/06/18 ip
- 8007030350 License for Metal Beliams Corp is amended to extend expression date until 810730 All other conditions remain unchanged PETERSON.M R Assistant Director for Export/Import & International Safeguards A 14471-2 80/06/24 ip
- B007070004 Forwards applications for license to export fuel rod nuclear assay sys & CF-252 source to West Germany HANSEN.L E Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/06/16 lp
- --8007070006 Application by Exxon Nuclear Corp for license to export 1 09 mg Cf-252 neutron source to West Germany HANSEN.L E Exxon Nuclear Co , Inc (subs of Exxon Corp) 80/06/16 1p
- -- B007070009 Application by Ezzon Nuclear Co.Inc for license to export fuel rad nuclear assay sys to West Germany HANSEN.L E Ezzon Nuclear Co., Inc. (subs. of Ezzon Corp.) 80706/16 Jpp
- 8007070007 ticense for Westinghouse to export 180 uC: Np-237.contained in 12 radiation surveillance capsules to Taiwan PETERBON, H R Assistant Director for Export/Import & International Safeguards 80/06/24 2pp
- 8007070018 Application by Transnuclear. Inc. to amend license to extend naryovers appracasion by transnuclear, inc to expiration date to 011101 MATSON,V Transnuclear, Inc 80/06/19 ip
- 8007070023 Forwards application for license export source math to Italy KEENAN, R.P. Westinghouse Electric Corp. ICS-0417 80/06/12 1p.
- --8007070024 Application by Westinghouse for license to export 3 7 kg U-235, contained in 617 kg depieted U.to Italy HERSCH.M M Westinghouse Electric Corp ICS-0417 80/06/12 ip
- B007070025 License for GA Co to export 1 035 kg U-233, contained in 5 2 kg U as TRIGA WirH fuel cluster elements, to Taiwan PETERSON, & R Assistant Director for Export/Import & International Bafeguards 80/06/24 2pp
- 8007070029 Application by Sigma Chemical Co for license to export 10 kg deuterium to New Zoaland * Sigma Chemical Co (subs of Sigma-Aldrich Corp.) D-46 HO/06/13 Ip
- 8007070034 Application by Borg-Warner Corp.Nuclear Valve Div to amend license to extend expiration date to 810701 HAN.S Y Dorg-Warner Corp., Nuclear Valve Div CSH/80/256, 30/06/19 19
- 8007070038 ticense for Mitsubishi Intl Corp to export 450 mCi Cf-252. NOTATION OF THE STATE OF THE ST
- 8007070041 Application by Westinghouse for license to export three WL-6377 compensated ionization chambers to France POCHAL-W F Westinghouse Electric Corp ZE-200399A 80/06/16 ip
- 8007070047 License for Chem-Nuclear Sys, Inc to export auxiliary deminerizer sys, including ion-exchange resins, filtration mati-air compressor, lead shields, pumps, hoses & miscellaneous parts, to Talwan PETERSON, H.R. Assistant Director for Export/Import & International Safeguards 80/06/24 ip
- 8007070111 License for GE to export 0 25 kg U-235, contained in 2 5 kg PARTY DELICATION OF THE TATE OF THE TAIL OF THE TRANSPORT OF THE TRANSPORT OF THE TAIL OF THE TRANSPORT OF T
- 8007070125 Submits breakdown for Taiwan fuel designed loading for Manshann 1 & 2 Total equals 162,911 kg, containing 4,474 kg V-235

 HESS.R J Westinghouse Electric Corp 80/06/19 ip
- 8007070140 Forwards Nukem Ombh of West Germany telex re export & storage of 129,200 kg natural U.containing 919 kg U-235. MATSON,V Transnuclear, Inc 80/06/02 2pp

- 8007070145 Forwards Nukem Gmbh telex re delay in export of highly
 - Transnuclear, Inc 80/06/09 3pp
- 8007070425 License for Halprin Supply Co to export 125 mCi tritium, contained in fails in Model 1127-E static electricity detection meter, to Singapore PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/06/24 2pp
- 8007090028 Transcript of 800516 open Affirmation Session 80-23 in Washington, DC re order in Tarapur export Pp 1-3 * Commission 80/05/16 4pp
- ~-8007090030 Informs of correction to SECY-80-238 re proposed exports of fuel & components to Tarapur Commission SECY papers cited are incorrectly referenced Draft memorandum & order encl BHSA.J R Office of International Programs, Director 80/05/13
- ~-8007090033 SECY-80-238A
 - ov/ovoudd SELY-80-2:884
 Forwards MMSS technical review for Commission's
 consideration in conjunction w/review of pending Tarapur
 fuel & component exports
 SHEA.J R Office of International Programs, Director 80/05/13
- ~-B00709003B Forwards proposed NMSS technical review for Commission consideration re proposed exports of fuel & components to Tarapur BURNETT,R F Division of Safeguards 80/05/12 4pp
- 8007090104 Responds to Subcommittee on Nuclear Regulation 800501 ltr posing questions re Commission approach to foreign health & safety issues Commission issued decision on reactor export to Philippines on 800506 W/respo
- --8007090114 Order granting issuance of licenses to Westinghouse for export of reactor to Philippines Separate Commissioner opinions encl
 CHILK, S J Office of the Secretary of the Commission 80/05/06
- B007090109 License for QA Co to export fuel cluster assembly tools, fuel cluster handling tools, fuel rod insp device & fuel rod storage rack, to Talwan PETERSONAN R Assistant Director for Export/Import & International Bafeguards B0/06/24 1p
- 8007100027 License for Byron Jackson Pump Div.Burg Warner Corp. to export specially designed or prepared parts & components for use in primary coolant pumps & other pumps to Taiwah PETERBON.M R Assistant Director for Export/Import & International Bafeguards 80/06/24 ip
- B007100146 Executive Branch position re Radium Chemical Co.Inc application for amend to license to export tritium to Buitzerland. Belgium & West Germany License amend should be granted NOBENZO.L V State.Dapt of Bureau of Oceans & Internati Environ & Scientific Affairs 80/06/24 2pp
- 8007100263 Forwards application by Westinghouse for license to export 6.0 kg U oxide pellets.containing max of 4 5% U-238, to KEENAN, R P Westinghouse Electric Corp ICS-0412 80/04/12 ip
- ---8007100271 Application by Westinghouse for license to export 6 0 kg U axide pellets, containing max of 4 5% U-235, to Belgium KEENAN, R P Westinghouse Electric Corp ICS-0412 80/06/12 ip
- B007100281 Forwards application by Mitsui & Co.Inc for license to export 99 kg U-235.contained in 3.640 kg UF-6.to Japan BAIKI.T Mitsui & Co., Ltd 80/06/03 lp
- --8007100287 Application by Mitsui & Co.Inc for license to export 99 kg U-235 contained in 3.640 kg UF-6, to Japan TAHA, K Mitsui & Co., Ltd MBK-TR-12 80/06/09 ip
- 8007100341 Requests assistance in obtaining ltr of assurance for encl 800609 application for Export License XSNM-1694 W/o application PETERSON, M R Assistant Director for Export/Import & International
- Assistant Director for Export/Import & International 80/06/27 ip Bafaquards
- 8007110010 Forwards application by Canadian Embassy for license to export 4 x 0 5 g Pu Metal #949 e to Canada HARRISON, J E Laos 80/06/09 ip

- --8007110012 Application by Canadian Embassy for license to export 4 x 0 9 g Fu Metal #949 e.to Canada HARRISON J E Canada 80/06/09 2pp
- 8007110021 Forwards application for license to export U oxide pellets to Belgium KEENAN.R P Westinghouse Clectric Corp ICS-0412 80/06/12 ip
- B007i10029 License for Metal Bellows Corp to export spare nuclear parts to Spain is amended to add another authorized ultimate
- f Assistant Director for Eipart/Impart & International 14845 80/06/27 1p Safeguards
- 8007110142 Transcript of 800513 closed meeting in Washington DC re disrussion of Tarapur export license Pp 1-14 * Commission 80/06/19 16pp
- B007110213 License for US Dept of Navy to export 3.019 kg depleted U.as component of 20mm ammunition, to Australia PETERSON H R Assistant Director for Export/Import & International Safeguards SER 63/779042 B0/06/27 Spp
- 8007110218 License for Westinghouse to export three compensated ionization chambers Model WL 6377 to France PETERSON N R Assistant Director for Export/Import & International Bafeguards ZE-20359 80/07/01 ip
- 8007110226 License for Westinghouse to export one proportional counter, Model WX33785, to France PETERSON.M R Assistant Director for Export/Import & International Safeguards ZE-20356 80/07/01 1p
- 8007110237 Application by Revter-Stokes, Inc for license to espart two fission counters, compensated somitation chamber & neutron ionization chamber to Mexico SKARUPALJ D Revter-Stokes: Inc 80/06/25 1p
- B007110241 License for Aldrich Chemical Co. Inc to export 1 kg deuterium.contained in 5 kg deuterium oxide.to Israel PETERSON:M R Assistant Director for Export/Import & International Safeguards 13/80 80/07/02 2pp
- 8007110252 Requests assistance in obtaining itr of assurance for encl 800612 application for Export License XSNM-1695 W/o application PETERSON M R Office of International Programs, Director 80/06/27
- B007110271 Amend 1 to license for Transnuclear, Inc. adding Allied Chemical Corp as supplier of natural U only PETERSDN,M R Assistant Director for Export/Import & International Safeguards NUX-319 80-059 80/07/01 1pp
- 8007110275 Forwards application by Mitsui & Co.inc for license to export 5.429 kg enriched U hexafluoride, enriched to max 3 95%, to Japan SAIKI,T Mitsui & Co., Ltd. 80/06/12 ip
- ~-800/110283 Application by Mitsul & Co.inc for license to export 5,429 kg enriched U hexafluoride,enriched to max 3 95% to Japan # Mitsul & Co., Ltd MBK-F3-86 (A) 80/06/12 ip
- B007110467 Forwards NUKEM B00611 ltr correcting typing error in supplemental info accompanying 800430 export license application & NUKEM 800611 ltr to ANL containing addl supplemental data MATSDN:V Transnuclear, Inc 80/06/18 7pp
- 8007j10480 Requests amend to license, to import addl 200 g Pu MATSON.V Transmuclear, Inc. 80/06/18 tp
- BOO7110491 License for Edlow Intl Co to export 0 50 g Pu, as Pu sulfate tetrahydrate: to Japan PETERSON, M R Assistant Director for Export/Import & International Bafeguards 8-89-79 BO/06/27 2pp
- 8007110528 Submits application to amend license to export adding Fuerios Electricas de Cataluna as ultimate consignee ROGERS.W F Metal Bellows Corp 80/06/26 1p
- 8007140253 Forwards Transnuclear, Inc 800418 re 80050A export license application W/o PETERBON, M R Assistant Director for Exp Safeguards 80/06/30 1p

- 8007140258 Advises that SNM shall be exported under general license regulations effective 800421 Application is being processed as component license WRIOMT.BL Office of International Programs. Director 80/04/18
- 8007140266 Advises that 15-day waiting period requirement was waived for license applications to eiport byproduct matl & components to Eixon West Obiman facility PETERSONN R Assistant Dijector for Export/Import & International Safeguards 80/06/30 1p
- --8007140274 License for Exxon Nuclear Co. Int to export one fuel rod nuclear assay sys to Hest Germany PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/06/30 Ip
- 8007140283 Advises that IS-day waiting period requirement was waived for license application to export byproduct matl & components to Exian West German facility PETERSON.H R Assistant Director for Export/Import & International Safeguards 99/06/27 lp
- --8007140288 License for Exxan Nuclear Co.Inc to export 1 09 mg Cf-252 neutron source to West Germany PETERSON M R Assistant Director for Export/Import & International Safeguards 80/06/27 2pp
- 8007140293 Amend I to license, extending expiration date from 801101 to 811101 & adding two suppliers All other export conditions remain unchanged
- PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/06/30 pp
- B007140539 SECY-80-301 1007440539 SECY-80-301
 Requests review of proposed issuance of license for GE to export components to Finland Equipment destined for country not previousty authorized to export per Nuclear Nonproliferation Act of 1978 Recommends issuance SHEA.J R Office of International Programs, Director 80/6 80/04/20
- --8007140546 Forwards application for license to export components to Finland Ltr of assurance & draft license encl HILSON, B D General Electric Co BDW-80013 80/01/30 3pp
- 8007140552 SECY-BO-294 Informs of Executive Branch response on pending license for Union Carbide Corp to export U-235 to France SHEA.J R Office of International Programs. Director 80/06/18
- --8007140360 Executive Branch position re application by Union Carbide Corp to export 9 85 kg U-235, enriched to 93% U, to France License should be issued Ltr of assurance encl NOSENZO, L V State, Dept of, Dureau of Oceans & Internati Environ & Scientific Affairs 80/06/11 2pp
- B007140567 Forwards application for export license for minor nuclear papart Ltr of assurance required PETERSON.H R Assistant Director for Export/Import & International Safeguards B0/06/27 ip
- 8007140577 Amend 1 to license for Radium Chemical Co Inc. extending expiration date from 800601 to 810701 & permitting change in intended distribution of tritium gas PETERSON, MR Assistant Director for Export/Import & International Safeguards 80/07/03 1p
- B007140579 License for Westinghouse to export proportional counter to be used as neutron detector for neutron source strength determination in GKSB research reactor, to West Germany PETERSON, MR Assistant Director for Export/Import & International Bafeguards 80/07/03 ip
- B007140583 Forwards Executive Branch responses on pending applications for Export Licenses XSNM-1431 & XSNM-1564 which require Commission review Final review should begin as soon as possible W/o encls
 SHEA.JR Office of International Programs, Director 80/07/01
- 8007140586 License for DDE to export U-235, contained in 27 1 kg U.to Mest Germany
 PETERSON, N.R. Assistant Director for Export/Import & International
- 8007140588 License for Isotope Products Lab to export 1g Cm-244, solid volume Citable for lactops Products Lab to export 1g Cm-244, solid curium metal oxide, to France PETERSDN, M R Assistant Director for Export/Import & International Bafeguards 80/06/30 2pp

- 8007140596 License for Teledyne Wah Change Albany to export 400 lbs Zircaloy-2 tube shells to Norway PETERSON,M R Assistant_Director for Export/Import & International 2pp
- 8007140603 License for Cerac, Inc to export 43 94 kg thorium, contained in 30 kg thorium oxide, to West Germany PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/06/30 2pp
- 8007140696 Discusses IE insp of License XBNM-1426 on 800610 No noncompliance noted Major areas inspected compliance w/ requirements of 10CFR70 & 71 re packaging of radioactive matl for transport NORDERHAUG. L R 80/06/25 2pg Region 5. San Francisco. Safeguards Branch
- B007140711 License for Aldrich Chemical Co to export 1 kg deuterium, contained in 5 kg deuterium oxide, to Bouth Korea PETERBON M R Assistant Director for Export/Import & International Bareguards 14/80 80/07/02 2pp
- 8007150001 Forwards application for export license for minor nuclear export its of assurance required W/o encl PETERSON.N R Assistant Director for Export/Import & International Bafaguards 80/07/02 ip
- 8007150003 License for Sigma Chemical Co to export 10 kg deuterium Oxide to France
 PETERSON, M. R. Assistant Director for Export/Import & International Safeguards D~45 80/07/02 2pp
- 800715000B License for Aldrich Chemical Co to export 1 kg deuterium oxide to New Zealand
 PETERSON.M R Assistant Director for Export/Import & International Bafeguards 10-80 80/07/02 2pp
- 8007150012 License for Aldrich Chemical Co to export 1 kg deuterium, contained in 5 kg deuterium oxide, to Venezuela PETERSON, M R Assistant Director for Export/Import & International Safeguards 11/80 80/97/02 2pp
- 8007150030 Cancels Export License Application X8NM-1486 since matl can be exported under licensee general license WRIGHT.B L Office of International Programs, Director 80/06/30
- 8007150034 Cancels Export License Application XRNM-1631 since matt can be exported under licensee general license WRIGHT.B L Office of International Programs. Director 80/06/30
- B007130D36 Discusses Transnuclear 800514 application to export 103 258 kg U.enriched to 93 3% U-235, to West Germany for conversion by NUKEM & fabrication at Hobeg into THTR fuel Forwards 1tr justifying need for highly enriched U MENNICKEN. J B Euratom Supply Agency (Belgium) 80/06/23. App
- --8007150040 Provides technical background info necessary for US evaluation of technical & economic justification for Transnuclear export of highly enriched U to Hest Garmany to fuel THTR reactor MATZ.0 . MULLER.H Nukem GmbH 80/05/21 6pp
- BOO7150039 Cancels Export License Application XSNM-1487 since mat1 can be exported under licensee general license WRIGHT.D L Office of International Programs, Director 80/06/30
- 8007150050 SECY-B0-298
 Recommends return of Rockwell Intl application for license to export specially-designed valve to India w/o action Executive Branch prefers returning w/o action as apposed to denial due to political differences involved Draft ltr encl. SHEA, J R Office of International Programs, Director BOY
- B007150062 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl. PETERSON M R Assistant Director for Export/Import & International Bafeguards 80/07/02 p
- 8007190063 License for Aldrich Chemical Co to export 5 kg deuterium, contained in 20 kg deuterium oxide to Belgium PETERSON,M R Assistant Director for Export/Import & International Bafeguards (2/80 80/07/02 2pp

- B007150073 License for Transhuclear, Inc to export 32 737 kg U-235, contained in 35 GBB kg U, to Sweden PETERSON.M R Assistant Director for Export/Import & International Bafeguards B0/06/30 2pp
- 800715007B License for Transhuclear, Inc to export 67 736 kg U-235, contained in 72 6 kg U.to France PETERBON.M R Assistant Director for Export/Import & International Bafeguards 80/06/30 2pp
- 8007150353 Forwards supplemental info on inventory forwarded directly to US Dept of State by Euratom Supply Co
 MATSON, V Transnuclear, Inc. 80/06/18 3pp
- 8007150836 Forwards Executive Branch response on pending application to export Pu & U to United Kingdom Application will require Commission review Application & amend encl W/o encls SHEA.J R Office of International Programs, Director 80/06/27 ip
- 8007160394 Forwards application by Monsanto Research Corp for license to export one neutron source Model 2765, containing approx i mg Cf-202, to India
- HOADLEY, S D Monsanto Research Corp 191-9AO(1) 80/07/01 1p
- ~-8007160399 Application by Monsanto Research Corp for license to export one neutron source Model 2765.containing approx 1 mg Cf-252. to India HOADLEY.S D Monsanto Research Corp L91~9AU(I) 80/07/01 1p
- 8007160403 Application by Aldrich Chemical Co.Inc for license to export I kg deuterium.contained in 5 kg deuterium oxide.to Jamaica EDELBTEIN.B Aldrich Chemical Co., Inc. (subs. of Bigma-Aldrich Corp.) 15/80 80/06/27 ip
- 8007160802 Ltr of assurance re Transnuclear. Inc 800523 application for license to export 704 997 kg U-235.contained in 21.0447 kg total U & 0 034 kg U-235.contained in 1 kg total U.to Switzerland MULLER.R E Switzerland 651 513 80/06/17 lp
- 8007140824 Cancels Export License Application XSNM-1549 since matl can be exported under general component license MRIGHT,B L Office of International Programs. Director 80/06/30
- 8007170003 Executive Branch position re Tech/Ops application for license to export 5.000 kg depleted U.in form of metal shielding to Albania.Bulgaria.Czechoslovakia.West Germany. Hungary, Mongolia.Poland & Soviet Union NOSENZO, L. V. State.Dept of, Bureau of Oceans & Internatl Environ & Bcientific Affairs 80/07/07 2pp
- 8007170072 Executive Branch position re Edlow Intl Co application for license to export 10.000 C1 tritium in bulk gaseous form to Canada License should be granted NOSENZOL V State-Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/07/03 2pp
- B007170077 License for Sigma Chemical Co to export 10 kg deuterium oxide to New Zealand PETERSDN.M R Assistant birector for Export/Import & International Bafeguards B0/07/08 2pp
- B007170080 License for Westinghouse to export three compensated ionization chambers to France PETERBON.M R Assistant Director for Export/Import & International Bafeguards B0/07/08 ip
- 8007170176 Response in apposition to Ctr for Development Policy 800613 patition to intervene re nuclear reactor export to South Korea If patition granted, public hearing must be rejected per applicable statute & regulations W/Certificate of Svc BECKER. J M Office of the Executive Legal Director 80/07/14 24pp
- B007170191 Response in opposition to Ctr for Development Policy B00613 patition to intervene re nuclear reactor export to South Korea Public participation will adversely affect public interest Certificate of Svc encl
 BETTAUER,R J State, Dapt of B0/07/14 30pp
- 8007170204 Executive Branch position re Halprin Supply Co application for license to export approx 125 mCi tritium to Singapore License should be granted MOSENZOL V State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/12 2pp

- 8007170223 Executive Granch position re GA Co application for liconse to export 1 035 kg U-235 contained in 5 2 kg U-to Taiwan Ltrs of assurance encl License should be granted NOBENZOL V State Dept of. Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/12 Spp
- 8007170229 Ltr of assurance re Transnuclear.Inc 800523 application for license to export 704 997 kg U-235, contained in 21,044 7 kg total U t 0 034 kg U-235, contained in 1 kg total U, to Switzerland MARCHAL, J European Communities. Commission of 80/06/13 lp
- 8007170235 Executive Branch position re Gladix Corp application for license to export 40.000 lb Zircaloy-4 trex tubes to Taiwan Ltr of assurance encl License should be granted NOSENZOL V State,Dept of: Bureau of Oceans & Intornati Environ & Scientific Affairs 80/06/12 4pp
- 8007170244 SECY-80-317
 Forwards Executive Branch responses to two pending export
 license applications for Taiwan
 SMEA, J.R. Office of International Programs, Director 80/07/01
- --B007170251 Forwards Executive Branch analysis re Westinghouse application for license to export 8.845 kg U-235.contained in 325.822 kg U.to faiwan NSEMOL V State.Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/12 13pp
- --B007170258 Application by Westinghouse for license to export U dioxide sintered pellets encapsulated in sealed fuel rods & assembled into fuel assemblies, to Toluga * Westinghouse Electric Corp 109-7823 78/11/17 ip.
- 8007170235 Executive Branch position re Tech Aid, Inc application for license to export 8,613 343 Kg heavy water to Taiwan End use statement encl HELFRICH, GF State, Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 80/06/26 2pp
- --8007170262 Forwards supplementary and use statement to application for license to export 4 tons heavy water to Taiwah HU.X Coordination Council for North American Affairs 80/05/14 28p
- 8007170523 SECY-80-318
 Recommends approval of proposed license to allow Nissho-Iwai
 American Corp to export 47 162 kg U & 44 003 kg U-235 to
 Japan
 SHEA, J R Dffice of International Programs, Director B0/07/01
 5pp
- --B007i70534 License for Nissho-Iwax American Corp to export 44 003 kg U-235.contained in 47 162 kg U.to Japan PETERSON.N R Office of International Programs, Director B0/07/01 2pp
- 8007180449 Forwards application for license to export 40 g U-235, contained in 1 226 g U, to France
 KEENAN.R P Westinghouse Electric Corp 109-0456 80/06/19 1p
- --8007180455 Application by Westinghouse for license to export 40 g U-235 contained in 1,226 g U. to France KEENAN.R P Westinghouse Electric Corp ICS-0456 80/06/19 ip
- B007210009 SECY-B0-316
 Recommends issuance of proposed license for Transnuctear, Inc
 to export 39 077 kg U, enriched to 93 3%, to Japan Forwards
 Executive Branch views re proposed export
 BHEALJ R Office of International Programs, Director 80/07/01
 5pp
- --8007210076 Forwards Executive Branch position re fransnuclear. Inc & Nissho-Iwai American Corp applications for licenses to export U-235 to Japan Licenses should be conditioned as noted NOSENZO, L V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/01/29 600
- --8007210083 License for Transnuclear. Inc to export 39 077 kg U.enriched to 93 3%, to Japan PETERSON,M R Assistant Director for Export/Import & International Safeguards NUK-231 78-169 B0/07/01 2pp
- B007210073 Executive Branch position re DOE application for license to export 5 37 kg U-P35, contained in 27 i kg U-to West Germany Ltr of assurance encl License should be granted, NOSENZO.L V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 80/06/11 3pp

- 8007210096 Executive Branch position re Wostinghouse application for license to export 8.845 kg U-235 contained in 325.022 kg U, to Taiwan Ltr of assurance encl License should be granted NOSENYOL V State. Dept of, Dureau of Oceans & Internati Environ & Scientific Affairs 80/06/12 13pp
- 8007210124 Amend 1 to license for Borg-Warner Corp increasing value of equipment & extending expiration date PETERSON.MR Assistant Director for Export/Import & International Safeguards A49365H 80/06/27 Ip
- 8007210129 Application by Sigma Chemical Co for license to export compounds containing deuterium to Australia STERN.H C Sigma Chemical Co (subs of Sigma-Aldrich Corp) D-47 80/06/23 ip
- 8007R10316 Application by Reuter-Stokes.Inc for license to export radiation detectors.Model RS-C6-0201-231,to Spain End use atement encl Reuter-Stokos, Inc. 80/06/30
- --8007210318 Advises of desire not to apply for extension of License XSNM-1597, due to deletion of requirement for SNM license for detectors EECKHOUT, A Router-Stokes. Inc 80/06/30 ip
- B007220107 Amends License ISNM-1699 authorizing import of 243 31 kg of U.containing 182 72 kg U-239 & 345 3 g of produced Pu Proposed amend represents no substantial change to circumstances involved in issuance of basic license MODRE.N Office of International Programs. Director 80/07/03
- --8007220114 Amends Transnuclear Inc License ISNM-1679 increasing quantity of Pv authorized for export to 545 G g PETERSUN, H R Assistant Director for Export/Import & International Safeguards 80/07/03 ip
- BOO7220207 Add1 response to FOIA request for documents re proposed nuclear reactors located near Gyaema.Korea Forwards JR Shea draft memo to Commissioners SECY-BO-229 is located in DC PDR Info partially withheld (ref FOIA Exemption 5) FELTON.J M Davision of Rules and Records 80/07/15 2pp
- --8007220214 Braft Commission paper re licenses for OE to export two reactors, XNU 7 & 8 to Korea Reactors would be located on Gyaems Forwards final Executive Branch views Info partially withheld (ref FOIA Exemption 8) SHEA, J. R. Office of International Programs. Director 80/07/15
- 3007220560 Response in opposition to Ctr for Law & Development Policy 800613 petition to intervene re license for reactor export to South Korpa lasues raised re environ impacts in foreign countries are beyond NRC jurisdiction W/Certificate of Byc. CDMAN, D Z . KENRICK, J R Westinghouse Electric Corp CDMAN, B Z Eckert, Seamans, Cherin & Mellott 80/07/14 15pp
- 1007230557 Forwards FR notice of applications for export licenses received SHEA, J.R. Office of International Programs, Director 80/07/03
- -8007230566 Notice of applications for export licenses received BHEA.J R Office of International Programs, Director 80/0 80/07/03
- OO7230602 Response in opposition to Ctr for Development Policy 800620 patitions to intervene re standing as matter of right NRC will submit upinion re possibility of discretionary hearing after Executive Branch views Cortificate of Bvc encl BECKER.J M Office of the Executive Legal Director 80/07/10.
- 007230719 Discusses application for license to export waste gas mgt treatment sys to Bouth Africa Application has been forwarded to US Dept of Commerce which assumed licensing authority over such items on 800625 PETERSON
- 107230723 Discusses application for license to export two personnel air locks to Bouth Africa Application has been forwarded to US Dept of Commerce, which assumed licensing authority over such items on 800625
 PETERSON, M.R. Assistant Director for Export/Import & International Safeguards 80/07/16 1p

- 8007240030 Forwards application for license to export 41 59 g U, containing 0 47 g U-235, & 41 59 g U, containing 0 34 g U-235, to Japan SHIMAS Hitsubishi International Corp (subs of Mitsubishi Corp.) 80/06/20 1p
- --B007240036 Application by Mitsubish; Intl Corp for license to export 41 59 g U.containing 0 47 g U-235 & 41 59 g U.containing 0 34 g U-235, to Japan End use statement encl SHIMA. S Mitsubishi International Corp (subs of Mitsubishi Corp) B0/06/20 3pp
- 8007240042 Requests Executive Branch position re Reuter-Stokes Inc application for license to export components for research Application of Perico Perico Perector for Export/Import & International PETFREDN,M R Assistant Director for Export/Import & International PETERSON, M R Assist Bafeguards BO/07/07
- 8007240046 Informs that license application for export of 8 5 metric tons of heavy water to Taiwan is being returned NRC has received info that matl is no longer required by customer since project has been cancelled PETERSON, MR Assistant Director for Export/Import & International Safeguards 80/07/09 ip
- 8007240082 Notifies that Reuter-Stokes Inc has requested withdrawal of export license application PETERBON, R Assistant Director for Export/Import & International Bafeguards 80/07/10 ip
- 8007240055 Discusses IE insp of Import License ISNM-77008 on 800411 No noncompliance noted Major areas inspected selected exam of procedures & records, interviews w/personnel & observations by inspector Portions withheld (ref 100FRZ 770)
 MARTIN.W 0 Region 1, Philadelphia, Safeguards Branch 80/05/20.
- --8007240089 IE Insp Rept 11-895/80-02 on 800411 No noncompliance noted, Major areas inspected irradiated Puel shipment, general requirements for transportation Portions withheld (ref iOCFR2 790)
 SMITH, 0 C Region 1. Philadelphia, Office of the Director DEVLIN, J W Region 1, Philadelphia, Safeguards Branch 80/05/13
- 8007240224 Forwards application for license to import 80,000 kg U, enriched to less than 3 5% U-235 from USSR HANSEN,L E Exxon Nuclear Co . Inc (subs of Exxon Corp) 80/06/23 | 1p
- --8007240247 Application by Exxon Nuclear Co.Inc for license to import 80.000 kg U.containing up to 2.800 kg U-235, from UBSR HANSEN,1 E Exxon Nuclear Co. Inc (subs of Exxon Corp.) 807/06/23 1p
- 8007240362 License for Edlow Intl Co to export 10,000 Ci tritium gas to Canada PETERSON.H R Assistant Director for Export/Import & International Bafeguards B0/07/15 ip
- 8007240370 Amend i to license for Nissho-Iwai Ambrican Corp extending expiration date from 800801 to 810801 PETER80N,H R Assistant Director for Export/Import & International Bafeguards MACPJ 2493KY 80/07/15 1p
- 8007240373 Licensa for DOE to export 6 45 kg U-235, contained in 32 6 kg U metal, to France PETER50N, M R Assistant Director for Export/Import & International Bafeguards 80/07/11 ⊉pp
- 8007240379 License Par GE to export 34 neutron detectors. Mod#1 NA-200. PETERSON, H R R Assistant Director for Export/Import & International NOW 80012 80/07/15 ip Hafeguards -
- B007240405 License for Nistho-Iwai American Corp to export 44 003 kg U-235.contained in 47 i62 kg U metal.to Japan PETERSON.K R Assistant Director for Export/Import & International Bafegyards NIAC-78-1103 E0/07/14 2pp
- 8007240410 License for Westinghouse to export 40 g U-235, contained in i.226 g U in 30-A cyclinder to France PETERSON, M R Assistant Director for Export/Import & International Bafeguards ICS-0456 80/07/15 2pp
- 8007240418 License for Transnuclear, Inc to export 704 997 kg U-235, contained in 21,044 7 kg U, & 0,034 kg U-235, contained in 1 kg U, to Switzerland PETERSON, M.R. Assistant Director for Export/Import & International Safeguards RBU 331 80-1201, 80/07/14 2pp

- 8007240421 License for Canadian Embassy to export 2 g Pv to Canada PETERSON, M R Assistant Director for Export/Import & International Safeguards 80/07/14 2pp
- 8007240434 Application by Edlow Intl Corp for license to export 20 micrograms Pu-242 in tracer solution to Japan HARMON, D W Edlow International Co SHIB-4 80/06/30 ip
- 8007240440 Executive Branch position re GE application for license to export neutron detectors to Finland License should be
- nted ENYO,L V State,Dept of, Bureau of Oceans & Internatl Environ & entific Affairs 80/07/07 3pp Scientific Affairs
- B007240447 Ltr of assurance re Westinghouse license to export 10 g U-235.contained in 1.226 g U.to France MARCHAL, J European Communities, Commission of 80/07/09 lp
- 8007240472 Forwards 800702 ltr of assurance re application for license to export 40.000 lb Zircaloy-4 trex tubes to Taiwan DEAN.D Taiwan (Republic of China) 80/07/07 2pp
- B007250030 Discusses application for license to export inservice insp sys to South Africa NRC forwarded application to US Dept of Commerce, which assumed export licensing authority over such items on B00425 PETERSON, N R Assistant Director for Export/Import & International Safaguards 80/07/17 in
- B007250033 Discusses application for license to export four sets of personnel air locks to South Africa NRC has forwarded application to US Dept of Commerce, which assumed export licensing authority over such atems on 800625 PETERSON.H R Assistant Director for Export/Import & International Safeguards 80/07/17 1p
- 8007250041 Discusses application for license to export ultrasonic insp sys to Argentina NRC has forwarded application to US Dept of Commerce, which assumed export licensing authority over such items on 800625 PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/07/16 ip
- 8007250555 Ltr of assurance re export of 213 kg U-235, contained in 6,159 kg U.to Japan 80/03/27 ip
- 8007250543 Forwards GE 800417 ltr re license application W/o encl PETERSON, M R Assistant Director for Export/Import & International Bafeguards 80/07/15 ip
- 8007250656 Forwards draft Commission Action Papers re applications for exports to Taiwan Requests comments as soon as possible BHEA, J R Diffice of International Programs, Director 80/07/18
- 8007250685 Response in opposition to Ctr for Law & Development Policy MOVELOWOOD weaponse in opposition to the far Law Blevelopmen BOOA20 petition to intervene Legislative history of Nuclear Non-Proliferation Act provides guidance to public participation W/Certificate of Svc COWAN, B Z , KENRICK, J R Westinghouse Electric Corp COWA Eckert, Seamans, Cherin & Mellott BO/07/21 13pp COWAN, B. Z.
- 8007250714 License for Sigma Chemical Co to export 10 kg deuterium axide to Australia PETERSON.H R Assistant Director for Export/Import & International Safeguards D-47 80/07/14 2pp
- B007280078 Returns 800314 application for license to export valve to India due to Executive Branch position that proposed export does not meet Atomic Energy Act criteria M/o encl 8HEA.JR Defice of International Programs. Director 80/05/14
- 8007280117 Amend 1 to license for QE changing name of ultimate consignee to Studsvik Energiteknik AB: in Sweden PETERSON.M R Assistant Director for Export/Import & International Bafeguards BDW 79202 80/07/17 ip
- 8007280131 Confirms telcon that qualification program for subj license will require 46 BWR fuel segments of which 20 will be unirradiated 9 | General Electric Co | BDW-80067 | 80/06/17 | 1p
- 8007280223 Application by Reuter-Stokes, Inc. for license to export one fission counter, Model RS-P6-1408-110, to Uraguay SKARUPA, J. D. Reuter-Stokes, Inc. 80/07/22 lpp

- B0072B02B9 Forwards 800707 application & proposed litense for export of 90,800 kg depleted U to Canada Executive Branch position not required Litense will be issued W/o encl PETERSON, H R Assistant Director for Export/Import & International Safeguards 80/07/15 ip
- 8007280293 Returns 780918 application for license to export 40.000 lb Zircaloy-4 trex tubes to Taiwan due to American Inst 800702 cancellation of order PETERSONN R Assistant Director for Export/Import & International Safeguards 80/07/15 lp
- 8007280360 Forwards application for license to export spare parts used in refueling sys that loads or unloads fuel elements into reactor to Cananda General Motors Corp BO/07/07 is
- --8007280366 Application by General Motors Corp for Excense to export spare parts in refueling sys that loads or unloads fuel slements into reactor to Canada SOKOLOWSKI, O General Motors Corp 83344 80/07/01 Ip
- 8007280372 Application by Westinghouse for license to export one compensated innization chamber, Model NL-23084, to Japan PACHAL, W.F. Westinghouse Electric Corp. 2E-60185 80/07/08 3pp
- 8007280383 Application by Air Products & Chemicals, Inc. for license to siport 54 3 g deuterium to United Kingdom NOVAKOVICH.D Air Products & Chemicals, Inc. 80/07/09 2pp
- B007280393 Application by Sigma Chemical Co for license to export compounds containing deuterium to France STERN.W C Sigma Chemical Co 1subs of Sigma-Aldrich Corp) D-48 B0/07/10 Ipp
- 8007280397 Forwards application to export 198,500 lb depleted U. contained in 200.000 lb depleted U to 75% titanium alloyed), to Canada SCHAEFFER, M R RM1 Co , RMI (stanium 80/07/07 10
- --8007280403 Application by RMI Co -- Extrusion Plant for license to export 198.500 lb depleted U.contained in 200.000 lb depleted U (0 75% titanium alloyed).to Canada SCHAEFFER.M R RMI Co . RMI Titanium 80/07/07 2pp
- 8007280407 Requests emend to export license to reflect new ultimate consignee WILSON.B D General Electric Co 80/06/17 ip
- B007280464 Requests amend extending export license
 YAHANA,K Nissho-lwai American Corp MACPJ 2473KY B0/07/03
- 8007280473 Requests import license to reimport 10 kg highly enriched U-235, contained in 55 fuel elements, along w/recovered scrap math. Prom France mat1. from France
 BALALIS.C 9 Union Carbide Corp 80/07/02 1p
- B0072B0517 Requests Executive Branch position re Monsanto Research Corpapilication for license to export Cf-252 neutron source to India CETERBUN.NR Assistant Director for Export/Import & International Bafeguards 80/07/10 ip Safequards
- 8007280525 Requests Executive Branch position re Transnuclear, Inc application for license to export BNM to The Netherlands PETERSON.M R Assistant Director for Export/Import & International Safeguards 80/07/14 ip
- B0072B0535 Requests Executive Branch position re Mitsubishi Intl Corp application for license to export SNM, in form of Make tubes, to Japan to Japan PETERSON, M R Assistant Director for Export/Import & International BO/07/14 in Safenuards
- 8007280547 Executive Branch position re Westinghouse application for amend to export likense extending expiration date to 811231 811231 NOSENZO.L V State,Dept of Bureau of Oceans & Internatl Environ & Scientific Affairs 80/07/08 2pp
- 8007280559 Executive Branch position re Edico Intl Co application license to export 3 3 mg Cf-252 to East Germany License should be granted NOSENZOL V State Dept of Bureau of Oceans & Internati.f
- andul de grances NOSENZO.L V State,Dept of, Bureau of Oceans & Internat1.F Scientific Affairs = 60/07/}1 | 2pp

- 8007280569 Amend I to license for integrated Photomatrix Inc changing quantity from 528 micrograms U-235 to 528 mg U-235 (99 9% enrichment)
 PETERSON, M.R. Assistant Director for Export/Import & International Bafeguards 60/07/14 ipp
- B007290025 Submits application for license to import 15,000 kg U, containing 225 kg U-235, from France MATSON, V Transnuclear, Inc 80-152/02 80/07/03 3pp
- 8007290027 Submits application for license to import 14,000 kg U. containing 140 kg U-235 from France
 MAT80N.V Transnuclear, Inc 80-151/01 80/07/07 3pp
- 8007290044 Ack receipt of 800906 ltm forwarding Executive Branch position re Westinghouse application to export two power reactors to South Kopea Questions impact of recent political developments on export' SHEA.J R Office of International Programs, Director 80/06/26
- 8007290212 Responds to 780929 request for Executive Branch position re Oladix Corp application to export 40,000 lb of Zircaloy-4 tubing Applicant abandoned request on 800708 HELFRICH.G F State, Dept of, Sureau of Oceans & Internati Environ & Scientific Affairs 80/07/11 lp
- 8007290390 Submits application for literate to import 40,000 kg U. containing 140 kg U-235.from France MATBON.V Transnuclear, Inc. 80-150/02 80/07/07 3pp
- 8007290446 Forwards application by Transnuclear, Inc for license to export 20 050 kg U.containing 18 707 kg U-235 to The Netherlands MATSON.V Transnuclear, Inc 80/07/03 ip
- --8007290452 Application by Transnuclear Inc for license to export 20 050 kg U.containing 18 707 kg U-235 to The Netherlands
 * Transnuclear Inc (NWK-333)80-149 80/07/03 4pp
- 8007290460 Forwards application by Marubeni America Corp for license to export 156.331 kg U.containing 3,496 kg U-235.to Japan NAKAI,T Marubeni America Corp (subs of Marubeni Corp) MAS-7408 80/07/11 1p
- --8007270467 Application by Marubeni America Corp for license to export 156.333 kg U.containing 3.486 kg U-235.to Japan NAKAI.T Marubeni America Corp (subs of Marubeni Corp) SK-1169/ZK0170 80/07/11 ip
- 8007270857 Application by Reactor Experiments.Inc for license to export 62 4 mg U-235.contained in 62 5 mg U-to Japan Ltr of assurance encl * Reactor Experiments, Inc. 080 80/07/15 2pp
- 8007290882 Forwards 800529 televito Soviet Union reprequest for U-308 stds.to be forwarded to State Dept Further communications or developments per application will be forwarded MULLER.L L DRG International Inc. 80706704 2pp
- BOO7300037 Licensp for Reuter-Stakes to export one radiation detector, Model RS-C2-2510-14.to Canada DEVINE.J B Assistant Director for Export/Import & International Bafeguards V-8517 80/07/23 2pp
- 8007300301 Forwards Dfc of Nurlear Reactor Regulation assessment of potential reducingical effects of Korean Nuclear Power Station on globul commons Assessment represents reasonable upperbound appraisal of potential plant releases DENTON.H R Office of Nuclear Reactor Regulation, Director 80/07/01 Epp
- 8007310018 Requests that application to export tritium to Yugoslavia be withdrawn, on behalf of Radiochemical Ctr HARNON, D H Edlow International Cc 80/07/18 1p
- B00731002B Ltr of assurance re Mitshubish: Nuclear Fueld Co application for license to export 399 Kg U-235 contained in 14,000 Kg U-to Japan MIYADAYASHI.M Gambia 80/07/14 1p
- 8007319039 Forwards application for export license for minor nuclear export Ltr of assumence required W/o encl DEVINE. J B Assistant Director fur Export/Import & International Bafeguards 80/07/22 ip
- B007310042 Submits application to amend license to extend expiration date to 851001
 WILSON, B B General Clectric Co BDW-80074 80/07/07 lp

- 8007310044 Submits application to amend license to extend expiration General Electric Co ROW-80073 80/07/07 1p
- 8007310066 Submits application to amend license to export 28 elements consisting of seven strings of four detectors each, to West
- Germany
 WILBON, B D General Electric Co , Nuclear Energy Products Div
 BDW-80080 80/07/15 lp
- 8007310069 Forwards application for license to export 12 samples of U dioxide pellets earh yr for five yrs.each shipment containing 7 g U-235, to Switzerland
 KEENAN.R P Westinghouse Electric Corp ICS-0512 80/07/01 ip
- --8007310073 Application by Westinghouse for license to export 12 samples of Y diuxide pellets each yr for five yrs, each shipment containing 7 g U-235, to Switzerland KEENAN R P Westinghouse Electric Corp FE-20162 80/07/01 lp
- B0073100B2 Application by Matheson Gas Products for license to export Bize 3 cylinder: containing 500 liters deuterium to Brazil F18HER, W F Matheson Gas Products 3532 X 80/07/11 2pp
- 8007310087 Application by Reuten-Stokes for license to export 1 4 g U dioxide on internal surface of Model RS-C3-2510-114 radiation detector, to Canada Ltr of assurance encl SKARUPA, J D Reuter-Stokes, Inc V-8817 80/04/17 2pp
- 8007310194 Requests Executive Branch position re Marubeni America Corp application for license to export SNN to Japan DEVINE, J B Assistant Director for Export/Import & International Bafeguards 80/07/22 ip
- 8007310197 License for QE to export miscellaneous replacement or spare parts & components to Finland PETERSON, M M Assistant Director for Export/Import & International Safeguards BDM-80013 80/07/10 ip
- BOO7310232 Responds to FOIA request for documents re export of SNM & replacement parts to India Forwards documents listed in App A. Documents will be placed in PDR FELTON.J M Division of Rules and Records BO/07/24 3pp
- --8007310247 Updates 800403 analysis of fuel requirements for Tarapur I & II Analysis is based on more detailed & current info Provides discussion, conclusions, refueling schedule & projected operating schedule for reactor QS Bedi ltr encl PCDERSEN.K Office of Policy Evaluations 79/01/16 9pp
- --8007310250 Provides supplementary info re Tarapur reactor fuel requirements, in response to Commissioner Ahearns question rebasis for fuel fabrication time DDB provided 9-month fabrication period Inadequate data available for analysis PEDERSEN, K. Office of Policy Evaluations 79/01/18 2pp
- --8007310260 Lists questions re review of License XSNM-1379 concerning proposed export of low enriched fuel to India Requests Executive Branch response SMEAsJR Office of International Programs, Director 79/05/25
- --B007310266 Forwards updated analysis of estimated fuel requirements for Tayapur reactors, reflecting fuel covered by application XSNM-1379 M/o enc1 BBVINE, J Office of Policy Evaluations 79/06/07 ip
- --8007310270 Application by GE for license to export six traversing incore probe detector assemblies to India
 HILSON B D General Electric Co BDH-79122 79/05/07 ip
- 8007310482 Application by Mitsubishi Intl Corp for license to export 450 nCi Cf-252 cormet wire to Japan NUGE,T Mitsubishi International Corp (subs of Mitsubishi Corp), PIT-L-1812 80/07/22 ip
- BOO7310484 Application by Sigma Chemical Co for license to export compounds containing deuterium to Canada STERN.W C. Bigma Chemical Co. (subs. of Sigma-Aldrich Corp.) D-49, BO/07/23 ip
- 8007510487 Forwards application for license to export reactor vessel gaskets, retaining clips & retaining clip screws to South Korea Mulk, H S Babcock & Wilcox Co 80/07/18 ip

---B007310490 Application by B&W for license to export reactor vessel gaskets, retaining clips & retaining clip screws to South Korea MUIR, HS Babcock & Wilcox Co 788-998052-51 80/07/17 ip

8007310511 Advises that NBS confirmed that matl requested for export on application is in sensing components installed in instruments Enriched U could be exported under general license Byproduct license required to export instruments MRIGHT, B L Office of International Programs, Director 80/07/24 1p

8007310520 Application by Agip USA Inc for license to export radioactive ref sources to Italy End use statement encl * AGIP USA. Inc 80-64203-2 80/07/09 5pp

8007310522 Amend I to license for GE extending expiration date to B31001 & clarifying categories of parts & components authorized for export to West Germany DEVINE, J B. Assistant Birector for Export/Import & International Bafeguards 80/07/23 ip

1			

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this indefindicates that the document is an enclosure to anoth document. To obtain the accession number of the princip document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Princip. Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTKOR	NOVERSION	SUBJECT CATEGORY
ABBOTT, W S	8007150318*	70-2651	AHEARNE, J F	0001000100	ED 000	AL BEGGGE A E		
ABERCROMBIE, H	8007220342	50-259 R		8007230108	50-320 H	ALDERSON, C. E	8007170559	50~553
ABERCROMBIE, H	8007220481	50-259 R	AHEARNE, J. F	8007020303	50-320 U	ALEXIS, C. P	8007010185*	40~6789
ABERCROMBIE, H	8007110271	50-240 8	AMEARNE J F	6007020129	COMMISSION	ALGER, D. M	8007140351	50~186
ABERCROMBIE, H	8007110425	50-276 B	AHEARNE, J. F AHEARNE, J. F	8007090104 8007010547	COMMIBBION 50-320 P	ALLAN, J M ALLEN, J	8007280408*	50~293
			RICHITETO F	avv/01034/	30~320 P	MULCH! O	8007070079*	50~280
ABERCROMBIE, M	8007290864	50-259 B	AHEARNE, J. F	84E011700B	50-320 н	ALLEN, J	B007070075*	50~280
ABERCROMBIE, H	8007140552	50-259 R	AHEARNE, J. F	8007080076	MUSSIMMOS	ALLEN, J	9007300412	50~290
ABGRAB, K	8007100268*	50-206 R	AHEARNE, J. F	8007110266	MOTERTHAD	ALLEN, B D	8007270647	50~275
ABLER, W.L	8007020452	PR	AMEARNE, J F	8007230735	COMMISSION	ALLEN, R B	8007070201*	TOPREP
ABOU-SAYED, I	8007230201	NUREG	AKEARNE, J F	8007230745	CONMITERION	ALLMEND INGER, P	8007030354	PR
ABRAHAMSON, D	8007140014*	PR	AHEARNE, J F	550-55-4-5				
ABRAMSON P B	8007240459	NUREO	AHEARNE, J F	8007280157	COMMISSION	AMBERO P J	8007100248*	50~206
ABRAMS, R	8007110121	PR	AHEARNE, J F	80072B0722	COMMISSION	ANDALMAN, E	8007080009	PR
ABT, S R	8007170331*	40-8681	AHEARNE, J F	8007270347	COMMISSION	ANDERS N A	8007140135*	SECY
ABT. S R	8007180491	40-8691	AREARNE, J. F	8007080159 8007160716	50-546 U COMMISSION	ANDERSON, T M ANDERSON, T M	8007140540*	ACRE
			incatte, o	MOD / 180 / 18	COURTOBIUM	WUNEUGRA' I U	8007100253	TOPREP
ABT,8 R ABT,8 R	8007170302* 8007180288	40-8602	AHEARNE, J F	8007280162	COMMISSION	ANDERSON, J L	8007230425	NUREO
ADT, S R		40-8602	AHEARNE, J F	8007170415	COMMISSION	ANDERSON, T M	8007140379*	TOPREP
ABT S R	9007280070	40-8661	AHEARNE, J F	8007110546	50~482 U	ANDERSON, T M	8007140416*	TOPREP
ADT. S R	8007170332* 8007170335*	40-8681	AKEARNE, J F	8007110552#	50~482 U	ANDERSON, T M	8007150656*	TOPREP
WELLO !!	600/1/0335*	40-B681	AHEARNE, J F	800711056 6 *	50-48⊋ U	ANDERSON, T M	8007160765*	TOPREP
ABT.S R	8007170308*	40-B602	AHEARNE, J. F	800711054B*	50-482 U	ANDEDOSN T M		
ABT, S R	8007280066	40-8602	AHEARNE, J. F.	8007110377	COMMISSION	ANDERSON, T K ANDERSON, D Q	8007140373≠	TOPREP
AUT, S R	8007180279	40-8681	AHEARNE, J. F.	8007110392*	COMMISSION	ANDERSON, T H	80072703214 8007010005	0A797
ADT, B R	8007180480	40-8698	AHEARNE, J F	8007110387#	COMMISSION	ANDERSON, T M		PR
ABT.S R	9007170297*	40-8602	AHEARNE, J F	8007110392*	COMMISSION	ANDERBON, T M	8007140367 8007140407	TOPREP TOPREP
ABT, S R	8007170329*	40-8481						*****
ABUAF, N	8007180361	RES	AHEARNE, J. F.	8007110538	COMMISSION	ANDERSON, T H	8007190646	TOPREP
ACERRA, L S	6007170214	50-373 B	AHEARNE, J. F.	8007140050	20-350 n	ANDERGON, T M	8007160743	TOPREP
ACKERMAN, N. C.	8007020694	40-8502	AHEARNE, J F	8007140062*	50-320 U	ANDERBON, T. K	8007170230	50-275
ACOSTA, A P	8007020028	408584	AHEARNE, J F AHEARNE, J F	6007140120 6007240027	COMMISSION	ANDERSON, T M ANDERSON, D T	8007080371	50-339
ACOSTA, A P				OUNT ENOUGH !	COMITERION	NUDERSON: D	8007100268*	50-206
ACOSTA, A P	8007010305 8007210540	40-8594	AHEARNE, J F	8007240034*	COMMISSION	ANDERSON, T M	8007020641	TOPREP
ACOSTA, A P		40-8594	AHEARNE, J F	8007240383	70-2153	ANDERSON, T 14	8007020644*	TOPREP
ADAM, L. D	8007290619	40-0594	AHEARNE, J F	8007250202	COMMISSION	ANDERSON, T M	8007020590	TOPREP
ADLER, T A	8007310393 8007140008	50-289 H	AHEARNE, J F	8007110297*	COMMISSION	ANDERSON, C. J	8007230621	50-397
7100-3(1) 1 17	800714008	50-287 G	AHEARNE, J. F.	8007250079	CORMISSION	ANDERBON, T M	8007210410	TOPREP
ADLER T A	9007140009*	90~289 Q	AHEARNE, J F	9007250082*	COMMISSION	AMBERSON N. D		
ADLER, T A	800714000B	50-289 0	AHEARINE, J F	8007250085*	COMMISSION	Anderbon, n r Anderbon, c	8007300099	50~339
ADLER, T A	8007140009*	50-289 0	AHEARNE, J F	8007250089*	COMMISSION		B007250175	20-355
ADLER T A	8007250680	50-287 G	AHEARNE, J F	8007250098*	COMMISSION	ANDERSON.C. ANDOGNINI.Q C	8007310231	NUREO
ADLER, T A	8007250689	50-287 C	AHEARNE, J. F	9007250101*	COMM 1881ON	ANDOONINI. C. C.	8007230176# 8007280252#	50~293 50~293
ADLER, T A	8007250680	50287 C	********				DVOTEDVEVE	20-273
ADLER, T A	8007250689	50-289 C	AHEARNE J F	8007250105*	COMMISBION	ANDOGNINI, 6 C.	8007140418	50-293
ADLER, T A	8007220001	50~289 G	AHCARNE, J. F.	6007250114×	COMMISSION	ANDOGNINI, O C	8007210006	50-293
ADLER, T A	8007220001	50-289 g	AHEARNE, J. F.	800725011B*	COMMISSION	ANDOGNINI, G C	8007210301	50-293
ADLER, T A	8007220002	50-287 0	AHEARNE, J. F.	8007240480	COMMISSION	ANDOGNINI, O C	8007030142	50-293
		107	AHEARNE, J F	80072404B1 *	COMWIREIOM	ANDOCHINI.C O	8007150557	50-293
ADLER.T A ADLER.T A	8007220002	50-289 G	AHEARNE, J F	8007240483*	COMMISSION	ANDOGNINI, Q C	8007250309	50-293
AGEE, J R	8007220595	50-289 Q	AMEARNE, J F	8007240487*	COMMISSION	ANDOQNINI, O C.	8007290596	50-293
AGEE, J R	8007280088*	QA799	AHEARNE, J F	8007240491*	COMMISSION	ANDREWS, M Q	8007080285*	TOPREP
AGEE, J. R.	8007140048* 8007160171*	QA999	AHEARNE, J F	8007240493*	COMMISSION	ANDREWS, I	8007020217#	50-324
	200/1001/1#	QA999	AHEARNE, J F	6007240496 *	COMMISSION	ANDREWS, J. P	8007180230	REOOD
AGEE, J R	8007290337*	QA999	AHRARNE, J F	8007240497#	COMMISSION	AMO. U. D	78871/	1
AGRAWAL, A K	8007210003	RES	AIROLA, E D	H007220189*	QA999	ANG.W.F. ANKLAM.T.M	8007160872*	50-416
AHEARNE, J.F.	8007010552*	COMMISSION	AKERS. D W	8007270217	50~254 P	ANTOUN, R L	8007300575	NUREO
AHEARNE, J F	8007220273*	40-299	ALBOSTA, D	8007160634	50-329 H	APPELHANS, A D.	8007090201*	TOPREP
AHEARNE, J F	8007100211*	50-302 P	ALDEN, W M	8007180433*	50-277 R	APPLEYARD, M H	9007310255 9005170626	NUREO
					"		PA0411080	20~350

AUTHOR	ACCESS I ON NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
ARAGON, R	8007310004	NUREO	BARDES, CR	8007110147*	50-320 J	BAXLEY, S X BAXLEY, S X BAXLEY, S X BAXTER, T A BAXTER, T A	8007030278*	50-321 8
ARAUZ, O A	8007220385*	90-302 P	BARDES, CR	8007110151*	50-320 J		8007110442*	50-321 6
ARCHITZEL, R	8007210247*	50-317 G	BARDES, CR	8007110156*	50-320 J		8007210492*	50-321 5
ARLOTTO, O A	8006270352	PR	BARDES, CR	8007110160*	50-320 J		8007070310	50-484 0
ARNOLD, R C	8007110030*	50-289 J	BARDES, CR	8007110167*	50-320 J		8007070315*	50-484 0
ARNOLD: R. C	8007070287	50-320 P	Bardes, C R	8007110176*	50-320 J	BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8007070315#	50-484 0
ARNOLD: R. C	8007170456	50-320 P	Bardes, C R	8007110178*	50-320 J		8007150527	50-312 0
ARNOLD: R. C	8007220485	50-320 0	Bardes, C R	8007110201*	50-320 J		8007150556#	50-312 0
ARNOLD: R. C	8007310439	50-320 P	Bardes, C R	8007110208*	50-320 J		8007150556#	50-312 0
ARSENAULT: F. J	8007220018	MISC	Bardes, C R	8007110212*	50-320 J		8007250345	50-312 P
ABH,RF	8007090359*	50-317 Q	BARDEB.C R	8007110217*	50~320 J	BAXTER, TA BAXTER, TA BAYNARD, PY BAYNARD, PY BAYNARD, PY	8007250408	50-484 0
ABHENDEN,MC	8007180011*	50-327 Q	BARI.R A	8007210010	RES		8007250408	50-484 0
ABPERGER,RG	8007080008	50-452 Q	BARI.R A	8007240294	RES		8007100101	REGOD
ABWELL,DL	8007100429	50-382 Q	BARI.R A	8007020364	RES		8007020387	50-302 P
ABWELL,DL	8007150417	50-382 Q	BARKER.J L	8007070080*	50-10 G		8007230193	PR
ABWELL, D L	8007270437*	50-382 Q	BARKER, J L	8007230388*	50-10 Q	BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY BAYNARD, PY	8007110122	50-302 P
ABWELL, D L	6007010341	50-382 F	BARKER, D G	8007300375	50-498 A		8007150708	50-302 R
ABWELL, D L	8007010317	50-382 S	BARLEY, S R	8007180110*	50-320 H		8007210203	50-302 P
ABWELL, D L	8007020397	50-382 S	BARNES, I	8007310195*	QA979		8007180294	50-302 P
ABWELL, D L	8007100163	50-382 K	BARNES, I	8007270504*	QA999		8007180313	50-302 P
ABWELL, D. L ABWELL, D. L ABWELL, D. L ABWELL, D. L ABWELL, D. L	8007100166* 8007300395* 8007080179 8007080234 8007220373	50-382 K 50-382 G 50-382 A 50-382 S 50-382 F	Barnes, I Barnes, I Barneich, J Darnes, J N Barnthouse, L W	8007250109* 8007140144* 8007010364* 8007310237 8007210498	0A999 0A999 50-361 A FOIA 50-247 P	BAYNARD, P. Y.	8007180384 8007230542 8007220383 8007240074 8007250326	50-302 P 50-302 Q 50-302 P 50-302 P
ASHELLID L	8007250379	50-382 F	BAROCH, C. J.	8007140397*	GA777	BAYNARD, PY BAYNARD, PY BAYNE, JP BAYNE, JP BAYNE, JP	8007280127	50-302 P
ATKINSONJJ P	8007220573*	50-414 A	Barrett, P. A.	8007230064*	50-341 G		8007280373	50-302 F
AU-YANO,M K	8007070201*	TOPREP	Barry, L. W.	8007250176	BECY		8007170316	50-286 Q
AUSTIN,M A	8007150148*	70-364	Barth, C. A.	8007030243	50-488 G		8007030254	50-286 F
AUSTIN,M,A	8007150809	70-364	Barth, C. A.	8007070311	50-488 G		8007070212	50-333 F
AUBTIN, M. A AUBTIN, M. A AUBTIN, J. H AUBTIN, M. A AUTIO, H. A	8007020005* 8007150135* 8007020566 8007280211 8007070284	70-135 70-364 50-437 A 71-9022 50-29 8	BARTH,C A. BARTLETT, W T BARTLETT, J W BARTLETT, J BARTMAN, V	8007250688 8007020746 8007100188* 8007280540 8007240378*	50-282	HE CONTRACT OF CON	8007180597 8007140347 8007280471 8007080303 8007080332	50-286 0 50-286 0 50-220 0 50-286 V 50-333 P
AUTIG:H A	8007210002	50-27 G	Bartnoff.s	8007070113	50-219 P	BAYNE, J P	8007080367	50-286 P
AVIB:A B.	8007280271	27-48	Bartram.b W	8007220111#	Waste Mgt	Bayne, J P	8007290728	50-286 P
AXELRAD:H	8007030119	PR	Bartram.b W	8007220036#	Waste Mgt	Bayne, J P	8007280461	50-286 I
AXELRAD:H	8007020604	30-376 G	Baskin.k P	8007230011	50-361 Q	Bayne, J P	8007290580	50-286 P
AXELRAD:H	8007020604	50-376 G	Baskin.k P	8007250361	50-361 Q	Bayne, J P	8007290755	50-286 F
AXELRAD, M AXELRAD, M AXELRAD, M AXELSON, W AYER, J E	8007100160 8007230535 8007230535 8007250406 8007090186*	PR 50-376 0 50-376 0 50-155 F 70-1257	Baskin, k p Baskin, k p Baskin, k p Baskin, k p Baskin, k p	8007110401 8007100384 8007300303 8007250355 8007310162	50-206 P REGOD 50-361 Q 50-206 Q 50-206 Q	BAYNE, J P BEACH, A B BEAN, R M BECHHOEFER, C BECHHOEFER, C	8007290692 8007110076* 8007310210 8007080209 8007140012	50-333 P 50-382 Q NUREQ 50-358 Q 50-409 Q
AYER, J. E	8007210315*	70-1257	Babkin, k p	8007290487	50-361 Q	BECHHOEFER, C	8007150505	50-409 Q
AYER, J. E	8007090183	70-1257	Babkin, k p	8007010465	50-206 P	BECK, M K	8007220073*	40-8771
AYERS, P. J	8007230532	50-10 D	Babkin, k p	8007010216	50-206 R	BECK, E J	8007280151	71-5979
AYRES, S. T	8007100175	50-272 G	Babkin, k p	8007010479	50-361 A	BECKER, J M	8007170176	XPORTLIC
BAGI, P. E	8007280137*	50-498 Q	Babkin, k p	8007010358	50-361 A	BECKER, J M	8007230602	XPORTLIC
BADRAN, S BAER, T S BAER, T S BAGAGLIO, M BAGDEN, G.	8007010551* 8007240155 8007220508 8007310327* 8007140549	50-237 8 71-6679 27-48 50-275 G PR	BASKIN, K.P. BASKIN, K.P. BASKIN, K.P. BASKIN, K.P. BASKIN, K.P.	8007080081 8007310201 8007080271 8007150579 8007210463	50-361 A 50-361 G 50-206 F 50-206 P 50-341 A	BECKMAN, D A BECKBTED, W F BEDNAR, L F BEENY, S T BEENY, S T	8007230174* 8007270449 8007080368* 8007250485 8007250485	50-334 0 50-322 8 50-298 5 50-395 M
BAODEN, O	8006240081	40-1162	BABKIN,K P	8007270620	50-361 A	BEERB, F C	8007180400*	50-271 R
BAILEY, R.	8007230158	90-320 S	BATEMAN, H	8007170682*	50-354 0	BEHAN, J L	8007180047*	50-322 H
BAIR, O O.	8007140315*	90-344 R	H HAMETAB	8007170274*	50-354 0	BELANGER, J L	8007310267*	50-305 G
BAISDEN, L.	8007210263	Contract	BATES,J W	8007100381*	70-1151	BELCHER, R L	8007230495	50-166 R
BAISDEN, L	8007310006	Contract	BATES,J, W	8007100410*	70-1201	BELGRAIR, D P	8007290932	71-370
BAKER, T. BAKER, K. R BAKER, K. R. BAKER, B. BAKER, B.	8007110443* 8007010393* 8007140493* 8007090290 8007090298*	NUREQ 50-255 Q 50-155 Q 50-466 Q	Bates, J W Bates, B J Bates, A Bates, E Bates, E F	8007140073* 8007250057* 8007030351 8007140691 8007290475*	70-143 0A999 PR PR 50-128 R	Belgrair, d p Belin, a Belin, a Belible, g a Belke, w l	8007290934* 8007020136 8007140229 8007220088* 8007070101	71-370 FOIA FOIA 50-335 Q 50-286 P
BAKER: B. L	8007170159	50-466 Q	BATES, A K	8007090347	50-327 P	BELL, J J	8007280265	50-287 G
BAKER: B L	8007170171*	50-466 Q	BATES, J N	8007180316#	70-143	Bell, J J	8007220033*	50-287 H
BAKER: B	8007230603	50-466 Q	BATES, J, O	8007230507	50-329 A	Belmore, C I	8007150712*	50-217 R
BALALIB: C Q	8007280473	XPORTLIC	BATTLE, R E	8007140610	NUREG	Benberger, D L	8007170577	50-460 8
BALLARD: R L	8007070033*	50-514 D	BAUCUS, M	8007250067#	50-320 H	Bender, M	7705140021	50-437 D
BALLARD,R L	8007300035	50-287 0	BAUER, R H	8007240094*	71-5607	BENNETT, H A BENNETT, H A BENNETT, H A BENSING, D BERGER, R F	8007180049	NUREO
BALLENTING,J M.	8007220358	50-327 R	BAUER, E R	8007280453*	50-317 8		8007250894*	GA777
BALLINGER,P L	8007080395*	50-278 R	BAUM, E A	8007030184	50-280 F		8007310241	NUREO
BALLINGER,P L	8007250425*	50-278 R	BAUM, E A	8007070201	50-337 P		8007100120	PRM
BALDUGH,R C	8007210388	50-445 M	BAUM, E A	8007150569	50-338 P		8007020613	50-556 0
Banasiakit. J	8007140540	50-10 D	BAUM.E.A	8007220579	50-338 F	Berger, R F	8007310153	SO-556 Q
Banasiakit J	8007180348	50-10 D	BAUM.E.A	8007240049	50-339 A	Berger, R F	8007220539	PR
Banasie M	8007090131	40-5021	BAUM.E.A	8007280432	50-338 F	Berick, D.	8007030107	PR
Bardesic R	8007110107*	50-320 J	BAUM.E.A	8007250383	50-338 F	Berkebile, R D	8007100194	REOGD
Bardesic R	8007110125*	50-320 J	BAUMANN.R.O	8007300581*	CONTRACT	Berman, M	8007110551	RES
Bardes, C r Bardes, C. r Bardes, C. r Bardes, C. r Bardes, C. r Bardes, C r	8007110128* 8007110132* 8007110135* 8007110140* 8007110143*	50-320 J 50-320 J 50-320 J 50-320 J 50-320 J	BAUH, P. W. BAUNACK, W. BAUNACK, W. BAXLEY, S. X	8007150573* 8007250263* 8007210255* 8007270010	50-133 R 50-220 Q 50-333 Q 50-220 S 50-344 S	BERMAN, M BERNERO, R M BERNBEN, S A BERTELL, R, BETANCOURT, B	8007280081 8007110487* 8007150116 8007020449 8007020693*	RES SECY PR PR 50-281 H

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NOMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY
BETETA, P M BETHUNE, E BETTAUER, R J BETTENHAUSEN, L BEYEA, J	8007180167* 8007110449 8007170191 8007230221* 8007170089	COMMISSION 50-313 H XPORTLIC 50-293 G 50-320 P	BOHN, M P BOHN, R J BOHN, M P BOHN, R J BOHN, R J	8007150059 8007010478 8007220065 8007210464 8007280482	RES 50-367 A RES 50-367 R 50-367 R	BRADFORD, W H BRADFORD, P A BRADFORD, W H BRADFORD, G P BRADFORD, G P	8007070399* 8007300291* 8007240376* 8007220203 8007220209*	50-348 7 50-257 6 50-348 6 50-287 6 50-287 6
BIALIK, E I BICKWIT, L BICKWIT, L BICKWIT, L BIDA, O	8007110121 8007150829 8007110532 8007140182 8007210007	PR COMMISSION SECY 50-247 P RES	BOHN R J BOLANDER, M A BOLANDER, M A BOLES, G S BOLES, G S	8007110438 8007280178 8007280186 8007290656* 8007290681*	50-367 R RES RES 50-327 B 50-327 B	BRADFORD, O P BRADLEY, E J BRADLEY, E J BRADLEY, E J BRADLEY, E J	8007220217* 8007140617 8007180443 8007220551 8007280384	50-289 'NUREQ 50-277 'S0-276 '
BIDDLE, C T BIDDLE, C T BIDDLE, C T BIDDLE, C T	8007020471 8007020471 8007080013 8007080017* 8007080015*	50-466	BONZON, L L BOOK, H E BOOK, H E BOOK, H E	8007310007 8007140609* 8007300585* 8006110739* 8007310339*	NUREC 27-48 50-254 G 27-10 50-295 G	BRAMLETT,L 8 BRAMLETT,L 8 BRAMLETT,L 8 BRAMLETT,L 8 BRAMLETT,L 8	8007010480* 8007150603* 8007150538* 8007210432* 8007210413*	50-313 ; 50-313 ; 50-313 ; 50-313 ;
BIDDLE.C T BIDDLE.C T BIELAWSKI.A P BIELAWSKI.A P	8007080017* 8007180432 8007180432 8007020462 8007020462	50-466 G 50-466 G 50-466 G 50-599 G 50-599 G	800K, H E 800K, H E 800K, H E 800K, H E 800K, H E	B007140657* B007140663* B007170556* B007140670* B007150130*	40-2940 40-2940 50-315 Q 40-2940 50-344 Q	BRAMLETT, L 9 BRAMLETT, L B BRANAGAN, E F BRANCH, W H BRANDENBURG, B	8007180318* 8007280511* 8007100369 8007290929 8007220160	50-313 50-313 NUREO 71-368 50-247
BIELAWSKI,A P BIERMAN,S R BIERMAN,S R BIGIARELLI,M J BINGHAM,J	8007230810 8007020016 8007310187 8007100172* 8007280187	50-255 0 RES RES 50-245 S PRM	800K, H E 800K, H E 800K, H E 800K, H E	8007110174 8007110184* 8007150124* 8007180023 8007180025*	50-206 0 50-206 0 50-344 0 50-508 0 50-508 0	BRAND, N E BRANDENBURD, B BRAUN, J BREAUX, D Q BREAUX, D Q	8007250502* 8007290522 8007030038* 8007140088* 8007140126*	50-395 ; 50-247 ; FOIA GA999 GA999
BIRCHELL,R C BIRCHELL,R C BIRGEL.B H BIRKEL,R A BIRKEL,R A	8007270637* 8007270818* 8007030071* 8007110517 8007160486	50-327 5 50-327 5 CONTRACT 50-369 A 50-369 A	800K, H E 800K, H E 800K, H E 800K, H E	8007230355* 8007230350 8007160721* 8007230297* 8007240331*	50-224 Q 50-224 Q 40-7982 50-206 Q 70-1257	BRICKLEY.R H BRICKLEY.R H BRICKLEY.R H BRICKLEY.R H BRICKLEY.R H	8007140088* 8007280088* 8007140048* 8007160171* 8007290337*	0A999 0A999 0A999 0A999
BIRKEL.R A BIRKEL.R A BIRKEL.R A BISCHOFF.C A BISHOP.T W	8007090091 8007170696 8007280011 8007300106 8007230639*	50-367 A 50-369 A 50-369 A 50-528 G 50-397 Q	BOOK, H E BOOK, H E BOOK, H E BOOK, H E	8007230291* 8007240322 8007310163 8007310168* 8007150106	50-204 Q 70-1257 50-288 Q 50-288 Q 50-344 Q	BRICKLEY,R H BRICKLEY,R H BRIDGES,A P BRIOGS,L BRIOGS,L	8007290321* 8007310316* 8007160513* 8004240215 8004240221	GA999 50-266 B CONTRACT 50-318 50-219
L S.40H818 C S.40H818 M C 40H818 N C.40H818	8007090224 8007100022 8007100255 8007310116 8007310108	50-376 G 50-299 G 90-445 O 50-466 G	BOOK, H E BOOK H, E BOOKE, B L BOOKE, B L BORDENICK, B K	8007230282 8007100003* 8007220520 8007220520 8007070046*	50-206 Q 50-320 Q 40-1162 40-1162 50-514 D	BRICHT,R M BRICHT,R M BRICHT,R M BRICHT,R M BRICHT,R M	8007030242 8007180540 8007010355 8007070329 8007080259	50-302 P 50-302 A 50-302 P 50-302 A 50-302 T
BISHOP.L L BISHOP.C J BISHOP.C J BISHOP.C J	8007110048 8007110048 8007100258 8007220092 8007220103*	PR PR 50-320 G 50-275 G 50-275 G	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8007080001 8007080003* 8007080005* 8007080059 8007160601	50-320 0 50-320 0 50-320 0 50-322 0 50-322 0	BRIGHT,R M BRIGHT,R M BRINKLER,J E BRINKLER,J E BRITIB,J 8	8007100153 8007150598 8007080417* 8007210431* 8007100001	50-302 , 50-302 & 50-309 50-309 PR
BISHOP,C J BISHOP,C J BISHOP,C J BISHOP,T A BISSETT,P	8007220556 6007310160 8007310463 8007240394 8007180082*	50-445 If 50-344 G 50-309 G NUREG 70-371	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORER, P. J BOROMANN, E A	8007140583 8007170201 8007240008 8007280572* 8007150108*	50-322 Q 50-514 Q 50-322 H 50-298 8 50-358 Q	BROCKETT, T BROCKETT, T BROCKETT, T BROCKETT, T BROCKETT, T BRODERICK, N E	8004240316 8007140550 8007230143 8007230148 8007030208*	14E 50~219 14E 50~54 50~285 7
BISSETT.PH BIVINS,WS BLACK,RL BLACK,RL BLACK,RL	8007170430* 8007230721* 8007010330 8007080030 8007190043	70-135 40-8452 50-522 0 50-466 0 50-341 0	BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A BORGMANN, E A	8007010084 8007080317 8007210302* 8007210313 8007250616	50-358	BROEML,D J BROEML,D J BROEML,D J BROEML,D J BROEML,D J	8007030233 8007100345 8007100058* 8007020594 8007070273	50-344 û PRM 50-344 û 50-344 û
BLACKWELL, R M BLACKWELL, R M BLACK, R L BLACK, R L BLACK, R L	8007280680* 8007280692* 8007180246 8007180260 8007180426	50-321 R 50-321 R 50-498 G 50-466 G 50-466 G	BORGMANN, É A BORGMANN, É A BORGMANN, É A BORGMANN, É A BORGMANN, É A	8007080374 8007070258 8007250576 8007280096 8007140369	50-358 G 50-358 F 50-358 G 50-358 G 50-358 K	BROEHL, D. J. BROEHL, D. J. BROEHL, D. J. BROEHL, D. J. BROEHL, D. J.	8007160661 8007180347 8007220570 8007250413 8007290554	50-344 (50-344) 50-344 (50-344 (
BLACK, R L BLACK, R L BLACK, R L BLACK, R L BLAKE, E L	8007220013 8007240489 8007270748 8007310473 8007180394	50-49B G 50-49B G 50-49B G 50-466 G 50-2B7 G	BOROMÁNN.E A BOROMANN.E A BOROO,O J BOROO,O J BORNHOEFT,W H	8007210424 8007230437 8007160366 8007250297 8007280067*	50-358 K 90-358 Q 50-369 S PT21 PR	BROGAN, O E BROMBERO, B BROOKS, T R BROOKS, H BROOKS, F K	8007010364* 8007210253 8007070085 8007140637* 8007160229*	50-361 : CONTRACT PR TOPREP CONTRACT
BLAKE, E L BLAKE, E L BLAKE, E L BLAKE, E L BLAKE, E L	8007180394 8007230521 8007230521 8007300437 8007300437	50-287 Q 50-287 Q 50-287 Q 50-287 Q 50-287 Q	BOSCHWITZ,R BOUKNIGHT,JA BOURNIA.A BOWDEN,TJ BOWDEN,DD	8007310528* 8007230778 8007180276 8007110502 80071140617	50-282 H 50-389 M 50-438 A PRM NUREO	BROBNAN, D.F. BROUND; R.J. BROWNE, W.G. BROWN, R.A. BROWN, G.F.	8007140051* 8007220019 8006110739* 8007150471* 8007090098	PR NUREO 27-10 50-280 (PR
BLAND.J S BLOCK.J A BLOEDEL.G A BLOUGH.A R BLUME.M B	8007010289 8007220334* 8007180049 8007230736* 8007010247	50-255 P TOPREP NUREG 50-277 G 50-445 M	BOWERS, E S BOWERS, E S BOWERS, E S BOWERS, E S BOWERS, E S	8007020586 8007020606 8007080204 8007110348 8007310167	50-322 0 50-322 0 50-322 0 50-498 0 50-445 0	BROWN, R L BROWN, C BROWN, E J BROWN, O D, BROWN, O D	8907210264* 8007140494* 8006120770 8007170297* 8007170329*	0A999 50~243 (* 080 40~8602 40~8681
BLUME, M B BLUME, M B BLUMMBERG, N BODDY, J R BODDY, J R	8007010264 8007280636* 8007020070* 8007220042* 8007220047*	50-445 M 50-445 M 50-277 Q WASTE MGT WASTE MOT	BOWERS, E S BOWNE, N D BOYD, D C BOYD, D C BOYD, D C	8007250708 8007140490 8007070061* 8007010393* 8007240210*	50-142	BROHN, R. BROHN, R BROHN, O, F BROWN, O D. BROWN, H H	9007220056* 9007220064* 9007020635 9007170271 9007030048	WASTE MOT WASTE MOT PR 40-8602 50-275
BODTKE,P J BOELDT,E J, BOGDEN,G BODDEN,G BOHANAN,R F	8007110414* 8007100170 8007100091* 8007220314 8007300575	50-255 R REGOD 40-1162 40-1162 NUREO	BOYER, V 8 BOZARTH, D P BOZICH, T A BOZICH, T A BRADFORD, P A	8007250471 8007250552* 7910150157 8007030099 8007030213*	50-352 A 50-440 A 40-4669 40-4669 50-273 P	BROWN, M H BROWN, R A BROWN, O D, BROWN, O D BROWN, C M	8007030048 8007280278 8007170327 8007230257* 8007300307*	50-275 (70-1177 40-8681 50-313 (50-263 (

A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BROWN. O D BROWN. O D BROWN. S C BROWN. S C	8007230244 8007290231 8007290244* 8007010363 8007010413	50-313 0 40-8102 40-8102 50-404 A 50-338 0	BURCHETTE, W H BURGESS, B L BURGER, J F BURGER, F J BURGER, F J	B007210455 B007240210* B007100050* B0071B0400* B007290024	50-445 M 50-282 0 PR 50-271 R 70-2902	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007290646 8007290657 8007290790 8007290820 8007290822	50-327 S 50-259 S 50-327 S 50-294 S 50-327 S
BROWN.R. BROWN.R BROWN.O D BROWN.L. J BROWN.M S	8007280508 8007230203 8007180112 8007300340 8007070272*	NUREG NUREG 50-285 G 50-199 G 50-316 S	BURIAN.R J BURKE.T J BURKHARDT.W BURKS.N BURNETT.R F	8007250110 8007020073* 8007090183 8007140674 8007220248*	71-8987 50-322 8 70-1257 FOIA 70-143	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007250414 8007270636 8007270665 8007270720 8007270810	50~327 S 50~327 S 50~327 S 50~260 S 50~327 S
BROWN, W S BROWN, B C BROWN, B C BROWN, B C	8007100246 8007150703* 8007180371 8007250365 8007310421	PR 50-315 S 50-281 Q 50-281 Q 50-280 P	BURNETT, R F BURNETT, R F BURNETTE, G W BURNETT, R F BURNETT, R F	8007090038* 8007020080 8007150407 8007020476 8007110584	100FR 70-1201 RES 70-572 70-143	R L HOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R CALHOUN, J R	8007290762 8007290685 8007290695 8007290578 8007290649	90-327
BROWN,H H BRUGGER,R M BRUGGER,R M BRUNER,R B BRUNNER,E J	8007250429 8007080266 8007080260 8007230601* 8004240212	50-275 G 50-186 S 50-186 S 70-2000 50-286 S	BURNETT, R F BURNETT, R BURNETT, R BURNE, B G BURNE, B Q	8007310453 8007250055* 8007250058* 8007070126 8007310319	70-1201 FOIA FOIA 50-255 Q 50-255 Q	CALHOUN, J R CALHOUN, J R CALHOUN, J R CALLAHAN, L J	8007290662 8007290675 8007290708 8007290737 8007220197*	50-327
BRUNNER, E J	8004240215	50-318 \$ 50-219 \$ 50-293 \$ 50-277 Q 50-277 Q	BURTON.R M	8007210125*	50-483 Q	CAMPBELL: M	8007170306*	FOIA
BRUNNER, E J	8004240221		BURWELL.S	8007020224	50-445 A	CAMPBELL: M	8007170314*	FOIA
BRUNNER, E J	8004240228		BUSTION.R R	8007100050*	PR	CAMPBELL: M	8007170438*	FOIA
BRUNNER, E J	8007020049*		BUTLER.W R	8007180177*	REOGD	CAMPBELL: R H	8007110003	70-2907
BRUNNER, E J	8007230730*		BUTLER.S D.	8007180011*	50-327 Q	CAMPBELL: T E	8007020596*	TOPREP
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	8007220050 8007230202* 8007230157* 8007180077 8007280254*	50-219 0 50-293 0 50-334 0 50-293 0 50-293 0	BYERLEY, T E CADENA, D G CAHILL, W J CAHILL, W J	8007020342 8007020523* 8007070174 8007010081 8007020077	PR 50~366 B PR 50-3 Q 50-3 Q	CANADY, K. B. CANLON, L. E. CANNON, R. H. CANTER, H. L. CANTRELL, F. B.	8007140007* 8007110536* 8007150522* 8007240420* 8007240329*	50-369
BRUANIER, E J BRUNNER, E J BRUNNER, E J. BRUNNER, E J. BRUNNER, E J	9007310118* 9007020035 9007170669 9007210157 8007210241	50-272	CAHILL,W J CAHILL,W J CAHILL,W J CAHILL,W J CAHILL,W J	8007170287 8007180540 8007180592 8007090228 8007090251	50-3 Q 50-3 Q 50-3 Q 50-247 P 50-247 P	CANTRELL, F S CANTRELL, F S CANTRELL, F S CAPHTON, D L CAPHTON, D L	8007150452* 8007290361* 8007300594* 8007220060* 8007230221*	50~564 G 50~438 G 50~518 G 50~219 G
BRUNNER, E J.	8007250258*	50-220 0	CAHILL, W. J.	8007170363	50-3 R	CAPHTON, D L	8007310131*	50-272 Q
BRUNNER, E J.	8007210251	50-333 0	Cahn, A. L.	8007230042	PR	CAPLAN, R	8007080046	50-320 Q
BRUNNER, E J.	8007230369	50-307 0	Cahn, A. L.	8007300452	TOPREP	CAPLAN, R	8007080048	50-320 G
BRUNNER, E J	8007230130	50-289 0	Cain, C. L.	8007300585*	50-254 0	CAPLAN, R	8007310128	50-277 Q
BRUNNER, E J	8007230377	50-307 0	Cain, C. L.	8007290244*	40-8102	CAPPER, W E	8007020650	71-381
BRUNNER, E J	8007020540	50-271 8	CAIN; J	8007210104	WABTE MOT	CAPRA,R A	8007030220	TOPREP
BRUNNER, E J,	8007020536	50-213 8	CALDHELL; R A	8007100225*	50-267 G	CAPRA,R A	8007240208	50-269 P
BRUNNER, E J	8007020145	50-247 8	CALDHELL; R A	8007070161*	50-284 G	CAPRA,L A	8007300168*	QA999
BRUNNER, E J	8007310499	50-247 0	CALDHELL; E	8007080255	50-155 H	CAPRA,L A	8007300178*	QA999
BRUNNER, E J,	8007310361	50-248 0	CALHOUN; J R	8007010382	50-327 B	CARACO,I R	8007140075*	QA999
BRUNNER, E J.	8007180445	50-219 Q	CALHOUN, J. R.	B007010435	50-327 6	CARBAUGH, E H	8007240009*	50-155 Q
BRUNNER, E J.	8007140615	50-334 S		B007010528	50-327 8	CARBON, M W	7904120321	50-353 Q
BRUNNER, E J.	8007230005	50-244 Q		B007010370	50-296 8	CARDILE, F P	8007100369	NUREQ
BRUNNER, E J.	8007310052	50-272 Q		B007010417	50-327 8	CAREY, N, W	8007010397	50-271 I
BRUNNER, E J	8007230182	50-293 Q		B007010479	50-327 8	CARFAGNO, S P	8007070368	50-338 P
BRUMMER, E. J.	8007230140	50-334 0	CALHOUN, J R	8007010525	50-327 8	CARLSON, R T	8007020066	50-322 8
BRUMMER, E. J.	8007230191	50-213 8	CALHOUN, J R	8007010534	50-327 8	CARLSON, R T	8007210326*	50-352 0
BRUMMER, E. J.	8007230241	50-220 0	CALHOUN, J, R	8007010490	50-327 8	CARLSON, R T	8007170668*	50-354 0
BRUMMER, E. J.	8007310104	50-272 0	CALHOUN, J R	8007010512	50-327 9	CARLSON, R T	8007010229*	50-443 0
BRUMMER, E. J.	8007280248	50-273 0	CALHOUN, J. R	8007080283	50-327 8	CARLSON, R T	8007020216	50-334 0
BRUNNER, E J	8007270010	50-220 8	CALHOUN, J. R	8007080273	50-259 8	CARLSON.R T	9007210345*	50-387 0
BRUNNER, E J	8007270058	50-286 8	CALHOUN, J. R	8007080301	50-259 8	CARLSON.R T	8007170606	50-286 0
BRUNNER, E J	8007250197	50-217 8	CALHOUN, J. R	8007080334	50-327 8	CARLSON.R T	8007170593	50-363 0
BRUNNER, J E	8007270701	50-327 A	CALHOUN, J. R	8007080394	50-260 8	CARLSON.R.T	8007210221*	50-352 0
BRYAN, J K	8007150006*	50-483 Q	CALHOUN, J. R	8007080405	50-260 8	CARLSON.R.T	9007020155	50-352 B
BRYAN, J K Bryan, J K Bryan, J K Bryan, J K Bryan, R H	8007150010* 8007210198 8007150534 8007250334 8007250334	50-483 0 50-483 0 50-483 F 50-483 S NUREG	CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R CALHOUN, J. R	8007110372 8007080281 8007080370 8007080413 8007080313	50-327	CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T CARLBON, R T	8007170437 8007010219 8007020111 8007170268 8007170283	50-387 Q 50-443 Q 50-410 S 50-354 Q 50-322 Q
BUCHHOLZ, R H	8007150104	PR	R L INDOHAD	8007080400	50-327 8	CARLBON.R T	8007020004	50-410 6
	8007140356	TOPREP	R L INDOHAD	8007090003	50-259 8	CARLBON.R T	8007170249	50-387 0
	8007140426	TOPREP	R L INDOHAD	8007110378	50-294 6	CARLBON.R T	8007210201	50-410 0
	8007090310	TOPREP	R L INDOHAD	8007110388	50-294 6	CARLBON.R T	8007210308	50-354 0
	8007150724	TOPREP	R L INDOHAD	8007150455	50-327 8	CARLBON.R T	8007220278	50-317 0
BUCHHOLZ, R. H BUCHHOLZ, R. H BUCHHOLZ, R. H BUCKALEW, W. H BUCKLEY, B.	8007220329 8007210391 8007210366 8007310007 8007020433	TOPREP NUREG Toprep Nureg 50-461 A	CALHOUN, J R	8007150504 8007150470 8007150580 8007150491 8007150570	50-327	CARLSON.R T CARLSON.J D CARLSON.R T CARLSON.R T CARLSON.R T	8007010182 8007170088* 8007170671 8007170610 8007170589	50-443 8 50-133 0 50-387 8 50-387 8 50-443 6
BUCKLEY, B. C	8007080343	50-275 A	CALHOUN.J R	8007160519	50-327 8	CARLSON:R T	8007180592	50-410
BUCKLEY, B. C	8007230029	50-275 A	CALHOUN.J R	8007210461	50-327 8	CARLBON:R T	8007300317	
BUCKLEY, B. C.	8007250550	50-275 A	CALHOUN.J R	8007180301	50-276 8	CARLBON:R T	8007300326	
BUDNITZ, R. J	8007230727	50-320 H	CALHOUN.J R.	8007220469	50-327 8	CARLBON:R.T	8007250267	
BULIBCHECK, T. S	8007220053	RES	CALHOUN.J R	8007230470	50-257 8	CARLBON:R.T	8007280242	
BULISCHECK, T,	8007180233	REB	CALHOUN, J R	8007250436	50-327 \$ 50-327 \$ 50-259 \$ 50-259 \$ 50-327 \$	CARLEON, R T	8007170454	50-354 0
BUMPUB, B E	8007240476	NUREG	CALHOUN, J R	8007220568		CARLEON, R T	8007280071	50-333 0
BUNKER, P. L.	8007220385*	50-302 P	CALHOUN, J R	8007230470		CARLEON, R T	8007140843	50-322 0
BUNTINO, J O	8007170481*	M18C	CALHOUN, J R	8007230523		CARLEON, R T	8007210013	50-443 A
BURACK, J. A	8007210320	70-157	CALHOUN, J R	8007250418		CARLEON, R T	8007210015	50-352 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CARLSON.R T CARLSON.R T CARLSON.R T CARLSON.R T CARLSON.R T	8007210048 8007310041 8007210045 8007210231 8007210276	50-462 S 50-277 Q 50-387 S 50-482 S 50-354 Q	CASHWELL,R J CATTON, I CATTON, I CAULDHELL,F S CAULDNELL,F S	8007310405* 8007220308 8007160240 8007020315 8007020695	50-156 R 50-3 D 50-142 F PR PR	CHILK, B J CHILK, S J CHILK, S J CHILK, B J CHILK, B J	8007230134 8007020661 8007020663 8007020664 8007020665	ACRS PR PR PR PR
CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8007210334 8007180534 8007250519 8007210033 8007210457	50-387 0 50-412 8 50-443 H 50-322 0 50-423 S	CAVANAUGH, W CAVANAUGH, W CECH, L CECH, L	8007100364 8007080066 8007150489 8007110423* 8007110448*	PRM 50-36B P 50-313 P 50-346 S 50-346 S	CHILK, B J CHILK, B J CHILK, B J CHILK, B J CHILK, B J	8007210331# 8007020647# 8007020660# 8007020602 8007020627	CONTRACT 70-143 70-149 50-443 0 50-271 0
CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8007210528 8007250287 8007210206 8007290249 8007290860	50-311 0 50-352 8 50-352 0 50-482 8 50-412 5	CEMBER, H CERNE, A C CERNE, A C CERNE, A C CERNE, A C	8007140483 8007010235* 8007210209* 8007180561* 8007210345*	REGOD 50-443	CHILK, S J CHILK, S J CHILK, S J CHILK, S J CHILK, S J	8007020656* 8007020597 8007100026* 8007090297 8007170282	70-143 50-395 M 50-295 O 50-452 O 10CFR
CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T CARLSON, R T	8007290845 8007310281 8007310289 8007310297 8007210533	50-387 \$ 50-352 \$ 50-354 \$ 50-482 \$ 50-423 Q	CHAFFEE, A CHAMBERLAIN W M CHANANIA,F D CHANANIA,F D CHANANIA,F D	8007210107* 8007140052 8007090223 8007090248 8007090252	50-224 Q PRM 50-375 M 50-395 M 50-395 M	CHILK.S J CHILK.S J CHILK.S J CHILK.S J	8007290758 8007300369 8007300394 8007300358 8007310462	50-445 Q 50-320 H 50-271 H 40-1162 50-409 Q
CARMEL, P CARMEAN, B D CARNEY, J J CARPENTER, J M CARPENTER, J M	8005090524* 8007080230 8007280059 8007310009 8007280683	PT9 MISC PR NUREG NUREG	CHANANIA,F D CHANANIA,F D CHANANIA,F D CHANDLER,L J CHANDLER,L J	9007150500 9007280620 8007280636* 8007030372 8007020094	50-445 M 50-445 M 50-445 M 50-320 H 50-320 Q	CHILSON, V T CHONGHI, N CHOWLES, N C CHOW, E T	8007240177* 8007100140 8007210481 8007230328* 8007110049*	50-250 R 50-339 P 50-320 H 50-305 G 50-263 G
CARROLL, D E CARROLL, D E CARROLL, D E CARROLL, J T CARTER, A R	8007020009* 8007010606 8007010607 8007230570 8007300074*	CONTRACT 50-10 0 ORO 50-219 8 COMMISSION	CHANDLER,L J CHANDLER,L J GHANDLER,L J CHANDLER,L J CHANDLER,L J	8007010304 8007030006 8007140034* 8007140006 8007070104	50-320 H 50-361 0 50-361 0 50-320 T 50-320 0	CHON, E T CHRISTIANSON, W CHRISTENBURY, E CHRISTOFFER, G CHRISTENBURY, E	8007240018* 8007100291* 8006120011 8007020211* 8007010138	50-301 Q 50-331 Q 50-261 T 50-275 Q 50-277 I
CARTER,K W CARTWRIGHT, J E CARTWRIGHT, U R CARTWRIGHT, U R CARTWRIGHT, N R	8007070278 8007020613 8007010353 8007010375* 8007010378	50-287	CHANDLER.L J CHANDLER.L J CHANDLER.L J CHANDLER.L J CHANDLER.L J	8007080061 8007090205 8007170357 8007140032 8007300271	50-320 0 50-361 0 50-320 0 50-341 0 50-320 P	CHRISTOFFER, O CHRISTENSEN, S CHURCH, J W CHURCHILL, B W CHURCHILL, B W	8007240107* 8007250413 8007150582* 8007230802 8007230802	50-263 0 50-344 0 50-327 P 50-502 0 50-502 0
CARTWRIGHT,W R CARTWRIGHT,W R CARTWRIGHT,W R CARTWRIGHT,W R CARTWRIGHT,W R	8007030262 8007030263 8007030270 8007030271* 8007030273	50-339 8 50-338 9 50-338 9 50-338 8 50-339 8	CHANDLER, L J CHANDLER, L J CHANDLER, L J CHANG, C I CHAPIN, D	8007310447 8007310470 8007310445 8007310225 8007140475	50-320 Q 50-361 Q 50-361 A NUREQ REGOD	CIESZIENICZ,S CIPOLLA,R C CLARDY,L CLARITY,H HE CLARK,A T	8007180336* 8007280404* 8007100291* 8007280489 8007020417	50-10 R 50-204 8 50-331 Q 50-263 P 50-269 P
CARTWRIGHT, U R	8007030275* 8007030281 8007030283* 8007030285 8007030288*	50-339 8 50-339 6 50-339 8 50-339 8 50-339 8	CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D CHAPLIN, B D	8007010458* 8007160525* 8007150519* 8007150514* 8007290817*	50-320 8 50-320 8 50-320 8 50-320 8 50-320 8	CLARK, A T CLARK, F H CLARK, R A CLARK, R A CLARK, R A	8007150057 8007140610 8007030194 8007020235 8007180538*	70-1308 NURE0 50-285 P 50-282 F 50-344 0
CARTWRIGHT,W R CARTWRIGHT,W R CARTWRIGHT,W R CARTWRIGHT,W R CARTWRIGHT,W R	8007070358 8007070343* 8007070374 8007070379* 8007090294	50-339 8 50-339 8 50-339 6 50-339 8 50-339 8	CHAPMAN, L D CHARMAN, L D CHARNDFF, Q CHARNDFF, Q CHASE, J W	8007110148 8007270233 8007300381 8007300381 8007280484*	RES RES 50-244 G 50-259 G	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8007100132 8007100136* 8007100141* 8007020288 8007030362	50-335 P 50-335 P 50-335 P 50-344 P 50-334 P
CARTWRIGHT, W R	8007090304* 8007090308 8007090312* 8007090317 8007090323*	50-339 8 50-339 8 50-339 8 50-339 8 50-339 8	CHATTERTON, M CHATTERTON, M CHAUDHARY, S K CHECK, P S CHECK, P, B	8007210102 8007240204 8007210309* 8007010176* 8007010207*	50-338 P 50-338 P 50-354 Q FOIA FOIA	CLARK.C CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8007100289* 8007100078 8007160365 8007160372* 8007160379*	50-352 H 50-339 P 50-344 P 50-344 P
CARTWRIGHT, W R	8007090335 8007090342* 8007090345 8007090353* 8007070373	50-339 8 50-339 8 50-338 6 50-338 8 50-338 8	CHECK, P B CHEN, J C CHEN, J C CHERN, W B CHERN, W B	8007170654* 8007170460 8007140642 8007180354 8007310246	50-270 P RES RES RES RUB NUREO	CLARK, R A CLARK, R A CLARK, R A CLARK, R A CLARK, R A	8007170472 8007170588 8007210123 8007100034* 8007180482	50-344 P 50-266 P 50-344 P 50-344 0
CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R CARTWRIGHT, W R	80070703B1* 8007140207 8007140225* 8007150686 8007150701*	50-338 \$ 50-339 8 50-339 8 50-338 8 50-338 8	CHESTER,R O CHESTER,R O CHIANO,R T CHIANOI,N J CHIANOI,N J	8007020356 8007140044 8007310217 8007080249 8007160377	RES RES NUREO 50-400 S 50-400 B	CLARK, A T CLARK, R A CLARK, R, A CLARK, R A CLAY, F, L	8007280035 8007180441 8007180448* 8007180454* 8007150047*	70-1308 50-344 P 50-344 P 50-344 P 70-1113
CARTWRIGHT, W R CARTWRIGHT, N R CARTWRIGHT, N R CARTWRIGHT, N R CARTWRIGHT, N R	8007150808 8007150810 8007150815* 8007150817* 8007150747	90-337 8 50-339 8 50-337 8 50-337 8 50-338 8	CHIANGI, N J CHILDERS, B CHILDS, W V CHILDS, W V	8007230247 8007090400 8007010495* 8007010519* 8007140374*	50-400 S REGOD 50-333 S 50-333 B 50-333 B	CLAY, E L CLAYTON, D N. CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007140527* 8007250396* 8007010424 8007010444 8007010489	70-143 50-397 A 50-364 A 50-348 8 50-364 A
CARTWRIGHT, W R	8007150777* 8007220575 8007220580* 8007220507 8007220512*	50-338 8 50-338 8 50-338 8 50-338 8 50-338 8	CHILDS'M A CHILDS'M A CHILDS'M A CHILDS'M A	8007140374* 8007150715* 8007280524* 8007280617* 8007280669*	50-333 8 50-333 8 50-333 8 50-333 8 50-333 8	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F, L	8007150714 8007010406 8007070292 8007070168 8007080222	50-348 P 50-348 B 50-364 A 50-348 R 50-364 A
CARTWRIGHT, N R	8007220401 8007220611* 8007230493 8007230497* 8007290838	50-337 9 50-339 9 50-339 9 50-339 9 50-338 8	CHILES, L CHILK, S J CHILK, S J CHILK, S J	8007110314* 8007140122* 8007140130* 8007220146* 8007140291*	50-335 H SECY SECY 50-482 Q FOIA	CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	8007090237 8007100185 8007210265 8007090214 8007100177	50-364 A 50-364 A 50-348 Q NUREO 50-364 A
CARTWRIGHT, N R CASE, E Q CASE, E Q CASE, E CASHWELL, R J	8007270843* 8007140066* 8007140071* 8007110547 8007310403	50-338 8 50-320 0 50-320 0 FDIA 50-156 R	CHILK'S A CHICK'S A CHICK'S A CHICK'S A CHICK'S A CHICK'S A	8007090114* 8007230234* 8007010308 8007280084* 8007230125	COMMISSION FOIA REGOD ORG ACRS	CLAYTON, F, L CLAYTON, F, L CLAYTON, F, L, CLAYTON, F, L CLAYTON, F, L	8007140343 8007160549 8007160579 8007290859 8007100261	50-364 A 90-348 Q 50-364 A 50-348 Q 50-348 K

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CLAYTON, F L	8007150662	50~348 R	COLLINS, J T COLLINS, J T COLLINS, J T COLLINS, J T	8007250237	50-320 8	CONTE,R J	8007240118	50-320 8
CLAYTON, F L	8007210479	50~348 P		8007170547	50-320 8	CONTE,R J	8007230218	50-320 8
CLAYTON, F L	8007220510	50~348 P		8007170462	50-320 R	CONTI,P L	8007010001	50-201 I
CLAYTON, F L	8007220558	50~348 P		8007170540	50-320 S	CONTRELL,F B	8007240327*	50-518 G
CLAYTON, F L	8007250320	50~364 A		8007180539	50-320 R	CONVERSANO,E	8007070418*	CONTRACT
CLAYTON, F. L.	9007220486	50~364 A	T L.SNIJLOD	8007230643	50-320 P	CONWAY, T W	8007220101*	WASTE MOT
	8007220554	50-348 P	T L.SNIJLOD	8007170553	50-320 8	CONWAY, J	8007170692*	50-219 G
	8007220410	50-364 A	T L.SNIJLOD	8007170564	50-320 S	CONWAY, W F	8007230699	50-271 G
	8007220591	50-364 A	T L.SNIJLOD	8007170557	50-320 S	CONWAY, T W	8007220036*	WASTE MOT
	8007230403	50-348 P	T L.SNIJLOD	8007240203	50-320 S	CONWAY, J T	8007010075	50-247 P
CLAYTON, F L	8007230495	50~364 A	COLLINS, M	8007150694	50-368 B	CONWAY, W F	8007180549	50-271 G
CLAYTON, F L	8007230492	50-364 A	COLLINS, M	8007150702	50-298 B	CONWAY, W F	8007180594	50-271 G
CLAYTON, F L	8007230510	50~364 G	COLLINS, M	8007150690	50-267 S	CONWAY, W F	8007180398	50-271 R
CLAYTON, F L	8007230546	50-364 A	COLLINS, J T	8007250719	50-320 R	CODK. R J	8006300138*	50-327 G
CLAYTON, F L	8007230553	50~348 P	COLLINS, J T	8007250713	50-320 F	CODK. R J	8007230412*	50-327 G
CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L CLAYTON F L	8007230567 8007230592 8007240071 8007310150 8007280557	50-364 A 50-364 A 50-364 A 50-364 Q 50-364 A	COLLINS.JT COLLINS.JT COLLINS.RC COLLINS.PF COLLINS.JT	8007240118 8007230218 8007280023 8007290055 8007310337	50-320 8 50-320 8 50-320 P MISC 50-320 P	N C.WGDS U R.WGDS U R.WGDS U R.WGDS U R.WGDS	8007020224 8007020649 8007020306 8007300304* 8007070119	PR 50-329
CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8007250479 8007280641 8007280490 8007290637 8007290642	50-348	COLLINS, M COLLINS, M COLLINS, M COLLINS, M	8007220397 8007220400 8007220401 8007220402 8007220404	50-295 6 50-295 8 50-295 8 50-295 8 50-295 8	COOK.J W COOK.J W COOK.J W COOK.J W	0007280060 8007310529* 8007140331* 8007150497 8007160612	50-327 A 50-327 G 50-275 R 50-327 A 50-327 G
CLAYTON, F L CLEMENT, C CLEMENT, C CLEMONS, P CLEVELAND, C J	8007310330 8007010450* 8007070372* 8007210304* 8007220038	50-364 Q 50-336 S 50-336 S 70-687 50-263 P	COLLINS, M COLLINS, M COLLINS, M COLLINS, M	8007220405 8007220404 8007220408 8007220409 8007220411	50-275 S 50-304 S 50-304 B 50-304 S 50-304 S	COOK. J W COOK. J W COOLEY, N J COONEY, M J	8007210483 8007290206 8007280124 8007240331* 8007070352	50-329 A 50-329 8 50-329 R 70-1257 50-278 8
CLOGBURN, T	8007210400*	50-368 S	COLLINS, M	8007220412	50-304 B	COONEY, M J	8007080214	50-277 8
CLUCAS, J A	8007010457	50-275 H	COLLINS, M	8007220413	50-304 B	COONEY, M J	8007180419	50-277 R
CLUSEN, R C	8007300234	FR	COLLINS, M	8007220414	50-304 B	COONEY, M J	8007210378	50-278 8
COCHRAN, T B	8007110006	70-143	COLLINS, J T	8007310136	50-287 R	COOPER, W E	8007310386	50-329 A
COCHRAN, T B	8007140498	FOIA	COLLINS, M	8007230339	50-237 B	COOPER, W E	8007110453	NUREO
COCHRAN, R G COCHRAN, R G COCHRAN, R G COFFEY, H E COFFMAN, F D	8007210502 8007210512* 8007240038 8007220101* 8007010073*	50-59 R 50-59 R 50-59 R Waste Mot Foia	COLLINS, M COLLINS, M COLLINS, M COLLINS, M	8007230345 8007230347 8007230351 8007230352 8007230357	50-295 8 50-295 8 50-295 8 50-295 8 50-295 8	COOPERAL J COPELANDAR L COPELANDAR L COPELANDAR L COPELANDAJ O	8007250501 8007030179 8007010366 8007100194 8007080058	50-298 8 PR 50-537 F 50-597 F 50-466 Q
COFFMAN, F D	8007010108*	FOIA	COLLING, M	B007230359	50-249 8	COPELAND, J Q.	8007090189	50-466 0
COFFMAN, F D	8007010114*	FOIA	COLLING, M	B007230397	50-245 8	COPELAND, J Q	8007080058	50-466 0
COFFMAN, F D	8007010126*	FOIA	COLLING, J T	B007310356	50-320 P	COPELAND, J Q	8007090189	50-466 0
COFFMAN, F D	8007010158*	FOIA	COLLING, J T	B007310458	50-320 P	COPELAND, R L	8007080264	50-537 B
COFFMAN, F D	9006120855	OEN TEC IB	COLLIER, R P	B007240394	NUREO	COPELAND, J Q	8007160639	50-466 0
CD001N, C L CD001N, C L CD001N, C L CD001N, C L CD001N, C L	8007030286* 8007020642* 8007110437* 8007110313* 8007150642*	50-321 S 50-321 S 50-366 S 50-321 S 50-366 B	COLOMBO, P COLOMBO, R W COLOMBO, R W COLOMBO, R W COLT, 8	8007310216 8007080277* 8007150592* 8007310418* 8007230630*	NUREO 50-312 8 50-312 R 50-312 8 50-320 H	GOPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O	8007160639 8007300417 8007250424 8007250424 8007270082	50-466 0 50-498 0 50-466 0 50-466 0
COGGIN, C L COGGIN, C L COGGIN, C L COGGIN, C L	8007280455* 8007170417* 8007210377* 8007210371* 8007220517*	50-366 8 50-321 9 50-366 8 50-321 8 50-321 8	COLTON.E COMPTON,R M CONDIE.K Q CONGEL.F J CONGEL.F J	8007020379 8007160742* 8007210017 8007030373 8007100369	XPORTLIC 50-338 Q REB NUREO NUREO NUREO	COPELAND, J G COPELAND, J G COPELAND, J G COPELAND, J G	8007300413 8007300447 8007300413 8007300447 8007300402	50-466 Q 50-466 Q 50-466 Q 50-466 Q 50-466 Q
COGOIN, C L COHEN, B L COHEN, I COHEN, B	8007300513* 8004300112* 8007280746* 8007250494* 8007070057*	50-321	CONGELIF J CONLONIT E CONLONIT E CONLONIT, E CONLONIT E	8007170359* 8007100413* 8007100435* 8007070169* 8007180234*	50-320	COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O	8007300435 8007310074 8007310308 8007300402 8007300435	50-466 Q 50-466 Q 50-466 Q 50-466 Q
COHEN, J C	8007180217*	State Prog	CONLON, T E	8007100151*	50-269	COPELAND, J G	8007310094	50-466 Q
COHIL B M	8007150119	FR	CONLON, T E	8007150021*		COPELAND, J G	800731030B	50-466 Q
COLBERT, W F	8007160697	50-341 A	CONLON, T E	8007180275*		CORBETT, J S	8007100441	71-9094
COLEMAN, R	8007170167	CONTRACT	CONLON, T E	8007290414*		CORBETT, J S	8007160417	71-9070
COLEMAN, R	8007240168	CONTRACT	CONNERB, E L	8007140027		CORCORAN, T	8007290221	40-299
COLEMAN, R	8007250556	CONTRACT	CONNELLY, D G	8007250587*	GA999	CORCORAN, T	8007020088*	50-10 U
COLEMAN, R	8007280712	CONTRACT	CONNER, T B	8007110553	PR	CORDANI, R A	8007010553	71-5341
COLEMAN, R	8007170217	CONTRACT	CONNER, T B	8007150112	PR	CORDANI, R A	8007020339	70-27
COULINS, P	8007020731*	CONTRACT	CONNELL, G	8007210377*	50-284 R	CORDANI, R A	8007020358*	70-27
COLLINS, R E	8007150071*	50-267 G	CONNER, T B	8007150058	27-39	CORE, M	8007070385*	50-285 S
COLLIER, R E COLLINS, P F COLLINS, J M COLLINS, J T COLLINS, F M	8007140096	PR	CONNER, T B	8007310424	50-395 M	CORNELL. D A	8007090418	REGOD
	8007020319	50-254 V	CONNOLLEY, J L	8007070385*	50-285 8	CORREA. M A	8007010523	50-272 J
	8007180428	50-400 V	CONRAD, E T	8007070058*	CONTRACT	CORREA. M. A	8007310342	50-272 J
	8007020182	50-320 R	CONRAD, R E	8007010334	50-334 P	CORREA. M A	8007310376	50-272 J
	8007210331*	CONTRACT	CONTE, R J	8007250207	50-320 8	CORREAN. J J	8007250028*	COMMIBBION
T L.BNIJLOO COLLINS.J T C.BNIJLOO T L.BNIJLOO T L.BNIJLOO	8007100183 8007110293 8007250207 8007250223 8007250201	50-320 P 50-320 P 50-320 B 50-287 S 50-320 S	CONTE, R J CONTE, R J CONTE, R, J CONTE, R J, CONTE, R J	8007250201 8007250214 8007250231 8007250237 8007170547	50-320 8 50-320 8 50-320 8 50-320 8 50-320 8	CORWIN.J W CORYELL.O P CORTELLO.F COSTELLO.F	8007110121 8007020220* 8007280225* 8007170349* 8007170438*	PR 70-1151 70-27 70-1869 FOIA
COLLING, F M	8007140203*	CONTRACT	CONTE.R J	8007170540	50-320 8	COSTELLO, F	8007140631*	40-8702
COLLING, J T	8007150053	50-320 R	CONTE.R J	8007170553	50-320 8	COTTLE, W T	8007170224*	50-327 G
COLLING, J T	8007180102	50-320 R	CONTE.R J	8007170564	50-320 9	COUNSIL, W G	8007300338*	50-213 P
COLLING, J T	8007250214	50-320 S	CONTE.R J	8007170557	50-320 8	COUNSIL, W G	8005300283	PR
COLLING, J T	8007250231	50-320 B	CONTE.R J	8007240203	50-320 8	COUNSIL, W G	8007100035	PR

429

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
COUNSIL.W O COUNSIL.W O COUNSIL.W O COUNSIL.W O	8007100035 8007020039 8007020472 8007170494 8007020472	PR 50-336 Q PR 50-213 Q PR	CREWS.E H CREWS.E H CREWS.E H CREWS.E H	8007090011 8007170561 8007080393 8007220219 8007310294	50-206 50-395 50-395	A Q Q	CROW, W T CROW, W T CROW, W T CROW, W T CROW, W T	8007010184* 8007020233* 8007030028* 8007280327* 8007220220*	70-2985 70-2910 70-1151 70-1319 70-135
COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	8007170519 8007010328 8007170320 8007170320 8007210520*	50-423 Q 50-245 P 50-213 Q 50-213 Q 50-423 S	CREWS,E H CREWS,E H CREWS,J L CREWS,J L CREWS,J L	8007070269 8007160252 8007300273 8007300339 8007300518	50-395 50-344 50-206	C A Q Q	CROW, W T CROW, W T CROW, W T CROW, W T	8007070195* 8007180078 8007230062* 8007240290* 8007240110*	70-1113 70-1151 70-2375 70-1739 70-1201
COUNBIL, W O COUNBIL, W O COUNBIL, W O COUNBIL, W O COUNBIL, W O	8007010337 8007030356 8007010337 8007010354 8007030356	50-213 F 50-245 F 50-213 F 50-423 Q 50-245 F	CREWS, J L CREWS, E H CREWS, E H CREWS, E H CREWS, E H	8007310321 8007170607 8007220390 8007220428 8007250308	50-375 50-375 50-375	Q A F A	CROWLY T CROWE, B M CROWELY, B R CROWLEY, B R	8007240125* 8007270083* 8007300113 8007070107* 8007100060*	70-27 70-143 PR 50-335 0 90-251 0
COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	8007010337 8007090294 8007180137 8007020569 8007180578	50-213 F PRM 50-213 Q 50-213 P 50-213 Q	CREWS.E H CREWS.E H CREWS.E H CREWS.E H	8007250459 8007250491 8007290626 8007250410# 8007080239#	50-395 50-395 50-336	S A F S	CROWLEY, B R CROWLEY, B R CROWN, H M CRUMP, M W CRUTCHFIELD, B	8007270432* 8007310501* 8007110539* 8007110248* 8007100077	50-566 0 50-270 0 CONTRACT TOPREP 50-206 P
COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8007020569 8007230048 8007290852 8007080164 8007290852	50~213 P PRM PR 50~334 P PR	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W	8007150163* 8007090373* 8005290612* 9007150314 8007020121*	70-364 50-271 PT9 70-2651 70-1100	Q	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007100102* 8007100107* 8007030335 8007100374 8007100401*	50-204 P 50-204 P 50-185 P 50-217 P
COUNSIL, W O COUNSIL, W O COUNSIL, W O	8007080135 8007070231 8007070251 8007070231 8007170425	50-245 P 50-213 F 50-245 P 50-213 F 50-213 F	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W	8005290603 8007310291 8007140631* 8007140627 8007210195*	PT9 70-474 40-8702 40-8702 70-33		CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007100408* 8007160421 8007160425* 8007160427* 8007250541	50-219 P 50-29 P 50-29 P 50-29 P 50-155 P
COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8007170425 8007100200 8007210387 8007140344 8007210237	50-213 F 50-245 P 50-245 P 50-334 P 50-213 P	CROCKER, H W CROCKER, H W CROCKER, H W CROCKER, H W CROCKET, L	9007230608* 8007010597 8007210190* 8007230212 8007310019		6 8	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007250846 8007250554 8007250858 8007010003 8007100276	50-245 P 50-217 P 50-10 P 50-237 P 50-255 P
COUNSIL,W O COUNSIL,W O COUNSIL,W O COUNSIL,W O	8007160369 8007210238 8007300324 8007220457 8007250300	50-213 G 50-336 P 50-213 P 50-245 P 50-245 P	CROLEY, B O CROSEMAN, W A CROSEMAN, W A CROSEMAN, W A CROSEMAN, W A	8007170612* 8007230574* 8007010212* 8007110076* 8007070091*	50-219 50-498 50-382	A 5 0 0	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8007100299* 8007110247 8007110254* 8007010111 8007010113	50-255 P 50-255 P 50-255 P 50-155 P 50-219 P
COUNBIL, W G COUNBIL, W G COUNBIL, W G COUNBIL, W G COWAR, F E	8007240053 8007240067 8007280574 8007280673 8007020605	50-213 P 50-213 P 50-245 P 50-213 P 50-478 Q	CROSSMAN, W A	8007110178* 8007100346* 8007110234* 8007240337* 8007020048	50-498 50-445 50-498	a a a s	CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D	8007010118 8007010120 8007010122 8007010124 8007010130	50-29 P 50-409 P 50-213 P 50-244 P 50-245 P
COWAN, F COWAN, B Z COWAN, B Z COWAN, B Z COWAN, B Z	8007300406 8007220560 8007220560 8007250685 8007250685	50-496 Q XPORTLIC XPORTLIC XPORTLIC XPORTLIC	CROSS.J L CROSSMAN,W A CROSSMAN,W A CROSSMAN,W A CROSSMAN	8007020740 8007180574* 8007230292* 8007280153* 8007210103	50-445 (50-498 (50-382 (9 9 9 9	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007010137 8007010146 8007020186 8007020190 8007020193	50-206 P 50-10 P 50-10 P 50-206 P 50-217 F
COX.F T COX.B CRABTREE,R A CRADDICK,W G CRAMER,E N	8007110056 8007020455* 8007080217 8007300575 8007140051*	PR 50-271 H 50-309 I NUREQ PR	CROSB.J L CROSB.J L CROSB.J L CROUSE.R P CROUSE.R P	8007250596 8007310067 8007300374 8007010254 8007240028*	50-259 (50-327 (50-346 (0 0 K 0 0	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007020402 8007020662 8007020666 8007020669 8007020676	50-409 D 50-10 Q 50-217 Q 50-245 Q 50-155 Q
CRAMER, E N CRANE, P A CRANE, P A CRANE, P A CRANE, P A	8007140036 8007250668 8007230667 8007280697 8007230016	PR 50-133	CROUSE, R P	8007020040 8007150824 8007170064 8007180310 8007140237	50-346 (50-346 (50-346 (0 0 0 0 0	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	8007010042 8007010217 8007010292 8007140623 8007140628#	50-10 P 50-10 P 50-10 P 50-244 P 50-244 P
CRANE,PA CRANE,PA CRANE,PA CRANE,PA CRANE,PA	8007240187 8007250658 8007140242 8007020374 8007010469	50-275 0 50-275 0 71-9094 50-275 A 50-133 P	CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P CROUSE, R P	8007010464 8007230076 8007230141 8007170532 8007180271	50-346 (50-346 (50-346 (р G G	CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D CRUTCHFIELD. D	800/140636* 80071/0042 80071/0240 8007020479 8007160457	50-244 P 50-155 F 50-407 F 50-10 P 50-10 P
CRANE, PA CRANE, PA CRANE, PA CRANE, PA CRANE, PA	8007070153 8007300280 8007160520 8007310468 8007150377	50-275 A 50-275 0 50-275 A 50-133 Q 50-275 F	CROUSE, R P	8007300141 8007070254 8007210216 8007310536# 8007150670	50-346 (50-346 (F Q Q	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007180289 8007250666 8007280107 8007180180 8007220198	50-255 P 50-255 P 50-244 P 50-155 H 50-206 P
CRANE, P A CRANE, P A CRANE, P A CREED, J R CREED, J R	8007180405 8007180340 8007180358 8007010578* 8007310267*	50-275	CROUSE, R P	8007230200 8007230200 8007250572 8007210454 8007270500	50-346 (50~346 (50~346 F	Q Q Q P Q	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8007220162* 8007220165* 8007240069 8007140236 8007240073	50-206 P 50-206 P 50-244 P 50-155 H 50-248 P
CREIGHTON, T CREMAR, D A CREWA, J L CREWA, E H CREWA, J L	8007220224* 8007070269 8007170569* 8007110489 8007220330	M180 50-10 D 50-206 G 50-395 B 50-73 Q	CROUSE,R P CROUSE,R P CROUSE,R P CROUSE,R P CROUSE,R P	8007310348 8007230581 8007250427 8007250382 8007250434	50-346 F 50-346 F 50-346 F	0 P P P	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	800/240079 800/180436 8007180438 800/180466 8007210638	50-409 P 50-10 P 50-10 P 50-27 P 50-409 P
CREMB' 1 F CLEMB' 1 F CLEMB' 1 F CLEMB' 1 F	8007210099 8007170084 8007240385 8007240407 8007240267	50-224	CROUSE, R. P CROUSE, R. P CROW, W. T. CROW, W. T CROW, W, T	8007280485 8007310380 8007010027 8007280179 8007020337	50-346 F 50-346 F 70-2909 70-143 70-824	p p	CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	800/230111 800/240295 800/250693 600/250694 800/280103	50-245 P 50-10 P 50-255 P 50-213 P 50-210 P
									· ·

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGGRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CRUTCHFIELD, D	8007290373	50-155 P	DALE, L F	8007160619	PR	DAVIS, A B	8007230549	70-925
CRUTCHFIELD, D	8007170049	50-206 H	DALE, L F	8007160610	50-416 A	DAVIS, S M	8007240153*	50-318 8
CRUTCHFIELD, D	8007280150	50-213 P	DALE, L F	8007070118	PR	DAVIS, S M	8007280453*	50-317 8
CRUTCHFIELD, D	8007250716	50-217 P	DALE, L F	8007250520*	50-416 B	DAVIS, S M	8007280676*	50-317 8
CRUTCHFIELD, D	8007280172	50-206 P	DALE, L F	8007010361	50-416 F	DAWSON, R S	8007290277	71-6717
CRUTCHFIELD, D	8007290364	50-155 P	DALE.L F	8007030245	50-416 A	DAWSON, D M	8007020611*	70-1308
CRUTCHFIELD, D	8007180196	50-213 F	DALE.L F	8007070245	50-416 E	DAWSON, R S	8007220279	71-9039
CRUTCHFIELD, D	8007240144	50-244 P	DALE.L F	8007210270	50-416 Q	DAWSON, R	8007290282*	71-6717
CRUTCHFIELD, D	8007280180	50-213 P	DALE.L F	8007110412	50-416 K	DEALE, V B	8007110042	50-522 0
CRUTCHFIELD, D	8007250032	50-10 P	DALE.L F	8007140388	50-416 E	DEAN, D	8007240472	XPORYLIC
CRUTCHFIELD, D	8007280142	50-244	DALE.L F	8007280494	50-416 A	DEASON, Y A	8007270171	RES
CRUTCHFIELD, D	8007280161		DALE.L F	6007180293	50-416 F	DEBDER.T K	8007150067	PR
CRUTCHFIELD, D	8007280206		DALE.L F	8007220569	50-416 A	DECKARD, J	8007250246*	50-546 V
CRUTCHFIELD, D	8007240250		DALTROFF.S L	8007210215*	50-277 Q	DECKER.T	8007170556*	50-315 G
CRUTCHFIELD, D	8007250691		DALTROFF.S L	6007010378	50-277 O	DEHART.R M	8007150077	PR
CRUTCHFIELD. D	8007280672	50-213 P	DALTROFF.S L	8007020072	50-277 Q	DELANEY, J C	8007010184*	70-2685
CRUTCHFIELD. D	8007250720	50-217 P	DALTROFF.S L	8007180104	50-277 Q	DELANEY, J C	8007010195*	70-2638
CRUTCHFIELD. D	8007280098	50-206 P	DALTROFF.S L	8007180117	50-277 Q	DELANEY, J C	8007020431*	70-2609
CRUTCHFIELD. D	8007280135	50-244 P	DALTROFF.S L	8007170507	50-277 Q	DELANEY, J C	8007020233*	70-2910
CRUTCHFIELD. D	8007280190	50-409 P	DALTROFF.S L	8007240003	PR	DELANEY, J C	8007020258	70-143
CRUTCHFIELD.D CULP.R H CULP.R H CULVER.J F CULVER.M N	8007300050 8007080058 8007080058 8007020444 8007150713*	50-244 F 50-466 G 50-466 G FR 50-302 R	DALTROFF.6 L DALTROFF.8 L DALTROFF.8 L DANCE.H C DANCE.H C	8007250631 8007210947 8007250511 8007010089 8007240272*	50-277 Q 50-277 Q 50-277 Q 50-277 Q 50-327 8 50-321 Q	DELANEY, J C DELANEY, J C DELANEY, J C DELANEY, J C DELANEY, J C	8007020304 8007240102* 8007230062* 8007240270* 8007240083*	70-143 70-1359 70-2375 70-1738 70-143
CUNNINGHAM, O E CUNNINGHAM, R E CUNNINGHAM, R E CUNNINGHAM, R E CUNNINGHAM, O E	8007010595	71-9980	BANCE, H C	8007280484*	50-259 G	DELGEDROE, L O	8007020076	50-295 Q
	8006170915	71-9139	DANCE, H C	8007100066*	50-321 G	DELGEDROE, L O	8007070267	50-373 K
	8007020078	50-201 P	DANCE, H C	8007170224*	50-327 G	DELGEDROE, L O	8007160606	50-373 A
	8007140580	50-201 P	DANCE, H C	8007310351*	50-259 G	DELLA RATTA, A	8007280746*	70-1100
	8007180460	71-9136	DANFORTH, J C	8007110571*	50-482 U	DELGNO, 8 D	8007150623*	50-315 8
CUNNINGHAM, A L	8007270404*	50-390 G	DANIELSON, D H	8007160741*	50-440 Q	DENNISON.A B DENNISON.A B DENNY, I L DENTON, H R DENTON, H R	8007110074	50-358 0
CUNNINGHAM, A L	8007270853*	50-328 G	DANIELSON, D H	8007180519*	50-456 Q		8007110094	50-358 0
CUNRINGHAM, O E	8007280058	71-170	DANIELSON, D H	8007240253*	50-358 Q		8007210108	40-2061
CUNRINGHAM, O H	8007300411	PR	DANIELSON, D H	8007230087*	50-358 Q		8007110548	BECY
CUNRINGHAM, O H	8007220003	70-143	DANIELSON, L J	8007150153	8EQQD		8007100098	BECY
CUNNINGHAM R N LARRAN J N LARRAN J M LARRAN J M LARRAN J M LARRAN J	8007310383 8007010537* 8007080410* 8007150599 8007280394*	50-5 F 50-206 S 50-206 S 50-206 R 50-206 S	DANIELSON, D H DANIELSON, D H DANIELSON, D H DANIELSON, D H DANIELSON, D H	8007230333* 8007230375* 8007230758* 8007230273* 8007310316*	50-346	DENTON, H R	8007010215* 8007170083 8004240480 8007160786 8007180481	FDIA ' 50-320 P 50-286 P 8ECY 50-553 H
CURRY, J B CURTIB, J R CURTIB, J R CURTIB, N W	6007300571 6007230277* 6007030021 6007310166* 6007230147	PR 50-204 G 50-206 B 50-288 G PR	DANIEL, 8 L DARIOS, E L DARMITZEL, R W DARMITZEL, R W DARMITZEL, R W	8007270251 8007020307 8007010347 8007160360 8007220347	NUREG PR TOPREP 50-70 P 50-70 P	DENTON, H R	8007110533 8007180463 8007180468 8007180067 8007180474	50-295 H 50-320 H 50-320 H 50-320 H 50-320 H
CONTENN W CONTENN W CONTENN W CONTENN W	8007110376* 8007270659* 8007080213 8007080240 8007140197	50-327 8 50-327 8 50-387 8 50-387 K 50-387 8	DAROIG, E L DAUCE, H DAVIDGON, R H DAVIDGON, D R DAVIDGON, D R	8007020329 8004240250 8007100328 8007180585* 8007180571*	PR 50-327 B PR 50-440 Q 50-440 Q	DENTON: H R	8007180492 8007230179 8007180060 8007180182 8007180459	50-320
CASTIO'N M CASTIO'N M CASTIO'N M CASTIO'N M	8007140340 8007140170 8007180434 8007240131 8007180282	50-397 8 50-397 6 50-387 6 50-387 K 50-387 8	DAVIDEON, D R DAVIDEON, D R DAVIDEON, D R DAVIDEON, D R DAVIDEON, D R	8007140534 8007080294 8007150553 8007230101 8007230321*	50-440 S 50-440 B 50-440 Q 50-440 Q 50-440 Q	DENTON, H R	8007270087 8007160731 8007210046 8007070021* 8007180546	50-320 H 50-320 H 8ECY 50-320 H
CURTIB, N W	8007180364	50-387 S	DAVIDSON, D R	8007150540	50-440 A	DENTON: M. R	8007180553	50-320 H
CURTIB, N W	8007240142*	50-387 K	DAVIDSON, D R	8007160406	50-440 G	DENTON: H. R	8007210208	50-320 H
CURTIB, N W	8007220441	50-387 F	DAVIDSON, D R	8007140598	50-440 B	DENTON: M. R	8006300097	ACRB
CURTIB, N W	8007250529	50-387 A	DAVIS, S	8007140611	PR	DENTON: H. R	8007020055	50-320 H
CURTIB, N W	8007250487	50-387 S	DAVIS, H A	8007030024	PR	DENTON: H. R	8007100207	50-302 P
CURTIS, N W CURTIS, N W CURTIS, N. W CURTIS, N. W CURTIS, N. W	8007280215 8007270455 8007270623 8007270264 8007270716	50-387 8 50-387 9 50-387 5 50-387 6 90-387 8	E A.SIVAD E A.SIVAD H L.SIVAD E R.SIVAD P L.SIVAD	8004240258 8004240276 8007070019* 8007210007 8007030050*	1&E 1&E 70-143 RES PR	DENTON, H. R.	8007250611 8007180004 8007180042 8007110195 8007010246	50-320 H
CURTNER, A P	8007230478	50-124 P	DAVIS.A B	8007100094	50-546 Q	DENTON.H R DENTON.H R DENTON.H R DENTON.H R DENTON.H R	9007020677	50-320 H
CUTCHIN, J M	8007010276	50-387 0	DAVIS.A B	8007140035	70-8		9007100392	MISC
CUTCHIN, J M	8007010273	50-387 0	DAVIS.A B	8007100085	50-409 Q		9007110493	90-320 H
CUTCHIN, J M	8007150709	50-387 0	DAVIS.A B	8007170545	50-315 Q		9007170549	90-320 H
CYPHERT, S B.	8007170364	50-445 M	DAVIS.O.R	8007110454	NASTE MOT		9007180224	MISC
CYPHERT.8 B	8007160547	50~449 H	DAVIS,C R	8007110457*	HASTE MOT	DENTON, H R	8007210530	50-320 H
CYPHERT.8 B	8007300418	50~445 M	DAVIS,A B	8007170300	70-925		8007170551	50-320 H
CYR.K	8007300370*	50~266 Q	DAVIS,A B	8007140464	50-344 Q		8007210645#	50-301 0
CYR.K D	8007100241	50~266 Q	DAVIS,A B	8007110200	50-10 Q		8007210647*	50-301 0
CYR.K D	8007290070	50~266 Q	DAVIS,A B	8007280454	50-87 Q		8007020090	50-443 H
CZYSCINSKI.K S	8007210005	RES	DAVIS, A B	8007210501	50-263 Q	DENTON: H R	8007020432	50-271 0
CZYSCINSKI.K S	8007310471	NUREQ	DAVIS, A B	8007230268	50-275 Q	DENTON: H R	8007020437*	50-271 0
D'AMORE,M	8007210077*	70-1:51	DAVIS, A B	8007160700	40-7782	DENTON: H R	8007100421	50-443 H
DAGBJARTSSON, S	8007310255	NUREO	DAVIS, A B	8007310335	50-275 Q	DENTON: H. R	8007100424	50-443 H
DAIL,L C.	8007030187*	50-413 A	DAVIS, A B	8007250626	70-925	DENTON: H R	8007140265*	50-346 M
DAIL:L C	8007210484*	50-413 A	DAVIS, J F	8007290622	50-312 P	DENTON, H R	8007180462	MIBC
DAIL:L C	8007250532	50-488 G	BAVIS, J P	8007210473	50-3 R	DENTON, H R	8007020325	COMMISSION
DALE:L F.	8007160617*	50-416 A	DAVIS, L D	8007210436	50-361 G	DENTON, H R	8007140040	50-320 0
DALE:L F	8007020615	50-416 B	DAVIS, L D	8007280710	70-925	DENTON, H R	8007280593*	50-320 0
DALE:L F	8007140575	PR	DAVIS, L D	8007160613	50-367 G	DENTON, H R	8007010254	50-484 0

AUTHOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
DENTON, H R	8007010263* 8007010272 8007030210 8007290047 8007100145	50-484 Q 50-484 Q 50-273 P 50-320 H 50-320 H	DICKINSON, P DICKEGN, H W DICKEGN, H W DICKEGN, H W DICKEGN, F S	8007010013 8007180352 8007140031 8007140634 8007280333	ORO RES RES RES 40-8745	DODDS, R T DODDS, R T DODDS, R T DODDS, R T DODDS, R T	8007170537# 8007180018# 8007210578* 8007240326# 8007240314#	50-361 Q 50-206 Q 50-528 Q 50-204 Q 50-344 Q
DENTON, H R	8007100399 8007290064 8007020243 8007020481 8007020485*	80-10 P 50-320 H 50-312 G 50-3 G	DICKSON, H W DICKSON, H W DIEHL, D S DICTCH, R DIETCH, R	8007300041 8007310251 8007030003 8007020362 8007020366*	NUREO RES PR 90-206 P 50-206 P	DODDS,R T DODDS,R T DOGGETT,S A DOHERTY,J F DOHERTY,J F	8007300318* 8007310516* 8007100174 8007030339 8007230246	50-361 0 50-928 0 50-466 0 50-466 A 50-466 0
DENTON, H R	8007020690 8007140106 8007070059 8007070064* 8007070069*	50-52B	DIGGS.R M DIGGS.R M DIMEGLIO.A F DIMEGLIO.A F DINCAUZE.D F	8007020510 8007210156 8007090272 8007210118 8007100079	50-277 P 50-331 P 50-193 P 71-17 PR	DOLAN, F X BOLAN, J E DOLAN, J E DOLAN, J E DOLAN, J E	8007220334* 6007310264* 6007110465 6007030206 6007020245	TOPREP 50-315 Q 50-315 Q 50-315 Q 50-315 Q
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007110484 8007140021 8007020399 8007290275 8007290287*	SECY 50-323 H 50-320 P 50-327 G 50-327 G	DIPIAZZA, R P DIPIAZZA, R P DIPIAZZA, R P DIPIAZZA, R P DIPIAZZA, R P	8006300292 8006300017 8007020221 8007100358 8007110522	70-1151 70-1151 70-1143 PRM PRM	DOLAN, J E DOLE, R DONAT, T J DONAT, T J DONEGAN, G C	8007020591 8007110571* 8007240377* 8007300330 8007300315*	50-315 P 50-486 U 50-369 G 50-369 B 00999
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007110082 8007110554 8007110563* 8007170330* 8007170333*	50-271 H 50-155 Q 50-155 Q 50-10 Q 50-10 Q	DIPIAZZA,R P DIPIAZZA,R P DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007180545 8007240076 8007300103* 8007020279* 8007300074*	70-1151 71-5450 70-143 NASTE MOT 70-143	DONOCHUE, D J DONOVAN, L J DORFMAN, L O DORNSIFE, W P DORNSIFE, W P	8007270023 8007250476 8007110327* 8007140046* 8007140046*	SECY TOPREP HISC PA PR
DENTON, H R	8007170336* 8007230225 8007230626 8007280122 8007290054	50-10 G 50-320 H 50-320 H 50-320 H 50-320 H	Dircks, W J Dircks, W J Dircks, W J Dircks, W J Dircks, W J	8007140102* 8005200252 8007090023*, 8007290286 8007290029*	50-397 0 50-320 U SECY PR SECY	DOTZLER, T DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8007290296* 8007310492* 8007220111* 8007140633* 8007010582*	50-327 Q FOIA HASTE MGT CONTRACT CONTRACT
DENTON, H R	8007300013 8007230542 8007230070 80072500B1 8007290234	50-320 H 50-440 H 50-320 H 50-320 H 50-312 H	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007290085 8007140118* 8007290028 8007250019* 8007140848	50-341 H 50-277 H SECY 10CFR COMMISSION	DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8007030071* 8007030357* 8007110575* 8007070052 9007070054*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007140572 8007220027 8007220129 8007300301 8007170439	REOGD 50-566 H 50-320 P XPORTLIC 50-337 P	DIRCKS, W J DIRCKS, W J DIRCKS, W J DIRCKS, W J	8007140854 8007180017 8006270181 8007020229 8007020264	COMMISSION State Prog 50-155 H 50-320 H Waste Mot	DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	8007070057# 8007070058* 8007070060* 8007070062* 8007160490	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007170443* 8007180174 8007280182 8007220031 8007230284	50-337 P RE00D 50-320 H 50-287 H 50-320 H	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007020113 8007010128 8007020117 8007020198 8007020053	State Prog State Prog 50-271 H 50-324 H 50-500 M	DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J BOUGHERTY, D J BOUGHERTY, D J	6007160476* 6007160476* 6007160504* 6007160513* 6007280527*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007230721 8007210649 8007230569 8007240297 8007240302*	COMMISSION 50-301 Q 50-320 H 50-327 P 50-327 P	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007020091 8007020069 8007020082 8007230117 8007110321	50-320 H MISC 50-10 U 50-201 P MISC	DRAGDNETTE,K 8 DRAKE,O A DRAPER.E L DRAPER.E L DRAPER.E L	8007020740 8007030366 8007290424 8007140495 8007220574	27-47 PR PR MUREO 50-458 Q
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007250624 8007280149 8007290039 8007250699 8007280076	50-289 H 50-561 H PROJ MISC 50-10 P	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007140230 8007110304 8007110335 8007110338 8007240132	NUREO 50-352 V 50-352 V	DRASTER, J J DREY, L A DREY, K DREY, K DREY, K	8007100122 8007100428 8007080226 8007210145 8007220386	REGOD REGOD 50-320 H 40-8502 50-10 D
DENTON, H R DENTON, H R DENTON, H R DENTON, H R DENTON, H R	8007290031 8007280106 8007290034 8007310549* 8007300284	50-289 H 50-320 H 50-483 A FDIA 50-259 P	DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007250225 8007250277 8007280823 8007280549 8007180214	50-546 U 50-275 H 50-329 H 50-171 H State Prog	DRISKILL, D D DRISKILL, D D DROMERICK, A N DROMERICK, A N DUBRY, N E	B007280137# B007150009* B007070053 B007280006 B007170310*	50-478 Q 50-478 Q 50-337 P 50-311 P 70-925
DEPOORTER, J DEVELIN, J, N DEVINCE, J DEVINCENTIS, J DEVINCENTIS, J	8007140405 8007140615 8007310266* 8007010223* 8007170576*	PR 50-334 8 F01A 50-443 Q 50-443 B	DIRCKS,W J DIRCKS,W J DIRCKS,W J DIRCKS,W J	8007250251 8007280509 8007150743 8007250167 8007280719	50-317 H 50-483 U FOIA 50-320 H PR	DUCE, 8 W DUCKWORTH, J P DUCKWORTH, J P DUCKWORTH, J P DUMMER, G H	8007270217 8007210028 80070100246 8007230441 0007210298*	50-254 P 50-201 Q 50-201 Q 50-201 Q CONTRACT
DEVINCENTIS, J DEVINE, J B DEVINE, J B DEVINE, J B	8007250623 8007310039 8007310194 8007300037 8007310522	50-443 G XPORTLIC XPORTLIC XPORTLIC XPORTLIC	Dircks, W J Dircks, W J Dircks, W J Dircks, W J	8007280714 8007240444 8007250062 8007250061* 8007310258	PR 50-335 H 50-320 H FOIA FOIA	DUNBAR, J DUNGAN, K W DUNGAN, K W DUNN, C N DUNN, C N	8007100192* 8007140468 8007160176 8006230660 8007230150*	50~237 G PR PR 50~334 G 50~334 G
DEVLIN, J W DEVLIN, J W DEVLIN, J W DEVLIN, J W	8007100074* 8005230131 8007240059* 8007230308* 8007290199*	50-293 Q 50-245 8 XPGRTLIC 50-289 Q 50-244 Q	DIRCKS, W J DIRCKS, W J DIRK, H DISE, D P DISE, D P	8007310524 8007310532 8007240413* 8007150122 8007070261	50-282 H 50-159 H 50-289 H PR 50-220 P	DUNN, C N DUNN, C N, DUNN, C N DUNN, C N	8007010375 8007210011 8007080276 8007080080 8007080186	50-334 P 50-334 G 50-334 G 50-334 P 50-334 P
DEWITT,R B DEWEY,L S. DEWEY,L S.	8007230366* 8007220443 8007150719 8007250407 8007100201*	50-213 0 50-259 R 50-250 M 50-389 M 50-255 P	DISE.D P DISE.D P DISE.D P DIXON.O A DIXON.B	8007070089 8007300049 8007170394* 8007280684* 8007280503	50-220 0 PR 50-220 P 50-409 0 50-344 Q	DUNN. C. N DUNN. C. N DUNN. C. N DUNN. C. N DUNN. B. D	B007080424 B007150643 B007160564* B007160654* B007170391*	50-334 0 50-334 0 50-334 P 50-334 0 50-280 R
DEWITT,R B DHILLON,H DIAMOND,M J DICKLJ W DICKERSON,M W	8007110207* 8007010619* 8007110101 8007310246 8007150091*	SO-155 P CONTRACT PR NUREO SO-267 Q	DOAN, P F DOBSON, W G DODDS, R T DODDS, R T DODDS, R T	8007090007* 8007310386 8007230639* 8007020191* 8007170270*	50-298 8 50-329 A 50-397 Q 50-361 Q 50-528 Q	DUNH.C N DUNN.C N DUNN.C N DUNN.C N	8007160480 8007160595 8007160595 8007160647 8007150483	50-334 P 50-334 P 50-334 0 50-334 C

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DUNN.C N DUNN.C N DUNN.C N DUNN.C N DUNN.C N	8007150567 8007180418 8007220504 8007150480 8007220588	50-334 Q 50-334 R 50-334 S 50-334 P 50-334 Q	EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8007170555 8007180150 8007280185 8007230198 8007310022	50-324 F 50-267 F 50-10 D 50-369 A 50-10 H	ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H	8007180295 8007180299 8007180304 8007180305 8007230381	50-312 0 50-397 0 70-1257 50-70 0 50-528 0
DUNN.C N DUNN.C N DUNN.C N DUNN.C N DUNNING.D E	8007170546 8007250294 8007290643 8007290680 8007090371	50-334 0 50-334 0 50-334 P 50-334 0 NUREO	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8007310025* 8007230083 8007230070 8007230075 8007230104	50-10 H 50-346 F 50-269 F 90-312 F 50-321 F	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007230385 8007230387 8007230390 8007230393 8007230394	50-275
A U, ARUD G U, SRUD G U, SRUD G U, SRUD G U, SRUD	B007110507 B007020225* B007170645* B007220285* B007170257*	PR 50-334 0 50-387 0 50-317 0 90-387 0	EISCHHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	6007230126 6007230184 8007230208 8007230616 8007250185	50-277 F 50-302 F 50-275 A 50-311 P 50-364 A	ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H	8007230399 8007230401 8007220065 8007170574+ 8007280143	50-312 G 50-397 G RES 50-260 P 50-361 B
DUTTON, D DUTTON, D DUTTON, D DUVALL, D D DWDRAK, J A	8007110521* 8007020218 8007220275 8007080191 8007240394	50-424	EISENHUT, D 0 EISENHUT, D 0 EISENHUT, D 0 EKLUND, S	8007300061 8007310358 8007290357 8007300275 8007020674*	50-259 F 50-295 H 50-259 Q 50-277 8 COMMISSION	ENGELKENIR H ENGELKENIR H ENGELIR E ENGLEHARTIR W ENGLEHARTIR W	8007310437* 8007310447 8007250515 8007220111* 8007220036*	50-344 B 50-397 A TOPREP WASTE MOT WASTE MOT
DYER, O H EADIE, O EADIE, O O EADIE, O O EADIE, O O	8007140495 8007070155 8007100082 8007230141 8007230279	PR WASTE MGT 40-8200 40-8714 40-8200	ELIN, J O ELLERBHAW, L E ELLERBHAW, L E ELLERBHAW, L E ELLERBHAW, L E	8007240314* 8007300198* 8007250109* 8007160207* 8007300314*	50-344 @ GA777 GA777 GA777 GA777	ENOLE, N J ERB, C M ERH, C A ERICKBON, R A ERICBON, D M	8007300590* 8007170635* 8007150023* 8007250055* 8007020011	CONTRACT 50-329 Q 50-483 Q FOIA RES
EADIE.G O EADIE.G EAGLETON.T F EARLEY.A F EARLLY.P J	8007250054 8007230720 8007110571* 8007090306 8007180111	40-1341 Waste Mgt 50-482 U 50-322 G 50-286 G	ELLIOTT, E D ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8007070092 8007090327 8007300346 8007310123 8007220546	PR 50-445	ERNST, M L ESKRIDGE, H E ESSIG, T H ESSIG, T H ESSIG, T H	8007310113 8007140613 8007100099* 8007280457* 8007230276*	NUREC 71-6294 50-546 G 50-87 G 50-295 G
EAST.D EASTER.J.H EBERSOLE,J C EBNETER.B D EDNETER.B.D	8007170106 8007020338* 8007240475 8007170611* 8007210309*	40-8745 State Prog ACRS 50-286 G 50-354 G	ELL TS. J EMRATH, R M ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007220559 8007220574# 8007140584 8007140587 8007020234	50-445 0 50-327 8 50-133 0 50-397 0 50-344 0	ETHERIDOE, M R ETHEREDOE, L EURY, L W EVANS, R D EVANS, V R	8007140037* 8007250072 8007210022 8007100030 8007160245	GA999 FOIA 50-261 G PR 50-317 F
EBNETER, S D EBNETER, S D EDNETER, S D ECKERNAN, K F ECKHARDT, B	8007250270* 8007280080* 8007310063* 8007030373 8007110278*	90-293 G 50-333 G 50-277 G NUREO COMMISSION	ENGELKEN, R H	8007020240 8007020242 8007020244 8007010016 8007220235	50-312 0 50-133 0 50-206 0 50-528 0 50-528 0	EVANB, V R EVDOKIMOFF, V N FABRIKANT, R FAHRNER, W J FAHRNER, W J	8007280481 8007090416 8007280636* 8007070078* 8007210136*	50-317 F RE00D 50-448 M 50-341 B 50-341 B
ECKHARDT, J H ECKHARDT, J H ECKHARDT, B EDDLEMAN EDELSTEIN, B	8007170539* 8007210578* 8007300365 8007100125 8007010577	50-361 Q 50-528 Q 50-498 U PRM XPORTLIC	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007220237 8007220239 8007220241 8007220244 8007220249	50-133	FAHRNER, W J FAHRNER, W J FAHRNER, W J FAIRHURBT, C FAIROBENT, J E	8007140326 8007170406 8007220545 8007030200 8007170362	50-341 9 50-341 8 50-341 6 PR 50-320 H
EDELSTEIN, B EDELSTEIN, B EDELSTEIN, B EDGEWORTH, P J EDGEWORTH, P J	8007020014 8007030063 8007160403 8007030337 8007070032	XPDRYLIC XPORTLIC XPORTLIC CONTRACT CONTRACT	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007220250 8007220252 8007140412 8007140414 8007140418	50-312	FAIRTILE, M II FALK, K M FALK, K M FANTLE, H	8007240037 8007280477 8007230607 8007310373 8007140227#	50-302 P 50-301 9 50-246 9 50-266 H 50-409 H
EDGEWORTH, P J EDGEWORTH, P J EDGEWORTH, P J EDMONDSON L R EDWARDS, D W	8007070037 8007090084 8007140626 8007280527* 8007110529	CONTRACT CONTRACT CONTRACT CONTRACT PRM	ENGELKEN, R H	8007290080 8007290086 8007290088 8007290090 8007030005	50-528	FARIS,H M FARLCY,A F FARLEY,A F FARNAN,J FARNELL,A S	8007210486* 8007030053 8007030053 8007310280 8007090045	50-413 A 50-322 0 50-322 0 FGIA 50-327 0
EDWARDE, D W EECKHOUT, A EGAN, G R EHRENSPERGER, W EHRENSPERGER, W	8007300009 8007210318* 8007280404* 8007080344 8007290774	PR XPDRYLIC 50-206 8 50-424 H 50-424 F	ENGELKEN, R H	8007030009 8007030007 8007030010 8007030014 8007030017	70-1257 70-734 50-206	FARNELL, A B FARNELL, A B FARNELL, A 9 FARODQUI, B M FARQOQUI, B M	B007090045 B007140020 B007140020 B007250393* B007250393*	50-327 Q 50-327 Q 50-327 Q 50-397 A 50-397 A
EICH, E EICHHORN, W H EICHHORN, W H EISENHUT, D G EISENHUT, D G	8007220479* 8007020453 8007020453 8006090165 8006130122	50-247 R 50-367 G 50-367 Q 50-320 P 50-320 P	ENGELKEN: R H ENGELKEN: R H ENGELKEN: R H ENGELKEN: R H	8007030018 8007020466 8007020470 8007020474 8007020477	50-344	FABANO, A FABANO, A FABANO, A FABANO, A FABANO, A	8007250207 8007250223 8007250201 8007250214 8007250231	50-320 8 50-287 8 50-320 8 50-320 8 50-320 8
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	9006230110 8006130063 8007020396 9007180471 8007180479*	50-275 A 50-320 F NUREQ TOPREP TOPREP	ENGELKEN'S H ENGELKEN'S H ENGELKEN'S H ENGELKEN'S H	8007020478 8007020480 8007180247 8007180251 8007180252	50-204 Q 50-312 Q 50-243 Q 50-288 Q 30-112 Q	FABANO, A FABANO, A N FAVLKENBERRY, B FAVLKENBERRY, B FAVLKENBERRY, B	8007250237 8007230218 8004240286 8004240300 8007170579*	50-320 8 50-320 8 50-312 8 50-206 8 50-206 0
EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	8007230079 8007180518 8007210032 8007020209 8007020183	50-320 P 50-344 Q 50-322 H 50-528 A 50-10 H	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007180254 8007180259 8007180261 8007180263 8007180266	50-27 G 50-224 G 50-142 G 50-433 G 50-326 G	FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B	8007220337* 8007210107* 8007240420* 8007240273* 8007310301*	50-73 0 50-224 9 50-312 9 50-206 9 50-312 9
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8007170323 8007180032 8007280079 8007310243 8007140221	50-10 G 50-10 G ORG 50-320 G 30-409 H	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007180267 8007180272 8007180274 8007180278 8007180281	50-139 0 50-228 0 50-89 Q 50-187 0 50-375 0	FAULKENBERRY, B FAUST, R FAY, C W FAY, C W FAY, C W	8007300343* 8007170071* 8007020340 8007140559 8007010030	50-206 G 50-317 P PR PR 50-266 G
EISENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8007170307 8007230001 8007240141 8007240477* 8007250001	50-289 P 50-275 A 50-269 P FOIA 50-320 P	ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	8007180283 8007180284 8007180287 8007180290 8007180292	70-984 50-528 G 50-133 G 50-344 G 50-206 G	FAY,C W Fay,C W Fay,C W Fay,C W	8007010062 8007160757 8007010043 8007010409 8007010420*	50-266 @ 50-266 @ 50-266 @ 50-266 \$ 50-266 \$

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	NO IBBBOOA REENUN	SUBJECT CATEODRY
FAY.C W FAY.C W FAY.C W FAY.C W FAY.C W	8007080381 8007080384* 8007110342 8007110347* 8007300085	50-301 8 50-301 8 50-301 8 50-301 8	FELTON, J M	8007240183 8007240474 8007280197 8007240453 8007250022	FOIA 50-443 H FOIA FOIA FOIA	FIDRELLI, Q FIDRELLI, Q FIDRELLI, Q FIDRELLI, Q FIDRELLI, Q	8007230754 8007310363 8007140198 8007140202 8007150027	50-275 Q 50-461 Q 50-483 8 90-461 B 50-358 8
FAY,C W	8007090230	50-301 'P	FELTON, J M	8007250067	FOIA	FIORELLI.O	8007150032	90-327 8
FAY,C W	8007110333	50-266 8	FELTON, J M	8007280267	FOIA	FIORELLI.O	8007210516	50-461 0
FAY,C W	8007110340*	50-266 9	FELTON, J M	8007310481	70-2478	FIORELLI.O	8007300151	50-483 0
FAY,C W	8007110353	50-301 9	FELTON, J M	8007310544	FOIA	FIORELLI.O	8007300160	50-483 0
FAY,C W	8007110357*	50-301 9	FELTON, J M	8007310232	FOIA	FIORELLI.O	8007140470	50-341 0
FAY, C W FAY, C W FAY, C W FAY, C W FAY, C W	80071 90648 80071 90682 80071 70526 80071 50653 8007220071	50-244 P 50-244 P 50-244 Q 50-244 P 50-244 Q	FELTON, J M FELTON, J M FELTON, J M FELTZ, D E FERGUSON, R	8007310276 8007310483 8007310285 8007290475* 8007240188*	FOIA FOIA 50-320 P 50-120 R FOIA	FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O FIORELLI, O	8007300132 8007300138 8007300300 8007150002 8007170186	50-331
FAY,C W	8007150618*	50-266 R	FERGUSON, J H	8007030131	50-280 P	FIORELLIO	8007170625	50-327 0
Fay,C W	8007210408	50-266 P	FERGUSON, J H	8007080069	50-338 P	FIORELLIO	8007310304	50-266 0
Fay,C W	8007240342	50-266 Q	FERGUSON, W J	8007150737	50-522 A	FIORELLIO	8007170478	50-341 8
Fay,C W	8007150610	50-266 R	FERGUSON, J H	8007110364	50-339 P	FIORELLIO	8007170520	50-327 8
Fay,C W	8007300430	50-301 Q	FERGUSON, J H	8007140393	50-338 P	FIORELLIO	8007210128	50-341 6
FAY.C W	8007300440	50-266 F	FERNOS, O	8007140581	50-376 Q	FIORELLI, O	800721000B	50-341 8
FAY.C W	8007300456	50-266 Q	FERNOS, O	6007230791	50-376 Q	FIORELLI, O	8007210012	50-546 8
FEE.W F	8007300331*	50-213 P	FERRARELLO, S	8007230573*	50-302 Q	FIORELLI, O	1007210021	50-546 8
PEE.W F	8007210387	50-245 P	FEUSS, J V	8007170277*	State Prog	FIORELLI, O	8007210025	50-546 8
FEE.W F	8007210238	50-336 P	FIDELL, E R	8007140619	50-320 H	FIORELLI, O	8007210031	50-546 8
FEE, W F	8007220457	50-245 P	FIELDER, J	8007010516	50-259 J	FIORELLI,O	8007210054	50-546 S
FEIERABEND, C D	8007070061*	50-202 Q	FIELDER, J	8007080261	50-364 J	FIORELLI,O	8007230615	50-546 S
FEIERABEND, C D	8007240210*	50-282 Q	FIELDER, J	8007310435	50-302 J	FIORELLI,O	8007150456	50-483 Q
FEIL, R A	8007180561*	50-410 Q	FIELDER, J	8007310436	50-259 J	FIORELLI,O	8007180511	50-461 S
FEIL, R	8007210545*	50-423 Q	FIELDS, M	8007310256	TOPREP	FIORELLI,O	8007180536	50-546 S
FEIT, R	8007220041	REVIEW GRP	FIENO.D	8007010103*	50-247 P	FIORELLI, Q	8007180503	50-358 8
FELTON, J M	8007020284	FOIA	FILKINB.D	8007280639*	50-244 8	FIORELLI, Q	8007180588	50-440 9
FELTON, J M	8007150756	FOIA	FINCKE.J R	8007290191	RES	FIORELLI, Q	8007180582	50-440 9
FELTON, J M	8007170264	70-1849	FINFROCK.I R	8007110023*	70-1335	FIORELLI, Q	8007240319	50-546 8
FELTON, J M	8007070026	50-514 D	FINFROCK.I R	8007010468	50-217 P	FIORELLI, Q	8007180545	50-440 8
FELTON, J M	8007280279#	FOIA	FINFROCK, I R	8007020377	50-219 G	FIORELLI,G	8007210283	50-373 Q
FELTON, J M	8006300220	50-320 H	FINFROCK, I R	8007030216	50-219 P	FIORELLI,G	8007230313	50-440 Q
FELTON, J M	8007010070	50-249 P	FINFROCK, I R	8007070257	50-219 8	FIORELLI,G	8007240340	50-456 Q
FELTON, J M	8007030004	70-2478	FINFROCK, I R	8007110370	50-219 S	FISCHER,K	8007280486	50-206 P
FELTON, J M	8007030033	FOIA	FINFROCK, I R	8007110375	50-219 S	FISH,R F	8007180130*	50-344 Q
FELTON.J M FELTON.J M FELTON.J M FELTON.J M FELTON.J M	8007110009 8007290235 8007020122 8007020132 8007020460	80-320 J PR Foia Foia Foia	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8007210042 8007090242 8007090259 8007250305 8007150705	50-219 G 50-219 F 50-219 G 50-219 G 50-219 R	FISH, R FISHER, W L FISHER, W L FISHER, C R	8007230203 8007230165 8007140041* 8007100089* 8007020205	50-344 6 50-312 8 70-8 50-407 G
FELTON, J M FELTON, J, M FELTON, J M FELTON, J M FELTON, J M	8007030064 8007030331 8007110478 8007140212 8007140277	FOIA FOIA 50~320 P FOIA FOIA	FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	8007160500 8007170279 8007180409 8007180415* 8007290184	50-217 P 50-217 P 50-217 P 50-217 P 50-217 P	FISHER, W L FISHER, W L FISHER, W L FISHER, W F	8007240007* 8007170310* 8007140471* 8007310515* 8007310002	50-155 O 70-925 50-346 Q 50-275 Q XPORTLIC
FELTON, J M	8007100008	70-143	FINKEL, A	8007210240*	50-352	F188E, L R	8007020438	PR
FELTON, J M	8007110004	70-143	FINKEL, A E	8007250270*		FITZPATRICK, T	8007160838*	COMMISSION
FELTON, J M	8007110004	Foia	FINKEL, A E	8007280080*		FITZSIMMONB, T	8007240154	71-9132
FELTON, J M	8007140237	Foia	FINKEL, A	8007310063*		FLANDERS, N	8007110389*	50-309 R
FELTON, J M	8007140226	Foia	FINLEY, A Q	8007270875*		FLEGER, S	8007070164*	NUREO
FELTON, J K	8007140616	50-320 H	FINLEY,N C	8007290251	NUREQ	FLEGER, B	8007070167*	NUREO
FELTON, J K	8007140233	50-320 H	FIGRELLI,O	8006300114	50-327 Q	FLEISCHAKER, D	8007160410	PRM
FELTON, J M	8007140635	50-458 H	FIGRELLI,O	8007140522	50-483 Q	FLEISCHAKER, D	8007100198	50-275 Q
FELTON, J K	8007140664	FQIA	FIGRELLI,O	8007110153	50-461 Q	FLCISCHAKER, D	8007230508	50-275 G
FELTON, J M	8007110139	50-302 H	FIGRELLI,O	8007090154	50-460 Q	FLEISCHAKER, D	8007230508	50-275 Q
FELTON, J K	8007140245	FOIA	FIORELLI.G	8007090174	50-440 Q	FLEIBCHAKER, D	8007300094	50-275 G
FELTON, J K	8007110149	FOIA	FIORELLI.G	8007110477	50-358 Q	FLEIBCHAKER, D	8007300094	50-275 G
FELTON, J K	8007140645	FOIA	FIORELLI.G	8007150017	50-483 Q	FLITTON, Y E	8007280174	RES
FELTON, J K	8007150786	FOIA	FIORELLI.G	8007160725	50-440 Q	FLOWERB, F D	8007070067	PR
FELTON, J K	8007140491	FOIA	FIORELLI.G	8007180508	50-454 Q	FLOYD, B O	8007220394*	50-331 P
FELTON, J M	8007140511	50-320 H	FIORELLI.O	8007150113	50-454 Q	FLOYD, 8 O	8007230484*	50~331 P
	8007170197	F01A	FIORELLI.O	80070200B1	50-341 Q	FLYNN, M J	8007020730	CONTRACT
	8007180098	50-302 H	FIORELLI.O	8007160469	50-546 Q	FLYNN, M J	8007030336	CONTRACT
	8007220207	F01A	FIORELLI.O	8007230002	50-456 Q	FLYNN, M J	8007110535	CONTRACT
	8007220263	40-299	FIORELLI.O	8007160751	50-461 Q	FLYNN, M J	8007210317	CONTRACT
FELTON, J M	8007220323	50-320 P	FIORELLI.Q	8007230072	50-358 Q	FLYNNIM J	8007140200	CONTRACT
FELTON, J M	8007220243	70-143	FIORELLI.Q	8007020027	50-546 Q	FLYNNIM J	8007170212	CONTRACT
FELTON, J M	8007230224	FQIA	FIORELLI.Q	8007180495	50-440 S	FLYNNIM J	8007180521	CONTRACT
FELTON, J M	8007230232	50-302 H	FIORELLI.Q	8007020324	50-358 S	FLYNNIM J	8007210105	CONTRACT
FELTON, J M	8007230240	50-466 G	FIORELLI.Q	8007070095	50-341 G	FLYNNIM J	8007210122	CONTRACT
FELTON, J M	8007230250	FOIA	FIGRELLI.G	8007230059	50-341 Q	FLYNN, M J	8007210154	CONTRACT
FELTON, J M	8007250083	FOIA	FIGRELLI.G	8007230402	50-329 Q	FLYNN, M J	8007140512	CONTRACT
FELTON, J M	8007280272	FOIA	FIGRELLI.G	8007110228	50-461 Q	FLYNN, M J	8007170135	CONTRACT
FELTON, J M	8007300082	70-143	FIGRELLI.G	8007110238	50-358 B	FLYNN, M J	8007300577	CONTRACT
FELTON, J M	8007230559	50-320 U	FIGRELLI.G	8007230327	50-346 Q	FLYNN, J, D	8007220280	90-358 A
FELTON, J M	8007230644	SO-10 D	FIORELLI,0	8007230345	50-304 @	FOBES, R L	8007220484*	50~255 B
	8007240195	FOIA	FIORELLI,0	8007230673	50-373 @	FOBES, R L	8007270616*	50~255 B
	8007240431	FOIA	FIORELLI,0	8007230704	50-546 @	FOGO, W	8007110279	50~255 K
	8007280283	FOIA	FIORELLI,0	8007070197	50-329 \$	FONNER, R L	8007210285	40~8502
	8007280290	FOIA	FIORELLI,0	8007230266	50-373 @	FONNER, R L	8007100446*	40~8502

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR	ACCESSION REMUN	SUBJECT CATEGORY
FONTECILLA.H M FONTECILLA.H FORD.U H FORD.C H FORD.C H	8007110496 8007110246* 8007110318 8007100113 8007230185	FOIA FOIA 50-546 U REGOD	GAMMILL,W P GANLEY,D E GARGER,S L GARCIA,P GARCIA,P	8007170675 8007180066* 8007220047 8007150074 8007100449	MISC 70-971 RES 40-9459 40-1162	GILLESPIE,F P GILLESPIE,F P GILLESPIE,F P GILLESPIE,F P GILLESPIE,F P	8007110113* 8007100095* 8007290393* 8007090170* 8007140086*	50-335 Q 50-261 Q 50-364 Q 50-369 Q 70-143
FOSTER, W E FOSTER, W E FOSTER, W E FOSTER, J FOSTER, S C	8007010171+ 8007250594+ 8007220208+ 8007110572 8007150479	0A999 0A999 0A999 CONTRACT 50-155 J	GARCIA:P J GARCIA:P J GARCIA:P J GARCIA:P J GARNER:P L	8007140693 8007100088 8007290262 8007230715 8007240459	40-4492 40-1162 40-1162 40-8452 NUREO	OILLESPIE,F P OILLESPIE,F P OILLEN,D H GILLESPIE,F P OILLETT,W T	8007140555* 8007160727* 8007230131 8007160761* 8007150547*	50~297
FOX.C J FOX.D F FRANCIS.E FRANCIS.F E FRANCIS.F E	8007010234 8007160126* 8007030226 8007150458 8007150458	TOPREP GA999 40-8745 50-484 G 50-484 G	GARNER, D GARRAHY, J J GARRETT, E G GARRITY, J H GARRITY, J H	8007180229 8007240389* 8006230378 8007110386 8007280604	50-346 P 70-2153 50-309 H 50-309 R 50-309 R	GILLETT, W T GILLESPIE, F P GILLEN, D M GILLEN, D GILLEN, D	8007150561* 8007180316* 8007230667 8007230672 8007230680	50-316 R 70-143 40-8728 40-8681 40-8584
FRANCIS, F E FRANXE, B FRANXE, B FRANTI, S P FREDERICK, E J	8007150458 8007020554* 8007150042 8007020453 8007290241	50-484 G 50-320 G 50-320 P 50-367 G RES	GARRISON,W A GARY,R J GARY,R J GARY,R J GARY,R J	8007310269* 8007140502* 8007170196 8007110592 8007140455	FOIA 50-445 Q 50-445 Q 50-445 Q 50-445 Q	GILLEN, D H GILLILAND, D L	8007230715 8007280577 8007280599 8007280637 8007230201	40-8452 50-70 P TOPREP 50-70 P NUREO
FREEBURN.R FREEMAN,R FREY.D O FREY.J M FRIES.B A	8007080285* 8007280671* 8007010055* 8007170418* 8007160446	TOPREP 50-409 G 50-546 H COMMISSION REGGO	GARY.R J GARY.R J GARY.F S GARY.R J GARY.R J	8007080062 8007080282 8007300027 8007180366 8007210352	50-446 8 50-445 F PR 50-445 A 50-445 8	OILMAN, D W OINSDERO, T OINSDERO, T OINSDERO, R	9007070234 9007190046 9007020085 9007210014 9007280537	50-205 P REB REB REB 50-10 D
FRIES.B A FRIES.R S FROST.S R FROST.S R FRYLING.R	8007100133 8007230100 8007100199 8007230473 8007150509	REGGD 40-7402 50-255 P 50-255 P 50-272 0	OARY.R J OASCHLER, J A GASSER, E R GASTON, H B OAY, N R	8007210478 8007290629 8007180193* 8007140473* 8007010060*	50-445 A 50-267 J CONTRACT 50-269 0 40-2674	GIROUX,E J GIROUX,E J GIVEL,M GLENN,J E	8007170236 8007170247 8007100188* 8007230237 8005020572	50-518 8 50-518 B PR 50-302 H 1&E
FULLER, J K FULLER, F. K FURBUSH, M H FURR, B J FURR, B J	8007220439 8007280645 8007180358 8007150097* 8007020087	PR 50-267 0 50-133 0 50-261 0 50-261 0	CAY,N R GEHR,A C GEHR,A C GENOLER,M W GEORGIOU,B S	B007010067* B007180405 B007300104 B007030305 B007300419	40-2674 50-275	QLISSMEYER, J A QDDDARD, R J QDQDL, E QDLDBERG, S C QOLDBERG, S C	8007170311 8007010331 8007250369 8007010131 8007070104	NUREQ 50-237 Q 30-10 D 50-399 Q 50-320 Q
FURR, B J FURR, B J FURR, B J FURR, B J FURR, B J	8007100031 8007220254 8007220240 8007170516 8007220227	50-261 0 50-261 0 50-324 0 50-324 0 50-261 0	OEOROIOU, B S OERSI, B J OERSINER, W C OERSINER, W C OERSINER, W C	8007250429 8007020345 8007110233* 8007210521* 8007110534	50-275	OOLDBERG, S C OOLDBERG, S C OOLDBERG, R OOLDBERG, S C	8007070074 8007170357 8007140875 8007140875 8007140891	50-250 Q 50-320 Q 50-346 M 50-346 M 50-320 Q
FURR. B J FURR. B J FURR. B J FURR. B J FURR. B J	6007240189 6007310449 6007260104 6007280111 6007250296	50-324	GERUSKY.T M GESSELL.T F GIBBONS.T D GIBBS.D C GIBBS.D C	8007100186* 8007310231 8007180275* 8007100005 8007280032	50-320 P NUREQ 50-375 G PR PR	GOLDBERG, B C GOLDBERG, B C GOLDMAN, M GOLDSMITH, R GOLDSMITH, R	8007220110 8007310314 8007080353* 8007180187* 8007180212*	50-599 0 50-502 0 PR 50-10 0 50-10 0
FURR.B J FURR.B J FURR.B J GASRIEL.E GADLER.S J	8007300561 8007310206 8007310306 8007030158 8007210150	50-324 0 50-324 0 50-324 0 PR 40-1341	OIBBS.H E OIBBS.M E OIBSON.A F OIBSON.A F OIBSON.J D	8007210446 8007300421 8007070019* 8007030370* 8007020327	50-255 G 50-329 G 70-143 70-1201 PR	GOLDBMITH, R GOLDBCHMIDT, N GOLDBMITH, R GOLDBMITH, R GOLDBMITH, R	8007020195* 8007020447 8007020203* 8007140625* 8007140629*	50-10 H PR 50-10 H 50-320 H 50-320 H
CAGLIARDD.TE CAGNE.GR CAHM.JW CAHM.JW CAHM.JW	8007210307* 8007180467* 8007010346* 8007080262* 8007080275*	50-277	OIEDT, J R OILBERT, L D OILBERTS, D E OILBERTS, D E OILBERTS, D E	B007250600 B007100346* B007170194* B007110234* B007210509*	40-1162 50-498 Q 50-306 Q 50-445 Q 50-263 Q	GOLDBMITH, W GOLDBMITH, R GOLDBMITH, R GOLDBMITH, R GOLDBMITH, R	8007290392* 8007230649 8007140337 8007140337 8007140337	QA979 50-10 D 50-10 Q 50-10 Q 50-10 Q
GAHR, J W GAHR, J W GAHR, J W GAHM, J W GAHR, J W	8007080425* 8007010506* 8007080215* 8007080304* 8007080407*	50-267 B 50-267 B 50-267 B 50-267 B 50-267 R	OILDERTS, D E OILBERTS, D E OILBERTS, D E, OILBERTS, D E OILBERTS, D E	8007010260 8007010267 8007010549 8007160707 8007140192*	50-282 0 50-282 0 50-282 0 50-282 0	COLDSMITH, R COLDSMITH, R CONCALVES, A COODLING, W	8007140337 8007220548 8007280537 8007030332 8007020237*	50-10 0 50-10 D 50-10 D FOIA 50-320 H
GAHM. J W GAHM. J W GAHM. J W GAMM. J W GAMIC. Z	8007100176* 8007230554* 8007230555* 8007230539* 8007140672*	50-267 S 50-267 S 50-267 S 50-267 S 50-267 S	GILBERT.R E GILBERTS.D E GILBERTS.D E GILBERTS.D E GILBERTS.D E	8007280730* 8007020162 8007210182 8007210132 8007310106	50-482	GOODLING, B GOODMAN, L B GOODWIN, W L GOODWIN, C GOODWIN, C	8007310375 8007160681* 8007100370* 8007280199 8007310472	50-289 H 50-407 R 70-1151 50-344 Q 50-344 Q
GALAZEN, T GALLAGHER, J U GALLAGHER, J H GALLAGHER, E J GALLAGHER, E J	8007290703 8007230722* 8007020041* 8007110148* 8007090159*	50-484	GILBERTS.D E GILBERTS.D E GILBERTS.D E GILBERTS.D E GILBERTS.D E	8007250565 8007250077 8007280057 8007220070 8007220542	50-263 Q 50-262 Q 50-263 Q 50-282 Q 50-282 Q	GOODWIN, C GOODWIN, C, GOODWIN, C GOODWIN, C,	8007250350 8007300296 8007150120* 8007250360 8007270889	50-344 Q 50-344 Q 50-344 Q 50-344 Q
			OILBERTS,D E GILBERTS,D E GILINBKY,V GILL,S A GILLELAND,J E	8007230211 8007290841 8007280725* 8007110014 8007300167	50-282 G 50-263 G COMMISSION 71-221 50-438 B	GOODHIN, G GOODHIN, C GOODHIN, C GOODHIN, C	8007210077* 8007010334 8007160420 8007070340 8007090227	70-1151 50-344 F FR 50-344 P 50-344 P
				8007100381* 8007100410* 8007010125* 8007070005* 8007140073*	70-1201 70-143 70-2478	ODDDWIN, C ODDDWIN, C ODDDWIN, C ODDDWIN, C	8007090300 8007090329 8007070300 8007070307* 8007090360	50-344 F 50-344 Q 50-344 P 50-344 P 50-344 P
				8007150107* 8007140527* 8007030278* 8007180401 8007280175	70-143	QDDDWIM, C QDDBWIM, C QDDDWIM, C QQDDWIM, C QORDON, Q J	8007160608 8007170424 8007250474 8007300387 8007160511	50-344 P 50-344 P 50-344 P 50-344 P 50-377 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEQURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CORDON, C COSSICK, L V COSSMANN, S R COSSMANN, S R	8007310231 8007170620 8007290174 8007280164 8007290201	NUREO 70-143 RES RES RES	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8007010258 8007010252 8007010245 8007010246 8007010271	50-352 Q 50-387 Q 50-443 Q 50-485 Q 50-354 Q	GRIER.B H GRIER.B H ORIER.B H GRIER.B H GRIER.B H	8007140287 8007280576 8007280581 8007280587 8007280594	50-387 Q 50-471 Q 50-412 Q 50-343 Q 50-322 Q
GRABOWSKI.A M	8007140001	50-367 Q	GRIER, B H ORIER, B H GRIER, B H GRIER, B H ORIER, B H	6007010275	50-213 Q	GRIER.B H	8007280600	50-423 Q
GRACE.R H	8007070275	50-309 P		8007010277	50-293 Q	GRIER.D H	8007280603	50-410 Q
GRAESSER.K L	8007140327	50-295 R		8007010279	50-317 Q	GRIER.B H	8007280608	50-352 Q
GRAESSER.K L	8007160655	50-295 8		8007010280	50-322 Q	GRIER.B H	8007280612	50-387 Q
GRAESSER.K L	8007220449	50-295 8		8007010283	50-363 Q	GRIER.B H	8007280614	50-354 Q
ORAESSER, K L	8007220587	50-304 8	ORIER, B H ORIER, B H GRIER, B H GRIER, B H ORIER, B H	8007010286	50-271 0	GRIER.B H	8007280616	50-443 0
ORAMBAU, Q	8007110145	State Prog		8007010288	50-29 0	GRIER.B H	8007280619	50-485 Q
ORANLUND, R W	8007100434	REGGD		8007010294	50-412 0	GRIER.B H	8007170581	50-277 P
ORAVES, R H	8007080077	50-213 8		8007010296	50-244 0	GRIER.B H	8007180530	50-29 P
ORAVES, R H	8007140359	50-213 8		8007010300	50-272 0	GRIER.B H	8007280401	50-293 Q
ORAVES.R H ORAVES.R H ORAVES.R H ORAVES.R H ORAY.F S	8007090321 8007180390 8007230411 8007250535 8007020368	50-213 8 50-213 R 50-213 Q 50-213 8 PR	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007010302 8007010303 8007010310 8007010312 8007010314	50~333	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007020612 8007020614 8007020617 8007020622 8007020625	70-364 50-317
ORAY, F S	8007020424	PR	GRIER, B H	8007010315	50-320 Q	ORIER, B H	8007020681	70-1143
ORAY, F S	8007030082	PR	GRIER, B H	8007010316	50-307 Q	ORIER, B H	8007020683	50-272 0
GRAY, J R	8007100029	50-344 G	GRIER, B H	8007010318	50-217 Q	ORIER, B H	8007020686	50-220 0
GRAY, J R	8007140023	70-1308	GRIER, B H	8007010321	50-334 Q	ORIER, B H	8007020687	50-286 0
GRAY, J R	8007170150	50-289 Q	GRIER, B H	8007010322	50-3 Q	ORIER, B H	8007020691	50-293 0
R (YARQ	8007170215	70-1308	GRIER, B H	8007020097	70-1100	GRIER, B H	8007020492	50-213 Q
RAY, J R	8007170220*	70-1308	GRIER, B H	8007020010	50-219 F	GRIER, B H	8007020494	50-334 Q
RAY, J R	8007250428	50-344 0	GRIER, B H	8007030399	50-219 F	GRIER, B H	8007020497	50-219 Q
RAY, J R	8007250433*	50-344 0	GRIER, B H	8007010545	50-219 Q	GRIER, B H	8007020700	50-245 Q
R L, YARQ	8007250437*	50-344 0	GRIER, B H	8007210551	50-293 Q	GRIER, B H	8007020703	50-277 Q
GREEN, H J	8007160478*	50-327 P	GRIER, B H	8007210554	50-317 G	ORIER.B H	8007020704	50-271 Q
GREENMAN, E O	8007230736*	50-277 Q	GRIER, B H	8007210555	50-3 G	ORIER.B H	8007020706	50-29 Q
OREENMAN, E O	8007020070*	50-277 Q	GRIER, B H	8007210559	50-213 G	ORIER.B H	8007020709	50-307 Q
GREENE, G A	8007310234	NUREQ	GRIER, B H	8007210561	50-334 G	ORIER.B H	8007020710	50-3 Q
OREENMAN, E	8007180101*	50-293 Q	GRIER, B H	8007210563	50-412 G	ORIER.B H	8007020713	50-244 Q
GREENMAN, E Q	8007170692*	50-219 0	GRIER, B H	8007210564	50-219 Q	ORIER.B H	8007020714	50-201 Q
OREENMAN, E Q	8007230137*	50-287 0	GRIER, B H	8007210548	50-363 Q	ORIER.B H	8007020715	50-320 Q
OREENMAN, E Q	8007020145	50-247 8	GRIER, B H	8007210571	50-322 Q	ORIER.B H	8007020717	50-333 Q
GREEN, D	8007160556*	50-259 R	GRIER, B H	8007210572	50-320 Q	ORIER.B H	8007150128	70-344
OREEN, D Q	8007150425	50-445 M	GRIER, B H	8007210575	50-309 Q	ORIER.B, H	8007020463	50-317 Q
OREEN,D G	8007250441	50-445 N	GRIER, B H	8007210580	50-245 Q	GRIER, B H	8007020484	50-293 Q
OREER,R H	8007108099*	50-546 Q	GRIER, B H	8007210585	50-220 Q	GRIER, B H	8007020487	50-244 Q
OREER,R J	8007280457*	50-87 Q	GRIER, B H	8007210590	50-410 Q	GRIER, B H	8007020489	50-220 Q
OREOER,L R,	800710089*	50-409 Q	GRIER, B H	8007210595	50-333 Q	GRIER, B H	8007020491	50-286 Q
OREOER,L R	8007240009*	50-155 Q	GRIER, B H	8007210595	50-286 Q	GRIER, B H	8007020492	50-277 Q
OREGER, L R	8007140471*	50-346 Q	GRIER, B. H	8007210400	50-277 Q	GRIER, B H	8007020494	50-245 0
OREGORY, W S	8007210607	REB	GRIER, B. H	8007210404	50-352 Q	GRIER, B H	8007020496	50-213 0
GRENIER, B L	8007230652*	50-275 A	GRIER, B. H	8007210404	50-387 Q	GRIER, B H	8007020497	50-3 0
ORENIER, B	8007160395*	50-275 A	GRIER, B. H	8007210410	50-272 Q	GRIER, B H	8007020498	50-334 0
OREW, P, C	8007030104	PR	GRIER, B. H	8007210412	50-354 Q	GRIER, B H	8007020501	50-309 0
ORIDLEY,R L	8007070249	QEN TEC 18	ORIER, D H	6007210613	50-443 0	GRIER, B H	8007020502	50-219 Q
ORIER,B H	8007100009	50-320 Q	ORIER, B H	8007210615	50-485 0	GRIER, B H	8007020503	50-354 Q
ORIER,B H	8007150141*	70-364	ORIER, B H	8007210619	50-244 0	GRIER, B H	8007020504	50-412 Q
ORIER,B H	8007210224*	50-277 Q	ORIER, B H	8007210623	50-271 0	GRIER, B H	8007020507	50-363 Q
ORIER,B H	8007090370	50-271 Q	ORIER, B H	8007210626	50-29 0	GRIER, B H	8007020508	50-485 Q
ORIER, B H	8007140431	50-354 Q	GRIER, B H	8007010399	50-219 F	GRIER, B H	8007020509	50-322 G
ORIER, B H	8007140433	50-271 Q	GRIER, B H	8007160337	50-317 Q	GRIER, B H	8007020511	50-410 G
ORIER, B H	8007140438	50-333 Q	GRIER, B H	8007160341	50-3 Q	GRIER, B H	8007020513	50-387 G
ORIER, B H	8007140440	50-273 Q	GRIER, B, H	8007160344	50-213 Q	GRIER, B H	8007020514	50-352 G
ORIER, B H	8007140445	50-219 Q	GRIER, B, H	8007160345	50-412 Q	GRIER, B H	8007020519	50-272 G
ORIER, B H	8007140452	50-245 Q	ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007160346	50-363 0	GRIER, B H	8007020521	50-333 G
ORIER, B H	8007140458	50-322 Q		8007160349	50-320 0	GRIER, B H	8007020524	50-443 Q
ORIER, B H	8007140459	50-410 Q		8007160352	50-309 0	GRIER, B H	8007020526	50-320 Q
ORIER, B H	8007140462	50-277 Q		8007160357	50-334 0	GRIER, B H	8007020528	50-271 Q
ORIER, B H	8007140466	50-387 Q		8007160358	50-286 0	GRIER, B H	8007020530	50-27 Q
ORIER.B H	8007140469	50-352 G	GRIER.B H	8007160362	50-272 Q	GRIER.B H	8007210120	50-289 Q
GRIER.B H	8007140474	50-220 G	GRIER.B H	8007160363	50-443 Q	GRIER.B H	8007160683	50-293 Q
GRIER.B H	8007250325*	50-286 G	GRIER.B H	8007160364	50-244 Q	GRIER.B H	8007160685	50-317 Q
GRIER.B H	8007020101	50-29 G	GRIER.B H	8007160367	50-485 Q	GRIER.B H	8007160688	50-3 Q
GRIER.B H	8007020110	50-334 G	GRIER.B H	8007160370	50-29 Q	GRIER.B H	8007160690	50-213 Q
ORIER, B H	8007020116	50-293	GRIER, B. H	8007160398	50-334 Q	GRIER.B H	8007160673	50-412 Q
ORIER, B H	8007020120		GRIER, B. H	8007160401	50-316 Q	GRIER.B H	8007160696	50-334 Q
ORIER, B H	8007020124		GRIER, B. H	8007160777	50-271 P	GRIER.B H.	8007160699	50-217 Q
ORIER, B H	8007020125		GRIER, B. H	8007220084	50-286 P	GRIER.B H	8007160701	50-383 Q
ORIER, B H	8007020133		GRIER, B. H	8007140254	50-217 Q	GRIER.B H	8007160704	50-322 Q
ORIER, B H	8007020134	50-244 Q	GRIER, B H	8007140257	50-273 Q	GRIER, B H	8007140708	50-320 Q
GRIER, B H	8007020140	50-213 Q	GRIER, B H	8007140260	50-245 Q	GRIER, B H	8007140711	50-309 Q
GRIER, B H	8007020143	50-277 Q	GRIER, B H	8007140264	50-410 Q	GRIER, B H	8007140714	50-248 Q
GRIER, B H	8007020144	50-245 Q	GRIER, B H	8007140267	50-277 Q	GRIER, B H	8007140717	50-410 Q
GRIER, B H	8007020147	50-333 Q	GRIER, B H	8007140269	50-333 Q	GRIER, B H	8007140720	50-220 Q
ORIER, B H	8007020154	50-284 Q	GRIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	8007140272	50-220 0	GRIER, B H	8007160723	50-333 9
GRIER, B H	8007020157	50-220 Q		8007140275	50-271 0	GRIER, B H,	8007160726	50-286 9
GRIER, B H	8007020161	50-320 Q		8007140278	50-322 0	GRIER, B H	8007160728	50-352 9
GRIER, B H	8007020163	50-307 Q		8007140280	50-352 0	GRIER, B H	8007160733	50-387 9
GRIER, B H	8007020165	50-217 Q		8007140284	50-354 0	GRIER, B H	8007160736	50-272 0

UFHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
. 8 H . 8 H . 8 H . B H	8007160737 8007160740 8007160744 8007160747 8007160750	50-354 Q 50-443 Q 50-485 Q 50-244 Q 50-271 Q	GRIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8007230128 8007230129 8007230132 8007230146 8007230149	50-322	HAIRSTON, W C	8007070199* 8007070204* 8007070208* 8007070214* 8007070217*	50-348 R 50-348 R 50-348 R 50-348 R 50-348 R
.B H .B H .B H .B H	8007160752 8007140780 8007140783 8007160788 8007160792	50-29 0 70-135 50-201 0 70-1143 50-77 0	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8007230151 8007230156 8007230159 8007230163 8007230166	50-410 0 50-286 0 50-352 0 50-277 0 50-387 0	HAIRSTON.W O HAIRSTON.W O HAIRSTON.W O HAIRSTON.W O HAIRSTON.W O	8007070219* 8007070223* 8007070226* 8007070228* 8007070230*	50-348 R 50-348 R 50-348 R 50-348 R 50-348 R
# 8. H 8. H 8. H 8.	8007160794 8007160803 8007160804 8007160809 8007160813	50~208 Q 50-97 Q 50-5 Q 50-225 Q 50-166 Q	ORIER.B H GRIER.B H GRIER.B H GRIER.B H GRIER.B H	8007230170 8007230173 8007230178 8007230180 8007230183	50-354 0 50-272 0 50-443 0 50-485 0 50-244 0	HAIRSTON, W C HAIRSTON, W C HAIRSTON, W C HAIRSTON, W C HAIRSTON, W C	8007070232* 8007160861 8007010446* 8007010412* 8007150668*	50-348 R 50-348 8 50-348 8 50-348 R
.B H .B H .B H	8007160820 8007160822 8007160825 8007160827 8007160828	50-134 0 50-179 0 50-20 0 50-57 0 50-223 0	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8007230186 8007230189 8007210289 8007230716 8007210197	50-271 0 50-29 0 70-687 50-277 0 50-277 0	HAIST, D P HAIST, D P HAIST, D. P HALE, C J HALE, C J	8007180018* 8007240326* 8007240314* 8007140088* 8007280088*	50-206 0 50-206 0 50-344 0 9A999 9A999
.B H &B H &B H &B H	8007140829 8007140831 8007140832 8007140833 8007140834	\$0-184 Q 70-398 \$0-47 Q \$0-170 Q \$0-277 Q	GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	8007210445 8007210451 8007250313 8007210071 8007210119	50-213 F 50-272 0 50-286 0 50-245 0 50-220 0	HALE.C J HALE.C J HALE.C J HALE.C J	8007140048* 8007140126* 8007150171* 8007290337* 8007290321*	GA999 GA999 GA999 GA999 GA999
.B H .B H .B H	8007140837 8007146840 8007140842 8007140845 8007140844	50-193 @ 70-1100 70-33 70-820 70-371	ORIER.B H ORIER.B H ORIER.B H ORIER.B H ORIER.B H	8007240323 8007240356 8007240372 8007240422 8007240430	50-333 Q 50-219 Q 50-293 Q 50-271 Q 50-277 Q	HALEMAN.QR HALEY.J HALL.RE HALL.R.E HALL.RE	8007020464 8007100191* 8007110076* 8007110234* 8007140447*	PR PR 50-382 0 50-445 0 50-382 0
# # # # # # # # # # # # # # # # # # #	R007160849 8007210126 8007210127 8007210133 8007210134	50-54 Q 50-77 Q 50-199 Q 50-20 Q 50-5 Q	ORIFFIS.C A ORIFFIN.W ORIMES.C T ORIMES.B K ORIMES.B K	8007310225 8007110101 8007230028 8007220216 8007140115	NUREO PR 50-219 P M160 50-277 H	HALL, R. E HALL, R. E HALL, R. E HALL, R. E HALL, R. E	8007240397# 8007280730# 8007140361 8007010372 8007010379	50-498 G 50-482 G 50-171 F 50-263 F 50-335 F
() B H. () B H () B H () B H () B H	8007210138 8007210140 8007210142 8007210143 8007210144	50-225 0 50-57 0 50-223 0 50-144 0 50-134 0	Grimes, B K Grimes, B K Grimes, B K Grimes, B K	8007110517 8007110439 8007030013 8007170259 8007300297	50-277 H NUREO 50-596 H 50-3 H 50-338 E	HALL,R E HALL,W C HALL,R E HALL,R A. HALLER,N M	8007270562 8007150326 8007270634 8007310269* 8007140121	50-237 F TOPREP 50-409 F FOIA SECY
1, B H 1, B H 1, B H 1, B H	8007210147 8007210149 8007210151 8007210153 8007210155	50-54 0 50-184 0 50-47 0 50-209 0 50-97 0	GROCE, R H GROCE, R. H GROCE, R H GROCE, R H GROCE, R H	8007210367 8007210379 8007210456 8007030225 8007210601	50-309 R 50-29 R 50-271 R 50-309 P 50-309 Q	HALSTEAD.R J HALSTEAD.R J HAMILL,M L HAMMERSCHMIDT HAMPBON,D C	8007140538 8007110257 8007250396* 8007240406 8007090395	PR PR 50-397 A 50-320 H REGOD
R, B H G B H G B H H B I H	8007210157 8007210161 8907210164 8007210171 8007210172	50-201 Q 50-193 Q 50-293 Q 50-317 Q 50-3 Q	ORONEMYER, E L OROSEMAN, K OROTENHUIS, M OROTENHUIS, M OROVER, J L	8007290050* 8007140214 8007140518 8007300567 8007280404*	8tate Prog FGIA 50-250 F 50-250 P 50-206 8	Han, K Han, B Y. Hanauer, S H Hangock, D Hangock, D	8007220142* 8007070034 8007170371* 8007030127 8007110019	GA999 XPORTLIC 50~556 G PR PR
R, B H R, B H R, D H R, B H R, B H	8007210174 8007210178 8007210181 8007210192 8007210193	50-213	GRUBB.R L GUILBERT.J GULBRANSEN.E A GUMBLE.F W GUMBLE.F W	8007030015 8007110242 8007100357 8007010455* 8007080354*	RES FOIA PRM 50-286 S 50-286 B	HANCOCK, J A HANCOCK, J A HANCOCK, J A HANCOCK, D HANCOCK, D	8007150503# 8007010463 8007110402 8007160570 8007160570	50-302 G 50-302 B 50-302 B 50-466 Q
R, B H R, B H R, B H R, B M R, B M	8007210199 8007210202 8007210204 8007210207 8007210207	50-322 G 50-320 G 50-309 G 50-245 G 50-410 G	QUPPY, J. P QURUNATHAM, 8 QUBTAFBON, P QUBTAVE, R P QUTH, R H	8007210003 8007220593* 8007010627* 8007020542 8007220538	RES 50-304 S CONTRACT CONTRACT 50-10 D	HANCOCK, D HANCOCK, D HANKLA, D J HANRAHAN, E J HANRAHAN, E J	8007160645 8007160645 8007210368 8007100032* 8007100038*	50-466 G 50-466 G 50-250 P 70-143 70-143
R. B H R. B H R. B H R. B H R. B H	8007210211 8007210218 8007210222 8007210225 8007210228	50-220 0 50-333 0 50-286 0 50-352 0 50-277 9	Kaase, W P Kaase, W P Haase, W P Haase, W P Haase, W P	8007230009* 8007110499 8006190126 8007020322 8007110578	50~244 Q TOPREP 50~241 P TOPREP TOPREP	HANRAHAN, E. J HANBEN, W. A HANBELL, D HANBEN, L. J HANBEN, L. J	8007140182 8007140541* 8007070028 8007020561 8007070177	50-247 P 50-483 G 50-514 D 71-9130 71-9130
R.B H R.B H R.B H R.B H R.B H	6007210271 8007210274 8007210278 8007210281 8007210284	50-387	Haabs, W P Haabs, W P Haabs, W P Haabs, W P Hackett, D B,	8007170693 8007140342* 8007250060 8007210229 8007030208*	50-206 P 50-29 P REGOD TDPREP 50-285 P	HANBEN, W A MANBEN, L. E, HANBEN, L. E HANBEN, L. E HANBEN, L. E	8007210125* 8007070004 8007070006* 8007070008* 8007240224	50-483 G XPORTLIC XPORTLIC XPORTLIC XPORTLIC
R, B H R, B H R, B H R, B H	8007210286 8007210290 8007210291 8007210294 8007210312	50-244 0 50-271 0 50-29 0 50-170 0 50-352 0	HAFERA.T HAGA.PB HAGAN.TF HAGAN.TE HAGAN.TT	8007150625* 8007210375 8007020386 8007070127 8007100304	50-254 R 50-437 A CONTRACT CONTRACT CONTRACT	HANSEN, L. E HANSEN, M. A HANSEN, L. E HANSON, W. W HARBIGON, D	8007240247* 8007300169* 8007160386 8007220307 8007160807	XPORTLIC 50-463 Q 71-6581 40-299 50-329 B
18, B H 18, B H 18, B H 18, B H 8, B H	8007250543 8007210019 8007230091 8007230076 8007230106	50-334	Hagan, T Hagen, H Hager, R Hager, R	8007180184 8007010103* 8007020550 8007280613 8007020007	CONTRACT 50-249 P 50-320 G 50-320 G CONTRACT	HARMON, D W HARMON, D W HARMON, D, W, HARRAN, G HARRIS, J, R	8007310503* 8007240434 8007310018 8007160680* 8007150021*	FOIA XPORTLIC XPORTLIC 50-245 R 50-269 G
IR, B H IR, B H IR, B H IR, B H IR, B H	8007230107 8007230113 8007230113 8007230121 8007230122	50-213	HACEY, H Hairston, W o Hairston, W o Hairston, W o Hairston, W o	8007250569 8007070174* 8007070180* 8007070190* 8007070194*	CONTRACT 50-348 R 50-348 R 50-348 R 50-348 R	HARRISON, JJ HARRISON, HC HARRISON, HC HARRISON, JE HARRISON, JE	8007160479* 8007170297* 8007170329* 8007110012* 8007110010	50-546 @ 40-8602 40-8681 XPORTLIC XPORTLIC

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
HARRIS, J R HARRISON, J J HARRISON, P HART, E W	8007270414* 8007230710* 8007330475 80072790600* 8007020316	50-424 Q 50-546 Q PR	HELFRICH. O F HELFRICH. O F HELM. K HELTEMES. C J HELTEMES. C J	8007170255 8007270212 8007020383 8007020089 8007020248	XPORTLIC XPORTLIC XPORTLIC TOPREP SECY	HERLIHY, D HERLIHY, D HERLIHY, D HERMANN, R A HERNANDEZ, G	B007280694 8007220070* B007220063 8007010224 8007230639*	CATEODRY
HART, J HARTER, E S HARTIGAN, J P HARTIGAN, J P HARTIGAN, J P HARTIGAN, J P	6007080239* 8007010266 8007110397* 8007220378* 8007280602*	50-382 8 40-8438 50-344 8 50-346 8 50-346 8	HELWIO,R A HELWICK,C HEMBY,E O HEMMINGER,E O HENDRIE,J M	8007070054* 8007070177 8007280487* 8007070362 8007180036	CONTRACT 50-142 O 50-594 A NUREO COMMIGSION	HERNANDEZ, O HERNANDEZ, O HERR, R. K HERSCH, M. M HERSKOUITZ, M. B	8007170539* 8007210578* 8007150009* 8007070024* 8007150014	50-361 Q 50-528 Q 50-498 Q XPORTLIC RES
HARTMAN, C J HARTMANN, A J HARTMAN, C J HARVEY, B L HARVEY, S L	8007280643* 8007230478 8007020644* 8007080346 8007170183*	50-346 S 50-155 F TOPREP 50-155 R 50-337 P	HENDRIE, J M HENDRIE, J M HENDRICKSON, T A HENDRICKSON, T A	7909110639 7909240355 7909260587 8007160109* 8007010584	COMMISSION COMMISSION CA999 COMMISSION	HESS.R J HESS.R J HESS.R J HEVBNER.A T HEWARD.R W	8007280495* 8007070125 8007280479 8007030113 8007030334	50-594 A XPORTLIC 50-594 A PR 50-320 T
HABHIMOTO, K HATFIELD, M D HATHAWAY, L R HAUGHNEY, C J HAUGHNEY, C J	8007170189* 8007140686 8007020188* 8007160415 8007020515	50-337 P REGOD COMMISSION PR 50-201 P	HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M HENNINO-BACHS, C	8007020672 8007070270 8007250007 8007250111 8007270251	COMMISSION TOPREP COMMISSION NUREO	HEYER,R S HICKEY,A E HICKLE,B J HICKMAN,O L HICKS,M M	8007230084 8007180208* 8007170377* 8007020033 8007100348	40-8585 50-213 F 50-285 R 70-2909 PR
HAUDHNEY, C J HAUDHNEY, C J HAVERKAMP, D HAWKINB, K L HAYDEN, L E	8007090384 8007140193 8007280069 8007250223 8007160644	50-201 P 50-201 P 50-201 P 50-289 B 50-352 H	HENRY, L HENRY, Q W HENSLEY, K D HENSLEY, K D	8007290067* 8007100181 8007100052* 8007100069* 8007100023*	50-320 H REGOD 70-143 70-143 70-143	HIESTAND, DS HIGGINS, JC HILF, CL HILGER, W HILL, NM	8007170348 8007310504* 8007170574* 8007180063* 8007310055*	50-409 Q 50-247 G 50-260 P 50-219 H 50-272 Q
HAYES, D W	8007210079 8007090179* 8007090159* 8007110479* 8007230412*	PT21 50-440 Q 50-440 Q 50-358 Q 50-329 Q	Hengley, K d Herbein, J o Herbein, J o Herbein, J o	8007180555 8007110040* 8007110032* 8007010155 8007020535	70-143 50-320 J 50-320 J 50-289 Q 50-289 Q	HILL, T M HILL, O E HILLMAN, R E HIMEDAUCH, N HIND, J A	8007280194 8007220503* 8007150712* 8007080348* 8007020211*	WASTE MGT TOPREP 50-217 R 50-155 R 50-295 Q
HAYEB, D W HAYHURST, R S HAYNEB, J Q HAZELRIQO, S	8007300143* 8007300136* 8007310469* 8007290706 8007010500*	50~454 Q 50~331 Q 50~320 Q 50~206 P 50~275 S	Herbein, J o Herbein, J o Herbein, J o Herbein, J o	8007010326 8007010388 8007070266 8007070248 8007070281	50-287 P 50-287 F 50-287 Q 50-287 S 50-287 P	A C.ONIH A C.ONIH A C.ONIH A C.ONIH A C.ONIH	8007020197 8007010578# 8007010573 8007110518# 8007110513	50-275 0 70-1308 70-1308 70-1308 70-925 70-925
HAZLE, A J HEALY, J W HEALY, J W HECTOR, A G HEDDINGB, T P	8007010274# 8007180603 8007100053 8007110019 8007180528	WASTE MOT ACRS REOOD PR WASTE MOT	HERBEIN, J Q	8007070274 8007070302 8007070343 8007080074 8007080244	50-320 P 50-287 S 50-287 P 50-287 P 50-287 F	A L'IGNIH A L'IGNIH A L'IGNIH A L'IGNIH A L'IGNIH	8007140094 8007140430 8007140682* 8007150096* 8007240107*	50-282 G 50-155 G 70-1193 70-2609 50-263 G
HEDEMAN, W N	8007110024 8007020400 8007280037 8007290696 8007240462	PR PR PR 50~10 D FOIA	HERBEIN, J O	8007080358 8007110446 8007140385 8007140419 8007080211	50-320 P 50-287 Q 50-320 H 50-320 P 50-289 B	A L'GNIH A L'GNIH A L'GNIH A L'GNIH A L'GNIH	8007140675 8007150092 8007240104 8007240024 8007310261	70-1193 70-2609 50-263 Q 50-346 Q 50-305 Q
HEGNER, L H HEIDER, L H HEIDER, L H HEIDER, L H	8007230174* 8007150143 8007110460 8007210579 8007230173	50-334 Q PR 50-271 Q 50-271 Q 50-271 Q	HERBEIN, JOHERBEIN, JO	8007080375 8007150721 8007140346 8007140365 8007140381	50-289 Q 50-289 Q 50-289 P 50-289 P 50-289 Q	HIND. J A HIND. J A HIND. J A HINBS. E HINBS. E	8007310267* 8007270867 8007270875* 8007140481* 8007140425	50-305 Q 50-254 Q 50-254 Q 50-264 Q 50-341 Q
HEIDER, L. H. HEIDER, L. H. HEIDER, L. H HEIM, Q. E. HEIMEMANN, J. M	8007250188 8007250278 8007140338 8007280236* 8007100218	50-271 Q 50-29 Q 50-29 P CONTRACT 50-10 D	HERBEIN, J G HERBEIN, J G HERBEIN, J G HERBEIN, J G HERBEIN, J G	8007180414 8007180587 8007160524 8007160618 8007160667	50-289 P 50-287 P 50-289 S 50-289 S 50-320 F	HIRATA, Y HIRATA, Y HO, F P HOADLEY, S D HOADLEY, S D	8007290487* 8007290477* 8007240409 8007160394 8007160399*	QA999 QA999 NUREQ XPORTLIC XPORTLIC
HEINEKE, J. M. HEINEKE, J. M. HEIBHMAN, R. F. HEIBHMAN, R. F. HEIBHMAN, R. F.	8007220024 8007220034 8007220112* 8007220095 8007100283	NUREO NUREO 50-315 Q 50-315 Q 90-331 Q	HERBEIN, J O	8007220498 8007220353 8007250356 8007180404 8007210372	71-9081 50-320 F 50-289 Q 50-320 J 50-289 P	HOAGLAND, X E HODGODN, A P. HODGES, J W HODGES, J W HODGES, J N	8007310019 8007010298 8007140527# 8007030298# 8007290393#	50-219 P 50-449 M 70-143 70-143
HEISHMAN, R F HEISHMAN, R, F HEISHMAN, R, F HEISHMAN, R, F HEISHMAN, R F,	8007070051 8007010178 8007140485 8007140548 8007140487	50-282 Q 50-255 Q 50-155 Q 50-346 Q 50-263 Q	Herbein, J o Herbein, J o Herbein, J o Herbein, J o	8007220584 8007210398 8007290504 8007220471 8007220592	50-320 J 50-287 Q 50-287 Q 50-287 F 50-289 Q	HODOEB, J W HODSON, W L HOEFLING, R K HOFFMAN, D P HOFFMAN, D P	8007160727* 8007070112 8007100241 8007210427 8007210427	70-1113 PR 90-246 Q 50-255 R
HEIBHMAN, R F HEIBHMAN, R F HEIBHMAN, R F HEIBHMAN, R F, HEIBHMAN, R F	8007110049* 8007110044 8007210322 8007240012 8007240185	50-263 Q 50-263 Q 50-346 Q 50-301 Q 50-282 Q	HERBEIN, J O HERBEIN, J O HERBEIN, J O HERBOLGHEMIER	8007220492 8007250401 8007270617 8007270799 8007270621	50-289 Q 50-289 Q 50-289 Q 50-289 R 50-10 D	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007100072 8007010200 8007150134 8007010313 8007010447	FR 50-155 P PR 50-155 Q 50-155 P
HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F HEISHMAN, R F	8007240236 8007230296 8007230314 8007230371 8007300307	50-358 Q 50-331 G 50-305 Q 50-10 Q 50-263 Q	HERDIA R HERDIA R HERDIA R HERDIA R HERDIA R	8007170129* 8007160872* 8007070107* 8007100131* 8007100060*	CONTRACT 50-414 G 50-335 G 50-327 G 50-251 G	HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P. HOFFMAN, D. P.	8007010473 8007240134 8007070210 8007030250 8007030250	50-155 F PR 50-155 P 50-255 P
HEISHMAN, R F HEISHMAN, R F HEISHMAN, R, F HEISHMAN, R, F HEISHMAN, R F,	8007140184 8007300401 8007150102 8007230275 8007240307	50-282 Q 50-346 Q 50-358 Q 50-373 Q 50-346 Q	HERDT.A R HERDT.A R HERDT.A R HERDT.A R HERDT.A R	8007290432*	50-338 Q 50-400 Q 50-338 Q 50-566 Q 50-416 Q	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P	8007080189 8007080338 8007310177 8007110204 8007110358	50-155 P 50-255 S 50-255 P 50-255 P 50-155 P 50-258 P
HEISHMAN, R F HEISHMAN, R F HEISHMAN, R, F HEISHMAN, R F HEISHMAN, R F	8007210277 8007240396 8007310530 8007310534 8007310278	50-358 G 50-305 G 50-373 Q 50-346 O 50-315 Q	HERDT, A R HEREFORD, J M HEREFORD, J M HERCIHY, D HERLIHY, D	8007010502* 8007210475* 8007010129	50-270 0 50-327 5 50-327 8 40-8728 40-8728	HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D P HOFFMAN, D, P	8007140350 8007140391 8007140310 8007140424 8007140444	50-255 G 50-155 F 50-255 G 50-155 Q 50-155 Q

AUTHOR	ACCESSION NUMBER	SUBJE		AUTHOR	Accession Number	SUBJEC CATEGO		AUTHOR	ACCEBBION NUMBER	SUBJECT CATEODRY
OFFMAN, D P OFFMAN, D P FFMAN, D P OFFMAN, D P OFFMAN, D P	8007150803 8007140458 8007140505 8007180424 8007210394	50~255 50~155 50~255 50~255 50~255	5 0 5 P 9 02	HOVEY, O K HOVEY, O K HOVEY, O K	8007150507 8007150513 8007150515 9007140431 8007170442	50-320 50-320 50-320 50-320 50-320	F 6 5 0 P	HURRAN. G HURSH. G HURST. J B HUSEBY. D E HUSTON. R W	8007180413* 8007300370 8007250174* 8007280676* 8007070008	50-245 R 50-312 H 50-320 H 50-317 S 50-255 P
OFFMAN, D P OFFMAN, D P OFFMAN, D P OFFMAN, D P OFFMAN, D P	8007220452 8007220472 8007220478 8007220513 8007230460	50-155 50-155 50-255 50-255 50-255	0 6	HO∧EA'O K HO∧EA'O K HO∧EA'O K HO∧EA'O K	8007170395 8007210359 8007210383 8007220442 8007310406	50-320 50-320 50-320 50-320 50-320	4 6 6	HUSTON,R W HUTTON,J R KUTTON,P K HYLAND,F B ICE,R D	8007070314 8007030084 8007220058 8007140188* 8007030064	90-255 S PR RES GA999 FDIA
OFFMAN, D P IOFFMAN, D P IOFFMAN, D P IOFFMAN, D P	8007230469 8007220341 8007230399 8007230516 8007240017	50-155 50-155 50-255 50-155 50-155	F 0	HOVEY, G K	8007230434 8007230439 8007290611 8007300447 8007150152	50-320 50-320 50-320 90-320 PR	8 8 8 8	IHRIG.R INGRAM.F L INGRAM.F L INGUGE.S IORII.J A	8007150475 8007010063 8007280129 8007220234* 8007100256*	50-484 Q 50-275 H 50-320 H 50-305 P TOPREP
ICEPMAN, D P ICEPMAN, D P ICEPMAN, D P ICEPMAN, D P	8007250373 8007280597 8007310422 8007280570 8007290606	50-185 50-185 50-185 50-185 50-185	٦ ٦	HOWERPU E HOWERP W HOWERP W HOWERP W HOWELLJ C	8007210373 8007100422* 8007100418* 8007100297 8007150107*	50-273 50-400 50-400 50-400 50-261	0 0 0 0	IPPOLITO, T A	8007070207 8007010208 8007140480 8007140484* 8007140492*	50-331 F 50-293 F 50-298 P 50-298 P 50-298 P
HOFFMAN. D P HOFFMAN. D P HOFFMAN. D P HOFFMAN. D P	8007290614 8007290630 8007300439 8007280533 8007290691	50-255 50-255 50-155 50-155 50-155	5 G F P Q	HOWELL, J C HOWELL, J C HOWINGTON, L C HOWLETT, G H HOWSON, T G	8007090170* 8007140555* 8007270145 8007210375* 8007150730	50-369 50-297 NUREQ 50-336 50-320	0 0 R I	IPPOLITO, T A	B007140500 B007140505* B007140514* B007210024 B007140605	50-254 P 50-254 P 50-254 P 50-259 F 50-325 P
HOGAN, J. P. HOHNE, F. C. HOLDEN, R. H. HOLDEN, R. H. HOLDEN, R. B.	8007100046 8007280200 8007020682 8007250710 8007310139	PR 40-8502 PR PR 50-332	g.	HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8007310935* 6007020215 6007230030 8007230120 8007230012	50-155 ACRS ACRS ACRS ACRS	H	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	8007140614* 8007140624* 8007210049 8007220028 8007180515	50-325 P 50-325 P 50-271 F 50-257 C 50-263 P
HOLLAND, P HOLLINGSWORTH HOLDDY, D J HOLDDY, D HOLDHAY, C F	8007220583* 8007170380 8007020012* 8007180082* 8007180352	50-249 50-259 70-135 70-371 RES	н	HOYLE, A HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8007070414 8007230013 8007230112 9007230023 8007230026	CONTRACT 50-327 ACRS ACRS ACRS	O	IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	8007230713 8007280229 8007280249* 8007240255 8007240225	30-278 F 50-333 P 50-333 P 50-278 P 80-277 P
HOLDHAY, C F HOLDHAY, C F HOLDHAY, C F HOLDHAY, C F HOLTER, Q H	6007140031 8007140634 8007300041 8007310251 8007240263	RES RES NUREO RES NUREO		HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	8007230729 8007210050 8007090215 6007110002 8007170527		0 0	IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A IPPOLITO,T A	B007240231* B007240234* B007240427 B007240433* B007280073	50-259 P 50-259 P 50-325 P 50-325 P 50-220 Q
HOLYDAK.R H HOLYDAK.R H HOLZWEIG.S F HONDERGER.R F HOOD.D	8007250448 8007290698 8007080360* 8007100086 8007020167*	50-373 50-373 PR PR 50-329	A A	HOATE'N C HOATE'N C HOATE'N C HOATE'N C	8007110330 8007110339 8007170554 8007300577 8007140363	50~280 100FR CONTRACT	G G	IPPOLITO,T.A IPPOLITO,T A IPPOLITO,T A IRVINE,R J IBLEY,T	8007310215 8007310222* 8007310229* 8007280294 8007010439*	50-331 P 50-331 P 50-331 P FOIA 50-346 B
HOOD, D 8 HOOD, D 8 HOOD, D 8	8007090393 8007140496 8007240040 8007300104 8007300261	50-329 50-329 50-329 50-329 50-329	F A A A	HOYLE, J C HOYLE, J C HUBBARD, J H HUBBARD, J H HUBBARD, J E	8007140497 8007310524 8007210486* 8007030189* 8007280116*	ACRS 50~413 50~413	Q A A H	19LEY, T 18LEY, T 18LEY, T 18RAEL, S. L. 18RAEL, S. L.	8007170450* 8007220465* 8007280378* 8006240237 8007010110	50-346 B 50-346 S 50-346 B 50-269 P 50-3 P
HOOD, D S HOPKINS, J B HORIN, W A HORIN, W A	8007290036 8007110049* 8007240019* 8007030246 8007030246	90-329 50-269 50-301 50-445 50-445	A 0 0	HUDSON, G HUDSON, T B HUDSON, T B HUDSON, T B	8007230223 8007250263* 8007160553 8007300070 8007300070	50-49B 50-49B	0 0 0	IBRAEL & L IWANICKI.R IWANICKI.R E JABLON, R A JADLON, R A	8007170898 800718005/ 8007290890 8007090051 8007090051	50-247 P 40-9697 40-9697 50-389 M 50-389 M
HORIN,W A HORIN,W A HORIN,W A HORIN,W A	8007180437 8007180437 8007310328 8007310328 8007240223*	50-445 50-445 50-445 50-445 50-206	0000	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	6907030389 8907090179* 8907310195* 8907290504* 8007010171*	70-33 50-440 Garry Garry Garry	Q	Jackiu, i n Jackiu, i n Jackion, p o Jacobe, a Jacobe, a	8007220112* 8007140558* 8007150580 8007010624 8007020024	50-315 Q 50-346 Q PR CONTRACT CONTRACT
HORNIA J HOBBLER, D. E HOBBLER, D. E HOBBLER, D. E HOSBLER, D. E	8007390343* 8007080007 8007020654 8007070337 8007070353*	50-206 50-320 50-320 50-320 50-320	G G G G	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	8007300198* 8007250109* 8007160157* 8007160146* 8007160207*	0A979 QA979 QA999 QA999 QA999		JACOBB, A JACOBB, A JACOBBON, R D JACOBB, B B JAMEB, H. E	8007010613 8007300595 8007100195* 8007300064 8007140380*	CONTRACT CONTRACT 50~263 S PR 40~299
HOSSLER, D E HOSSLER, D E HOUGHTON, T C HOUGHTON, T C	8007070365* 8007070371* 8007010087 8007010100 800707050	50-320 50-320 50-416 50-416 50-395	0 0 A A F	HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D	8007250187* 8907250594* 8007210539* 8007220208* 8007140421	98999 98989 98989 98989 98989	3	JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F JANECEK.R F	8007020756 8007010170 8007070116 8007080063 8007230678#	50-249 Q 50-237 P 50-10 P 50-10 P 50-10 Q
HOUGHTON, T C HOUGHTON, T C HOUGHON, K D HOVEY, G, K HOVEY, G, K	8007020061 80070240287 8007010079* 8007020534 8007010454	50-375 50-414 50-309 50-320 50-320	Á A P P S	HUNNICUTT, D M HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A HUNSTAD, A A	6007290331 8007010529* 8007160562* 8007210380* 6007210444*	50-313 9 50-306 6 50-282 8 50-306 8 50-282 8	} ! f	Janecek, R F Janecek, R F Janecek, R F Janecek, R, F, Janecek, R F	8007100142 8007160630 8007210212 8007310353 8007300485	50-254 P 50-237 Q 50-237 P 50-254 Q 50-237 Q
HOVEY, G. K HOVEY, O. K HOVEY, O. K HOVEY, O. K HOVEY, O. K	8007010460 8007160522 8007070320 8007110422 8007140352	50-320 50-320 50-320 50-320 50-320	P 6 P P	HUNSTAD, A A HUNT, M D HUNTER, D R HUNTER, V H HUNTER, V H		50-282 8 50-369 0 50-277 0 48999 98999		Janecek, R F Janecek, R F Janecek, R F Janinek, M Janinek, M,	8007280595 8007280567 8007310432 8007010159	50-10 D NUREG 50-10 G Btate Prog State Prog
HOVEY, O K HOVEY, O K HOVEY, O K HOVEY, O K	9007170373 8007180374 8007180499 8007160594 8007170338	50~320 50~320 50~320	ն 8 Ե Ե	HUNTER, R S HUNTER, R S HUPPERT, W M, HUPPERT, W W	8007300252 8007250473 8007010151*	50-315 G 50-315 G 50-315 P GA999 GA999		JANTNEK, M. JANORSKI) R L JELINEK, J A JENKING, R, V JENKING, G R.	8007270060 8007020312 8007220082* 8007220371*	State Prog PR 40-8771 50-304 8 50-321 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
JENKINS.O R JENKINS.O R JENKINS.O R JENKINS.O R	8007210093* 8007240376* 8007290404* 8007290853* 8007240147	70-1151 50-348 Q 50-390 Q 50-328 Q PR	JORDAN. W S JORDAN. W S JORDAN. W S JORDAN. W S JORDAN. W S	B007100037* B007100042* B007100033 B007100037* B007100042*	50-155 G 50-155 G 50-155 G 50-155 G 50-155 G	KAVANAUGH, P 11 KAY, J A KAY, J A KAY, J A KAY, J A	8007140516 8007080310 8007080079 8007140300 8007280621	50-382 K 50-29 F 50-29 P 50-29 P 50-29 P
JERNIGAN, E P JETT. G JEWELL, W A JOHN, D F	8007300328* 8007090025* 8007140079* 8007240134* 8007170388	50-217 G SECY 10CFR 50-285 S 50-445 M	JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S	B0070B0005* B0070B0005* B00711004B B00711004B	50-269 C 50-269 G 50-269 G PR PR	KAY,JA KAY,JA KAY,JA KEARNEY,JJ KEARNEY,RW	8007280584 8007280626 8007280492 8007020671 8007110011	50-29 P 50-29 P 50-29 F PR 50-320 J
JOHN, D F JOHNSON, M T JOHNSON, C JOHNSON, J	8007170388 8007170388 8007030012 8007030098 8007250332*	50-445 M 50-445 M PR PR 50-286 Q	JORDAN, W S JORDAN, W S JORDAN, W S JORDAN, W S JORGENSEN, B L	8007220529 8007220530* 8007220529 8007220530* 8007010373*	50-287	KEARNEY, J KEE, E J KEENAN, R P KEENAN, R P KEENAN, R P	8007210168 8007210017 8007070023 8007100263 8007100271*	PR RES XPORTLIC XPORTLIC XPORTLIC
JOHNSON, R E JOHNSON, M JOHNSON, M JOHNSON, A H	8007210430* 8007280262* 8007030367 8007210165* 8007100061*	OEN TEC 18 50-293 Q 71-9027 50-244 Q 50-335 Q	JOUKOFF.P JDY.D JDY.D R JDY.D R JDY.D R	8007110184* 8007100072* 8007100057* 8007100020* 8003250864	50-206 Q 70-143 70-143 70-143 70-143	KEENAN, R P KEENAN, T KEENAN, R P KEENAN, R P KEENAN, R P	8007110021 8007170202 8007180449 8007180455* 8007310069	XPORTLIC FOIA XPORTLIC XPORTLIC XPORTLIC
ДОНИВОМ, W D В 1 ЛОВИНОС В А ЛОВИНОС В А ЛОВИНОС В В В В В В В В В В В В В В В В В В В	8007220197* 8007210139 8006170304 8007210107* 8007100378	50-313 Q ACRS MISC 50-224 Q PRM	H C'ABNAGC H C'ABNAGC H C'ABNAGC H C'ABNAGC B G'ABC	8007220251* 8007150605* 8007020012* 9007140648* 8007180082*	70-143 50-204 R 70-135 70-135 70-371	KEENAN, R P KEENEY, W P KEENY, 8 M KEESE, B KEHLER, P	8007310073* 8007220184 8007090145 8007300573 8007100363	XPORTLIC 71-9132 PR PR NUREG
Э Я КОВИНОС С С , ООУВИНОС О М , КОВИНОС О М , КОВИНОС О М , КОВИНОС О М , КОВИНОС	8007210423 8007100051 8007070275 8007180256 8007210601	QEN TEC 18 50-344 0 50-320 G 50-395 Q 50-309 Q	ANTIAN'C ADANEL'T H ADANEL'T H ADANEL'T H	8007280746* 8007170630* 8007230124* 8007250494* 8007240256	70-1100 70-135 70-371 70-820 50-276 \$	KEHDE, D V KEIMIO, R R KEIMIO, R R KEIMIO, R R KCIMIO, R R	8007230221* 8004240221 8005230131 8007020536 8007310345*	50-293 0 50-219 S 50-245 8 50-213 S 50-245 0
ОВИНОСИ ОВИНОСЬ ОВ	8007100037 8007300295* 8007180467 8007250524 8007250404	50-344 0 50-344 0 71-4478 PR 50-307 P	JULIAN.C JUNCE.W R JUBTUS.P E KAHLE.J B	8007240260 8007020359 8007220566 8007300047 8007150049*	50-296 S WABTE MGT 50-155 F 50-344 P 70-1113	KEIMIG.R R KEIMIG.R R KELLER, J H KELLEY, W D	8007310055# 8007230191 8007250197 8007290217 8007010051#	50-272 0 50-213 8 50-217 8 50-254 P GA999
JOHNSTON, M P JOHNSTON, M P JOHNSON, M D JOHNSON, R W JOHNSON, R P	8007230508 8007230508 8007270331 8007310433 8007300076	\$0-275	KAHLE, J B KAHLE, J B KAHLE, R KALLYIANAKIS, N	8007020220* 8007010301* 8007280225* 8007160504* 8007080162	70-1151 70-824 70-27 CONTRACT 50-265 S	KELLEY,D L KELLOOG,P J KELLOGG,P J KELLY,A KELLY,J A F	8007150171* 8007100124* 8007230362 8007100134 8007100225*	50-285 0 50-416 0 50-280 8 PRM 50-267 0
0 9,83400 U MOBAHOU U MOBAHOU U MOBAHOU U MOBAHOU U MOBAHOU U MOBAHOU	8007240478 8007090166* 8007090167* 8007020287* 8007020292	NUREG NUREG NUREG FOIA FOIA	KALIVIANAKIB, N KALIVIANAKIB, N KALIVIANAKIB, N KALIVIANAKIB, N KALWARF, D R	8007150619 8007280470 8007240112 8007240105 8007030350	50-254 R 50-265 P 50-265 B 50-254 S NUREO	KELLY,A F KELLY,A F KELLY,A F KELLY,J KELLY,J E	8007100223 8007070141* 8007070157 8007210162 8007140417*	50~267 0 50~284 0 50~284 0 50~445 S PR
JONES, Q C JONES, K A JONES, C C JONES, U C	8005130445 8007070113 8007220081* 8007310234 8007020257	REB PR HASTE MOT NUREO 50-285 Q	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8005160107 8005200282 8005160225 8005200319 8005200324	50-320 H 50-289 H 50-320 H 50-320 H 50-289 H	KEMPER.J S KEMPER.J S KEMPER.J S KEMPER.J S	8007210442 8007210321* 8007210214* 8007240224 8007250152	H180 50-352 0 50-352 5 50-352 5
JONEB, W C JONEB, W C JONEB, W C JONEB, C E	8007110096# 8007020075 8007210197 8007020430 8007150118#	50-285 Q 50-285 Q 50-285 Q 50-285 Q 50-454 Q	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8005200345 8005160124 8005200357 8005200366 8005200454	50-289 H 50-320 H 50-320 H MISC 50-320 H	KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S	8007310286* 8007070265 8007210567 8007180446* 8007280388*	50-352 8 50-352 8 50-352 0 50-277 P 50-278 P
JONEB, Y I JONEB, W C JONEB, W C JONEB, W C	8007020419 8007030001 8007180122* 8007080056 8007140026	50-285 Q FR 50-285 Q 40-215 50-275 Q	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8006120212 8006120428 8006120437 8006120484 8007100438*	50-320 H 50-289 H 50-320 H 50-320 H 50-320 H	KEMPINERS,W L KENDRICK.H KENNA,W B KENNA,W B KENNA,W B	8007140521* 8007220030* 8007100374* 8007100404* 8007010117*	CONTRACT 50-566 H 70-1151 70-1201 70-143
JONES, D E JONES, H C, JONES, H C, JONES, J. A	8007150072 8007140086* 8007010471 8007300078 8007010352	PR 70-143 50-285 P 50-285 P 50-400 F	KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C KAMMERER, C	8006120419 8006120501 8006120402 8007110399 8007250190	20-350 H CGWM1881DM H18C 20-350 H W18C	KENNA, U B KENNA, W B KENNA, W B KENNA, W B	8007100362 8007100390 8007020213 8007070003 8007140067*	70-1151 70-1201 70-1151 70-2478 70-143
ONEB'M C CONEB'N V CONEB'N V CONEB'N V	8007170366 8007170628 8007170632 8007270830* 8007080364	50-400 K 50-400 A 50-400 C 50-270 B 50-285 P	KANAK,K K KANAK,K K KANE,W F KANKLIN.J E KANN.O A	8007020354 8007140044 8007140227 8007300143* 8007280400*	RES RES 50-375 A 50-454 Q 50-337 P	KENNA, W B KENNA, W B KENNA, W B	8007150101* 8007140513 8007010301* 8007010295* 8007030295*	50-241 0 70-143 70-824 70-824 70-143
JONES, W. C. JONES, W. C. JONES, W. C. JONES, B. W.	8007070123 8007170376 8007230530 8007230558 8007100244	50-275 Q 50-285 R 50-285 F 50-285 Q 50-577 Q	KAPLAN,A L KAPLAN,A L KAPLAN,A L KAPLAN,A L KAPLAN,A L	8007150033* 8007030231* 8007150031* 8007080212 8007280077	70-1113 70-1113 70-1113 70-1113 71-4786	KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8007280220 8007010105 8007150027 8007110102 8007100093	70-27 70-143 70-1113 50-335 0 50-261 0
JONES, R K JONES, W C JONES, W C JONES, W L	8007310497 8007280530 8007280601 8007310466 8007220110	HASTE MOT 50-285 P 80-285 Q 80-275 Q 50-577 Q	KABCBAK, R M KABBETAUM, N L KATZ, L KAUFMANN, R S KAUFMAN, N C	8007290689 8007110571* 8007290368* 8007140076 8007230177	NUREO 30-482 U QA777 MISC RES	KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8007270385 8007070165 8007140078 8007150087 8007140058	50-364 0 50-369 0 70-143 50-261 0 70-143
JONES, B W JONES, D W JONESON, A JORDAN, A C, JORDAN, W B	8007230612 8007280286 8007110245* 8007100104 8007240050*	50~155	KAUFMANN, R S KAUFMANN, R S KAUFMAN, N, C KAUFMANN, R S KAUFMANN, R S	8007100452 8007140607* 8007280171 8007210067 8007230667	40-8502 40-8502 RES 40-8768 40-8728	KENNA, W B KENNA, W B KENNA, W B KENNA, W B KENNA, W B	8007140542 8007160718 8007160838 8007160745 8007180308	50-297 0 70-1113 70-143 50-338 0 70-143

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	GUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
INREDY: R T TWNEDY: E 11 NNEDY: E 14 NNEDY: R T ENNEDY: R T	800702016B 8007020323* 8007110093* 8007180501 8007300069	COMMISSION 50-320 U 50-271 H COMMISSION COMMISSION	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	6007220215 6007220226 6007220226 6007220226	50-546	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J, O	8007170409 8007170413 8007170617 8007170619 8007170623	70-8 40-3372 50-264 9 70-34 70-1489
ENNEDY, R T ENNEDY, R T ENNEDY, R T ENNEDY, R T ENNEDY, R T	8007180164 8007180216 8007180550 8007180488 8007180029	COMMISSION COMMISSION COMMISSION COMMISSION	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J G	8007020310 8007160158 8007160165 8007160173 8007160178	50-344 0 50-315 0 50-295 0 50-255 0 50-329 0	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007170626 8007170629 8007170633 8007170636 8007170638	50-87 Q 50-116 Q 50-294 Q 50-150 Q 50-152 Q
ENNETH B F ENNEDY R T CWIEDY R T ENRICK J R ENRICK J R	8007070128 8007110278 8007180474 8007220560 8007220560	71-392 COMMISSION COMMISSION XPORTLIC XPORTLIC	KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007160182 8007160187 8007160191 8007160198 8007160200	50-282	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007170641 8007170644 8007170646 8007170653 8007170657	50-182 Q 50-151 Q 50-123 Q 50-186 Q 50-2 Q
ENRICK.JR ENRICK.JR ENFORD.C EPFORD.C	8007290485 8007250485 8007300052 8007080086 8007140495	XPORTLIC XPORTLIC 50-327 E 50-320 0 50-461 Q	KEPPLER.J Q KEPPLER.J O KEPPLER.J Q KEPPLER.J Q	8007140203 8007140309 8007140314 8007140317 8007140319	50-305 0 50-10 0 50-373 0 50-155 0 50-331 0	KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8007170662 8007250006 8007140178 8007230289 8007230305	50-156 Q 40-4337 40-7402 50-10 Q 50-315 Q
LEPPLER, J G	8007140508 9007140510 8007140517 8007140523 8007140532	50-367 G 50-341 G 50-155 G 50-407 G 50-263 G	NEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O	8007140321 8007140323 8007140325 8007140358 8007140360	50-263	KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8007230307 8007230310 8007230312 8007230320 8007230323	50-35B 0 50-440 0 50-155 0 50-409 0 50-341 0
(EPPLER, J O (EPPLER, J O L PALARS) (EPPLER, J O (EPPLER, J O	8007140535 8007140537 8007140545 8007140551 8007140554	50-331 Q 50-373 Q 50-10 Q 50-440 Q 50-358 Q	KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q KEPPLER, J. Q.	8007140401 8007240004 8007280628 8007280631 8007280635	50-358 0 50-155 0 50-483 0 50-544 0 50-367 0	KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	8007230327 8007230330 8007230332 8007230334 8007230338	50-331 0 50-441 0 50-347 0 50-243 0 50-544 0
\EPPLER, J O \EPPLER, J O \EPPLER, J O \EPPLER, J O \EPPLER, J O	9007140557 8007290048 8007070072 8007020029 8007020034	50-341	KEPPLER.J Q KEPPLER.J Q. KEPPLER.J Q KEPPLER.J Q KEPPLER.J Q	8007280438 8007280644 8007280653 8007280457 8007280707	50-461 0 50-341 0 50-440 0 50-358 0 50-329 0	KEPPLER.J.O KEPPLER.J.O KEPPLER.J.O KEPPLER.J.O KEPPLER.J.O	8007230340 8007230343 8007230346 8007230356 8007230358	50-346 Q 50-483 Q 50-266 Q 50-305 Q 50-329 Q
KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	8007020037 8007020043 8007020051 8007020054 8007020056	50-266 Q 50-315 Q 50-155 Q 50-263 Q 50-346 Q	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007280709 8007100436 8007030023 8007030026 8007030027	50-373	KEPPLER,J G KEPPLER,J G KEPPLER,J G KEPPLER,J G KEPPLER,J G	8007300574 8007310507 8007180003 8007210034 8007180566	50-254 Q 50-295 Q 50-10 Q 50-266 P 50-263 Q
MEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G KEPPLER.J G	8007020088 8007020063 8007020065 8007210353 8007210354	30-409 0 50-331 0 50-10 0 50-315 0 50-279 0	KERPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007030030 8007030032 8007030037 8007030037 8007030042	50-266 0 50-407 0 50-155 0 50-10 0 50-315 0	KEPPLER, J G. KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8007180575 B007180497 B007180509 B007210550 B007240245	50-155 0 50-331 0 50-10 0 40-2674 40-4337
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007210358 8007210360 8007210362 8007210363 8007210364	50~255 Q 50~327 Q 50~282 Q 50~546 Q 50~346 Q	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J, O	8007030043 8007030044 8007020549 8007020549 8007020552	50-263 0 50-346 0 50-546 0 50-266 0 50-155 0	KEPPLER. J O KEPPLER. J O KEPPLER. J G KEPPLER, J G KEPPLER, J G	8007240291 8007280429 8007280681 8007240402 8007290061	50-249 Q 50-346 Q 50-373 Q 50-255 F 50-454 B
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007210401 8007210407 8007210412 8007010068 8007010071	50-493	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	9007020555 8007020558 8007020559 8007020562 8007020565	50-358	MEPPLER, J G KERR, O W KERR, O W KERR, O W KERR, O W	8007310521 8007270359* 8007270028 8007180021 8007010017*	50-329 G COMMISSION SECY WASTE MOT ORG
KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G KEPPLER, J G	8007010074 8007010078 8007010080 8007010086 8007010104	50-546 0 50-305 0 50-266 0 50-10 0 50-461 0	KEPPLER.J Q KEPPLER.J O KEPPLER.J O KEPPLER.J Q	8007020548 8007020570 8007020571 8007020573 8007020576	50-315	KERR, O. W KERR, O W KERR, O W KERR, O W KERR, O W	8007010035 8007020156 8007020699 8007140569 8007250639	State Prog State Prog State Prog State Prog State Prog
KEPPLER.J 0 KEPPLER.J 0 KEPPLER.J 0 KEPPLER.J 0 KEPPLER.J 0	8007010107 8007010112 8007010115 8007010114 8007010123	50~341 0 50~409 0 50~155 0 50~346 0 50~463 0	Keppler, J C Keppler, J C Keppler, J, C Keppler, J, C Keppler, J C	8007020578 8007020584 8007020587 8007020589 8007140574	50-407 G 50-461 G 50-367 G 50-10 G 50-483 A	KERR, Q. W KERR IGAN, J KERR IGAN, J KERR IGAN, J KERR IGAN, J	8007210068 8007160416 8007020196 8007110554 8007110561	State Prog 50-311 P 50-528 A 50-311 P 50-311 P
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O,	8007010127 8007010132 8007010136 8007010139 8007010144	50~263 0 50~367 0 50~331 0 50~440 0 50~329 0	Keppler, J o Keppler, J o Keppler, J o Keppler, J o	8007140581 8007170422 8007170426 8007170430 8007170459	50-544 A 70-1220 50-315 Q 50-10 Q 50-358 Q	KERRIGAN, J. KERRIGAN, J. D. KETCHEN, E. O. KETCHEN, E. G. KETCHEN, E. G.	8007210277 8007280006 8007010282 8007090320 8007140019	50-311 F 50-311 P 50-369 Q 50-369 Q
KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER, J O KEPPLER, J O	8007170094 8007010047 8007210116 8007220148 8007220156	50-979 0 40-2674 50-469 0 50-915 0 50-10 0	KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O	9007170465 9007170467 9007170474 9007170479 9007170486	50-440 Q 50-327 Q 50-155 Q 50-407 Q 50-341 Q	KETZLACH, N KETZLACH, N KETZLACH, N KEY, W J KHARANA, S S	8007150839 8007240110* 8007240125* 8007230375* 8007160569*	70~824 70~1201 70~27 50~304 G 50~454 K
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	6007220174 6007220178 6007220183 6007220188 6007220175	50-359 G 50-440 G 50-329 G 50-155 G 50-407 G	Keppler, J Q Keppler, J Q Keppler, J, Q Keppler, J, Q Keppler, J, Q	8007170489 8007170495 8007170500 8007170501 8007170504	50-331 Q 50-461 Q 70-725 50-367 Q 50-263 Q	KIENLE, C. F KIENLE, D KIGGINS, B R KILLOUOH, G Q KIM, B. M	8007250396+ 8007020653 8007010079 8007090371 8007170416+	50~397 A 50~320 H FOIA NUREO FOIA
KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	800/220198 800/220201 8007220204 8007220206 8007220212	50-341 0 50-331 0 50-461 0 50-367 0 50-263 0	KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	8007170510 8007170515 8007170518 8007170524 8007170528	50~546 0 50~346 0 50~483 0 50~266 0 50~305 0	KING'K B KIMKEL' J J KIMBET' T J KIM'S W	80052906074 8007310269* 8007100368* 8007170161* 8007220119*	PT9 FOIA CONTRACT CONTRACT WASTE MOT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KINNEY, W W KINNEY, W W KINNEY, W W KINNEMAN, J D KINNEMAN, J D	8007030357* 8007210195* 8007210190* 8007230597 8007180338	CONTRACT 70-33 70-1143 70-2000 70-997	LACEY,W S LACEY,W S LACEY,W S LACEY,W S	8007090338* 8007090348* 8007180322* 8007220434* 8007250324*	50-334 5 50-334 8 50-334 S 50-334 S 50-334 S	LEMPOES, T E LEMPOES, T E LEMPOES, T E LEMPOES, T E LEMPOES, T E	8007210100 8007280465 8007250192 8007170360 8007250472	50-220 0 50-220 0 50-220 0 50-220 R 50-410 A
KINNEMAN, J D KINNEMAN, J D KINNEMAN, J D KINNY, W W KINTNER, L.	8007230014 8007230216 8007310272 8007070373* 8007070007	70-184 18E 40-8045 50-271	LACEY,W S LACEY.W S LACY,F P LADD.E LADUN,R H	8007250331* 8007300388* 8007150522* 8007160851* 8007100074*	50-334 5 50-334 5 50-327 P COMMISSION 50-293 Q	LEMPOES, T E LEMPOES, T E LEMAHAN, J J LEMAHAN, J J LEMAHAN, J J	8007280275 8007290586 8007110536* 8007100435* 8007180234*	50-220 I 50-220 S 50-424 Q 50-400 Q 50-553 Q
KINTNER, L	8007100018	50-364 A	LADUN,R H	8007230308*	50-289 0	LENTSCH.J W	8007170562	50-344 R
KINTNER, L	8007210305	50-364 A	LADUN,R H	8007230366*	50-219 0	LENTSCH.J W	8007070331	NUREG
KINTNER, L	8007210304	50-364 A	LAFEVER,C W	8007290693*	50-327 8	LENTSCH.J W	8007250413	50-344 Q
KINTNER, L	8007210593	50-364 A	LAFLEUR,J D	8007170509	50-320 P	LESSOR.L C	8007020333	50-298 Q
KINTNER, L	8007210598	50-364 A	LAFLEUR,J D	8007020177	50-315 H	LESSOR.L C	8007080295	50-298 B
KINTNER, L	8007280121	50-364 A	LAFLEUR, J D	8007020181	50-206 H	LESSOR, L C	8007090005	50-278 8
KIPER, K L	8007210624	50-410 A	LAFLEUR, J D	8007020185	50-341 H	LESSOR, L C	8007080365	50-278 9
KIRK, B L	8007210498	50-247 P	LAFLEUR, J D	8007020189	27-47	LESSOR, L C	8007080391	50-278 R
KISNER, R. A	8007280092	REB	LAFLEUR, J D	8007020197	50-171 H	LESSOR, L C	8007280584	50-278 9
KISTER, H	8007250392*	50-286 Q	LAFLEUR, J D	8007020202	27-10	LESSOR, L C	8007250421	50-278 R
KISTER, H B	8007210165*	50-244 Q	LAFBER.F A	8007290038*	SO-483 A	LESSY, R P	8007010143	50-376 G
KISTER, H B	8007250263*	50-220 Q	LAGDMARBIND,R	8007250284*	SO-275 H	LESSY, R P	8007220149	27-39
KISTER, H B	8007210255*	50-333 Q	LAHR.T N	8007020415	Mibc	LEVERANCE, J	8007140408*	PR
KISTER, H B	8007310504*	50-247 Q	LAINAB.O	8007110584	Foia	LEVERING, R	8007220451	50-10 D
KISTER, H	8007290010	50-220 B	LAINAB.O	8007110504	Foia	LEVINE, M M	8007180253	RES
KLAMUT,C J	8007210005	RES	LAINAS, Q C	8007100310*	50-255 P	LEWIS.R C	8007150506*	50-302
KLEINSORGE,N P	8007100313*	50-400 G	LAINAS, Q, C	8007110244*	50-255 P	LEWIS.R C	8007160817*	
KLINE,J A	8007030048	50-275 G	LAINAS, Q C	8007010050	50-237 P	LEWIS.R C	8007220075*	
KLINE,J A	8007250429	50-275 G	LAINAS, Q C	8007030300	50-217 P	LEWIS.R C	8007240277*	
KLINGAMAN,R M	8007140413	50-320 F	LAINAS, Q C	8007180079	50-409 F	LEWIS.R C	8007280475*	
KLOTZ, A. B.	8007020439	PR	LAINAB, OC	8007240056	50-213 P	LEWIS,R C	8007100059	50-335 0
KLOTZ, A. B	8007020441	PR	LAINAB, OC	8007280008	50-29 P	LEWIS,R C	8007100064	50-321 0
KNAPP, P.	8007210304*	70-487	LAINAB, GC	8007210591	50-206 S	LEWIS,R C	8007240266*	50-250 0
KNAPP, P	8007150081	50-286 B	LAMB, HR	8007100437	PRM	LEWIS,R C	8007100119	50-416 0
KNICELEY, J. R.	8007150076*	70-2409	LAMBERT, R	8007100191*	PR	LEWIS,M I	8007030349	PR
KNIEL,K KNIGHTON,G W KNOP,R C KNOP,R C KNOP,R C,	8007010230* 8007160805 8006300138* 8007110168* 8007140541*	FDIA REQQD 50-329 Q 50-461 Q 50-483 Q	LAMPE,W F LANAHAN,M P LANCASTER,K F LANDOVER,R S LANDSMAN,R B	8007310398 8007210267* 8007110410* 8007140599 8007090179*	50-289 H CONTRACT 50-302 8 PR 50-440 Q	LEWIS, R C LEWIS, R C LEWIS, M I LEWIS, L	8007170219 8007180005 8007170420 8007020465 8007030087	50-327 G 50-327 G 50-324 G PR PR
KNOP,R C	8007150023*	30-483 G	LANDSMAN.R B	8007090159*	50-440 Q	LEWIS, L	8007070043	PR
KNOP,R C	8007160764*	50-461 G	LAND.P M	8007110451	PRM	LEWIS, R C	8007240368*	50-369 G
KNOP,R C	8007230066*	50-341 G	LANDNER.R R	8007250705	PR	LEWIS, L	8007170105	PR
KNOP,R C	8007310367*	50-461 G	LANPHER.L C	8007300110	50-275 Q	LEWIS, C	8007160494*	CDNTRACT
KNOP,R C	8007300169*	50-483 G	LANPHER.L.C	8007300110	50-275 Q	LEWIS, R C	8007070394	50-348 G
KNOP, R. C.	8007300304*	50-327 G	LANPHER,L C	8007310389	50-312 0	LEWIS, M I	8007070276	50-320
KNOP R. C	8007300157*	50-483 G	LANPHER,L C	8007310389	50-312 0	LEWIS, M I	8007100240	
KNOTTB. J. B	8007100270	PRM	LANTZ,P M	8007300041	NUREO	LEWIS, R C	8007150475	
KNOTTB. J. B.	8007160625	50-445 M	LAPP,R E	8007180221*	COMMISSION	LEWIS, R C	8007220059	
KNOTTB. J. B	8007160625	50-445 M	LARKIND,R	8007160773	MISC	LEWIS, M I	8007100215	
KNUTH, D, F	8007020667	PR	LAROCHE, G	8007230148*	50-287 G	LEWIS, M	8007140005	50-287 Q
KNUTH, D F	8007140286	FOIA	LARSON, H J	8007030348	PR	LEWIS, R C	8007240256	50-276 B
KNUTH, D F	8007310262	FOIA	LARSON, J R	8007290226	RES	LEWIS, R C	8007160797	50-335 Q
KNUTH, D, F	8007170491	PR	LASH, T R	8007070084	PR	LEWIG, R C	8007280418*	50-270 Q
KOCH, L J	8007160638*	50-461 \$	LATHAM, B B	8007290781	DRO	LEWIS, R C	8007240260	50-276 S
KOCH: L. J.	8007160651*	50-461 S	LATHAM, 8 B	8007290781	ORG	LEWIS.R C	8007280460	50-259 G
KOCH: L. J	8007160665*	50-461 S	LAWRENCE, J, F	8007070036*	50-514 D	LEWIS.R C	8007240261	50-250 G
KOCH: L. J.	8007160679*	50-461 S	LAWRENCE, J F	8007070040*	50-514 D	LEWIS.R C	8007310551	50-269 F
KOCH: L. J	8007250559	50-461 A	LAWRENCE, J F	8007070044*	50-514 D	LEWIS.M I	8007310143	50-269 G
KOCH: L. J	8007230518	50-461 B	LAWRENCE, J F	8007070046*	50-514 D	LEWIS.R C	8007310538	50-269 G
KOCH, L J	8007300429	50-461 B	LAWRENCE, R D	8007310217	NUREO	LEWIS.B H	8007280627	50-445 K
KOCH, L J	8007280506	50-461 B	LAWEDN, J E	8007210491	NUREO	LEX.B L	8007020118	REGOD
KOCHER, D C	8007180045	NUREO	LAWTON, M D.	8007100427	REGOD	LEYSE.R H	8007250621+	COMMISSION
KOCHER, D C	8007280095	RES	LAXALT, P	8007140231*	50-10 H	LI.C Y	8007010568	50-317 P
KOEBTER, O, L	8007290017*	50-482 G	LAZARUB, W J	8004240228	50-293 B	LI.C Y	8007170064	90-317 P
KOLTAY, P. 8 KOPACZ, J KOSTMAYER, P H KOTSCH, J L KOTSCH, J. L	8007170611* 8007080172* 8007110343* 8007230153 8007230245	50~286	LAZARUS, W LAZARUS, W LAZO, R. M LEACH, F J LEASE, R 8	8007230398* 8007230383* 8007020620 8007170612* 8007210541*	50-307 Q 50-307 Q 50-367 O 50-395 A 50-316 S	LI,C Y LI,C Y LI,C Y LIBRIZZI,F P LIBRIZZI,F P	8007020469 8007230176 8007210069 8007070348 8007070110	50-317 P 50-317 P 50-317 P 50-272 R 50-311 P
KOTBCH, J L	8007300268	40-6659	LEBERSTIEN, J H	8007020598*	50-336 P	LIBRIZZI,F P	8007080068	50-272 F
KOVACS, B	8007270858	PR	LEBOEUF, R J	8007100437	PRM	LIBRIZZI,F P	8007080247	50-272 S
KRACHT, W H	8007270631	50-266 H	LEDERER, P D	8007100126	PRM	LIBRIZZI,F P	8007080423	50-272 S
KRAMER, P B	8007100137	Regod	LEE, B,	8007180034*	COMMISSION	LIBRIZZI,F P	8007100197	50-272 S
KRAUSE, L	8007140638	50-458 H	LEE, B	8007240135*	NUREO	LIBRIZZI,F P	8007150516	50-272 S
KRAWCZAK, A T	8007010488*	50-295 8	LEE, B	8007180579*	COMMISSION	LIBRIZZI,F P	8007110444	50-272 0
KRAWCZAK, A T	8007220453*	50-295 8	LEE, E W	8007160741*	50-440 G	LIBRIZZI,F P	8007150421	50-272 8
KREGER, W. E	8007010270	50-320 P	LEE, E W	8007180519*	50-456 G	LIBRIZZI,F P	8007150672	50-272 6
KRICHIVER, R	8007100385	PRM	LEE, O R	8007010234*	50-267 G	LIBRIZZI,F P	8007210365	50-272 P
KUEHN, L B	8007130578*	50-327 P	LEE, T, D	8007140086*	70-143	LIBRIZZI,F P	8007170437	50-311 8
KUGE.T.	8007310482	XPORTLIC	LEE.W F	8007100035	PR	LIBRIZZI,F P	8007220381	50-272 S
KUNSITIB.T J	8007020578*	50-338 P	LEFEVRE.H	8007170313	50-482 A	LIBRIZZI,F P	8007220619	50-272 S
KUSHNER.W L	8007140648*	70-135	LEFEVRE.H E	8007300047	50-344 P	LIBRIZZI,F P	8007210494	50-272 S
KYGER.J A.	8007180031	NUREG	LEIBY.A C,	8007100437	PRM	LIBRIZZI,F P	8007280442	50-272 P
LACEY.L R.	8007300580*	50-321 Q	LEMPGEB,T E	8007180073	50-220 Q	LIBRIZZI,F P	8007290699	50-272 R

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHER	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
.18R1ZZI.F P _18R1ZZI.F P _18R1ZZI.F P _1BR1ZZI.F P _ICHTENBERGER	8007280624 8007290684 8007290718 8007290837 8007020103*	50-311 S 50-311 S 50-272 S 50-272 S 70-1100	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8007180600 8007230025 8007010329 8007090324 8007020436	50-317 Q 71-383 50-317 P 50-317 P 50-317 P	MACDONALD, C E	8007210583 8007210587* 8007220115 8007220125* 8007230038	71-5998 71-5998 71-5998 71-5971 71-5979
ICHTENBERGER ICHTENBERGER ICHTENBERGER ICHTENBERGER ICITRA, É A	8007020102 8007280737* 8007020107 8007220423 8007210237	71-6078 70-1100 70-1100 70-1100 50-528 A	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	8007250662 8007020557 8007100228 8007210044 8007210574	50~317	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8007230040* 8007240450 8007240457* 8007220039 8007220055	71~5979 71-251 71-251 71-6697 71-249
LICITRA-E A LIEBERMAN, J LIM.T H LINDBLAD.W J LINDBLAD.W J	8007250046 8007300 190* 8007090277 8007290832* 8007290825	50-482 A 50-266 G 50-224 H 50-514 F 50-514 F	LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUZA, K V. HACARTHUR, T C	8007090291 8007170352 8007220590 8007210491 8007290410*	50-317 P 50-317 P 50-317 F NUREG 27-47	MACDONALD, C E	8007220067* 8007220086 8007220091 8007220079 8007220106*	71-249 71-4717 71-9070 71-121 71-121
Linder, F Linder, F Linder, F Linder, F Linder, F	8007020679 8007140371 8007180355 8007280696* 8007180362	50-407 0 50-409 0 50-409 0 50-409 0 50-409 0	MACARTOR, J D MACDONALD, C E MACDONALD, C E, MACDONALD, C E MACDONALD, C E	8007140043 8007010576 8007010579* 8007090061 8007090066*	PR 71-252 71-252 71-387 71-387	MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8007220131 8007220135* 8007220143 8007220152* 8007230047	71-5748 71-5768 71-6387 71-6387 71-4824
LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8007180092 8007140305 8007160677 8007220096 8007210447	50-409 Q 50-409 P 50-409 R 50-409 Q 50-409 P	MACDONALD, C E MACDONALD, C E MACDONALD, C C MACDONALD, C E MACDONALD, C E	9007010570 8007010574* 8007110161 8007110166* 8007100080	71-384 71-384 71-9009 71-9009 71-5088	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E.	8007230053 8007310013 8007310015* 8007280532 8007280543*	71-371 71-173 71-173 71-4698 71-4698
LINDER: F LINDER: F LINDER: F LINDER: F LINDER: F	8007280050 8007220525 8007270480 8007300244 8007310434	50-407 G 50-409 P 50-409 G 50-407 G 50-409 I	MACDUNALD; C E MACDUNALD; C E MACDUNALD; C E MACDUNALD; C E MACDUNALD; C E	8007020024 8007020495 8007020318 8007020522* 8007100100	71-169 71-6144 71-391 71-391 71-6400	MACDONALD, C E	8007280541 8007280545* 8007280575 8007280580* 8007280698	71-9030 71-9030 71- 4 049 71-9049 71-9053
LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J	8007100091* 8007010569 8007280175 8007140593 8007140693	40-1162 40-1162 40-8681 40-6659 40-4492	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8007020500 8007020506* 8007020512 8007020517* 8007020327	71-5942 71-5942 71-9016 71-9016 71-9015	MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E	8007280703* 8007290116 8007240175 8007240179* 8007240186	71-9053 71-9053 71-383 71-383 71-139
L INEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J LINEHAN, J J	8007070105 8007230153 8007230131 8007230576 8007230667	40-8102 40-6657 40-2257 40-6622 40-8728	MACDONALD.CE. MACDONALD.CE MACDONALD.CE MACDONALD.CE MACDONALD.CE MACDONALD.CE	8007020532* 8007020422 8007020428* 8007020484 4007020583*	71-9015 71-6698 71-6698 71-9022 71-9022	MACDONALD, C E	8007240193* 8007240200 8007240201 8007240207* 8007240212	71-139 71-9044 71-6294 71-6294 71-9132
Linchan, J J Linchan, J J Linchan, J J Linchan, J J Linchan, J J	8007230572 8007230580 8007230084 8007230245 8007230715	40-8681 40-8584 40-8585 40-6659 40-8452	MACDONALD, C E	8007110265 8007110270* 8007110452 8007110461* 8007110464	71-6375 71-6375 71-6078 71-6076 71-9130	MACDONALD.C.E MACDONALD.CE. MACDONALD.CE MACDONALD.CE MACDONALD.CE	8007240215* 8007240217* 8007270016 8007270018* 8007280718	71-9044 71-9132 71-9010 71-9010 71-4986
LINEHAN, J J Lineaberger, Q a Lingren, C L Linneman, R e Linton, D V	8007300248 8007270744 8007180085 8007170328* 8007070399	40-8459 50-444 0 Regod Foia Pr	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C.E MACDONALD.C.E	8007110468* 8007110473 8007110476* 8007100040 8007100041*	71-9130 71-5926 71-5926 71-6591 71-6581	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E,	8007280720* 8007280762 8007280766* 800729008 8007290011*	71-4986 71-9080 71-9080 71-6568 71-6569
LINTON,O W LIPINSKI,W C LIST,R LITTLE,W B LITTLE,W B	8007130070 8007210027 8007230739* 8007100291* 8007230303*	PR ACRS COMMISSION 50-331 G 50-331 G	MACDONALD; C C MACDONALD; C E MACDONALD; T H MACDONALD; C, E MACDONALD; C E	8007110281 80071102904 8007110481 8007140698 8007140702*	71-5450 71-5450 50-307 H 71-346 71-346	MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACH, 8.R.	8007280771 8007280773* 8007280776 8007280779* 8007310325*	71~9139 71~9139 71~6387 71~6387 50~327 P
LITTLE, # LIVEMORE, H # LLOYD, L L LGATS, E T LOCHSTET, W A	8007280234 8007310367* 8007020332 8007150059 8007110067	Contract 50–461 g Pr Res Pr	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E	8007140706 8007140709* 8007160310 8007160317* 8007160322	71-5 71-5 71-391 71-391 71-389	MACIOLEKIN J MACKENZIEID R. MADDENIW MADDENIW MADEDAIT J	8007150712* 8007210007 8007020022* 8007290199* 8007020211*	50-219 R REB 70-1143 50-244 G 50-295 G
LOCKE, J. W LOCKE, R. F LOCKE, R. F LODDER, H LOCIUDICE, J. M	8007240381 8007180358 8007250386 8007310162# 8007300598#	PR 50-133 0 50-133 0 QA999 CBNTRACT	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C. E MACDONALD, C E	8007160335* 8007160343 8007160347* 8007220089 8007220097*	71-389 71-393 71-393 71-9136 71-9136	MADEDA,T J MADEDA,T J MADISON,A MADISON,W R MADEEN,C.L	8007240107* 8007280435* 8007140494* 8007220434* 8004240281	50-263 G 50-346 G 50-263 G 50-338 R 50-267 B
LOTS:L LONG:F J LONG:F J LONG:F W	8007010722 8007170584* 8007170567* 8007310235*	50-255 P 50-553 Q 50-553 O 50-387 Q	MACDONALD, C E	8007170471 8007170474 8007170480 8007170485 8007170487	71-2 71-82 71-109 71-143 71-179	Madren, G L Madren, G. L Madren, G L Madren, G L Madren, G L	8007150165 8007220177 8007150083 8007150125 8007300349	50-285 Q 50-313 Q 50-267 Q 50-278 Q 50-313 Q
			7. C. E C. E C. E C. E.	8007170492 8007140381 8007140387* 8007140409 8007140412*	71-271 71-4988 71-4988 71-4984 71-4984	Madsen, 0 L Madsen, 3. L Madsen, 0 L Madsen, 0 L Madsen, 0 L	8007070020 8007070172 8007010231 8007110086 8007310334	50-313 H 50-313 Q 50-267 Q 50-285 Q 50-313 S
			6. 8 8 8 8	8007160767 8007160772* 8007170093 8007170097* 8007220046	71-392 71-392 71-5341 71-5341 71-6501	Madben, g l Madben, g l Madben, g, l Magee, h Magroh, r.	8007290331 8007300320 8007300329 8007140504* 8007100189*	50-313 8 50-313 0 50-313 0 FOIA 50-237 8
			# E E	8007170113 8007170118* 8007170178 8007180084 8007180088	71-5862 71-5862 71-9039 71-3450 71-9080	Magroh, R Makatura, L Makepeace, J. M Makepeace, J. M Malek, F. A	8007220572* 8007030264* 8007119404* 8007240172* 8007140582	50-237 B 50-346 B 50-247 S 50-247 S PR

ROHTUA	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MALLORY, K MALLORY, K MALONE, K MALONE, T MALONEY, G P	8007090166* 8007090167* 8007030019* 8007090163 8007160384	NUREO	- -{ 3	MARRAM, E P MARRACK D MARRACK, D MARRANZING, A P MARRACK, D	8007160498* 8007160560 8007160565* 8007160692 8007220552	CONTRACT 50-466 G 50-466 G 50-274 F 50-466 G		MATHENS.E.R MATHENS.E.R MATHENS.E.R MATHENS.E.R MATHENS.E.R	8007150464 8007240321 8007240334 8007160544 8007240415	50-305 S 50-305 Q 50-305 Q 50-305 R 50-305 Q
MALONEY, G P MALONEY, G P MALONEY, G P MALONEY, G P MANCUSO, F	8007250016 8007150676 8007220080 8007230267 8007010478	50-315 50-315	0 9 0	MARRONE, J MARRONE, J MARRONE, J MARRONE, J MARRONE, J	8007110077* 8007110051* 8007110052* 8007110057* 8007110060*	50-320 J 50-320 J 50-320 J 50-320 J 50-320 J	 	MATHENS, E R MATHENS, E R MATHENS, E R MATHENS, E R MATHISEN, R L	8007140485 8007280665 8007280675 8007280414 8007030352	50-305 S 50-305 S 50-305 S 50-305 F 40-8102
MANDLER, J W MANGUBI, J MANN, D C MANRY, M MANRY, M	B007210602 B007070043 B007310210 B0071102B5 B007010494		s 8	MARRONE, J MARRONE, J MARRONE, J MARRONE, J MARRONE, J	8007110062* 8007110068* 8007110072* 8007110222* 8007110224*	50-320 J 50-320 J 50-320 J 50-320 J 50-320 J	 	MATSON, V MATSON, V MATSON, V MATSON, V MATSON, V	8007070145 8007070145 800707018 8007110469 8007110480	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007010510 8007030272 8007030276 8007030280 8007020628	50-366 50-366	5 5 9 9	MARRONE, J MARRONE, J MARRONE, J MARRONE, J MARRONE, J	8007110089# 8007110091* 8007110095* 8007110098* 8007110103*	50-320 J 50-320 J 50-320 J 50-320 J) ,	MATSON, V MATSON, V MATSON, V MATSON, V MATSON, V	8007150353 8007290025 8007290444 8007290027 8007290390	YPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007030261 8007030284 8007020520 8007030277 8007020638	50-321 50-366 50-366	8 8 8 8	MARRONE, J MARSHALL, N H MARSHALL, E N MARSH, R J MARSH, R J	8007110084* 8007160649* 8007300012* 8007170584* 8007270380*	50-320 5 50-329 1 50-320 1 50-553 0 50-335 0	1	MATTIA.H J MATTIA.H J MATTIA.J C MATTIMOE.J J MATTIMOE.J J	8007020287* 8007020292* 8007210338* 8007240198 8007180541	FOIA FOIA 50-352 0 50-312 0 50-312 0
MANRY, M MANRY, M MANRY, M MANRY, M	8007110307 8007110400 8007110429 8007110304 8007110432	50-321 50-366 50-321	9 9 8 8	MARSHALL,W H MARTIN,T T MARTIN,J B MARTIN,R MARTIN,W G.	8007140017 8007210307* 8007230463* 8004240250 8007020017*	50~277 (50~10 [))) 5	MATTIMOE, J J MATTIA, M J MATTIMOE, J J MATTIA, M J	8007240192 8007210240* 8007020398* 8007250676 8007020731*	50-312 G 50-352 G CONTRACT 50-312 G CONTRACT
MANRY, M MANRY, M MANRY, M MANRY, M	8007110364 8007110368 8007110455 8007110415 8007150539	50-321 50-321 50-321	8 8 9 8	MARTIN, W O MARTIN, W O MARTIN, W O MARTIN, W O MARTIN, W O	8007020008* 8007100071* 8007180071* 8007240059 8007140644	70-135 50-293 70-371 XPORTLIC 70-135	a	MATTIMDE, J MATTIA, M J MATTIA, M J MATITA, M J MATTIA, M J	8007270847 8007170172* 8007240170* 8007250562* 8007070134*	50-312 Q CONTRACT CONTRACT CONTRACT CONTRACT
MANRY, M MANRY, M. MANRY, M MANRY, M MANRY, M	8007150635 8007280450 8007150678 8007150496 8007150666	50-366 50-366 50-321	8 8 8 8	MARTIN:R D MARTIN:T T MARTIN:W G MARTIN:L.E MARTIN:L.E	8007070399* 8007280262* 8007280743* 8007070091* 8007100346*	50-293 70-1100 50-482	a a a	MATTIA,M J MATTIA,M J MATTIA,M J MATTIMOE,J J MATTIA,M J	8007100312* 8007140210 8007100368* 8007100203 8007110539*	CONTRACT CONTRACT CONTRACT 50-312 P CONTRACT
MANRY, M MANRY, M MANRY, M MANRY, M	8007170382 8007170392 8007170405 8007170451 8007170481	50-321 50-321 50-366 50-321 50-321	6 9 8 8	MARTIN, W G MARTIN, T J MARTIN, W G MARTIN, W G MARTIN, R D	8007020015 8007210282* 8007020002 8007170622 8007240281*	70-135 70-135	a a	MATTIMOE, J J MATTIMOE, J J MATTIMOE, J J MATTIA, M J MATTIAN J	8007080270 80071801734 8007300072 80071702144 80071702224	50-312 S CONTRACT PR CONTRACT CONTRACT
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007170453 8007170414 8007280678 8007280686* 8007210393	50-366 50-321 50-321 50-321 50-366	8 8 R R	MARTIN, W O MARTIN, W G. MARTIN, T MARTIN, W O MARTIN, T T	8007230301 8007290174 8007230398* 8007100068 8007230383*	50-244 50-309 50-293	a a a a a	MATTIA,M J MATTIA,M J HATTIA,M J MATTIA,M J MATTIMON J J	8007180524* 8007210113* 8007210135* 8007210140* 8007080183	CONTRACT CONTRACT CONTRACT CONTRACT 50-312 P
HANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007210370 8007210384 8007210484 8007280505 8007310527	50-321 50-321 50-321 50-346 50-321	5 9 8 9	MARTIN.W C MARTIN.W C MARTIN.T T MARTIN.I E MARTIN.W C	8007230119 8007230361 8007020540 8007280730* 8007250486	50-271	a s a	MATTIMOE, J J MATTIA, M J MATTIA, M J MATTIA, M J MATTIMOE, J J	8007300081 8007140521* 8007170129* 8007170161* 8007230432	PR CONTRACT CONTRACT CONTRACT 50-312 P
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	8007240124 8007220514 8007240165 8007250411 8007280448	50-366 50-321 50-366 50-366 50-321	8 8 6 8	MARTIN, J B MARTIN, J B MARTIN, D E MARTIN, D E MARTIN, R	8007070030 8007230671* 8007290463 8007290470* 8007010538	27-39 50-10 PROJ PROJ 90-348	D P	MATTAM J MATTAM J MATTAMIJ J MATTAMIJ J MATTAMIJ J	8007170145* 8007300581* 8007310410 8007020151 8007110475*	CONTRACT CONTRACT 50-312 B 50-329 A BECY
MANRY, M MANRY, M MANRY, M MANRY, M MANRY, H	8007280519 8007280445 8007280572 8007280629 8007280689	50-366 50-321 50-321 50-321 50-321	6 9 9 8	MARTIN,R A MARTIN,T MARTIN,T J MARTIN,W.Q MARTIN W Q	8007010581 8007150081 8007310293* 8007140615 8007180058	50-282 50-286 50-384 50-334 70-371	P	MATTSON, R J MATTSON, R J MATTSON, R J MATTSON, R J MATTSON, R J	8007100456 8007110322* 8007210176 8007230635 8007150061	50-320 H MISC 50-322 A 50-275 A FINANCIAL
MANRY, M MANGER, W. C MANGER, W. C MANSER, W. C MANSER, W. C	8007300392 8007160843* 800707014* 8007010109* 8007140064*	50-321 70-143 70-143 70-143 70-143	В	MARTIN, R MARTIN, T J MARTIN, J B MARTIN, W MARTIN, W Q	8007170076 8007250279 8007230075 8007230158 8007280733	50-282 50-354 PRDJ 50-320 70-1100	P 0 8	MATZ,O MAURO,C L MAXWELL,L V MAXWELL,O F MAXWELL,D R	8007150040* 8007250056 8007020375* 8007100432* 8007220101*	50-320 H 50-67 R 50-413 G WASTE MQT
MANBER, W C MANBER, W C MANBER, W C MANBER, W C MANBER, W C.	8007030292 8007020637 8007070191 8007070350 8007280552	70-143 70-143 70-143 70-143 70-143		MARTIN, T MASON, D O MASON, T J MASON, T J MASON, T J	8007290058 8007100013 8007010085* 8007010077* 8007210558*		8	MAXWELL, L V MAYER, L O MAYER, L O MAYER, L O MAYER, L O	8007020370 8007030222 8007010335 8007010351 8007010325	50-67 R 50-263 P 50-263 P 50-263 F 50-263 F
MANSER, W. C. MANSER, W. G. MARCHAL, J. MARCHAL, J. MARK, R. H	8007250464 8007270713 8007170229 8007240447 8007220503*	70-143 70-143 XPORTLIC XPORTLIC TOPREP	}	MASON, T J MASSEY, W E MATHEWS, E R MATHEWS, E R MATHENS, E R	8007210549* 8007180031 8007010034 8007020716 8007020032	40-2674 NUREQ 50-305 50-305 50-305	Ω Ω Q	MAYER,L D MAYER,L D MAYER,L O MAYER,L D MAYER,L D	8007010531 8007010311 8007010376 80070103819 8007010524	50-304 5
MARKEY, E. J. MARDITA, C. R. MARRACK, D. MARRACK, D. MARRACK, D.	8007110343* 8007110501* 8007030025 8007030029* 8007110080	50-352 50-320 50-466 50-466 50-466	U P G G	MATHEWS, E. R. MATHEWS, E. R. MATHEWS, E. R. MATHEWS, E. R. MATHEWS, E. R.	8007020254 8007220229 8007110317 8007080204 8007080386	50~305 50~305 50~305 50~305 50~305	0 8 8 8	MAYER,L O MAYER,L O MAYER,L O MAYER,L O MAYER,L O	8007100123 8007080251 8007100067 8007100190 8007080265	50-236 F. 50-263 P 50-263 P 50-263 B, 50-263 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MAYER, L D	8007210184	50-263 P	MCGAUGHY,R W	9007210355#	50-397 G	MEKBEL,C	8007150566*	50-344 S
MAYER, L D	8007280056	71-9018	MCGAUGHY,R W	8007210209#	50-410 G	MELLINGER,C U	8007140013	50-289 H
MAYER, L D	8007150481	50-282 Q	MCGAUGHY,J P	8007160866#	50-414 G	MELOTT,R K	8007150166	PR
MAYER, L O	8007110115	50-282 F	MCGAUGHY,R W	8007170599#	50-363 G	MENARD,H H	8007030193	PR
MAYER, L O	8007150611	90-263 R	MCGAUGHY,R W	8007210240#	80-352 G	MENARD,H H	8007280024	PR
MAYER, L O	8007160558	50~282 R	MCGAUGHY, J P	8007170592	50-416 S	MENNICKEN, JB	8007150036	XPORTLIC
MAYER, L O	8007170378	50~263 P	MCGAUGHY, J P	8007160585	50-416 S	MERRIWEATHER, N	8007180275*	50-395 O
MAYER, L O	8007210379	50~306 B	MCGAUGHY, J P	8007160642	50-416 S	MERRILL, JA	8007220019	NUREO
MAYER, L O	8007210437	50~282 S	MCGAUGHY, R H	8007170274*	50-354 G	MERBON, BD	8007010390*	50-317 R
MAYER, L O	8007180300	50~263 P	MCGAUGHY, R H	8007170289*	50-322 O	MERSON, BD	8007010392*	50-317 R
MAYER.L O	8007280441	50-263 F	MCGAUGHY, J P	8007020579	50-416 B	MERSON, S D	8007010387	50-317 R
MAYER.L O	8007280391	50-263 F	MCGAUGHY, J P	8007020640	50-416 B	MERSON, S D	8007220351	50-317 R
MAYER.L O	8007280410	50-263 P	MCGAUGHY, J P	8007160611	50-416 B	MERSON, S D	8007220355*	50-317 R
MAYER.L O	8007280488	50-263 F	MCGAUGHY, R W	8007170257*	50-387 Q	MESSINGER, M	8007100015*	70-143
MAYER.L O	8007270669	50-282 8	MCGAUGHY, R W	8007180561*	50-410 Q	MESSITT, B R	8007160830*	50-335 Q
MAYS, S. E. MAYS, S. MCBREARTY, R. A. MCBRIDE, A. F. MCGABE, E.	8007230172 8007080305* 8007210209* 8007250552* 8004240212	50~334 P 50-409 P 50-410 Q 50-460 A 50-286 S	M 94/40/00/00 M M MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8007210545* 8006170577 8007020601 8007160862* 8007020538	50-423	MESSITT, BR MEYER, RO MEYER, RO MEYER, RO MEYERS, S	8007170429* 8007010082* 8007010174* 8007010210* 8007100024	50-324 G FOIA FOIA FOIA PR
MCCABE, E MCCABE, E C MCCABE, E C MCCABE, E C MCCANN, M	8004240215 8007230736* 8007230174* 8007210247* 8007170057*	50-318 S 50-277 Q 50-334 Q 50-317 Q 50-204 H	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P	8007020630 8007070290 8007110413 8007110430 8007150093	50-416 8 50-416 8 50-416 8 50-416 6 50-416 8	MEYER, C J MEYER, J F MEYER, J F MICHEL, C J	8007030007 8007110575* 8007010408 8007230446 8007150520*	FOIA CONTRACT 50-247 P 50-247 P 70-143
MCCARTNEY,R M	8007020553	50-320 H	9 L.YHOUADDN	8007150097	50-416 8	MICHEL, C J	8007280184*	70-143
MCCARREL,S F	8007010418	50-344 P	9 L.YHOUADDN	8007150105	50-416 8	MICHEL, C J	8007010101	71-5768
MCCARREL,S F	8007300333	50-344 O	9 L.YHOUADDN	8007170396	50-416 8	MICHEL, C J	8007010121*	71-5768
MCCAULEY,B K	8007230513	50-10 D	9 L.YHOUADDN	8007170290	50-416 6	MICHEL, C J	8007070333	70-143
MCCLAIN,C M	8007220364*	50-217 R	9 L.YHOUADDN	8007170435	50-416 8	MICHEL, C, J	8007180475	71-249
MCCLINTOCK,R O	6007170337*	70-1849	9 L.YMOUADON	9007220388	50-416 8	MICHEL, C J	8007150563	70-143
MCCLINTOCK,R O	8007170345*	70-1849	9 L.YMOUADON	8007220389	50-416 8	MICHEL, C J	8007150518	70-143
MCCLINTOCK,R O	8007170341*	70-1849	9 L.YMOUADON	8007250432	50-416 0	MICHEL, C. J	8007290547	70-143
MCCLINTOCK,R O	8007170349*	70-1849	9 L.YMOUADON	8007250510	50-416 8	MIDURA, H J	8007150596	50-272 R
MCCLINTOCK,R O	8007170407*	70-1849	9 L.YMOUADON	8007280566	50-416 8	MILEHAM, J	8007110159	FOIA
MCCLINTOCK, R O	8007170292*	FOIA	P. YKOUGON	8007290655	50-416 8	MILHISER.R J	9007080239*	50-382 8
MCCLINTOCK, R O	8007170306*	FOIA	P. L. YHOUGON	8007290666	50-416 8	MILLER, J G	8007110023*	70-1333
MCCLINTOCK, R O	7812210553	PT9	P. L. YHOUGON	8007290671	50-416 6	MILLER, J, G	8007110020*	70-1333
MCCLINTOCK, R O	8007170304*	FOIA	P. L. YHOUGON	8007290714	50-416 8	MILLER, J,	8007110024*	70-1333
MCCLINTOCK, R O	8007170432*	FOIA	P. L. YHOUGON	8007290791	50-416 8	MILLER, J G	8007110015*	70-1333
MCCLINTOCK, RO	8007170399*	FOIA	MCGOLDRICK, F F	8007150074*	9ECY	MILLER, W H	8007100413*	50-324 Q
MCCLINTOCK, RO	8007170411*	FOIA	MCGOVERN, J J	8007210293*	70-687	MILLER, D 8	8007030059*	PR
MCCLINTOCK, RO	8007170314*	FOIA	MCGREY, J G	8007150140	PR	MILLER, T	8007140024	50-323 H
MCCLINTOCK, RO	8005090527*	PT9	MCGREGOR, L G	8007210327*	50-346 Q	MILLER, B W	8007090408	REOGD
MCCLINTOCK, RO	8007280224	40-8329	MCGREW, J W	8007010240	71-4888	MILLER, H J	8007020148	WASTE MGT
MCCONNELLIJU	8007150325*	70-2451	MCGNIFF.J M	8007010245	71-9030	MILLER,L C	9007250057*	GA999
MCCOLLOUGH,U D	8005090523	PT9	MCGNIFF.J M	8007150585*	50-327 8	MILLER,W H	8007100151*	50-269 G
MCCOLLOUGH,U D	8007150014	RE8	MCGNIRE.J P	8007310235*	50-389 0	MILLER,L	8007170579*	50-206 G
MCCOLLOUGH,U D	8007290789	50-344 G	MCGNIRE.J P	8007010540	50-293 8	MILLER,R W	8007310255	NUREQ
MCCEINTOCK,R O	8007240060	50-367 F	MCGNIRE.J D	8007070378	50-293 B	MILLER,R B	8007140377*	TOPREP
MCCORKLE, G W MCCORKLE, G H MCCORKLE, G H MCCORKLE, G W	8007240072 8007240080 8007020244 8007020505 8007140598	70-754 70-1252 70-1193 70-1739 70-135	MCGULRE.P J MCGUIRE.P J MCGUIRE.P J MCGUIRE.P J MCGUIRE.P J	8007030287 8007070357 8007080182 8007080196 8007080202	50-293 8 50-293 8 50-293 8 50-293 8 50-293 8	MILLER, R B MILLER, R B MILLER, W O MILLER, W O MILLER, W J	B007140416* B007160755* B0071109B0 B007020251 B0071705B3	TOPREP TOPREP 50-315 P 50-267 P 40-8380
MCCORKLE.G W MCCORKLE.G W MCCORKLE.G W MCCORKLE.G W MCCRACKEN.X W	8007240076 8007250648 8007310452 8007310475 8007220515*	70-734 70-27 70-25 70-25 50-348 P	MCKIDBEN, J C MCGUIRE, P J MCGUIRE, P J MCGUIRE, P J	8007140641 8007180393 8007180679 8007310004 8007080266	50-293 8 50-293 P 50-293 R NUREO 50-186 8	MILLER, J R MILLER, J. R MILLER, J. R MILLER, J R MILLER, H O	B007020169 B007020174# B007020490 B007020493* B007020250	50-150 P 50-150 P 50-193 P 50-193 P 40-4492
MCCRAY, J G MCCREERY, O E MCDDUALL, A J MCDDUGALL, A J	8007030138 8007220045 8007280052 8007170172* 8007240173*	PR RES PR Contract Contract	MCKIBBEN, J C MCKIBBEN, J C MCKINHEY, R D MCLOUGHLIN, M T MCLOUGHLIN, M T	8007080240 8007140351 8007220051 8007010545* 8007070382*	50-186	MILLER, H. O MILLER, J R MILLER, J R HILLER, J R MILLER, H J	8007030228 8007140630 8007140639 8007250483* 8007230161	70-1113 TOPREP TOPREP TOPREP 40-8714
MCDOWELL-BOYER	8007280095	RES	MCLOUGHLIN, M T	8007070388*	50-293 8	MILLER, D E	8007310815#	50-295 Q
MCDUFFIE.M A	8007020427	50-400 A	MCLOUGHLIN, M T	8007030289*	50-293 8	MILLER, T R	8007070282	50-329 Q
MCDUFFIE.M A	8007220210	50-400 Q	MCLOUGHLIN, M T	8007080200*	50-293 8	MILLER, J R	8007110274	50-463 A
MCDUFFIE.M A	8007150533	50-400 A	MCLOUGHLIN, M T	8007080205*	50-293 8	MILLER, D S	8007020607	50-309 Q
MCDUFFIE.M A	8007220456	50-400 A	MCLOUGHLIN, M T	8007140448*	50-293 8	MILLER, D S	8007020610#	50-309 Q
MCDUFFIE.M A MCELHANEY.D L MCELHANEY.D L MCELHANEY.D L MCELHURRY.B R	8007280507	50-400 R	MCMASTER, C F	8007140029	50-287 H	MILLER,D S	8007020407	50-307 0
	8007140379*	TOPREP	MCNAMARA, A	8007180590*	50-244 R	MILLER,D S	8007020610*	50-307 0
	8007140416*	TOPREP	MCNEILL, W M	8007160411*	QA979	MILLER,J G	8007250117*	COMMISSION
	8007160755*	TOPREP	MCPHILLIPS, J	8007110003	70-2909	MILLER,M I.	8007020462	50-597 0
	8007100352	PR	MCPHILLIPS, J L	8007110059	70-2909	MILLER,M I	8007020462	50-597 0
MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGARRY, J M	6007230160* 6007140243 8007240140 8007140004 6007140004	04999 F01A PR 50-349 0 50-369 0	MCPHILLIPS, J L MCNETHY, P J MEANS, D S MEBUS, C F MECKLINO, M	8007110055 8007180227* 8007030305 8007230686 8005070512	70-2909 M180 50-522 A 50-320 H 50-320 H	MILLER,K L MILLER,J R MILLER,J R MILLER,J R MILLER,M I	8007140004 8007150028 8007150035* 8007150041* 80070700045	50-920 T 50-184 P 50-184 P 50-184 P 50-329 G
MCGARRY, J M HCGAUGHY, R W HCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W	6007290887 8007100014* 8007210338* 8007170482* 8007010335*	PR 50-320	MEDLOCK,R L MEDROW,L A K MEIER,M O MEINCKE,J A MEIRS,R L	8007240007 8007170122 8007300545 8007110407 8007100152	40-8452 CONTRACT PR 50-255 R PROJ	MILLER, W I MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8007090045 8007210039 8007210041 8007210043 8007210051	50-329 0 70-143 71-5980 71-9019 YUPREP

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESS FON NUMBER	SUBJEC CATEGOR
MILLER, W O MILLER, W O MILLER, W O MILLER, H J MILLER, J R	8007180502 8007210038 8007210057 8007230279 8007220134	70-8 70-824 50-293 P 40-8200 TOPREP	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007150472 8007140643 8007140443 8007160650 8007160666	50-327 P 50-327 F 50-328 S 50-438 S 50-328 S	MINER, L E HINER, S MINER, L E MINERS, W MINDOUE, R B	8007250012* 8007010546 8007240258* 8007290771 8007160694*	40-4337 50-315 40-4337 DRG 50-341
MILLER, D B MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8007280041 8007170621 8007180076 8007180104 8007180109	50-329 A 70-754 50-317 P 50-269 P 50-244 P	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007210091 8007230726 8007280615 8007150546 8007150551	50-257	MINDOUE, R B MINDOUE, R B MINDOUE, R B MINDOUE, R B MINDOUE, R B	8007070578 8007250019* 8007070015 8007140574 8007140055	SECY LOCFR SECY SECY SECY
MILLER, W O MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8007180113 8007210074 8007210097 8007230052 8007230057	50-219 P 70-697 70-27 50-269 P 50-244 P	MILLS,L M MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007150640 8007150692 8007160424 8007210036 8007210596	50-327 P 50-327 P 50-438 S 50-327 Q 50-327 Q	MINDOUE, R B MINDR.O C MINTZER.D MISHIMA, J MISHIMA, J	8007170504* 8007270809* 8007250578* 8007070186* 8007210315*	10CFR DRO CONTRAC' 70-1257 70-1257
MILLER, W O MILLER, W O MILLER, H J MILLER, D 8 MILLER, D 8	8007230114 8007290707* 8007230620 8007110345 8007110345	50-329 A 50-329 A 40-8727 PR PR	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007150521 8007160473 8007230255 8007300003 8007170272	50-327 P 50-566 B 50-566 B PRM 50-390 Q	MITCHELL, W MITCHELL, D G MITCHELL, D G MITCHELL, D G	800723018B 8007070256* E007070313* B007080214* 8007160526*	MISC 50-287 50-289 50-289 50-289
MILLER, O E MILLER, O E MILLER, M I MILLER, M I MILLER, J R	8007150413 8007150420* 8007140020 8007140020 8007280499	50-326 R 50-326 R 50-327 0 50-327 0 50-264 F	MILLB,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007170342 8007170356 8007150571 8007150459 8007160471	50-566 S 50-566 B 50-327 P 50-566 S 50-327 P	MITCHELL.D G MITCHELL.D G MITTL.R L MITTL.R L MITTL.R L	8007140623* 8007290805* 8007070285 8007030161 8007030229	50-287 50-287 50-272 50-272 50-311
MILLER, L K MILLER, W O MILLER, W O MILLER, M E MILLER, W D	8007150404* 8007210089 8007210094 8007290789 8007250580	50-272 R 70-1257 70-364 50-344 G 70-25	MILLE,L M MILLE,L M MILLE,L M MILLE,L M	8007170513 8007170591 8007310355 8007170560 8007220376	50-390 5 50-390 8 50-259 0 50-260 P 50-259 P	MITTLIR L MITTLIR L MITTLIR L MITTLIR L MIYABAYASHIIM	8007030244 8007160628 8007210219 8007210389 8007250555	50-311 50-311 50-311 50-311 XPORTLIC
MILLER,W O MILLER,M I MILLER,W I MILLER,W O MILLER,M E	8007280064 8007220194 8007220194 8007250157 8007220500	50-315 P 50-327 Q 50-327 G 40-8584 50-445 M	MILLE.L M MILLE.L M MILLE.L M MILLE.L M MILLE.L M	8007230445 8007230487 8007230582 8007310056 8007220522	50-259 8 50-390 8 50-390 0 50-327 0 50-259 0	MIYABAYASHI,M MIYABAKI,D H MODENOB,L MOEGLING,J B MOFFETT,T	8007310028 8007140072 8007100131* 8007100328 8007110343	XPORTL IN NUREO 50-327 PR 50-320
MILLER,W O MILLER,W O MILLER,W O MILLER,W O MILLER,M I	8007230081 8007280277 8007280282 8007280564 8007230810	50-54 F 40-6622 70-1143 40-8681 50-255 G	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007230431 8007310208 8007220460 8007220532 8007230494	50-328	MOFFITT, A E MONBOISSE, R M MONBOISSE, R M MONBOISSE, R M MONBOISSE, R M	9007150004 8007100254 8007100257* 8007100254 8007100257*	PR PR PR PR
MILLER, M I MILLER, D S MILLER, D S MILLER, D. B MILLER, D B	8007230810 8007300122 8007300127* 8007300122 8007300127*	50-255	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8007230499 8007230467 8007230477 8007230480 8007230486	50-327 F 50-327 P 50-327 P 50-327 P 50-328 S	MONTAGUE, P MONTAGUE, P MONTI, U A MOODY, D E MOODY, D E	9007220326 8007300323 8007150667 8007180090 8007010057	FOIA 50-10 50-3 50-307 50-29
MILLBAP,W J MILLB,L.M MILLB,L M MILLB,L M MILLB,L M	8007030370* 8007070268 8007110039* 8007070042 8007020347	70-1201 50-259 P 50-327 Q 40-1341 50-327 Q	MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007230505 8007230511 8007230528 8007230533 8007230587	50-390 8 50-327 A 50-518 S 50-327 P 50-390 8	U 0.Y000M B 0.Y000M B 0.Y000M H U,Y000M B 0.Y000M	8007280136* 8007170582 8007180144 8007140030 8007280458	50-320 50-29 50-29 PRM 50-309
HILLS,L. M MILLS,L. M MILLS,L. M MILLS,L. M MILLS,L. M	8007020499 8007280468* 8007020619 8007160571 8007170664	50-257 0 50-257 0 50-370 8 50-328 8 50-328 8	MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007300572 8007230408 8007230575 8007290479 8007280460	50-259 Q 50-327 P 50-327 F 50-327 Q 50-438 S	MDQDY, D E MOQDY, D E MOQDY, D E MOQDY, D T	8007210506 8007140403 8007090233 8007250273 8007280425*	50-29 50-309 50-29 50-29 50-27
MILLB,L M MILLB,L,M. MILLB,L M MILLS,L M MILLB,L M	8006250275 8007140240 8007010426 8007250585 8007240279*	50-518 8 PRM 50-438 A 40-1341 50-518 Q	HILLB,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007290724 8007280548 8007290632 8007290729 8007290749	50-327 P 50-327 F 50-328 8 50-438 8 50-438 6	MBON, C W MOON, C W MOON, C W MOON, C W	8007240010 8007300397 8007300404 9007300423 8007300424	50-466 50-466 50-466 50-466 50-466
MILLB.L M MILLB.L.M MILLB.L M MILLB.L M MILLB.L M	8007010327 8007010339 8007010386 8007020543 8007020544	50-327 P 50-318 A 50-328 A 50-328 B 50-328 B	MILLB,L M MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8007290913 8007280498 8007280623 8007290679 8007290757	50-390 Q 50-327 Q 50-327 P 50-327 P 50-327 P	MDON.C W MOONEY,R R MODRE,V A MOORE,V A MODRE,D E	8007310312 8007150159 8007070053* 8007070055* 8007070005*	50-466 REGGD 50-514 50-514 70-2478
MILLB, L M MILLB, L M MILLB, L M MILLB, L M	8007020627 8007180523 8007080220 8007100252 8007080286	50-327 Q 50-259 Q 50-327 Q 50-553 B 50-259 P	MILLS, L. M. MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8007300434 8007310376 8007310412 8007310323 8007310411	50-327 F 50-327 P 50-327 P 50-327 P 50-327 P	MODRE, D E MODRE, O W MODRE, J B MODRE, J C	8007100075* 8007020545 8007020547* 8007210287 8007080075	50-261 50-334 50-334 70-114 50-302
MILLB.L M MILLB.L.M MILLB.L.M MILLB.L.M MILLB.L.M	8007080331 8007100205 8007100233 8007080253 8007080380	50-327 Q 50-438 Q 50-438 S 50-370 A 50-257 P	MILLB.L M MINARICK.J W MINECK.D.L MINECK.D L MINECK.D L	8007310416 8007290552* 8007230233 8007030212 8007030224	50-327 P 50-440 A 50-331 P 50-331 S 50-331 S	MOORE, O C MOORE, N MOORE, O C MOORE, J E MOORE, J E	8007150484 8007220107 8007150385 8007150711 8007170354	50-302 XPORTUI 50-302 50-247 50-155
MILLS, L. M, MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8007090388 8007090222 8007100169 8007220236 8007090249	50-390 V 50-390 8 50-438 0 50-518 0 50-327 8	MINECK, D L MINECK, D L MINECK, D L MINECK, D L MINECK, D L	8007030238 8007110411 8007110471 8007220599 8007230484*	50-331 8 50-331 8 50-331 8 50-331 8 50-331 P	MOORE,V A MORDAN,U.E MORIARTY,J M MORIARTY,J M MORIARTY,J M	8007290525 8007280218 8007090270* 8007090275* 8007010459	50-352 50-395
MILLO, L M MILLO, L M MILLO, L, M, MILLO, L, M MILLO, L, M	8007100209 8007110320 8007270927 8007140349 8007140422	50-438 8 50-518 8 PR 50-518 8 50-390 8	MINECK, D.L. MINECK, D.L. MINECK, D.L. MINECK, D.L. MINECK, D.L.	8007220497 8007220367 8007220394 8007230492 8007230464	50-331 8 50-331 R 50-331 P 50-331 P 50-331 S	N L.YTRISON TO LAISING TO LAISING TO LAISING TO LAISING TO LAISING TO LAISING	8007010357 8007230598 8007210047* 8007010567 8007170088*	40-630

AU FHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
MORRIEL, P J MORRIESON, U M MORRIES R H MORROW, D MORROW, D	8007300525* 8007300005 8007310397 8007070120 8007070115	50-344 G ORG 50-275 A 40-8502 40-8380	MURPHY, C E MURPHY, C E MURPHY, R MURPHY, C E MURPHY, C E	8007290344 8007290407 8007070178 8007300587 8007100412	50-438 Q 50-424 Q PR 50-516 Q 50-400 Q	NAPUDA, O NAPUDA, G NAPUDA, G NARBUT, P NARRON, L	8007180101* 8007170692* 8007230137* 8007180018* 8007170599*	50-293 Q 50-217 Q 50-289 Q 50-204 Q 50-363 Q
MORROW, D MORROW, D MORROW, D MORROW, D MORROW, D	80070200B3 800702045B 8007020064 8007030219 8007210066	40-8497 40-8721 40-8497 40-8380 40-8502	MURPHY, C E	8007100417 8007290422 8007310240 8007070097 8007100356	50-413 Q 50-566 Q 50-416 Q 50-335 Q 50-324 Q	NARROW, L NASH, D NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F	8007170288* 8007250598 8007160627 8007010428 8007010411	50-322 G 50-482 M 50-577 C 50-275 P 50-454 A
MORROW, D MORROW, D MORROW, D MORSE, W T MORSE, A K	8007210063 8007280054 8007280303 8007140407 8007280657*	40-8697 40-8502 40-8502 50-443	MURPHY, C E MURPHY, C E MURPHY, P M MURPHY, W P MURPHY, W P	8007110034 8007110515 8007070314 8007010317 8007010371	50-327 0 50-424 0 50-255 0 50-271 8 50-271 8	NAUGHTON:W F NAUGHTON:W F NAUGHTON:W F NAUGHTON:W F NAUGHTON:W F	8007010211 8007020408 8007020431 8007080299 8007140559	50-295 P 50-454 K 50-454 B 50-454 K 50-454 K
MORSE, A K MORSE, A MORTON, K V MORTON, K V MORTON, K V	8007310101 8007280454 8007210247* 8007010427* 8007020009*	50-409 G 50-409 G CONTRACT CONTRACT CONTRACT	MURPHY, W P MURPHY, W P MURPHY, H J MURPHY, E S MURPHY, H J	8007010403# 8007070260 8007080280# 8007240283 8007080426#	50-271 8 50-271 8 50-272 8 NUREQ \$0-272 8	NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F NAUGHTON, W F	8007150474 8007290678 8007140320 8007220540 8007280605	50-295 P 50-454 K 50-454 K 50-454 K 50-295 P
MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V. MORTON, K. V.	8007020025* 8007020553* 8007010519* 8007210259* 8007300598*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MURPHY, C E MURPHY, M. J MURPHY, C E MURPHY, C E MURPHY, M J	8007140840 8007100202* 8007180189 8007310495* 8007150517*	50-416	NAUGHTON, W F NAVARRO, C C NEIGHBORB, D NEILL, R H NEILBON, R M	8007280670 8007180169* 8007310517 8007030045 8007230655*	50-454 8 COMMISBION 50-261 P PR FOIA
MORTON, K V MORTON, K V MOSBY, W R MOSBLEY, N C MOSBLEY, N C	8007310010* 8007250578* 8007230194 8007150778* 8007110555	CONTRACT CONTRACT RES ORO 50-315 P	MURPHY, M J MURPHY, C E MURPHY, C E MURPHY, M J	8007150628* 8007150677* 8007240265 8007280126 8007170448*	50-272 8 50-272 8 50-518 G 50-321 G 50-311 8	NEILSON, L E NEISLER, J H NELSON, P R NELSON, P R NELSON, P R	8004010434 8007230700* 8007170322* 8007170326* 8007170266*	MIBC 50-373 Q 70-1849 FOIA 50-219 Q
MOSELEY, N C MOSELEY, N C MOSES, V R MOSZYNSKI, J R MOWRY, W R.	8007250051 8007250480 8007100090 8007150066 8007020084	50-272 S 50-266 P PR RES XPORTLIC	MURPHY, M J MURPHY, M J MURPHY, H J MURPHY, H MURPHY, H	8007220382* 8007220627* 8007210507* 8007230488 8007230489*	50-272 S 50-272 S 50-272 S 50-271 S 50-271 S	NELSON.P R NELSON.J NELSON.J D NELSON.J D NELSON.J D	8007170276* 8007020176 8007210183 8007210177 8007230135	50-219 G MISC 40-8452 40-8452 40-8452
MROCIKA, E J MROCIKA, E J MROCIKA, E J MROCIKA E J MROCIKA, E J	8007010445 8007070318 8007070361 8007100157 8007100167	50-334 S 50-336 S 50-336 S 50-245 S 50-245 S	MURPHY, P M MURPHY, P M MURPHY, M J MURPHY, C E MURPHY, M J	8007230810 8007230810 8007280632* 8007310212 8007270711*	50-255	NELSON, O NELSON, C C NELSON, R R NELSON, R L NELSON, J D	8007080082 8007110525 8007090398 8007230328* 8007230725#	COMMISSION 50-307 P REQQD 50-305 Q 40-8452
MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J MROCZKA, E J	8007110464 8007180408 8007160676 8007210374 8007180298	50-245 8 50-245 R 50-245 R 50-336 R 50-245 8	MURPHY, M J MURPHY, M J MURRAY, J P MURRAY, T D MURRAY, T. D	8007290729* 8007290844* 8007300390* 8007010434 8007030260	50-272	NELSON, C C NELSON, C C NEUMAN, R F NEUMANN, M R NEUMANN, M R	8007100161 8007290007 8004300385 8007020702 8007030002	50-335 P 50-70 P 50-155 H 40-8380 40-8380
MROCIKA,E J MROCIKA,E J MUCHNICKI,E D MUCHNICKI,E D MUDREY,M 0	B007250409 B007290697 B006110406 B007100246 B007140402	50-336 S 50-245 G PR PR PR	HURRAY, T D MURRAY, T. D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8007150609 8007110427 8007110391 8007110407 8007110418	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8	NEUMANN, M R NEUMANN, M R NEUMANN, M R NEUMANN, M R NEUMANN, M R	8007210144 8007220035 8007240100 8007220022 8007140390	40-8380 40-8380 40-8380 40-8380 40-8380
MUELLER, E W MUENCH, O W MUIR, H B MUIR, H B MUKHERJEE, H	8007010133* 8006300368 8007310490* 8007310487 8007020135*	Etate Prug 50-556 A YPORTLIC XPORTLIC WASTE MOT	MURRAY, T D MURRAY, M J MURRAY, M J MURRAY, T D MURRAY, M. J	8007110440 8007140432 8007140437* 8007140318 8007150056	50-344 S PR PR 50-346 R 50-367 Q	NEUMANN, M R NEWBERRY, B NEWMAN, M K NEWMAN, J R NEWMAN, J R	8007210224 8007110485* 8007010091* 8007020471 8007020471	40-8380 50-320 P 40-2474 50-466 Q 50-466 Q
MULLER, D R MULLER, H MULLER, L L MULLER, R E MULLER, D R	8007250063 8007150040* 8007270882 8007160802 8007240046	50-320 H XPORTLIC XPORTLIC XPORTLIC 50-445 A	MURRAY, T. D MURRAY, T. D MURRAY, T. D MURRAY, T. D. MURRAY, T. D.	8007150560 8007240126 8007170441 8007220375 8007220458	50-346 B 50-346 B 50-346 B 50-346 B 50-346 B	R , CANAMAN R , CANAMAN R , CANAMAN R , CANAMAN R , CANAMAN	8007080017* 8007080017* 8007090189 8007090189 8007160570	50-466 Q 50-466 Q 50-466 Q 50-466 Q 50-466 Q
BINUM L L.ORNUM L L.ORNUM N J.ORIITHUM N J.ORIITHUM	8007180470* 8007030375 8007100373 8007020270 8007020262	71-9136 71-9039 71-9053 BECY BECY	MURRAY, M. J. MURRAY, T. D.	8007250442 8007280576 8007280571 8007280630 8007280583	27-39 50-346	R L. (NAMUEN R L. (NAMUEN R L. (NAMUEN R L. (NAMUEN R L. (NAMUEN	8007160570 8007160645 8007160645 8007160639 8007160639	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0
MURDOCK, L. T MURPHY, C & MURPHY, C & MURPHY, C & MURPHY, C &	8007210170* 8007160869* 8007100384* 8007110527* 8007100423*	40-4492 50-416	MURRAY, T. D MUSE, L. A MUSOLF, D. MYERS. H MYERS, F. S	8007280609 8007100349 8007010583* 8007230565* 8007010029*	50-346 8 71-389 50-282 P 50-320 U QA999	R L , NAMWEN R L , NAMWEN R L , NAMWEN R L , NAMWEN R L , NAMWEN	8007180432 8007180432 8007250424 8007250424 8007290082	50-466 0 50-466 0 50-466 0 50-466 0 50-466 0
	# #	50-335 0 50-400 0 50-389 0 50-324 0	MYERS, I L MYNATT, F R MYRABO, A L NAIDU, K R	8007180022* 8007140507 8007150614* 8007110479* 8007170635*	Btate Prog REB 50-243 R 50-358 Q 50-329 Q	NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, J R	8007270082 8007300413 8007300449 8007300413 8007300447	50-466 Q 50-466 Q 50-466 Q 50-466 Q 50-466 Q
				8007310225 8007290460 8007290467* 8007110326* 8007080390*	NUREQ XPORTLIC XPORTLIC 50-905 8 50-905 8	NEWHAN, J R NEWHAN, J R NEWHAN, J R	8007310094 8007310309 8007310094 8007310309 8007100130	50-446 0 50-446 0 50-466 0 50-466 0 PRM
				8007160474* 8007160502* 8007160510* 8007280674* 8007280685*	50-305 8 50-305 8 50-305 8 50-305 8 50-305 8	NEY,WR NICHOLSON,T J NICHOLS,T,C NIELSEN,AD NIELSEN,GA	8007070121 8007170179 8007310428 8007140014 8007180337	PR PR 70-2860 50-275 H 50-409 D

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJEC
NIJHAWAN, 8 NIJHAWAN, 8 NILBON, R NILBON, R NIMITZ-R	8007170460 8007140642 7909210176 8007070402 8007150081	RES RES REGOD PR 50-286 S	NGVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007170651 8007170667 8007180119 8007210004 8007210035	50-289 P 50-312 P 50-277 P 50-269 P 50-346 P	G'REILLY, J P G'REILLY, J P G'REILLY, J P G'REILLY, J P	8007140490 8007020170 8007020171 8007020173 8007020178	50~321 50~375 50~375 50~416 50~321
NIX.R T NIX.R T NIX.R T NIX.R T NIX.R T	8007010503* 8007030274* 8007030242* 8007030279* 8007110426*	50-366 S 50-366 S 50-366 S 50-366 S 50-321 S	NGVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007210110 8007210115 8007210573 8007210581 8007210589	50-302 P 50-346 P 50-346 S 50-302 P 50-313 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020179 8007020180 8007020187 8007020192 8007020200	50-302 50-348 50-261 50-259 50-280
NIX.R T NIX.R T NIX.R T NIX.R T NIX.R T	8007150544* 8007150685* 8007150508* 8007150674* 8007170387*	50-321	NOVAK, T K NOVAK, T K NOVAK, F M NOVAK, T K NOVAK, T K	8007240244 8007170241 8007180506 8007170558 8007210023	50-312 P 50-247 P 50-321 P 50-331 P 50-313 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	G007020204 8007020231 8007150468* 8007210414 8007210419	50-269 50-250 50-280 50-437 50-348
NIX.R T NIX.R T NIX.R T NIX.R T NIX.R T	8007170408* 8007170410* 8007170463* 8007170497* 8007170468*	50-321	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007210026 8007240085 8007240288 8007240304 8007240311	50-259 P 50-246 V 50-335 P 50-344 P 50-368 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	6007210422 8007210437 8007210449 8007210458 8007210462	50-241 50-489 50-249 50-250 50-302
NIX,R T NIX,R,T NIX,R T NIX,R,T, NIX,R T	8007280512* 8007240128* 8007240167* 8007250412* 8007280447*	50-346 8 50-366 9 50-366 8 50-366 8 50-321 8	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M	8007240330 8007240335 8007240338 8007240346 8007240350	50-264 P 50-265 P 50-335 P 50-309 P 50-336 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007210448 8007210471 8007210472 8007210477 8007210488	50-424 50-395 50-395 50-280 50-327
NIX,R T NIX,R T NIX,R T NIX,R T NIX,R T	8007280526* 8007280446* 8007280588* 8007280640* 8007280690*	50-366 8 50-321 8 50-321 8 50-321 8 50-321 8	NOVAK, T M NOVAK, T M NOVAK, T M NOVAK, T M NOVAKOVICH, D	8007240380 8007240389 8007240399 8007280169 8007280383	50-317 P 50-282 P 50-70 P 50-330 P XPORTLIC	G'REILLY,J P G'REILLY,J P G'REILLY,J P G'REILLY,J P	8007010175 8007010179 8007010188 8007010206 8007010213	50-437 50-261 50-488 50-250 50-269
NIXON,W A NIXON,W A NIXON,W A NOCELLA,8,J.	8007220220* 8007210480 8007310271 8007310320 8007140248	70-195 40-2061 40-2061 40-8027 F01A	NOVAK, T K NOVAK, T K NOVAK, T K NOVAK, T K NOVAK, T K	8007210020 8007280342 8007280345 8007280350 8007280353	50-309 P 50-277 P 50-289 P 50-313 P 50-346 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007010220 8007010225 8007010239 8007010242 8007010248	50-321 50-259 50-280 50-395 50-395
NOONAN, V. NORDERHAUO, L. R NORDERHAUO, L. R NORDERHAUO, L. R NORDERHAUO, L. R	8004240210 8007140696 8007010177 8007240032 8007210474	I&E XPDRTLIC 50-344 G 70-1257 50-27 G	NOVAK, T K NOVAK, T M NOVAK, F K NOVAK, T K NOVAK, T K	8007230651 8007230656 8007230708 8007250278 8007280117	50-312 P 50-321 P 50-326 P 50-302 P 50-270 P	G.WEITTA' 1 b G.WEITTA' 1 b G.WEITTA' 1 b G.WEITTA' 1 b G.WEITTA' 1 b	8007010250 8007010251 8007010253 8007310223* 8007220017	50-416 50-302 50-349 50-387 50-375
NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORELIUB, C E	8007240495 8007230154 8007240361 8007310523 8007210125*	70-25 50-312 S 50-106 G 50-139 G 50-483 G	NOVAK, T K NOVAK, T K NOVAK, T K NOVARRO, J P NOVARRO, J P	8007300553 8007310336 8007310350 8007210040* 8007070243	50-270 P 50-321 P 50-346 P 50-322 Q 50-322 K	G'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P G'REILLY, J P	8007220020 8007220026 8007220029 8007220040 8007220043	50-332 50-437 50-257 50-348 50-261
NORELIUB. C E NORTHOLM, L J NORTH, H 8 NORTH, H NORTON, B	8007280435* 8007310055* 8007110184* 8007230297* 8007070123	50~346	NOVARRO, J P NOVARRO, J P NOVARRO, J P NOWICKI, S J NOWICKI, S J	8007140390 8007150655 8007230458 8007110127 8007110118	50-322 B 50-322 A 50-322 A 50-244 F 50-219 F	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007220048 8007220054 8007220062 8007220066 8007220072	50-269 50-488 50-250 50-280 50-321
NORTON, B NOBENZO, L V NOBENZO, L V NOBENZO, L V NOBENZO, L V	8007180405 8007210074* 8007010012 8007140560* 8007210073	50~R75 0 BECY XPORTLIC BECY XPORTLIC	MUNNBERGER, C E MUNN, D E MUNN, D E MUNN, D E	8007100214 8007100217 8007010443 8007210473 8007140571	50-244 F 50-204 G 40-2257 50-361 B PR	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007220076 8007220078 8007220083 8007160218 8007160223	50-302 50-416 50-375 50-348 50-261
NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	8007170204 8007170223 8007170235 8007170251* 8007210076	XPORTLIC XPORTLIC XPORTLIC BECY XPORTLIC	NYOAARD, O NYOAARD, O R NYORON, J O'CONNOR, L A O'CONNOR, L A	8007280659* 8007310101 8007140606 8007140355 8007150622	50-409 G 50-409 G 40-8502 50-213 I 50-245 I	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007160230 8007160255 8007160262 8007160265 8007160274	50-488 50-249 50-302 50-250 50-424
NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	8007010009 8007010019 8007020240 8007100144 8007170072	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	O'DONNELL, A J O'HANLON, J P O'HEAR, J W O'NEILL, T V O'NEILL, J	8007140045 8007280546 8007220573* 8007270056* 8007310400	PR 50-313 B 50-414 A M18C 50-155 O	0'REILLY, J P 0'REILLY, J P 0'REILLY, J P 0'REILLY, J P	8007140278 8007140281 8007140287 8007140307 8007140315	50-416 50-395 50-327 50-280 50-437
NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V. NOTLEY, D. P	8007170003 8007240440 8007280547 8007280559 8007140302*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC FOIA	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007010134* 8007150038* 8007310339* 8007240084 8007240089	50-293 P 70-1113 50-295 Q 50-437 Q 50-259 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007140269 8007140294 8007140299 8007140301 8007140306	50-324 50-321 50-416 50-518 50-259
NOVAK, T. M NOVAK, T NOVAK, T NOVAK, T NOVAK, T M	8007250702 8007020314 8007020451 8007100155 8007100455	50-344 P 50-249 P 50-271 H 50-277 P 50-309 F	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007240108 8007240113 8007240122 8007240139 8007240202	50-348	G LY, LIERY O B CAREILLY, J P CAREILLY, J P CAREILLY P CAREILLY, D CAREILLY, D CAREILLY, D CAREILLY, D CAREILLY, D CAREILLY, D CAREI	800725033B 8007250339 8007250344 8007250368 8007250372	50~364 50~400 50~369 50~48/ 50~
NOVAK, T. M. NOVAK, T. M NOVAK, T. M NOVAK, T. M NOVAK, T. M	8007030371 8007020447 8007100006 8007110512 8007110541	50-313 P 90-302 F 50-346 P H18C 50-336 P	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007240206 8007240213 8007240218 8007240220 8007240222	50-250 0 50-321 0 50-416 0 50-395 0 50-395 0	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007250375 8007250377 8007250378 8007250380 8007250381	5,' *
NOVAK, T. M. NOVAK, T. M NOVAK, T. M NOVAK, T. M NOVAK, T. M	8007020711 8007170060 8007170444 8007180341 8007210088	50-259 P 50-307 P 50-309 F 50-331 P 50-315 F	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P,	8007240230 8007140476 8007140479 8007140484 8007140489	50-280 Q 50-259 Q 50-518 Q 50-416 Q 50-324 Q	O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007250384 8007250387 8007310537 8007020721 8007020723	51 51 51 71 71

ŧ

SOHTUA	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
O'REILLY, J P	8007020725 8007020729 8007020732 8007020733 8007020735	70-1201 70-143 70-1113 70-1319 70-1151	DLAGCDAGA,M T OLDBERG, T OLIU,W E OLIU,W OLIVADOTI,J R	8007310241 8007010233* 8007310004 8007160773 8007280125	HUREO FOIA HUREO HIBC 71-192	PAGE.R O PAGE.R O PAGE.R O PAGE.R O PAGE.R O	8007030022 8007280320 8007220211 8007220242* 8007070187	70-1151 70-1319 70-135 70-135 70-1113
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020736 8007020739 8007020741 8007020743 8007020745	50-321 0 50-332 0 50-375 0 50-302 0 50-261 0	OLLER, R E OLLER, R E OLLER, R E OLLER, R E OLMSTEAD, N J	8007140157* 8007250189* 8007210539* 8007270862* 8007230536	QA799 QA999 QA999 QA999 GO-275 Q	PAGE,R G PAGE,R G PAGE,R G PAGE,R G PAGE,R G	8007240098 8007230056 8007240282 8007240106 8007240119	70-1359 70-2375 70-1738 70-1201 70-27
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020748 8007020751 8007020752 8007020757 8007020751	50-395 0 50-348 0 50-250 0 50-290 0 50-299 0	OLMSTEAD, W J OLSEN, A F OLSEN, A F OLSHAN, L II OLSHAN, L N	8007310461 8007010006 8007010293 8007110557 8007170319	50-275 G 70-824 70-824 50-247 P 50-245 P	PAGE.R G PALCHESKO.C M PALUSAMY.S S PANXASKIE.P J PANKASKIE.P J	8007290072 8007250343 8007020644* 8007010082* 8007010187*	70-143 40-2561 TOPREP FOIA FOIA
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020763 8007070010 8007020374 8007020380 8007020381	50-267 0 70-143 50-416 0 50-437 0 50 395 0	OLSHAN, L. R OLSHANIH, L. N OLSON, J. F OLSON, R. C OLSON, A. N	8007300092 8007310514 8007100208 8007020349 8007140617	50-286 P 50-286 P 50-282 O 50-317 P NUMEO	PANKASKIE.P J PANKASKIE.P J PAPAY.L T PAPAY.L T PAPAY.L T	8007010191* 8007010238* 8007020149* 8007240088 8007170565*	FDIA FDIA 50-361 Q 50-361 Q 50-206 Q
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020384 8007020385 8007020391 8007020409 8007020434	50-375	OLSON, J F OLSON, J F OLSON, J F OPLINGER, J O OPREA, O W	8007140011 8007230583 8007250422 7704200225 8007230718	PR PR 50-282 9 XPORTLIC 50-498 0	PAPAY, L T PAPAY, L T PAPAY, L T PAPERIELLO, C J PAPERIELLO, C	8007090330 8007230287* 8007230579 8004240258 8004240278	50-361 8 50-206 0 50-361 8 I&E I&E
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007020440 8007020445 8007020450 8007020454 800702045 <i>9</i>	50-261	DPREA, O W DPREA, O W DPREA, O W DPREA, O W DPREA, O W	8007170203 8007020618 8007090246 8007090365 8007110337	50~498	PAPPAS, H PAPPAS, H PAPPAS, H PAPPAS, H PAPPAS, H	8007140597 8007010150 8007010157 8007020278 8007210334	ORO 50-10 0 DRG . 50-10 0 ORO
O'REILLY, J P	8007290395 8007300576 8007310344 8007160781 8007160784	50-259	OPRCA.O W OPRCA.O W OPRCA.O W OPREA.O W OPREA.O W	8007150445 8007160604 8007210511 8007220578 8007230512	\$0-498 \$ 50-498 8 50-498 \$ 50-498 \$ 50-498 \$	Pappas, H Pappas, H Pappas, H Pappas, H Pappas, H	8007150770 8007220261 8007140421 8007290104 8007030052	ORO ORO ORO ORO 50-10 Q
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007160787 8007160791 8007160794 8007160800 8007170070	50-416 0 50-348 0 50-302 0 50-261 0 50-259 0	OPREA, O W OPREA, O W OPREA, O W OPREA, O W	8007230525 8007230476 8007230540 8007300340 8007300382	50-498 8 50-498 8 50-498 5 50-466 H 50-498 8	Pappag, H Pappag, H Pappag, H Pappag, H Parimi, S R	8007030054 8007240065 8007170343 8007140566 8007220234*	ORG ORG ORG 50-10 0 50-305 P
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170075 8007170104 8007170107 8007170115 8007170119	50-469 0 50-267 0 50-250 0 50-321 0 50-280 0	OBANN'E M OBTOBRA'D U OBTOBRA'D U	8007290654 8007290694 8007280047 8007180072 8007080095	50-57 R 50-57 R 40-8102 NUREO 50-347 O	PARIS,O H PARKER.W O PARKER.W O PARKER.W O PARKER.W O	8007220004 8004050317 8007100419* 8007090402 8007140397	50-320 0 50-369 5 50-413 0 PR 50-269 P
O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170126 8007170131 8007170134 8007170137 8007170141	50-992	OBANN.E W OBT.F OBTENDORF,D L OSTEN.J OSTEN.J	8007080055 8007160662* 8007280677* 8007150616 8007290709	50~367 0 50~295 8 50~407 0 50~254 J 50~254 J	PARKER.W O PARKER.W O PARKER.W O PARKER.W O PARKER.W O	8007010065 80071400B3 80070301B6 8007020537 8007100036	50-269 G NUREO PRM 50-413 8 50-369 G
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170144 8007170149 8007170149 8007170152 8007170154	70-1201 70-824 70-27 70-1113 70-143	OSTON, B G OSTRANDER, F W OSTRANDER, F W OSTRANDER, F W OSTRANDER, F W	8007100198* 8007300357 8007300377* 8007300481 8007300490*	PR 50-344 Q 50-522 Q 50-344 Q 50-344 Q	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8007100137 8007180349 8007150015 8007010205 8007010309	50-270 Q 50-270 Q 50-267 Q 50-267 F 50-367 F
O'SEIFTA' 1 6 O'SEITTA' 1 6 O'SEITTA' 1 6 O'SEITTA' 1 6	8007170159 8007170164 8007170164 8007170173 8007170177	50-160 0 50-111 0 50-83 0 50-62 0 50-539 0	OSTRANDER.F U OSTRANDER.F U OSTRANDER.F U OTT.W.R OTTOSON.H L	8007300494* 8007300500* 8007300506* 8007090017* 8007290883	50-344	PARKER,W O PARKER,W O PARKER,W O PARKER,W O PARKER,W O	8007010340 8007180533 8007020575 8007020192 8007070319	50-269 P 50-269 Q 50-269 P 50-269 Q 50-269 8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007170181 8007170185 8007170186 8007230199 8007230206	50-124 Q 50-127 Q 50-406 Q 50-437 Q 50-348 Q	OTTOBON: H L	8007250434 8007280072 8007010533 8007100242 8007250358	50-206 Q 50-206 Q 50-206 S 50-206 R 50-206 Q	PARKER, W O	8007250598 8007280068 8007080223 8007090271 8007220245	50-369 0 50-269 0 50-269 P 50-269 P 50-269 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8007230210 8007230213 8007230215 8007230217	50-302 0 50-414 0 50-399 0 50-395 0 50-241 0	011090N.# L 011090N.# L 011080N.# L 0WEN.W # 0WBLEY, 0 F	8007080403 8007280371 8007280374 8007020648 8007110341	50-206 S 50-206 S 50-206 S PR TOPREP	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007080201 8007080345 8007110360 8007240357 8007110294	50-270 B 50-369 A 50-269 8 50-369 Q 50-269 P
	1	50-488 G 50-267 G 50-250 G 50-321 G	OWSLEY, O F OWSLEY, O, F OWZARSKI P C PACE, P L PACHAL, W, F	8007110215 8007290733 8007280002 8007220421* 9007280372	TOPREP TOPREP RC8 50-250 S XPORTLIC	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007160657 8007210114 8007210261 8007240469 8007250166	50-369 8 50-369 0 50-413 0 50-369 0 50-269 0
		G G	PAGANG, F G PAGE, R G	8007310193 8007010055 8007010261* 8007010094 8007010189	50-338 F 70-1052 70-1062 70-2885 70-2836	PARKER, W D PARKER, W O PARKER, W O- PARKER, W O PARKER, W O	8007110309 8007280416 8007180321 8007180417 8007290267	50-369 A 50-270 G 50-270 B 50-287 B 50-270 Q
				8007010195* 8007020429 8007020230 8007100117 8007020341	70-2838 70-2609 70-2910 40-8027 70-487	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W. O	8007150575 8007160514 8007210417 8007210459 8007210609	50-269 P 50-413 8 50-269 8 50-269 8 50-287 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUIHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007220477 8007210389 8007280437 8007210425 8007220563	50~269 P 50~369 A 50~269 P 50~270 P 50~269 S	PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R PENDERGRAFT, R	8007080178* 8007280655* 8007090336* 8007150660* 8007150693*	50-368 S 50-368 S 50-368 S 50-368 S 50-368 S	PETERSON, M R	8007140538 8007140596 8007140603 8007150073 8007150078	YPORTLIC YPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W D PARKER, W D PARKER, W D PARKER, W D PARKER, W D	8007310471 8007220424 8007220534 8007220561 8007280501	50-270 Q 50-267 S 50-369 A 50-259 P 50-413 S	PENDERGRAFT, R PENTZ, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L	8007210382* 8007280717* 8007020050 8007210292* 8007230281*	50-368 R CONTRACT 50-295 Q 50-373 Q 50-373 Q	PETERSON, M R	8007170534* 8007110218 8007110226 8007110271 8007210083*	SECY XPORTLIC XPORTLIC XPORTLIC SECY
PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	8007220365 8007300459 8007280427 8007280544 8007290635	50-347 A 50-367 A 50-270 P 50-267 P 50-287 S	PEOPLES, D L	8007020388 8007110206* 8007020074 8007240298* 8007100004	PR 50-10 Q 50-249 Q 50-249 Q 50-10 Q	PETERSON, M R PETERSON, M R PETERSON, N R PETERSON, M R PETERSON, M R	8007110241 8007140711 8007150001 8007150003 8007150008	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARKER, W O PARKER, W O PARKER, W O PARMENTER, F PARRIS, H O	8007290824 8007300355 8007310379 8007160547 8007240455	50-270 8 50-369 8 50-269 P 50-445 M 50-259 8	PEOPLES, D L	8007100343 8007140235 8007280688* 8007010347 8007230187	PRM PRM 50-373 Q 50-10 F PR	PETERSON, M R	8007150012 8007150062 8007150063 8007140577 8007140579	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARRIS,H Q PARROTT,M W PARROTT,M W PARRY,S J S PARSONS,R	8007270651 8007280170* 8007300018 8007100334* 8007110506	50-327 P COMMIBBION PR FOIA 50-320 P	PEOPLES, D L	8007250641 8007250650 8007300469 8007310533* 8007150529	50-10 0 50-10 0 PR 50-373 0 50-373 A	PETERSON, M R	8007140584 8007220114* 8007240042 8007170077 8007170080	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARTLOW, J Q PARTLOW, J Q PARTLOW, J Q, PARTLOW, J Q, PARTLOW, J Q,	8007100081* 8007010221 8007170632 8007210109 8007250673	70-143 70-143 70-135 70-364 70-1113	PEOPLES, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L PEOPLES, D L	8007240351* 8007250638 8007280074 8007310357 8007250467	50-456 Q 50-10 Q 50-254 Q 50-254 Q 50-373 Q	PETERSON, M R	8007240046 8007240052 8007280517 8007310199 8007240373	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PARTLOW, J Q PARTLOW, J Q PABEMAN, N A PABTERNAK, R J, PASTERNAK, R J	8007250053 8007230712 8007310430* 8007010164 8007180128	70-27 70-364 50-286 S 50-333 Q 50-333 Q	PEOPLEB, D L PERANICH, M W PERLMAN, J PERLMAN, J PERLMAN, J	8007220518 8007270030 8007070418* 8007100112* 8007300587*	50-373 A 0A999 CONTRACT CONTRACT 50-390 A	PETERSON, M R	8007240409 8007240418 8007240421 8007250714 8007280525	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J PASTERNAK,R J	8007010484 8007010511 8007010481 8007250669 8007090192	50-333	PERLMAN, J PERLMAN, J PERNY, C D PERRIGO, L D PERROTTI, D J	8007280236* 8007300590* 8007010125* 8007290246 8007110276*	TOATHOO TOATHOO CA1-OT EB BBA D 15E-OB	PETERSON, M R	8007280535 8007280569 8007240362 8007240370 8007240379	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PABTERNAK,R J PABTERNAK,R J PABTERNAK,R J PABTERNAK,R J PABTERNAK,R J	8007210526 8007140368 8007140383 8007250290 8007150707	50-333	PERROTTI.D J PERRY,J C PERRY,J C PERRY,J C PERSON,L	8007210093* 8007080420* 8007150826* 8007280553* 8007230576	70-1151 50-344 8 50-344 8 50-344 8 40-6622	PETERSON, M R	8007240410 8007250563 8007280287 8007280293 8007230719	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PASTERNAK, R J PASTERNAK, R J PASTERNAK, R, J PASTERNAK, R J PATE, R J	8007310474 8007280515 8007280610 8007280662 8007020191*	50-333 0 50-333 6 50-333 8 50-333 8 50-341 0	PETERSON, R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8007070099 8007010170 8007020020 8007020057 8007020238	40-1162 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8007230723 8007250041 8007250030 8007250033 8007280117	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
PATE, R J PATEL, B R PATON, W D PATON, W D, PATON, W D	8007300318* 8007220334* 8007010333 8007090055 8007150697	50-361 0 TOPREP 50-329 0 50-329 0 50-329 H	PETERSON, M R	8007020344 8007020348 8007020351 8007030236 8007010014	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETRICK, N A	8005090053 8007010142 8007100441 8007020378 8007070325	50-462 S 50-462 Q 50-462 Q 50-462 Q 50-462 S
PATON, W. D PATON, W. D PATON, W. D PATON, W. D PATON, W. D	8007170226 8007170232 8007170369 8007170385 8007180242	50-327 0 50-327 0 50-556 0 50-327 0 50-327 0	PETERBON: M R PETERBON: M R. PETERBON: M R PETERBON: M R PETERBON: M R	8007020274 8007020263 8007020425 8007020289 8007020277	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PETRICK,N A PETRICK,N A PETRICK,N A PFAFF,S J PHILBRICK,S S	8007310302* 8007290590 8007300511 8007230020 8007180609	50-482 S 50-482 S 50-482 A 40-6659 50-70 0
PATTERBON, J D PATTERBON, J D PATTERBON, J D PATTERBON, J P PATTERBON, J P	8007020404 8007020413* 8007100355 8007110518* 8007140682*	PR PR PRM 70-925 70-1193	PETERSON, M R PETERSON, A F PETERSON, D S PETERSON, M R, PETERSON, M R	8007070038 8007070279 8007150159 8007020373 8007030340	XPORTLIC 50-250 G REGGD XPORTLIC XPORTLIC	PHILLIPS, H S PHILLIPS, D L PHILLIPS, H S PHILLIPS, L E	8007010212* 8007100075 8007080302* 8007230292* 8007020724	50-498 G TOPREP 50-298 S 50-498 G TOPREP
PATTERBON, J P PATTON, R M PATTON, R. M. PATTON, R M PATTON, R M PATTON, R M	8007290875# 8007150095 8007220102# 8007150103 8007220093	50-254 Q PR PR PR PR PR	PETERSON, M R PETERSON, M R, PETERSON, M R, PETERSON, M R PETERSON, M R	8007070007 8007070025 8007070047 8007070111 8007070425	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILLIPS, L E PHILLIPS, J PHILPOTT, F T PHILPOTT, F T PHILPOTT, F T	8007160814* 8007230508 8007070323* 8007080207* 8007110362*	REGOD 50-275 G 50-269 B 50-270 B 50-269 S
PAULBON, W A PAULBON, W A PAXTON, H C PECK, C, C PECK, H.	8007140524 8007310519 8007290789 8007100003* 8007020457	50-219 P 50-219 P 50-344 0 50-320 G PR	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8007090109 8007100027 8007110252 8007100341 8007110029	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILPOTT, F T PHILPOTT, F T PHILPOTT, F T PHILPOTT, F T PHILPOTT, F T	8007180326* 8007210421* 8007210470* 8007210617* 8007220427*	50-270 6 50-249 5 50-249 8 50-287 6 50-287 8
PEDERSEN, K PEDERSEN, K PEERY, W W PEERY, W W PEERY, W W	8007310247* 8007310250* 8007010304* 8007010291* 8007290401*	FOIA FOIA 50-219 Q 50-334 Q 50-259 Q	PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R PETERSON, M R	8007110213 8007110491 8007140283 8007140288* 8007140567	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PHILPOTT.F T PIACSEK.B E PIACSEK.B E PICKARD,W C PIELAGE,H W	8007290640# 8007250012# 8007240258# 8007070052 8007240375	50-287 8 40-4337 40-4337 CONTRACT PR
PELTIER, 1 A. PENDERORAFT, R PENDERORAFT, R PENDERORAFT, R PENDERORAFT, R	8007280123 8007010535* 8007010441* 8007010440* 8007080166*	50-358 A 50-348 S 50-348 S 50-348 S 50-348 S	PETERSON, M R PETERSON, M R, PETERSON, M R PETERSON, M R PETERSON, M R	8007210124 8007140253 8007140246 8007140274* 8007140293	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PIERCE, D A PIERBON, G K PIGGIT, D R PIGGIT, D R PIGGIT, D R	8007150490 8007210169 8007140034* 8007140034* 8007300359	50-280 J 40-4492 50-341 0 50-361 0 50-361 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
PILANT, J M	8007030199	50~278 Q	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8007160076	QA999	REID.R W	8007100111	50-302 P
PILANT, J M	8007100014	50~278 Q		8007160177	QA999	REID.R W	8007100115*	50-302 P
PILANT, J M	8007210152	50~278 Q		8007290378*	QA999	REID.R W	8007100121*	50-302 P
PILANT, J M	8007160440	50~278 P		8007160393	QA999	REID.R W	8007020488	50-321 F
PILANT, J M	8007280452	50~278 P		8007250582	QA999	REID.R W	8007140123	50-289 P
PIRTLE.G L	8007010578*	70-1308	POTAPOVS, U	8007230155	0A777	REID, R W	8007020438	50-277 P
PIRTLE.G L	8007150096*	70-2609	POTAPOVS, U	8007220136	QA777	Reid, R W	8007070035	50-269 P
PIZZICA,P A	8007240459	NUREO	POTAPOVS, U	8007220182	QA779	Reid, R W	8007170054	50-278 P
PLANJE,T J	6007220122	50-123 D	POTAPOVS, U	8007300173	QA777	Reid, R W	8007170457	50-346 P
PLANT.R L	8007070263	50-10 D	POTAPOVS, U	8007290338	QA777	Reid, R W	8007170461*	50-346 P
PLASKON,R E	8007010046	50-514 Q	POTAPOVS.U	8007300308	QAYYY	REID, R W	8007170477*	50-346 P
PLASKON,R E	8007210515	50-516 Q	POTTER.J P	8007010304*	50-217 Q	REID, R W	8007180115	50-366 P
PLATO,P	8007230223	RES	POTTER.J P	8007010291*	50-334 Q	REID, R W	8007180134*	50-366 P
PLATO,P	8007160280	RES	POTTER.J P	8007150471*	50-280 Q	REID, R W	8007180138*	50-366 P
PLATO,P	8007020659	PR	POTTHOFF.F H	8007180276*	50-465 Q	REID, R W	8007210329	50-346 P
PLATO,P PLATO,P PLEASANT,J C PLEASET,M G PLEASET,M S	8007110543 8007280338 8007090371 8005150676 8007160691	ORG CONTRACT NUREO ACRB PROJ	POWERS, D PRATT, C M PRATT, C M PRATT, C M PREISTER, D J	8007030171 8007230242 8007220140 8007270522 8007020577	PR PR 50-247 0 50-247 0 50-498 M	REID,R W REID,R W REID,R W REID,R W REID,R W	8007210333* 8007210340* 8007180125 8007180133* 8007180149*	50-346 P 50-346 P 50-346 P 50-346 P
PLESSET, M 8 PLESSET, M 8 PLESSET, M 8 PLESSET, M 8	8006160059 8007010359 8007210248 8007210531 8007210354	ACRS ACRS 50-327 0 50-327 0 ACRS	PRICE, D S PRITCHARD, G C PROOM, B C PROOM, B C PURCELL, J F	8007150511* 8007100083 8007100134 8007210442 8007280141	50-302 Q PR PRM MISC 50-367 R	REID.R W REID.R W REID.R W REID.R W REID.R W	8007180484 8007280130 8007180154 8007180457 8007220320	50-321 P 50-289 G 50-289 H 50-289 H
PLEBGET, N S POCHAL, W F POCHAL, W F POCHAL, W F POINDEXTER, C H	8007210523 8007010102 8007020458 8007070041 8007230175	ACRS XPORTLIC XPORTLIC XPORTLIC PR	PUSCHEL,M A GUATTROCCHI,J GUENNOI,S M GUICK,D R RACE,M A	8007310498 8007110017* 8007110434* 8007240377* 8007080039	FOIA 50-320 J 50-346 8 50-367 Q 50-327 0	REID.R W REID.R W REID.R W REID.R W REID.R W	8007230344 8007240354 8007240371 8007240392 8007240398	50-287 H 50-287 H 50-287 H 50-287 H
POIRIER, M R POIRIER, M R POLK, P J POLLARD, R POLLARD, R B	800/150449 8007150449 8007280255* 8007290012* 8007080050*	50-445 M 50-445 M 50-353 P SECY 50-287 O	RADOBEVIC, J R RAE, J B RAGER, M RAGER, M RAGER, M	8007030208* 8007140040* 8007030217* 8007030235* 8007030241*	50-285 P PR 50-331 6 50-331 6 50-331 8	REID.R W REID.R W REID.R W REID.R W REID.R W	8007240404 8007240412 8007240416 8007240419 8007240423	50-289 H 50-269 H 50-289 H 50-289 H
POLLARD, R D	8007270803*	ORG	RAGER, M	8007110419*	50-331 S	REID.R W	8007240428	50-289 H
POMERCY, D L	8007010244*	FDIA	RAGER, M	8007110482*	50-331 S	REID.R W	8007240238	50-277 P
POND, O D	8007020556	PR	RANDALL, M G	8007100416	REGOD	REID.R W	8007240242*	50-277 P
POOLE, D C	8007240382	50-302 0	RANDALL, J D	8007270468	50-128 R	REID.R W	8007240251*	50-277 P
POPEO, D J	8007100120	PRN	RANDGLFH, M L	8007020356	RES	REID.R W	8007280107	50-346 F
PORTER, W L PORTER, W L POTAPOVS, U POTAPOVS, U	8007240359	PR	RANDOLPH, K L	8007140044	RE8	REID.R W	8007290874	50-302 8
	8007030183	50-413 A	RANSOHOFF, J A	8007230354#	71-121	REID.R W	8007310340	50-287 F
	8007210474	50-413 A	RAPHAEL, D	8007280672#	50-409 Q	REIDHAAR.D L	8007090197	50-142 Q
	8007310195*	GA999	RASIN, W. H	8007140010#	50-369 Q	REIDLINGER.B A	8007140657*	40-2740
	8007310188*	GA999	RATHBUN, D J	8007310494	40-299	REIDLINGER.B A	8007140663*	40-2940
POTAPOVS, U	8007140082*	0A999	RATHBUN, D J	8007300279	40-299	REIL, K O	8007290152	NUREO
POTAPOVS, U	8007310176*	QA799	RATHBUN, D J	8007300288	40-299	REIS, E J	8007010143	50-376 0
POTAPOVS, U	8007010154*	QA999	RATHKOPF, C	8007180464*	50-339 H	REIS, E J	8007030240	50-309 0
POTAPOVS, U	8007300192*	QA999	RAUNER, L M	8007090377	FOIA	REIST, S D	8007080054	50-329 0
POTAPOVS, U	8007250075*	QA999	RAUBCH, J K	8007100432*	50-413 O	REIZEN, M S	8007290065*	State Prog
POTAPOVS. U	8007280085	0A999	RAUSCH, J K	9007250607*	50-369 Q	REKEMEYER,P C	8007220025	WASTE MOT
POTAPOVS. U	8907270481*	QA999	RAVENBCROFT, U	9007310506*	FOIA	REKITO,W A	8007220060*	50-219 G
POTAPOVS. U	8007140063*	QA999	RAYHOND, W J	8007070373*	50-271 Q	REKITO,W.A	8007310131*	50-272 G
POTAPOVS. U	8007160133	QA999	RAYHOND, W J	8007020540	50-271 S	REMLEY,M E	8007230588*	70-25
POTAPOVS. U	8007010147*	QA999	REBELDWBKI, T	8007250332*	50-286 Q	REMPLE,L	8007210158	WASTE MOT
POTAPOVS, U	8007140039*	04979	REBELOWSKI, T	8007290058	50-286 6	RENBEROER, D. L.	8007230007	50-508 0:
POTAPOVS, U	8007160115*	94979	RECORD, D, J	8007010532*	50-327 8		8007250354	50-397 0:
POTAPOVS, U	8007160193*	94949	RECORD, D J	8007150488*	90-327 8		8007270444	50-460 0:
POTAPOVS, U	8007010034*	94949	REDDOCH, T W	8007140610	NUREO		8007270405	50-509 0:
POTAPOVS, U	8007160404*	94949	REDMOND, R F	8007010383	50-150 8		8007230003	50-397 0:
POTAPOVS, U	8007160150	0A999	REED. B. R	8007010555*	50-320 P	RENBERGER, D. L.	8007230623*	50-397 G
POTAPOVS, U	8007250184	0A999	REED. C	8007110462*	MASTE MOT		8007300279	50-460 G
POTAPOVS, U	8007100333*	0A999	REED. C	8007180010*	50-10 Q		8007300306	50-508 G
POTAPOVS, U	8007160161	0A999	REED. C	8007080248	TOPREP		8007300544	50-397 G
POTAPOVS, U	8007250589*	0A999	REED. C	8007070345	50-237 P		8007010002	50-397 A
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	6007210257 8007210269 8007220145* 8007210536 8007010139	QA999 QA999 QA999 QA999 QA999	REED, C REEDER, D REEVES, E A REEVES, R W	6007220352 8007220482 8007150409 8007010585* 8007020412	TOPREP TOPREP RES 50-202 P PR	RENBERGER, D L RENBERGER, D L RENBERGER, D L RENBERGER, D L RENBERGER, D L	8007160487 8007130680 8007290518 8007310171 8007180329	NUREQ 50-397 A 50-460 0 50-397 Q 50-508 Q
POTAPOVS, U	8007220196*	0A999	REGAN, W H	8007070031*	50-514 D	RENBERGER.D L RENBERGER.D L RENBERGER.D L RENBERGER.D L RENBERGER.D L	8007250391	50-397 A
POTAPOVS, U	8007300310	0A999	REGAN, W H	8007020684	50-498 H		8007310409	50-397 A
POTAPOVS, U	8007300314*	QA999	REHM, T A	8007020023	COMMISSION		8007210392	50-397 A
POTAPOVS, U	8007100326	QA999	REHM, T A	8007110018	COMMISSION		8007250544	50-460 A
POTAPOVS, U	8007290327	QA999	REHM, T A	8007140516	COMMISSION		8007270704	50-397 8
POTAPOVS, U	8007290307	QA999	REHM, T A	8007090122	COMMISSION	RENBERGER, D L	8007300344	50-50B F
POTAPOVS, U	8007290474	QA999	REHM, T A.	8007180544	COMMISSION	RENFRO, W	8007110080	50-466 0
POTAPOVS, U	8007250052	QA999	REHM, T A	8007240209	COMMISSION	RENTFRO, W	8007220552	50-466 0
POTAPOVS, U	8007310174	QA999	REHM, T A	8007300088	COMMISSION	REQUA, O	8007110123	50-309 P
POTAPOVS, U	8007140057	QA999	REID, R W	8005270617	50-302 P	REQUA, O	8007140465	50-309 P
POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U	8007290856 8007300182* 8007140039 8007290862* 8007010015	ህሕናሃዋ ባለማየዋ ባለዓየም ዐልዓየዋ ዐልዓየዋ	REID.R W REID.R W REID.R W REID.R W	8007010575 8007020019 8007160429 8007160434* 8007160453*	50-312 P 50-289 P 50-269 P 90-269 P 90-269 P	REGUA, O REVELEY, W T REVELEY, W T REVELEY, W T REVELEY, W T	8007070388 8007090306 8007090306 8007170384 8007170384	50-307 F 50-322 0 50-322 0 50-322 0 50-322 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REVELEY, W T	8007220444	MIBC	ROONEY, M A	8007140038	70-1308	RYAN.R G	8007150044	State Prog
REVES, L A	8007210327*	50-346 0		8007220138	70-1308	RYAN.R G	8007170234	State Prog
REVES, L A	8007300606*	50-346 0		8007220147	70-1308	RYAN.M T	8007280095	RES
REVNOLDS, S D	8007300225*	50-334 0		8007220168	70-1308	RYAN.R G	8007180558	State Prog
REVNOLDS, S D	8007280246*	50-354 0		8007220170	70-1308	RYAN.R G	8007170254	State Prog
REYNOLDS, R S REYNOLDS, R S REYNOLDS, R S REYNOLDS, R S	8007300321* 8007010482 8007030246 8007030246 8007180437	50~354	ROONEY, M A ROONEY, M A ROONEY, M A ROONEY, M A ROOT, L D	8007220138 8007220147 8007220168 8007220170 8007020719	70-1308 70-1308 70-1308 70-1308 50-331 Q	RYAN.R O RYAN.R G SABOL.A R SAHA.P SAIKI.T	8007250524 8007250301 8007210341* 8007180245 8007100281	State Prog State Prog 50~387 F RES XPORTLIC
REYNOLDS, R H REYNOLDS, R H REYNOLDS, R H REYNOLDS, R H	9007180437 9007270800* 8007270827* 8007250416* 8007250472*	50~445 0 50~327 5 50~327 9 50~327 9 50~327 5	RODT/L D RODT/L D RODT/L D RODT/L D RODT/L D	8007010453 8007070272 8007070142 8007070252 8007140259	50-331 P 50-331 Q 50-331 P 50-331 P 50-331 G	SAIKI,T SALTZMAN,J SALTZMAN,J BALTZMAN,J SALTZMAN,J	8007110275 8007110023× 8007110022× 8007110024± 8007110026×	XPORTLIC 70-1333 70-1333 70-1333 50-289 J
REYNDLDS, W B REYNDLDS, W B REYNDLDS, N B REYNDLDS, N S	8007270533 8007270533 8007270473* 8007310328 8007310328	50-346 M 50-346 H 50-327 B 50-445 Q 50-445 Q	ROOTIL D ROOTIL D ROOTIL D ROOTIL D	8007160624 8007140434 8007140366 8007250675 8007250677	50-331 P 50-331 P 50-331 P 50-331 Q 50-331 Q	SALTZMAN, J SALTZMAN, J SALTZMAN, J SALTZMAN, J SALTZMAN, J	8007110030* 8007110037* 8007110040* 8007110032* 8007140251	50-287 J 50-320 J 50-320 J 50-320 J 50-346 M
RHOADS, O G	8007210355*	50-387 Q	ROOT.L D	8007170563	50-331 G	SALTZMAN, J	8007140256	50-346 M
RHODE, G K	8007080337	50-410 A	ROOT.L D	8007220494	50-331 G	SALZBERG, H	8007220257	40-299
RHYNE, G A	8007140488*	50-269 Q	ROOT.L D	8007220544	50-331 G	SAMPLES, M D	8007160629	50-445 M
RICE, W M	8007270441	50-498 B	ROOT.L D	8007280490	50-331 P	SAMPLES, M D	8007160629	50-445 M
RICHARDS, J R	8007080269	PR	ROOT.L D	8007280377	50-331 P	SANDERS, C I	8007070406	PR
RIDDLE, M W	8007210414	50-317 E	ROSAVER, P J	8007020044	71-5	SANDVIK,R M	8007300364	50~344 H
RIGOUT, E F	8007240391	PT21	ROSENTHAL, A J	8007280205*	50-10 D	SANDVIK,R M	8007300372	50-522 0
RIEDEL, J T	8007240409	NUREO	ROSENFIELD, A R	8007230201	Nureo	SANGER,H S	8007100047	PR
RIEGER, S N	8007010432	40-8726	ROSE, D F	8007010145*	Fola	SANGER,H S	8007100050*	PR
RIEGER, S N	8007280702	40-8728	ROSE, D F	8007010152*	Fola	SANTMAN,L D	8007140521*	CONTRACT
RILEY, J L	8007030034	50-349 0	ROSS, D F	8007010204*	FOIA	SARSOUR, B	8007140322*	50~344 R
RILEY, J L	8007030040#	50-349 0	ROSS, D F	8007010178*	FDIA	SASSANI, A	8007310069*	50-277 G
RILEY, R G	8007310210	NURE0	ROSS, D A	8007180451*	50-219 Q	SASTRE, C	8007190240	RES
RIPLEY, W I	8007180140#	50-289 H	ROSS, D A	8007180587	50-219 G	SAVAR, T O	8007010244*	FOIA
RISCHLING, J L,	8007180597#	90-315 B	ROSS, D M	8007240090	71-5407	SAVNDERS, G A	8007020279	40~8693
RIBCHLING, J L	8007150695#	50-316 S	ROSE, D A	8007070265*	50-219 8	BAUTER, O	8007140297*	FOIA
RITEHER, J A	8007080010	50-443 I	ROSE, D A	8007110373*	50-219 8	BAUTER, O	8007100327	FOIA
RITTE, P H	8007210455	50-445 M	ROSE, D A	8007110383*	50-219 8	BAVAGE, M R	8007090408	REGOD
RIZZO, R R	8007100312#	CONTRACT	ROSE, D A	8007250170	50-219 0	BAGYER, R O	8007280067*	PR
RIZZO, P G	8007240153#	50-318 S	ROSE, D F	8007160392	50-219 A	BAGYER, H B	8007280536*	50-329 H
ROBERTS, U J	8007070162*	50-320 H	R099, D A	8007220363	90-219 R	SAWYER, E. E.	8007180461*	50-287 H
ROBERTS, K	8007180101*	50-273 O	R082T0C2Y, Z R	8007030359	TOPREP	BCARAND, R. A.	8007300560*	40-8727
ROBERTS, K	8007280262*	50-273 O	R0TH, J	8007150163*	70-364	SCARAND, R. A.	8007180074	40-8478
ROBERTS, M J	8007180016	RES	R0TH, J	8007020121*	70-1100	SCARAND, R. A.	8007100431	Waste Mgt
ROBERTS, J P	8007180510	70-2423	R0TH, J	8007140608*	27-48	BCARAND, R. A.	8007100446*	40-8502
ROBERTS, J P	8007230706	70-2623	ROTH, J.	8007230212	50-245 8	SCARANO, R A	8007210285	40-8502
ROBERTS, F P	8007220019	NUREO	ROTH, J	8007270003*	70-1100	SCARANO, R A	8007010261	40-1162
ROBINSON, R K	8007020701	PR	ROTH, A. J	8007230798	50-389 ((SCARANO, R A	8007010559	40-1162
ROBINSON, M J	8007140454	PR	ROTHBERG, O	8007100140	50-339 P	SCARANO, R A	8007100445	40-8502
ROBINSON, F	8007010539*	50-327 8	ROTHFLEISCH, J	8007210243	40-8380	SCARANO, R A	8007240103	40-8584
ROBINSON, R K RODGERS, J RODRIGUEZ, R J ROECKLEIN, A K ROGERS, R F	8007280009 8007140405 8007150588 8007030373 8007240292*	PR PR 50-312 R NUREO 50-321 Q	ROTHFLEISCH, J ROTHFLEISCH, J ROTHFLEISCH, J ROTHKOPF, C L	8007170583 8007230161 8007230279 8007300042 8007280140*	40-8380 40-8714 40-8200 40-8380 50-289 Q	BCARAND, R A SCARAND, R A BCARAND, R A SCARAND, R A SCARAND, R A	9007020446 9007180131 9007240079 9007020092 9007170436*	40-1162 40-6622 40-1341 WASTE MGT 40-8745
RDOERB, R F	8007100066*	50-321 Q	ROTHSCHILD, H U	8007220015	70-1308	SCARAND, R A	9007300062*	40-8745
RDOERB, W L	8007020128	WABTE HGT	ROTHSCHILD, H U	8007220009	70-1308		9007140600	40-8502
RDOERB, W L	8007030190	PR	ROTHSCHILD, H U	8007220011*	70-1308		9007170433	40-8745
RDOERB, W F	8007010572	XPORTLIC	ROUSE, L C	8007020423*	50-268 P		9007180086	40-8380
RDOERB, L	8007250010*	COMMISSION	ROUSE, L C	8007310542	70-25		9007010270	Waste Mgt
ROGERB, W. F	8007110528	XPORTLIC	ROUSE, L C	8007210310	70-1257	BCARANDIR A	9007100019	40-8481
ROGERB, C. S	8007310153	50-556 G	ROUSE, L C	8007230288	70-1143	SCARANDIR A	9007100450	40-8584
ROGERB, W. H	8007110443*	50-321 B	ROY, R	8007140449*	PR	BCARANDIR A	9007310543	40-6459
ROTSMAN, A. Z	8007270003*	SECY	ROY, R	8007140449*	PR	BCARANDIR A	9007310544	40-8714
ROTSMAN, A. Z	8007270012*	SECY	ROYTEX, C	8007230276*	50-295 0	SCARANDIR A	9007210054	40-8502
ROMANO,F R	8007880195*	50-320 H	RUDOLPH.J P	8007280622*	90-346 9	SCARANDIR A	#007230071	40-8502
ROMAN,T W	8007170361*	50-220 R	RUEKDERO.D	8007220393	50-10 D	SCARANDIR A	#007230077	40-8502
ROMIC,B	8007150180	FR	RUHLMAN.W A	8007220088*	50-335 0	SCARANDIR A	#007230082	40-8502
ROMINE,D R	8007010419*	50-327 B	RUITER.O H	8007160548*	50-305 R	SCARANDIR A	#007230274	40-8502
ROMINE,D	8007010541*	50-327 S	RUDCCHZO.J P	8007070134*	CONTRACT	SCARANDIR A	#007230318	40-8502
ROMINE, PF	8007010515*	50-327 8	RUSCHE, B C	8007020331*	COMMISSION	SCARANO,R A	8007250642	40-8502
ROMINE, D	8007010522*	50-327 8	RUSCHE, B C	8007020334*	COMMISSION	SCARANO,R A	8007230171	40-2259
ROMINE, D	8007080288*	50-327 9	RUSSELL, L B	8007240132	50-318 8	SCARANO,R A	8007230145	WASTE MGT
ROMINE, D,	8007080291*	50-327 9	RUSSELL, L B	8007280451	50-317 8	SCARANO,R A	8007230050	40-4492
ROMINE, D	8007220474*	50-327 8	RUSSELL, L B	8007280664	50-317 8	SCARANO,R A	8007230294	40-8200
ROXINE, D	8007270770*	50-327 8	RUBBELL, L B	8007300351	50-318 8	SCARANO, R A	9007230711	40-8728
ROMINE, D	8007270715*	50-327 8	RUBTLING, D H	8007140692	50-274 F	SCARANO, R A	8007290228	WASTE MOT
ROMNEY, N	8007100140	50-339 P	RYAN, R O	8007020099	State Prog	SCARANO, R A	9007180303	40-8452
ROOD, H	8007070421	50-361 A	RYAN, R H	8007090413	RECOD	SCARANO, R A	9007240300	40-8585
ROOD, H	8007020208	50-361 A	RYAN, R O	8007020690	State Prog	SCARANO, R A	9007300042	40-8380
ROOD, H	8007210053	30-206 P	RYAN.R O RYAN.R O RYAN.R O RYAN.R O RYAN.R O	8007020130	DRG	SCARANG, R. A	8007230063	40~8502
ROONEY, V L	8007100049	50-133 P		8007020443*	ORG	SCHADE, A. R	8007250440	PROJ
ROONEY, M A	8007020608	70-1308		8007070132	ORG	SCHAEFFER, M. R	8007280397	XPORTLIC
ROONEY, V L	8007140528	50-271 P		8007110375*	COMMISSION	SCHAEFFER, M. R	8007280403*	XPORTLIC
ROONEY, M A	8007140038	70-1308		8007020766	State Prog	SCHAFFSTALL, R	8007100420*	50-10 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHGR	ACCESSION NUMBER	BUBJECT
SCHAUB, J B	8007280360	XPORTLIC	SCHWENCER, A	8007250004	50-352 H	SEYFRITAK V	8007010044	50-247 Q
SCHENDEL, K R	8007010214	40-8585	SCHWENCER, A	8007250475	50-352 H	SEYFRITAK V	8007010048	50-298 Q
SCHERER, A E	8007110243	TOPREP	SCHWENCER, A	8007250022	50-327 D	SEYFRITAK V	8007010053	50-285 Q
SCHERER, A E	8007030343	PR	SCHWENCER, A	8007250322	50-416 A	SEYFRITAK V	8007020675	50-498 A
SCHERER, A E	8007100210	TOPREP	SCHWENCER, A	8007250322	50-311 P	SEYFRITAK V	8007220094	50-313 Q
SCHERER.A E SCHERER.A E SCHERER.A E SCHERER.A E SCHMIDT.E W	8007070351 8007080274 8007100219 8007140491 8007310183	NUREO TOPREP TOPREP NUREO RES	C M'11038 C M'11038 N C'11038 N L'11038	8007140439* 8007170374 8007140587 8007180387 8007230527	PA 50-466 G 70-1308 70-1308 27-37	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007220078 8007220104 8007220107 8007220113 8007220118	50-498 Q 50-458 Q 50-482 Q 50-382 Q 50-556 Q
SCHMIDT.E W	800731 0181	RES	SCOTT, H J	8007250442	27-37	SEYFRIT, K V	8007220120	50-290 G
SCHMIDT.A D	800701 0483	70~335 8	SCOTT, J N	8007300116	50-466 0		8007220124	50-285 G
SCHMIDT.A D	8007080284	50~335 6	SEAL, M M	8007020076*	50-443 H		8007220126	50-267 G
SCHMIDT.A D	8007140382	50~335 8	SEAL, M M	8007140108*	50-437 H		8007220128	50-445 G
SCHMIDT.A D	8007140364	50~335 8	SEAL, M M	8007140028	50-367 H		8007020318	50-382 A
SCHMIDT, A D SCHMIDT, A D SCHMIDT, A D SCHMIDT, E N SCHMIDT, A D	8007150527 8007240174 8007150532 8007280004 8007220419	50~335 5 50~250 ft 50~335 S RES 50~250 S	BEIDLE: W C BEIDLE: W C BEIDLE: W C	8007210137 8007150064 8007180490 8007010203 8007110061	50-458	BEYFRIT, K V BEYFRIT, K V BEYFRIT, K V SEYFRIT, K V	8007160321 8007160324 8007160327 8007160331 8007160334	50-313
SCHNEIDER: F U SCHNEIDER: F U SCHNEIDER: F U SCHNEIDER: F U SCHNEIDER: F U	8007170570 8007170642 8007100379 8007030249 8007210608	50~272	BEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8007070089 8007100342 8007110187 8007110229 8007140436	50-482 Q 50-498 Q 50-482 Q 50-445 Q 50-382 Q	SEYFRIT, K V BEYFRIT, K V BEYFRIT, K V 'SEYFRIT, K V SEYFRIT, K V	8007140404 8007140410 8007290057 8007290059 8007290066	50-458 Q 50-278 Q 50-458 Q 50-478 Q 50-482 Q
SCHNEIDER, F 14 SCHNEIDER, F 14 SCHNEIDER, F 14 SCHNEIDER, F 14 SCHOLL, R F	8007210268 8007150631 8007210552 8007140429 8007160463*	50~272 0 50~272 0 50~272 0 50~272 F 50~10 P	SEIDLE, W C SEIDLE, W C SEIDLE, W C SEIDLE, W C	8007240333 8007180567 8007280724 8007140497 8007230278	50-490 G 50-445 G 50-482 G 50-445 G 50-478 G	SEYFRIT, K V SCYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007290068 8007290075 8007290077 8007010024 8007280137*	50-382 Q 50-556 Q 50-445 Q 50-313 H 50-498 Q
SCHOLL, R F	8007250035*	50-10 P	SEIDLE.W C	8007280144	50-382 Q	BEYFRIT, K V	8007240031	50-313 Q
SCHOPPMAN, M A	8007010491*	50-335 S	SEIDLE.W C	8007270433	50-382 Q	BEYFRIT, K V	8007240035	50-458 Q
SCHOPPMAN, M A	8007080270*	50-335 S	SEIDLE.W C	8007300371	50-382 Q	SEYFRIT, K V	8007240039	50-498 Q
SCHOPPMAN, M A	8007140387*	50-335 B	SEIDLE.W C	8007270013	50-482 G	SEYFRIT, K V	8007240043	50-482 Q
SCHOPPMAN, M A	8007140372*	50-335 S	SEIFERT.G W	8007250025	COMMIGBION	SEYFRIT, K V	8007240043	50-382 Q
SCHOPPMAN, M A	8007150636*	50-335 6	BEIKEN, B J	8007270254*	50-482 8	BEYFRIT, K V	8007240047	50-285 Q
SCHOPPMAN, M A	8007150536*	50-335 8	BEKULER, B N	8007300337	50-482 A	BEYFRIT, K V	8007240051	50-278 G
SCHROEDER, F	8007010249*	F01A	BEKULER, B N	8007080026	50-367 Q	BEYFRIT, K V	8007240054	50-267 Q
SCHULTZ, G	8007100235	50-367 H	BEKULER, B N	8007160387	70-1308	BEYFRIT, K V	8007240057	50-445 Q
SCHUMACHER, M C	8007310515*	50-295 0	BEKULER, B N	8007180387	70-1308	BEYFRIT, K V	8007280132	50-498 Q
SCHUSTER, M D SCHWARZ, C E ECHWENDIMAN, L SCHWENDIMAN, L SCHWENSFEIR, R	8007230154 8007319234 8007090186* 8007219315* 8007070048	50-312 S NUREO 70-1257 70-1257 70-33	SEKULER, B N SEKULER, B, N SEKULER, G N SELLS, D SENCEHAL, M E	8007230527 8007250442 8007310133 8007180285 8007140011	27-39 27-39 27-39 50-352 A PR	SEYFRIT, K V	8007170469 8007170673 8007170676 8007170690 8007170683	50-450 Q 50-492 Q 50-498 Q 50-382 Q 50-445 Q
SCHWEIKER, R S SCHWEIBNINZ, E SCHWEIBINZ, E R SCHWENSFEIR, R SCHWENCER, A	8007110323* 8007160479* 8007230017* 8007210175* 8007020395	MISC 50-546 G 50-496 G 70-33 50-364 A	SENECHAL, M E SERABIAN, J A SERABIAN, J A SETHNESS, E D. SETLYUR, A V	8007250422 8007220285* 8007230021* 8007110459* 8007220234*	50-282 0 50-317 0 50-277 F HASTE HOT 50-305 P	BEYFRIT, K V BEYFRIT, K V BEYFRIT, K V BEYFRIT, K V	8007230364 8007230369 8007230370 8007230373 8007230376	50-498 q 50-382 q 50-445 q 50-482 q 50-458 q
BCHWENCER, A	8007110033	50-275 E	SEYFRIT, K V	8007210324*	70-197	BEYFRIT, K V	8007150007	50-498 Q
BCHWENCER, A	8007010287	50-364 A		8007240348*	70-1062	BEYFRIT, K V	8007150007*	50-498 Q
BCHWENGER, A	8007010148	50-370 A		8007240492*	0A999	BEYFRIT, K V	8007310324	50-285 Q
BCHWENCER, A	8007070109	50-311 E		8007250316	50-458 Q	BEYFRIT, K V	8007310331	50-313 H
BCHWENCER, A	8007020473	50-364 A		8007250319	50-499 Q	SHALLER, D V	8007090289	50-316 8
SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A	8007020747 8007020086 8007020042 8007020707 8007020722	90-327 P 50-311 P 50-327 P 50-390 A 90-327 P	SEYFRIT.K V SEYFRIT,K V SEYFRIT,K V SEYFRIT,K V SEYFRIT.K V	8007250321 8007250323 8007250328 8007140563 8007140568	50-482 Q 50-382 Q 50-445 Q 50-298 Q 50-458 Q	SHALLER, D V SHALLER, D V SHALLER, D V SHALLER, D V	8007280510 8007150586 8007150684 8007150542 8007150555	50-315 8 50-315 8 50-316 8 50-318 R 50-316 R
BCHWENCER A	B007100272	50-392 H	SEYFRIT, K V	8007240505	50-498 Q	SHALLER, D V	8007150696	50-315 8
BCHWENCER, A	B007110510	50-352 H		8007240507	50-445 Q	SHALLER, D V	8007210537	50-316 8
BCHWENCER, A	B007110576	50-445 F		8007240510	50-382 Q	SHALLER, D V	8007310397	50-315 V
BCHWENCER, A	B007030195	50-327 P		8007240511	50-458 Q	SHANBAKY, M M	8007170547	50-320 8
BCHWENCER, A	B007020673	50-361 A		8007240513	50-462 Q	SHANBAKY, M M	8007170540	50-320 8
SCHWENCER A	8007110526	50-528 H	BEYFRIT, K V	8007020249	50-459 0	BHANBAKY, M M	8007170553	50-320 8
SCHWENCER, A	8007140025	50-352 H	BEYFRIT, K V	8007020253	50-478 0	BHANBAKY, M M	8007170564	50-320 8
SCHWENCER, A	8007140053	50-445 D	BEYFRIT, K V	8007020255	50-445 0	SHANBAKY, M M	8007170557	50-320 8
SCHWENCER, A	8007160451	50-352 A	BEYFRIT, K V	8007020259	50-482 0	BHANBAKY, M M	8007240203	50-320 8
SCHWENCER, A	8007180081	50-329 A	BEYFRIT, K V	8007020261	50-382 0	BHAPAR, H K	8007080036	FOIA
BCHWENCER, A	8007180334	50-395 A	BEYFRIT, K V	8007020243	50-285 0	SHAPAR, H K	8005270154	FOIA
BCHWENCER, A	8007170496	50-327 P	SEYFRIT, K V	8007020248	50-298 0	SHAPAR, H K	8007290002	BECY
BCHWENCER, A	8007170503*	50-327 P	SEYFRIT, K V	8007020269	50-313 0	SHAPAR, H K	8007220268*	40-299
BCHWENCER, A	8007170517*	50-327 P	SEYFRIT, K V	8007020272	50-267 0	SHAPAR, H K	8007160607	50-413 M
BCHWENCER, A	8007180061	50-327 P	SEYFRIT, K V	8007210342	50-313 0	SHEA, J, R	8007310260*	FOIA
SCHWENCER, A	8007180345	50-352 H	SEYFRIT, K V	8007210346	50-382 Q	RHEA, J. R	8007090030*	IOCFR
SCHWENCER, A	8007180595	50-327 P	SEYFRIT, K V	8007210348	50-482 Q	SHEA, J. R	8007090033*	IOCFR
SCHWENCER, A	8007180596*	50-327 P	SEYFRIT, K V	8007210350	50-285 Q	SHEA, J. R	8007250019*	IOCFR
SCHWENCER, A	8007180599*	50-327 P	GEYFRIT, K V	8007210351	50-445 Q	SHEA, J. R	8007020093	XPORTLIC
SCHWENCER, A	8007170542*	50-528 0	SEYFRIT, K V	8007010020	50-382 Q	SHEA, J. R	8007280078	XPORTLIC
Schwencer, a Schwencer, a Schwencer, a Schwencer, a Schwencer, a	8007170538 8007180019 8007230170 8007240312* 8007240081	50-528 0 50-329 A 50-329 H 50-327 P 50-311 P	SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V SEYFRIT, K V	8007010025 8007010026 8007010028 8007010037 8007010040	50-492 Q 50-445 G 50-458 Q 50-478 Q 50-313 Q	BHEA: J. R BHEA: J. R BHEA: J. R BHEA: J. R. BHEA: J. R	8007020123 8007020734 8007140552 8007150050 8007140539	XPORTLIC XPORTLIC SECY SECY BECY

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
BHEA, J R BHEA, J R BHEA, J R BHEA, J R BHEA, J R	8007150069 8007150054 8007280062 8007290044 8007150836	SECY SECY SECY XPORTLIC XPORTLIC	SHREVE.D B SHRIVER.B L SHROEDER.F SHUM.E Y SHUM.E Y	8007020553* 8007210429 8007010241* 8007020514 8007280179	CONTRACT 50-62 F FDIA 70-2909 70-143	SMITH, H SMITH, G H SMITH, G H SMITH, G H	8007020426 8007210167 8007020982 8007230018 8007210090	50-206 + 70-33 50-329 + 50-277 + 40-8681
SHEA, K H SHEA, K H SHEA, J R SHEA, J R	8007020453 8007080021 8007020453 8007280084 8007140583	50-367 G 50-367 G 50-367 G SECY XPURTLIC	T YWBY F318 O E 'BLUNHS O E 'BLUNHS A E 'BLUNHS A E 'BLUNHS	8007030028* 8007150818 8007010542* 8007270540 8007150057	70-1151 70-1151 50-263 S 50-412 R RES	BMITH, R L SMITH, R L SMITH, R L SMITH, F M SMITH, I W	8007070346 8007070247 8007080292 8007140646 8007090220	50-271 · 50-271 · 50-271 · 71-6387 50-287 [
HEA, J R R KEA, J R	8007170244 8007170523 8007210009 8007230557 8007230546#	SECY SECY SECY XPORTLIC XPORTLIC	SIEGEL, B L SIEGEL, B L SIEGEL, B SIEGEL, B L SIEGEL, B L	8007010088* 8007010103* 8007010119* 8007010149* 8007010161*	50-249 P 50-249 P 90-265 P FOIA FOIA	SMITH, PA SMITH, RD SMITH, TH SMITH, RG SMITH, IW	8007280520 8007170660 8007230171 8007310120 8007110324	CONTRACT WASTE MGT 50-213 REGGD 50-269
SHEA, JR SHEA, JR SHEDLOBKY, JT SHEEHAN, DP SHEEHAN, DP	8007220214# 8007250454 8007310345# 8007080007 8007070337	FOIA XPORTLIC 50-245 G 50-320 O 50-320 O	SIEGEL, B L SIEGEL, B L BIEGEL, B L BILBERG, J E SILBERG, J E	8007010165* 8007010168* 8007010173* 8007020689 8007100191*	FOIA FOIA FOIA PR PR	W 1.HTIMS H O.HTIMS H O.HTIMS D C.NOSHTIMS H O.HTIMS	8607220533* 8007230212 8007230216 8007160523* 8007290001	50-289 (50-245 1&E 50-327 70-1100
SHEEHAN, D P BHEEHAN, D P BHEEHAN, D P BHEEHAN, D P BHELDON, K P	8007070353* 8007070365* 8007070371* 8007280613 8007140387	50~320 0 50~320 0 50~320 0 50~320 0 PR	SILBERG, J E SILBERG, J E SILKER, W B SIMONS, C S SIMONS, C S	8007300463 8007300463 8007170311 8007080273 8007080278*	50-282 G 50-282 G NUREO 40-8056 40-8056	SMITH, I W SMITH, R L SMITH, R L SMITH, I W SMITH, I W	8007220085 8007210448 8007250488 8007250446 8007250452*	50~289 C 50~271 } 50~271 , 50~289 G 50~289 G
BHECTEA' M 7 BHECTEA' M 7 BHECTEA' M 7 BHECTEA' M 7	8007140387 8007030031 8007010611* 8007110025 8007010590	PR 40~8647 40~8027 40~2061 40~8647	SIMPSDN, A K SINGER, L SINGER, L SINGER, L N SIMPSDN, A K SIMPSDN, L N SIMPSDN, L N	B007110005 B007070104 B007080041 B007180411 B007220045	PR 50-320 0 50-320 0 50-320 0 RES	SMITH, I W SMITH, I W SMITH, I W SMITH, I W	8007250426 8007250678 8007250739 8007250753 8007250730	50-289 0 50-255 0 50-289 0 50-389 M 50-329 0
SHELLEY, W J. BHELLEY, W J. BHELLEY, W J. BHEPHERD, T A SHEPHERD, T A	8007010407 8007250434 8007230544* 8007280073 8007210183	40-8027 40-8027 70-725 40-8452 40-8452	SINKIN'T V SINKIN'T V SINKIN'T V	8007220524* 8007110001 8007300415 8007310145 8007310145	50-409 P 50-498 Q 50-498 Q 50-498 Q 50-498 Q	SMITH I W BMITH, I W SMITH, R L SMITH, R L SMITH, P D	8007290752 8007290766 8007280661 8007310385 8007240478	50-329 0 50-329 0 50-271 F 50-271 P NUREO
SHEPHERD, T A SHEPLEY, 8 E SHERBONDY, B N SHERMAN, H D SHERMAN, F L	8007210177 8007170103* 8007250374 8007250150 8007220527	40-8452 50-373	BIRI.W E GKARITKA, J GKARUPA.J D GKARUPA.J D GKARUPA.J D	8007220023* 8007100256* 8007310087 8007110237 8007280223	MISC TOPREP XPORTLIC XPORTLIC XPORTLIC	EMOKER,C 5 EMYTH,H P D ENAPP.C ENIEZEK,J H ENOW.B A	8007160474* 8007160402 8007090218 8007020144* 8007150584	50-305 S PR 50-275 H MISC 50-244 R
BHERMAN, F. L. BHERWOOD, Q. O. BHERWOOD, Q. Q. BHERWOOD, Q. Q. BHERWOOD, Q. Q.	8007290445 8007160703* 8007110478* 8007140068* 8007010507	70-33 50-341 A SECY 10CFR TOPREP	SKOROHOD: P M SLABACK, L A SLEAR, D G SLEMMONS, D B SLOAN, D E	8007020463 8007150342 8007160670 8007100112* 8007240353	FOIA REGOD 50-207 P CONTRACT 50-227 S	SNOW B A SNOW B A SNYDER, T K SNYDER, T K SNYDER, T K	8007160637 8007210443 8007300498* 8007300508* 8007300508*	50-244 8 50-244 8 50-237 0 50-237 0 50-237 0
SHEW.D SHEWMAKER.R E SHIELDS.S W SHIELDS.S W SHIELDS.R O	8007160209 8007010046* 8007020031* 8007010096 8007170275	CONTRACT 50~546 H 50~546 G 50~546 A PRI1	SLOBODIEN M J SLUIG, I J SMEDIRA, C SMEDIRA, C SMITH, C N	8007170337* 8007310179* 8007230349 8007230354* 8007100076*	70-1869 GA999 71-121 71-121 70-143	SNYDER, O L SNYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J	8007280188* 8007070151 8007010290 8007110272 8007110280*	50~320 H 50~320 H 50~320 P 50~320 P 50~320 P
SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8007140506 8007210058 8007100227 8007230238 8007230073	50~546 Q 50~546 A 50~546 S 50~546 Q 50~546 Q	SMITH, OH SMITH, OH SMITH, OH SMITH, OH SMITH, RL	8007150190* 8007100002 8007010197* 8009020572 8007020341	70-364 50-320 G 40-6789 I&E PR	SNYDER, B J SNYDER, B J SNYDER, B J BNYDER, B J SNYDER, B J	8007110272* 8007070211 8007180237 8007100193 8007240158	50-320 P 50-320 0 50-320 H 50-320 P 50-320 P
SHIELDS, S W SHIELDS, S W SHIELDS, S W SHIELDS, S W	8007220549 8007280591 8007250397 8007250667 8007240030	50-546 H 50-546 F 50-546 B 50-546 B XPORTLIC	SMITH, OH SMITH, OH SMITH, OH SMITH, OH	80070201 <i>0</i> 6* 8007210295* 8006110736 8007010285 8007010299	70-1100 70-687 27-10 50-334 0 50-219 0	SNYDER, D J SNYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J	8007;80107 8007280579 8007210121 8007230293 8007230298	50-320 H 50-320 0 50-320 H 50-320 H
SHIMA, S SHIMSHAK, R SHINEFLUO, M J, SHISSIAS, J A SHISSIAS, J A	8007240036* 8007080300 8007230524 8007110456 8007030232	XPURTLIC 50-409 P 50-10 D 50-272 P 50-272 R	Smith, oh Smith, oh Smith, oh Smith, oh Smith, oh	8007240057* 8007140604 8007140653 8007210180* 8007010180	XPORTL1C 27-48 40-2940 70-33 40-6789	SNYDER, B J SNYDER, B J SNYDER, B J SNYDER, B J BOHINKI, B M	8007230311 8007270032 8007300006 8007300010 8007080044	50-320 H 50-320 H 50-320 H 50-320 H 50-320 H
SHIVELY, C N SHIVELY, C N SHIVELY, C N SHIVELY, C, N SHIVELY, C, N	8007010414+ 8007080154+ 8007140405+ 8007150650+ 8007240150+	50-368 8 50-368 8 50-368 8 50-313 8 50-313 8	emith, oh emith, rh emith, pa emith, oh emith, pa	8006260362 8007250076* 8007010580 8007210185 8007030068	50-271	SOMINKI, S M SOMINKI, S M SOMINKI, S M SOMINKI, S M	6007140015 6007220021 8007220159 8007300397 8007300404	50-466 0 50-466 0 50-466 0 50-466 0
SHOLLY, S, C SHOLLY, S, C SHOLLY, S, C SHOLLY, S SHOLLY, S	8007020651 8007020648 8007030057 8007110075 8007080007	50-289 0 50-289 0 50-289 0 50-320 0 50-320 0	BMITH,PA BMITH,RH BMITH,RH BMITH,PA BMITH,PA	8007030353 8007280408* 8007020534 8007030349 8007070021	CONTRACT 50-293 Q 50-213 B GONTRACT CONTRACT	BOHINKI, S M BOHINKI, S N BOKOLOWSKI, O BOLBRIO, C W BOHMER, J C	8007300423 8007300424 8007280366* 8007100363 8007240437	50-466 G 50-466 G XPORTLIC NUREG FOIA
SHOLLY, S SHOLLY, S SHOLLY, S SHOLLY, S	8007020454 8007070337 8007070353* 8007070345* 8007070371*	50-320 0 50-320 0 50-320 0 50-320 0 50-320 0	Smith, PA Smith, PA Smith, PA Smith, PA Smith, DR	80070700 <i>6</i> 5 8007100010 8007100011 8007020572 8007180173	CONTRACT CONTRACT CONTRACT CONTRACT REGGD	SONNEBORN, M R EDONG, A L BOUCY, A R SOUDER, J L SOUDER, J L	B007020457 B007280327* B007010404 B007210018 B007230109	50-320 H 70-1319 50-29 1 50-528 H 50-440 H
BHOLLY, B C, BHOLLY, B C BHOLLY, B C, BHON, F, J BHORB, E M	8007140004 8007310138 8007170210 8007220006 8007250630	50-320 T 50-287 0 50-287 0 50-320 0 50-367 0	BMITH, PA SMITH, P.A SMITH, P.A SMITH, PA SMITH, PA	8007140590 8007110559 8007150048 8007150055 8007150060	GUNTRACT CONTRACT GUNTRACT GUNTRACT GUNTRAGT	Souder, J L Soxman, K A Spangenberg, C Spangler, R C Spannaus, H	8007210084 8007290051* 8007230015* 8007150136* 8007140011	50-287 H 50-320 H 70-184 50-298 Q PR

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT Category	
PANNAUS, W PARKB, E 'EIS, T P PELLMAN, G N PENCER, O S	8007250422 8007020335 8007170647 8007250264* 8007230629*	50-282	STELLO, V STELLO, V STELLO, V STENSVAAQ, J M STEPMENSON, B B	8007210280 8007300044 8007220586 8007090048 8007010497	50-293 Q 50-271 Q 50-219 Q PR 50-237 B	SHANSON, D T SHANSON, E R SHANSON, D T SHANSON, D G SHANSON, D T	8007010257 8007140558* 8007020468 8007170618 8007010332	50-522 0 50-346 0 50-70 0 NUREO 50-289 0	•
PENCER, G S PENCER, G S PENCER, G S PENCER, G S PENCER, G S	8007020158* 8007170265 8007170530 8007180014 8007210556*	50-341 0 50-528 0 50-341 0 50-204 0 50-528 0	STEPHENSON, 8 B STEPHENSON, 8 B STEPHENSON, 6 B STEPHENSON, 6 B STEPHENSON, 8 B	8007010544 8007100179 8007100187 8007180333 8007220455	50-237 8 50-237 8 50-237 8 50-10 R 50-249 8	SWANSON, D T SWANSON, D T SWANSON, D T SWART.F E SWARTZ, L L	8007100216 8007230617* 8007310219 8007020309 8007010269	50-269 P 50-289 0 50-289 0 50-247 0 50-289 0	
PENCER.Q S PENCER.Q S PENCER.Q S PENCER.Q S PENCER.W C	8007020131 8007240318 8007240307 8007300313 8007160664	50-361 0 50-206 0 50-344 0 50-361 0 50-281 0	STEPHENSON, D D STEPHENSON, B B STEPHENSON, B B STEPHENS, C R STEPTOE, P P	8007310480 8007220557 8007220577 8007310493 8007300362	50-249	SWARTZ, L L SWARTZ, L L SWARTZ, L L SWARTZ, L L SWARTZ, L L	8007210503* 8007030290 8007030293* 8007030294* 8007030297*	50-289 0 50-289 0 50-289 0 50-289 0	
PENCER, G 8 PENCER, G 8 PENCER, G 8 PENCER, G 8 PENCER, W C	8007210543 8007230618 8007240093* 8007310505 8007110390	50-528 0 50-397 0 50-361 0 50-528 0 50-281 0	STEPTOE, P P BTEPTOE, P P STERNBERG, D IS STERNBERG, D STERNBERG, D	8007150052 8007150052 8007010141* 8007030345 8007170088*	50-155 Q 50-155 Q 50-293 P 50-320 T 50-133 Q	SWARTZ.L L SWARTZ.L L SWARTZ.L L SWARTZ.L L SWARTZ.L L	8007030277* 8007030301* 8007030302* 8007030303* 8007030304*	50-289 C 50-289 C 50-287 C 50-289 C 50-289 C	
PESSARD, R L PESSARD, R L PESSARD, R L PETH, O 'ETH, O	8007070086* 8007170103* 8007230388* 8007220121* 8007070148*	50-10 Q 50-373 Q 50-10 Q 50-599 Q PR	STERNBERG, D M BTERN, W. C BTERNBERG, D M STERNBERG, D M STERNBERG, D M	8007240375* 8007210129 8007300295* 8007310327* 8007300525*	50-275 G XPORTLIC 50-344 G 50-275 G 50-344 G	SWART, F.E. SWARTZ, L.L. SWARTZ, L.L. SWARTZ, L.L. SWARTZ, L.L.	8007090333 8007090212 8007170370 8007220562 8007220564	50-267 P 50-289 0 50-289 0 50-289 0 50-289 0	
'RINGER, D FRINGER, D 'RINGER, D RING, C A FABLE, C R	8006200071* 8006200066 8007020475 8007270628 8007280006	50-488 0 50-488 0 50-488 0 50-266 H 50-311 P	STERN, W. C. STERN, W. C. STEVENBOM, R. L. STEVENB. S. C. STEVENB. S. C.	8007280393 8007310484 8007070175* 8007070375 8007240130	XPORTLIC XPORTLIC 70-1119 50-285 8 50-285 8	SWART,F E SWARTZ,L L SWARTZ,L L SWARTZ,L L SWARTZ,L L	8007280493 8007230500 8007230609 8007230614* 8007250683	50-267 P 50-269 0 50-269 0 50-289 0 50-289 0	
TAGGERS,H O TAHLE,G R AHL,D H IAHL,D M TAIDER,C R	8007250215* 8007210618 8007150431 8007150431 8007100264	CDMMI68ION 50-327 P 50-445 M 50-445 M BECY	STEWART.R C STEWART.K L STIEGLITZ.W O STITT.B D STITT.B D	8007140447* 8007210200 8007150710 8007310009 8007280683	50-382 Q 71-139 50-280 P NUREO NUREO	SHARTZ,L L. SWAYNE,R W SHEARINGEN,J D. SWEARINGEN,J D. SWETLAND,P	8007310315 8007100330* 8007010385* 8007150501* 8007230398*	50-289 0 GA979 50-327 8 50-327 8 50-309 Q	
TAMIRIS, D. TAMPLEY, N.L. TAMPLEY, N.L. ARK.R. M. ARKEY, R. II	8007110497 8006300375 8006300382* 8007090391 8007150629	PR 50-416 F 50-416 F 50-387 A 50-261 R	STOCKS.H S STOCKS.J P STOCKS.J P STOCKS.J P STOCKS.J P	8007020300 8007070015* 8007030368 8007150471* 8007110262*	PR 70-143 70-1201 50-280 Q 50-321 Q	SWITZER, D. C SWYLER, K. J SYLVIA, B. R SYLVIA, B. R SYLVIA, B. R.	8007300331* 8007210005 8007240005 8007020001 8007090057	50-213 P REB 50-338 F 71-5957 50-280 Q	
ARK,R M FARKEY,R B FARKEY,R B FARKEY,R B ARK,R M	8007230325 9007220426 8007220440 9007220445* 8007270006	50-387 F 50-261 V 50-261 B 50-261 B 50-387 A	PONTO PORTO PROPER OF STANDER PROPER STANDER PROPER STANDER PROPER STANDER PROPER STANDER PROPER STANDER PROPER STANDER STANDE	8007210082* 8007240349 8007270400 8007270844 8007300560*	70-1151 50-348 0 50-390 0 50-328 0 50-321 0	SYLVIA,B R. SYLVIA,B R. SYLVIA,B R. SYLVIA,B R. SYLVIA,B R.	8007090423 8007150462 8007160543 8007010422 8007030156	50-280 Q 50-280 Q 50-280 Q 50-280 P 50-339 P	
TEARNS, C F TEARNS, C F TEBBING, G E TEELE, P W TEELE, T, A	8007170318* 8007290402 8007020461 8007150049* 8007170368	FOIA 40-1852 PR 70-1113 50-409 0	STOHR, J P STOHR, J P BTOHR, J P BTOHBER, C R BTOHBER, C R	8007270404 8007110250 8007216062 8007110296* 8007110282*	27-47 50-321 0 70-1151 COMMISSION COMMISSION	BYLVIA,B R. BYLVIA,B R. BYLVIA,B R. BYLVIA,B R. BYLVIA,B R.	8007020454 8007020585 8007030151 8007310277 8007070200	50-338 P PR 50-339 P PR 50-339 E	
FEEL, G, L FEIN, E L FELLO, V ELLO, V ELLO, V	8007280222 8007140564 7704160256 8007250649* 8007140078*	50-368 P PR 50-334 P 50-482 H 50-397 G	BTOIDER, C.R. STOLLER, S. M. STONE, I'A. STONEBURNER, W. STONEBURNER, W.	8007010278 8007070042* 8007150522* 8007030011* 8007030014*	COMMISSION CONTRACT 50-327 P 70-2478 70-2478	SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR	8007210030 8007070283 8007210092 8007080419 8007100273	50-280 Q 50-338 Q 50-280 S 50-280 P 50-280 P	
ECTO' A ECTO' A ECTO' A ECTO' A	8007140097 8007090019# 8007110588 8007140169 8007020104	50-397 0 8ECY 50-346 H 50-280 0 50-498 0	BTONE, R. J. BTONEBURNER, W. BTONEBURNER, W. STONEBURNER, W. BTONE, R.	8004110523 8007030020* 8007310485* 8007310496* 8007240468*	PR 70-2478 70-2478 70-2478 50-335 H	SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR	8007110189 8007110202 8007170334 8007250545 8007250640	50-280 Q 50-337 P 50-280 Q 50-280 Q	
ELLO, V ELLO, V ELLO, V ELLO, V	8007010031 8007020267 8007140153 8007020298 8007140180	50-546 H 50-259 Q 50-259 Q 50-321 Q 50-321 Q	STONE, W A STONE, J C. STRAHL, J F STRAND, N O STRAND, N O.	8007250057* 8007300086 8007140051* 8007310498 8007310502	QA999 TOPREP PR 50-397 Q 50-397 Q	9YLVIA,B R 8YLVIA,B R 9YLVIA,B R 8YLVIA,B.R. 8YLVIA,B.R.	8007100157 8007110334 8007110357 8007110341 8007140158	50-337 P 50-280 Q 50-339 P 50-337 P 50-339 P	
TELLO, V TELLO, V TELLO, V ELLO, V	8007090013 8007110131 8007110214 8007100295 8007100308*	50-346 Q 50-254 Q 50-346 Q 50-546 Q 50-546 Q	BTRASHA, J STREET, P A STREETER, J F STREETER, J F STRELDH, R.	8007110488 8007210131* 8007220112* 8007240018* 8007070092	50-327 H 50-320 H 50-315 Q 50-301 Q FR	SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	8007140197 8007140406 8007150671 8007160507 8007160671	50-339 P 50-339 P 50-339 G 50-339 P 50-339 P	
TELLO, V ELLO, V ELLO, V TELLO, V	8007110544 8007160468 8007220140 8007250142 8007250633	50-546 H M18C 50-482 Q 50-546 A 50-482 H	STRONO, T R SU, T M SU, T M, SULLIVAN, R F SULLIVAN, J. H	8007270048* 8007170475 8007230252 8007280484* 8007150512*	State Prog 50-322 A 50-322 A 50-259 G 50-327 S	SYLVIA, B R. SYLVIA, B R SYLVIA, B. R. SYLVIA, R. R BYLVIA, B R.	8007170175 8007170387 8007170412 8007170527 8007170601	50-339 P 50-280 R 50-280 F 50-280 0 50-338 F	
ELLO, V ELLO, V ELLO, V ELLO, V	8007280083 8007210288 8007210343* 8007220174 8007220187*	50-546 0 50-217 0 50-217 0 50-273 0 50-273 0	Bummerb, J Bun, Y H Bundaram, R K, Bundaram, R, K Bunderdan, D H	8007290042* 8007020364 8007170460 8007140642 8007140220*	PROJ RES RES FOIA	BYLVIA, B R SYLVIA, B R BYLVIA, B R SYLVIA, B. R SYLVIA, B. R	8007210435 8007170348 8007220431 8007220487 8007210244	50-280 P 50-280 V 50-338 R 50-337 P 50-337 P	
ELLO, V FELLO, V FELLO, V ELLO, V. FLLO, V.	8007220191* 8007230138 8007250088 8007300038 8007300040*	50-293 Q QA999 50-368 Q 50-54 Q 50-54 Q	SUNGTROM, R. F SUTTON, J W SWAN, W B, SWAN, W. B SWANBY, O, T,	8007150158 8007210275* 8007240327* 8007300394* 8007220271	PR QA9 P9 50-518 Q 50-518 Q 40-3453	SYLVIA, B.R. SYLVIA, B.R. SYLVIA, B.R. SYLVIA, B.R. SYLVIA, B.R.	8007210337 8007210347 8007210453 8007220384 8007230447	50-339 P 50-339 P 50-281 P 50-339 P 50-338 Q	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY
SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR	8007240092 8007290220 8007240115 8007240149 8007250415	50-338 F 50-280 Q 50-339 P 50-339 P 50-338 P	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8007020390 8007110570 8007210186 8007240046 8007280399	50-344 A 50-518 H 50-322 A 50-445 A 50-364 A	TOLLISON, A C	8007080185# 8007110405 8007140395 8007140399# 8007150492	50-325 S 50-324 R 50-324 S 50-324 S 50-324 Q
SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR	8007280395 8007250379 8007250388 8007250430 8007280367	50-339 P 50-339 P 50-339 F 50-339 P 50-339 P	TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L TEDESCO,R L	8007270202 8007280154 8007300033 8007300077 8007300080	50-364 A 50-338 F 50-373 A 50-367 F 50-438 A	TOLLISON, A C	8007150654 8007150665* 8007220464 80072204703 8007220521	50-325 9 50-329 5 90-324 8 50-324 5 50-324 9
SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R SYLVIA.B R	800/280406 8007280423 8007280440 8007280444 8007280651	50-339 P 50-339 P 50-339 F 50-339 E 50-338 P	TEDESCO.R L TELFORD.J T TEMME.K E TERNEY.H B TEUFEL.D	8007310338 8007110550 8007210163 8007110248* 8007020554*	50-347 A TOPREP 40-2259 TOPREP 50-320 Q	TOLL 150N, A C	8007250334 8007250341* 8007270826 8007270833* 8007270823	50-324 8 50-324 8 50-325 8 50-325 8 50-325 8
SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR SYLVIA, BR	8007270700 8007300458 8007300183 8007300450 8007310370	50-338 P 50-339 P 50-339 P 50-339 P 50-281 P	TEUFEL, D THEOFANUS, T O THIES, A C THOW, T THOMAS, R D	8007150042 8007090380 8007140443 8007160556* 8007100003*	50-320 P F01A 50-269 G 50-259 R 50-320 G	TOLLISON, A C TOME, A TOME, A TOMLINSON, D P TOMLINSON, D P	8007290831* 8007280508 8007230205 8007140447* 8007280153*	50-325 8 NUREG NUREO 50-362 9 50-362 0
R K.AIVYS R B.AIVYSYS R B.AIVYSYS B.INSWONGER B.INSWON	8007310346 8007310384 8007140038 8007140038 8007220138	50-339 P 50-339 P 70-1308 70-1308 70-1308	THOMAS, R D	8006110739* 8007310339* 8007140657* 8007140663* 8007170556*	27-10 50-275 0 40-2940 40-2940 50-315 0	TOMPKINS, B A	8007020646 8007300408 8007070080* 8007250615 8007280483	50-295 Q 50-344 Q 50-10 Q 50-289 S 50-269 S
R 11 X B WOYLANZB R 11 X B WOY	8007220147 8007220148 8007220170 8007220138 8007220147	70-1308 70-1308 70-1308 70-1308 70-1308	THOMAS, R D THOMAS, R E THOMAS, N THOMAS, R D THOMAS, R, D	8007140670* 8007250398* 8007150452* 8007160721* 8007240331*	40-2940 50-397 A 50-566 @ 40-7982 70-1257	TOURTELLOTTE, J TOURTELLOTTE, J TOURTELLOTTE, J TRAGESER, C M TRAGESER, C M	8007070123 8007160574 8007230536 8007100109 8007300584	50-275 G 50-289 G 50-275 G CONTRACT 50-390 A
SZHAJKOHSKI:R SZHAJKOHSKI:R SZWAJKOHSKI:R TAFT:J P TAH:P	8007220168 8007220170 8007230519 8007290475* 7906220186	70-1308 70-1308 70-1308 50-128 R 50-285 O	THOMAS, H IN THOMAS, R. D THOMAS, W N THOMAS, J O THOMAS, H N	8007030078 8007070070 8007010430 8007310153 8007020592	PRM 50-344 8 50-280 P 50-556 0 50-338 P	TRAMMELL,C TRAMMELL,C M TRAVIESO-DIAZ TRAVIESO-DIAZ TRAVIESO-DIAZ	8007020021 8007140529 8007150556* 8007150556* 8007250353	50-344 P 50-344 F 50-312 G 50-312 G 50-320 G
TAMBLING, T N TAMBLING, T N TAMBLING, T H TAPIA, J I, TAPIA, J I	8007210327* 8007240253* 8007300604* 8007110178* 8007240337*	50-346	THOMAS, R H THOMAS, C D THOMAS, E B THOMAS, R D THOMAS, R, D	8007070326* 8007280089 8007170393 8007240138 8007240350	50-213 6 50-275 A 50-220 P 1&E 27-48	TREAKLE, K TREIBEL, W C TREVING, T TREVING, T TRIBBLE, J E	8007020127 8007020025* 8007010882* 8007140650 8007170925	FOIA CONTRACT CONTRACT FOIA 50-271 G
TAPIA, J TAPIA, J I TARAS, D N TAUCHE, H TAHA, K	8007150136* 8007280153* 8007300066 8007220499* 8007100287*	50-298 Q 50-382 Q PR TOPREP XPORTLIC	THOMPSON, D THOMPSON, H L THOMPSON, M A THOMPSON, M A THOMPSON, W E	8004240316 8007230256# 8007020281 8007020708 8007230175#	I&E FOIA WASTE MOT WASTE MOT 50-289 F	TRIMBLE, D C	8007020194 8007020210 8007020003 8007020201 8007010354	50~313
TAYLOR.C W TAYLOR.C W TAYLOR.R C TAYLOR.J J TAYLOR.J B	8007100028* 8007100044* 8007180574* 8007110492 8007280285	70-143 70-143 50-445 G PR FOIA	THOMPSON, C M THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, D	8007220503* 8007140550 8007230143 8007230148 8007240133	TOPREP 50-219 S I&E 50-54 S 50-289 S	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	9007010369 8007010527 8007010436 8007010470 8007010407	50~313 F 50~368 8 50~368 8 50~313 R 50~368 8
TAYLOR,O A TAYLOR,J H TAYLOR,J H TAYLOR,J H TAYLOR,J H TAYLOR,J J	8007210017 8007070198 8007300294 8007080312 8007230594	RES TOPREP PRM TOPREP 50-409 D	THOMSEN, F T THORNBURGH, D	8007100171 8007230797 8007230797 8007230797 8007250351 8007020313*	50-522	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8007010437 8007070148 8007080160 8007080171 8007180095	50-348 S 50-313 F 50-348 S 50-348 S 71-9108
TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, L	8007170417 8007170421* 8007230239 8007240001 8007290145	TOPREP TOPREP 50-320 8 TOPREP NUREO	THORPE, J R TIEPEL, E, W TIEPEL, E W TIEPEL, E W TIERNEY, F P	8007240367 8007210171 8007210095 8007220303 8007260660	PR 40-8502 40-8502 40-8304 50-282 B	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8007300325* 8007100143 8007280646 8007300055 8007070253	50-313 Q 50-313 R 50-368 S PR 50-313 P
TEDESCO, R. L.	8007010227* 8007070575 8007020302 8007030175 8007030196	FOIA 50~364 A 50~410 G 50~387 A 50~397 A	TIERNEY, F P TILLMAN, A TILLMAN, A TIMKO, D R TOBIN, W J	8007250340 8007150107* 8007110113* 8007180422* 8007010089	50-282 \$ 50-261 0 50-335 0 50-334 R 50-327 8	TRIMBLE, D C	8007070287 8007180429 8007080144 8007300335* 8007040328	50-313 P 50-313 P 50-369 8 50-313 0 50-368 8
TEDESCO, R, L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8007030197 8007030201 8007010184 8007010228 8007010237	50-460 A 50-491 A 50-413 A 50-553 A 50-416 A	TGBIN, W J TOBIN, W J TODD, W E TOKAR, M TOKAR, M	8007110113* 8007160761* 8007210259 8007010181* 8007010218*	50-335 G 50-338 Q PR FOIA FOIA	TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C TRIMBLE.D C	8007100148 8007140396 8007150641 8007160348 8007150647	50-313 H 50-368 S 50-313 S 50-368 P 50-368 S
Tedesco, R L Tedesco, R L Tedesco, R, L Tedesco, R L Tedesco, R L	8007010243 8007010590 8007010557 8007010558 8007010960	50-461 A 50-528 A 50-329 A 50-458 A 50-361 A	TOKAR.M TOLLISON.A C TOLLISON.A C TOLLISON.A C TOLLISON.A C	B007010222* B007240196* B007100377* B007010556 B007010564*	FOIA 50-324 Q 50-324 Q 50-325 B 50-325 B	TRIMBLE,D C TRIMBLE,D C TRIMBLE,D C TRIMBLE,D C TRIMBLE,D C	9007150683 8007150394 8007150595 8007150530 8007170281	50-340 8 50-313 P 50-313 8 50-313 8 50-313 F
TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L TEDESCO, R L	8007010561 8007010563 8007020214 8007020219 8007020227	50-354 A 50-311 P 50-440 A 50-363 A 50-478 A	TOLL ISON: A C TOLL ISON: A C TOLL ISON: A C TOLL ISON: A C TOLL ISON: A C	8007010501 8007010509* 8007010513 8007010521* 8007020334	50-325 B 50-325 B 50-325 S 50-325 S 50-324 S	TRIMBLE,D C TRIMBLE,D C TRIMBLE,D C TRIMBLE,D C TRIMBLE,D C	8007220495 8007290603 8007210396 8007210396 8007210381	50-313 Q 50-313 P 50-348 8 50-313 P 50-348 R
YEDESCO, R. L YEDESCO, R. L YEDESCO, R. L YEDESCO, R. L YEDESCO, R. L	8007020228 8007020232 8007020252 8007020257 8007020245	50-327 P 50-358 A 50-518 A 50-352 A 50-514 A	TOLLISON, A C	8007020361+ 8007160632 8007070234 8007070237+ 8007080180	50-324 8 50-324 8 50-325 8 50-325 8 50-325 8	TRIMBLE, D C	B007210420 B007210406 B007240176 B007180312 B007240148	50-313 R 50-313 B 50-313 B 50-313 B 50-313 S

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
TRIMBLE, D C TRIOLD, K TRIPP, L E TRIPP, L E TRIPP, L E	6007280504 6007020153 6007020225 8007170415 6007220265	XPDRTLIC * 50-334 Q * 50-387 Q * 50-317 Q	UHRIG, RE UHRIG, RE ULLRICH, WIT ULLRICH, WIT UPRIGHT, CM	8007280647 8007270624 8007210403 8007280649 8007150511	50-335 F 50-335 F 50-277 8 50-277 8 * 50-302 0	VARQA, S. A.	8007100156* 8007100165* 8007210311 8007210323* 8007010192	50-261 P 50-261 P 50-250 P
TRIPP.L E TRIPP.L E TRIPP L E TROJANOWSKI.R TROJANOWSKI.R	8007300328 9007280244 9007300321 8007110274 8007240374	* 50-354 @ * 50-354 @ * 50-321 @	UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M UPRIGHT.C M	8007220088: 8007160830: 8007100061: 8007180011: 8007170429:	+ 50-335 0 + 50-335 0 + 50-327 0	VARGA, SA VARGA, SA VARGA, SA VARGA, SA VARGA, SA	8007100109 8007100106* 8007100114* 8007170423 8007170427*	50-286 P 50-286 P 50-286 P 50-316 P 50-316 P
TROMBETTA, R TROMBETTA, R TROMBETTA, R TROSHOSKI, W TROUP, G L	8007140238 8007140516 8007310299 8007210255 8007290401		UPRIGHT, C M UPTON, R T UTLEY, E E UTLEY, E E UTLEY, E E	8007280425# 8007290253# 8007210273 8007010416 8007010425		VARQA, SA VARQA, SA VARQA, SA VARQA, SA VARQA, SA	8007170434* 8007170245 8007170447 8007180191 8007210037	50-316 P 50-247 F 50-247 P 50-334 P 50-281 P
TRGUP, Q L TRGWBRIDGE, Q F TRGWBRIDGE, Q F TRGWBRIDGE, Q F TRGWBRIDGE, Q F	8007290410# 8007020482 8007020621 8007020482 8007020621	27-47 50-320	OTLEY, E E OTLEY, E E OTLEY, E E	8007010307 8007010324 8007010342 8007010384 8007010423	50-261 F 50-324 F 50-324 F 50-261 P 50-324 P	VARQA, S. A. VARQA, S. A. VARQA, S. A. VARQA, S. A. VARQA, S. A.	8007160808 8007180044 8007180046* 8007180053* 8007210055	50~250 H 50~286 P 50~286 P 50~286 P 50~284 P
TROWBRIDGE.O F TROWBRIDGE.O F TROWBRIDGE.O F TRUBATCH.S TRUSSELL.H H	8007140006 8007230604 8007230604 8007240137* 8007170679	50-320 T 50-289 Q 50-289 G NUREQ 40-8102	ALTEN'E E ALTEN'E E ALTEN'E E ALTEN'E E	8007010514 8007240151 8007150626 8007210415 8007250420	50~261 F PR 50~261 P 50~324 P 50~261 P	VARGA, SA VARGA, SA VARGA, SA VARGN, C VERRELLI, DM	8007210059 8007210078 8007300029 8007150749 8007140641	50~247 P 50~247 F 50~348 P FDIA 50~277 P
TUITE,P T TUMA.A T TURK,S E TURK,S E TURK,S E	9007170286* 8007100116 9007030291 8007170261 8007230741	50-219 Q REGOD 70-2909 50-445 Q 50-445 Q	UTLEY, E E UTLEY, E, E UTLEY, E, E UTLEY, E E VALENTINE, P C	8007280679 8007290690 8007290686 8007290723 8007310446	50-241 P 50-241 P 50-241 P 50-324 P 50-275 Q	VERRELLI,D VERRECCHIA.P VERRELLI,D M VILLALVA,I VILLAFORTH,J C	8007070389 8007280274 8007180487* 8007020095* 8007140640	50~321 P FOIA 50~321 P TOPREP PR
TURK, S E TURK, S E TURK S E TURNER, E A TURNER, E A	8007230748 8007250456 8007030294# 8007150075# 8007010072	50-445	VALCRE,C J VALCRE,C J VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8007110112 8007110112 8007280043 8007250357 8007300514	50-272	VILLFORTH, J C VIBBING, Q S VOEGELI.R J VOOEDING, E L VOOT-LOWELL.R	8007150084 8007230073 8007290040 8007130652* 8007240281*	PR 50~313 F 50~313 P TOPREP 50~250 G
TURNER, E A TURNER, E A TURNER, E A TURNER, E A TURNER, E A	8007020478* 8007100443 8007100443 8007160219 8007070304	50-498 A 50-498 G 50-498 S 50-498 S 50-498 S	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8007020728 8007100077 8007290523 8007210546* 8007020531	PR PRM 50-528 G 50-528 G 50-528 S	VOIGHT,A F VOIGT,H H VOIGT,H H VOIGT,H H VOLGENAU,E	8007240157 8007140370 8007140378* 8007140378* 8007020698	71~5088 50~452
TWEED, R M TWEED, R M TYE, L S UDALL, M K	6007300545 8007300552 8007300537 8007010284 8007180431*	10cfr 10cfr 10cfr Org Cammission	VAN BRUMT, E E VAN BRUMT, E E VAN BRUMT, E E VAN BRUMT, E E VAN BRUMT, E C	8007020525 8007080227 8007300152 8007300530 8007090285	50-528 8 50-528 A NUREO 50-528 G 50-528 A	VOLLEN,R J VOLLEN,R J. VOLLMER,R,H VOLLMER,R H VON ZELLEN,B W	8007080055 8007080055 8007020737 8007300030 8007220587	50-367 Q 50-367 Q Financial Financial 50-10 D
UDALL, H K UDALL, H K UDALL, H K UDV, A C UDV, A C	8007180427* 8004280239 8007110809 8007250306 8007270163	COMM1881ON 50-352 U PRM 50-325 P 50-324 P	VAN BRUNT, E E VAN BRUNT, E E VAN DRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	6007150089 8007110398 8007140207 8007140339 8007290516	PR 50-528 A 50-528 S 50-528 S 50-528 G	VONHERRMANN, J VONHERRMANN, J VORDERBRUEOGEN VORDERBRUEOGEN VORGE, J VORGE, J	8007280508 8007230205 8007170270* 8007310516* 8007300095*	NUREQ NUREQ 50~528 Q 50~528 Q 50~261 Q
UHRIO,R E UHRIO,R E UHRIO,R E UHRIO,R E	800724007\$ 8007080330 8007220543 8007100128 8007070100*	50-250 R 50-335 R 50-250 R 50-250 G 50-235 G	VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8007160546 8007160652 8007170470 8007310456 8007290722	50-530 S 50-528 S 50-528 S PR 50-528 S	VRANKEN, J V WAGMAN, N A WAGMER, P C WAGMER, A G WAGMER, B	8007140439* 8007170311 8005190062 8007100124* 8007110144	PR NUREG 50~285 P 50~416 G 50~302 H
UHRIGIRE. UHRIGIRE UHRIGIRE UHRIGIRE	8007160810* 8007220069* 8007020976 8007160579 8007100021	50-335 Q 50-335 Q PR 50-387 S 50-335 Q	VAN BRUNT, E E VAN BRUNT, E E VAN DE POLL, II VAN NESB, S C VAN PAABBEN, H L	8007290773 8007280585 8007310179* 8007100178* 8007170618	50-528 8 50-528 K GA999 50-272 G NUREG	WAONER, P. C WAONER, P. C WAONER, T. E WALBRIDGE, W. C WALBRIDGE, W. C WALBRIDGE, W. C	8007020067 8007170658 8007140875 8007250370 8007310477	50~285 P 50~285 P 50~346 M 50~312 Q 50~312 Q
UHRIG, REUHRIG, REUHR	8007100025 8007240263* 8007030221 8007110199 8007310220*	50-250 G 50-250 G 50-335 P 50-250 P 50-389 G	VAN RODYEN, D VAN RODYEN, D VAN WINKLE, N, VANDENBURGH, D VANDENBURGH, D	8007220053 8007180233 8007210478 8007140701 8007180097	RES 50-247 P NUREG 50-29 G	WALBRIDGE, W C WALBRIDGE, W C WALKER, R. D WALKER, F M WALL, L B	8007240123 8007250348* 8007170103* 8007220340* 8007210141	50-312 P 50-312 P 50-373 Q 50-327 R 40-8745
UHRIG:RE UHRIG:RE UHRIG:RE UHRIG:RE UHRIG:RE	8007080140 8007230181 800709086 8007110261 8007210064	50-250 P PR 50-335 P 50-250 P 50-250 Q	VANDEMBURGH, D VANDENBURGH, D VANDEMBURGH, D VANDEMBURGH, D VANDELL T E	8007010403 8007170116 8007170321 8007070407 8007170635#	PR 50-27 0 50-307 0 PR 50-327 0	HALLIS, Q B HALSH, B Q HALSKE, C HALSKE, C HALSKE, C	8007300399 8007070060* 8007310445* 8007230751* 8007140047	TOPREP CONTRACT PR COMMISSION PRM
UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E UHRIG.R E	8007110256 8007210060 8007250312 8007160375 8007250272	50-250 P 50-387 0 50-335 0 50-250 0 50-336 0	VANDENBURGH, D VANDENBURGH, D VANDEORN, P VANDEORN, P VANSICKEL, J	8007310464 8007280439 8007310235* 8007310245* 8007220371*	PR 50-27 P 50-389 G 50-416 G 50-331 R	HALBKE, C HALBKE, C HALTERB, D K HALTER, J F HAMBACK, T V	8007310441 8007280016 8007070169* 8007160457 8007110124	PR PR 50-387 G NUREO 50-255 P
UKRIG R E UHRIG R E UHRIG R E UHRIG R E UHRIG R. E	6007250282 6007300558 8007310084 8007220374 8007220380	50-250 G 50-250 G 50-250 G 50-335 P 50-250 P	VARANINI,E E VARANINI,E E VARDEL,T E VARGA.S A VARGA.S A	8007030104 8007280044 8007150023# 8007020139 8007020139	PR PR 50~483 G M18C 50~327 A	WAMBACH, J L WAMBACH, T V WANDKE, N E WANDKE, N E WANDKE, N E	8007290180 8007280114 8007220387 8007010484 8007010473	RES 50-255 P 50-264 S 50-275 S 50-275 S
UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E	8007220379 8007230442 8007230454 8007280531 8007280562	50-250 F 50-250 F 50-250 F 50-250 P	VARGA.S A VARGA.S A VARGA.S A VARGA.S A VARGA.S A	8007020109 8007020357* 8007020330 8007210314* 8007100150	50-247 P 50-247 P 50-261 F 50-250 P 50-261 P	Wandke, n e Wang, t Wang, c h Wang, c h Ward, b	8007160668 8007080219 8007150559 8007150649	50-304 8 40-299 50-106 H 50-243 P 40-8771

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WARD, K. D WARD, B WARD, K. D WARD, E. C WAREMBOURG, D	8007230333* 8007220048 8007230273* 8007030178 8007080254	50-346	WENSLAWSKI,FA WENSLAWSKI,FA WENSLAWSKI,FA WENSLAWSKI,FA WERLING,JA	8007180025* 8007230355* 8007030021 8007310168* 8007010396	50-508	WIDNER, W A	8007220281 8007080322 8007090337 8007140357 8007140384	50-321 9 50-321 P 50-321 0 NUREO 50-321 0
Warembourg, D Harembourg, D Warembourg, D Warembourg, D Warembourg, D	8007080268 8007080422 8007010344 8007010496 8007080210	50-267 S 50-267 S 50-267 R 50-267 S 50-267 S	Werling, Ja Werling, Ja Werling, Ja Werling, Ja Werling, Ja	8007010400* 8007010454* 8007010526 8007010536* 8007070276	50-334 S 50-334 S 50-334 S 50-334 S 50-334 S	WIDNER, W A	8007250292 8007310275 8007310287* 8007220422 8007280634	50-321 Q 50-321 Q 50-321 Q 50-321 Q 50-321 P
HAREMBOURG, D HAREMBOURG, D HAREMBOURG, D HAREMBOURG, D HAREMBOURG, D	8007080289 8007080406 8007100173 8007230543 8007230548	50-267 8 50-267 R 50-267 S 50-267 S 50-267 S	Werling, Ja Werling, Ja Werling, Ja Werling, Ja Werling, Ja	8007070334 8007070340 8007180317 8007220430 8007250315	50-334 5 50-334 5 50-334 8 50-334 6 50-334 5	WIDNER, W A WIDNER, W A WIDNER, W A WIDNER, W A WIDDEFF, M P	8007280541 8007290618 8007260538 8007280514 8007140003	50-321 0 50-321 0 50-321 0 50-321 F 50-287 0
Warembourg, D Waring, J P Warnick, R F Warnick, R F Warnick, R F	8007230534 8007010244* 8007140494* 8007230328* 8007300309*	90-267 B FOIA 90-263 Q 50-305 Q 50-263 Q	WERLING, JA WERNER, J WERNER, BJ WESCOTT, HM WESCOTT, HM	8007300383 8007110416* 8007280589* 8007110168* 8007160764*	50-334 8 50-344 8 90-346 8 50-461 Q 50-461 Q	WIDOFF, M P WIDOFF, M P WIDOFF, M P WIESEMANN, R A WIESEMANN, R A	8007140003 8007290779 8007290779 8007180357 8007220488*	50-287 Q 50-287 Q 50-289 Q 50-244 P TGPREP
WASSERBACH, A E WASSERBACH, A E WASSERBACH, A E WASSERBACH, A E WASSERBACH, A E	8007030209* 8007180250* 8007160779 8007010508 8007030204	PR 50-320 H PR 50-320 H PR	WESCOTT, H M WEST, J T WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F	8007300157* 8007110493* 8004240281 8007150171* 8007220197*	50-463 Q 50-320 P 50-267 S 50-285 Q 50-313 Q	WIGGINTON, D WIGGIN, E A WIGGINS, E J WIGGINS, E	7904030186 7904100156 8007110031 8007100361 8007170157	50-334 P 50-334 C PR CONTRACT CONTRACT
WATFORD, M WATKINS, D WATGON, J H WEAVER, C L WEAVER, J	8007150633* 8007070049* 8007150013 8007070264 8007210390	50-261 R 50-514 D 50-437 H 50-10 D 50-397 U	WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F WESTFALL, R M WETTERHANN, M J	8007150091* 8007150136* 8007300354* 8007110493* 8007020407	50-247 G 50-298 G 50-313 G 50-320 P PR	WILBORN, E WILBOURN, G R WILCOX, J D WILD, A A WILD, P A	8007230257* 8007150466* 8007160872* 8007020655 8007140585	50-313 0 50-327 5 50-416 0 50-320 H 50-339 8
HEAVER, J HEBB, M HEBB, R E NEBER, D A HEBSTER, E H	8007300367 8007280355 8007300332 8007250186 8007230362	50-397 U 50-272 Q 50-272 9 50-313 P 50-280 S	HETTERHAHN, K J NETTERHAHN, K J WHARTON, R J WHARTON, R J WHATLEY, H E	8007150507 8007150509 8007140034* 8007140034* 8007180478*	50-272 0 50-272 0 50-361 0 50-361 0 50-320 H	NILD.P A WILLIB.C A WILLIAMS.R E WILLIAMS C C WILLIAMS.C C	8007140601 8007160798 8007010562* 8007150118* 8007160479*	50-339 S REGGD 40-1162 50-454 Q 50-546 G
HEEKS, E. D HEONER, M S HEIGAND, J G HEIL, C H	8007150548 8007100135 8007160240 8007210148* 8007280435*	50-133 R REGGD 50-142 F 50-458 G 50-346 G	WHEATLEY, P D WHEELER, M WHEELER, R V WHIPPLE, G H, WHITE, J G	8007280186 8007160405 8007140599 8007080357* 8007160569*	RES PR PR PR 50-454 K	WILLIAMS,C C WILLIAMS,C C WILLIAMS,C C WILLIAMS,C E WILLIAMS,J E	8007230019* 8007230700* 8007230710* 8007280315 8007250117*	50-456 Q 50-373 Q 50-546 Q 71-9010 COMMISSION
WEINER,RE WEINER,RE WEISEMANN,RA WEISS,AJ WEISS,AJ	8007140190* 8007170390 8007220496* 8007310216 8007310471	50-247 P 50-344 P TOPREP NUREO NUREO	WHITESIDES.O E WHITE.T WHITE.J R WHITESELL.D E WHITESELL.D E	8007110493* 8007220154* 8007100014* 8007010051* 8007160411*	50-320 P 50-482 G 50-320 G GA977 GA979	WILLIB.E WILLIAMS.F C WILLSEY, W S WILSON.B D WILSON.W E	8007110406* 8007300569 8007310414 8007310270* 8007110231*	50-324 R PR 50-277 R FOIA PR
WEISS, J. D WEISS, E R WEISS, D WEISS, D WEISS, E R	8007010106# 800724004# 8007010252 8007100462# 8007150552	71-5768 COMMISSION 70-734 71-9094 70-143	WHITESELL, D E WHITESELL, D E WHITE, L D WHITESELL, D E WHITE, M	8007100339* 8007210275* 8007230008* 8007210264* 8007210029	QA999 QA999 50-244 Q QA999 ACRS	WILSON, WE WILSON, BA WILSON, BP HILSON, FR	8007110239* 8007110225 8007030211 8007140546* 8007170317*	PR PR Toprep Secy 50-482 A
ME188, B H ME188, B H ME188, B H ME188, E H	8007080043 8007160145 8007160155 8007160160 8007160167	50-289 G 50-320 H 50-320 H 50-320 H 50-320 H	WHITESELL,DE WHITE,LD WHITE,WH WHITE,WH WHITE,WH WHITE,LD	8007220155* 8007020018 8007100062* 8007100062* 8007180141	QA799 50-244 Q 50-344 Q 50-344 Q 50-244 Q	N F YOSTIM N F YOSTIM MITSON'S D MITSON'S D MITSON'S N	9007020421 9007290131 9007290407 9007030239 9007010297	PR
WE188, B H WE188, B H WE188, D WE188, E R WE188, E R	8007140170 8007140183 8007280090 8007140022* 8007140018	50-320 H 50-320 H 70-371 50-287 G 50-287 G	WHITE, L D WHITENER, H L WHITE, L D WHITE, L D WHITE, E B	8007240145 8007280425* 8007070342 8007080272 8007100257*	PR 50-270 0 50-244 F 50-244 P PR	MITEON' 7 F MITEON' 7 F MITEON' 7 F MITEON' 6 C	8007080051 8007010340 8007010374* 8007010429 8007010442*	50-329 0 50-281 8 50-281 8 50-280 8 50-280 8
Weiss, E R Weiss, E R Weiss, E R Weiss, E R Weiss, D	8007140022* 8007300039 8007300043 8007250043 8007180372	50-287	WHITE, L D WHITE, L D WHITE, L D WHITE, L D WHITE, L D	8007250498 8007220403 8007270740 8007280633 8007310350	50-244	MITSON' 7 F MITSON' 7 F MITSON' 7 F MITSON' 7 F	8007140519 8007070389 8007070397* 8007070224 8007070229*	50-322 F 50-280 8 50-280 8 50-280 8 50-280 8
Heiss.d Heiss.d. Heiss.d Weiss.J Weiss.e R.	8007210106 8007250363 8007280027 8007210078 8007230227	70-820 70-371 70-754 70-33 FOIA	WHITE, L D WHITE, L D WHITMAN, C D WHITMEY, C O WHITMEY, C O	8007310378 8007310401 8007310554 8007080192* 8007180704*	50~244 F 50-244 P NUREO 50-293 S 50-293 R	WILSON, R P WILSON, J N WILSON, J N WILSON, J N WILSON, B D	8007110087 8007170339 8007170347* 8007170351* 8007310042	PR 50-322 A 50-322 A 50-322 A XPORTLIC
WE188.E R WE188.E R WE188.E R WE188.D WE188.D	8007210495* 8007210487 8007210495* 8007230731 8007230044	50-289 G 50-289 G 50-289 G 40-8681 70-1287	WICHERS, D L WICHERS, D L WICHERS, D L WICHERS, D L WICHERS, D L	8007010591 8007020079 8007030358 8007070147 8007150651*	40-8502 40-8502 40-8502 40-8502 40-8502	WILSON, B D WILSON, J L WILSON, J N WILSON, J L	8007310044 8007140249 8007140259* 8007240464 8007180319	#PORTLIC 50-280 \$ 50-280 \$ 50-322 A 50-281 \$
Heiss. D Heiss. D Heiss. D Heiss. D Heiss. B	8007250049 8007250161 8007280045 8007280101 8007240133	70-8 70-754 70-2623 70-687 50-289 8	WICHERS, D.L. WICHERS, D.L. WICHERS, D.L. WICHERS, D.L. WIDMER, W.A.	8007150644 8007210548* 8007210542 8007210101 8007110259*	40-8502 40-8502 40-8502 40-8502 50-321 Q	MILSON, J C MILSON, J C MILSON, J C MILSON, J C	8007180327* 8007310044 8007230133 8007280607 8007280618*	50-281 S XPORTLIC 50-322 A 50-280 S 50-280 S
HENSLAWAKI.F A HEISELE R HEISELE R HEISELE R	8007290781 8007290781 8007100094 8007170359* 8007150130*	ORG ORG PR 50-320 G 50-344 G	WIDNER, W A	8007240264* 8007090074 8007010474 8007280128* 8007080287	50-321 Q 50-321 Q 50-321 P 50-321 Q 50-321 P	WILSON, J L WINANS, L F WINTERS, C E WITHROW, G C WDFFORD, A W	8007280625 8007100017 8007240228 8007190664 8007160867*	50-280 8 PR 70-1062 50-155 Q 50-322 Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT	Υ	POHTUA	ACCESSION NUMBER	SUBJECT CATEOGR					
JHLSEN, W D	8007080285*	TOPREP		YIN, I T	6007230087*	50-35B	 G	ZAHLER, R E	8007180391	50-289	
DLF, J F	8007020423	50-320	G .	YIN, I T	8007230758*	50-275	G	ZAHLER, R E	8007180421	50-287	ö
OLF, J F	8007080002	50-320	Q	YIN, I T	6007310316*	50-266	ä	ZAHLER, R E	80071B0391	50-269	ŏ
プレディ ン F	8007140006	50~320	Ϋ́	YODER, R C	8007300014	PR	_	ZAHLER, R E	8007180421	50-267	ō
OLF, J F	8007220006	50-320	Q.	YORE, J R	8007070050*	50-514	D	ZAHLER.R E	8007230506	50-289	ō
ILF.S J	8007290746	50-466	Q	YOUNGBLOOD, B J	8007150047	50-280	H	ZAKLER, R E	8007230514#	50~289	Q
DLFE.S J	8007020434	50-466	C	YOUNG, M F	6007290152	NUREO		ZAHLER, R E	8007230610	50-289	9
DLFE, S J	B007030061	50-466	Q	YOUNG, T	8007240395*	50-275	Q	ZAHLER R E	8007230514 *	50-287	0
OLFE, B J	8007220004	50-466	G	AUNMBEDOD'B A	8007010571	90-369	A	ZAHLER R E	6007230610	50-289	0
DLFE, B J	8007250703	50-466	Q	YOUNGBLOOD, B J	8007020688	50-281	н	ZAHLER.R E	8007290533	50-346	М
OLFE,8 J JLIVER,J	8007300356	50-445	M	A B 'GOD'BONDOA	8007070203	50-339	P	ZAHLER R E	8007290533	50-346	M
JLIVER, J	8007220545	50-358	Ģ.	YOUNGBLOOD, B J	8007090378	50-387	A	ZAJACIL D	B007310245*	50-416	Q
OLTNER, E	8007220969	50-358	o	AONNOBFOOD B 3	8007180339	50-387	Q	ZARAKAB, P	8007230044	PR	_
ONO, T	8007230124* 8007170571	70-371		YOUNGBLOOD, B J	8007110137	50-482	F	ZARAKAS, P	8007090279	50-3	P
		40-299		YOUNGELOOD, B J	9007110154	50-483	F	ZARAKAS, P	8007110396	50-247	8
DNO.T	8007140371 8007010337	40-299 50-309	6	YOUNGBLOOD, B J	8007110583	50-369	A	ZARAKAS, P	8007140375 8007220476	NUREC	
100 E C	6007080413	70E-08	8	YOUNGBLOOD, B. J.	8007180440	50~387	Ġ	ZARAKAS, P	8007220504	50-247 50-247	R P
300' E C	8007210428	50-309	8	YOUNGBLOOD, B J	8007170685	50-367	A	ZARAKAS, P ZARAKAS, P	8007220523	50-247	R
DODHEAD, C P	6007100043	50-341	ő	YOUNGSLOOD, B J	8007180039 8007310327*	50-339 50-275	P Q	ZARAKAB, P	8007230471	50-247	P
			•				-				
JODHCAD, C P	8007300428	50-409	<u>o</u>	AUNHOBEOOD'B 1	8007170449*	50-339	₽	ZARAKAB, P	8007240127	50-3	1
00DRVFF.R L	8007300580*	50-321	O.	YOUNGDAHL R C	8007140392	50-3	P	ZARAKAB, P	8007240169	50-247	8
2008' K	8004240210	18.5		AUGMENTOOD'B 1	8007180062	50-443	A	ZARAKAB, P	8007290682	50-3	H
DODS, T G	8007140449	PRM		AGAMOBEGOD'B ?	8007180069	50-367	A	ZARKAS, P	8007220454	50-247	P
	8007180055	50-412	a	AQONGBEDGD'B 1	8007180520	50-410	A	ZECH, Q Q	8007100149	ACRB	
MOLEVER, E J	6007010349	50-412	a	YOUNGUL.OOD, 9 J	8007230127	50-969	A	ZEFF.D W	8007100397*	70-1201	
COLEVER E J	6007210016	50-412	G	YOUNGBLOOD, B J	8007230547	50-482	24	ZELAC,R E	8007100007	PR	
RAY. J. R	#44410E2700B	50-289	0	YOUNGBLOOD, B J	8007230552*	50-402	M	ZELLNER,R J	8007280270	FOIA	
RAY, J R	6007230142	50-289	Q	ADANOBFDOD'B 1	8007280013	50~482	M	ZENTNER, M A	8007210331*	CONTRACT	
ICHT: B L	8007140258	XPORTL IC		ADONGBFG000'B ?	8007280015	50-462	М	ZENTNER, K A	8007140203*	CONTRACT	-
HIGHT F 5	8007030365	PR		YOUNGALOOD, B J	8007230622	50-443	Н	ZQLICZYNBKI,J B	8007210512*	50-59	R
H A THOIS	8007020013	40-4492		AUCHOUP'B 1	8007280166	50~369	A	Z IBULSKY, H	8007250494*	70-820	
RIGHT, O. C.	8007140493*	50-155	Q	AONOBEODUB 1	8007270004	50-389	М	ZIMMERMAN, R P	E005230131	50-245	8
SIGHT, K H	8007100084	40-4492		AUMOBEOOD! B ?	8007290019	50-307	A	ZIMMERMAN, R P	8007310365*	50-245	Q.
RIGHT, K H	8007 (00097	40-4492		ADMAGROOD'B 1	8007250181	50-349	A	ZITTEL. H. E.	8007140503	REB	
IGHT O C	8007230303*	20-331	g.	YUAN, O	8007070084	PR	_	ZITTEL, H E	8007170648	RES	
RECHT. R W	0007270361*	50-439	a	YUHAS, O P	8007100014*	50-320	g	ZULLA: 8 8	8007250317*	50-286	a
RECHT, B L	8007150030	XPORTLIC		YUHAB, Q P	8007180025*	50-50B	a	ZULLA, 8 8	8007010452	50-286	8
IGHT. B L	8007150034	XPORTLIC		YUHAB, O P	8007230355*	50-224	g .	ZULLA, S. B	8007010448	50-286	8
KIGHT, D C	8007150039	XPORTLIC		YUNDT, C P	8007080418	50-344	6	ZULLA, S S	8007080350	50-284	8
IGHT. B L	8007140824	XPORTL10		YUNDT, C P	8007140312	50-344	R	ZULLA, 6 8	8007080355	50-286	8
KIGHT'B L	8007310511	XPORTLIC.		YUNDT, C. P.	8007150581	50-344	8	ZULLA, B	6007140333	50-266	8
1, G	8007230620	40-8727		YUNDT, C. P.	8007150820	50-344	s	ZULLA, B S.	8007210466	50-286	Q.
J.K Jller.G e	B007170262*	XPORTLIC		YUNDT, C.P.	8007280648	50-344	8 5	ZULLA S S.	8007290052	50-284	8
ILLERIO E	8007030215	50-461	G .	YUNDT, C. P.	8007280545	50-344	a	ZULLA, S S	8007210376	50-286	R
LLER. 0 E	8007160626	50-461	8	YUNDT, C.P.	8007280963	50-344	6	ZULLA, B 8	8007210418	50-284	8
TTKE, Q	8007020346	XFORTLIC		ZAHLER, R. E	8007020633	50-289	Q O	ZULLA, B 8	8007310426	50-286	8
MANA.K NDELL.L A	8007260464	XPORTLIC	Δ.	ZAHLER, R E	8007020633	50~289	0	ZUMBRUN, R A	8007100257*	PR	
WN.AD	8007300354*	50-313 PR	a	ZAHLERIR E. ZAHLERIR E	8007140224 8007140224	50-287 50-289	č	ZUMBRUN, R A	8007100257*	PR	
MINICA N	8007150133	LK		SMILERIN L	9001140554	30-50Y	•	ZURAKOWSKI, P R.	8007140670*	40-2940	
								ZWETZIQ.Q 9	8007320337*	50-73	g
								ZWETZIQ.Q B	8007310301*	50-312	a

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
OM Co. Minnesota Mining & Mfg Co AGIP USA, Inc Accuracy in Media Advanced Technology, Inc	8007020415 8007310520 8007280294 8007090377 8007140248	MISC XPORTLIC FOIA FOIA FOIA	
Advisory Council on Historic Preservation Asmospace Corp Agriculture.Dept of Agriculture.Dept of. Forest Service Air Force.Dept of	8007210141 8007170618 8007280333 8007290421 8007020444	40-8745 NUREQ 40-8745 50-10 PR	D
Air Products & Chemicals, Inc Alabama Power Co	8007150077 8007280383 8007010406 8007010412* 8007010424	PR XPORTLIC 50-348 50-348 50-364	8 8 A
	8007010444 8007010446* 8007010489 8007070168 8007070176*	50-348 50-348 50-364 50-348 50-348	S A R R
	8007070180* 8007070190* 8007070194* 8007070199* 8007070204*	50-348 50-348 50-348 50-348 50-348	R R R R
	8007070208* 8007070214* 8007070217* 8007070219* 8007070223*	50-348 50-348 50-348 50-348 50-348	R R R R
	8007070226* 8007070228* 8007070230* 8007070232* 8007070272	50-348 50-348 50-348 50-348 50-344	R R R R
	8007080222 8007080228* 8007080232* 8007080234* 8007080243*	50~364 50~364 50~364 50~364 50~364	A A A A
	8007080250* 8007090214 8007090237 8007100177	50-364 NUREQ 50-364 50-364 50-364	A A A
	8007100185 8007100261 8007100261 8007100267* 8007100274*	50-348 50-348 50-348 50-348 50-348	RKKKK
	8007100276* 8007110502 8007140343 8007150662 8007150668*	50-348 PRM 50-364 50-348 50-348	K A R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B007150714	50-348 P
	B007160549	50-348 Q
	8007160579	50-364 A
	8007140841 8007210245	50-348 S 50-348 O
	6007210253	30-340 Y
	B007210499	50-348 P
	B007220410	50-344 A
	B007220486	50-364 A
	8007220510 8007220510	50-348 P 50-348 P
	800/220510	30-348 P
	8007220515+	50~348 P
	B007220554	50-348 P
	8007220554	50-34B P
	8007220558	50-348 P 50-348 P
	8007220559	50-348 P
	B0072205B1	50-364 A
	B007230403	50-348 P
	B007230403	50-348 P
	6007230485	50-364 A
	8007230492	50-364 A
	8007230510	50-364 Q
	8007230546	50-364 A
	8007230553	50-348 P
	8007230553 8007230567	50-348 P 50-364 A
	800/23036/	30-384 W
	8007230592	50-364 A
	8007240071	50-364 A
	8007250320	50-364 A
	8007250479 8007280052	50~348 0 PR
	DD07 RD0038	1.18
	8007280490	50-364 A
	6007280557	50~364 A
	6007280441	50-346 F 50-364 A
	80072904 37 8007290442	50-364 A
	8007290859	50-348 G
	6007310150	50-364 0
	8007310330 8007310374*	50~364 0 50~364 0
Alabama, State of	B007180022*	State Proc
Alaska, State of	8007010133*	State Prog
Aldrich Chemical Co , Inc (subs of Sigma-Aldrich Corp)	8007010577	XPORTL IC
Signa-Attitu curp /	8007020014	XPORTL IC
	8007030063	XPORTL IC
	8007160403	XPORTLIC '
Allan Spector & Associates,Ltd	8007220317*	40~1162
Allied General Nuclear Services	E007180049	NUREO
	8007310139	50-332 0
Ailis-Chalmers Corp	E007110014	71-221
	B007110016+	71-221
Alpha-Onega Gervices, Inc	B007280151	71-5979
	B007280155*	71 5979
	8007280160*	71-5979
	B007280165*	71-5979

AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT CATEGOR	S.A.	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
American Electric Power Co , Inc American Institute for Research in the Behavioral Sciences	8007280173* 8007280177* 8007020412 8007180208*	71-5979 71-5979 PR 50-213	F		8007280998* 8007280998* 8007290516 8007290516 8007290529	50-528 50-528 50-528 50-528 50-528	0 K K K
American Mine Services, Inc American Nuclear Insurers	8007170172# 8007240170* 8007240173* 8007100134 8007210442	CONTRACT CONTRACT CONTRACT PRM MISC	т		8007290722 8007290722 8007290773 8007300106 8007300106	50-528 50-528 50-528 50-528 50-528	5550
American Nuclear Society	8007280057 8007280067* 8007100254 8007100257* 8007140046*	PR PR PR PR PR			8007300104 8007300152 8007300514 8007300530 8007300530	50-528 NURE0 50-528 50-528 50-528	G G G
American Warming & Ventilating, Inc Amersham Corp Ames Laboratory, Energy & Mineral Resources Res Institute	8007240353 8007290932 8007290934* 8007240157	50-329 71-370 71-370 71-5088	5	Arisona, State of Arisona, Univ of	8007300530 8007310454 8007020009* 8007030138 8007140411	50-528 PR CONTRACT PR PR	Gr.
Anaconda Co , Amaconda Copper Co Div Anchor/Darling Valve (subs Anchor/Darli ng Industries)		WASTE MG		Arkansas Power & Light Co	8007150140 8007010356 8007010367 8007010380* 8007010407	FR 50-313 50-313 50-313 50-368	P F F S
Anderson-Greenwood & Co nefco.inc inti-Nuclear Group Representing York	8007300315* 8007230483* 8007220203 8007220207*	0A999 50-327 50-269 50-269 50-289	P G G		8007010414# 8007010436 8007010437 8007010440#	50-368 50-368 50-368 50-368	8 8 9
ptech Engineering Services organne National Laboratory	8007280404* 8007100343 8007180031 8007210027	50-206 NUREQ NUREQ ACRS	S		8007010441* 8007010470 8007010480* 8007010927 8007010935*	50-348 50-313 50-313 50-348 50-348	8 R R B B
rgonne National Laboratory - Argonne West rizona Public Service Co	800722010* 8007220184 8007020525 8007020525	COMMISSI 71-9132 50-528 50-528	S S		8007020003 8007020194 8007020201 8007020210	71-5957 50-313 50-313 50-313	0 0 P F
	8007020525 8007020529* 8007020529* 8007020529* 8007020531	50~528 50~528 50~528 50~528 50~528	6 5 6 8		8007070148 8007070148 8007070253 8007070253 8007080046 8007080144	50-313 50-313 50-313 50-313 50-368 50-368	E P P P S
	8007020533* 8007020728 8007080227 8007080227 8007080227	50~528 PR 50~528 50~528 50~528	8 A A A		8007080154* 8007080160 8007080166* 8007080171 8007080178*	50-368 50-368 50-368 50-368	6 88 85 50
	8007090285 8007100077 8007110398 8007140207 8007140207	50-528 PRM 50-528 50-528 50-528	A 8 5		8007090287 8007090328 8007090334* 8007100143 8007100148 8007100148	50-313 50-368 50-368 50-313 50-313	5 8 8 H
	8007140217* 8007140217* 8007140339 8007140339 8007140341*	50-528 50-528 50-528 50-528	6 6 5 5 5 6		8007100366 8007140396 8007140405* 8007150394 8007150394	PRM 50-360 50-360 50-313	8 8 P
	8007140341* 8007140448 8007150009 8007160546 8007160591*	50-528 PRM PR 50-530 50-530	8 8		8007150489 8007150489 8007150494* 8007150494* 8007150530	50-313 50-313 50-313 50-313 50-313	P P P
	8007160652 8007160652 8007160658* 8007160658*	50-528 50-528 50-528 50-528 50-528	9 9 8 8		8007150538* 8007150595 8007150603* 8007150641	50-313 50-313 50-313 50-313	8 9 9 9
	8007160658* 8007170470 8007170470 8007170493* 8007170493*	50-528 50-528 50-528 50-528 50-528	5 5 8 8 8		8007150647 8007150650* 8007150660* 8007150693*	50-368 50-313 50-368 50-368 50-368	
	•	50-528 40-8771 50-528 50-528 50-528	а а а к		8007150694 8007170281 8007170285* 8007180095 8007180312	50-368 50-368 50-319 50-319 71-9108 50-319	P F F
		50~528 10~528 10~528 10~528 10~528	к к % к		8007180318* 8007180429 8007180429 8007180429 8007210381 8007210382*	50-313 50-313 50-313 50-368 50-368	E P R R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	B007210394 B007210400* B007210404 B007210413* B007210420	50-368 S 50-368 S 50-313 S 50-313 S 50-313 R		8007080013 8007080017# 8007080058 8007090189 8007150425	50-466 G 50-466 G 50-466 G 50-466 G
	8007210432* 8007210450 8007220495 8007240120 8007240148	50-313 R 50-313 R 50-313 Q 50-313 P 50-313 S		8007150425 8007160553 8007160570 8007160639 8007160645	50-445 M 50-498 G 50-466 G 50-466 G
	8007240150* 8007240176 8007280222 8007280226* 8007280504	50-313 8 50-313 8 50-368 P 50-368 P 50-313 8		8007180432 8007250424 8007250441 8007300090 8007300402	50-446 G 50-446 G 50-445 N 50-498 G 50-466 G
	8007280511* 8007280546 8007280546 8007280646 8007280655*	50-313 S 50-313 S 50-313 S 50-368 S 50-368 S		8007300404 8007300413 8007300417 8007300435 8007300449	50-498 Q 50-466 G 50-466 G 50-466 G
	8007270403 8007300055 8007300325* 8007300335*	50-313 P PR 50-313 Q 50-313 Q 50-313 Q	Baker Testing Services, Inc Baltimore Gas & Electric Co	8007310094 8007310308 8007070128 8007070133* 8007010327	50-466 G 50-466 G 71-392 71-392 50-317 P
Arkansas, State of Armstrong Cork Co Army, Dept of, Headquarters Materiel Development & Readiness Command	8007300335# 8007030024 8007070406 8007300066	50-313 Q PR PR PR		8007010387 8007010390* 8007010392* 8007020349 8007020349	50-317 R 50-317 R 50-317 R 50-317 P 50-317 P
Army,Dept of Army,Dapt of, Office of Surgeon General	8007020375 8007020375* 8007020382* 8007150080 8007020461	50-67 R 50-67 R 50-67 R PR PR		8007020354# 8007020354# 8007020436 8007020436 8007020442#	50-317 P 50-317 P 50-317 P 50-317 P 50-317 P
Arnold & Porter Association of American Geographers Atlas Minerals Atomic Energy of Canada, Ltd Atomic Industrial Forum	8007250150 6007180227* 8007220291 8007240391 8007030348	WASTE HQT HISC 40-3453 PT21 PR		8007020442* 8007020448* 8007020448* 8007090291 8007090324	50-317 P 50-317 P 50-317 P 50-317 P 50-317 P
	8007110031 8007140031 8007140047 8007230751# 8007240135# 8007280016	PR PR PRN COMMISSION NUREO PR		8007090356 8007090359* 8007100228 8007100228 8007110203*	50-317 Q 50-317 Q 50-317 Q 50-317 Q NUREQ
Austin, TX Automated Correspondence Systems, Inc	8007280032 8007310441 8007310445* 8007210388 8007170222*	PR PR PR 50-445 M CONTRACT		8007110207* 8007160245 8007160245 8007170111 8007170352	NUREG 50-317 F 50-317 F 50-317 Q 50-317 P
BDM Corp Babcock & Hilcox Co	8007070040* 8007010004 8007010010* 8007010293 8007020350*	CONTRACT 70-824 70-824 70-824 70-824		8007170352 8007170353* 8007170353* 8007170576 6007180600	50-317 P 50-317 P 50-317 P 50-317 0 50-317 0
	8007080312 8007090198 8007090201* 8007170417 8007170421*	TOPREP TOPREP TOPREP TOPREP TOPREP		8007210044 8007210044 8007220351 8007220351 8007220355*	50-317 G 50-317 G 50-317 R 50-317 R 50-317 R
	8007180486* 8007230237 8007240001 8007240002* 8007300294	TOPREP 50-320 S TOPREP TOPREP PRM		8007220355* 8007220570 8007230025 8007230175 8007240152	50-317 R 50-317 F 71-383 PR 50-318 S
Babcock & Wilcox Co , Naval Nuclear Fuel Div	8007310469 8007310490* 8007010553	XPORTLIC XPORTLIC 71-5941		8007240153* 8007250662 8007250662 8007280451 8007280453*	50-318 8 50-317 0 50-317 0 50-317 8 50-317 8
Babcock & Wilcox Co , Nuclear Material	8007020339 8007020358* 8007020345* 8007020005*	70-27 70-27 70-27 70-135		8007280481 8007280664 8007280676* 8007300351	50-317 F 50-317 S 50-317 S 50-318 S
Div	8007100397* 8007150135* 8007150148*	70-1201 70-364 70-364	Bangor Hydro-Electric Co Barbay Engineers, Inc Barr Engineering Co	8007080031* 8007160227* 8007220307	50-443 I CONTRACT 40-297
	8007150809 8007150814* 8007160397* 8007280211	70-364 70-364 98777 71-9022	Battelle Memorial Institute Battelle Memorial Institute, Columbus Laboratories	8007300249 8007140220* 8007150712*	PR FOIA :
Badger Safe Energy Alliance, Inc Baker & Botts	8007150475 8007020471 8007020405	50-484 G 50-466 G 50-498 G		8007230201 8007240394 8007250110 8007250115*	NUREG NUREG 71-5957 71-5957
					1

AUTHOR AFFILIAT (ON	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	
Battelle Memorial Institute, Pacific Northwest Laboratory	8007280004 8007310181 8007310183 8007010187#	RES RES RES FOIA			8007300556* 8007300559* 8007300542* 8007300544* 8007300564*	50-482 50-482 50-482 50-482 50-482	A A A A
	8007010191# 8007010238# 8007020016 8007030350 8007090186# 8007100378	FOIA FOIA RES NUREO 70-1257 PRM	7	Bechtel Power Corp (subs of Bechtel Corp)	8007300564* 8007300566* 8007300568* 8007300570* 8007020118	50-482 50-482 50-482 50-482 REGOD	A A A
	8007170311 8007180330 8007210001 8007210315* 8007220019	NUREG RES RES 70-1257 NUREG	7		8007100062* 8007140075* 8007150116 8007230042 8007300452	50-344 GA999 PR PR TOPREP	o
	8007220058 8007240283 8007280002 8007280202* 8007290244	RES NUREG RES FOIA RES		Bendix Corp Bergen-Patterson Pipe Support Corp Bernard Johnson, Inc Bethlehem Steel Corp Black & Veatch	8007300570* 8007270448 8007270145 8007150004 8007140454	CONTRACT 50-322 NUREQ PR PR	S
Bear Creet Uranium Co	8007300014 8007300113 8007310187 8007310210 8007240007	PR PR RES NUREG 40-8452	2	Black Hills Alliance Boeing Co Booke.B L Borg-Warner Corp , Nuclear Valvo Div	8007140674 8007220257 8007280218 8007220520 8007070034	FOIA 40-299 40-8481 40-1162 XPORTLIC	
Bechtel Associates Professional Coep Bechtel Corp	8007070254* 8007030248* 8007140045 8007140049* 8007140428*	50-331 50-416 PR PR 50-155	P A G	Boston Edison Co	8007010540 8007010545* 8007030142 8007030287 8007030289*	50-293 50-293 50-293 50-293 50-293	8 F 8
	8007150806* 8007220396* 8007230484* 8007280551* 8007280556*	50-255 50-331 50-331 50-250 50-250	G P P P		8007070357 8007070378 8007070382* 8007070388* 8007080182	50-293 50-293 50-293 50-293 50-293	8 8 8
	8007300514* 8007300514* 8007300514* 8007300517* 8007300517*	50-482 50-482 50-482 50-482 50-482	A A A A		8007080192* 8007080194 8007080200* 8007080202 8007080205*	50-293 50-293 50-293 50-293 50-293	8 8 8 8
	8007300517* 8007300520* 8007300521* 8007300522* 8007300522*	50-482 50-482 50-482 50-482 50-482	A A A A		8007140415 8007150152 8007150557 8007150699 8007150704*	50-293 PR 50-293 50-293 50-293	G P R R
	8007300522* 8007300524* 8007300526* 8007300526* 8007300526*	50-482 50-482 50-482 50-482 50-482	A A A A		8007160641 8007160648* 8007180393 8007180402* 8007210006	50-293 50-293 50-293 50-293 50-293	6 P P G
	8007300528* 8007300529* 8007300529* 8007300529* 8007300533*	50-482 50-482 50-482 50-482 50-482	A A A A		8007210301 8007210373 8007230196* 8007250309 8007280252*	50-293 50-293 50-293 50-293 50-293	G G G
	8007300533# 8007300533# 8007300534# 8007300534# 8007300534#	50-482 50-482 50-482 50-482 50-482	A A A A	Boston Univ Hedical Center Boston,MA Branch Radiographic Laboratories, Inc Brand & Hall	8007290596 8007090416 8007290929 8007290931* 8007250485	50-293 REGOD 71-368 71-368 50-395	P H
	8007300535* 8007300536* 8007300536* 8007300536* 8007300538*	50-482 50-482 50-482 50-482 50-482	A A A A	Brand-Rex Co Briggs Engineering & Testing Bronson Methodist Hosp Kalamazoo,NI	8007250502* 8007220189* 8007020469 8007080273 8007080278*	50-375 QA999 FOIA 40-8054 40-8056	М
	8007300538* 8007300538* 8007300539* 8007300540* 8007300542*	50-482 50-482 50-482 50-482 50-482	A A A A	Brookhaven Nationel Laboratory	8005130445 8007010082* 8007010372 8007010379 8007020085	RES FOIA 50-263 50-335 RES	F F
	8007300542* 8007300542* 8007300543* 8007300546* 8007300546*	50-482 50-482 50-482 50-482 50-482	A A A A		8007020364 8007140361 8007150066 8007180233 8007180240	RES 50-171 RES RES RES	F
	8007300546* 8007300547* 8007300547* 8007300547* 8007300549*	50-482 50-482 50-482 50-482 50-482	A A A A		8007180245 8007180253 8007180361 8007210003 8007210005	RES RES RES RES	
	8007300549* 8007300549* 8007300551* 8007300554*	50-482 50-482 50-482 50-482	A A A		8007210007 8007210010 8007210014 8007220047	RES RES RES RES	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	₹Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8007220053 8007230455* 8007240294 8007290562 8007290634	RES FOIA RES 50-237 50-409	F F		8007100220* 8007140613 8007140620* 8007160491 8007220423	TOPREP 71-6294 71-6294 NUREQ 70-1100	
Brown & Caldwell	8007310216 8007310217 8007310234 8007310471 8007010226*	NUREO NUREO NUREO NUREO 50-204	R	C F Braun & Co California State Univ,Northridge California, State of	8007210233* 8007010374* 8007020316 8007030048 8007030104	TOPREP 50-36; State Pr 50-275 PR	A og O
Brown & Root Corp (subs of Halliburton Corp) Brownsville.TX	8007100248* 8007290441 8007150449	50-204 50-498 50-445	R S		8007100086 8007140052 8007170145± 8007250429	PR PRM CONTRACT 50-275 PR	G
Bruce Norton Burns & Ros Co	8007180405 8007010004* 8007010007* 8007010018* 8007010023*	50-275 50-397 50-397 50-397 50-397 50-397	0 A A A	California. Univ of. Berkeley California. Univ of. Davis California. Univ of. Irvine	800728044 8007280486 8007290622 8007300110 8007300419 8007310389	50-204 50-312 50-275 50-275 50-312	P G G
	8007010032* 8007010033* 8007010038* 8007010041* 8007010045* 8007010049*	50-397 50-397 50-397 50-397 50-397 50-397	A A A A		8007070277 8007250072 8007080353* 8007150615 8007150620*	50-224 FOIA PR 50-326 50-326	H R R
	8007010052* 8007010054* 8007010058* 8007010057* 8007010061*	50-397 50-397 50-397 50-397 50-397	A A A A	California, Univ of, Los Angeles Calvert County, MD	8007010619* 8007090197 8007160240 8007220308 8007210416	CONTRACT 50-142 50-142 50-3 50-317	G F Q E
	8007010064* 8007010069* 8007010073* 8007010076* 8007070290	50-397 50-397 50-397 50-397 TOPREP	A A A	Camp Dresser & McKee, Inc ,Environmental Sciences, Div Canada Capital Legal Foundation Carolina Environmental Study Group	8007110459* 8007110012* 8007080249 8007030034 8007030034	WASTE MG XPORTLIC PR 50-369 50-369	
C-E Operating Plants Owners Group C-E Power Systems	8007160109* 8007020557 8007020102 8007020105* 8007020107	QA979 50-255 71-6078 71-6078 70-1100	Р	Carolina Power & Light Co	8007030040# 8007030040# 8007010307 8007010324 8007010324	50-349 50-349 50-241 50-324 50-324	9 9 F F
	8007020108* 8007020112* 8007020114* 8007020115* 8007020574*	71-4078 71-4078 70-1100 71-6078 50-255			8007010342 8007010342 8007010352 8007010352 8007010352	50-324 50-324 50-400 50-400 50-400	F F F F
	8007020574* 8007020574* 8007020574* 8007020574* 8007020581*	50-255 50-255 50-255 50-255 50-255	ም የ የ የ		8007010352 8007010384 8007010401 8007010408 8007010410	50-400 50-261 50-261 50-261 50-261	F p & s & s
	8007020581* 8007020581* 8007020581* 8007020588*	50-255 50-255 50-255 50-255 50-255	P P P P		8007010416 8007010423 8007010423 8007010425 8007010425	50-325 50-324 50-324 50-324 50-324	P ያ G G
	8007020588* 8007020588* 8007020588* 8007020588* 8007020593*	50-255 50-255 50-255 50-255 50-255	P P P P		8007010431# 8007010431# 8007010461 8007010466 8007010901	50-324 50-324 50-241 50-241 50-325	9 9 8 8
	8007020593* 8007020593* 8007020593* 8007020593* 8007020597*	50-255 50-255 50-255 50-255 50-255	P P P P		8007010509* 8007010513 8007010514 8007010521* 8007010556	50-325 50-325 50-261 50-325 50-325	8 F 8
	8007020597* 8007020400* 8007020400* 8007020400* 8007020600*	50-255 50-255 50-255 50-255 50-255	9 P P P		8007010564* 8007020087 8007020334 8007020361* 8007020427	50-325 50-261 50-324 50-324 50-400	# O # # A
	8007020600* 8007030343 8007070351 8007080274 8007080285*	50-255 PR NUREQ TOPREP TOPREP	P		8007020427 8007020427 8007020427 8007020540 8007020563	50-400 50-400 50-400 50-324 50-324	A A S S
	8007090332* 8007090332* 8007090341* 8007090341* 8007090346*	50-317 50-317 50-317 50-317 50-317	P P P		8007070234 8007070237* 8007080180 8007080185* 8007080249	50-325 50-325 50-325 50-325 50-400	00 00 00 00
	8007090346* 8007090352* 8007090348* 8007100219	50-317 50-317 50-317 TOPREP	P P		8007080257* 8007100031 8007100297 8007100377*	50-400 50-261 50-400 50-324	G G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8007100418* 8007100422* 8007110405 8007110405 8007110406*	50-400 50-400 50-324 50-324 50-324	G G R R R		8007170655 8007170655 8007170655 8007170661 8007170661	50-400 50-400 50-400 50-400 50-400	K K K K
	8007110405* 8007140398 8007140399* 8007150097* 8007150492	50-324 50-324 50-324 50-261 50-324	R S G G		8007170461 8007170461 8007170463* 8007170463* 8007170463*	50-400 50-400 50-400 50-400 50-400	K C C C
	8007150535 8007150626 8007150629 8007150633* 8007150654	50-400 50-261 50-261 50-261 50-325	A ዮ ጽ ጽ		8007170663* 8007170672 8007170672 8007170672 8007170672	50-400 50-400 50-400 50-400 50-400	С К К К
	8007150665* 8007160377 8007160632 8007170366 8007170366	50-325 50-400 50-324 50-400 50-400	e e e		8007170677 8007170677 8007170677 8007170677 8007170678*	50-400 50-400 50-400 50-400 50-400	K K K C
	8007170366 8007170366 8007170367* 8007170367* 8007170367*	50-400 50-400 50-400 50-400 50-400	К К К		8007170478* 8007170478* 8007170478* 8007170464 8007170484	50-400 50-400 50-400 50-400 50-400	C C C K K
	8007170367* 8007170372 8007170372 8007170372 8007170372	50-400 50-400 50-400 50-400 50-400	K K K K		8007170684 8007170684 8007170686* 8007170686* 8007170686*	50-400 50-400 50-400 50-400 50-400	K C C
	8007170377 8007170377 8007170377 8007170377 8007170516	50-400 50-400 50-400 50-400 50-324	Ф К К		8007170484* 8007170487 8007170487 8007170487 8007170487	50-400 50-400 50-400 50-400 50-400	С К К К
	8007170516 8007170541 8007170541 8007170541 8007170541	50-324 50-400 50-400 50-400 50-400	д К К К		8007170490 8007170690 8007170690 8007170690 8007180428	50-400 50-400 50-400 50-400 50-400	K K K V
	8007170572 8007170572 8007170572 8007170572 8007170578	50-400 50-400 50-400 50-400 50-400	К К К К		8007210022 8007210415 8007220210 8007220227 8007220254	50-261 50-324 50-400 50-261 50-261	а Р О
	8007170578 8007170578 8007170578 8007170574 8007170594	50-400 50-400 50-400 50-400 50-400	к к к к		8007220260 8007220426 8007220429* 8007220433* 8007220435*	50-324 50-261 50-261 50-261 50-261	g>>>>
	8007170594 8007170594 8007170600 8007170600 8007170600	50-400 50-400 50-400 50-400 50-400	X X K K		800722043B* 8007220440 8007220445* 8007220456 8007220456	50-261 50-261 50-261 50-400 50-400	8
	8007170600 8007170615 8007170615 8007170615 8007170615	50-400 50-400 50-400 50-400 50-400	к к к к		8007220456 8007220456 8007220464 8007220470* 8007220521	50-400 50-400 50-324 50-324 50-324	A B S
	8007170627 8007170627 8007170627 8007170627 8007170628	50-400 50-400 50-400 50-400 50-400	K K K X A		8007220521 8007230247 8007230247 8007230247 8007230247	50-324 50-400 50-400 50-400 50-400	8 8 8
	8007170628 8007170628 8007170628 8007170639* 8007170639*	50-400 50-400 50-400 50-400 50-400	A A A A		8007240151 8007240189 8007240189 8007240196* 8007250296	PR 50-324 50-324 50-324 50-324	g g
	8007170639* 8007170639* 8007170643 8007170643 8007170643	50-400 50-400 50-400 50-400 50-400	А А К К К		6007250334 8007250341* 8007250420 8007280104 8007280111	50-324 50-324 50-261 50-260 50-324	8 8 9 0
	8007170643 8007170650 8007170650 8007170650 8007170650	50-400 50-400 50-400 50-400 50-400	К К К К		6007280507 8007280507 8007280507 8007280507 8007280513*	50-400 50-400 50-400 50-400 50-400	R R R R
	8007170652 8007170652 8007170652 8007170652 8007170655	50-400 50-400 50-400 50-400 50-400	C C C C K		8007280513* 8007280513* 8007280513* 8007280679 8007270686	50~400 50~400 50~400 50~261 50~261	R R R R P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	łΥ
	8007290690 8007290723 8007290823 8007290826	50-261 50-324 50-325 50-325	p p s s	Citizens Concerned About Nuclear Power, Inc	8007310123 8007310123 8007300415	50-445 50-445 50-498	G G
	8007290831*	50-325 50-325	s 6	Citizens for Energy & Employment	8007310145 8007080008	50-498 50-452	G
	8007270B33* 8007300561 8007300561 8007310206 8007310206	50-324 50-324 50-324 50-324	a a a	Citizens for Equitable Utilities Citizens for Safe Environment Citizens for a Better Environment	8007310145 8007210158 8007020175* 8007020203* 8007140337	50-498 WASTE MG 50-10 50-10 50-10	G H H Q
Carrier Corp Carrier Air Conditioning Div.	8007310306 8007310306 8007310449 8007310449 8007170236	50-324 50-324 50-324 50-324 50-518	0 0 0 5		9007190187* 8007180212* 8007220549 8007230649 9007260537	50-10 50-10 50-10 50-10 50-10	9 D D
	8007170247 7910150157	50-518 40-4669	8	Citazens for the Conservation of Natural Resources.Inc	8007140581	50-374	Q
Case Hestern Catalytic, Inc. (subs. of Air Products &	8007030099	40-4669 REGGD		Cleveland Electric Illuminating Co	8007230791 8007080294	50-376 50-440	6
Chemicals, Inc)	6007160230	REGOD			8007140534 8007150540	50-440 50-440	8 A
Center for Law & Social Policy Center for Law in the Public Interest	8007310237 8007020136 8007140228 8007230508 8007300096	FOIA FOIA FOIA 50-275 50-275	o o		8007150553 8007150553 8007160598 8007180406 8007180585*	50-440 50-440 50-440 50-440 50-440	0 0 0 0 0
Central & South West Corp Central Electric Power Cooperative. Inc Central Maine Power Co Central Vermont Public Service Corp Cerac. Inc	8007150431 8007250485 8007080016* 8007080018* 8007020379	50-445 50-375 50-443 50-443 XPORTLIG	M M I I		6007180585* 8007180591* 8007180591* 8007230101 8007230101	50-440 50-440 50-440 50-440 50-440	0 0 0 0
Chem-Nuclear Systems, Inc	8007010482 8007100461 8007160417 8007170446* 8007170452*	27-47 71-9094 71-9070 50-320 50-320	P P	Cleveland, OH Cleveland-Cliffs Iron Ca	8007230321* 8007230321* 8007290533 8007140875 8007290849	50-440 50-440 50-344 50-346 40-8200	G G M M
	8007170455* 8007170458* 8007170464* 8007170466* 8007170473*	50~320 50~320 50~320 50~320 50~320	ե ե ե	Colorado State Univ	8007310457 8007170297* 8007170302* 8007170308* 8007170327*	40-8402 40-8602 40-8602 40-8602 40-8681	
	8007170478* 8007170482* 8007170488* 8007170490* 8007170499*	50-320 50-320 50-320 50-320 50-320	ր թ թ		8007170331# 8007170332# 8007170335# 8007210177 8007210183	40-8691 40-8691 40-8681 40-8452 40-8452	
	8007170502* 8007170505* 8007170511* 8007170521* 8007170533*	50-320 50-320 50-320 50-320 50-320	6 6 6 6		8007230135 8007230725* 8007280066 8007280070 8007280073	40-8452 40-8452 40-9602 40-9681 40-8452	
Chemtron Corp Chemtron Corp , Tube Turns Div Chen & Associates, Inc	8007170535* 8007160478* 8007230100 8007210079 8007210143	50-320 50-320 40-7402 PT21 40-2259	н Н	Colorado, State of Colt Industries, Inc	8007010274* 8007020359 8007210160* 8007090270* 8007090275*	WASTE MOT WASTE MOT CONTRACT 50-352 50-352	T
Chavron Research Co Chickering & Gregory	80071 00133 8007140034*	REGOD 50-361	0	Colt Industries, Inc . Fairbanks Morse Engine Div	6007010357	50-395	8
Christa-Maria	8007300359 8007100037* 8007100042*	50-361 50-155 50-155	0 0 0	Combustion Engineering, Inc	8007010459 8007020103* 8007090361* 8007100210	50-375 70-1100 50-317 TOPREP	8
Cincinnati Gas & Electric Co	8007010084 8007070258 8007080317 8007080374 8007140359	50-358 50-358 50-358 50-358 50-358	9 F A Q K		8007100212* 8007110243 8007110248* 8007140037* 8007180496*	TOPREP TOPREP TOPREP GA999 TOPREP	
	8007140377* 8007150108* 8007210302* 8007210313 8007210424	50-358 50-358 50-358 50-358 50-358	к а а к	Commerce,Dept of Commerce,Dept of, National Oceanographic (8007250057* 8007260737* 8007020553* 8007240381 9007240409	QA999 70-1100 CONTRACT PR NUREQ	ı
	8007220280 8007230437 8007250576 8007250616 8007280096	50-358 50-358 50-358 50-358 50-358	A G G G G	Atmospheric Adminstration Committee for Application of Nuremberg Principles to US Nuclear Power Production Commonwealth Edison Co	8007110001 in 8007010190	50-498 50-237	r
Citizens Against Nuclear Power Citizens Association for Sound Energy	80 07250369 80 07090327 80 07220546 80 07220546	50-10 50-445 50-445 50-445	D G G G		8007010190 8007010211 8007010211	50-297 50-295 50-295 50-10	P P P
	8007220559 8007220559 8007300366 8007300366	50-445 50-445 50-445 50-445	G G G Q		8007010347 8007010347 8007010347 8007010347	50-10 50-10 50-10 50-10	F F F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATIO	N	ACCESSION NUMBER	SUBJECT CATEGOR	IY
	8007010347 8007010347 8007010411 8007010428 8007010484	50-10 50-10 50-454 50-295 50-295	F F A P			8007180333 8007180333 8007180333 8007180336* 8007180336*	50-10 50-10 50-10 50-10 50-10	R R R R
	8007010488* 8007010493 8007010497 8007010500* 8007010505*	50-295 50-295 50-237 50-295 50-237	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5			8007180336* 8007180560 8007180560 8007180579* 8007180592	50-10 50-3 50-3 COMMI88I 50-3	R G O O O
	8007010544 8007010551* 8007020050 8007020074 8007020076	50-237 50-237 50-295 50-247 50-295	8 8 0 0			8007180592 8007210212 8007210212 8007210212 8007210292*	50-3 50-237 50-237 50-237 50-373	Q P P Q
	8007020076 8007020368 8007020408 8007020408 8007020408	50-295 PR 50-454 50-454 50-454	Q К К К			8007210272* 8007220352 8007220354* 8007220357* 8007220359*	50-373 TOPREP TOPREP TOPREP TOPREP	a
	800702040B 8007020420* 8007020420* 8007020420* 8007020420*	50-454 50-454 50-454 50-454 50-454	к к к к			8007220361* 8007220387 8007220391* 8007220399 8007220400	TOPREP 50-304 50-304 50-295 50-295	8 8 8
	B007020462 B007020631 B007020631 B007020756 B007070116	50-599 50-454 50-454 50-249 50-10	9 9 9			8007220401 8007220402 8007220404 8007220405 8007220406	50-295 50-295 50-295 50-295 50-304	8 8 8
	8007070116 8007070116 8007070267 8007070267 8007070345	50-10 50-10 50-373 50-373 50-237	Р Р К Х Р			8007220409 8007220409 8007220411 8007220412 8007220413	50-304 50-304 50-304 50-304 50-304	8 8 8 8
	8007070345 8007070345 8007080063 8007080162 8007080172*	50-237 50-237 50-10 50-245 50-245	P P P B			8007220414 8007220449 8007220453* 8007220455 8007220459*	50-304 50-295 50-295 50-249 50-249	\$ 6 \$ \$ \$ \$
	8007080248 8007080277 8007080277 8007080277 8007080277	TOPREP 50-454 50-454 50-454 50-454	к к к			8007220518 8007220540 8007220557 8007220572* 8007220577	50-373 50-454 50-237 50-237 50-249	A 8 8
	8007100004 8007100004 8007100004 8007100130 8007100142	50-10 50-10 50-10 PRM 50-254	Q Q Q			8007220583* 8007220587 8007220593* 8007230187 8007230281*	50-249 50-304 50-304 PR 50-373	6 8 9
	8007100142 8007100147* 8007100147* 8007100179 8007100187	50-254 50-254 50-254 50-237 50-237	8 6 6			8007230339 8007230345 8007230347 8007230351 8007230352	50-237 50-295 50-295 50-295 50-295	9 8 9
	8007100189* 8007100192* 8007100343 8007110206* 8007140235	50-237 50-237 PRM 50-10 PRM	d 8 8			8007230357 8007230359 8007230397 8007230678* 8007240105	50-295 50-249 50-245 50-10 50-254	8 8 8 8
	8007140320 8007140327 8007140327 8007140328* 8007140331*	50-454 50-295 50-295 50-454 50-295	К Я К Я			8007240107# 8007240112 8007240114* 8007240298* 8007240351#	50-254 50-265 50-265 50-249 50-456	8 8 Q Q
	8007140331* 8007150476 8007150476 8007150529 8007150616	50-295 50-295 50-295 50-373 50-254	R P P A J			8007240351# 8007250448 8007250455# 8007250467 8007250638	50-454 50-373 50-373 50-373 50-10	A A G
	8007150619 8007150619 8007150625* 8007150625* 8007160559	50-254 50-254 50-254 50-254 50-454	R R R R			8007250638 8007250638 8007250638 8007250638 8007250638	50-10 50-10 50-10 50-10 50-10	0 0 0
	8007160606 8007160627 8007160630 8007160630 8007160635	50-373 50-599 50-237 50-237 50-295	A C Q Q			8007250641 8007250641 8007250641 8007250641 8007250641	50-10 50-10 50-10 50-10 50-10	0 0 0
	8007140442* 8007140448 8007140472* 8007180010* 8007180034*	50-295 50-304 50-304 50-10 COMMISSI	8 8 8			8007250641 8007250641 8007250650 8007250650 8007250650	50-10 50-10 50-10 50-10 50-10	0 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8007250490 8007250450 8007250490 8007250450 8007280074	50-10 50-10 50-10 50-10 50-254	G G G G		6007090279 6007110396 6007110404# 6007140375 8007150669	50-3 50-247 50-247 NUREG 50-3	P S S
	8007280470 8007280474* 8007280567 8007280595 8007280605	50-265 50-265 NUREG 50-10 50-295	P P D	•	9007170287 8007170363 8007170363 8007170363 8007170365+	50-3 50-3 50-3 50-3 50-3	G R R R
	8007280405 8007280470 8007280488* 8007290478 8007290498	50-295 50-454 50-373 50-454 50-373	P 5 Q K A		8007170365* 8007170365* 8007210473 8007210473 8007220160	50-3 50-3 50-3 50-3 50-247	R R R Q
	8007290709 8007300469 8007300485 8007300485 8007300485	50-254 PR 50-237 50-237 50-237	J a a a		8007220160 8007220454 8007220476 8007220479* 8007220504	50-247 50-247 50-247 50-247 50-247	9225
	8007310353 8007310353 8007310357 8007310432 8007310480	50-254 50-254 50-254 50-10 50-249	G G G G		8007220523 8007220523 8007220523 8007220524* 8007220524*	50-3 50-3 50-3 50-3 50-3	R R R R
Conference of Radiation Control Program Directors, Inc	8007310486* 8007310533* 8007280170*	50-249 50-373 COMMISS	10N G Ø		8007220524* 8007230044 8007230471 8007240127	50-3 PR 50-247 50-3	R P I
Congress (Joint & Rotating Committees, etc.)	80073 0 0018 80061 70 304	PR Misc			6007240127 6007240129#	50-3 50-3	1
Connecticut Light & Power Co Connecticut Yankee Atomic Power Co	8007110363 8007080040* 8007010337 8007010337	50-320 50-443 50-213 50-213	U I F F		8007240169 8007240172* 8007290522 8007290682	50-247 50-247 50-247 50-3	S G H
	8007010337 8007020472 8007020569 8007020569 8007030356	50-213 PR 50-213 50-213 50-245		Consolidated Rail Corp Consumers Power Co	8007030341 8007010200 8007010313 8007010447 8007010451#	PR 50-155 50-155 50-155 50-155	е Q Р
	8007030354 8007030354 8007080077 8007090231 8007090321	50-245 50-245 50-213 50-213 50-213	F 5 F 5	•	8007010473 8007020224 8007020305 8007020649 8007030250	50-155 PR 50-329 50-255	F G G P
	8007090326* 8007100035 8007140355 8007140359	50-213 PR 50-213 50-213	s I s		8007030251# 8007030269 8007070119 8007070210 8007080189	50-255 50-155 50-327 50-155 50-255	P P A P
	8007160369 8007170320 8007170425 8007170494 8007180390	50-213 50-213 50-213 50-213 50-213	G G F G R		8007080197* 8007080338 8007080346 8007080346* 8007090008	50-255 50-255 50-155 50-155 50-255	SI P R P
	8007180375* 8007180578 8007210237 8007230411 8007240053	50-213 50-213 50-213 50-213 50-213	R Q P Q		8007090010# 8007090045 8007090314 8007090319# 8007100092	50-255 50-327 50-255 50-255 PR	P 9 8
	8007240058* 8007240062* 8007240067 8007240070* 8007250535	007240058* 50-213 007240062* 50-213 007240067 50-213 007240070* 50-213	P P ያ		8007100197 8007100201* 8007100204* 8007110204 8007110209*	50-255 50-255 50-255 50-155 50-155	6 6 6
	8007270852 8007300324 8007300331* 8007300338* 8007300342*	PR 50-213 50-213 50-213 50-213	P P P		8007110210* 8007110297 8007110301* 8007110358	50-155 50-255 50-255 50-255	6 % % b
Connecticut, State of	8007010478 8007020556	NUREG PR	г		8007110409 8007110414* 8007140004	50-255 50-255 50-369	R R O
Conner, Moore & Corber	8007030113 8007160858* 8007020407 8007130058	PR COMMISS PR 27-39			8007140004 8007140007# 8007140010#	50-369 50-369 50-369	0
Consolidated Edison Co of New York	8007150509 8007310424 8007010081 8007010081	50-272 50-375 50-3 50-3	M Q Q		8007140010* 8007140020 8007140020 8007140310 8007140350	50-369 50-329 50-329 50-255 50-255	9
	8007020077 8007020077 8007030050*	50-3 50-3 PR	Q Q		8007140391 8007140391 8007140392	50-155 50-155 50-3	F F P
	8007090228 8007090251	50-247 50-247	b b		8007140424 8007140444	50-155 50-155	G G

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEOGRY
	8007140543 8007150052 8007150134 8007150497 8007150497	PR 50-155 PR 50-329 50-329	Ф А А		8007140571 8007140477 8007160481* 8007170348 8007180092	50-409 G T 50-409 R 50-409 R 50-409 G
•	8007150664 8007150803 8007160458 8007160505 8007160612	50-155 50-255 50-155 50-255 50-329	а е е Р		8007180355 8007180362 8007210447 8007220096 8007220525	50-409 Q 50-409 Q 50-409 P 50-409 Q 50-409 P
	8007180424 8007210273 8007210374 8007210427 8007210440*	50-155 PRM 50-255 50-255 50-255	0 R R R		8007280050 8007280696* 8007290480 8007300244 8007310434	50~409 G 50~409 G 50~409 G 50~409 I
	8007210483 8007210483 8007220194 8007220341 8007220452	50-329 50-329 50-329 50-155 50-155	A O F Q	Dames & Moore	8007310443* 8007210170* 8007220042* 8007220049* 8007220526*	50-409 I 40-4492 Habte Mot Habte Mgt 50-409 P
	8007220472 8007220478 8007220484* 8007220513 8007220566	50-155 50-255 50-255 50-255 50-155	e 8	Darling Valve & Mfg Dartmouth College Davy McKee Corp	8007240156* 8007240159* 8007300399 8007240011* 8007240013*	50~339 P 50~339 P TOPREP 40~8452 40~6452
	8007230395 8007230460 8007230465 8007230473 8007230478	50-255 50-255 50-155 50-255 50-155	Q Q Q P F	Dawn Hining Co De Laval Turbins Inc	8007240013* 8007240022* 8007150045 8007210485* 9007210485*	40~8452 40~8452 Warte Mot 50~445 A 50~445 A
	8007230479# 8007230484* 8007230516 8007230810 8007240017	50-155 50-331 50-155 50-255 50-155	F P G G		8007210490* 8007210490* 8007210496* 8007210496* 8007210500*	50-445 A 50-445 A 50-445 A 50-445 A 50-445 A
	8007240136 8007240146 8007240146 8007250373 8007280041	PR 50-329 50-329 50-155 50-329	K K G A		8007210500* 8007210504* 8007210504* 8007210508* 8007210508*	50-445 A 50-445 A 50-445 A 50-445 A 50-445 A
	8007280040 8007280040 8007280124 8007280533 8007280570	50-329 50-329 50-329 50-155 50-155	A A R P F		8007210510* 8007210510* 8007210514* 8007210514* 8007210517*	50-445 A 50-445 A 50-445 A 50-445 A 50-445 A
	8007280570 8007280597 8007290206 8007290606 8007290614	50-155 50-155 50-327 50-155 50-255	F J 8 0 6		8007210517* 8007210519* 8007210519* 8007210527* 8007210527*	50-445 A 50-445 A 50-445 A 50-445 A 50-445 A
	8007290616# 8007290630 8007290691 8007290701 8007300439	50-255 50-255 50-155 50-329 50-155	g q q A F	Debevoise & Liberman	8007030246 8007100290 8007140004 8007140243 8007160625	50-445 G PRM 50-369 G FOIA 50-445 M
	8007310177 8007310422 8007310425* 8007310488 8007310529*	50-255 50-155 50-155 FOIA 50-329	0 1 1	Defense,Dept of, Defense Nuclear Agency	8007180437 8007240140 8007290887 8007310328 8007150342	50-445 G PR PR 50-445 G REGOD
Contra Costa Industrial X-Ray Co Contra Costa Inspection Co Cooperative Power Association	8007310529* 8007220279 8007290277 8007290282* 8007010421	50-329 71-9039 71-6717 71-6717 50-484	1	Delaware, State of Delta Ewitchboard Co Dennison: A B Detroit Edison Co.	8007140043 8007140564 8007210527* 8007110094 8007070098*	PR PR 50-445 A 50-358 Q 50-341 S
Coordination Council for North American Affairs	8007170242*	XPORTLIC			8007140326 8007140378*	50-341 B 50-452 0
Corning Olass Works. Zircoa Products Div Cotter Corp Coulse Region Energy Coalition Countil of Energy Resource Tribes	8007250343 8007210104 8007140227* 8007030158	40-2561 WASTE MG 50-409 PR	т н		8007140425 8007140481* 8007160687	50-341 0 50-341 0 50-341 A
Council on Environmental Quality Grane Co Creare, Inc Critical Hass Energy Project	8007090148* 8007220121* 8007240161* 8007220334* 8007280274	PR 50-599 50-339 TOPREP FOIA	Ø P	Doggett, 8 A Doherty, J F	8007210136* 8007220545 8007100174 8007030339	50-341 8 50-341 8 50-466 9 50-466 A
Cyprus Mines Corp D'Appolonia Consulting Engineers, Inc	8007020281 8007020708 8007020712* 8006240082*	WASTE MO WASTE MO WASTE MO 40-1162	Т	Donovan, Hamester & Rattien, Inc Dow Chamical Co Dow Chamical Go , Dow Chemical U.S A Div	8007230246 8007070054# 8007250476 8007250705	50-466 Q CONTRACT TOPREP PR
DRG International, Inc	8007290982	XPORTL1C		Duke Power Go	B006050319	8 946-05
Daedalean Associates, Inc Dairyland Power Cooperative	8007230231 8007020679 8007080300 8007140305	REB 50-409 50-409 50-409	Q Р Р		8007010045 8007010205 8007010205 8007010205	50-269 G 50-269 F 50-269 F 50-269 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	JRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
,	8007010309 8007010340 8007010360 8007020537 8007020575	50-369 50-269 50-269 50-413 50-269	F P P S P		8007220192 8007220192 8007220245 8007220245 8007220245	50-249 0 50-249 0 50-249 0 50-269 0 50-269 0
	8007020575 8007020575 8007020648 8007030087 8007030185	50-269 50-269 PR PR 50-413	P P		6007220365 8007220424 8007220427* 8007220477 8007220483*	50-349 ^ 50-269 - 50-269 8 50-269 P
	8007030185 8007030186 8007030189* 8007030189* 80070700043	50-413 PRM 50-413 50-413 PR	A A		8007220536 8007220561 8007220563 8007220563 8007220563	50-369 A 50-257 P 50-269 S 50-269 S
	8007070319 8007070319 8007070319 8007070323* 8007070323*	50-269 50-269 50-269 50-269 50-269	\$ \$ \$ \$ \$ \$ \$		8007240357 8007240359 8007240469 8007250166 8007250166	50~369 0 PR 50~369 0 50~269 0
	8007070323* 8007080201 8007080207* 8007080223 8007080223	50-269 50-270 50-270 50-269 50-269	8 5 6 P		8007250166 8007250532 8007250578 8007280068 8007280416	50-269 û 50-488 û 50-369 û 50-269 û
	8007080223 8007080345 8007090271 8007090271 8007090276*	50-269 50-369 50-269 50-269 50-269	P A P P P		8007280427 8007280427 8007280430* 8007280430* 8007280437	50-270 P 50-270 P 50-270 P 50-270 P 50-269 P
	8007070276# 8007070402 8007100036 8007100139 8007100419#	50-269 PR 50-369 50-270 50-413	P Q Q Q		8007280437 8007280437 8007280438* 8007280438* 8007280438*	50-269 P 50-269 P 50-269 P 50-269 P
	8007110294 8007110294 8007110294 8007110309 8007110331*	50-269 50-269 50-269 50-369 50-269	P P A P		8007280501 8007280544 8007290267 8007290635 8007290640*	50-413 S 50-269 P 50-270 0 50-287 S 50-287 S
	8007110331* 8007110331* 8007110340 8007110342* 8007140083	50-269 50-269 50-269 50-269 NUREO	P P S S		8007290824 8007290830* 8007300330 8007300330 8007300355	50-270 8 50-270 8 50-369 8 50-369 8 50-369 8
	8007140397 8007140463 8007140463 8007140463 8007150015	50-269 50-269 50-269 50-269 50-269	P Q Q Q		8007300459 8007310379 8007310379 8007310381* 8007310381*	50-349 A 50-249 P 50-249 P 50-249 P 50-249 P
	8007150575 8007150575 8007150583* 8007150583* 8007160514	50-269 50-269 50-269 50-269 50-413	6 6 6	Duquesne Light Co	8007310382* 8007310382* 8007310491 8006230660 8007010336	50-269 F 50-269 F 50-270 G 50-334 G 50-334 F
	8007160514 800716051B* 8007160657 8007160657 8007160663*	50-413 50-413 50-369 50-369 50-369	S S S S		8007010348 8007010395 8007010396 8007010400* 8007010456*	50-412 0 50-334 P 50-334 8 50-334 9 50-334 8
	8007160463* 8007170105 6007180321 8007180326* 8007180349	50-369 PR 50-270 50-270 50-270	s s o		9007010524 9007010534* 9007020546 9007020547* 9007070296	50-334 B 50-334 B 50-334 R 50-334 R 50-334 \$
	8007180417 8007180533 8007180533 8007180533 8007210114	50-287 50-269 50-269 50-269 50-369	ត ០ ០ ០ ០		8007080080 8007080084* 8007080186 8007080276 8007080424	50~334 # 50~334 # 50~334 # 50~334 0
	8007210114 8007210241 8007210385 9007210417 8007210421*	50-369 50-413 50-369 50-269 50-269	Q Q A 8 5		8007090334 8007090338* 8007090340 8007090348* 8007150480	50-334 9 50-334 9 50-334 9 50-334 9
	8007210425 8007210426* 8007210459 8007210470* 8007210476	50-270 50-270 50-269 50-269 50-413	P P S 6 A		8007150483 8007150547 8007150643 8007140480 8007140555	50-334 0 50-334 0 50-334 P 50-334 P
	8007210486* 8007210486* 8007210609 8007210617* 8007220192	50-413 50-413 50-287 50-287 50-249	A A S B Q		8007160564* 8007160375 8007160647 8007160654* 8007170546	50-334 P 50-334 Q 50-334 Q 50-334 Q

AUTHOR AFFÎLIATION	ACCESSION NUMBER	SUBJEC	RΥ	AUTHÚR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8007180055 8007180317 8007180322* 8007180418 8007180422*	50~412 50~334 50~334 50~334 50~334	G S R R	Ed L. Reed & Associates, Inc Edison Electric Institute Ediow International Co	8007110462* 8007020671 8007100180* 8007210168 8007240434	WASTE M PR PR PR PR XPORTLI	
	8007210011 8007210016 8007220430 8007220434 8007220506	50-334 50-412 50-334 50-334 50-334	0 9 9 9	Eichhorn,Eichhorn & Lint Electric Power Research Institute	8007310018 8007310503* 8007310506* 8007020453 8007010233*	XPORTLI FOIA FOIA 50-367 FOIA	c o
	6007220588 6007230150* 6007250294 6007250318 8007250324*	50-334 50-334 50-334 50-334 50-334	0 0 8	Elyriæ Memorial Hosp Elyria, CH Energy Products Group Energy, Dept of	8007140398* 8007100194 8007160457 8004110523 8007010013	50-3 REGOD NUREG PR ORG	P
	8007250331 * 8007270540 8007270643 8007270680 8007300383	50-334 50-412 50-334 50-334 50-334	8 R P G 8		8007010017* 8007020435 8007020493* 8007030084 8007090098	ORG PR 50-281 PR PR	н
E L Conwell & Ca EDS Nuclear, Inc	8007300388* 8007020450 8007020452* 8007300498* 8007300498*	.50-334 71-361 71-361 50-237 50-237	9 0		8007090103* 8007100024 8007100094 8007110451 8007140190*	PR PR PR PRM 50-247	P
	8007300498* 8007300498* 8007300508* 8007300508* 8007300508*	50-237 50-237 50-237 50-237 50-237	Q Q Q Q		8007150074* 8007170051* 8007170370 8007180444* 8007220030*	8ECY 50-204 50-344 50-339 50-564	H H H
EQLO Idaho.Inc	8007300508# 8007300508# 8007030015 8007140072 8007150059	50-237 50-237 REB NUREO REB	9		8007240090 8007240094* 8007240154 8007280140* 8007300234	71-5607 71-5607 71-9132 50-289 PR	¢
	8007150409 800722003B 800722004S	838 E45-08 838	P	Energy Dept of, Clinch River Breeder Reactor Plant	8007300411 8007010366	PR 50-537	F
	8007220065 8007230172	RES 50-334	Р		8007030179 8007080264 8007100194	PR 50-537 50-537	B F
	8007230177 8007230185 8007230194 8007230205	RES RES RES NUREO		Energy, Dept of, Idaho Operations Office Engineering Decision Analysis Company, Inc	8007270174 8007220353#	RES 50-70	P
	8007230425 8007250184	NUREG 50-313	p		8007220356# 8007220362# 8007220366#	50-70 50-70 50-70	Р Р Р
	8007250304 8007280164 8007280171 8007280174	50-325 AEB AEB REB	P	Environmental Coalition on Nuclear Power Environmental Policy Institute	6007220367* 8007280606* 8007070275 8007080086 8007030107	50-70 TOPREP 50-320 50-320 PR	P @ @
	8007280186 8007290163 8007290180 8007290191	RES 50-324 RES RES	P	Environmental Protection Agency	9007020400 9007110026 9007230594 9007250600	PR PR 50-409 40-1162	D
EQ8G, Inc.	8007290201 8007290226 8007310007 8007310255 8007030208*	RES RES NUREO NUREO 50-285	P	Essex Corp.	8007290696 8007290696 8007090163 8007090166*	PR 50-10 NUREO NUREO	p
	8007100363 8007210017 800721003	NUREG REB REB		Euratom Supply Agency (Selgium) European Communities, Commission of	8007070167* 8007150036 8007170229	NUREG XPORTLIC XPORTLIC	
Eastern Utilities Associates Eastman Kodak Co	8007280508 8007080020#		I	Exxon Minerals Co : USA	8007240447 8007170679 8007280047	XPORTLIC 40-8102 40-8102	
Ebasco Barvices: Inc. (subs of Enserch Corp) Eberline Instrument Corp	8007010244 8007020326# 8007170129#	40-8438 50-335 CONTRACT		Exxon Nuclear Co , Inc (wubs of Exxon Corp)	7909210176	REGOD	
Eckert, Seamans, Cherin & Mellott Ecolaire Condenser, Inc	8007220560 8007250685 8007310398	XPORTLIC XPORTLIC 50-289	: :		8007020701 8007070004 8007070006* 8007070008* 8007070402	PR XPORTLIC XPORTLIC XPORTLIC PR	;
Ecology Action of Diwago	8007080046 8007080046 8007080046 8007080046	50-320 50-320 50-320 50-320 50-320	0		8007110215 8007110341 8007140386 8007240224	TOPREP TOPREP 71-6381 XPORTLIC	
	8007080046 8007080048 8007080048 8007080048	50-320 50-320 50-320 50-320	0000	Para Lauri - Tri	8007240247* 8007280009 8007290733	PR TOPREP	
	8007080048 8007080048	50-320 50-320	0	Farm Legal - TN Federal American Partners	8007140691 8007020013 8007100084	PR 40-4492 40-4492	
	8007080048 8007310128	50-320 50-277	Ģ Ģ		9007100087 8007210169	40-4492 40-4492	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTH(AFFILIA	T 1 0N	ACCESSION NUMBER	SUBJECT CATEGOR	
Federal Emergency Management Agency Federal Energy Regulatory Commission Firex Corp	8007090025* 8007140079* 8007240040 8007100218 8007090398	SECY 10CFR 50-369 50-10 REGGD	F D	Florida Power Corp	* ** # ** ** ** ** ** ** ** ** ** ** ** *	8007010355 8007010463 8007020387 8007020242 8007070327	50-302 50-302 50-302 50-302 50-302	9 9 9
Fitchburg Gas & Electric Light Co Fleischaker, D S Florida Cities	8007080017* 8007100198 8007230508 8007300096 8007090051	50-443 50-275 50-275 50-275 50-369	I G G M			8007080075 8007080259 8007100101 8007100153 8007110122	50-302 50-302 REGGD 50-302 50-302	p F p
Florida Power & Light Co	8007230778 8007010483 8007010491* 8007020296 8007020321*	50-389 50-335 50-335 PR 50-335	M S S			8007110402 8007110410× 8007150385 8007150484 8007150503*	50-302 50-302 50-302 50-302 50-302	5 S P P Q
	8007030221 8007070100* 8007080140 8007080284 8007080290*	50-335 50-335 50-250 50-335 50-335	P Q P S S			8007150598 8007150708 8007150713* 8007180294 8007180313	50-302 50-302 50-302 50-302 50-302	0 R R P
	8007080330 8007080335* 8007090284 8007109021 8007100025	50-335 50-335 50-335 50-335 50-250	R R P G			8007180384 8007180540 8007210203 8007220383 8007230193	50-302 50-302 50-302 50-302 PR	ն () ե
	8007100128 8007110199 8007110199 8007110254 8007110261	50-250 50-250 50-250 50-250 50-250	Q Р Р Р			8007230562 8007230573* 8007240074 8007240382 8007250326	50-302 50-302 50-302 50-302 50-302	0: 0: P 0: P
	8007110241 8007140364 8007140372* 8007140382 8007140389*	50-250 50-335 50-335 50-335 50-335	P 8 8 8 8	Fluor Power Service,)	Inc	8007250330* 8007280127 8007280133* 8007280373 8007220234*	50-302 50-302 50-302 50-302 50-305	6 6 6 F F
	8007150532 8007150536* 8007150627 8007150636* 8007160375	50-335 50-335 50-335 50-335 50-250	S S G	Foster Wheeler Corp Foundation Sciences, In Fox Industries Frankhauser, D D Frankin Institute/Fra Center		8007290858 8007170568* 8007010236 8007220565 8007070368	PR 50~344 TOPREP 50~358 50~338	R G P
	9007160599 8007160810# 8007210060 8007210064 8007210064	50-387 50-335 50-387 50-250 50-250	9 0 0	Friends of the Earth Gage-Babcock Associate Gambia	es. Inc	8007310265* 8007110506 8007140034* 8007150119 8007310028	FOIA 50-320 50-361 PR XPORTLIC	P O
	8007220069* 8007220374 8007220379 8007220380 8007220419	50-335 50-335 50-335 50-250 50-250	0 P G P S	Gasser Associates,P A Gaston County,NC General Atomic Co (su	bs of Gulf Gil	8007180193* 8007140461 8007140473* 8007140486* 8007020205	CONTRACT 50-269 50-269 50-269 PR	9
	8007220543 8007220543 8007220550#	50-250 50-250 50-250	R R R	Co) General Atomic Co (su	ubs of Gulf Oil	8007100046 8007020084	PR XPORTL10	;
	8007220550* 8007230181 8007230442 8007230442 8007230454	50-250 PR 50-250 50-250 50-250	R F F	Corp) General Electric Co		8004190915 8007010090* 8007010092*	71-9139 50-397 50-397	A
	8007230454 8007230798 8007240075 8007240075	50-250 50-389 50-250 50-250	F M R R			8007010095* 8007010098* 8007010349 8007010507 8007010595	50-397 50-397 TOPREP TOPREP 71-5980	A
	8007240086* 8007240086* 8007240174 8007240174	50-250 50-250 50-250 50-250	R R R			8007010598* 8007010600* 8007010602* 8007010603* 8007010605*	71-5980 71-5980 71-5980 71-5980 71-5980	
	8007240177* 8007240177* 8007240263* 8007250272	50-250 50-250 50-250 50-335	R R G			8007020611* 8007030231* 8007070067 8007070249	70-130B 70-1113 PR GEN TEC	18
	8007250282 8007250282 8007250312 8007280531	50-250 50-250 50-335 50-250	Q Q P			8007090212 8007090310 8007100135 8007100191*	70-1113 TOPREP REGGD PR	
	8007280531 8007280562 8007280562 8007280647 8007290624	50-250 50-250 50-250 50-335 50-335	P P F F			8007110498* 8007110503* 8007140038 8007140048*	BECY BECY 70-1308 10CFR	٠.
	8007300558 8007300558 8007310084	50-250 50-250 50-250	Q Q Q			8007140354 8007140426 8007140450*	TOPREP TOPREP 50-331	ę.
	8007310084 8007310220*	50-250 50-389	G G			8007140946* 8007150031*	SECY 70-1113	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJE CATEO	
	8007150033# 8007150104 8007150407 8007150724 8007160360	70-1113 PR RES TOPREP 50-70	P		8007110429 8007110432 8007110437* 8007110442* 8007110455	50-344 50-321 50-321 50-321	. 8 8
	8007140703* 8007140709* 8007170574* 8007180123* 8007180440	50-341 50-341 50-260 50-277 71-9136	A A P P		8007110463# 8007110521# 8007140357 8007140364 8007150133	50-321 50-424 NUREQ 50-321 PR	Q
	8007180470* 8007210364 8007220138 8007220147 8007220168	71-9136 TOPREP 70-1308 70-1308 70-1308			8007150494 8007150506* 8007150539 8007150544* 8007150635	50-321 50-321 50-321 50-321 50-366	8 8 8
	8007220170 8007220329 8007220349 8007250515 8007250567*	70-1308 TOPREP 50-70 TOPREP GA999	Р		8007150642* 8007150666 8007150674* 8007150678 8007150685*	50-346 50-321 50-321 50-366 50-346	8888
	8007280058 8007280131 8007280407 8007280577 8007280579	71-170 XPORTLIC XPORTLIC 50-70 TOPREP			8007170382 8007170387* 8007170392 8007170405 8007170408*	50-321 50-321 50-321 50-366 50-321	8 8 8 8
General Electric Co . Nuclear Energy Products Div	8007280637 8007310042 8007310044 8007310270# 8007210391	50-70 XPORTLIC XPORTLIC FOIA NUREO			8007170410* 8007170414 8007170419* 8007170451 8007170453	50-366 50-321 50-321 50-321 50-366	8 8 8
General Motors Corp General Public Utilities - GPU Service	8007280077 8007310066 8007280360 8007280366* 8007030334	71-4986 XPORTLIC XPORTLIC XPORTLIC 50-320			8007170469* 8007170469* 8007170491 8007170497* 8007210370	50-321 50-366 50-321 50-321 50-321	8 8 8
Corp Quo-Genters, Inc	8007150730 8007160670 8007240367 8007160498*	50-320 50-289 PR CONTRACT			8007210371# 8007210384 8007210384 8007210393 8007210397#	50-321 50-321 50-321 50-366 50-366	8 8 8 8
Georgia Power Co	8007010474 8007010474 8007010503* 8007010510 8007010518*	50-321 50-364 50-366 50-366 50-366	P		8007210484 8007210492* 8007220275 8007220281 8007220281	50-321 50-321 50-424 50-321 50-321	8 0 0
	8007020218 8007020342 8007020520 8007020523* 8007020628 8007020628	50-424 PR 50-366 50-366 50-321 50-321	9 8 8 P		8007220422 8007220514 8007220519* 8007240124 8007240128*	50-321 50-321 50-321 50-366 50-366	8 8 8
	8007020638 8007020642* 8007030261 8007030261 8007030272	50-321 50-321 50-321 50-321 50-346	***************************************		8007240165 8007240167# 8007240264# 8007250292 8007250292	50-344 50-344 50-321 50-321 50-321	8 0 0
	8007030274* 8007030276 8007030277 8007030278* 8007030279*	50-366 50-321 50-366 50-321 50-366	8 6 8 8 8 8		8007250411 8007250412# 8007280128# 8007280445 8007280446#	50-366 50-366 50-321 50-321 50-321	8 0 8
	8007030280 8007030282* 8007030284 8007030286* 8007080287	50-346 50-346 50-321 50-321 50-321	8 8 9 8		8007280448 8007280449* 8007280450 8007280455* 8007280505	50-321 50-321 50-366 50-366	8 8 8
	8007080287 8007080322 8007080327* 8007080344 8007090074	50-321 50-321 50-321 50-424 50-321	Р Р Р Н		8007280512* 8007280514 8007280518 8007280526* 8007280538	50~366 50~321 50~366 50~366 50~321	8880
	8007090339 8007090339 8007110259* 8007110285 8007110304	50-321 50-321 50-321 50-321 50-321	0 0 0 8 8		8007280541 8007280541 8007280572 8007280586* 8007280429	50-321 50-321 50-321 50-321 50-321	8 8
	8007110307 8007110313* 8007110366 8007110368 8007110400	50-321 50-321 50-366 50-321 50-321	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$		8007280634 8007280634 8007280640* 8007280642* 8007280642*	50-321 50-321 50-321 50-321 50-321	р В Р
	8007110403# 8007110415 8007110424#	50-321 50-321 50-321	S		8007280678 8007280678 8007280682 8007280682 8007280684	50-321 50-321 50-321 50-321 50-321	R R R B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	_
	8007280686* 8007280670* 8007280672* 8007280672* 8007290672*	50-321 R 50-321 S 50-321 R 50-321 R 50-321 Q		8007280189 8007280536* 8007200367 8007310375 8007250284*	PRM 50-329 50-397 50-289	H U H
	8007290618 8007290774 8007290774 8007290777* 8007290777*	50-321 G 50-424 F 50-424 F 50-424 F 50-424 F	House of Rep , Interior & Insular Affairs :	8007250244* 8004280237 8007020279* 8007110509 8007180431*	50-546 (50-352 (WASTE MOT PRM COMMISSION	
	8007300392 8007300513* 8007310275 8007310275 8007310287*	50-321 S 50-321 S 50-321 Q 50-321 Q 50-321 Q	Hause of Rep , Interst & Foreign Commerce	8007230545* 8007110279* 8007300345 8007220051	50-320 COMM198100 50-498 C	
Georgia, State of Georgia, Univ of,	8007310287* 8007310527 8007310527 8007310527 8007150069 8007100349	50-321 Q 50-321 Q 50-321 Q PR 71-389	Haveton Lighting & Power Co	8007020471 8007020471 8007020418 8007020478* 8007020478*	50-466 50-498 50-498 50-498	Q G B A A E
Germany, Federal Republic of Gibbs & Hill, Inc. (subs. of Dravo Corp.) Gilbert/Commonwealth Cos	8007100353* 8007020554* 8007310255 8007210527* 8007070104	71-387 50-320 Q NUREQ 50-445 A TOPREP		8007080D15* 8007080D17* 8007080D58 8007090189 8007090246	50-466 50-466 50-466	0000
Coldberg, Fieldman & Hjelmfelt Colder Associates Coldsmith, R	8007220385* 8007140875 8007250542* 8007280717* 8007140337	50-302 P 50-346 M CONTRACT CONTRACT 50-10 G		8007070244 8007070365 8007070365 8007100433 8007100443	50-498 50-498 50-498 6	0 8 8 0 8
Gould-Brown Boveri Greenpeace Foundation Ouif & Hestern Industries, Inc Ouif Nuclear, Inc	8007080191 8007020127 8007010142* 8007010151* 8007140582	50-354 A FDIA GA799 GA999 PR		8007100443 8007110337 8007110337 8007150075* 8007150425	50-498 50-498	8 8 9 0 M
Quif Oil Corp , Quif Mineral Resources Co Oulf Science & Technology Co Oulf States Utilities Co	8007020128 8007030190 8007020135* 8007160495 8007210148*	WASTE MGT PR WASTE MGT NUREQ 50-458 Q		8007150425 8007150425 8007150645 8007150645 8007150645	50-445 50-498 50-498	M M S 8
HEW, Dept of, Food & Drug Administration HKS, Dept of, VS Public Health Service	8007220594 8007290424 8007110539# 8007070264 8007140640	50-458 Q PR CONTRACT 50-10 D PR		8007150219 8007150570 8007150604 8007150604 8007150609*	50-466 50-498 50-498	6 0 6 9
Hanford Engineering Development Laboratory	8007150084 8007140646 8007140649* 8007140654*	PR 71-6387 71-6387 71-6387		9007160607* 9007160639 9007160645 9007170203 9007180432	50~466 (50~466 (50~478 (8 6 6 6
	8007140658* 8007140662* 8007140666* 8007140668* 8007140678*	71-6387 71-6387 71-6387 71-6387 71-6387 71-6387		8007210511 8007210511 8007220578 8007220578 8007230476	50-498 50-498 50-498	8 8 0 0
Harding-Lawson Associates	8007140687# 8007140690# 8007250440 8007250444# 8007280236#	71-4387 71-4387 PROJ PROJ CONTRACT		8007230476 8007230512 8007230512 8007230525 8007230540	50-478 50-478 50-478	99999
Harrisburg Hosp Harrisburg.PA Health Physics Sociaty High Rock Lake Association Hill Christopher & Phillips	8005190626 8007100001 8006200066 8006200071* 8007030048	50-320 P PR 50-488 G 50-488 G 50-275 G		8007230540 8007230718 8007230718 8007250424 8007250441	50-478 50-498 50-466	8 0 0 0 N
Hirata Valve Industry Co . Ltd , Kawaski Div	8007300110 8007310389 8007290477*	50-275 G 50-312 G QA999		8007290082 8007300070 8007300090 8007300348 8007300348	50-498 50-498 50-466	G G H H
Hittman Nuclear & Development Corp (subs Hittman Gorp) House of Rep	8007290487* 8007170286* 8007020088* 8007020217*	0A979 50-219 0 50-10 U 50-324 H		8007300348 8007300375 8007300375 8007300382 8007300402	50-498 50-498 50-498	H A A B Q
	8007020237* 8007110343* 8007110449 8007160634	50-320 H 50-352 U 50-313 H 50-329 H		8007300413 8007300435 8007300449 8007310094	50-466 50-466 50-466 50-466	000
	8007180427* 8007210390 8007240406 8007250215* 8007250264*	COMMISSION 50-397 U 50-320 H COMMISSION 50-317 H	Howard Univ Hudson Light & Power Dept Husco, Inc Hunton & [[1]]	8007310309 8'	50-466	Q.

AUTHOR AFFILIATION	ACCESSION NOMER	SUBJEC	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
Hydrology Associates,Inc	8007090306 8007170384 8007220446 8007240029* 8007240041*	50-322 50-322 MISC 40-8453 40-8453	G G		8007140002 8007160692 8007160698* 8007230142 8007230164*	PR 50-274 50-274 50-289 50-289	F
ERT Corp Idaho <i>N</i> ational Engineering Laboratory	8007240048* 8007160490 8007240257 8007280683 8007290217	40-B452 CONTRAC RES NUREO		International Atomic Energy Agency (Austria)	8007280024 8007310397 8007020674*	PR 50-275 COHMISS ORO	A NOI
Illinois Power Co	B007030217	50-254 50-461	G.	International Structural Engineers, Inc	9007300587*	50-390	A
	8007030215 8007110233* 8007160424 8007160638*	50-461 50-461 50-461 50-461	0 0 8 8	Iowa Electric Light & Power Co	8007010453 8007020719 8007030212 8007030217* 8007030224	50-331 50-331 50-331 50-331 50-331	P 0 8 8
	8007160651* 8007160665* 8007160679* 8007210521* 8007230518	50-461 50-461 50-461 50-461 50-461	8 9 9 9		8007030235* 8007030238 8007030241* 8007070142 8007070252	50-331 50-331 50-331 50-331 50-331	8 8 8 9
Illinois Safe Energy Alliance	8007250559 8007280506 8007300429 8007140337 8007230524	50-461 50-461 50-461 50-10 50-10	A 9 5 0 D		8007070255* 8007070272 8007110411 8007110419* 8007110471	50-331 50-331 50-331 50-331 50-331	р 0 8 8
Illinois, State of	8007070028 8007080026 8007140432 8007140439* 8007140449*	50-514 50-367 PR PR PR	G		8007110482* 8007140366 8007140434 8007140442* 8007160259	50-331 50-331 50-331 50-331 50-331	8 P P Q
	8007140521* 8007150056 8007160587 8007180387 8007230527	CONTRAC 50-367 70-1308 70-1308 27-39	G		8007160624 8007170563 8007220367 8007220371* 8007220394	50-331 50-331 50-331 50-331 50-331	P Q R R
Interg-Miller Engineering Co Indiana & Michigan Electric Co	8007250442 8007310133 8007290221 8007310494 8007020245	27-39 27-39 40-299 40-299 50-315	Q		8007220494 8007220497 8007220544 8007220599 8007230233	50-331 50-331 50-331 50-331 50-331	0 8 0 8
	8007020591 8007030206 8007090289 8007090292* 8007110465	50-315 50-315 50-314 50-314 50-315	P G S G		8007230464 8007230482 8007250675 8007250677 8007280377	50-331 50-331 50-331 50-331 50-331	5 P Q Q P
	8007150586 8007150597* 8007150623* 8007150684 8007150695*	50-315 50-315 50-315 50-316 50-316	88888	lsham, Linco)n & Beale	8007280480 8007020462 8007080349 8007080360* 8007090045	50-331 50-599 PR PR 50-329	P Q
	8007150696 8007150703* 8007160384 8007180324 8007210537	50-315 50-315 50-315 50-315 50-314	8 0 8		8007090316 8007140020 8007150052 8007150431 8007160593	50-255 50-327 50-155 50-445 PR	0 0 0 M
	8007210541* 8007220080 8007220080 8007230269 8007230269	50-316 50-318 50-318 50-318 50-318	8 0 0 0		8007210445 8007220194 8007230810 8007300362 8007300368	50-255 50-327 50-255 50-255 50-155	90000
	8007250016 8007250493 8007280510 8007300252 8007310284*	50-314 50-315 50-315 50-315 50-315	0 P S Q	Island Closeup News Service Isotope Products Laboratories	8007300421 8007300464 8007300468 8007140214 8007020383	50-327 50-155 50-155 FOIA XPORILIC	9
Indiana & Michigan Power Co	8007310399 8007150542 8007150547*	50-315 50-315 50-315	V R R	Izaak Walton League of America, Porter	8007080055	50-367	c
Indiana State Univ	8007150555 8007150561* 8007250028*	50-314 50-314 CDMMISSI	R	County Chapter Jack R. Benjamin & Associates.Inc Japan Jersey Central Power & Light Co	8007220372* 8007250555 8007010468 8007020377	50-70 XPORTLIC 50-219 50-219	P Q
Indiana. State of Inside D O E . McGraw-Hill Publication Institute for Energy & Environmenta! Research Heidelberg, H. Oermany Interex Corp	8007020300 8007170202 8007150042 8007310417*	PR FOIA 50~320 50~277	P R		8007030216 8007070113 8007070259 8007070265*	50-219 50-219 50-219 50-219	P P S
Interior Dept of	8007140016 8007140511	50-275 50-397	H		8007090259	50-219	Q
Interior Dept of, Bureau of Mines Interior Dept of, Fish & Wildlife Service	8007150710		A P		8007070262 8007110023* 8007110370 8007110373* 8007110375	50-219 70-1333 50-219 50-219 50-219	F 8 9 8
Interior, Dept of, Geological Survey	8007210368 8007310377 8004280218 8007030193	50-250 50-250 PR PR	P P		8007110383* 8007150705 8007140500	50-217 50-219 50-219	8 R P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFF1LIATION	ACCESSION NUMBER	SUBJECT	
	8007170279 8007180409 8007180415* 8007180423* 8007180451*	50-219 50-219 50-219 50-219 50-219	P P P P		8007230458 8007230462* 8007230598 8007250568 8007290689	50-322 50-322 50-322 50-322 NUREO	A K A
	8007180587 8007210042 8007220363 8007220364* 8007230570	50-219 50-219 50-219 50-219 50-219	G G R R S	Los Alanos Scientific Laboratory	8007100053 8007140405 8007180175 8007180603 8007210407	REGGD PR REGGD ACRS RES	
Jones, Brown & Clifford	8007230574* 8007250170 8007250305 8007290184 8007300340	50-219 50-219 50-219 50-219 50-133	8 a a P G	Los Alamos Technical Associates,Inc Los Angeles, CA Louisiana Power & Light Co \	8007280209* 8007140051* 8007010319 8007010341 8007010343*	FOIA PR 50-382 50-382 50-382	ተተ
Jones, Grey & Bayley Justice, Dept of	8007140026 8007160347 8007170364 8007280636* 8007300418	50-275 50-445 50-445 50-445 50-445	G M M M		8007020397 8007020405* 8007080179 8007080234 8007080239*	50-392 50-392 50-392 50-392 50-382	8 8 8 8
KMC. Inc KMS Fusion Inc (subs of KMS Industrie s. Inc.)		PR XPORTLIC			8007100163 8007100166* 8007100169* 8007100429	50-382 50-382 50-382 50-382	K K Q
Kaman Sciences Corp Kansas Gas & Electric Co Kansas, Univ of	8007160513* 8007290017* 8007170317*	CONTRACT 50~482 50-482			8007150417 8007160584	50-382 50-382	GI K
Kawecki Berylco Industries, Inc Karr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8007020153 8007020667 8007140286	XPORTLIC PR FOIA			8007140616 8007220373 8007250399 8007270439*	50-382 50-382 50-382 50-382	K F G
	8007210108 8007310262	40-2061 FOIA		Lowenstoin, Newman, Reis, Axelrad 多 Toll	8007300395* 8007020348 8007020424	50-382 PR PR	Q
Kerr-McGee Carp Kerr-McGee Nuclear Corp	8007110025 8007110027* 8007170491 8007010590	40~2041 40-2041 PR 40-8447			8007020453 8007020471	50-367 50-466	000
	8007010592* 8007010609 8007010611* 8007010615* 8007030031	40-8647 40-8027 40-8027 40-8027 40-8647			8007020604 8007030082 8007030119 8007080017* 8007080021	50-376 PR PR 50-466 50-367	0
Lancaster County, PA	8007030035+ 8007230564+ 8007250634 8007280116+	40-8647 70-925 40-8027 50-320	н		8007080058 8007070187 8007100160 8007100180* 8007150425	50-446 50-446 PR PR 50-445	о о м
Laos Lapp.inc Lawler.Matusky & Skeily Engineers Lawrence Berkeley Laboratory Lawrence Livermore Laboratory	8007110010 8007180221* 8007170403* 8007220023* 8007140617	XPORTLIC COMMISSI 50-220 MISC NUREG			8007150425 8007160570 8007160639 8007160645 8007180432	50-445 50-466 50-466 50-466 50-466	M 0 0 0
	8007180072 8007220024 8007220034 8007240478	NUREO NUREO NUREO NUREO			8007230535 8007250424 8007250441 8007250082	50-376 50-466 50-445 50-466	o o ž o
LeBosuf, Lamb, Leiby & MacRae	8007020212 8007100437 8007140370	PR PRM 50-452	G.		8007300027 8007300090 8007300413	FR 50~498 50~466	g' G
	8007140370 8007140378* 8007140378*	50-452 50-452 50-452	G G		8007300449 8007310094 8007310308	30-466 50-466 50-466	9
	8007140619 8007170393 8007300032	50-320 50-220 FR	H P	Lower Aliouays Craek, NJ Magnaflus Corp (subs of Peabody Galion Corp)	8007110112 8007020044	50-272 71-5	Ģ
League of Women Voters of San Luis Obispo.CA Lehigh Univ	8007010457 8007140642 8007170460	50-275 RES RES	н	Maine Public Service Co Maine Yankee Atomic Power Co	8007020047* 8007080038* 8007010339	71-5 50-443 50-309	8
Lester B. Knight & Associates.Inc Levy, Outman, Goldberg & Kaplan Life Cycle Engineering.Inc	8007310019 8007290054* 8007070092 8007170535*	50-219 MISC PR 50-320	P P		8007030225 8007080217 8007080413 8007080417* 8007090275	50-309 50-309 50-309 50-309 50-309	P 18 8 P,
Lockheed Environmental Sciences Long Island Lighting Co	8007010226* 8007100268* 8007010066 8007020073* 8007030053	50-204 50-206 50-514 50-322 50-322	R R G S G		8007110386 8007110367* 8007140403 8007170321 8007180090	50-309 50-309 50-309 50-309 50-309	8 0 0
	8007090243 8007090245* 800709030A	50-322 50-322	K K		8007210367 8007210369* 8007210428	50-307 50-309 50-309	R
	8007140390 8007150655 8007160867*	50-322 50-322 50-322	8 A Q		8007210431* 8007210401	50-309 50-309	0
	8007170384 8007210040* 8007210515	50-322 50-322 50-516	о G		8007250404 8007250405* 8007280458 8007280404	50-309 50-309 50-309 50-309	P O R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Υ
Maine, State of Mallinckrodt, Inc Manchester Memorial Hosp Manchester, CT Mapleton Intervenors	8007280611* 8007110481 8007110934 8007150318* 8007140017	50-309 PR 70-2651		8007070313* 8007070320 8007070322* 8007070343 8007070343	50-289 50-320 50-320 50-289 50-289	8 P P P
Marine Biological Consultants, Inc , Mark IV Industries, NRD Div Marquette Univ	8007160649* 8007010226* 8007100268* 8007110159 8007240258*			6007080074 8007080211 8007080214* 8007080244 8007080358	50-287 50-287 50-287 50-287 50-320	P 8 8 F P
Marrack, D	8007250012* 8007030025 8007030029* 8007110080 8007140540	50-466 50-466		8007080358 8007080375 8007110015* 8007110020* 8007110023*	50-320 50-289 70-1333 70-1333 70-1333	Q Q
Marsh & McLennan, Inc . M & M Nuclear Consultants, Inc Div	8007140545* 8007220552 8007010516	50-259 50-272		8007110024* 8007110030* 8007110032* 8007110040* 8007110422	70-1333 50-287 50-320 50-320 50-320	カフファ
	8007080261 8007150479 8007150490 8007160415 8007310342	50~155 50~280 PR 50~272		8007110446 8007140006 8007140224 8007140346 8007140352	50-289 50-320 50-289 50-289 50-320	9 7 9 P
	8007310374 8007310374 8007310435 8007310436	50-272 50-272 50-302 50-259		8007140365 8007140381 8007140385 8007140385 8007140413	50-289 50-289 50-320 50-320 50-320	P G H H P
Marubeni America Corp (subs of Marubeni Corp)	8007310436 8007290460	50-259 XPORTLIC		8007140419 8007140419 8007150499	50-320 50-320 50-320	P P P
Macyland, State of	8007290467* 8007020338* 8007070085	XPORTLIC State Pro PR		8007150502* 8007150507	50-320 50-320	р Р
Maryland, Univ of Massachusetts Institute of Technology	8007230495 8007100030	50-146 PR		8007150513 8007150514# 8007150515	50-320 50-320 50-320	8 8
Massachusetts Municipal Wholesale Co Massachusetts, State of	8007210258* 8007080037* 8007030365 8007160851*	CONTRACT 50-443 PR COMMISSIO		8007150519* 8007150589 8007150721	50-320 50-289 50-289	BP
Massachusetts, Univ of Matheson Cas Products Mayer, Brown & Platt	8007100077 8007310082 8007020608 8007140038	PR XPORTLIC 70-1308 70-1308		8007140431 8007140522 8007140524 8007140525*	50-320 50-320 50-287 50-320	8
	8007220138 8007220147 8007220168 8007220170	70-1308 70-1308 70-1308 70-1308 70-1308		8007160526* 8007160596 8007160618 8007160623* 8007160667	50-289 50-320 50-289 50-289 50-320	8888
McDermott, Will & Emery	8007230519 8007170388	90~445		8007160667 8007170338	50-320 50-320	F
McGeam Chemical Co , Inc McGraw-Hill Publications Co McPhillips, J L	8007280270 8007020731* 8007110003 8007110055	FOIA CONTRACT 70-2909 70-2909		8007170340# 8007170373 8007170375	50-320 50-320 50-320	P P
Medi-Physics, Inc Hedinaelsctric Cooperative Inc Hemorial Hosp of Natrona County	8007070178 8007170388 8007100129	PR 50-445 REGGD		8007170442 8007170456 8007180376 8007180391	50-320 50-320 50-320 50-289	PPP
Casper.WY Memphis Btate Univ Metai Bailows Corp	8007280286 8007010572 8007110528	50-538 XPORTLIC XPORTLIC		8007180394 8007180396 8007180404	50-287 50-289 50-320	٥
Metropolitan Edison Co	8007010155 8007010326 8007010388	50-289 (50-289 (8007180404 8007180414 8007180421	50-320 50-289 50-289	9
	8007010388 8007010454 8007010458* 8007010460	50-289 F 50-320 F 50-320 F		8007210359 8007210372 8007210383 8007210398 8007220442	50-320 50-289 50-320 50-289 50-320	R P O P
	8007010460 8007020482	50-320 50-320 (40-320		8007220471 8007220485 8007220492 8007220498 8007220553	50-289 50-320 50-289 71-9081 50-320	F 0 0 F
		((8007220553 8007220555* 8007220555* 8007220584 8007220584	50-320 50-320 50-320 50-320 50-320	作を作りり
				8007220572 8007230434 8007230439 9007230514* 8007230521	50~289 50~320 50~320 50~289 50~289	9 9 9

AUTHDR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	łΥ	AUFHOR AFFILIATION	ACCESSION NUMBER	SUBJECT
	8007230404 8007230410 8007250354 8007250401 8007250504	50-289 50-289 50-289 50-289 50-289	 0 0 0 0 0		8007110417* 8007110417* 8007110430 8007110430 8007140388	50~416 S 50~416 S 50~416 S 50~416 S 50~416 E
	8007250615 8007280483 8007290617 8007290797 8007290805*	50-287 50-287 50-287 50-287 50-287	S G R R		8007140388 8007140575 8007150093 8007150093 8007150097	50-416 E PR 50-416 S 50-416 S 50-416 S
	8007290811 8007290817* 8007300437 8007300447 8007300449	50~320 50~320 50~289 50~320 50~446	9 8 9 P 9		8007150099 8007150105 8007150105 8007160585 8007160585	50-416 8 50-416 8 50-416 8 50-416 8 50-416 9
Michigan, State of Michigan, Univ of	8007310137 8007310406 8007310439 8007290065* 8007020659	50-289 50-320 50-320 State Pro	G p P		8007160610 8007160611 8007160611 8007160617* 8007160617	50~416 A 50~416 S 50~416 B 50~416 A PR
	8007080357# 8007110543 8007160280 8007230223 8007280338	PR ORG RES REB CONTRACT	r		8007160642 8007160642 8007160862* 8007160864* 8007170290	50-416 S 50-416 B 50-416 Q 50-416 Q 50-416 B
Microtech Industries, Inc	8007020378* 8007070134* 8007020404 8007020413* 8007100005	CONTRACT CONTRACT PR PR PR			8007170290 8007170294* 8007170294* 8007170396 8007170396	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S
Midwest Environmental Protection Association Miller Technical Services	8007100355 8007210150 8007300279	PRM 40-1341 40-299			8007170400* 8007170400* 8007170435 8007170435	50-416 B 50-416 B 50-416 B 50-416 S
Miller Technical Bervices	8007300285* 8007300288	40-279 40-279			8007170592 8007180293	50-416 S 50-416 F
Milier, D 6	8007300289* 8007020407 8007020410* 8007030059* 8007110345	40-299 50-309 50-309 PR PR	o G		8007180293 8007210270 8007220368 6007220369	50-416 F 50-416 Q 50-416 S 50-416 S
Miner & Miner.inc Ministry of Concern for Public Health Minnesota, State of	8007300122 8007300127* 8007110575* 8007020447 8007100208	50-309 50-309 Contract Pr 50-282	о С С		8007220949 8007220973* 8007250432 8007250910 8007250920*	50-416 A 50-416 A 50-416 G 50-416 B 50-416 B
Minnesota, Univ of, Minneapolis	8007140011 8007230583 8007250422 8007030200 8007140014*	PR PR 50-282 PR PR	Q		6007250520* 6007280494 8007280494 6007280566 6007290655	50-416 S 50-416 A 50-416 S 50-416 S
Mississippi Pawer & Light Co	8006190577 8006300375 8006300382* 8006300384* 8007010361	50-416 50-416 50-416 50-416 50-416	8 F F F		6007270655 6007270666 6007270666 8007270671 8007270671	50-416 8 50-416 9 50-416 9 50-416 8 50-416 8
	8007010381 8007020538 8007020539 8007020539* 8007020539*	50-416 50-416 50-416 50-416 50-416	, E S S S	Mississippians Against Disposal	8007290714 8007290714 8007290791 8007290791 8007080009	50-416 S 50-416 S 50-416 S 50-416 S PR
	8007020341* 8007020541* 8007020579 8007020401 8007020401	50-416 50-416 50-416 50-416 50-416	8 9 9 8 8 8 8 8	Missouri, State of Missouri, Univ of, Columbia Missouri, Univ of, Rolla	8007270038* 8007080266 8007080266 8007140351 8007220122	50-483 A 50-186 S 50-186 S 50-186 S 50-123 Q
	8007020403* 8007020403* 8007020415 8007020430 8007020430	50-416 50-416 50-416 50-416 50-416	8 8 8 6 8	Mitsubishi International Corp (subs of Mitsubishi Corp) Mitsui & Co , Ltd	6007240030 6007240036* 6007310462 6007100281 8007100287*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8007020432* 8007020432* 8007020640 8007020640 8007030245	50-416 50-416 50-416 50-416 50-416	8 8 8 8 8	Mobile Systems Monsanto Research Corp	8007110275 8007110283* 8007100368* 8007170161* 8007160394	XPORTLIC XPORTLIC CONTRACT CONTRACT XPORTLIC
	8007070118 8007070118 8007070245 8007070245 8007070298	PR PR 50-416 50-416 50-416	E: E: 8	Montana. State of Morrison Knudsen Co , Inc Mount Sinai Hartford.CT Monicipally Owned Electric Systems	8007160377* 8007020332 8007220117* 6007230601* 8007030189*	XPORTLIC FR WABTE HOT : 70-2000 50-413 A
	8007070298 8007110412 8007110413 8007110413	50-416 50-416 50-416 50-416	8 K 8	Association Mutual Atomic Energy Liabritty Underwrit ers	8007100134 8007210442	PRM (

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
NL Industries, NL Nuclear Div NPS industries, Inc NUS Corp	8007280315 8007160807 8007160309* 8007100309* 8007100311*	71-9010 50-329 50-280 50-280 50-280	S P P		8007080345 8007080346* 8007080391 8007080395* 8007090005	50-278 8 50-278 8 50-278 R 50-278 R 50-278 S
	8007100315* 8007100315* 8007100315* 8007100321* 8007100321*	50-280 50-280 50-280 50-280 50-280	ն Ն Ե		8007090007* 8007100016 8007150702 8007160440 8007210152	50-278 B 50-278 G 50-278 B 50-278 P 50-278 Q
	8007100321* 8007100323* 8007100323* 8007100323* 8007100323*	50-280 50-280 50-280 50-280 50-280	ր Բ Բ		8007240259* 8007250421 8007250425* 8007250501 8007280452	50-298 P 50-298 R 50-298 R 50-298 S 50-298 P
	8007100329* 8007100329* 8007100329* 8007100335* 8007100335*	50-280 50-280 50-280 50-280 50-280	P P P P	Neighbars for the Environment Neutron Products, Inc	6007280447* 6007280584 8007280592* 8007140036 8007230347	50-278 P 50-278 S 50-278 S PR 71-121
	8007100338* 8007100338* 8007100347* 8007100347* 8007100347*	50-280 50-280 50-280 50-280 50-280	P P P P	Nevada, State of New Bedford Gas & Edison Light Co New England Coalition on Nuclear Pollution	8007230354* 8007230739* 8007080022* 8007110048	71-121 COMMISSION 50-443 I PR
	8007100351* 8007100351* 8007100351* 8007100357* 8007100357*	50-280 50-280 50-280 50-280 50-280	P P P P	New England Power Co New Hampshire, State of New Jersey, State of	8007080014* 8007180447* 8007100175 8007100178* 8007290035* 8007030045	50-443 I MISC 50-272 0 50-272 0 50-289 H PR
	8007100359# 8007100365# 8007100365# 8007100365# 8007100371#	50-280 50-280 50-280 50-280 50-280	ե ե ե	New Mexico, State of New York Federation for Safe Energy New York, State Univ of, Buffalo	8007210135* 8007010508 8007030204 8007030209* 8007280454	CONTRACT 50-320 H PR PR FR 50-57 R
	8007100371* 8007100375* 8007100375* 8007100380* 8007100380*	50-280 50-280 50-280 50-280 50-280	P P P P	New York, State of	8007290694 8007110121 8007150047 8007170277* 8007180047*	50-57 R PR PR State Prog 50-322 H
	8007100382* 8007100382* 8007100387* 8007100387* 8007100391*	50~280 50~280 50~280 50~280 50~280	Ե Ե Ե Ե	Newport News Industrial Corp (subs of Newport News Shipbuilding & DryDock Co)	8007180217* 8007210267* 8007080230	State Prog CONTRACT MISC
	8007100391* 8007100403* 8007100407* 8007100407* 8007100407*	50-280 50-280 50-280 50-280 50-280	Р Р Р	Niagara Mohawk Power Corp	8007070089 8007070261 8007080337 8007150122 8007170360 8007170361*	50-220 P 50-220 P 50-410 A PR 50-220 R 50-220 R
	8007100409* 8007100414* 8007100414* 8007100415* 8007100415*	50-280 50-280 50-280 50-280 50-280	P P P		8007170397* 8007170397* 8007180073 8007210100 8007250192	50-220 P 50-220 P 50-220 Q 50-220 Q 50-220 Q
	8007140051* 8007220032* 8007220036* 8007220101* 8007220111*	PR WASTE MO WASTE MO WASTE MO	T T		8007250472 8007280275 8007280275 8007280445 8007280540	50-410 A 50-220 I 50-220 I 50-220 Q 50-220 H
NUSAC, Inc National Audubon Society. Central Midwest Regional Office National Campaign for Radioactive Waste Safety	8007280527* 8007140656* 8007170089 8007220326 8007300323	CONTRACT FOIA 50-320 FOIA 50-10	P D	Nissho-Iwai American Corp North Anna Environmental Coalition	8007290586 8007290600* 8007300049 8007280464 8007070075* 8007070079*	50-220 S 50-220 E PR XPORTLIC 50-280 H 50-280 H
National Council on Radiation Protection & Measurements National Employee Benefit Associates National Wildlife Federation Natural Resources Defense Council		PR FOIA REGOD PR PR	•	North Carolina Electric Membership Corp North Dakota. State of Northcutt Ely Northeast Nuclear Energy Co (subs of Northeast Utilities)	8007300412 8007210486* 8007150438 8007210435 8005300283	50-280 0 50-413 A 50-484 Q 50-445 M PR
		70-143			8007010328 8007010337 8007010337 8007010337 8007010354	50-245 P 50-213 F 50-213 F 50-213 F 50-423 Q
		Y 9027 E0 278 298	Q Q		8007010445 8007010450* 8007020039 8007020472 8007020569	50-336 6 50-336 8 50-336 0 PR 50-213 P
		278	s 6		8007030356 8007030356	50-245 F 50-245 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOC	78Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8007030354 8007070251 8007070318 8007070324* 8007070341	50-245 50-245 50-336 50-336 50-336			8007010549 8007010583* 8007020162 8007030178 8007030178	50-282 50-282 50-263 50-282 50-282	Q P Q R
	8007070372* 8007080135 8007080164 8007080167* 8007080174*	50-336 50-245 50-336 50-336 50-336	8 8 8 8		8007030180* 8007030180* 8007030183* 8007030183* 8007030222	50-282 50-282 50-282 50-282 50-263	R R R P
	8007090231 8007090231 8007100035 8007100157 8007100164*	50-213 50-213 PR 50-245 50-245	F F S S		9007070315* 9007080251 9007080245 9007100067 9007100123	50-484 50-263 50-263 50-263 50-236	0 P P P
•	8007100147 8007100172* 8007170425 8007170519 8007180408	50-245 50-245 50-213 50-423 50-245	5 5 6 7 8		8007100190 8007100195* 8007110115 8007110115 8007140192*	50-263 50-263 50-282 50-282 50-282	5 5 F Q
	8007180413* 8007210238 8007210245* 8007210374 8007210375*	50-245 50-336 50-334 50-336 50-336	R P R R		8007150481 8007150611 80071506144 8007160558 8007160562#	50-263 50-263 50-263 50-282 50-282	0 R R R
	8007210387 8007210520* 8007220457 8007220457 8007220467*	50245 50245 50245 50245 50245	6 8 8		8007160562# 8007160660 8007160707 8007160707 8007170194#	50-282 50-282 50-282 50-282 50-306	R G G
	8007220467* 8007250300 8007250300 8007250303* 8007250303*	50-245 50-245 50-245 50-245 50-245	P P P		8007170398 8007180300 8007180306* 8007210132 8007210182	50-243 50-243 50-243 50-243 50-243	P P Q Q
	8007250407 8007250410* 8007280574 8007280582* 8007290852	50-334 50-336 50-245 50-245 PR	8 8 P		8007210184 8007210176* 8007210379 8007210380* 8007210437	50-263 50-263 50-306 50-306 50-292	P 8 8
Northeast Utilities	8007010337 8007020437 8007020441 8007070294 8007100200	50-213 PR PR PRM 50-245	F		8007210444* 8007210509* 8007220090 8007220090 8007220542	50-282 50-263 50-282 50-282 50-282	900
	8007100200 8007110466 8007110474* 8007140344 8007150622	50-245 50-245 50-245 50-336 50-245	P S P I		8007220542 8007230211 8007230211 8007230077 8007250077	50-282 50-282 50-282 50-282 50-282	0 0 0
	8007150422 8007140676 8007160680* 8007170320 8007180137	50-245 50-245 50-245 50-213 50-213	I R R Q Q		8007250340 8007250408 8007250565 8007280056 8007280056	50-282 50-484 50-263 71-9018 71-9018	6 0 0
	8007180278 8007180307# 8007230048 8007280673 8007280673	50-245 50-245 PRM 50-213 50-213	8 9 P		8007280056 8007280057 8007280381 8007280410 8007280410	71-9108 50-263 50-263 50-263 50-263	ā !
Northern Illinois Univ Northern Indiana Public Service Co	8007290697 8007220589 8007010478 8007020453 8007110438	50-245 50-10 50-367 50-367 50-367	Q D A O R		8007280441 8007280488 8007280489 8007290469 8007290677*	50-263 50-263 50-263 50-282 50-282	f f
	8007210464 8007250630 8007280118 8007280141 8007280482	50-367 50-367 50-367 50-367 50-367	R Q R R	Northern Thunder	8007290841 8007300463 8007310106 8007310106 8007290703	50-263 50-282 50-282 50-282 50-484	e e e
Northern States Power Co	8007010260 8007010260 8007010267 8007010267 8007010311	50-282 50-282 50-282 50-282	0 0 0 F	Northwestern Univ Notre Deme, Univ of	8007140483 8007250578* 8007010040* 8007010067* 8007010077*	REGOD CONTRAC 40-2674 40-2674 40-2674	
	8007010325 8007010335 8007010351 8007010376 8007010381*	50-263 50-263 50-263 50-306 50-306	F F P P		8007010085* 8007010091* 8007010097* 8007210558* 8007210549*	40-2674 40-2674 40-2674 40-2674 40-2674	3
	8007010524 8007010529* 8007010531 8007010542* 8007010549	50-304 50-304 50-243 50-243 50-282	8 8 9	Nuclear Assurance Corp	8007180469 8007220068 8007220073* 8007300001 8007100312*	71-6698 40-8771 40-8771 71-6698 CONTRAC	1

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJEC1 CATEGOR			AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
Nucloar Energy Liability Insurance Association	8007110017* 8007110043 8007110044* 8007110051*	50-320 50-320 50-320 50-320 50-320)))			8007180555 8007210028 8007230441 8007250464 8007280184*	70-143 50-201 50-201 70-143 70-143	Q Q
	8007110052* 8007110052* 8007110052* 8007110057* 8007110050*	50-320 50-320 50-320 50-320 50-320	7 7 6		Nuclear Fuel Services, Inc , West Valley Reprocessing Plant	9007280187* 8007280552 8007290547 8007290713 8007080244	70-143 70-143 70-143 70-143 50-201	Q
	8007110060* 8007110062* 8007110062* 8007110068* 8007110068*	50-320 50-320 50-320 50-320 50-320	7 7 7		Nuclear Packaging, Inc	8007020561 8007020685* 8007070177 8007070179* 8007070182*	71-9130 71-9130 71-9130 71-9130 71-9130	
	8007110072* 8007110072* 8007110077* 8007110084* 8007110089*	50-320 50-320 50-320 50-320 50-320)))		Nuclear Power Plant Standards Committee Nuclear Safety Associates Nusem GmbH	8007070185# 8007280125 8007300337 8007100184# 8007150040#	71-9130 71-192 50-482 PR XPORTLIC	A
	8007110091* 8007110095* 8007110098* 8007110098* 8007110103*	50-320 50-320 50-320 50-320 50-320	J J J		Oak Ridge National Laboratory	8007020356 8007070371 8007070375 8007110493* 8007140031	RES Nureo Regod 50-320 Res	P
	8007 10103* 8007 10107* 8007 10125* 8007 10128* 8007 10128*	50-320 50-320 50-320 50-320 50-320				8007140044 8007140503 8007140507 8007140610 8007140634	RES RES RES NUREO RES	
	8007110132* 8007110132* 8007110135* 8007110140* 8007110143*	50-320 50-320 50-320 50-320 50-320	J J J			8007150016 8007170648 8007180065 8007180352 8007180354	RES NUREO RES RES	
	8007110147* 8007110147* 8007110151* 8007110151* 8007110156*	50-320 50-320 50-320 50-320 50-320) 1 1			8007210498 8007280092 8007280095 8007290241 8007300041	50-247 REB RES RES NUREO	Р
	8007110154# 8007110160# 8007110167# 8007110173#	50-320 50-320 50-320 50-320 50-320	7 7 7		Office of Management & Budget	8007300575 8007310246 8007310251 8007310554 8007170418*	COMMISSI NUREO NUREO NUREO	.DN
	8007110176* 8007110176* 8007110178*	50-320 50-320 50-320	ή ή		Offshare Power Systems (subs of Westinghouse Electric Corp)	8007290729* 8007210395	COMMISSI 50-437	ON A
	8007110201* 8007110208* 8007110212*	50-320 50-320 50-320	7		Ogla Patrolaum, Inc Ohio State Univ	8007210404* 8007020293 8007010383	50-437 40-8693 50-150	8
	8007110217* 8007110222* 8007110222* 8007110224*	50-320 50-320 50-320	, ,		Ohio. State of Oklahoma, State of	8007090408 8006110406 8007100246 8007020613 8007220539	regad Pr Pr 50-556 Pr	e
Nuclear Engineering Co , Inc , (subs of Teledyne, Inc)	8007110224* 8007220508 8007240155	50-320 27-48 71-6679	J		Oklahoma. Univ of	8007310153 8007030066 8007210491	30-334 Foia Nureo	0
Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.)	B007010001 B007010101	50~201 71-5768	I		Dmaha Public Power District	8007010471 8007010477*	50-285 50-285	P P
	8007010109* 8007010121* 8007020437 8007030292 8007070014*	70-143 71-5768 70-143 70-143 70-143				8007020075 8007020279 8007020312 8007020419 8007020430	50-285 50-285 PR 50-285 50-285	Q Q Q
	8007070191 8007070333 8007070335* 8007070350 8007100023*	70-143 70-143 70-143 70-143 70-143				8007030001 8007070375 8007070385* 8007080364 8007110096*	PR 50-285 50-285 50-285 50-285	6 8 9 0
	8007100028* 8007100044* 8007100052* 8007100069* 8007140064*	70-143 70-143 70-143 70-143 70-143				8007170374 8007170379* 8007180122* 8007210187 8007230530	50-285 50-285 50-285 50-285 50-285	R Q Q F
	8007150518 8007150520* 8007150563 8007160843* 8007180475	70-143 70-143 70-143 70-143 71-249				8007230558 8007240130 9007240134* 8007280530 8007280601	50-285 50-285 50-285 50-285 50-285	G 8 8 9 G
	8007180483* 8007180491	71-249 40-8681		1	Oregon State Univ	8007300078 8007150559 8007150562*	50-285 50-106 50-106	H H

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC' CATEODI		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Gregon, State of	8007150449 8007100017 8007180524* 8007280503 8007300357	50-243 PR CONTRAC' 50-344 50-344			8007280215 8007280450 8007280450 8007280450 8007290244 8007290264	50-397 S 50-397 S 50-397 S 50-397 S 50-397 S
	8007300364 8007300372 8007300372 8007300377* 8007300377*	50-344 50-522 50-522 50-522 50-522	H 0 0 0		8007290455 8007290455 8007290623 8007290623 8007290623	50-387 9 50-387 9 50-387 6 50-387 8 50-387 9
	6007300481 8007300490# 8007300494# 8007300500# 8007300506#	50-344 50-344 50-344 50-344 50-344	0 0 0 0	Pennsylvania State Univ Pennsylvania, State of	8007290714 8007100434 8007140449* 8007310383 8007010555*	50-397 S REGOD PR 50-5 F 50-320 P
Ortioff Mineral Services Corp (subs of Ortloff Corp) Osann, E W	8007220077* 8007080055	40-8771 50-367	Ģ		8007020313* 8007070278	50-320 U 50-287 G 50-320 P
PRC Planning & Economics, Alan M Voorhees & Associates Div	8007220448*	50-387	F		8007100186# 8007140046# 8007160644	PR 50-352 H
PSE & G Research Corp PX Engineering Co ,Inc	8007110450* 8006170721	50-272 71-9139	Q.	Seed Andrew Muslam Francis	8007230685 8007080005*	50-320 H 50-289 G
Pacific Gas & Electric Co	8006190923 8006190925 8007010469 8007020394	71-9139 71-9139 50-133 50-275		People Against Nuclear Energy	8007220527 8007220530* 8007280413	50-287 Q 50-287 Q 50-287 Q 50-320 Q
	8007070123 8007070153	50-275 50-275	Q A	Perkins, Cole. Stone, Olsen & Williams	8007100171 8007230797	50-522 G 50-522 G 50-522 G
	8007070206* 8007100152	50-275 PROJ	Ä	Peru Petrotomics, Inc	8007250351 8007180169* 8007230020	COMMISSION 40-6659
	8007100154* 8007140242	PROJ 71-9094		Philadelphia Electric Co	8007010378 8007020041*	50-277 G 50-277 G
	8007150377 8007150548 8007150573*	50-275 50-133 50-133	F R R		8007020072 8007020072 8007070352 8007080216	50-277 G 50-278 S 50-277 S
	8007140520 8007140521*	50-275 50-275	A		8007080216 8007090265	50-277 S 50-352 S
	8007180340 8007180344* 8007180358 8007180405	50-275 50-275 50-133 50-275	A A G G		8007090265 8007100158* 8007170507	50-352 S 50-277 P 50-277 G
	8007210574 8007230016 8007230662 8007240187	50-317 50-133 50-133 50-275	ର ପ ଜ		8007180104 8007180104 8007180117 8007180117 8007180419	50-277 G 50-277 G 50-277 G 50-277 G 50-277 R
	8007250386 8007250658	50-133 50-275	o q		800718041 9 8007180433*	50-277 R 50-277 R
	8007250668 8007280697 8007290825 8007290832*	50~133 50~275 50~514 50~514			8007180443 8007180443 8007180443	50-277 R 50-277 P 50-277 P
Pacific Legal Foundation	8007270835* 8007300280 8007310448 8007100254	50~514 50~275 50~133 PR	r Q Q		8007180446* 8007180446* 8007210214* 8007210215* 8007210321*	50-277 P 50-277 P 50-352 0 50-277 0 50-352 0
Pathfinder Mines Corp	8007100257 * 8007010443	PR 40~2259			8007210378 8007210403	50-278 B 50-277 B
Pennsylvania Power & Light Co	8007080213 8007080213 8007080240 8007080240	50~387 50~387 50~387 50~387	8 8 K K		8007210547 8007210547 8007210567	50-277 G 50-277 G 50-277 G 50-352 G
	8007140170 8007140170	50~387 50~387	8 8		8007210547 8007220551 8007230722*	50-352 Q 50-277 P 50-277 Q
	8007140179* 8007140179* 8007140197	50-387 50-387 50-387	8 8 8		8007240003 8007240226	PR 50-352 B
	8007140340	50~387	S		8007240226 80072501 5 2	50-352 B 50-352 B
	8007180282 8007180364 8007180364 8007180434	50-387 50-387 50-387 50-387	8 8 8		8007250152 8007250471 8007250511	50-352 & 50-352 A 50-277 Q
	8007180434 8007210341*	50-387 50-387	s a		8007250511 8007250631 8007250631	50-277 Q 50-277 Q 50-277 Q
	8007220441 8007230147 8007240131 8007240131	50-387 PR 50-387 50-387	F K K		8007280384 8007280388*	50-278 P 50-278 P
	8007240142* 8007240142* 8007240143* 8007240143*	50-387 50-387 50-387 50-387	K K K K		8007280370* 8007280560 8007280649 8007280649 8007310286*	50-278 P 50-277 Q 50-277 S 50-277 S 50-352 S
	8007250487	50-387	5		8007310286* 8007310414	50-352 8 50-277 R
	8007250487 8007250529 8007280215	50-387 50-387 50-387	B A S	Philibrick, S S Philippines Pioneer Service & Engineering Co.	8007180609 8007160798 8007080208*	50-70 G REQOD 50-305 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY
Pittsburgh, Univ of Popular Bluff Hosp Popular Bluff,HO Portland Cement Association Portland General Electric Co	8006300112* 8007100357 8007100116 8007310010* 8007010334	ACRS PRM REGOD CONTRAC 50-344			8007150707 8007150715* 8007170316 8007180111 6007180128	50-333 50-333 50-284 50-286 50-333	6 6 0
	8007010418 8007020594 8007030233 8007070273 8007070300	50-344 50-344 50-344 50-344 50-344	Р С С Р Р		8007180597 8007210376 8007210377# 8007210418 8007210466	50-286 50-286 50-286 50-286 50-286	G R R S G
	8007070307# 8007070340 8007080418 8007080420# 8007090227	50-344 50-344 50-344 50-344 50-344	P P S S P		8007210526 8007220160 8007230262 8007250270 8007250317*	50-333 50-247 PR 50-333 50-286	9 9 9
	8007070300 8007070327 8007070331 8007070340 8007100037	50-344 50-344 NUREG 50-344 50-344	G G		8007250669 8007280461 8007280461 8007280463* 8007280463*	50-333 50-284 50-284 50-284 50-286	G f I I
	8007100051 8007100058* 8007100062* 8007100345 8007140312	50-344 50-344 50-344 PRM 50-344	G G G R		8007280471 8007280515 8007280524* 8007280610 8007280617*	50-220 50-333 50-333 50-333 50-333	0 8 8 8
	8007140315# 8007150120# 8007150581 8007150820 8007150826#	50-344 50-344 50-344 50-344 50-344	R G S S		8007280642 8007280669* 8007290052 8007290522 8007290580	50-333 50-333 50-284 50-247 50-286	8 8 9 P
	8007160420 8007160608 8007160661 8007170424 8007170483*	PR 50-344 50-344 50-344 50-344	թ 0		8007290692 8007290728 8007290755 8007310426 8007310430#	50-333 50-286 50-286 50-286 50-286	P F S S
	8007170562 8007180347 8007220570 8007230797 8007250350	50-344 50-344 50-344 50-522 50-344	R S P G	Prairie Alliance President of US & Executive Offices	8007310474 8007140337 8007020096# 8007140028 8007140108#	50-333 50-10 50-443 50-367 50-437	G O H H H
	8007250360 8007250413 8007250474 8007250481* 8007280177	50-344 50-344 50-344 50-344 50-344	6 6 6	Princeton Univ Principia College Project Associates Public Service Co of Colorado	8007150013 8007090267 8007090418 8007070418* 8007010234*	50-437 50-10 REGOD CONTRAC 50-247	H D T Q
	8007280545 8007280553* 8007280563 8007280573* 8007280648	50-344 50-344 50-344 50-344 50-344	នេះនេះ		8007010344 8007010346* 8007010496 8007010506* 8007020307	50-267 50-267 50-267 50-267 50-267	R R 8 G
	8007270994 8007270887 8007300294 8007300333 8007300387	50~344 50~344 50~344 50~344 50~344	8 0 0 P		8007080210 8007080215* 8007080254 8007080262* 8007080268	50-267 50-267 50-267 50-267 50-267	8 8 9
otomac Research, Inc ower Authority of the State of New York	8007310433 8007310472 8007300581* 8007010164 8007010448	50-344 50-344 CONTRACT 50-333 50-266	9 0 9		8007080275* 8007080289 8007080304* 8007080404 8007080407*	50-267 50-267 50-267 50-267 50-267	9 9 8 R
	8007010452 8007010455* 8007010481 8007010485* 8007010486	50-284 50-284 50-333 50-333	6 8 8 8 8		8007080422 8007080425* 8007090333 8007100173 8007100176*	50-267 50-267 50-267 50-267 50-267	9 9 8 8
	8007010495* 8007010511 8007010519* 8007030284 8007070212	50~333 50~333 50~333 50~286 50~333	8 9 F F		8007150690 8007220439 8007230534 8007230539* 8007230543	50-267 PR 50-267 50-267 50-267	5 5 8
	8007080303 8007080332 8007080350 8007080354* 8007080355	50-286 50-333 50-286 50-286 50-286	۷ 8 8		6007230548 8007230554* 8007230555* 8007280493 8007280645	50-247 50-247 50-267 50-267 50-267	8 8 9 0
	8007080362# 8007080367 8007090192 8007090195# 8007140333	90-286 50-286 50-333 50-333 50-286	S P R R S	Public Bervice Co of Indiana. Inc	8007280652* 8007290629 8007010096 8007020031* 8007100229	50-267 50-267 50-546 50-546 50-546	8 0 4 0
	8007140347 8007140368 8007140374* 8007140383 8007140384*	50-286 50-333 50-333 50-333 50-333	8 8 8 8		8007140506 8007210058 8007220547 8007230093 8007230238	50-546 50-546 50-546 50-546 50-546	q A H Q G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Public Service Co of New Hampshire	8007250397 8007280591 8007280667 8007010223* 8007080011*	50-546 50-546 50-546 50-443 50-443	S F S Q I	Purdus Univ RMI Co : RMI Titanium RPF Ecological Associates	8007230535 8007090380 8007280397 8007280403* 8007220538	50-376 G FOIA XPORTLIC XPORTLIC 50-10 D	
Public Service Co of Oklahoma Public Service Electric & Gas Co of New Jersey	8007170594* 8007250623 8006300368 8007300569 8007030161	50-443 50-443 50-556 PR 50-272	9 Q A	Rad Services, inc Radiation Detection Co Radiation Management Corp	8005090524* 8007020482 8005290407* 8007170328* 8007170416*	PT9 PR PT9 FOIA FOIA	
\	8007030161 8007030227 8007030232 8007030244 8007030247	50-272 50-311 50-272 50-311 50-272	P P R P	Raiph Stone & Co Reactor Controls, Inc Reactor Experiments, Inc Rensselaer Polytechnic Inst	8007310420* 8007160504* 8007010193* 8007290857 8007090413	50-277 R CONTRACT 50-237 P XPORTLIC REGOD	
	8007030247 8007070110 8007070285 8007070289*	50-272 50-311 50-272 50-272 50-272	P P P P P	Reuter-Stokes, Inc	8007300598* 8007100113 8007110237 8007210316 8007210318*	CONTRACT REGOD XPORTLIC XPORTLIC XPORTLIC	
	8007070348 8007070356* 8007080068 8007080068 8007080267	50-272 50-272 50-272 50-272 50-272	R R F F	Rhine-Scheide-Veroime Zware Appavatenbouw Rhode Island, State of	8007280223 8007310087 8007310179* 8007310182* 8007090272	XPORTLIC XPORTLIC GAPPP GAPPP BO-193 P	
	8007080280* 8007080423 8007080424* 8007100197 8007100202*	50-272 50-272 50-272 50-272 50-272	8 S G G G	Rochester Gas & Electric Carp	8007210118 8007210130* 8007240389* 8007020018 8007070342	71-17 71-17 70-2153 50-244 G 50-244 F	
	8007110444 8007110456 8007110456 8007140429 8007150509	50-272 50-272 50-272 50-272 50-272	0 P P F G		8007080272 8007150584 8007150590* 8007160637 8007180141	50-244 P 50-244 R 50-244 R 50-244 S 50-244 G	! ! 3
	8007150516 8007150517* 8007150596 8007150604* 8007150621	50-272 50-272 50-272 50-272 50-272	5 5 R R R B		8007210443 8007220403 8007220407* 8007230008* 8007240145	50-244 9 50-244 P 50-244 P 50-244 Q PR	
	8007150628* 8007150631 8007150672 8007150679* 8007160628	50-272 50-272 50-272 50-272 50-272 50-311	8 0 8 5 9		8007250498 8007280633 8007280639* 8007270740 8007310350	50-244 Q 50-244 9 50-244 S 50-244 P 50-244 F) ;
	8007160633* 8007170437 8007170448* 8007170570 8007170570	50-311 50-311 50-311 50-272 50-272	P = 8 = 6 = 6	Rockwell International Corp . Atomics International Div Rockwell International Corp . Energy Bystems Div	8007310378 8007310401 8007100013 8007230507	50-244 F 50-244 P PR 50-329 A	•
	8007170642 8007170642 8007210219 8007210268 8007210268	50-272 50-272 50-311 50-272 50-272	9 9 P 9	Rocky Mountain Energy Co	8007250589* 8007020702 8007030002 8007160390 8007180057	70~25 40~8380 40~8380 40~8380 40~8697	
	8007210282* 8007210365 8007210389 8007210494 8007210507*	50-354 50-272 50-311 50-272 50-272	G P P S		8007210146 8007210224 8007220022 8007220035 8007240100	40-8380 40-8380 40-8380 40-8380 40-8380	
	8007210552 8007210408 8007210408 8007220381 8007220382*	50-272 50-272 50-272 50-272 50-272	Q Q Q B 8	Ropes & Gray Rural America S F Appliance, Ltd S M Stoller Corp (subs of Arthur D	8007290890 8007280672* 8007280677* 8007280656 8007070062*	40-8497 50-443 [50-409 9 50-409 9 40-215 CONTRACT	j
	8007220617 8007220627* 8007250297 8007280442 8007280442	50-272 50-272 50-354 50-272 50-272	8 8 9 P P	Little, Inc. SCS Engineers, Inc. SEP Owners Group Sacranento Municipal Utility District	800707005B* 8007100420* 8007080183 8007080270	CONTRACT 50-10 P 50-312 P 50-312 8	.
	8007280443* 8007280443* 8007280624 8007280632* 8007290684	50-272 50-272 50-311 50-311 50-311	P 8 8 8		8007080277* 8007100203 8007100206* 8007150556* 8007150588	50-312 8 50-312 P 50-312 P 50-312 0 50-312 R	P
	8007290499 8007290710* 8007290711* 8007290718 8007290729*	50-272 50-272 50-311 50-272 50-272	R R 6 8 8		8007150592* 8007180541 8007230432 8007230443* 8007240123	50-312 R 50-312 0 50-312 P 50-312 P 50-312 P	R '
Puerto Rico Electric Power Authority	8007290837 8007290844* 8007310293* 8007020604	50-272 50-272 50-354 50-376	8 8 8 9		8007240192 8007240198 8007250348*		a ¦ a ;

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEO		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	
	8007250370 8007250676 8007290847 8007300072 8007300081	\$0-312 \$0-312 \$0-312 PR PR	9 9		8007250353 8007250353 8007250408 8007290533 8007300361	50-320 50-320 50-484 50-346 50-266	0 0 H Q
Safe Energy Alliance	8007300370 8007310410 8007310418* 8007310477 8007110003	50-312 50-312 50-312 50-312 70-2909	H S S	Sheenan, D. P	8007300437 8007300463 8007070337 8007070353* 8007070365*	50-289 50-282 50-320 50-320 50-320	0000
Balisbury.MA Baluda River Electric Cooperative.Inc San Diego Cas & Electric Co San Luis Obispo Mothers for Peace	8007110055 8007140407 8007210486* 8007070234 8007230508	70-2909 30-443 30-413 50-206 50-275	G A P G	Sheldon, Harmon & Weiss	8007070371 w 8007080007 8007080004 8007080005 w 8007080043	50-320 50-320 50-287 50-287 50-289	0000
Sandia Laboratories	8007300096 8007310466 8007020011 8007110148 8007110551	\$0-275 \$0-275 REB REB REB	G G		8007100033 8007100037* 8007100042* 8007110048 8007140018	50-155 50-155 50-155 PR 50-289	0000
	8007180049 8007280081 8007290152 8007290233 8007290251	NUREO RES NUREO RES NUREO			8007140022* 8007140387 8007150552 8007210487 8007210495*	50-289 PR 70-143 50-289 50-289	0
Sargent & Lundy, Inc	8007310007 8007310231 8007310241 8007020416 8007150486	NUREO NUREO NUREO PR NUREO			8007220529 8007220530# 8007230229 8007240044# 8007240050#	50-269 50-269 FOIA COMMIESI COMMIES	
	8007150537* 8007160566* 8007160569* 8007160574* 8007230160*	50-373 50-454 50-454 50-454 QA999	K K		8007280043 8007290781 8007300039 8007300043 8007290781	FOIA ORG PR PR ORG	
Sassafras Audubon Society Beanpower, Inc Beience Applications, Inc	8007010055* 6007010244* 6007010582* 6007140433*	50-546 FOIA CONTRAC CONTRAC		Sierra Club	8007290809* 8007030003 8007070029	ORG PR XPORTLIC	;
	8007140650 8007250552+	FOIA 50-460	Á		8007210129 8007280393	XPORTLIC XPORTLIC	
Self-Powered Lighting, Etd Senate	8007280213* 8007240462 8007020323*	FD1A FD1A 50-320	U		8007310484 8007030305	XPORTE 10 50-522	A
	8007110093* 8007110314*	50-271 50-335	H	Slemmons, D. B Small Dusiness Administration	8007100112# 8007210331# 8007140475	CONTRACT CONTRACT REGOD	
	8007110318 8007110323* 8007110507 8007110571*	50-546 MISC PR 50-482	U	Social Research Applications Corp South Carolina Electric & Oas Co	8007180405 8007160496* 8007070269 8007070270*	50-275 CONTRACT 50-395 50-395	r c
	8007140231* 800724046B* 8007250067* 800731052B*	50-10 50-335 50-320 50-282	H H H		8007080393 8007090011 8007110489	50-395 50-395 50-395	A A B
Senate, Appropriations Senate, Judiciary Committee	8007020188* 8007110005	COMMISS:	NO I		8007140252 8007170407 8007170412#	50-395 50-395 50-395	A
Benete. Small Business Sensible Maine Power	8007080082 8007020607 8007020610* 8007110345	COMMISS 50-309 50-309 PR	0 0 0		8007180256 8007220219 8007220390 8007220392#	50-395 50-395 50-395 50-395	0 0 F
Shannon & Wilson, Inc	8007300122 8007300127* 8007250393* 8007250396* 8007250398*	50-309 50-309 50-397 50-397 50-397	0 0 A A		8007220428 8007250308 8007250459 8007250471	50-395 50-395 50-395 50-395	A A B A
Shaw, Pittman, Potts & Troubridge	8007020482 8007020421	50-320 50-320	9	•	8007290626 8007290627*	50-395 50-395	F
	8007020633 8007020689 8007070310 8007070315*	50-287 PR 50-484 50-484	G G	South Carolina, State of South Dakota, State of	8007310428 8007110087 8007300074* 8007150458 8007010216	70-2860 PR COMMISSI 50-484 50-206	ON R
	8007100191+ 8007140224 8007150527 8007180884+	50-209 50-312 50-312	000		8007010216 8007010358 8007010358 8007010465	50-206 50-361 50-361 50-206	A A P
		50-287 50-287 50-287	00000	5	B007010479 B007010479 B007010533 B007010537+ B007020149+	50-361 50-261 50-206 50-26 50-361	A A S S O
			0	8	8007020149* 8007020362	50-341	G P
			þ		B007020346* B007020372*	50-206 50-206	þ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8007080081 8007080081 8007080271 8007080403 8007080410*	50-341 50-341 50-204 50-206 50-206	A A F S		8007170235 8007170251* 8007170255 8007210073 8007210076*	XPORTLIC SECY XPORTLIC XPORTLIC SECY
	8007090330 8007090330 8007090337* 8007090337* 8007100262	50-361 50-361 50-361 50-361 50-206	S S S R		8007210076 8007240440 8007280547 8007280559 8007290212	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8007100262 8007100386 8007110401 8007140034* 8007140034*	50-204 REGOD 50-204 50-361 50-361	R P G	Stearns-Roger, Inc Stone & Webster Engineering Corp	8007030039* 8007030047* 8007030055* 8007010172* 8007020327	40~8647 40~8647 40~8647 50~333 PR
	8007140051* 8007150579 8007150587* 8007150599 8007150605*	PR 50-206 50-206 50-206 50-206	P R ጸ		8007100277# 8007100280* 8007100284* 8007100284* 8007100284*	50-280 50-280 50-280 50-280 50-280
	9007170565* 9007210463 9007210493 9007230011 9007230287*	50-206 50-361 50-361 50-361 50-206	Q A S Q Q		8007100288* 8007100293* 8007100293* 8007100293* 8007100293*	50-280 50-280 50-280 50-280 50-280
	8007230579 8007240088 8007240088 8007250355 8007250358	50-361 50-361 50-361 50-206 50-206	5 G G G		8007100278* 8007100278* 8007100278* 8007100278* 8007100303*	50~280 50~280 50~280 50~280
	8007250361 8007250636 8007280072 8007280376 8007280382*	50-361 50-204 50-206 50-206 50-206	Q Q Q S S		8007110193# 8007110194# 8007110196# 8007240166# 8007300064	50-280 50-280 50-280 50-337 PR
	8007280391 8007280396* 8007290489 8007290620 8007290706	50-204 50-204 50-361 50-361 50-204	S S Q A P	Stroock, Stroock & Laven Strodent Nurses Association of Pennsylvan ia	8007140585 8007140601 8007240161# 8007240437 8007110443#	50-337 50-337 50-39 FOIA NJG-38UN
	8007290883 8007300303 8007310162 8007310201 8007310201	50-206 50-361 50-206 50-361 50-361	@ @ @ @	Switzerland Synergy, Inc Systems Control, Inc TECH-SIL, Inc	8007140802 8007070052 8007300178* 8007300188* 8007170214	XPORTLIC CONTRACT GA999 GA999 50-379
Southwest Research Institute Southwest Research and Information Center Opingel & McDiermid	8007030071* 8007070174 8007030127 8007110019 8007090051	CONTRACT PR PR PR 50-389	м	Taiwan (Republic of China) Taunton Municipal Lighting Plant Tech/Ops (Technical Operations, Inc.)	8007240472 8007080093* 8007090975 8007090976* 8007090978*	XPORTLIC 50-443 71-9039 71-9039 71-9039
Bt Elizabeth Hosp Appleton, WI Btandard Dil Co of Indiana (see also AMOCO)	8007150449 8007150449 8007150459 8007100416 8007090131	50-445 50-445 50-484 REGOD 40-5021	н н о		8007030379* 8007030381* 8007030384* 8007030385* 8007030386*	71-9037 71-9039 71-9039 71-9039 71-9039
Standardized Nuclear Unit Power Plant System	8005090053	50-482	9		8007030387* 8007100373	71~9039 71~9053
-,	8007010162 8007020378 8007070325 8007070325	50-482 50-482 50-482 50-482	Q Q S S	Technassgciates, Inc	8007100376# 8007140203# 8007210331#	71-9053 CONTRACT CONTRACT
	B007070325 B007070325 B007100441 B007290254* B007290590	50~482 50~482 50~482 50~482 50~482	8 9 8	Teknekron, inc Teledyne Energy Systems Teledyne Engineering Services	B007070057* B007010240 B007010245 B007150526 B007110453	CONTRACT 71-4888 71-9030 TOPREP NUREO
	8007300511 8007310302* 8007310302* 8007310302* 8007310302*	50-482 50-482 50-482 50-482 50-482	A 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Temple Univ Tennessee Valley Authority	8007310384 8007310387* 8007100007 8006250275 8007010327	50-329 50-329 PR 50-518 50-327
Stanford Univ State,Dept of State,Dept of, Bureau of Oceans & Internatl Environ & Scientífic Affairs	8007010627* 80070100191 8007010009	CONTRACT XPORTLIC XPORTLIC			8007010338 8007010350* 8007010370 8007010377* 8007010382	50-518 50-518 50-296 50-296 50-327
	8007010012 8007010019	XPORTLIC XPORTLIC			8007010385* 8007010386	50-327 50-328
	8007020260 8007100146 8007140560* 8007170003	XPORTLIC XPORTLIC SECY XPORTLIC	:		8007010386 8007010417 8007010419#	50-328 50-327 50-327
	B007170072 B007170204 B007170223	XPORTLIC XPORTLIC XPORTLIC	:		8007010424 8007010435 8007010438* 8007010490	50-438 50-327 50-327 50-327

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODS	RY
	8007010499 8007010502> 8007010512 8007010515> 8007010522+	50-327 50-327	\$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8007110039* 8007110291 8007110320 8007110320 8007110320	50-327 50-260 50-518 50-518 50-518	9 9
	8007010525 8007010528 8007010532* 8007010534 8007010539*	50-327 50-327 50-327 50-327 50-327	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8007110320 8007110320 8007110320 8007110328* 8007110328*	50-518 50-518 50-519 50-519 50-519	8888
	8007010541* 8007020347 8007020499 8007020499 8007020499	50-327 50-327 50-259 50-259 50-259	5 G G G		8007110328* 8007110328* 8007110328* 8007110328* 8007110372	50-518 50-518 50-518 50-518 50-327	8 8 8 8
	8007020499 8007020543 8007020544 8007020545* 8007020551*	50-257 50-328 50-328 50-328 50-328	0 9 9 9 8 8		8007110376* 8007110378 8007110380* 8007110388 8007110394*	50-327 50-296 50-296 50-296 50-296	8 8 8 9
	8007020619 8007020619 8007020627 8007020740 8007020742	50-370 50-370 50-327 50-327 PR	s s o o		8007110425 8007140240 8007140349 8007140353* 8007140422	50-276 PRM 50-518 50-518 50-370	8 8 8
	8007070042 8007070045* 8007070248 8007080220 8007080253	40-1341 40-1341 50-259 50-327 50-390	P Q A		8007140422 8007140427* 8007140427* 8007140443 8007140456*	50-370 50-370 50-370 50-328 50-328	8888
	8007080283 8007080281 8007080283 8007080286 8007080286	50-390 50-327 50-327 50-259 50-259	₹ \$ \$ ₽ ₽		8007150455 8007150466* 8007150470 8007150472 8007150472	50-327 50-327 50-327 50-327 50-327	8 9 P
	8007080286 8007080288* 8007080291* 8007080293 8007080297*	50-259 50-327 50-327 50-259 50-259	2 2 2 3 3 4 3 4 3 4 3 4 3 4 3 4 3 4 3 4		8007150488# 8007150491 8007150501# 8007150504 8007150512#	50-327 50-327 50-327	8 8 8
	9007080301 8007080308* 8007080331 8007080331 8007080333*	50-259 50-259 50-259 50-327 50-259	5 8 9 8		8007150521 8007150521 8007150522* 8007150544 8007150544	50-327 50-327 50-438	Р Р А А
	8007080334 8007080341* 8007080370 8007080373* 8007080380	50-327 50-327 50-260 50-260 50-259	S S S P		8007150551 8007150570 8007150571 8007150571 8007150574*	50-259 50-327 50-327	A 8 P 9
	8007080380 8007080388 8007080388 8007080394 8007080399*	50~259 50~390 50~390 50~260 50~260	P V S S		8007180578* 8907150580 8007150582* 8007150585* 8007150640	50-327 50-327 50-327	Р 9 8 9
	8007080400 8007080402# 8007080405 8007080411# 8007080415	50-327 50-327 50-260 50-260 50-276	8 9 8 8 8		8007150640 8007150659 8007150663* 8007150692 8007150692	50-566 50-566	P 8 9 P
	8007080416* 8007090003 8007090006* 6007090222 8007090222	50-296 50-259 50-259 50-390 60-390	9 8 8 9 9		8007160424 8007160424 8007160471 8007160471 8007160473	50-438 50-327 50-327	8 9 P 8
	8007090249 6007090249 6007090258* 8007090258* 6007100047	50-327 50-327 50-327 50-327 PR	8 8 8		8007160473 8007160478* 8007160484* 8007160519 8007160523*	50-327 50-327 50-327	\$ P P \$
	9007100050# 8007100054# 6007100169 9007100205 8007100205	50~438	G G Q		8007160552 8007160556* 8007160571 8007160571 8007160571	50-257 50-328 50-328	R R S S
	8007100209 8007100209 8007100213* 8007100213* 8007100233	50-438 50-438 50-438	8 8 8 8		8007160578* 8007160578* 8007160578* 8007160643 8007160643	50-328 50-328 50-327	9 8 F F
	8007100233 8007100236* 8007100236* 8007100252 8007100328	50-400 50-408	6 6 9 9		8007140450 8007140450 8007140454* 8007140454* 8007140444	50-438 (50-438 (8 8 8 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUDJEC.	lY .	AUTHOR AFFILIATIO		ACCESSION NUMBER	SUBJECT CATEGOR	
	8007170272 8007170342 8007170342 8007170344* 8007170344*	50-370 50-546 50-566 50-566 50-566	0 9 8 8 9			8007230480 8007230481 * 8007230481 * 8007230486 8007230487	50-327 50-327 50-327 50-328 50-390	P P S
	6007170356 8007170356 8007170358* 8007170358* 8007170513	50-566 50-566 50-566 50-566 50-390				8007230487 8007230490 8007230491* 8007230494 8007230499	50-390 50-259 50-259 50-328 50-327	8 8 9 F
	8007170513 8007170525* 8007170525* 8007170540 8007170591	50-390 50-390 50-390 50-260 50-390	3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5			8007230505 8007230505 8007230511 8007230523 8007230528	50-390 50-390 50-327 50-259 50-318	5 A S S
	8007170591 8007170664 8007170664 8007170664 8007180301	50-390 50-328 50-328 50-328 50-296	5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6			8007230531 * 8007230533 8007230533 8007230575 8007230575	50-259 50-327 50-327 50-327 50-327	8 P F F
	8007180314* 8007180523 8007210036 8007210036 8007210036	50-296 50-259 50-327 50-327 50-327	8 0 0 0			8007230582 8007230587 8007230587 8007230591* 8007230591*	50-370 50-370 50-370 50-370 50-370	9888
	8007210036 8007210091 8007210091 8007210091 8007210103	50-327 50-259 50-259 50-259 50-259	Q Q Q Q			8007230724 8007230724 8007230724 8007240279* 8007240455	50-259 50-259 50-259 50-518 50-259	9 9 9 9
	8007210103 8007210461 8007210475# 8007210596 8007220236	50-259 50-327 50-327 50-327 50-518	Q \$ \$ Q Q			8007250414 8007250416* 8007250418 8007250436 8007250497*	50-327 50-327 50-327 50-327 50-327	8888
	8007220342 8007220342 8007220342 8007220346* 8007220346*	50-259 50-259 50-259 50-259 50-259	R R R R			8007250585 8007250576 8007250576 8007250576 8007280001	40-1341 50-259 50-259 50-259 50-327	0 0 0 P
	8007220346* 8007220358 8007220360* 8007220376 8007220376	50-259 50-327 50-327 50-259 50-259	ጽ ጽ የ የ			8007280001 8007280449 * 8007280469 * 8007280468 * 8007280478	50-327 50-259 50-259 50-259 50-327	р О О
	8007220374 8007220377* 8007220377* 8007220377* 8007220443	50-259 50-259 50-259 50-259 50-259	P P P R			8007280498 8007280548 8007280548 8007280615 8007280615	50-327 50-327 50-327 50-259 50-259	G F G
	8007220443 8007220443 8007220450 8007220460 8007220462*	50-259 50-259 50-553 50-327 50-259	R R S A R		•	8007280613 8007280613 8007280623 8007280623 8007280660	50-259 50-259 50-327 50-327 50-439	0 P B
	8007220462* 8007220462* 8007220469 8007220474* 8007220481	50-259 50-259 50-327 50-327 50-259	R R S S R			8007290479 8007290578 8007290610 8007290632 8007290633	50-327 50-327 50-328 50-328 50-327	9 8 8
	8007220481 8007220481 8007220491* 8007220491* 8007220491*	50-259 50-259 50-259 50-259 50-259	ቪ R R R			8007290636 8007290639 * 8007290646 8007290649 8007290651	50-327 50-327 50-327 50-327 50-327	8 8 8 8 P
	8007220522 8007220522 8007220522 8007220532 8007220568	50-259 50-259 50-259 50-327 50-327	ପ ଫ ଫ P ଶ			8007270656* 8007270657 8007270657* 8007270642 8007270664*	50-327 50-259 50-327 50-327 50-259	88888
	8007220574* 8007230255 8007230255 8007230408 8007230408	50-327 50-546 50-566 50-327 50-327	8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8			9007290665 8007290672* 8007290673* 8007290675 8007290679	50-327 50-327 50-327 50-327 50-327	8 8 8 P
	8007230431 8007230445 8007230452* 8007230467 8007230467	50-328 50-259 50-259 50-327 50-327	8 8 8 P			8007290679 8007290681 * 8007290685 8007290693 * 8007290695	50-327 50-327 50-327 50-327 50-294	P 50 50 50
	8007230470 8007230474* 8007230477 8007230477 8007230480	50-259 50-259 50-327 50-327 50-327	\$ \$ P P			8007270702* 8007270715* 8007270715* 8007270720 8007270724	50-296 50-327 50-327 50-260 50-327	99995
								Ė

AUTHOR AFF(LIATION	ACCESSION NUMBER	SUBJEC	IRY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC	
	8007270724 8007270725 8007270725 8007270726* 8007270734	50-327 50-438 50-438 50-240 50-518	P	Texas, Univ of The Nuclear Regulatory Commission Three Mile Island Alert	8007210320 8007290294* 8007140003 8007140008 8007140009*	70-157 50-327 50-289 50-289 50-289	0000
	8007290737 8007290744* 8007290749 8007290749 8007290757	50-259 50-259 50-438 50-438 50-327	55 S S P		8007220001 8007220002 8007250680 8007250689 8007250779	50-289 50-289 50-289 50-289 50-289	9 9 9 9
	8007290757 8007290762 8007290770* 8007290790 8007290800*	50-327 50-327 50-327 50-327 50-327	8 8 8	Time & Frequency Technology, Inc Todd Shipyards Toledo Edison Co	8007220224* 8007240228 8007010254 8007010434 8007010439*	MISC 70-1062 50-346 50-346 50-346	Q 8 8
	8007290810 8007290813 8007290818* 8007290820 8007290822	50-327 50-390 50-327 50-296 50-327	8 9 8		8007010464 8007020040 8007030260 8007030264* 8007090284	50-344 50-344 50-344 50-346 50-346	P Q 8 8 6 F
	B007290827* B007290829* B007290864 B007290927 B007300003	50-327 50-296 50-259 PR PRM	s s		8007110391 8007110397* 8007110407 8007110416* 8007110418	50-346 50-346 50-346 50-346 50-346	8 8 9 9
	8007300147 8007300374 8007300376* 8007300376* 8007300434	50-438 50-327 50-327 50-327 50-327	\$ * * F		8007110423* 8007110427 8007110434* 8007110440 8007110448*	50-346 50-346 50-346 50-346 50-346	8 8 8
	8007300434 8007300572 8007300572 8007310056 8007310067	80-327 50-259 50-259 50-327 50-259	6 0 0		8007140237 8007140318 8007140322* 8007150560 8007150566*	50~346 50~346 50~346 50~346 50~346	G R R S
	8007310067 8007310067 8007310200 8007310200 8007310200	50-259 50-259 50-259 50-259 50-259	0 0 0 0		8007150607 8007150670 8007150824 8007170064 8007170441	50-346 50-346 50-346 50-346 50-346	9 0 0
	6007310323 6007310325* 8007310355 8007310396 6007310396	50-327 50-327 50-259 50-327 50-3 27	Р 0 р р		8007170450# 8007170532 8007180271 8007180310 8007210216	50-346 50-346 50-346 50-346 50-346	8 0 0
	8007310411 8007310411 8007310412 8007310416 8007310416	50-327 50-327 50-327 50-327 50-327	ዮ የ የ የ		8007210454 8007220375 8007220378* 8007220458 8007220465*	50-346 50-346 50-346 50-346 50-346	P 8 8 8
Teton Exploration Brilling Co . Inc	8007010129 8007010140* 8007010432 9007280694 8007280702	40-8728 40-8728 40-8728 40-8728 40-8728			8007230076 8007230141 8007230200 8007230200 8007230581	50-346 50-346 50-346 50-346 50-346	0 0 0 0
Teras A & M Univ	8007210502 8007210512* 8007240038 8007290468 8007290475*	50-59 50-59 50-59 50-128 50-128	R R R R		8007240028* 8007240126 8007250382 8007250427 8007250434	50-346 50-346 50-346 50-346 50-346	0 8 9 9
Texas Instruments, Inc	8007070048 8007210175# 8007220527 8007250445 8007280147#	70-33 70-33 70-33 70-33 50-367	R		8007250438# 8007250572 8007260465 8007280571 8007280578#	50-346 50-346 50-346 50-346 50-346	P G P 8
Texas Public Interest Research Group Texas Utilities Generating Co	8007030075 8007170374 8007300114 8007030246 8007080062	PR 50-466 50-466 50-445 50-446	0 0 6 8		8007280583 8007280589* 8007280594 8007280402* 8007280409	50-346 50-346 50-346 50-346 50-346	8 8 8
	8007080282 8007110592 8007140455 8007140502* 8007160425	50-445 50-445 50-445 50-445 50-445	F G G M		8007280422* 8007280430 8007280643* 8007270500 8007300141	50-346 50-346 50-346 50-346 PR	8 8 8 0
	8007170196 8007180366 8007180437 8007210352 8007210478	50-445 50-445 50-445 50-445 50-445	Q A Q 8 A	Transnuclear, Inc	8007310348 8007310380 8007310536* 8007030011* 8007030016*	50-346 50-346 50-346 70-2478 70-2478	Q P Q
Teras, State of	8007310328 8007020577 8007110054 8007170216# 8007300573	50-445 50-498 PR CONTRACT PR	e M		80070300£0* 8007070018 8007070043 8007070140 8007070145	70-2478 XPORTLIC PR XPORTLIC XPORTLIC	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Υ		AUTHOR ILIATION	ACCESSION NUMBER	SUBJEC*	
	8007110449 8007110480 8007150353 8007290025 8007290027	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC				9007230488 9007230489* 9007230495 9007230173 8007250188	50-271 50-271 50-271 50-271 50-271	8 9 9
	8007290390 8007290446 8007290452* 8007310485* 8007310496*	XPORTLIC XPORTLIC XPORTLIC 70-2478 70-2478		Vermont, State of Vet Admin Hosp	Marthport, NY	8007250488 8007280661 8007310385 8007110101 8007070112	50-271 50-271 50-271 PR PR	P F P
Transportation,Dept of Tubeco, Inc Tulsa Gamma Ray, Inc	8007020447 8007140521* 80072703&8* 8007270372* 8007210200	PR GGNTRACT GA999 GA999 71-139		Virginia Electric	& Power Co	8007010340 8007010353 8007010363 8007010375* 8007010394*	50-286 50-339 50-404 50-339 50-286	8 6 6
Twomey, Latham & Schmitt Underwriters Laboratory Union 76 Minerals Exploration Co	8007210205* 8007290701 8007010373* 8007010305 8007210560	71-139 0R0 50-313 40-8584 40-8584	F			8007010398 8007010413 8007010419* 8007010422 8007010422	50-339 50-338 50-339 50-280 50-280	8 9 P P
Union Carbide Corp	8007210566* 8007080217 8007140371 8007170571 8007210293*	40-8584 40-299 40-299 40-299 70-487				8007010422 8007010429 8007010430 8007010430 8007010430	50-280 50-280 50-280 50-280	P 9 P P
	8007220025 8007220056* 8007220064* 8007220074* 8007220081*	WASTE MO WASTE MO WASTE MO WASTE MO	r T T			8007010430 8007010442* 8007020001 8007020456 8007020585	50-280 50-280 71-5957 50-338 PR	Р 8 Р
	8007220087* 8007280473 8007290145 8007310497 8007310500*	WASTE MO XPORTLIC NUREC WASTE MO WASTE MO	r			8007020592 8007020598* 8007030078 8007030131 8007030131	50-336 50-338 PRM 50-280 50-280	P P
Union Electric Co	8007100379 8007150006* 8007150010* 8007150534 8007210198	50-483 50-483 50-483 50-483 50-483	A Q Q F Q			8007030135* 8007030135* 8007030151 8007030156 8007030184	50-260 50-260 50-339 50-339 50-260	ቴ 6 6
Union Minerals Union of Concerned Scientists	8007250334 8007020028 8007290619 8007010284 8007080050*	50-483 40-8584 40-8584 ORG 50-289	g G			8007030184 8007030262 8007030269 8007030267* 8007030267*	50-280 50-339 50-339 50-339 50-338	F 8 8 8
	8007140022* 8007210495* 8007290012* 8007290781 8007290803*	50-289 50-289 SECY ORG ORG	G G			8007030270 8007030271* 8007030273 8007030275* 8007030281	50-338 50-338 50-339 50-339 50-339	8 8 8 8
United Illuminating United Nuclear Corp	8007080012* 8007140380* 8007180277 8007180288 8007180480	50-443 40-277 40-8681 40-8602 40-8678	1			8007030283* 8007030285 8007030288* 8007070200 8007070201	50-339 50-339 50-339 50-339 50-339	5 6 8 6 P
United Nuclear Corp ,Naval Products Div Utah, State of	8007220063 8007220070* 8007280194 8007180066* 8007210090	40-8728 40-8728 WASTE MO 70-371 40-8681	r			8007070224 8007070229* 8007070283 8007070283 8007070358	50-280 50-280 50-338 50-339	88008
Utility Workers Union of America Valcor Engineering Corp Valore, C Vanderbilt Univ.	8007100348 8007160366 8007250297 8007110112 8007090048	PR 50-369 PT21 50-272 PR	5 0			8097070363* 8097070373 8097070374 8097070379* 8097070381*	50-339 50-338 50-339 50-339 50-338	8888
Vermont Electric Cooperative, Inc Vermont Yankee Nuclear Power Corp	8007080028* 8007010317 8007010391 8007010397 8007010405*	50-443 50-271 50-271 50-271 50-271	I 8 1 B			8007070389 8007070397* 8007080069 8007080072* 8007080419	50-280 50-280 50-338 50-336 50-280	9 9 9 9
	8007070247 8007070240 8007070346 8007080292 8007080296*	50-271 50-271 50-271 50-271 50-271	F 8 P Q Q			8007090057 8007090057 8007090057 8007090057 8007090296	50-260 50-260 50-260 50-260 50-339	a :
I	8007110460 8007170325 8007180398 8007180400* 8007180549	50-271 50-271 50-271 50-271 50-271	9 9 R R G			8007090304* 8007090308 8007090312* 8007090317 8007090323*	50-339 50-339 50-339 50-339 50-339	8 8
	8007180594 8007210448 8007210456 8007210467* 8007210579	50-271 50-271 50-271 50-271 50-271	G Н R R G			8007090335 8007090342* 8007090345 8007090353* 8007090423	50-339 50-339 50-338 50-338 50-280	8 S B G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEORRY	,
	8007070423 8007090423 8007100159 8007100273 8007100273	50-280 50-280 50-337 50-280 50-280	G G P P		8007220431 8007220431 8007220436* 8007220436* 8007220487	50-338 50-338 50-338	222
	8007100273 8007100273 8007110189 8007110189 8007110202	50-280 50-280 50-280 50-280 50-339	P P Q Q P		8007220507 8007220512* 8007220575 8007220579 8007220579	50-338 50-338	988FF
	8007110300 8007110300 8007110334 8007110334 8007110359	50-338 50-338 50-280 50-280 50-339	9 9 0 0 P		8007220580* 8007220582* 8007220582* 8007220401 8007220411*	50-338 50-338 50-337	86-688
	8007110361 8007110364 8007110365* 8007110390 8007110420	50-339 50-339 50-339 50-281 50-339	P P Q S		8007230447 8007230447 8007230493 8007230497* 8007240005	50-338 50-338 50-338	9000
	6007140158 6007140167 6007140209 6007140225* 8007140249	50-339 50-339 50-339 50-339 50-280	P 5 8 8		8007240049 8007240092 8007240092 8007240115 8007240116*	50~338 50~338 50~339	AFFPF
	8007140259* 8007140393 8007140393 8007140400* 8007140400*	50-260 50-338 50-338 50-338 50-336	8 P P P		8007240149 8007250345 8007250379 8007250383 8007250383	50-281 50-337 50-338	ተመውሞው
	8007140406 8007140411* 8007150462 8007150462	50-339 50-339 50-280 50-280 50-338	P G G P		8007250385* 8007250385* 8007250388 8007250415 8007250415	50-338 50-339 50-338	4646
	8007150567 8007150671 8007150686 8007150701* 8007150767	50-338 50-339 50-338 50-338 50-338	P 0 8 8		8007250430 8007250545 8007250545 8007250545 8007250545	50-280 50-280 50-280	P 0 0 0 0
	8007150777* 8007150808 8007150810 8007150815* 8007150817*	50-338 50-339 50-339 50-339 50-339	8 8 8 8		8007280367 8007280375 8007280400* 8007280406 8007280423	50-339 50-339 50-339	ተተመመ ቀ
	8007160507 8007160543 8007160543 8007160664 8007160671	50-339 50-280 50-280 50-281 50-339	6 0 0 6		8007280432 8007280432 8007280440 8007280444 8007280607	50~338 50~337 50~339	***
	8007170175 8007170183+ 8007170187+ 8007170334 8007170334	50-337 50-337 50-337 50-280 50-280	P የ የ		B007280618* B007280625 B007280651 B007280651 B007290220	50-280 50-338 50-338	2000
	8007170334 8007170334 8007170348 8007170348 8007170350>	50-280 50-280 50-280 50-280 50-280	9 9 V V		8007270220 8007270700 8007270700 8007270838 8007270840	50-338 50-338 50-338	98440
	8007170389 8007170389 8007170391* 8007170391* 8007170412	50-280 50-280 50-280 50-280 50-280	R R R F	•	8007290B40 8007290B40 8007290B40 8007290B43* 80073001B3	50-280 50-280 50-338	40000
	8007170412 8007170529 8007170529 8007170566* 8007170601	50-280 50-280 50-280 50-260 50-338	F Q Q P F		8007300450 8007300458 8007310277 8007310346 8007310384	50-339 PR 50-339	44 44
	8007170601 8007180317 8007180327* 8007180371	50-338 50-281 50-281 50-281 50-280	F S Q Q	Virginia Tech	8007310370 8007310421 8007310421 8007230498 8007230503*	50-281 50-280 50-280 50-124 50-124	ተተተተ ተ
		10 10 10 17	8 8 9	Virginia, Univ of Vollen, 8 J	8007210429 8007210429 8007210433* 8007210433* 8007080055	50-62 50-62 50-62 50-367	ፍክባጥጥ
		39 30 30	P P	WAPORA.Inc Wapner, Cymningham, Yaughan, Genders & McLaughlin	8007030357* 8007110144	CONTRACT 50-302	H
		11 39	P P	Washington Public Power Supply System	8007010002 8007010083*	50-397 50-397	A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY
	8007150680 8007160487 8007170577 8007170577 8007170585*	50-397 NUREO 50-460 50-460 50-460	A S S	,	8007180455* 8007180504* 8007180565 8007210077* 8007210287	XPORTCIO TOPREP 70-1191 70-1151 70-1143	
	8007170\$85* 8007180329 8007210392 8007230003 8007230007	50-440 50-508 50-397 50-397 50-508	6 Q A Q Q		8007220496* 8007220560 8007230015* 8007240096 8007250685	TOPREP XPORTLIC 70-184 71-5450 XPORTLIC	
	8007230423* 8007250354 8007250391 8007250544 8007290405	50-397 50-397 50-397 50-460 50-508	Q Q A A G		8007280372 8007280479 8007280495* 8007290687* 8007310069	XPORTL10 50-594 50-594 50-454 XPORTL10	A A K
	8007290444 8007290518 8007290704 8007300299	50-460 50-460 50-397 50-460	9 9 9	Westinghouse Electric Corp , Nuclear Energy Systems	8007310073* 8007020590 8007020596*	XPORTLIC TOPREP TOPREP	:
	8007300299 8007300306 8007300344 8007300544 8007310171	50-460 50-508 50-508 50-397 50-397	0 F 0		8007140373# 6007220486# 8007220499# 8007220503# 8006300017	TOPREP TOPREP TOPREP TOPREP 70-1151	
	8007310409 8007310498 8007310502	50-397 50-397 50-397	A Q	Div	B006300292 B007210410	70-1151 TOPREP	
Washington State Univ	8007110225 8007110231* 8007110239*	PR PR PR		Group	8007220482 8007140034*	TOPREP	
Washington Univ Washington, State of	8007160540 8007180368 8007150159	50-10 50-10 REGOD	D D	White, M. P. Consulting Engineer Widoff, Reager, Selkowitz 3 Adler	8007210029 8007140003 8007140008	50-361 ACRS 50-289 50-289	6 6
Hashington, Univ. of	8007210113* 8007290045* 8007290050* 8007020025*	State Pr State Pr State Pr CONTRACT	og og		8007140009* 8007220001 8007220002 8007220585 8007250480	50-289 50-289 50-289 50-289 50-289	9999
Western Canada Hydraulic Laboratories, Ltd Western Nuclear, Inc. (subs. of Phelps	8007070130* 8007070079	50-329 40-1162	A		80072506B9 8007270779	50-289 50-289	9
Dodge Corp }	8007100091*	40-1162		Williams Collego, Massachusetts Williams∼Robinette & Associates, Inc	8007100137 8007240021	REGGD 40-1162	
Western Nuclear, Inc Westinghouse Electric Gorp	8007140549 8007220314 8006240081 8007010005 8007010079	PR 40-1162 40-1162 PR FOIA			8007010030 8007010030 8007010036 8007010043 8007010042	50-244 50-305 50-244 50-244	9 9999
	8007010102 8007020221 8007020641 8007020644* 8007020658	XPORTLIC 70-1143 TOPREP TOPREP XPORTLIC			8007010062 8007010409 8007010420* 8007020340 8007080381 8007080384*	50-266 50-266 50-266 PR 50-301 50-301	0 88 80
	8007030012 8007070023 8007070024* 8007070041 8007070125	PR XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8007090230 8007110317 8007110326# 8007110333 8007110340#	50-301 50-305 50-305 50-266 50-266	300000
	8007080371 8007100191* 8007100253 8007100254* 8007100263	50-339 PR TOPREP TOPREP XPORTLIC			8007110342 8007110347* 8007110353 8007110357* 8007140559	50-301 50-301 50-301 50-301 PR	8888
	8007100271* 8007100358 8007100370* 8007110021 8007110492	XPORTLIC PRM 70-1151 XPORTLIC PR			8007150610 8007150618* 8007150618* 8007150648 8007150648	50-266 50-266 50-266 50-266 50-266	8 8 8 8
	8007110522 8007140367 8007140379* 8007140407 8007140416*	PRM TOPREP TOPREP TOPREP TOPREP			9007190453 8007190482 8007150482 8007150482 8007140757	50-266 50-266 50-266 50-266 50-266	P P G
	B007140420* B007140540* B007150646 B007150652* B007150656*	TOPREP ACRS TOPREP TOPREP TOPREP			9007170524 8007170524 8007210408 8007210408 8007210438*	50~266 50~266 50~266 50~266 50~266	9 9 9 9 9
	8007160188* 8007160743 8007160755* 8007160765* 8007170230	QA979 TOPREP TOPREP TOPREP 50-295	8		8007210438* 8007210452* 8007210460* 8007210465* 8007210465*	50~266 50~266 50~266 50~266 50~266	ф ф ф ф
	8007170258* 8007180357 8007180449	SECY 50-244 XPORTLIC	P	•	8007220071 8007230802	50-266 50-502	i á

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
	8007240342 8007240342 8007300085 8007300381 8007300430	50-266 50-266 PR 50-266 50-266	G G G		8007210542 8007210548* 8007210553* 8007220303 8007220310*	40-8502 40-8502 40-8502 40-8304 40-8304	2
Wisconsin Public Service Corp	8007300440 8007300440 8007300456 8007020032 8007020256	50-266 50-266 50-266 50-305 50-305	F G G	Wyoming Outdoor Council Wyoming, State of	8007220315* 8007280200 8007170106 8007220520 8007010567	40-8304 40-8502 40-8745 40-1162 40-8304	!
	8007020716 8007080206 8007080386 8007080390* 8007160464	50-305 50-305 50-305 50-305 50-305	й Р 8 8		8007020064 8007020083 8007020458 8007020694 8007030219	40-8697 40-8697 40-8721 40-8502 40-8380	!
	8007160474¥ 8007160465 8007160502* 8007160510* 8007160544	50-305 50-305 50-305 50-305 50-305	\$ \$ \$ \$		8007030226 8007030352 8007070115 8007070120 8007210063	40-8745 40-8102 40-8380 40-8502 40-8697	
	8007160548* 8007220229 8007240321 8007240334 8007240415	50-309 50-305 50-305 50-305 50-305	R P G Q	Yale Univ Yankee Atomic Electric Co	8007210066 8007280054 8007280303 8007020464 8007010057	40-8502 40-8502 40-8502 PR 50-29	q
	8007280414 8007280649 8007280674* 8007280675 8007280685*	50-305 50-305 50-305 50-305 50-305	F 8 8 8		6007010403 6007010404 6007020307 6007020315 6007020329	PR 50-29 PR PR PR	I
Wisconsin's Environmental Decade Ulisconsin, State of	6007230407 6007280477 6007310373 6007110257 6007140402	50-266 50-301 50-266 PR PR	о С Н		8007020695 8007070284 8007070407 8007080079 8007080310	PR 50-29 PR 50-29 50-29	8 P F
Misconsin, Univ. of Madison	8007140408* 8007140417* 8007140538 8007180337 8007310403	PR PR PR 50-407 50-156	D R		8007090233 8007110529 8007140030 8007140300 8007140338	50-29 PRM PRM 50-29 50-29	F P P
Wm Harsh Rice Univ Wolfbein.S L Wollver, J D Woodward-Clyde Consultants, Inc	6007310405* 6007310231 6007030345* 6007220565 6007010364*	50-155 NUREO CONTRAC 50-358 50-361	R G A		B007140701 B007150143 B007170116 B0071705B2 B0071B0097	NUREG PR 50-29 50-29 50-29	a a a
Worsham, forsythe & Sampels	6007080063* 6007250400* 8007250402* 8007250403* 8007140625	50-361 50-397 50-397 50-397 50-445	A A A M		8007180144 8007210002 8007210399 8007210405* 8007210504	50-29 50-29 50-29 50-29 50-29	Q R R Q
Hyle Laboratories Wyoming Mineral Corp	6007310269* 6007010214 6007010591 6007020079 6007030358	FOIA 40-8585 40-8502 40-8502 40-8502			8007250273 8007250278 8007280439 8007280439 8007280492	50-27 50-29 50-29 50-29 50-29	Q Q P P
	8007030363* 8007030364* 8007070147 8007150644 8007150651*	40-8502 40-8502 40-8502 40-8502 40-8502			8007280584 8007280621 8007280626 8007300007 8007310464	50-29 50-29 50-29 PR PR	p P N
	8007150657* 8007150667* 8007210095 8007210101 8007210191	40-8502 40-8502 40-8502 40-8502 40-8502		Yarway Corp York, PA Zimmer Area Citizens — Zimmer Area Citizens of KY	8007010029* 8007220033* 8007300012* 8007110094	GA999 50-289 50-320 50-358	H H Q

REPORT NUMBER INDEX

subject category column in this index gives the docket mber and the symbol for the category of information than that docket; for example, 50-320 P. The docket subject cories are defined in Appendix A.

Dject categories for nondocketed items are also entered this column by symbol; for example, ACRS. These cateries are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESBION NUMBER	BUBJECT CATEOGRY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	BUBJECT CATEODRY	OTHER REPORT NUMBER
111-017-02	8007220372*	50-70 F	1	8007230177	8007230177	RES	LD-MR-005
11600 02	80072304624	50-322 /	\	8007230185	8007230185	RES	RE-A-80-044
21A A05A	#EES01237008	TOPREP		80072301 94	8007230194	RES	RE-A-80-047
36A93 R1	8007210404*	50-437 /		8007230223	8007230223	RES	
441TL337	8007020135×	WABTE MOT	16569	8007230231	8007230231	AEB	
44250-1	8007310269*	FOIA		B007240257	8007240257	REB	
BO-RD-100	8007010226*	50-206 F		8007240294	6007240294	RES	
80-RD-100	8007100269*	50-206 F		8007250186	8007250186		E00-EA-5174
8005130445	8005130445	RES		8007250306	6007250306		9 E00-EA-5197
E007020011	8007020011	RES		8007280002	8007280002	RES	
E007020016	8007020016	RES		8007280004	8007280004	RES	
8007020085	8007020085	RES	BNL-NUREG-27461	8007280081	8007280081	HES	4441/ML-13
8007020356 8007020364	8007020356	RES	ORNL/HABRD-75	8007280092	0007280092	RES	ORNC/FTR-059
8007020354	8007020364 8007030015	RES RES	BNL-NUREQ-27595	8007280095 8007280164	8007280095 8007280164	RES RES	ORNL/HASRD-84 EGG-TFBP-5043
2007030013	8007030019	KEB		8007200104	0007280164	KEB	E00*1P8P*3043
8007110148	8007110148	REG		E007280171	8007280171	RES	LO-MR-007
8007110551	8007110551	REB	CON Misono de	8007280174 8007280178	8007280174 8007280178	RES	LTR 141-109
E007140031 E007140044	8007140031 8007140044	RES RES	ORNL/HASRD-81 ORNL/HASRD-82	8007280186	8007280176	REB REB	EGG-CAAP-5191 EGG-CAAP-5190
6007140503	8007140503	RES	ORNL/ED/EI8-131	8007290163	0007290163		P EQQ-EA-5178
8007140507	0007440807	RES		8007290174	0007000174	nee	CAA_TERE_TO.CAG
8007140634	9007140507 800/140634	RES	ORNL/HASRD-03	8007270174	8007290174 8007290180	RES RES	EGG-TFBP-TR-502 UBNRC-P394
B007140642	8007140642	REG	NRC-04-74-180	8007270191	8007270180	RES	USNRC-P394
B007150016	8007150016	RES	ORNL/FTR-850	8007290201	8007270201	RES	EGG-TF0P-5080
8007150059	8007150059	RES	E00-CDAP-5144	8007290226	8007270226	RES	E00-CAAP-5189
8007150066	8007150066	RES		8007290233	8007290233	RES	
8007150407	8007150407	REB		B007290241	6007290241	RES	
8007150409	8007150409	RES	EEQ-LOFT-5165	8007290246	8007290246	RES	
8007160280	6007160280	RES		8007310181	8007310181	REG	
B007170460	8007170460	REB	NRC-04-74-180	8007310183	8007310183	RES	
B007170648	900717064B	REB	ORNL/ED/EIS-130	8007310197	8007310187	RES	
8007180233	8007180233	REB		Ø007310251	8007310251	RES	ORNL/HASRD-86
8007180240	8007180240	REG		BAW-1421	8007090201*	TOPREP	
8007180245	8007180245	RES		BAV-1423	9007240002*	TOPREF	
8007180253	8007180253	RES		019 219 BIE-HAB	8007010010+	70-824	
8007180330	8007180330	RES		BAM-381	B007020350*	70-824	19876
8007180352	8007180352	RES RES	ORNL/HASRD-77	CEN-119(B)-#P CEN-121(B)-#P	8007090332*		P
8007180354 8007180361	8007180354 8007180361	RES	ORNL/ED/EAS-80/	CEN-124(B)-NP PT1	8007090341* 8007090352*	50-317 1 50-317 1	p o
8007210001	8007210001	RES		CEN-124(B)-NP PT2	B007090361*		, P
8007210003	8007210003	REB		CEN-124(8)-NP PT3	B007090368*	80217	p.
8007210005	8007210003	RES		CEN-133(B)	8007090368*	50-317 50-317	
B007210007	8007210007	RES		CENPD-153-NP R1	8007110248*	TOPREP	•
8007210010	8007210010	RES		CENPD-183 R1	8007100212*	TOPREP	LD-80~035
8007210014	8007210014	REB		CENPD-255 R1	8007100220#	TOPREP	
8007210017	8007210017	RES	EGG-LOFT-5172	EDAC-117-253 01 R1	8007280406*	TOPREP	
8007210402	8007210602	RES	** * * *	EDAC-117-253 OF R1 8	80072203624		p
8007210407	8007210607	RES		EDAC-117-253 Of R1 S	80072203664		Þ
8007220038	8007220038		E99-EA-5186	EDAC-117-253 02 R1	8007220356*	50-70 I	þ
8007220045	8007220045	RES	E00-L0FT-5192	EDAC-117-258 01	8007220369+	90-70	Þ
8007220047	6007220047	RES	BNL-NUREQ-27591	EDAC-117-258 02	80072203534	50-70	Þ
8007220053	0007220053	REB	BNL-NUREG-27759	EE-46-0004	8007280652*		Ġa .
8007220058	8007220058	RE8		EGDP-ESE-15 R2	8007140373*	TOPREP	
8007220065	8007220065	RES	EQQ-CDAP-517G	QAI-TR-106 R2A	8007070106	TOPREP	
8007230172	8007230172	50-334 P	EGO-EA-5174	I.D 77-11-07	8007140051*	₽R	

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
ISBN 0-87448-106-1 J231 NAC-E-801 R1 NEDD-24781-1 NUREG-0030 V3 NO2	8007140046* 8007220317* 8007300001 8007220334* 8007240262	40-1162 71-6698	16747 16834 CREARE – TN-307	ORD-4207-13 PNL-2882 PNL-3340 PNL-3340 SECY-75-429	8007290475* 8007300113 8007090186* 8007210315* 8007080034	50-128 F PR 70-1257 70-1257 FOIA	_
NUREG-0304 V4 NUREG-0561 R1 NUREG-0597 NUREG-0662 V1 NUREG-0668 DRFT	8007310004 8007030374 8007030373 8007180007* 8007100369	NUREO NUREO NUREO 50-320 NUREO	P	8ECY-79-106 8ECY-79-299 8ECY-79-371A 8ECY-79-424 8ECY-80-107A	8007110548 8007100098 8007020248 8007140121 8007160786	SECY SECY SECY SECY	
NUREO-0675 89 NUREO-0680 NUREO-0685 NUREO-0687 NUREO-0694	8007110034* 9007110560 8007090017* 8007170440* 8007220368	NUREC	Ē	SECY-80-107B SECY-80-132C SECY-80-132E SECY-80-153 SECY-80-153A	8007110484 8007180012* 8007180004 8007070598 8007140574	8ECY 50-320 F 50-320 F SECY	
NUREG-0698 NUREG-1385 NUREG/CR-0208 RI NUREG/CR-0508 NUREG/CR-0570 V2 APP	8007280087 8007180049 8007100363 8007290145 8007240283	50-320 NUREG NUREG NUREG NUREG	P BANDBO-7027 ANL-CT-78-37-2 Y/DW-128	9ECY-80-171 8ECY-80-181 8ECY-80-280 8ECY-80-238A 8ECY-80-242	8007100264 8007170083 8007110532 8007090033* 8007230179	SECY SO-320 SECY 10CFR SECY	p
NUREO/CR-0742 NUREO/CR-0743 NUREO/CR-0830 NUREO/CR-1100 NUREO/CR-1118	8007310231 8007290251 8007220019 8007210498 8007220034	NUREG NUREG NUREG 50-247 1 NUREG	GAND78-7017 GAND79-0349 PNL-3022 PORNL/NUREO/TM-3 UCRL-52742	SECY-80-274 SECY-80-275 SECY-80-275 SECY-80-275A SECY-80-275B	8007250019* 8007090015 8007140059* 8007140055 8007170604*	10CFR BECY BECY BECY 10CFR	
NUREO/CR-1119 NUREO/CR-1169 V3 NUREO/CR-1184 NUREO/CR-1195 NUREO/CR-1198 V1	8007310225 8007180072 8007310007 8007270217 8007310241	NUREO NUREO NUREO 50-254 I NUREO	4259 UCRL-92730 8AND79-1787 SNICO-1023 GAND79-2378/1	8ECY-80-278 8ECY-80-283 8ECY-80-271 8ECY-80-274 8ECY-80-278	8007250176 8007140182 8007290002 8007140552 8007150050	SECY 50-247 SECY SECY SECY	P 43FR48621
NUREG/CR-1209 NUREG/CR-1234 NUREG/CR-1253 NUREG/CR-1258 V2 NUREG/CR-1260	8007310019 8007220024 8007170311 8007140617 8007300041	50-219 NUREQ NUREQ NUREQ NUREG	0 UCRL-52744 PNL-3286 UCID-18123-79-4 DRNL/NUREO/TM-3	5ECY-80-299 BECY-80-301 BECY-80-306 SECY-80-307 SECY-80-308	8007290023 8007140339 8007150069 8007150054 8007280062	SECY SECY SECY SECY	
NUREO/CR-1289 NUREO/CR-1295 NUREO/CR-1301 NUREO/CR-1314 NUREO/CR-1357	8007310216 8007310246 8007310210 8007030350 8007310234	NUREG NUREG NUREG NUREG NUREG	BNL-NUREG-51143 ORNL/NUREG-43 PNL-3275 PNL-3286 BNL-NUREG-51157	8ECY-80-313 8ECY-80-314 8ECY-80-317 8ECY-80-318 8ECY-87-4-095	8007280086 8007210009 8007170244 8007170523 8007020270	SECY SECY SECY SECY	
NUREG/CR-1361 NUREG/CR-1396 NUREG/CR-1413 NUREG/CR-1425 NUREG/CR-1439	8007230425 8007290152 8007180045 8007310255 8007310217	NUREO NUREO NUREO NUREO NUREO	E00-2025 9AND80-0920 GRNL-ANDREG-70 E00-2032 BNL-NUREG-51187	8ECY-R-74-132 8G-07 T18-6171 TR-3193-1 TR-3887-2 R1 NO1	8007020262 8007300007* 8007080285* 8007100188* 8007310387*	SECY ORG TOPREP PR 50-329	50-89-07 A
NUREO/CR-1440 NUREO/CR-1440 NUREO/CR-1459 NUREO/CR-1460 NUREO/CR-1464	8007280508 8007230205 8007140092 8007180031 8007140610	NUREO NUREO NUREO NUREO NUREO	E00-EA-5153 E00-EA-5153 E00-2039 ANL-E0-43 ORNL/NUREO/TM-3	URCL-15172 VEP-FRD-35 WCAP-9183 R9 WCAP-8587 R1 WCAP-8587 R2 81	8007030208* 8007020598* 8007100254* 8007150656* 8007160765*		P SAN-L-807027 P EQDP-ESE-10 EQDP-ESE-4
NUREG/CR-1477 NUREG/CR-1483 NUREG/CR-1486 NUREG/CR-1489 NUREG/CR-1500	8007310554 8007300575 8007240409 8007240478 8007210491	NUREG NUREG NUREG NUREG NUREG	ORNL/NUREG/TM-3 ORNL/NUREG/TM-3 UCRL-52746	HCAP-8587 81 HCAP-8587 82 HCAP-8587 82-E02A HCAP-8587 82-E04A HCAP-8587 82-E10A	8007140420* 8007140379* 8007140416* 8007160735* 8007150652*	TOPREP TOPREP TOPREP TOPREP TOPREP	EQDP-E8E-2 E15A
NUREG/CR-1504 NUREG/CR-1512 NUREG/CR-1513 NUREG/CR-1520 NUREG/CR-1520	8007240459 8007170418 8007310471 8007310009 8007280483	NUREO NUREO NUREO NUREO NUREO	ANL-80-47 ATR-80(7814)-1 BNL-NUREO-51219 EG9-2045 EG9-2045	WCAP-9570 R1 WCAP-9744 WCAP-9749 WCAP-9754 WMTP 11 21 R0	8007020644* 8007220499* 8007020596* 8007220503* 8007210452*	TOPREP TOPREP TOPREP TOPREP 50-266	F
NUREO/CR-1523 NUREO/CR-1555 NUREO/CR-1557 NUREO/CR-1580 VI NUREO/CR-1580 V2	8007090371 8007230201 8007240374 8007090166* 8007090167*	NUREO NUREO NUREO NUREO NUREO	ORNL/NUREG/TM/- BHI-2064 BHI-2038	WMTP 11 21 RO WMTP 11 22 RO WMTP 11, 22 RO Y1003JO1A12	8007210460* 8007210465* 8007210469* 8007170874*	50-266 50-266	무 무 무
NUS-3544 NUS-3582 NUS-3574 NUS-3575 DNWI-18	8007220111* 8007220036* 8007220032* 8007220101* 8007300249	WASTE MOT WASTE MOT WASTE MOT PR	16693 16693 16693 16693 111-016				

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER

	PRINCIPAL	DATE	BUBJECT	
ENCLOSURE	DOCUMENT	IBSUED	CATEGOR	Υ
B005090524	8005090523	80/02/26	PT9	
8005090527	8005090523	80/05/59	PTG	
8005090529	8005090523	80/05/59	PT9	
B005290607	8005290603	80/05/07	PTT	
8005290612	8005290403	80/03/07	PTS	
8005290516	8005290603	89/05/07	PT9	
8006110739	8006110736	80/04/24	27-10	_
B006200071	8009500099	B0/05/23	50-488	G
8006240082	8006240081	80/05/28	40-1142	
8006260145	8004260142	80/06/10	50-255	Р
8006300112	8006300097	80/05/23	ACRIS	
BE100E300B	B006300114	80/05/14	50-329	G
B004300382	B006300375	80/06/27	50-416	F
8006300384	6004300375	80/06/27	50-416	F
8007010004	8007010002	80/06/14	50~397	Α
8007010007	8007010002	80/06/16	50~397	Α
B00701000B	8007010003	80/04/05	50-237	þ
8007010010	8007010006	80/03/25	70-B24	,
8007010011	8007010003	80/06/03	50~237	P
8007010017	8007010013	80/09/10	ORG	
B00701001B	8007010002	B0/06/16	50-397	Α
8007010021	8007010002	80/06/16	50-397	۸
8007010023	8007010002	80/06/16	50-397	A
8007010029	8007010015	80/06/17	QA799	**
8007010032	8007010002	60/06/19	50-397	A
			-	
8007010033	B007010002	80/06/16	50-397	Α
E007010034	B007010015	B0/06/17	0A999	
8007010038	8007010002	B0/06/16	30-397	Α
8007010037	8007010015	80/06/17	0A797	
8007010041	8007010002	80/06/16	50-397	Α
000/010041	000101000	00/00/10	30 477	п
ED-20101001	7001-0000	00.404.444	No Don	Α
B007010045	8007010002	80/06/16	50-397	
8007010046	8007010031	80/06/16	50-546	Н
8007010049	8007010002	80/06/16	50~397	Α
8007010051	8007010015	80/06/17	94799	
8007010052	BC07010002	80/06/16	50-397	Α
8007010054	8007010002	80/06/16	50-397	Α
B007010055	8007010031	80/04/16	50-546	Ĥ
8007010058	8007010002	80/06/16	50-397	Ą
B007010059	8007010002	90/06/16	50-397	A
B007010060	B007010047	90/06/09	40-2674	
8007010061	8007010002	B0/06/16	50-397	Α
B007010064	8007010002	80/06/16	50-397	A
B007010067	8907010047	B0/06/09	40-2674	
8007010067	B007010002	80/06/16	50-397	Α
8007010073	8007010002	80/06/16	50-397	A
8007010076	E007010002	80/06/16	50-397	Α
B007010077	8007010047	80/06/09	40~2674	
8007010082	8007010070	80/06/20	FDIA	
80070100B3	8007010002	80/06/16	50-397	A
	8007010002	80/06/09	40-2674	n
8007010085	V60010V040	90/00/07	70-60/4	

	PRINCIPAL	DATE	BUBJECT
F. 101 - 501 - 50			
ENCLOSURE	DOCUMENT	188UED	CATEGORY
			~~~~~~
8007010088	B007010070	B0/06/20	50-249 P
8007010090	8007010002	80/06/16	50~397 A
8007010091	8007010047	80/04/09	
			40-2674
8007010092	8007010002	80/04/14	50-397 A
8007010093	11007010070	60/09/50	F01A
8007010095	8007010002	80/06/16	50-397 A
8007010097	B007010047	80/06/09	40-2674
B00701009B	8007010002	80/06/16	50-397 A
8007010099	8007010070	80/05/20	50-309 P
8007010103	6007010070	B0/06/20	30-249 P
8007010106	0007010101	80/09/25	71-574B
8007010108			
	8007010070	80/06/20	FOIA
8007010109	8007010105	80/06/11	70-143
B007010114	B007010070	80/06/50	FO1A
8007010117	B007010105	B0/06/11	70-143
BQ07010119	8007010070	B0/05/20	50-265 P
8007010121	8007010101	80/05/22	71-576B
8007010125	8007010105	80/06/11	70-143
8007010126	8007010070	おひへひひへおひ	LUIV
8007010133	8007010128	80/06/17	State Prog
8007010134	8007010070	80/06/20	50-273 P
6007010140	8007010129	80/02/01	40-B728
8007010141	B007010070	80/06/20	50-293 P
8007010142	B007010135	80/06/04	<b>በ</b> ልያማኝ
8007010145	8007010070	BO/06/20	FOIA
8007010147	8007010135	80/06/04	9A999
8007010149	E007010070	80/06/20	FOIA
8007010151	8007010135	80/04/04	0A999
8007010152	8007010070		
		80/06/20	FOIA
B007010154	8007010135	80/06/04	QA999
800701015B	B007010070	B0/06/20	FOIA
8007010141	8007010070	BO/04/20	FDIA
8007010163	8007010135	80/06/04	QA999
8007010165	8007010070	80/06/20	FOIA
8007010167	8007010135	80/05/04	
900/010101	900/010133	00/00/04	QA999
0000010170	ED07010075	50.101.555	
8007010168	8007010070	B0\09\50	E01V
8007010171	B007010135	80/04/04	9A999
8007010172	B007010164	80/05/11	50-333 0
8007010173	8007010070	60/06/20	FO1A
8007010176	8007010070	80/04/20	FOIA
000101010	GENIDIANIN	DOLOGUE	LOTE
8007010191	8007010070	00/04/00	COTA
		80/04/20	FOIA
8007010184	8007010094	80/06/13	70-2665
B007010185	6007010180	80/05/28	40~6789
8007010187	8007010070	BO/05/20	FDIA
B007010191	8007010070	80/06/20	FOIA
0007010193	8007010190	80/06/24	50-237 P
8007010174	B007010070	80/06/20	FOIA
9007010195	8007010189	80/09/13	70-2838
8007010197	8007010180	B0/05/28	40-6789
800701019B	8007010070	80/04/20	FOIA

ACCESSIO	N NUMBER				ACCEBEI	ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
B007010199	8007010192	B0/04/13	50-247	P	8007010529 8007010532		80/06/27	50-304 8 50-327 8
6007010204 6007010207 6007010207	8007010070 8007010070 8007010180	80/05/20 80/06/20	FOIA FOIA 40-6789		8007010535 8007010535	8007010527	80/06/24 80/06/26	50-368 8 50-334 8
8007010210	8007010100	80\07\50	FOIA		8007010537		80\09\53	50~204 8
B007010212 B007010215	8007010203 8007010070	80/05/19 80/06/20	50~498 FOIA	q	8007010539 8007010541		80/06/23 80/06/25	50-327 B
8007010218 8007010222	B007010070 B007010070	80/06/20	FOIA FOIA		8007010542 8007010543		80\09\52 80\09\59	50-263 S 50-293 S
8007010223	8007010219	80/05/30	50~443	G	8007010551		80/06/24	50-237 B
8007010226 8007010227	8007010216 8007010070	80/06/25 80/06/20	50-206 FOIA	R	8007010552 8007010555		B0/06/09 B0/06/09	COMMISSION 50-320 P
8007010229 8007010230	8007010219 8007010070	80/05/30	50-443 FOIA	G	8007010542 8007010544		80/05/30 80/05/30	40~1162 50-325 B
8007010232	8007010219	80/05/30	50-443	q	8007010574	8007010570	80/06/13	71-384
8007010233 8007010234	8007010070 8007010231	80/06/20 80/06/20	FDIA 50~267	a	8007010578 8007010579		80/06/12	70-130B 71-252
8007010235 8007010238	8007010219 8007010070	80/05/30 80/06/20	50-443 FD1A	a	8007010582 8007010583		80\09\18 80\09\08	CONTRACT 50-282 P
B007010241	B007010070	80/06/50	FOIA		8007010585		B0/06/18	50-282 P
B007010244 B007010249	8007010070 8007010070	80/06/50	FOIA FOIA		8007010572 8007010598		80/05/04 80/05/14	40-8647 71-5980
80070102 <i>5</i> 3 8007010274	8007010256 8007010270	80/06/16 80/06/16	50-484 WASTE M	o er	8007010400 8007010402	8007010595 8007010595	80/05/14 80/05/14	71~5980 71~5980
8007010281	B007010056	80/05/09	70-1062		8007010403	6007010595	80/05/14	71-5980
8007010291 8007010295	B007010285 B007010293	80/04/24 80/06/13	50-334 70-824	Q	8007010605 8007010611	6007010595 6007010609	80/05/14 80/06/10	71-5980 40-8027
8007010301 8007010306	8007010293 8007010299	90/06/13 90/04/24	70-824 50-219	Q	8007010615 8007010619	8007010609 8007010613	80/06/10 80/06/16	40-8027 CONTRACT
8007010343	800701 <b>0</b> 341	80/06/25	50-382	F	6007010627	8007010624	80/04/16	CONTRACT
800701034 <i>6</i> 8007010350	8007010344 8007010338	80/06/23 80/06/25	50~267 50-518	R A	8007020005 8007020008	8007020002 8007020002	80/05/28 80/05/28	70-135 70-135
8007010364 8007010373	8007010358 8007010369	80/06/27 B0/06/19	50-361 50-313	A F	8007020009 8007020012	8007020007 8007020002	80/05/15 80/05/28	CONTRACT 70-135
8007010374	B007010358	80/06/27	50-361	A	B007020017	8007020015	80/05/23	70-1143
8007010375 8007010377	B007010353 B007010370	60/06/24 60/06/25	50-239 50-296	8 8	8007020022 8007020025	8007020015 8007020024	80/05/23 80/05/28	70-1143 CONTRACT
8007010360 8007010381	8007010369 8007010376	60/06/19 60/06/27	50-313 408-08	F	8007020031 8007020041	B007020027	80/05/13 80/05/28	50-546 Q 50~277 Q
B0070103B5	8007010382	80/07/53	50-327	S	8007020047	B007020044	80/06/12	71-5
8007010390 8007010392	800701038 <b>9</b> 800701038 <b>9</b>	80/06/13 80/06/13	50-317 50-317	R Fit	8007020049 8007020060	8007020035 8007020035	80/05/28 80/05/28	50-277 G 50-277 G
8007010393 8007010394	8007010178 8007010340	80/05/2 <i>6</i> 80/05/22	50~255 50~261	8	9007020070 8007020073	8007020035 8007020044	90/05/2B 78/09/14	50-277 G 50-322 S
8007010400	8007010394	B0/06/24	5D-334	8	6007020088	8007020082	80/04/57	50-10 U
8007010405 8007010412	B007010391 B007010406	80/04/25 80/06/27	50~271 50-348	8	8007020095 8007020096	8007020089 8007020090	79/09/13 BO/06/11	TOPREP 50-443 H
B007010414 B007010415	8007010407 8007010398	80\06\26 80\06\26	50-348 50-339	9 9	8007020103 8007020103	B007020097 B007020102	80/05/30 80/05/30	70-1100 71-6078
8007010419	8007010417	80/06/25	50-327	9	8007020106	8007020097	80/05/30	70-1100
8007010420 8007010431	8007010409 8007010425	80/06/25 80/06/25	50-266 50-324	5 0	800702010B 8007020112	8007020102 8007020102	80/05/30 80/05/30	71-6078 71 <b>-6</b> 078
8007010438 8007010439	8007010435 8007010434	80/06/26 80/06/23	50-327 50-346	5 5	8007020114 8007020115	8007020107 8007020102	80/05/06 80/05/30	70-1100 71-6078
8007010440	8007010437	80/06/27	50-348	8	8007020121	8007020097	80/05/30	70-1100
8007010441 8007010442	8007010436 8007010429	80/06/25	50-368 50-280	8	8007020135 8007020144	8007020128 800702013 <del>7</del>	80/06/10 79/11/14	WASTE MOT
8007010446 8007010450	B007010444 B007010445	80/06/25 80/06/24	50-348 50-336	8 5	8007020149 800702015B	8007020131 8007020131	80/06/13 80/06/13	50-361 G 50-361 G
8007010451	8007010447	80/06/27	50-155	Р	8007020164	8007020155	80/05/27	50-352 B
8007010455 8007010456	8007010448 8007010394	B0/06/27 B0/06/24	50-284 50-334	5 5	8007020166 8007020167	8007020131 8007020159	80/06/13 79/11/26	50-341 Q 50-329 A
8007010458 8007010477	8007010454 8007010471	B0/06/25	50-320 50-285	B	8007020174 8007020175	8007020149 8007020131	80/06/16 80/06/13	50-150 P 50-361 Q
8007010480	B007010470	80/06/25	50-313	R	8007020188	8007020129	80/06/05	COMMISSION
8007010485 8007010488	8007010491 8007010484	80/06/27 80/06/25	50-233 50-295	8	8007020191 8007020195	8007020131 8007020183	80/06/13 80/06/19	50-361 Q 50-10 H
8007010491 8007010495	8007010483 8007010486	80/06/19 80/06/25	50-335 50-333	5 6	8007020203 8007020203	8007020183 8007020199	80/06/19 80/06/11	50-10 H 50-295 G
8007010500 8007010502	8007010493	80/06/26	50-295 86-207	8	8007020217	8007020198	80/06/18	50-324 H
8007010502 8007010503 8007010505	B007010499 B007010494	80/06/25 80/06/24	50~327 50~366	8	8007020220 8007020223	8007020213 8007020216	80/05/0B	70-1151 50-334 q
8007010505	8007010497 8007010496	80/06/23 80/06/23	50-237 50-247	S	8007020233 8007020237	8007020230 8007020229	80/04/17 80/04/09	70-2910 50-320 H
			50-325	8	8007020271	8007020267	80/06/18	50-259 0
			50-327 50-366	\$ 8	8007020275 8007020275	8007020267 8007020264 8007020284	80/06/19 80/06/09	50-259 G WASTE MGT FOIA
			0-352 0-333	6 8	8007020287 8007020290 9007020280	8007020288	80/02/12 80/06/17	50-344 P
					8007020292	8007020284	80/02/12	FOIA

ACCESSION	NUMBER			ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL	DATE	SUBJECT	PRINCIPAL DATE	SUBJECT
	DOCUMENT	IBSUED	CATEGORY	ENCLOSURE DOCUMENT ISSUED	CATEGORY
8007020294	8007020288	80/06/17	50-344 P	8007030035 8007030031 80/05/09	40-8647
8007020301	8007020298	80/06/19	50-321 Q	8007030038 8007030031 80/06/23	FDIA
8007020305	8007020298	80/06/19	50-321 Q	8007030039 8007030031 80/05/09	40-8647
8007020313	8007020303	80/06/04	50-320 U	8007030040 8007030034 80/06/09	50-369 G
8007020321	8007020317	80/06/02	50-335 Q	8007030047 8007030031 80/05/09	40-8647
8007020323	8007020303	80/06/04	50-320 U	8007030050 8007030045 80/05/13	PR
8007020326	8007020317	80/06/02	50-335 G	8007030055 8007030031 80/05/05/13	40-8647
8007020331	8007020325	80/06/13	COMMISSION	8007030057 8007030045 80/05/13	PR
8007020336	8007020325	80/06/13	COMMISSION	8007030051 8007030068 80/06/13	CONTRACT
8007020338	8007020099	80/05/21	State Prog	8007030135 8007030131 80/06/30	50-280 P
8007020350	8007010006	80/03/25	70-824	8007030180 8007030178 80/06/30	50-282 R
8007020354	8007020349	80/06/24	50-317 P	8007030183 8007030178 80/06/30	50-282 R
8007020357	8007020109	80/05/19	50-247 P	8007030189 8007030185 80/07/01	50-413 A
8007020358	8007020339	80/05/30	70-27	8007030208 8007030174 80/06/04	50-285 P
8007020361	8007020334	80/06/24	50-324 B	8007030209 8007030204 80/06/17	PR
8007020365	8007020339	80/05/30	70-27	8007030213 8007030210 80/06/16	\$0-273 P
8007020366	8007020342	80/06/30	50-204 P	8007030217 8007030212 80/06/26	\$0-331 S
8007020372	8007020342	80/06/30	50-204 P	8007030231 8007030228 80/06/16	70-1113
8007020375	8007020370	80/05/14	50-67 R	8007030235 8007030224 80/06/26	50-331 S
8007020382	8007020370	80/05/14	50-67 R	8007030241 8007030238 80/06/26	50-331 S
8007020398	8007020386	80/06/10	CONTRACT	8007030248 8007030245 80/06/30	50-414 A
8007020405	8007020397	80/06/27	50-382 8	8007030251 8007030230 80/07/01	50-255 P
8007020411	8007020402	80/06/11	50-409 D	8007030264 8007030260 80/06/27	50-346 S
8007020413	8007020406	80/06/10	PR	8007030267 8007030262 80/06/30	50-337 S
8007020420	8007020408	80/06/27	50-454 K	8007030269 8007030263 80/06/30	50-338 S
8007020423	8007020417	80/04/23	50-266 P	8007030271 8007030270 80/04/30	50-338 8
8007020428	8007020422	80/06/19	71-6698	8007030274 8007030272 80/04/24	50-366 9
8007020431	8007020429	80/06/13	70-2609	8007030275 8007030273 80/04/24	50-339 8
8007020437	8007020432	80/06/11	50-271 G	8007030278 8007030274 80/04/24	50-321 8
8007020442	8007020436	80/06/27	50-317 P	8007030279 8007030277 80/04/24	50-366 8
8007020443	8007020130	80/04/12	ORO	8007030282 8007030280 80/04/24	30-366 S
8007020448	8007020436	80/04/27	50-317 P	8007030283 8007030281 80/06/30	50-339 S
8007020455	8007020451	80/04/18	50-271 H	8007030284 8007030284 80/06/25	50-321 S
8007020485	8007020481	80/06/19	50-3 G	8007030288 8007030285 80/07/01	50-339 S
8007020493	8007020490	80/04/17	50-193 P	8007030289 8007030287 80/07/01	50-293 S
8007020506	8007020500	80/06/18	71-5942	8007030293 8007030290 80/07/01	50-287 G
8007020517	8007020512	80/06/18	71-9016	8007030294 8007030291 90/07/02	70-2709
8007020522	8007020518	80/06/17	71-381	8007030295 8007030292 80/06/17	70-143
8007020523	8007020520	80/06/26	50-366 S	8007030296 8007030290 80/07/01	50-289 G
8007020529	8007020525	80/06/26	50-528 S	8007030297 8007030290 80/07/01	50-289 G
8007020532	8007020527	80/06/18	71-7015	8007030298         8007030292         800/06/17           8007030297         8007030290         800/07/01           8007030301         8007030290         80/07/01           8007030302         8007030290         80/07/07/01           8007030303         8007030290         80/07/01	70-143
8007020533	8007020531	80/06/25	50-528 8		50-287 G
8007020537	8007020538	80/06/24	50-416 8		50-289 G
8007020541	8007020538	80/06/24	50-416 8		50-289 G
8007020545	8007020543	80/06/26	50-928 8		50-289 G
8007020547	8007020546	80/06/25	50-334 R	8007030304 8007030290 80/07/01	50-289 G
8007020551	8007020544	80/06/26	50-328 B	8007030344 8007030334 80/06/12	CONTRACT
8007020553	8007020542	80/06/10	CONTRACT	8007030357 8007030353 80/06/12	CONTRACT
8007020554	8007020550	80/06/16	50-320 Q	8007030343 8007030338 80/06/02	40-8502
8007020574	8007020557	80/06/30	50-255 P	8007030364 8007030358 80/06/02	40-8502
8007020581	8007020557	80/06/30	50-255 P	8007030370 8007030368 80/05/07	71-9039
8007020583	8007020484	80/06/39	71-9022	8007030374 8007030375 80/06/13	
8007020588	8007020557	80/06/30	50-255 P	8007030378 8007030375 80/06/13	
8007020593	8007020557	80/06/30	50-255 P	8007030379 8007030375 80/06/13	
8007020596	8007020590	80/06/30	TDPREP	8007030381 8007030375 80/06/13	
8007020598 8007020599 8007020600 8007020603 8007020610	8007020592 8007020557 8007020557 8007020401 8007020407	80/06/30 80/06/30 80/06/30 80/06/13	50-33B F 50-25B P 50-25B P 50-414 9 50-307 0	8007030384 8007030375 80/06/13 8007030385 8007030375 80/06/13 8007030386 8007030375 80/06/13 8007030387 8007030375 80/06/13 8007030395 8007030389 80/06/13	71-9039 71-9039 71-9039
8007020611 8007020632 8007020642 8007020644 8007020647	8007020608 8007020630 8007020638 8007020641 8007020645	80/06/12 80/06/25 80/06/27 80/06/30 80/06/27	70-1308 50-416 6 50-321 6 TOPREP 70-143	8007070005 8007070003 80/05/07 8007070006 8007070004 80/06/16 8007070001 8007070004 80/06/16 8007070014 8007070010 80/06/19 8007070015 8007070010 80/06/19	XPORTLIC XPORTLIC 70-143
8007020652 8007020656 8007020660 8007020674 8007020676	8007020450 8007020445 8007020445 8007020472 8007020475	80/06/04 80/06/27 80/06/27 80/06/11 80/06/10	71-381 70-143 70-143 COMMISSION 50-498 A	8007070017 8007070010 80/06/19 8007070019 8007070010 80/06/19 8007070024 8007070023 80/06/12 8007070031 8007070026 80/06/19 8007070033 8007070026 80/06/19	XPORTL10 50-514 D
8007020685 8007020693 8007020712 8007020731 8007030011	8007020561 8007020688 8007020708 8007020730 8007030004	80/06/05 80/06/25 80/06/09 80/06/23	71-9130 50-281 H WASTE MGT CONTRACT 70-2478	8007070036 8007070026 80/06/19 8007070039 8007070035 80/06/24 8007070040 8007070026 80/06/19 8007070044 8007070026 80/06/19 8007070045 8007070042 80/06/19	50-269 P 50-514 D 50-514 D
8007030016 8007030019 8007030020 8007030028 8007030029	8007030004 8007030013 8007030004 8007030022 8007030025	80/04/23 80/04/23 80/04/23 90/04/19 80/04/11	70-2478 80-856 H 70-2478 70-1151 50-466 G	8007070046         8007070024         80/06/15           8007070047         8007070026         80/06/15           8007070050         8007070026         80/06/15           8007070053         8007070026         80/06/15           8007070054         8007070052         80/06/15	50~514 D 50~514 D 50~514 D

	ACCESS10					ACCEBSI	ON MUMBER			
							PRINCIPAL			
MODIFICATION   MODI	8007070055 8007070056 8007070057 8007070058	8007070051 8007070052 8007070052	80/05/21 80/06/18 80/06/18	50-282 CONTRAC CONTRAC	g T I	B0070B0014 B0070B0015 B0070B0017 B0070B0017	80070B0010 80070B0013 80070B0010 80070B0013	80/07/03 80/06/30 80/07/03 80/06/30	50-443 50-466 50-443 50-466	I G I
	8007070062 8007070064 8007070069	8007070052 8007070059 8007070059	80\09\50 80\09\50 80\09\18	CONTRAC 50-280 50-280	т Н Н	8007080019 8007080020 8007080022 8007080025	8007080010 8007080010 8007080010	80/07/03 80/07/03 80/07/03	50-443 50-443 50-443	I I
	8007070079 8007070080 8007070087	8007070057 8007070072 8007070083	80/05/23 80/05/23 80/05/23	50-280 50-10 50-482	H G G	8007080033 8007080037 8007080038	8007080010 8007080010 8007080010	80/07/03 80/07/03 80/07/03	50-443 50-443 50-443	I I I
8007701313   8007701128   807047013   71-992   8007701118   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   807047013   8070	8007070100 8007070102 8007070103	8007070097 8007070097 8007070097	80/06/24 80/06/24 80/06/24	50-335 50-735 50-335	G G	9007080072 9007080083 9007080084	8007080069 8007080081 8007080080	80/07/03 80/07/01 80/07/03	50-338 50-361 50-334	P A P
000770710176   0007707146   0007707146   0007707146   000770146   000770171   0007701716   0007707146   0007701716   0007701146   000770146   000770146   000770146   000770146   000770146   000770146   000770146   000770146   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770147   000770	8007070133 8007070134 8007070161	8007070128 8007070129 8007070157	60/06/13 60/06/10 60/06/20	71-392 CONTRAC 50-284	T Q	8007080149 8007080172 8007080176	8007080164 8007080162 8007080164	80/06/59 80/06/59 80/06/59	50-336 50-265 50-336	Р В Р
B007701919   B007070118   B00760118   B0076011   B0076011   B0077601201   B0077601201   B007760119   B00776	8007070176 8007070179 8007070180	6007070166 6007070177 6007070166	80/06/30 80/06/06 80/06/30	50-348 71-9130 50-348	R	8007080192 8007080199 8007080200	8007080182 8007080189 8007080196	80/07/02 80/07/01 80/07/02	50-293 50-255 50-293	8 8
B0070708208   B0070701-15   B0070708023   B00708023   B0	8007070190 8007070194 8007070195	8007070168 8007070168 8007070187	80/06/30 80/06/30 80/06/24	50-348 50-348 70-1113	R	8007080208 8007080214 8007080215	8007080204 8007080211 8007080210	80/07/02 80/07/03 80/07/01	30-305 50-289 50-267	8 8
BOO70701224   BOO7070124   BOO7070124   BOO7070124   BOO7070124   BOO7070124   BOO7070124   BOO7070124   BOO7070124   BOO7070224   BOO7070124   BOO7070224   BOO7070225   BO	8007070206 8007070208 8007070214	8007070153 8007070169 8007070169	60/07/01 60/06/30 60/06/30	50-275 50-348 50-348	A R R	8007080234 8007080239 8007080243	8007080222 8007080234 8007080222	80/06/30 80/07/03 90/06/30	50-344 50-362 50-344	A 8 A
B007070232	8007070223 8007070226 8007070228	6007070168 6007070168 6007070168	80/07/30 80/07/30 80/09/30	50-349 50-349 50-349	R R R	8007080252 8007080275 8007080277	8007080254 8007080268 8007080270	80/06/19 80/06/19 80/06/26	50-267 50-267 50-312	8 8
B007070265   B007070269   B01061/27   S0-219   S007080297   B007070269   B00707026   B007070269   B00707026	8007070232 8007070237 8007070254	8007070148 8007070234 8007070252	60/06/30 60/06/27 60/07/01	50-348 50-325 50-331	# 5 P	8007080285 9007080288 8007080290	8007080274 8007080283 8007080284	80/07/01 80/06/27 80/06/25	TOPREP 50-327 50-335	<b>8</b>
B007070315   B007070310   B007070320   B007070320   B007070321   B007070322   B007070323   B007070323   B007070322   B007070324   B007070323   B007070324   B00	8007070265 8007070270 8007070289	8007070259 8007070269 8007070285	80/04/27 80/07/03 80/06/27	50-219 50-395 50-272	5 C P	8007080297 8007080302 8007080304	8007080293 8007080295 8007080289	80/06/27 80/06/12 80/07/01	50-259 50-298 50-267	8 8
BO07070355	8007070315 8007070322 8007070323	8007070310 8007070320 8007070319	80/07/01 80/07/02 80/04/30	50~484 50~320 50~269	0 P 5	8007080327 8007080333 8007080335	8007080322 8007080313 8007080330	80/07/02 80/07/01 79/03/01	50-321 50-259 50-335	e ន ន
8007070372         8007070361         80706/27         50-336         8         8007080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         807080363         80707080363         807080363         80708	8007070353 8007070354 8007070363	8007070337 8007070348 8007070358	90/06/27 80/06/13 80/07/02	50-320 50-272 50-339	R B	8007080353 8007080354 8007080357	8007080349 8007080350 8007080349	80/05/18 80/07/02 80/05/18	PR 50-286 PR	
BO070703BB   BO070703B7   BO07080703B7   BO070	8007070372 8007070379 8007070381	8007070361 8007070374 8007070373	80/06/27 80/07/02 80/07/03	50-336 50-339 50-338	8 8	9007090368 9007090373 8007090384	8007080365 8007080370 8007080381	80/06/16 80/06/30 80/06/27	50-278 50-260 50-301	9 9
8007080005 8007080004 80/07030 50-287 a 8007080416 8007080419 80/04/30 30-2876 8 800708004 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 800708001 80070	8007070388 8007070397 8007070397	8007070387 8007070389 8007070394	80/07/01 80/07/01 80/06/21	50-293 50-260 50-348	8 0	8007080399 8007080402 8007080409	8007080394 8007080400 8007080406	80/06/27 80/07/01 80/07/01	50-260 50-327 50-267	8 8 R
	8007080005 8007080006 8007080011	8007080004 8007080001 8007080010	80/06/30 80/07/03 80/07/03	50-289 50-320 50-443	0 I	8007080416 8007080417 8007080420	8007080415 8007080413 8007080418	80/04/30 80/07/02 80/04/27	50-276 50-309 50-344	9 9

ACCESSION N	UMBER				ACCESSION	NUMBER		
	RINCIPAL Document	DATE ISSUED	SUBJECT CATEGOR*		ENCLOSURE	PRINCEPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGORY
8007070006 Be	007090005	80/07/01 80/07/01 80/08/13	50~272 50~259 50~298	5 5 5	8007100072 8007100074 8007100076	900710000B 900710006B 900710000B	80/06/27 80/06/04 80/06/27	70~143 50~29 1 Q 70~143
9007090014 8	007090008 007090013 007090013	80/07/02 80/06/20 80/06/20	50-255 50-346 50-346	e a	8007100081 8007100089 8007100091	8007100008 8007100085 8007100088	80/06/27 80/06/05 80/06/16	70-143 50-409 9 40-1162
8007090017 8 8007090019 8 8007090021 8	007090015 007090015 007090015	80/06/03 80/06/03 80/06/03	SECY SECY SECY	u	8007100095 8007100099 8007100102 8007100105	0007100093 8007100098 8007100097 8007100097	80/05/29 80/05/29 80/05/29	50-261 0 50-546 0 50-206 P 50-206 P
8007070030 8 8007070033 8 8007090038 8	00709002B 00709002B 00709002B	80/06/03 80/05/16 80/05/16 80/05/16 80/05/12	SECY 10CFR 10CFR 10CFR 71-387		8007100106 8007100107 8007100110 8007100112 8007100114	E01001008 7,4000170008 E0100170008 10100107	80/06/13 80/05/29 80/06/13 80/06/13	50-286 P 50-206 P 50-286 P CONTRACT 50-286 P
8007090114 B 8007090148 B 8007090156 B	007090145 007090154	80/05/19 80/06/06 80/04/11 80/05/21 80/05/21	PR COMMISSIO PR 50-440 50-440	N G G	8007100115 8007100118 8007100121 8007100124 8007100131	800/100111 8007100111 8007100111 8007100119 8007100127	80/05/28 81/46/08 80/05/18 80/05/28	50-302 P 50-302 P 50-302 P 50-416 Q 50-327 Q
8007090167 B 8007090170 B 800709017B B	907090163 907090163 907090165 907090176 907090176	80/05/30 80/05/30 80/05/24 80/05/21 80/05/21	NUREG NUREG 50-369 50-440 50-440	G G G	8007100136 8007100138 8007100141 8007100147 8007100151	8007100132 8007100132 8007100132 8007100142 8007100144	80/06/13 80/06/13 80/06/13 80/07/03 80/05/27	50-335 P 50-335 P 50-335 P 50-254 P 50-269 G
8007090195 8 8007090201 8 8007090245 8	007090198 007090243	80/06/24 80/07/03 80/07/01 80/06/27 80/07/02	70-1257 50-333 TOPREP 50-322 50-327	R X S	8007100154 8007100156 8007100158 8007100162 8007100164	B007100152 B007100150 B007100155 B007100150 B007100157	80/06/16 80/06/12 80/06/19 80/06/12 80/07/02	PROJ 50-261 P 50-277 P 50-261 P 50-265 S
8007090275 B 8007090276 B 8007090292 B	007090245 007090271 007090289	80/07/02 80/07/02 80/07/01 90/07/02 80/06/30	50-352 50-352 50-249 50-314 50-466	S 6 9 5 0	8007100165 8007100166 8007100168 8007100172 8007100176	8007100150 8007100163 8007100163 8007100167 8007100173	80/06/12 80/06/27 80/06/27 80/07/02 80/07/02	50-261 P 50-382 K 50-382 K 50-245 S 50-267 S
8007070312 8 8007070317 8 8007070323 8	00709030B 007090314 007090317	80/07/02 80/07/02 80/07/03 80/07/02 80/07/04	50-337 50-337 50-259 50-337 50-213	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	8007100178 8007100180 8007100184 8007100185 8007100188	8007100175 8007100160 8007100160 8007100193 8007100160	80/06/26 80/07/07 80/07/07 80/06/26 80/07/07	50-272 C PR PR 90-320 P PR
8007090334 8 8007090337 8 8007090338 8	007090328 007090330 007090334	80/05/26 80/07/03 80/05/27 80/07/02 80/06/26	50-317 50-368 50-361 50-334 50-317	P 6 9 9 9 P	8007100189 8007100191 8007100192 8007100195 8007100201	8007100179 8007100160 8007100187 8007100190 8007100199	80/07/02 80/07/07 80/07/02 80/07/01 80/07/03	30-237 6 PR 50-237 6 50-263 5 50-255 P
8007090346 8 8007090348 8 8007090352 8	007090324 007090340 007090324	80/07/02 80/06/26 80/06/26 80/06/26 80/07/02	50-339 50-317 50-334 50-317 50-338	5 P 5 P 6	8007100202 8007100204 8007100206 8007100211 9007100212	8007100197 8007100199 8007100203 8007100207 8007100210	80/07/02 80/07/03 80/06/19 80/05/28 80/06/24	50-272 8 50-255 P 50-312 P 50-302 P TOPREP
8007090361 8- 8007090369 8- 8007090373 8-		90/05/27 90/06/26 80/06/26 80/05/09 80/03/24	50-317 50-317 50-317 50-271 50-320	G P P O O	8007100213 8007100220 8007100225 8007100236 8007100256	8007100209 8007100223 8007100233 8007100233	80/07/02 80/07/03 80/06/17 80/06/30 80/04/21	50-438 S TOPREP 50-267 G 50-438 S TOPREP
8007100014 B 8007100015 B 8007100020 B	007100009 007100009 00710000B 00710000B	80/01/07 80/01/09 80/06/27 80/06/27 80/05/27	50-320 50-320 70-143 70-143 70-143	0 0	8007100257 8007100247 8007100268 8007100271 8007100276	8007100254 8007100261 8007100262 8007100261	80/07/03 80/07/08 80/06/30 80/06/12 80/07/08	PR 50-348 K 50-206 R XPBRYL10 50-348 K
8007100028 8 8007100032 8 8007100034 8		80/07/03 80/06/27 80/06/27 80/07/07 80/06/24	50-275 70-143 70-143 50-344 50-155	o o	8007100277 8007100280 8007100284 8007100287 8007100288	8007100273 8007100273 8007100273 8007100281 8007100273	80/0//07 80/07/07 80/07/07 80/06/03 80/07/07	50-280 P 50-280 P 50-280 P XPORTLIC 50-280 P
8007100041 B 8007100042 B 8007100044 B	00710000B	80/06/27 80/06/24 80/06/26 80/06/27 80/07/07	70-143 71-6581 50-155 70-143 PR	a	8007100287 8007100291 8007100293 8007100298 8007100297	8007100272 8007100283 8007100273 8007100273	80/05/23 80/05/20 60/07/07 80/07/07 60/06/06	50-352 H 50-331 Q 50-280 P 50-280 P 50-255 P
8007100054 B 8007100057 B 8007100058 B	007100008 007100051		70-143 PR 70-143 50-344 50-251	e a	8007100301 8007100303 8007100305 8007100307 8007100308	8007100297 8007100273 8007100297 8007100296 8007100295	80/04/14 80/07/07 80/04/16 80/06/06 80/06/28	50-400 G 50-280 P 50-400 G 50-255 P 50-346 Q
60071000A2 B 60071000A6 B 80071000A9 B	007100051 007100064	80/05/29 80/06/16 80/05/29 80/06/27 80/06/04	50-335 50-344 50-321 70-143 50-273	a o a	8007100309 8007100310 8007100311 8007100312 8007100313	8007100273 8007100294 8007100273 8007100304 8007100297	80/07/0/ 80/06/06 80/07/0/ 80/06/10 80/06/16	50-280 P 50-255 P 50-280 P CONTRACT 50-400 G

ACCESS10	NUMBER				ACCESBIO				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC*	₹Y	ENCLOSURE	PRINCIPAL DDGUMENT	DATE 186UED	SUBJECT CATEGOR	
8007100315 8007100321 8007100323 8007100329 8007100330	8007100273 8007100273 8007100273 8007100273 8007100223	80/07/07 80/07/07 80/07/07 80/07/07 80/06/05	50-280 50-280 50-280 50-280 6A999	P P P	8007110040 8007110042 8007110045 8007110046 8007110070	8007110009 8007110009 8007110061 8007110009 8007110061	80/06/23 80/06/23 80/05/21 80/06/23 80/05/21	50-320 50-320 50-382 50-320 50-382	 
8007100333 8007100334 8007100335 8007100336 8007100338	8007100324 8007100327 8007100273 8007100324 8007100273	80/06/05 80/04/16 80/07/07 80/06/05 80/07/07	QA999 FOIA 50-280 GA999 50-280	P P	8007110072 8007110076 9007110077 8007110084 8007110084	8007110009 8007110001 8007110009 8007110009 8007110009	80/06/23 80/05/21 80/06/23 80/06/23 80/06/23	50-320 50-320 50-320 50-320	נונטני
8007100339 8007100346 8007100347 8007100351 8007100353	8007100326 8007100342 6007100273 6007100273 8007100349	80/06/05 80/05/23 80/07/07 80/07/07 80/06/17	9A999 50-498 50-280 50-280 71-389	G P P	8007110091 8007110093 8007110095 8007110096 8007110098	8007110007 8007110082 8007110009 8007110086 8007110009	80/06/23 80/06/23 80/06/23 80/06/23	50-320 50-271 50-320 50-285 50-320	このこまら
8007100357 8007100365 8007100367 8007100368 8007100370	8007100273 8007100273 8007100356 8007100361 8007100362	80/07/07 80/07/07 80/06/24 80/06/18 80/04/30	50-280 50-280 50-324 CONTRACT 70-1151	P P O	8007110103 8007110107 8007110113 8007110125 8007110128	8007110009 8007110009 8007110102 8007110009 8007110009	80/06/23 80/06/23 80/06/23 80/06/23	50-320 50-320 50-335 50-320 50-320	,,,,,
8007100371 8007100374 8007100375 8007100376 8007100377	8007100273 8007100362 8007100273 8007100373 8007100356	80/07/07 80/04/30 80/07/07 80/06/16 80/06/24	50-280 70-1151 50-280 71-9053 50-324	P P Q	8007110132 8007110135 8007110134 8007110140 8007110143	8007110009 8007110009 8007110131 8007110009 8007110009	80/06/23 80/06/23 80/06/29 80/06/23	50-320 50-320 50-254 50-320 50-320	とくるくら
8007100380 8007100381 8007100382 8007100384 8007100387	8007100273 8007100362 8007100273 8007100356 8007100273	80/07/07 80/04/30 80/07/07 80/06/24 80/07/07	50-280 70-1151 50-280 50-324 50-280	р О	8007110145 8007110147 8007110151 8007110156 8007110158	8007110131 8007110009 8007110009 8007110009 8007110153	05/90/08 E2/90/08 E2/90/08 E2/90/08	50-254 50-320 50-320 50-320 50-441	e ) ) )
8007100391 8007100395 8007100397 8007100398 8007100401	8007100273 8007100356 8007100356 8007100356 8007100394	80/07/07 80/06/24 80/04/30 80/06/24 80/06/02	50-280 50-324 70-1801 50-324 50-219	Р О О Р	8007110140 8007110146 8007110167 8007110168 8007110173	8007110009 8007110141 8007110009 8007110153 8007110009	ES\40\08 E1\40\08 ES\40\08 0\$\70\08	50-320 71-7009 50-320 50-461 50-320	) ) )
B007100403 B007100404 B007100403 B007100407	8007100273 8007100390 8007100394 8007100273 8007100394	80/07/07 80/04/30 80/06/02 80/07/07 80/06/02	20~219 20~280 20~219 20~280	P P P	8007110174 8007110178 8007110189 8007110184 8007110192	8007110009 8007110009 8007110174 8007110174 8007110187	80/06/23 80/06/23 80/05/23 80/05/23	50-320 50-320 50-206 50-206 50-482	00000
8007100409 8007100410 8007100413 8007100414 8007100415	8007100273 8007100390 8007100354 8007100273	80/07/07 80/04/30 80/06/24 80/07/07 80/07/07	50-280 70-1201 50-324 50-280 50-280	р () Р	8007110193 8007110194 8007110196 8007110198 8007110201	8007110189 8007110189 8007110189 8007110187 8007110009	80/07/07 80/07/07 80/07/07 80/05/23 80/06/23	50-280 50-280 50-280 50-482 50-320	9 9
8007100418 8007100419 8007100420 8007100422 8007100423	8007100412 8007100417 8007100399 8007100412 8007100417	80/06/23 80/06/23 80/06/23 80/06/23	50-400 50-413 50-10 50-400 50-413	0 P 0	8007110203 8007110204 8007110207 8007110208 8007110209	8007110195 8007110200 8007110195 8007110009 8007110204	80/06/04 80/06/19 80/06/04 80/06/23 80/07/07	NUREQ 50-10 NUREG 50-320 50-155	G J
8007100426 8007100428 8007100430 8007100432 8007100435	8007100417 8007100412 8007100412 8007100417 8007100412	80/04/53 80/04/53 80/04/53 80/04/53	50~413 50~400 50~400 50~413 50~400	0 0 0	8007110210 8007110212 8007110217 8007110220 8007110222	8007110204 8007110009 8007110009 8007110214 8007110009	80/07/07 80/06/23 80/06/23 80/06/20 80/06/23	50-155 50-320 50-320 50-344 50-320	このにに出
8007100438 8007100444 8007100462 8007110007 8007110012	8006300220 8007100445 8007100461 8007110004 8007110010	80/06/20 80/06/16 80/06/27 80/06/27	50-320 40-8502 71-9094 70-143 XPORTLIC	н	8007110224 8007110231 8007110233 8007110234 9007110239	8007110009 8007110225 8007110228 8007110229 8007110225	80/06/23 79/10/08 80/06/19 80/05/23 79/10/08	50-320 PR 50-441 50-445 PR	0 0 7
8007110015 8007110016 8007110017 8007110020 8007110022	8007110009 8007110014 8007110009 8007110009	80/06/23 80/06/23 80/06/23 80/06/23	70-1333 71-221 50-320 70-1333 70-1333	J	8007110246 8007110248 8007110254 8007110257 8007110252	8007110242 8007110243 8007110247 8007110250 8007110250	80/04/17 80/05/14 80/06/06 80/06/23 80/06/23	FDIA TOPREP 50-255 50-321 50-321	P G
8007110023 8007110024 8007110027 8007110028 8007110030	8007110009 8007110009 8007110025 8007110009 8007110009	80/06/23 80/06/23 80/06/23	70-1333 70-1333 40-2041 50-289 50-289	7	8007110264 8007110268 8007110270 8007110278 8007110278	8007110247 8007110250 8007110265 8007110250 8007110266	80/06/15 80/06/53 80/06/53 80/06/06	50-255 50-321 71-6375 50-321 COMMISSI	P G G
8007110032 8007110036 8007110037 6007110037 8007110040	8007110009 8007110033 8007110009 8007110034 8007110009	B0/06/23 B0/06/13 B0/06/23 B0/06/24 B0/06/23	50-320 50-275 50-320 50-327 50-320	プロンのつ	8007110280 8007110282 8007110283 8007110284 8007110290	6007110272 8007110266 8007110275 8007110272 8007110281	80/06/24 80/06/12 80/06/12 80/06/24 80/06/27	50-320 COMMISSI XPORTLIC 50-320 71-5450	
8007110046 8007110049 8007110051 8007110052 8007110057	6007110009 8007110044 8007110009 8007110009 8007110009	80/06/23 80/06/23 80/06/23 80/06/23	50-320 50-263 50-320 50-320 50-320	50)))	8007110292 8007110294 8007110297 8007110301 8007110313	8007110272 8007110266 8007110266 8007110297 8007110304	80/06/24 80/06/12 80/06/12 80/07/07 80/07/01	50-320 CDMM1891 COMM1881 50-255 50-321	

ACCESS 10	NUMBER			ACCESSION NUMBER	
ENCLOSURE	PRINCIPAL	DATE	SUBJECT	PRINCIPAL DATE	SUBJECT
	DOCUMENT	I SSUED	CATEGORY	ENCLOQUEE DOCUMENT ISSUED	CATEGORY
8007110314	8007110306	B0/06/30	50-335 H	8007140046 8007140036 80/07/04	PR
8007110322	8007110321	B0/06/27	M1sc	8007140048 8007140033 80/06/12	QA999
8007110323	8007110321	B0/06/27	M1sc	8007140047 8007140045 80/07/03	PR
8007110326	8007110317	B0/07/02	50-305 S	8007140051 8007140036 80/07/04	PR
8007110327	8007110321	B0/06/27	M1sc	8007140059 8007140055 80/06/25	SECY
8007110328	8007110320	80/07/02	50-518 8	8007140062 8007140030 80/06/23	50-320 U
8007110331	8007110294	80/07/07	50-267 P	8007140063 8007140057 80/06/11	QA999
8007110340	8007110333	80/07/03	50-266 9	8007140064 8007140058 80/06/23	70-143
8007110343	8007110338	80/06/30	50-352 U	8007140066 8007140060 80/06/13	50-320 G
8007110349	8007110342	80/06/30	50-301 S	8007140067 8007140058 80/06/23	70-143
8007110357 8007110362 8007110365 8007110373	8007110353 8007110360 8007110364 6007110370 8007110372	80/07/03 80/07/03 80/07/09 80/07/01 80/06/27	50-301 S 50-269 S 50-339 P 50-219 S 50-327 S	8007140068 8007140065 80/06/26 8007140071 8007140060 80/06/13 8007140073 8007140058 80/06/25 8007140079 8007140057 80/06/11 8007140079 8007140074 80/06/18	10LFR 50-320 G 70-143 GA999 10CFR
9007110380	8007110378	80/07/03	50-296 5	8007140082 8007140057 80/06/11	GA999
8007110382	8007110377	80/06/24	COMMISSION	8007140086 8007140078 80/06/24	70-143
8007110383	8007110375	80/07/01	50-217 S	8007140087 8007140057 80/06/11	GA999
8007110387	8007110377	80/06/24	COMMISSION	8007140088 8007140057 80/06/11	GA999
8007110389	8007110386	80/07/07	50-309 R	8007140098 8007140097 80/05/05	50-397 G
8007110392	8007110377	80/06/24	COMMISSION	8007140102 8007140097 80/05/03	50-397 0
8007110394	8007110388	80/07/03	50-296 B	8007140108 8007140106 80/06/19	50-437 H
8007110395	8007110377	80/06/24	COMMISSION	8007140118 8007140115 80/06/09	50-277 H
8007110397	8007110371	80/07/03	50-346 B	8007140122 8007140121 79/07/02	660Y
8007110403	8007110400	80/06/30	50-321 B	8007140125 8007140123 80/06/20	50-269 P
8007110404 8007110406 8007110410 8007110414 8007110416	8007110394 8007110405 8007110402 8007110407 8007110407	80/07/07 80/07/03 80/07/07 80/07/03 80/07/03	50-247 S 50-324 R 50-302 S 50-255 R 50-346 B	8007140130 8007140121 79/07/02 8007140135 8007140121 79/07/02 8007140139 8007140121 79/07/02 8007140139 8007140121 79/07/02 8007140155 8007140153 80/06/18 8007140161 8007140153 80/06/18	SECY SECY SECY 50-259 Q 50-259 Q
8007110417	8007110413	80/07/02	50-416 S	8007140174 8007140169 80/05/28	50-280 G
8007110419	8007110411	80/07/03	50-331 S	8007140179 8007140170 80/07/08	50-387 B
8007110423	8007110418	80/07/03	50-346 S	8007140190 8007140182 80/06/12	50-247 P
8007110426	8007110415	80/07/03	50-321 S	8007140192 8007140184 80/06/25	50-282 G
8007110434	8007110427	80/07/02	50-346 S	8007140203 8007140200 80/06/30	CONTRACT
8007110437	8007110429	80/06/30	50-366 S	8007140217 8007140207 80/07/03	50-528 S
8007110442	8007110432	80/07/01	50-321 S	8007140220 8007140212 80/06/26	FGIA
8007110443	8007110439	80/06/23	NUREO	8007140225 8007140209 80/07/07	50-339 8
8007110448	8007110440	80/07/03	50-346 S	8007140227 8007140221 80/06/26	50-409 H
8007110450	8007110444	80/07/08	50-272 O	8007140231 8007140230 80/06/27	50-10 H
8007110457	8007110454	80/06/16	TOM STEAM TOM STEAM TOM STEAM TOM STEAM S 19C-08	8007140259 8007140249 80/07/08	50-280 S
8007110459	8007110454	80/06/16		8007140255 8007140255 80/06/11	50-346 M
8007110461	8007110452	80/06/23		8007140274 8007140265 80/06/30	XPORTLIC
8007110462	8007110454	80/06/16		8007140288 8007140283 80/06/27	XPORTLIC
8007110463	8007110455	80/07/02		8007140281 8007140277 80/06/26	FOIA
8007110468	8007110464	80/06/23	71-9130		FOIA
8007110474	8007110466	80/07/02	50-245 S		FOIA
8007110476	8007110473	80/06/23	71-5926		50-344 R
8007110479	8007110477	80/05/27	50-358 G		50-346 R
8007110482	8007110471	80/07/03	50-331 B		50-454 K
8007110485 8007110487 8007110493 8007110495 8007110498	8007110478 8007110484 8007110478 8007110484 8007110484	80/04/20 80/04/26 80/04/26 80/04/20	50-320 P BECY 50-320 P BECY BECY	8007140331 8007140327 80/07/07 8007140341 8007140339 80/07/03 8007140342 8007140343 80/07/09 8007140353 800/140349 80/07/03 8007140372 8007140364 80/06/30	50-295 R 50-528 S 50-29 P 50-518 S 50-335 S
8007110501 8007110503 8007110518 8007110521	8007110478 8007110484 8007110513 8007110515 8007110515	80/06/26 80/06/20 80/06/23 80/06/24 80/06/24	50-320 P SECY 70-925 50-424 Q 50-424 Q	8007140373         8007140367         80/06/16           8007140374         8007140368         80/07/07           8007140377         8007140349         80/07/11           8007140376         80/07/07         80/07/07           8007140377         80/07/07/07         80/07/10	TOPREP 50-033 6 50-056 K 50-452 G TOPREP
8007110531	8007110515	80/06/24	50-424 Q	8007140380 B007140371 80/07/07	40-279
8007110536	8007110515	80/06/24	50-424 G	8007140389 8007140382 80/06/29	50-335 8
8007110537	8007110535	80/06/20	CONTRACT	8007140394 8007140383 80/07/07	50-333 8
8007110552	8007110546	80/06/23	50-482 U	8007140396 8007140392 B0/07/08	50-3 P
8007110563	8007110556	80/06/26	50-155 Q	8007140399 8007140395 80/07/08	50-324 8
8007110566	8007110546	80/06/23	50-482 U	B007140400         B007140393         80/07/11           8007140405         8007140394         80/07/07           8007140408         8007140402         80/07/10           8007140411         8007140402         80/07/11           8007140416         80/07/11         80/07/11	50-338 P
8007110568	8007110546	80/06/23	50-482 U		50-348 B
8007110571	8007110546	80/06/23	50-462 U		PR
8007110575	8007110572	80/06/13	CDNTRACT		50-339 P
8007140007	8007140004	80/07/09	50-369 G		TOPREP
B007140009	800714000B	80/06/18	50-289 G	8007140417 8007140402 8D/07/10	PR
B007140010	8007140004	80/07/09	50-369 G	8007140420 8007140407 80/06/12	TUPREP
B007140014	8007140011	80/07/03	PR	8007140427 8007140422 80/07/03	50-390 S
B007140022	8007140016	80/07/07	50-289 G	8007140428 8007140424 80/07/09	50-155 G
B007140034	8007140032	80/07/09	50-361 G	8007140439 8007140432 80/07/07	PR
8007140037	8007140033	80/06/12	0A979	B007140441 8007140436 80/05/28	50-382 Q
8007140039	8007140033	80/06/12	GA979	B007140442 8007140434 80/07/03	50-331 P
8007140040	8007140036	80/07/04	PR	B007140447 8007140436 80/05/28	50-382 Q
8007140041	8007140035	80/06/03	70-8	8007140447 8007140432 80/07/07	PR
8007140042	8007140033	80/06/12	GA999	8007140450 8007140434 80/07/03	50-331 P

ACCEBS10					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT	
8007140456 8007140471 8007140473 8007140481 8007140486	8007140443 8007140464 8007140461 8007140470 8007140480	80/07/07 80/04/17 80/04/28 80/04/25 80/06/24	50~328 50~346 50~269 50~341 50~298	5 0 0 0	8007150107 8007150108 8007150118 8007150120 6007150124	8007150087 8007150102 8007150113 8007150104 8007150106	80/06/24 80/06/30 80/06/06 80/07/02 80/07/02	50-261 50-358 50-454 50-344 50-344	0 0 0
8007140498 8007140492 8007140493 8007140494 8007140502	8007140461 8007140480 8007140485 8007140487 8007140497	80/04/28 80/06/24 80/05/27 80/05/30 80/06/19	50-269 50-298 50-155 50-263 50-445	9 0 0 0	8007150126 8007150130 8007150135 8007150136 8007150141	8007150106 8007150106 8007150128 8007150125 8007150126	80/07/02 80/07/02 80/06/19 80/06/06 80/06/19	50-344 50-344 70-364 50-298 70-364	Q Q
8007140504 8007140505 8007140509 8007140514 8007140521	8007140491 8007140500 8007140500 8007140500 8007140512	80/07/10 80/06/26 80/06/26 80/07/03	FO1A 50~254 50-254 50-254 CONTRACT	р Р Р	8007150148 8007150150 8007150156 8007150163 8007150171	8007150128 8007150128 8007150128 8007150128 8007150145	80/06/19 80/06/19 80/06/19 80/06/19 80/06/04	70-364 70-364 70-364 70-364 50-285	a
8007140526 8007140527 8007140540 8007140541 8007140546	8007140522 8007140513 8007140531 8007140522 8007140539	80/05/19 80/05/14 80/06/05 80/05/19 80/06/20	50-483 70-143 ACRS 50-483 SECY	o a	8007150318 8007150325 8007150332 8007150452 8007150466	8007150314 8007150314 8007150314 8007150447 8007150455	80/04/10 80/04/10 80/04/10 80/06/05 80/07/07	70-2651 70-2651 70-2651 50-566 50-327	Q 8
8007140555 8007140558 8007140560 8007140578 8007140607	8007140548 8007140548 8007140552 8007140572 8007140600	80/05/25 80/05/27 80/05/18 80/07/01 80/06/13	50-297 50-346 SECY REGGD 40-8502	G G	8007150468 8007150471 8007150488 8007150494 8007150501	8007150462 8007150462 8007150470 8007150489 8007150491	80/06/20 80/06/20 80/06/26 80/07/10	50-280 50-280 50-327 50-313 50-327	0 8 P 8
8007140608 8007140609 8007140614 8007140618 8007140620	8007140604 8007140604 8007140605 8007140605 8007140613	80/05/21 80/05/21 80/07/01 80/07/01 80/06/20	27-48 27-48 50-325 50-325 71-6294	P	8007150502 8007150503 8007150504 8007150508 8007150510	8007150499 8007150495 8007150495 8007150496 8007150495	80/07/08 80/04/25 80/04/25 80/07/08 80/06/25	50-302 50-302 50-321	P 0 0 8 0
8007140424 8007140425 8007140428 8007140429 8007140431	8007140605 8007140616 8007140623 8007140616 8007140627	80/07/01 80/07/02 80/06/13 80/07/02 80/05/21	50-325 50-320 50-244 50-320 40-8702	Р Н Р Н	8007150511 8007150512 8007150514 8007150517 8007150517	8007150495 8007150504 8007150513 8007150514 8007150515	80/06/25 80/07/07 80/07/09 80/07/07 80/07/09	50-302 50-327 50-320 50-272 50-320	0 8 8 8
8007140632 8007140633 8007140636 8007140637 8007140643	8007140623 8007140626 8007140623 8007140630 8007140639	80/06/13 80/06/05 80/06/13 80/06/19 80/06/19	50-244 CONTRACT 50-244 TOPREP TOPREP	P	8007150520 8007150522 8007150534 8007150537 8007150538	8007150518 8007150521 8007150532 8007150529 8007150530	80/07/09 80/07/09 80/07/07 80/07/08 80/07/11	70-143 50-327 50-335 50-373 50-313	P 8
8007140648 8007140649 8007140654 8007140656 8007140657	8007140544 8007140646 8007140646 8007140645 8007140653	80/05/21 80/07/02 80/07/02 80/07/09 80/05/21	70-135 71-4387 71-6387 FOTA 40-2940		B007150544 8007150547 8007150556 B007150561 B007150562	B007150539 8007150542 8007150527 8007150555 8007150559	80/07/03 80/07/09 80/07/11 80/07/09 80/07/10	50-321 50-315 50-312 50-316 50-106	B R O R W
8007140658 8007140662 8007140663 8007140666 8007140668	8007140646 8007140646 8007140653 8007140646 8007140646	80/07/02 80/07/02 80/05/21 80/07/02 80/07/02	71-6387 71-6387 40-2940 71-6387 71-6387		8007150556 8007150573 8007150574 8007150578 8007150582	8007150540 8007150548 8007150570 8007150571 8007150571	80/07/10 80/07/07 80/07/10 80/07/11 80/07/11	50-346 50-133 50-259 50-327 50-327	8 R 8 P
8007140670 8007140673 8007140678 8007140682 8007140687	8007140653 8007140646 8007140646 8007140675 8007140646	80/05/21 80/07/02 80/07/02 80/07/02 80/07/02	40~2940 71~4387 71~6387 70~1193 71~4387		8007150583 8007150585 8007150587 8007150590 8007150592	8007150575 8007150580 8007150579 8007150584 8007150588	80/07/11 80/07/09 80/07/09 80/07/09 80/07/07	50-269 50-327 50-206 50-244 50-312	P 8 8
8007140490 8007140702 8007140709 8007150006 8007150009	8007140646 8007140698 8007140706 8007150002 8007150007	80/07/02 80/07/01 80/07/01 80/04/30 80/06/30	71-6397 71-346 71-5 50-483 50-498	a 0	8007150597 8007150603 8007150604 8007150605 8007150614	8007130584 8007130575 8007130574 8007130579 8007130611	80/07/08 80/07/10 80/07/10 80/07/08 80/07/09	50-315 50-313 50-272 50-204 50-263	8 8 8 8
8007150010 8007150019 8007150021 8007150023 8007150031	8007150002 8007150015 8007150015 8007150017 8007150027	80/06/30 80/06/23 80/06/23 80/06/04 80/06/17	50-483 50-269 50-269 50-483 70-1113	0 0 0	8007150618 8007150620 8007150623 8007150625 8007150628	8007150610 8007150615 8007150586 8007150619 8007150621	80/07/10 80/07/08 80/07/08 80/07/01 80/07/08	50-266 50-326 50-315 50-254 50-272	R R B R B
		7,	70-1113 50-184 50-184 113 TLTC	P P	8007150633 8007150636 8007150642 8007150650 8007150651	8007150629 8007150627 8007150635 8007150641 8007150644	80/07/10 80/07/03 80/07/03 80/07/07 80/06/16	50-261 50-335 50-366 50-313 40-8502	8
				Þ	8007150452 8007150454 8007150457 8007150460 8007150463	8007150646 8007150646 8007150644 8007150647 8007150659	80/06/16 80/06/16 80/06/16 80/07/09 80/07/11	TOPREP TOPREP 40-9502 50-348 50-544	8
					8007150667 8007150667 8007150668 8007150674 8007150679	8007150454 8007150444 8007150662 8007150666 8007150672	80/07/11 80/06/15 80/07/11 80/07/08 80/07/08	50-325 40-8502 50-348 50-321 50-272	R B B

ACCESS ION					ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1590ED	SUBJECT CATEGORY	
8007150685 8007150693 8007150695 8007150701 8007150703	80071506/8 8007150683 8007150684 8007150686 8007150696	80/07/07 80/07/09 80/07/08 80/07/07 80/07/10	50-346 50-346 50-314 50-338 50-315	6 6 6 8	8007140651 8007140654 8007140656 8007140658 8007140662	8007160626 8007160647 8007160650 8007160652 8007160655	80/07/08 80/07/09 80/07/07 80/07/09 80/07/09	50+461 9 50-334 6 50-438 9 50-528 9	8 3
8007150704 8007150712 8007150713 8007150715 8007150777	8007150699 8007150705 8007150708 8007150707 8007150767	80/07/08 80/07/08 80/07/09 80/07/10 80/07/10	50-293 50-219 50-302 50-333 50-338	R R R S	8007160663 8007160665 8007160672 8007160679 8007140690	8007160657 8007160626 8007160668 8007160626 8007160676	80/07/07 80/07/08 80/06/2/ 80/07/08 80/07/09		ā
8007150778 8007150806 8007150814 8007150815 8007150817	8007150803 8007150809 8007150809 8007150808 8007150810	80/06/12 80/07/09 80/05/09 80/07/07 80/07/07	DRG 50-255 70-364 50-339 50-339	9 5	8007140481 8007140498 8007140498 8007140709	8007160677 8007160687 8007160692 8007160687 8007160687	80/07/08 80/07/08 80/07/08 80/07/08 80/07/08	50-274 F 50-341 /	A
8007150826 8007160109 8007160115 8007160121	8007150820 8007160096 8007160096 8007160096	80/07/09 80/06/17 80/06/17 80/06/17	50-344 GA999 GA999 GA999 GA999	ន	8007160710 8007160721 8007140727 8007160724 8007160741	8007160700 8007160700 8007160718 8007160725 8007160725	80/06/27 80/06/27 80/06/27 80/06/04 80/06/04	40-7982 40-7982 70-1113 50-440 50-440	
8007160146 8007160157 8007160171 8007160188 8007160193	8007160133 8007160150 8007160161 8007160177	80/05/01 80/05/14 80/05/19 80/06/17 80/06/17	GA999 GA999 GA999 GA999 GA999		80071 60742 80071 60755 80071 60756 80071 60764 80071 60764	8007160732 8007160743 8007160751 8007160745 8007160781	80/06/05 80/06/16 80/06/11 80/07/01 80/06/11	50-338 G TGPRFP 50-461 G 50-338 G 50-461 G	3
8007160202 8007160207 8007160227 8007160317 8007160335	8007160177 8007160177 8007160208 8007160310 8007160322	80/06/17 80/06/17 80/07/02 80/07/01 80/07/01	0A999 0A999 CONTRACT 71-391 71-389		8007160765 8007160772 8007160810 8007160817	8007160743 8007160767 8007160797 8007160805 8007160797	61/40/08 16/10/08 0E/40/08 11/40/08 0E/40/08	TOPREP 71-392 50-335 REGOD 50-335	
8007160347 8007160372 8007160376 8007160379 8007160387	8007160343 8007160365 8007160365 8007160365 8007160381	80/07/01 80/06/27 80/06/27 80/06/27 80/07/07	71-393 50-344 50-344 50-344 71-4888	P P	8007 i 60826 8007 i 60830 8007 i 60843 8007 i 6085 8007 i 60858	8007160797 8007160797 8007160836 8007160848 8007160854	80/06/30 80/06/30 80/06/27 80/06/04 80/06/04	50-335 G 50-335 G 70-143 COMM15810N COMM15810N	9 V
0007160395 0007160397 8007160399 0007160404 0007160408	8007160392 8007160393 8007160394 8007160393 8007160393	80/07/07 80/06/18 80/07/01 80/06/18 80/06/18	50-275 QA999 XPORTLIC QA999 QA999	A	8007160862 8007160866 8007160867 8007160867 8007160870	8007160860 8007160860 8007160863 8007160860 8007160860	BO/07/01 BO/07/01 BO/06/25 BO/07/01 BO/07/01	50-416 0 50-416 0 90-322 0 50-416 0	3
8007160411 8007160412 8007160425 8007160427 8007160434	8007160393 8007160409 8007160421 8007160421 8007160429	80/06/18 80/07/07 80/06/02 80/06/02 80/06/12	0A999 71-4986 50-29 50-29 50-269	P P P	8007160872 8007170031 8007170037 8007170071 8007170088	8007160860 8007170049 8007170049 8007170066 8007170084	80/07/01 80/07/02 80/07/02 80/06/16 80/06/12	50-416 Q 50-206 H 50-206 H 50-317 P 50-133 Q	1
8007160445 8007160453 8007160463 8007160474 8007160478	8007160429 8007160429 8007160459 8007160464 8007160471	80/06/12 80/06/12 80/06/19 80/07/07 80/07/11	50-267 50-269 50-10 50-305 50-327	Р Р 9 Р	8007170097 8007170098 8007170103 8007170118 8007170129	6007170093 6007170094 6007170094 6007170113 6007170122	80/07/07 80/05/29 80/05/29 80/07/09 80/07/08	71-5341 50-373 8 50-373 8 71-5862 CONTRACT	
8007160479 8007160484 8007160496 8007160498 8007160502	8007160469 8007160471 8007160490 8007160490 8007160485	80/06/10 80/07/11 80/06/19 80/06/19 80/07/11	50-544 50-327 CONTRACT CONTRACT 50-305	0 P	8007170145 8007170141 8007170171 8007170172 8007170183	8007170135 8007170157 8007170159 8007170167 8007170175	90/07/10 90/07/08 90/07/08 90/06/09 80/07/14	CONTRACT CONTRACT 50-446 G CUNTRACT 50-739 P	
8007160504 8007160510 8007160513 8007160518 8007160521	8007140490 8007140485 8007140490 8007140514 8007140520	80/06/19 80/07/11 80/06/19 80/07/11 80/07/10	CONTRACT 50-305 CONTRACT 50-413 50-275	8 8 A	8007170189 8007170194 8007170216 8007170220 8007170221	8007170179 8007170186 8007170212 8007170215 8007170219	B0/07/14 B0/06/30 B0/06/30 B0/07/15 B0/06/02	50-339 P 50-306 G CONTRACT 70-1308 50-327 G	3
8007160523 8007160525 8007160526 8007160548 8007160551	8007160517 8007160522 8007160524 8007160544 8007160546	80/07/11 80/06/30 80/07/11 80/07/09 80/07/08	50-327 50-320 50-289 50-305 50-530	S B R R	8007170222 8007170224 8007170251 800717025 8007170238	8007170217 8007170219 8007170244 8007170249 8007170244	80/06/26 80/06/02 80/07/01 80/06/03 80/07/01	CONTRACT 50-327 (1 50-327 (1 50-387 (1 6ECY	
8007160556 8007160562 8007160564 8007160565 8007160566	8007160552 8007160558 8007160555 8007160560 8007160559	80/07/10 80/07/11 80/07/09 80/07/08 80/07/03	50-259 50-282 50-334 50-466 50-454	R R P G K	8007170262 8007170266 800710270 8007170271 8007170274	8007170255 8007170264 8007170265 8007170264 8007170268	80/06/26 80/06/02 80/05/20 80/06/02 80/05/30	XPORTLIC 50-219 G 50-52B G 50-219 G 50-354 G	) )
8007160569 8007160574 8007160578 8007160609 8007160617	8007140559 8007140559 8007140571 8007140404 8007140410	80/07/03 80/07/03 80/04/18 80/07/11 80/06/11	50~454 50~454 50~328 50~498 50~415	К 5 Б А	8007170274 8007170277 8007170285 8007170286 8007170288	8007170264 8007170254 8007170281 8007170264 8007170263	80/06/02 80/07/02 80/07/11 80/06/02 80/05/30	50-219 6 State Prog 50-319 F 50-219 6	9
8007160623 8007160638 8007160638 8007160649	8007160618 8007160628 8007160626 8007160641 8007160634	80/07/11 80/07/07 80/07/08 80/07/03 80/07/09	50-289 50-311 50-461 50-293 50-329	8 8 8 8 8	8007170292 8007170294 8007170296 8007170296 8007170298	8007170264 8007170290 800717028P 8007170291 8007170264	80/06/02 80/07/13 80/07/03 80/06/10 80/06/02	FOIA 50-416 9 10078 40-8602 FOIA	3

		NOCE ASTON	NUMBER		
PRINCIPAL DATE	SUBJECT	ENCLOSURE	PRINCIPAL	DATE	SUBJECT
ENCLOSURE DOCUMENT ISSUED	CATEGORY		DOCUMENT	ISSUED	CATEGORY
8007170302 8007170291 80/06/10	40-8602	8007170482	8007170442	B0/07/09	50-320 P
8007170304 8007170264 80/06/02	FDIA	8007170483	8007170472	B0/06/30	50-344 P
8007170305 8007170300 80/06/12	70-925	8007170488	8007170442	B0/07/09	50-320 P
8007170306 8007170264 80/06/02	FDIA	8007170490	8007170442	B0/07/09	50-320 P
8007170308 9007170291 80/06/10	40-8602	8007170493	8007170470	B0/07/09	50-528 S
8007170310 8007170300 80/06/16	70-925	8007170497	8007170481	80/07/08	50-321 8
8007170314 8007170264 80/06/02	F01A	8007170499	8007170442	80/07/09	50-320 P
8007170317 8007170313 80/07/02	50-482 A	8007170502	8007170442	80/07/09	50-320 P
8007170318 8007170264 80/06/02	F01A	8007170503	8007170496	80/07/01	50-327 P
8007170322 8007170264 80/06/02	70-1869	8007170505	8007170442	80/07/09	50-320 P
8007170324 8007170264 80/06/02	70-1869	8007170508	8007170496	80/07/01	50-327 P
8007170328 8007170264 80/06/02	FDIA	8007170511	8007170442	80/07/09	50-320 P
8007170328 8007170364 80/06/02	FDIA	8007170517	8007170496	80/07/01	50-327 P
8007170329 8007170327 80/06/11	40-8681	8007170521	8007170442	80/07/09	50-320 P
8007170330 8007170323 80/06/19	50-10 G	8007170525	8007170513	80/07/11	50-390 S
8007170331 8007170327 80/06/11	40-8691	8007170533	6007170442	80/07/09	50-320 P
8007170332 8007170327 80/06/11	40-8681	8007170534	6007170523	80/07/01	8ECY
8007170333 8007170323 80/06/19	50-10 G	8007170535	6007170442	80/07/09	50-320 P
8007170335 8007170327 80/06/11	40-8681	8007170539	6007170530	80/05/20	50-361 Q
8007170336 8007170323 80/06/19	50-10 G	8007170542	6007170538	80/07/02	50-528 G
8007170337         8007170264         80/06/02           8007170340         8007170338         80/07/03           8007170341         8007170264         80/06/02           8007170344         8007170342         80/07/10           8007170345         8007170264         80/06/02	70-1869	8007170550	8007170545	80/06/10	50-315 G
	30-320 P	8007170556	8007170545	80/06/10	50-315 G
	70-1869	8007170565	8007170561	80/07/01	50-206 G
	50-566 S	8007170566	8007170560	80/07/14	50-260 P
	70-1869	8007170567	8007170559	80/06/19	50-553 G
8007170347         8007170339         80/07/03           8007170349         8007170264         80/06/02           8007170350         800717034B         80/07/15           8007170351         8007170359         80/07/15           8007170353         80/07/170352         80/07/14	90-322 A	8007170568	8007170562	80/07/01	50-344 R
	70-1869	8007170569	8007170561	80/07/01	50-206 Q
	50-280 V	8007170573	8007170561	80/07/01	50-206 Q
	50-322 A	8007170574	8007170560	80/07/14	50-260 P
	50-317 P	8007170579	8007170561	80/07/01	50-206 Q
8007170355         B007170354         B0/07/15           8007170358         8007170356         80/07/10           8007170359         8007170357         80/07/10           8007170361         8007170360         80/07/11           8007170365         8007170363         80/07/30	50-155	8007170584 8007170585 8007170594 8007170599 8007170604	8007170559 8007170577 8007170589 8007170593 8007170597	80/06/19 80/07/11 80/06/12 80/05/22 80/07/03	50-553 Q 50-440 S 50-443 S 50-343 Q 10GFR
B007170367 B007170366 B0/06/26	50~400 K	8007170611	8007170604	80/05/21	50-286 Q
B007170371 8007170369 B0/07/15	50~556 0	8007170612	8007170607	80/07/14	50-395 A
B007170379 8007170376 B0/07/09	50~285 R	8007170630	8007170622	80/05/28	70-135
B007170397 B007170392 B0/07/08	50~321 E	8007170635	8007170625	80/06/30	50-329 Q
B007170391 B007170389 B0/07/14	50~280 R	8007170639	8007170628	80/06/26	50-400 A
8007170394 8007170393 80/07/16	50-220 P	8007170645	8007170637	80/05/28	50-387 G
8007170397 8007170393 80/07/16	50-220 P	8007170656	8007170647	80/07/03	50-270 P
8007170399 8007170264 80/06/02	FDIA	8007170663	8007170632	80/06/26	50-400 C
8007170400 8007170396 80/07/10	50-416 S	8007170665	8007170634	80/06/17	50-354 G
8007170402 8007170264 80/06/02	FDIA	8007170668	8007170660	80/07/03	WASTE MOT
8007170403 8007170393 80/07/16	50-220 P	8007170670	8007170654	80/06/17	50-354 Q
8007170407 8007170264 80/06/02	70-1869	8007170678	8007170652	80/06/26	50-400 C
8007170408 8007170392 80/07/08	50-321 S	8007170681	8007170678	80/07/03	MIEC
8007170410 8007170405 80/07/08	50-366 S	8007170602	8007170654	80/06/17	50-354 Q
8007170411 8007170264 80/06/02	FOIA	8007170686	8007170652	80/06/26	50-400 C
8007170416 8007170264 80/06/02	FDIA	8007170692	8007170688	80/05/28	50-219 0
8007170418 8007170415 80/06/20	COMMISSION	8007180007	8007180004	80/05/30	50-320 P
8007170419 8007170414 80/07/10	50-321 S	8007180010	8007180003	80/07/01	50-10 0
8007170421 8007170417 80/07/07	TOPREP	8007180011	8007180005	80/06/05	50-327 0
8007170427 8007170423 80/06/18	50-316 P	8007180012	8007180004	80/05/30	50-320 P
8007170427 8007170420 80/06/06 8007170431 8007170423 80/06/18 8007170432 8007170264 80/06/02 8007170434 8007170243 80/06/18 8007170436 8007170433 80/06/13	50-324	8007180018 8007180022 8007180025 8007180034 8007180044	8007180014 8007180017 8007180023 8007180029 8007180044	80/05/23 80/06/04 80/05/23 80/06/12 80/06/27	50-204
800717043B         8007170264         80/06/02           8007170440         8007170433         80/06/13           8007170443         8007170439         80/07/03           8007170445         8007170439         80/07/03           8007170446         8007170442         80/07/09	FD1A 40-6745 50-337 P 50-320 P	8007180047 8007180051 8007180053 8007180063 8007180066	B007180042 B007180044 B007180044 B007180060 B007180058	80/06/03 80/06/27 80/06/27 80/05/14 80/06/27	50-322 H 50-286 P 50-286 P 50-219 H 70-371
800717044B         8007170437         80/07/10           8007170449         8007170439         80/07/03           8007170450         8007170441         80/07/03           8007170452         8007170442         80/07/09           8007170435         8007170442         80/07/09	50-311 8 50-339 P 50-346 8 50-320 P	8007180070 8007180071 8007180082 8007180101 8007180110	8007180061 8007180058 8007180058 8007180077 8007180107	80/07/01 80/06/27 80/06/27 80/05/23 80/07/02	50-327 P 70-371 70-371 50-293 Q 50-320 H
8007170463 8007170451 80/07/08 8007170464 8007170448 80/07/09	50-320 P 50-344 P 50-321 S 50-320 P 50-320 P	8007180122 8007180123 8007180133 8007180134 8007180135	8007180112 8007180119 8007180125 8007180115 8007180115	80/07/01 80/07/01 80/07/07 80/07/02 80/07/02	50-285 q 50-277 P 50-346 P 50-366 P 50-366 P
8007170469 8007170457 80/07/02 8007170473 8007170442 80/07/09 8007170477 8007170457 80/07/02	50-344 S 50-344 P 50-320 P 50-346 P 50-320 P	8007180138 8007180140 8007180149 8007180160 8007180169	8007180115 8007180125 8007180125 8007180154 8007180164	80/07/02 80/07/07 80/07/07 80/07/09 80/05/08	50-366 P 50-346 P 50-346 P 50-289 H COMMISSION

ACCESS ION	NUMBER					CESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	<u>′</u>	ENCL	OSURE	PRINCIPAL DOCUMENT	DATE ISSUFD	TOSUBUR YRODSTAD	_
8007180179 8007180187 8007180193 8007180199 8007180208	8007180174 8007180032 8007180186 8007180189 8007180196	80/07/03 80/06/19 80/06/27 80/07/02 80/06/07	CONTRACT 50-553	6 9 F	80072 80072 80072 80072	210148 210160 210165 210170	8007210137 8007210154 8007210157 8007210169 8007210167	B0/04/01 B0/06/30 B0/05/29 B0/07/01 B0/06/24	CONTRACT	a a
8007180212 8007180217 8007180220 8007180221 8007180227	8007180032 8007180214 8007180189 8007180216 8007180224	80/04/19 80/07/03 80/07/02 80/05/12 80/06/06	fitate Pro	ā	80072 80072 80073	210184 210189 210190	8007210167 8007210167 8007210176 8007210185 8007210167	80/06/24 80/06/23 80/06/09 80/06/24	70-33 70-33 50-322 70-1143 70-33	A
8007180234 8007180250 8007180265 8007180275 8007180276	8007180189 8007180237 8007180254 8007180254 8007180260	80/07/02 80/06/26 80/06/24 80/06/24 80/07/16	50-395 50-395	0 H G 0	9007a 9007a 9007a	210196 210205 210209 210214 210215	8007210186 8007210200 8007210201 8007210206 8007210197	80/07/02 80/06/27 80/06/03 80/07/03 80/07/02	71-139 50-410 50-352	9 0 0
8007180306 8007180307 8007180314 8007180316 8007180318	8007180300 8007180298 8007180301 8007180308 8007180312	80/07/16 B0/07/11 B0/07/14 B0/07/07 B0/07/17	50-245	6 8 8	80073 80072 80073	210226 210226	8007210204 8007210197 8007210197 8007210197 8007210229	80/07/03 80/07/02 80/07/03 80/07/02 80/07/17	50-277 50-352	0 0 0 0
8007180322 8007180324 8007180327 8007180334 8007180344	8007180317 8007180321 8007180319 8007180333 8007180340	B0/07/11 B0/07/10 B0/07/11 B0/07/09 B0/07/15	50-270 50-281 50-10	8 8 8 A	80073 80073 80073	210235 210240 210245 210247 210255	8007210197 8007210206 8007210238 8007210231 8007210231	B0/07/02 B0/07/03 B0/07/10 B0/06/04 B0/06/09	50-352 50-336 50-317	0 9 P 0
8007180375 8007180400 8007180402 8007180413 8007180415	8007180390 8007180398 8007180393 8007180408 8007180409	80/07/11 80/07/08 80/07/07 80/07/09 80/07/14	50-271 50-293 50-245	R R P R	80072 80073 80072	210258 210264 210267 210275 210282	8007210253 8007210257 8007210263 8007210269 8007210276	80/05/27 80/05/27 80/01/01 80/05/28 80/06/27	CONTRACT GA999 CONTRACT GA999 50-354	G.
8007180422 8007180423 8007180427 8007180431 8007180433	8007180418 8007180409 8007180035 8007180035 8007180419	80/07/11 80/07/14 78/12/05 78/12/05 80/07/10	COMMISSIC		80072 80073 80072	210292 210293 210294 210295 210298	8007210283 8007210289 8007210289 8007210289 8007210289	80/07/14 80/06/30 80/07/08 80/06/30 80/06/30	70~697	G G
8007180446 8007180448 8007180451 8007180453 8007180454	8007180443 8007180441 8007180445 8007180441 8007180441	B0/07/16 B0/07/10 B0/06/23 B0/07/10 B0/07/10	50-344 50-219 60-344	P Q P P	90073 90073 90073	210299 210302 210304 210307 210309	8007210288 8007210297 8007210289 8007210197 8007210308	80/07/08 80/07/11 80/06/30 80/07/02 80/06/04	50~358 70~687 50~277	G G G
8007180455 8007180461 8007180464 8007180467 8007180470	8007180449 8007180457 8007180458 8007180462 8007180460	80/06/19 80/07/09 80/05/14 80/06/11		H	80072 89072 80073	210314 210315 210318 210319 210321	8007210311 8007210310 8007210316 8007210311 8007210312	80/06/12 80/06/24 80/06/30 80/06/12 80/06/26	70-1257 XPORTLIC 50-250	Gi P
8007180478 8007180479 8007180483 8007180486 8007180487	8007180474 8007180471 8007180475 8007180471 8007180484	80/05/12 80/06/11 80/06/2/ 80/06/11 80/07/07	TOPREP 71-249 TOPREP	H P	80072 80073 80072	210323 210324 210325 210326 210327	8007210311 8007210320 8007210322 8007210312 8007210322	80/05/12 79/09/04 80/05/05 80/05/25 80/05/05	70-157 50-346 50-35⊋	р () () ()
8007180496 8007180499 8007180504 8007180513 8007180519	8007180471 8007180470 8007180471 8007180508 8007180508	B0/06/11 B0/04/09 B0/06/11 B0/06/05 B0/06/05	TOPREP 50-445 TOPREP 50-456 50-456	a a a	80072 80072 80073	210330 210331 210333 210335 210336	8007210312 8007210317 8007210329 8007210329 8007210312	80/06/26 80/06/24 80/07/02 80/07/02 80/06/26	CONTRACT 50-346 50-346	Ф Р Ф
8007180524 8007180538 8007180561 8007180574 8007180579	8007180521 8007180518 8007180552 8007180567 8007180474	80/04/30 80/04/12 80/04/12 80/04/17 80/06/30	CONTRACT 50-344 50-410 50-445 COMMISSIC	0 0 0 70	8007 8007 8007	210340 210341 210343 210345 210349	8007210329 8007210334 8007210288 8007210334 8007210334	80/0//02 80/06/27 80/07/08 80/06/27 80/06/27	50-387 50-219 50-387	9 0 0 0
8007180585 8007180591 8007180596 8007180598 8007180599	8007180582 8007180588 8007180595 8007180595 8007180595	80/07/10 80/07/08 80/07/01 80/07/01 80/07/01	50-440 50-440 50-327 50-327 50-327	9 9 9 9	8007; 8007; 8007;	210355 210369 210371 210375 210377	8007210334 8007210367 8007210370 8007210374 8007210374	B0/06/27 79/08/29 80/07/14 80/07/11 80/07/14	70-307 50-321 50-33A	0 R R R
8007210040 8007210047 8007210076 8007210077 8007210082	8007210033 8007210046 8007210009 8007210062 8007210062	80/07/01 80/05/15 80/07/01 80/07/08 80/07/08	50-322 50-320 8ECY 70-1151 70-1151	g H	80072 80073 80073	210380 210382 210397 210400 210404	8007210377 8007210381 8007210393 8007210394 8007210395	80/07/14 80/07/15 80/07/11 80/07/14 80/07/15	8AE-06 AAE-06 8AE-06	5 R 8 B A
8007210083 8007210086 8007210093 8007210107 8007210113	8007210009 8007210062 8007210062 8007210079 8007210105	80/07/01 80/07/08 80/07/08 80/04/11 80/06/30	SECY 70-1151 70-1151 50-224 CONTRACT	q	8007; 8007; 8007;	210405 210413 210421 210426 210430	8007210399 8007210404 8007210417 8007210425 8007210423	79/08/29 80/07/14 80/07/11 80/07/14 80/06/13	50 -313 50-269 50-270	R B F B
8007210125 8007210130 8007210131 8007210135 8007210136	8007210114 8007210118 8007210121 8007210122 8007210128	80/06/10 80/07/01 80/07/09 80/06/30 80/07/01	50-483 71-17 50-320 CDNTRACT 50-341	о н я	9007: 8007: 9007:	210431 210432 210433 210438 210440	8007210428 8007210420 8007210427 8007210408 8007210427	80/07/09 80/07/15 80/07/15 80/07/08 79/08/29	50-309 50-313 50-62 50-255	8 F 9

ACCESSIO	NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	BATE ISSUED	SUBJECT	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 189UED	CATEGO	
B007210444 B007210452	B007210437 8007210408	80/07/15	50-282 50-246	5. P	9007220121 8007220125	8007220110 8007220115	B0/07/1B B0/07/09	50-599 71-5971	G
B007210460 B007210465	8007210408 8007210408	80/07/08 80/07/08	50-266 50-266	þ	8007220135 8007220142	8007220131 8007220136	80/07/10 80/07/07	71~576E GA999	
8007210467 8007210469	8007210456 6007210408	79/08/31 B0/07/08	50-271 50-246	R P	8007220145 8007220146	8007220136 8007220140	80/07/07 80/07/03	0A999 50-482	
8007210470 8007210475	8007210459 8007210461	80/07/11 80/07/11	50-249 50-327	S 5	8007220150 8007220152	8007220136 8007220143	80/07/07 80/07/10	0A999 71-6387	,
8007210485 8007210486	8007210478 8007210476	80/07/15 80/07/14	50-445 50-413	A	8007220154 8007220155	8007220140 8007220136	80/07/03 80/07/07	50-482 GA799	G
8007210490 8007210492	8007210478 8007210484	80/07/15 80/07/14	50-445 50-321	A	8007220145 8007220145	8007220158 8007220158	80/06/25 80/06/25	50-206 50-206	P
8007210495 8007210496	8007210487 8007210478	80/07/14 80/07/15	50-287 50-445	G A	8007220175 8007220181	8007220174 8007220174	80/07/0B 80/07/08	50-293 50-293	o o
8007210500	8007210478	80/07/15	50-445	A	8007220185	B007220177	80/06/05	50-313	Q
8007210503 8007210504 8007210507	8007210487 8007210478 8007210494	B0/07/14 B0/07/15 B0/07/14	50-269 50-445 50-272	G A B	8007220197 8007220199	8007220174 8007220182	80/07/08 80/07/07	50-293 0A999	g -
800721050B 800721050B	800721047B 8007210501	80/07/15 80/05/24	50-445 90-243	A	8007220191 8907220196 8007220197	8007220174 8007220182 8007220177	80/07/08 80/07/07	50~293 0A999	G C
0007210510	8007210478	80/07/15	50-445	A	9007220199	8007220174	80/06/05 80/07/08	50-313 50-293	G G
8007210512 8007210514	8007210502 8007210478	80/07/11 80/07/15	50~59 50-445	R	8007220202 6007220208	8007220182 8007220182	80/07/07 80/07/07	9A999 9A999	_
B007210517 B007210519	8007210478 8007210478	B0/07/15 B0/07/15	50-445 50-445	A	6007220207 6007220214	B007220203 B007220207	80/07/08 80/07/15	50-269 FOIA	G
8007210520	8007210457	80/07/01	50-423	8	8007220217	8007220203	80/07/08	50-287	Q
8007210521 8007210527	8007210514 8007210478	80/06/24 80/07/15	50-461 50-445	A	8007220220 8007220224	8007220211 8007220216	80/06/23 80/06/09	70~135 M18C	
8007210539 8007210541	8007210534 8007210537	80/05/29 80/07/14	0A777 50-314	8	8007220234 8007220242	8007220229 8007220211	80\0P\53 80\0P\50	50~305 70-135	F
8007210545 8007210546	8007210533 8007210543	80/07/12 80/07/08	50-423 50-528	Q Q	8007220248 8007220231	8007220243 8007220243	80/07/16 80/07/16	70-143 70-143	
8007210548 8007210553	9007210542 8007219542	80\07\50 80\07\50	40-8502 40-8502	_	8007220268 8007220273	8007220263 8007220263	80/07/15 80/07/15	40-279 40-299	
8007210556 8007210558	8007210543 8007210550	80/07/0B 80/07/10	50-528 40-2474	a	8007R20285 8007220310	8007220278 8007220303	80/06/04 80/07/07	50-317	G
8007210565 8007210566	8007210543 B007210540	80/07/08 80/05/04	50~52B 40-8584	G	B007220315 B007220317	8007220303 8007220303 8007220314	80/07/07 80/06/30	40-8304 40-8304 40-1162	
8007210569 8007210578	B007210550 B007210543	80/07/10 80/07/08	40~2674 50-528	G	8007220334 8007220337	8007220329 8007220330	80/07/08 80/06/04	TOPREP 50~73	q
6007210587 8007210617	8007210593 8007210609	80/07/09 80/07/11	71~5998 50-2 <b>B</b> 7	9	8007220346 8007220353	8007220342 8007220349	79/08/17	50-259	R
8007210640 8007210645	8007210638 8007210643	80/07/01 80/07/10	50-409 50-301	P	8007220354 8007220358	8007220352 8007220351	80/07/17 80/07/15 80/07/15	50-70 TOPREP	P.
8007210647	8007210643	80/07/10	50-301	G	8007220356	B007220349	80/07/17	50-317 50-70	R P
8007210549 8007220011	8007210643 8007220009	80/07/10 80/07/18	50-301 70-1308	Ģ	6007220357 8007220357	8007220352 8007220352	60/07/15 60/07/15	TOPREP TOPREP	
8007220023 8007220030	8007220018 8007220027	80/07/02 80/07/01	M180 50-546	н	8007220360 8007220361	8007220358 8007220352	60/07/14 60/07/15	50-327 TOPREP	R
B007220032 B007220033	8007220025 B007220031	80/05/19 80/07/08	WASTE MG1 50-289	н	8007220362	8007220349	80/07/17	50-70	P
8007220036 8007220042	8007220025 8007220025	80/06/19	WASTE MOT	•	8007220364 8007220366 8007220369	8007220363 8007220349 8007220349	80/07/17 80/07/17	50-219 50-70 50-70	b U
8007220049 8007220052	8007220025 8007220050	80/05/19 80/05/09	WASTE MOT		8007220371 8007220372	8007220367 8007220349	80/07/15 80/07/15	50-70 50-70	Ŕ
8007220056 8007220060	8007220025 8007220050	80/06/19	WASTE MOT		8007220377	8007220374	B0/07/14	50~259	P
B007220064 B007220067	8007220025 8007220055	80/05/09 80/06/19 80/07/10	50-219 WASTE MGT 71-249	G	8007220378 8007220382	8007220375 8007220381	80/07/17 80/07/11	50-346 50-272	9
B007220069	8007220059	80/06/27	, .	Ø	8007R2385 8007220391	8007220383 8007220387	80/07/17 80/03/03	50-304 50-304	9 8
8007220070 B007220073	8007220063 8007220068	80/06/17 80/06/20	40-8728 40-8771		8007#2039# 8007#2039&	8007220390 8007220394	80/07/18 80/07/15	50-395 50-331	F
8007220074 8007220075	8007220025 8007220059	80/06/19 80/06/27		Q	8007220407 8007220421	8007220403 8007220419	80/07/14 80/07/10	50-244 50-250	9
8007220077 8007220079	8007220048 8007220059	80/06/20 80/06/27	40-8771 50-335	o	B007#20427	8007220424	80/07/17	50~269	g
B0072200B1 B0072200B2	8007220025 8007220048	80/06/19 80/06/20	WASTE MGT 40-8771		8007220427 8007220433 8007220434	8007220426 8007220426 8007220430	80/07/11 80/07/11	50~261 50~261	Ÿ
8007220087 8007220088	8007220025 8007220059	80/06/19 80/06/27	WASTE MOT	n.	8007220435 8007220435 8007220435	8007220430 8007220426 8007220431	80/07/15 80/07/11 80/07/15	50~334 50~261 50~338	S V R
8007220097	8007220087	60/07/20	71-9136	_	8007220498	8007220426	B0/07/11	50-241	٧
8007220100 8007220101 8007220101	8007220095 8007220025 8007220093	80/05/05 80/06/19	WASTE MOT	3	8007220445 8007220448	8007220440 8007220441	80/07/16 80/07/17	50~261 50-387	8 F
8007220102 8007220103	8007220093	80/05/17 80/07/15	PR 50-275	9	8007220453 8007220459	8007220449 8007220455	80/07/16 80/07/09	50-295 50-249	8
8007220106 8007220111	8007220099 8007220025	80/07/10 80/06/19	71-121 WASTE MOT		8007220462 8007220465	8007220443 8007220458	79/02/15 B0/07/17	50-259 50-346	R S
8007220112 8007220114	8007220095 8007220107	80/05/05 80/07/03	DO-315 XPORTLIC	3	8007220467 8007220470	8007220457 8007220464	B0/07/14 B0/07/16	50~245 50~324	P 8
8007220119	8007220025	B0/06/19	TOM STEAM		8007220474	8007220469	BO/07/14	50-327	S

ACCESSION	NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1980ED	SUBJECT CATEGOR'		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUDJECT CATEGORY	r
8007220479 8007220483 8007220484 8007220488 8007220491	8007220476 8007220477 8007220478 8007220482 8007220481	80/07/15 80/07/11 80/07/16 80/07/17 80/01/31	50-247 50-269 50-255 TOPREP 50-259	R P S	8007230452 , 8007230462 8007230474 8007230479 9007230479	8007230445 800723045B 8007230470 800723047B 8007230480	80/07/15 80/07/21 80/07/15 80/06/12 80/07/18	50~322 50~259 50~155	SASFP
8007220496 8007220499 8007220503 8007220512 8007220515	8007220482 8007220482 8007220482 8007220307 8007220307	80/07/17 80/07/17 80/07/17 80/07/17 80/07/14	TOPREP TOPREP TOPREP 50-338 50-348	8	8007230483 8007230484 8007230499 8007230491 8007230491	8007230480 8007230482 8007230488 8007230490 8007230493	B0/07/18 B0/07/15 B0/07/17 B0/07/18 B0/07/17	50-327 50-331 50-271 50-259 50-338	4 4 8 8 8
8007220519 8007220524 8007220526 8007220530 8007220533	8007220514 8007220523 8007220525 8007220529 8007220529	B0/07/17 B0/07/15 B0/07/14 B0/07/16 B0/07/16	50-321 50-3 50-409 50-289 50-289	5 P 0	8007230503 8007230514 8007230531 8007230539 8007230539	8007230498 8007230504 8007230523 8007230534 8007230547	80/07/18 80/07/19 80/07/19 80/07/19 80/07/10	50-124 50-269 50-259 50-267 50-462	9 9 8 8 8
8007220550 8007220555 8007220572 9007220573 8007220574	8007220543 8007220553 8007220557 8007220569 8007220568	79/03/01 80/07/11 80/07/14 80/07/17 80/07/18	50-250 50-320 50-237 50-416 50-327	8 8 8	8007230554 8007230555 81007230564 8007230565 8007230565	8007230548 8007230543 8007230549 8007230559 8007230557	80/07/15 80/07/15 80/07/15 80/07/17 80/07/03	50-267 50-267 70-925 50-320 XPORTL10	B B
8007220580 8007220582 8007220583 8007220593 8007220611	8007220575 8007220579 8007220577 8007220587 8007220601	80/07/16 80/07/12 80/07/16 80/07/16 80/07/17	50~338 50~338 50~249 50~304 50~339	8 F 8 6 8	8007230573 8007230574 8007230571 8007230601 8007230608	0007230542 8007230570 8007230587 8007230597 8007230597	80/07/16 80/07/17 80/07/18 80/06/25 80/06/25	50~302 50~219 50~390 70~2000 70~2000	G 5 9
8007220627 8007230006 8007230008 8007230009 8007230015	8007220619 8007230002 8007230005 8007230005 8007230014	80/07/11 80/06/10 80/06/26 80/06/26 80/07/02	50-272 50~456 50-244 50-244 70-184	8 9 9	8007230614 8007230614 8007230617 8007230623 8007230629	8007230597 8007230607 8007230609 8007230618	80/06/25 80/07/21 80/07/21 80/07/09 80/07/09	70-2000 50-289 50-289 50-397 50-397	G G
8007230019 8007230021 8007230040 8007230062 8007230066	8007230002 8007230018 8007230038 8007230054 8007230059	80/06/10 80/06/27 80/07/09 80/06/30 80/06/17	50~454 50~277 71~5979 70~2375 50~341	Q F	8007230630 8007230632 8007230652 8007230655 8007230655	8007230626 8007230618 8007230618 8007230635 8007230644	80/05/25 80/07/09 80/07/09 80/06/30 80/07/17	50-320 50-397 50-397 50-275 FDIA	H G A
8007230078 8007230087 8007230124 8007230137 8007230150	8007230072 8007230072 8007230119 8007230130 8007230140	80/06/12 80/06/12 80/06/11 80/06/12 80/07/01	50-358 50-358 70-371 50-289 50-334	G G G	8007230463 8007230471 8007230478 8007230700 8007230701	8007230644 8007230644 8007230644 8007230693 8007230704	80/07/17 60/07/17 80/07/17 80/06/19 80/06/19	50-10 50-10 50-10 50-373 50-546	D D Q Q
8007230157 8007230160 8007230162 8007230164 8007230168	8007230140 8007230135 8007230140 8007230142 8007230142	80/07/01 80/07/02 80/07/01 80/06/04 80/06/04	50-334 GA999 50-334 50-269 50-269	0 0 0	8007230721 8007230722 8007230725 8007230730 8007230732	8007230715 8007230716 8007230715 8007230716 8007230716	80/07/10 80/07/01 80/07/10 80/07/01 80/07/01	40 -0452 50-277 40-8452 50-277 50-277	0 0 0
8007230174 8007230195 8007230196 8007230202 8007230209	8007230140 8007220471 8007230182 8007230182 8007230182	80/07/01 80/07/17 80/06/27 80/06/27 80/06/27	50-334 50-289 50-293 50-293 50-293	0 F 0 0	8007230734 8007230736 8007230739 8007230751 8007230751	8007230714 8007230714 8007230735 8007230745 8007230754	80/07/01 80/07/01 80/06/12 80/06/12 80/06/23	50-277 50-277 CDMM15811 COMM19811 50-295	
8007230221 8007230234 8007230256 8007230257 8007230272	8007230182 8007230224 8007230250 8007230244 8007230268	80/06/27 80/07/16 80/07/16 80/06/20 80/06/24	50-293 FOIA FOIA 50-313 50-295	0 0 0	8007240002 8007240004 8007240009 9007240011 8007240013	8007240001 8007240004 8007240007 8007240007 8007240007	80/07/18 80/06/13 80/06/13 80/07/01 80/07/01	TOPREP 50-155 50-155 40-8452 40-8452	0
8007230273 8007230274 8007230281 8007230287 8007230291	8007230266 8007230268 8007230283 8007230282 8007230282	80/06/23 80/06/24 80/07/03 80/07/16 80/07/16	50-373 50-275 50-373 50-206 50-206	0 0 0 0	8007240019 8007240018 8007240028 9007240028 8007240029	8007240007 8007240012 8007240007 8007240024 8007240007	80/07/01 80/06/05 80/07/01 80/07/03 80/07/01	40~8452 50~301 40~8452 50~346 40~8452	0
8007230292 8007230295 8007230297 8007230303 8007230308	8007230278 8007230282 8007230282 8007230296 8007230301	80/05/19 80/07/16 80/07/16 80/05/18 80/05/20	50-49B 50-206 50-206 50-331 50-289	9 9 9	8007240034 8007240036 8007240041 8007240044 8007240048	8007240027 8007240030 8007240007 8007240027 8007240007	80/06/30 80/06/20 80/07/01 80/06/30 80/07/01	COMMISSI XPORTLIC 40-8452 COMMISSI 40-8482	
8007230317 8007230321 8007230324 8007230328 8007230333	8007230314 8007230313 8007230111 8007230314 8007230327	80/05/18 80/07/15 80/07/01 80/05/18 80/05/19	50-305 50-440 50-245 50-305 50-346	0 P 0	8007240050 800724005B 8007240059 8007240061 8007240062	8007240027 8007240053 8007240055 8007240056 8007240053	80/06/30 80/07/16 80/05/20 80/06/16 80/07/16	COMM1881 50-213 XPORTLIC 50-213 50-213	P
8007230354 8007230355 8007230366 8007230375 8007230379	8007230349 8007230350 8007230361 8007230365 8007230371	80/06/24 80/06/09 80/06/11 80/06/19	71-121 50-224 50-213 50-304 50-10	0 0 0	8007240070 8007240086 8007240093 8007240094 8007240094	8007240067 8007240075 8007240086 8007240090 8007240096	80/07/14 78/08/30 80/03/28 80/06/20	50-213 50-250 50-361 71-5607 70-1359	P R O
8007230383 8007230388 8007230398 8007230412 8007230443	8007230377 8007230371 8007230387 8007230402 8007230432	80/05/12 80/05/19 80/05/09 80/05/17 80/07/09	50-309 50-10 50-309 50-329 50-312	0 0 0 P	8007240107 8007240109 8007240110 8007240114 8007240116	B007240104 B007240105 B007240106 B007240112 B007240115	80/07/02 80/07/16 80/07/01 80/07/15 80/07/22	50~263 50~254 70~1201 50~265 50~339	9

ACCESSIO:	4 NUMBER			ACCESSIO			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	enclosure	PRINCIPAL DOCUMENT	DATE 198UED	SUBJECT CATEGORY
8007240125	8007240119	80/07/01	70-27	B007240493	8007240480	80/07/10	COMMISSION
8007240128	8007240124	80/07/15	50-366 8	8007240494	8007240480	80/07/10	COMMISSION
8007240129	8007240127	80/07/15	50-3 I	B007240497	8007240480	80/07/10	COMMISSION
8007240134	8007240130	80/07/21	50-285 8	B007250010	8007250007	80/07/02	COMMISSION
8007240135	8007240132	80/07/01	NUREO	B007250010	8007250006	80/06/24	40-4337
8007240137	8007240132	80/07/01	NUREG	8007250019	8007250014	80/07/11	10CFR
8007240142	8007240131	80/07/11	50-387 K	8007250028	8007250025	60/05/20	COMMISSION
8007240143	8007240131	80/07/11	50-387 K	8007250035	8007250032	80/07/08	50-10 P
8007240150	8007240148	80/07/17	50-313 S	8007250055	8007250022	80/07/22	FOIA
8007240153	8007240152	80/07/18	50-318 S	8007250057	8007250052	80/06/10	GA999
8007240156	8007240149	80/07/22	50-339 P	800725005B	8007250022	80/07/22	FOIA
8007240159	8007240149	80/07/22	50-339 P	8007250041	8007250022	80/07/22	FOIA
8007240161	8007240149	80/07/22	50-339 P	8007250067	8007250042	80/07/15	50-320 H
8007240166	8007240149	80/07/22	50-339 P	80072500B2	8007250079	80/07/09	COMMISSION
8007240167	8007240165	80/07/17	50-366 S	80072500B2	8007250079	80/07/09	COMMISSION
8007240170	8007240168	80/06/09	CONTRACT	80072500B9	8007250079	80/07/09	COMMISSION
8007240172	8007240169	80/07/17	50-247 S	8007250095	8007250052	80/06/10	GA777
8007240173	8007240168	80/06/09	CONTRACT	8007250096	8007250088	80/07/10	50-388 G
8007240177	8007240174	80/07/05	50-250 R	8007250098	8007250079	80/07/09	COMMISSION
8007240179	8007240175	80/07/15	71-383	8007250100	8007250052	80/06/10	GA777
8007240188	8007240183	80/07/18	FOIA	8007250101	8007250079	80/07/09	COMMISSION
8007240193	8007240186	80/07/15	71-137	8007250105	8007250079	80/07/09	COMMISSION
8007240196	8007240187	80/07/03	50-324 G	8007250109	8007250052	80/06/10	CA999
8007240207	8007240201	80/07/15	71-6274	8007250114	8007250079	80/07/09	COMMISSION
8007240210	8007240185	80/06/06	50-282 G	8007250115	8007250110	80/06/11	71-5957
8007240215 8007240217 8007240231 8007240234 8007240240	8007240200 8007240212 8007240225 8007240225 8007240236	80/07/15 80/07/15 80/07/15 80/07/15 80/06/10	71-9044 71-9132 50-257 P 50-259 P 50-358 Q	8007250117 8007250118 8007250137 8007250174 8007250180	B007250111 B007250079 B007250079 B007250167 B007250176	80/07/07 80/07/09 80/07/09 80/07/10 80/06/04	COMMISSION COMMISSION 50-320 H SECY
8007240242	8007240238	80/07/15	50-277 P	8007250189	8007250184	80/05/14	GA979
8007240247	8007240224	80/06/23	XPORTLIC	8007250215	8007250202	80/07/03	COMMISSION
8007240249	8007240238	80/07/15	50-277 P	8007250246	8007250225	80/07/02	50~546 U
8007240251	8007240238	80/07/15	50-277 P	8007250258	8007250241	80/07/08	50~220 G
8007240253	8007240236	80/06/10	50-358 Q	8007250262	8007250241	80/07/08	50~220 G
8007240258	8007240245	80/07/16	40-4337	8007250263	8007250241	80/07/08	50-220 Q
8007240259	8007240255	80/07/14	50-298 P	8007250264	8007250251	80/07/07	50-317 H
8007240263	8007240261	80/07/11	50-250 Q	8007250270	8007250267	80/06/16	50-293 Q
8007240264	8007240252	80/07/11	50-321 Q	8007250270	8007250277	80/07/02	50-275 H
8007240266	8007240261	80/07/11	50-250 Q	8007250303	8007250300	80/07/15	50-245 P
8007240272	8007240261	80/07/11	50-250 0	8007280317	8007250313	80/07/03	50-286 0
8007240273	8007240267	80/06/27	50-204 0	8007230324	8007250315	80/07/21	50-334 8
8007240276	8007240261	80/07/11	50-250 0	8007230325	8007250313	80/07/03	50-286 0
8007240277	8007240252	80/07/11	50-321 0	8007230329	8007250313	80/07/03	50-286 0
8007240279	8007240265	80/07/08	50-518 0	8007250339	8007250326	80/07/22	50-302 P
8007240281	8007240261	80/07/11	50-250 G	8007250331	8007250315	80/07/21	50-334 B
8007240285	8007240252	80/07/11	50-321 G	8007250332	8007250313	80/07/03	50-286 G
8007240290	8007240282	80/06/30	70-1738	8007250341	8007250334	80/07/17	50-324 B
8007240292	8007240252	80/07/11	50-321 G	8007250348	8007250345	80/07/22	50-312 P
8007240293	8007240253	80/07/08	50-518 G	8007250385	8007250383	80/07/24	50-338 F
8007240298	8007240291	80/07/17	50-249 Q	8007250393	6007250391	80/07/11	50-397 A
8007240302	8007240297	80/07/10	50-327 P	8007250394	6007250391	80/07/11	50-397 A
8007240305	8007240265	80/07/08	50-518 Q	8007250398	6007250391	80/07/11	50-397 A
8007240306	8007240297	80/07/10	50-327 P	8007250400	6007250391	80/07/11	50-397 A
8007240312	8007240297	80/07/10	50-327 P	8007250402	8007250391	80/07/11	50-397 A
8007240313	8007240307	80/07/10	50-346 0	8007250403	8007250391	80/07/11	50-397 A
8007240314	8007240309	80/06/26	50-344 0	8007250405	8007250404	80/07/14	50-309 P
8007240326	8007240318	80/06/20	50-206 0	8007250410	8007250407	80/07/18	50-336 B
8007240329	8007240265	80/07/08	50-518 0	8007250412	8007250411	80/07/17	50-366 B
8007240331	8007240322	80/06/11	70-1257	8007250416	8007250414	80/07/22	50-327 B
8007240337	8007240333	80/06/03	50-498 0	8007250425	8007250421	80/07/18	50-298 R
8007240348	8007240228	79/09/04	70-1062	8007250433	8007250428	80/07/23	50-344 Q
8007240351	8007240340	80/07/16	50-456 0	8007250437	8007250428	80/07/23	50-344 Q
8007240368	8007240357	80/07/03	50-369 0	8007250438	8007250434	80/07/22	50-346 P
8007240376	8007240369	80/06/10	50-348 0	8007250444	8007250440	80/06/04	PROJ
8007240377	8007240357	80/07/03	30-369 Q	8087250452	8007250446	80/07/21	50-287 Q
8007240378	8007240371	80/07/09	50-289 H	8087250455	8007250448	80/07/18	50-373 A
8007240389	8007240383	80/07/02	70-2153	800725048	8007250474	80/07/22	50-344 P
8007240395	8007240385	80/06/18	50-275 Q	8087250483	8007250476	80/07/21	TOPREP
8007240413	8007240404	80/07/09	50-289 H	8087250494	8007250486	80/06/17	70-820
8007240420	8007240407	80/04/18	50-312	8007250499	8007250434	80/07/15	50-327 8
8007240433	8007240427	80/07/15		8007250502	8007250485	80/07/24	50-395 M
8007240441	8007240427	80/07/15		8007250520	8007250510	80/07/21	50-416 B
8007240457	8007240450	80/07/09		8007250552	8007250544	80/07/22	50-460 A
8007240468	8007240444	80/07/15		8007250562	8007250556	80/06/09	CONTRACT
8007240479 8007240481 8007240483 8007240487 8007240491	8007240474 8007240480 8007240480 8007240480 8007240480	80/07/21 80/07/10 80/07/10 80/07/10 80/07/10	FOIA COMMISSION COMMISSION COMMISSION	8007230578 8007230587 8007230588 8007230588 8007230589	8007250569 8007250582 8007250580 8007250582 8007250582	80/07/02 80/06/26 80/07/11 80/06/26 80/06/26	CONTRACT GA999 70-25 GA999 GA999

ij

ACCESSION NUMBER			ACCESSI	ON NUMBER		
PRINCIPAL ENCLOSURE DOCUMENT	ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 185UED	SUBJECT CATEGORY
8007250594 800725058 8007250603 800725059 8007250607 800725059 8007250621 800725062 8007250649 800725062	82 80/06/26 88 80/06/30 98 80/06/30 1 80/05/29	GA777 50-367 G 50-369 G COMMISSION 50-482 H	6007280527 6007280527 6007280533 6007280543 6007280543	8007280518 8007280520 8007280523 8007280532 8007280531	80/07/17 80/07/03 80/07/02 80/07/14 80/07/22	50-366 S CONTRACT 50-329 H 71-6698 50-250 P
8007280047 80072800 8007280080 80072800 8007280084 80072800 8007280088 80072800 8007280113 800728010	71 80/06/17 79 80/06/25 85 80/04/29	PR 50~333	8007280553 8007280555 8007280555 8007280573 8007280578	8007280545 8007280531 8007280561 8007280563 8007280571	B0/07/16 B0/07/22 B0/07/14 B0/07/16 B0/07/22	50-344 S 50-250 P 71-9030 50-344 S 50-346 S
8007280116 800728016 8007280128 800728013 8007280133 800728013 8007280134 800728013 8007280137 800728013	26 80/07/09 27 80/07/23 29 80/06/23	50-320 H 50-321 0 50-302 P 50-320 H 50-498 0	8007280580 8007280582 8007280588 8007280585 8007280587	8007280574 8007280572 8007280583	80/07/14 80/07/16 80/07/22 80/07/23 80/07/23	71-9049 50-245 P 50-321 S 50-346 S 50-528 K
8007280140 800728013 8007280147 80072801 8007280148 80072801 8007280153 80072801 8007280155 80072801	80/07/07 4 80/06/20 4 80/06/20	50~289 0 50~347 R 50~342 Q 50~382 Q 71~5979	8007280592 8007280593 8007280595 8007280602 8007280602	8007280579 8007280595 8007280596	80/07/02 80/07/02 80/07/23 80/07/21	50-278 S 50-320 G 50-528 K 50-346 S TOPREP
8007280160 80072801 8007280165 80072801 8007280170 80072801 8007280173 80072801 8007280177 80072801	51 80/06/30 52 80/06/19 51 80/06/30	71-5979 71-5979 COMMISSION 71-5979 71-5979	900728041 8007280419 8007280418 8007280422 8007280422	8007280610 8007280607 8007280609	B0/07/24 B0/07/22 B0/07/24 B0/07/23 B0/07/21	50-309 R 50-333 S 50-280 S 50-346 S 50-311 S
8007280184 80072801 8007280187 80072801 8007280188 80072801 8007280195 80072801 8007280202 80072801	79 80/06/06 32 80/07/07 32 80/07/07	70-143 70-143 50-320 H 50-320 H FOIA	8007280638 8007280635 8007280645 8007280645 8007280645	8007280633 8007280629 8007280634	80/07/25 80/07/24 80/07/22 80/07/17 80/07/22	50-445 M 50-244 S 50-321 S 50-321 P 50-346 S
8007280205 800728011 8007280209 800728011 8007280213 800728011 8007280225 80072802 8007280226 80072802	97 B0/07/21 97 B0/07/21 20 B0/06/03	50-10 D FOIA FOIA 70-27 50-348 P	8007280492 8007280495 8007280545 8007280454 8007280472	8007280446 8007280656 8007280662	80/07/16 80/06/30 80/07/17 80/07/22 80/07/17	50-267 0 50-368 5 50-409 0 50-333 8 50 409 0
8007280234 80072802 8007280246 80072802 8007280249 80072802 8007280251 80072802 8007280252 80072802	42 80/06/16 29 80/07/11 29 80/07/11	CONTRACT 50-354 9 50-333 P 50-333 P 50-293 9	8007280674 8007280677 8007280677 8007280686 8007280684	6007280664 6007280656 8007280678	80/07/21 80/07/18 80/07/17 80/07/10 80/07/17	90-305 S 50-317 S 50-409 O 50-321 R 50-409 O
8007280255 80072802 8007280256 80072802 8007280258 80072802 9007280242 80072802 8007280279 80072802	48 80/07/11 48 80/07/11 48 80/07/11	50-333 P 50-293 Q 50-293 Q 50-293 Q FOIA	8007280685 8007280686 800728086 8007280696 8007280691	8007280681 8007280681 8007280682	80/07/22 80/07/10 80/07/17 80/07/22 80/07/17	50-305 S 50-321 R 50-373 0 50-321 S 50-409 0
8007280327 80072803 8007280366 80072803 8007280382 80072803 8007280388 80072803 8007280390 80072803	60 80/07/07 76 80/07/21 84 80/07/22	70-1319 XPDRTLIC 50-204 8 50-278 P 50-278 P	8007280492 8007280494 8007280707 800728071 8007280721	6007280656 8007280698 6007280712	80/07/10 80/07/17 80/07/14 80/06/09 80/07/21	50-321 R 50-409 G 71-9053 CONTRACT 71-4986
8007280394 80072803 8007280400 80072803 8007280403 80072803 8007280404 80072803 8007280408 80072804	95 80/07/22 97 80/07/07 91 80/07/16	50-206 8 50-339 P XPURTLIC 50-206 S 50-293 Q	800728072 800728072 800728072 800728073 800728073	B007280724 B007880722 B007280724	80/06/12 80/06/17 80/06/12 80/06/17 80/07/09	COMM1991ON 50-482 O COMM1891ON 50-482 G 70-1100
8007280418 80072804 8007280421 80072804 8007280425 80072804 8007280430 80072804 8007280430 80072804	16 80/07/09 16 80/07/09 27 80/07/22	50-270 G 50-270 G 50-270 G 50-270 P 50-346 G	800728074; 800728074; 800728075; 800728077; 800728077;	8007280733 8007280762 8007280771	80/07/09 80/07/09 80/07/21 80/07/22 80/07/23	70-1100 70-1100 71-9080 71-9139 71-6387
8007280438 80072804 8007280443 80072804 8007280446 80072804 8007280449 80072804 8007280453 80072804	42 80/07/16 45 80/07/22 48 80/07/17	50-269 P 50-272 P 50-321 8 50-321 8 50-317 8	800729000; 800729000; 800729001; 800729001; 800729001;	5 B007290002 B007290008 B007290002	80/07/11 80/06/17 80/07/21 80/06/17 80/07/07	70-1100 SECY 71-6569 SECY 50-482 Q
8007280455 80072804 8007280457 80072804 8007280463 80072804 8007280467 80072804 8007280468 80072804	54 60/06/23 61 80/07/24 52 80/07/16	50-346 8 50-87 Q 50-284 I 50-298 P 50-259 Q	800729001 800729002 800729003 800729003 800729004	9 8007290028 8 8007290031 8 8007290034	80/07/16 80/06/02 80/07/16 80/07/21 80/07/14	71-9010 9ECY 50-209 H 90-483 A PROJ
8007280474 80072804 8007280475 80072804 8007280478 80072804 8007280484 80072804 8007280487 80072804	60 80/07/09 60 80/07/09 60 80/07/09	50-265 P 50-259 Q 50-259 Q 50-259 Q 50-294 A	800729004 800729005 800729005 800729005 800729006	0 007290041 1 8007290047 5 8007290055	80/07/16 80/07/16 80/06/17 80/07/16 80/07/16	State Prog State Prog 50-320 H MISC State Prog
8007280475 60072804 8007280511 90072805 8007280512 80072805 8007280513 80072805 8007280524 80072805	04 B0/07/18 05 B0/07/14 07 B0/07/21	50-574 A 50-313 8 50-346 9 50-400 R 50-333 6	8007.29006 8007.29006 8007.29019 8007.29023 8007.29024	3 8007290072 9 8007290174 7 8007290231	80/06/18 80/07/16 80/05/30 90/06/20 80/06/20	50-320 H 70~143 50-244 G 40-8102 40-8102

ACCESSIO	N NUMBER					ON NUMBER			
	PRINCIPAL DDCUHENT	DATE ISSUED	SUBJEC CATEGO		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	BUBUEC	PΥ
8007290253 8007290254 8007290262 8007290267	8007290236 8007290245 8007290277 8007290275	80/05/27 60/07/03 80/05/01	50~482 71~6717 50~327	Q.	80073D0048 80073D0051 80073D0056 80073D062	8007300046 8007300046 8007300046 8007300046	E1\40\08 E1\40\08 E1\40\08 E1\40\08	40-0745 40-0745 40-0745 40-0745	
8007290296 8007290321	8007290275 8007290307		QA999	G	B007300074 8007300094	800730006B 80073000B2	80/05/06	COMMITTED 70-149	I (H)
8007290337 8007290359 8007290361	8007290327 8007290347 8007290344	80/06/05 80/06/12 80/06/16	COMM 1 59	I DN	8007300103 8007300127 8007300136	8007300122 8007300122 8007300132	80/07/16 80/07/26 80/06/25	70~143 50~J09 50~331	Q
6007290366 6007290378	8007290338 8007290338	B0/07/21	QA999 QA999		8007300143 8007300157	8007300139 8007300151	80/06/25 80/06/24	50-454 50-461	q
6007290380	8007290369	B0/06/19	50-375	a	9007300164 9007300169	6007300160 6007300160	80/06/24	50~401	q
8007290392 8007290393	800729033B 8007290385	80/07/21 80/06/20	GA999 50-364	Q	B007300178	8007300173	80/06/24 80/07/17	50~40% GA999	q
8007290401	B007270395	80/05/20	50~259	G	8007300182	8007300173	B0/07/17	GATTY	
8007290404	8007290400	80/06/17 80/06/20	90-390 27-47	G	8007300188 8007300192	8007300173 8007300173	80/07/17 80/07/17	0A999 0A999	
8007290410 8007290414	8007270406 8007270409	80/06/16	50~424	G	8007300194	8007300173	80/07/17	08448	
8007290432	8007290422	60/06/23	50-566	Q.	8007300198	8007300173	80/07/17	94940	
6007290439	8007270433	80/07/08 80/07/03	90-782 XPORTL I	O O	8007300285 8007300289	8007300279 8007300288	80/06/30	40 -299 40 -299	
8007290452 8007290467	8007290446 8007290460	80/07/11	XPORTLI		8007300291	8007300284	80/07/23	50-259	P
6007290470	8007290463	00/06/10	PROJ	_	8007300295	8007300293	80/07/08	50 J44	Q
8007290475	6007290468	80/07/25 80/06/06	50-128 QA999	R	8007300304 8007300309	8007300300 8007300307	80/04/26	50~(129 50 040	0
8007290477 8007290481	8007290474 8007290474	80/05/05	GA999		8007300314	8007300310	80/04/04	50 R63 88999	Q
8007290487	8007290474	80/06/08	0A999		8007300315	8007300308	80/07/21	04979	
8007290492	8007290474	80/06/06 80/06/06	0A999 0A999		8007300318 8007300321	8007300313 8007300317	80/07/03 80/06/13	50 361 50 354	Ü
8007290497 8007290504	8007290474 8007290474	80/06/06	0A999		8007300325	8007300320	80/07/22	90-313	Q
8007290600	B007290586	80/07/22	50-220	s	8007300328 8007300331	8007300326	80/06/13	30 - 217	Q
8007270414 8007270427	8007290614 8007290626	80/07/23 80/07/24	50-255 50-395	B	8007300331	8007300324 8007300329	80/07/14 80/07/22	50-213	P
8007290839	0007270536	80/07/22	50-327	8	B00730033B	6007300324	80/07/14	50-213	ř
8007290640	8007280635	BO/07/24	50-287	8	8007300342	8007300324 8007300339	80/07/14	50-219	p
8007290656 8007290659	8007290649 8007290646	80/07/25 80/07/18	50-327 50-327	8	8007300343 8007300353	8007300339	80/07/09 80/06/12	50-206 50-310	9
8007270664	8007290457	BQ/07/18	50-259	ã	8007300354	8007300349	80/06/12	50 -313	ă
8007290672	8007270665	80/07/22	50~327 80~327	8	9007300376 9007300377	8007300374 8007300372	80/07/25	50-327	×
8007290673 800729067 <i>1</i>	8007290662 8007290669	80/07/25	50-327 50-202	8	8007300388	8007300372	B0/07/03 B0/07/24	20~334	9
8007270681	B007290675	00/07/25	50-327	8	8007300390	8007300381	80/07/20	50-266	ö
8007270487	9007290678 9007290685	80/07/07 80/07/24	50-454 50-327	8 K	8007300375 8007300470	8007300391 80073004B1	80/07/08 80/07/23	50~362 50 -344	9
8007270693 8007290702	8007270695	80/07/24	50-276	6	8007300494	8007300481	80/07/23	50 -344	Q
8007290707	8007290701	80/07/22	50-329	A	8007300498	8007300485	80/07/16	50~207	q
8007290710	8007270699	80/07/18	50-272	R	8007300500	8007300481	B0/07/23	50-044	õ
8007290711	0007290684	80/07/23	50-311	B	9007300506	8007300481	80/07/23	50 344	ø
8007290715 8007290726	800727070B 8007270720	80/07/25 80/07/22	50-327 50-260	8 8	9007300508 9007300508	8007800485 8007300485	80/07/16 80/07/16	50~23 <i>7</i> 50~237	q
8007290729	8007290718	80/07/23	50~272	8	8007300513	8007300392	80/07/24	50-021	to
8007270744	8007290737	80/07/25	50-257	8	6007300514	8007300511	80/07/29	50~402	٨
8007290770 8007290777	8007270762 8007270774	80/07/23 80/07/23	50-327 50-424	B	8007300517 8007300520	8007300511 8007300511	80/07/29 80/07/29	50~462 50~462	Å
8007270782	8007270771	80/07/07	CRO	•	8007300521	8007300511	80/07/29	50-402	Ä
8007290800	0007270790	00/07/16	50-327	9	8007300522 8007300524	8007300511	00/07/27	50-402	A
8007290803 8007290805	8007290781 8007290799	00/07/25 00/07/24	DR0 50-289	Я	8007300524 8007300525	8007300511 8007300518	80/07/29 80/07/09	50~344 50~344	A.
8007290B09	8007270781	80/07/25	ORG		E0073D0526	8007300511	80/07/29	50 -402	Ā
B007290B17	8007290911	80/07/18	50-320	8	6007300528	8007300511	60/07/29	50 402	A .
8007290818 8007290827	8007290810 8007290822	80/07/22 80/07/21	50-327 50-327	8	8007300529 8007300533	8007300511 8007300511	80/07/29 80/07/29	50-402 50-402	A
6007270827	8007270820	80/07/18	50-296	Ğ	8007300534	8007300511	B0/07/29	50-492	Ã
8007270830	8007270824	80/07/25	50~270	В	8007300535	8007300511	80/07/29	50~402	٨
8007290831	8007290823	80/07/25	50-925	В	8007300536	8007300511	B0/07/R9	50-AB2	٨
8007290832	8007290825	80/07/25	20-214	F	E00730053B	8007300511	80/07/29	50 -492	A
8007270833 8007270835	8007290824 8007290825	80/07/23 80/07/25	50-325 50-514	S F	9007300539 9007300540	8007300511 8007300511	80/07/29 60/07/29	50 · 402 50 ~ 402	A
8007290843	8007270838	00/07/22	50~JJB	ß	800730054⊋	8007300511	80/07/29	50 - 402	٨
8007290844	8007270837	80/07/23	50-270	S	B007300543	8007300511	80/07/29	50-402	٨
8007290853	8007270846	B0/06/19	50~128	a	8007300546	8007300511	80/07/29	50 -492	A
8007290862	8007290888	60/09/11	QA999		8007300547	8007300511	80/07/29	50 402	Ā
8007290871 8007290875	8007290869 8007290869	80/07/21 80/07/21		Q Q	600730054 <del>7</del> 6007300551	8007300511 8007300511	BO/07/29 BO/07/29	50~402 50~402	A
8007290878	8007270874	80/07/18		P	BQ07300554	8007300511	80/07/29	50 -492	Ā
8007290931	8007290929	80/07/11	71-240		0007000884	8007300511	60/07/29	50~482	A
8007270934	8007290922	80/07/11 80/07/14	71-340 71-370		800730095 <i>6</i> 8007300559	8007300511	80/07/29	50 402	Â
8007300007	0007300000	80/07/10	ORO		<b>90073005</b> 60	8007300557	80/04/16	40-0727	
8007300012 8007300040	8007300010 8007300038	80/07/16 80/07/11		H O	8007300562 8007300564	8007300511 8007300511	80/07/29 80/07/29	50 402 50-402	A
		A	20 01	-	450, 400001	300,000004	~~. ~		

ACCESSION	NUMBER			
	PRINCIPAL	DATE	SUBJECT	
ENCLIBURE	DOCUMENT	ISBUED	CATEGORY	•
8007300566	8007300511	80/07/29	50-482	A
8007300568	8007300511	B0/07/29	50-482	A
8007300570	8007300511	B0/07/29	50-482	A
8007300580	8007300574	BO/06/23	30-321	G
8007300591	8007300579	80/07/11	CONTRACT	-
9007300585	8007300574	80/06/27	50-254	G.
80073005B7	8007300584	80/07/02	50~390	Α
8007300590	8007300577	80/07/10	CONTRACT	
8007300574	8007300589	80/06/17	50~518	Q
8007300598	8007300395	80/04/27	CONTRACT	
B007300404	8007300401	80/06/25	50-34A	a
B007300404	8007300601	80/06/25	50-346	a
8007310010	8007310006	80/07/01	CONTRACT	
8007310015	8007310013	80/07/11	71-173	
8007310025	8007310022	80/07/10	50-10	Н
8007310055	8007310052	80/06/26	50-272	G
8007310043	8007310041	BO/06/56	50-277	G
8007310073	8007310069	80/07/01	XP DRTL. I C	
8007310118	8007310104	80/07/08	50-272	G
8007310124	8007310104	60/07/0B	50-272	Q
8007310131	8007310104	80/07/08	50-272	a
8007310169	8007310163	80/06/26	50-288	a
8007310176	8007310174	80/06/10	QA <b>77</b> 7	
8007310179	8007310174	80/06/10	QA999	
8007310182	8007310174	80/06/10	<b>4</b> 0.777	
8007310188	8007310174	80/06/10	QA999	
8007310189	8007310174	80/06/10	QA799	
8007310195	8007310174	80/06/10	0A777	
8007310220	8007310212	80/07/21	50-307	G
9007310222	8007310215	80/07/17	50-331	Р
8007310223	6007310212	80/07/21	50-389	0
8007310226	8007310215	80/07/17	50-33 i	P
8007310228	8007310212	80/07/21	50-387	G
8007310229	8007310215	80/07/17	50-331	P
8007310235	8007310212	80/07/21	50-389	a
8007310245	8007310240	80/07/53	50-416	a
8007310247	8007310232	80/07/24	FOIA	
8007310250	8007310232	B0/07/24	FOIA	
8007310240	8007310232	BO/07/24	FOLA	
9007310265	8007310258	80/07/24	FOIA	
8007310266	8007310232	80/07/24	FOIA	_
8007310267	8007310261	80/07/11	50-305	G
8007310269	6007310258	80/07/24	FOIA	
8007310270	8007310232	80/07/24	FDIA	_
8007310284	8007310278	80/07/25	50-315	G
8007310286	8007310281	80/07/11	50-352	8
8007310287	8007310275	80/07/14	50-321	g
8007310293	8007310287	80/07/11	50-354	8
8007310301	8007310294	80/07/02	50-312	q
8007310302	8007310297	80/07/11	50-482	8

	* 170.752.			
	PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATEGOR	
ENCLUSURE	DOCUMENT	135000		
B007310310	8007310285	80/07/25	50-320	þ
8007310316	8007310304	80/06/30	99~598	G)
8007310325	8007310323	80/07/29	50-327	P
8007310327	8007310321	80/07/10	50~275	G
B007310339	8007310335	80/06/30	50-295	G
B007310341	8007310340	80/07/21	50-289	F
B007310351	6007310344	80/06/23	50-259	G
8007310365	E007310341	80/06/19	50-245	a
8007310366	8007310363	80/06/23	50-461	G
		80/06/23	50-461	Ğ
8007310367	6007310363	80/00/60	JU 101	ч
		80/07/25	50-364	G.
8007310374	6007310330		50~269	P
80073103B1	8007310379	80/07/25		
8007310382	8007310379	80/07/25	50-269	P
8007310387	9007310386	80/05/15	50~327	Α
8007310405	0007310403	80/07/11	50-154	R
8007310417	8007310414	80/07/08	50-277	8
8007310418	8007310410	80/07/17	50~312	8
8007310420	8007310414	80/07/08	50-277	R
8007310425	8007310422	80/07/22	50-155	J
8007310430	8007310426	80/07/25	50~286	8
0007310430	2007310780	00707745		_
8007310437	8007310433	80/07/21	50-344	S
		80/07/24	50~409	ĩ
8007310443	8007310434		PR	•
8007310445	8007316441	80/07/07		G
8007310469	8007310467	80/07/28	50-320	u
8007310485	80073104B1	80/07/22	70-247B	
				_
8007310486	8007310480	BO/07/10	50-249	Q
B007310490	80073104B9	80/07/18	XPORTLIC	:
8007310492	6007310483	80/07/24	FQIA	
8007310495	8007310491	80/07/16	50~270	a
8007310496	6007310481	80/07/22	70-2478	
8007310500	8007310497	80/07/15	WASTE MG	T
8007310501	8007310491	80/07/16	50-270	a
8007310503	8007310481	80/07/22	FOIA	
8007310504	8007310499	80/06/19	50-247	G
8007310506	B007310481	80/07/22	FOIA	
0007010000	200,010101	20121.22		
8007310510	E007310507	80/04/27	50-295	G
8007310515	8007310507	80/06/27	50-295	ö
8007310516	8007310505	80/07/11	50-526	ä
			50-262	Н
8007310528	8007310526	80/07/24		
8007310529	8007310521	00/07/25	50-329	q
				_
8007310533	0007310530	80/07/22	50~373	Q
8007310535	8007310532	80/07/24	50-155	Н
8007310536	8007310534	80/07/22	<b>50~J4</b> 6	G
B007310549	8007310544	80/07/22	FOIA	

ACCESSION NUMBER



#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

#### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3. Transmittal and acknowledgement letters.
- 4. Certificates of service to the PSAR.

### C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

### D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

#### E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

;

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

#### H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

#### I, FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indomnity and insurance matters.

#### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

#### L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1 Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

#### M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- 1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- 3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

#### N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

### O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS
  proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3. Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6 All general technical correspondence, meeting announcements or meeting summaties relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11 Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

### R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

### S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1.7.

### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

8. Corrections to above items.

# U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

# W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

#### APPENDIX B

### **DEFINITIONS OF NONDOCKETED CATEGORIES**

### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

# CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

### DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

### FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.

- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

### I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

### MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
  - a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
  - b. They present the results of Commission licensing and policy decisions.
  - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

# ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3., Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

# PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
  - 1. Application submitted by the utility.
  - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
  - 3. Applicant's Quality Assurance Manual.
  - 4. Early site review information.
  - 5. Backup technical documents submitted in support of the application.
  - 6. Early site visits.
- B. Utility PSAR and Amendments
  - 1. PSARs submitted by the utility,
  - 2. Amendments and changes to the PSAR.
  - 3. Transmittal letters.
  - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
  - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
  - 1. Submittals and related material pertaining to the antitrust review.

### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

### 2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

### PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are.

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE. For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

# RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

# REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- 2. Summary minutes of review group meetings representing views expressed, including dissenting views
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

# RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include.

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

### STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes:

- Correspondence between and among NRC Office of State Programs and State officials, mostly State haison officers, regarding:
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

### XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

		,